

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

1ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021		2.670000
029		.149900
051		15.400000
111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.67	22.739959
115	Κατχ Τιμή X 1.8117/ 6.67	18.893831
116	Κατχ Τιμή X 1.8117/ 6.46	22.893045
117	Κατχ Τιμή X 1.8117/ 6.67	18.893831
118	Κατχ Τιμή X 1.8117/ 6.67	17.283129
150		.074800
211		.802900
212		.786500
213		1.875000
214		3.800000
221		.097700
224		.070000
231		.710000
241		6.240000
242		5.000000
251		290.000000
252		210.000000
301		4.320000
302		7.120000
360		10.700000
361		27.500000
362		5.250000
363		.580000
364		3.520000
365		22.500000
366		20.630000
367		.112600
368		20.000000
369		12.150000
370		8.000000
371		7.200000
372		1.270000
373		2.040000
374		2.750000
375		1.500000
376		
377		3.190000
378		.480000
379		14.000000
380		.260000
401		253.330000
402		365.970000
403		99.490000
404		200.770000
405		199.000000
406		308.980000
407		52.110000
408		4.280000
409		118.980000
410		109.980000
411		25.830000
412		2.820000
417		126.960000

420	91.820000
428	421.470000
450	108.650000
451	150.570000
452	92.260000
453	85.620000
454	115.740000
455	408.640000

501	501				
211		50.000000 x	.802900 =		40.145000
214		3.000000 x	3.800000 =		11.400000
401		1.000000 x	253.330000 =		253.330000
118		3.000000 x	17.283129 =		51.849387
114		8.000000 x	22.739959 =		181.919672
				ΑΘΡΟΙΣΜΑ =	538.644059
				Η.Δ. =	592.508465
502	502				
211		80.000000 x	.802900 =		64.232000
114		8.000000 x	22.739959 =		181.919672
402		1.000000 x	365.970000 =		365.970000
214		7.000000 x	3.800000 =		26.600000
118		4.000000 x	17.283129 =		69.132516
				ΑΘΡΟΙΣΜΑ =	707.854188
				Η.Δ. =	778.639607
503	503				
211		110.000000 x	.802900 =		88.319000
428		1.000000 x	421.470000 =		421.470000
214		10.000000 x	3.800000 =		38.000000
118		4.000000 x	17.283129 =		69.132516
114		8.000000 x	22.739959 =		181.919672
				ΑΘΡΟΙΣΜΑ =	798.841188
				Η.Δ. =	878.725307
504	504				
211		40.000000 x	.802900 =		32.116000
214		2.000000 x	3.800000 =		7.600000
114		8.000000 x	22.739959 =		181.919672
403		1.000000 x	99.490000 =		99.490000
				ΑΘΡΟΙΣΜΑ =	321.125672
				Η.Δ. =	353.238239
505	505				
211		200.000000 x	.802900 =		160.580000
214		10.000000 x	3.800000 =		38.000000
114		8.000000 x	22.739959 =		181.919672
118		8.000000 x	17.283129 =		138.265032
404		1.000000 x	200.770000 =		200.770000
				ΑΘΡΟΙΣΜΑ =	719.534704
				Η.Δ. =	791.488174

506	506			
211		95.000000 x	.802900 =	76.275500
214		6.000000 x	3.800000 =	22.800000
405		1.000000 x	199.000000 =	199.000000
242		2.500000 x	5.000000 =	12.500000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672

		ΑΘΡΟΙΣΜΑ =		630.760204

		Η.Δ. =		693.836224
507	507			
211		165.000000 x	.802900 =	132.478500
214		10.000000 x	3.800000 =	38.000000
242		7.000000 x	5.000000 =	35.000000
406		1.000000 x	308.980000 =	308.980000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032

		ΑΘΡΟΙΣΜΑ =		834.643204

		Η.Δ. =		918.107524
508	508			
211		40.000000 x	.802900 =	32.116000
407		1.000000 x	52.110000 =	52.110000
115		4.000000 x	18.893831 =	75.575324
116		16.000000 x	22.893045 =	366.288720
408		2.000000 x	4.280000 =	8.560000
214		2.000000 x	3.800000 =	7.600000

		ΑΘΡΟΙΣΜΑ =		542.250044

		Η.Δ. =		596.475048
509	509			
211		80.000000 x	.802900 =	64.232000
117		8.000000 x	18.893831 =	151.150648
409		1.000000 x	118.980000 =	118.980000
214		5.000000 x	3.800000 =	19.000000

		ΑΘΡΟΙΣΜΑ =		353.362648

		Η.Δ. =		388.698913
510	510			
211		80.000000 x	.802900 =	64.232000
117		8.000000 x	18.893831 =	151.150648
214		5.000000 x	3.800000 =	19.000000
410		1.000000 x	109.980000 =	109.980000

		ΑΘΡΟΙΣΜΑ =		344.362648

		Η.Δ. =		378.798913

511	511			
212		17.000000 x	.786500 =	13.370500
411		1.000000 x	25.830000 =	25.830000
214		1.000000 x	3.800000 =	3.800000
115		4.000000 x	18.893831 =	75.575324
112		30.000000 x	17.729980 =	531.899400

			ΑΘΡΟΙΣΜΑ =	650.475224

			Η.Δ. =	715.522746
512	512			
211		10.000000 x	.802900 =	8.029000
115		2.000000 x	18.893831 =	37.787662
214		1.000000 x	3.800000 =	3.800000
112		2.000000 x	17.729980 =	35.459960
412		1.000000 x	2.820000 =	2.820000

			ΑΘΡΟΙΣΜΑ =	87.896622

			Η.Δ. =	96.686284
518	518			
211		180.000000 x	.802900 =	144.522000
212		5.000000 x	.786500 =	3.932500
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
112		8.000000 x	17.729980 =	141.839840
417		1.000000 x	126.960000 =	126.960000
214		12.000000 x	3.800000 =	45.600000

			ΑΘΡΟΙΣΜΑ =	783.039044

			Η.Δ. =	861.342948
521	521			
211		40.000000 x	.802900 =	32.116000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
214		3.000000 x	3.800000 =	11.400000
420		1.000000 x	91.820000 =	91.820000

			ΑΘΡΟΙΣΜΑ =	386.388188

			Η.Δ. =	425.027007
550	550			
211		80.000000 x	.802900 =	64.232000
214		5.000000 x	3.800000 =	19.000000
117		8.000000 x	18.893831 =	151.150648
450		1.000000 x	108.650000 =	108.650000

			ΑΘΡΟΙΣΜΑ =	343.032648

			Η.Δ. =	377.335913

560	560			
211		80.000000 x	.802900 =	64.232000
117		8.000000 x	18.893831 =	151.150648
455		1.000000 x	408.640000 =	408.640000
214		7.000000 x	3.800000 =	26.600000

			ΑΘΡΟΙΣΜΑ =	650.622648

			H.Δ. =	715.684913
621	621			
213		.100000 x	1.875000 =	.187500
508		.005000 x	596.475048 =	2.982375
116		.200000 x	22.893045 =	4.578609
111		.800000 x	15.951934 =	12.761547

			B.T =	20.510031
623	623			
213		.100000 x	1.875000 =	.187500
508		.005000 x	596.475048 =	2.982375
504		.005000 x	353.238239 =	1.766191
116		.200000 x	22.893045 =	4.578609
112		.100000 x	17.729980 =	1.772998
518		.010000 x	861.342948 =	8.613429
509		.005000 x	388.698913 =	1.943495

			B.T =	21.844597
625	625			
213		.100000 x	1.875000 =	.187500
116		.200000 x	22.893045 =	4.578609
112		.100000 x	17.729980 =	1.772998
504		.005000 x	353.238239 =	1.766191
509		.005000 x	388.698913 =	1.943495
518		.014300 x	861.342948 =	12.317204
508		.005000 x	596.475048 =	2.982375

			B.T =	25.548372
630	630			
512		.020000 x	96.686284 =	1.933726

			B.T =	1.933726
630.1	630.1			
510		.006000 x	378.798913 =	2.272793

			B.T =	2.272793

641	641			
231		.200000 x	.710000 =	.142000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.951934 =	3.190387
113		.150000 x	23.479183 =	3.521877
252		.002500 x	210.000000 =	.525000

			B.T =	7.814264
651	651			
221		150.000000 x	.097700 =	14.655000
111		1.500000 x	15.951934 =	23.927901
112		.500000 x	17.729980 =	8.864990
509		.003600 x	388.698913 =	1.399316
509		.011100 x	388.698913 =	4.314558
511		.050000 x	715.522746 =	35.776137
630		.600000 x	1.933726 =	1.160236
625		1.000000 x	25.548372 =	25.548372
224		120.000000 x	.070000 =	8.400000

			B.T =	124.046510
652	652			
221		650.000000 x	.097700 =	63.505000
509		.011000 x	388.698913 =	4.275688
630		.320000 x	1.933726 =	.618792
625		1.000000 x	25.548372 =	25.548372
511		.050000 x	715.522746 =	35.776137
509		.001920 x	388.698913 =	.746302
112		.500000 x	17.729980 =	8.864990
111		1.500000 x	15.951934 =	23.927901

			B.T =	163.263183
1121	1121			
112		.007000 x	17.729980 =	.124110
501		.000100 x	592.508465 =	.059251
503		.002000 x	878.725307 =	1.757451

			T.E =	1.940811
1122	1122			
112		.007000 x	17.729980 =	.124110
503		.000330 x	878.725307 =	.289979
501		.000080 x	592.508465 =	.047401
505		.000600 x	791.488174 =	.474893
507		.001400 x	918.107524 =	1.285351
509		.004447 x	388.698913 =	1.728544

			T.E =	3.950277

1123A	1123A			
112		.007000 x	17.729980 =	.124110
501		.000100 x	592.508465 =	.059251
503		.002000 x	878.725307 =	1.757451
509		.005312 x	388.698913 =	2.064769
506		.001330 x	693.836224 =	.922802

			T.E =	4.928382
1123B	1123B			
509		.001487 x	388.698913 =	.577995

			T.E =	.577995
1140	1140			
112		.010000 x	17.729980 =	.177300
521		.000200 x	425.027007 =	.085005
501		.000100 x	592.508465 =	.059251

			T.E =	.321556
1610	1610			
111		.050000 x	15.951934 =	.797597
1122		.200000 x	3.950277 =	.790055
507		.000200 x	918.107524 =	.183622
501		.000100 x	592.508465 =	.059251
502		.000200 x	778.639607 =	.155728

			T.E =	1.986252
1620	1620			
112		.250000 x	17.729980 =	4.432495
1122		1.000000 x	3.950277 =	3.950277
501		.002000 x	592.508465 =	1.185017

			T.E =	9.567789
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	15.951934 =	3.987984
501		.000100 x	592.508465 =	.059251

			T.E =	14.747234
2111	2111			
112		.010000 x	17.729980 =	.177300
509		.005202 x	388.698913 =	2.022012
507		.001540 x	918.107524 =	1.413886
502		.002000 x	778.639607 =	1.557279
501		.000830 x	592.508465 =	.491782

			T.E =	5.662258

2112	2112			
213		.400000 x	1.875000 =	.750000
502		.002900 x	778.639607 =	2.258055
112		.250000 x	17.729980 =	4.432495
116		.250000 x	22.893045 =	5.723261
507		.002000 x	918.107524 =	1.836215
509		.004896 x	388.698913 =	1.903070
508		.004000 x	596.475048 =	2.385900

			T.E =	19.288996
2251	2251			
111		.600000 x	15.951934 =	9.571160
621		1.050000 x	20.510031 =	21.535533
112		.600000 x	17.729980 =	10.637988
509		.012432 x	388.698913 =	4.832305

			T.E =	46.576986
2252	2252			
111		1.400000 x	15.951934 =	22.332708
621		1.050000 x	20.510031 =	21.535533
113		1.400000 x	23.479183 =	32.870856
509		.012432 x	388.698913 =	4.832305

			T.E =	81.571401
2253	2253			
111		1.500000 x	15.951934 =	23.927901
621		1.050000 x	20.510031 =	21.535533
652		.020000 x	163.263183 =	3.265264
651		.250000 x	124.046510 =	31.011628
509		.012432 x	388.698913 =	4.832305
113		2.500000 x	23.479183 =	58.697958
112		.200000 x	17.729980 =	3.545996

			T.E =	146.816583
2254	2254			
111		.800000 x	15.951934 =	12.761547
652		.100000 x	163.263183 =	16.326318
621		.350000 x	20.510031 =	7.178511
509		.003788 x	388.698913 =	1.472391
113		1.500000 x	23.479183 =	35.218775

			T.E =	72.957542

2522	2522			
221		300.000000 x	.097700 =	29.310000
112		1.400000 x	17.729980 =	24.821972
623		.800000 x	21.844597 =	17.475678
630		.250000 x	1.933726 =	.483432
641		3.000000 x	7.814264 =	23.442792
625		.500000 x	25.548372 =	12.774186
511		.040000 x	715.522746 =	28.620910
509		.008880 x	388.698913 =	3.451646
509		.001500 x	388.698913 =	.583048
509		.005550 x	388.698913 =	2.157279
113		1.600000 x	23.479183 =	37.566693

			T.E =	180.687635
2921	2921			
301		1.000000 x	4.320000 =	4.320000
2522		.005000 x	180.687635 =	.903438
652		.002000 x	163.263183 =	.326526
113		.400000 x	23.479183 =	9.391673
111		.400000 x	15.951934 =	6.380774

			T.E =	21.322411
2922	2922			
302		1.020000 x	7.120000 =	7.262400
652		.012000 x	163.263183 =	1.959158
111		.600000 x	15.951934 =	9.571160
113		.800000 x	23.479183 =	18.783346

			T.E =	37.576065
5110	5110			
111		.100000 x	15.951934 =	1.595193

			T.E =	1.595193
5120	5120			
111		.080000 x	15.951934 =	1.276155

			T.E =	1.276155
5130	5130			
111		.050000 x	15.951934 =	.797597

			T.E =	.797597
5140	5140			
111		.030000 x	15.951934 =	.478558
550		.003750 x	377.335913 =	1.415010

			T.E =	1.893568

5150	5150			
111		.030000 x	15.951934 =	.478558
550		.002500 x	377.335913 =	.943340

			T.E =	1.421898
5160	5160			
213		.400000 x	1.875000 =	.750000
111		.160000 x	15.951934 =	2.552309
508		.001500 x	596.475048 =	.894713

			T.E =	4.197022
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	17.729980 =	.886499
111		.040000 x	15.951934 =	.638077

			T.E =	1.582576
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	17.729980 =	.531899
111		.020000 x	15.951934 =	.319039

			T.E =	.908938
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	17.729980 =	1.418398

			T.E =	4.938398
5240	5240			
112		.080000 x	17.729980 =	1.418398

			T.E =	1.418398
5311	5311			
111		.002000 x	15.951934 =	.031904
630.1		.020000 x	2.272793 =	.045456
510		.000250 x	378.798913 =	.094700
630		.020000 x	1.933726 =	.038675

			T.E =	.210734

5312	5312			
111		.001300 x	15.951934 =	.020738
630.1		.020000 x	2.272793 =	.045456
510		.000163 x	378.798913 =	.061744
630		.020000 x	1.933726 =	.038675

			T.E =	.166612
5321	5321			
111		.004000 x	15.951934 =	.063808

			T.E =	.063808
5322	5322			
111		.003300 x	15.951934 =	.052641

			T.E =	.052641
5330	5330			
111		.022200 x	15.951934 =	.354133

			T.E =	.354133
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.951934 =	.052641

			T.E =	.110641
5351	5351			
113		.005000 x	23.479183 =	.117396

			T.E =	.117396
5352	5352			
111		.005000 x	15.951934 =	.079760
113		.014000 x	23.479183 =	.328709

			T.E =	.408468
5353	5353			
111		.010000 x	15.951934 =	.159519
113		.020000 x	23.479183 =	.469584

			T.E =	.629103

5354	5354			
111		.035000 x	15.951934 =	.558318
113		.025000 x	23.479183 =	.586980

			T.E =	1.145297
5361A	5361A			
365		.003000 x	22.500000 =	.067500
630		.000300 x	1.933726 =	.000580
510		.000188 x	378.798913 =	.071214
113		.001500 x	23.479183 =	.035219

			T.E =	.174513
5361B	5361B			
366		.003000 x	20.630000 =	.061890
510		.000188 x	378.798913 =	.071214
630		.000300 x	1.933726 =	.000580
113		.001500 x	23.479183 =	.035219

			T.E =	.168903
5362A	5362A			
365		.005000 x	22.500000 =	.112500
630		.000500 x	1.933726 =	.000967
510		.000313 x	378.798913 =	.118564
113		.002500 x	23.479183 =	.058698

			T.E =	.290729
5362B	5362B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	1.933726 =	.000967
510		.000313 x	378.798913 =	.118564
113		.002500 x	23.479183 =	.058698

			T.E =	.281379
5363A	5363A			
365		.003000 x	22.500000 =	.067500
113		.001000 x	23.479183 =	.023479
510		.000125 x	378.798913 =	.047350
630		.000300 x	1.933726 =	.000580

			T.E =	.138909

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	23.479183 =	.023479
630		.000300 x	1.933726 =	.000580
510		.000125 x	378.798913 =	.047350

			T.E =	.133299
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	23.479183 =	.042263
630		.000500 x	1.933726 =	.000967
510		.000225 x	378.798913 =	.085230

			T.E =	.240959
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	1.933726 =	.000967
510		.000225 x	378.798913 =	.085230
113		.001800 x	23.479183 =	.042263

			T.E =	.231609
5371	5371			
111		17.300000 x	15.951934 =	275.968458
111		9.600000 x	15.951934 =	153.138566

			T.E =	429.107025
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	378.798913 =	37.879891
630		.100000 x	1.933726 =	.193373
113		.800000 x	23.479183 =	18.783346

			T.E =	84.856610
5380	5380			
111		5.000000 x	15.951934 =	79.759670
550		.412500 x	377.335913 =	155.651064

			T.E =	235.410734
5390	5390			
111		.120000 x	15.951934 =	1.914232
111		.030000 x	15.951934 =	.478558

			T.E =	2.392790

5510	5510				
361		15.000000 x	27.500000 =	412.500000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	5.250000 =	157.500000	
550		.375000 x	377.335913 =	141.500967	
113		20.000000 x	23.479183 =	469.583660	
365		2.000000 x	22.500000 =	45.000000	
111		20.000000 x	15.951934 =	319.038680	

			T.E =	1,556.723307	
5521	5521				
111		1.000000 x	15.951934 =	15.951934	
630.1		10.000000 x	2.272793 =	22.727930	
510		.125000 x	378.798913 =	47.349864	
630		10.000000 x	1.933726 =	19.337260	

			T.E =	105.366988	
5522	5522				
111		1.500000 x	15.951934 =	23.927901	

			T.E =	23.927901	
5530	5530				
453		.187500 x	85.620000 =	16.053750	
111		1.000000 x	15.951934 =	15.951934	
111		1.000000 x	15.951934 =	15.951934	

			T.E =	47.957618	
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.951934 =	11.963951	

			T.E =	20.663951	
5551	5551				
111		2.000000 x	15.951934 =	31.903868	
111		1.000000 x	15.951934 =	15.951934	

			T.E =	47.855802	
5552	5552				
379		1.000000 x	14.000000 =	14.000000	
630		.100000 x	1.933726 =	.193373	
510		.050000 x	378.798913 =	18.939946	
113		.400000 x	23.479183 =	9.391673	

			T.E =	42.524991	

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	23.479183 =	18.783346
630		.100000 x	1.933726 =	.193373
510		.100000 x	378.798913 =	37.879891
			T.E =	79.356610
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	378.798913 =	37.879891
630		.100000 x	1.933726 =	.193373
113		.800000 x	23.479183 =	18.783346
			T.E =	77.486610
5570	5570			
111		.100000 x	15.951934 =	1.595193
111		.030000 x	15.951934 =	.478558
			T.E =	2.073751
5580	5580			
111		.020000 x	15.951934 =	.319039
111		.030000 x	15.951934 =	.478558
			T.E =	.797597
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	15.951934 =	478.558020
550		.125000 x	377.335913 =	47.166989
367		20,000.000000 x	.112600 =	2,252.000000
			T.E =	2,786.425009
5621	5621			
111		1.000000 x	15.951934 =	15.951934
630		10.000000 x	1.933726 =	19.337260
630.1		10.000000 x	2.272793 =	22.727930
510		.125000 x	378.798913 =	47.349864
			T.E =	105.366988
5622	5622			
111		1.500000 x	15.951934 =	23.927901
			T.E =	23.927901

5630	5630			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.951934 =	11.963951

			T.E =	20.663951
5640	5640			
111		10.000000 x	15.951934 =	159.519340
111		2.000000 x	15.951934 =	31.903868

			T.E =	191.423208
5650	5650			
111		.120000 x	15.951934 =	1.914232
111		.030000 x	15.951934 =	.478558

			T.E =	2.392790
5710	5710			
362		40.000000 x	5.250000 =	210.000000
111		5.000000 x	15.951934 =	79.759670
112		1.000000 x	17.729980 =	17.729980
560		.125000 x	715.684913 =	89.460614
510		.125000 x	378.798913 =	47.349864
509		.125000 x	388.698913 =	48.587364
114		1.000000 x	22.739959 =	22.739959
380		800.000000 x	.260000 =	208.000000
363		15.000000 x	.580000 =	8.700000
377		250.000000 x	3.190000 =	797.500000
378		100.000000 x	.480000 =	48.000000

			T.E =	1,577.827451
5720	5720			
111		.500000 x	15.951934 =	7.975967
510		.062500 x	378.798913 =	23.674932
630		10.000000 x	1.933726 =	19.337260
630.1		10.000000 x	2.272793 =	22.727930

			T.E =	73.716089
5730	5730			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	15.951934 =	11.963951

			T.E =	20.663951