

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών

1ο Τρίμηνο του 2012

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
026	.099900
036	.090700
273	1.112900
297.1	2.170000
510	3.020000
511	.620000
513	1.200000
561	2.300000
565.3	3.800000
566.3	5.050000
567.13	18.120000
571.5.1	2.710000
572.1.7	3.670000
575.3	
581.2	9.090000
582.2	25.500000
588.3	
603.3	5.340000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	65.000000
630.1.2	305.000000
634.1.1	95.000000
647.2	19.000000
660.1.1	16.000000
667	139.000000
671.3.8	4,200.000000
672.4.6	5,050.000000
673.1.5	5,250.000000
684.6.2	115.000000
686.1	410.000000
687.1.1	2,400.000000
703.2.2	25.500000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,070.000000
719.1.3	1,100.000000
720.11	9.000000
729.1.2	1,040.000000
730.2.5	2.300000
732.5.30	75.000000
744.9	74,900.000000
755.10	14,190.000000
757.1.4	18,710.000000
760.1.4	4,800.000000
801.3.2	.220500
801.7.1	1.900000
812.1.2	.183200
812.2.3	1.884100
813.2.3	3.018300
816.3.2	.985000
820.5.1	.924000
820.5.4	3.156400
825.6.1	.594200
826.2.1	1.700000

835.1.2	76.500000
841.3.5	192.000000
842.3.2	81.400000
848.1.2	34.200000
852.1.6	995.000000
855.1.13	2,732.000000
858.1.2	3.200000
859.1.2	5.000000
865.13.10	19,950.000000
865.13.9	16,500.000000
865.8.3	41.000000
867.1.22	75,800.000000
871.7.4	49.520000
872.23.1	4.400000
880.1.2	.780000
885.1.2	20.000000
890.1.1	120.000000
910.2.5	9,500.000000
911.1.17	3,430.000000
912.1.5	3,694.000000
913.1.9	68.900000
914.1.8	140.000000
915.1.6	338.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,780.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,600.000000
931.1.5	370.000000
931.2.4	1,070.000000
932.4.2	348.000000
933.1.1	15.500000
934.1.1	324.000000
935.1.1	76.500000
950.1.1	5.900000
951.1.7	701.000000
951.2.2	12,650.000000
952.1.4	331.800000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.099900 =	.109890	
297.1		1.200000 x	2.170000 =	2.604000	
582.2		1.300000 x	25.500000 =	33.150000	
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	84.914967	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	20.419486 =	6.125846	
001		.300000 x	15.741598 =	4.722479	

			T.E =	21.756325	
100	100				
931.1.5		1.000000 x	370.000000 =	370.000000	
003		4.000000 x	20.419486 =	81.677944	
002		6.000000 x	17.312112 =	103.872672	

			T.E =	555.550616	
101	101				
931.2.4		1.000000 x	1,070.000000 =	1,070.000000	
002		9.000000 x	17.312112 =	155.809008	
003		6.000000 x	20.419486 =	122.516916	

			T.E =	1,348.325924	
102	102				
820.5.4		1.020000 x	3.156400 =	3.219528	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	10.765848	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	442.328995	
104	104				
933.1.1		1.000000 x	15.500000 =	15.500000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	

			T.E =	60.777918	

ΑΤΗΕ		1ο Τρίμηνο του 2012		Σελ.	5
				Ημ/νία	20/07/2012
105	105				
934.1.1		1.000000 x	324.000000 =		324.000000
002		2.000000 x	17.312112 =		34.624224
003		2.000000 x	20.419486 =		40.838972

			T.E =		399.463196
106	106				
951.1.7		1.030000 x	701.000000 =		722.030000
002		4.000000 x	17.312112 =		69.248448
003		4.000000 x	20.419486 =		81.677944

			T.E =		872.956392
107	107				
952.1.4		1.030000 x	331.800000 =		341.754000
002		1.000000 x	17.312112 =		17.312112
003		1.000000 x	20.419486 =		20.419486

			T.E =		379.485598
108	108				
951.2.2		1.030000 x	12,650.000000 =		13,029.500000
003		6.000000 x	20.419486 =		122.516916
002		6.000000 x	17.312112 =		103.872672

			T.E =		13,255.889588
109	109				
953.1.3		1.030000 x	26,500.000000 =		27,295.000000
003		12.000000 x	20.419486 =		245.033832
002		12.000000 x	17.312112 =		207.745344

			T.E =		27,747.779176
11	11				
603.3		1.030000 x	5.340000 =		5.500200
003		.500000 x	20.419486 =		10.209743

			T.E =		15.709943
110	110				
950.1.1		1.050000 x	5.900000 =		6.195000
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897

			T.E =		13.741320

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	165.438959	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	61.030639	
14	14				
026		15.000000 x	.099900 =	1.498500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	20.419486 =	40.838972	
x		2.000000 x	17.312112 =	34.624224	

			T.E =	149.961696	
15	15				
x		1.000000 x	65.000000 =	65.000000	
x		2.000000 x	20.419486 =	40.838972	
x		2.000000 x	17.312112 =	34.624224	
x		.100000 x	65.000000 =	6.500000	

			T.E =	146.963196	
16	16				
003		1.000000 x	305.000000 =	305.000000	
002		3.000000 x	20.419486 =	61.258458	
630.1.2		3.000000 x	17.312112 =	51.936336	
		.050000 x	305.000000 =	15.250000	

			T.E =	433.444794	
17	17				
634.1.1		1.200000 x	95.000000 =	114.000000	
003		2.000000 x	20.419486 =	40.838972	
002		.200000 x	17.312112 =	3.462422	
634.1.1		.050000 x	95.000000 =	4.750000	

			T.E =	163.051394	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	23.083897	

19	19			
660.1.1		1.030000 x	16.000000 =	16.480000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422

			T.E =	24.026320
2	2			
561		5.320000 x	2.300000 =	12.236000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267

			T.E =	34.874959
20	20			
667		1.000000 x	139.000000 =	139.000000
667		.020000 x	139.000000 =	2.780000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

			T.E =	292.706392
21	21			
671.3.8		1.000000 x	4,200.000000 =	4,200.000000
671.3.8		.100000 x	4,200.000000 =	420.000000
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720

			T.E =	5,374.631960
22	22			
672.4.6		1.000000 x	5,050.000000 =	5,050.000000
672.4.6		.100000 x	5,050.000000 =	505.000000
003		20.000000 x	20.419486 =	408.389720
002		20.000000 x	17.312112 =	346.242240

			T.E =	6,309.631960
23	23			
673.1.5		1.000000 x	5,250.000000 =	5,250.000000
003		25.000000 x	20.419486 =	510.487150
002		25.000000 x	17.312112 =	432.802800
687.1.1		.020000 x	2,400.000000 =	48.000000
687.1.1		1.000000 x	2,400.000000 =	2,400.000000
673.1.5		.020000 x	5,250.000000 =	105.000000

			T.E =	8,746.289950

24	24				
684.6.2		1.000000 x	115.000000 =	115.000000	
003		1.000000 x	20.419486 =	20.419486	
684.6.2		.020000 x	115.000000 =	2.300000	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	155.031598	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	569.126392	
26	26				
703.2.2		1.020000 x	25.500000 =	26.010000	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

			T.E =	35.442900	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	20.419486 =	204.194860	
002		10.000000 x	17.312112 =	173.121120	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.741598 =	78.707990	

			T.E =	5,698.823970	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	
001		6.000000 x	15.741598 =	94.449588	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,747.188764	
29	29				
718.3.3		1.000000 x	1,070.000000 =	1,070.000000	
002		8.000000 x	17.312112 =	138.496896	
718.3.3		.050000 x	1,070.000000 =	53.500000	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	1,425.352784	

3	3			
026		1.200000 x	.099900 =	.119880
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

			T.E =	
30	30			
719.1.3		1.000000 x	1,100.000000 =	1,100.000000
719.1.3		.100000 x	1,100.000000 =	110.000000
003		16.000000 x	20.419486 =	326.711776
002		16.000000 x	17.312112 =	276.993792
001		8.000000 x	15.741598 =	125.932784

			T.E =	1,939.638352
31	31			
720.11		1.020000 x	9.000000 =	9.180000
003		.300000 x	20.419486 =	6.125846

			T.E =	15.305846
32	32			
729.1.2		1.000000 x	1,040.000000 =	1,040.000000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
729.1.2		.030000 x	1,040.000000 =	31.200000

			T.E =	1,146.663196
33	33			
757.1.4		1.000000 x	18,710.000000 =	18,710.000000
757.1.4		.050000 x	18,710.000000 =	935.500000
002		15.000000 x	17.312112 =	259.681680
003		15.000000 x	20.419486 =	306.292290
001		7.000000 x	15.741598 =	110.191186

			T.E =	20,321.665156
34	34			
273		1.000000 x	1.112900 =	1.112900
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
273		.100000 x	1.112900 =	.111290

			T.E =	12.543669

35	35			
730.2.5		1.050000 x	2.300000 =	2.415000
003		.120000 x	20.419486 =	2.450338
002		.120000 x	17.312112 =	2.077453
730.2.5		.250000 x	2.300000 =	.575000

			T.E =	7.517792
36	36			
732.5.30		1.050000 x	75.000000 =	78.750000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845

			T.E =	93.842639
37	37			
744.9		1.000000 x	74,900.000000 =	74,900.000000
744.9		.020000 x	74,900.000000 =	1,498.000000
001		10.000000 x	15.741598 =	157.415980
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720

			T.E =	77,310.047940
38	38			
755.10		1.000000 x	14,190.000000 =	14,190.000000
755.10		.020000 x	14,190.000000 =	283.800000
001		10.000000 x	15.741598 =	157.415980
002		10.000000 x	17.312112 =	173.121120
003		10.000000 x	20.419486 =	204.194860

			T.E =	15,008.531960
39	39			
760.1.4		1.000000 x	4,800.000000 =	4,800.000000
760.1.4		.050000 x	4,800.000000 =	240.000000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	5,172.060593
4	4			
565.3		1.250000 x	3.800000 =	4.750000
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692

			T.E =	27.388959

40	40			
036		3.000000 x	.090700 =	.272100
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
510		.350000 x	3.020000 =	1.057000
511		.250000 x	.620000 =	.155000
513		.250000 x	1.200000 =	.300000

			T.E =	18.763319
41	41			
801.3.2		1.050000 x	.220500 =	.231525
003		.100000 x	20.419486 =	2.041949
801.3.2		.105000 x	.220500 =	.023153
002		.100000 x	17.312112 =	1.731211

			T.E =	4.027837
42	42			
801.7.1		1.050000 x	1.900000 =	1.995000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
801.7.1		.210000 x	1.900000 =	.399000

			T.E =	9.940320
43	43			
812.1.2		1.050000 x	.183200 =	.192360
003		.020000 x	20.419486 =	.408390
002		.020000 x	17.312112 =	.346242

			T.E =	.946992
44	44			
812.2.3		1.050000 x	1.884100 =	1.978305
003		.060000 x	20.419486 =	1.225169
002		.060000 x	17.312112 =	1.038727

			T.E =	4.242201
45	45			
813.2.3		1.050000 x	3.018300 =	3.169215
813.2.3		.105000 x	3.018300 =	.316922
003		.050000 x	20.419486 =	1.020974
002		.050000 x	17.312112 =	.865606

			T.E =	5.372716

46	46			
816.3.2		.157500 x	.985000 =	.155138
816.3.2		1.050000 x	.985000 =	1.034250
002		.120000 x	17.312112 =	2.077453
003		.120000 x	20.419486 =	2.450338

			T.E =	5.717179
47	47			
820.5.1		1.050000 x	.924000 =	.970200
820.5.1		.157500 x	.924000 =	.145530
003		.140000 x	20.419486 =	2.858728
002		.140000 x	17.312112 =	2.423696

			T.E =	6.398154
48	48			
825.6.1		1.050000 x	.594200 =	.623910
003		.100000 x	20.419486 =	2.041949
002		.100000 x	17.312112 =	1.731211
825.6.1		.157500 x	.594200 =	.093587

			T.E =	4.490656
49	49			
826.2.1		1.000000 x	1.700000 =	1.700000
003		.200000 x	20.419486 =	4.083897

			T.E =	5.783897
5	5			
566.3		1.250000 x	5.050000 =	6.312500
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692

			T.E =	28.951459
50	50			
842.3.2		1.000000 x	81.400000 =	81.400000
842.3.2		.030000 x	81.400000 =	2.442000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743

			T.E =	102.707799
51	51			
841.3.5		1.000000 x	192.000000 =	192.000000
841.3.5		.030000 x	192.000000 =	5.760000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	235.491598

52	52				
835.1.2		1.050000 x	76.500000 =	80.325000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	

			T.E =	193.519794	
53	53				
848.1.2		1.020000 x	34.200000 =	34.884000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	38.967897	
54	54				
858.1.2		1.020000 x	3.200000 =	3.264000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	7.347897	
55	55				
859.1.2		1.020000 x	5.000000 =	5.100000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	9.183897	
56	56				
865.8.3		1.050000 x	41.000000 =	43.050000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	118.513196	
57	57				
865.13.9		1.020000 x	16,500.000000 =	16,830.000000	
002		25.000000 x	17.312112 =	432.802800	
003		25.000000 x	20.419486 =	510.487150	
001		10.000000 x	15.741598 =	157.415980	

			T.E =	17,930.705930	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.312112 =	2,250.574560	
003		130.000000 x	20.419486 =	2,654.533180	
001		130.000000 x	15.741598 =	2,046.407740	

			T.E =	85,025.515480	

59	59				
871.7.4		1.000000 x	49.520000 =	49.520000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
871.7.4		.020000 x	49.520000 =	.990400	

			T.E =	95.788318	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	61.287598	
60	60				
872.23.1		1.020000 x	4.400000 =	4.488000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
880.1.2		1.000000 x	.780000 =	.780000	

			T.E =	27.906959	
61	61				
885.1.2		1.000000 x	20.000000 =	20.000000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	42.638959	
62	62				
890.1.1		1.000000 x	120.000000 =	120.000000	
890.1.1		.050000 x	120.000000 =	6.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	201.463196	
63	63				
910.2.5		1.000000 x	9,500.000000 =	9,500.000000	
002		50.000000 x	17.312112 =	865.605600	
001		30.000000 x	15.741598 =	472.247940	
003		50.000000 x	20.419486 =	1,020.974300	
910.2.5		.020000 x	9,500.000000 =	190.000000	

			T.E =	12,048.827840	

7	7				
571.5.1		1.400000 x	2.710000 =	3.794000	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	

			T.E =	15.113479	
8	8				
572.1.7		1.350000 x	3.670000 =	4.954500	
002		.700000 x	17.312112 =	12.118478	
003		.700000 x	20.419486 =	14.293640	

			T.E =	31.366619	
80	80				
911.1.17		1.050000 x	3,430.000000 =	3,601.500000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	4,733.447940	
81	81				
912.1.5		1.050000 x	3,694.000000 =	3,878.700000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	5,010.647940	
82	82				
913.1.9		1.200000 x	68.900000 =	82.680000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	233.606392	
83	83				
914.1.8		1.100000 x	140.000000 =	154.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	229.463196	
84	84				
915.1.6		1.050000 x	338.000000 =	354.900000	
002		8.000000 x	17.312112 =	138.496896	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	656.752784	

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720

			T.E =	14,510.681960
86	86			
865.13.10		1.020000 x	19,950.000000 =	20,349.000000
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480

			T.E =	21,858.263920
87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	20.419486 =	2,450.338320
002		120.000000 x	17.312112 =	2,077.453440

			T.E =	
88	88			
917.1		1.000000 x	7,780.000000 =	7,780.000000
917.1		.030000 x	7,780.000000 =	233.400000
918.1.1		.030000 x	2,010.000000 =	60.300000
920.1.1		.030000 x	7,479.000000 =	224.370000
923.1.1		.030000 x	61.620000 =	1.848600
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480
923.2.1		.030000 x	161.400000 =	4.842000
923.2.1		1.000000 x	161.400000 =	161.400000
923.1.1		1.000000 x	61.620000 =	61.620000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
918.1.1		1.000000 x	2,010.000000 =	2,010.000000

			T.E =	19,526.044520
89	89			
852.1.6		1.000000 x	995.000000 =	995.000000
855.1.13		1.000000 x	2,732.000000 =	2,732.000000
855.1.13		.020000 x	2,732.000000 =	54.640000
925.1.1		.020000 x	4,600.000000 =	92.000000
003		60.000000 x	20.419486 =	1,225.169160
002		60.000000 x	17.312112 =	1,038.726720
925.1.1		1.000000 x	4,600.000000 =	4,600.000000
852.1.6		.020000 x	995.000000 =	19.900000

			T.E =	10,757.435880

9

9

575.3
003
002

1.200000 x
.300000 x
.300000 x

.000000 =
20.419486 =
17.312112 =

.000000
6.125846
5.193634

T.E =