

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

3ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	Κατχ Τιμή X 1.8117/ 6.46	16.829739
112	Κατχ Τιμή X 1.8117/ 6.46	18.705943
113	Κατχ Τιμή X 1.8117/ 6.46	24.769248
114	Κατχ Τιμή X 1.8117/ 6.46	18.705943
115	Κατχ Τιμή X 1.8117/ 6.46	24.152261
116	Κατχ Τιμή X 1.8117/ 6.67	23.989407
117	Κατχ Τιμή X 1.8117/ 6.67	18.233796
118	Κατχ Τιμή X 1.8117/ 6.67	19.931416
119	Κατχ Τιμή X 1.8117/ 6.67	18.117000
120	Κατχ Τιμή X 1.8117/ 6.67	19.931416
121	Κατχ Τιμή X 1.8117/ 6.67	17.389061
122	Κατχ Τιμή X 1.8117/ 6.67	18.298985
123	Κατχ Τιμή X 1.8117/ 4.00	62.435711
211		.820200
212		.937000
213		3.800000
214		1.840000
221		.097700
222		.070000
231		35.000000
232		35.000000
241		290.000000
242		335.000000
251		.511400
252		1.750000
253		3.700000
254		5.000000
255		.696500
256		3.500000
261		
262		.980000
263		.540000
311		424.010000
312		127.720000
313		200.190000
314		4.300000
315		52.420000
316		4.300000
317		119.700000
318		25.980000
319		20.960000
320		148.810000
321		202.570000
322		281.440000
323		320.500000
324		175.840000
325		301.180000
326		100.090000
327		4.300000
351		428.920000
352		364.160000
353		428.920000
354		562.720000
355		281.440000
356		46.180000
357		221.290000
358		44.550000
359		92.370000
360		97.280000

361	74.400000
362	257.520000
363	97.420000
380	541.750000
381	541.750000
382	541.750000
383	623.070000
384	1,031.980000
385	187.500000
386	494.740000
387	71.380000
388	71.380000
389	71.380000

401	401			
211		110.000000 x	.820200 =	90.222000
213		10.000000 x	3.800000 =	38.000000
117		4.000000 x	18.233796 =	72.935184
116		8.000000 x	23.989407 =	191.915256
311		1.000000 x	424.010000 =	424.010000

			ΑΘΡΟΙΣΜΑ =	817.082440

			Η.Δ. =	898.790684
402	402			
211		180.000000 x	.820200 =	147.636000
312		1.000000 x	127.720000 =	127.720000
112		8.000000 x	18.705943 =	149.647544
212		5.000000 x	.937000 =	4.685000
213		12.000000 x	3.800000 =	45.600000
116		8.000000 x	23.989407 =	191.915256
117		8.000000 x	18.233796 =	145.870368

			ΑΘΡΟΙΣΜΑ =	813.074168

			Η.Δ. =	894.381585
403	403			
211		80.000000 x	.820200 =	65.616000
254		2.500000 x	5.000000 =	12.500000
213		6.000000 x	3.800000 =	22.800000
117		8.000000 x	18.233796 =	145.870368
116		8.000000 x	23.989407 =	191.915256
313		1.000000 x	200.190000 =	200.190000

			ΑΘΡΟΙΣΜΑ =	638.891624

			Η.Δ. =	702.780786
404	404			
211		80.000000 x	.820200 =	65.616000
213		5.000000 x	3.800000 =	19.000000
212		2.000000 x	.937000 =	1.874000
119		4.000000 x	18.117000 =	72.468000
118		8.000000 x	19.931416 =	159.451328
112		4.000000 x	18.705943 =	74.823772
314		1.000000 x	4.300000 =	4.300000

			ΑΘΡΟΙΣΜΑ =	397.533100

			Η.Δ. =	437.286410

405	405				
211		40.000000 x	.820200 =		32.808000
213		2.000000 x	3.800000 =		7.600000
115		16.000000 x	24.152261 =		386.436176
118		4.000000 x	19.931416 =		79.725664
316		2.000000 x	4.300000 =		8.600000
315		1.000000 x	52.420000 =		52.420000

			ΑΘΡΟΙΣΜΑ =		567.589840

			Η.Δ. =		624.348824
406	406				
211		80.000000 x	.820200 =		65.616000
213		5.000000 x	3.800000 =		19.000000
317		1.000000 x	119.700000 =		119.700000
120		8.000000 x	19.931416 =		159.451328

			ΑΘΡΟΙΣΜΑ =		363.767328

			Η.Δ. =		400.144061
407	407				
212		17.000000 x	.937000 =		15.929000
318		1.000000 x	25.980000 =		25.980000
112		30.000000 x	18.705943 =		561.178290
213		1.000000 x	3.800000 =		3.800000
118		4.000000 x	19.931416 =		79.725664

			ΑΘΡΟΙΣΜΑ =		686.612954

			Η.Δ. =		755.274249
408	408				
211		30.000000 x	.820200 =		24.606000
112		4.000000 x	18.705943 =		74.823772
116		8.000000 x	23.989407 =		191.915256
117		4.000000 x	18.233796 =		72.935184
320		1.000000 x	148.810000 =		148.810000
213		3.000000 x	3.800000 =		11.400000

			ΑΘΡΟΙΣΜΑ =		524.490212

			Η.Δ. =		576.939233
409	409				
211		50.000000 x	.820200 =		41.010000
112		4.000000 x	18.705943 =		74.823772
117		4.000000 x	18.233796 =		72.935184
116		8.000000 x	23.989407 =		191.915256
324		1.000000 x	175.840000 =		175.840000
213		5.000000 x	3.800000 =		19.000000

			ΑΘΡΟΙΣΜΑ =		575.524212

			Η.Δ. =		633.076633

410	410				
211		100.000000 x	.820200 =	82.020000	
117		4.000000 x	18.233796 =	72.935184	
116		8.000000 x	23.989407 =	191.915256	
112		4.000000 x	18.705943 =	74.823772	
321		1.000000 x	202.570000 =	202.570000	
213		10.000000 x	3.800000 =	38.000000	

			ΑΘΡΟΙΣΜΑ =	662.264212	

			Η.Δ. =	728.490633	
411	411				
211		200.000000 x	.820200 =	164.040000	
117		4.000000 x	18.233796 =	72.935184	
116		8.000000 x	23.989407 =	191.915256	
112		4.000000 x	18.705943 =	74.823772	
213		20.000000 x	3.800000 =	76.000000	
325		1.000000 x	301.180000 =	301.180000	

			ΑΘΡΟΙΣΜΑ =	880.894212	

			Η.Δ. =	968.983633	
412	412				
211		40.000000 x	.820200 =	32.808000	
116		8.000000 x	23.989407 =	191.915256	
326		1.000000 x	100.090000 =	100.090000	
213		2.000000 x	3.800000 =	7.600000	

			ΑΘΡΟΙΣΜΑ =	332.413256	

			Η.Δ. =	365.654582	
413	413				
211		15.000000 x	.820200 =	12.303000	
213		1.500000 x	3.800000 =	5.700000	
118		3.000000 x	19.931416 =	59.794248	
112		3.000000 x	18.705943 =	56.117829	
327		1.000000 x	4.300000 =	4.300000	

			ΑΘΡΟΙΣΜΑ =	138.215077	

			Η.Δ. =	152.036585	
501	501				
211		170.000000 x	.820200 =	139.434000	
351		1.000000 x	428.920000 =	428.920000	
380		1.000000 x	541.750000 =	541.750000	
213		3.000000 x	3.800000 =	11.400000	

			ΑΘΡΟΙΣΜΑ =	1,121.504000	

			Η.Δ. =	1,233.654400	

502	502				
211		170.000000 x	.820200 =		139.434000
381		1.000000 x	541.750000 =		541.750000
352		1.000000 x	364.160000 =		364.160000
213		3.000000 x	3.800000 =		11.400000

			ΑΘΡΟΙΣΜΑ =		1,056.744000

			Η.Δ. =		1,162.418400
503	503				
211		170.000000 x	.820200 =		139.434000
213		3.000000 x	3.800000 =		11.400000
353		1.000000 x	428.920000 =		428.920000
382		1.000000 x	541.750000 =		541.750000

			ΑΘΡΟΙΣΜΑ =		1,121.504000

			Η.Δ. =		1,233.654400
504	504				
211		190.000000 x	.820200 =		155.838000
213		6.000000 x	3.800000 =		22.800000
383		1.000000 x	623.070000 =		623.070000
354		1.000000 x	562.720000 =		562.720000

			ΑΘΡΟΙΣΜΑ =		1,364.428000

			Η.Δ. =		1,500.870800
505	505				
211		1,250.000000 x	.820200 =		1,025.250000
213		7.500000 x	3.800000 =		28.500000
384		1.000000 x	1,031.980000 =		1,031.980000
355		1.000000 x	281.440000 =		281.440000

			ΑΘΡΟΙΣΜΑ =		2,367.170000

			Η.Δ. =		2,603.887000
506	506				
211		200.000000 x	.820200 =		164.040000
385		1.000000 x	187.500000 =		187.500000
356		1.000000 x	46.180000 =		46.180000
213		2.000000 x	3.800000 =		7.600000

			ΑΘΡΟΙΣΜΑ =		405.320000

			Η.Δ. =		445.852000
507	507				
211		2,100.000000 x	.820200 =		1,722.420000
213		35.000000 x	3.800000 =		133.000000
386		1.000000 x	494.740000 =		494.740000
357		1.000000 x	221.290000 =		221.290000

			ΑΘΡΟΙΣΜΑ =		2,571.450000

			Η.Δ. =		2,777.166000

508	508				
358		1.000000 x	44.550000 =	44.550000	
387		1.000000 x	71.380000 =	71.380000	

			ΑΘΡΟΙΣΜΑ =	115.930000	

			Η.Δ. =	121.726500	
509	509				
359		1.000000 x	92.370000 =	92.370000	
388		1.000000 x	71.380000 =	71.380000	

			ΑΘΡΟΙΣΜΑ =	163.750000	

			Η.Δ. =	171.937500	
510	510				
360		1.000000 x	97.280000 =	97.280000	
389		1.000000 x	71.380000 =	71.380000	

			ΑΘΡΟΙΣΜΑ =	168.660000	

			Η.Δ. =	177.093000	
511	511				
509		.800000 x	171.937500 =	137.550000	

			Η.Δ. =	137.550000	
512	512				
501		.600000 x	1,233.654400 =	740.192640	

			Η.Δ. =	740.192640	
513	513				
363		1.000000 x	97.420000 =	97.420000	
121		8.000000 x	17.389061 =	139.112488	
122		8.000000 x	18.298985 =	146.391880	
123		8.000000 x	62.435711 =	499.485688	

			Η.Δ. =	882.410056	
1111A	1111A				
214		.200000 x	1.840000 =	.368000	
511		.020000 x	137.550000 =	2.751000	
405		.020000 x	624.348824 =	12.486976	
513		.020000 x	882.410056 =	17.648201	

			Β.Τ =	33.254178	

1111B	1111B			
501		1.000000 x	1,233.654400 =	1,233.654400
506		1.000000 x	445.852000 =	445.852000
509		2.000000 x	171.937500 =	343.875000

			ΑΘΡΟΙΣΜΑ =	2,023.381400
	B.T =	.002500 x	2,023.381400 =	5.058454

1112A	1112A			
506		1.000000 x	445.852000 =	445.852000
512		1.000000 x	740.192640 =	740.192640

			ΑΘΡΟΙΣΜΑ =	1,186.044640
	B.T =	.025000 x	1,186.044640 =	29.651116

1112B	1112B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
1113A	1113A			
214		.200000 x	1.840000 =	.368000
112		.250000 x	18.705943 =	4.676486
511		.035000 x	137.550000 =	4.814250
513		.035000 x	882.410056 =	30.884352
405		.025000 x	624.348824 =	15.608721

			B.T =	56.351808
1113B	1113B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
1114A	1114A			
112		.250000 x	18.705943 =	4.676486
506		.033000 x	445.852000 =	14.713116
512		.033000 x	740.192640 =	24.426357

			B.T =	43.815959
1114B	1114B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454

1121A	1121A			
214		.150000 x	1.840000 =	.276000
115		.500000 x	24.152261 =	12.076131
405		.020000 x	624.348824 =	12.486976

			B.T =	24.839107
1121B	1121B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
1122A	1122A			
506		1.000000 x	445.852000 =	445.852000
512		1.000000 x	740.192640 =	740.192640

			AΘΡΟΙΣΜΑ =	1,186.044640
	B.T =	.012500 x	1,186.044640 =	14.825558

1122B	1122B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
1123A	1123A			
214		.150000 x	1.840000 =	.276000
112		.150000 x	18.705943 =	2.805891
405		.025000 x	624.348824 =	15.608721
115		1.000000 x	24.152261 =	24.152261

			B.T =	42.842873
1123B	1123B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
1124A	1124A			
112		.150000 x	18.705943 =	2.805891
506		.020000 x	445.852000 =	8.917040
512		.020000 x	740.192640 =	14.803853

			B.T =	26.526784
1124B	1124B			
1111B		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454

3110A 1	3110A 1			
221		250.000000 x	.097700 =	24.425000
607		.500000 x	10.161695 =	5.080848
701 2		.500000 x	4.737706 =	2.368853
701 5		.250000 x	2.961066 =	.740267
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
606		.800000 x	9.277435 =	7.421948
113		1.200000 x	24.769248 =	29.723098
714		1.400000 x	8.082127 =	11.314978
407		.040000 x	755.274249 =	30.210970
319		.020000 x	20.960000 =	.419200
112		1.200000 x	18.705943 =	22.447132

B.T = 138.702640

3110A 2	3110A 2			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
714		1.400000 x	8.082127 =	11.314978
113		1.200000 x	24.769248 =	29.723098
112		1.200000 x	18.705943 =	22.447132
319		.020000 x	20.960000 =	.419200

B.T = 146.786459

3110A 3	3110A 3			
221		250.000000 x	.097700 =	24.425000
112		1.200000 x	18.705943 =	22.447132
113		1.200000 x	24.769248 =	29.723098
714		1.400000 x	8.082127 =	11.314978
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.040000 x	755.274249 =	30.210970
319		.020000 x	20.960000 =	.419200

B.T = 149.267486

3110A 4	3110A 4			
221		250.000000 x	.097700 =	24.425000
113		1.200000 x	24.769248 =	29.723098
630		.250000 x	3.040732 =	.760183
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 4		.500000 x	4.441599 =	2.220800
611		.500000 x	26.625441 =	13.312721
610		.800000 x	22.779600 =	18.223680
407		.040000 x	755.274249 =	30.210970
112		1.200000 x	18.705943 =	22.447132
714		1.400000 x	8.082127 =	11.314978
319		.020000 x	20.960000 =	.419200
			B.T =	157.351306
3110B	3110B			
713 1		1.000000 x	5.310748 =	5.310748
704		1.000000 x	10.621496 =	10.621496
			B.T =	15.932244
3120A 1	3120A 1			
3110A 1		1.000000 x	138.702640 =	138.702640
			B.T =	138.702640
3120A 2	3120A 2			
3110A 2		1.000000 x	146.786459 =	146.786459
			B.T =	146.786459
3120A 3	3120A 3			
3110A 3		1.000000 x	149.267486 =	149.267486
			B.T =	149.267486
3120A 4	3120A 4			
3110A 4		1.000000 x	157.351306 =	157.351306
			B.T =	157.351306
3120B	3120B			
713 2		1.000000 x	5.790753 =	5.790753
705		1.000000 x	11.581506 =	11.581506
			B.T =	17.372259

3210A 1	3210A 1			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275
3110A 1		.800000 x	138.702640 =	110.962112

			B.T =	127.288348
3210A 2	3210A 2			
111		.400000 x	16.829739 =	6.731896
3110A 2		.800000 x	146.786459 =	117.429167
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275

			B.T =	133.755404
3210A 3	3210A 3			
111		.400000 x	16.829739 =	6.731896
3110A 3		.800000 x	149.267486 =	119.413989
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275

			B.T =	135.740225
3210A 4	3210A 4			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275
3110A 4		.800000 x	157.351306 =	125.881045

			B.T =	142.207281
3210A 5	3210A 5			
111		.400000 x	16.829739 =	6.731896
3110A 1		.800000 x	138.702640 =	110.962112
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996

			B.T =	126.122070
3210A 6	3210A 6			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
3110A 2		.800000 x	146.786459 =	117.429167

			B.T =	132.589125

3210A 7	3210A 7			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
3110A 3		.800000 x	149.267486 =	119.413989
			B.T =	134.573946
3210A 8	3210A 8			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
3110A 4		.800000 x	157.351306 =	125.881045
			B.T =	141.041002
3210B	3210B			
713 1		1.000000 x	5.310748 =	5.310748
704		1.000000 x	10.621496 =	10.621496
			B.T =	15.932244
3220A 1	3220A 1			
3210A 1		1.000000 x	127.288348 =	127.288348
			B.T =	127.288348
3220A 2	3220A 2			
3210A 2		1.000000 x	133.755404 =	133.755404
			B.T =	133.755404
3220A 3	3220A 3			
3210A 3		1.000000 x	135.740225 =	135.740225
			B.T =	135.740225
3220A 4	3220A 4			
3210A 4		1.000000 x	142.207281 =	142.207281
			B.T =	142.207281
3220A 5	3220A 5			
3210A 5		1.000000 x	126.122070 =	126.122070
			B.T =	126.122070

3220A 6	3220A 6			
3210A 6		1.000000 x	132.589125 =	132.589125

			B.T =	132.589125
3220A 7	3220A 7			
3210A 7		1.000000 x	134.573946 =	134.573946

			B.T =	134.573946
3220A 8	3220A 8			
3210A 8		1.000000 x	141.041002 =	141.041002

			B.T =	141.041002
3220B	3220B			
713 2		1.000000 x	5.790753 =	5.790753
705		1.000000 x	11.581506 =	11.581506

			B.T =	17.372259
3300A 1	3300A 1			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.961066 =	.740267
701 2		.500000 x	4.737706 =	2.368853
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
607		.500000 x	10.161695 =	5.080848
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
714		2.600000 x	8.082127 =	21.013530
113		2.000000 x	24.769248 =	49.538496
111		2.700000 x	16.829739 =	45.440295
319		.040000 x	20.960000 =	.838400

			B.T =	196.513954
3300A 2	3300A 2			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
319		.040000 x	20.960000 =	.838400
113		2.000000 x	24.769248 =	49.538496
407		.040000 x	755.274249 =	30.210970
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
714		2.600000 x	8.082127 =	21.013530
111		2.700000 x	16.829739 =	45.440295

			B.T =	204.597774

3300A 3

3300A 3

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.961066 =	.740267
701	4	.800000 x	4.441599 =	3.553279
701	2	.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.040000 x	755.274249 =	30.210970
714		2.600000 x	8.082127 =	21.013530
319		.040000 x	20.960000 =	.838400
113		2.000000 x	24.769248 =	49.538496
111		2.700000 x	16.829739 =	45.440295

B.T =

207.078801

3300A 4

3300A 4

221		300.000000 x	.097700 =	29.310000
113		2.000000 x	24.769248 =	49.538496
714		2.600000 x	8.082127 =	21.013530
111		2.700000 x	16.829739 =	45.440295
701	5	.250000 x	2.961066 =	.740267
701	4	.800000 x	4.441599 =	3.553279
701	4	.500000 x	4.441599 =	2.220800
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
610		.800000 x	22.779600 =	18.223680
407		.040000 x	755.274249 =	30.210970
319		.040000 x	20.960000 =	.838400

B.T =

215.162620

3300B 1

3300B 1

713	1	1.000000 x	5.310748 =	5.310748
704		1.000000 x	10.621496 =	10.621496

B.T =

15.932244

3300B 2

3300B 2

713	2	1.000000 x	5.790753 =	5.790753
705		1.000000 x	11.581506 =	11.581506

B.T =

17.372259

3400A 1	3400A 1			
221		300.000000 x	.097700 =	29.310000
255		5.000000 x	.696500 =	3.482500
701 5		.250000 x	2.961066 =	.740267
701 2		.800000 x	4.737706 =	3.790165
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
607		.500000 x	10.161695 =	5.080848
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	20.960000 =	.628800

B.T = 209.863891

3400A 2	3400A 2			
221		300.000000 x	.097700 =	29.310000
407		.040000 x	755.274249 =	30.210970
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	20.960000 =	.628800
255		5.000000 x	.696500 =	3.482500

B.T = 217.947711

3400A 3	3400A 3			
221		300.000000 x	.097700 =	29.310000
111		2.700000 x	16.829739 =	45.440295
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.040000 x	755.274249 =	30.210970
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
319		.030000 x	20.960000 =	.628800
255		5.000000 x	.696500 =	3.482500

B.T = 220.428737

3400A 4	3400A 4			
221		300.000000 x	.097700 =	29.310000
407		.040000 x	755.274249 =	30.210970
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 4		.500000 x	4.441599 =	2.220800
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
610		.800000 x	22.779600 =	18.223680
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	20.960000 =	.628800
255		5.000000 x	.696500 =	3.482500

			B.T =	228.512557
3400B 1	3400B 1			
704		1.000000 x	10.621496 =	10.621496

			B.T =	10.621496
3400B 2	3400B 2			
705		1.000000 x	11.581506 =	11.581506

			B.T =	11.581506
4110A 1	4110A 1			
221		350.000000 x	.097700 =	34.195000
111		4.000000 x	16.829739 =	67.318956
701 5		.100000 x	2.961066 =	.296107
701 2		.800000 x	4.737706 =	3.790165
701 2		.500000 x	4.737706 =	2.368853
630		.100000 x	3.040732 =	.304073
607		.500000 x	10.161695 =	5.080848
606		.800000 x	9.277435 =	7.421948
407		.070000 x	755.274249 =	52.869197
113		1.500000 x	24.769248 =	37.153872

			B.T =	210.799019

4110A 2	4110A 2			
221		350.000000 x	.097700 =	34.195000
701 5		.100000 x	2.961066 =	.296107
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.100000 x	3.040732 =	.304073
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
407		.070000 x	755.274249 =	52.869197
113		1.500000 x	24.769248 =	37.153872
111		4.000000 x	16.829739 =	67.318956

B.T = 218.882838

4110A 3	4110A 3			
221		350.000000 x	.097700 =	34.195000
407		.070000 x	755.274249 =	52.869197
701 5		.100000 x	2.961066 =	.296107
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
630		.100000 x	3.040732 =	.304073
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
113		1.500000 x	24.769248 =	37.153872
111		4.000000 x	16.829739 =	67.318956

B.T = 221.363865

4110A 4	4110A 4			
221		350.000000 x	.097700 =	34.195000
407		.070000 x	755.274249 =	52.869197
610		.800000 x	22.779600 =	18.223680
701 5		.100000 x	2.961066 =	.296107
701 4		.800000 x	4.441599 =	3.553279
701 4		.500000 x	4.441599 =	2.220800
630		.100000 x	3.040732 =	.304073
611		.500000 x	26.625441 =	13.312721
113		1.500000 x	24.769248 =	37.153872
111		4.000000 x	16.829739 =	67.318956

B.T = 229.447684

4110B	4110B			
112		8.000000 x	18.705943 =	149.647544
508		1.000000 x	121.726500 =	121.726500
513		1.000000 x	882.410056 =	882.410056
506		1.000000 x	445.852000 =	445.852000

B.T = 1,599.636100

4120A 1	4120A 1			
221		350.000000 x	.097700 =	34.195000
701 2		1.200000 x	4.737706 =	5.685247
607		1.200000 x	10.161695 =	12.194034
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	18.705943 =	93.529715

			B.T =	168.283996
4120A 2	4120A 2			
221		350.000000 x	.097700 =	34.195000
701 4		1.200000 x	4.441599 =	5.329919
611		1.200000 x	26.625441 =	31.950529
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	18.705943 =	93.529715

			B.T =	187.685163
4120B	4120B			
4110B		.040000 x	1,599.636100 =	63.985444

			B.T =	63.985444
4130A 1	4130A 1			
221		350.000000 x	.097700 =	34.195000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	755.274249 =	37.763712
606		.800000 x	9.277435 =	7.421948
607		.500000 x	10.161695 =	5.080848
701 2		.500000 x	4.737706 =	2.368853
701 2		.800000 x	4.737706 =	3.790165
111		2.000000 x	16.829739 =	33.659478

			B.T =	146.960004
4130A 2	4130A 2			
221		350.000000 x	.097700 =	34.195000
407		.050000 x	755.274249 =	37.763712
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

			B.T =	155.043823

4130A 3	4130A 3			
221		350.000000 x	.097700 =	34.195000
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.050000 x	755.274249 =	37.763712
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

			B.T =	157.524850
4130A 4	4130A 4			
221		350.000000 x	.097700 =	34.195000
701 4		.500000 x	4.441599 =	2.220800
701 4		.800000 x	4.441599 =	3.553279
611		.500000 x	26.625441 =	13.312721
610		.800000 x	22.779600 =	18.223680
407		.050000 x	755.274249 =	37.763712
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

			B.T =	165.608670
4130B	4130B			
4120B		1.000000 x	63.985444 =	63.985444

			B.T =	63.985444
4210A 1	4210A 1			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.961066 =	.444160
601		1.050000 x	25.244609 =	26.506839
630		.150000 x	3.040732 =	.456110
701 2		1.050000 x	4.737706 =	4.974591
701 2		.300000 x	4.737706 =	1.421312
607		.300000 x	10.161695 =	3.048509
222		10.000000 x	.070000 =	.700000

			B.T =	43.902021
4210A 2	4210A 2			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.961066 =	.444160
701 4		.300000 x	4.441599 =	1.332480
701 2		1.050000 x	4.737706 =	4.974591
630		.150000 x	3.040732 =	.456110
611		.300000 x	26.625441 =	7.987632
601		1.050000 x	25.244609 =	26.506839
222		10.000000 x	.070000 =	.700000

			B.T =	48.752312

4210A 3	4210A 3			
221		65.000000 x	.097700 =	6.350500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.161695 =	3.048509
630		.150000 x	3.040732 =	.456110
701 5		.150000 x	2.961066 =	.444160
701 2		.300000 x	4.737706 =	1.421312
701 2		1.050000 x	4.737706 =	4.974591
609		1.050000 x	21.599988 =	22.679987

B.T = 40.075169

4210A 4	4210A 4			
221		65.000000 x	.097700 =	6.350500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.737706 =	4.974591
701 5		.150000 x	2.961066 =	.444160
701 4		.300000 x	4.441599 =	1.332480
609		1.050000 x	21.599988 =	22.679987
630		.150000 x	3.040732 =	.456110
611		.300000 x	26.625441 =	7.987632

B.T = 44.925460

4210B	4210B			
111		4.000000 x	16.829739 =	67.318956
113		2.500000 x	24.769248 =	61.923120
112		.200000 x	18.705943 =	3.741189
112		1.500000 x	18.705943 =	28.058915

B.T = 161.042179

4220A 1	4220A 1			
221		200.000000 x	.097700 =	19.540000
111		1.200000 x	16.829739 =	20.195687
113		1.000000 x	24.769248 =	24.769248
407		.040000 x	755.274249 =	30.210970
606		.800000 x	9.277435 =	7.421948
607		.500000 x	10.161695 =	5.080848
630		.250000 x	3.040732 =	.760183
701 5		.250000 x	2.961066 =	.740267
701 2		.800000 x	4.737706 =	3.790165
701 2		.500000 x	4.737706 =	2.368853

B.T = 114.878168

4220A 2	4220A 2			
221		200.000000 x	.097700 =	19.540000
113		1.000000 x	24.769248 =	24.769248
606		.800000 x	9.277435 =	7.421948
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
407		.040000 x	755.274249 =	30.210970
111		1.200000 x	16.829739 =	20.195687

B.T = 122.961987

4220A 3	4220A 3			
221		200.000000 x	.097700 =	19.540000
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.040000 x	755.274249 =	30.210970
113		1.000000 x	24.769248 =	24.769248
111		1.200000 x	16.829739 =	20.195687
701 5		.250000 x	2.961066 =	.740267

B.T = 125.443014

4220A 4	4220A 4			
221		200.000000 x	.097700 =	19.540000
111		1.200000 x	16.829739 =	20.195687
407		.040000 x	755.274249 =	30.210970
611		.500000 x	26.625441 =	13.312721
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 4		.800000 x	4.441599 =	3.553279
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
113		1.000000 x	24.769248 =	24.769248

B.T = 133.526833

4300A 1	4300A 1			
221		350.000000 x	.097700 =	34.195000
111		2.000000 x	16.829739 =	33.659478
113		1.200000 x	24.769248 =	29.723098
701 5		.250000 x	2.961066 =	.740267
701 2		.800000 x	4.737706 =	3.790165
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
607		.500000 x	10.161695 =	5.080848
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
714		1.150000 x	8.082127 =	9.294446

			ΑΘΡΟΙΣΜΑ =	157.245254
	B.T =	.200000 x	157.245254 =	31.449051

4300A 2	4300A 2			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
714		1.150000 x	8.082127 =	9.294446
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	165.329074
	B.T =	.200000 x	165.329074 =	33.065815

4300A 3	4300A 3			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 2		.500000 x	4.737706 =	2.368853
630		.250000 x	3.040732 =	.760183
610		.800000 x	22.779600 =	18.223680
607		.500000 x	10.161695 =	5.080848
407		.040000 x	755.274249 =	30.210970
714		1.150000 x	8.082127 =	9.294446
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	167.810101
	B.T =	.200000 x	167.810101 =	33.562020

4300A 4	4300A 4			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.961066 =	.740267
701 4		.800000 x	4.441599 =	3.553279
701 4		.500000 x	4.441599 =	2.220800
714		1.150000 x	8.082127 =	9.294446
113		1.200000 x	24.769248 =	29.723098
610		.800000 x	22.779600 =	18.223680
630		.250000 x	3.040732 =	.760183
611		.500000 x	26.625441 =	13.312721
407		.040000 x	755.274249 =	30.210970
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	175.893920
	B.T =	.200000 x	175.893920 =	35.178784

4300B	4300B			
221		2.000000 x	.097700 =	.195400
112		.400000 x	18.705943 =	7.482377
262		4.000000 x	.980000 =	3.920000

			B.T =	11.597777
601	601			
111		1.500000 x	16.829739 =	25.244609

			B.T =	25.244609
602	602			
403		.002500 x	702.780786 =	1.756952

			B.T =	1.756952
603	603			
111		.300000 x	16.829739 =	5.048922
412		.003300 x	365.654582 =	1.206660
401		.001000 x	898.790684 =	.898791

			B.T =	7.154373
604	604			
111		.200000 x	16.829739 =	3.365948
404		.005000 x	437.286410 =	2.186432
401		.001100 x	898.790684 =	.988670
412		.004000 x	365.654582 =	1.462618

			B.T =	8.003668

605	605			
112		.100000 x	18.705943 =	1.870594
401		.001000 x	898.790684 =	.898791
402		.006200 x	894.381585 =	5.545166
412		.004000 x	365.654582 =	1.462618
406		.006200 x	400.144061 =	2.480893

B.T = 12.258062

606	606			
111		.100000 x	16.829739 =	1.682974
401		.001000 x	898.790684 =	.898791
412		.005000 x	365.654582 =	1.828273
406		.006700 x	400.144061 =	2.680965
404		.005000 x	437.286410 =	2.186432

B.T = 9.277435

607	607			
111		.100000 x	16.829739 =	1.682974
412		.005000 x	365.654582 =	1.828273
401		.001400 x	898.790684 =	1.258307
406		.006700 x	400.144061 =	2.680965
404		.006200 x	437.286410 =	2.711176

B.T = 10.161695

608	608			
111		.100000 x	16.829739 =	1.682974
412		.005000 x	365.654582 =	1.828273
406		.006700 x	400.144061 =	2.680965
404		.012500 x	437.286410 =	5.466080
401		.002000 x	898.790684 =	1.797581

B.T = 13.455874

609	609			
214		.100000 x	1.840000 =	.184000
405		.005000 x	624.348824 =	3.121744
115		.200000 x	24.152261 =	4.830452
111		.800000 x	16.829739 =	13.463791

B.T = 21.599988

610	610				
214		.100000 x	1.840000 =	.184000	
412		.005000 x	365.654582 =	1.828273	
406		.005000 x	400.144061 =	2.000720	
405		.005000 x	624.348824 =	3.121744	
402		.010000 x	894.381585 =	8.943816	
112		.100000 x	18.705943 =	1.870594	
115		.200000 x	24.152261 =	4.830452	
			B.T =	22.779600	
611	611				
214		.100000 x	1.840000 =	.184000	
112		.100000 x	18.705943 =	1.870594	
405		.005000 x	624.348824 =	3.121744	
412		.005000 x	365.654582 =	1.828273	
406		.005000 x	400.144061 =	2.000720	
402		.014300 x	894.381585 =	12.789657	
115		.200000 x	24.152261 =	4.830452	
			B.T =	26.625441	
612	612				
214		.150000 x	1.840000 =	.276000	
408		.010000 x	576.939233 =	5.769392	
405		.005000 x	624.348824 =	3.121744	
115		.200000 x	24.152261 =	4.830452	
111		.300000 x	16.829739 =	5.048922	
			AΘΡΟΙΣΜΑ =	19.046510	
	B.T =	1.068000 x	19.046510 =	20.341673	
613	613				
214		.150000 x	1.840000 =	.276000	
409		.010000 x	633.076633 =	6.330766	
405		.005000 x	624.348824 =	3.121744	
115		.200000 x	24.152261 =	4.830452	
111		.500000 x	16.829739 =	8.414870	
			AΘΡΟΙΣΜΑ =	22.973832	
	B.T =	1.282000 x	22.973832 =	29.452453	
614	614				
214		.150000 x	1.840000 =	.276000	
111		.500000 x	16.829739 =	8.414870	
115		.200000 x	24.152261 =	4.830452	
410		.010000 x	728.490633 =	7.284906	
405		.005000 x	624.348824 =	3.121744	
			AΘΡΟΙΣΜΑ =	23.927972	
	B.T =	1.602000 x	23.927972 =	38.332611	

615	615				
214		.150000 x	1.840000 =	.276000	
410		.010000 x	728.490633 =	7.284906	
111		.700000 x	16.829739 =	11.780817	
405		.005000 x	624.348824 =	3.121744	
115		.200000 x	24.152261 =	4.830452	
			AΘΡΟΙΣΜΑ =	27.293920	
	B.T =	1.832000 x	27.293920 =	50.002461	
616	616				
214		.150000 x	1.840000 =	.276000	
111		.800000 x	16.829739 =	13.463791	
405		.005000 x	624.348824 =	3.121744	
411		.010000 x	968.983633 =	9.689836	
115		.200000 x	24.152261 =	4.830452	
			AΘΡΟΙΣΜΑ =	31.381824	
	B.T =	2.137000 x	31.381824 =	67.062958	
617	617				
112		4.000000 x	18.705943 =	74.823772	
513		1.000000 x	882.410056 =	882.410056	
506		1.000000 x	445.852000 =	445.852000	
503		1.000000 x	1,233.654400 =	1,233.654400	
			AΘΡΟΙΣΜΑ =	2,636.740228	
	B.T =	.006250 x	2,636.740228 =	16.479626	
618	618				
112		4.000000 x	18.705943 =	74.823772	
513		1.000000 x	882.410056 =	882.410056	
506		1.000000 x	445.852000 =	445.852000	
503		1.000000 x	1,233.654400 =	1,233.654400	
			AΘΡΟΙΣΜΑ =	2,636.740228	
	B.T =	.007700 x	2,636.740228 =	20.302900	
619	619				
112		4.000000 x	18.705943 =	74.823772	
503		1.000000 x	1,233.654400 =	1,233.654400	
506		1.000000 x	445.852000 =	445.852000	
513		1.000000 x	882.410056 =	882.410056	
			AΘΡΟΙΣΜΑ =	2,636.740228	
	B.T =	.010000 x	2,636.740228 =	26.367402	

620	620			
112		4.000000 x	18.705943 =	74.823772
513		1.000000 x	882.410056 =	882.410056
506		1.000000 x	445.852000 =	445.852000
503		1.000000 x	1,233.654400 =	1,233.654400

			ΑΘΡΟΙΣΜΑ =	2,636.740228
	B.T =	.012500 x	2,636.740228 =	32.959253

621	621			
112		4.000000 x	18.705943 =	74.823772
506		1.000000 x	445.852000 =	445.852000
503		1.000000 x	1,233.654400 =	1,233.654400
513		1.000000 x	882.410056 =	882.410056

			ΑΘΡΟΙΣΜΑ =	2,636.740228
	B.T =	.016600 x	2,636.740228 =	43.769888

630	630			
413		.020000 x	152.036585 =	3.040732

			B.T =	3.040732
701 1	701 1			
406		.012580 x	400.144061 =	5.033812

			B.T =	5.033812
701 2	701 2			
406		.011840 x	400.144061 =	4.737706

			B.T =	4.737706
701 3	701 3			
406		.011544 x	400.144061 =	4.619263

			B.T =	4.619263
701 4	701 4			
406		.011100 x	400.144061 =	4.441599

			B.T =	4.441599
701 5	701 5			
406		.007400 x	400.144061 =	2.961066

			B.T =	2.961066

702	702			
112		8.000000 x	18.705943 =	149.647544
506		1.000000 x	445.852000 =	445.852000
513		.300000 x	882.410056 =	264.723017
509		2.000000 x	171.937500 =	343.875000

			ΑΘΡΟΙΣΜΑ =	1,204.097561
	B.T =	.002500 x	1,204.097561 =	3.010244

703	703			
112		4.000000 x	18.705943 =	74.823772
513		.300000 x	882.410056 =	264.723017
503		1.000000 x	1,233.654400 =	1,233.654400
510		2.000000 x	177.093000 =	354.186000
506		1.000000 x	445.852000 =	445.852000

			ΑΘΡΟΙΣΜΑ =	2,373.239189
	B.T =	.002500 x	2,373.239189 =	5.933098

704	704			
112		4.000000 x	18.705943 =	74.823772
513		.500000 x	882.410056 =	441.205028
506		1.000000 x	445.852000 =	445.852000
502		1.000000 x	1,162.418400 =	1,162.418400

			ΑΘΡΟΙΣΜΑ =	2,124.299200
	B.T =	.005000 x	2,124.299200 =	10.621496

705	705			
112		4.000000 x	18.705943 =	74.823772
513		.600000 x	882.410056 =	529.446034
506		1.000000 x	445.852000 =	445.852000
504		1.000000 x	1,500.870800 =	1,500.870800

			ΑΘΡΟΙΣΜΑ =	2,550.992606
	B.T =	.004540 x	2,550.992606 =	11.581506

706	706			
501		1.000000 x	1,233.654400 =	1,233.654400
509		2.000000 x	171.937500 =	343.875000
506		1.000000 x	445.852000 =	445.852000

			ΑΘΡΟΙΣΜΑ =	2,023.381400
	B.T =	.002500 x	2,023.381400 =	5.058454

707	707			
505		1.000000 x	2,603.887000 =	2,603.887000
510		2.000000 x	177.093000 =	354.186000
506		1.000000 x	445.852000 =	445.852000

			ΑΘΡΟΙΣΜΑ =	3,403.925000
	B.T =	.001000 x	3,403.925000 =	3.403925

708	708				
708A		1.000000 x	18.095961 =		18.095961
708B		1.000000 x	5.058454 =		5.058454

			B.T =		23.154415
708A	708A				
214		.050000 x	1.840000 =		.092000
513		.010000 x	882.410056 =		8.824101
511		.010000 x	137.550000 =		1.375500
405		.012500 x	624.348824 =		7.804360

			B.T =		18.095961
708B	708B				
706		1.000000 x	5.058454 =		5.058454

			B.T =		5.058454
709	709				
709A		1.000000 x	14.825558 =		14.825558
709B		1.000000 x	5.058454 =		5.058454

			B.T =		19.884012
709A	709A				
506		1.000000 x	445.852000 =		445.852000
512		1.000000 x	740.192640 =		740.192640

			AΘΡΟΙΣΜΑ =		1,186.044640
	B.T =	.012500 x	1,186.044640 =		14.825558

709B	709B				
706		1.000000 x	5.058454 =		5.058454

			B.T =		5.058454
710	710				
710A		1.000000 x	51.675323 =		51.675323
710B		1.000000 x	5.058454 =		5.058454

			B.T =		56.733777
710A	710A				
214		.200000 x	1.840000 =		.368000
405		.025000 x	624.348824 =		15.608721
513		.035000 x	882.410056 =		30.884352
511		.035000 x	137.550000 =		4.814250

			B.T =		51.675323

710B	710B			
706		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
711	711			
711A		1.000000 x	39.495287 =	39.495287
711B		1.000000 x	5.058454 =	5.058454

			B.T =	44.553741
711A	711A			
506		1.000000 x	445.852000 =	445.852000
512		1.000000 x	740.192640 =	740.192640

			AΘΡΟΙΣΜΑ =	1,186.044640
	B.T =	.033300 x	1,186.044640 =	39.495287

711B	711B			
706		1.000000 x	5.058454 =	5.058454

			B.T =	5.058454
712	712			
513		1.000000 x	882.410056 =	882.410056

			AΘΡΟΙΣΜΑ =	882.410056
	B.T =	.004000 x	882.410056 =	3.529640

713 1	713 1			
704		.500000 x	10.621496 =	5.310748

			B.T =	5.310748
713 2	713 2			
705		.500000 x	11.581506 =	5.790753

			B.T =	5.790753
714	714			
714A		1.000000 x	3.734608 =	3.734608
714B		1.000000 x	4.347519 =	4.347519

			B.T =	8.082127

714A	714A			
242		.070000 x	335.000000 =	23.450000
114		2.000000 x	18.705943 =	37.411886
252		1.000000 x	1.750000 =	1.750000
113		2.000000 x	24.769248 =	49.538496

			AΘΡΟΙΣΜΑ =	112.150382
	B.T =	.033300 x	112.150382 =	3.734608

714B	714B			
113		.100000 x	24.769248 =	2.476925
114		.100000 x	18.705943 =	1.870594

			B.T =	4.347519
1111	1111			
1111A		1.000000 x	33.254178 =	33.254178
1111B		1.000000 x	5.058454 =	5.058454

			T.E =	38.312632
1112	1112			
1112A		1.000000 x	29.651116 =	29.651116
1112B		1.000000 x	5.058454 =	5.058454

			T.E =	34.709570
1113	1113			
1113A		1.000000 x	56.351808 =	56.351808
1113B		1.000000 x	5.058454 =	5.058454

			T.E =	61.410262
1114	1114			
1114A		1.000000 x	43.815959 =	43.815959
1114B		1.000000 x	5.058454 =	5.058454

			T.E =	48.874413
1121	1121			
1121A		1.000000 x	24.839107 =	24.839107
1121B		1.000000 x	5.058454 =	5.058454

			T.E =	29.897561
1122	1122			
1122A		1.000000 x	14.825558 =	14.825558
1122B		1.000000 x	5.058454 =	5.058454

			T.E =	19.884012

1123	1123				
1123A		1.000000 x	42.842873 =		42.842873
1123B		1.000000 x	5.058454 =		5.058454

			T.E =		47.901327
1124	1124				
1124A		1.000000 x	26.526784 =		26.526784
1124B		1.000000 x	5.058454 =		5.058454

			T.E =		31.585238
1210	1210				
707		1.000000 x	3.403925 =		3.403925

			T.E =		3.403925
1220	1220				
708		1.000000 x	23.154415 =		23.154415

			T.E =		23.154415
1230	1230				
709		1.000000 x	19.884012 =		19.884012

			T.E =		19.884012
1311	1311				
712		.250000 x	3.529640 =		.882410

			T.E =		.882410
1312	1312				
712		.250000 x	3.529640 =		.882410
701 1		1.000000 x	5.033812 =		5.033812
602		1.000000 x	1.756952 =		1.756952

			T.E =		7.673174
1313	1313				
712		.250000 x	3.529640 =		.882410
603		1.000000 x	7.154373 =		7.154373
701 2		1.000000 x	4.737706 =		4.737706

			T.E =		12.774489

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	16.829739 =	1.682974	
712		.250000 x	3.529640 =	.882410	

			T.E =	37.565384	
1321	1321				
112		.200000 x	18.705943 =	3.741189	
701	1	1.000000 x	5.033812 =	5.033812	
602		1.000000 x	1.756952 =	1.756952	

			T.E =	10.531953	
1322	1322				
112		.200000 x	18.705943 =	3.741189	
603		1.000000 x	7.154373 =	7.154373	
701	2	1.000000 x	4.737706 =	4.737706	

			T.E =	15.633268	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	16.829739 =	1.682974	
112		.100000 x	18.705943 =	1.870594	

			T.E =	38.553568	
2110	2110				
712		.500000 x	3.529640 =	1.764820	
702		1.000000 x	3.010244 =	3.010244	
608		1.000000 x	13.455874 =	13.455874	
701	4	1.000000 x	4.441599 =	4.441599	

			T.E =	22.672537	
2120	2120				
712		.500000 x	3.529640 =	1.764820	
702		1.000000 x	3.010244 =	3.010244	
701	2	1.000000 x	4.737706 =	4.737706	
603		1.000000 x	7.154373 =	7.154373	

			T.E =	16.667143	
2130	2130				
712		.500000 x	3.529640 =	1.764820	
604		1.000000 x	8.003668 =	8.003668	
701	2	1.000000 x	4.737706 =	4.737706	
702		1.000000 x	3.010244 =	3.010244	

			T.E =	17.516438	

2140	2140				
712		.500000 x	3.529640 =	1.764820	
605		1.000000 x	12.258062 =	12.258062	
702		1.000000 x	3.010244 =	3.010244	
701	2	1.000000 x	4.737706 =	4.737706	

				T.E =	21.770832
2210	2210				
712		.500000 x	3.529640 =	1.764820	
609		1.050000 x	21.599988 =	22.679987	
702		1.000000 x	3.010244 =	3.010244	
701	2	1.000000 x	4.737706 =	4.737706	

				T.E =	32.192757
2220	2220				
712		.500000 x	3.529640 =	1.764820	
702		1.000000 x	3.010244 =	3.010244	
701	2	1.000000 x	4.737706 =	4.737706	
609		1.150000 x	21.599988 =	24.839986	

				T.E =	34.352756
2230	2230				
111		.200000 x	16.829739 =	3.365948	
609		1.200000 x	21.599988 =	25.919986	
701	2	1.000000 x	4.737706 =	4.737706	

				T.E =	34.023639
2240	2240				
111		.300000 x	16.829739 =	5.048922	
609		1.200000 x	21.599988 =	25.919986	
701	2	1.000000 x	4.737706 =	4.737706	

				T.E =	35.706613
2310	2310				
612		1.000000 x	20.341673 =	20.341673	
701	3	1.000000 x	4.619263 =	4.619263	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	30.894034
2320	2320				
613		1.000000 x	29.452453 =	29.452453	
703		1.000000 x	5.933098 =	5.933098	
701	3	1.000000 x	4.619263 =	4.619263	

				T.E =	40.004814

2330	2330				
614		1.000000 x	38.332611 =	38.332611	
703		1.000000 x	5.933098 =	5.933098	
701	3	1.000000 x	4.619263 =	4.619263	

				T.E =	48.884972
2340	2340				
615		1.000000 x	50.002461 =	50.002461	
703		1.000000 x	5.933098 =	5.933098	
701	3	1.000000 x	4.619263 =	4.619263	

				T.E =	60.554822
2350	2350				
616		1.000000 x	67.062958 =	67.062958	
701	3	1.000000 x	4.619263 =	4.619263	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	77.615319
2410	2410				
617		1.000000 x	16.479626 =	16.479626	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	22.412724
2420	2420				
618		1.000000 x	20.302900 =	20.302900	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	26.235998
2430	2430				
619		1.000000 x	26.367402 =	26.367402	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	32.300500
2440	2440				
620		1.000000 x	32.959253 =	32.959253	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	38.892351
2450	2450				
621		1.000000 x	43.769888 =	43.769888	
703		1.000000 x	5.933098 =	5.933098	

				T.E =	49.702986

3110	1	3110	1			
	3110A 1			1.000000 x	138.702640 =	138.702640
	3110B			1.000000 x	15.932244 =	15.932244

				T.E =		154.634884
3110	2	3110	2			
	3110A 2			1.000000 x	146.786459 =	146.786459
	3110B			1.000000 x	15.932244 =	15.932244

				T.E =		162.718703
3110	3	3110	3			
	3110A 3			1.000000 x	149.267486 =	149.267486
	3110B			1.000000 x	15.932244 =	15.932244

				T.E =		165.199730
3110	4	3110	4			
	3110A 4			1.000000 x	157.351306 =	157.351306
	3110B			1.000000 x	15.932244 =	15.932244

				T.E =		173.283550
3120	1	3120	1			
	3120A 1			1.000000 x	138.702640 =	138.702640
	3120B			1.000000 x	17.372259 =	17.372259

				T.E =		156.074899
3120	2	3120	2			
	3120A 2			1.000000 x	146.786459 =	146.786459
	3120B			1.000000 x	17.372259 =	17.372259

				T.E =		164.158718
3120	3	3120	3			
	3120A 3			1.000000 x	149.267486 =	149.267486
	3120B			1.000000 x	17.372259 =	17.372259

				T.E =		166.639745
3120	4	3120	4			
	3120A 4			1.000000 x	157.351306 =	157.351306
	3120B			1.000000 x	17.372259 =	17.372259

				T.E =		174.723565

3210 1	3210 1				
3210A 1		1.000000 x	127.288348 =		127.288348
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		143.220592
3210 2	3210 2				
3210A 2		1.000000 x	133.755404 =		133.755404
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		149.687648
3210 3	3210 3				
3210A 3		1.000000 x	135.740225 =		135.740225
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		151.672469
3210 4	3210 4				
3210A 4		1.000000 x	142.207281 =		142.207281
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		158.139525
3210 5	3210 5				
3210A 5		1.000000 x	126.122070 =		126.122070
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		142.054314
3210 6	3210 6				
3210A 6		1.000000 x	132.589125 =		132.589125
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		148.521369
3210 7	3210 7				
3210A 7		1.000000 x	134.573946 =		134.573946
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		150.506190
3210 8	3210 8				
3210A 8		1.000000 x	141.041002 =		141.041002
3210B		1.000000 x	15.932244 =		15.932244

			T.E =		156.973246

3220	1	3220	1			
	3220A	1		1.000000 x	127.288348 =	127.288348
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	144.660607
3220	2	3220	2			
	3220A	2		1.000000 x	133.755404 =	133.755404
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	151.127663
3220	3	3220	3			
	3220A	3		1.000000 x	135.740225 =	135.740225
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	153.112484
3220	4	3220	4			
	3220A	4		1.000000 x	142.207281 =	142.207281
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	159.579540
3220	5	3220	5			
	3220A	5		1.000000 x	126.122070 =	126.122070
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	143.494329
3220	6	3220	6			
	3220A	6		1.000000 x	132.589125 =	132.589125
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	149.961384
3220	7	3220	7			
	3220A	7		1.000000 x	134.573946 =	134.573946
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	151.946205
3220	8	3220	8			
	3220A	8		1.000000 x	141.041002 =	141.041002
	3220B			1.000000 x	17.372259 =	17.372259

					T.E =	158.413261

3300 1	3300 1				
3300A 1		1.000000 x	196.513954 =		196.513954
3300B 1		1.000000 x	15.932244 =		15.932244

			T.E =		212.446198
3300 2	3300 2				
3300A 1		1.000000 x	196.513954 =		196.513954
3300B 2		1.000000 x	17.372259 =		17.372259

			T.E =		213.886213
3300 3	3300 3				
3300A 2		1.000000 x	204.597774 =		204.597774
3300B 1		1.000000 x	15.932244 =		15.932244

			T.E =		220.530018
3300 4	3300 4				
3300A 2		1.000000 x	204.597774 =		204.597774
3300B 2		1.000000 x	17.372259 =		17.372259

			T.E =		221.970033
3300 5	3300 5				
3300A 3		1.000000 x	207.078801 =		207.078801
3300B 1		1.000000 x	15.932244 =		15.932244

			T.E =		223.011045
3300 6	3300 6				
3300A 3		1.000000 x	207.078801 =		207.078801
3300B 2		1.000000 x	17.372259 =		17.372259

			T.E =		224.451060
3300 7	3300 7				
3300A 4		1.000000 x	215.162620 =		215.162620
3300B 1		1.000000 x	15.932244 =		15.932244

			T.E =		231.094864
3300 8	3300 8				
3300A 4		1.000000 x	215.162620 =		215.162620
3300B 2		1.000000 x	17.372259 =		17.372259

			T.E =		232.534879

3400 1	3400 1				
3400A 1		1.000000 x	209.863891 =	209.863891	
3400B 1		1.000000 x	10.621496 =	10.621496	

			T.E =	220.485387	
3400 2	3400 2				
3400A 1		1.000000 x	209.863891 =	209.863891	
3400B 2		1.000000 x	11.581506 =	11.581506	

			T.E =	221.445397	
3400 3	3400 3				
3400A 2		1.000000 x	217.947711 =	217.947711	
3400B 1		1.000000 x	10.621496 =	10.621496	

			T.E =	228.569207	
3400 4	3400 4				
3400A 2		1.000000 x	217.947711 =	217.947711	
3400B 2		1.000000 x	11.581506 =	11.581506	

			T.E =	229.529217	
3400 5	3400 5				
3400A 3		1.000000 x	220.428737 =	220.428737	
3400B 1		1.000000 x	10.621496 =	10.621496	

			T.E =	231.050233	
3400 6	3400 6				
3400A 3		1.000000 x	220.428737 =	220.428737	
3400B 2		1.000000 x	11.581506 =	11.581506	

			T.E =	232.010243	
3400 7	3400 7				
3400A 4		1.000000 x	228.512557 =	228.512557	
3400B 1		1.000000 x	10.621496 =	10.621496	

			T.E =	239.134053	
3400 8	3400 8				
3400A 4		1.000000 x	228.512557 =	228.512557	
3400B 2		1.000000 x	11.581506 =	11.581506	

			T.E =	240.094063	

4110	1	4110	1				
	4110A	1		1.000000 x	210.799019 =		210.799019
	4110B			.025000 x	1,599.636100 =		39.990903

						T.E =	250.789922
4110	2	4110	2				
	4110A	2		1.000000 x	218.882838 =		218.882838
	4110B			.025000 x	1,599.636100 =		39.990903

						T.E =	258.873741
4110	3	4110	3				
	4110A	3		1.000000 x	221.363865 =		221.363865
	4110B			.025000 x	1,599.636100 =		39.990903

						T.E =	261.354768
4110	4	4110	4				
	4110A	4		1.000000 x	229.447684 =		229.447684
	4110B			.025000 x	1,599.636100 =		39.990903

						T.E =	269.438587
4120	1	4120	1				
	4120A	1		1.000000 x	168.283996 =		168.283996
	4120B			1.000000 x	63.985444 =		63.985444

						T.E =	232.269440
4120	2	4120	2				
	4120A	2		1.000000 x	187.685163 =		187.685163
	4120B			1.000000 x	63.985444 =		63.985444

						T.E =	251.670607
4130	1	4130	1				
	4130A	1		1.000000 x	146.960004 =		146.960004
	4130B			1.000000 x	63.985444 =		63.985444

						T.E =	210.945448
4130	2	4130	2				
	4130A	2		1.000000 x	155.043823 =		155.043823
	4130B			1.000000 x	63.985444 =		63.985444

						T.E =	219.029267

4130	3	4130	3			
4130A	3			1.000000 x	157.524850 =	157.524850
4130B				1.000000 x	63.985444 =	63.985444

T.E =						221.510294
4130	4	4130	4			
4130A	4			1.000000 x	165.608670 =	165.608670
4130B				1.000000 x	63.985444 =	63.985444

T.E =						229.594114
4210	1	4210	1			
4210A	1			1.000000 x	43.902021 =	43.902021
4210B				1.000000 x	161.042179 =	161.042179

T.E =						204.944200
4210	2	4210	2			
4210A	2			1.000000 x	48.752312 =	48.752312
4210B				1.000000 x	161.042179 =	161.042179

T.E =						209.794491
4210	3	4210	3			
4210A	3			1.000000 x	40.075169 =	40.075169
4210B				1.000000 x	161.042179 =	161.042179

T.E =						201.117348
4210	4	4210	4			
4210A	4			1.000000 x	44.925460 =	44.925460
4210B				1.000000 x	161.042179 =	161.042179

T.E =						205.967639
4220B	1	4220B	1			
319				.020000 x	20.960000 =	.419200
701	2			.320000 x	4.737706 =	1.516066
601				.320000 x	25.244609 =	8.078275
4220A	1			.800000 x	114.878168 =	91.902534
111				.400000 x	16.829739 =	6.731896
714				1.150000 x	8.082127 =	9.294446

T.E =						117.942417

4220B 2	4220B 2			
319		.020000 x	20.960000 =	.419200
4220A 2		.800000 x	122.961987 =	98.369590
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275
714		1.150000 x	8.082127 =	9.294446

T.E = 124.409472

4220B 3	4220B 3			
319		.020000 x	20.960000 =	.419200
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275
4220A 3		.800000 x	125.443014 =	100.354411
714		1.150000 x	8.082127 =	9.294446
111		.400000 x	16.829739 =	6.731896

T.E = 126.394294

4220B 4	4220B 4			
319		.020000 x	20.960000 =	.419200
111		.400000 x	16.829739 =	6.731896
4220A 4		.800000 x	133.526833 =	106.821466
701 2		.320000 x	4.737706 =	1.516066
601		.320000 x	25.244609 =	8.078275
714		1.150000 x	8.082127 =	9.294446

T.E = 132.861349

4220B 5	4220B 5			
319		.020000 x	20.960000 =	.419200
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
4220A 1		.800000 x	114.878168 =	91.902534
111		.400000 x	16.829739 =	6.731896
714		1.150000 x	8.082127 =	9.294446

T.E = 116.776138

4220B 6	4220B 6			
319		.020000 x	20.960000 =	.419200
4220A 2		.800000 x	122.961987 =	98.369590
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
714		1.150000 x	8.082127 =	9.294446

T.E = 123.243193

4220B 7	4220B 7			
319		.020000 x	20.960000 =	.419200
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
4220A 3		.800000 x	125.443014 =	100.354411
714		1.150000 x	8.082127 =	9.294446
111		.400000 x	16.829739 =	6.731896

T.E = 125.228015

4220B 8	4220B 8			
319		.020000 x	20.960000 =	.419200
701 2		.320000 x	4.737706 =	1.516066
609		.320000 x	21.599988 =	6.911996
4220A 4		.800000 x	133.526833 =	106.821466
714		1.150000 x	8.082127 =	9.294446
111		.400000 x	16.829739 =	6.731896

T.E = 131.695070

4230 1	4230 1			
221		250.000000 x	.097700 =	24.425000
111		2.000000 x	16.829739 =	33.659478
714		1.150000 x	8.082127 =	9.294446
701 5		.250000 x	2.961066 =	.740267
701 2		.500000 x	4.737706 =	2.368853
701 2		.800000 x	4.737706 =	3.790165
630		.250000 x	3.040732 =	.760183
607		.500000 x	10.161695 =	5.080848
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
113		1.200000 x	24.769248 =	29.723098
319		.020000 x	20.960000 =	.419200

T.E = 147.894454

4230 2	4230 2			
221		250.000000 x	.097700 =	24.425000
630		.250000 x	3.040732 =	.760183
701 5		.250000 x	2.961066 =	.740267
701 4		.500000 x	4.441599 =	2.220800
701 2		.800000 x	4.737706 =	3.790165
611		.500000 x	26.625441 =	13.312721
606		.800000 x	9.277435 =	7.421948
407		.040000 x	755.274249 =	30.210970
714		1.150000 x	8.082127 =	9.294446
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478
319		.020000 x	20.960000 =	.419200

T.E = 155.978274

4230	3	4230	3			
221				250.000000 x	.097700 =	24.425000
701	5			.250000 x	2.961066 =	.740267
701	4			.800000 x	4.441599 =	3.553279
701	2			.500000 x	4.737706 =	2.368853
630				.250000 x	3.040732 =	.760183
610				.800000 x	22.779600 =	18.223680
607				.500000 x	10.161695 =	5.080848
407				.040000 x	755.274249 =	30.210970
714				1.150000 x	8.082127 =	9.294446
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478
319				.020000 x	20.960000 =	.419200

T.E = 158.459301

4230	4	4230	4			
221				250.000000 x	.097700 =	24.425000
701	5			.250000 x	2.961066 =	.740267
701	4			.500000 x	4.441599 =	2.220800
701	4			.800000 x	4.441599 =	3.553279
630				.250000 x	3.040732 =	.760183
319				.020000 x	20.960000 =	.419200
111				2.000000 x	16.829739 =	33.659478
407				.040000 x	755.274249 =	30.210970
611				.500000 x	26.625441 =	13.312721
610				.800000 x	22.779600 =	18.223680
714				1.150000 x	8.082127 =	9.294446
113				1.200000 x	24.769248 =	29.723098

T.E = 166.543120

4240	1	4240	1			
221				300.000000 x	.097700 =	29.310000
701	5			.250000 x	2.961066 =	.740267
701	2			.500000 x	4.737706 =	2.368853
701	2			.800000 x	4.737706 =	3.790165
630				.250000 x	3.040732 =	.760183
607				.500000 x	10.161695 =	5.080848
606				.800000 x	9.277435 =	7.421948
407				.040000 x	755.274249 =	30.210970
714				1.150000 x	8.082127 =	9.294446
319				.020000 x	20.960000 =	.419200
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478

T.E = 152.779454

4240	2	4240	2			
221				300.000000 x	.097700 =	29.310000
701	5			.250000 x	2.961066 =	.740267
701	4			.500000 x	4.441599 =	2.220800
701	2			.800000 x	4.737706 =	3.790165
630				.250000 x	3.040732 =	.760183
319				.020000 x	20.960000 =	.419200
113				1.200000 x	24.769248 =	29.723098
407				.040000 x	755.274249 =	30.210970
611				.500000 x	26.625441 =	13.312721
606				.800000 x	9.277435 =	7.421948
714				1.150000 x	8.082127 =	9.294446
111				2.000000 x	16.829739 =	33.659478

					T.E =	160.863274
4240	3	4240	3			
221				300.000000 x	.097700 =	29.310000
701	5			.250000 x	2.961066 =	.740267
701	4			.800000 x	4.441599 =	3.553279
701	2			.500000 x	4.737706 =	2.368853
630				.250000 x	3.040732 =	.760183
610				.800000 x	22.779600 =	18.223680
607				.500000 x	10.161695 =	5.080848
407				.040000 x	755.274249 =	30.210970
714				1.150000 x	8.082127 =	9.294446
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478
319				.020000 x	20.960000 =	.419200

					T.E =	163.344301
4240	4	4240	4			
221				300.000000 x	.097700 =	29.310000
714				1.150000 x	8.082127 =	9.294446
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478
701	5			.250000 x	2.961066 =	.740267
701	4			.500000 x	4.441599 =	2.220800
701	4			.800000 x	4.441599 =	3.553279
630				.250000 x	3.040732 =	.760183
611				.500000 x	26.625441 =	13.312721
610				.800000 x	22.779600 =	18.223680
407				.040000 x	755.274249 =	30.210970
319				.020000 x	20.960000 =	.419200

					T.E =	171.428120
4300	1	4300	1			
4300A	1			1.000000 x	31.449051 =	31.449051
4300B				1.000000 x	11.597777 =	11.597777

					T.E =	43.046828

4300	2	4300	2			
	4300A	2		1.000000 x	33.065815 =	33.065815
	4300B			1.000000 x	11.597777 =	11.597777
<hr/>						
					T.E =	44.663592
4300	3	4300	3			
	4300A	3		1.000000 x	33.562020 =	33.562020
	4300B			1.000000 x	11.597777 =	11.597777
<hr/>						
					T.E =	45.159797
4300	4	4300	4			
	4300A	4		1.000000 x	35.178784 =	35.178784
	4300B			1.000000 x	11.597777 =	11.597777
<hr/>						
					T.E =	46.776561
4400		4400				
	251			1.050000 x	.511400 =	.536970
	113			.050000 x	24.769248 =	1.238462
<hr/>						
					T.E =	1.775432
4500		4500				
	251			1.050000 x	.511400 =	.536970
	114			.100000 x	18.705943 =	1.870594
	113			.100000 x	24.769248 =	2.476925
<hr/>						
					T.E =	4.884489
4600		4600				
	256			1.000000 x	3.500000 =	3.500000
	113			.100000 x	24.769248 =	2.476925
<hr/>						
					T.E =	5.976925
4700		4700				
	253			1.000000 x	3.700000 =	3.700000
	113			.100000 x	24.769248 =	2.476925
<hr/>						
					T.E =	6.176925