

. .& .

3

μ

μ

3

μ

2012

111	15.315315
112	16.843762
113	19.864197
114	16.843762
115	19.864197
116	23.150104
117	9.691373
118	21.107527
119	9.691373
120	16.261841
121	16.071707
122	13.094761
123	62.286246
211	1.227600
212	1.482900
213	4.550000
214	1.874500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.559100
252	2.184000
253	4.500000
254	4.500000
255	.887200
256	4.300000
261	
262	.980000
263	.640000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401			
211		110.000000 x	1.227600 =	135.036000
213		10.000000 x	4.550000 =	45.500000
117		4.000000 x	9.691373 =	38.765492
116		8.000000 x	23.150104 =	185.200832
311		1.000000 x	437.840000 =	437.840000
			=	842.342324
			H. . =	926.576556
402	402			
211		180.000000 x	1.227600 =	220.968000
312		1.000000 x	134.530000 =	134.530000
112		8.000000 x	16.843762 =	134.750096
212		5.000000 x	1.482900 =	7.414500
213		12.000000 x	4.550000 =	54.600000
116		8.000000 x	23.150104 =	185.200832
117		8.000000 x	9.691373 =	77.530984
			=	814.994412
			H. . =	896.493853
403	403			
211		80.000000 x	1.227600 =	98.208000
254		2.500000 x	4.500000 =	11.250000
213		6.000000 x	4.550000 =	27.300000
117		8.000000 x	9.691373 =	77.530984
116		8.000000 x	23.150104 =	185.200832
313		1.000000 x	206.720000 =	206.720000
			=	606.209816
			H. . =	666.830798
404	404			
211		80.000000 x	1.227600 =	98.208000
213		5.000000 x	4.550000 =	22.750000
212		2.000000 x	1.482900 =	2.965800
119		4.000000 x	9.691373 =	38.765492
118		8.000000 x	21.107527 =	168.860216
112		4.000000 x	16.843762 =	67.375048
314		1.000000 x	4.530000 =	4.530000
			=	403.454556
			H. . =	443.800012

405	405			
211		40.000000 x	1.227600 =	49.104000
213		2.000000 x	4.550000 =	9.100000
115		16.000000 x	19.864197 =	317.827152
118		4.000000 x	21.107527 =	84.430108
316		2.000000 x	4.530000 =	9.060000
315		1.000000 x	55.210000 =	55.210000
			=	524.731260
			H. . =	577.204386
406	406			
211		80.000000 x	1.227600 =	98.208000
213		5.000000 x	4.550000 =	22.750000
317		1.000000 x	126.080000 =	126.080000
120		8.000000 x	16.261841 =	130.094728
			=	377.132728
			H. . =	414.846001
407	407			
212		17.000000 x	1.482900 =	25.209300
318		1.000000 x	27.370000 =	27.370000
112		30.000000 x	16.843762 =	505.312860
213		1.000000 x	4.550000 =	4.550000
118		4.000000 x	21.107527 =	84.430108
			=	646.872268
			H. . =	711.559495
408	408			
211		30.000000 x	1.227600 =	36.828000
112		4.000000 x	16.843762 =	67.375048
116		8.000000 x	23.150104 =	185.200832
117		4.000000 x	9.691373 =	38.765492
320		1.000000 x	156.740000 =	156.740000
213		3.000000 x	4.550000 =	13.650000
			=	498.559372
			H. . =	548.415309
409	409			
211		50.000000 x	1.227600 =	61.380000
112		4.000000 x	16.843762 =	67.375048
117		4.000000 x	9.691373 =	38.765492
116		8.000000 x	23.150104 =	185.200832
324		1.000000 x	185.200000 =	185.200000
213		5.000000 x	4.550000 =	22.750000
			=	560.671372
			H. . =	616.738509

410	410				
211		100.000000 x	1.227600 =	122.760000	
117		4.000000 x	9.691373 =	38.765492	
116		8.000000 x	23.150104 =	185.200832	
112		4.000000 x	16.843762 =	67.375048	
321		1.000000 x	213.360000 =	213.360000	
213		10.000000 x	4.550000 =	45.500000	
			=	672.961372	
			H. . =	740.257509	
411	411				
211		200.000000 x	1.227600 =	245.520000	
117		4.000000 x	9.691373 =	38.765492	
116		8.000000 x	23.150104 =	185.200832	
112		4.000000 x	16.843762 =	67.375048	
213		20.000000 x	4.550000 =	91.000000	
325		1.000000 x	317.230000 =	317.230000	
			=	945.091372	
			H. . =	1,039.600509	
412	412				
211		40.000000 x	1.227600 =	49.104000	
116		8.000000 x	23.150104 =	185.200832	
326		1.000000 x	103.360000 =	103.360000	
213		2.000000 x	4.550000 =	9.100000	
			=	346.764832	
			H. . =	381.441315	
413	413				
211		15.000000 x	1.227600 =	18.414000	
213		1.500000 x	4.550000 =	6.825000	
118		3.000000 x	21.107527 =	63.322581	
112		3.000000 x	16.843762 =	50.531286	
327		1.000000 x	4.530000 =	4.530000	
			=	143.622867	
			H. . =	157.985154	
501	501				
211		170.000000 x	1.227600 =	208.692000	
380		1.000000 x	568.910000 =	568.910000	
213		3.000000 x	4.550000 =	13.650000	
351		1.000000 x	451.770000 =	451.770000	
			=	1,243.022000	
			H. . =	1,367.324200	

508	508			
358		1.000000 x	46.930000 =	46.930000
387		1.000000 x	74.960000 =	74.960000

			=	121.890000

			H. . =	127.984500
509	509			
359		1.000000 x	97.290000 =	97.290000
388		1.000000 x	74.960000 =	74.960000

			=	172.250000

			H. . =	180.862500
510	510			
360		1.000000 x	102.460000 =	102.460000
389		1.000000 x	74.960000 =	74.960000

			=	177.420000

			H. . =	186.291000
511	511			
509		.800000 x	180.862500 =	144.690000

			H. . =	144.690000
512	512			
501		.600000 x	1,367.324200 =	820.394520

			H. . =	820.394520
513	513			
363		1.000000 x	102.610000 =	102.610000
121		8.000000 x	16.071707 =	128.573656
122		8.000000 x	13.094761 =	104.758088
123		8.000000 x	62.286246 =	498.289968

			H. . =	834.231712
1111A	1111A			
214		.200000 x	1.874500 =	.374900
511		.020000 x	144.690000 =	2.893800
405		.020000 x	577.204386 =	11.544088
513		.020000 x	834.231712 =	16.684634

			B.T =	31.497422

1111B	1111B			
501		1.000000 x	1,367.324200 =	1,367.324200
506		1.000000 x	550.187000 =	550.187000
509		2.000000 x	180.862500 =	361.725000

			=	2,279.236200
	B.T =	.002500 x	2,279.236200 =	5.698091

1112A	1112A			
506		1.000000 x	550.187000 =	550.187000
512		1.000000 x	820.394520 =	820.394520

			=	1,370.581520
	B.T =	.025000 x	1,370.581520 =	34.264538

1112B	1112B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
1113A	1113A			
214		.200000 x	1.874500 =	.374900
112		.250000 x	16.843762 =	4.210941
511		.035000 x	144.690000 =	5.064150
513		.035000 x	834.231712 =	29.198110
405		.025000 x	577.204386 =	14.430110

			B.T =	53.278210
1113B	1113B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
1114A	1114A			
112		.250000 x	16.843762 =	4.210941
506		.033000 x	550.187000 =	18.156171
512		.033000 x	820.394520 =	27.073019

			B.T =	49.440131
1114B	1114B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091

1121A	1121A			
214		.150000 x	1.874500 =	.281175
115		.500000 x	19.864197 =	9.932099
405		.020000 x	577.204386 =	11.544088

			B.T =	21.757361
1121B	1121B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
1122A	1122A			
506		1.000000 x	550.187000 =	550.187000
512		1.000000 x	820.394520 =	820.394520
			=	1,370.581520
	B.T =	.012500 x	1,370.581520 =	17.132269

1122B	1122B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
1123A	1123A			
214		.150000 x	1.874500 =	.281175
112		.150000 x	16.843762 =	2.526564
405		.025000 x	577.204386 =	14.430110
115		1.000000 x	19.864197 =	19.864197

			B.T =	37.102046
1123B	1123B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
1124A	1124A			
112		.150000 x	16.843762 =	2.526564
506		.020000 x	550.187000 =	11.003740
512		.020000 x	820.394520 =	16.407890

			B.T =	29.938195
1124B	1124B			
1111B		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091

3110A 1

3110A 1

221		250.000000 x	.099900 =	24.975000
607		.500000 x	10.266974 =	5.133487
701	2	.500000 x	4.911777 =	2.455889
701	5	.250000 x	3.069860 =	.767465
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
606		.800000 x	9.363783 =	7.491026
113		1.200000 x	19.864197 =	23.837036
714		1.400000 x	7.050743 =	9.871040
407		.040000 x	711.559495 =	28.462380
319		.020000 x	22.070000 =	.441400
112		1.200000 x	16.843762 =	20.212514

B.T =

128.366585

3110A 2

3110A 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
714		1.400000 x	7.050743 =	9.871040
113		1.200000 x	19.864197 =	23.837036
112		1.200000 x	16.843762 =	20.212514
319		.020000 x	22.070000 =	.441400

B.T =

135.845598

3110A 3

3110A 3

221		250.000000 x	.099900 =	24.975000
112		1.200000 x	16.843762 =	20.212514
113		1.200000 x	19.864197 =	23.837036
714		1.400000 x	7.050743 =	9.871040
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
319		.020000 x	22.070000 =	.441400

B.T =

137.971620

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
113		1.200000 x	19.864197 =	23.837036
630		.250000 x	3.159703 =	.789926
701 5		.250000 x	3.069860 =	.767465
701 4		.800000 x	4.604791 =	3.683833
701 4		.500000 x	4.604791 =	2.302396
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
407		.040000 x	711.559495 =	28.462380
112		1.200000 x	16.843762 =	20.212514
714		1.400000 x	7.050743 =	9.871040
319		.020000 x	22.070000 =	.441400

			B.T =	145.450633
3110B	3110B			
713 1		1.000000 x	5.817456 =	5.817456
704		1.000000 x	11.634911 =	11.634911

			B.T =	17.452367
3120A 1	3120A 1			
3110A 1		1.000000 x	128.366585 =	128.366585

			B.T =	128.366585
3120A 2	3120A 2			
3110A 2		1.000000 x	135.845598 =	135.845598

			B.T =	135.845598
3120A 3	3120A 3			
3110A 3		1.000000 x	137.971620 =	137.971620

			B.T =	137.971620
3120A 4	3120A 4			
3110A 4		1.000000 x	145.450633 =	145.450633

			B.T =	145.450633
3120B	3120B			
713 2		1.000000 x	6.302452 =	6.302452
705		1.000000 x	12.604904 =	12.604904

			B.T =	18.907356

3210A 1 3210A 1

111	.400000 x	15.315315 =	6.126126
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351
3110A 1	.800000 x	128.366585 =	102.693268

B.T = 117.742514

3210A 2 3210A 2

111	.400000 x	15.315315 =	6.126126
3110A 2	.800000 x	135.845598 =	108.676478
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351

B.T = 123.725724

3210A 3 3210A 3

111	.400000 x	15.315315 =	6.126126
3110A 3	.800000 x	137.971620 =	110.377296
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351

B.T = 125.426542

3210A 4 3210A 4

111	.400000 x	15.315315 =	6.126126
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351
3110A 4	.800000 x	145.450633 =	116.360506

B.T = 131.409752

3210A 5 3210A 5

111	.400000 x	15.315315 =	6.126126
3110A 1	.800000 x	128.366585 =	102.693268
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540

B.T = 116.566703

3210A 6 3210A 6

111	.400000 x	15.315315 =	6.126126
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540
3110A 2	.800000 x	135.845598 =	108.676478

B.T = 122.549913

3210A 7 3210A 7

111	.400000 x	15.315315 =	6.126126
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540
3110A 3	.800000 x	137.971620 =	110.377296

B.T = 124.250731

3210A 8 3210A 8

111	.400000 x	15.315315 =	6.126126
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540
3110A 4	.800000 x	145.450633 =	116.360506

B.T = 130.233941

3210B 3210B

713 1	1.000000 x	5.817456 =	5.817456
704	1.000000 x	11.634911 =	11.634911

B.T = 17.452367

3220A 1 3220A 1

3210A 1	1.000000 x	117.742514 =	117.742514
---------	------------	--------------	------------

B.T = 117.742514

3220A 2 3220A 2

3210A 2	1.000000 x	123.725724 =	123.725724
---------	------------	--------------	------------

B.T = 123.725724

3220A 3 3220A 3

3210A 3	1.000000 x	125.426542 =	125.426542
---------	------------	--------------	------------

B.T = 125.426542

3220A 4 3220A 4

3210A 4	1.000000 x	131.409752 =	131.409752
---------	------------	--------------	------------

B.T = 131.409752

3220A 5 3220A 5

3210A 5	1.000000 x	116.566703 =	116.566703
---------	------------	--------------	------------

B.T = 116.566703

3220A 6 3220A 6

3210A 6 1.000000 x 122.549913 = 122.549913

B.T = 122.549913

3220A 7 3220A 7

3210A 7 1.000000 x 124.250731 = 124.250731

B.T = 124.250731

3220A 8 3220A 8

3210A 8 1.000000 x 130.233941 = 130.233941

B.T = 130.233941

3220B 3220B

713 2 1.000000 x 6.302452 = 6.302452

705 1.000000 x 12.604904 = 12.604904

B.T = 18.907356

3300A 1 3300A 1

221 300.000000 x .099900 = 29.970000

701 5 .250000 x 3.069860 = .767465

701 2 .500000 x 4.911777 = 2.455889

701 2 .800000 x 4.911777 = 3.929422

630 .250000 x 3.159703 = .789926

607 .500000 x 10.266974 = 5.133487

606 .800000 x 9.363783 = 7.491026

407 .040000 x 711.559495 = 28.462380

714 2.600000 x 7.050743 = 18.331932

113 2.000000 x 19.864197 = 39.728394

111 2.700000 x 15.315315 = 41.351351

319 .040000 x 22.070000 = .882800

B.T = 179.294070

3300A 2 3300A 2

221 300.000000 x .099900 = 29.970000

701 5 .250000 x 3.069860 = .767465

701 4 .500000 x 4.604791 = 2.302396

701 2 .800000 x 4.911777 = 3.929422

630 .250000 x 3.159703 = .789926

319 .040000 x 22.070000 = .882800

113 2.000000 x 19.864197 = 39.728394

407 .040000 x 711.559495 = 28.462380

611 .500000 x 25.531986 = 12.765993

606 .800000 x 9.363783 = 7.491026

714 2.600000 x 7.050743 = 18.331932

111 2.700000 x 15.315315 = 41.351351

B.T = 186.773083

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
714		2.600000 x	7.050743 =	18.331932
319		.040000 x	22.070000 =	.882800
113		2.000000 x	19.864197 =	39.728394
111		2.700000 x	15.315315 =	41.351351

B.T =

188.899106

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
113		2.000000 x	19.864197 =	39.728394
714		2.600000 x	7.050743 =	18.331932
111		2.700000 x	15.315315 =	41.351351
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	4	.500000 x	4.604791 =	2.302396
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
407		.040000 x	711.559495 =	28.462380
319		.040000 x	22.070000 =	.882800

B.T =

196.378119

3300B 1

3300B 1

713	1	1.000000 x	5.817456 =	5.817456
704		1.000000 x	11.634911 =	11.634911

B.T =

17.452367

3300B 2

3300B 2

713	2	1.000000 x	6.302452 =	6.302452
705		1.000000 x	12.604904 =	12.604904

B.T =

18.907356

3400A 1 3400A 1

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.887200 =	4.436000
701	5	.250000 x	3.069860 =	.767465
701	2	.800000 x	4.911777 =	3.929422
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
113		2.000000 x	19.864197 =	39.728394
113		.500000 x	19.864197 =	9.932099
112		1.000000 x	16.843762 =	16.843762
111		2.700000 x	15.315315 =	41.351351
319		.030000 x	22.070000 =	.662100

B.T = 191.953299

3400A 2 3400A 2

221		300.000000 x	.099900 =	29.970000
407		.040000 x	711.559495 =	28.462380
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
113		2.000000 x	19.864197 =	39.728394
113		.500000 x	19.864197 =	9.932099
112		1.000000 x	16.843762 =	16.843762
111		2.700000 x	15.315315 =	41.351351
319		.030000 x	22.070000 =	.662100
255		5.000000 x	.887200 =	4.436000

B.T = 199.432312

3400A 3 3400A 3

221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.315315 =	41.351351
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
113		2.000000 x	19.864197 =	39.728394
113		.500000 x	19.864197 =	9.932099
112		1.000000 x	16.843762 =	16.843762
319		.030000 x	22.070000 =	.662100
255		5.000000 x	.887200 =	4.436000

B.T = 201.558334

3400A 4 3400A 4

221		300.000000 x	.099900 =	29.970000
407		.040000 x	711.559495 =	28.462380
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	4	.500000 x	4.604791 =	2.302396
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
113		2.000000 x	19.864197 =	39.728394
113		.500000 x	19.864197 =	9.932099
112		1.000000 x	16.843762 =	16.843762
111		2.700000 x	15.315315 =	41.351351
319		.030000 x	22.070000 =	.662100
255		5.000000 x	.887200 =	4.436000

B.T = 209.037347

3400B 1 3400B 1

704		1.000000 x	11.634911 =	11.634911
-----	--	------------	-------------	-----------

B.T = 11.634911

3400B 2 3400B 2

705		1.000000 x	12.604904 =	12.604904
-----	--	------------	-------------	-----------

B.T = 12.604904

4110A 1 4110A 1

221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.315315 =	61.261260
701	5	.100000 x	3.069860 =	.306986
701	2	.800000 x	4.911777 =	3.929422
701	2	.500000 x	4.911777 =	2.455889
630		.100000 x	3.159703 =	.315970
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.070000 x	711.559495 =	49.809165
113		1.500000 x	19.864197 =	29.796296

B.T = 195.464500

4110A 2 4110A 2

221		350.000000 x	.099900 =	34.965000
701	5	.100000 x	3.069860 =	.306986
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.100000 x	3.159703 =	.315970
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
407		.070000 x	711.559495 =	49.809165
113		1.500000 x	19.864197 =	29.796296
111		4.000000 x	15.315315 =	61.261260

B.T = 202.943513

4110A 3 4110A 3

221		350.000000 x	.099900 =	34.965000
407		.070000 x	711.559495 =	49.809165
701	5	.100000 x	3.069860 =	.306986
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.100000 x	3.159703 =	.315970
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
113		1.500000 x	19.864197 =	29.796296
111		4.000000 x	15.315315 =	61.261260

B.T = 205.069535

4110A 4 4110A 4

221		350.000000 x	.099900 =	34.965000
407		.070000 x	711.559495 =	49.809165
610		.800000 x	21.677063 =	17.341650
701	5	.100000 x	3.069860 =	.306986
701	4	.800000 x	4.604791 =	3.683833
701	4	.500000 x	4.604791 =	2.302396
630		.100000 x	3.159703 =	.315970
611		.500000 x	25.531986 =	12.765993
113		1.500000 x	19.864197 =	29.796296
111		4.000000 x	15.315315 =	61.261260

B.T = 212.548548

4110B 4110B

112		8.000000 x	16.843762 =	134.750096
508		1.000000 x	127.984500 =	127.984500
513		1.000000 x	834.231712 =	834.231712
506		1.000000 x	550.187000 =	550.187000

B.T = 1,647.153308

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.911777 =	5.894132
607		1.200000 x	10.266974 =	12.320369
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	16.843762 =	84.218810

B.T = 164.278311

4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.604791 =	5.525749
611		1.200000 x	25.531986 =	30.638383
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	16.843762 =	84.218810

B.T = 182.227942

4120B	4120B			
4110B		.040000 x	1,647.153308 =	65.886132

B.T = 65.886132

4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.640000 =	26.880000
407		.050000 x	711.559495 =	35.577975
606		.800000 x	9.363783 =	7.491026
607		.500000 x	10.266974 =	5.133487
701 2		.500000 x	4.911777 =	2.455889
701 2		.800000 x	4.911777 =	3.929422
111		2.000000 x	15.315315 =	30.630630

B.T = 147.063428

4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	711.559495 =	35.577975
701 4		.500000 x	4.604791 =	2.302396
701 2		.800000 x	4.911777 =	3.929422
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
111		2.000000 x	15.315315 =	30.630630
263		42.000000 x	.640000 =	26.880000

B.T = 154.542441

4130A 3 4130A 3

221		350.000000 x	.099900 =	34.965000
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.050000 x	711.559495 =	35.577975
111		2.000000 x	15.315315 =	30.630630
263		42.000000 x	.640000 =	26.880000

B.T = 156.668463

4130A 4 4130A 4

221		350.000000 x	.099900 =	34.965000
701	4	.500000 x	4.604791 =	2.302396
701	4	.800000 x	4.604791 =	3.683833
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
407		.050000 x	711.559495 =	35.577975
263		42.000000 x	.640000 =	26.880000
111		2.000000 x	15.315315 =	30.630630

B.T = 164.147476

4130B 4130B

4120B		1.000000 x	65.886132 =	65.886132
-------	--	------------	-------------	-----------

B.T = 65.886132

4210A 1 4210A 1

221		65.000000 x	.099900 =	6.493500
630		.150000 x	3.159703 =	.473955
701	5	.150000 x	3.069860 =	.460479
701	2	.300000 x	4.911777 =	1.473533
701	2	1.050000 x	4.911777 =	5.157366
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.266974 =	3.080092
601		1.050000 x	22.972973 =	24.121622

B.T = 41.960547

4210A 2 4210A 2

221		65.000000 x	.099900 =	6.493500
701	5	.150000 x	3.069860 =	.460479
701	4	.300000 x	4.604791 =	1.381437
630		.150000 x	3.159703 =	.473955
611		.300000 x	25.531986 =	7.659596
701	2	1.050000 x	4.911777 =	5.157366
222		10.000000 x	.070000 =	.700000
601		1.050000 x	22.972973 =	24.121622

B.T = 46.447955

4210A 3 4210A 3

221		65.000000 x	.099900 =	6.493500
701	5	.150000 x	3.069860 =	.460479
701	2	.300000 x	4.911777 =	1.473533
701	2	1.050000 x	4.911777 =	5.157366
630		.150000 x	3.159703 =	.473955
609		1.050000 x	19.298563 =	20.263491
607		.300000 x	10.266974 =	3.080092
222		10.000000 x	.070000 =	.700000

B.T = 38.102417

4210A 4 4210A 4

221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701	5	.150000 x	3.069860 =	.460479
701	4	.300000 x	4.604791 =	1.381437
701	2	1.050000 x	4.911777 =	5.157366
630		.150000 x	3.159703 =	.473955
611		.300000 x	25.531986 =	7.659596
609		1.050000 x	19.298563 =	20.263491

B.T = 42.589825

4210B 4210B

111		4.000000 x	15.315315 =	61.261260
112		1.500000 x	16.843762 =	25.265643
113		2.500000 x	19.864197 =	49.660493
112		.200000 x	16.843762 =	3.368752

B.T = 139.556148

4220A 1 4220A 1

221		200.000000 x	.099900 =	19.980000
701	2	.800000 x	4.911777 =	3.929422
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
113		1.000000 x	19.864197 =	19.864197
111		1.200000 x	15.315315 =	18.378378
701	5	.250000 x	3.069860 =	.767465

B.T = 107.252169

4220A 2 4220A 2

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.315315 =	18.378378
113		1.000000 x	19.864197 =	19.864197
611		.500000 x	25.531986 =	12.765993
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380

B.T = 114.731182

4220A 3 4220A 3

221		200.000000 x	.099900 =	19.980000
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
111		1.200000 x	15.315315 =	18.378378
407		.040000 x	711.559495 =	28.462380
113		1.000000 x	19.864197 =	19.864197
701	5	.250000 x	3.069860 =	.767465

B.T = 116.857204

4220A 4 4220A 4

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.315315 =	18.378378
407		.040000 x	711.559495 =	28.462380
611		.500000 x	25.531986 =	12.765993
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	4	.800000 x	4.604791 =	3.683833
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
113		1.000000 x	19.864197 =	19.864197

B.T = 124.336217

4300A 1 4300A 1

221		350.000000 x	.099900 =	34.965000
701	5	.250000 x	3.069860 =	.767465
701	2	.800000 x	4.911777 =	3.929422
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630

			=	146.570615
B.T =		.200000 x	146.570615 =	29.314123

4300A 2 4300A 2

221		350.000000 x	.099900 =	34.965000
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630

			=	154.049628
B.T =		.200000 x	154.049628 =	30.809926

4300A 3 4300A 3

221		350.000000 x	.099900 =	34.965000
113		1.200000 x	19.864197 =	23.837036
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
111		2.000000 x	15.315315 =	30.630630

			=	156.175650
B.T =		.200000 x	156.175650 =	31.235130

4300A 4 4300A 4

221		350.000000 x	.099900 =	34.965000
113		1.200000 x	19.864197 =	23.837036
611		.500000 x	25.531986 =	12.765993
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	4	.500000 x	4.604791 =	2.302396
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
111		2.000000 x	15.315315 =	30.630630

			=	163.654663
B.T =		.200000 x	163.654663 =	32.730933

4300B 4300B

221		2.000000 x	.099900 =	.199800
112		.400000 x	16.843762 =	6.737505
262		4.000000 x	.980000 =	3.920000

B.T = 10.857305

601 601

111		1.500000 x	15.315315 =	22.972973
-----	--	------------	-------------	-----------

B.T = 22.972973

602 602

403		.002500 x	666.830798 =	1.667077
-----	--	-----------	--------------	----------

B.T = 1.667077

603 603

111		.300000 x	15.315315 =	4.594595
412		.003300 x	381.441315 =	1.258756
401		.001000 x	926.576556 =	.926577

B.T = 6.779927

604 604

111		.200000 x	15.315315 =	3.063063
404		.005000 x	443.800012 =	2.219000
401		.001100 x	926.576556 =	1.019234
412		.004000 x	381.441315 =	1.525765

B.T = 7.827063

605	605			
112		.100000 x	16.843762 =	1.684376
401		.001000 x	926.576556 =	.926577
402		.006200 x	896.493853 =	5.558262
412		.004000 x	381.441315 =	1.525765
406		.006200 x	414.846001 =	2.572045

			B.T =	12.267025
606	606			
111		.100000 x	15.315315 =	1.531532
401		.001000 x	926.576556 =	.926577
412		.005000 x	381.441315 =	1.907207
406		.006700 x	414.846001 =	2.779468
404		.005000 x	443.800012 =	2.219000

			B.T =	9.363783
607	607			
111		.100000 x	15.315315 =	1.531532
412		.005000 x	381.441315 =	1.907207
401		.001400 x	926.576556 =	1.297207
406		.006700 x	414.846001 =	2.779468
404		.006200 x	443.800012 =	2.751560

			B.T =	10.266974
608	608			
111		.100000 x	15.315315 =	1.531532
412		.005000 x	381.441315 =	1.907207
406		.006700 x	414.846001 =	2.779468
404		.012500 x	443.800012 =	5.547500
401		.002000 x	926.576556 =	1.853153

			B.T =	13.618860
609	609			
214		.100000 x	1.874500 =	.187450
405		.005000 x	577.204386 =	2.886022
115		.200000 x	19.864197 =	3.972839
111		.800000 x	15.315315 =	12.252252

			B.T =	19.298563

610	610			
214		.100000 x	1.874500 =	.187450
412		.005000 x	381.441315 =	1.907207
406		.005000 x	414.846001 =	2.074230
405		.005000 x	577.204386 =	2.886022
402		.010000 x	896.493853 =	8.964939
112		.100000 x	16.843762 =	1.684376
115		.200000 x	19.864197 =	3.972839
			B.T =	21.677063
611	611			
214		.100000 x	1.874500 =	.187450
112		.100000 x	16.843762 =	1.684376
405		.005000 x	577.204386 =	2.886022
412		.005000 x	381.441315 =	1.907207
406		.005000 x	414.846001 =	2.074230
402		.014300 x	896.493853 =	12.819862
115		.200000 x	19.864197 =	3.972839
			B.T =	25.531986
612	612			
214		.150000 x	1.874500 =	.281175
408		.010000 x	548.415309 =	5.484153
405		.005000 x	577.204386 =	2.886022
115		.200000 x	19.864197 =	3.972839
111		.300000 x	15.315315 =	4.594595
			=	17.218784
	B.T =	1.068000 x	17.218784 =	18.389661
613	613			
214		.150000 x	1.874500 =	.281175
409		.010000 x	616.738509 =	6.167385
405		.005000 x	577.204386 =	2.886022
115		.200000 x	19.864197 =	3.972839
111		.500000 x	15.315315 =	7.657658
			=	20.965079
	B.T =	1.282000 x	20.965079 =	26.877231
614	614			
214		.150000 x	1.874500 =	.281175
111		.500000 x	15.315315 =	7.657658
115		.200000 x	19.864197 =	3.972839
410		.010000 x	740.257509 =	7.402575
405		.005000 x	577.204386 =	2.886022
			=	22.200269
	B.T =	1.602000 x	22.200269 =	35.564831

615	615			
214		.150000 x	1.874500 =	.281175
410		.010000 x	740.257509 =	7.402575
111		.700000 x	15.315315 =	10.720721
405		.005000 x	577.204386 =	2.886022
115		.200000 x	19.864197 =	3.972839

			=	25.263332
	B.T =	1.832000 x	25.263332 =	46.282424

616	616			
214		.150000 x	1.874500 =	.281175
111		.800000 x	15.315315 =	12.252252
405		.005000 x	577.204386 =	2.886022
411		.010000 x	1,039.600509 =	10.396005
115		.200000 x	19.864197 =	3.972839

			=	29.788293
	B.T =	2.137000 x	29.788293 =	63.657583

617	617			
112		4.000000 x	16.843762 =	67.375048
513		1.000000 x	834.231712 =	834.231712
506		1.000000 x	550.187000 =	550.187000
503		1.000000 x	1,367.324200 =	1,367.324200

			=	2,819.117960
	B.T =	.006250 x	2,819.117960 =	17.619487

618	618			
112		4.000000 x	16.843762 =	67.375048
513		1.000000 x	834.231712 =	834.231712
506		1.000000 x	550.187000 =	550.187000
503		1.000000 x	1,367.324200 =	1,367.324200

			=	2,819.117960
	B.T =	.007700 x	2,819.117960 =	21.707208

619	619			
112		4.000000 x	16.843762 =	67.375048
503		1.000000 x	1,367.324200 =	1,367.324200
506		1.000000 x	550.187000 =	550.187000
513		1.000000 x	834.231712 =	834.231712

			=	2,819.117960
	B.T =	.010000 x	2,819.117960 =	28.191180

620 620

112	4.000000 x	16.843762 =	67.375048
513	1.000000 x	834.231712 =	834.231712
506	1.000000 x	550.187000 =	550.187000
503	1.000000 x	1,367.324200 =	1,367.324200

		=	2,819.117960
B.T =	.012500 x	2,819.117960 =	35.238975

621 621

112	4.000000 x	16.843762 =	67.375048
506	1.000000 x	550.187000 =	550.187000
503	1.000000 x	1,367.324200 =	1,367.324200
513	1.000000 x	834.231712 =	834.231712

		=	2,819.117960
B.T =	.016600 x	2,819.117960 =	46.797358

630 630

413	.020000 x	157.985154 =	3.159703
-----	-----------	--------------	----------

B.T = 3.159703

701 1 701 1

406	.012580 x	414.846001 =	5.218763
-----	-----------	--------------	----------

B.T = 5.218763

701 2 701 2

406	.011840 x	414.846001 =	4.911777
-----	-----------	--------------	----------

B.T = 4.911777

701 3 701 3

406	.011544 x	414.846001 =	4.788982
-----	-----------	--------------	----------

B.T = 4.788982

701 4 701 4

406	.011100 x	414.846001 =	4.604791
-----	-----------	--------------	----------

B.T = 4.604791

701 5 701 5

406	.007400 x	414.846001 =	3.069860
-----	-----------	--------------	----------

B.T = 3.069860

702	702			
112		8.000000 x	16.843762 =	134.750096
506		1.000000 x	550.187000 =	550.187000
513		.300000 x	834.231712 =	250.269514
509		2.000000 x	180.862500 =	361.725000

			=	1,296.931610
	B.T =	.002500 x	1,296.931610 =	3.242329

703	703			
112		4.000000 x	16.843762 =	67.375048
513		.300000 x	834.231712 =	250.269514
503		1.000000 x	1,367.324200 =	1,367.324200
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	550.187000 =	550.187000

			=	2,607.737762
	B.T =	.002500 x	2,607.737762 =	6.519344

704	704			
112		4.000000 x	16.843762 =	67.375048
513		.500000 x	834.231712 =	417.115856
506		1.000000 x	550.187000 =	550.187000
502		1.000000 x	1,292.304200 =	1,292.304200

			=	2,326.982104
	B.T =	.005000 x	2,326.982104 =	11.634911

705	705			
112		4.000000 x	16.843762 =	67.375048
513		.600000 x	834.231712 =	500.539027
506		1.000000 x	550.187000 =	550.187000
504		1.000000 x	1,658.309400 =	1,658.309400

			=	2,776.410475
	B.T =	.004540 x	2,776.410475 =	12.604904

706	706			
501		1.000000 x	1,367.324200 =	1,367.324200
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	550.187000 =	550.187000

			=	2,279.236200
	B.T =	.002500 x	2,279.236200 =	5.698091

707	707			
505		1.000000 x	3,243.663500 =	3,243.663500
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	550.187000 =	550.187000

			=	4,166.432500
	B.T =	.001000 x	4,166.432500 =	4.166433

708	708			
708A		1.000000 x	17.097997 =	17.097997
708B		1.000000 x	5.698091 =	5.698091

			B.T =	22.796088
708A	708A			
214		.050000 x	1.874500 =	.093725
513		.010000 x	834.231712 =	8.342317
511		.010000 x	144.690000 =	1.446900
405		.012500 x	577.204386 =	7.215055

			B.T =	17.097997
708B	708B			
706		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
709	709			
709A		1.000000 x	17.132269 =	17.132269
709B		1.000000 x	5.698091 =	5.698091

			B.T =	22.830360
709A	709A			
506		1.000000 x	550.187000 =	550.187000
512		1.000000 x	820.394520 =	820.394520

			=	1,370.581520
	B.T =	.012500 x	1,370.581520 =	17.132269

709B	709B			
706		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
710	710			
710A		1.000000 x	49.067270 =	49.067270
710B		1.000000 x	5.698091 =	5.698091

			B.T =	54.765361
710A	710A			
214		.200000 x	1.874500 =	.374900
405		.025000 x	577.204386 =	14.430110
513		.035000 x	834.231712 =	29.198110
511		.035000 x	144.690000 =	5.064150

			B.T =	49.067270

710B	710B			
706		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
711	711			
711A		1.000000 x	45.640365 =	45.640365
711B		1.000000 x	5.698091 =	5.698091

			B.T =	51.338456
711A	711A			
506		1.000000 x	550.187000 =	550.187000
512		1.000000 x	820.394520 =	820.394520

			=	1,370.581520
	B.T =	.033300 x	1,370.581520 =	45.640365

711B	711B			
706		1.000000 x	5.698091 =	5.698091

			B.T =	5.698091
712	712			
513		1.000000 x	834.231712 =	834.231712

			=	834.231712
	B.T =	.004000 x	834.231712 =	3.336927

713 1	713 1			
704		.500000 x	11.634911 =	5.817456

			B.T =	5.817456
713 2	713 2			
705		.500000 x	12.604904 =	6.302452

			B.T =	6.302452
714	714			
714A		1.000000 x	3.379947 =	3.379947
714B		1.000000 x	3.670796 =	3.670796

			B.T =	7.050743

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	16.843762 =	33.687524
252		1.000000 x	2.184000 =	2.184000
113		2.000000 x	19.864197 =	39.728394

			=	101.499918
	B.T =	.033300 x	101.499918 =	3.379947

714B	714B			
113		.100000 x	19.864197 =	1.986420
114		.100000 x	16.843762 =	1.684376

			B.T =	3.670796
1111	1111			
1111A		1.000000 x	31.497422 =	31.497422
1111B		1.000000 x	5.698091 =	5.698091

			T.E =	37.195513
1112	1112			
1112A		1.000000 x	34.264538 =	34.264538
1112B		1.000000 x	5.698091 =	5.698091

			T.E =	39.962629
1113	1113			
1113A		1.000000 x	53.278210 =	53.278210
1113B		1.000000 x	5.698091 =	5.698091

			T.E =	58.976301
1114	1114			
1114A		1.000000 x	49.440131 =	49.440131
1114B		1.000000 x	5.698091 =	5.698091

			T.E =	55.138222
1121	1121			
1121A		1.000000 x	21.757361 =	21.757361
1121B		1.000000 x	5.698091 =	5.698091

			T.E =	27.455452
1122	1122			
1122A		1.000000 x	17.132269 =	17.132269
1122B		1.000000 x	5.698091 =	5.698091

			T.E =	22.830360

1123	1123				
1123A		1.000000 x	37.102046 =	37.102046	
1123B		1.000000 x	5.698091 =	5.698091	

			T.E =	42.800137	
1124	1124				
1124A		1.000000 x	29.938195 =	29.938195	
1124B		1.000000 x	5.698091 =	5.698091	

			T.E =	35.636286	
1210	1210				
707		1.000000 x	4.166433 =	4.166433	

			T.E =	4.166433	
1220	1220				
708		1.000000 x	22.796088 =	22.796088	

			T.E =	22.796088	
1230	1230				
709		1.000000 x	22.830360 =	22.830360	

			T.E =	22.830360	
1311	1311				
712		.250000 x	3.336927 =	.834232	

			T.E =	.834232	
1312	1312				
712		.250000 x	3.336927 =	.834232	
701 1		1.000000 x	5.218763 =	5.218763	
602		1.000000 x	1.667077 =	1.667077	

			T.E =	7.720072	
1313	1313				
712		.250000 x	3.336927 =	.834232	
603		1.000000 x	6.779927 =	6.779927	
701 2		1.000000 x	4.911777 =	4.911777	

			T.E =	12.525936	

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.315315 =	1.531532	
712		.250000 x	3.336927 =	.834232	

			T.E =	37.365763	
1321	1321				
112		.200000 x	16.843762 =	3.368752	
701	1	1.000000 x	5.218763 =	5.218763	
602		1.000000 x	1.667077 =	1.667077	

			T.E =	10.254592	
1322	1322				
112		.200000 x	16.843762 =	3.368752	
603		1.000000 x	6.779927 =	6.779927	
701	2	1.000000 x	4.911777 =	4.911777	

			T.E =	15.060456	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.315315 =	1.531532	
112		.100000 x	16.843762 =	1.684376	

			T.E =	38.215908	
2110	2110				
712		.500000 x	3.336927 =	1.668464	
702		1.000000 x	3.242329 =	3.242329	
608		1.000000 x	13.618860 =	13.618860	
701	4	1.000000 x	4.604791 =	4.604791	

			T.E =	23.134444	
2120	2120				
712		.500000 x	3.336927 =	1.668464	
702		1.000000 x	3.242329 =	3.242329	
701	2	1.000000 x	4.911777 =	4.911777	
603		1.000000 x	6.779927 =	6.779927	

			T.E =	16.602497	
2130	2130				
712		.500000 x	3.336927 =	1.668464	
604		1.000000 x	7.827063 =	7.827063	
701	2	1.000000 x	4.911777 =	4.911777	
702		1.000000 x	3.242329 =	3.242329	

			T.E =	17.649633	

2140 2140

712		.500000 x	3.336927 =	1.668464
605		1.000000 x	12.267025 =	12.267025
702		1.000000 x	3.242329 =	3.242329
701	2	1.000000 x	4.911777 =	4.911777

T.E = 22.089595

2210 2210

712		.500000 x	3.336927 =	1.668464
609		1.050000 x	19.298563 =	20.263491
702		1.000000 x	3.242329 =	3.242329
701	2	1.000000 x	4.911777 =	4.911777

T.E = 30.086061

2220 2220

712		.500000 x	3.336927 =	1.668464
702		1.000000 x	3.242329 =	3.242329
701	2	1.000000 x	4.911777 =	4.911777
609		1.150000 x	19.298563 =	22.193347

T.E = 32.015917

2230 2230

111		.200000 x	15.315315 =	3.063063
609		1.200000 x	19.298563 =	23.158276
701	2	1.000000 x	4.911777 =	4.911777

T.E = 31.133116

2240 2240

111		.300000 x	15.315315 =	4.594595
609		1.200000 x	19.298563 =	23.158276
701	2	1.000000 x	4.911777 =	4.911777

T.E = 32.664647

2310 2310

612		1.000000 x	18.389661 =	18.389661
701	3	1.000000 x	4.788982 =	4.788982
703		1.000000 x	6.519344 =	6.519344

T.E = 29.697987

2320 2320

613		1.000000 x	26.877231 =	26.877231
703		1.000000 x	6.519344 =	6.519344
701	3	1.000000 x	4.788982 =	4.788982

T.E = 38.185557

2330	2330				
614		1.000000 x	35.564831 =	35.564831	
703		1.000000 x	6.519344 =	6.519344	
701	3	1.000000 x	4.788982 =	4.788982	

			T.E =	46.873157	
2340	2340				
615		1.000000 x	46.282424 =	46.282424	
703		1.000000 x	6.519344 =	6.519344	
701	3	1.000000 x	4.788982 =	4.788982	

			T.E =	57.590750	
2350	2350				
616		1.000000 x	63.657583 =	63.657583	
701	3	1.000000 x	4.788982 =	4.788982	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	74.965909	
2410	2410				
617		1.000000 x	17.619487 =	17.619487	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	24.138831	
2420	2420				
618		1.000000 x	21.707208 =	21.707208	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	28.226552	
2430	2430				
619		1.000000 x	28.191180 =	28.191180	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	34.710524	
2440	2440				
620		1.000000 x	35.238975 =	35.238975	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	41.758319	
2450	2450				
621		1.000000 x	46.797358 =	46.797358	
703		1.000000 x	6.519344 =	6.519344	

			T.E =	53.316702	

3110 1	3110 1				
3110A 1		1.000000 x	128.366585 =	128.366585	
3110B		1.000000 x	17.452367 =	17.452367	

			T.E =	145.818952	
3110 2	3110 2				
3110A 2		1.000000 x	135.845598 =	135.845598	
3110B		1.000000 x	17.452367 =	17.452367	

			T.E =	153.297965	
3110 3	3110 3				
3110A 3		1.000000 x	137.971620 =	137.971620	
3110B		1.000000 x	17.452367 =	17.452367	

			T.E =	155.423987	
3110 4	3110 4				
3110A 4		1.000000 x	145.450633 =	145.450633	
3110B		1.000000 x	17.452367 =	17.452367	

			T.E =	162.903000	
3120 1	3120 1				
3120A 1		1.000000 x	128.366585 =	128.366585	
3120B		1.000000 x	18.907356 =	18.907356	

			T.E =	147.273941	
3120 2	3120 2				
3120A 2		1.000000 x	135.845598 =	135.845598	
3120B		1.000000 x	18.907356 =	18.907356	

			T.E =	154.752954	
3120 3	3120 3				
3120A 3		1.000000 x	137.971620 =	137.971620	
3120B		1.000000 x	18.907356 =	18.907356	

			T.E =	156.878976	
3120 4	3120 4				
3120A 4		1.000000 x	145.450633 =	145.450633	
3120B		1.000000 x	18.907356 =	18.907356	

			T.E =	164.357989	

3210 1	3210 1				
3210A 1		1.000000 x	117.742514 =	117.742514	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	135.194881	
3210 2	3210 2				
3210A 2		1.000000 x	123.725724 =	123.725724	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	141.178091	
3210 3	3210 3				
3210A 3		1.000000 x	125.426542 =	125.426542	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	142.878909	
3210 4	3210 4				
3210A 4		1.000000 x	131.409752 =	131.409752	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	148.862119	
3210 5	3210 5				
3210A 5		1.000000 x	116.566703 =	116.566703	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	134.019070	
3210 6	3210 6				
3210A 6		1.000000 x	122.549913 =	122.549913	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	140.002280	
3210 7	3210 7				
3210A 7		1.000000 x	124.250731 =	124.250731	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	141.703098	
3210 8	3210 8				
3210A 8		1.000000 x	130.233941 =	130.233941	
3210B		1.000000 x	17.452367 =	17.452367	

			T.E =	147.686308	

3220 1 3220 1

3220A 1
3220B1.000000 x
1.000000 x117.742514 =
18.907356 =117.742514
18.907356-----
T.E =

136.649870

3220 2 3220 2

3220A 2
3220B1.000000 x
1.000000 x123.725724 =
18.907356 =123.725724
18.907356-----
T.E =

142.633080

3220 3 3220 3

3220A 3
3220B1.000000 x
1.000000 x125.426542 =
18.907356 =125.426542
18.907356-----
T.E =

144.333898

3220 4 3220 4

3220A 4
3220B1.000000 x
1.000000 x131.409752 =
18.907356 =131.409752
18.907356-----
T.E =

150.317108

3220 5 3220 5

3220A 5
3220B1.000000 x
1.000000 x116.566703 =
18.907356 =116.566703
18.907356-----
T.E =

135.474059

3220 6 3220 6

3220A 6
3220B1.000000 x
1.000000 x122.549913 =
18.907356 =122.549913
18.907356-----
T.E =

141.457269

3220 7 3220 7

3220A 7
3220B1.000000 x
1.000000 x124.250731 =
18.907356 =124.250731
18.907356-----
T.E =

143.158087

3220 8 3220 8

3220A 8
3220B1.000000 x
1.000000 x130.233941 =
18.907356 =130.233941
18.907356-----
T.E =

149.141297

3300 1 3300 1

3300A 1

1.000000 x

179.294070 =

179.294070

3300B 1

1.000000 x

17.452367 =

17.452367

T.E =

196.746437

3300 2 3300 2

3300A 1

1.000000 x

179.294070 =

179.294070

3300B 2

1.000000 x

18.907356 =

18.907356

T.E =

198.201426

3300 3 3300 3

3300A 2

1.000000 x

186.773083 =

186.773083

3300B 1

1.000000 x

17.452367 =

17.452367

T.E =

204.225450

3300 4 3300 4

3300A 2

1.000000 x

186.773083 =

186.773083

3300B 2

1.000000 x

18.907356 =

18.907356

T.E =

205.680439

3300 5 3300 5

3300A 3

1.000000 x

188.899106 =

188.899106

3300B 1

1.000000 x

17.452367 =

17.452367

T.E =

206.351473

3300 6 3300 6

3300A 3

1.000000 x

188.899106 =

188.899106

3300B 2

1.000000 x

18.907356 =

18.907356

T.E =

207.806462

3300 7 3300 7

3300A 4

1.000000 x

196.378119 =

196.378119

3300B 1

1.000000 x

17.452367 =

17.452367

T.E =

213.830486

3300 8 3300 8

3300A 4

1.000000 x

196.378119 =

196.378119

3300B 2

1.000000 x

18.907356 =

18.907356

T.E =

215.285475

3 μ

2012

. 42
μ/ 27/12/2013

3400 1 3400 1

3400A 1	1.000000 x	191.953299 =	191.953299
3400B 1	1.000000 x	11.634911 =	11.634911

T.E = 203.588210

3400 2 3400 2

3400A 1	1.000000 x	191.953299 =	191.953299
3400B 2	1.000000 x	12.604904 =	12.604904

T.E = 204.558203

3400 3 3400 3

3400A 2	1.000000 x	199.432312 =	199.432312
3400B 1	1.000000 x	11.634911 =	11.634911

T.E = 211.067223

3400 4 3400 4

3400A 2	1.000000 x	199.432312 =	199.432312
3400B 2	1.000000 x	12.604904 =	12.604904

T.E = 212.037216

3400 5 3400 5

3400A 3	1.000000 x	201.558334 =	201.558334
3400B 1	1.000000 x	11.634911 =	11.634911

T.E = 213.193245

3400 6 3400 6

3400A 3	1.000000 x	201.558334 =	201.558334
3400B 2	1.000000 x	12.604904 =	12.604904

T.E = 214.163238

3400 7 3400 7

3400A 4	1.000000 x	209.037347 =	209.037347
3400B 1	1.000000 x	11.634911 =	11.634911

T.E = 220.672258

3400 8 3400 8

3400A 4	1.000000 x	209.037347 =	209.037347
3400B 2	1.000000 x	12.604904 =	12.604904

T.E = 221.642251

4110 1	4110 1				
4110A 1		1.000000 x	195.464500 =	195.464500	
4110B		.025000 x	1,647.153308 =	41.178833	

			T.E =	236.643333	
4110 2	4110 2				
4110A 2		1.000000 x	202.943513 =	202.943513	
4110B		.025000 x	1,647.153308 =	41.178833	

			T.E =	244.122346	
4110 3	4110 3				
4110A 3		1.000000 x	205.069535 =	205.069535	
4110B		.025000 x	1,647.153308 =	41.178833	

			T.E =	246.248368	
4110 4	4110 4				
4110A 4		1.000000 x	212.548548 =	212.548548	
4110B		.025000 x	1,647.153308 =	41.178833	

			T.E =	253.727381	
4120 1	4120 1				
4120A 1		1.000000 x	164.278311 =	164.278311	
4120B		1.000000 x	65.886132 =	65.886132	

			T.E =	230.164443	
4120 2	4120 2				
4120A 2		1.000000 x	182.227942 =	182.227942	
4120B		1.000000 x	65.886132 =	65.886132	

			T.E =	248.114074	
4130 1	4130 1				
4130A 1		1.000000 x	147.063428 =	147.063428	
4130B		1.000000 x	65.886132 =	65.886132	

			T.E =	212.949560	
4130 2	4130 2				
4130A 2		1.000000 x	154.542441 =	154.542441	
4130B		1.000000 x	65.886132 =	65.886132	

			T.E =	220.428573	

4130 3 4130 3

4130A 3
4130B1.000000 x
1.000000 x156.668463 =
65.886132 =156.668463
65.886132-----
T.E =

222.554595

4130 4 4130 4

4130A 4
4130B1.000000 x
1.000000 x164.147476 =
65.886132 =164.147476
65.886132-----
T.E =

230.033608

4210 1 4210 1

4210A 1
4210B1.000000 x
1.000000 x41.960547 =
139.556148 =41.960547
139.556148-----
T.E =

181.516695

4210 2 4210 2

4210A 2
4210B1.000000 x
1.000000 x46.447955 =
139.556148 =46.447955
139.556148-----
T.E =

186.004103

4210 3 4210 3

4210A 3
4210B1.000000 x
1.000000 x38.102417 =
139.556148 =38.102417
139.556148-----
T.E =

177.658565

4210 4 4210 4

4210A 4
4210B1.000000 x
1.000000 x42.589825 =
139.556148 =42.589825
139.556148-----
T.E =

182.145973

4220B 1 4220B 1

319
701 2
601
4220A 1
714
111.020000 x
.320000 x
.320000 x
.800000 x
1.150000 x
.400000 x22.070000 =
4.911777 =
22.972973 =
107.252169 =
7.050743 =
15.315315 =.441400
1.571769
7.351351
85.801735
8.108354
6.126126-----
T.E =

109.400736

4220B 2 4220B 2

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.315315 =	6.126126
714	1.150000 x	7.050743 =	8.108354
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351
4220A 2	.800000 x	114.731182 =	91.784946

T.E = 115.383946

4220B 3 4220B 3

319	.020000 x	22.070000 =	.441400
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351
111	.400000 x	15.315315 =	6.126126
4220A 3	.800000 x	116.857204 =	93.485763
714	1.150000 x	7.050743 =	8.108354

T.E = 117.084764

4220B 4 4220B 4

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.315315 =	6.126126
4220A 4	.800000 x	124.336217 =	99.468974
701 2	.320000 x	4.911777 =	1.571769
601	.320000 x	22.972973 =	7.351351
714	1.150000 x	7.050743 =	8.108354

T.E = 123.067974

4220B 5 4220B 5

319	.020000 x	22.070000 =	.441400
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540
4220A 1	.800000 x	107.252169 =	85.801735
714	1.150000 x	7.050743 =	8.108354
111	.400000 x	15.315315 =	6.126126

T.E = 108.224924

4220B 6 4220B 6

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.315315 =	6.126126
714	1.150000 x	7.050743 =	8.108354
701 2	.320000 x	4.911777 =	1.571769
609	.320000 x	19.298563 =	6.175540
4220A 2	.800000 x	114.731182 =	91.784946

T.E = 114.208135

4220B 7 4220B 7

319		.020000 x	22.070000 =	.441400
701	2	.320000 x	4.911777 =	1.571769
609		.320000 x	19.298563 =	6.175540
111		.400000 x	15.315315 =	6.126126
4220A	3	.800000 x	116.857204 =	93.485763
714		1.150000 x	7.050743 =	8.108354

T.E = 115.908952

4220B 8 4220B 8

319		.020000 x	22.070000 =	.441400
111		.400000 x	15.315315 =	6.126126
4220A	4	.800000 x	124.336217 =	99.468974
701	2	.320000 x	4.911777 =	1.571769
609		.320000 x	19.298563 =	6.175540
714		1.150000 x	7.050743 =	8.108354

T.E = 121.892163

4230 1 4230 1

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.069860 =	.767465
701	2	.500000 x	4.911777 =	2.455889
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630
319		.020000 x	22.070000 =	.441400

T.E = 137.022015

4230 2 4230 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.315315 =	30.630630
407		.040000 x	711.559495 =	28.462380
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036

T.E = 144.501028

4230 3 4230 3

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
319		.020000 x	22.070000 =	.441400
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630

T.E = 146.627050

4230 4 4230 4

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	4	.800000 x	4.604791 =	3.683833
630		.250000 x	3.159703 =	.789926
319		.020000 x	22.070000 =	.441400
113		1.200000 x	19.864197 =	23.837036
407		.040000 x	711.559495 =	28.462380
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
714		1.150000 x	7.050743 =	8.108354
111		2.000000 x	15.315315 =	30.630630

T.E = 154.106063

4240 1 4240 1

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.069860 =	.767465
701	2	.500000 x	4.911777 =	2.455889
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
607		.500000 x	10.266974 =	5.133487
606		.800000 x	9.363783 =	7.491026
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630
319		.020000 x	22.070000 =	.441400

T.E = 142.017015

4240 2 4240 2

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	2	.800000 x	4.911777 =	3.929422
630		.250000 x	3.159703 =	.789926
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.315315 =	30.630630
407		.040000 x	711.559495 =	28.462380
611		.500000 x	25.531986 =	12.765993
606		.800000 x	9.363783 =	7.491026
714		1.150000 x	7.050743 =	8.108354
113		1.200000 x	19.864197 =	23.837036

T.E = 149.496028

4240 3 4240 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.069860 =	.767465
701	4	.800000 x	4.604791 =	3.683833
701	2	.500000 x	4.911777 =	2.455889
630		.250000 x	3.159703 =	.789926
610		.800000 x	21.677063 =	17.341650
607		.500000 x	10.266974 =	5.133487
407		.040000 x	711.559495 =	28.462380
714		1.150000 x	7.050743 =	8.108354
319		.020000 x	22.070000 =	.441400
113		1.200000 x	19.864197 =	23.837036
111		2.000000 x	15.315315 =	30.630630

T.E = 151.622050

4240 4 4240 4

221		300.000000 x	.099900 =	29.970000
319		.020000 x	22.070000 =	.441400
113		1.200000 x	19.864197 =	23.837036
714		1.150000 x	7.050743 =	8.108354
701	5	.250000 x	3.069860 =	.767465
701	4	.500000 x	4.604791 =	2.302396
701	4	.800000 x	4.604791 =	3.683833
630		.250000 x	3.159703 =	.789926
611		.500000 x	25.531986 =	12.765993
610		.800000 x	21.677063 =	17.341650
407		.040000 x	711.559495 =	28.462380
111		2.000000 x	15.315315 =	30.630630

T.E = 159.101063

4300 1 4300 1

4300A	1	1.000000 x	29.314123 =	29.314123
4300B		1.000000 x	10.857305 =	10.857305

T.E = 40.171428

3 μ

2012

. 49
μ/ 27/12/2013

4300 2 4300 2

4300A 2
4300B

1.000000 x
1.000000 x

30.809926 =
10.857305 =

30.809926
10.857305

T.E = 41.667231

4300 3 4300 3

4300A 3
4300B

1.000000 x
1.000000 x

31.235130 =
10.857305 =

31.235130
10.857305

T.E = 42.092435

4300 4 4300 4

4300A 4
4300B

1.000000 x
1.000000 x

32.730933 =
10.857305 =

32.730933
10.857305

T.E = 43.588238

4400 4400

251
113

1.050000 x
.050000 x

.559100 =
19.864197 =

.587055
.993210

T.E = 1.580265

4500 4500

251
113
114

1.050000 x
.100000 x
.100000 x

.559100 =
19.864197 =
16.843762 =

.587055
1.986420
1.684376

T.E = 4.257851

4600 4600

256
113

1.000000 x
.100000 x

4.300000 =
19.864197 =

4.300000
1.986420

T.E = 6.286420

4700 4700

253
113

1.000000 x
.100000 x

4.500000 =
19.864197 =

4.500000
1.986420

T.E = 6.486420