

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

2ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	Κατχ Τιμή X 1.8117/ 6.46	15.951934
002	Κατχ Τιμή X 1.8117/ 6.46	17.729980
003	Κατχ Τιμή X 1.8117/ 6.46	23.479183
004	Κατχ Τιμή X 1.8117/ 6.67	22.739959
005	Κατχ Τιμή X 1.8117/ 6.67	18.893831
006	(Κατχ Τιμή + Εξαπτ.Τιμή X .8117)	158.009496
007	(Κατχ Τιμή + Εξαπτ.Τιμή X .8117)	158.009496
008	Κατχ Τιμή X 1.8117/ 6.67	18.893831
009		.074800
011		52.260000
012		4.290000
013		25.900000
014		254.090000
015		199.590000
016		30.830000
017		367.070000
018.1		2.830000
018.2		4.290000
019.1		2.830000
019.2		4.290000
021		2.670000
022		.070000
024		50.000000
026		.097700
027		.117200
029		.149900
032		35.000000
035		.125600
036		.128500
040		.203400
051		15.400000
052		15.400000
053		.070000
054		.080000
055		.090000
056		10.580000
057		10.580000
058		9.090000
061		13.560000
062		13.560000
065		13.610000
066		35.000000
067		45.000000
081		11.010000
101		
102		
111		.078400
112		.087900
113		.570000
114		
116		.090300
117		
118		
124		5.900000
127		83.240000
128		90.430000
131		.650000
132		.930000
142		.325000

146	.340000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.281700
181	
201	290.000000
203.2	335.000000
203.4	210.000000
205	420.000000
208	1,239.000000
210	
211	
212	1,400.000000
214	
219	3.500000
223.1	1,700.000000
223.2	1,450.000000
223.3	1,135.000000
223.4	1,440.000000
225	4.000000
226	11.500000
227	11.500000
228	35.000000
229	
230	
231	20.000000
232	45.000000
233	21.300000
234	2.700000
236	2.600000
237	1.100000
238	2.600000
240	1.600000
241	
242	1.300000
243.1	2.660000
243.2	3.650000
243.3	4.450000
243.5	6.250000
244	
245	18.600000
246	9.000000
249	19.000000
251	.650000
252	1.750000
253	2.200000
254	2.780000
258	7.377000
259	24.070000
260	.492800
261	.523400
262	.492800
264	1.008000
265	.641500
266	.553000

267	.716500
268	.826500
271	.736500
272	.666500
273	.836500
274	1.031800
276	.518500
277	.754000
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.719000
283	1.000100
284	
285	.052500
286	1.627700
288	1.766700
289	.707000
290	3.300000
291	5.000000
293	
294	3.099000
295	5.649200
296	11.781900
297.2	
298.1	4.210000
298.2	3.620000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600

372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	13.560000
403	15.880000
406	19.630000
409	23.370000
410	31.790000
411	29.680000
412	32.030000
414	23.370000
415	23.370000
418	32.720000
419	32.720000
421	108.710000
422	149.410000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.085000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000

481	5.535000
482	.829400
483	.165000
484	3.800000
485	.779800
487	13.480000
488	5.000000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.006100
498	1.124000
499	1.540900
500	2.266200
501	3.070000
502	4.230000
503	1.006100
504	1.332400
505	19.170000
506	1.149500
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	48.900000
515	41.230000
519	52.970000
520	47.060000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.060000
565.5	4.530000
565.6	6.290000
566.3	4.090000
566.5	6.240000
566.6	8.330000

1101	1101			
001		.500000 x	15.951934 =	7.975967

			B.T =	7.975967
1102	1102			
001		1.000000 x	15.951934 =	15.951934

			B.T =	15.951934
1103	1103			
001		.300000 x	15.951934 =	4.785580

			B.T =	4.785580
1104	1104			
015		1.000000 x	199.590000 =	199.590000
291		2.200000 x	5.000000 =	11.000000
004		7.000000 x	22.739959 =	159.179713
002		7.000000 x	17.729980 =	124.109860
484		5.250000 x	3.800000 =	19.950000
485		83.000000 x	.779800 =	64.723400

			AΘΡΟΙΣΜΑ =	578.552973
	B.T =	.004000 x	578.552973 =	2.314212

1111	1111			
006		.060000 x	158.009496 =	9.480570

			B.T =	9.480570
1112	1112			
006		.090000 x	158.009496 =	14.220855

			B.T =	14.220855
1116	1116			
007		.025000 x	158.009496 =	3.950237

			B.T =	3.950237
1117	1117			
007		.110000 x	158.009496 =	17.381045

			B.T =	17.381045
1121	1121			
009		4.000000 x	.074800 =	.299200

			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.951934 =	6.380774

			B.T =	6.380774
1127	1127			
001		.130000 x	15.951934 =	2.073751

			B.T =	2.073751
1128	1128			
006		.024000 x	158.009496 =	3.792228

			B.T =	3.792228
1131	1131			
007		.090000 x	158.009496 =	14.220855

			B.T =	14.220855
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000

			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600

			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800

			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100

			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.097700 =	14.655000

			B.T =	39.374250
1417	1417			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.290000 x	37.605000 =	10.905450
026		150.000000 x	.097700 =	14.655000

			B.T =	39.954450

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000
026		150.000000 x	.097700 =	14.655000

			B.T =	41.286750
1421	1421			
021		.200000 x	2.670000 =	.534000
1407		.540000 x	37.605000 =	20.306700
051		.540000 x	15.400000 =	8.316000
039		4.000000 x	.000000 =	.000000

			B.T =	
1422	1422			
021		.250000 x	2.670000 =	.667500
039		5.000000 x	.000000 =	.000000
051		.330000 x	15.400000 =	5.082000
1407		.620000 x	37.605000 =	23.315100
035		75.000000 x	.125600 =	9.420000

			B.T =	
1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

			B.T =	152.456250
1427	1427			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.097700 =	14.655000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000

			B.T =	162.974700
1428	1428			
021		.200000 x	2.670000 =	.534000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.090000 =	108.000000
051		.200000 x	15.400000 =	3.080000

			B.T =	126.656000

1429	1429			
021		.200000 x	2.670000 =	.534000
035		200.000000 x	.125600 =	25.120000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

			B.T =	148.696000
1431	1431			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
032		.960000 x	35.000000 =	33.600000

			B.T =	46.434600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	15.400000 =	9.856000
032		.320000 x	35.000000 =	11.200000

			B.T =	33.890600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.125600 =	138.160000

			B.T =	139.094500
1437	1437			
021		.200000 x	2.670000 =	.534000
1407		.620000 x	37.605000 =	23.315100
051		.380000 x	15.400000 =	5.852000
035		75.000000 x	.125600 =	9.420000

			B.T =	39.121100
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.097700 =	24.425000

			B.T =	26.561000
1442	1442			
021		.250000 x	2.670000 =	.667500
051		.740000 x	15.400000 =	11.396000
026		900.000000 x	.097700 =	87.930000

			B.T =	99.993500

1443	1443			
021		.250000 x	2.670000 =	.667500
051		.860000 x	15.400000 =	13.244000
026		700.000000 x	.097700 =	68.390000

			B.T =	82.301500
1444	1444			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.097700 =	58.620000
051		1.000000 x	15.400000 =	15.400000

			B.T =	74.687500
1445	1445			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.097700 =	43.965000
051		1.060000 x	15.400000 =	16.324000

			B.T =	60.956500
1446	1446			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.097700 =	34.195000
051		1.120000 x	15.400000 =	17.248000

			B.T =	52.110500
1447	1447			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	15.400000 =	15.400000
026		400.000000 x	.097700 =	39.080000

			B.T =	58.155900
1448	1448			
021		.250000 x	2.670000 =	.667500
039		5.000000 x	.000000 =	.000000
026		400.000000 x	.097700 =	39.080000
051		1.000000 x	15.400000 =	15.400000
1407		.080000 x	37.605000 =	3.008400

			B.T =	58.155900
1449	1449			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.097700 =	34.195000
1407		.040000 x	37.605000 =	1.504200
051		1.060000 x	15.400000 =	16.324000

			B.T =	52.690700

1451	1451			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
026		600.000000 x	.097700 =	58.620000
053		1,500.000000 x	.070000 =	105.000000

			B.T =	166.167750
1452	1452			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.070000 =	105.000000
029		600.000000 x	.149900 =	89.940000

			B.T =	197.487750
1453	1453			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.097700 =	43.965000
053		1,650.000000 x	.070000 =	115.500000
1407		.050000 x	37.605000 =	1.880250

			B.T =	162.012750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.149900 =	67.455000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000

			B.T =	185.502750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.070000 =	115.500000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.080000 =	120.000000
026		600.000000 x	.097700 =	58.620000

			B.T =	181.167750

1457	1457			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.149900 =	89.940000
054		1,500.000000 x	.080000 =	120.000000
1407		.050000 x	37.605000 =	1.880250

			B.T =	212.487750
1458	1458			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.149900 =	67.455000
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.080000 =	132.000000

			B.T =	202.002750
1461	1461			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
053		1,500.000000 x	.070000 =	105.000000
026		500.000000 x	.097700 =	48.850000

			B.T =	157.525900
1462	1462			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000
026		400.000000 x	.097700 =	39.080000

			B.T =	84.531250
1463	1463			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
026		250.000000 x	.097700 =	24.425000
515		1.050000 x	41.230000 =	43.291500
051		.100000 x	15.400000 =	1.540000

			B.T =	71.937750

1464	1464			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
519		.600000 x	52.970000 =	31.782000
051		.420000 x	15.400000 =	6.468000
026		150.000000 x	.097700 =	14.655000
			B.T =	57.951600
1465	1465			
021		.200000 x	2.670000 =	.534000
1407		.030000 x	37.605000 =	1.128150
519		.900000 x	52.970000 =	47.673000
051		.150000 x	15.400000 =	2.310000
026		450.000000 x	.097700 =	43.965000
			B.T =	95.610150
1466	1466			
021		.200000 x	2.670000 =	.534000
1407		.030000 x	37.605000 =	1.128150
519		.840000 x	52.970000 =	44.494800
026		450.000000 x	.097700 =	43.965000
051		.210000 x	15.400000 =	3.234000
			B.T =	93.355950
1467	1467			
021		.200000 x	2.670000 =	.534000
026		450.000000 x	.097700 =	43.965000
051		.350000 x	15.400000 =	5.390000
1407		.030000 x	37.605000 =	1.128150
519		.700000 x	52.970000 =	37.079000
			B.T =	88.096150
1471	1471			
251		1.000000 x	.650000 =	.650000
351		4.000000 x	.668400 =	2.673600
358		1.000000 x	3.035000 =	3.035000
364		2.000000 x	1.030000 =	2.060000
372		.400000 x	2.246200 =	.898480
370		6.000000 x	.267400 =	1.604400
			ΑΘΡΟΙΣΜΑ =	10.921480
	B.T =	.476190 x	10.921480 =	5.200700

1472	1472			
251		.600000 x	.650000 =	.390000
351		2.000000 x	.668400 =	1.336800
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
			ΑΘΡΟΙΣΜΑ =	9.445760
	B.T =	.666667 x	9.445760 =	6.297176
1473	1473			
251		.500000 x	.650000 =	.325000
354		4.000000 x	.895800 =	3.583200
364		2.000000 x	1.030000 =	2.060000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
351		4.000000 x	.668400 =	2.673600
			ΑΘΡΟΙΣΜΑ =	26.000040
	B.T =	.416667 x	26.000040 =	10.833359
1474	1474			
251		.500000 x	.650000 =	.325000
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			ΑΘΡΟΙΣΜΑ =	31.567000
	B.T =	.416667 x	31.567000 =	13.152927
1475	1475			
251		.300000 x	.650000 =	.195000
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			ΑΘΡΟΙΣΜΑ =	89.915600
	B.T =	.416667 x	89.915600 =	37.464863

1476	1476			
251		.500000 x	.650000 =	.325000
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000

			ΑΘΡΟΙΣΜΑ =	5.516760
	B.T =	.500000 x	5.516760 =	2.758380

1478	1478			
251		3.000000 x	.650000 =	1.950000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400

			ΑΘΡΟΙΣΜΑ =	5.880500
	B.T =	.500000 x	5.880500 =	2.940250

1479	1479			
251		6.000000 x	.650000 =	3.900000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000

			ΑΘΡΟΙΣΜΑ =	75.078800
	B.T =	.454545 x	75.078800 =	34.126693

1480	1480			
251		8.000000 x	.650000 =	5.200000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400

			ΑΘΡΟΙΣΜΑ =	145.418400
	B.T =	.227273 x	145.418400 =	33.049676

1485	1485			
021		.000500 x	2.670000 =	.001335
451		.230000 x	1.178800 =	.271124
453		.230000 x	.085000 =	.019550
487		.040000 x	13.480000 =	.539200

			B.T =	.831209
1487	1487			
443		.120000 x	1.930000 =	.231600
445		.060000 x	1.553500 =	.093210
453		.640000 x	.085000 =	.054400
451		.170000 x	1.178800 =	.200396
446		.010000 x	2.540000 =	.025400

			B.T =	.605006

1488	1488			
444		.170000 x	2.143200 =	.364344
445		.050000 x	1.553500 =	.077675
451		.170000 x	1.178800 =	.200396
453		.500000 x	.085000 =	.042500
446		.030000 x	2.540000 =	.076200

			B.T =	.761115
1489	1489			
444		.100000 x	2.143200 =	.214320
446		.020000 x	2.540000 =	.050800
453		.430000 x	.085000 =	.036550
451		.350000 x	1.178800 =	.412580
445		.100000 x	1.553500 =	.155350

			B.T =	.869600
1490	1490			
444		.300000 x	2.143200 =	.642960
451		.570000 x	1.178800 =	.671916
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200

			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800

			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000
446		.030000 x	2.540000 =	.076200

			B.T =	2.756980
1501	1501			
011		1.000000 x	52.260000 =	52.260000
012		2.000000 x	4.290000 =	8.580000
005		3.500000 x	18.893831 =	66.128409
005		14.000000 x	18.893831 =	264.513634
485		15.000000 x	.779800 =	11.697000
484		1.750000 x	3.800000 =	6.650000

			B.T =	409.829043

1502	1502			
013		1.000000 x	25.900000 =	25.900000
001		26.000000 x	15.951934 =	414.750284
005		3.500000 x	18.893831 =	66.128409
484		.900000 x	3.800000 =	3.420000
482		15.000000 x	.829400 =	12.441000

			B.T =	522.639693
1503	1503			
014		1.000000 x	254.090000 =	254.090000
002		2.600000 x	17.729980 =	46.097948
004		7.000000 x	22.739959 =	159.179713
485		44.000000 x	.779800 =	34.311200
484		2.600000 x	3.800000 =	9.880000

			B.T =	503.558861
1504	1504			
015		1.000000 x	199.590000 =	199.590000
004		7.000000 x	22.739959 =	159.179713
002		7.000000 x	17.729980 =	124.109860
485		83.000000 x	.779800 =	64.723400
484		5.250000 x	3.800000 =	19.950000
291		2.200000 x	5.000000 =	11.000000

			B.T =	578.552973
1505	1505			
016		1.000000 x	30.830000 =	30.830000
004		7.000000 x	22.739959 =	159.179713
002		1.750000 x	17.729980 =	31.027465
485		17.500000 x	.779800 =	13.646500
484		1.750000 x	3.800000 =	6.650000

			B.T =	241.333678
1506	1506			
017		1.000000 x	367.070000 =	367.070000
002		3.500000 x	17.729980 =	62.054930
484		6.000000 x	3.800000 =	22.800000
004		7.000000 x	22.739959 =	159.179713
485		70.000000 x	.779800 =	54.586000

			B.T =	665.690643
2101	2101			
002		.300000 x	17.729980 =	5.318994

			T.E =	5.318994

2102	2102			
002		.400000 x	17.729980 =	7.091992

			T.E =	7.091992
2103	2103			
002		.400000 x	17.729980 =	7.091992

			T.E =	7.091992
2104A	2104A			
002		.900000 x	17.729980 =	15.956982

			T.E =	15.956982
2104B	2104B			
002		1.400000 x	17.729980 =	24.821972

			T.E =	24.821972
2104E	2104E			
002		2.900000 x	17.729980 =	51.416942

			T.E =	51.416942
2104H	2104H			
002		4.400000 x	17.729980 =	78.011912

			T.E =	78.011912
2104Z	2104Z			
002		3.900000 x	17.729980 =	69.146922

			T.E =	69.146922
2104Γ	2104Γ			
002		1.900000 x	17.729980 =	33.686962

			T.E =	33.686962
2104Δ	2104Δ			
002		2.400000 x	17.729980 =	42.551952

			T.E =	42.551952
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.729980 =	60.281932

			T.E =	60.281932

2105A	2105A			
002		.900000 x	17.729980 =	15.956982

			T.E =	15.956982
2105B	2105B			
002		1.400000 x	17.729980 =	24.821972

			T.E =	24.821972
2105E	2105E			
002		2.900000 x	17.729980 =	51.416942

			T.E =	51.416942
2105H	2105H			
002		4.400000 x	17.729980 =	78.011912

			T.E =	78.011912
2105Z	2105Z			
002		3.900000 x	17.729980 =	69.146922

			T.E =	69.146922
2105Γ	2105Γ			
002		1.900000 x	17.729980 =	33.686962

			T.E =	33.686962
2105Δ	2105Δ			
002		2.400000 x	17.729980 =	42.551952

			T.E =	42.551952
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.729980 =	60.281932

			T.E =	60.281932
2106A	2106A			
002		5.900000 x	17.729980 =	104.606882

			T.E =	104.606882
2106B	2106B			
002		7.400000 x	17.729980 =	131.201852

			T.E =	131.201852

2106E	2106E			
002		11.900000 x	17.729980 =	210.986762

			T.E =	210.986762
2106H	2106H			
002		16.400000 x	17.729980 =	290.771672

			T.E =	290.771672
2106I	2106I			
002		19.400000 x	17.729980 =	343.961612

			T.E =	343.961612
2106Z	2106Z			
002		14.900000 x	17.729980 =	264.176702

			T.E =	264.176702
2106Γ	2106Γ			
002		8.900000 x	17.729980 =	157.796822

			T.E =	157.796822
2106Δ	2106Δ			
002		10.400000 x	17.729980 =	184.391792

			T.E =	184.391792
2106Θ	2106Θ			
002		17.900000 x	17.729980 =	317.366642

			T.E =	317.366642
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.729980 =	237.581732

			T.E =	237.581732
2107A	2107A			
002		5.900000 x	17.729980 =	104.606882

			T.E =	104.606882
2107B	2107B			
002		7.400000 x	17.729980 =	131.201852

			T.E =	131.201852

2107E	2107E			
002		11.900000 x	17.729980 =	210.986762

			T.E =	210.986762
2107H	2107H			
002		16.400000 x	17.729980 =	290.771672

			T.E =	290.771672
2107I	2107I			
002		19.400000 x	17.729980 =	343.961612

			T.E =	343.961612
2107Z	2107Z			
002		14.900000 x	17.729980 =	264.176702

			T.E =	264.176702
2107Γ	2107Γ			
002		8.900000 x	17.729980 =	157.796822

			T.E =	157.796822
2107Δ	2107Δ			
002		10.400000 x	17.729980 =	184.391792

			T.E =	184.391792
2107Θ	2107Θ			
002		17.900000 x	17.729980 =	317.366642

			T.E =	317.366642
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.729980 =	237.581732

			T.E =	237.581732
2108Α	2108Α			
002		.700000 x	17.729980 =	12.410986

			T.E =	12.410986
2108Β	2108Β			
002		1.600000 x	17.729980 =	28.367968

			T.E =	28.367968

2108Ε	2108Ε			
002		4.600000 x	17.729980 =	81.557908

			T.E =	81.557908
2108Η	2108Η			
002		7.600000 x	17.729980 =	134.747848

			T.E =	134.747848
2108Ζ	2108Ζ			
002		6.600000 x	17.729980 =	117.017868

			T.E =	117.017868
2108Γ	2108Γ			
002		2.600000 x	17.729980 =	46.097948

			T.E =	46.097948
2108Δ	2108Δ			
002		3.600000 x	17.729980 =	63.827928

			T.E =	63.827928
2108Θ	2108Θ			
002		8.600000 x	17.729980 =	152.477828

			T.E =	152.477828
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.729980 =	99.287888

			T.E =	99.287888
2109	2109			
002		.030000 x	17.729980 =	.531899
1506		.004000 x	665.690643 =	2.662763
1503		.001000 x	503.558861 =	.503559

			T.E =	3.698221
2110	2110			
002		.040000 x	17.729980 =	.709199
1501		.005000 x	409.829043 =	2.049145
1506		.004000 x	665.690643 =	2.662763
1503		.001000 x	503.558861 =	.503559

			T.E =	5.924666

2111	2111			
002		.100000 x	17.729980 =	1.772998
1504		.005000 x	578.552973 =	2.892765

			T.E =	4.665763
2112	2112			
002		.120000 x	17.729980 =	2.127598
1504		.005500 x	578.552973 =	3.182041
1501		.004000 x	409.829043 =	1.639316

			T.E =	6.948955
2113	2113			
002		1.400000 x	17.729980 =	24.821972
002		.300000 x	17.729980 =	5.318994

			T.E =	30.140966
2114	2114			
002		1.500000 x	17.729980 =	26.594970
1501		.005000 x	409.829043 =	2.049145
002		.400000 x	17.729980 =	7.091992

			T.E =	35.736107
2115	2115			
481		.300000 x	5.535000 =	1.660500
003		1.200000 x	23.479183 =	28.175020
1501		.011000 x	409.829043 =	4.508119
002		.600000 x	17.729980 =	10.637988

			T.E =	44.981627
2116	2116			
2115		1.300000 x	44.981627 =	58.476115

			T.E =	58.476115
2117	2117			
002		.600000 x	17.729980 =	10.637988
1501		.125000 x	409.829043 =	51.228630

			T.E =	61.866618
2118	2118			
2117		1.300000 x	61.866618 =	80.426603

			T.E =	80.426603

2121	2121			
001		.400000 x	15.951934 =	6.380774
002		1.800000 x	17.729980 =	31.913964

			T.E =	38.294738
2122	2122			
001		.500000 x	15.951934 =	7.975967
1501		.005000 x	409.829043 =	2.049145
002		2.000000 x	17.729980 =	35.459960

			T.E =	45.485072
2123	2123			
002		.200000 x	17.729980 =	3.545996
1504		.008300 x	578.552973 =	4.801990

			T.E =	8.347986
2124	2124			
002		.200000 x	17.729980 =	3.545996
1501		.005000 x	409.829043 =	2.049145
1504		.010000 x	578.552973 =	5.785530

			T.E =	11.380671
2125	2125			
481		.400000 x	5.535000 =	2.214000
1501		.020000 x	409.829043 =	8.196581
002		1.000000 x	17.729980 =	17.729980
003		1.500000 x	23.479183 =	35.218775

			T.E =	63.359335
2126	2126			
2125		1.300000 x	63.359335 =	82.367136

			T.E =	82.367136
2127	2127			
002		1.000000 x	17.729980 =	17.729980
1501		.166600 x	409.829043 =	68.277519

			T.E =	86.007499
2128	2128			
2127		1.300000 x	86.007499 =	111.809749

			T.E =	111.809749

2131	2131			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
2132	2132			
1504		.001600 x	578.552973 =	.925685

			T.E =	.925685
2133	2133			
002		.100000 x	17.729980 =	1.772998
002		.600000 x	17.729980 =	10.637988

			T.E =	12.410986
2134	2134			
1504		.002500 x	578.552973 =	1.446382

			T.E =	1.446382
2135.1	2135.1			
2121		1.300000 x	38.294738 =	49.783159

			T.E =	49.783159
2135.2	2135.2			
2122		1.300000 x	45.485072 =	59.130594

			T.E =	59.130594
2135.3	2135.3			
2127		1.300000 x	86.007499 =	111.809749

			T.E =	111.809749
2135.4	2135.4			
2128		1.300000 x	111.809749 =	145.352674

			T.E =	145.352674
2141	2141			
001		2.000000 x	15.951934 =	31.903868
003		2.500000 x	23.479183 =	58.697958

			T.E =	90.601826

2142	2142			
001		2.000000 x	15.951934 =	31.903868
1501		.005000 x	409.829043 =	2.049145
003		3.000000 x	23.479183 =	70.437549

			T.E =	104.390562
2143	2143			
481		.500000 x	5.535000 =	2.767500
001		2.000000 x	15.951934 =	31.903868
003		3.000000 x	23.479183 =	70.437549
1501		.025000 x	409.829043 =	10.245726

			T.E =	115.354643
2144	2144			
2143		1.300000 x	115.354643 =	149.961036

			T.E =	149.961036
2145	2145			
001		2.000000 x	15.951934 =	31.903868
003		1.000000 x	23.479183 =	23.479183
1501		.200000 x	409.829043 =	81.965809

			T.E =	137.348860
2146	2146			
2145		1.300000 x	137.348860 =	178.553518

			T.E =	178.553518
2151	2151			
001		1.200000 x	15.951934 =	19.142321
003		.800000 x	23.479183 =	18.783346

			T.E =	37.925667
2152	2152			
001		1.500000 x	15.951934 =	23.927901
003		1.000000 x	23.479183 =	23.479183

			T.E =	47.407084
2161	2161			
1505		.003300 x	241.333678 =	.796401

			T.E =	.796401

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.951934 =	12.761547

			T.E =	13.028547
2163	2163			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	578.552973 =	2.314212

			T.E =	2.463812
2172	2172			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547
2173	2173			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2174	2174			
007		.050000 x	158.009496 =	7.900475

			T.E =	7.900475
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547

2178	2178			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
2179	2179			
007		.018000 x	158.009496 =	2.844171

			T.E =	2.844171
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.830000 =	.404124
005		.400000 x	18.893831 =	7.557532
484		.100000 x	3.800000 =	.380000
482		.700000 x	.829400 =	.580580
018.1		.042800 x	2.830000 =	.121124

			T.E =	9.043360
2186	2186			
018.2		.142800 x	4.290000 =	.612612
005		.400000 x	18.893831 =	7.557532
018.2		.042800 x	4.290000 =	.183612
482		1.400000 x	.829400 =	1.161160
484		.200000 x	3.800000 =	.760000

			T.E =	10.274916
2187	2187			
019.1		.142800 x	2.830000 =	.404124
485		1.100000 x	.779800 =	.857780
019.1		.428000 x	2.830000 =	1.211240
005		.400000 x	18.893831 =	7.557532
484		.100000 x	3.800000 =	.380000

			T.E =	10.410676
2188	2188			
019.2		.142800 x	4.290000 =	.612612
005		.400000 x	18.893831 =	7.557532
485		1.800000 x	.779800 =	1.403640
484		.200000 x	3.800000 =	.760000
019.2		.042800 x	4.290000 =	.183612

			T.E =	10.517396

2201	2201			
001		1.000000 x	15.951934 =	15.951934
002		2.000000 x	17.729980 =	35.459960

			T.E =	51.411894
2202	2202			
001		1.000000 x	15.951934 =	15.951934
002		5.000000 x	17.729980 =	88.649900

			T.E =	104.601834
2203	2203			
001		1.000000 x	15.951934 =	15.951934
002		2.500000 x	17.729980 =	44.324950

			T.E =	60.276884
2204	2204			
001		1.000000 x	15.951934 =	15.951934
002		5.000000 x	17.729980 =	88.649900

			T.E =	104.601834
2206	2206			
001		1.000000 x	15.951934 =	15.951934
003		3.000000 x	23.479183 =	70.437549

			T.E =	86.389483
2207	2207			
001		1.000000 x	15.951934 =	15.951934
003		6.000000 x	23.479183 =	140.875098

			T.E =	156.827032
2211	2211			
001		2.000000 x	15.951934 =	31.903868

			T.E =	31.903868
2212	2212			
001		1.000000 x	15.951934 =	15.951934

			T.E =	15.951934
2213	2213			
001		2.000000 x	15.951934 =	31.903868

			T.E =	31.903868

2214	2214			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2221	2221			
001		1.200000 x	15.951934 =	19.142321
002		1.600000 x	17.729980 =	28.367968

			T.E =	47.510289
2222	2222			
001		1.200000 x	15.951934 =	19.142321
002		2.500000 x	17.729980 =	44.324950

			T.E =	63.467271
2223	2223			
001		3.000000 x	15.951934 =	47.855802

			T.E =	47.855802
2224	2224			
001		5.000000 x	15.951934 =	79.759670

			T.E =	79.759670
2226	2226			
001		1.500000 x	15.951934 =	23.927901
002		5.000000 x	17.729980 =	88.649900

			T.E =	112.577801
2227	2227			
001		1.500000 x	15.951934 =	23.927901
002		12.000000 x	17.729980 =	212.759760

			T.E =	236.687661
2231	2231			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2232	2232			
003		.020000 x	23.479183 =	.469584

			T.E =	.469584

2236	2236			
001		.100000 x	15.951934 =	1.595193
002		.300000 x	17.729980 =	5.318994

			T.E =	6.914187
2237	2237			
001		.200000 x	15.951934 =	3.190387
003		.700000 x	23.479183 =	16.435428

			T.E =	19.625815
2238	2238			
001		.100000 x	15.951934 =	1.595193
002		.400000 x	17.729980 =	7.091992

			T.E =	8.687185
2239	2239			
001		.200000 x	15.951934 =	3.190387
003		.800000 x	23.479183 =	18.783346

			T.E =	21.973733
2241	2241			
001		.300000 x	15.951934 =	4.785580
003		.100000 x	23.479183 =	2.347918

			T.E =	7.133499
2242	2242			
001		.400000 x	15.951934 =	6.380774
003		.150000 x	23.479183 =	3.521877

			T.E =	9.902651
2243	2243			
001		.500000 x	15.951934 =	7.975967
003		.250000 x	23.479183 =	5.869796

			T.E =	13.845763
2246	2246			
001		.250000 x	15.951934 =	3.987984
003		.050000 x	23.479183 =	1.173959

			T.E =	5.161943

2247	2247			
001		.350000 x	15.951934 =	5.583177
003		.100000 x	23.479183 =	2.347918

			T.E =	7.931095
2248	2248			
001		.450000 x	15.951934 =	7.178370
003		.200000 x	23.479183 =	4.695837

			T.E =	11.874207
2251	2251			
001		.100000 x	15.951934 =	1.595193
002		.300000 x	17.729980 =	5.318994

			T.E =	6.914187
2252	2252			
001		.100000 x	15.951934 =	1.595193
002		.600000 x	17.729980 =	10.637988

			T.E =	12.233181
2261A	2261A			
003		.400000 x	23.479183 =	9.391673

			T.E =	9.391673
2261B	2261B			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
2261Γ	2261Γ			
003		.900000 x	23.479183 =	21.131265

			T.E =	21.131265
2261Δ	2261Δ			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
2262A	2262A			
003		.550000 x	23.479183 =	12.913551

			T.E =	12.913551

2262B	2262B			
003		.900000 x	23.479183 =	21.131265

			T.E =	21.131265
2262Γ	2262Γ			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
2262Δ	2262Δ			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2263Α	2263Α			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
2263Β	2263Β			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
2263Γ	2263Γ			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2263Δ	2263Δ			
003		2.100000 x	23.479183 =	49.306284

			T.E =	49.306284
2264.1Α	2264.1Α			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2264.1Β	2264.1Β			
003		1.850000 x	23.479183 =	43.436489

			T.E =	43.436489
2264.1Γ	2264.1Γ			
003		2.100000 x	23.479183 =	49.306284

			T.E =	49.306284

2264.1Δ	2264.1Δ			
003		2.300000 x	23.479183 =	54.002121

			T.E =	54.002121
2264.2A	2264.2A			
003		2.000000 x	23.479183 =	46.958366

			T.E =	46.958366
2264.2B	2264.2B			
003		2.400000 x	23.479183 =	56.350039

			T.E =	56.350039
2264.2Γ	2264.2Γ			
003		2.800000 x	23.479183 =	65.741712

			T.E =	65.741712
2264.2Δ	2264.2Δ			
003		3.200000 x	23.479183 =	75.133386

			T.E =	75.133386
2264.3A	2264.3A			
003		2.400000 x	23.479183 =	56.350039

			T.E =	56.350039
2264.3B	2264.3B			
003		2.850000 x	23.479183 =	66.915672

			T.E =	66.915672
2264.3Γ	2264.3Γ			
003		3.300000 x	23.479183 =	77.481304

			T.E =	77.481304
2264.3Δ	2264.3Δ			
003		3.750000 x	23.479183 =	88.046936

			T.E =	88.046936
2265A	2265A			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592

ΑΤΟΕ	2ο Τρίμηνο του 2009		Σελ. Ημ/νία	37 26/05/2010
2265B	2265B			
003		.800000 x	23.479183 =	18.783346

			T.E =	18.783346
2266.1	2266.1			
2261A		1.000000 x	9.391673 =	9.391673
2261A		.350000 x	9.391673 =	3.287086

			T.E =	12.678759
2266.10	2266.10			
2263B		1.000000 x	28.175020 =	28.175020
2263B		.350000 x	28.175020 =	9.861257

			T.E =	38.036277
2266.11	2266.11			
2263Γ		1.000000 x	37.566693 =	37.566693
2263Γ		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.12	2266.12			
2263Δ		1.000000 x	49.306284 =	49.306284
2263Δ		.350000 x	49.306284 =	17.257199

			T.E =	66.563483
2266.13	2266.13			
2264.1A		1.000000 x	37.566693 =	37.566693
2264.1A		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.14	2266.14			
2264.1B		1.000000 x	43.436489 =	43.436489
2264.1B		.350000 x	43.436489 =	15.202771

			T.E =	58.639260
2266.15	2266.15			
2264.1Γ		1.000000 x	49.306284 =	49.306284
2264.1Γ		.350000 x	49.306284 =	17.257199

			T.E =	66.563483

2266.16	2266.16			
2264.1Δ		1.000000 x	54.002121 =	54.002121
2264.1Δ		.350000 x	54.002121 =	18.900742

			T.E =	72.902863
2266.17	2266.17			
2264.2A		1.000000 x	46.958366 =	46.958366
2264.2A		.350000 x	46.958366 =	16.435428

			T.E =	63.393794
2266.18	2266.18			
2264.2B		1.000000 x	56.350039 =	56.350039
2264.2B		.350000 x	56.350039 =	19.722514

			T.E =	76.072553
2266.19	2266.19			
2264.2Γ		1.000000 x	65.741712 =	65.741712
2264.2Γ		.350000 x	65.741712 =	23.009599

			T.E =	88.751311
2266.2	2266.2			
2261B		1.000000 x	16.435428 =	16.435428
2261B		.350000 x	16.435428 =	5.752400

			T.E =	22.187828
2266.20	2266.20			
2264.2Δ		1.000000 x	75.133386 =	75.133386
2264.2Δ		.350000 x	75.133386 =	26.296685

			T.E =	101.430071
2266.21	2266.21			
2264.3A		1.000000 x	56.350039 =	56.350039
2264.3A		.350000 x	56.350039 =	19.722514

			T.E =	76.072553
2266.22	2266.22			
2264.3B		1.000000 x	66.915672 =	66.915672
2264.3B		.350000 x	66.915672 =	23.420485

			T.E =	90.336157

2266.23	2266.23				
2264.3Γ		1.000000 x	77.481304 =	77.481304	
2264.3Γ		.350000 x	77.481304 =	27.118456	
			T.E =	104.599760	
2266.24	2266.24				
2264.3Δ		1.000000 x	88.046936 =	88.046936	
2264.3Δ		.350000 x	88.046936 =	30.816428	
			T.E =	118.863364	
2266.25	2266.25				
2265A		1.000000 x	11.739592 =	11.739592	
2265A		.350000 x	11.739592 =	4.108857	
			T.E =	15.848449	
2266.26	2266.26				
2265B		1.000000 x	18.783346 =	18.783346	
2265B		.350000 x	18.783346 =	6.574171	
			T.E =	25.357517	
2266.3	2266.3				
2261Γ		1.000000 x	21.131265 =	21.131265	
2261Γ		.350000 x	21.131265 =	7.395943	
			T.E =	28.527208	
2266.4	2266.4				
2261Δ		1.000000 x	28.175020 =	28.175020	
2261Δ		.350000 x	28.175020 =	9.861257	
			T.E =	38.036277	
2266.5	2266.5				
2262A		1.000000 x	12.913551 =	12.913551	
2262A		.350000 x	12.913551 =	4.519743	
			T.E =	17.433294	
2266.6	2266.6				
2262B		1.000000 x	21.131265 =	21.131265	
2262B		.350000 x	21.131265 =	7.395943	
			T.E =	28.527208	

2266.7	2266.7			
2262Γ		1.000000 x	28.175020 =	28.175020
2262Γ		.350000 x	28.175020 =	9.861257

			T.E =	38.036277
2266.8	2266.8			
2262Δ		1.000000 x	37.566693 =	37.566693
2262Δ		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.9	2266.9			
2263A		1.000000 x	16.435428 =	16.435428
2263A		.350000 x	16.435428 =	5.752400

			T.E =	22.187828
2267	2267			
003		3.500000 x	23.479183 =	82.177141

			T.E =	82.177141
2268A	2268A			
003		5.000000 x	23.479183 =	117.395915

			T.E =	117.395915
2268B	2268B			
003		5.900000 x	23.479183 =	138.527180

			T.E =	138.527180
2268Γ	2268Γ			
003		6.400000 x	23.479183 =	150.266771

			T.E =	150.266771
2268Δ	2268Δ			
003		6.900000 x	23.479183 =	162.006363

			T.E =	162.006363
2269A	2269A			
003		2.000000 x	23.479183 =	46.958366

			T.E =	46.958366

2269B	2269B			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549
2269Γ	2269Γ			
003		4.000000 x	23.479183 =	93.916732

			T.E =	93.916732
2270.1	2270.1			
2267		1.000000 x	82.177141 =	82.177141
2267		.600000 x	82.177141 =	49.306285

			T.E =	131.483426
2270.2	2270.2			
2268A		1.000000 x	117.395915 =	117.395915
2268A		.600000 x	117.395915 =	70.437549

			T.E =	187.833464
2270.3	2270.3			
2268B		1.000000 x	138.527180 =	138.527180
2268B		.600000 x	138.527180 =	83.116308

			T.E =	221.643488
2270.4	2270.4			
2268Γ		1.000000 x	150.266771 =	150.266771
2268Γ		.600000 x	150.266771 =	90.160063

			T.E =	240.426834
2270.5	2270.5			
2268Δ		1.000000 x	162.006363 =	162.006363
2268Δ		.600000 x	162.006363 =	97.203818

			T.E =	259.210181
2271A	2271A			
003		2.500000 x	23.479183 =	58.697958

			T.E =	58.697958
2271B	2271B			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549

2271E	2271E			
003		4.500000 x	23.479183 =	105.656324

			T.E =	105.656324
2271H	2271H			
003		6.000000 x	23.479183 =	140.875098

			T.E =	140.875098
2271I	2271I			
003		7.000000 x	23.479183 =	164.354281

			T.E =	164.354281
2271Z	2271Z			
003		5.500000 x	23.479183 =	129.135507

			T.E =	129.135507
2271Γ	2271Γ			
003		3.500000 x	23.479183 =	82.177141

			T.E =	82.177141
2271Δ	2271Δ			
003		4.000000 x	23.479183 =	93.916732

			T.E =	93.916732
2271Θ	2271Θ			
003		6.500000 x	23.479183 =	152.614690

			T.E =	152.614690
2271ΣΤ	2271ΣΤ			
003		5.000000 x	23.479183 =	117.395915

			T.E =	117.395915
2272A	2272A			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549
2272B	2272B			
003		3.700000 x	23.479183 =	86.872977

			T.E =	86.872977

2272E	2272E			
003		5.800000 x	23.479183 =	136.179261

			T.E =	136.179261
2272H	2272H			
003		7.900000 x	23.479183 =	185.485546

			T.E =	185.485546
2272I	2272I			
003		9.300000 x	23.479183 =	218.356402

			T.E =	218.356402
2272Z	2272Z			
003		7.200000 x	23.479183 =	169.050118

			T.E =	169.050118
2272Γ	2272Γ			
003		4.400000 x	23.479183 =	103.308405

			T.E =	103.308405
2272Δ	2272Δ			
003		5.100000 x	23.479183 =	119.743833

			T.E =	119.743833
2272Θ	2272Θ			
003		8.600000 x	23.479183 =	201.920974

			T.E =	201.920974
2272ΣΤ	2272ΣΤ			
003		6.500000 x	23.479183 =	152.614690

			T.E =	152.614690
2273A	2273A			
003		8.500000 x	23.479183 =	199.573056

			T.E =	199.573056
2273B	2273B			
003		10.000000 x	23.479183 =	234.791830

			T.E =	234.791830

2273Γ	2273Γ			
003		11.500000 x	23.479183 =	270.010605

			T.E =	270.010605
2273Δ	2273Δ			
003		13.000000 x	23.479183 =	305.229379

			T.E =	305.229379
2274.1	2274.1			
2271A		1.300000 x	58.697958 =	76.307345

			T.E =	76.307345
2274.10	2274.10			
2271I		1.300000 x	164.354281 =	213.660565

			T.E =	213.660565
2274.11	2274.11			
2272A		1.300000 x	70.437549 =	91.568814

			T.E =	91.568814
2274.12	2274.12			
2272B		1.300000 x	86.872977 =	112.934870

			T.E =	112.934870
2274.13	2274.13			
2272Γ		1.300000 x	103.308405 =	134.300927

			T.E =	134.300927
2274.14	2274.14			
2272Δ		1.300000 x	119.743833 =	155.666983

			T.E =	155.666983
2274.15	2274.15			
2272Ε		1.300000 x	136.179261 =	177.033039

			T.E =	177.033039
2274.16	2274.16			
2272ΣΤ		1.300000 x	152.614690 =	198.399097

			T.E =	198.399097

2274.17	2274.17			
2272Z		1.300000 x	169.050118 =	219.765153

			T.E =	219.765153
2274.18	2274.18			
2272H		1.300000 x	185.485546 =	241.131210

			T.E =	241.131210
2274.19	2274.19			
2272Θ		1.300000 x	201.920974 =	262.497266

			T.E =	262.497266
2274.2	2274.2			
2271B		1.300000 x	70.437549 =	91.568814

			T.E =	91.568814
2274.20	2274.20			
2272I		1.300000 x	218.356402 =	283.863323

			T.E =	283.863323
2274.21	2274.21			
2273A		1.300000 x	199.573056 =	259.444973

			T.E =	259.444973
2274.22	2274.22			
2273B		1.300000 x	234.791830 =	305.229379

			T.E =	305.229379
2274.23	2274.23			
2273Γ		1.300000 x	270.010605 =	351.013787

			T.E =	351.013787
2274.24	2274.24			
2273Δ		1.300000 x	305.229379 =	396.798193

			T.E =	396.798193
2274.3	2274.3			
2271Γ		1.300000 x	82.177141 =	106.830283

			T.E =	106.830283

2274.4	2274.4			
2271Δ		1.300000 x	93.916732 =	122.091752

			T.E =	122.091752
2274.5	2274.5			
2271E		1.300000 x	105.656324 =	137.353221

			T.E =	137.353221
2274.6	2274.6			
2271ΣΤ		1.300000 x	117.395915 =	152.614690

			T.E =	152.614690
2274.7	2274.7			
2271Ζ		1.300000 x	129.135507 =	167.876159

			T.E =	167.876159
2274.8	2274.8			
2271Η		1.300000 x	140.875098 =	183.137627

			T.E =	183.137627
2274.9	2274.9			
2271Θ		1.300000 x	152.614690 =	198.399097

			T.E =	198.399097
2275	2275			
003		1.000000 x	23.479183 =	23.479183

			T.E =	23.479183
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	210.000000 =	6.930000
251		6.000000 x	.650000 =	3.900000
003		5.000000 x	23.479183 =	117.395915
001		9.000000 x	15.951934 =	143.567406

			T.E =	280.493321
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.729980 =	5.318994

			T.E =	5.608994

2303	2303			
001		.250000 x	15.951934 =	3.987984
003		.250000 x	23.479183 =	5.869796

			T.E =	9.857779
2304	2304			
201		.000400 x	290.000000 =	.116000
002		.100000 x	17.729980 =	1.772998

			T.E =	1.888998
2311	2311			
201		.040000 x	290.000000 =	11.600000
203.4		.040000 x	210.000000 =	8.400000
003		7.000000 x	23.479183 =	164.354281
001		9.000000 x	15.951934 =	143.567406
251		6.000000 x	.650000 =	3.900000

			T.E =	331.821687
2312	2312			
201		.002000 x	290.000000 =	.580000
203.4		.002000 x	210.000000 =	.420000
251		.250000 x	.650000 =	.162500
001		.250000 x	15.951934 =	3.987984
003		.150000 x	23.479183 =	3.521877

			T.E =	8.672361
2313	2313			
201		.002000 x	290.000000 =	.580000
251		.200000 x	.650000 =	.130000
203.4		.001000 x	210.000000 =	.210000
003		.100000 x	23.479183 =	2.347918
001		.200000 x	15.951934 =	3.190387

			T.E =	6.458305
2314.1	2314.1			
511		1.000000 x	.489500 =	.489500
003		.030000 x	23.479183 =	.704375

			T.E =	1.193875
2314.2	2314.2			
512		1.000000 x	.375000 =	.375000
003		.030000 x	23.479183 =	.704375

			T.E =	1.079375

3101	3101			
021		.250000 x	2.670000 =	.667500
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
026		175.000000 x	.097700 =	17.097500
052		.430000 x	15.400000 =	6.622000
056		.860000 x	10.580000 =	9.098800

			T.E =	105.752997
3102	3102			
021		.250000 x	2.670000 =	.667500
052		.420000 x	15.400000 =	6.468000
056		.840000 x	10.580000 =	8.887200
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
026		200.000000 x	.097700 =	19.540000

			T.E =	107.829897
3103	3103			
021		.250000 x	2.670000 =	.667500
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
056		.820000 x	10.580000 =	8.675600
052		.410000 x	15.400000 =	6.314000
026		250.000000 x	.097700 =	24.425000

			T.E =	112.349297
3104	3104			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.097700 =	29.310000
052		.400000 x	15.400000 =	6.160000
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
056		.800000 x	10.580000 =	8.464000

			T.E =	116.868697
3111	3111			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	23.479183 =	35.218775
001		4.000000 x	15.951934 =	63.807736
026		200.000000 x	.097700 =	19.540000
057		.840000 x	10.580000 =	8.887200
052		.420000 x	15.400000 =	6.468000

			T.E =	134.589211

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
026		250.000000 x	.097700 =	24.425000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	23.479183 =	35.218775
001		2.000000 x	15.951934 =	31.903868
052		.410000 x	15.400000 =	6.314000

			T.E =	133.336727
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
001		3.000000 x	15.951934 =	47.855802
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.097700 =	29.310000

			T.E =	165.547653
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.097700 =	14.655000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.951934 =	79.759670
052		.420000 x	15.400000 =	6.468000

			T.E =	118.091870
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
026		175.000000 x	.097700 =	17.097500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	110.336197
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.097700 =	19.540000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
052		.560000 x	15.400000 =	8.624000

			T.E =	112.489097

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.097700 =	24.425000

			T.E =	116.794897
3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.097700 =	29.310000
052		.530000 x	15.400000 =	8.162000
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
061		.800000 x	13.560000 =	10.848000

			T.E =	121.254697
3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	23.479183 =	129.135507
001		7.000000 x	15.951934 =	111.663538
026		200.000000 x	.097700 =	19.540000
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000

			T.E =	277.836045
3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.097700 =	24.425000
065		.730000 x	13.610000 =	9.935300
003		5.500000 x	23.479183 =	129.135507
001		7.000000 x	15.951934 =	111.663538
052		.410000 x	15.400000 =	6.314000

			T.E =	282.140845
3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	23.479183 =	70.437549
001		6.000000 x	15.951934 =	95.711604
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.097700 =	19.540000

			T.E =	203.186153

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.097700 =	24.425000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	23.479183 =	70.437549
001		6.000000 x	15.951934 =	95.711604
052		.430000 x	15.400000 =	6.622000

			T.E =	207.798953
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	23.479183 =	35.218775
001		4.000000 x	15.951934 =	63.807736
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.097700 =	19.540000

			T.E =	139.248411
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.097700 =	24.425000
003		1.500000 x	23.479183 =	35.218775
001		2.000000 x	15.951934 =	31.903868
052		.540000 x	15.400000 =	8.316000

			T.E =	137.782327
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
001		3.000000 x	15.951934 =	47.855802
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.097700 =	29.310000

			T.E =	169.933653
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
001		3.500000 x	15.951934 =	55.831769
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.097700 =	34.195000
052		.400000 x	15.400000 =	6.160000
062		.600000 x	13.560000 =	8.136000

			T.E =	181.755320

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
001		3.500000 x	15.951934 =	55.831769
065		.250000 x	13.610000 =	3.402500
027		350.000000 x	.117200 =	41.020000
062		.560000 x	13.560000 =	7.593600
052		.420000 x	15.400000 =	6.468000

			T.E =	188.073720
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.117200 =	49.810000
062		.550000 x	13.560000 =	7.458000
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
001		4.000000 x	15.951934 =	63.807736
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000

			T.E =	203.898287
3217	3217			
001		2.500000 x	15.951934 =	39.879835

			T.E =	39.879835
3218	3218			
001		5.000000 x	15.951934 =	79.759670

			T.E =	79.759670
3219	3219			
001		3.000000 x	15.951934 =	47.855802
003		4.000000 x	23.479183 =	93.916732

			T.E =	141.772534
3220	3220			
001		5.000000 x	15.951934 =	79.759670
003		4.000000 x	23.479183 =	93.916732

			T.E =	173.676402
3221	3221			
001		3.000000 x	15.951934 =	47.855802
003		6.000000 x	23.479183 =	140.875098

			T.E =	188.730900

3222	3222			
001		5.000000 x	15.951934 =	79.759670
003		6.000000 x	23.479183 =	140.875098

			T.E =	220.634768
3223A.1	3223A.1			
001		2.000000 x	15.951934 =	31.903868
1502		.050000 x	522.639693 =	26.131985
003		1.500000 x	23.479183 =	35.218775

			AΘΡΟΙΣΜΑ =	93.254627
	T.E =	.500000 x	93.254627 =	46.627314

3223A.2	3223A.2			
001		3.000000 x	15.951934 =	47.855802
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366

			AΘΡΟΙΣΜΑ =	120.946153
	T.E =	.500000 x	120.946153 =	60.473076

3223A.3	3223A.3			
001		2.000000 x	15.951934 =	31.903868
1502		.050000 x	522.639693 =	26.131985
003		1.500000 x	23.479183 =	35.218775

			AΘΡΟΙΣΜΑ =	93.254627
	T.E =	.500000 x	93.254627 =	46.627314

3223A.4	3223A.4			
001		3.000000 x	15.951934 =	47.855802
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985

			AΘΡΟΙΣΜΑ =	120.946153
	T.E =	.500000 x	120.946153 =	60.473076

3223A.5	3223A.5			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985

			AΘΡΟΙΣΜΑ =	128.922120
	T.E =	.500000 x	128.922120 =	64.461060

3223A.6	3223A.6			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985
			AΘΡΟΙΣΜΑ =	128.922120
	T.E =	.500000 x	128.922120 =	64.461060
3223A.7	3223A.7			
001		4.000000 x	15.951934 =	63.807736
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
			AΘΡΟΙΣΜΑ =	136.898087
	T.E =	.500000 x	136.898087 =	68.449043
3223B.1	3223B.1			
001		2.000000 x	15.951934 =	31.903868
003		1.500000 x	23.479183 =	35.218775
1502		.050000 x	522.639693 =	26.131985
			AΘΡΟΙΣΜΑ =	93.254627
	T.E =	.250000 x	93.254627 =	23.313657
3223B.2	3223B.2			
001		3.000000 x	15.951934 =	47.855802
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985
			AΘΡΟΙΣΜΑ =	120.946153
	T.E =	.250000 x	120.946153 =	30.236538
3223B.3	3223B.3			
001		2.000000 x	15.951934 =	31.903868
003		1.500000 x	23.479183 =	35.218775
1502		.050000 x	522.639693 =	26.131985
			AΘΡΟΙΣΜΑ =	93.254627
	T.E =	.250000 x	93.254627 =	23.313657
3223B.4	3223B.4			
001		3.000000 x	15.951934 =	47.855802
1502		.050000 x	522.639693 =	26.131985
003		2.000000 x	23.479183 =	46.958366
			AΘΡΟΙΣΜΑ =	120.946153
	T.E =	.250000 x	120.946153 =	30.236538

3223B.5	3223B.5			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985

			AΘΡΟΙΣΜΑ =	128.922120
	T.E =	.250000 x	128.922120 =	32.230530

3223B.6	3223B.6			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985

			AΘΡΟΙΣΜΑ =	128.922120
	T.E =	.250000 x	128.922120 =	32.230530

3223B.7	3223B.7			
001		4.000000 x	15.951934 =	63.807736
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	522.639693 =	26.131985

			AΘΡΟΙΣΜΑ =	136.898087
	T.E =	.250000 x	136.898087 =	34.224522

3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.951934 =	79.759670
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.097700 =	14.655000

			T.E =	122.751070
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	35.000000 =	5.250000
056		.800000 x	10.580000 =	8.464000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769

			T.E =	99.123865

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	35.000000 =	7.000000
051		.200000 x	15.400000 =	3.080000
001		3.500000 x	15.951934 =	55.831769
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	23.479183 =	18.783346
056		.800000 x	10.580000 =	8.464000

			T.E =	101.214115
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	35.000000 =	14.000000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769
056		.800000 x	10.580000 =	8.464000

			T.E =	105.134115
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
056		.800000 x	10.580000 =	8.464000
032		.400000 x	35.000000 =	14.000000
026		100.000000 x	.097700 =	9.770000

			T.E =	121.287389
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	35.000000 =	5.600000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769

			T.E =	103.084315
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	35.000000 =	7.350000
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	15.951934 =	55.831769
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	23.479183 =	28.175020
061		.840000 x	13.560000 =	11.390400

			T.E =	114.412239

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	35.000000 =	14.700000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
061		.840000 x	13.560000 =	11.390400

			T.E =	118.528239
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
061		.840000 x	13.560000 =	11.390400
032		.420000 x	35.000000 =	14.700000
026		100.000000 x	.097700 =	9.770000

			T.E =	125.289839
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
052		.294000 x	15.400000 =	4.527600
056		.588000 x	10.580000 =	6.221040
001		2.500000 x	15.951934 =	39.879835
003		1.100000 x	23.479183 =	25.827101
058		.500000 x	9.090000 =	4.545000
026		140.000000 x	.097700 =	13.678000

			T.E =	95.145826
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
026		140.000000 x	.097700 =	13.678000

			T.E =	98.407266
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
026		175.000000 x	.097700 =	17.097500

			T.E =	98.309406

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.097700 =	17.097500
052		.378000 x	15.400000 =	5.821200
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
061		.574000 x	13.560000 =	7.783440

			T.E =	101.421326
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.097700 =	13.678000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
001		2.500000 x	15.951934 =	39.879835
003		1.100000 x	23.479183 =	25.827101
081		.500000 x	11.010000 =	5.505000

			T.E =	96.105826
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.097700 =	13.678000
003		1.100000 x	23.479183 =	25.827101
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	15.951934 =	39.879835
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800

			T.E =	99.367266
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
081		.500000 x	11.010000 =	5.505000
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
026		175.000000 x	.097700 =	17.097500

			T.E =	99.269406

3407.2

3407.2

021	.175000 x	2.670000 =	.467250
026	175.000000 x	.097700 =	17.097500
061	.574000 x	13.560000 =	7.783440
001	2.500000 x	15.951934 =	39.879835
003	1.100000 x	23.479183 =	25.827101
081	.500000 x	11.010000 =	5.505000
052	.378000 x	15.400000 =	5.821200

T.E = 102.381326

3501

3501

021	.200000 x	2.670000 =	.534000
1407	.180000 x	37.605000 =	6.768900
003	2.000000 x	23.479183 =	46.958366
001	5.000000 x	15.951934 =	79.759670
067	1.050000 x	45.000000 =	47.250000
032	.200000 x	35.000000 =	7.000000

T.E = 188.270936

3502

3502

021	.200000 x	2.670000 =	.534000
026	100.000000 x	.097700 =	9.770000
067	1.050000 x	45.000000 =	47.250000
003	2.000000 x	23.479183 =	46.958366
1407	.100000 x	37.605000 =	3.760500
001	5.000000 x	15.951934 =	79.759670
032	.200000 x	35.000000 =	7.000000

T.E = 195.032536

3503

3503

021	.200000 x	2.670000 =	.534000
026	150.000000 x	.097700 =	14.655000
1407	.080000 x	37.605000 =	3.008400
003	2.000000 x	23.479183 =	46.958366
001	5.000000 x	15.951934 =	79.759670
067	1.000000 x	45.000000 =	45.000000
032	.200000 x	35.000000 =	7.000000

T.E = 196.915436

3504

3504

021	.200000 x	2.670000 =	.534000
003	3.200000 x	23.479183 =	75.133386
001	5.000000 x	15.951934 =	79.759670
517	4.000000 x	.000000 =	.000000
055	180.000000 x	.090000 =	16.200000
026	250.000000 x	.097700 =	24.425000

T.E =

3505	3505			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.097700 =	24.425000
517		4.000000 x	.000000 =	.000000
055		420.000000 x	.090000 =	37.800000
003		5.000000 x	23.479183 =	117.395915
001		5.500000 x	15.951934 =	87.735637

			T.E =	
3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	41.230000 =	47.414500
026		200.000000 x	.097700 =	19.540000
001		5.000000 x	15.951934 =	79.759670
003		2.500000 x	23.479183 =	58.697958

			T.E =	206.213128
3511	3511			
021		.200000 x	2.670000 =	.534000
069		1.050000 x	.000000 =	.000000
032		.200000 x	35.000000 =	7.000000
003		2.000000 x	23.479183 =	46.958366
1407		.180000 x	37.605000 =	6.768900
001		5.000000 x	15.951934 =	79.759670

			T.E =	
3512	3512			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.097700 =	9.770000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	23.479183 =	46.958366
001		5.000000 x	15.951934 =	79.759670
069		1.050000 x	.000000 =	.000000
032		.200000 x	35.000000 =	7.000000

			T.E =	
3513	3513			
001		2.500000 x	15.951934 =	39.879835

			T.E =	39.879835
3514	3514			
001		5.000000 x	15.951934 =	79.759670

			T.E =	79.759670

3801	3801			
201		.001500 x	290.000000 =	.435000
203.4		.002500 x	210.000000 =	.525000
251		.300000 x	.650000 =	.195000
003		.500000 x	23.479183 =	11.739592
001		.400000 x	15.951934 =	6.380774

			T.E =	19.275365
3802	3802			
3801		.050000 x	19.275365 =	.963768

			T.E =	.963768
3811	3811			
203.4		.004000 x	210.000000 =	.840000
001		.200000 x	15.951934 =	3.190387
251		.100000 x	.650000 =	.065000
003		.800000 x	23.479183 =	18.783346

			T.E =	22.878733
3816	3816			
201		.002500 x	290.000000 =	.725000
001		.400000 x	15.951934 =	6.380774
251		.200000 x	.650000 =	.130000
003		.600000 x	23.479183 =	14.087510
203.4		.003000 x	210.000000 =	.630000

			T.E =	21.953283
3817	3817			
3816		.150000 x	21.953283 =	3.292992

			T.E =	3.292992
3821	3821			
201		.014000 x	290.000000 =	4.060000
003		2.400000 x	23.479183 =	56.350039
001		.600000 x	15.951934 =	9.571160
251		.600000 x	.650000 =	.390000
203.4		.018000 x	210.000000 =	3.780000

			T.E =	74.151200
3822	3822			
3821		.150000 x	74.151200 =	11.122680

			T.E =	11.122680

3823	3823			
201		.020000 x	290.000000 =	5.800000
003		3.000000 x	23.479183 =	70.437549
001		.600000 x	15.951934 =	9.571160
203.4		.025000 x	210.000000 =	5.250000
251		.180000 x	.650000 =	.117000

			T.E =	91.175709
3824	3824			
3823		.200000 x	91.175709 =	18.235142

			T.E =	18.235142
3831	3831			
201		.020000 x	290.000000 =	5.800000
251		.800000 x	.650000 =	.520000
203.4		.024000 x	210.000000 =	5.040000
003		4.500000 x	23.479183 =	105.656324
001		1.100000 x	15.951934 =	17.547127

			T.E =	134.563451
3832	3832			
3831		.150000 x	134.563451 =	20.184518

			T.E =	20.184518
3833	3833			
201		.022000 x	290.000000 =	6.380000
203.4		.025000 x	210.000000 =	5.250000
003		6.000000 x	23.479183 =	140.875098
001		1.100000 x	15.951934 =	17.547127
251		1.000000 x	.650000 =	.650000

			T.E =	170.702225
3834	3834			
3833		.200000 x	170.702225 =	34.140445

			T.E =	34.140445
3841	3841			
203.4		.001500 x	210.000000 =	.315000
003		.500000 x	23.479183 =	11.739592

			T.E =	12.054592

3851	3851			
203.4		.052000 x	210.000000 =	10.920000
003		1.300000 x	23.479183 =	30.522938
251		1.100000 x	.650000 =	.715000

			T.E =	42.157938
3852	3852			
001		.300000 x	15.951934 =	4.785580
003		.100000 x	23.479183 =	2.347918

			T.E =	7.133499
3871	3871			
260		1.030000 x	.492800 =	.507584
003		.050000 x	23.479183 =	1.173959

			T.E =	1.681543
3872	3872			
261		1.030000 x	.523400 =	.539102
003		.040000 x	23.479183 =	.939167

			T.E =	1.478269
3873	3873			
262		1.030000 x	.492800 =	.507584
003		.050000 x	23.479183 =	1.173959

			T.E =	1.681543
3874	3874			
258		1.450000 x	7.377000 =	10.696650
003		.150000 x	23.479183 =	3.521877

			T.E =	14.218527
3875	3875			
259		1.000000 x	24.070000 =	24.070000
003		.300000 x	23.479183 =	7.043755

			T.E =	31.113755
3876	3876			
003		.060000 x	23.479183 =	1.408751

			T.E =	1.408751

3881.1	3881.1			
111		1,023.391800 x	.078400 =	80.233917
001		5.000000 x	15.951934 =	79.759670

			T.E =	159.993587
3881.2	3881.2			
112		627.989998 x	.087900 =	55.200321
001		5.000000 x	15.951934 =	79.759670

			T.E =	134.959991
3882	3882			
127		1.050000 x	83.240000 =	87.402000
001		4.000000 x	15.951934 =	63.807736

			T.E =	151.209736
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	23.479183 =	46.958366
001		1.300000 x	15.951934 =	20.737514

			T.E =	80.357380
4102	4102			
081		1.200000 x	11.010000 =	13.212000
003		3.500000 x	23.479183 =	82.177141
001		1.700000 x	15.951934 =	27.118288

			T.E =	122.507428
4103	4103			
081		1.150000 x	11.010000 =	12.661500
001		3.000000 x	15.951934 =	47.855802
003		4.000000 x	23.479183 =	93.916732

			T.E =	154.434034
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.951934 =	47.855802

			T.E =	59.416302
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	23.479183 =	21.131265
001		1.000000 x	15.951934 =	15.951934

			T.E =	40.936699

4106	4106			
081		.320000 x	11.010000 =	3.523200
003		.900000 x	23.479183 =	21.131265
001		.700000 x	15.951934 =	11.166354

			T.E =	35.820819
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	15.951934 =	31.903868
003		3.000000 x	23.479183 =	70.437549

			T.E =	115.553417
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.951934 =	46.260609
003		4.000000 x	23.479183 =	93.916732

			T.E =	162.614971
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	39.954450 =	13.984058
001		2.900000 x	15.951934 =	46.260609
003		2.500000 x	23.479183 =	58.697958

			T.E =	131.604124
4206	4206			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	39.954450 =	13.984058
003		3.100000 x	23.479183 =	72.785467
001		2.900000 x	15.951934 =	46.260609

			T.E =	145.691633
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.951934 =	46.260609
003		4.000000 x	23.479183 =	93.916732
1417		.350000 x	39.954450 =	13.984058

			T.E =	166.822898

4211	4211			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.951934 =	46.260609
1447		.350000 x	58.155900 =	20.354565
003		2.500000 x	23.479183 =	58.697958

			T.E =	137.974631
4212	4212			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.951934 =	46.260609
1447		.350000 x	58.155900 =	20.354565
003		3.100000 x	23.479183 =	72.785467

			T.E =	152.062141
4213	4213			
081		1.150000 x	11.010000 =	12.661500
1447		.350000 x	58.155900 =	20.354565
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609

			T.E =	173.193406
4221	4221			
001		.800000 x	15.951934 =	12.761547
003		1.000000 x	23.479183 =	23.479183

			T.E =	36.240730
4222	4222			
001		.400000 x	15.951934 =	6.380774
003		.400000 x	23.479183 =	9.391673

			T.E =	15.772447
4226	4226			
003		1.300000 x	23.479183 =	30.522938

			T.E =	30.522938
4251	4251			
083		32.000000 x	.000000 =	.000000
1412		.200000 x	27.931800 =	5.586360
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609

			T.E =	

4257	4257			
083		32.000000 x	.000000 =	.000000
1417		.200000 x	39.954450 =	7.990890
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609

			T.E =	
4261	4261			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.951934 =	46.260609
003		4.000000 x	23.479183 =	93.916732
1445		.200000 x	60.956500 =	12.191300

			T.E =	
4262	4262			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.951934 =	46.260609
003		4.000000 x	23.479183 =	93.916732
1447		.200000 x	58.155900 =	11.631180

			T.E =	
4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.951934 =	15.951934

			T.E =	16.386934
4301	4301			
081		1.020000 x	11.010000 =	11.230200
1412		.350000 x	27.931800 =	9.776130
003		4.200000 x	23.479183 =	98.612569
001		2.900000 x	15.951934 =	46.260609
083		5.000000 x	.000000 =	.000000

			T.E =	
4305	4305			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.951934 =	46.260609
1417		.350000 x	39.954450 =	13.984058
003		2.700000 x	23.479183 =	63.393794

			T.E =	

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	39.954450 =	13.984058
083		3.000000 x	.000000 =	.000000
003		3.300000 x	23.479183 =	77.481304
001		2.900000 x	15.951934 =	46.260609

			T.E =	
4307	4307			
081		1.020000 x	11.010000 =	11.230200
083		5.000000 x	.000000 =	.000000
003		4.200000 x	23.479183 =	98.612569
1417		.350000 x	39.954450 =	13.984058
001		2.900000 x	15.951934 =	46.260609

			T.E =	
4311	4311			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.155900 =	20.354565
003		2.700000 x	23.479183 =	63.393794
001		2.900000 x	15.951934 =	46.260609
083		2.000000 x	.000000 =	.000000

			T.E =	
4312	4312			
081		1.050000 x	11.010000 =	11.560500
1447		.350000 x	58.155900 =	20.354565
003		3.300000 x	23.479183 =	77.481304
001		2.900000 x	15.951934 =	46.260609
083		3.000000 x	.000000 =	.000000

			T.E =	
4313	4313			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.951934 =	46.260609
1447		.350000 x	58.155900 =	20.354565
003		2.700000 x	23.479183 =	63.393794

			T.E =	
4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.951934 =	15.951934

			T.E =	16.386934

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
251		4.000000 x	.650000 =	2.600000
003		25.000000 x	23.479183 =	586.979575
1446		.100000 x	52.110500 =	5.211050
001		10.000000 x	15.951934 =	159.519340

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.650000 =	2.600000
1446		.100000 x	52.110500 =	5.211050
003		25.000000 x	23.479183 =	586.979575
001		10.000000 x	15.951934 =	159.519340

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
1446		.100000 x	52.110500 =	5.211050
003		25.000000 x	23.479183 =	586.979575
001		10.000000 x	15.951934 =	159.519340
251		4.000000 x	.650000 =	2.600000

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
1446		.200000 x	52.110500 =	10.422100
003		32.000000 x	23.479183 =	751.333856
001		11.000000 x	15.951934 =	175.471274
251		8.000000 x	.650000 =	5.200000

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
251		8.000000 x	.650000 =	5.200000
001		11.000000 x	15.951934 =	175.471274
1446		.200000 x	52.110500 =	10.422100
003		32.000000 x	23.479183 =	751.333856

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
251		8.000000 x	.650000 =	5.200000
001		11.000000 x	15.951934 =	175.471274
003		32.000000 x	23.479183 =	751.333856
1446		.200000 x	52.110500 =	10.422100

			T.E =	
4401	4401			
001		1.200000 x	15.951934 =	19.142321

			T.E =	19.142321
4402	4402			
001		3.000000 x	15.951934 =	47.855802

			T.E =	47.855802
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	23.479183 =	23.479183
002		.500000 x	17.729980 =	8.864990

			T.E =	32.894673
4502	4502			
081		.050000 x	11.010000 =	.550500
003		1.300000 x	23.479183 =	30.522938
002		.500000 x	17.729980 =	8.864990

			T.E =	39.938428
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.729980 =	8.864990
003		1.400000 x	23.479183 =	32.870856

			T.E =	42.286346
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		2.300000 x	23.479183 =	54.002121

			T.E =	59.871615

4505	4505			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		2.700000 x	23.479183 =	63.393794

			T.E =	69.263288
4506	4506			
081		.050000 x	11.010000 =	.550500
003		3.600000 x	23.479183 =	84.525059
002		.300000 x	17.729980 =	5.318994

			T.E =	90.394553
4507	4507			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		3.200000 x	23.479183 =	75.133386

			T.E =	81.002880
4508	4508			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		3.000000 x	23.479183 =	70.437549

			T.E =	76.307043
4511	4511			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		3.800000 x	23.479183 =	89.220895

			T.E =	95.090389
4512	4512			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	23.479183 =	93.916732
002		.300000 x	17.729980 =	5.318994

			T.E =	99.786226
4515	4515			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		5.000000 x	23.479183 =	117.395915

			T.E =	123.265409

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		4.500000 x	23.479183 =	105.656324

			T.E =	111.525818
4517	4517			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		6.500000 x	23.479183 =	152.614690

			T.E =	158.484184
4518	4518			
081		.050000 x	11.010000 =	.550500
003		5.700000 x	23.479183 =	133.831343
002		.300000 x	17.729980 =	5.318994

			T.E =	139.700837
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		5.200000 x	23.479183 =	122.091752

			T.E =	127.961246
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		3.500000 x	23.479183 =	82.177141

			T.E =	88.046635
4522	4522			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		2.700000 x	23.479183 =	63.393794

			T.E =	69.263288
4525	4525			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	23.479183 =	105.656324
002		.300000 x	17.729980 =	5.318994

			T.E =	111.525818

4526	4526			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		4.000000 x	23.479183 =	93.916732

			T.E =	99.786226
4527	4527			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		6.000000 x	23.479183 =	140.875098

			T.E =	146.744592
4528	4528			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		5.200000 x	23.479183 =	122.091752

			T.E =	127.961246
4529	4529			
081		.050000 x	11.010000 =	.550500
003		4.700000 x	23.479183 =	110.352160
002		.300000 x	17.729980 =	5.318994

			T.E =	116.221654
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	23.479183 =	58.697958

			T.E =	59.248458
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	23.479183 =	46.958366

			T.E =	47.508866
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	23.479183 =	89.220895

			T.E =	89.771395
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	23.479183 =	72.785467

			T.E =	73.335967

4537	4537				
081		.050000 x	11.010000 =	.550500	
003		5.500000 x	23.479183 =	129.135507	

			T.E =	129.686007	
4538	4538				
081		.050000 x	11.010000 =	.550500	
003		4.600000 x	23.479183 =	108.004242	

			T.E =	108.554742	
4539	4539				
081		.050000 x	11.010000 =	.550500	
003		4.200000 x	23.479183 =	98.612569	

			T.E =	99.163069	
4541	4541				
081		.050000 x	11.010000 =	.550500	
003		2.500000 x	23.479183 =	58.697958	

			T.E =	59.248458	
4542	4542				
081		.050000 x	11.010000 =	.550500	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	47.508866	
4543	4543				
081		.050000 x	11.010000 =	.550500	
003		4.000000 x	23.479183 =	93.916732	

			T.E =	94.467232	
4544	4544				
081		.050000 x	11.010000 =	.550500	
003		6.000000 x	23.479183 =	140.875098	

			T.E =	141.425598	
4601.1	4601.1				
101		105.000000 x	.000000 =	.000000	
001		.600000 x	15.951934 =	9.571160	
1417		.023000 x	39.954450 =	.918952	
003		.700000 x	23.479183 =	16.435428	

			T.E =		

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
001		.600000 x	15.951934 =	9.571160
1447		.023000 x	58.155900 =	1.337586
003		.700000 x	23.479183 =	16.435428

			T.E =	
4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.951934 =	20.737514
003		1.300000 x	23.479183 =	30.522938
1417		.056000 x	39.954450 =	2.237449

			T.E =	
4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
003		1.300000 x	23.479183 =	30.522938
1447		.056000 x	58.155900 =	3.256730
001		1.300000 x	15.951934 =	20.737514

			T.E =	
4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	39.954450 =	3.555946
003		1.800000 x	23.479183 =	42.262529
001		1.900000 x	15.951934 =	30.308675

			T.E =	
4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.951934 =	30.308675
1447		.089000 x	58.155900 =	5.175875
003		1.800000 x	23.479183 =	42.262529

			T.E =	
4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.951934 =	100.497184
1417		.332000 x	39.954450 =	13.264877
003		5.500000 x	23.479183 =	129.135507

			T.E =	

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.951934 =	100.497184
1447		.332000 x	58.155900 =	19.307759
003		5.500000 x	23.479183 =	129.135507
			T.E =	
4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	39.954450 =	1.198634
003		.700000 x	23.479183 =	16.435428
001		.700000 x	15.951934 =	11.166354
			T.E =	
4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
001		.700000 x	15.951934 =	11.166354
1447		.030000 x	58.155900 =	1.744677
003		.700000 x	23.479183 =	16.435428
			T.E =	
4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.951934 =	22.332708
1417		.070000 x	39.954450 =	2.796812
003		1.300000 x	23.479183 =	30.522938
			T.E =	
4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.951934 =	22.332708
1447		.070000 x	58.155900 =	4.070913
003		1.300000 x	23.479183 =	30.522938
			T.E =	
4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	39.954450 =	4.394990
003		1.800000 x	23.479183 =	42.262529
001		2.100000 x	15.951934 =	33.499061
			T.E =	

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.951934 =	33.499061
1447		.110000 x	58.155900 =	6.397149
003		1.800000 x	23.479183 =	42.262529

			T.E =	
4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.951934 =	103.687571
1417		.404000 x	39.954450 =	16.141598
003		5.500000 x	23.479183 =	129.135507

			T.E =	
4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.951934 =	103.687571
1447		.404000 x	58.155900 =	23.494984
003		5.500000 x	23.479183 =	129.135507

			T.E =	
4621.1	4621.1			
111		53.000000 x	.078400 =	4.155200
1417		.010000 x	39.954450 =	.399545
003		.500000 x	23.479183 =	11.739592
001		.400000 x	15.951934 =	6.380774

			T.E =	22.675110
4621.2	4621.2			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	15.951934 =	6.380774
1447		.010000 x	58.155900 =	.581559
003		.500000 x	23.479183 =	11.739592

			T.E =	22.857124
4622.1	4622.1			
111		75.000000 x	.078400 =	5.880000
1417		.020000 x	39.954450 =	.799089
003		.500000 x	23.479183 =	11.739592
001		.450000 x	15.951934 =	7.178370

			T.E =	25.597051

4622.2	4622.2			
111		75.000000 x	.078400 =	5.880000
1447		.020000 x	58.155900 =	1.163118
003		.500000 x	23.479183 =	11.739592
001		.450000 x	15.951934 =	7.178370

			T.E =	25.961080
4623.1	4623.1			
111		150.000000 x	.078400 =	11.760000
1417		.050000 x	39.954450 =	1.997723
003		.950000 x	23.479183 =	22.305224
001		.950000 x	15.951934 =	15.154337

			T.E =	51.217284
4623.2	4623.2			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	15.951934 =	15.154337
1447		.050000 x	58.155900 =	2.907795
003		.950000 x	23.479183 =	22.305224

			T.E =	52.127356
4624.1	4624.1			
111		225.000000 x	.078400 =	17.640000
001		1.500000 x	15.951934 =	23.927901
1417		.085000 x	39.954450 =	3.396128
003		1.300000 x	23.479183 =	30.522938

			T.E =	75.486967
4624.2	4624.2			
111		225.000000 x	.078400 =	17.640000
001		1.500000 x	15.951934 =	23.927901
1447		.085000 x	58.155900 =	4.943252
003		1.300000 x	23.479183 =	30.522938

			T.E =	77.034090
4625.1	4625.1			
111		750.000000 x	.078400 =	58.800000
1417		.320000 x	39.954450 =	12.785424
003		4.300000 x	23.479183 =	100.960487
001		5.200000 x	15.951934 =	82.950057

			T.E =	255.495968

4625.2	4625.2			
111		750.000000 x	.078400 =	58.800000
001		5.200000 x	15.951934 =	82.950057
1447		.320000 x	58.155900 =	18.609888
003		4.300000 x	23.479183 =	100.960487

			T.E =	261.320432
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	25.597051 =	56.313512

			T.E =	56.313512
4633.2	4633.2			
4622.2		2.200000 x	25.961080 =	57.114376

			T.E =	57.114376
4634.1	4634.1			
4622.1		1.200000 x	25.597051 =	30.716461
4623.1		1.000000 x	51.217284 =	51.217284

			T.E =	81.933745
4634.2	4634.2			
4622.2		1.200000 x	25.961080 =	31.153296
4623.2		1.000000 x	52.127356 =	52.127356

			T.E =	83.280652
4661.1	4661.1			
112		43.750000 x	.087900 =	3.845625
1417		.014507 x	39.954450 =	.579619
003		.500000 x	23.479183 =	11.739592
001		.400000 x	15.951934 =	6.380774

			T.E =	22.545609
4661.2	4661.2			
112		43.750000 x	.087900 =	3.845625
1447		.014507 x	58.155900 =	.843668
003		.500000 x	23.479183 =	11.739592
001		.400000 x	15.951934 =	6.380774

			T.E =	22.809658
4662.1	4662.1			
112		58.333300 x	.087900 =	5.127497
1417		.022840 x	39.954450 =	.912560
003		.500000 x	23.479183 =	11.739592
001		.450000 x	15.951934 =	7.178370

			T.E =	24.958019

4662.2	4662.2			
112		58.333300 x	.087900 =	5.127497
001		.450000 x	15.951934 =	7.178370
1447		.022840 x	58.155900 =	1.328281
003		.500000 x	23.479183 =	11.739592

			T.E =	25.373740
4663.1	4663.1			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.951934 =	14.356741
1417		.043218 x	39.954450 =	1.726751
003		.900000 x	23.479183 =	21.131265

			T.E =	46.444257
4663.2	4663.2			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.951934 =	14.356741
1447		.043218 x	58.155900 =	2.513382
003		.900000 x	23.479183 =	21.131265

			T.E =	47.230887
4664.1	4664.1			
112		97.222221 x	.087900 =	8.545833
1417		.045077 x	39.954450 =	1.801027
003		.950000 x	23.479183 =	22.305224
001		.950000 x	15.951934 =	15.154337

			T.E =	47.806421
4664.2	4664.2			
112		97.222221 x	.087900 =	8.545833
001		.950000 x	15.951934 =	15.154337
1447		.045077 x	58.155900 =	2.621494
003		.950000 x	23.479183 =	22.305224

			T.E =	48.626888
4665.1	4665.1			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.951934 =	23.927901
1417		.047530 x	39.954450 =	1.899035
003		1.300000 x	23.479183 =	30.522938

			T.E =	71.732286

4665.2	4665.2			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.951934 =	23.927901
1447		.047530 x	58.155900 =	2.764150
003		1.300000 x	23.479183 =	30.522938

			T.E =	72.597401
4666.1	4666.1			
112		486.111099 x	.087900 =	42.729166
1417		.277862 x	39.954450 =	11.101823
003		4.300000 x	23.479183 =	100.960487
001		5.200000 x	15.951934 =	82.950057

			T.E =	237.741533
4666.2	4666.2			
112		486.111000 x	.087900 =	42.729157
001		5.200000 x	15.951934 =	82.950057
1447		.277862 x	58.155900 =	16.159315
003		4.300000 x	23.479183 =	100.960487

			T.E =	242.799015
4701	4701			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.951934 =	7.975967
1417		.020000 x	39.954450 =	.799089
003		.400000 x	23.479183 =	9.391673

			T.E =	25.576729
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.951934 =	7.975967
1447		.020000 x	58.155900 =	1.163118
003		.400000 x	23.479183 =	9.391673

			T.E =	25.940758
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	39.954450 =	.599317
003		.350000 x	23.479183 =	8.217714
001		.400000 x	15.951934 =	6.380774

			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.951934 =	6.380774
1447		.015000 x	58.155900 =	.872339
003		.350000 x	23.479183 =	8.217714

			T.E =	
4711	4711			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.951934 =	7.975967
1417		.020000 x	39.954450 =	.799089
003		.400000 x	23.479183 =	9.391673

			T.E =	
4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.951934 =	7.975967
1447		.020000 x	58.155900 =	1.163118
003		.400000 x	23.479183 =	9.391673

			T.E =	
4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	39.954450 =	.599317
003		.350000 x	23.479183 =	8.217714
001		.400000 x	15.951934 =	6.380774

			T.E =	
4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.951934 =	6.380774
1447		.015000 x	58.155900 =	.872339
003		.350000 x	23.479183 =	8.217714

			T.E =	
4721.1	4721.1			
128		.080000 x	90.430000 =	7.234400
001		.300000 x	15.951934 =	4.785580
1417		.004000 x	39.954450 =	.159818
003		.350000 x	23.479183 =	8.217714

			T.E =	20.397512

4721.2	4721.2				
128		.080000 x	90.430000 =		7.234400
001		.300000 x	15.951934 =		4.785580
1447		.004000 x	58.155900 =		.232624
003		.350000 x	23.479183 =		8.217714
				T.E =	20.470318
4722.1	4722.1				
128		.100000 x	90.430000 =		9.043000
1417		.005000 x	39.954450 =		.199772
003		.350000 x	23.479183 =		8.217714
001		.350000 x	15.951934 =		5.583177
				T.E =	23.043663
4722.2	4722.2				
128		.100000 x	90.430000 =		9.043000
001		.350000 x	15.951934 =		5.583177
1447		.005000 x	58.155900 =		.290780
003		.350000 x	23.479183 =		8.217714
				T.E =	23.134670
4723	4723				
128		.120000 x	90.430000 =		10.851600
001		.400000 x	15.951934 =		6.380774
1417		.006000 x	39.954450 =		.239727
003		.350000 x	23.479183 =		8.217714
				T.E =	25.689814
4724.1	4724.1				
128		.150000 x	90.430000 =		13.564500
1417		.008000 x	39.954450 =		.319636
001		.400000 x	15.951934 =		6.380774
003		.400000 x	23.479183 =		9.391673
				T.E =	29.656582
4724.2	4724.2				
128		.150000 x	90.430000 =		13.564500
1447		.008000 x	58.155900 =		.465247
003		.400000 x	23.479183 =		9.391673
001		.400000 x	15.951934 =		6.380774
				T.E =	29.802194

4725.1	4725.1				
128		.180000 x	90.430000 =	16.277400	
1417		.009000 x	39.954450 =	.359590	
001		.450000 x	15.951934 =	7.178370	
003		.400000 x	23.479183 =	9.391673	
			T.E =		33.207034
4725.2	4725.2				
128		.180000 x	90.430000 =	16.277400	
001		.450000 x	15.951934 =	7.178370	
1447		.009000 x	58.155900 =	.523403	
003		.400000 x	23.479183 =	9.391673	
			T.E =		33.370847
4801.1	4801.1				
4662.1		1.000000 x	24.958019 =	24.958019	
4662.1		.100000 x	24.958019 =	2.495802	
			T.E =		27.453821
4801.2	4801.2				
4662.2		1.000000 x	25.373740 =	25.373740	
4662.2		.100000 x	25.373740 =	2.537374	
			T.E =		27.911114
4802.1	4802.1				
4664.1		1.000000 x	47.806421 =	47.806421	
4664.1		.050000 x	47.806421 =	2.390321	
			T.E =		50.196742
4802.2	4802.2				
4664.2		1.000000 x	48.626888 =	48.626888	
4664.2		.050000 x	48.626888 =	2.431344	
			T.E =		51.058232
4803.1	4803.1				
4665.1		1.000000 x	71.732286 =	71.732286	
4665.1		.030000 x	71.732286 =	2.151969	
			T.E =		73.884255
4803.2	4803.2				
4665.2		1.000000 x	72.597401 =	72.597401	
4665.2		.030000 x	72.597401 =	2.177922	
			T.E =		74.775323

4811.1	4811.1				
001		.225000 x	15.951934 =	3.589185	
003		.250000 x	23.479183 =	5.869796	
4662.1		1.000000 x	24.958019 =	24.958019	

			T.E =	34.417000	
4811.2	4811.2				
001		.225000 x	15.951934 =	3.589185	
003		.250000 x	23.479183 =	5.869796	
4662.2		1.000000 x	25.373740 =	25.373740	

			T.E =	34.832721	
4812.1	4812.1				
001		.475000 x	15.951934 =	7.577169	
4664.1		1.000000 x	47.806421 =	47.806421	
003		.475000 x	23.479183 =	11.152612	

			T.E =	66.536202	
4812.2	4812.2				
001		.475000 x	15.951934 =	7.577169	
003		.475000 x	23.479183 =	11.152612	
4664.2		1.000000 x	48.626888 =	48.626888	

			T.E =	67.356669	
4813.1	4813.1				
001		.750000 x	15.951934 =	11.963951	
003		.650000 x	23.479183 =	15.261469	
4665.1		1.000000 x	71.732286 =	71.732286	

			T.E =	98.957705	
4813.2	4813.2				
001		.750000 x	15.951934 =	11.963951	
003		.650000 x	23.479183 =	15.261469	
4665.2		1.000000 x	72.597401 =	72.597401	

			T.E =	99.822820	
4814.1	4814.1				
001		2.600000 x	15.951934 =	41.475028	
4666.1		1.000000 x	237.741533 =	237.741533	
003		2.150000 x	23.479183 =	50.480243	

			T.E =	329.696805	

4814.2	4814.2			
001		2.600000 x	15.951934 =	41.475028
4666.2		1.000000 x	242.799015 =	242.799015
003		2.150000 x	23.479183 =	50.480243

			T.E =	334.754287
4821.1	4821.1			
003		.450000 x	23.479183 =	10.565632
4662.1		1.000000 x	24.958019 =	24.958019

			T.E =	35.523651
4821.2	4821.2			
003		.450000 x	23.479183 =	10.565632
4662.2		1.000000 x	25.373740 =	25.373740

			T.E =	35.939372
4822.1	4822.1			
003		.807500 x	23.479183 =	18.959440
4664.1		1.000000 x	47.806421 =	47.806421

			T.E =	66.765861
4822.2	4822.2			
003		.807500 x	23.479183 =	18.959440
4664.2		1.000000 x	48.626888 =	48.626888

			T.E =	67.586328
4823.1	4823.1			
003		1.040000 x	23.479183 =	24.418350
4665.1		1.000000 x	71.732286 =	71.732286

			T.E =	96.150636
4823.2	4823.2			
003		1.040000 x	23.479183 =	24.418350
4665.2		1.000000 x	72.597401 =	72.597401

			T.E =	97.015751
4824.1	4824.1			
003		3.010000 x	23.479183 =	70.672341
4666.1		1.000000 x	237.741533 =	237.741533

			T.E =	308.413874

4824.2	4824.2			
003		3.010000 x	23.479183 =	70.672341
4666.2		1.000000 x	242.799015 =	242.799015

			T.E =	313.471356
4831.1	4831.1			
003		1.200000 x	23.479183 =	28.175020
4661.1		1.000000 x	22.545609 =	22.545609

			T.E =	50.720629
4831.2	4831.2			
003		1.200000 x	23.479183 =	28.175020
4661.2		1.000000 x	22.809658 =	22.809658

			T.E =	50.984678
4832.1	4832.1			
003		1.600000 x	23.479183 =	37.566693
4662.1		1.000000 x	24.958019 =	24.958019

			T.E =	62.524712
4832.2	4832.2			
003		1.600000 x	23.479183 =	37.566693
4662.2		1.000000 x	25.373740 =	25.373740

			T.E =	62.940433
4833.1	4833.1			
002		2.000000 x	17.729980 =	35.459960
4664.1		1.000000 x	47.806421 =	47.806421

			T.E =	83.266381
4833.2	4833.2			
002		2.000000 x	17.729980 =	35.459960
4664.2		1.000000 x	48.626888 =	48.626888

			T.E =	84.086848
4834.1	4834.1			
003		2.300000 x	23.479183 =	54.002121
4665.1		1.000000 x	71.732286 =	71.732286

			T.E =	125.734407

4834.2	4834.2			
003		2.300000 x	23.479183 =	54.002121
4665.2		1.000000 x	72.597401 =	72.597401

			T.E =	126.599522
4835	4835			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	23.479183 =	23.479183
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.641500 =	1.283000

			T.E =	
4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.951934 =	15.951934
003		1.000000 x	23.479183 =	23.479183
1447		.005000 x	58.155900 =	.290780
265		2.000000 x	.641500 =	1.283000

			T.E =	
4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	23.479183 =	23.479183
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.641500 =	1.283000

			T.E =	
4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
1447		.005000 x	58.155900 =	.290780
003		1.000000 x	23.479183 =	23.479183
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.641500 =	1.283000
201		.010000 x	290.000000 =	2.900000

			T.E =	

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
003		1.000000 x	23.479183 =	23.479183
1417		.010000 x	39.954450 =	.399545
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.641500 =	1.283000
201		.010000 x	290.000000 =	2.900000
			T.E =	50.208662
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
265		2.000000 x	.641500 =	1.283000
201		.010000 x	290.000000 =	2.900000
1447		.010000 x	58.155900 =	.581559
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
			T.E =	52.168722
4841	4841			
003		.700000 x	23.479183 =	16.435428
			T.E =	16.435428
4842	4842			
003		1.000000 x	23.479183 =	23.479183
			T.E =	23.479183
4843	4843			
003		.250000 x	23.479183 =	5.869796
			T.E =	5.869796
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
003		25.000000 x	23.479183 =	586.979575
1401		.250000 x	234.711000 =	58.677750
001		10.000000 x	15.951934 =	159.519340
			T.E =	1,585.176665
4845	4845			
132		620.000000 x	.930000 =	576.600000
003		15.000000 x	23.479183 =	352.187745
001		6.000000 x	15.951934 =	95.711604
1401		.180000 x	234.711000 =	42.247980
			T.E =	1,066.747329

4851	4851			
001		.100000 x	15.951934 =	1.595193

			T.E =	1.595193
4852	4852			
001		.150000 x	15.951934 =	2.392790

			T.E =	2.392790
4853	4853			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
4854	4854			
001		.250000 x	15.951934 =	3.987984

			T.E =	3.987984
4855	4855			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
4856	4856			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547
4857	4857			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
4858	4858			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
4859	4859			
001		.400000 x	15.951934 =	6.380774

			T.E =	6.380774
4860	4860			
001		.500000 x	15.951934 =	7.975967

			T.E =	7.975967

4861	4861			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
4862	4862			
001		1.700000 x	15.951934 =	27.118288

			T.E =	27.118288
5101	5101			
214		1.100000 x	.000000 =	.000000
001		1.000000 x	15.951934 =	15.951934
003		4.000000 x	23.479183 =	93.916732

			T.E =	
5102	5102			
483		1.800000 x	.165000 =	.297000
001		1.000000 x	15.951934 =	15.951934
489		.360000 x	.000000 =	.000000
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.000000 =	2.700000

			T.E =	
5103	5103			
265		1.050000 x	.641500 =	.673575
003		.200000 x	23.479183 =	4.695837
002		.050000 x	17.729980 =	.886499

			T.E =	6.255911
5104	5104			
001		2.000000 x	15.951934 =	31.903868
003		.150000 x	23.479183 =	3.521877

			T.E =	35.425745
5105	5105			
214		.010000 x	.000000 =	.000000
003		.500000 x	23.479183 =	11.739592
001		2.000000 x	15.951934 =	31.903868

			T.E =	

5106	5106			
214		.050000 x	.000000 =	.000000
003		2.500000 x	23.479183 =	58.697958
001		2.000000 x	15.951934 =	31.903868
			T.E =	
5201	5201			
201		1.100000 x	290.000000 =	319.000000
003		10.000000 x	23.479183 =	234.791830
002		5.000000 x	17.729980 =	88.649900
251		6.000000 x	.650000 =	3.900000
			T.E =	646.341730
5202	5202			
203.2		1.080000 x	335.000000 =	361.800000
251		6.000000 x	.650000 =	3.900000
002		4.500000 x	17.729980 =	79.784910
003		9.000000 x	23.479183 =	211.312647
			T.E =	656.797557
5203	5203			
201		1.120000 x	290.000000 =	324.800000
251		12.000000 x	.650000 =	7.800000
003		16.000000 x	23.479183 =	375.666928
002		8.000000 x	17.729980 =	141.839840
			T.E =	850.106768
5204	5204			
203.2		1.100000 x	335.000000 =	368.500000
251		12.000000 x	.650000 =	7.800000
003		14.000000 x	23.479183 =	328.708562
002		7.000000 x	17.729980 =	124.109860
			T.E =	829.118422
5211	5211			
201		1.100000 x	290.000000 =	319.000000
003		12.000000 x	23.479183 =	281.750196
002		6.000000 x	17.729980 =	106.379880
251		14.000000 x	.650000 =	9.100000
			T.E =	716.230076

5212	5212				
203.2		1.080000 x	335.000000 =	361.800000	
251		14.000000 x	.650000 =	9.100000	
002		5.000000 x	17.729980 =	88.649900	
003		10.000000 x	23.479183 =	234.791830	

			T.E =	694.341730	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.650000 =	5.200000	
003		9.000000 x	23.479183 =	211.312647	
002		4.500000 x	17.729980 =	79.784910	

			T.E =	615.297557	
5221	5221				
203.2		.014000 x	335.000000 =	4.690000	
251		.100000 x	.650000 =	.065000	
003		.200000 x	23.479183 =	4.695837	
002		.050000 x	17.729980 =	.886499	

			T.E =	10.337336	
5222	5222				
203.2		.018000 x	335.000000 =	6.030000	
003		.200000 x	23.479183 =	4.695837	
002		.070000 x	17.729980 =	1.241099	
251		.100000 x	.650000 =	.065000	

			T.E =	12.031935	
5223	5223				
203.2		.026000 x	335.000000 =	8.710000	
251		.100000 x	.650000 =	.065000	
002		.100000 x	17.729980 =	1.772998	
003		.200000 x	23.479183 =	4.695837	

			T.E =	15.243835	
5226	5226				
203.2		.016000 x	335.000000 =	5.360000	
251		.100000 x	.650000 =	.065000	
003		.200000 x	23.479183 =	4.695837	
002		.050000 x	17.729980 =	.886499	

			T.E =	11.007336	

5227	5227				
203.2		.022000 x	335.000000 =	7.370000	
251		.100000 x	.650000 =	.065000	
003		.200000 x	23.479183 =	4.695837	
002		.100000 x	17.729980 =	1.772998	

			T.E =	13.903835	
5228	5228				
203.2		.030000 x	335.000000 =	10.050000	
003		.200000 x	23.479183 =	4.695837	
002		.150000 x	17.729980 =	2.659497	
251		.150000 x	.650000 =	.097500	

			T.E =	17.502834	
5231	5231				
203.2		.018000 x	335.000000 =	6.030000	
251		.150000 x	.650000 =	.097500	
002		.100000 x	17.729980 =	1.772998	
003		.250000 x	23.479183 =	5.869796	

			T.E =	13.770294	
5232	5232				
203.2		.025000 x	335.000000 =	8.375000	
251		.150000 x	.650000 =	.097500	
003		.250000 x	23.479183 =	5.869796	
002		.120000 x	17.729980 =	2.127598	

			T.E =	16.469893	
5233	5233				
203.2		.034000 x	335.000000 =	11.390000	
251		.200000 x	.650000 =	.130000	
003		.250000 x	23.479183 =	5.869796	
002		.150000 x	17.729980 =	2.659497	

			T.E =	20.049293	
5236	5236				
203.2		.016000 x	335.000000 =	5.360000	
003		.350000 x	23.479183 =	8.217714	
002		.250000 x	17.729980 =	4.432495	
251		.080000 x	.650000 =	.052000	

			T.E =	18.062209	

5237	5237				
203.2		.022000 x	335.000000 =		7.370000
251		.080000 x	.650000 =		.052000
003		.350000 x	23.479183 =		8.217714
002		.300000 x	17.729980 =		5.318994

			T.E =		20.958708
5238	5238				
203.2		.030000 x	335.000000 =		10.050000
251		.100000 x	.650000 =		.065000
003		.350000 x	23.479183 =		8.217714
002		.350000 x	17.729980 =		6.205493

			T.E =		24.538207
5241	5241				
203.2		.030000 x	335.000000 =		10.050000
251		.100000 x	.650000 =		.065000
003		.500000 x	23.479183 =		11.739592
002		.500000 x	17.729980 =		8.864990

			T.E =		30.719582
5243	5243				
003		.150000 x	23.479183 =		3.521877

			T.E =		3.521877
5244	5244				
003		.350000 x	23.479183 =		8.217714

			T.E =		8.217714
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	17.729980 =		8.864990
251		.200000 x	.650000 =		.130000

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
002		.600000 x	17.729980 =		10.637988
251		.100000 x	.650000 =		.065000
283		.100000 x	1.000100 =		.100010

			T.E =		

5251	5251				
243.3		1.050000 x	4.450000 =	4.672500	
251		.100000 x	.650000 =	.065000	
003		.300000 x	23.479183 =	7.043755	
002		.300000 x	17.729980 =	5.318994	

			T.E =	17.100249	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	23.479183 =	58.697958	
002		2.500000 x	17.729980 =	44.324950	
245		.110000 x	18.600000 =	2.046000	

			T.E =	125.528908	
5252.2	5252.2				
246		1.100000 x	9.000000 =	9.900000	
246		.110000 x	9.000000 =	.990000	
002		2.500000 x	17.729980 =	44.324950	
003		2.500000 x	23.479183 =	58.697958	

			T.E =	113.912908	
5252.3	5252.3				
249		1.100000 x	19.000000 =	20.900000	
249		.110000 x	19.000000 =	2.090000	
003		2.500000 x	23.479183 =	58.697958	
002		2.500000 x	17.729980 =	44.324950	

			T.E =	126.012908	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
219		.060000 x	3.500000 =	.210000	
003		1.500000 x	23.479183 =	35.218775	
002		1.500000 x	17.729980 =	26.594970	

			T.E =	66.223745	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	23.479183 =	18.783346	
002		.800000 x	17.729980 =	14.183984	
251		.600000 x	.650000 =	.390000	
203.2		.025000 x	335.000000 =	8.375000	

			T.E =	47.532330	

5262	5262			
201		.030000 x	290.000000 =	8.700000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
265		.300000 x	.641500 =	.192450
252		.200000 x	1.750000 =	.350000
203.2		.025000 x	335.000000 =	8.375000
251		.300000 x	.650000 =	.195000

			T.E =	59.021613
5266	5266			
201		.020000 x	290.000000 =	5.800000
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988
203.2		.015000 x	335.000000 =	5.025000
251		.600000 x	.650000 =	.390000

			T.E =	35.940498
5267	5267			
201		.030000 x	290.000000 =	8.700000
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984
265		.300000 x	.641500 =	.192450
252		.300000 x	1.750000 =	.525000
203.2		.015000 x	335.000000 =	5.025000
251		.300000 x	.650000 =	.195000

			T.E =	47.604780
5271	5271			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990
251		.600000 x	.650000 =	.390000
203.2		.025000 x	335.000000 =	8.375000

			T.E =	34.009582
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986
265		.200000 x	.641500 =	.128300
252		.100000 x	1.750000 =	.175000
203.2		.025000 x	335.000000 =	8.375000
251		.300000 x	.650000 =	.195000

			T.E =	44.679714

5273	5273			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990
203.2		.015000 x	335.000000 =	5.025000
251		.600000 x	.650000 =	.390000

			T.E =	30.659582
5274	5274			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986
265		.200000 x	.641500 =	.128300
252		.100000 x	1.750000 =	.175000
203.2		.015000 x	335.000000 =	5.025000
251		.300000 x	.650000 =	.195000

			T.E =	41.329714
5276	5276			
201		1.080000 x	290.000000 =	313.200000
003		19.000000 x	23.479183 =	446.104477
002		19.000000 x	17.729980 =	336.869620
252		18.000000 x	1.750000 =	31.500000
251		6.000000 x	.650000 =	3.900000

			T.E =	1,131.574097
5277	5277			
203.2		1.080000 x	335.000000 =	361.800000
251		6.000000 x	.650000 =	3.900000
002		18.000000 x	17.729980 =	319.139640
003		18.000000 x	23.479183 =	422.625294
252		18.000000 x	1.750000 =	31.500000

			T.E =	1,138.964934
5279	5279			
201		1.080000 x	290.000000 =	313.200000
251		12.000000 x	.650000 =	7.800000
002		5.000000 x	17.729980 =	88.649900
003		10.000000 x	23.479183 =	234.791830

			T.E =	644.441730

5280	5280				
203.2		1.080000 x	335.000000 =	361.800000	
251		12.000000 x	.650000 =	7.800000	
003		10.000000 x	23.479183 =	234.791830	
002		5.000000 x	17.729980 =	88.649900	

			T.E =	693.041730	
5281	5281				
203.2		.014000 x	335.000000 =	4.690000	
002		.250000 x	17.729980 =	4.432495	
251		.040000 x	.650000 =	.026000	

			T.E =	9.148495	
5282	5282				
203.2		.020000 x	335.000000 =	6.700000	
251		.060000 x	.650000 =	.039000	
002		.350000 x	17.729980 =	6.205493	

			T.E =	12.944493	
5283	5283				
203.2		.026000 x	335.000000 =	8.710000	
251		.080000 x	.650000 =	.052000	
002		.400000 x	17.729980 =	7.091992	

			T.E =	15.853992	
5286	5286				
203.2		.008000 x	335.000000 =	2.680000	
003		.120000 x	23.479183 =	2.817502	
251		.030000 x	.650000 =	.019500	
002		.120000 x	17.729980 =	2.127598	

			T.E =	7.644600	
5288	5288				
003		.300000 x	23.479183 =	7.043755	

			T.E =	7.043755	
5289	5289				
003		1.000000 x	23.479183 =	23.479183	

			T.E =	23.479183	

5291	5291			
203.2		.020000 x	335.000000 =	6.700000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992
251		.200000 x	.650000 =	.130000
220		26.000000 x	.000000 =	.000000

			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988
251		.200000 x	.650000 =	.130000
220		26.000000 x	.000000 =	.000000
203.2		.010000 x	335.000000 =	3.350000

			T.E =	
5293	5293			
203.2		.020000 x	335.000000 =	6.700000
251		.150000 x	.650000 =	.097500
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992
203.2		.016000 x	335.000000 =	5.360000

			T.E =	28.641165
5294	5294			
203.2		.020000 x	335.000000 =	6.700000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992
203.2		.022000 x	335.000000 =	7.370000
251		.100000 x	.650000 =	.065000

			T.E =	30.618665
5295	5295			
203.2		.020000 x	335.000000 =	6.700000
251		.050000 x	.650000 =	.032500
003		.250000 x	23.479183 =	5.869796
002		.250000 x	17.729980 =	4.432495

			T.E =	17.034791
5301	5301			
226		1.050000 x	11.500000 =	12.075000
251		.250000 x	.650000 =	.162500
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988

			T.E =	36.962998

5302	5302			
227		1.050000 x	11.500000 =	12.075000
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592
251		.200000 x	.650000 =	.130000

			T.E =	32.809582
5321	5321			
203.2		.012000 x	335.000000 =	4.020000
003		.900000 x	23.479183 =	21.131265
002		.900000 x	17.729980 =	15.956982
251		.500000 x	.650000 =	.325000
226		1.050000 x	11.500000 =	12.075000

			T.E =	53.508247
5322	5322			
203.2		.012000 x	335.000000 =	4.020000
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984
227		1.050000 x	11.500000 =	12.075000
251		.450000 x	.650000 =	.292500

			T.E =	49.354830
5323	5323			
203.2		.012000 x	335.000000 =	4.020000
251		.500000 x	.650000 =	.325000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
228		1.050000 x	35.000000 =	36.750000

			T.E =	82.304163
5324	5324			
203.2		.012000 x	335.000000 =	4.020000
229		1.050000 x	.000000 =	.000000
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
251		.500000 x	.650000 =	.325000

			T.E =	
5325	5325			
203.2		.012000 x	335.000000 =	4.020000
230		1.050000 x	.000000 =	.000000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
251		.500000 x	.650000 =	.325000

			T.E =	

5326	5326			
203.2		.012000 x	335.000000 =	4.020000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
251		.500000 x	.650000 =	.325000
231		1.050000 x	20.000000 =	21.000000

			T.E =	66.554163
5341	5341			
203.2		.037000 x	335.000000 =	12.395000
232		1.050000 x	45.000000 =	47.250000
251		.600000 x	.650000 =	.390000
002		1.100000 x	17.729980 =	19.502978
003		1.100000 x	23.479183 =	25.827101

			T.E =	105.365079
5342	5342			
203.2		.037000 x	335.000000 =	12.395000
232		1.100000 x	45.000000 =	49.500000
251		.600000 x	.650000 =	.390000
003		1.700000 x	23.479183 =	39.914611
002		1.700000 x	17.729980 =	30.140966

			T.E =	132.340577
5343	5343			
233		1.050000 x	21.300000 =	22.365000
233		.084000 x	21.300000 =	1.789200
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984

			T.E =	57.121530
5351	5351			
035		.200000 x	.125600 =	.025120
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		.100000 x	.650000 =	.065000
236		1.060000 x	2.600000 =	2.756000

			T.E =	11.087953
5352	5352			
035		.200000 x	.125600 =	.025120
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
237		1.060000 x	1.100000 =	1.166000
251		.100000 x	.650000 =	.065000

			T.E =	9.497953

5353	5353			
035		.200000 x	.125600 =	.025120
251		.100000 x	.650000 =	.065000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
238		1.060000 x	2.600000 =	2.756000

			T.E =	11.087953
5354	5354			
035		.200000 x	.125600 =	.025120
239		1.060000 x	.000000 =	.000000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
251		.100000 x	.650000 =	.065000

			T.E =	
5355	5355			
035		.200000 x	.125600 =	.025120
240		1.060000 x	1.600000 =	1.696000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		.100000 x	.650000 =	.065000

			T.E =	10.027953
5356	5356			
035		.200000 x	.125600 =	.025120
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		.100000 x	.650000 =	.065000
241		1.060000 x	.000000 =	.000000

			T.E =	
5421	5421			
205		.055000 x	420.000000 =	23.100000
1471		1.000000 x	5.200700 =	5.200700
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141

			T.E =	172.532771
5422	5422			
205		.035000 x	420.000000 =	14.700000
1472		1.000000 x	6.297176 =	6.297176
003		3.000000 x	23.479183 =	70.437549
002		3.000000 x	17.729980 =	53.189940

			T.E =	144.624665

5426	5426			
205		.095000 x	420.000000 =	39.900000
1473		1.000000 x	10.833359 =	10.833359
1471		1.000000 x	5.200700 =	5.200700
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880

			T.E =	303.189037
5427	5427			
205		.105000 x	420.000000 =	44.100000
1474		1.000000 x	13.152927 =	13.152927
1471		1.000000 x	5.200700 =	5.200700
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860

			T.E =	350.917768
5428	5428			
205		.075000 x	420.000000 =	31.500000
002		5.500000 x	17.729980 =	97.514890
003		5.500000 x	23.479183 =	129.135507
1474		1.000000 x	13.152927 =	13.152927
1472		1.000000 x	6.297176 =	6.297176

			T.E =	277.600500
5431	5431			
205		.070000 x	420.000000 =	29.400000
208		.030000 x	1,239.000000 =	37.170000
002		7.000000 x	17.729980 =	124.109860
003		7.000000 x	23.479183 =	164.354281
1475		1.000000 x	37.464863 =	37.464863
1471		1.000000 x	5.200700 =	5.200700

			T.E =	397.699704
5432	5432			
205		.070000 x	420.000000 =	29.400000
380		1.000000 x	16.150000 =	16.150000
003		5.000000 x	23.479183 =	117.395915
1475		.800000 x	37.464863 =	29.971890
1471		1.000000 x	5.200700 =	5.200700
002		5.000000 x	17.729980 =	88.649900

			T.E =	286.768405

5436	5436			
205		.050000 x	420.000000 =	21.000000
1476		1.000000 x	2.758380 =	2.758380
003		4.500000 x	23.479183 =	105.656324
002		4.500000 x	17.729980 =	79.784910

			T.E =	209.199614
5437	5437			
205		.065000 x	420.000000 =	27.300000
002		5.000000 x	17.729980 =	88.649900
003		5.000000 x	23.479183 =	117.395915
1476		1.000000 x	2.758380 =	2.758380

			T.E =	236.104195
5438	5438			
205		.050000 x	420.000000 =	21.000000
002		4.000000 x	17.729980 =	70.919920
003		4.000000 x	23.479183 =	93.916732
1476		1.000000 x	2.758380 =	2.758380

			T.E =	188.595032
5441.1	5441.1			
205		.065000 x	420.000000 =	27.300000
222.3		.004000 x	.000000 =	.000000
002		4.500000 x	17.729980 =	79.784910
1476		1.000000 x	2.758380 =	2.758380
003		4.500000 x	23.479183 =	105.656324

			T.E =	
5441.2	5441.2			
205		.065000 x	420.000000 =	27.300000
002		4.500000 x	17.729980 =	79.784910
223.3		.004000 x	1,135.000000 =	4.540000
003		4.500000 x	23.479183 =	105.656324
1476		1.000000 x	2.758380 =	2.758380

			T.E =	220.039614
5441.3	5441.3			
205		.065000 x	420.000000 =	27.300000
243.1		.550000 x	2.660000 =	1.463000
002		4.500000 x	17.729980 =	79.784910
1476		1.000000 x	2.758380 =	2.758380
003		4.500000 x	23.479183 =	105.656324

			T.E =	216.962614

5442.1	5442.1			
205		.080000 x	420.000000 =	33.600000
222.3		.004000 x	.000000 =	.000000
1476		1.000000 x	2.758380 =	2.758380
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900

			T.E =	
5442.2	5442.2			
205		.080000 x	420.000000 =	33.600000
223.3		.004000 x	1,135.000000 =	4.540000
003		5.000000 x	23.479183 =	117.395915
1476		1.000000 x	2.758380 =	2.758380
002		5.000000 x	17.729980 =	88.649900

			T.E =	246.944195
5442.3	5442.3			
205		.080000 x	420.000000 =	33.600000
002		5.000000 x	17.729980 =	88.649900
1476		1.000000 x	2.758380 =	2.758380
003		5.000000 x	23.479183 =	117.395915
243.1		.055000 x	2.660000 =	.146300

			T.E =	242.550495
5443.1	5443.1			
205		.065000 x	420.000000 =	27.300000
1476		1.000000 x	2.758380 =	2.758380
003		4.000000 x	23.479183 =	93.916732
222.3		.004000 x	.000000 =	.000000
002		4.000000 x	17.729980 =	70.919920

			T.E =	
5443.2	5443.2			
205		.065000 x	420.000000 =	27.300000
223.3		.004000 x	1,135.000000 =	4.540000
003		4.000000 x	23.479183 =	93.916732
1476		1.000000 x	2.758380 =	2.758380
002		4.000000 x	17.729980 =	70.919920

			T.E =	199.435032

5443.3	5443.3			
205		.065000 x	420.000000 =	27.300000
243.1		.550000 x	2.660000 =	1.463000
1476		1.000000 x	2.758380 =	2.758380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920

			T.E =	196.358032
5446.1	5446.1			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.758380 =	2.758380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
222.2		.010000 x	.000000 =	.000000

			T.E =	
5446.2	5446.2			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.758380 =	2.758380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
223.2		.010000 x	1,450.000000 =	14.500000
205		.025000 x	420.000000 =	10.500000

			T.E =	200.970032
5447.1	5447.1			
203.2		.025000 x	335.000000 =	8.375000
002		4.500000 x	17.729980 =	79.784910
1476		1.000000 x	2.758380 =	2.758380
003		4.500000 x	23.479183 =	105.656324
222.2		.010000 x	.000000 =	.000000
205		.040000 x	420.000000 =	16.800000

			T.E =	
5447.2	5447.2			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.758380 =	2.758380
003		4.500000 x	23.479183 =	105.656324
002		4.500000 x	17.729980 =	79.784910
223.2		.010000 x	1,450.000000 =	14.500000
205		.040000 x	420.000000 =	16.800000

			T.E =	227.874614

5448.1	5448.1			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.758380 =	2.758380
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
222.2		.010000 x	.000000 =	.000000

			T.E =	
5448.2	5448.2			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.758380 =	2.758380
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
223.2		.010000 x	1,450.000000 =	14.500000
205		.025000 x	420.000000 =	10.500000

			T.E =	180.365451
5449	5449			
205		.045000 x	420.000000 =	18.900000
243.5		.850000 x	6.250000 =	5.312500
1476		1.000000 x	2.758380 =	2.758380
003		3.000000 x	23.479183 =	70.437549
002		3.000000 x	17.729980 =	53.189940

			T.E =	150.598369
5451.1	5451.1			
205		.090000 x	420.000000 =	37.800000
1476		1.000000 x	2.758380 =	2.758380
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
222.3		.004000 x	.000000 =	.000000

			T.E =	
5451.2	5451.2			
205		.090000 x	420.000000 =	37.800000
003		5.000000 x	23.479183 =	117.395915
1476		1.000000 x	2.758380 =	2.758380
002		5.000000 x	17.729980 =	88.649900
223.3		.004000 x	1,135.000000 =	4.540000

			T.E =	251.144195

5451.3	5451.3			
205		.090000 x	420.000000 =	37.800000
002		5.000000 x	17.729980 =	88.649900
1476		1.000000 x	2.758380 =	2.758380
003		5.000000 x	23.479183 =	117.395915
243.1		.550000 x	2.660000 =	1.463000
			T.E =	248.067195
5456	5456			
205		.055000 x	420.000000 =	23.100000
1478		1.000000 x	2.940250 =	2.940250
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
			T.E =	190.876902
5457	5457			
205		.085000 x	420.000000 =	35.700000
1476		1.500000 x	2.758380 =	4.137570
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860
261		2.200000 x	.523400 =	1.151480
			T.E =	329.453191
5461.1	5461.1			
205		.065000 x	420.000000 =	27.300000
1479		1.000000 x	34.126693 =	34.126693
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890
222.2		.010000 x	.000000 =	.000000
			T.E =	
5461.2	5461.2			
205		.065000 x	420.000000 =	27.300000
002		5.500000 x	17.729980 =	97.514890
223.2		.010000 x	1,450.000000 =	14.500000
1479		1.000000 x	34.126693 =	34.126693
003		5.500000 x	23.479183 =	129.135507
			T.E =	302.577090
5462.1	5462.1			
205		.065000 x	420.000000 =	27.300000
002		5.500000 x	17.729980 =	97.514890
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	23.479183 =	129.135507
1480		1.000000 x	33.049676 =	33.049676
			T.E =	

5462.2	5462.2			
205		.065000 x	420.000000 =	27.300000
223.2		.010000 x	1,450.000000 =	14.500000
002		5.500000 x	17.729980 =	97.514890
1480		1.000000 x	33.049676 =	33.049676
003		5.500000 x	23.479183 =	129.135507

			T.E =	301.500073
5463.1	5463.1			
205		.055000 x	420.000000 =	23.100000
222.2		.010000 x	.000000 =	.000000
1479		.500000 x	34.126693 =	17.063347
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880

			T.E =	
5463.2	5463.2			
205		.055000 x	420.000000 =	23.100000
002		6.000000 x	17.729980 =	106.379880
1479		.500000 x	34.126693 =	17.063347
003		6.000000 x	23.479183 =	140.875098
223.2		.010000 x	1,450.000000 =	14.500000

			T.E =	301.918325
5464.1	5464.1			
205		.070000 x	420.000000 =	29.400000
222.2		.010000 x	.000000 =	.000000
002		7.000000 x	17.729980 =	124.109860
1479		.500000 x	34.126693 =	17.063347
003		7.000000 x	23.479183 =	164.354281

			T.E =	
5464.2	5464.2			
205		.070000 x	420.000000 =	29.400000
002		7.000000 x	17.729980 =	124.109860
223.2		.010000 x	1,450.000000 =	14.500000
003		7.000000 x	23.479183 =	164.354281
1479		.500000 x	34.126693 =	17.063347

			T.E =	349.427488

5465.1	5465.1			
203.2		.045000 x	335.000000 =	15.075000
002		5.500000 x	17.729980 =	97.514890
222.2		.005000 x	.000000 =	.000000
1476		1.000000 x	2.758380 =	2.758380
003		5.500000 x	23.479183 =	129.135507
208		.030000 x	1,239.000000 =	37.170000

T.E =

5465.2	5465.2			
203.2		.045000 x	335.000000 =	15.075000
1476		1.000000 x	2.758380 =	2.758380
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890
223.2		.005000 x	1,450.000000 =	7.250000
208		.030000 x	1,239.000000 =	37.170000

T.E =

288.903777

5466.1	5466.1			
203.2		.025000 x	335.000000 =	8.375000
002		5.000000 x	17.729980 =	88.649900
1479		.900000 x	34.126693 =	30.714024
003		5.000000 x	23.479183 =	117.395915
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
1479		.900000 x	34.126693 =	30.714024
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900

T.E =

259.634839

5467.1	5467.1			
203.2		.013000 x	335.000000 =	4.355000
222.2		.000960 x	.000000 =	.000000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
222.2		.012000 x	.000000 =	.000000
203.2		.001040 x	335.000000 =	.348400

T.E =

5467.2	5467.2			
203.2		.013000 x	335.000000 =	4.355000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
223.2		.012000 x	1,450.000000 =	17.400000
223.2		.000960 x	1,450.000000 =	1.392000
203.2		.001040 x	335.000000 =	.348400

			T.E =	167.727471
5468.1	5468.1			
203.2		.025000 x	335.000000 =	8.375000
203.2		.002000 x	335.000000 =	.670000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000

			T.E =	
5468.2	5468.2			
203.2		.025000 x	335.000000 =	8.375000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
223.2		.000800 x	1,450.000000 =	1.160000
223.2		.010000 x	1,450.000000 =	14.500000
203.2		.002000 x	335.000000 =	.670000

			T.E =	189.541652
5469.1	5469.1			
203.2		.025000 x	335.000000 =	8.375000
222.2		.010000 x	.000000 =	.000000
1479		.500000 x	34.126693 =	17.063347
003		4.500000 x	23.479183 =	105.656324
002		4.500000 x	17.729980 =	79.784910

			T.E =	
5469.2	5469.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.500000 x	23.479183 =	105.656324
1479		.500000 x	34.126693 =	17.063347
002		4.500000 x	17.729980 =	79.784910

			T.E =	225.379580

5471	5471			
203.2		.035000 x	335.000000 =	11.725000
251		3.000000 x	.650000 =	1.950000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930

			T.E =	157.907071
5472.1	5472.1			
203.2		.026000 x	335.000000 =	8.710000
003		3.500000 x	23.479183 =	82.177141
222.4		.010000 x	.000000 =	.000000
002		3.500000 x	17.729980 =	62.054930
251		3.000000 x	.650000 =	1.950000

			T.E =	
5472.2	5472.2			
203.2		.026000 x	335.000000 =	8.710000
251		3.000000 x	.650000 =	1.950000
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141
223.4		.010000 x	1,440.000000 =	14.400000

			T.E =	169.292071
5501.1	5501.1			
211		.040000 x	.000000 =	.000000
003		5.000000 x	23.479183 =	117.395915
002		2.500000 x	17.729980 =	44.324950
252		.100000 x	1.750000 =	.175000
251		.050000 x	.650000 =	.032500

			T.E =	
5501.2	5501.2			
212		.040000 x	1,400.000000 =	56.000000
003		5.000000 x	23.479183 =	117.395915
002		2.500000 x	17.729980 =	44.324950
252		.100000 x	1.750000 =	.175000
251		.050000 x	.650000 =	.032500

			T.E =	217.928365
5502	5502			
210		.040000 x	.000000 =	.000000
252		.100000 x	1.750000 =	.175000
251		.050000 x	.650000 =	.032500
003		4.000000 x	23.479183 =	93.916732
002		2.000000 x	17.729980 =	35.459960

			T.E =	

5511.1	5511.1			
211		.020000 x	.000000 =	.000000
252		.100000 x	1.750000 =	.175000
003		3.200000 x	23.479183 =	75.133386
002		1.600000 x	17.729980 =	28.367968

			T.E =	
5511.2	5511.2			
212		.020000 x	1,400.000000 =	28.000000
252		.100000 x	1.750000 =	.175000
003		3.200000 x	23.479183 =	75.133386
002		1.600000 x	17.729980 =	28.367968

			T.E =	131.676354
5512	5512			
205		.020000 x	420.000000 =	8.400000
003		3.000000 x	23.479183 =	70.437549
252		.100000 x	1.750000 =	.175000
002		1.500000 x	17.729980 =	26.594970

			T.E =	105.607519
5513.1	5513.1			
211		.020000 x	.000000 =	.000000
002		2.000000 x	17.729980 =	35.459960
003		4.000000 x	23.479183 =	93.916732
252		.100000 x	1.750000 =	.175000

			T.E =	
5513.2	5513.2			
212		.020000 x	1,400.000000 =	28.000000
003		4.000000 x	23.479183 =	93.916732
002		2.000000 x	17.729980 =	35.459960
252		.100000 x	1.750000 =	.175000

			T.E =	157.551692
5514	5514			
205		.020000 x	420.000000 =	8.400000
003		3.800000 x	23.479183 =	89.220895
002		1.800000 x	17.729980 =	31.913964
252		.100000 x	1.750000 =	.175000

			T.E =	129.709859

5521	5521			
205		.030000 x	420.000000 =	12.600000
252		.150000 x	1.750000 =	.262500
002		.800000 x	17.729980 =	14.183984
003		2.000000 x	23.479183 =	46.958366

			T.E =	74.004850
5531.1	5531.1			
211		.010000 x	.000000 =	.000000
252		.020000 x	1.750000 =	.035000
003		2.200000 x	23.479183 =	51.654203
002		.700000 x	17.729980 =	12.410986

			T.E =	
5531.2	5531.2			
212		.010000 x	1,400.000000 =	14.000000
252		.020000 x	1.750000 =	.035000
003		2.200000 x	23.479183 =	51.654203
002		.700000 x	17.729980 =	12.410986

			T.E =	78.100189
5531.3	5531.3			
205		.010000 x	420.000000 =	4.200000
003		2.200000 x	23.479183 =	51.654203
002		.700000 x	17.729980 =	12.410986
252		.020000 x	1.750000 =	.035000

			T.E =	68.300189
5532.1	5532.1			
211		.010000 x	.000000 =	.000000
252		.020000 x	1.750000 =	.035000
003		3.000000 x	23.479183 =	70.437549
002		1.000000 x	17.729980 =	17.729980

			T.E =	
5532.2	5532.2			
212		.010000 x	1,400.000000 =	14.000000
252		.020000 x	1.750000 =	.035000
003		3.000000 x	23.479183 =	70.437549
002		1.000000 x	17.729980 =	17.729980

			T.E =	102.202529

5532.3	5532.3			
205		.010000 x	420.000000 =	4.200000
003		3.000000 x	23.479183 =	70.437549
002		1.000000 x	17.729980 =	17.729980
252		.020000 x	1.750000 =	.035000

			T.E =	92.402529
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	23.479183 =	8.217714

			T.E =	10.002714
5601	5601			
203.2		.028000 x	335.000000 =	9.380000
003		2.500000 x	23.479183 =	58.697958
002		2.500000 x	17.729980 =	44.324950
251		4.000000 x	.650000 =	2.600000

			T.E =	115.002908
5602	5602			
203.2		.018000 x	335.000000 =	6.030000
003		2.300000 x	23.479183 =	54.002121
002		2.300000 x	17.729980 =	40.778954
251		3.000000 x	.650000 =	1.950000

			T.E =	102.761075
5603	5603			
203.2		.013000 x	335.000000 =	4.355000
251		2.500000 x	.650000 =	1.625000
002		2.000000 x	17.729980 =	35.459960
003		2.000000 x	23.479183 =	46.958366

			T.E =	88.398326
5604	5604			
243.5		1.100000 x	6.250000 =	6.875000
243.5		.165000 x	6.250000 =	1.031250
003		2.200000 x	23.479183 =	51.654203
002		2.200000 x	17.729980 =	39.005956

			T.E =	98.566409

5605	5605			
243.3		1.100000 x	4.450000 =	4.895000
003		2.000000 x	23.479183 =	46.958366
002		2.000000 x	17.729980 =	35.459960
243.3		.187000 x	4.450000 =	.832150

			T.E =	88.145476
5606	5606			
243.2		1.100000 x	3.650000 =	4.015000
243.2		.220000 x	3.650000 =	.803000
003		1.800000 x	23.479183 =	42.262529
002		1.800000 x	17.729980 =	31.913964

			T.E =	78.994493
5607	5607			
205		.012000 x	420.000000 =	5.040000
205		.002400 x	420.000000 =	1.008000
003		2.500000 x	23.479183 =	58.697958
002		2.500000 x	17.729980 =	44.324950
242		.440000 x	1.300000 =	.572000
242		2.200000 x	1.300000 =	2.860000

			T.E =	112.502908
5608.1	5608.1			
205		.012000 x	420.000000 =	5.040000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
205		.002400 x	420.000000 =	1.008000
222.1		.006000 x	.000000 =	.000000
222.1		.001200 x	.000000 =	.000000

			T.E =	
5608.2	5608.2			
205		.012000 x	420.000000 =	5.040000
205		.002400 x	420.000000 =	1.008000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
223.1		.006000 x	1,700.000000 =	10.200000
223.1		.001200 x	1,700.000000 =	2.040000

			T.E =	162.520071

5611	5611			
205		.060000 x	420.000000 =	25.200000
002		7.000000 x	17.729980 =	124.109860
003		7.000000 x	23.479183 =	164.354281
251		5.000000 x	.650000 =	3.250000

			T.E =	316.914141
5612.1	5612.1			
205		.060000 x	420.000000 =	25.200000
251		5.000000 x	.650000 =	3.250000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860
222.1		.006000 x	.000000 =	.000000

			T.E =	
5612.2	5612.2			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860
251		5.000000 x	.650000 =	3.250000
223.1		.006000 x	1,700.000000 =	10.200000

			T.E =	327.114141
5613.1	5613.1			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
003		1.500000 x	23.479183 =	35.218775
002		1.500000 x	17.729980 =	26.594970
222.2		.003000 x	.000000 =	.000000

			T.E =	
5613.2	5613.2			
205		.015000 x	420.000000 =	6.300000
002		1.500000 x	17.729980 =	26.594970
003		1.500000 x	23.479183 =	35.218775
205		.001500 x	420.000000 =	.630000
223.2		.003000 x	1,450.000000 =	4.350000

			T.E =	73.093745
5614.1	5614.1			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
222.2		.002000 x	.000000 =	.000000
205		.001500 x	420.000000 =	.630000

			T.E =	

5614.2	5614.2			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
223.2		.002000 x	1,450.000000 =	2.900000
205		.001500 x	420.000000 =	.630000

			T.E =	57.180996
5615.1	5615.1			
205		.008000 x	420.000000 =	3.360000
205		.001440 x	420.000000 =	.604800
222.2		.000900 x	.000000 =	.000000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980

			T.E =	
5615.2	5615.2			
205		.008000 x	420.000000 =	3.360000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
223.2		.000900 x	1,450.000000 =	1.305000
205		.001440 x	420.000000 =	.604800

			T.E =	46.478963
5616	5616			
205		.003000 x	420.000000 =	1.260000
205		.007500 x	420.000000 =	3.150000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980

			T.E =	45.619163
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
521		.250000 x	2.390000 =	.597500

			T.E =	46.206663
5619	5619			
205		.001400 x	420.000000 =	.588000
003		.200000 x	23.479183 =	4.695837

			T.E =	5.283837

5620	5620			
203.2		.012000 x	335.000000 =	4.020000
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994
251		.020000 x	.650000 =	.013000
220		4.200000 x	.000000 =	.000000
			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
002		30.000000 x	17.729980 =	531.899400
003		30.000000 x	23.479183 =	704.375490
251		16.000000 x	.650000 =	10.400000
			T.E =	
5622	5622			
211		1.100000 x	.000000 =	.000000
251		16.000000 x	.650000 =	10.400000
003		30.000000 x	23.479183 =	704.375490
002		30.000000 x	17.729980 =	531.899400
			T.E =	
5626	5626			
205		.030000 x	420.000000 =	12.600000
251		1.000000 x	.650000 =	.650000
003		1.500000 x	23.479183 =	35.218775
002		1.500000 x	17.729980 =	26.594970
			T.E =	75.063745
6101	6101			
267		1.050000 x	.716500 =	.752325
003		.050000 x	23.479183 =	1.173959
			T.E =	1.926284
6102	6102			
252		.050000 x	1.750000 =	.087500
267		1.030000 x	.716500 =	.737995
003		.060000 x	23.479183 =	1.408751
			T.E =	2.234246
6103	6103			
268		1.050000 x	.826500 =	.867825
003		.050000 x	23.479183 =	1.173959
			T.E =	2.041784

6104	6104			
252		.050000 x	1.750000 =	.087500
268		1.030000 x	.826500 =	.851295
003		.060000 x	23.479183 =	1.408751

			T.E =	2.347546
6111	6111			
266		1.100000 x	.553000 =	.608300
003		.150000 x	23.479183 =	3.521877

			T.E =	4.130177
6116	6116			
280		1.050000 x	1.000000 =	1.050000
003		.100000 x	23.479183 =	2.347918

			T.E =	3.397918
6117	6117			
281		1.050000 x	5.780000 =	6.069000
003		.150000 x	23.479183 =	3.521877

			T.E =	9.590877
6118	6118			
266		1.150000 x	.553000 =	.635950
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	8.877783
6119	6119			
293		1.100000 x	.000000 =	.000000
003		.150000 x	23.479183 =	3.521877

			T.E =	
6120	6120			
289		1.050000 x	.707000 =	.742350
003		.100000 x	23.479183 =	2.347918

			T.E =	3.090268
6121	6121			
266		1.100000 x	.553000 =	.608300
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	8.850133

6122	6122			
265		1.050000 x	.641500 =	.673575
003		.200000 x	23.479183 =	4.695837

			T.E =	5.369412
6123	6123			
265		.900000 x	.641500 =	.577350
265		.090000 x	.641500 =	.057735
266		.100000 x	.553000 =	.055300
002		.150000 x	17.729980 =	2.659497
266		.010000 x	.553000 =	.005530
003		.150000 x	23.479183 =	3.521877

			T.E =	6.877289
6126	6126			
265		1.250000 x	.641500 =	.801875
003		.200000 x	23.479183 =	4.695837
003		.200000 x	23.479183 =	4.695837

			T.E =	10.193548
6127	6127			
290		4.800000 x	3.300000 =	15.840000
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984

			T.E =	48.807330
6128	6128			
290		1.200000 x	3.300000 =	3.960000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	12.201833
6201	6201			
264		1.400000 x	1.008000 =	1.411200
002		.250000 x	17.729980 =	4.432495
003		.250000 x	23.479183 =	5.869796

			T.E =	11.713491
6202	6202			
264		1.300000 x	1.008000 =	1.310400
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	9.552233

6203	6203			
282		1.200000 x	.719000 =	.862800
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	15.286007
6204	6204			
282		1.300000 x	.719000 =	.934700
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	17.418365
6205	6205			
277		1.250000 x	.754000 =	.942500
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	21.547082
6221	6221			
265		1.150000 x	.641500 =	.737725
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	8.979558
6222	6222			
265		1.200000 x	.641500 =	.769800
003		.350000 x	23.479183 =	8.217714
002		.350000 x	17.729980 =	6.205493

			T.E =	15.193007
6223	6223			
265		1.250000 x	.641500 =	.801875
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990

			T.E =	21.406457
6224	6224			
271		.720000 x	.736500 =	.530280
282		.480000 x	.719000 =	.345120
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	9.117233

6225	6225			
271		.720000 x	.736500 =	.530280
002		.250000 x	17.729980 =	4.432495
003		.250000 x	23.479183 =	5.869796
282		.480000 x	.719000 =	.345120

			T.E =	11.177691
6226	6226			
265		1.200000 x	.641500 =	.769800
002		.700000 x	17.729980 =	12.410986
003		.700000 x	23.479183 =	16.435428

			T.E =	29.616214
6227	6227			
265		1.250000 x	.641500 =	.801875
002		.850000 x	17.729980 =	15.070483
003		.850000 x	23.479183 =	19.957306

			T.E =	35.829664
6228	6228			
282		1.250000 x	.719000 =	.898750
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	17.382415
6229	6229			
282		1.250000 x	.719000 =	.898750
002		.450000 x	17.729980 =	7.978491
003		.450000 x	23.479183 =	10.565632

			T.E =	19.442873
6230	6230			
277		1.100000 x	.754000 =	.829400
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	21.433982
6231	6231			
265		1.150000 x	.641500 =	.737725
003		.250000 x	23.479183 =	5.869796
002		.250000 x	17.729980 =	4.432495

			T.E =	11.040016

6232	6232			
265		1.150000 x	.641500 =	.737725
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992

			T.E =	17.221390
6236	6236			
253		.500000 x	2.200000 =	1.100000
003		1.800000 x	23.479183 =	42.262529
002		1.800000 x	17.729980 =	31.913964
565.3		.350000 x	3.060000 =	1.071000
392		.350000 x	24.930000 =	8.725500
390		2.100000 x	1.500000 =	3.150000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
276		5.850000 x	.518500 =	3.033225
272		1.500000 x	.666500 =	.999750
266		2.000000 x	.553000 =	1.106000

			T.E =	120.486968
6237	6237			
253		.850000 x	2.200000 =	1.870000
260		9.500000 x	.492800 =	4.681600
388		.350000 x	48.870000 =	17.104500
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
565.5		.350000 x	4.530000 =	1.585500
392		.350000 x	24.930000 =	8.725500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.666500 =	3.332500
266		2.100000 x	.553000 =	1.161300

			T.E =	213.318052
6238	6238			
253		.400000 x	2.200000 =	.880000
266		13.000000 x	.553000 =	7.189000
002		5.000000 x	17.729980 =	88.649900
265		6.000000 x	.641500 =	3.849000
003		5.000000 x	23.479183 =	117.395915

			T.E =	217.963815
6239	6239			
277		1.100000 x	.754000 =	.829400
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994

			T.E =	13.192149

6301	6301			
266		1.250000 x	.553000 =	.691250
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992

			T.E =	17.174915
6302	6302			
266		9.000000 x	.553000 =	4.977000
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141

			T.E =	149.209071
6401	6401			
265		1.150000 x	.641500 =	.737725
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	8.979558
6402	6402			
265		1.200000 x	.641500 =	.769800
002		.300000 x	17.729980 =	5.318994
003		.300000 x	23.479183 =	7.043755

			T.E =	13.132549
6403	6403			
265		1.250000 x	.641500 =	.801875
003		.350000 x	23.479183 =	8.217714
002		.350000 x	17.729980 =	6.205493

			T.E =	15.225082
6406	6406			
265		1.200000 x	.641500 =	.769800
002		.600000 x	17.729980 =	10.637988
003		.600000 x	23.479183 =	14.087510

			T.E =	25.495298
6407	6407			
265		1.250000 x	.641500 =	.801875
002		.700000 x	17.729980 =	12.410986
003		.700000 x	23.479183 =	16.435428

			T.E =	29.648289

6411	6411			
565.3		1.650000 x	3.060000 =	5.049000
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	19.472207
6412	6412			
565.5		1.550000 x	4.530000 =	7.021500
003		.450000 x	23.479183 =	10.565632
002		.450000 x	17.729980 =	7.978491

			T.E =	25.565623
6413	6413			
565.6		1.450000 x	6.290000 =	9.120500
002		.550000 x	17.729980 =	9.751489
003		.550000 x	23.479183 =	12.913551

			T.E =	31.785540
6416	6416			
566.3		1.600000 x	4.090000 =	6.544000
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	20.967207
6417	6417			
566.5		1.500000 x	6.240000 =	9.360000
002		.450000 x	17.729980 =	7.978491
003		.450000 x	23.479183 =	10.565632

			T.E =	27.904123
6418	6418			
566.6		1.400000 x	8.330000 =	11.662000
003		.550000 x	23.479183 =	12.913551
002		.550000 x	17.729980 =	9.751489

			T.E =	34.327040
6421	6421			
565.3		1.050000 x	3.060000 =	3.213000
003		.400000 x	23.479183 =	9.391673

			T.E =	12.604673

6422	6422				
565.5		1.050000 x	4.530000 =		4.756500
003		.500000 x	23.479183 =		11.739592

			T.E =		16.496092
6423	6423				
565.6		1.050000 x	6.290000 =		6.604500
003		.600000 x	23.479183 =		14.087510

			T.E =		20.692010
6426	6426				
566.3		1.050000 x	4.090000 =		4.294500
003		.400000 x	23.479183 =		9.391673

			T.E =		13.686173
6427	6427				
566.5		1.050000 x	6.240000 =		6.552000
003		.500000 x	23.479183 =		11.739592

			T.E =		18.291592
6428	6428				
566.6		1.050000 x	8.330000 =		8.746500
003		.600000 x	23.479183 =		14.087510

			T.E =		22.834010
6431	6431				
278		1.100000 x	3.600000 =		3.960000
003		.150000 x	23.479183 =		3.521877

			T.E =		7.481877
6432	6432				
251		.100000 x	.650000 =		.065000
279		1.080000 x	3.720000 =		4.017600
003		.250000 x	23.479183 =		5.869796
002		.250000 x	17.729980 =		4.432495

			T.E =		14.384891
6441	6441				
266		1.100000 x	.553000 =		.608300
003		.100000 x	23.479183 =		2.347918
002		.100000 x	17.729980 =		1.772998

			T.E =		4.729216

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	23.479183 =	.939167

			T.E =	
6446.2	6446.2			
285		1.100000 x	.052500 =	.057750
003		.040000 x	23.479183 =	.939167

			T.E =	.996917
6447	6447			
251		.050000 x	.650000 =	.032500
002		.100000 x	17.729980 =	1.772998
003		.100000 x	23.479183 =	2.347918
286		1.050000 x	1.627700 =	1.709085

			T.E =	5.862501
6448	6448			
251		.050000 x	.650000 =	.032500
003		.100000 x	23.479183 =	2.347918
002		.100000 x	17.729980 =	1.772998
288		1.050000 x	1.766700 =	1.855035

			T.E =	6.008451
6501	6501			
282		3.000000 x	.719000 =	2.157000
002		4.000000 x	17.729980 =	70.919920
003		4.000000 x	23.479183 =	93.916732
296		1.000000 x	11.781900 =	11.781900
295		11.000000 x	5.649200 =	62.141200

			T.E =	240.916752
6502	6502			
002		1.500000 x	17.729980 =	26.594970
003		1.500000 x	23.479183 =	35.218775
6501		1.000000 x	240.916752 =	240.916752

			T.E =	302.730497
6503	6503			
002		1.300000 x	17.729980 =	23.048974
6501		.950000 x	240.916752 =	228.870914
003		1.300000 x	23.479183 =	30.522938

			T.E =	282.442826

6504	6504			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.910000 x	240.916752 =	219.234244

			T.E =	268.685240
6505	6505			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		.870000 x	240.916752 =	209.597574

			T.E =	250.806737
6506	6506			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		.810000 x	240.916752 =	195.142569

			T.E =	236.351732
6507	6507			
002		.900000 x	17.729980 =	15.956982
6501		.920000 x	240.916752 =	221.643412
003		.900000 x	23.479183 =	21.131265

			T.E =	258.731659
6508	6508			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.030000 x	240.916752 =	248.144255

			T.E =	301.716166
6509	6509			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		1.010000 x	240.916752 =	243.325920

			T.E =	284.535083
6510	6510			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.080000 x	240.916752 =	260.190092

			T.E =	309.641088

6511	6511			
002		1.500000 x	17.729980 =	26.594970
6501		.920000 x	240.916752 =	221.643412
003		1.500000 x	23.479183 =	35.218775

			T.E =	283.457156
6512	6512			
002		1.400000 x	17.729980 =	24.821972
003		1.400000 x	23.479183 =	32.870856
6501		.820000 x	240.916752 =	197.551737

			T.E =	255.244565
6513	6513			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		.780000 x	240.916752 =	187.915067

			T.E =	241.486978
6514	6514			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.760000 x	240.916752 =	183.096732

			T.E =	232.547727
6515	6515			
002		1.000000 x	17.729980 =	17.729980
6501		.800000 x	240.916752 =	192.733402
003		1.000000 x	23.479183 =	23.479183

			T.E =	233.942565
6516	6516			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.220000 x	240.916752 =	293.918437

			T.E =	347.490349
6517	6517			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.120000 x	240.916752 =	269.826762

			T.E =	319.277758

6518	6518			
002		1.100000 x	17.729980 =	19.502978
003		1.100000 x	23.479183 =	25.827101
6501		.670000 x	240.916752 =	161.414224

			T.E =	206.744303
6519	6519			
002		1.300000 x	17.729980 =	23.048974
6501		1.280000 x	240.916752 =	308.373443
003		1.300000 x	23.479183 =	30.522938

			T.E =	361.945354
6520	6520			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.120000 x	240.916752 =	269.826762

			T.E =	319.277758
6521	6521			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.210000 x	240.916752 =	291.509270

			T.E =	345.081182
6522	6522			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.190000 x	240.916752 =	286.690935

			T.E =	336.141930
6523	6523			
002		1.200000 x	17.729980 =	21.275976
6501		1.280000 x	240.916752 =	308.373443
003		1.200000 x	23.479183 =	28.175020

			T.E =	357.824438
6524	6524			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.800000 x	240.916752 =	192.733402

			T.E =	242.184397

6525	6525			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.040000 x	240.916752 =	250.553422

			T.E =	300.004418
6526	6526			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		.900000 x	240.916752 =	216.825077

			T.E =	270.396989
6527	6527			
002		1.300000 x	17.729980 =	23.048974
6501		1.120000 x	240.916752 =	269.826762
003		1.300000 x	23.479183 =	30.522938

			T.E =	323.398674
6528	6528			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.840000 x	240.916752 =	202.370072

			T.E =	251.821067
6529	6529			
002		1.200000 x	17.729980 =	21.275976
6501		1.080000 x	240.916752 =	260.190092
003		1.200000 x	23.479183 =	28.175020

			T.E =	309.641088
6530	6530			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		.710000 x	240.916752 =	171.050894

			T.E =	212.260057
6531	6531			
002		.600000 x	17.729980 =	10.637988
003		.600000 x	23.479183 =	14.087510
6501		.480000 x	240.916752 =	115.640041

			T.E =	140.365539

6532	6532			
294		6.000000 x	3.099000 =	18.594000
003		2.500000 x	23.479183 =	58.697958
002		2.500000 x	17.729980 =	44.324950
294		.300000 x	3.099000 =	.929700
296		1.000000 x	11.781900 =	11.781900

			T.E =	134.328508
6541	6541			
282		.350000 x	.719000 =	.251650
002		.500000 x	17.729980 =	8.864990
296		.120000 x	11.781900 =	1.413828
003		.500000 x	23.479183 =	11.739592
295		1.050000 x	5.649200 =	5.931660

			T.E =	28.201720
6542	6542			
295		1.050000 x	5.649200 =	5.931660
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984
296		.100000 x	11.781900 =	1.178190

			T.E =	40.077180
6543	6543			
295		.400000 x	5.649200 =	2.259680
296		.130000 x	11.781900 =	1.531647
003		.200000 x	23.479183 =	4.695837

			T.E =	8.487164
7101	7101			
201		.000500 x	290.000000 =	.145000
002		.500000 x	17.729980 =	8.864990
1445		.010000 x	60.956500 =	.609565
003		.850000 x	23.479183 =	19.957306

			T.E =	29.576861
7102	7102			
201		.000500 x	290.000000 =	.145000
1445		.010000 x	60.956500 =	.609565
002		.400000 x	17.729980 =	7.091992
003		.700000 x	23.479183 =	16.435428

			T.E =	24.281985

7103	7103			
201		.000500 x	290.000000 =	.145000
1445		.004000 x	60.956500 =	.243826
003		.600000 x	23.479183 =	14.087510
002		.300000 x	17.729980 =	5.318994

			T.E =	19.795330
7104	7104			
201		.000500 x	290.000000 =	.145000
1445		.008000 x	60.956500 =	.487652
002		.600000 x	17.729980 =	10.637988
003		1.000000 x	23.479183 =	23.479183

			T.E =	34.749823
7111	7111			
201		.000500 x	290.000000 =	.145000
003		.600000 x	23.479183 =	14.087510
1413		.027000 x	29.264100 =	.790131
001		.300000 x	15.951934 =	4.785580

			T.E =	19.808221
7116	7116			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.951934 =	5.583177
003		.650000 x	23.479183 =	15.261469
1418		.027000 x	41.286750 =	1.114742

			T.E =	22.104388
7121	7121			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.951934 =	4.785580
1445		.027000 x	60.956500 =	1.645826
003		.800000 x	23.479183 =	18.783346

			T.E =	25.359752
7122	7122			
201		.000500 x	290.000000 =	.145000
1444		.027000 x	74.687500 =	2.016563
003		.800000 x	23.479183 =	18.783346
001		.300000 x	15.951934 =	4.785580

			T.E =	25.730489

7123	7123			
201		.000500 x	290.000000 =	.145000
1462		.015000 x	84.531250 =	1.267969
1446		.006000 x	52.110500 =	.312663
001		.300000 x	15.951934 =	4.785580
003		.900000 x	23.479183 =	21.131265
1445		.006000 x	60.956500 =	.365739
			T.E =	28.008216
7124.1	7124.1			
201		.000500 x	290.000000 =	.145000
1465		.015000 x	95.610150 =	1.434152
001		.300000 x	15.951934 =	4.785580
1445		.012000 x	60.956500 =	.731478
003		.900000 x	23.479183 =	21.131265
			T.E =	28.227475
7124.2	7124.2			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.951934 =	4.785580
1445		.012000 x	60.956500 =	.731478
1466		.015000 x	93.355950 =	1.400339
003		.900000 x	23.479183 =	21.131265
			T.E =	28.193662
7124.3	7124.3			
201		.000500 x	290.000000 =	.145000
1467		.015000 x	88.096150 =	1.321442
1445		.012000 x	60.956500 =	.731478
003		.900000 x	23.479183 =	21.131265
001		.300000 x	15.951934 =	4.785580
			T.E =	28.114765
7131	7131			
201		.000500 x	290.000000 =	.145000
1426		.006000 x	152.456250 =	.914738
1413		.021000 x	29.264100 =	.614546
001		.300000 x	15.951934 =	4.785580
003		.600000 x	23.479183 =	14.087510
			T.E =	20.547374

7132	7132			
201		.000500 x	290.000000 =	.145000
1427		.006000 x	162.974700 =	.977848
001		.350000 x	15.951934 =	5.583177
1418		.021000 x	41.286750 =	.867022
003		.650000 x	23.479183 =	15.261469

			T.E =	22.834516
7133	7133			
201		.000500 x	290.000000 =	.145000
1463		.015000 x	71.937750 =	1.079066
1418		.006000 x	41.286750 =	.247721
001		.350000 x	15.951934 =	5.583177
1427		.006000 x	162.974700 =	.977848
003		.600000 x	23.479183 =	14.087510

			T.E =	22.120322
7134	7134			
201		.000500 x	290.000000 =	.145000
1464		.015000 x	57.951600 =	.869274
1427		.006000 x	162.974700 =	.977848
1418		.006000 x	41.286750 =	.247721
003		.600000 x	23.479183 =	14.087510
001		.350000 x	15.951934 =	5.583177

			T.E =	21.910529
7136	7136			
201		.000500 x	290.000000 =	.145000
001		.250000 x	15.951934 =	3.987984
003		.400000 x	23.479183 =	9.391673
1418		.017000 x	41.286750 =	.701875

			T.E =	14.226531
7138	7138			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.951934 =	4.785580
1418		.027000 x	41.286750 =	1.114742
003		.800000 x	23.479183 =	18.783346

			T.E =	24.828669
7141	7141			
201		.000500 x	290.000000 =	.145000
001		.400000 x	15.951934 =	6.380774
1445		.027000 x	60.956500 =	1.645826
003		1.000000 x	23.479183 =	23.479183

			T.E =	31.650782

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
003		.650000 x	23.479183 =	15.261469
001		.350000 x	15.951934 =	5.583177

			T.E =	
7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.350000 x	15.951934 =	5.583177
003		.650000 x	23.479183 =	15.261469
1421		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849

			T.E =	
7148	7148			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
001		.450000 x	15.951934 =	7.178370
1413		.014000 x	29.264100 =	.409697
003		.600000 x	23.479183 =	14.087510

			T.E =	
7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.450000 x	15.951934 =	7.178370
1413		.007000 x	29.264100 =	.204849
1422		.016000 x	.000000 =	.000000
003		.600000 x	23.479183 =	14.087510

			T.E =	
7150	7150			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
1418		.014000 x	41.286750 =	.578015
003		.650000 x	23.479183 =	15.261469
001		.350000 x	15.951934 =	5.583177

			T.E =	

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.951934 =	5.583177
003		.650000 x	23.479183 =	15.261469
1422		.016000 x	.000000 =	.000000
1427		.007000 x	162.974700 =	1.140823
1418		.007000 x	41.286750 =	.289007

			T.E =	
7152	7152			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.951934 =	7.178370
003		.700000 x	23.479183 =	16.435428
1447		.014000 x	58.155900 =	.814183
1448		.016000 x	.000000 =	.000000

			T.E =	
7153	7153			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.951934 =	7.178370
1447		.007000 x	58.155900 =	.407091
1448		.016000 x	.000000 =	.000000
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	23.479183 =	16.435428

			T.E =	
7161	7161			
201		.000800 x	290.000000 =	.232000
1453		.020000 x	162.012750 =	3.240255
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	23.479183 =	37.566693
002		1.600000 x	17.729980 =	28.367968
001		.600000 x	15.951934 =	9.571160

			T.E =	80.319119
7162	7162			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.951934 =	9.571160
002		1.600000 x	17.729980 =	28.367968
1458		.020000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	23.479183 =	37.566693

			T.E =	

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	185.502750 =	3.710055
1445		.022000 x	60.956500 =	1.341043
001		.600000 x	15.951934 =	9.571160
003		1.600000 x	23.479183 =	37.566693
002		1.600000 x	17.729980 =	28.367968
			T.E =	80.788919
7164	7164			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.951934 =	9.571160
003		1.600000 x	23.479183 =	37.566693
1455		.020000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
002		1.600000 x	17.729980 =	28.367968
			T.E =	
7165	7165			
201		.000800 x	290.000000 =	.232000
1459		.020000 x	202.002750 =	4.040055
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	23.479183 =	37.566693
002		1.600000 x	17.729980 =	28.367968
001		.600000 x	15.951934 =	9.571160
			T.E =	81.118919
7166	7166			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.951934 =	7.975967
003		1.200000 x	23.479183 =	28.175020
1445		.022000 x	60.956500 =	1.341043
1453		.017000 x	162.012750 =	2.754217
002		1.200000 x	17.729980 =	21.275976
			T.E =	61.754222
7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.951934 =	7.975967
1458		.017000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
			T.E =	

7168	7168			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.951934 =	7.975967
1454		.017000 x	185.502750 =	3.153547
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976

			T.E =	62.153552
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
001		.500000 x	15.951934 =	7.975967

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
003		1.200000 x	23.479183 =	28.175020
1459		.017000 x	202.002750 =	3.434047
1445		.022000 x	60.956500 =	1.341043
002		1.200000 x	17.729980 =	21.275976
001		.500000 x	15.951934 =	7.975967

			T.E =	62.434052
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.951934 =	1.595193

			T.E =	1.798193
7176	7176			
003		1.500000 x	23.479183 =	35.218775

			T.E =	35.218775
7177	7177			
003		1.100000 x	23.479183 =	25.827101

			T.E =	25.827101
7178	7178			
003		.900000 x	23.479183 =	21.131265

			T.E =	21.131265

7179	7179			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592
7181	7181			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
7206	7206			
142		26.000000 x	.325000 =	8.450000
1412		.040000 x	27.931800 =	1.117272
002		.300000 x	17.729980 =	5.318994
003		.600000 x	23.479183 =	14.087510

			T.E =	28.973776
7207	7207			
142		26.000000 x	.325000 =	8.450000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	23.479183 =	11.739592
002		.250000 x	17.729980 =	4.432495

			T.E =	25.180723
7208	7208			
142		26.000000 x	.325000 =	8.450000
003		.400000 x	23.479183 =	9.391673
1412		.025000 x	27.931800 =	.698295
002		.200000 x	17.729980 =	3.545996

			T.E =	22.085964
7209	7209			
142		26.000000 x	.325000 =	8.450000
1412		.005000 x	27.931800 =	.139659
003		.300000 x	23.479183 =	7.043755
002		.150000 x	17.729980 =	2.659497

			T.E =	18.292911
7211	7211			
146		15.000000 x	.340000 =	5.100000
1445		.001000 x	60.956500 =	.060957
003		.400000 x	23.479183 =	9.391673
002		.200000 x	17.729980 =	3.545996
283		.075000 x	1.000100 =	.075008

			T.E =	18.173633

7221	7221			
203.2		.001500 x	335.000000 =	.502500
003		.200000 x	23.479183 =	4.695837
492		.200000 x	.540000 =	.108000
002		.150000 x	17.729980 =	2.659497
506		1.150000 x	1.149500 =	1.321925
254		.020000 x	2.780000 =	.055600
			T.E =	9.343359
7222	7222			
254		.050000 x	2.780000 =	.139000
003		.250000 x	23.479183 =	5.869796
002		.150000 x	17.729980 =	2.659497
506		1.200000 x	1.149500 =	1.379400
492		.200000 x	.540000 =	.108000
			T.E =	10.155693
7223	7223			
254		.050000 x	2.780000 =	.139000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
508		1.200000 x	.860000 =	1.032000
493		.200000 x	.730000 =	.146000
			T.E =	9.558833
7231	7231			
274		1.200000 x	1.031800 =	1.238160
003		.250000 x	23.479183 =	5.869796
002		.250000 x	17.729980 =	4.432495
274		.200000 x	1.031800 =	.206360
			T.E =	11.746811
7241	7241			
297.2		.051072 x	.000000 =	.000000
003		1.400000 x	23.479183 =	32.870856
002		1.400000 x	17.729980 =	24.821972
495		.500000 x	.000000 =	.000000
001		.200000 x	15.951934 =	3.190387
			T.E =	

7242	7242			
297.2		.057000 x	.000000 =	.000000
002		2.800000 x	17.729980 =	49.643944
003		2.800000 x	23.479183 =	65.741712
001		.200000 x	15.951934 =	3.190387
495		1.000000 x	.000000 =	.000000

			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		1.300000 x	.650000 =	.845000

			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		1.300000 x	.650000 =	.845000

			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.650000 =	.845000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	
7244	7244			
251		1.200000 x	.650000 =	.780000
273		1.200000 x	.836500 =	1.003800
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980

			T.E =	42.992963
7245	7245			
251		.500000 x	.650000 =	.325000
273		1.200000 x	.836500 =	1.003800
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986

			T.E =	30.175214

7246	7246			
265		.500000 x	.641500 =	.320750
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
298.1		6.700000 x	4.210000 =	28.207000
			T.E =	69.736913
7301	7301			
096		1.050000 x	.000000 =	.000000
003		.900000 x	23.479183 =	21.131265
1444		.001500 x	74.687500 =	.112031
1445		.025000 x	60.956500 =	1.523913
001		.400000 x	15.951934 =	6.380774
			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1444		.002000 x	74.687500 =	.149375
1445		.025000 x	60.956500 =	1.523913
003		1.000000 x	23.479183 =	23.479183
001		.500000 x	15.951934 =	7.975967
			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	60.956500 =	1.523913
1444		.001000 x	74.687500 =	.074688
003		2.000000 x	23.479183 =	46.958366
001		1.000000 x	15.951934 =	15.951934
			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
001		.800000 x	15.951934 =	12.761547
1444		.001500 x	74.687500 =	.112031
1445		.025000 x	60.956500 =	1.523913
003		1.600000 x	23.479183 =	37.566693
			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
1445		.004000 x	60.956500 =	.243826
001		.150000 x	15.951934 =	2.392790
1444		.000200 x	74.687500 =	.014938
003		.300000 x	23.479183 =	7.043755
			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1417		.033000 x	39.954450 =	1.318497
001		.600000 x	15.951934 =	9.571160
1445		.005000 x	60.956500 =	.304783
003		2.200000 x	23.479183 =	51.654203

			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
1445		.005000 x	60.956500 =	.304783
1417		.033000 x	39.954450 =	1.318497
003		1.100000 x	23.479183 =	25.827101
001		.500000 x	15.951934 =	7.975967

			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.951934 =	6.380774
003		.900000 x	23.479183 =	21.131265
1445		.004000 x	60.956500 =	.243826
1417		.022000 x	39.954450 =	.878998

			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.951934 =	7.975967
003		2.500000 x	23.479183 =	58.697958
1449		.030000 x	52.690700 =	1.580721

			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
001		.100000 x	15.951934 =	1.595193
1449		.004000 x	52.690700 =	.210763
003		.300000 x	23.479183 =	7.043755

			T.E =	11.455391
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	52.690700 =	1.317268
1444		.002000 x	74.687500 =	.149375
003		.600000 x	23.479183 =	14.087510
001		.300000 x	15.951934 =	4.785580

			T.E =	27.374733

7317	7317			
163		1.050000 x	6.900000 =	7.245000
001		.300000 x	15.951934 =	4.785580
003		.800000 x	23.479183 =	18.783346
1449		.025000 x	52.690700 =	1.317268
1444		.001500 x	74.687500 =	.112031

			T.E =	32.243225
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	52.690700 =	1.317268
001		.100000 x	15.951934 =	1.595193
1444		.001000 x	74.687500 =	.074688
003		1.300000 x	23.479183 =	30.522938

			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
001		.100000 x	15.951934 =	1.595193
1444		.001000 x	74.687500 =	.074688
1449		.025000 x	52.690700 =	1.317268
003		1.300000 x	23.479183 =	30.522938

			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	52.690700 =	1.317268
1444		.001000 x	74.687500 =	.074688
003		1.500000 x	23.479183 =	35.218775
001		.400000 x	15.951934 =	6.380774

			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
001		.400000 x	15.951934 =	6.380774
1444		.001000 x	74.687500 =	.074688
1449		.025000 x	52.690700 =	1.317268
003		1.500000 x	23.479183 =	35.218775

			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
001		.040000 x	15.951934 =	.638077
1449		.002000 x	52.690700 =	.105381
1444		.000100 x	74.687500 =	.007469
003		.200000 x	23.479183 =	4.695837

			T.E =	
7326.1	7326.1			
029		.200000 x	.149900 =	.029980
001		.500000 x	15.951934 =	7.975967
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
003		3.000000 x	23.479183 =	70.437549
173		48.000000 x	.281700 =	13.521600

			T.E =	93.392348
7326.2	7326.2			
029		.200000 x	.149900 =	.029980
174		48.000000 x	.000000 =	.000000
003		3.000000 x	23.479183 =	70.437549
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
001		.500000 x	15.951934 =	7.975967

			T.E =	
7327	7327			
029		.200000 x	.149900 =	.029980
175		95.000000 x	.000000 =	.000000
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	23.479183 =	93.916732
001		.600000 x	15.951934 =	9.571160

			T.E =	
7328.1	7328.1			
029		.300000 x	.149900 =	.044970
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	23.479183 =	93.916732
001		.700000 x	15.951934 =	11.166354
171		108.000000 x	.000000 =	.000000

			T.E =	

7328.2

7328.2

029	.300000 x	.149900 =	.044970
172	108.000000 x	.000000 =	.000000
001	.700000 x	15.951934 =	11.166354
1449	.020000 x	52.690700 =	1.053814
1444	.007000 x	74.687500 =	.522813
003	4.000000 x	23.479183 =	93.916732

T.E =

7331

7331

029	1.500000 x	.149900 =	.224850
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
169	54.000000 x	.000000 =	.000000
003	3.500000 x	23.479183 =	82.177141
001	.500000 x	15.951934 =	7.975967

T.E =

7332

7332

029	2.000000 x	.149900 =	.299800
170	108.000000 x	.000000 =	.000000
003	4.500000 x	23.479183 =	105.656324
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
001	.800000 x	15.951934 =	12.761547

T.E =

7333

7333

029	.300000 x	.149900 =	.044970
1449	.020000 x	52.690700 =	1.053814
003	2.500000 x	23.479183 =	58.697958
002	.500000 x	17.729980 =	8.864990
167	1.050000 x	.000000 =	.000000

T.E =

7334

7334

029	.300000 x	.149900 =	.044970
168	1.050000 x	.000000 =	.000000
003	3.000000 x	23.479183 =	70.437549
1449	.020000 x	52.690700 =	1.053814
002	.600000 x	17.729980 =	10.637988

T.E =

7335	7335			
001		.450000 x	15.951934 =	7.178370
1445		.026000 x	60.956500 =	1.584869
003		1.000000 x	23.479183 =	23.479183
1444		.007000 x	74.687500 =	.522813

			T.E =	32.765235
7336	7336			
001		.400000 x	15.951934 =	6.380774
003		.900000 x	23.479183 =	21.131265
1445		.022000 x	60.956500 =	1.341043
1444		.006000 x	74.687500 =	.448125

			T.E =	29.301206
7337	7337			
001		.350000 x	15.951934 =	5.583177
003		.800000 x	23.479183 =	18.783346
1445		.017000 x	60.956500 =	1.036261
1444		.005000 x	74.687500 =	.373438

			T.E =	25.776221
7338	7338			
026		.500000 x	.097700 =	.048850
001		.300000 x	15.951934 =	4.785580
1445		.017000 x	60.956500 =	1.036261
003		.700000 x	23.479183 =	16.435428

			T.E =	22.306119
7340	7340			
289		1.100000 x	.707000 =	.777700
001		.400000 x	15.951934 =	6.380774
003		1.100000 x	23.479183 =	25.827101
1445		.026000 x	60.956500 =	1.584869
1444		.007000 x	74.687500 =	.522813

			T.E =	35.093256
7341	7341			
003		.200000 x	23.479183 =	4.695837
1441		.003000 x	26.561000 =	.079683

			T.E =	4.775520
7346	7346			
003		.200000 x	23.479183 =	4.695837

			T.E =	4.695837

7347	7347			
001		.200000 x	15.951934 =	3.190387
003		.500000 x	23.479183 =	11.739592
1445		.009000 x	60.956500 =	.548609
1444		.002000 x	74.687500 =	.149375

			T.E =	15.627962
7351	7351			
001		.200000 x	15.951934 =	3.190387
003		.600000 x	23.479183 =	14.087510
1444		.009000 x	74.687500 =	.672188

			T.E =	17.950084
7352	7352			
001		.200000 x	15.951934 =	3.190387
1444		.012000 x	74.687500 =	.896250
003		.700000 x	23.479183 =	16.435428

			T.E =	20.522065
7355	7355			
001		.150000 x	15.951934 =	2.392790
1444		.008000 x	74.687500 =	.597500
003		.600000 x	23.479183 =	14.087510

			T.E =	17.077800
7356	7356			
001		.100000 x	15.951934 =	1.595193
003		.550000 x	23.479183 =	12.913551
1444		.007000 x	74.687500 =	.522813

			T.E =	15.031557
7357	7357			
001		.050000 x	15.951934 =	.797597
003		.500000 x	23.479183 =	11.739592
1444		.006000 x	74.687500 =	.448125

			T.E =	12.985313
7359	7359			
021		.100000 x	2.670000 =	.267000
026		20.000000 x	.097700 =	1.954000
065		.040000 x	13.610000 =	.544400
003		.900000 x	23.479183 =	21.131265
002		.900000 x	17.729980 =	15.956982

			T.E =	39.853647

7360	7360			
021		.050000 x	2.670000 =	.133500
002		.700000 x	17.729980 =	12.410986
026		13.000000 x	.097700 =	1.270100
065		.027000 x	13.610000 =	.367470
003		.700000 x	23.479183 =	16.435428

			T.E =	30.617484
7361	7361			
021		.050000 x	2.670000 =	.133500
002		1.000000 x	17.729980 =	17.729980
065		.015000 x	13.610000 =	.204150
003		1.400000 x	23.479183 =	32.870856
346.1		30.000000 x	.057200 =	1.716000
026		14.000000 x	.097700 =	1.367800

			T.E =	54.022286
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	23.479183 =	32.870856
002		1.000000 x	17.729980 =	17.729980
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	54.393486
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	23.479183 =	32.870856
002		1.000000 x	17.729980 =	17.729980
348		8.000000 x	.103600 =	.828800
346.2		22.000000 x	.103600 =	2.279200
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	55.414286
7363	7363			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.097700 =	1.660900
065		.020000 x	13.610000 =	.272200
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
346.1		35.000000 x	.057200 =	2.002000

			T.E =	62.911269

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
346.1		24.000000 x	.057200 =	1.372800
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
348		11.000000 x	.103600 =	1.139600
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.097700 =	1.660900
			T.E =	63.421669
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
348		11.000000 x	.103600 =	1.139600
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.097700 =	1.660900
			T.E =	64.535269
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.097700 =	.977000
003		3.000000 x	23.479183 =	70.437549
1446		.010000 x	52.110500 =	.521105
002		2.000000 x	17.729980 =	35.459960
346.1		45.000000 x	.057200 =	2.574000
			T.E =	110.103114
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.110500 =	.521105
003		3.000000 x	23.479183 =	70.437549
002		2.000000 x	17.729980 =	35.459960
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
026		10.000000 x	.097700 =	.977000
			T.E =	110.799114
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
346.2		30.000000 x	.103600 =	3.108000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	23.479183 =	70.437549
1446		.010000 x	52.110500 =	.521105
002		2.000000 x	17.729980 =	35.459960
026		10.000000 x	.097700 =	.977000
			T.E =	112.191114

7371.1	7371.1						
026		-	14.000000 x	.097700 =	-	1.367800	
7361			1.000000 x	54.022286 =		54.022286	
029			14.000000 x	.149900 =		2.098600	

				T.E =		54.753086	
7371.2	7371.2						
026		-	14.000000 x	.097700 =	-	1.367800	
028			14.000000 x	.000000 =		.000000	
7361			1.000000 x	54.022286 =		54.022286	

				T.E =			
7372.1	7372.1						
026		-	14.000000 x	.097700 =	-	1.367800	
029			14.000000 x	.149900 =		2.098600	
7362.1			1.000000 x	54.393486 =		54.393486	

				T.E =		55.124286	
7372.2	7372.2						
026		-	14.000000 x	.097700 =	-	1.367800	
028			14.000000 x	.000000 =		.000000	
7362.1			1.000000 x	54.393486 =		54.393486	

				T.E =			
7372.3	7372.3						
026		-	14.000000 x	.097700 =	-	1.367800	
7362.2			1.000000 x	55.414286 =		55.414286	
029			14.000000 x	.149900 =		2.098600	

				T.E =		56.145086	
7372.4	7372.4						
026		-	14.000000 x	.097700 =	-	1.367800	
028			14.000000 x	.000000 =		.000000	
7362.2			1.000000 x	55.414286 =		55.414286	

				T.E =			
7373.1	7373.1						
026		-	17.000000 x	.097700 =	-	1.660900	
029			17.000000 x	.149900 =		2.548300	
7363			1.000000 x	62.911269 =		62.911269	

				T.E =		63.798669	

7373.2	7373.2				
026		-	17.000000 x	.097700 =	-
028			17.000000 x	.000000 =	1.660900
7363			1.000000 x	62.911269 =	.000000

T.E =					
7374.1	7374.1				
026		-	17.000000 x	.097700 =	-
7364.1			1.000000 x	63.421669 =	1.660900
029			17.000000 x	.149900 =	63.421669

T.E =					
7374.2	7374.2				64.309069
026		-	17.000000 x	.097700 =	-
028			17.000000 x	.000000 =	1.660900
7364.1			1.000000 x	63.421669 =	.000000

T.E =					
7374.3	7374.3				
026		-	17.000000 x	.097700 =	-
029			17.000000 x	.149900 =	1.660900
7364.2			1.000000 x	64.535269 =	2.548300

T.E =					
7374.4	7374.4				65.422669
026		-	17.000000 x	.097700 =	-
028			17.000000 x	.000000 =	1.660900
7364.2			1.000000 x	64.535269 =	.000000

T.E =					
7376.1	7376.1				
026		-	10.000000 x	.097700 =	-
7366			1.000000 x	110.103114 =	.977000
029			10.000000 x	.149900 =	110.103114

T.E =					
7376.2	7376.2				110.625114
026		-	10.000000 x	.097700 =	-
028			10.000000 x	.000000 =	.977000
7366			1.000000 x	110.103114 =	.000000

T.E =					

7377.1	7377.1				
026		-	10.000000 x	.097700 =	- .977000
7367.1			1.000000 x	110.799114 =	110.799114
029			10.000000 x	.149900 =	1.499000

				T.E =	111.321114
7377.2	7377.2				
026		-	10.000000 x	.097700 =	- .977000
028			10.000000 x	.000000 =	.000000
7367.1			1.000000 x	110.799114 =	110.799114

				T.E =	
7377.3	7377.3				
026		-	10.000000 x	.097700 =	- .977000
029			10.000000 x	.149900 =	1.499000
7367.2			1.000000 x	112.191114 =	112.191114

				T.E =	112.713114
7377.4	7377.4				
026		-	10.000000 x	.097700 =	- .977000
7367.2			1.000000 x	112.191114 =	112.191114
028			10.000000 x	.000000 =	.000000

				T.E =	
7381	7381				
456			.100000 x	1.610000 =	.161000

				T.E =	.161000
7382	7382				
443			.150000 x	1.930000 =	.289500
447			.050000 x	4.393700 =	.219685
003			.300000 x	23.479183 =	7.043755

				T.E =	7.552940
7383	7383				
002			.250000 x	17.729980 =	4.432495
003			.150000 x	23.479183 =	3.521877

				T.E =	7.954372
7384	7384				
003			.500000 x	23.479183 =	11.739592

				T.E =	11.739592

7385	7385			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592
7386	7386			
003		.600000 x	23.479183 =	14.087510

			T.E =	14.087510
7387	7387			
261		1.500000 x	.523400 =	.785100
003		1.000000 x	23.479183 =	23.479183
7361		1.100000 x	54.022286 =	59.424515

			T.E =	83.688798
7388	7388			
003		2.500000 x	23.479183 =	58.697958
7361		.600000 x	54.022286 =	32.413372

			T.E =	91.111329
7389.1.1	7389.1.1			
7371.1		.300000 x	54.753086 =	16.425926

			T.E =	16.425926
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	65.422669 =	19.626801

			T.E =	19.626801
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	55.124286 =	16.537286

			T.E =	16.537286
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	56.145086 =	16.843526

			T.E =	16.843526
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	63.798669 =	19.139601

			T.E =	19.139601
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	64.309069 =	19.292721

			T.E =	19.292721
7389.2.1	7389.2.1			
7371.1		.500000 x	54.753086 =	27.376543

			T.E =	27.376543
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	65.422669 =	32.711335

			T.E =	32.711335

ΑΤΟΕ	2ο Τρίμηνο του 2009		Σελ. Ημ/νία	160 26/05/2010
7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	55.124286 =	27.562143

			T.E =	27.562143
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	56.145086 =	28.072543

			T.E =	28.072543
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	63.798669 =	31.899335

			T.E =	31.899335
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	64.309069 =	32.154535

			T.E =	32.154535
7391	7391			
003		.250000 x	23.479183 =	5.869796

			T.E =	5.869796

7392	7392			
298.1		1.081080 x	4.210000 =	4.551347
003		.400000 x	23.479183 =	9.391673

			T.E =	13.943020
7393	7393			
294		.347760 x	3.099000 =	1.077708
003		.300000 x	23.479183 =	7.043755

			T.E =	8.121463
7394	7394			
297.2		1.423800 x	.000000 =	.000000
003		.400000 x	23.479183 =	9.391673

			T.E =	
7395	7395			
522		1.100000 x	.000000 =	.000000
003		.300000 x	23.479183 =	7.043755

			T.E =	
7396	7396			
523		1.200000 x	7.500000 =	9.000000
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	23.423207
7397	7397			
524		1.150000 x	7.500000 =	8.625000
003		.700000 x	23.479183 =	16.435428

			T.E =	25.060428
7398	7398			
525		1.070000 x	7.840000 =	8.388800
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	24.872465
7399	7399			
526		1.100000 x	1.400000 =	1.540000
003		.250000 x	23.479183 =	5.869796

			T.E =	7.409796

7416	7416			
003		.800000 x	23.479183 =	18.783346

			T.E =	18.783346
7417	7417			
003		1.800000 x	23.479183 =	42.262529

			T.E =	42.262529
7418	7418			
003		2.600000 x	23.479183 =	61.045876

			T.E =	61.045876
7419	7419			
003		.800000 x	23.479183 =	18.783346

			T.E =	18.783346
7420	7420			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
7421	7421			
003		.800000 x	23.479183 =	18.783346

			T.E =	18.783346
7422	7422			
003		.350000 x	23.479183 =	8.217714

			T.E =	8.217714
7431	7431			
332		1.150000 x	88.540000 =	101.821000
003		4.000000 x	23.479183 =	93.916732
1444		.001000 x	74.687500 =	.074688
1445		.020000 x	60.956500 =	1.219130

			T.E =	197.031550
7432	7432			
331		1.150000 x	85.390000 =	98.198500
1444		.001000 x	74.687500 =	.074688
1445		.020000 x	60.956500 =	1.219130
003		4.400000 x	23.479183 =	103.308405

			T.E =	202.800723

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	60.956500 =	1.219130	
003		5.100000 x	23.479183 =	119.743833	
1444		.001000 x	74.687500 =	.074688	

			T.E =	219.236151	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.100000 x	23.479183 =	143.223016	

			T.E =	242.715334	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
003		4.200000 x	23.479183 =	98.612569	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	206.643886	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
003		4.600000 x	23.479183 =	108.004242	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	216.035559	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.300000 x	23.479183 =	124.439670	

			T.E =	232.470987	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.300000 x	23.479183 =	147.918853	

			T.E =	255.950170	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	23.479183 =	105.656324	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	249.515641	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
003		4.900000 x	23.479183 =	115.047997	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	258.907314	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.600000 x	23.479183 =	131.483425	

			T.E =	275.342742	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.600000 x	23.479183 =	154.962608	

			T.E =	298.821925	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	23.479183 =	115.047997	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	271.304314	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
003		5.300000 x	23.479183 =	124.439670	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	280.695987	

7463	7463			
333		1.250000 x	123.970000 =	154.962500
1445		.020000 x	60.956500 =	1.219130
1444		.001000 x	74.687500 =	.074688
003		6.000000 x	23.479183 =	140.875098

			T.E =	297.131416
7464	7464			
333		1.250000 x	123.970000 =	154.962500
1445		.020000 x	60.956500 =	1.219130
1444		.001000 x	74.687500 =	.074688
003		7.000000 x	23.479183 =	164.354281

			T.E =	320.610599
7491	7491			
331		.115000 x	85.390000 =	9.819850
1445		.002000 x	60.956500 =	.121913
1444		.000100 x	74.687500 =	.007469
003		.915000 x	23.479183 =	21.483452

			T.E =	31.432684
7492	7492			
331		.125000 x	85.390000 =	10.673750
003		.945000 x	23.479183 =	22.187828
1444		.000100 x	74.687500 =	.007469
1445		.002000 x	60.956500 =	.121913

			T.E =	32.990960
7493	7493			
333		.115000 x	123.970000 =	14.256550
1445		.002000 x	60.956500 =	.121913
1444		.000100 x	74.687500 =	.007469
003		.990000 x	23.479183 =	23.244391

			T.E =	37.630323
7494	7494			
333		.125000 x	123.970000 =	15.496250
1445		.002000 x	60.956500 =	.121913
1444		.000100 x	74.687500 =	.007469
003		1.050000 x	23.479183 =	24.653142

			T.E =	40.278774

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734
003		.488000 x	23.479183 =	11.457841

			T.E =	16.432457
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734
003		.504000 x	23.479183 =	11.833508

			T.E =	17.235074
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	23.479183 =	12.397009
1444		.000050 x	74.687500 =	.003734
1445		.001000 x	60.956500 =	.060957

			T.E =	19.589974
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	23.479183 =	13.148342
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734

			T.E =	20.961158
7501	7501			
7433		1.000000 x	219.236151 =	219.236151

			T.E =	219.236151
7503	7503			
7443		1.000000 x	232.470987 =	232.470987

			T.E =	232.470987
7506	7506			
7453		1.000000 x	275.342742 =	275.342742

			T.E =	275.342742
7508	7508			
7463		1.000000 x	297.131416 =	297.131416

			T.E =	297.131416

7511	7511			
331		.115000 x	85.390000 =	9.819850
003		.915000 x	23.479183 =	21.483452
1445		.002000 x	60.956500 =	.121913
1444		.000100 x	74.687500 =	.007469

			T.E =	31.432684
7513	7513			
331		.125000 x	85.390000 =	10.673750
1445		.002000 x	60.956500 =	.121913
1444		.000100 x	74.687500 =	.007469
003		.945000 x	23.479183 =	22.187828

			T.E =	32.990960
7521	7521			
331		1.150000 x	85.390000 =	98.198500
003		5.700000 x	23.479183 =	133.831343
1445		.020000 x	60.956500 =	1.219130

			T.E =	233.248973
7523	7523			
331		1.150000 x	85.390000 =	98.198500
003		4.800000 x	23.479183 =	112.700078
1445		.020000 x	60.956500 =	1.219130

			T.E =	212.117708
7524	7524			
331		1.250000 x	85.390000 =	106.737500
003		6.100000 x	23.479183 =	143.223016
1445		.020000 x	60.956500 =	1.219130

			T.E =	251.179646
7526	7526			
331		1.250000 x	85.390000 =	106.737500
1445		.020000 x	60.956500 =	1.219130
003		5.000000 x	23.479183 =	117.395915

			T.E =	225.352545
7531	7531			
332		1.150000 x	88.540000 =	101.821000
1445		.020000 x	60.956500 =	1.219130
003		5.200000 x	23.479183 =	122.091752

			T.E =	225.131882

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	60.956500 =	1.219130	
003		5.400000 x	23.479183 =	126.787588	

			T.E =	238.681718	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	23.479183 =	133.831343	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	287.804973	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	23.479183 =	143.223016	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	310.479646	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
1445		.010000 x	60.956500 =	.609565	
003		3.000000 x	23.479183 =	70.437549	

			T.E =	110.896114	
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	23.479183 =	93.916732	
1445		.010000 x	60.956500 =	.609565	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
1445		.010000 x	60.956500 =	.609565	
003		3.700000 x	23.479183 =	86.872977	

			T.E =	149.024842	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
1445		.010000 x	60.956500 =	.609565	
003		4.200000 x	23.479183 =	98.612569	
336		.350000 x	.000000 =	.000000	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
003		4.800000 x	23.479183 =	112.700078
1445		.010000 x	60.956500 =	.609565
338		.350000 x	.000000 =	.000000

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	292.866911
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	311.048411
7554	7554			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	339.825277
7556	7556			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	358.006777

7558	7558				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	60.956500 =	.182870	
003		1.500000 x	23.479183 =	35.218775	

			T.E =	42.232844	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	23.479183 =	35.218775	
1445		.003000 x	60.956500 =	.182870	

			T.E =	42.232844	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	23.479183 =	122.091752	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	225.131882	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
1445		.020000 x	60.956500 =	1.219130	
003		5.700000 x	23.479183 =	133.831343	

			T.E =	287.804973	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	60.956500 =	1.219130	
003		5.400000 x	23.479183 =	126.787588	

			T.E =	238.681718	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	23.479183 =	143.223016	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	310.479646	
7565	7565				
003		1.500000 x	23.479183 =	35.218775	

			T.E =	35.218775	
7566	7566				
7561		1.500000 x	225.131882 =	337.697823	

			T.E =	337.697823	

7567	7567			
7562		1.500000 x	287.804973 =	431.707460

			T.E =	431.707460
7568	7568			
7563		1.500000 x	238.681718 =	358.022577

			T.E =	358.022577
7569	7569			
7564		1.500000 x	310.479646 =	465.719469

			T.E =	465.719469
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	23.479183 =	70.437549

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	23.479183 =	70.437549
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	23.479183 =	70.437549

			T.E =	272.987049
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	23.479183 =	93.916732
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	23.479183 =	89.220895

			T.E =	187.419395

7577	7577			
334		1.150000 x	132.830000 =	152.754500
003		4.200000 x	23.479183 =	98.612569

			T.E =	251.367069
7578	7578			
336		1.150000 x	.000000 =	.000000
003		4.700000 x	23.479183 =	110.352160

			T.E =	
7581	7581			
326		1.050000 x	63.530000 =	66.706500
3211		.020000 x	139.248411 =	2.784968
1445		.005000 x	60.956500 =	.304783
003		2.300000 x	23.479183 =	54.002121

			T.E =	123.798372
7601	7601			
401		1.100000 x	13.560000 =	14.916000
457		.500000 x	.803800 =	.401900
003		.500000 x	23.479183 =	11.739592

			T.E =	27.057492
7602	7602			
403		1.100000 x	15.880000 =	17.468000
457		.500000 x	.803800 =	.401900
003		.550000 x	23.479183 =	12.913551

			T.E =	30.783451
7603	7603			
406		1.100000 x	19.630000 =	21.593000
457		.500000 x	.803800 =	.401900
003		.650000 x	23.479183 =	15.261469

			T.E =	37.256369
7604.1	7604.1			
409		1.100000 x	23.370000 =	25.707000
003		.750000 x	23.479183 =	17.609387
457		.500000 x	.803800 =	.401900

			T.E =	43.718287

7604.2	7604.2			
410		1.100000 x	31.790000 =	34.969000
003		.750000 x	23.479183 =	17.609387
457		.500000 x	.803800 =	.401900

			T.E =	52.980287
7606	7606			
401		1.100000 x	13.560000 =	14.916000
003		.600000 x	23.479183 =	14.087510

			T.E =	29.003510
7607	7607			
403		1.100000 x	15.880000 =	17.468000
003		.650000 x	23.479183 =	15.261469

			T.E =	32.729469
7608	7608			
406		1.100000 x	19.630000 =	21.593000
003		.750000 x	23.479183 =	17.609387

			T.E =	39.202387
7609.1	7609.1			
409		1.100000 x	23.370000 =	25.707000
003		.850000 x	23.479183 =	19.957306

			T.E =	45.664306
7609.2	7609.2			
410		1.100000 x	31.790000 =	34.969000
003		.850000 x	23.479183 =	19.957306

			T.E =	54.926306
7611	7611			
411		1.100000 x	29.680000 =	32.648000
457		.500000 x	.803800 =	.401900
003		.500000 x	23.479183 =	11.739592

			T.E =	44.789492
7612	7612			
412		1.100000 x	32.030000 =	35.233000
003		.550000 x	23.479183 =	12.913551
457		.500000 x	.803800 =	.401900

			T.E =	48.548451

7613	7613			
411		1.100000 x	29.680000 =	32.648000
003		.600000 x	23.479183 =	14.087510

			T.E =	46.735510
7614	7614			
412		1.100000 x	32.030000 =	35.233000
003		.650000 x	23.479183 =	15.261469

			T.E =	50.494469
7616	7616			
414		1.100000 x	23.370000 =	25.707000
457		.500000 x	.803800 =	.401900
003		.600000 x	23.479183 =	14.087510

			T.E =	40.196410
7617	7617			
415		1.100000 x	23.370000 =	25.707000
457		.500000 x	.803800 =	.401900
003		.650000 x	23.479183 =	15.261469

			T.E =	41.370369
7618	7618			
414		1.100000 x	23.370000 =	25.707000
003		.700000 x	23.479183 =	16.435428

			T.E =	42.142428
7619	7619			
415		1.100000 x	23.370000 =	25.707000
003		.750000 x	23.479183 =	17.609387

			T.E =	43.316387
7621	7621			
418		1.100000 x	32.720000 =	35.992000
457		.800000 x	.803800 =	.643040
003		1.200000 x	23.479183 =	28.175020

			T.E =	64.810060
7622	7622			
419		1.100000 x	32.720000 =	35.992000
003		1.400000 x	23.479183 =	32.870856
457		.800000 x	.803800 =	.643040

			T.E =	69.505896

7626.1	7626.1			
298.2		18.000000 x	3.620000 =	65.160000
421		1.000000 x	108.710000 =	108.710000
002		7.000000 x	17.729980 =	124.109860
003		7.000000 x	23.479183 =	164.354281

			T.E =	462.334141
7626.2	7626.2			
298.2		18.000000 x	3.620000 =	65.160000
422		1.000000 x	149.410000 =	149.410000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860

			T.E =	503.034141
7627.1	7627.1			
298.2		16.000000 x	3.620000 =	57.920000
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880
421		1.000000 x	108.710000 =	108.710000

			T.E =	413.884978
7627.2	7627.2			
298.2		16.000000 x	3.620000 =	57.920000
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880
422		1.000000 x	149.410000 =	149.410000

			T.E =	454.584978
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	23.479183 =	1.173959

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	23.479183 =	1.408751

			T.E =	6.237751
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	23.479183 =	1.878335

			T.E =	7.807335

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	23.479183 =	2.347918

			T.E =	10.575918
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	23.479183 =	1.408751

			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	23.479183 =	1.408751

			T.E =	
7701	7701			
024		.001500 x	50.000000 =	.075000
002		.050000 x	17.729980 =	.886499
003		.120000 x	23.479183 =	2.817502

			T.E =	3.779001
7702	7702			
024		.001800 x	50.000000 =	.090000
003		.080000 x	23.479183 =	1.878335
002		.050000 x	17.729980 =	.886499

			T.E =	2.854834
7706	7706			
024		.002000 x	50.000000 =	.100000
003		.150000 x	23.479183 =	3.521877
002		.080000 x	17.729980 =	1.418398

			T.E =	5.040276
7707	7707			
024		.002300 x	50.000000 =	.115000
003		.090000 x	23.479183 =	2.113126
002		.100000 x	17.729980 =	1.772998

			T.E =	4.001124

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	23.479183 =	4.226253
002		.120000 x	17.729980 =	2.127598

			T.E =	6.478851
7709	7709			
024		.002800 x	50.000000 =	.140000
003		.120000 x	23.479183 =	2.817502
002		.150000 x	17.729980 =	2.659497

			T.E =	5.616999
7711	7711			
002		.050000 x	17.729980 =	.886499
1485		.200000 x	.831209 =	.166242
003		.200000 x	23.479183 =	4.695837

			T.E =	5.748577
7712	7712			
002		.080000 x	17.729980 =	1.418398
1485		.250000 x	.831209 =	.207802
003		.250000 x	23.479183 =	5.869796

			T.E =	7.495996
7713	7713			
002		.160000 x	17.729980 =	2.836797
003		.300000 x	23.479183 =	7.043755
1485		.280000 x	.831209 =	.232739

			T.E =	10.113290
7720	7720			
443		.080000 x	1.930000 =	.154400
003		.300000 x	23.479183 =	7.043755
002		.100000 x	17.729980 =	1.772998
1485		.200000 x	.831209 =	.166242

			T.E =	9.137395
7721	7721			
002		.070000 x	17.729980 =	1.241099
003		.200000 x	23.479183 =	4.695837
1485		.200000 x	.831209 =	.166242

			T.E =	6.103177

7722.1.1	7722.1.1			
7720		.300000 x	9.137395 =	2.741219

			T.E =	2.741219
7722.1.2	7722.1.2			
7721		.300000 x	6.103177 =	1.830953

			T.E =	1.830953
7722.2.1	7722.2.1			
7720		.400000 x	9.137395 =	3.654958

			T.E =	3.654958
7722.2.2	7722.2.2			
7721		.400000 x	6.103177 =	2.441271

			T.E =	2.441271
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	23.479183 =	5.869796
002		.150000 x	17.729980 =	2.659497

			T.E =	9.759293
7735	7735			
441		.350000 x	.075500 =	.026425
444		.150000 x	2.143200 =	.321480
003		.150000 x	23.479183 =	3.521877

			T.E =	3.869782
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535
003		.250000 x	23.479183 =	5.869796
446		.005000 x	2.540000 =	.012700

			T.E =	6.117953
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.869600 =	.173920
003		.300000 x	23.479183 =	7.043755
1488		.600000 x	.761115 =	.456669

			T.E =	7.689444

7738	7738			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.869600 =	.173920
1488		.300000 x	.761115 =	.228335
003		.300000 x	23.479183 =	7.043755

			T.E =	7.461109
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	23.479183 =	3.521877

			T.E =	3.867427
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	23.479183 =	5.869796
1492		.250000 x	2.756980 =	.689245

			T.E =	6.588616
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	23.479183 =	5.869796

			T.E =	6.588616
7742	7742			
442		.250000 x	.118300 =	.029575
003		.200000 x	23.479183 =	4.695837
463		.125000 x	3.970000 =	.496250

			T.E =	5.221662
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	23.479183 =	3.521877
464		.125000 x	3.720000 =	.465000

			T.E =	4.016452
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	23.479183 =	3.521877
465		.125000 x	5.870000 =	.733750

			T.E =	4.285202

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
003		.800000 x	23.479183 =	18.783346
1489		.200000 x	.869600 =	.173920

			T.E =	19.676086
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	23.479183 =	3.521877
443		.090000 x	1.930000 =	.173700

			T.E =	3.722002
7747	7747			
441		.350000 x	.075500 =	.026425
443		.170000 x	1.930000 =	.328100
003		.250000 x	23.479183 =	5.869796

			T.E =	6.224321
7748	7748			
443		.090000 x	1.930000 =	.173700
002		.100000 x	17.729980 =	1.772998
445		.030000 x	1.553500 =	.046605
003		.200000 x	23.479183 =	4.695837
450		.060000 x	2.760000 =	.165600

			T.E =	6.854740
7749	7749			
443		.160000 x	1.930000 =	.308800
445		.050000 x	1.553500 =	.077675
003		.250000 x	23.479183 =	5.869796
002		.150000 x	17.729980 =	2.659497
450		.100000 x	2.760000 =	.276000

			T.E =	9.191768
7751	7751			
003		.150000 x	23.479183 =	3.521877
1491		.125000 x	1.488894 =	.186112

			T.E =	3.707989
7752	7752			
003		.250000 x	23.479183 =	5.869796
1491		.250000 x	1.488894 =	.372224

			T.E =	6.242019

7753	7753			
441		1.000000 x	.075500 =	.075500
003		.650000 x	23.479183 =	15.261469
443		.080000 x	1.930000 =	.154400
1491		.200000 x	1.488894 =	.297779
1490		.090000 x	1.546426 =	.139178

			T.E =	15.928326
7754	7754			
441		.800000 x	.075500 =	.060400
1487		.090000 x	.605006 =	.054451
003		.800000 x	23.479183 =	18.783346
1490		.090000 x	1.546426 =	.139178
1491		.200000 x	1.488894 =	.297779

			T.E =	19.335154
7755	7755			
442		.250000 x	.118300 =	.029575
003		1.000000 x	23.479183 =	23.479183
1491		.200000 x	1.488894 =	.297779
1492		.160000 x	2.756980 =	.441117

			T.E =	24.247654
7756	7756			
442		.300000 x	.118300 =	.035490
003		.350000 x	23.479183 =	8.217714
1492		.300000 x	2.756980 =	.827094

			T.E =	9.080298
7761	7761			
441		.650000 x	.075500 =	.049075
1489		.200000 x	.869600 =	.173920
1488		.600000 x	.761115 =	.456669
003		.800000 x	23.479183 =	18.783346
467		.100000 x	3.380000 =	.338000
473		.100000 x	2.750000 =	.275000

			T.E =	20.076010
7762	7762			
473		.100000 x	2.750000 =	.275000
003		.200000 x	23.479183 =	4.695837

			T.E =	4.970837

7764	7764			
474		.125000 x	3.770000 =	.471250
003		.100000 x	23.479183 =	2.347918

			T.E =	2.819168
7765	7765			
475		.125000 x	6.230000 =	.778750
003		.200000 x	23.479183 =	4.695837

			T.E =	5.474587
7766	7766			
442		.275000 x	.118300 =	.032533
473		.110000 x	2.750000 =	.302500
1492		.275000 x	2.756980 =	.758170
003		.880000 x	23.479183 =	20.661681

			T.E =	21.754883
7767.1	7767.1			
7755		.150000 x	24.247654 =	3.637148

			T.E =	3.637148
7767.2	7767.2			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183
473		.200000 x	2.750000 =	.550000

			AΘΡΟΙΣΜΑ =	24.499875
	T.E =	.150000 x	24.499875 =	3.674981

7767.3	7767.3			
7755		.250000 x	24.247654 =	6.061914

			T.E =	6.061914
7767.4	7767.4			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183

			AΘΡΟΙΣΜΑ =	24.499875
	T.E =	.250000 x	24.499875 =	6.124969

7767.5	7767.5			
7755		.350000 x	24.247654 =	8.486679

			T.E =	8.486679
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183

			ΑΘΡΟΙΣΜΑ =	24.499875
	T.E =	.350000 x	24.499875 =	8.574956

7767.7	7767.7			
7755		.450000 x	24.247654 =	10.911444

			T.E =	10.911444
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183
473		.200000 x	2.750000 =	.550000

			ΑΘΡΟΙΣΜΑ =	24.499875
	T.E =	.450000 x	24.499875 =	11.024944

7768	7768			
460		.200000 x	4.250000 =	.850000
003		.450000 x	23.479183 =	10.565632
460		.030000 x	4.250000 =	.127500
002		.450000 x	17.729980 =	7.978491

			T.E =	19.521623
7769	7769			
460		.200000 x	4.250000 =	.850000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
460		.030000 x	4.250000 =	.127500

			T.E =	9.219333
7770	7770			
460		.090000 x	4.250000 =	.382500
003		.150000 x	23.479183 =	3.521877
002		.150000 x	17.729980 =	2.659497
460		.020000 x	4.250000 =	.085000

			T.E =	6.648874

7771	7771			
441		1.000000 x	.075500 =	.075500
1488		.160000 x	.761115 =	.121778
1487		.080000 x	.605006 =	.048400
003		1.300000 x	23.479183 =	30.522938
473		.100000 x	2.750000 =	.275000
467		.110000 x	3.380000 =	.371800

			T.E =	31.415417
7772	7772			
441		1.000000 x	.075500 =	.075500
458		.100000 x	5.030000 =	.503000
443		.100000 x	1.930000 =	.193000
003		.500000 x	23.479183 =	11.739592

			T.E =	12.511092
7773	7773			
441		1.000000 x	.075500 =	.075500
459		.100000 x	5.030000 =	.503000
443		.100000 x	1.930000 =	.193000
003		.600000 x	23.479183 =	14.087510

			T.E =	14.859010
7774	7774			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183

			T.E =	24.499875
7785.1	7785.1			
441		.350000 x	.075500 =	.026425
003		.700000 x	23.479183 =	16.435428
477		.160000 x	.000000 =	.000000
476		.120000 x	2.366400 =	.283968

			T.E =	
7785.2	7785.2			
441		.350000 x	.075500 =	.026425
476		.120000 x	2.366400 =	.283968
478		.160000 x	2.937600 =	.470016
003		.700000 x	23.479183 =	16.435428

			T.E =	17.215837

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.869600 =	.173920
003		1.000000 x	23.479183 =	23.479183
1488		.600000 x	.761115 =	.456669
477		.110000 x	.000000 =	.000000

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.869600 =	.173920
1488		.600000 x	.761115 =	.456669
003		1.000000 x	23.479183 =	23.479183
478		.110000 x	2.937600 =	.323136

			T.E =	24.459333
7787	7787			
441		1.000000 x	.075500 =	.075500
476		.090000 x	2.366400 =	.212976
1488		.160000 x	.761115 =	.121778
1487		.080000 x	.605006 =	.048400
003		1.000000 x	23.479183 =	23.479183
477		.160000 x	.000000 =	.000000

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
479		1.000000 x	1.815600 =	1.815600
003		.700000 x	23.479183 =	16.435428

			T.E =	18.269903
7791	7791			
441		1.000000 x	.075500 =	.075500
1487		.050000 x	.605006 =	.030250
1491		.200000 x	1.488894 =	.297779
003		.500000 x	23.479183 =	11.739592

			T.E =	12.143121
7792	7792			
482		.150000 x	.829400 =	.124410
003		.500000 x	23.479183 =	11.739592

			T.E =	11.864002

7793	7793			
480		.500000 x	3.366000 =	1.683000
003		.200000 x	23.479183 =	4.695837

			T.E =	6.378837
7794	7794			
482		.150000 x	.829400 =	.124410
003		.500000 x	23.479183 =	11.739592

			T.E =	11.864002
7797	7797			
201		.000500 x	290.000000 =	.145000
002		.060000 x	17.729980 =	1.063799

			T.E =	1.208799
7798	7798			
201		.000600 x	290.000000 =	.174000
002		.070000 x	17.729980 =	1.241099

			T.E =	1.415099
7801	7801			
496		1.200000 x	1.006100 =	1.207320
003		.150000 x	23.479183 =	3.521877

			T.E =	4.729197
7806	7806			
498		1.150000 x	1.124000 =	1.292600
003		.300000 x	23.479183 =	7.043755

			T.E =	8.336355
7807	7807			
499		1.150000 x	1.540900 =	1.772035
003		.400000 x	23.479183 =	9.391673

			T.E =	11.163708
7808	7808			
500		1.150000 x	2.266200 =	2.606130
003		.600000 x	23.479183 =	14.087510

			T.E =	16.693640

7809	7809			
501		1.200000 x	3.070000 =	3.684000
003		.800000 x	23.479183 =	18.783346

			T.E =	22.467346
7810	7810			
502		1.200000 x	4.230000 =	5.076000
003		.900000 x	23.479183 =	21.131265

			T.E =	26.207265
7811	7811			
503		1.200000 x	1.006100 =	1.207320
003		.800000 x	23.479183 =	18.783346

			T.E =	19.990666
7812	7812			
504		1.300000 x	1.332400 =	1.732120
003		.900000 x	23.479183 =	21.131265

			T.E =	22.863385
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	23.479183 =	14.087510

			T.E =	33.257510
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	23.479183 =	4.695837

			T.E =	5.484237
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	23.479183 =	23.479183

			T.E =	28.855183
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	23.479183 =	14.087510

			T.E =	21.343010

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	23.479183 =	11.739592

			T.E =	17.493592
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.149500 =	1.264450
002		.300000 x	17.729980 =	5.318994
003		.150000 x	23.479183 =	3.521877

			T.E =	10.981321
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	23.479183 =	3.521877
002		.350000 x	17.729980 =	6.205493

			T.E =	12.671370
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	23.479183 =	3.521877
002		.400000 x	17.729980 =	7.091992

			T.E =	12.435869
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	23.479183 =	1.878335

			T.E =	2.329335
7915.1	7915.1			
7911		.850000 x	10.981321 =	9.334123

			T.E =	9.334123
7915.2	7915.2			
7912		.850000 x	12.671370 =	10.770665

			T.E =	10.770665
7915.3	7915.3			
7913		.850000 x	12.435869 =	10.570489

			T.E =	10.570489

7921	7921				
529		1.030000 x	1.400000 =	1.442000	
002		.040000 x	17.729980 =	.709199	

			T.E =	2.151199	
7922	7922				
530		1.030000 x	2.190000 =	2.255700	
002		.050000 x	17.729980 =	.886499	

			T.E =	3.142199	
7923	7923				
531		1.030000 x	1.180000 =	1.215400	
002		.050000 x	17.729980 =	.886499	

			T.E =	2.101899	
7931	7931				
519		1.050000 x	52.970000 =	55.618500	
003		1.500000 x	23.479183 =	35.218775	

			T.E =	90.837275	
7932.1	7932.1				
514		.000000 x	48.900000 =	.000000	
003		.000000 x	23.479183 =	.000000	

			T.E =	.000000	
7932.2	7932.2				
520		.000000 x	47.060000 =	.000000	
003		.000000 x	23.479183 =	.000000	

			T.E =	.000000	
7933.1	7933.1				
514		.000000 x	48.900000 =	.000000	
003		.000000 x	23.479183 =	.000000	

			T.E =	.000000	
7933.2	7933.2				
520		.000000 x	47.060000 =	.000000	
003		.000000 x	23.479183 =	.000000	

			T.E =	.000000	

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	27.504582
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	23.479183 =	5.869796

			T.E =	6.244796
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	23.479183 =	2.347918

			T.E =	3.097918
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.729980 =	5.318994
003		.300000 x	23.479183 =	7.043755
251		.100000 x	.650000 =	.065000

			T.E =	13.430749
7941	7941			
067		.040000 x	45.000000 =	1.800000
001		.100000 x	15.951934 =	1.595193

			T.E =	3.395193
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.951934 =	1.595193

			T.E =	9.145193