

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

3ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
008	16.777917
009	.074800
011	53.630000
012	4.400000
013	26.580000
014	260.720000
015	200.790000
016	31.630000
017	369.270000
018.1	2.900000
018.2	4.400000
019.1	2.900000
019.2	4.400000
021	2.670000
022	.070000
024	50.000000
026	.099900
027	.119300
029	.152800
032	36.000000
035	.091000
036	.093500
040	.203400
051	15.400000
052	15.400000
053	.085000
054	.085000
055	.090000
056	10.580000
057	10.580000
058	9.090000
061	13.560000
062	13.560000
065	13.610000
066	35.000000
067	45.500000
081	11.010000
101	
102	
111	.077500
112	.085000
113	.570000
114	
116	.088500
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.650000
132	.930000
142	.350000

146	.380000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.255300
181	
201	290.000000
203.2	370.000000
203.4	290.000000
205	450.000000
208	1,450.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,500.000000
223.4	1,580.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	2.000000
237	1.100000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.600000
246	12.000000
249	20.000000
251	.775000
252	1.900000
253	2.400000
254	3.058000
258	7.856500
259	25.500000
260	.583300
261	.639200
262	.583300
264	1.133900
265	.835300
266	.643000

267	.903400
268	1.033700
271	1.003300
272	.901300
273	1.162000
274	1.433200
276	.812400
277	1.016500
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.970800
283	1.093500
284	
285	.062000
286	1.696200
288	1.841000
289	.769200
290	3.300000
291	5.000000
293	
294	3.518600
295	6.185800
296	12.370900
297.2	
298.1	5.470000
298.2	4.700000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600

372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.090000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000

481	5.467500
482	1.300000
483	.165000
484	3.930000
485	1.047200
487	13.480000
488	5.000000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.905500
498	1.011600
499	1.386800
500	2.039600
501	2.763000
502	3.807000
503	.905500
504	1.199100
505	19.170000
506	1.290700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	38.800000
515	41.230000
519	47.670000
520	37.340000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.450000
565.5	5.150000
565.6	7.100000
566.3	4.600000
566.5	7.050000
566.6	9.400000

1101	1101				
001		.500000 x	15.741598 =		7.870799

			B.T =		7.870799
1102	1102				
001		1.000000 x	15.741598 =		15.741598

			B.T =		15.741598
1103	1103				
001		.300000 x	15.741598 =		4.722479

			B.T =		4.722479
1104	1104				
015		1.000000 x	200.790000 =		200.790000
291		2.200000 x	5.000000 =		11.000000
004		7.000000 x	23.886192 =		167.203344
002		7.000000 x	17.312112 =		121.184784
484		5.250000 x	3.930000 =		20.632500
485		83.000000 x	1.047200 =		86.917600

			AΘΡΟΙΣΜΑ =		607.728228
	B.T =	.004000 x	607.728228 =		2.430913

1111	1111				
006		.060000 x	183.150721 =		10.989043

			B.T =		10.989043
1112	1112				
006		.090000 x	183.150721 =		16.483565

			B.T =		16.483565
1116	1116				
007		.025000 x	183.150721 =		4.578768

			B.T =		4.578768
1117	1117				
007		.110000 x	183.150721 =		20.146579

			B.T =		20.146579
1121	1121				
009		4.000000 x	.074800 =		.299200

			B.T =		.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639

			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408

			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617

			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565

			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000

			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600

			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800

			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100

			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.099900 =	14.985000

			B.T =	39.704250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000

			B.T =	40.284450

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000
026		150.000000 x	.099900 =	14.985000

			B.T =	41.616750
1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	15.400000 =	8.316000
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000

			B.T =	
1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.091000 =	6.825000
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

			B.T =	
1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

			B.T =	152.456250
1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.099900 =	14.985000

			B.T =	163.304700
1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	15.400000 =	3.080000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

			B.T =	126.656000

1429	1429			
021		.200000 x	2.670000 =	.534000
035		200.000000 x	.091000 =	18.200000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

			B.T =	141.776000
1431	1431			
021		.300000 x	2.670000 =	.801000
032		.960000 x	36.000000 =	34.560000
1407		.320000 x	37.605000 =	12.033600

			B.T =	47.394600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	15.400000 =	9.856000
032		.320000 x	36.000000 =	11.520000

			B.T =	34.210600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.091000 =	100.100000

			B.T =	101.034500
1437	1437			
021		.200000 x	2.670000 =	.534000
035		75.000000 x	.091000 =	6.825000
051		.380000 x	15.400000 =	5.852000
1407		.620000 x	37.605000 =	23.315100

			B.T =	36.526100
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.099900 =	24.975000

			B.T =	27.111000
1442	1442			
021		.250000 x	2.670000 =	.667500
051		.740000 x	15.400000 =	11.396000
026		900.000000 x	.099900 =	89.910000

			B.T =	101.973500

1443	1443				
021		.250000 x	2.670000 =	.667500	
026		700.000000 x	.099900 =	69.930000	
051		.860000 x	15.400000 =	13.244000	

			B.T =	83.841500	
1444	1444				
021		.250000 x	2.670000 =	.667500	
026		600.000000 x	.099900 =	59.940000	
051		1.000000 x	15.400000 =	15.400000	

			B.T =	76.007500	
1445	1445				
021		.250000 x	2.670000 =	.667500	
051		1.060000 x	15.400000 =	16.324000	
026		450.000000 x	.099900 =	44.955000	

			B.T =	61.946500	
1446	1446				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
051		1.120000 x	15.400000 =	17.248000	

			B.T =	52.880500	
1447	1447				
021		.250000 x	2.670000 =	.667500	
026		400.000000 x	.099900 =	39.960000	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	

			B.T =	59.035900	
1448	1448				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
039		5.000000 x	.000000 =	.000000	
026		400.000000 x	.099900 =	39.960000	

			B.T =		
1449	1449				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
051		1.060000 x	15.400000 =	16.324000	
1407		.040000 x	37.605000 =	1.504200	

			B.T =	53.460700	

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
029		600.000000 x	.152800 =	91.680000
1407		.050000 x	37.605000 =	1.880250

			B.T =	221.727750
1453	1453			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.099900 =	44.955000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000

			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
029		450.000000 x	.152800 =	68.760000

			B.T =	211.557750
1455	1455			
021		.250000 x	2.670000 =	.667500
053		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250
028		450.000000 x	.000000 =	.000000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750

1457	1457			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.152800 =	91.680000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000

			B.T =	221.727750
1458	1458			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
028		450.000000 x	.000000 =	.000000

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
029		450.000000 x	.152800 =	68.760000

			B.T =	211.557750
1461	1461			
021		.250000 x	2.670000 =	.667500
026		500.000000 x	.099900 =	49.950000
053		1,500.000000 x	.085000 =	127.500000
1407		.080000 x	37.605000 =	3.008400

			B.T =	181.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
026		400.000000 x	.099900 =	39.960000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000

			B.T =	85.411250
1463	1463			
021		.300000 x	2.670000 =	.801000
051		.100000 x	15.400000 =	1.540000
026		250.000000 x	.099900 =	24.975000
1407		.050000 x	37.605000 =	1.880250
515		1.050000 x	41.230000 =	43.291500

			B.T =	72.487750

1464	1464				
021		.200000 x	2.670000 =	.534000	
026		150.000000 x	.099900 =	14.985000	
1407		.120000 x	37.605000 =	4.512600	
519		.600000 x	47.670000 =	28.602000	
051		.420000 x	15.400000 =	6.468000	

			B.T =	55.101600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
051		.150000 x	15.400000 =	2.310000	
519		.900000 x	47.670000 =	42.903000	
1407		.030000 x	37.605000 =	1.128150	
026		450.000000 x	.099900 =	44.955000	

			B.T =	91.830150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
051		.210000 x	15.400000 =	3.234000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	47.670000 =	40.042800	
026		450.000000 x	.099900 =	44.955000	

			B.T =	89.893950	
1467	1467				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	47.670000 =	33.369000	
026		450.000000 x	.099900 =	44.955000	
051		.350000 x	15.400000 =	5.390000	

			B.T =	85.376150	
1471	1471				
251		1.000000 x	.775000 =	.775000	
351		4.000000 x	.668400 =	2.673600	
370		6.000000 x	.267400 =	1.604400	
372		.400000 x	2.246200 =	.898480	
364		2.000000 x	1.030000 =	2.060000	
358		1.000000 x	3.035000 =	3.035000	

			AΘΡΟΙΣΜΑ =	11.046480	
	B.T =	.476190 x	11.046480 =	5.260223	

1472	1472			
251		.600000 x	.775000 =	.465000
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		2.000000 x	.668400 =	1.336800
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	9.520760
	B.T =	.666667 x	9.520760 =	6.347177
1473	1473			
251		.500000 x	.775000 =	.387500
360		1.000000 x	13.580000 =	13.580000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
364		2.000000 x	1.030000 =	2.060000
361		1.000000 x	1.136300 =	1.136300
354		4.000000 x	.895800 =	3.583200
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	26.062540
	B.T =	.416667 x	26.062540 =	10.859400
1474	1474			
251		.500000 x	.775000 =	.387500
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			AΘΡΟΙΣΜΑ =	31.629500
	B.T =	.416667 x	31.629500 =	13.178969
1475	1475			
251		.300000 x	.775000 =	.232500
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			AΘΡΟΙΣΜΑ =	89.953100
	B.T =	.416667 x	89.953100 =	37.480488

1476	1476			
251		.500000 x	.775000 =	.387500
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000

			ΑΘΡΟΙΣΜΑ =	5.579260
	B.T =	.500000 x	5.579260 =	2.789630

1478	1478			
251		3.000000 x	.775000 =	2.325000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400

			ΑΘΡΟΙΣΜΑ =	6.255500
	B.T =	.500000 x	6.255500 =	3.127750

1479	1479			
251		6.000000 x	.775000 =	4.650000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000

			ΑΘΡΟΙΣΜΑ =	75.828800
	B.T =	.454545 x	75.828800 =	34.467602

1480	1480			
251		8.000000 x	.775000 =	6.200000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400

			ΑΘΡΟΙΣΜΑ =	146.418400
	B.T =	.227273 x	146.418400 =	33.276949

1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.090000 =	.020700
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124

			B.T =	.832359
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.090000 =	.057600
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210

			B.T =	.608206

1488	1488			
444		.170000 x	2.143200 =	.364344
453		.500000 x	.090000 =	.045000
451		.170000 x	1.178800 =	.200396
446		.030000 x	2.540000 =	.076200
445		.050000 x	1.553500 =	.077675

			B.T =	.763615
1489	1489			
444		.100000 x	2.143200 =	.214320
453		.430000 x	.090000 =	.038700
451		.350000 x	1.178800 =	.412580
446		.020000 x	2.540000 =	.050800
445		.100000 x	1.553500 =	.155350

			B.T =	.871750
1490	1490			
444		.300000 x	2.143200 =	.642960
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200
451		.570000 x	1.178800 =	.671916

			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800

			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
446		.030000 x	2.540000 =	.076200
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000

			B.T =	2.756980
1501	1501			
011		1.000000 x	53.630000 =	53.630000
012		2.000000 x	4.400000 =	8.800000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	1.047200 =	15.708000
484		1.750000 x	3.930000 =	6.877500

			B.T =	466.137973

1502	1502				
013		1.000000 x	26.580000 =	26.580000	
005		3.500000 x	21.778427 =	76.224495	
001		26.000000 x	15.741598 =	409.281548	
482		15.000000 x	1.300000 =	19.500000	
484		.900000 x	3.930000 =	3.537000	

			B.T =	535.123043	
1503	1503				
014		1.000000 x	260.720000 =	260.720000	
002		2.600000 x	17.312112 =	45.011491	
004		7.000000 x	23.886192 =	167.203344	
484		2.600000 x	3.930000 =	10.218000	
485		44.000000 x	1.047200 =	46.076800	

			B.T =	529.229635	
1504	1504				
015		1.000000 x	200.790000 =	200.790000	
004		7.000000 x	23.886192 =	167.203344	
002		7.000000 x	17.312112 =	121.184784	
485		83.000000 x	1.047200 =	86.917600	
484		5.250000 x	3.930000 =	20.632500	
291		2.200000 x	5.000000 =	11.000000	

			B.T =	607.728228	
1505	1505				
016		1.000000 x	31.630000 =	31.630000	
004		7.000000 x	23.886192 =	167.203344	
002		1.750000 x	17.312112 =	30.296196	
485		17.500000 x	1.047200 =	18.326000	
484		1.750000 x	3.930000 =	6.877500	

			B.T =	254.333040	
1506	1506				
017		1.000000 x	369.270000 =	369.270000	
002		3.500000 x	17.312112 =	60.592392	
484		6.000000 x	3.930000 =	23.580000	
004		7.000000 x	23.886192 =	167.203344	
485		70.000000 x	1.047200 =	73.304000	

			B.T =	693.949736	
2101	2101				
002		.300000 x	17.312112 =	5.193634	

			T.E =	5.193634	

2102	2102			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2108A	2108A			
002		.700000 x	17.312112 =	12.118478

			T.E =	12.118478
2108B	2108B			
002		1.600000 x	17.312112 =	27.699379

			T.E =	27.699379

2108E	2108E			
002		4.600000 x	17.312112 =	79.635715

			T.E =	79.635715
2108H	2108H			
002		7.600000 x	17.312112 =	131.572051

			T.E =	131.572051
2108Z	2108Z			
002		6.600000 x	17.312112 =	114.259939

			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491

			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603

			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163

			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827

			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1506		.004000 x	693.949736 =	2.775799
1503		.001000 x	529.229635 =	.529230

			T.E =	3.824392
2110	2110			
002		.040000 x	17.312112 =	.692484
1501		.005000 x	466.137973 =	2.330690
1506		.004000 x	693.949736 =	2.775799
1503		.001000 x	529.229635 =	.529230

			T.E =	6.328203

2111	2111				
002		.100000 x	17.312112 =	1.731211	
1504		.005000 x	607.728228 =	3.038641	

			T.E =	4.769852	
2112	2112				
002		.120000 x	17.312112 =	2.077453	
1504		.005500 x	607.728228 =	3.342505	
1501		.004000 x	466.137973 =	1.864552	

			T.E =	7.284511	
2113	2113				
002		1.400000 x	17.312112 =	24.236957	
002		.300000 x	17.312112 =	5.193634	

			T.E =	29.430590	
2114	2114				
002		1.500000 x	17.312112 =	25.968168	
1501		.005000 x	466.137973 =	2.330690	
002		.400000 x	17.312112 =	6.924845	

			T.E =	35.223703	
2115	2115				
481		.300000 x	5.467500 =	1.640250	
003		1.200000 x	20.419486 =	24.503383	
1501		.011000 x	466.137973 =	5.127518	
002		.600000 x	17.312112 =	10.387267	

			T.E =	41.658418	
2116	2116				
2115		1.300000 x	41.658418 =	54.155943	

			T.E =	54.155943	
2117	2117				
002		.600000 x	17.312112 =	10.387267	
1501		.125000 x	466.137973 =	58.267247	

			T.E =	68.654514	
2118	2118				
2117		1.300000 x	68.654514 =	89.250868	

			T.E =	89.250868	

2121	2121				
001		.400000 x	15.741598 =	6.296639	
002		1.800000 x	17.312112 =	31.161802	

			T.E =	37.458441	
2122	2122				
001		.500000 x	15.741598 =	7.870799	
1501		.005000 x	466.137973 =	2.330690	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	44.825713	
2123	2123				
002		.200000 x	17.312112 =	3.462422	
1504		.008300 x	607.728228 =	5.044144	

			T.E =	8.506567	
2124	2124				
002		.200000 x	17.312112 =	3.462422	
1501		.005000 x	466.137973 =	2.330690	
1504		.010000 x	607.728228 =	6.077282	

			T.E =	11.870395	
2125	2125				
481		.400000 x	5.467500 =	2.187000	
1501		.020000 x	466.137973 =	9.322759	
002		1.000000 x	17.312112 =	17.312112	
003		1.500000 x	20.419486 =	30.629229	

			T.E =	59.451100	
2126	2126				
2125		1.300000 x	59.451100 =	77.286430	

			T.E =	77.286430	
2127	2127				
002		1.000000 x	17.312112 =	17.312112	
1501		.166600 x	466.137973 =	77.658586	

			T.E =	94.970698	
2128	2128				
2127		1.300000 x	94.970698 =	123.461907	

			T.E =	123.461907	

2131	2131			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2132	2132			
1504		.001600 x	607.728228 =	.972365

			T.E =	.972365
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267

			T.E =	12.118478
2134	2134			
1504		.002500 x	607.728228 =	1.519321

			T.E =	1.519321
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973

			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	44.825713 =	58.273427

			T.E =	58.273427
2135.3	2135.3			
2127		1.300000 x	94.970698 =	123.461907

			T.E =	123.461907
2135.4	2135.4			
2128		1.300000 x	123.461907 =	160.500479

			T.E =	160.500479
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715

			T.E =	82.531911

2142	2142				
001		2.000000 x	15.741598 =	31.483196	
1501		.005000 x	466.137973 =	2.330690	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	95.072344	
2143	2143				
481		.500000 x	5.467500 =	2.733750	
001		2.000000 x	15.741598 =	31.483196	
003		3.000000 x	20.419486 =	61.258458	
1501		.025000 x	466.137973 =	11.653449	

			T.E =	107.128853	
2144	2144				
2143		1.300000 x	107.128853 =	139.267509	

			T.E =	139.267509	
2145	2145				
001		2.000000 x	15.741598 =	31.483196	
003		1.000000 x	20.419486 =	20.419486	
1501		.200000 x	466.137973 =	93.227595	

			T.E =	145.130277	
2146	2146				
2145		1.300000 x	145.130277 =	188.669360	

			T.E =	188.669360	
2151	2151				
001		1.200000 x	15.741598 =	18.889918	
003		.800000 x	20.419486 =	16.335589	

			T.E =	35.225506	
2152	2152				
001		1.500000 x	15.741598 =	23.612397	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	44.031883	
2161	2161				
1505		.003300 x	254.333040 =	.839299	

			T.E =	.839299	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278

			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	607.728228 =	2.430913

			T.E =	2.580513
2172	2172			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536

			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713

			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.900000 =	.414120
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.930000 =	.393000
482		.700000 x	1.300000 =	.910000
018.1		.042800 x	2.900000 =	.124120

			T.E =	10.552611
2186	2186			
018.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	4.400000 =	.188320
482		1.400000 x	1.300000 =	1.820000
484		.200000 x	3.930000 =	.786000

			T.E =	12.134011
2187	2187			
019.1		.142800 x	2.900000 =	.414120
485		1.100000 x	1.047200 =	1.151920
019.1		.428000 x	2.900000 =	1.241200
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.930000 =	.393000

			T.E =	11.911611
2188	2188			
019.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	1.047200 =	1.884960
484		.200000 x	3.930000 =	.786000
019.2		.042800 x	4.400000 =	.188320

			T.E =	12.198971

ΑΤΟΕ	3ο Τρίμηνο του 2010	Σελ. Ημ/νία	31 16/07/2011
2201	2201		
001	1.000000 x	15.741598 =	15.741598
002	2.000000 x	17.312112 =	34.624224

		T.E =	50.365822
2202	2202		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2203	2203		
001	1.000000 x	15.741598 =	15.741598
002	2.500000 x	17.312112 =	43.280280

		T.E =	59.021878
2204	2204		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2206	2206		
001	1.000000 x	15.741598 =	15.741598
003	3.000000 x	20.419486 =	61.258458

		T.E =	77.000056
2207	2207		
001	1.000000 x	15.741598 =	15.741598
003	6.000000 x	20.419486 =	122.516916

		T.E =	138.258514
2211	2211		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196
2212	2212		
001	1.000000 x	15.741598 =	15.741598

		T.E =	15.741598
2213	2213		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379

			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280

			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560

			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344

			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390

			T.E =	.408390

2236	2236				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

				T.E =	6.767793
2237	2237				
001		.200000 x	15.741598 =	3.148320	
003		.700000 x	20.419486 =	14.293640	

				T.E =	17.441960
2238	2238				
001		.100000 x	15.741598 =	1.574160	
002		.400000 x	17.312112 =	6.924845	

				T.E =	8.499005
2239	2239				
001		.200000 x	15.741598 =	3.148320	
003		.800000 x	20.419486 =	16.335589	

				T.E =	19.483908
2241	2241				
001		.300000 x	15.741598 =	4.722479	
003		.100000 x	20.419486 =	2.041949	

				T.E =	6.764428
2242	2242				
001		.400000 x	15.741598 =	6.296639	
003		.150000 x	20.419486 =	3.062923	

				T.E =	9.359562
2243	2243				
001		.500000 x	15.741598 =	7.870799	
003		.250000 x	20.419486 =	5.104872	

				T.E =	12.975671
2246	2246				
001		.250000 x	15.741598 =	3.935400	
003		.050000 x	20.419486 =	1.020974	

				T.E =	4.956374

2247	2247				
001		.350000 x	15.741598 =	5.509559	
003		.100000 x	20.419486 =	2.041949	

				T.E =	7.551508
2248	2248				
001		.450000 x	15.741598 =	7.083719	
003		.200000 x	20.419486 =	4.083897	

				T.E =	11.167616
2251	2251				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

				T.E =	6.767793
2252	2252				
001		.100000 x	15.741598 =	1.574160	
002		.600000 x	17.312112 =	10.387267	

				T.E =	11.961427
2261A	2261A				
003		.400000 x	20.419486 =	8.167794	

				T.E =	8.167794
2261B	2261B				
003		.700000 x	20.419486 =	14.293640	

				T.E =	14.293640
2261Γ	2261Γ				
003		.900000 x	20.419486 =	18.377537	

				T.E =	18.377537
2261Δ	2261Δ				
003		1.200000 x	20.419486 =	24.503383	

				T.E =	24.503383
2262A	2262A				
003		.550000 x	20.419486 =	11.230717	

				T.E =	11.230717

2262B	2262B			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049

			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818

			T.E =	46.964818
2264.2Α	2264.2Α			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972
2264.2Β	2264.2Β			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561

			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355

			T.E =	65.342355
2264.3Α	2264.3Α			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.3Β	2264.3Β			
003		2.850000 x	20.419486 =	58.195535

			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304

			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073

			T.E =	76.573073
2265Α	2265Α			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728

			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.11	2266.11			
2263Γ		1.000000 x	32.671178 =	32.671178
2263Γ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617

			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686
			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640
			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368
			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096
			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774
			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824
			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368
			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437
			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =	67.384304	
2264.3Γ		.350000 x	67.384304 =	23.584506	
			T.E =	90.968810	
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =	76.573073	
2264.3Δ		.350000 x	76.573073 =	26.800576	
			T.E =	103.373649	
2266.25	2266.25				
2265A		1.000000 x	10.209743 =	10.209743	
2265A		.350000 x	10.209743 =	3.573410	
			T.E =	13.783153	
2266.26	2266.26				
2265B		1.000000 x	16.335589 =	16.335589	
2265B		.350000 x	16.335589 =	5.717456	
			T.E =	22.053045	
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =	18.377537	
2261Γ		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =	24.503383	
2261Δ		.350000 x	24.503383 =	8.576184	
			T.E =	33.079567	
2266.5	2266.5				
2262A		1.000000 x	11.230717 =	11.230717	
2262A		.350000 x	11.230717 =	3.930751	
			T.E =	15.161468	
2266.6	2266.6				
2262B		1.000000 x	18.377537 =	18.377537	
2262B		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774

			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967

			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710

			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453

			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972

2269B	2269B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2269Γ	2269Γ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2270.1	2270.1			
2267		1.000000 x	71.468201 =	71.468201
2267		.600000 x	71.468201 =	42.880921

			T.E =	114.349122
2270.2	2270.2			
2268A		1.000000 x	102.097430 =	102.097430
2268A		.600000 x	102.097430 =	61.258458

			T.E =	163.355888
2270.3	2270.3			
2268B		1.000000 x	120.474967 =	120.474967
2268B		.600000 x	120.474967 =	72.284980

			T.E =	192.759947
2270.4	2270.4			
2268Γ		1.000000 x	130.684710 =	130.684710
2268Γ		.600000 x	130.684710 =	78.410826

			T.E =	209.095536
2270.5	2270.5			
2268Δ		1.000000 x	140.894453 =	140.894453
2268Δ		.600000 x	140.894453 =	84.536672

			T.E =	225.431125
2271A	2271A			
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.048715
2271B	2271B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458

2271E	2271E			
003		4.500000 x	20.419486 =	91.887687

			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916

			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402

			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173

			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098

			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019

			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939

			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220

			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299

			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738

			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379

			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580

			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631

			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860

			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089

			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318

			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330

			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323

			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727

			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459

			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193

			T.E =	135.381193
2274.15	2274.15			
2272Ε		1.300000 x	118.433019 =	153.962925

			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389

			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121

			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854

			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586

			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320

			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318

			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316

			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313

			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661

			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327

			T.E =	106.181327
2274.5	2274.5			
2271Ε		1.300000 x	91.887687 =	119.453993

			T.E =	119.453993
2274.6	2274.6			
2271ΣΤ		1.300000 x	102.097430 =	132.726659

			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325

			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991

			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	290.000000 =	9.570000
251		6.000000 x	.775000 =	4.650000
003		5.000000 x	20.419486 =	102.097430
001		9.000000 x	15.741598 =	141.674382

			T.E =	266.691812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634

			T.E =	5.483634

2303	2303				
001		.250000 x	15.741598 =	3.935400	
003		.250000 x	20.419486 =	5.104872	

			T.E =	9.040271	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.312112 =	1.731211	

			T.E =	1.847211	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	290.000000 =	11.600000	
003		7.000000 x	20.419486 =	142.936402	
001		9.000000 x	15.741598 =	141.674382	
251		6.000000 x	.775000 =	4.650000	

			T.E =	312.460784	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	290.000000 =	.580000	
251		.250000 x	.775000 =	.193750	
001		.250000 x	15.741598 =	3.935400	
003		.150000 x	20.419486 =	3.062923	

			T.E =	8.352072	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.775000 =	.155000	
203.4		.001000 x	290.000000 =	.290000	
003		.100000 x	20.419486 =	2.041949	
001		.200000 x	15.741598 =	3.148320	

			T.E =	6.215268	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.419486 =	.612585	

			T.E =	1.102085	
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	20.419486 =	.612585	

			T.E =	.987585	

3101	3101			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
052		.430000 x	15.400000 =	6.622000
056		.860000 x	10.580000 =	9.098800

			T.E =	103.260033
3102	3102			
021		.250000 x	2.670000 =	.667500
052		.420000 x	15.400000 =	6.468000
056		.840000 x	10.580000 =	8.887200
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		200.000000 x	.099900 =	19.980000

			T.E =	105.391933
3103	3103			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.820000 x	10.580000 =	8.675600
052		.410000 x	15.400000 =	6.314000
026		250.000000 x	.099900 =	24.975000

			T.E =	110.021333
3104	3104			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.400000 x	15.400000 =	6.160000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000

			T.E =	114.650733
3111	3111			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
026		200.000000 x	.099900 =	19.980000
057		.840000 x	10.580000 =	8.887200
052		.420000 x	15.400000 =	6.468000

			T.E =	129.598321

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	535.123043 =	26.756152
026		250.000000 x	.099900 =	24.975000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	15.400000 =	6.314000

			T.E =	129.500677
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.099900 =	29.970000

			T.E =	160.081418
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.099900 =	14.985000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
052		.420000 x	15.400000 =	6.468000

			T.E =	117.370190
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	107.843233
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.560000 x	15.400000 =	8.624000

			T.E =	110.051133

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.099900 =	24.975000

			T.E =	114.466933
3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.530000 x	15.400000 =	8.162000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.800000 x	13.560000 =	10.848000

			T.E =	119.036733
3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
026		200.000000 x	.099900 =	19.980000
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000

			T.E =	259.975359
3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
052		.410000 x	15.400000 =	6.314000

			T.E =	264.390159
3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.099900 =	19.980000

			T.E =	193.185046

3208	3208			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.730000 x	13.610000 =	9.935300
052		.430000 x	15.400000 =	6.622000
026		250.000000 x	.099900 =	24.975000

			T.E =	197.907846
3211	3211			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
052		.560000 x	15.400000 =	8.624000
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	13.560000 =	11.390400

			T.E =	134.257521
3212	3212			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
052		.540000 x	15.400000 =	8.316000
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	535.123043 =	26.756152
062		.820000 x	13.560000 =	11.119200

			T.E =	133.946277
3213	3213			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000

			T.E =	164.467418
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	13.610000 =	3.674700
062		.600000 x	13.560000 =	8.136000
052		.400000 x	15.400000 =	6.160000
026		350.000000 x	.099900 =	34.965000

			T.E =	176.293917

3215	3215			
021		.250000 x	2.670000 =	.667500
052		.420000 x	15.400000 =	6.468000
065		.250000 x	13.610000 =	3.402500
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
062		.560000 x	13.560000 =	7.593600
027		350.000000 x	.119300 =	41.755000

			T.E =	182.577317
3216	3216			
021		.250000 x	2.670000 =	.667500
001		4.000000 x	15.741598 =	62.966392
062		.550000 x	13.560000 =	7.458000
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972
027		425.000000 x	.119300 =	50.702500

			T.E =	198.454216
3217	3217			
001		2.500000 x	15.741598 =	39.353995

			T.E =	39.353995
3218	3218			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944

			T.E =	128.902738
3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944

			T.E =	160.385934
3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916

			T.E =	169.741710

3222	3222				
001		5.000000 x	15.741598 =		78.707990
003		6.000000 x	20.419486 =		122.516916

			T.E =		201.224906
3223A.1	3223A.1				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	535.123043 =		26.756152
003		1.500000 x	20.419486 =		30.629229

			AΘΡΟΙΣΜΑ =		88.868577
	T.E =	.500000 x	88.868577 =		44.434289

3223A.2	3223A.2				
001		3.000000 x	15.741598 =		47.224794
1502		.050000 x	535.123043 =		26.756152
003		2.000000 x	20.419486 =		40.838972

			AΘΡΟΙΣΜΑ =		114.819918
	T.E =	.500000 x	114.819918 =		57.409959

3223A.3	3223A.3				
001		2.000000 x	15.741598 =		31.483196
003		1.500000 x	20.419486 =		30.629229
1502		.050000 x	535.123043 =		26.756152

			AΘΡΟΙΣΜΑ =		88.868577
	T.E =	.500000 x	88.868577 =		44.434289

3223A.4	3223A.4				
001		3.000000 x	15.741598 =		47.224794
1502		.050000 x	535.123043 =		26.756152
003		2.000000 x	20.419486 =		40.838972

			AΘΡΟΙΣΜΑ =		114.819918
	T.E =	.500000 x	114.819918 =		57.409959

3223A.5	3223A.5				
001		3.500000 x	15.741598 =		55.095593
1502		.050000 x	535.123043 =		26.756152
003		2.000000 x	20.419486 =		40.838972

			AΘΡΟΙΣΜΑ =		122.690717
	T.E =	.500000 x	122.690717 =		61.345359

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	122.690717
	T.E =	.500000 x	122.690717 =	61.345359

3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	130.561516
	T.E =	.500000 x	130.561516 =	65.280758

3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	88.868577
	T.E =	.250000 x	88.868577 =	22.217144

3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	114.819918
	T.E =	.250000 x	114.819918 =	28.704980

3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	88.868577
	T.E =	.250000 x	88.868577 =	22.217144

3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	535.123043 =	26.756152
003		2.000000 x	20.419486 =	40.838972

			ΑΘΡΟΙΣΜΑ =	114.819918
	T.E =	.250000 x	114.819918 =	28.704980

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	122.690717
	T.E =	.250000 x	122.690717 =	30.672679

3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	122.690717
	T.E =	.250000 x	122.690717 =	30.672679

3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	535.123043 =	26.756152

			ΑΘΡΟΙΣΜΑ =	130.561516
	T.E =	.250000 x	130.561516 =	32.640379

3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.099900 =	14.985000

			T.E =	122.029390
3301	3301			
021		.200000 x	2.670000 =	.534000
032		.150000 x	36.000000 =	5.400000
001		3.500000 x	15.741598 =	55.095593
003		.800000 x	20.419486 =	16.335589
1407		.150000 x	37.605000 =	5.640750
056		.800000 x	10.580000 =	8.464000
051		.300000 x	15.400000 =	4.620000

			T.E =	96.089932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
051		.200000 x	15.400000 =	3.080000

			T.E =	98.230182
3303	3303			
021		.200000 x	2.670000 =	.534000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
032		.400000 x	36.000000 =	14.400000

			T.E =	102.350182
3304	3304			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.099900 =	9.990000
032		.400000 x	36.000000 =	14.400000
001		3.500000 x	15.741598 =	55.095593
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
056		.800000 x	10.580000 =	8.464000

			T.E =	117.499576
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	36.000000 =	5.760000
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
061		.840000 x	13.560000 =	11.390400
001		3.500000 x	15.741598 =	55.095593
051		.320000 x	15.400000 =	4.928000

			T.E =	100.060382
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
051		.210000 x	15.400000 =	3.234000

			T.E =	110.214426

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
061		.840000 x	13.560000 =	11.390400
003		1.200000 x	20.419486 =	24.503383
1407		.210000 x	37.605000 =	7.897050
001		3.500000 x	15.741598 =	55.095593

			T.E =	114.540426
3314	3314			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.099900 =	9.990000
032		.420000 x	36.000000 =	15.120000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400

			T.E =	121.522026
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
026		140.000000 x	.099900 =	13.986000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600

			T.E =	91.562320
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280
026		140.000000 x	.099900 =	13.986000
058		.500000 x	9.090000 =	4.545000
052		.392000 x	15.400000 =	6.036800

			T.E =	94.823760
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
026		175.000000 x	.099900 =	17.482500

			T.E =	94.802900

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
052		.378000 x	15.400000 =	5.821200
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.574000 x	13.560000 =	7.783440

			T.E =	97.914820
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000

			T.E =	92.522320
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800

			T.E =	95.783760
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
026		175.000000 x	.099900 =	17.482500

			T.E =	95.762900

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
052		.378000 x	15.400000 =	5.821200
061		.574000 x	13.560000 =	7.783440
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000

			T.E =	98.874820
3501	3501			
021		.200000 x	2.670000 =	.534000
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000
003		2.000000 x	20.419486 =	40.838972
1407		.180000 x	37.605000 =	6.768900
001		5.000000 x	15.741598 =	78.707990

			T.E =	181.824862
3502	3502			
021		.200000 x	2.670000 =	.534000
067		1.050000 x	45.500000 =	47.775000
001		5.000000 x	15.741598 =	78.707990
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.099900 =	9.990000

			T.E =	188.806462
3503	3503			
021		.200000 x	2.670000 =	.534000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.000000 x	45.500000 =	45.500000
032		.200000 x	36.000000 =	7.200000
026		150.000000 x	.099900 =	14.985000

			T.E =	190.774362
3504	3504			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.099900 =	24.975000
055		180.000000 x	.090000 =	16.200000
517		4.000000 x	.000000 =	.000000
003		3.200000 x	20.419486 =	65.342355
001		5.000000 x	15.741598 =	78.707990

			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.099900 =	24.975000
517		4.000000 x	.000000 =	.000000
001		5.500000 x	15.741598 =	86.578789
003		5.000000 x	20.419486 =	102.097430
055		420.000000 x	.090000 =	37.800000

T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
026		200.000000 x	.099900 =	19.980000
003		2.500000 x	20.419486 =	51.048715
001		5.000000 x	15.741598 =	78.707990
515		1.150000 x	41.230000 =	47.414500

T.E =

197.952205

3511	3511			
021		.200000 x	2.670000 =	.534000
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
069		1.050000 x	.000000 =	.000000
032		.200000 x	36.000000 =	7.200000

T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
069		1.050000 x	.000000 =	.000000
001		5.000000 x	15.741598 =	78.707990
026		100.000000 x	.099900 =	9.990000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972

T.E =

3513	3513			
001		2.500000 x	15.741598 =	39.353995

T.E =

39.353995

3514	3514			
001		5.000000 x	15.741598 =	78.707990

T.E =

78.707990

3801	3801				
201		.001500 x	290.000000 =		.435000
203.4		.002500 x	290.000000 =		.725000
001		.400000 x	15.741598 =		6.296639
003		.500000 x	20.419486 =		10.209743
251		.300000 x	.775000 =		.232500

			T.E =		17.898882
3802	3802				
3801		.050000 x	17.898882 =		.894944

			T.E =		.894944
3811	3811				
203.4		.004000 x	290.000000 =		1.160000
003		.800000 x	20.419486 =		16.335589
001		.200000 x	15.741598 =		3.148320
251		.100000 x	.775000 =		.077500

			T.E =		20.721408
3816	3816				
201		.002500 x	290.000000 =		.725000
003		.600000 x	20.419486 =		12.251692
001		.400000 x	15.741598 =		6.296639
251		.200000 x	.775000 =		.155000
203.4		.003000 x	290.000000 =		.870000

			T.E =		20.298331
3817	3817				
3816		.150000 x	20.298331 =		3.044750

			T.E =		3.044750
3821	3821				
201		.014000 x	290.000000 =		4.060000
203.4		.018000 x	290.000000 =		5.220000
251		.600000 x	.775000 =		.465000
003		2.400000 x	20.419486 =		49.006766
001		.600000 x	15.741598 =		9.444959

			T.E =		68.196725
3822	3822				
3821		.150000 x	68.196725 =		10.229509

			T.E =		10.229509

3823	3823				
201		.020000 x	290.000000 =	5.800000	
003		3.000000 x	20.419486 =	61.258458	
203.4		.025000 x	290.000000 =	7.250000	
001		.600000 x	15.741598 =	9.444959	
251		.180000 x	.775000 =	.139500	

			T.E =	83.892917	
3824	3824				
3823		.200000 x	83.892917 =	16.778583	

			T.E =	16.778583	
3831	3831				
201		.020000 x	290.000000 =	5.800000	
203.4		.024000 x	290.000000 =	6.960000	
001		1.100000 x	15.741598 =	17.315758	
003		4.500000 x	20.419486 =	91.887687	
251		.800000 x	.775000 =	.620000	

			T.E =	122.583445	
3832	3832				
3831		.150000 x	122.583445 =	18.387517	

			T.E =	18.387517	
3833	3833				
201		.022000 x	290.000000 =	6.380000	
003		6.000000 x	20.419486 =	122.516916	
001		1.100000 x	15.741598 =	17.315758	
251		1.000000 x	.775000 =	.775000	
203.4		.025000 x	290.000000 =	7.250000	

			T.E =	154.237674	
3834	3834				
3833		.200000 x	154.237674 =	30.847535	

			T.E =	30.847535	
3841	3841				
203.4		.001500 x	290.000000 =	.435000	
003		.500000 x	20.419486 =	10.209743	

			T.E =	10.644743	

3851	3851			
203.4		.052000 x	290.000000 =	15.080000
251		1.100000 x	.775000 =	.852500
003		1.300000 x	20.419486 =	26.545332

			T.E =	42.477832
3852	3852			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949

			T.E =	6.764428
3871	3871			
260		1.030000 x	.583300 =	.600799
003		.050000 x	20.419486 =	1.020974

			T.E =	1.621773
3872	3872			
261		1.030000 x	.639200 =	.658376
003		.040000 x	20.419486 =	.816779

			T.E =	1.475155
3873	3873			
262		1.030000 x	.583300 =	.600799
003		.050000 x	20.419486 =	1.020974

			T.E =	1.621773
3874	3874			
258		1.450000 x	7.856500 =	11.391925
003		.150000 x	20.419486 =	3.062923

			T.E =	14.454848
3875	3875			
259		1.000000 x	25.500000 =	25.500000
003		.300000 x	20.419486 =	6.125846

			T.E =	31.625846
3876	3876			
003		.060000 x	20.419486 =	1.225169

			T.E =	1.225169

3881.1	3881.1			
111		1,023.391800 x	.077500 =	79.312865
001		5.000000 x	15.741598 =	78.707990

			T.E =	158.020855
3881.2	3881.2			
112		627.989998 x	.085000 =	53.379150
001		5.000000 x	15.741598 =	78.707990

			T.E =	132.087140
3882	3882			
127		1.050000 x	81.220000 =	85.281000
001		4.000000 x	15.741598 =	62.966392

			T.E =	148.247392
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	20.419486 =	40.838972
001		1.300000 x	15.741598 =	20.464077

			T.E =	73.964549
4102	4102			
081		1.200000 x	11.010000 =	13.212000
003		3.500000 x	20.419486 =	71.468201
001		1.700000 x	15.741598 =	26.760717

			T.E =	111.440918
4103	4103			
081		1.150000 x	11.010000 =	12.661500
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944

			T.E =	141.564238
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.741598 =	47.224794

			T.E =	58.785294
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	20.419486 =	18.377537
001		1.000000 x	15.741598 =	15.741598

			T.E =	37.972635

4106	4106			
081		.320000 x	11.010000 =	3.523200
003		.900000 x	20.419486 =	18.377537
001		.700000 x	15.741598 =	11.019119

			T.E =	32.919856
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458

			T.E =	105.953654
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944

			T.E =	149.766208
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
001		2.900000 x	15.741598 =	45.650634
003		2.500000 x	20.419486 =	51.048715

			T.E =	123.460407
4206	4206			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
003		3.100000 x	20.419486 =	63.300407
001		2.900000 x	15.741598 =	45.650634

			T.E =	135.712098
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
1417		.350000 x	40.284450 =	14.099558

			T.E =	154.089636

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	59.035900 =	20.662565	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	130.023414	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	59.035900 =	20.662565	
003		3.100000 x	20.419486 =	63.300407	

			T.E =	142.275106	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		4.000000 x	20.419486 =	81.677944	
001		2.900000 x	15.741598 =	45.650634	

			T.E =	160.652643	
4221	4221				
001		.800000 x	15.741598 =	12.593278	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	33.012764	
4222	4222				
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.464434	
4226	4226				
003		1.300000 x	20.419486 =	26.545332	

			T.E =	26.545332	
4251	4251				
083		32.000000 x	.000000 =	.000000	
1412		.200000 x	27.931800 =	5.586360	
001		2.900000 x	15.741598 =	45.650634	
003		4.000000 x	20.419486 =	81.677944	

			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
1417		.200000 x	40.284450 =	8.056890
001		2.900000 x	15.741598 =	45.650634

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.946500 =	12.389300
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
1447		.200000 x	59.035900 =	11.807180
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E =

4301	4301			16.176598
081		1.020000 x	11.010000 =	11.230200
083		5.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
003		4.200000 x	20.419486 =	85.761841
1412		.350000 x	27.931800 =	9.776130

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
003		2.700000 x	20.419486 =	55.132612
1417		.350000 x	40.284450 =	14.099558

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
1417		.350000 x	40.284450 =	14.099558
003		3.300000 x	20.419486 =	67.384304
001		2.900000 x	15.741598 =	45.650634

T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
1417		.350000 x	40.284450 =	14.099558
003		4.200000 x	20.419486 =	85.761841
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000

T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	20.419486 =	55.132612
1447		.350000 x	59.035900 =	20.662565
001		2.900000 x	15.741598 =	45.650634

T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
1447		.350000 x	59.035900 =	20.662565
003		3.300000 x	20.419486 =	67.384304
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634

T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	59.035900 =	20.662565
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000

T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E = 16.176598

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980
251		4.000000 x	.775000 =	3.100000

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.775000 =	3.100000
001		10.000000 x	15.741598 =	157.415980
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
1446		.100000 x	52.880500 =	5.288050
251		4.000000 x	.775000 =	3.100000
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
251		8.000000 x	.775000 =	6.200000
003		32.000000 x	20.419486 =	653.423552
1446		.200000 x	52.880500 =	10.576100
001		11.000000 x	15.741598 =	173.157578

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578
251		8.000000 x	.775000 =	6.200000

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.775000 =	6.200000
001		11.000000 x	15.741598 =	173.157578

			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918

			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	20.419486 =	20.419486
002		.500000 x	17.312112 =	8.656056

			T.E =	29.626042
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.300000 x	20.419486 =	26.545332

			T.E =	35.751888
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.400000 x	20.419486 =	28.587280

			T.E =	37.793836
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818

			T.E =	52.708951

4505	4505				
081		.050000 x	11.010000 =	.550500	
003		2.700000 x	20.419486 =	55.132612	
002		.300000 x	17.312112 =	5.193634	

			T.E =	60.876746	
4506	4506				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.600000 x	20.419486 =	73.510150	

			T.E =	79.254283	
4507	4507				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.200000 x	20.419486 =	65.342355	

			T.E =	71.086489	
4508	4508				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	67.002592	
4511	4511				
081		.050000 x	11.010000 =	.550500	
003		3.800000 x	20.419486 =	77.594047	
002		.300000 x	17.312112 =	5.193634	

			T.E =	83.338180	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	87.422078	
4515	4515				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		5.000000 x	20.419486 =	102.097430	

			T.E =	107.841564	

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687

			T.E =	97.631821
4517	4517			
081		.050000 x	11.010000 =	.550500
003		6.500000 x	20.419486 =	132.726659
002		.300000 x	17.312112 =	5.193634

			T.E =	138.470793
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.700000 x	20.419486 =	116.391070

			T.E =	122.135204
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327

			T.E =	111.925461
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.500000 x	20.419486 =	71.468201

			T.E =	77.212335
4522	4522			
081		.050000 x	11.010000 =	.550500
003		2.700000 x	20.419486 =	55.132612
002		.300000 x	17.312112 =	5.193634

			T.E =	60.876746
4525	4525			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687

			T.E =	97.631821

4526	4526			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.000000 x	20.419486 =	81.677944

			T.E =	87.422078
4527	4527			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		6.000000 x	20.419486 =	122.516916

			T.E =	128.261050
4528	4528			
081		.050000 x	11.010000 =	.550500
003		5.200000 x	20.419486 =	106.181327
002		.300000 x	17.312112 =	5.193634

			T.E =	111.925461
4529	4529			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.700000 x	20.419486 =	95.971584

			T.E =	101.715718
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.599215
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972

			T.E =	41.389472
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047

			T.E =	78.144547
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	20.419486 =	63.300407

			T.E =	63.850907

4537	4537			
081		.050000 x	11.010000 =	.550500
003		5.500000 x	20.419486 =	112.307173

			T.E =	112.857673
4538	4538			
081		.050000 x	11.010000 =	.550500
003		4.600000 x	20.419486 =	93.929636

			T.E =	94.480136
4539	4539			
081		.050000 x	11.010000 =	.550500
003		4.200000 x	20.419486 =	85.761841

			T.E =	86.312341
4541	4541			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.599215
4542	4542			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972

			T.E =	41.389472
4543	4543			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944

			T.E =	82.228444
4544	4544			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	20.419486 =	122.516916

			T.E =	123.067416
4601.1	4601.1			
101		105.000000 x	.000000 =	.000000
1417		.023000 x	40.284450 =	.926542
003		.700000 x	20.419486 =	14.293640
001		.600000 x	15.741598 =	9.444959

			T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	59.035900 =	1.357826
001		.600000 x	15.741598 =	9.444959
003		.700000 x	20.419486 =	14.293640

T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	40.284450 =	2.255929
003		1.300000 x	20.419486 =	26.545332
001		1.300000 x	15.741598 =	20.464077

T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
1447		.056000 x	59.035900 =	3.306010
003		1.300000 x	20.419486 =	26.545332
001		1.300000 x	15.741598 =	20.464077

T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	40.284450 =	3.585316
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
1447		.089000 x	59.035900 =	5.254195
001		1.900000 x	15.741598 =	29.909036
003		1.800000 x	20.419486 =	36.755075

T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	40.284450 =	13.374437
003		5.500000 x	20.419486 =	112.307173
001		6.300000 x	15.741598 =	99.172067

T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
1447		.332000 x	59.035900 =	19.599919
003		5.500000 x	20.419486 =	112.307173
001		6.300000 x	15.741598 =	99.172067

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	40.284450 =	1.208534
001		.700000 x	15.741598 =	11.019119
003		.700000 x	20.419486 =	14.293640

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1447		.030000 x	59.035900 =	1.771077
003		.700000 x	20.419486 =	14.293640

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	40.284450 =	2.819912
001		1.400000 x	15.741598 =	22.038237
003		1.300000 x	20.419486 =	26.545332

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
1447		.070000 x	59.035900 =	4.132513
003		1.300000 x	20.419486 =	26.545332
001		1.400000 x	15.741598 =	22.038237

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	40.284450 =	4.431290
003		1.800000 x	20.419486 =	36.755075
001		2.100000 x	15.741598 =	33.057356

T.E =

4613.2 4613.2

102	315.000000 x	.000000 =	.000000
1447	.110000 x	59.035900 =	6.493949
001	2.100000 x	15.741598 =	33.057356
003	1.800000 x	20.419486 =	36.755075

T.E =

4614.1 4614.1

102	1,050.000000 x	.000000 =	.000000
1417	.404000 x	40.284450 =	16.274918
003	5.500000 x	20.419486 =	112.307173
001	6.500000 x	15.741598 =	102.320387

T.E =

4614.2 4614.2

102	1,050.000000 x	.000000 =	.000000
1447	.404000 x	59.035900 =	23.850504
003	5.500000 x	20.419486 =	112.307173
001	6.500000 x	15.741598 =	102.320387

T.E =

4621.1 4621.1

111	53.000000 x	.077500 =	4.107500
1417	.010000 x	40.284450 =	.402845
001	.400000 x	15.741598 =	6.296639
003	.500000 x	20.419486 =	10.209743

T.E =

21.016727

4621.2 4621.2

111	53.000000 x	.077500 =	4.107500
001	.400000 x	15.741598 =	6.296639
1447	.010000 x	59.035900 =	.590359
003	.500000 x	20.419486 =	10.209743

T.E =

21.204241

4622.1 4622.1

111	75.000000 x	.077500 =	5.812500
1417	.020000 x	40.284450 =	.805689
001	.450000 x	15.741598 =	7.083719
003	.500000 x	20.419486 =	10.209743

T.E =

23.911651

4622.2	4622.2			
111		75.000000 x	.077500 =	5.812500
1447		.020000 x	59.035900 =	1.180718
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719

			T.E =	24.286680
4623.1	4623.1			
111		150.000000 x	.077500 =	11.625000
1417		.050000 x	40.284450 =	2.014223
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512

			T.E =	47.992252
4623.2	4623.2			
111		150.000000 x	.077500 =	11.625000
001		.950000 x	15.741598 =	14.954518
1447		.050000 x	59.035900 =	2.951795
003		.950000 x	20.419486 =	19.398512

			T.E =	48.929825
4624.1	4624.1			
111		225.000000 x	.077500 =	17.437500
1417		.085000 x	40.284450 =	3.424178
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397

			T.E =	71.019407
4624.2	4624.2			
111		225.000000 x	.077500 =	17.437500
1447		.085000 x	59.035900 =	5.018052
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397

			T.E =	72.613280
4625.1	4625.1			
111		750.000000 x	.077500 =	58.125000
1417		.320000 x	40.284450 =	12.891024
001		5.200000 x	15.741598 =	81.856310
003		4.300000 x	20.419486 =	87.803790

			T.E =	240.676123

4625.2	4625.2			
111		750.000000 x	.077500 =	58.125000
001		5.200000 x	15.741598 =	81.856310
1447		.320000 x	59.035900 =	18.891488
003		4.300000 x	20.419486 =	87.803790

			T.E =	246.676587
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.911651 =	52.605632

			T.E =	52.605632
4633.2	4633.2			
4622.2		2.200000 x	24.286680 =	53.430696

			T.E =	53.430696
4634.1	4634.1			
4622.1		1.200000 x	23.911651 =	28.693981
4623.1		1.000000 x	47.992252 =	47.992252

			T.E =	76.686233
4634.2	4634.2			
4622.2		1.200000 x	24.286680 =	29.144016
4623.2		1.000000 x	48.929825 =	48.929825

			T.E =	78.073841
4661.1	4661.1			
112		43.750000 x	.085000 =	3.718750
1417		.014507 x	40.284450 =	.584407
001		.400000 x	15.741598 =	6.296639
003		.500000 x	20.419486 =	10.209743

			T.E =	20.809539
4661.2	4661.2			
112		43.750000 x	.085000 =	3.718750
1447		.014507 x	59.035900 =	.856434
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

			T.E =	21.081566
4662.1	4662.1			
112		58.333300 x	.085000 =	4.958331
1417		.022840 x	40.284450 =	.920097
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743

			T.E =	23.171889

4662.2	4662.2			
112		58.333300 x	.085000 =	4.958331
001		.450000 x	15.741598 =	7.083719
1447		.022840 x	59.035900 =	1.348380
003		.500000 x	20.419486 =	10.209743

			T.E =	23.600173
4663.1	4663.1			
112		105.000000 x	.085000 =	8.925000
1417		.043218 x	40.284450 =	1.741013
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438

			T.E =	43.210989
4663.2	4663.2			
112		105.000000 x	.085000 =	8.925000
1447		.043218 x	59.035900 =	2.551414
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438

			T.E =	44.021389
4664.1	4664.1			
112		97.222221 x	.085000 =	8.263889
1417		.045077 x	40.284450 =	1.815902
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512

			T.E =	44.432821
4664.2	4664.2			
112		97.222221 x	.085000 =	8.263889
001		.950000 x	15.741598 =	14.954518
1447		.045077 x	59.035900 =	2.661161
003		.950000 x	20.419486 =	19.398512

			T.E =	45.278080
4665.1	4665.1			
112		174.999001 x	.085000 =	14.874915
1417		.047530 x	40.284450 =	1.914720
001		1.500000 x	15.741598 =	23.612397
003		1.300000 x	20.419486 =	26.545332

			T.E =	66.947364

4665.2	4665.2			
112		174.999001 x	.085000 =	14.874915
1447		.047530 x	59.035900 =	2.805976
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397

			T.E =	67.838620
4666.1	4666.1			
112		486.111099 x	.085000 =	41.319443
1417		.277862 x	40.284450 =	11.193518
001		5.200000 x	15.741598 =	81.856310
003		4.300000 x	20.419486 =	87.803790

			T.E =	222.173061
4666.2	4666.2			
112		486.111000 x	.085000 =	41.319435
001		5.200000 x	15.741598 =	81.856310
1447		.277862 x	59.035900 =	16.403833
003		4.300000 x	20.419486 =	87.803790

			T.E =	227.383368
4701	4701			
113		13.000000 x	.570000 =	7.410000
1417		.020000 x	40.284450 =	.805689
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

			T.E =	24.254282
4702	4702			
113		13.000000 x	.570000 =	7.410000
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

			T.E =	24.629311
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	40.284450 =	.604267
001		.400000 x	15.741598 =	6.296639
003		.350000 x	20.419486 =	7.146820

			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
1417		.020000 x	40.284450 =	.805689
001		.500000 x	15.741598 =	7.870799
003		.400000 x	20.419486 =	8.167794

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
003		.350000 x	20.419486 =	7.146820
1417		.015000 x	40.284450 =	.604267
001		.400000 x	15.741598 =	6.296639

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

T.E =

4721.1	4721.1			
128		.080000 x	88.240000 =	7.059200
1417		.004000 x	40.284450 =	.161138
003		.350000 x	20.419486 =	7.146820
001		.300000 x	15.741598 =	4.722479

T.E =

19.089637

4721.2	4721.2				
128		.080000 x	88.240000 =	7.059200	
001		.300000 x	15.741598 =	4.722479	
1447		.004000 x	59.035900 =	.236144	
003		.350000 x	20.419486 =	7.146820	

			T.E =	19.164643	
4722.1	4722.1				
128		.100000 x	88.240000 =	8.824000	
001		.350000 x	15.741598 =	5.509559	
1417		.005000 x	40.284450 =	.201422	
003		.350000 x	20.419486 =	7.146820	

			T.E =	21.681802	
4722.2	4722.2				
128		.100000 x	88.240000 =	8.824000	
001		.350000 x	15.741598 =	5.509559	
1447		.005000 x	59.035900 =	.295180	
003		.350000 x	20.419486 =	7.146820	

			T.E =	21.775559	
4723	4723				
128		.120000 x	88.240000 =	10.588800	
1417		.006000 x	40.284450 =	.241707	
003		.350000 x	20.419486 =	7.146820	
001		.400000 x	15.741598 =	6.296639	

			T.E =	24.273966	
4724.1	4724.1				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	
1417		.008000 x	40.284450 =	.322276	

			T.E =	28.022709	
4724.2	4724.2				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1447		.008000 x	59.035900 =	.472287	
003		.400000 x	20.419486 =	8.167794	

			T.E =	28.172721	

4725.1	4725.1			
128		.180000 x	88.240000 =	15.883200
1417		.009000 x	40.284450 =	.362560
001		.450000 x	15.741598 =	7.083719
003		.400000 x	20.419486 =	8.167794

			T.E =	31.497274
4725.2	4725.2			
128		.180000 x	88.240000 =	15.883200
1447		.009000 x	59.035900 =	.531323
003		.400000 x	20.419486 =	8.167794
001		.450000 x	15.741598 =	7.083719

			T.E =	31.666037
4801.1	4801.1			
4662.1		1.000000 x	23.171889 =	23.171889
4662.1		.100000 x	23.171889 =	2.317189

			T.E =	25.489078
4801.2	4801.2			
4662.2		1.000000 x	23.600173 =	23.600173
4662.2		.100000 x	23.600173 =	2.360017

			T.E =	25.960190
4802.1	4802.1			
4664.1		1.000000 x	44.432821 =	44.432821
4664.1		.050000 x	44.432821 =	2.221641

			T.E =	46.654462
4802.2	4802.2			
4664.2		1.000000 x	45.278080 =	45.278080
4664.2		.050000 x	45.278080 =	2.263904

			T.E =	47.541984
4803.1	4803.1			
4665.1		1.000000 x	66.947364 =	66.947364
4665.1		.030000 x	66.947364 =	2.008421

			T.E =	68.955785
4803.2	4803.2			
4665.2		1.000000 x	67.838620 =	67.838620
4665.2		.030000 x	67.838620 =	2.035159

			T.E =	69.873779

4811.1	4811.1				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.1		1.000000 x	23.171889 =	23.171889	

			T.E =	31.818620	
4811.2	4811.2				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.2		1.000000 x	23.600173 =	23.600173	

			T.E =	32.246904	
4812.1	4812.1				
001		.475000 x	15.741598 =	7.477259	
4664.1		1.000000 x	44.432821 =	44.432821	
003		.475000 x	20.419486 =	9.699256	

			T.E =	61.609336	
4812.2	4812.2				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.2		1.000000 x	45.278080 =	45.278080	

			T.E =	62.454595	
4813.1	4813.1				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.1		1.000000 x	66.947364 =	66.947364	

			T.E =	92.026228	
4813.2	4813.2				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.2		1.000000 x	67.838620 =	67.838620	

			T.E =	92.917484	
4814.1	4814.1				
001		2.600000 x	15.741598 =	40.928155	
4666.1		1.000000 x	222.173061 =	222.173061	
003		2.150000 x	20.419486 =	43.901895	

			T.E =	307.003111	

4814.2	4814.2			
001		2.600000 x	15.741598 =	40.928155
4666.2		1.000000 x	227.383368 =	227.383368
003		2.150000 x	20.419486 =	43.901895

			T.E =	312.213418
4821.1	4821.1			
003		.450000 x	20.419486 =	9.188769
4662.1		1.000000 x	23.171889 =	23.171889

			T.E =	32.360658
4821.2	4821.2			
003		.450000 x	20.419486 =	9.188769
4662.2		1.000000 x	23.600173 =	23.600173

			T.E =	32.788942
4822.1	4822.1			
003		.807500 x	20.419486 =	16.488735
4664.1		1.000000 x	44.432821 =	44.432821

			T.E =	60.921556
4822.2	4822.2			
003		.807500 x	20.419486 =	16.488735
4664.2		1.000000 x	45.278080 =	45.278080

			T.E =	61.766815
4823.1	4823.1			
003		1.040000 x	20.419486 =	21.236265
4665.1		1.000000 x	66.947364 =	66.947364

			T.E =	88.183629
4823.2	4823.2			
003		1.040000 x	20.419486 =	21.236265
4665.2		1.000000 x	67.838620 =	67.838620

			T.E =	89.074885
4824.1	4824.1			
003		3.010000 x	20.419486 =	61.462653
4666.1		1.000000 x	222.173061 =	222.173061

			T.E =	283.635714

4824.2	4824.2			
003		3.010000 x	20.419486 =	61.462653
4666.2		1.000000 x	227.383368 =	227.383368

			T.E =	288.846021
4831.1	4831.1			
003		1.200000 x	20.419486 =	24.503383
4661.1		1.000000 x	20.809539 =	20.809539

			T.E =	45.312922
4831.2	4831.2			
003		1.200000 x	20.419486 =	24.503383
4661.2		1.000000 x	21.081566 =	21.081566

			T.E =	45.584949
4832.1	4832.1			
003		1.600000 x	20.419486 =	32.671178
4662.1		1.000000 x	23.171889 =	23.171889

			T.E =	55.843067
4832.2	4832.2			
003		1.600000 x	20.419486 =	32.671178
4662.2		1.000000 x	23.600173 =	23.600173

			T.E =	56.271351
4833.1	4833.1			
002		2.000000 x	17.312112 =	34.624224
4664.1		1.000000 x	44.432821 =	44.432821

			T.E =	79.057045
4833.2	4833.2			
002		2.000000 x	17.312112 =	34.624224
4664.2		1.000000 x	45.278080 =	45.278080

			T.E =	79.902304
4834.1	4834.1			
003		2.300000 x	20.419486 =	46.964818
4665.1		1.000000 x	66.947364 =	66.947364

			T.E =	113.912182

4834.2 4834.2

003	2.300000 x	20.419486 =	46.964818
4665.2	1.000000 x	67.838620 =	67.838620

T.E = 114.803438

4835 4835

122	1.050000 x	.000000 =	.000000
1417	.005000 x	40.284450 =	.201422
003	1.000000 x	20.419486 =	20.419486
001	1.000000 x	15.741598 =	15.741598
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.835300 =	1.670600

T.E =

4835.2 4835.2

122	1.050000 x	.000000 =	.000000
1447	.005000 x	59.035900 =	.295180
003	1.000000 x	20.419486 =	20.419486
001	1.000000 x	15.741598 =	15.741598
265	2.000000 x	.835300 =	1.670600
201	.010000 x	290.000000 =	2.900000

T.E =

4836.1 4836.1

123	1.050000 x	.000000 =	.000000
1417	.005000 x	40.284450 =	.201422
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.835300 =	1.670600
003	1.000000 x	20.419486 =	20.419486
001	1.000000 x	15.741598 =	15.741598

T.E =

4836.2 4836.2

123	1.050000 x	.000000 =	.000000
1447	.005000 x	59.035900 =	.295180
003	1.000000 x	20.419486 =	20.419486
201	.010000 x	290.000000 =	2.900000
001	1.000000 x	15.741598 =	15.741598
265	2.000000 x	.835300 =	1.670600

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	40.284450 =	.402845
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.835300 =	1.670600

			T.E =	47.329529
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
1447		.010000 x	59.035900 =	.590359
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
265		2.000000 x	.835300 =	1.670600
201		.010000 x	290.000000 =	2.900000

			T.E =	49.087557
4841	4841			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
4842	4842			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486
4843	4843			
003		.250000 x	20.419486 =	5.104872

			T.E =	5.104872
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
003		25.000000 x	20.419486 =	510.487150
1401		.250000 x	234.711000 =	58.677750
001		10.000000 x	15.741598 =	157.415980

			T.E =	1,506.580880
4845	4845			
132		620.000000 x	.930000 =	576.600000
1401		.180000 x	234.711000 =	42.247980
003		15.000000 x	20.419486 =	306.292290
001		6.000000 x	15.741598 =	94.449588

			T.E =	1,019.589858

4851	4851			
001		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240

			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400

			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639

			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799

			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
001		1.000000 x	15.741598 =	15.741598
003		4.000000 x	20.419486 =	81.677944

			T.E =	1,197.419542
5102	5102			
483		1.800000 x	.165000 =	.297000
001		1.000000 x	15.741598 =	15.741598
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.000000 =	2.700000
489		.360000 x	.000000 =	.000000

			T.E =	
5103	5103			
265		1.050000 x	.835300 =	.877065
003		.200000 x	20.419486 =	4.083897
002		.050000 x	17.312112 =	.865606

			T.E =	5.826568
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923

			T.E =	34.546119
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
003		.500000 x	20.419486 =	10.209743
001		2.000000 x	15.741598 =	31.483196

			T.E =	51.692939

5106	5106				
214		.050000 x	1,000.000000 =	50.000000	
003		2.500000 x	20.419486 =	51.048715	
001		2.000000 x	15.741598 =	31.483196	

			T.E =	132.531911	
5201	5201				
201		1.100000 x	290.000000 =	319.000000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
251		6.000000 x	.775000 =	4.650000	

			T.E =	614.405420	
5202	5202				
203.2		1.080000 x	370.000000 =	399.600000	
251		6.000000 x	.775000 =	4.650000	
002		4.500000 x	17.312112 =	77.904504	
003		9.000000 x	20.419486 =	183.775374	

			T.E =	665.929878	
5203	5203				
201		1.120000 x	290.000000 =	324.800000	
251		12.000000 x	.775000 =	9.300000	
003		16.000000 x	20.419486 =	326.711776	
002		8.000000 x	17.312112 =	138.496896	

			T.E =	799.308672	
5204	5204				
203.2		1.100000 x	370.000000 =	407.000000	
251		12.000000 x	.775000 =	9.300000	
003		14.000000 x	20.419486 =	285.872804	
002		7.000000 x	17.312112 =	121.184784	

			T.E =	823.357588	
5211	5211				
201		1.100000 x	290.000000 =	319.000000	
003		12.000000 x	20.419486 =	245.033832	
002		6.000000 x	17.312112 =	103.872672	
251		14.000000 x	.775000 =	10.850000	

			T.E =	678.756504	

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
251		14.000000 x	.775000 =	10.850000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	701.205420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.775000 =	6.200000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	586.879878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.775000 =	.077500	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	

			T.E =	10.207003	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	
251		.100000 x	.775000 =	.077500	

			T.E =	12.033245	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.775000 =	.077500	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	

			T.E =	15.512608	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
251		.100000 x	.775000 =	.077500	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	

			T.E =	10.947003	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	
251		.100000 x	.775000 =	.077500	

			T.E =	14.032608	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
251		.150000 x	.775000 =	.116250	

			T.E =	17.896964	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.775000 =	.116250	
002		.100000 x	17.312112 =	1.731211	
003		.250000 x	20.419486 =	5.104872	

			T.E =	13.612333	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
251		.150000 x	.775000 =	.116250	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	

			T.E =	16.548575	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.775000 =	.155000	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	

			T.E =	20.436688	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
251		.080000 x	.775000 =	.062000	

			T.E =	17.456848	

5237	5237				
203.2		.022000 x	370.000000 =		8.140000
251		.080000 x	.775000 =		.062000
002		.300000 x	17.312112 =		5.193634
003		.350000 x	20.419486 =		7.146820

			T.E =		20.542454
5238	5238				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.775000 =		.077500
003		.350000 x	20.419486 =		7.146820
002		.350000 x	17.312112 =		6.059239

			T.E =		24.383559
5241	5241				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.775000 =		.077500
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056

			T.E =		30.043299
5243	5243				
003		.150000 x	20.419486 =		3.062923

			T.E =		3.062923
5244	5244				
003		.350000 x	20.419486 =		7.146820

			T.E =		7.146820
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	17.312112 =		8.656056
251		.200000 x	.775000 =		.155000

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
251		.100000 x	.775000 =		.077500
002		.600000 x	17.312112 =		10.387267
283		.100000 x	1.093500 =		.109350

			T.E =		

5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
002		.300000 x	17.312112 =	5.193634	
003		.300000 x	20.419486 =	6.125846	
251		.100000 x	.775000 =	.077500	

			T.E =	16.121979	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
245		.110000 x	18.600000 =	2.046000	

			T.E =	116.834995	
5252.2	5252.2				
246		1.100000 x	12.000000 =	13.200000	
246		.110000 x	12.000000 =	1.320000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	108.848995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
249		.110000 x	20.000000 =	2.200000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	

			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
219		.060000 x	3.500000 =	.210000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	

			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.600000 x	.775000 =	.465000	
203.2		.025000 x	370.000000 =	9.250000	

			T.E =	45.700278	

5262	5262			
201		.030000 x	290.000000 =	8.700000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
265		.300000 x	.835300 =	.250590
252		.200000 x	1.900000 =	.380000
203.2		.025000 x	370.000000 =	9.250000
251		.300000 x	.775000 =	.232500
			T.E =	56.544688
5266	5266			
201		.020000 x	290.000000 =	5.800000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
203.2		.015000 x	370.000000 =	5.550000
251		.600000 x	.775000 =	.465000
			T.E =	34.453959
5267	5267			
201		.030000 x	290.000000 =	8.700000
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
265		.300000 x	.835300 =	.250590
252		.300000 x	1.900000 =	.570000
203.2		.015000 x	370.000000 =	5.550000
251		.300000 x	.775000 =	.232500
			T.E =	45.488368
5271	5271			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.600000 x	.775000 =	.465000
203.2		.025000 x	370.000000 =	9.250000
			T.E =	33.220799
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
265		.200000 x	.835300 =	.167060
252		.100000 x	1.900000 =	.190000
203.2		.025000 x	370.000000 =	9.250000
251		.300000 x	.775000 =	.232500
			T.E =	43.211679

5273	5273				
201		.016000 x	290.000000 =	4.640000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
203.2		.015000 x	370.000000 =	5.550000	
251		.600000 x	.775000 =	.465000	

			T.E =	29.520799	
5274	5274				
201		.024000 x	290.000000 =	6.960000	
003		.700000 x	20.419486 =	14.293640	
002		.700000 x	17.312112 =	12.118478	
265		.200000 x	.835300 =	.167060	
252		.100000 x	1.900000 =	.190000	
203.2		.015000 x	370.000000 =	5.550000	
251		.300000 x	.775000 =	.232500	

			T.E =	39.511679	
5276	5276				
201		1.080000 x	290.000000 =	313.200000	
003		19.000000 x	20.419486 =	387.970234	
002		19.000000 x	17.312112 =	328.930128	
252		18.000000 x	1.900000 =	34.200000	
251		6.000000 x	.775000 =	4.650000	

			T.E =	1,068.950362	
5277	5277				
203.2		1.080000 x	370.000000 =	399.600000	
251		6.000000 x	.775000 =	4.650000	
002		18.000000 x	17.312112 =	311.618016	
003		18.000000 x	20.419486 =	367.550748	
252		18.000000 x	1.900000 =	34.200000	

			T.E =	1,117.618764	
5279	5279				
201		1.080000 x	290.000000 =	313.200000	
251		12.000000 x	.775000 =	9.300000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	613.255420	

5280	5280				
203.2		1.080000 x	370.000000 =	399.600000	
251		12.000000 x	.775000 =	9.300000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	

			T.E =	699.655420	
5281	5281				
203.2		.014000 x	370.000000 =	5.180000	
002		.250000 x	17.312112 =	4.328028	
251		.040000 x	.775000 =	.031000	

			T.E =	9.539028	
5282	5282				
203.2		.020000 x	370.000000 =	7.400000	
251		.060000 x	.775000 =	.046500	
002		.350000 x	17.312112 =	6.059239	

			T.E =	13.505739	
5283	5283				
203.2		.026000 x	370.000000 =	9.620000	
251		.080000 x	.775000 =	.062000	
002		.400000 x	17.312112 =	6.924845	

			T.E =	16.606845	
5286	5286				
203.2		.008000 x	370.000000 =	2.960000	
003		.120000 x	20.419486 =	2.450338	
251		.030000 x	.775000 =	.023250	
002		.120000 x	17.312112 =	2.077453	

			T.E =	7.511042	
5288	5288				
003		.300000 x	20.419486 =	6.125846	

			T.E =	6.125846	
5289	5289				
003		1.000000 x	20.419486 =	20.419486	

			T.E =	20.419486	

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.200000 x	.775000 =	.155000
220		26.000000 x	.000000 =	.000000

			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.200000 x	.775000 =	.155000
220		26.000000 x	.000000 =	.000000
203.2		.010000 x	370.000000 =	3.700000

			T.E =	
5293	5293			
203.2		.020000 x	370.000000 =	7.400000
251		.150000 x	.775000 =	.116250
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
203.2		.016000 x	370.000000 =	5.920000

			T.E =	28.528889
5294	5294			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
203.2		.022000 x	370.000000 =	8.140000
251		.100000 x	.775000 =	.077500

			T.E =	30.710139
5295	5295			
203.2		.020000 x	370.000000 =	7.400000
251		.050000 x	.775000 =	.038750
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028

			T.E =	16.871650
5301	5301			
226		1.050000 x	13.000000 =	13.650000
251		.250000 x	.775000 =	.193750
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267

			T.E =	36.482709

5302	5302				
227		1.050000 x	13.000000 =	13.650000	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	
251		.200000 x	.775000 =	.155000	

			T.E =	32.670799	
5321	5321				
203.2		.012000 x	370.000000 =	4.440000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
251		.500000 x	.775000 =	.387500	
226		1.050000 x	13.000000 =	13.650000	

			T.E =	52.435938	
5322	5322				
203.2		.012000 x	370.000000 =	4.440000	
227		1.050000 x	13.000000 =	13.650000	
251		.450000 x	.775000 =	.348750	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	48.624028	
5323	5323				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
228		1.050000 x	35.000000 =	36.750000	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.775000 =	.387500	

			T.E =	79.309098	
5324	5324				
203.2		.012000 x	370.000000 =	4.440000	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.775000 =	.387500	

			T.E =		
5325	5325				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.775000 =	.387500	
230		1.050000 x	.000000 =	.000000	

			T.E =		

5326	5326				
203.2		.012000 x	370.000000 =	4.440000	
231		1.050000 x	22.000000 =	23.100000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.775000 =	.387500	

			T.E =	65.659098	
5341	5341				
203.2		.037000 x	370.000000 =	13.690000	
003		1.100000 x	20.419486 =	22.461435	
002		1.100000 x	17.312112 =	19.043323	
251		.600000 x	.775000 =	.465000	
232		1.050000 x	45.000000 =	47.250000	

			T.E =	102.909758	
5342	5342				
203.2		.037000 x	370.000000 =	13.690000	
003		1.700000 x	20.419486 =	34.713126	
002		1.700000 x	17.312112 =	29.430590	
251		.600000 x	.775000 =	.465000	
232		1.100000 x	45.000000 =	49.500000	

			T.E =	127.798717	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
233		.084000 x	21.300000 =	1.789200	

			T.E =	54.339478	
5351	5351				
035		.200000 x	.091000 =	.018200	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.775000 =	.077500	
236		1.060000 x	2.000000 =	2.120000	

			T.E =	9.762020	
5352	5352				
035		.200000 x	.091000 =	.018200	
003		.200000 x	20.419486 =	4.083897	
237		1.060000 x	1.100000 =	1.166000	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.775000 =	.077500	

			T.E =	8.808020	

5353	5353			
035		.200000 x	.091000 =	.018200
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.775000 =	.077500
003		.200000 x	20.419486 =	4.083897
238		1.060000 x	2.600000 =	2.756000

			T.E =	10.398020
5354	5354			
035		.200000 x	.091000 =	.018200
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.775000 =	.077500
239		1.060000 x	.000000 =	.000000

			T.E =	
5355	5355			
035		.200000 x	.091000 =	.018200
251		.100000 x	.775000 =	.077500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
240		1.060000 x	1.400000 =	1.484000

			T.E =	9.126020
5356	5356			
035		.200000 x	.091000 =	.018200
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.775000 =	.077500
241		1.060000 x	.000000 =	.000000

			T.E =	
5421	5421			
205		.055000 x	450.000000 =	24.750000
003		3.500000 x	20.419486 =	71.468201
1471		1.000000 x	5.260223 =	5.260223
002		3.500000 x	17.312112 =	60.592392

			T.E =	162.070816
5422	5422			
205		.035000 x	450.000000 =	15.750000
1472		1.000000 x	6.347177 =	6.347177
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336

			T.E =	135.291971

5426	5426			
205		.095000 x	450.000000 =	42.750000
1473		1.000000 x	10.859400 =	10.859400
1471		1.000000 x	5.260223 =	5.260223
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916

			T.E =	285.259211
5427	5427			
205		.105000 x	450.000000 =	47.250000
1474		1.000000 x	13.178969 =	13.178969
002		7.000000 x	17.312112 =	121.184784
1471		1.000000 x	5.260223 =	5.260223
003		7.000000 x	20.419486 =	142.936402

			T.E =	329.810378
5428	5428			
205		.075000 x	450.000000 =	33.750000
002		5.500000 x	17.312112 =	95.216616
1472		1.000000 x	6.347177 =	6.347177
1474		1.000000 x	13.178969 =	13.178969
003		5.500000 x	20.419486 =	112.307173

			T.E =	260.799935
5431	5431			
205		.070000 x	450.000000 =	31.500000
1475		1.000000 x	37.480488 =	37.480488
1471		1.000000 x	5.260223 =	5.260223
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
208		.030000 x	1,450.000000 =	43.500000

			T.E =	381.861897
5432	5432			
205		.070000 x	450.000000 =	31.500000
003		5.000000 x	20.419486 =	102.097430
1475		.800000 x	37.480488 =	29.984390
1471		1.000000 x	5.260223 =	5.260223
002		5.000000 x	17.312112 =	86.560560
380		1.000000 x	16.150000 =	16.150000

			T.E =	271.552603

5436	5436				
205		.050000 x	450.000000 =	22.500000	
003		4.500000 x	20.419486 =	91.887687	
1476		1.000000 x	2.789630 =	2.789630	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	195.081821	
5437	5437				
205		.065000 x	450.000000 =	29.250000	
1476		1.000000 x	2.789630 =	2.789630	
003		5.000000 x	20.419486 =	102.097430	
002		5.000000 x	17.312112 =	86.560560	

			T.E =	220.697620	
5438	5438				
205		.050000 x	450.000000 =	22.500000	
1476		1.000000 x	2.789630 =	2.789630	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	176.216022	
5441.1	5441.1				
205		.065000 x	450.000000 =	29.250000	
222.3		.004000 x	.000000 =	.000000	
003		4.500000 x	20.419486 =	91.887687	
1476		1.000000 x	2.789630 =	2.789630	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	207.831821	
5441.2	5441.2				
205		.065000 x	450.000000 =	29.250000	
223.3		.004000 x	1,500.000000 =	6.000000	
002		4.500000 x	17.312112 =	77.904504	
1476		1.000000 x	2.789630 =	2.789630	
003		4.500000 x	20.419486 =	91.887687	

			T.E =	207.831821	
5441.3	5441.3				
205		.065000 x	450.000000 =	29.250000	
243.1		.550000 x	2.700000 =	1.485000	
1476		1.000000 x	2.789630 =	2.789630	
003		4.500000 x	20.419486 =	91.887687	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	203.316821	

5442.1	5442.1			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	2.789630 =	2.789630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5442.2	5442.2			
205		.080000 x	450.000000 =	36.000000
223.3		.004000 x	1,500.000000 =	6.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	2.789630 =	2.789630
002		5.000000 x	17.312112 =	86.560560

T.E =

233.447620

5442.3	5442.3			
205		.080000 x	450.000000 =	36.000000
243.1		.055000 x	2.700000 =	.148500
1476		1.000000 x	2.789630 =	2.789630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

T.E =

227.596120

5443.1	5443.1			
205		.065000 x	450.000000 =	29.250000
222.3		.004000 x	.000000 =	.000000
1476		1.000000 x	2.789630 =	2.789630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

T.E =

5443.2	5443.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	2.789630 =	2.789630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

188.966022

5443.3	5443.3			
205		.065000 x	450.000000 =	29.250000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	2.789630 =	2.789630
002		4.000000 x	17.312112 =	69.248448
243.1		.550000 x	2.700000 =	1.485000

T.E = 184.451022

5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.789630 =	2.789630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.2		.010000 x	.000000 =	.000000
205		.025000 x	450.000000 =	11.250000

T.E =

5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.789630 =	2.789630
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000
205		.025000 x	450.000000 =	11.250000

T.E = 191.216022

5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
205		.040000 x	450.000000 =	18.000000
1476		1.000000 x	2.789630 =	2.789630
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504

T.E =

5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.789630 =	2.789630
003		4.500000 x	20.419486 =	91.887687
205		.040000 x	450.000000 =	18.000000
002		4.500000 x	17.312112 =	77.904504
223.2		.010000 x	1,700.000000 =	17.000000

T.E = 216.831821

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
002		3.500000 x	17.312112 =	60.592392
1476		1.000000 x	2.789630 =	2.789630
003		3.500000 x	20.419486 =	71.468201
205		.025000 x	450.000000 =	11.250000

T.E =

5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.789630 =	2.789630
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.010000 x	1,700.000000 =	17.000000
205		.025000 x	450.000000 =	11.250000

T.E =

172.350223

5449	5449			
205		.045000 x	450.000000 =	20.250000
003		3.000000 x	20.419486 =	61.258458
1476		1.000000 x	2.789630 =	2.789630
002		3.000000 x	17.312112 =	51.936336
243.5		.850000 x	5.900000 =	5.015000

T.E =

141.249424

5451.1	5451.1			
205		.090000 x	450.000000 =	40.500000
1476		1.000000 x	2.789630 =	2.789630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5451.2	5451.2			
205		.090000 x	450.000000 =	40.500000
1476		1.000000 x	2.789630 =	2.789630
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

237.947620

5451.3	5451.3			
205		.090000 x	450.000000 =	40.500000
243.1		.550000 x	2.700000 =	1.485000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	2.789630 =	2.789630
003		5.000000 x	20.419486 =	102.097430

			T.E =	233.432620
5456	5456			
205		.055000 x	450.000000 =	24.750000
1478		1.000000 x	3.127750 =	3.127750
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

			T.E =	178.804142
5457	5457			
205		.085000 x	450.000000 =	38.250000
1476		1.500000 x	2.789630 =	4.184445
003		7.000000 x	20.419486 =	142.936402
261		2.200000 x	.639200 =	1.406240
002		7.000000 x	17.312112 =	121.184784

			T.E =	307.961871
5461.1	5461.1			
205		.065000 x	450.000000 =	29.250000
1479		1.000000 x	34.467602 =	34.467602
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.010000 x	.000000 =	.000000

			T.E =	
5461.2	5461.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,700.000000 =	17.000000
002		5.500000 x	17.312112 =	95.216616
1479		1.000000 x	34.467602 =	34.467602
003		5.500000 x	20.419486 =	112.307173

			T.E =	288.241391
5462.1	5462.1			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	33.276949 =	33.276949
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616

			T.E =	

5462.2	5462.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,700.000000 =	17.000000
003		5.500000 x	20.419486 =	112.307173
1480		1.000000 x	33.276949 =	33.276949
002		5.500000 x	17.312112 =	95.216616

T.E = 287.050738

5463.1	5463.1			
205		.055000 x	450.000000 =	24.750000
1479		.500000 x	34.467602 =	17.233801
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
222.2		.010000 x	.000000 =	.000000

T.E =

5463.2	5463.2			
205		.055000 x	450.000000 =	24.750000
223.2		.010000 x	1,700.000000 =	17.000000
002		6.000000 x	17.312112 =	103.872672
1479		.500000 x	34.467602 =	17.233801
003		6.000000 x	20.419486 =	122.516916

T.E = 285.373389

5464.1	5464.1			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	34.467602 =	17.233801
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

T.E =

5464.2	5464.2			
205		.070000 x	450.000000 =	31.500000
223.2		.010000 x	1,700.000000 =	17.000000
003		7.000000 x	20.419486 =	142.936402
1479		.500000 x	34.467602 =	17.233801
002		7.000000 x	17.312112 =	121.184784

T.E = 329.854987

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
1476		1.000000 x	2.789630 =	2.789630
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,450.000000 =	43.500000

T.E =

5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
1476		1.000000 x	2.789630 =	2.789630
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
223.2		.005000 x	1,700.000000 =	8.500000
208		.030000 x	1,450.000000 =	43.500000

T.E =

278.963419

5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
1479		.900000 x	34.467602 =	31.020842
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

T.E =

5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,700.000000 =	17.000000
1479		.900000 x	34.467602 =	31.020842

T.E =

245.928832

5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
002		3.500000 x	17.312112 =	60.592392
222.2		.012000 x	.000000 =	.000000
222.2		.000960 x	.000000 =	.000000
003		3.500000 x	20.419486 =	71.468201
203.2		.001040 x	370.000000 =	.384800

T.E =

5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.012000 x	1,700.000000 =	20.400000
223.2		.000960 x	1,700.000000 =	1.632000

			T.E =	159.287393
5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
203.2		.002000 x	370.000000 =	.740000
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000

			T.E =	
5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.000800 x	1,700.000000 =	1.360000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
203.2		.002000 x	370.000000 =	.740000
223.2		.010000 x	1,700.000000 =	17.000000

			T.E =	179.276392
5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
002		4.500000 x	17.312112 =	77.904504
003		4.500000 x	20.419486 =	91.887687
1479		.500000 x	34.467602 =	17.233801

			T.E =	
5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
002		4.500000 x	17.312112 =	77.904504
003		4.500000 x	20.419486 =	91.887687
1479		.500000 x	34.467602 =	17.233801

			T.E =	213.275992

5471	5471				
203.2		.035000 x	370.000000 =		12.950000
251		3.000000 x	.775000 =		2.325000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392

			T.E =		147.335593
5472.1	5472.1				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
251		3.000000 x	.775000 =		2.325000
222.4		.010000 x	.000000 =		.000000

			T.E =		
5472.2	5472.2				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
223.4		.010000 x	1,580.000000 =		15.800000
251		3.000000 x	.775000 =		2.325000

			T.E =		159.805593
5501.1	5501.1				
211		.040000 x	750.000000 =		30.000000
251		.050000 x	.775000 =		.038750
252		.100000 x	1.900000 =		.190000
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280

			T.E =		175.606460
5501.2	5501.2				
212		.040000 x	1,500.000000 =		60.000000
251		.050000 x	.775000 =		.038750
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280
252		.100000 x	1.900000 =		.190000

			T.E =		205.606460
5502	5502				
210		.040000 x	.000000 =		.000000
252		.100000 x	1.900000 =		.190000
002		2.000000 x	17.312112 =		34.624224
003		4.000000 x	20.419486 =		81.677944
251		.050000 x	.775000 =		.038750

			T.E =		

5511.1	5511.1			
211		.020000 x	750.000000 =	15.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	1.900000 =	.190000

			T.E =	108.231734
5511.2	5511.2			
212		.020000 x	1,500.000000 =	30.000000
252		.100000 x	1.900000 =	.190000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379

			T.E =	123.231734
5512	5512			
205		.020000 x	450.000000 =	9.000000
003		3.000000 x	20.419486 =	61.258458
002		1.500000 x	17.312112 =	25.968168
252		.100000 x	1.900000 =	.190000

			T.E =	96.416626
5513.1	5513.1			
211		.020000 x	750.000000 =	15.000000
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
252		.100000 x	1.900000 =	.190000

			T.E =	131.492168
5513.2	5513.2			
212		.020000 x	1,500.000000 =	30.000000
252		.100000 x	1.900000 =	.190000
002		2.000000 x	17.312112 =	34.624224
003		4.000000 x	20.419486 =	81.677944

			T.E =	146.492168
5514	5514			
205		.020000 x	450.000000 =	9.000000
252		.100000 x	1.900000 =	.190000
003		3.800000 x	20.419486 =	77.594047
002		1.800000 x	17.312112 =	31.161802

			T.E =	117.945848

5521	5521			
205		.030000 x	450.000000 =	13.500000
252		.150000 x	1.900000 =	.285000
003		2.000000 x	20.419486 =	40.838972
002		.800000 x	17.312112 =	13.849690

			T.E =	68.473662
5531.1	5531.1			
211		.010000 x	750.000000 =	7.500000
003		2.200000 x	20.419486 =	44.922869
002		.700000 x	17.312112 =	12.118478
252		.020000 x	1.900000 =	.038000

			T.E =	64.579348
5531.2	5531.2			
212		.010000 x	1,500.000000 =	15.000000
252		.020000 x	1.900000 =	.038000
003		2.200000 x	20.419486 =	44.922869
002		.700000 x	17.312112 =	12.118478

			T.E =	72.079348
5531.3	5531.3			
205		.010000 x	450.000000 =	4.500000
252		.020000 x	1.900000 =	.038000
003		2.200000 x	20.419486 =	44.922869
002		.700000 x	17.312112 =	12.118478

			T.E =	61.579348
5532.1	5532.1			
211		.010000 x	750.000000 =	7.500000
252		.020000 x	1.900000 =	.038000
003		3.000000 x	20.419486 =	61.258458
002		1.000000 x	17.312112 =	17.312112

			T.E =	86.108570
5532.2	5532.2			
212		.010000 x	1,500.000000 =	15.000000
003		3.000000 x	20.419486 =	61.258458
002		1.000000 x	17.312112 =	17.312112
252		.020000 x	1.900000 =	.038000

			T.E =	93.608570

5532.3	5532.3			
205		.010000 x	450.000000 =	4.500000
003		3.000000 x	20.419486 =	61.258458
002		1.000000 x	17.312112 =	17.312112
252		.020000 x	1.900000 =	.038000

			T.E =	83.108570
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	20.419486 =	7.146820

			T.E =	8.931820
5601	5601			
203.2		.028000 x	370.000000 =	10.360000
251		4.000000 x	.775000 =	3.100000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280

			T.E =	107.788995
5602	5602			
203.2		.018000 x	370.000000 =	6.660000
003		2.300000 x	20.419486 =	46.964818
002		2.300000 x	17.312112 =	39.817858
251		3.000000 x	.775000 =	2.325000

			T.E =	95.767675
5603	5603			
203.2		.013000 x	370.000000 =	4.810000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
251		2.500000 x	.775000 =	1.937500

			T.E =	82.210696
5604	5604			
243.5		1.100000 x	5.900000 =	6.490000
003		2.200000 x	20.419486 =	44.922869
002		2.200000 x	17.312112 =	38.086646
243.5		.165000 x	5.900000 =	.973500

			T.E =	90.473016

5605	5605				
243.3		1.100000 x	4.500000 =	4.950000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
243.3		.187000 x	4.500000 =	.841500	

			T.E =	81.254696	
5606	5606				
243.2		1.100000 x	3.800000 =	4.180000	
243.2		.220000 x	3.800000 =	.836000	
002		1.800000 x	17.312112 =	31.161802	
003		1.800000 x	20.419486 =	36.755075	

			T.E =	72.932876	
5607	5607				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
242		2.200000 x	1.500000 =	3.300000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
242		.440000 x	1.500000 =	.660000	

			T.E =	104.768995	
5608.1	5608.1				
205		.012000 x	450.000000 =	5.400000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	
205		.002400 x	450.000000 =	1.080000	

			T.E =		
5608.2	5608.2				
205		.012000 x	450.000000 =	5.400000	
223.1		.006000 x	2,100.000000 =	12.600000	
223.1		.001200 x	2,100.000000 =	2.520000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
205		.002400 x	450.000000 =	1.080000	

			T.E =	153.660593	

5611	5611				
205		.060000 x	450.000000 =		27.000000
003		7.000000 x	20.419486 =		142.936402
002		7.000000 x	17.312112 =		121.184784
251		5.000000 x	.775000 =		3.875000

			T.E =		294.996186
5612.1	5612.1				
205		.060000 x	450.000000 =		27.000000
222.1		.006000 x	.000000 =		.000000
003		7.000000 x	20.419486 =		142.936402
002		7.000000 x	17.312112 =		121.184784
251		5.000000 x	.775000 =		3.875000

			T.E =		
5612.2	5612.2				
205		.060000 x	450.000000 =		27.000000
251		5.000000 x	.775000 =		3.875000
223.1		.006000 x	2,100.000000 =		12.600000
003		7.000000 x	20.419486 =		142.936402
002		7.000000 x	17.312112 =		121.184784

			T.E =		307.596186
5613.1	5613.1				
205		.015000 x	450.000000 =		6.750000
222.2		.003000 x	.000000 =		.000000
205		.001500 x	450.000000 =		.675000
002		1.500000 x	17.312112 =		25.968168
003		1.500000 x	20.419486 =		30.629229

			T.E =		
5613.2	5613.2				
205		.015000 x	450.000000 =		6.750000
223.2		.003000 x	1,700.000000 =		5.100000
205		.001500 x	450.000000 =		.675000
003		1.500000 x	20.419486 =		30.629229
002		1.500000 x	17.312112 =		25.968168

			T.E =		69.122397
5614.1	5614.1				
205		.010000 x	450.000000 =		4.500000
205		.001500 x	450.000000 =		.675000
003		1.200000 x	20.419486 =		24.503383
002		1.200000 x	17.312112 =		20.774534
222.2		.002000 x	.000000 =		.000000

			T.E =		

5614.2	5614.2			
205		.010000 x	450.000000 =	4.500000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,700.000000 =	3.400000
205		.001500 x	450.000000 =	.675000

			T.E =	53.852918
5615.1	5615.1			
205		.008000 x	450.000000 =	3.600000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
222.2		.000900 x	.000000 =	.000000
205		.001440 x	450.000000 =	.648000

			T.E =	
5615.2	5615.2			
205		.008000 x	450.000000 =	3.600000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,700.000000 =	1.530000
205		.001440 x	450.000000 =	.648000

			T.E =	43.509598
5616	5616			
205		.003000 x	450.000000 =	1.350000
205		.007500 x	450.000000 =	3.375000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	42.456598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
521		.250000 x	2.390000 =	.597500

			T.E =	42.729098
5619	5619			
205		.001400 x	450.000000 =	.630000
003		.200000 x	20.419486 =	4.083897

			T.E =	4.713897

5620	5620			
203.2		.012000 x	370.000000 =	4.440000
220		4.200000 x	.000000 =	.000000
251		.020000 x	.775000 =	.015500
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846

T.E =

5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.775000 =	12.400000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360

T.E =

5622	5622			
211		1.100000 x	750.000000 =	825.000000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
251		16.000000 x	.775000 =	12.400000

T.E =

1,969.347940

5626	5626			
205		.030000 x	450.000000 =	13.500000
251		1.000000 x	.775000 =	.775000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168

T.E =

70.872397

6101	6101			
267		1.050000 x	.903400 =	.948570
003		.050000 x	20.419486 =	1.020974

T.E =

1.969544

6102	6102			
252		.050000 x	1.900000 =	.095000
003		.060000 x	20.419486 =	1.225169
267		1.030000 x	.903400 =	.930502

T.E =

2.250671

6103	6103			
268		1.050000 x	1.033700 =	1.085385
003		.050000 x	20.419486 =	1.020974

T.E =

2.106359

6104	6104				
252		.050000 x	1.900000 =	.095000	
003		.060000 x	20.419486 =	1.225169	
268		1.030000 x	1.033700 =	1.064711	

			T.E =	2.384880	
6111	6111				
266		1.100000 x	.643000 =	.707300	
003		.150000 x	20.419486 =	3.062923	

			T.E =	3.770223	
6116	6116				
280		1.050000 x	1.000000 =	1.050000	
003		.100000 x	20.419486 =	2.041949	

			T.E =	3.091949	
6117	6117				
281		1.050000 x	5.780000 =	6.069000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	9.131923	
6118	6118				
266		1.150000 x	.643000 =	.739450	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	8.285770	
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	20.419486 =	3.062923	

			T.E =		
6120	6120				
289		1.050000 x	.769200 =	.807660	
003		.100000 x	20.419486 =	2.041949	

			T.E =	2.849609	
6121	6121				
266		1.100000 x	.643000 =	.707300	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.253620	

6122	6122				
265		1.050000 x	.835300 =	.877065	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.960962	
6123	6123				
265		.900000 x	.835300 =	.751770	
265		.090000 x	.835300 =	.075177	
003		.150000 x	20.419486 =	3.062923	
002		.150000 x	17.312112 =	2.596817	
266		.010000 x	.643000 =	.006430	
266		.100000 x	.643000 =	.064300	

			T.E =	6.557417	
6126	6126				
265		1.250000 x	.835300 =	1.044125	
003		.200000 x	20.419486 =	4.083897	
003		.200000 x	20.419486 =	4.083897	

			T.E =	9.211919	
6127	6127				
290		4.800000 x	3.300000 =	15.840000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	46.025278	
6128	6128				
290		1.200000 x	3.300000 =	3.960000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.506320	
6201	6201				
264		1.400000 x	1.133900 =	1.587460	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

			T.E =	11.020360	
6202	6202				
264		1.300000 x	1.133900 =	1.474070	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	9.020390	

6203	6203				
282		1.200000 x	.970800 =		1.164960
002		.350000 x	17.312112 =		6.059239
003		.350000 x	20.419486 =		7.146820

			T.E =		14.371019
6204	6204				
282		1.300000 x	.970800 =		1.262040
002		.400000 x	17.312112 =		6.924845
003		.400000 x	20.419486 =		8.167794

			T.E =		16.354679
6205	6205				
277		1.250000 x	1.016500 =		1.270625
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056

			T.E =		20.136424
6221	6221				
265		1.150000 x	.835300 =		.960595
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897

			T.E =		8.506915
6222	6222				
265		1.200000 x	.835300 =		1.002360
002		.350000 x	17.312112 =		6.059239
003		.350000 x	20.419486 =		7.146820

			T.E =		14.208419
6223	6223				
265		1.250000 x	.835300 =		1.044125
002		.500000 x	17.312112 =		8.656056
003		.500000 x	20.419486 =		10.209743

			T.E =		19.909924
6224	6224				
271		.720000 x	1.003300 =		.722376
003		.200000 x	20.419486 =		4.083897
002		.200000 x	17.312112 =		3.462422
282		.480000 x	.970800 =		.465984

			T.E =		8.734680

6225	6225				
271		.720000 x	1.003300 =	.722376	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
282		.480000 x	.970800 =	.465984	

			T.E =		10.621260
6226	6226				
265		1.200000 x	.835300 =	1.002360	
003		.700000 x	20.419486 =	14.293640	
002		.700000 x	17.312112 =	12.118478	

			T.E =		27.414479
6227	6227				
265		1.250000 x	.835300 =	1.044125	
003		.850000 x	20.419486 =	17.356563	
002		.850000 x	17.312112 =	14.715295	

			T.E =		33.115983
6228	6228				
282		1.250000 x	.970800 =	1.213500	
003		.400000 x	20.419486 =	8.167794	
002		.400000 x	17.312112 =	6.924845	

			T.E =		16.306139
6229	6229				
282		1.250000 x	.970800 =	1.213500	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	

			T.E =		18.192719
6230	6230				
277		1.100000 x	1.016500 =	1.118150	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =		19.983949
6231	6231				
265		1.150000 x	.835300 =	.960595	
002		.250000 x	17.312112 =	4.328028	
003		.250000 x	20.419486 =	5.104872	

			T.E =		10.393495

6232	6232			
265		1.150000 x	.835300 =	.960595
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794

			T.E =	16.053234
6236	6236			
253		.500000 x	2.400000 =	1.200000
266		2.000000 x	.643000 =	1.286000
386		.350000 x	28.630000 =	10.020500
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
565.3		.350000 x	3.450000 =	1.207500
392		.350000 x	24.930000 =	8.725500
390		2.100000 x	1.500000 =	3.150000
388		.350000 x	48.870000 =	17.104500
272		1.500000 x	.901300 =	1.351950
276		5.850000 x	.812400 =	4.752540

			T.E =	116.715366
6237	6237			
253		.850000 x	2.400000 =	2.040000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.150000 =	1.802500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
266		2.100000 x	.643000 =	1.350300
272		5.000000 x	.901300 =	4.506500
260		9.500000 x	.583300 =	5.541350

			T.E =	202.017542
6238	6238			
253		.400000 x	2.400000 =	.960000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
265		6.000000 x	.835300 =	5.011800
266		13.000000 x	.643000 =	8.359000

			T.E =	202.988790
6239	6239			
277		1.100000 x	1.016500 =	1.118150
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634

			T.E =	12.437629

6301	6301			
266		1.250000 x	.643000 =	.803750
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845

			T.E =	15.896389
6302	6302			
266		9.000000 x	.643000 =	5.787000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	137.847593
6401	6401			
265		1.150000 x	.835300 =	.960595
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897

			T.E =	8.506915
6402	6402			
265		1.200000 x	.835300 =	1.002360
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846

			T.E =	12.321839
6403	6403			
265		1.250000 x	.835300 =	1.044125
003		.350000 x	20.419486 =	7.146820
002		.350000 x	17.312112 =	6.059239

			T.E =	14.250184
6406	6406			
265		1.200000 x	.835300 =	1.002360
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692

			T.E =	23.641319
6407	6407			
265		1.250000 x	.835300 =	1.044125
002		.700000 x	17.312112 =	12.118478
003		.700000 x	20.419486 =	14.293640

			T.E =	27.456244

6411	6411				
565.3		1.650000 x	3.450000 =	5.692500	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	18.898559	
6412	6412				
565.5		1.550000 x	5.150000 =	7.982500	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	

			T.E =	24.961719	
6413	6413				
565.6		1.450000 x	7.100000 =	10.295000	
002		.550000 x	17.312112 =	9.521662	
003		.550000 x	20.419486 =	11.230717	

			T.E =	31.047379	
6416	6416				
566.3		1.600000 x	4.600000 =	7.360000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	20.566059	
6417	6417				
566.5		1.500000 x	7.050000 =	10.575000	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	

			T.E =	27.554219	
6418	6418				
566.6		1.400000 x	9.400000 =	13.160000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	

			T.E =	33.912379	
6421	6421				
565.3		1.050000 x	3.450000 =	3.622500	
003		.400000 x	20.419486 =	8.167794	

			T.E =	11.790294	

6422	6422				
565.5		1.050000 x	5.150000 =	5.407500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	15.617243	
6423	6423				
565.6		1.050000 x	7.100000 =	7.455000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.706692	
6426	6426				
566.3		1.050000 x	4.600000 =	4.830000	
003		.400000 x	20.419486 =	8.167794	

			T.E =	12.997794	
6427	6427				
566.5		1.050000 x	7.050000 =	7.402500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	17.612243	
6428	6428				
566.6		1.050000 x	9.400000 =	9.870000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	22.121692	
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	7.022923	
6432	6432				
251		.100000 x	.775000 =	.077500	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
279		1.080000 x	3.720000 =	4.017600	

			T.E =	13.528000	
6441	6441				
266		1.100000 x	.643000 =	.707300	
002		.100000 x	17.312112 =	1.731211	
003		.100000 x	20.419486 =	2.041949	

			T.E =	4.480460	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.419486 =	.816779

			T.E =	
6446.2	6446.2			
285		1.100000 x	.062000 =	.068200
003		.040000 x	20.419486 =	.816779

			T.E =	.884979
6447	6447			
251		.050000 x	.775000 =	.038750
003		.100000 x	20.419486 =	2.041949
286		1.050000 x	1.696200 =	1.781010
002		.100000 x	17.312112 =	1.731211

			T.E =	5.592920
6448	6448			
251		.050000 x	.775000 =	.038750
288		1.050000 x	1.841000 =	1.933050
003		.100000 x	20.419486 =	2.041949
002		.100000 x	17.312112 =	1.731211

			T.E =	5.744960
6501	6501			
282		3.000000 x	.970800 =	2.912400
295		11.000000 x	6.185800 =	68.043800
296		1.000000 x	12.370900 =	12.370900
002		4.000000 x	17.312112 =	69.248448
003		4.000000 x	20.419486 =	81.677944

			T.E =	234.253492
6502	6502			
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
6501		1.000000 x	234.253492 =	234.253492

			T.E =	290.850889
6503	6503			
002		1.300000 x	17.312112 =	22.505746
6501		.950000 x	234.253492 =	222.540817
003		1.300000 x	20.419486 =	26.545332

			T.E =	271.591895

6504	6504				
002		1.200000 x	17.312112 =	20.774534	
6501		.910000 x	234.253492 =	213.170678	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	258.448595	
6505	6505				
002		1.000000 x	17.312112 =	17.312112	
6501		.870000 x	234.253492 =	203.800538	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	241.532136	
6506	6506				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		.810000 x	234.253492 =	189.745329	

			T.E =	227.476927	
6507	6507				
002		.900000 x	17.312112 =	15.580901	
003		.900000 x	20.419486 =	18.377537	
6501		.920000 x	234.253492 =	215.513213	

			T.E =	249.471651	
6508	6508				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.030000 x	234.253492 =	241.281097	

			T.E =	290.332174	
6509	6509				
002		1.000000 x	17.312112 =	17.312112	
6501		1.010000 x	234.253492 =	236.596027	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	274.327625	
6510	6510				
002		1.200000 x	17.312112 =	20.774534	
6501		1.080000 x	234.253492 =	252.993771	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	298.271689	

6511	6511				
002		1.500000 x	17.312112 =	25.968168	
6501		.920000 x	234.253492 =	215.513213	
003		1.500000 x	20.419486 =	30.629229	

			T.E =	272.110610	
6512	6512				
002		1.400000 x	17.312112 =	24.236957	
003		1.400000 x	20.419486 =	28.587280	
6501		.820000 x	234.253492 =	192.087863	

			T.E =	244.912101	
6513	6513				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.780000 x	234.253492 =	182.717724	

			T.E =	231.768801	
6514	6514				
002		1.200000 x	17.312112 =	20.774534	
6501		.760000 x	234.253492 =	178.032654	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	223.310572	
6515	6515				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		.800000 x	234.253492 =	187.402794	

			T.E =	225.134392	
6516	6516				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.220000 x	234.253492 =	285.789260	

			T.E =	334.840338	
6517	6517				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.120000 x	234.253492 =	262.363911	

			T.E =	307.641829	

6518	6518			
002		1.100000 x	17.312112 =	19.043323
6501		.670000 x	234.253492 =	156.949840
003		1.100000 x	20.419486 =	22.461435

			T.E =	198.454597
6519	6519			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.280000 x	234.253492 =	299.844470

			T.E =	348.895547
6520	6520			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.120000 x	234.253492 =	262.363911

			T.E =	307.641829
6521	6521			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.210000 x	234.253492 =	283.446725

			T.E =	332.497803
6522	6522			
002		1.200000 x	17.312112 =	20.774534
6501		1.190000 x	234.253492 =	278.761655
003		1.200000 x	20.419486 =	24.503383

			T.E =	324.039573
6523	6523			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.280000 x	234.253492 =	299.844470

			T.E =	345.122387
6524	6524			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.800000 x	234.253492 =	187.402794

			T.E =	232.680711

6525	6525				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.040000 x	234.253492 =	243.623632	

			T.E =	288.901549	
6526	6526				
002		1.300000 x	17.312112 =	22.505746	
6501		.900000 x	234.253492 =	210.828143	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	259.879220	
6527	6527				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.120000 x	234.253492 =	262.363911	

			T.E =	311.414988	
6528	6528				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.840000 x	234.253492 =	196.772933	

			T.E =	242.050851	
6529	6529				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.080000 x	234.253492 =	252.993771	

			T.E =	298.271689	
6530	6530				
002		1.000000 x	17.312112 =	17.312112	
6501		.710000 x	234.253492 =	166.319979	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	204.051577	
6531	6531				
002		.600000 x	17.312112 =	10.387267	
6501		.480000 x	234.253492 =	112.441676	
003		.600000 x	20.419486 =	12.251692	

			T.E =	135.080635	

6532	6532				
294		6.000000 x	3.518600 =	21.111600	
296		1.000000 x	12.370900 =	12.370900	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
294		.300000 x	3.518600 =	1.055580	

			T.E =	128.867075	
6541	6541				
282		.350000 x	.970800 =	.339780	
295		1.050000 x	6.185800 =	6.495090	
296		.120000 x	12.370900 =	1.484508	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =	27.185177	
6542	6542				
295		1.050000 x	6.185800 =	6.495090	
296		.100000 x	12.370900 =	1.237090	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	37.917458	
6543	6543				
295		.400000 x	6.185800 =	2.474320	
296		.130000 x	12.370900 =	1.608217	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.166434	
7101	7101				
201		.000500 x	290.000000 =	.145000	
002		.500000 x	17.312112 =	8.656056	
1445		.010000 x	61.946500 =	.619465	
003		.850000 x	20.419486 =	17.356563	

			T.E =	26.777084	
7102	7102				
201		.000500 x	290.000000 =	.145000	
003		.700000 x	20.419486 =	14.293640	
1445		.010000 x	61.946500 =	.619465	
002		.400000 x	17.312112 =	6.924845	

			T.E =	21.982950	

7103	7103				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	20.419486 =	12.251692	
002		.300000 x	17.312112 =	5.193634	
1445		.004000 x	61.946500 =	.247786	

			T.E =	17.838111	
7104	7104				
201		.000500 x	290.000000 =	.145000	
002		.600000 x	17.312112 =	10.387267	
003		1.000000 x	20.419486 =	20.419486	
1445		.008000 x	61.946500 =	.495572	

			T.E =	31.447325	
7111	7111				
201		.000500 x	290.000000 =	.145000	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.741598 =	4.722479	
003		.600000 x	20.419486 =	12.251692	

			T.E =	17.909302	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.616750 =	1.123652	
003		.650000 x	20.419486 =	13.272666	
001		.350000 x	15.741598 =	5.509559	

			T.E =	20.050877	
7121	7121				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1445		.027000 x	61.946500 =	1.672556	
003		.800000 x	20.419486 =	16.335589	

			T.E =	22.875624	
7122	7122				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1444		.027000 x	76.007500 =	2.052203	
003		.800000 x	20.419486 =	16.335589	

			T.E =	23.255271	

7123	7123				
201		.000500 x	290.000000 =	.145000	
1462		.015000 x	85.411250 =	1.281169	
1446		.006000 x	52.880500 =	.317283	
001		.300000 x	15.741598 =	4.722479	
1445		.006000 x	61.946500 =	.371679	
003		.900000 x	20.419486 =	18.377537	

			T.E =	25.215148	
7124.1	7124.1				
201		.000500 x	290.000000 =	.145000	
1465		.015000 x	91.830150 =	1.377452	
1445		.012000 x	61.946500 =	.743358	
003		.900000 x	20.419486 =	18.377537	
001		.300000 x	15.741598 =	4.722479	

			T.E =	25.365827	
7124.2	7124.2				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1445		.012000 x	61.946500 =	.743358	
1466		.015000 x	89.893950 =	1.348409	
003		.900000 x	20.419486 =	18.377537	

			T.E =	25.336784	
7124.3	7124.3				
201		.000500 x	290.000000 =	.145000	
1467		.015000 x	85.376150 =	1.280642	
1445		.012000 x	61.946500 =	.743358	
001		.300000 x	15.741598 =	4.722479	
003		.900000 x	20.419486 =	18.377537	

			T.E =	25.269017	
7131	7131				
201		.000500 x	290.000000 =	.145000	
1413		.021000 x	29.264100 =	.614546	
1426		.006000 x	152.456250 =	.914738	
001		.300000 x	15.741598 =	4.722479	
003		.600000 x	20.419486 =	12.251692	

			T.E =	18.648455	

7132	7132				
201		.000500 x	290.000000 =	.145000	
1427		.006000 x	163.304700 =	.979828	
1418		.021000 x	41.616750 =	.873952	
003		.650000 x	20.419486 =	13.272666	
001		.350000 x	15.741598 =	5.509559	

			T.E =	20.781005	
7133	7133				
201		.000500 x	290.000000 =	.145000	
1463		.015000 x	72.487750 =	1.087316	
001		.350000 x	15.741598 =	5.509559	
003		.600000 x	20.419486 =	12.251692	
1427		.006000 x	163.304700 =	.979828	
1418		.006000 x	41.616750 =	.249701	

			T.E =	20.223096	
7134	7134				
201		.000500 x	290.000000 =	.145000	
1464		.015000 x	55.101600 =	.826524	
1427		.006000 x	163.304700 =	.979828	
001		.350000 x	15.741598 =	5.509559	
1418		.006000 x	41.616750 =	.249701	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.962304	
7136	7136				
201		.000500 x	290.000000 =	.145000	
001		.250000 x	15.741598 =	3.935400	
1418		.017000 x	41.616750 =	.707485	
003		.400000 x	20.419486 =	8.167794	

			T.E =	12.955679	
7138	7138				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.616750 =	1.123652	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	

			T.E =	22.326720	
7141	7141				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.946500 =	1.672556	
001		.400000 x	15.741598 =	6.296639	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	28.533681	

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666

T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666

T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
003		.600000 x	20.419486 =	12.251692
001		.450000 x	15.741598 =	7.083719

T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.450000 x	15.741598 =	7.083719
003		.600000 x	20.419486 =	12.251692
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849

T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
001		.350000 x	15.741598 =	5.509559
1418		.014000 x	41.616750 =	.582635
003		.650000 x	20.419486 =	13.272666

T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
1427		.007000 x	163.304700 =	1.143133
001		.350000 x	15.741598 =	5.509559
1418		.007000 x	41.616750 =	.291317
1422		.016000 x	.000000 =	.000000
003		.650000 x	20.419486 =	13.272666

T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.014000 x	59.035900 =	.826503
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	59.035900 =	.413251
1426		.007000 x	152.456250 =	1.067194
001		.450000 x	15.741598 =	7.083719
003		.700000 x	20.419486 =	14.293640

T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1445		.022000 x	61.946500 =	1.362823
1453		.020000 x	187.752750 =	3.755055
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E = 75.165394

7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E =

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	211.557750 =	4.231155
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E = 75.641494

7164	7164			
201		.000800 x	290.000000 =	.232000
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
001		.600000 x	15.741598 =	9.444959
002		1.600000 x	17.312112 =	27.699379

T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
002		1.600000 x	17.312112 =	27.699379
1459		.020000 x	211.557750 =	4.231155
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
001		.600000 x	15.741598 =	9.444959

T.E = 75.641494

7166	7166			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
1445		.022000 x	61.946500 =	1.362823
1453		.017000 x	187.752750 =	3.191797
002		1.200000 x	17.312112 =	20.774534

T.E = 57.935336

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
1454		.017000 x	211.557750 =	3.596482
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799

			T.E =	58.340021
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
1459		.017000 x	211.557750 =	3.596482
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383

			T.E =	58.340021
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160

			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229

			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435

			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537

7179	7179			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743
7181	7181			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
7206	7206			
142		26.000000 x	.350000 =	9.100000
1412		.040000 x	27.931800 =	1.117272
003		.600000 x	20.419486 =	12.251692
002		.300000 x	17.312112 =	5.193634

			T.E =	27.662597
7207	7207			
142		26.000000 x	.350000 =	9.100000
002		.250000 x	17.312112 =	4.328028
003		.500000 x	20.419486 =	10.209743
1412		.020000 x	27.931800 =	.558636

			T.E =	24.196407
7208	7208			
142		26.000000 x	.350000 =	9.100000
002		.200000 x	17.312112 =	3.462422
1412		.025000 x	27.931800 =	.698295
003		.400000 x	20.419486 =	8.167794

			T.E =	21.428512
7209	7209			
142		26.000000 x	.350000 =	9.100000
002		.150000 x	17.312112 =	2.596817
1412		.005000 x	27.931800 =	.139659
003		.300000 x	20.419486 =	6.125846

			T.E =	17.962322
7211	7211			
146		15.000000 x	.380000 =	5.700000
1445		.001000 x	61.946500 =	.061947
003		.400000 x	20.419486 =	8.167794
002		.200000 x	17.312112 =	3.462422
283		.075000 x	1.093500 =	.082013

			T.E =	17.474176

7221	7221				
203.2		.001500 x	370.000000 =	.555000	
003		.200000 x	20.419486 =	4.083897	
254		.020000 x	3.058000 =	.061160	
492		.200000 x	.540000 =	.108000	
506		1.150000 x	1.290700 =	1.484305	
002		.150000 x	17.312112 =	2.596817	

			T.E =	8.889179	
7222	7222				
254		.050000 x	3.058000 =	.152900	
003		.250000 x	20.419486 =	5.104872	
492		.200000 x	.540000 =	.108000	
002		.150000 x	17.312112 =	2.596817	
506		1.200000 x	1.290700 =	1.548840	

			T.E =	9.511428	
7223	7223				
254		.050000 x	3.058000 =	.152900	
493		.200000 x	.730000 =	.146000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	
508		1.200000 x	.860000 =	1.032000	

			T.E =	8.877220	
7231	7231				
274		1.200000 x	1.433200 =	1.719840	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
274		.200000 x	1.433200 =	.286640	

			T.E =	11.439380	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
003		1.400000 x	20.419486 =	28.587280	
002		1.400000 x	17.312112 =	24.236957	
001		.200000 x	15.741598 =	3.148320	
495		.500000 x	.000000 =	.000000	

			T.E =		

7242	7242			
297.2		.057000 x	.000000 =	.000000
002		2.800000 x	17.312112 =	48.473914
003		2.800000 x	20.419486 =	57.174561
001		.200000 x	15.741598 =	3.148320
495		1.000000 x	.000000 =	.000000

			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		1.300000 x	.775000 =	1.007500

			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.775000 =	1.007500

			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.775000 =	1.007500

			T.E =	
7244	7244			
251		1.200000 x	.775000 =	.930000
273		1.200000 x	1.162000 =	1.394400
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486

			T.E =	40.055998
7245	7245			
251		.500000 x	.775000 =	.387500
273		1.200000 x	1.162000 =	1.394400
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478

			T.E =	28.194019

7246	7246			
265		.500000 x	.835300 =	.417650
298.1		6.700000 x	5.470000 =	36.649000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	74.798248
7301	7301			
096		1.050000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
1444		.001500 x	76.007500 =	.114011
003		.900000 x	20.419486 =	18.377537
001		.400000 x	15.741598 =	6.296639

			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
003		1.000000 x	20.419486 =	20.419486
1445		.025000 x	61.946500 =	1.548663
1444		.002000 x	76.007500 =	.152015

			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
001		1.000000 x	15.741598 =	15.741598
1444		.001000 x	76.007500 =	.076008
003		2.000000 x	20.419486 =	40.838972

			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
001		.800000 x	15.741598 =	12.593278
1444		.001500 x	76.007500 =	.114011
1445		.025000 x	61.946500 =	1.548663
003		1.600000 x	20.419486 =	32.671178

			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
1445		.004000 x	61.946500 =	.247786
1444		.000200 x	76.007500 =	.015202
003		.300000 x	20.419486 =	6.125846
001		.150000 x	15.741598 =	2.361240

			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1417		.033000 x	40.284450 =	1.329387
001		.600000 x	15.741598 =	9.444959
1445		.005000 x	61.946500 =	.309733
003		2.200000 x	20.419486 =	44.922869

			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
1445		.005000 x	61.946500 =	.309733
001		.500000 x	15.741598 =	7.870799
1417		.033000 x	40.284450 =	1.329387
003		1.100000 x	20.419486 =	22.461435

			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
1417		.022000 x	40.284450 =	.886258
001		.400000 x	15.741598 =	6.296639
1445		.004000 x	61.946500 =	.247786
003		.900000 x	20.419486 =	18.377537

			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
1449		.030000 x	53.460700 =	1.603821
003		2.500000 x	20.419486 =	51.048715
001		.500000 x	15.741598 =	7.870799

			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
001		.100000 x	15.741598 =	1.574160
1449		.004000 x	53.460700 =	.213843
003		.300000 x	20.419486 =	6.125846

			T.E =	10.519528
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.460700 =	1.336518
1444		.002000 x	76.007500 =	.152015
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692

			T.E =	25.497704

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1444		.001500 x	76.007500 =	.114011
001		.300000 x	15.741598 =	4.722479
1449		.025000 x	53.460700 =	1.336518
003		.800000 x	20.419486 =	16.335589

			T.E =	29.753597
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160

			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160

			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
003		1.500000 x	20.419486 =	30.629229
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008

			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.500000 x	20.419486 =	30.629229

			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
1444		.000100 x	76.007500 =	.007601
1449		.002000 x	53.460700 =	.106921
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664

T.E =

7326.1	7326.1			
029		.200000 x	.152800 =	.030560
1449		.020000 x	53.460700 =	1.069214
173		48.000000 x	.255300 =	12.254400
1444		.005000 x	76.007500 =	.380038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799

T.E =

82.863469

7326.2	7326.2			
029		.200000 x	.152800 =	.030560
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799
174		48.000000 x	.000000 =	.000000

T.E =

7327	7327			
029		.200000 x	.152800 =	.030560
175		95.000000 x	.000000 =	.000000
001		.600000 x	15.741598 =	9.444959
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944

T.E =

7328.1	7328.1			
029		.300000 x	.152800 =	.045840
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
171		108.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
001		.700000 x	15.741598 =	11.019119

T.E =

7328.2	7328.2			
029		.300000 x	.152800 =	.045840
172		108.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
001		.700000 x	15.741598 =	11.019119

T.E =

7331	7331			
029		1.500000 x	.152800 =	.229200
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
003		3.500000 x	20.419486 =	71.468201
001		.500000 x	15.741598 =	7.870799
169		54.000000 x	.000000 =	.000000

T.E =

7332	7332			
029		2.000000 x	.152800 =	.305600
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
003		4.500000 x	20.419486 =	91.887687
170		108.000000 x	.000000 =	.000000
001		.800000 x	15.741598 =	12.593278

T.E =

7333	7333			
029		.300000 x	.152800 =	.045840
002		.500000 x	17.312112 =	8.656056
1449		.020000 x	53.460700 =	1.069214
003		2.500000 x	20.419486 =	51.048715
167		1.050000 x	.000000 =	.000000

T.E =

7334	7334			
029		.300000 x	.152800 =	.045840
1449		.020000 x	53.460700 =	1.069214
002		.600000 x	17.312112 =	10.387267
003		3.000000 x	20.419486 =	61.258458
168		1.050000 x	.000000 =	.000000

T.E =

7335	7335				
001		.450000 x	15.741598 =	7.083719	
003		1.000000 x	20.419486 =	20.419486	
1445		.026000 x	61.946500 =	1.610609	
1444		.007000 x	76.007500 =	.532053	

			T.E =	29.645867	
7336	7336				
001		.400000 x	15.741598 =	6.296639	
003		.900000 x	20.419486 =	18.377537	
1445		.022000 x	61.946500 =	1.362823	
1444		.006000 x	76.007500 =	.456045	

			T.E =	26.493045	
7337	7337				
001		.350000 x	15.741598 =	5.509559	
1444		.005000 x	76.007500 =	.380038	
1445		.017000 x	61.946500 =	1.053091	
003		.800000 x	20.419486 =	16.335589	

			T.E =	23.278276	
7338	7338				
026		.500000 x	.099900 =	.049950	
1445		.017000 x	61.946500 =	1.053091	
003		.700000 x	20.419486 =	14.293640	
001		.300000 x	15.741598 =	4.722479	

			T.E =	20.119160	
7340	7340				
289		1.100000 x	.769200 =	.846120	
001		.400000 x	15.741598 =	6.296639	
1445		.026000 x	61.946500 =	1.610609	
1444		.007000 x	76.007500 =	.532053	
003		1.100000 x	20.419486 =	22.461435	

			T.E =	31.746855	
7341	7341				
003		.200000 x	20.419486 =	4.083897	
1441		.003000 x	27.111000 =	.081333	

			T.E =	4.165230	
7346	7346				
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.083897	

7347	7347				
001		.200000 x	15.741598 =	3.148320	
1445		.009000 x	61.946500 =	.557519	
1444		.002000 x	76.007500 =	.152015	
003		.500000 x	20.419486 =	10.209743	

			T.E =	14.067596	
7351	7351				
001		.200000 x	15.741598 =	3.148320	
003		.600000 x	20.419486 =	12.251692	
1444		.009000 x	76.007500 =	.684068	

			T.E =	16.084079	
7352	7352				
001		.200000 x	15.741598 =	3.148320	
003		.700000 x	20.419486 =	14.293640	
1444		.012000 x	76.007500 =	.912090	

			T.E =	18.354050	
7355	7355				
001		.150000 x	15.741598 =	2.361240	
003		.600000 x	20.419486 =	12.251692	
1444		.008000 x	76.007500 =	.608060	

			T.E =	15.220991	
7356	7356				
001		.100000 x	15.741598 =	1.574160	
1444		.007000 x	76.007500 =	.532053	
003		.550000 x	20.419486 =	11.230717	

			T.E =	13.336930	
7357	7357				
001		.050000 x	15.741598 =	.787080	
1444		.006000 x	76.007500 =	.456045	
003		.500000 x	20.419486 =	10.209743	

			T.E =	11.452868	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.099900 =	1.998000	
065		.040000 x	13.610000 =	.544400	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	

			T.E =	36.767838	

7360	7360			
021		.050000 x	2.670000 =	.133500
065		.027000 x	13.610000 =	.367470
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
026		13.000000 x	.099900 =	1.298700

			T.E =	28.211789
7361	7361			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
346.1		30.000000 x	.057200 =	1.716000
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.099900 =	1.398600

			T.E =	49.351642
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
026		14.000000 x	.099900 =	1.398600
065		.015000 x	13.610000 =	.204150
346.1		22.000000 x	.057200 =	1.258400

			T.E =	49.722842
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
026		14.000000 x	.099900 =	1.398600
346.2		22.000000 x	.103600 =	2.279200
065		.015000 x	13.610000 =	.204150

			T.E =	50.743642
7363	7363			
021		.050000 x	2.670000 =	.133500
346.1		35.000000 x	.057200 =	2.002000
026		17.000000 x	.099900 =	1.698300
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
065		.020000 x	13.610000 =	.272200

			T.E =	57.551712

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
346.1		24.000000 x	.057200 =	1.372800
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.099900 =	1.698300

			T.E =	58.062112
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.099900 =	1.698300
065		.020000 x	13.610000 =	.272200
348		11.000000 x	.103600 =	1.139600
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
346.2		24.000000 x	.103600 =	2.486400

			T.E =	59.175712
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.099900 =	.999000
346.1		45.000000 x	.057200 =	2.574000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.880500 =	.528805
002		2.000000 x	17.312112 =	34.624224

			T.E =	100.117987
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.099900 =	.999000
002		2.000000 x	17.312112 =	34.624224
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000

			T.E =	100.813987
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
346.2		30.000000 x	.103600 =	3.108000
026		10.000000 x	.099900 =	.999000

			T.E =	102.205987

7371.1	7371.1						
026	-	14.000000 x	.099900 =	-	1.398600		
029		14.000000 x	.152800 =		2.139200		
7361		1.000000 x	49.351642 =		49.351642		

			T.E =		50.092242		
7371.2	7371.2						
026	-	14.000000 x	.099900 =	-	1.398600		
028		14.000000 x	.000000 =		.000000		
7361		1.000000 x	49.351642 =		49.351642		

			T.E =		50.092242		
7372.1	7372.1						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.1		1.000000 x	49.722842 =		49.722842		
029		14.000000 x	.152800 =		2.139200		

			T.E =		50.463442		
7372.2	7372.2						
026	-	14.000000 x	.099900 =	-	1.398600		
028		14.000000 x	.000000 =		.000000		
7362.1		1.000000 x	49.722842 =		49.722842		

			T.E =		50.463442		
7372.3	7372.3						
026	-	14.000000 x	.099900 =	-	1.398600		
029		14.000000 x	.152800 =		2.139200		
7362.2		1.000000 x	50.743642 =		50.743642		

			T.E =		51.484242		
7372.4	7372.4						
026	-	14.000000 x	.099900 =	-	1.398600		
028		14.000000 x	.000000 =		.000000		
7362.2		1.000000 x	50.743642 =		50.743642		

			T.E =		51.484242		
7373.1	7373.1						
026	-	17.000000 x	.099900 =	-	1.698300		
7363		1.000000 x	57.551712 =		57.551712		
029		17.000000 x	.152800 =		2.597600		

			T.E =		58.451012		

7373.2	7373.2					
026	-	17.000000 x	.099900 =	-	1.698300	
7363		1.000000 x	57.551712 =		57.551712	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
029		17.000000 x	.152800 =		2.597600	

			T.E =		58.961412	
7374.2	7374.2					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
028		17.000000 x	.000000 =		.000000	

			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.099900 =	-	1.698300	
029		17.000000 x	.152800 =		2.597600	
7364.2		1.000000 x	59.175712 =		59.175712	

			T.E =		60.075012	
7374.4	7374.4					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	59.175712 =		59.175712	

			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.099900 =	-	.999000	
7366		1.000000 x	100.117987 =		100.117987	
029		10.000000 x	.152800 =		1.528000	

			T.E =		100.646987	
7376.2	7376.2					
026	-	10.000000 x	.099900 =	-	.999000	
7366		1.000000 x	100.117987 =		100.117987	
028		10.000000 x	.000000 =		.000000	

			T.E =			

7377.1	7377.1				
026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.152800 =		1.528000
7367.1		1.000000 x	100.813987 =		100.813987

			T.E =		101.342987
7377.2	7377.2				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	100.813987 =		100.813987

			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.099900 =	-	.999000
7367.2		1.000000 x	102.205987 =		102.205987
029		10.000000 x	.152800 =		1.528000

			T.E =		102.734987
7377.4	7377.4				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.2		1.000000 x	102.205987 =		102.205987

			T.E =		
7381	7381				
456		.100000 x	1.610000 =		.161000

			T.E =		.161000
7382	7382				
443		.150000 x	1.930000 =		.289500
447		.050000 x	4.393700 =		.219685
003		.300000 x	20.419486 =		6.125846

			T.E =		6.635031
7383	7383				
002		.250000 x	17.312112 =		4.328028
003		.150000 x	20.419486 =		3.062923

			T.E =		7.390951
7384	7384				
003		.500000 x	20.419486 =		10.209743

			T.E =		10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692

			T.E =	12.251692
7387	7387			
261		1.500000 x	.639200 =	.958800
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.351642 =	54.286806

			T.E =	75.665092
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.351642 =	29.610985

			T.E =	80.659700
7389.1.1	7389.1.1			
7371.1		.300000 x	50.092242 =	15.027673

			T.E =	15.027673
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.075012 =	18.022504

			T.E =	18.022504
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.463442 =	15.139033

			T.E =	15.139033
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.484242 =	15.445273

			T.E =	15.445273
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.451012 =	17.535304

			T.E =	17.535304
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.961412 =	17.688424

			T.E =	17.688424
7389.2.1	7389.2.1			
7371.1		.500000 x	50.092242 =	25.046121

			T.E =	25.046121
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.075012 =	30.037506

			T.E =	30.037506

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.463442 =	25.231721

			T.E =	25.231721
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.484242 =	25.742121

			T.E =	25.742121
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.451012 =	29.225506

			T.E =	29.225506
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.961412 =	29.480706

			T.E =	29.480706
7391	7391			
003		.250000 x	20.419486 =	5.104872

			T.E =	5.104872

7392	7392				
298.1		1.081080 x	5.470000 =	5.913508	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.081302	
7393	7393				
294		.347760 x	3.518600 =	1.223628	
003		.300000 x	20.419486 =	6.125846	

			T.E =	7.349474	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	

			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	

			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	

			T.E =	6.644872	

7416	7416			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7417	7417			
003		1.800000 x	20.419486 =	36.755075

			T.E =	36.755075
7418	7418			
003		2.600000 x	20.419486 =	53.090664

			T.E =	53.090664
7419	7419			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7420	7420			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
7421	7421			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7422	7422			
003		.350000 x	20.419486 =	7.146820

			T.E =	7.146820
7431	7431			
332		1.150000 x	88.540000 =	101.821000
1445		.020000 x	61.946500 =	1.238930
003		4.000000 x	20.419486 =	81.677944
1444		.001000 x	76.007500 =	.076008

			T.E =	184.813882
7432	7432			
331		1.150000 x	85.390000 =	98.198500
1445		.020000 x	61.946500 =	1.238930
1444		.001000 x	76.007500 =	.076008
003		4.400000 x	20.419486 =	89.845738

			T.E =	189.359176

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
003		5.100000 x	20.419486 =	104.139379	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	203.652816	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	224.072302	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	193.814279	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.600000 x	20.419486 =	93.929636	

			T.E =	201.982073	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	216.275713	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
003		6.300000 x	20.419486 =	128.642762	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	236.695199	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.500000 x	20.419486 =	91.887687	

			T.E =	235.768125	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	

			T.E =	243.935919	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.600000 x	20.419486 =	114.349122	

			T.E =	258.229559	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.600000 x	20.419486 =	134.768608	

			T.E =	278.649045	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	

			T.E =	256.332919	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	264.500713	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1444		.001000 x	76.007500 =	.076008	
003		6.000000 x	20.419486 =	122.516916	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	278.794354	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
003		7.000000 x	20.419486 =	142.936402	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	299.213840	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1444		.000100 x	76.007500 =	.007601	
1445		.002000 x	61.946500 =	.123893	
003		.915000 x	20.419486 =	18.683830	

			T.E =	28.635173	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.945000 x	20.419486 =	19.296414	

			T.E =	30.101658	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
003		.990000 x	20.419486 =	20.215291	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	

			T.E =	34.603335	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		1.050000 x	20.419486 =	21.440460	

			T.E =	37.068204	

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
003		.488000 x	20.419486 =	9.964709

			T.E =	14.940381
7497	7497			
331		.062500 x	85.390000 =	5.336875
003		.504000 x	20.419486 =	10.291421
1444		.000050 x	76.007500 =	.003800
1445		.001000 x	61.946500 =	.061947

			T.E =	15.694043
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	20.419486 =	10.781489
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800

			T.E =	17.975510
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	20.419486 =	11.434912
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800

			T.E =	19.248784
7501	7501			
7433		1.000000 x	203.652816 =	203.652816

			T.E =	203.652816
7503	7503			
7443		1.000000 x	216.275713 =	216.275713

			T.E =	216.275713
7506	7506			
7453		1.000000 x	258.229559 =	258.229559

			T.E =	258.229559
7508	7508			
7463		1.000000 x	278.794354 =	278.794354

			T.E =	278.794354

7511	7511				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.915000 x	20.419486 =	18.683830	

			T.E =	28.635173	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
003		.945000 x	20.419486 =	19.296414	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	

			T.E =	30.101658	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	215.828500	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	20.419486 =	98.013533	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	197.450963	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	232.535295	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		5.000000 x	20.419486 =	102.097430	

			T.E =	210.073860	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	20.419486 =	106.181327	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	209.241257	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	61.946500 =	1.238930	
003		5.400000 x	20.419486 =	110.265224	

			T.E =	222.179154	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
1445		.020000 x	61.946500 =	1.238930	
003		5.700000 x	20.419486 =	116.391070	

			T.E =	270.384500	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	291.835295	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
1445		.010000 x	61.946500 =	.619465	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	101.726923	
7537	7537				
336		.300000 x	.000000 =	.000000	
1445		.010000 x	61.946500 =	.619465	
003		4.000000 x	20.419486 =	81.677944	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
1445		.010000 x	61.946500 =	.619465	
003		3.700000 x	20.419486 =	75.552098	

			T.E =	137.713863	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
003		4.200000 x	20.419486 =	85.761841	
1445		.010000 x	61.946500 =	.619465	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
338		.350000 x	.000000 =	.000000
1445		.010000 x	61.946500 =	.619465
003		4.800000 x	20.419486 =	98.013533

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.946500 =	1.238930

			T.E =	271.468832
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.946500 =	1.238930

			T.E =	289.650332
7554	7554			
321		1.150000 x	.000000 =	.000000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	61.946500 =	1.238930
003		9.000000 x	20.419486 =	183.775374

			T.E =	312.307804
7556	7556			
323		1.150000 x	126.500000 =	145.475000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930

			T.E =	330.489304

7558	7558				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	20.419486 =	30.629229	
1445		.003000 x	61.946500 =	.185840	

			T.E =	37.646269	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	20.419486 =	30.629229	
1445		.003000 x	61.946500 =	.185840	

			T.E =	37.646269	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	61.946500 =	1.238930	
003		5.200000 x	20.419486 =	106.181327	

			T.E =	209.241257	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	270.384500	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	20.419486 =	110.265224	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	222.179154	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	291.835295	
7565	7565				
003		1.500000 x	20.419486 =	30.629229	

			T.E =	30.629229	
7566	7566				
7561		1.500000 x	209.241257 =	313.861886	

			T.E =	313.861886	

7567	7567			
7562		1.500000 x	270.384500 =	405.576750

			T.E =	405.576750
7568	7568			
7563		1.500000 x	222.179154 =	333.268731

			T.E =	333.268731
7569	7569			
7564		1.500000 x	291.835295 =	437.752943

			T.E =	437.752943
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.1		.030000 x	.000000 =	.000000

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
003		3.000000 x	20.419486 =	61.258458
327.3		.030000 x	196.650000 =	5.899500

			T.E =	263.807958
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	20.419486 =	77.594047

			T.E =	175.792547

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	238.516341	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	20.419486 =	95.971584	

			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	134.257521 =	2.685150	
1445		.005000 x	61.946500 =	.309733	
003		2.300000 x	20.419486 =	46.964818	

			T.E =	116.666201	
7601	7601				
401		1.100000 x	12.200000 =	13.420000	
457		.500000 x	.803800 =	.401900	
003		.500000 x	20.419486 =	10.209743	

			T.E =	24.031643	
7602	7602				
403		1.100000 x	14.290000 =	15.719000	
457		.500000 x	.803800 =	.401900	
003		.550000 x	20.419486 =	11.230717	

			T.E =	27.351617	
7603	7603				
406		1.100000 x	17.660000 =	19.426000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	20.419486 =	13.272666	

			T.E =	33.100566	
7604.1	7604.1				
409		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	
457		.500000 x	.803800 =	.401900	

			T.E =	38.849515	

7604.2	7604.2			
410		1.100000 x	28.610000 =	31.471000
003		.750000 x	20.419486 =	15.314615
457		.500000 x	.803800 =	.401900

			T.E =	47.187515
7606	7606			
401		1.100000 x	12.200000 =	13.420000
003		.600000 x	20.419486 =	12.251692

			T.E =	25.671692
7607	7607			
403		1.100000 x	14.290000 =	15.719000
003		.650000 x	20.419486 =	13.272666

			T.E =	28.991666
7608	7608			
406		1.100000 x	17.660000 =	19.426000
003		.750000 x	20.419486 =	15.314615

			T.E =	34.740615
7609.1	7609.1			
409		1.100000 x	21.030000 =	23.133000
003		.850000 x	20.419486 =	17.356563

			T.E =	40.489563
7609.2	7609.2			
410		1.100000 x	28.610000 =	31.471000
003		.850000 x	20.419486 =	17.356563

			T.E =	48.827563
7611	7611			
411		1.100000 x	26.710000 =	29.381000
457		.500000 x	.803800 =	.401900
003		.500000 x	20.419486 =	10.209743

			T.E =	39.992643
7612	7612			
412		1.100000 x	28.830000 =	31.713000
003		.550000 x	20.419486 =	11.230717
457		.500000 x	.803800 =	.401900

			T.E =	43.345617

7613	7613				
411		1.100000 x	26.710000 =	29.381000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	41.632692	
7614	7614				
412		1.100000 x	28.830000 =	31.713000	
003		.650000 x	20.419486 =	13.272666	

			T.E =	44.985666	
7616	7616				
414		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.803800 =	.401900	
003		.600000 x	20.419486 =	12.251692	

			T.E =	35.786592	
7617	7617				
415		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	20.419486 =	13.272666	

			T.E =	36.807566	
7618	7618				
414		1.100000 x	21.030000 =	23.133000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	37.426640	
7619	7619				
415		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	

			T.E =	38.447615	
7621	7621				
418		1.100000 x	29.450000 =	32.395000	
457		.800000 x	.803800 =	.643040	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	57.541423	
7622	7622				
419		1.100000 x	29.450000 =	32.395000	
003		1.400000 x	20.419486 =	28.587280	
457		.800000 x	.803800 =	.643040	

			T.E =	61.625320	

7626.1	7626.1			
298.2		18.000000 x	4.700000 =	84.600000
421		1.000000 x	97.840000 =	97.840000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402

			T.E =	446.561186
7626.2	7626.2			
298.2		18.000000 x	4.700000 =	84.600000
422		1.000000 x	134.470000 =	134.470000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

			T.E =	483.191186
7627.1	7627.1			
298.2		16.000000 x	4.700000 =	75.200000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
421		1.000000 x	97.840000 =	97.840000

			T.E =	399.429588
7627.2	7627.2			
298.2		16.000000 x	4.700000 =	75.200000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
422		1.000000 x	134.470000 =	134.470000

			T.E =	436.059588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169

			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559

			T.E =	7.562559

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	20.419486 =	2.041949

			T.E =	10.269949
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169

			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169

			T.E =	
7701	7701			
024		.001500 x	50.000000 =	.075000
002		.050000 x	17.312112 =	.865606
003		.120000 x	20.419486 =	2.450338

			T.E =	3.390944
7702	7702			
024		.001800 x	50.000000 =	.090000
003		.080000 x	20.419486 =	1.633559
002		.050000 x	17.312112 =	.865606

			T.E =	2.589164
7706	7706			
024		.002000 x	50.000000 =	.100000
003		.150000 x	20.419486 =	3.062923
002		.080000 x	17.312112 =	1.384969

			T.E =	4.547892
7707	7707			
024		.002300 x	50.000000 =	.115000
003		.090000 x	20.419486 =	1.837754
002		.100000 x	17.312112 =	1.731211

			T.E =	3.683965

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	20.419486 =	3.675507
002		.120000 x	17.312112 =	2.077453

			T.E =	5.877961
7709	7709			
024		.002800 x	50.000000 =	.140000
002		.150000 x	17.312112 =	2.596817
003		.120000 x	20.419486 =	2.450338

			T.E =	5.187155
7711	7711			
002		.050000 x	17.312112 =	.865606
1485		.200000 x	.832359 =	.166472
003		.200000 x	20.419486 =	4.083897

			T.E =	5.115975
7712	7712			
002		.080000 x	17.312112 =	1.384969
003		.250000 x	20.419486 =	5.104872
1485		.250000 x	.832359 =	.208090

			T.E =	6.697930
7713	7713			
002		.160000 x	17.312112 =	2.769938
1485		.280000 x	.832359 =	.233061
003		.300000 x	20.419486 =	6.125846

			T.E =	9.128844
7720	7720			
443		.080000 x	1.930000 =	.154400
002		.100000 x	17.312112 =	1.731211
1485		.200000 x	.832359 =	.166472
003		.300000 x	20.419486 =	6.125846

			T.E =	8.177929
7721	7721			
002		.070000 x	17.312112 =	1.211848
1485		.200000 x	.832359 =	.166472
003		.200000 x	20.419486 =	4.083897

			T.E =	5.462217

7722.1.1	7722.1.1			
7720		.300000 x	8.177929 =	2.453379

			T.E =	2.453379
7722.1.2	7722.1.2			
7721		.300000 x	5.462217 =	1.638665

			T.E =	1.638665
7722.2.1	7722.2.1			
7720		.400000 x	8.177929 =	3.271172

			T.E =	3.271172
7722.2.2	7722.2.2			
7721		.400000 x	5.462217 =	2.184887

			T.E =	2.184887
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817

			T.E =	8.931688
7735	7735			
441		.350000 x	.075500 =	.026425
444		.150000 x	2.143200 =	.321480
003		.150000 x	20.419486 =	3.062923

			T.E =	3.410828
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535
003		.250000 x	20.419486 =	5.104872
446		.005000 x	2.540000 =	.012700

			T.E =	5.353029
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.871750 =	.174350
003		.300000 x	20.419486 =	6.125846
1488		.600000 x	.763615 =	.458169

			T.E =	6.773465

7738	7738			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.871750 =	.174350
1488		.300000 x	.763615 =	.229085
003		.300000 x	20.419486 =	6.125846

			T.E =	6.544380
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	20.419486 =	3.062923

			T.E =	3.408473
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	20.419486 =	5.104872
1492		.250000 x	2.756980 =	.689245

			T.E =	5.823692
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	20.419486 =	5.104872

			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
003		.200000 x	20.419486 =	4.083897
463		.125000 x	3.970000 =	.496250

			T.E =	4.609722
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.720000 =	.465000

			T.E =	3.557498
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
465		.125000 x	5.870000 =	.733750

			T.E =	3.826248

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
003		.800000 x	20.419486 =	16.335589
1489		.200000 x	.871750 =	.174350

			T.E =	17.228759
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	20.419486 =	3.062923
443		.090000 x	1.930000 =	.173700

			T.E =	3.263048
7747	7747			
441		.350000 x	.075500 =	.026425
443		.170000 x	1.930000 =	.328100
003		.250000 x	20.419486 =	5.104872

			T.E =	5.459397
7748	7748			
443		.090000 x	1.930000 =	.173700
002		.100000 x	17.312112 =	1.731211
445		.030000 x	1.553500 =	.046605
003		.200000 x	20.419486 =	4.083897
450		.060000 x	2.760000 =	.165600

			T.E =	6.201013
7749	7749			
443		.160000 x	1.930000 =	.308800
445		.050000 x	1.553500 =	.077675
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.760000 =	.276000

			T.E =	8.364163
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.488894 =	.186112

			T.E =	3.249035
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.488894 =	.372224

			T.E =	5.477095

7753	7753				
441		1.000000 x	.075500 =	.075500	
443		.080000 x	1.930000 =	.154400	
003		.650000 x	20.419486 =	13.272666	
1491		.200000 x	1.488894 =	.297779	
1490		.090000 x	1.546426 =	.139178	

			T.E =	13.939523	
7754	7754				
441		.800000 x	.075500 =	.060400	
1487		.090000 x	.608206 =	.054739	
003		.800000 x	20.419486 =	16.335589	
1491		.200000 x	1.488894 =	.297779	
1490		.090000 x	1.546426 =	.139178	

			T.E =	16.887684	
7755	7755				
442		.250000 x	.118300 =	.029575	
003		1.000000 x	20.419486 =	20.419486	
1492		.160000 x	2.756980 =	.441117	
1491		.200000 x	1.488894 =	.297779	

			T.E =	21.187957	
7756	7756				
442		.300000 x	.118300 =	.035490	
003		.350000 x	20.419486 =	7.146820	
1492		.300000 x	2.756980 =	.827094	

			T.E =	8.009404	
7761	7761				
441		.650000 x	.075500 =	.049075	
1489		.200000 x	.871750 =	.174350	
1488		.600000 x	.763615 =	.458169	
003		.800000 x	20.419486 =	16.335589	
467		.100000 x	3.380000 =	.338000	
473		.100000 x	2.750000 =	.275000	

			T.E =	17.630183	
7762	7762				
473		.100000 x	2.750000 =	.275000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.358897	

7764	7764			
474		.125000 x	3.770000 =	.471250
003		.100000 x	20.419486 =	2.041949

			T.E =	2.513199
7765	7765			
475		.125000 x	6.230000 =	.778750
003		.200000 x	20.419486 =	4.083897

			T.E =	4.862647
7766	7766			
442		.275000 x	.118300 =	.032533
473		.110000 x	2.750000 =	.302500
1492		.275000 x	2.756980 =	.758170
003		.880000 x	20.419486 =	17.969148

			T.E =	19.062350
7767.1	7767.1			
7755		.150000 x	21.187957 =	3.178194

			T.E =	3.178194
7767.2	7767.2			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486
473		.200000 x	2.750000 =	.550000

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.150000 x	21.440178 =	3.216027

7767.3	7767.3			
7755		.250000 x	21.187957 =	5.296989

			T.E =	5.296989
7767.4	7767.4			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.756980 =	.441117

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.250000 x	21.440178 =	5.360044

7767.5	7767.5			
7755		.350000 x	21.187957 =	7.415785

			T.E =	7.415785
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.350000 x	21.440178 =	7.504062

7767.7	7767.7			
7755		.450000 x	21.187957 =	9.534581

			T.E =	9.534581
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.450000 x	21.440178 =	9.648080

7768	7768			
460		.200000 x	4.250000 =	.850000
003		.450000 x	20.419486 =	9.188769
460		.030000 x	4.250000 =	.127500
002		.450000 x	17.312112 =	7.790450

			T.E =	17.956719
7769	7769			
460		.200000 x	4.250000 =	.850000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
460		.030000 x	4.250000 =	.127500

			T.E =	8.523820
7770	7770			
460		.090000 x	4.250000 =	.382500
003		.150000 x	20.419486 =	3.062923
002		.150000 x	17.312112 =	2.596817
460		.020000 x	4.250000 =	.085000

			T.E =	6.127240

7771	7771				
441		1.000000 x	.075500 =	.075500	
1488		.160000 x	.763615 =	.122178	
1487		.080000 x	.608206 =	.048656	
003		1.300000 x	20.419486 =	26.545332	
473		.100000 x	2.750000 =	.275000	
467		.110000 x	3.380000 =	.371800	

			T.E =	27.438467	
7772	7772				
441		1.000000 x	.075500 =	.075500	
458		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.500000 x	20.419486 =	10.209743	

			T.E =	10.981243	
7773	7773				
441		1.000000 x	.075500 =	.075500	
459		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	13.023192	
7774	7774				
442		.250000 x	.118300 =	.029575	
473		.200000 x	2.750000 =	.550000	
1492		.160000 x	2.756980 =	.441117	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	21.440178	
7785.1	7785.1				
441		.350000 x	.075500 =	.026425	
003		.700000 x	20.419486 =	14.293640	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.366400 =	.283968	

			T.E =		
7785.2	7785.2				
441		.350000 x	.075500 =	.026425	
476		.120000 x	2.366400 =	.283968	
478		.160000 x	2.937600 =	.470016	
003		.700000 x	20.419486 =	14.293640	

			T.E =	15.074049	

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.871750 =	.174350
003		1.000000 x	20.419486 =	20.419486
1488		.600000 x	.763615 =	.458169
477		.110000 x	.000000 =	.000000

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.871750 =	.174350
1488		.600000 x	.763615 =	.458169
003		1.000000 x	20.419486 =	20.419486
478		.110000 x	2.937600 =	.323136

			T.E =	21.401566
7787	7787			
441		1.000000 x	.075500 =	.075500
476		.090000 x	2.366400 =	.212976
1488		.160000 x	.763615 =	.122178
1487		.080000 x	.608206 =	.048656
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
479		1.000000 x	1.815600 =	1.815600
003		.700000 x	20.419486 =	14.293640

			T.E =	16.128115
7791	7791			
441		1.000000 x	.075500 =	.075500
1487		.050000 x	.608206 =	.030410
1491		.200000 x	1.488894 =	.297779
003		.500000 x	20.419486 =	10.209743

			T.E =	10.613432
7792	7792			
482		.150000 x	1.300000 =	.195000
003		.500000 x	20.419486 =	10.209743

			T.E =	10.404743

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	5.766897	
7794	7794				
482		.150000 x	1.300000 =	.195000	
003		.500000 x	20.419486 =	10.209743	

			T.E =	10.404743	
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	17.312112 =	1.038727	

			T.E =	1.183727	
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	17.312112 =	1.211848	

			T.E =	1.385848	
7801	7801				
496		1.200000 x	1.905500 =	2.286600	
003		.150000 x	20.419486 =	3.062923	

			T.E =	5.349523	
7806	7806				
498		1.150000 x	1.011600 =	1.163340	
003		.300000 x	20.419486 =	6.125846	

			T.E =	7.289186	
7807	7807				
499		1.150000 x	1.386800 =	1.594820	
003		.400000 x	20.419486 =	8.167794	

			T.E =	9.762614	
7808	7808				
500		1.150000 x	2.039600 =	2.345540	
003		.600000 x	20.419486 =	12.251692	

			T.E =	14.597232	

7809	7809				
501		1.200000 x	2.763000 =	3.315600	
003		.800000 x	20.419486 =	16.335589	

			T.E =	19.651189	
7810	7810				
502		1.200000 x	3.807000 =	4.568400	
003		.900000 x	20.419486 =	18.377537	

			T.E =	22.945937	
7811	7811				
503		1.200000 x	.905500 =	1.086600	
003		.800000 x	20.419486 =	16.335589	

			T.E =	17.422189	
7812	7812				
504		1.300000 x	1.199100 =	1.558830	
003		.900000 x	20.419486 =	18.377537	

			T.E =	19.936367	
7813	7813				
505		1.000000 x	19.170000 =	19.170000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	31.421692	
7901	7901				
490		1.080000 x	.730000 =	.788400	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.872297	
7902	7902				
527		1.050000 x	5.120000 =	5.376000	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	25.795486	
7903	7903				
528		1.050000 x	6.910000 =	7.255500	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.507192	

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743

			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.290700 =	1.419770
002		.300000 x	17.312112 =	5.193634
003		.150000 x	20.419486 =	3.062923

			T.E =	10.552327
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239

			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845

			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559

			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.552327 =	8.969478

			T.E =	8.969478
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238

			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303

			T.E =	10.038303

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.312112 =	.692484

			T.E =	2.134484
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.312112 =	.865606

			T.E =	3.121306
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.312112 =	.865606

			T.E =	2.081006
7931	7931			
519		1.050000 x	47.670000 =	50.053500
003		1.500000 x	20.419486 =	30.629229

			T.E =	80.682729
7932.1	7932.1			
514		.000000 x	38.800000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	37.340000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	38.800000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	37.340000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743

			T.E =	25.765799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872

			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949

			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.775000 =	.077500

			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160

			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160

			T.E =	9.124160