

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

2ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
008	16.777917
009	.074800
021	2.670000
022	.070000
024	45.000000
026	.099900
027	.119300
029	.151500
032	36.000000
035	.086500
036	.088800
040	.203400
051	15.400000
052	15.400000
053	.085000
054	.085000
055	.090000
056	10.580000
057	10.580000
058	9.090000
061	13.560000
062	13.560000
065	13.610000
066	35.000000
067	45.500000
081	11.010000
101	
102	
111	.075900
112	.083300
113	.570000
114	
116	.086700
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.650000
132	.930000
142	.340000
146	.370000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.256100
181	
201	290.000000
203.2	370.000000

203.4	290.000000
205	450.000000
208	1,435.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,500.000000
223.4	1,580.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	2.000000
237	1.100000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.600000
246	12.000000
249	20.000000
251	.861000
252	2.100000
253	2.652000
254	3.532000
258	7.852500
259	25.240000
260	.545500
261	.598400
262	.545500
264	1.257500
265	.954000
266	.713000
267	1.024000
268	1.171500
271	1.111500
272	1.001500
273	1.236500
274	1.525100
276	.873000
277	1.119000
278	3.600000
279	3.720000
280	1.000000

281	5.780000
282	1.094000
283	1.305700
284	
285	.075000
286	1.788000
288	1.940600
289	.904700
290	3.500000
291	5.000000
293	
294	3.687800
295	6.490000
296	12.990000
297.2	
298.1	6.920000
298.2	5.550000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.735200
352	1.133000
354	.985400
356	.661600
357	1.441300
358	3.338500
360	14.938000
361	1.249900
362	1.397000
363	1.779400
364	1.133000
366	5.000500
370	.294100
371	1.779400
372	2.470800
373	2.735500
375	3.470900
376	.220400
377	.926400
378	14.950000
379	27.450000
380	16.560000
381	74.770000
386	28.630000
388	48.870000

390	1.500000
392	27.420000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.077700
442	.121800
443	1.987900
444	2.207500
445	1.600000
446	2.662500
447	4.525500
450	2.842800
451	1.214200
453	.085000
455	3.090000
456	1.658300
457	.827900
458	5.280000
459	5.280000
460	4.377500
462	
463	4.089100
464	3.630000
465	6.180000
467	3.397500
471	3.960000
473	2.832500
474	3.883100
475	6.416900
476	2.437300
477	
478	3.060000
479	1.876600
480	
481	5.467500
482	1.421100
483	.167500
484	4.160000
485	1.218700
487	13.884000
488	5.500000
490	.730000
491	.540000
492	.540000
493	.730000

494	5.480000
495	
496	.905500
498	1.011600
499	1.386800
500	2.039600
501	2.763000
502	3.807000
503	.905500
504	1.199100
505	19.170000
506	1.431700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.410000
514	42.680000
515	43.500000
519	50.290000
520	41.070000
521	2.461700
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.600000
536	2.500000
537	1.700000
565.3	3.800000
565.5	5.650000
565.6	7.800000
566.3	5.050000
566.5	7.750000
566.6	10.300000

1101	1101			
001		.500000 x	15.741598 =	7.870799
		-----		
			B.T =	7.870799
1102	1102			
001		1.000000 x	15.741598 =	15.741598
		-----		
			B.T =	15.741598
1103	1103			
001		.300000 x	15.741598 =	4.722479
		-----		
			B.T =	4.722479
1104	1104			
015		1.000000 x	.000000 =	.000000
291		2.200000 x	5.000000 =	11.000000
485		83.000000 x	1.218700 =	101.152100
484		5.250000 x	4.160000 =	21.840000
002		7.000000 x	17.312112 =	121.184784
004		7.000000 x	23.886192 =	167.203344
		-----		
			AΘΡΟΙΣΜΑ =	422.380228
	B.T =	.004000 x	422.380228 =	1.689521
		-----		
1111	1111			
006		.060000 x	183.150721 =	10.989043
		-----		
			B.T =	10.989043
1112	1112			
006		.090000 x	183.150721 =	16.483565
		-----		
			B.T =	16.483565
1116	1116			
007		.025000 x	183.150721 =	4.578768
		-----		
			B.T =	4.578768
1117	1117			
007		.110000 x	183.150721 =	20.146579
		-----		
			B.T =	20.146579
1121	1121			
009		4.000000 x	.074800 =	.299200
		-----		
			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000
		-----		
			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600
		-----		
			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639
		-----		
			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408
		-----		
			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617
		-----		
			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565
		-----		
			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800
		-----		
			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200
		-----		
			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000
		-----		
			B.T =	.187000



1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000
		-----		
			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000
		-----		
			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
1407		.320000 x	37.605000 =	12.033600
051		.960000 x	15.400000 =	14.784000
		-----		
			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
1407		.360000 x	37.605000 =	13.537800
051		.900000 x	15.400000 =	13.860000
		-----		
			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100
		-----		
			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.099900 =	14.985000
1407		.250000 x	37.605000 =	9.401250
		-----		
			B.T =	39.704250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
051		.900000 x	15.400000 =	13.860000
1407		.290000 x	37.605000 =	10.905450
		-----		
			B.T =	40.284450

1418	1418			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000

-----  
B.T = 41.616750

1421	1421			
021		.200000 x	2.670000 =	.534000
1407		.540000 x	37.605000 =	20.306700
051		.540000 x	15.400000 =	8.316000
039		4.000000 x	.000000 =	.000000

-----  
B.T =

1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.086500 =	6.487500
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

-----  
B.T =

1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

-----  
B.T = 152.456250

1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.099900 =	14.985000

-----  
B.T = 163.304700

1428	1428			
021		.200000 x	2.670000 =	.534000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.090000 =	108.000000
051		.200000 x	15.400000 =	3.080000

-----  
B.T = 126.656000

1429	1429			
021		.200000 x	2.670000 =	.534000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.090000 =	108.000000
035		200.000000 x	.086500 =	17.300000
		-----		
			B.T =	140.876000
1431	1431			
021		.300000 x	2.670000 =	.801000
032		.960000 x	36.000000 =	34.560000
1407		.320000 x	37.605000 =	12.033600
		-----		
			B.T =	47.394600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	15.400000 =	9.856000
032		.320000 x	36.000000 =	11.520000
		-----		
			B.T =	34.210600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.086500 =	95.150000
		-----		
			B.T =	96.084500
1437	1437			
021		.200000 x	2.670000 =	.534000
1407		.620000 x	37.605000 =	23.315100
051		.380000 x	15.400000 =	5.852000
035		75.000000 x	.086500 =	6.487500
		-----		
			B.T =	36.188600
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.099900 =	24.975000
		-----		
			B.T =	27.111000
1442	1442			
021		.250000 x	2.670000 =	.667500
026		900.000000 x	.099900 =	89.910000
051		.740000 x	15.400000 =	11.396000
		-----		
			B.T =	101.973500

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	12 22/12/2011
1443	1443		
021	.250000 x	2.670000 =	.667500
051	.860000 x	15.400000 =	13.244000
026	700.000000 x	.099900 =	69.930000
-----			
		B.T =	83.841500
1444	1444		
021	.250000 x	2.670000 =	.667500
051	1.000000 x	15.400000 =	15.400000
026	600.000000 x	.099900 =	59.940000
-----			
		B.T =	76.007500
1445	1445		
021	.250000 x	2.670000 =	.667500
051	1.060000 x	15.400000 =	16.324000
026	450.000000 x	.099900 =	44.955000
-----			
		B.T =	61.946500
1446	1446		
021	.250000 x	2.670000 =	.667500
026	350.000000 x	.099900 =	34.965000
051	1.120000 x	15.400000 =	17.248000
-----			
		B.T =	52.880500
1447	1447		
021	.250000 x	2.670000 =	.667500
051	1.000000 x	15.400000 =	15.400000
026	400.000000 x	.099900 =	39.960000
1407	.080000 x	37.605000 =	3.008400
-----			
		B.T =	59.035900
1448	1448		
021	.250000 x	2.670000 =	.667500
039	5.000000 x	.000000 =	.000000
051	1.000000 x	15.400000 =	15.400000
1407	.080000 x	37.605000 =	3.008400
026	400.000000 x	.099900 =	39.960000
-----			
		B.T =	
1449	1449		
021	.250000 x	2.670000 =	.667500
1407	.040000 x	37.605000 =	1.504200
051	1.060000 x	15.400000 =	16.324000
026	350.000000 x	.099900 =	34.965000
-----			
		B.T =	53.460700

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.151500 =	90.900000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	220.947750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
026		450.000000 x	.099900 =	44.955000
		-----		
			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
029		450.000000 x	.151500 =	68.175000
		-----		
			B.T =	210.972750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	189.987750

1457	1457			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.151500 =	90.900000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	220.947750
1458	1458			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.151500 =	68.175000
054		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	210.972750
1461	1461			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.099900 =	49.950000
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	181.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
026		400.000000 x	.099900 =	39.960000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	43.500000 =	43.500000
051		.100000 x	15.400000 =	1.540000
		-----		
			B.T =	87.681250
1463	1463			
021		.300000 x	2.670000 =	.801000
026		250.000000 x	.099900 =	24.975000
515		1.050000 x	43.500000 =	45.675000
1407		.050000 x	37.605000 =	1.880250
051		.100000 x	15.400000 =	1.540000
		-----		
			B.T =	74.871250

1464	1464				
021		.200000 x	2.670000 =	.534000	
051		.420000 x	15.400000 =	6.468000	
1407		.120000 x	37.605000 =	4.512600	
519		.600000 x	50.290000 =	30.174000	
026		150.000000 x	.099900 =	14.985000	
			B.T =	56.673600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	50.290000 =	45.261000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.099900 =	44.955000	
			B.T =	94.188150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	50.290000 =	42.243600	
026		450.000000 x	.099900 =	44.955000	
051		.210000 x	15.400000 =	3.234000	
			B.T =	92.094750	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.099900 =	44.955000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	50.290000 =	35.203000	
			B.T =	87.210150	
1471	1471				
251		1.000000 x	.861000 =	.861000	
351		4.000000 x	.735200 =	2.940800	
358		1.000000 x	3.338500 =	3.338500	
364		2.000000 x	1.133000 =	2.266000	
372		.400000 x	2.470800 =	.988320	
370		6.000000 x	.294100 =	1.764600	
			AΘΡΟΙΣΜΑ =	12.159220	
	B.T =	.476190 x	12.159220 =	5.790099	

1472	1472			
251		.600000 x	.861000 =	.516600
351		2.000000 x	.735200 =	1.470400
361		1.000000 x	1.249900 =	1.249900
363		2.000000 x	1.779400 =	3.558800
372		.300000 x	2.470800 =	.741240
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	10.477740
	B.T =	.666667 x	10.477740 =	6.985163
1473	1473			
251		.500000 x	.861000 =	.430500
354		4.000000 x	.985400 =	3.941600
364		2.000000 x	1.133000 =	2.266000
372		.700000 x	2.470800 =	1.729560
370		4.000000 x	.294100 =	1.176400
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	28.672760
	B.T =	.416667 x	28.672760 =	11.946993
1474	1474			
251		.500000 x	.861000 =	.430500
372		.500000 x	2.470800 =	1.235400
370		4.000000 x	.294100 =	1.176400
366		2.000000 x	5.000500 =	10.001000
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
357		4.000000 x	1.441300 =	5.765200
			AΘΡΟΙΣΜΑ =	34.796400
	B.T =	.416667 x	34.796400 =	14.498512
1475	1475			
251		.300000 x	.861000 =	.258300
379		1.000000 x	27.450000 =	27.450000
371		2.000000 x	1.779400 =	3.558800
376		160.000000 x	.220400 =	35.264000
377		6.000000 x	.926400 =	5.558400
378		1.000000 x	14.950000 =	14.950000
375		2.000000 x	3.470900 =	6.941800
354		3.000000 x	.985400 =	2.956200
			AΘΡΟΙΣΜΑ =	96.937500
	B.T =	.416667 x	96.937500 =	40.390657



1476	1476			
251		.500000 x	.861000 =	.430500
373		.200000 x	2.735500 =	.547100
370		6.000000 x	.294100 =	1.764600
352		3.000000 x	1.133000 =	3.399000
		-----		
			ΑΘΡΟΙΣΜΑ =	6.141200
	B.T =	.500000 x	6.141200 =	3.070600
		-----		
1478	1478			
251		3.000000 x	.861000 =	2.583000
372		.500000 x	2.470800 =	1.235400
356		2.000000 x	.661600 =	1.323200
370		6.000000 x	.294100 =	1.764600
		-----		
			ΑΘΡΟΙΣΜΑ =	6.906200
	B.T =	.500000 x	6.906200 =	3.453100
		-----		
1479	1479			
251		6.000000 x	.861000 =	5.166000
370		12.000000 x	.294100 =	3.529200
381		1.000000 x	74.770000 =	74.770000
		-----		
			ΑΘΡΟΙΣΜΑ =	83.465200
	B.T =	.454545 x	83.465200 =	37.938689
		-----		
1480	1480			
251		8.000000 x	.861000 =	6.888000
381		2.000000 x	74.770000 =	149.540000
370		16.000000 x	.294100 =	4.705600
		-----		
			ΑΘΡΟΙΣΜΑ =	161.133600
	B.T =	.227273 x	161.133600 =	36.621317
		-----		
1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.085000 =	.019550
487		.040000 x	13.884000 =	.555360
451		.230000 x	1.214200 =	.279266
		-----		
			B.T =	.855511
1487	1487			
443		.120000 x	1.987900 =	.238548
451		.170000 x	1.214200 =	.206414
453		.640000 x	.085000 =	.054400
446		.010000 x	2.662500 =	.026625
445		.060000 x	1.600000 =	.096000
		-----		
			B.T =	.621987

1488	1488			
444		.170000 x	2.207500 =	.375275
453		.500000 x	.085000 =	.042500
451		.170000 x	1.214200 =	.206414
446		.030000 x	2.662500 =	.079875
445		.050000 x	1.600000 =	.080000
		-----		
			B.T =	.784064
1489	1489			
444		.100000 x	2.207500 =	.220750
453		.430000 x	.085000 =	.036550
451		.350000 x	1.214200 =	.424970
446		.020000 x	2.662500 =	.053250
445		.100000 x	1.600000 =	.160000
		-----		
			B.T =	.895520
1490	1490			
444		.300000 x	2.207500 =	.662250
445		.100000 x	1.600000 =	.160000
446		.030000 x	2.662500 =	.079875
451		.570000 x	1.214200 =	.692094
		-----		
			B.T =	1.594219
1491	1491			
444		.270000 x	2.207500 =	.596025
445		.060000 x	1.600000 =	.096000
451		.650000 x	1.214200 =	.789230
446		.020000 x	2.662500 =	.053250
		-----		
			B.T =	1.534505
1492	1492			
444		.200000 x	2.207500 =	.441500
446		.030000 x	2.662500 =	.079875
445		.040000 x	1.600000 =	.064000
455		.730000 x	3.090000 =	2.255700
		-----		
			B.T =	2.841075
1501	1501			
011		1.000000 x	.000000 =	.000000
012		2.000000 x	.000000 =	.000000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	1.218700 =	18.280500
484		1.750000 x	4.160000 =	7.280000
		-----		
			B.T =	

1502	1502			
013		1.000000 x	.000000 =	.000000
005		3.500000 x	21.778427 =	76.224495
001		26.000000 x	15.741598 =	409.281548
482		15.000000 x	1.421100 =	21.316500
484		.900000 x	4.160000 =	3.744000

-----  
B.T =

1503	1503			
014		1.000000 x	.000000 =	.000000
002		2.600000 x	17.312112 =	45.011491
004		7.000000 x	23.886192 =	167.203344
484		2.600000 x	4.160000 =	10.816000
485		44.000000 x	1.218700 =	53.622800

-----  
B.T =

1504	1504			
015		1.000000 x	.000000 =	.000000
004		7.000000 x	23.886192 =	167.203344
002		7.000000 x	17.312112 =	121.184784
485		83.000000 x	1.218700 =	101.152100
484		5.250000 x	4.160000 =	21.840000
291		2.200000 x	5.000000 =	11.000000

-----  
B.T =

1505	1505			
016		1.000000 x	.000000 =	.000000
004		7.000000 x	23.886192 =	167.203344
002		1.750000 x	17.312112 =	30.296196
485		17.500000 x	1.218700 =	21.327250
484		1.750000 x	4.160000 =	7.280000

-----  
B.T =

1506	1506			
017		1.000000 x	.000000 =	.000000
002		3.500000 x	17.312112 =	60.592392
484		6.000000 x	4.160000 =	24.960000
004		7.000000 x	23.886192 =	167.203344
485		70.000000 x	1.218700 =	85.309000

-----  
B.T =

2101	2101			
002		.300000 x	17.312112 =	5.193634

-----  
T.E = 5.193634

2102	2102			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2108A	2108A			
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	12.118478
2108B	2108B			
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	27.699379

2108Ε	2108Ε			
002		4.600000 x	17.312112 =	79.635715
		-----		
			T.E =	79.635715
2108Η	2108Η			
002		7.600000 x	17.312112 =	131.572051
		-----		
			T.E =	131.572051
2108Ζ	2108Ζ			
002		6.600000 x	17.312112 =	114.259939
		-----		
			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491
		-----		
			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603
		-----		
			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163
		-----		
			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827
		-----		
			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1506		.004000 x	.000000 =	.000000
1503		.001000 x	.000000 =	.000000
		-----		
			T.E =	
2110	2110			
002		.040000 x	17.312112 =	.692484
1501		.005000 x	.000000 =	.000000
1506		.004000 x	.000000 =	.000000
1503		.001000 x	.000000 =	.000000
		-----		
			T.E =	



2111	2111			
002		.100000 x	17.312112 =	1.731211
1504		.005000 x	.000000 =	.000000
-----				
			T.E =	
2112	2112			
002		.120000 x	17.312112 =	2.077453
1504		.005500 x	.000000 =	.000000
1501		.004000 x	.000000 =	.000000
-----				
			T.E =	
2113	2113			
002		1.400000 x	17.312112 =	24.236957
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	29.430590
2114	2114			
002		1.500000 x	17.312112 =	25.968168
1501		.005000 x	.000000 =	.000000
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	
2115	2115			
481		.300000 x	5.467500 =	1.640250
003		1.200000 x	20.419486 =	24.503383
1501		.011000 x	.000000 =	.000000
002		.600000 x	17.312112 =	10.387267
-----				
			T.E =	
2116	2116			
2115		1.300000 x	.000000 =	.000000
-----				
			T.E =	
2117	2117			
002		.600000 x	17.312112 =	10.387267
1501		.125000 x	.000000 =	.000000
-----				
			T.E =	
2118	2118			
2117		1.300000 x	.000000 =	.000000
-----				
			T.E =	

2121	2121			
001		.400000 x	15.741598 =	6.296639
002		1.800000 x	17.312112 =	31.161802
		-----		
			T.E =	37.458441
2122	2122			
001		.500000 x	15.741598 =	7.870799
1501		.005000 x	.000000 =	.000000
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	
2123	2123			
002		.200000 x	17.312112 =	3.462422
1504		.008300 x	.000000 =	.000000
		-----		
			T.E =	
2124	2124			
002		.200000 x	17.312112 =	3.462422
1501		.005000 x	.000000 =	.000000
1504		.010000 x	.000000 =	.000000
		-----		
			T.E =	
2125	2125			
481		.400000 x	5.467500 =	2.187000
1501		.020000 x	.000000 =	.000000
002		1.000000 x	17.312112 =	17.312112
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	
2126	2126			
2125		1.300000 x	.000000 =	.000000
		-----		
			T.E =	
2127	2127			
002		1.000000 x	17.312112 =	17.312112
1501		.166600 x	.000000 =	.000000
		-----		
			T.E =	
2128	2128			
2127		1.300000 x	.000000 =	.000000
		-----		
			T.E =	

2131	2131			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
2132	2132			
1504		.001600 x	.000000 =	.000000
		-----		
			T.E =	
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267
		-----		
			T.E =	12.118478
2134	2134			
1504		.002500 x	.000000 =	.000000
		-----		
			T.E =	
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973
		-----		
			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	.000000 =	.000000
		-----		
			T.E =	
2135.3	2135.3			
2127		1.300000 x	.000000 =	.000000
		-----		
			T.E =	
2135.4	2135.4			
2128		1.300000 x	.000000 =	.000000
		-----		
			T.E =	
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	82.531911

2142	2142			
001		2.000000 x	15.741598 =	31.483196
1501		.005000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
-----				
			T.E =	
2143	2143			
481		.500000 x	5.467500 =	2.733750
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458
1501		.025000 x	.000000 =	.000000
-----				
			T.E =	
2144	2144			
2143		1.300000 x	.000000 =	.000000
-----				
			T.E =	
2145	2145			
001		2.000000 x	15.741598 =	31.483196
003		1.000000 x	20.419486 =	20.419486
1501		.200000 x	.000000 =	.000000
-----				
			T.E =	
2146	2146			
2145		1.300000 x	.000000 =	.000000
-----				
			T.E =	
2151	2151			
001		1.200000 x	15.741598 =	18.889918
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	35.225506
2152	2152			
001		1.500000 x	15.741598 =	23.612397
003		1.000000 x	20.419486 =	20.419486
-----				
			T.E =	44.031883
2161	2161			
1505		.003300 x	.000000 =	.000000
-----				
			T.E =	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	.000000 =	.000000
		-----		
			T.E =	
2172	2172			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536
		-----		
			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400
		-----		
			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713
		-----		
			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2185	2185			
018.1		.142800 x	.000000 =	.000000
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.160000 =	.416000
482		.700000 x	1.421100 =	.994770
018.1		.042800 x	.000000 =	.000000
		-----		
			T.E =	
2186	2186			
018.2		.142800 x	.000000 =	.000000
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	.000000 =	.000000
482		1.400000 x	1.421100 =	1.989540
484		.200000 x	4.160000 =	.832000
		-----		
			T.E =	
2187	2187			
019.1		.142800 x	.000000 =	.000000
485		1.100000 x	1.218700 =	1.340570
019.1		.428000 x	.000000 =	.000000
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.160000 =	.416000
		-----		
			T.E =	
2188	2188			
019.2		.142800 x	.000000 =	.000000
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	1.218700 =	2.193660
484		.200000 x	4.160000 =	.832000
019.2		.042800 x	.000000 =	.000000
		-----		
			T.E =	

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	31 22/12/2011
2201	2201		
001	1.000000 x	15.741598 =	15.741598
002	2.000000 x	17.312112 =	34.624224
-----			
		T.E =	50.365822
2202	2202		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560
-----			
		T.E =	102.302158
2203	2203		
001	1.000000 x	15.741598 =	15.741598
002	2.500000 x	17.312112 =	43.280280
-----			
		T.E =	59.021878
2204	2204		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560
-----			
		T.E =	102.302158
2206	2206		
001	1.000000 x	15.741598 =	15.741598
003	3.000000 x	20.419486 =	61.258458
-----			
		T.E =	77.000056
2207	2207		
001	1.000000 x	15.741598 =	15.741598
003	6.000000 x	20.419486 =	122.516916
-----			
		T.E =	138.258514
2211	2211		
001	2.000000 x	15.741598 =	31.483196
-----			
		T.E =	31.483196
2212	2212		
001	1.000000 x	15.741598 =	15.741598
-----			
		T.E =	15.741598
2213	2213		
001	2.000000 x	15.741598 =	31.483196
-----			
		T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344
		-----		
			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390
		-----		
			T.E =	.408390



2236	2236				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	
				-----	
				T.E =	6.767793
2237	2237				
001		.200000 x	15.741598 =	3.148320	
003		.700000 x	20.419486 =	14.293640	
				-----	
				T.E =	17.441960
2238	2238				
001		.100000 x	15.741598 =	1.574160	
002		.400000 x	17.312112 =	6.924845	
				-----	
				T.E =	8.499005
2239	2239				
001		.200000 x	15.741598 =	3.148320	
003		.800000 x	20.419486 =	16.335589	
				-----	
				T.E =	19.483908
2241	2241				
001		.300000 x	15.741598 =	4.722479	
003		.100000 x	20.419486 =	2.041949	
				-----	
				T.E =	6.764428
2242	2242				
001		.400000 x	15.741598 =	6.296639	
003		.150000 x	20.419486 =	3.062923	
				-----	
				T.E =	9.359562
2243	2243				
001		.500000 x	15.741598 =	7.870799	
003		.250000 x	20.419486 =	5.104872	
				-----	
				T.E =	12.975671
2246	2246				
001		.250000 x	15.741598 =	3.935400	
003		.050000 x	20.419486 =	1.020974	
				-----	
				T.E =	4.956374

2247	2247				
001		.350000 x	15.741598 =	5.509559	
003		.100000 x	20.419486 =	2.041949	
				-----	
				T.E =	7.551508
2248	2248				
001		.450000 x	15.741598 =	7.083719	
003		.200000 x	20.419486 =	4.083897	
				-----	
				T.E =	11.167616
2251	2251				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	
				-----	
				T.E =	6.767793
2252	2252				
001		.100000 x	15.741598 =	1.574160	
002		.600000 x	17.312112 =	10.387267	
				-----	
				T.E =	11.961427
2261A	2261A				
003		.400000 x	20.419486 =	8.167794	
				-----	
				T.E =	8.167794
2261B	2261B				
003		.700000 x	20.419486 =	14.293640	
				-----	
				T.E =	14.293640
2261Γ	2261Γ				
003		.900000 x	20.419486 =	18.377537	
				-----	
				T.E =	18.377537
2261Δ	2261Δ				
003		1.200000 x	20.419486 =	24.503383	
				-----	
				T.E =	24.503383
2262A	2262A				
003		.550000 x	20.419486 =	11.230717	
				-----	
				T.E =	11.230717

2262B	2262B			
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049
		-----		
			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818
		-----		
			T.E =	46.964818
2264.2Α	2264.2Α			
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	40.838972
2264.2Β	2264.2Β			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561
		-----		
			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355
		-----		
			T.E =	65.342355
2264.3Α	2264.3Α			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.3Β	2264.3Β			
003		2.850000 x	20.419486 =	58.195535
		-----		
			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304
		-----		
			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073
		-----		
			T.E =	76.573073
2265Α	2265Α			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728
		-----		
			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184
		-----		
			T.E =	33.079567
2266.11	2266.11			
2263Γ		.350000 x	32.671178 =	11.434912
2263Γ		1.000000 x	32.671178 =	32.671178
		-----		
			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322
		-----		
			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912
		-----		
			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617
		-----		
			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322
		-----		
			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686
			-----	
			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640
			-----	
			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368
			-----	
			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096
			-----	
			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774
			-----	
			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824
			-----	
			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368
			-----	
			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437
			-----	
			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =		67.384304
2264.3Γ		.350000 x	67.384304 =		23.584506
					-----
			T.E =		90.968810
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =		76.573073
2264.3Δ		.350000 x	76.573073 =		26.800576
					-----
			T.E =		103.373649
2266.25	2266.25				
2265A		1.000000 x	10.209743 =		10.209743
2265A		.350000 x	10.209743 =		3.573410
					-----
			T.E =		13.783153
2266.26	2266.26				
2265B		1.000000 x	16.335589 =		16.335589
2265B		.350000 x	16.335589 =		5.717456
					-----
			T.E =		22.053045
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =		18.377537
2261Γ		.350000 x	18.377537 =		6.432138
					-----
			T.E =		24.809675
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =		24.503383
2261Δ		.350000 x	24.503383 =		8.576184
					-----
			T.E =		33.079567
2266.5	2266.5				
2262A		1.000000 x	11.230717 =		11.230717
2262A		.350000 x	11.230717 =		3.930751
					-----
			T.E =		15.161468
2266.6	2266.6				
2262B		1.000000 x	18.377537 =		18.377537
2262B		.350000 x	18.377537 =		6.432138
					-----
			T.E =		24.809675

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184
		-----		
			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912
		-----		
			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774
		-----		
			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967
		-----		
			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710
		-----		
			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453
		-----		
			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	40.838972



2269B	2269B			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458
2269Γ	2269Γ			
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	81.677944
2270.1	2270.1			
2267		1.000000 x	71.468201 =	71.468201
2267		.600000 x	71.468201 =	42.880921
		-----		
			T.E =	114.349122
2270.2	2270.2			
2268A		1.000000 x	102.097430 =	102.097430
2268A		.600000 x	102.097430 =	61.258458
		-----		
			T.E =	163.355888
2270.3	2270.3			
2268B		1.000000 x	120.474967 =	120.474967
2268B		.600000 x	120.474967 =	72.284980
		-----		
			T.E =	192.759947
2270.4	2270.4			
2268Γ		1.000000 x	130.684710 =	130.684710
2268Γ		.600000 x	130.684710 =	78.410826
		-----		
			T.E =	209.095536
2270.5	2270.5			
2268Δ		1.000000 x	140.894453 =	140.894453
2268Δ		.600000 x	140.894453 =	84.536672
		-----		
			T.E =	225.431125
2271A	2271A			
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.048715
2271B	2271B			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458

2271E	2271E			
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098
		-----		
			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019
		-----		
			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939
		-----		
			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220
		-----		
			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299
		-----		
			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738
		-----		
			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379
		-----		
			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580
		-----		
			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631
		-----		
			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860
		-----		
			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089
		-----		
			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318
		-----		
			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330
		-----		
			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323
		-----		
			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995
		-----		
			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727
		-----		
			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459
		-----		
			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193
		-----		
			T.E =	135.381193
2274.15	2274.15			
2272Ε		1.300000 x	118.433019 =	153.962925
		-----		
			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657
		-----		
			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389
		-----		
			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121
		-----		
			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854
		-----		
			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995
		-----		
			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586
		-----		
			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320
		-----		
			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318
		-----		
			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316
		-----		
			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313
		-----		
			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661
		-----		
			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327
		-----		
			T.E =	106.181327
2274.5	2274.5			
2271Ε		1.300000 x	91.887687 =	119.453993
		-----		
			T.E =	119.453993
2274.6	2274.6			
2271ΣΤ		1.300000 x	102.097430 =	132.726659
		-----		
			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325
		-----		
			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991
		-----		
			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657
		-----		
			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
003		5.000000 x	20.419486 =	102.097430
203.4		.033000 x	290.000000 =	9.570000
001		9.000000 x	15.741598 =	141.674382
251		6.000000 x	.861000 =	5.166000
		-----		
			T.E =	267.207812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	5.483634

2303	2303				
001		.250000 x	15.741598 =	3.935400	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	9.040271	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.312112 =	1.731211	
		-----			
			T.E =	1.847211	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	290.000000 =	11.600000	
003		7.000000 x	20.419486 =	142.936402	
001		9.000000 x	15.741598 =	141.674382	
251		6.000000 x	.861000 =	5.166000	
		-----			
			T.E =	312.976784	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	290.000000 =	.580000	
251		.250000 x	.861000 =	.215250	
001		.250000 x	15.741598 =	3.935400	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	8.373572	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.861000 =	.172200	
203.4		.001000 x	290.000000 =	.290000	
003		.100000 x	20.419486 =	2.041949	
001		.200000 x	15.741598 =	3.148320	
		-----			
			T.E =	6.232468	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.419486 =	.612585	
		-----			
			T.E =	1.102085	
2314.2	2314.2				
512		1.000000 x	.410000 =	.410000	
003		.030000 x	20.419486 =	.612585	
		-----			
			T.E =	1.022585	

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		175.000000 x	.099900 =	17.482500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	
-----					
			T.E =	103.260033	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		200.000000 x	.099900 =	19.980000	
-----					
			T.E =	105.391933	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.099900 =	24.975000	
-----					
			T.E =	110.021333	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.099900 =	29.970000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.800000 x	10.580000 =	8.464000	
-----					
			T.E =	114.650733	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	20.419486 =	30.629229	
001		4.000000 x	15.741598 =	62.966392	
026		200.000000 x	.099900 =	19.980000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	
-----					
			T.E =	129.598321	



3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	.000000 =	.000000
026		250.000000 x	.099900 =	24.975000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	15.400000 =	6.314000

-----  
T.E =

3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.099900 =	29.970000

-----  
T.E =

3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.099900 =	14.985000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
052		.420000 x	15.400000 =	6.468000

-----  
T.E =

117.370190

3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

-----  
T.E =

107.843233

3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.560000 x	15.400000 =	8.624000

-----  
T.E =

110.051133

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.099900 =	24.975000

-----  
T.E = 114.466933

3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.530000 x	15.400000 =	8.162000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.800000 x	13.560000 =	10.848000

-----  
T.E = 119.036733

3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
026		200.000000 x	.099900 =	19.980000
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000

-----  
T.E = 259.975359

3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
052		.410000 x	15.400000 =	6.314000

-----  
T.E = 264.390159

3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.099900 =	19.980000

-----  
T.E = 193.185046

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
052		.430000 x	15.400000 =	6.622000
-----				
			T.E =	197.907846
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	13.560000 =	11.390400
026		200.000000 x	.099900 =	19.980000
052		.560000 x	15.400000 =	8.624000
-----				
			T.E =	134.257521
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	.000000 =	.000000
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
062		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.099900 =	24.975000
-----				
			T.E =	
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.099900 =	29.970000
-----				
			T.E =	
3214	3214			
021		.250000 x	2.670000 =	.667500
062		.600000 x	13.560000 =	8.136000
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.099900 =	34.965000
052		.400000 x	15.400000 =	6.160000
-----				
			T.E =	

3215	3215			
021		.250000 x	2.670000 =	.667500
052		.420000 x	15.400000 =	6.468000
027		350.000000 x	.119300 =	41.755000
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.250000 x	13.610000 =	3.402500
062		.560000 x	13.560000 =	7.593600

-----  
T.E =

3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.119300 =	50.702500
052		.350000 x	15.400000 =	5.390000
001		4.000000 x	15.741598 =	62.966392
065		.270000 x	13.610000 =	3.674700
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
062		.550000 x	13.560000 =	7.458000

-----  
T.E =

3217	3217			
001		2.500000 x	15.741598 =	39.353995

-----  
T.E = 39.353995

3218	3218			
001		5.000000 x	15.741598 =	78.707990

-----  
T.E = 78.707990

3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944

-----  
T.E = 128.902738

3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944

-----  
T.E = 160.385934

3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916

-----  
T.E = 169.741710

3222	3222				
001		5.000000 x	15.741598 =		78.707990
003		6.000000 x	20.419486 =		122.516916
		-----			
			T.E =		201.224906
3223A.1	3223A.1				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	.000000 =		.000000
003		1.500000 x	20.419486 =		30.629229
		-----			
			AΘΡΟΙΣΜΑ =		62.112425
	T.E =	.500000 x	62.112425 =		31.056213
		-----			
3223A.2	3223A.2				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	.000000 =		.000000
		-----			
			AΘΡΟΙΣΜΑ =		88.063766
	T.E =	.500000 x	88.063766 =		44.031883
		-----			
3223A.3	3223A.3				
001		2.000000 x	15.741598 =		31.483196
003		1.500000 x	20.419486 =		30.629229
1502		.050000 x	.000000 =		.000000
		-----			
			AΘΡΟΙΣΜΑ =		62.112425
	T.E =	.500000 x	62.112425 =		31.056213
		-----			
3223A.4	3223A.4				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	.000000 =		.000000
		-----			
			AΘΡΟΙΣΜΑ =		88.063766
	T.E =	.500000 x	88.063766 =		44.031883
		-----			
3223A.5	3223A.5				
001		3.500000 x	15.741598 =		55.095593
1502		.050000 x	.000000 =		.000000
003		2.000000 x	20.419486 =		40.838972
		-----			
			AΘΡΟΙΣΜΑ =		95.934565
	T.E =	.500000 x	95.934565 =		47.967283
		-----			

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	95.934565
	T.E =	.500000 x	95.934565 =	47.967283
		-----		
3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	103.805364
	T.E =	.500000 x	103.805364 =	51.902682
		-----		
3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	62.112425
	T.E =	.250000 x	62.112425 =	15.528106
		-----		
3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
		-----		
			ΑΘΡΟΙΣΜΑ =	88.063766
	T.E =	.250000 x	88.063766 =	22.015942
		-----		
3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	62.112425
	T.E =	.250000 x	62.112425 =	15.528106
		-----		
3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	88.063766
	T.E =	.250000 x	88.063766 =	22.015942
		-----		

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	95.934565
	T.E =	.250000 x	95.934565 =	23.983641
		-----		
3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
1502		.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
		-----		
			ΑΘΡΟΙΣΜΑ =	95.934565
	T.E =	.250000 x	95.934565 =	23.983641
		-----		
3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	103.805364
	T.E =	.250000 x	103.805364 =	25.951341
		-----		
3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
026		150.000000 x	.099900 =	14.985000
061		.840000 x	13.560000 =	11.390400
001		5.000000 x	15.741598 =	78.707990
052		.560000 x	15.400000 =	8.624000
		-----		
			T.E =	122.029390
3301	3301			
021		.200000 x	2.670000 =	.534000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	36.000000 =	5.400000
		-----		
			T.E =	96.089932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
056		.800000 x	10.580000 =	8.464000
001		3.500000 x	15.741598 =	55.095593
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
051		.200000 x	15.400000 =	3.080000
-----				
			T.E =	98.230182
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	36.000000 =	14.400000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	102.350182
3304	3304			
021		.200000 x	2.670000 =	.534000
032		.400000 x	36.000000 =	14.400000
026		100.000000 x	.099900 =	9.990000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	117.499576
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	36.000000 =	5.760000
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
051		.320000 x	15.400000 =	4.928000
-----				
			T.E =	100.060382
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
061		.840000 x	13.560000 =	11.390400
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
051		.210000 x	15.400000 =	3.234000
-----				
			T.E =	110.214426



3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
061		.840000 x	13.560000 =	11.390400
003		1.200000 x	20.419486 =	24.503383
1407		.210000 x	37.605000 =	7.897050
001		3.500000 x	15.741598 =	55.095593
-----				
			T.E =	114.540426
3314	3314			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
1407		.130000 x	37.605000 =	4.888650
001		3.500000 x	15.741598 =	55.095593
003		1.200000 x	20.419486 =	24.503383
061		.840000 x	13.560000 =	11.390400
026		100.000000 x	.099900 =	9.990000
-----				
			T.E =	121.522026
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
026		140.000000 x	.099900 =	13.986000
-----				
			T.E =	91.562320
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
052		.392000 x	15.400000 =	6.036800
058		.500000 x	9.090000 =	4.545000
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280
-----				
			T.E =	94.823760
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
058		.500000 x	9.090000 =	4.545000
-----				
			T.E =	94.802900

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
003		1.100000 x	20.419486 =	22.461435
061		.574000 x	13.560000 =	7.783440
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
		-----		
			T.E =	97.914820
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
026		140.000000 x	.099900 =	13.986000
		-----		
			T.E =	92.522320
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
061		.588000 x	13.560000 =	7.973280
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
052		.392000 x	15.400000 =	6.036800
		-----		
			T.E =	95.783760
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
026		175.000000 x	.099900 =	17.482500
056		.574000 x	10.580000 =	6.072920
052		.287000 x	15.400000 =	4.419800
		-----		
			T.E =	95.762900

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
061		.574000 x	13.560000 =	7.783440
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
052		.378000 x	15.400000 =	5.821200
		-----		
			T.E =	98.874820
3501	3501			
021		.200000 x	2.670000 =	.534000
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000
		-----		
			T.E =	181.824862
3502	3502			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.099900 =	9.990000
		-----		
			T.E =	188.806462
3503	3503			
021		.200000 x	2.670000 =	.534000
067		1.000000 x	45.500000 =	45.500000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
032		.200000 x	36.000000 =	7.200000
026		150.000000 x	.099900 =	14.985000
		-----		
			T.E =	190.774362
3504	3504			
021		.200000 x	2.670000 =	.534000
003		3.200000 x	20.419486 =	65.342355
001		5.000000 x	15.741598 =	78.707990
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.090000 =	16.200000
026		250.000000 x	.099900 =	24.975000
		-----		
			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.099900 =	24.975000
003		5.000000 x	20.419486 =	102.097430
001		5.500000 x	15.741598 =	86.578789
517		4.000000 x	.000000 =	.000000
055		420.000000 x	.090000 =	37.800000

-----  
T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	43.500000 =	50.025000
001		5.000000 x	15.741598 =	78.707990
003		2.500000 x	20.419486 =	51.048715
026		200.000000 x	.099900 =	19.980000

-----  
T.E =

200.562705

3511	3511			
021		.200000 x	2.670000 =	.534000
069		1.050000 x	.000000 =	.000000
003		2.000000 x	20.419486 =	40.838972
1407		.180000 x	37.605000 =	6.768900
001		5.000000 x	15.741598 =	78.707990
032		.200000 x	36.000000 =	7.200000

-----  
T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.099900 =	9.990000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
069		1.050000 x	.000000 =	.000000
032		.200000 x	36.000000 =	7.200000

-----  
T.E =

3513	3513			
001		2.500000 x	15.741598 =	39.353995

-----  
T.E =

39.353995

3514	3514			
001		5.000000 x	15.741598 =	78.707990

-----  
T.E =

78.707990

3801	3801				
201		.001500 x	290.000000 =		.435000
203.4		.002500 x	290.000000 =		.725000
001		.400000 x	15.741598 =		6.296639
003		.500000 x	20.419486 =		10.209743
251		.300000 x	.861000 =		.258300
		-----			
			T.E =		17.924682
3802	3802				
3801		.050000 x	17.924682 =		.896234
		-----			
			T.E =		.896234
3811	3811				
203.4		.004000 x	290.000000 =		1.160000
001		.200000 x	15.741598 =		3.148320
251		.100000 x	.861000 =		.086100
003		.800000 x	20.419486 =		16.335589
		-----			
			T.E =		20.730008
3816	3816				
201		.002500 x	290.000000 =		.725000
251		.200000 x	.861000 =		.172200
003		.600000 x	20.419486 =		12.251692
001		.400000 x	15.741598 =		6.296639
203.4		.003000 x	290.000000 =		.870000
		-----			
			T.E =		20.315531
3817	3817				
3816		.150000 x	20.315531 =		3.047330
		-----			
			T.E =		3.047330
3821	3821				
201		.014000 x	290.000000 =		4.060000
003		2.400000 x	20.419486 =		49.006766
001		.600000 x	15.741598 =		9.444959
251		.600000 x	.861000 =		.516600
203.4		.018000 x	290.000000 =		5.220000
		-----			
			T.E =		68.248325
3822	3822				
3821		.150000 x	68.248325 =		10.237249
		-----			
			T.E =		10.237249

3823	3823			
201		.020000 x	290.000000 =	5.800000
003		3.000000 x	20.419486 =	61.258458
001		.600000 x	15.741598 =	9.444959
251		.180000 x	.861000 =	.154980
203.4		.025000 x	290.000000 =	7.250000
		-----		
			T.E =	83.908397
3824	3824			
3823		.200000 x	83.908397 =	16.781679
		-----		
			T.E =	16.781679
3831	3831			
201		.020000 x	290.000000 =	5.800000
251		.800000 x	.861000 =	.688800
203.4		.024000 x	290.000000 =	6.960000
003		4.500000 x	20.419486 =	91.887687
001		1.100000 x	15.741598 =	17.315758
		-----		
			T.E =	122.652245
3832	3832			
3831		.150000 x	122.652245 =	18.397837
		-----		
			T.E =	18.397837
3833	3833			
201		.022000 x	290.000000 =	6.380000
251		1.000000 x	.861000 =	.861000
003		6.000000 x	20.419486 =	122.516916
001		1.100000 x	15.741598 =	17.315758
203.4		.025000 x	290.000000 =	7.250000
		-----		
			T.E =	154.323674
3834	3834			
3833		.200000 x	154.323674 =	30.864735
		-----		
			T.E =	30.864735
3841	3841			
203.4		.001500 x	290.000000 =	.435000
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.644743

3851	3851			
203.4		.052000 x	290.000000 =	15.080000
003		1.300000 x	20.419486 =	26.545332
251		1.100000 x	.861000 =	.947100
		-----		
			T.E =	42.572432
3852	3852			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	6.764428
3871	3871			
260		1.030000 x	.545500 =	.561865
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	1.582839
3872	3872			
261		1.030000 x	.598400 =	.616352
003		.040000 x	20.419486 =	.816779
		-----		
			T.E =	1.433131
3873	3873			
262		1.030000 x	.545500 =	.561865
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	1.582839
3874	3874			
258		1.450000 x	7.852500 =	11.386125
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	14.449048
3875	3875			
259		1.000000 x	25.240000 =	25.240000
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	31.365846
3876	3876			
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	1.225169

3881.1	3881.1			
111		1,023.391800 x	.075900 =	77.675438
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	156.383428
3881.2	3881.2			
112		627.989998 x	.083300 =	52.311567
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	131.019557
3882	3882			
127		1.050000 x	81.220000 =	85.281000
001		4.000000 x	15.741598 =	62.966392
		-----		
			T.E =	148.247392
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	20.419486 =	40.838972
001		1.300000 x	15.741598 =	20.464077
		-----		
			T.E =	73.964549
4102	4102			
081		1.200000 x	11.010000 =	13.212000
003		3.500000 x	20.419486 =	71.468201
001		1.700000 x	15.741598 =	26.760717
		-----		
			T.E =	111.440918
4103	4103			
081		1.150000 x	11.010000 =	12.661500
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	141.564238
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	58.785294
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	20.419486 =	18.377537
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	37.972635



4106	4106			
081		.320000 x	11.010000 =	3.523200
003		.900000 x	20.419486 =	18.377537
001		.700000 x	15.741598 =	11.019119
		-----		
			T.E =	32.919856
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	105.953654
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	149.766208
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
001		2.900000 x	15.741598 =	45.650634
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	123.460407
4206	4206			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
003		3.100000 x	20.419486 =	63.300407
001		2.900000 x	15.741598 =	45.650634
		-----		
			T.E =	135.712098
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
1417		.350000 x	40.284450 =	14.099558
		-----		
			T.E =	154.089636

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	59.035900 =	20.662565	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	130.023414	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	59.035900 =	20.662565	
003		3.100000 x	20.419486 =	63.300407	
		-----			
			T.E =	142.275106	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		4.000000 x	20.419486 =	81.677944	
001		2.900000 x	15.741598 =	45.650634	
		-----			
			T.E =	160.652643	
4221	4221				
001		.800000 x	15.741598 =	12.593278	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	33.012764	
4222	4222				
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	14.464434	
4226	4226				
003		1.300000 x	20.419486 =	26.545332	
		-----			
			T.E =	26.545332	
4251	4251				
083		32.000000 x	.000000 =	.000000	
001		2.900000 x	15.741598 =	45.650634	
1412		.200000 x	27.931800 =	5.586360	
003		4.000000 x	20.419486 =	81.677944	
		-----			
			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1417		.200000 x	40.284450 =	8.056890
003		4.000000 x	20.419486 =	81.677944

-----  
T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.946500 =	12.389300
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

-----  
T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1447		.200000 x	59.035900 =	11.807180
003		4.000000 x	20.419486 =	81.677944

-----  
T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

-----  
T.E =

4301	4301			16.176598
081		1.020000 x	11.010000 =	11.230200
083		5.000000 x	.000000 =	.000000
003		4.200000 x	20.419486 =	85.761841
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634

-----  
T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
1417		.350000 x	40.284450 =	14.099558
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634

-----  
T.E =

4306	4306				
081		1.050000 x	11.010000 =	11.560500	
1417		.350000 x	40.284450 =	14.099558	
003		3.300000 x	20.419486 =	67.384304	
001		2.900000 x	15.741598 =	45.650634	
083		3.000000 x	.000000 =	.000000	
-----					
			T.E =		
4307	4307				
081		1.020000 x	11.010000 =	11.230200	
003		4.200000 x	20.419486 =	85.761841	
1417		.350000 x	40.284450 =	14.099558	
001		2.900000 x	15.741598 =	45.650634	
083		5.000000 x	.000000 =	.000000	
-----					
			T.E =		
4311	4311				
081		1.080000 x	11.010000 =	11.890800	
1447		.350000 x	59.035900 =	20.662565	
003		2.700000 x	20.419486 =	55.132612	
001		2.900000 x	15.741598 =	45.650634	
083		2.000000 x	.000000 =	.000000	
-----					
			T.E =		
4312	4312				
081		1.050000 x	11.010000 =	11.560500	
083		3.000000 x	.000000 =	.000000	
1447		.350000 x	59.035900 =	20.662565	
003		3.300000 x	20.419486 =	67.384304	
001		2.900000 x	15.741598 =	45.650634	
-----					
			T.E =		
4313	4313				
081		1.080000 x	11.010000 =	11.890800	
1447		.350000 x	59.035900 =	20.662565	
003		2.700000 x	20.419486 =	55.132612	
001		2.900000 x	15.741598 =	45.650634	
083		2.000000 x	.000000 =	.000000	
-----					
			T.E =		
4321	4321				
201		.001500 x	290.000000 =	.435000	
001		1.000000 x	15.741598 =	15.741598	
-----					
			T.E =	16.176598	

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
251		4.000000 x	.861000 =	3.444000
001		10.000000 x	15.741598 =	157.415980
003		25.000000 x	20.419486 =	510.487150
1446		.100000 x	52.880500 =	5.288050

-----  
T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.861000 =	3.444000
003		25.000000 x	20.419486 =	510.487150
1446		.100000 x	52.880500 =	5.288050
001		10.000000 x	15.741598 =	157.415980

-----  
T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980
251		4.000000 x	.861000 =	3.444000

-----  
T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
251		8.000000 x	.861000 =	6.888000
003		32.000000 x	20.419486 =	653.423552
1446		.200000 x	52.880500 =	10.576100
001		11.000000 x	15.741598 =	173.157578

-----  
T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.861000 =	6.888000
001		11.000000 x	15.741598 =	173.157578

-----  
T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.861000 =	6.888000
001		11.000000 x	15.741598 =	173.157578
			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918
			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794
			T.E =	47.224794
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	20.419486 =	20.419486
002		.500000 x	17.312112 =	8.656056
			T.E =	29.626042
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.300000 x	20.419486 =	26.545332
			T.E =	35.751888
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.400000 x	20.419486 =	28.587280
			T.E =	37.793836
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818
			T.E =	52.708951

4505	4505				
081		.050000 x	11.010000 =	.550500	
003		2.700000 x	20.419486 =	55.132612	
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	60.876746	
4506	4506				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.600000 x	20.419486 =	73.510150	
		-----			
			T.E =	79.254283	
4507	4507				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.200000 x	20.419486 =	65.342355	
		-----			
			T.E =	71.086489	
4508	4508				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.000000 x	20.419486 =	61.258458	
		-----			
			T.E =	67.002592	
4511	4511				
081		.050000 x	11.010000 =	.550500	
003		3.800000 x	20.419486 =	77.594047	
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	83.338180	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		4.000000 x	20.419486 =	81.677944	
		-----			
			T.E =	87.422078	
4515	4515				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		5.000000 x	20.419486 =	102.097430	
		-----			
			T.E =	107.841564	

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	97.631821
4517	4517			
081		.050000 x	11.010000 =	.550500
003		6.500000 x	20.419486 =	132.726659
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	138.470793
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.700000 x	20.419486 =	116.391070
		-----		
			T.E =	122.135204
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327
		-----		
			T.E =	111.925461
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	77.212335
4522	4522			
081		.050000 x	11.010000 =	.550500
003		2.700000 x	20.419486 =	55.132612
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	60.876746
4525	4525			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	20.419486 =	91.887687
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	97.631821



4526	4526			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	87.422078
4527	4527			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	20.419486 =	122.516916
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	128.261050
4528	4528			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327
		-----		
			T.E =	111.925461
4529	4529			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.700000 x	20.419486 =	95.971584
		-----		
			T.E =	101.715718
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.599215
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	41.389472
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047
		-----		
			T.E =	78.144547
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	20.419486 =	63.300407
		-----		
			T.E =	63.850907

4537	4537			
081		.050000 x	11.010000 =	.550500
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	112.857673
4538	4538			
081		.050000 x	11.010000 =	.550500
003		4.600000 x	20.419486 =	93.929636
		-----		
			T.E =	94.480136
4539	4539			
081		.050000 x	11.010000 =	.550500
003		4.200000 x	20.419486 =	85.761841
		-----		
			T.E =	86.312341
4541	4541			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.599215
4542	4542			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	41.389472
4543	4543			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	82.228444
4544	4544			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	123.067416
4601.1	4601.1			
101		105.000000 x	.000000 =	.000000
1417		.023000 x	40.284450 =	.926542
003		.700000 x	20.419486 =	14.293640
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	59.035900 =	1.357826
001		.600000 x	15.741598 =	9.444959
003		.700000 x	20.419486 =	14.293640

-----  
T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	40.284450 =	2.255929
003		1.300000 x	20.419486 =	26.545332
001		1.300000 x	15.741598 =	20.464077

-----  
T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
1447		.056000 x	59.035900 =	3.306010
003		1.300000 x	20.419486 =	26.545332
001		1.300000 x	15.741598 =	20.464077

-----  
T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	40.284450 =	3.585316
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

-----  
T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
1447		.089000 x	59.035900 =	5.254195
001		1.900000 x	15.741598 =	29.909036
003		1.800000 x	20.419486 =	36.755075

-----  
T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	40.284450 =	13.374437
003		5.500000 x	20.419486 =	112.307173
001		6.300000 x	15.741598 =	99.172067

-----  
T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
1447		.332000 x	59.035900 =	19.599919
003		5.500000 x	20.419486 =	112.307173
001		6.300000 x	15.741598 =	99.172067

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	40.284450 =	1.208534
001		.700000 x	15.741598 =	11.019119
003		.700000 x	20.419486 =	14.293640

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1447		.030000 x	59.035900 =	1.771077
003		.700000 x	20.419486 =	14.293640

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	40.284450 =	2.819912
001		1.400000 x	15.741598 =	22.038237
003		1.300000 x	20.419486 =	26.545332

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
1447		.070000 x	59.035900 =	4.132513
003		1.300000 x	20.419486 =	26.545332
001		1.400000 x	15.741598 =	22.038237

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	40.284450 =	4.431290
003		1.800000 x	20.419486 =	36.755075
001		2.100000 x	15.741598 =	33.057356

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
1447		.110000 x	59.035900 =	6.493949
001		2.100000 x	15.741598 =	33.057356
003		1.800000 x	20.419486 =	36.755075

-----  
T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	40.284450 =	16.274918
003		5.500000 x	20.419486 =	112.307173
001		6.500000 x	15.741598 =	102.320387

-----  
T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
1447		.404000 x	59.035900 =	23.850504
003		5.500000 x	20.419486 =	112.307173
001		6.500000 x	15.741598 =	102.320387

-----  
T.E =

4621.1	4621.1			
111		53.000000 x	.075900 =	4.022700
1417		.010000 x	40.284450 =	.402845
001		.400000 x	15.741598 =	6.296639
003		.500000 x	20.419486 =	10.209743

-----  
T.E = 20.931927

4621.2	4621.2			
111		53.000000 x	.075900 =	4.022700
001		.400000 x	15.741598 =	6.296639
1447		.010000 x	59.035900 =	.590359
003		.500000 x	20.419486 =	10.209743

-----  
T.E = 21.119441

4622.1	4622.1			
111		75.000000 x	.075900 =	5.692500
1417		.020000 x	40.284450 =	.805689
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743

-----  
T.E = 23.791651

4622.2	4622.2			
111		75.000000 x	.075900 =	5.692500
1447		.020000 x	59.035900 =	1.180718
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719
		-----		
			T.E =	24.166680
4623.1	4623.1			
111		150.000000 x	.075900 =	11.385000
1417		.050000 x	40.284450 =	2.014223
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	47.752252
4623.2	4623.2			
111		150.000000 x	.075900 =	11.385000
001		.950000 x	15.741598 =	14.954518
1447		.050000 x	59.035900 =	2.951795
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	48.689825
4624.1	4624.1			
111		225.000000 x	.075900 =	17.077500
1417		.085000 x	40.284450 =	3.424178
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
		-----		
			T.E =	70.659407
4624.2	4624.2			
111		225.000000 x	.075900 =	17.077500
1447		.085000 x	59.035900 =	5.018052
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
		-----		
			T.E =	72.253280
4625.1	4625.1			
111		750.000000 x	.075900 =	56.925000
1417		.320000 x	40.284450 =	12.891024
001		5.200000 x	15.741598 =	81.856310
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	239.476123

4625.2	4625.2			
111		750.000000 x	.075900 =	56.925000
001		5.200000 x	15.741598 =	81.856310
1447		.320000 x	59.035900 =	18.891488
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	245.476587
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.791651 =	52.341632
		-----		
			T.E =	52.341632
4633.2	4633.2			
4622.2		2.200000 x	24.166680 =	53.166696
		-----		
			T.E =	53.166696
4634.1	4634.1			
4622.1		1.200000 x	23.791651 =	28.549981
4623.1		1.000000 x	47.752252 =	47.752252
		-----		
			T.E =	76.302233
4634.2	4634.2			
4622.2		1.200000 x	24.166680 =	29.000016
4623.2		1.000000 x	48.689825 =	48.689825
		-----		
			T.E =	77.689841
4661.1	4661.1			
112		43.750000 x	.083300 =	3.644375
1417		.014507 x	40.284450 =	.584407
001		.400000 x	15.741598 =	6.296639
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	20.735164
4661.2	4661.2			
112		43.750000 x	.083300 =	3.644375
1447		.014507 x	59.035900 =	.856434
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	21.007191
4662.1	4662.1			
112		58.333300 x	.083300 =	4.859164
1417		.022840 x	40.284450 =	.920097
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	23.072723



4662.2	4662.2			
112		58.333300 x	.083300 =	4.859164
001		.450000 x	15.741598 =	7.083719
1447		.022840 x	59.035900 =	1.348380
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	23.501006
4663.1	4663.1			
112		105.000000 x	.083300 =	8.746500
1417		.043218 x	40.284450 =	1.741013
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438
		-----		
			T.E =	43.032489
4663.2	4663.2			
112		105.000000 x	.083300 =	8.746500
1447		.043218 x	59.035900 =	2.551414
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438
		-----		
			T.E =	43.842889
4664.1	4664.1			
112		97.222221 x	.083300 =	8.098611
1417		.045077 x	40.284450 =	1.815902
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	44.267543
4664.2	4664.2			
112		97.222221 x	.083300 =	8.098611
001		.950000 x	15.741598 =	14.954518
1447		.045077 x	59.035900 =	2.661161
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	45.112802
4665.1	4665.1			
112		174.999001 x	.083300 =	14.577417
1417		.047530 x	40.284450 =	1.914720
001		1.500000 x	15.741598 =	23.612397
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	66.649865

4665.2	4665.2			
112		174.999001 x	.083300 =	14.577417
1447		.047530 x	59.035900 =	2.805976
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
		-----		
			T.E =	67.541122
4666.1	4666.1			
112		486.111099 x	.083300 =	40.493055
1417		.277862 x	40.284450 =	11.193518
001		5.200000 x	15.741598 =	81.856310
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	221.346672
4666.2	4666.2			
112		486.111000 x	.083300 =	40.493046
001		5.200000 x	15.741598 =	81.856310
1447		.277862 x	59.035900 =	16.403833
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	226.556979
4701	4701			
113		13.000000 x	.570000 =	7.410000
1417		.020000 x	40.284450 =	.805689
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	24.254282
4702	4702			
113		13.000000 x	.570000 =	7.410000
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	24.629311
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	40.284450 =	.604267
001		.400000 x	15.741598 =	6.296639
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
1417		.020000 x	40.284450 =	.805689
001		.500000 x	15.741598 =	7.870799
003		.400000 x	20.419486 =	8.167794

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	40.284450 =	.604267
001		.400000 x	15.741598 =	6.296639
003		.350000 x	20.419486 =	7.146820

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820

T.E =

4721.1	4721.1			
128		.080000 x	88.240000 =	7.059200
1417		.004000 x	40.284450 =	.161138
001		.300000 x	15.741598 =	4.722479
003		.350000 x	20.419486 =	7.146820

T.E =

19.089637

4721.2	4721.2				
128		.080000 x	88.240000 =	7.059200	
1447		.004000 x	59.035900 =	.236144	
003		.350000 x	20.419486 =	7.146820	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	19.164643	
4722.1	4722.1				
128		.100000 x	88.240000 =	8.824000	
1417		.005000 x	40.284450 =	.201422	
001		.350000 x	15.741598 =	5.509559	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	21.681802	
4722.2	4722.2				
128		.100000 x	88.240000 =	8.824000	
001		.350000 x	15.741598 =	5.509559	
1447		.005000 x	59.035900 =	.295180	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	21.775559	
4723	4723				
128		.120000 x	88.240000 =	10.588800	
1417		.006000 x	40.284450 =	.241707	
001		.400000 x	15.741598 =	6.296639	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	24.273966	
4724.1	4724.1				
128		.150000 x	88.240000 =	13.236000	
1417		.008000 x	40.284450 =	.322276	
003		.400000 x	20.419486 =	8.167794	
001		.400000 x	15.741598 =	6.296639	
		-----			
			T.E =	28.022709	
4724.2	4724.2				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1447		.008000 x	59.035900 =	.472287	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	28.172721	

4725.1	4725.1			
128		.180000 x	88.240000 =	15.883200
001		.450000 x	15.741598 =	7.083719
1417		.009000 x	40.284450 =	.362560
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	31.497274
4725.2	4725.2			
128		.180000 x	88.240000 =	15.883200
001		.450000 x	15.741598 =	7.083719
1447		.009000 x	59.035900 =	.531323
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	31.666037
4801.1	4801.1			
4662.1		1.000000 x	23.072723 =	23.072723
4662.1		.100000 x	23.072723 =	2.307272
		-----		
			T.E =	25.379995
4801.2	4801.2			
4662.2		1.000000 x	23.501006 =	23.501006
4662.2		.100000 x	23.501006 =	2.350101
		-----		
			T.E =	25.851107
4802.1	4802.1			
4664.1		1.000000 x	44.267543 =	44.267543
4664.1		.050000 x	44.267543 =	2.213377
		-----		
			T.E =	46.480920
4802.2	4802.2			
4664.2		1.000000 x	45.112802 =	45.112802
4664.2		.050000 x	45.112802 =	2.255640
		-----		
			T.E =	47.368442
4803.1	4803.1			
4665.1		1.000000 x	66.649865 =	66.649865
4665.1		.030000 x	66.649865 =	1.999496
		-----		
			T.E =	68.649361
4803.2	4803.2			
4665.2		1.000000 x	67.541122 =	67.541122
4665.2		.030000 x	67.541122 =	2.026234
		-----		
			T.E =	69.567356

4811.1	4811.1			
001		.225000 x	15.741598 =	3.541860
4662.1		1.000000 x	23.072723 =	23.072723
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	31.719454
4811.2	4811.2			
001		.225000 x	15.741598 =	3.541860
003		.250000 x	20.419486 =	5.104872
4662.2		1.000000 x	23.501006 =	23.501006
		-----		
			T.E =	32.147737
4812.1	4812.1			
001		.475000 x	15.741598 =	7.477259
003		.475000 x	20.419486 =	9.699256
4664.1		1.000000 x	44.267543 =	44.267543
		-----		
			T.E =	61.444058
4812.2	4812.2			
001		.475000 x	15.741598 =	7.477259
003		.475000 x	20.419486 =	9.699256
4664.2		1.000000 x	45.112802 =	45.112802
		-----		
			T.E =	62.289317
4813.1	4813.1			
001		.750000 x	15.741598 =	11.806199
4665.1		1.000000 x	66.649865 =	66.649865
003		.650000 x	20.419486 =	13.272666
		-----		
			T.E =	91.728729
4813.2	4813.2			
001		.750000 x	15.741598 =	11.806199
003		.650000 x	20.419486 =	13.272666
4665.2		1.000000 x	67.541122 =	67.541122
		-----		
			T.E =	92.619986
4814.1	4814.1			
001		2.600000 x	15.741598 =	40.928155
003		2.150000 x	20.419486 =	43.901895
4666.1		1.000000 x	221.346672 =	221.346672
		-----		
			T.E =	306.176722

4814.2	4814.2			
001		2.600000 x	15.741598 =	40.928155
003		2.150000 x	20.419486 =	43.901895
4666.2		1.000000 x	226.556979 =	226.556979
		-----		
			T.E =	311.387029
4821.1	4821.1			
003		.450000 x	20.419486 =	9.188769
4662.1		1.000000 x	23.072723 =	23.072723
		-----		
			T.E =	32.261492
4821.2	4821.2			
003		.450000 x	20.419486 =	9.188769
4662.2		1.000000 x	23.501006 =	23.501006
		-----		
			T.E =	32.689775
4822.1	4822.1			
003		.807500 x	20.419486 =	16.488735
4664.1		1.000000 x	44.267543 =	44.267543
		-----		
			T.E =	60.756278
4822.2	4822.2			
003		.807500 x	20.419486 =	16.488735
4664.2		1.000000 x	45.112802 =	45.112802
		-----		
			T.E =	61.601537
4823.1	4823.1			
003		1.040000 x	20.419486 =	21.236265
4665.1		1.000000 x	66.649865 =	66.649865
		-----		
			T.E =	87.886130
4823.2	4823.2			
003		1.040000 x	20.419486 =	21.236265
4665.2		1.000000 x	67.541122 =	67.541122
		-----		
			T.E =	88.777387
4824.1	4824.1			
003		3.010000 x	20.419486 =	61.462653
4666.1		1.000000 x	221.346672 =	221.346672
		-----		
			T.E =	282.809325

4824.2	4824.2			
003		3.010000 x	20.419486 =	61.462653
4666.2		1.000000 x	226.556979 =	226.556979
		-----		
			T.E =	288.019632
4831.1	4831.1			
003		1.200000 x	20.419486 =	24.503383
4661.1		1.000000 x	20.735164 =	20.735164
		-----		
			T.E =	45.238547
4831.2	4831.2			
003		1.200000 x	20.419486 =	24.503383
4661.2		1.000000 x	21.007191 =	21.007191
		-----		
			T.E =	45.510574
4832.1	4832.1			
003		1.600000 x	20.419486 =	32.671178
4662.1		1.000000 x	23.072723 =	23.072723
		-----		
			T.E =	55.743901
4832.2	4832.2			
003		1.600000 x	20.419486 =	32.671178
4662.2		1.000000 x	23.501006 =	23.501006
		-----		
			T.E =	56.172184
4833.1	4833.1			
002		2.000000 x	17.312112 =	34.624224
4664.1		1.000000 x	44.267543 =	44.267543
		-----		
			T.E =	78.891767
4833.2	4833.2			
002		2.000000 x	17.312112 =	34.624224
4664.2		1.000000 x	45.112802 =	45.112802
		-----		
			T.E =	79.737026
4834.1	4834.1			
003		2.300000 x	20.419486 =	46.964818
4665.1		1.000000 x	66.649865 =	66.649865
		-----		
			T.E =	113.614683



4834.2	4834.2			
003		2.300000 x	20.419486 =	46.964818
4665.2		1.000000 x	67.541122 =	67.541122

T.E = 114.505940

4835	4835			
122		1.050000 x	.000000 =	.000000
1417		.005000 x	40.284450 =	.201422
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.954000 =	1.908000
201		.010000 x	290.000000 =	2.900000

T.E =

4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
265		2.000000 x	.954000 =	1.908000
1447		.005000 x	59.035900 =	.295180
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598

T.E =

4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
1417		.005000 x	40.284450 =	.201422
003		1.000000 x	20.419486 =	20.419486
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.954000 =	1.908000

T.E =

4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
1447		.005000 x	59.035900 =	.295180
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.954000 =	1.908000

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	40.284450 =	.402845
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.954000 =	1.908000
201		.010000 x	290.000000 =	2.900000
		-----		
			T.E =	47.566929
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
003		1.000000 x	20.419486 =	20.419486
1447		.010000 x	59.035900 =	.590359
002		1.000000 x	17.312112 =	17.312112
201		.010000 x	290.000000 =	2.900000
265		2.000000 x	.954000 =	1.908000
		-----		
			T.E =	49.324957
4841	4841			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
4842	4842			
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	20.419486
4843	4843			
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.104872
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
001		10.000000 x	15.741598 =	157.415980
1401		.250000 x	234.711000 =	58.677750
003		25.000000 x	20.419486 =	510.487150
		-----		
			T.E =	1,506.580880
4845	4845			
132		620.000000 x	.930000 =	576.600000
003		15.000000 x	20.419486 =	306.292290
001		6.000000 x	15.741598 =	94.449588
1401		.180000 x	234.711000 =	42.247980
		-----		
			T.E =	1,019.589858

4851	4851			
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240
		-----		
			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717
		-----		
			T.E =	26.760717
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
003		4.000000 x	20.419486 =	81.677944
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	1,197.419542
5102	5102			
483		1.800000 x	.167500 =	.301500
488		.540000 x	5.500000 =	2.970000
489		.360000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400
		-----		
			T.E =	
5103	5103			
265		1.050000 x	.954000 =	1.001700
003		.200000 x	20.419486 =	4.083897
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	5.951203
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	34.546119
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
003		.500000 x	20.419486 =	10.209743
001		2.000000 x	15.741598 =	31.483196
		-----		
			T.E =	51.692939

5106	5106			
214		.050000 x	1,000.000000 =	50.000000
003		2.500000 x	20.419486 =	51.048715
001		2.000000 x	15.741598 =	31.483196
		-----		
			T.E =	132.531911
5201	5201			
201		1.100000 x	290.000000 =	319.000000
003		10.000000 x	20.419486 =	204.194860
002		5.000000 x	17.312112 =	86.560560
251		6.000000 x	.861000 =	5.166000
		-----		
			T.E =	614.921420
5202	5202			
203.2		1.080000 x	370.000000 =	399.600000
002		4.500000 x	17.312112 =	77.904504
003		9.000000 x	20.419486 =	183.775374
251		6.000000 x	.861000 =	5.166000
		-----		
			T.E =	666.445878
5203	5203			
201		1.120000 x	290.000000 =	324.800000
251		12.000000 x	.861000 =	10.332000
003		16.000000 x	20.419486 =	326.711776
002		8.000000 x	17.312112 =	138.496896
		-----		
			T.E =	800.340672
5204	5204			
203.2		1.100000 x	370.000000 =	407.000000
251		12.000000 x	.861000 =	10.332000
003		14.000000 x	20.419486 =	285.872804
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	824.389588
5211	5211			
201		1.100000 x	290.000000 =	319.000000
003		12.000000 x	20.419486 =	245.033832
002		6.000000 x	17.312112 =	103.872672
251		14.000000 x	.861000 =	12.054000
		-----		
			T.E =	679.960504

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
251		14.000000 x	.861000 =	12.054000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	
		-----			
			T.E =	702.409420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.861000 =	6.888000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
		-----			
			T.E =	587.567878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
		-----			
			T.E =	10.215603	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	
251		.100000 x	.861000 =	.086100	
		-----			
			T.E =	12.041845	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.861000 =	.086100	
002		.100000 x	17.312112 =	1.731211	
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	15.521208	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
		-----			
			T.E =	10.955603	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	
-----					
			T.E =	14.041208	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
251		.150000 x	.861000 =	.129150	
-----					
			T.E =	17.909864	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.861000 =	.129150	
002		.100000 x	17.312112 =	1.731211	
003		.250000 x	20.419486 =	5.104872	
-----					
			T.E =	13.625233	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
251		.150000 x	.861000 =	.129150	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	
-----					
			T.E =	16.561475	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.861000 =	.172200	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	
-----					
			T.E =	20.453888	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
251		.080000 x	.861000 =	.068880	
-----					
			T.E =	17.463728	

5237	5237				
203.2		.022000 x	370.000000 =		8.140000
251		.080000 x	.861000 =		.068880
002		.300000 x	17.312112 =		5.193634
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		20.549334
5238	5238				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.861000 =		.086100
003		.350000 x	20.419486 =		7.146820
002		.350000 x	17.312112 =		6.059239
		-----			
			T.E =		24.392159
5241	5241				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.861000 =		.086100
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056
		-----			
			T.E =		30.051899
5243	5243				
003		.150000 x	20.419486 =		3.062923
		-----			
			T.E =		3.062923
5244	5244				
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		7.146820
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	17.312112 =		8.656056
251		.200000 x	.861000 =		.172200
		-----			
			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
002		.600000 x	17.312112 =		10.387267
251		.100000 x	.861000 =		.086100
283		.100000 x	1.305700 =		.130570
		-----			
			T.E =		



5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
002		.300000 x	17.312112 =	5.193634	
003		.300000 x	20.419486 =	6.125846	
251		.100000 x	.861000 =	.086100	
		-----			
			T.E =	16.130579	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
245		.110000 x	18.600000 =	2.046000	
		-----			
			T.E =	116.834995	
5252.2	5252.2				
246		1.100000 x	12.000000 =	13.200000	
246		.110000 x	12.000000 =	1.320000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
		-----			
			T.E =	108.848995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
249		.110000 x	20.000000 =	2.200000	
		-----			
			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	
219		.060000 x	3.500000 =	.210000	
		-----			
			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.600000 x	.861000 =	.516600	
203.2		.025000 x	370.000000 =	9.250000	
		-----			
			T.E =	45.751878	

5262	5262			
201		.030000 x	290.000000 =	8.700000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
252		.200000 x	2.100000 =	.420000
265		.300000 x	.954000 =	.286200
203.2		.025000 x	370.000000 =	9.250000
251		.300000 x	.861000 =	.258300
-----				
			T.E =	56.646098
5266	5266			
201		.020000 x	290.000000 =	5.800000
251		.600000 x	.861000 =	.516600
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
203.2		.015000 x	370.000000 =	5.550000
-----				
			T.E =	34.505559
5267	5267			
201		.030000 x	290.000000 =	8.700000
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
265		.300000 x	.954000 =	.286200
252		.300000 x	2.100000 =	.630000
251		.300000 x	.861000 =	.258300
203.2		.015000 x	370.000000 =	5.550000
-----				
			T.E =	45.609778
5271	5271			
201		.016000 x	290.000000 =	4.640000
203.2		.025000 x	370.000000 =	9.250000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.600000 x	.861000 =	.516600
-----				
			T.E =	33.272399
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
203.2		.025000 x	370.000000 =	9.250000
252		.100000 x	2.100000 =	.210000
251		.300000 x	.861000 =	.258300
265		.200000 x	.954000 =	.190800
-----				
			T.E =	43.281219

5273	5273			
201		.016000 x	290.000000 =	4.640000
203.2		.015000 x	370.000000 =	5.550000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.600000 x	.861000 =	.516600
-----				
			T.E =	29.572399
5274	5274			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
265		.200000 x	.954000 =	.190800
252		.100000 x	2.100000 =	.210000
251		.300000 x	.861000 =	.258300
203.2		.015000 x	370.000000 =	5.550000
-----				
			T.E =	39.581219
5276	5276			
201		1.080000 x	290.000000 =	313.200000
003		19.000000 x	20.419486 =	387.970234
002		19.000000 x	17.312112 =	328.930128
252		18.000000 x	2.100000 =	37.800000
251		6.000000 x	.861000 =	5.166000
-----				
			T.E =	1,073.066362
5277	5277			
203.2		1.080000 x	370.000000 =	399.600000
003		18.000000 x	20.419486 =	367.550748
002		18.000000 x	17.312112 =	311.618016
252		18.000000 x	2.100000 =	37.800000
251		6.000000 x	.861000 =	5.166000
-----				
			T.E =	1,121.734764
5279	5279			
201		1.080000 x	290.000000 =	313.200000
003		10.000000 x	20.419486 =	204.194860
002		5.000000 x	17.312112 =	86.560560
251		12.000000 x	.861000 =	10.332000
-----				
			T.E =	614.287420

ΑΤΟΕ		2ο Τρίμηνο του 2011		Σελ.	100
				Ημ/νία	22/12/2011
5280	5280				
203.2		1.080000 x	370.000000 =		399.600000
251		12.000000 x	.861000 =		10.332000
002		5.000000 x	17.312112 =		86.560560
003		10.000000 x	20.419486 =		204.194860
-----					
				T.E =	700.687420
5281	5281				
203.2		.014000 x	370.000000 =		5.180000
251		.040000 x	.861000 =		.034440
002		.250000 x	17.312112 =		4.328028
-----					
				T.E =	9.542468
5282	5282				
203.2		.020000 x	370.000000 =		7.400000
251		.060000 x	.861000 =		.051660
002		.350000 x	17.312112 =		6.059239
-----					
				T.E =	13.510899
5283	5283				
203.2		.026000 x	370.000000 =		9.620000
002		.400000 x	17.312112 =		6.924845
251		.080000 x	.861000 =		.068880
-----					
				T.E =	16.613725
5286	5286				
203.2		.008000 x	370.000000 =		2.960000
251		.030000 x	.861000 =		.025830
002		.120000 x	17.312112 =		2.077453
003		.120000 x	20.419486 =		2.450338
-----					
				T.E =	7.513622
5288	5288				
003		.300000 x	20.419486 =		6.125846
-----					
				T.E =	6.125846
5289	5289				
003		1.000000 x	20.419486 =		20.419486
-----					
				T.E =	20.419486

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
220		26.000000 x	.000000 =	.000000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.200000 x	.861000 =	.172200
-----				
			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
220		26.000000 x	.000000 =	.000000
251		.200000 x	.861000 =	.172200
203.2		.010000 x	370.000000 =	3.700000
-----				
			T.E =	
5293	5293			
203.2		.020000 x	370.000000 =	7.400000
251		.150000 x	.861000 =	.129150
203.2		.016000 x	370.000000 =	5.920000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	28.541789
5294	5294			
203.2		.020000 x	370.000000 =	7.400000
203.2		.022000 x	370.000000 =	8.140000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.100000 x	.861000 =	.086100
-----				
			T.E =	30.718739
5295	5295			
203.2		.020000 x	370.000000 =	7.400000
002		.250000 x	17.312112 =	4.328028
003		.250000 x	20.419486 =	5.104872
251		.050000 x	.861000 =	.043050
-----				
			T.E =	16.875950
5301	5301			
226		1.050000 x	13.000000 =	13.650000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.250000 x	.861000 =	.215250
-----				
			T.E =	36.504209

5302	5302				
227		1.050000 x	13.000000 =	13.650000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
251		.200000 x	.861000 =	.172200	
-----					
			T.E =	32.687999	
5321	5321				
203.2		.012000 x	370.000000 =	4.440000	
226		1.050000 x	13.000000 =	13.650000	
002		.900000 x	17.312112 =	15.580901	
003		.900000 x	20.419486 =	18.377537	
251		.500000 x	.861000 =	.430500	
-----					
			T.E =	52.478938	
5322	5322				
203.2		.012000 x	370.000000 =	4.440000	
227		1.050000 x	13.000000 =	13.650000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.450000 x	.861000 =	.387450	
-----					
			T.E =	48.662728	
5323	5323				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.861000 =	.430500	
228		1.050000 x	35.000000 =	36.750000	
-----					
			T.E =	79.352098	
5324	5324				
203.2		.012000 x	370.000000 =	4.440000	
251		.500000 x	.861000 =	.430500	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
229		1.050000 x	.000000 =	.000000	
-----					
			T.E =		
5325	5325				
203.2		.012000 x	370.000000 =	4.440000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.861000 =	.430500	
230		1.050000 x	.000000 =	.000000	
-----					
			T.E =		

5326	5326				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.861000 =	.430500	
231		1.050000 x	22.000000 =	23.100000	
-----					
			T.E =	65.702098	
5341	5341				
203.2		.037000 x	370.000000 =	13.690000	
232		1.050000 x	45.000000 =	47.250000	
251		.600000 x	.861000 =	.516600	
002		1.100000 x	17.312112 =	19.043323	
003		1.100000 x	20.419486 =	22.461435	
-----					
			T.E =	102.961358	
5342	5342				
203.2		.037000 x	370.000000 =	13.690000	
232		1.100000 x	45.000000 =	49.500000	
251		.600000 x	.861000 =	.516600	
003		1.700000 x	20.419486 =	34.713126	
002		1.700000 x	17.312112 =	29.430590	
-----					
			T.E =	127.850317	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
233		.084000 x	21.300000 =	1.789200	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
-----					
			T.E =	54.339478	
5351	5351				
035		.200000 x	.086500 =	.017300	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.861000 =	.086100	
236		1.060000 x	2.000000 =	2.120000	
-----					
			T.E =	9.769720	
5352	5352				
035		.200000 x	.086500 =	.017300	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
237		1.060000 x	1.100000 =	1.166000	
-----					
			T.E =	8.815720	

5353	5353			
035		.200000 x	.086500 =	.017300
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		.100000 x	.861000 =	.086100
238		1.060000 x	2.600000 =	2.756000
-----				
			T.E =	10.405720
5354	5354			
035		.200000 x	.086500 =	.017300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.861000 =	.086100
239		1.060000 x	.000000 =	.000000
-----				
			T.E =	
5355	5355			
035		.200000 x	.086500 =	.017300
240		1.060000 x	1.400000 =	1.484000
251		.100000 x	.861000 =	.086100
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
-----				
			T.E =	9.133720
5356	5356			
035		.200000 x	.086500 =	.017300
003		.200000 x	20.419486 =	4.083897
241		1.060000 x	.000000 =	.000000
251		.100000 x	.861000 =	.086100
002		.200000 x	17.312112 =	3.462422
-----				
			T.E =	
5421	5421			
205		.055000 x	450.000000 =	24.750000
1471		1.000000 x	5.790099 =	5.790099
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
-----				
			T.E =	162.600692
5422	5422			
205		.035000 x	450.000000 =	15.750000
1472		1.000000 x	6.985163 =	6.985163
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336
-----				
			T.E =	135.929957



5426	5426			
205		.095000 x	450.000000 =	42.750000
1473		1.000000 x	11.946993 =	11.946993
1471		1.000000 x	5.790099 =	5.790099
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672

-----  
T.E = 286.876680

5427	5427			
205		.105000 x	450.000000 =	47.250000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402
1474		1.000000 x	14.498512 =	14.498512
1471		1.000000 x	5.790099 =	5.790099

-----  
T.E = 331.659797

5428	5428			
205		.075000 x	450.000000 =	33.750000
002		5.500000 x	17.312112 =	95.216616
003		5.500000 x	20.419486 =	112.307173
1474		1.000000 x	14.498512 =	14.498512
1472		1.000000 x	6.985163 =	6.985163

-----  
T.E = 262.757464

5431	5431			
205		.070000 x	450.000000 =	31.500000
002		7.000000 x	17.312112 =	121.184784
208		.030000 x	1,435.000000 =	43.050000
1475		1.000000 x	40.390657 =	40.390657
1471		1.000000 x	5.790099 =	5.790099
003		7.000000 x	20.419486 =	142.936402

-----  
T.E = 384.851942

5432	5432			
205		.070000 x	450.000000 =	31.500000
003		5.000000 x	20.419486 =	102.097430
1475		.800000 x	40.390657 =	32.312526
1471		1.000000 x	5.790099 =	5.790099
002		5.000000 x	17.312112 =	86.560560
380		1.000000 x	16.560000 =	16.560000

-----  
T.E = 274.820615

5436	5436			
205		.050000 x	450.000000 =	22.500000
003		4.500000 x	20.419486 =	91.887687
1476		1.000000 x	3.070600 =	3.070600
002		4.500000 x	17.312112 =	77.904504
		-----		
			T.E =	195.362791
5437	5437			
205		.065000 x	450.000000 =	29.250000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	220.978590
5438	5438			
205		.050000 x	450.000000 =	22.500000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	176.496992
5441.1	5441.1			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
223.3		.004000 x	.000000 =	.000000
		-----		
			T.E =	
5441.2	5441.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
223.3		.004000 x	1,500.000000 =	6.000000
		-----		
			T.E =	208.112791
5441.3	5441.3			
205		.065000 x	450.000000 =	29.250000
243.1		.550000 x	2.700000 =	1.485000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	203.597791

5442.1	5442.1			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5442.2	5442.2			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

233.728590

5442.3	5442.3			
205		.080000 x	450.000000 =	36.000000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.070600 =	3.070600
243.1		.055000 x	2.700000 =	.148500

T.E =

227.877090

5443.1	5443.1			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.3		.004000 x	.000000 =	.000000

T.E =

5443.2	5443.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

189.246992

5443.3	5443.3			
205		.065000 x	450.000000 =	29.250000
243.1		.550000 x	2.700000 =	1.485000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944

-----  
T.E = 184.731992

5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
222.2		.010000 x	.000000 =	.000000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944

-----  
T.E =

5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	3.070600 =	3.070600
002		4.000000 x	17.312112 =	69.248448
205		.025000 x	450.000000 =	11.250000

-----  
T.E = 191.496992

5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000
205		.040000 x	450.000000 =	18.000000

-----  
T.E =

5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
205		.040000 x	450.000000 =	18.000000
223.2		.010000 x	1,700.000000 =	17.000000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504

-----  
T.E = 217.112791

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.070600 =	3.070600
003		3.500000 x	20.419486 =	71.468201
205		.025000 x	450.000000 =	11.250000
002		3.500000 x	17.312112 =	60.592392
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
002		3.500000 x	17.312112 =	60.592392
1476		1.000000 x	3.070600 =	3.070600
003		3.500000 x	20.419486 =	71.468201
223.2		.010000 x	1,700.000000 =	17.000000

T.E =

172.631193

5449	5449			
205		.045000 x	450.000000 =	20.250000
1476		1.000000 x	3.070600 =	3.070600
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336
243.5		.850000 x	5.900000 =	5.015000

T.E =

141.530394

5451.1	5451.1			
205		.090000 x	450.000000 =	40.500000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.070600 =	3.070600
002		5.000000 x	17.312112 =	86.560560

T.E =

5451.2	5451.2			
205		.090000 x	450.000000 =	40.500000
223.3		.004000 x	1,500.000000 =	6.000000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

T.E =

238.228590

5451.3	5451.3			
205		.090000 x	450.000000 =	40.500000
243.1		.550000 x	2.700000 =	1.485000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	233.713590
5456	5456			
205		.055000 x	450.000000 =	24.750000
1478		1.000000 x	3.453100 =	3.453100
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
		-----		
			T.E =	179.129492
5457	5457			
205		.085000 x	450.000000 =	38.250000
261		2.200000 x	.598400 =	1.316480
003		7.000000 x	20.419486 =	142.936402
1476		1.500000 x	3.070600 =	4.605900
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	308.293566
5461.1	5461.1			
205		.065000 x	450.000000 =	29.250000
222.2		.010000 x	.000000 =	.000000
002		5.500000 x	17.312112 =	95.216616
1479		1.000000 x	37.938689 =	37.938689
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	
5461.2	5461.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,700.000000 =	17.000000
1479		1.000000 x	37.938689 =	37.938689
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
		-----		
			T.E =	291.712478
5462.1	5462.1			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	36.621317 =	36.621317
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.010000 x	.000000 =	.000000
		-----		
			T.E =	

5462.2	5462.2			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	36.621317 =	36.621317
003		5.500000 x	20.419486 =	112.307173
223.2		.010000 x	1,700.000000 =	17.000000
002		5.500000 x	17.312112 =	95.216616

-----  
T.E = 290.395106

5463.1	5463.1			
205		.055000 x	450.000000 =	24.750000
002		6.000000 x	17.312112 =	103.872672
1479		.500000 x	37.938689 =	18.969345
003		6.000000 x	20.419486 =	122.516916
222.2		.010000 x	.000000 =	.000000

-----  
T.E =

5463.2	5463.2			
205		.055000 x	450.000000 =	24.750000
223.2		.010000 x	1,700.000000 =	17.000000
003		6.000000 x	20.419486 =	122.516916
1479		.500000 x	37.938689 =	18.969345
002		6.000000 x	17.312112 =	103.872672

-----  
T.E = 287.108933

5464.1	5464.1			
205		.070000 x	450.000000 =	31.500000
222.2		.010000 x	.000000 =	.000000
1479		.500000 x	37.938689 =	18.969345
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

-----  
T.E =

5464.2	5464.2			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	37.938689 =	18.969345
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
223.2		.010000 x	1,700.000000 =	17.000000

-----  
T.E = 331.590531

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
003		5.500000 x	20.419486 =	112.307173
1476		1.000000 x	3.070600 =	3.070600
002		5.500000 x	17.312112 =	95.216616
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,435.000000 =	43.050000
-----				

T.E =

5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
002		5.500000 x	17.312112 =	95.216616
1476		1.000000 x	3.070600 =	3.070600
003		5.500000 x	20.419486 =	112.307173
223.2		.005000 x	1,700.000000 =	8.500000
208		.030000 x	1,435.000000 =	43.050000
-----				

T.E =

278.794389

5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
002		5.000000 x	17.312112 =	86.560560
1479		.900000 x	37.938689 =	34.144820
003		5.000000 x	20.419486 =	102.097430
222.2		.010000 x	.000000 =	.000000
-----				

T.E =

5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
003		5.000000 x	20.419486 =	102.097430
1479		.900000 x	37.938689 =	34.144820
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,700.000000 =	17.000000
-----				

T.E =

249.052810

5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
222.2		.000960 x	.000000 =	.000000
222.2		.012000 x	.000000 =	.000000
203.2		.001040 x	370.000000 =	.384800
-----				

T.E =



5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
223.2		.000960 x	1,700.000000 =	1.632000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.012000 x	1,700.000000 =	20.400000
-----				
			T.E =	159.287393
5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
203.2		.002000 x	370.000000 =	.740000
222.2		.010000 x	.000000 =	.000000
222.2		.000800 x	.000000 =	.000000
-----				
			T.E =	
5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
203.2		.002000 x	370.000000 =	.740000
223.2		.000800 x	1,700.000000 =	1.360000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000
-----				
			T.E =	179.276392
5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.500000 x	37.938689 =	18.969345
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
002		4.500000 x	17.312112 =	77.904504
1479		.500000 x	37.938689 =	18.969345
003		4.500000 x	20.419486 =	91.887687
-----				
			T.E =	215.011536

5471	5471				
203.2		.035000 x	370.000000 =		12.950000
251		3.000000 x	.861000 =		2.583000
002		3.500000 x	17.312112 =		60.592392
003		3.500000 x	20.419486 =		71.468201
		-----			
			T.E =		147.593593
5472.1	5472.1				
203.2		.026000 x	370.000000 =		9.620000
251		3.000000 x	.861000 =		2.583000
222.4		.010000 x	.000000 =		.000000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
		-----			
			T.E =		
5472.2	5472.2				
203.2		.026000 x	370.000000 =		9.620000
251		3.000000 x	.861000 =		2.583000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
223.4		.010000 x	1,580.000000 =		15.800000
		-----			
			T.E =		160.063593
5501.1	5501.1				
211		.040000 x	750.000000 =		30.000000
251		.050000 x	.861000 =		.043050
002		2.500000 x	17.312112 =		43.280280
003		5.000000 x	20.419486 =		102.097430
252		.100000 x	2.100000 =		.210000
		-----			
			T.E =		175.630760
5501.2	5501.2				
212		.040000 x	1,500.000000 =		60.000000
251		.050000 x	.861000 =		.043050
252		.100000 x	2.100000 =		.210000
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280
		-----			
			T.E =		205.630760
5502	5502				
210		.040000 x	.000000 =		.000000
251		.050000 x	.861000 =		.043050
003		4.000000 x	20.419486 =		81.677944
002		2.000000 x	17.312112 =		34.624224
252		.100000 x	2.100000 =		.210000
		-----			
			T.E =		

5511.1	5511.1			
211		.020000 x	750.000000 =	15.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	2.100000 =	.210000
		-----		
			T.E =	108.251734
5511.2	5511.2			
212		.020000 x	1,500.000000 =	30.000000
252		.100000 x	2.100000 =	.210000
002		1.600000 x	17.312112 =	27.699379
003		3.200000 x	20.419486 =	65.342355
		-----		
			T.E =	123.251734
5512	5512			
205		.020000 x	450.000000 =	9.000000
252		.100000 x	2.100000 =	.210000
003		3.000000 x	20.419486 =	61.258458
002		1.500000 x	17.312112 =	25.968168
		-----		
			T.E =	96.436626
5513.1	5513.1			
211		.020000 x	750.000000 =	15.000000
252		.100000 x	2.100000 =	.210000
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	131.512168
5513.2	5513.2			
212		.020000 x	1,500.000000 =	30.000000
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
252		.100000 x	2.100000 =	.210000
		-----		
			T.E =	146.512168
5514	5514			
205		.020000 x	450.000000 =	9.000000
003		3.800000 x	20.419486 =	77.594047
252		.100000 x	2.100000 =	.210000
002		1.800000 x	17.312112 =	31.161802
		-----		
			T.E =	117.965848

5521	5521				
205		.030000 x	450.000000 =		13.500000
002		.800000 x	17.312112 =		13.849690
003		2.000000 x	20.419486 =		40.838972
252		.150000 x	2.100000 =		.315000
				T.E =	68.503662
5531.1	5531.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	2.100000 =		.042000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
				T.E =	64.583348
5531.2	5531.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.100000 =		.042000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
				T.E =	72.083348
5531.3	5531.3				
205		.010000 x	450.000000 =		4.500000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
252		.020000 x	2.100000 =		.042000
				T.E =	61.583348
5532.1	5532.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	2.100000 =		.042000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
				T.E =	86.112570
5532.2	5532.2				
212		.010000 x	1,500.000000 =		15.000000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
252		.020000 x	2.100000 =		.042000
				T.E =	93.612570

5532.3	5532.3			
205		.010000 x	450.000000 =	4.500000
003		3.000000 x	20.419486 =	61.258458
252		.020000 x	2.100000 =	.042000
002		1.000000 x	17.312112 =	17.312112
		-----		
			T.E =	83.112570
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	8.931820
5601	5601			
203.2		.028000 x	370.000000 =	10.360000
251		4.000000 x	.861000 =	3.444000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	108.132995
5602	5602			
203.2		.018000 x	370.000000 =	6.660000
003		2.300000 x	20.419486 =	46.964818
002		2.300000 x	17.312112 =	39.817858
251		3.000000 x	.861000 =	2.583000
		-----		
			T.E =	96.025675
5603	5603			
203.2		.013000 x	370.000000 =	4.810000
003		2.000000 x	20.419486 =	40.838972
002		2.000000 x	17.312112 =	34.624224
251		2.500000 x	.861000 =	2.152500
		-----		
			T.E =	82.425696
5604	5604			
243.5		1.100000 x	5.900000 =	6.490000
003		2.200000 x	20.419486 =	44.922869
002		2.200000 x	17.312112 =	38.086646
243.5		.165000 x	5.900000 =	.973500
		-----		
			T.E =	90.473016

5605	5605				
243.3		1.100000 x	4.500000 =	4.950000	
243.3		.187000 x	4.500000 =	.841500	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
		-----			
			T.E =	81.254696	
5606	5606				
243.2		1.100000 x	3.800000 =	4.180000	
003		1.800000 x	20.419486 =	36.755075	
002		1.800000 x	17.312112 =	31.161802	
243.2		.220000 x	3.800000 =	.836000	
		-----			
			T.E =	72.932876	
5607	5607				
205		.012000 x	450.000000 =	5.400000	
002		2.500000 x	17.312112 =	43.280280	
205		.002400 x	450.000000 =	1.080000	
242		2.200000 x	1.500000 =	3.300000	
003		2.500000 x	20.419486 =	51.048715	
242		.440000 x	1.500000 =	.660000	
		-----			
			T.E =	104.768995	
5608.1	5608.1				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	
		-----			
			T.E =		
5608.2	5608.2				
205		.012000 x	450.000000 =	5.400000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
223.1		.006000 x	2,100.000000 =	12.600000	
223.1		.001200 x	2,100.000000 =	2.520000	
205		.002400 x	450.000000 =	1.080000	
		-----			
			T.E =	153.660593	

5611	5611			
205		.060000 x	450.000000 =	27.000000
251		5.000000 x	.861000 =	4.305000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
-----				
			T.E =	295.426186
5612.1	5612.1			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
222.1		.006000 x	.000000 =	.000000
251		5.000000 x	.861000 =	4.305000
-----				
			T.E =	
5612.2	5612.2			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.861000 =	4.305000
223.1		.006000 x	2,100.000000 =	12.600000
-----				
			T.E =	308.026186
5613.1	5613.1			
205		.015000 x	450.000000 =	6.750000
002		1.500000 x	17.312112 =	25.968168
205		.001500 x	450.000000 =	.675000
003		1.500000 x	20.419486 =	30.629229
222.2		.003000 x	.000000 =	.000000
-----				
			T.E =	
5613.2	5613.2			
205		.015000 x	450.000000 =	6.750000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
223.2		.003000 x	1,700.000000 =	5.100000
205		.001500 x	450.000000 =	.675000
-----				
			T.E =	69.122397
5614.1	5614.1			
205		.010000 x	450.000000 =	4.500000
222.2		.002000 x	.000000 =	.000000
205		.001500 x	450.000000 =	.675000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
-----				
			T.E =	

5614.2	5614.2			
205		.010000 x	450.000000 =	4.500000
003		1.200000 x	20.419486 =	24.503383
205		.001500 x	450.000000 =	.675000
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,700.000000 =	3.400000
			T.E =	53.852918
5615.1	5615.1			
205		.008000 x	450.000000 =	3.600000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	450.000000 =	.648000
			T.E =	
5615.2	5615.2			
205		.008000 x	450.000000 =	3.600000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,700.000000 =	1.530000
205		.001440 x	450.000000 =	.648000
			T.E =	43.509598
5616	5616			
205		.003000 x	450.000000 =	1.350000
205		.007500 x	450.000000 =	3.375000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
			T.E =	42.456598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
521		.250000 x	2.461700 =	.615425
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
			T.E =	42.747023
5619	5619			
205		.001400 x	450.000000 =	.630000
003		.200000 x	20.419486 =	4.083897
			T.E =	4.713897



5620	5620			
203.2		.012000 x	370.000000 =	4.440000
251		.020000 x	.861000 =	.017220
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
220		4.200000 x	.000000 =	.000000
-----				
			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.861000 =	13.776000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
-----				
			T.E =	
5622	5622			
211		1.100000 x	750.000000 =	825.000000
251		16.000000 x	.861000 =	13.776000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
-----				
			T.E =	1,970.723940
5626	5626			
205		.030000 x	450.000000 =	13.500000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
251		1.000000 x	.861000 =	.861000
-----				
			T.E =	70.958397
6101	6101			
267		1.050000 x	1.024000 =	1.075200
003		.050000 x	20.419486 =	1.020974
-----				
			T.E =	2.096174
6102	6102			
252		.050000 x	2.100000 =	.105000
003		.060000 x	20.419486 =	1.225169
267		1.030000 x	1.024000 =	1.054720
-----				
			T.E =	2.384889
6103	6103			
268		1.050000 x	1.171500 =	1.230075
003		.050000 x	20.419486 =	1.020974
-----				
			T.E =	2.251049

6104	6104			
252		.050000 x	2.100000 =	.105000
268		1.030000 x	1.171500 =	1.206645
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	2.536814
6111	6111			
266		1.100000 x	.713000 =	.784300
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	3.847223
6116	6116			
280		1.050000 x	1.000000 =	1.050000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	3.091949
6117	6117			
281		1.050000 x	5.780000 =	6.069000
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	9.131923
6118	6118			
266		1.150000 x	.713000 =	.819950
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	8.366270
6119	6119			
293		1.100000 x	.000000 =	.000000
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	
6120	6120			
289		1.050000 x	.904700 =	.949935
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.991884
6121	6121			
266		1.100000 x	.713000 =	.784300
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	8.330620

6122	6122				
265		1.050000 x	.954000 =		1.001700
003		.200000 x	20.419486 =		4.083897
		-----			
			T.E =		5.085597
6123	6123				
265		.900000 x	.954000 =		.858600
266		.010000 x	.713000 =		.007130
265		.090000 x	.954000 =		.085860
003		.150000 x	20.419486 =		3.062923
002		.150000 x	17.312112 =		2.596817
266		.100000 x	.713000 =		.071300
		-----			
			T.E =		6.682630
6126	6126				
265		1.250000 x	.954000 =		1.192500
003		.200000 x	20.419486 =		4.083897
003		.200000 x	20.419486 =		4.083897
		-----			
			T.E =		9.360294
6127	6127				
290		4.800000 x	3.500000 =		16.800000
002		.800000 x	17.312112 =		13.849690
003		.800000 x	20.419486 =		16.335589
		-----			
			T.E =		46.985278
6128	6128				
290		1.200000 x	3.500000 =		4.200000
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897
		-----			
			T.E =		11.746320
6201	6201				
264		1.400000 x	1.257500 =		1.760500
003		.250000 x	20.419486 =		5.104872
002		.250000 x	17.312112 =		4.328028
		-----			
			T.E =		11.193400
6202	6202				
264		1.300000 x	1.257500 =		1.634750
003		.200000 x	20.419486 =		4.083897
002		.200000 x	17.312112 =		3.462422
		-----			
			T.E =		9.181070

6203	6203				
282		1.200000 x	1.094000 =	1.312800	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	14.518859	
6204	6204				
282		1.300000 x	1.094000 =	1.422200	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	16.514839	
6205	6205				
277		1.250000 x	1.119000 =	1.398750	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	20.264549	
6221	6221				
265		1.150000 x	.954000 =	1.097100	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
		-----			
			T.E =	8.643420	
6222	6222				
265		1.200000 x	.954000 =	1.144800	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	
		-----			
			T.E =	14.350859	
6223	6223				
265		1.250000 x	.954000 =	1.192500	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
		-----			
			T.E =	20.058299	
6224	6224				
271		.720000 x	1.111500 =	.800280	
003		.200000 x	20.419486 =	4.083897	
282		.480000 x	1.094000 =	.525120	
002		.200000 x	17.312112 =	3.462422	
		-----			
			T.E =	8.871720	

6225	6225			
271		.720000 x	1.111500 =	.800280
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
282		.480000 x	1.094000 =	.525120
		-----		
			T.E =	10.758300
6226	6226			
265		1.200000 x	.954000 =	1.144800
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	27.556919
6227	6227			
265		1.250000 x	.954000 =	1.192500
003		.850000 x	20.419486 =	17.356563
002		.850000 x	17.312112 =	14.715295
		-----		
			T.E =	33.264358
6228	6228			
282		1.250000 x	1.094000 =	1.367500
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	16.460139
6229	6229			
282		1.250000 x	1.094000 =	1.367500
002		.450000 x	17.312112 =	7.790450
003		.450000 x	20.419486 =	9.188769
		-----		
			T.E =	18.346719
6230	6230			
277		1.100000 x	1.119000 =	1.230900
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	20.096699
6231	6231			
265		1.150000 x	.954000 =	1.097100
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	10.530000

6232	6232			
265		1.150000 x	.954000 =	1.097100
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	16.189739
6236	6236			
253		.500000 x	2.652000 =	1.326000
392		.350000 x	27.420000 =	9.597000
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
565.3		.350000 x	3.800000 =	1.330000
390		2.100000 x	1.500000 =	3.150000
276		5.850000 x	.873000 =	5.107050
266		2.000000 x	.713000 =	1.426000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		1.500000 x	1.001500 =	1.502250
		-----		
			T.E =	118.480176
6237	6237			
253		.850000 x	2.652000 =	2.254200
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.650000 =	1.977500
392		.350000 x	27.420000 =	9.597000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	1.001500 =	5.007500
266		2.100000 x	.713000 =	1.497300
260		9.500000 x	.545500 =	5.182250
		-----		
			T.E =	203.567142
6238	6238			
253		.400000 x	2.652000 =	1.060800
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
266		13.000000 x	.713000 =	9.269000
265		6.000000 x	.954000 =	5.724000
		-----		
			T.E =	204.711790
6239	6239			
277		1.100000 x	1.119000 =	1.230900
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	12.550379

6301	6301			
266		1.250000 x	.713000 =	.891250
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	15.983889
6302	6302			
266		9.000000 x	.713000 =	6.417000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	138.477593
6401	6401			
265		1.150000 x	.954000 =	1.097100
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	8.643420
6402	6402			
265		1.200000 x	.954000 =	1.144800
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	12.464279
6403	6403			
265		1.250000 x	.954000 =	1.192500
003		.350000 x	20.419486 =	7.146820
002		.350000 x	17.312112 =	6.059239
		-----		
			T.E =	14.398559
6406	6406			
265		1.200000 x	.954000 =	1.144800
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	23.783759
6407	6407			
265		1.250000 x	.954000 =	1.192500
002		.700000 x	17.312112 =	12.118478
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	27.604619

6411	6411				
565.3		1.650000 x	3.800000 =	6.270000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	19.476059	
6412	6412				
565.5		1.550000 x	5.650000 =	8.757500	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	
		-----			
			T.E =	25.736719	
6413	6413				
565.6		1.450000 x	7.800000 =	11.310000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	
		-----			
			T.E =	32.062379	
6416	6416				
566.3		1.600000 x	5.050000 =	8.080000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	21.286059	
6417	6417				
566.5		1.500000 x	7.750000 =	11.625000	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	
		-----			
			T.E =	28.604219	
6418	6418				
566.6		1.400000 x	10.300000 =	14.420000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	
		-----			
			T.E =	35.172379	
6421	6421				
565.3		1.050000 x	3.800000 =	3.990000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	12.157794	



6422	6422				
565.5		1.050000 x	5.650000 =	5.932500	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	16.142243	
6423	6423				
565.6		1.050000 x	7.800000 =	8.190000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	20.441692	
6426	6426				
566.3		1.050000 x	5.050000 =	5.302500	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	13.470294	
6427	6427				
566.5		1.050000 x	7.750000 =	8.137500	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	18.347243	
6428	6428				
566.6		1.050000 x	10.300000 =	10.815000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	23.066692	
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	7.022923	
6432	6432				
251		.100000 x	.861000 =	.086100	
279		1.080000 x	3.720000 =	4.017600	
002		.250000 x	17.312112 =	4.328028	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	13.536600	
6441	6441				
266		1.100000 x	.713000 =	.784300	
002		.100000 x	17.312112 =	1.731211	
003		.100000 x	20.419486 =	2.041949	
		-----			
			T.E =	4.557460	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.419486 =	.816779
-----				
			T.E =	
6446.2	6446.2			
285		1.100000 x	.075000 =	.082500
003		.040000 x	20.419486 =	.816779
-----				
			T.E =	.899279
6447	6447			
251		.050000 x	.861000 =	.043050
286		1.050000 x	1.788000 =	1.877400
002		.100000 x	17.312112 =	1.731211
003		.100000 x	20.419486 =	2.041949
-----				
			T.E =	5.693610
6448	6448			
251		.050000 x	.861000 =	.043050
002		.100000 x	17.312112 =	1.731211
288		1.050000 x	1.940600 =	2.037630
003		.100000 x	20.419486 =	2.041949
-----				
			T.E =	5.853840
6501	6501			
282		3.000000 x	1.094000 =	3.282000
295		11.000000 x	6.490000 =	71.390000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
296		1.000000 x	12.990000 =	12.990000
-----				
			T.E =	238.588392
6502	6502			
002		1.500000 x	17.312112 =	25.968168
6501		1.000000 x	238.588392 =	238.588392
003		1.500000 x	20.419486 =	30.629229
-----				
			T.E =	295.185789
6503	6503			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.950000 x	238.588392 =	226.658972
-----				
			T.E =	275.710050

6504	6504			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.910000 x	238.588392 =	217.115437
		-----		
			T.E =	262.393354
6505	6505			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.870000 x	238.588392 =	207.571901
		-----		
			T.E =	245.303499
6506	6506			
002		1.000000 x	17.312112 =	17.312112
6501		.810000 x	238.588392 =	193.256598
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	230.988196
6507	6507			
002		.900000 x	17.312112 =	15.580901
6501		.920000 x	238.588392 =	219.501321
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	253.459759
6508	6508			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.030000 x	238.588392 =	245.746044
		-----		
			T.E =	294.797121
6509	6509			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		1.010000 x	238.588392 =	240.974276
		-----		
			T.E =	278.705874
6510	6510			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.080000 x	238.588392 =	257.675463
		-----		
			T.E =	302.953381

6511	6511			
002		1.500000 x	17.312112 =	25.968168
6501		.920000 x	238.588392 =	219.501321
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	276.098718
6512	6512			
002		1.400000 x	17.312112 =	24.236957
6501		.820000 x	238.588392 =	195.642481
003		1.400000 x	20.419486 =	28.587280
		-----		
			T.E =	248.466719
6513	6513			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.780000 x	238.588392 =	186.098946
		-----		
			T.E =	235.150023
6514	6514			
002		1.200000 x	17.312112 =	20.774534
6501		.760000 x	238.588392 =	181.327178
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	226.605096
6515	6515			
002		1.000000 x	17.312112 =	17.312112
6501		.800000 x	238.588392 =	190.870714
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	228.602312
6516	6516			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.220000 x	238.588392 =	291.077838
		-----		
			T.E =	340.128916
6517	6517			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.120000 x	238.588392 =	267.218999
		-----		
			T.E =	312.496917

6518	6518			
002		1.100000 x	17.312112 =	19.043323
003		1.100000 x	20.419486 =	22.461435
6501		.670000 x	238.588392 =	159.854223
		-----		
			T.E =	201.358980
6519	6519			
002		1.300000 x	17.312112 =	22.505746
6501		1.280000 x	238.588392 =	305.393142
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	354.444219
6520	6520			
002		1.200000 x	17.312112 =	20.774534
6501		1.120000 x	238.588392 =	267.218999
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	312.496917
6521	6521			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.210000 x	238.588392 =	288.691954
		-----		
			T.E =	337.743032
6522	6522			
002		1.200000 x	17.312112 =	20.774534
6501		1.190000 x	238.588392 =	283.920186
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	329.198104
6523	6523			
002		1.200000 x	17.312112 =	20.774534
6501		1.280000 x	238.588392 =	305.393142
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	350.671059
6524	6524			
002		1.200000 x	17.312112 =	20.774534
6501		.800000 x	238.588392 =	190.870714
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	236.148631

6525	6525				
002		1.200000 x	17.312112 =	20.774534	
6501		1.040000 x	238.588392 =	248.131928	
003		1.200000 x	20.419486 =	24.503383	
		-----			
			T.E =	293.409845	
6526	6526				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.900000 x	238.588392 =	214.729553	
		-----			
			T.E =	263.780630	
6527	6527				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.120000 x	238.588392 =	267.218999	
		-----			
			T.E =	316.270076	
6528	6528				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.840000 x	238.588392 =	200.414249	
		-----			
			T.E =	245.692167	
6529	6529				
002		1.200000 x	17.312112 =	20.774534	
6501		1.080000 x	238.588392 =	257.675463	
003		1.200000 x	20.419486 =	24.503383	
		-----			
			T.E =	302.953381	
6530	6530				
002		1.000000 x	17.312112 =	17.312112	
6501		.710000 x	238.588392 =	169.397758	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	207.129356	
6531	6531				
002		.600000 x	17.312112 =	10.387267	
6501		.480000 x	238.588392 =	114.522428	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	137.161387	

6532	6532				
294		6.000000 x	3.687800 =	22.126800	
296		1.000000 x	12.990000 =	12.990000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
294		.300000 x	3.687800 =	1.106340	
			T.E =	130.552135	
6541	6541				
282		.350000 x	1.094000 =	.382900	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
296		.120000 x	12.990000 =	1.558800	
295		1.050000 x	6.490000 =	6.814500	
			T.E =	27.621999	
6542	6542				
295		1.050000 x	6.490000 =	6.814500	
296		.100000 x	12.990000 =	1.299000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
			T.E =	38.298778	
6543	6543				
295		.400000 x	6.490000 =	2.596000	
296		.130000 x	12.990000 =	1.688700	
003		.200000 x	20.419486 =	4.083897	
			T.E =	8.368597	
7101	7101				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.946500 =	.619465	
002		.500000 x	17.312112 =	8.656056	
003		.850000 x	20.419486 =	17.356563	
			T.E =	26.777084	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.946500 =	.619465	
002		.400000 x	17.312112 =	6.924845	
003		.700000 x	20.419486 =	14.293640	
			T.E =	21.982950	

7103	7103				
201		.000500 x	290.000000 =	.145000	
1445		.004000 x	61.946500 =	.247786	
003		.600000 x	20.419486 =	12.251692	
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	17.838111	
7104	7104				
201		.000500 x	290.000000 =	.145000	
002		.600000 x	17.312112 =	10.387267	
1445		.008000 x	61.946500 =	.495572	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	31.447325	
7111	7111				
201		.000500 x	290.000000 =	.145000	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.741598 =	4.722479	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	17.909302	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.616750 =	1.123652	
001		.350000 x	15.741598 =	5.509559	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	20.050877	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.946500 =	1.672556	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	22.875624	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	76.007500 =	2.052203	
001		.300000 x	15.741598 =	4.722479	
003		.800000 x	20.419486 =	16.335589	
		-----			
			T.E =	23.255271	



7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	87.681250 =		1.315219
1446		.006000 x	52.880500 =		.317283
001		.300000 x	15.741598 =		4.722479
1445		.006000 x	61.946500 =		.371679
003		.900000 x	20.419486 =		18.377537
				T.E =	25.249198
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	15.741598 =		4.722479
1445		.012000 x	61.946500 =		.743358
1465		.015000 x	94.188150 =		1.412822
003		.900000 x	20.419486 =		18.377537
				T.E =	25.401197
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	92.094750 =		1.381421
1445		.012000 x	61.946500 =		.743358
003		.900000 x	20.419486 =		18.377537
001		.300000 x	15.741598 =		4.722479
				T.E =	25.369796
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	87.210150 =		1.308152
1445		.012000 x	61.946500 =		.743358
001		.300000 x	15.741598 =		4.722479
003		.900000 x	20.419486 =		18.377537
				T.E =	25.296527
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	29.264100 =		.614546
1426		.006000 x	152.456250 =		.914738
001		.300000 x	15.741598 =		4.722479
003		.600000 x	20.419486 =		12.251692
				T.E =	18.648455

7132	7132			
201		.000500 x	290.000000 =	.145000
1427		.006000 x	163.304700 =	.979828
1418		.021000 x	41.616750 =	.873952
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	20.781005
7133	7133			
201		.000500 x	290.000000 =	.145000
1463		.015000 x	74.871250 =	1.123069
1427		.006000 x	163.304700 =	.979828
1418		.006000 x	41.616750 =	.249701
003		.600000 x	20.419486 =	12.251692
001		.350000 x	15.741598 =	5.509559
-----				
			T.E =	20.258848
7134	7134			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
003		.600000 x	20.419486 =	12.251692
1464		.015000 x	56.673600 =	.850104
1427		.006000 x	163.304700 =	.979828
1418		.006000 x	41.616750 =	.249701
-----				
			T.E =	19.985884
7136	7136			
201		.000500 x	290.000000 =	.145000
001		.250000 x	15.741598 =	3.935400
1418		.017000 x	41.616750 =	.707485
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	12.955679
7138	7138			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1418		.027000 x	41.616750 =	1.123652
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	22.326720
7141	7141			
201		.000500 x	290.000000 =	.145000
1445		.027000 x	61.946500 =	1.672556
003		1.000000 x	20.419486 =	20.419486
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	28.533681

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
001		.350000 x	15.741598 =	5.509559
1413		.007000 x	29.264100 =	.204849
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	29.264100 =	.409697
001		.450000 x	15.741598 =	7.083719
1422		.016000 x	.000000 =	.000000
003		.600000 x	20.419486 =	12.251692

-----  
T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
003		.600000 x	20.419486 =	12.251692
001		.450000 x	15.741598 =	7.083719

-----  
T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
1418		.014000 x	41.616750 =	.582635
1422		.016000 x	.000000 =	.000000

-----  
T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.007000 x	41.616750 =	.291317
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.304700 =	1.143133
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
1447		.014000 x	59.035900 =	.826503
1448		.016000 x	.000000 =	.000000
001		.450000 x	15.741598 =	7.083719
003		.700000 x	20.419486 =	14.293640

-----  
T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	59.035900 =	.413251
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

-----  
T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1453		.020000 x	187.752750 =	3.755055
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

-----  
T.E = 75.165394

7162	7162			
201		.000800 x	290.000000 =	.232000
002		1.600000 x	17.312112 =	27.699379
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
001		.600000 x	15.741598 =	9.444959

-----  
T.E =

7163	7163			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.741598 =	9.444959
003		1.600000 x	20.419486 =	32.671178
1445		.022000 x	61.946500 =	1.362823
1454		.020000 x	210.972750 =	4.219455
002		1.600000 x	17.312112 =	27.699379

T.E = 75.629794

7164	7164			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.741598 =	9.444959
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379

T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
1459		.020000 x	210.972750 =	4.219455
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E = 75.629794

7166	7166			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
1445		.022000 x	61.946500 =	1.362823
1453		.017000 x	187.752750 =	3.191797
002		1.200000 x	17.312112 =	20.774534

T.E = 57.935336

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
1454		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
		-----		
			T.E =	58.330076
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
003		1.200000 x	20.419486 =	24.503383
1459		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.946500 =	1.362823
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	58.330076
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435
		-----		
			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	18.377537

7179	7179			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7181	7181			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
7206	7206			
142		26.000000 x	.340000 =	8.840000
1412		.040000 x	27.931800 =	1.117272
002		.300000 x	17.312112 =	5.193634
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	27.402597
7207	7207			
142		26.000000 x	.340000 =	8.840000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	20.419486 =	10.209743
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	23.936407
7208	7208			
142		26.000000 x	.340000 =	8.840000
003		.400000 x	20.419486 =	8.167794
1412		.025000 x	27.931800 =	.698295
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	21.168512
7209	7209			
142		26.000000 x	.340000 =	8.840000
1412		.005000 x	27.931800 =	.139659
003		.300000 x	20.419486 =	6.125846
002		.150000 x	17.312112 =	2.596817
		-----		
			T.E =	17.702322
7211	7211			
146		15.000000 x	.370000 =	5.550000
1445		.001000 x	61.946500 =	.061947
003		.400000 x	20.419486 =	8.167794
002		.200000 x	17.312112 =	3.462422
283		.075000 x	1.305700 =	.097928
		-----		
			T.E =	17.340091

7221	7221				
203.2		.001500 x	370.000000 =	.555000	
003		.200000 x	20.419486 =	4.083897	
492		.200000 x	.540000 =	.108000	
002		.150000 x	17.312112 =	2.596817	
506		1.150000 x	1.431700 =	1.646455	
254		.020000 x	3.532000 =	.070640	
			T.E =	9.060809	
7222	7222				
254		.050000 x	3.532000 =	.176600	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	
506		1.200000 x	1.431700 =	1.718040	
492		.200000 x	.540000 =	.108000	
			T.E =	9.704328	
7223	7223				
254		.050000 x	3.532000 =	.176600	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
508		1.200000 x	.860000 =	1.032000	
493		.200000 x	.730000 =	.146000	
			T.E =	8.900920	
7231	7231				
274		1.200000 x	1.525100 =	1.830120	
274		.200000 x	1.525100 =	.305020	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
			T.E =	11.568040	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
001		.200000 x	15.741598 =	3.148320	
495		.500000 x	.000000 =	.000000	
002		1.400000 x	17.312112 =	24.236957	
003		1.400000 x	20.419486 =	28.587280	
			T.E =		



7242	7242			
297.2		.057000 x	.000000 =	.000000
001		.200000 x	15.741598 =	3.148320
495		1.000000 x	.000000 =	.000000
003		2.800000 x	20.419486 =	57.174561
002		2.800000 x	17.312112 =	48.473914
		-----		
			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
251		1.300000 x	.861000 =	1.119300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
251		1.300000 x	.861000 =	1.119300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		1.300000 x	.861000 =	1.119300
		-----		
			T.E =	
7244	7244			
251		1.200000 x	.861000 =	1.033200
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
273		1.200000 x	1.236500 =	1.483800
		-----		
			T.E =	40.248598
7245	7245			
251		.500000 x	.861000 =	.430500
273		1.200000 x	1.236500 =	1.483800
002		.700000 x	17.312112 =	12.118478
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	28.326419

7246 7246

265	.500000 x	.954000 =	.477000
298.1	6.700000 x	6.920000 =	46.364000
002	1.000000 x	17.312112 =	17.312112
003	1.000000 x	20.419486 =	20.419486

T.E = 84.572598

7301 7301

096	1.050000 x	.000000 =	.000000
1445	.025000 x	61.946500 =	1.548663
001	.400000 x	15.741598 =	6.296639
1444	.001500 x	76.007500 =	.114011
003	.900000 x	20.419486 =	18.377537

T.E =

7302 7302

097	1.050000 x	.000000 =	.000000
1445	.025000 x	61.946500 =	1.548663
1444	.002000 x	76.007500 =	.152015
003	1.000000 x	20.419486 =	20.419486
001	.500000 x	15.741598 =	7.870799

T.E =

7303 7303

096	1.100000 x	.000000 =	.000000
001	1.000000 x	15.741598 =	15.741598
003	2.000000 x	20.419486 =	40.838972
1445	.025000 x	61.946500 =	1.548663
1444	.001000 x	76.007500 =	.076008

T.E =

7304 7304

096	1.100000 x	.000000 =	.000000
1445	.025000 x	61.946500 =	1.548663
001	.800000 x	15.741598 =	12.593278
1444	.001500 x	76.007500 =	.114011
003	1.600000 x	20.419486 =	32.671178

T.E =

7305 7305

096	.160000 x	.000000 =	.000000
001	.150000 x	15.741598 =	2.361240
1444	.000200 x	76.007500 =	.015202
1445	.004000 x	61.946500 =	.247786
003	.300000 x	20.419486 =	6.125846

T.E =

7311	7311			
098		1.150000 x	.000000 =	.000000
1445		.005000 x	61.946500 =	.309733
1417		.033000 x	40.284450 =	1.329387
003		2.200000 x	20.419486 =	44.922869
001		.600000 x	15.741598 =	9.444959
-----				
			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
003		1.100000 x	20.419486 =	22.461435
1417		.033000 x	40.284450 =	1.329387
1445		.005000 x	61.946500 =	.309733
-----				
			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1417		.022000 x	40.284450 =	.886258
1445		.004000 x	61.946500 =	.247786
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1449		.030000 x	53.460700 =	1.603821
003		2.500000 x	20.419486 =	51.048715
-----				
			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
1449		.004000 x	53.460700 =	.213843
003		.300000 x	20.419486 =	6.125846
001		.100000 x	15.741598 =	1.574160
-----				
			T.E =	10.519528
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.460700 =	1.336518
1444		.002000 x	76.007500 =	.152015
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	25.497704

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1449		.025000 x	53.460700 =	1.336518
001		.300000 x	15.741598 =	4.722479
1444		.001500 x	76.007500 =	.114011
003		.800000 x	20.419486 =	16.335589

-----  
T.E = 29.753597

7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	76.007500 =	.076008
001		.100000 x	15.741598 =	1.574160
1449		.025000 x	53.460700 =	1.336518
003		1.300000 x	20.419486 =	26.545332

-----  
T.E =

7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160

-----  
T.E =

7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	20.419486 =	30.629229
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
001		.400000 x	15.741598 =	6.296639

-----  
T.E =

7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	76.007500 =	.076008
1449		.025000 x	53.460700 =	1.336518
003		1.500000 x	20.419486 =	30.629229
001		.400000 x	15.741598 =	6.296639

-----  
T.E =

7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	53.460700 =	.106921
1444		.000100 x	76.007500 =	.007601
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664

-----  
T.E =

7326.1	7326.1			
029		.200000 x	.151500 =	.030300
173		48.000000 x	.256100 =	12.292800
003		3.000000 x	20.419486 =	61.258458
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
001		.500000 x	15.741598 =	7.870799

-----  
T.E = 82.901609

7326.2	7326.2			
029		.200000 x	.151500 =	.030300
174		48.000000 x	.000000 =	.000000
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799

-----  
T.E =

7327	7327			
029		.200000 x	.151500 =	.030300
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944
001		.600000 x	15.741598 =	9.444959
175		95.000000 x	.000000 =	.000000

-----  
T.E =

7328.1	7328.1			
029		.300000 x	.151500 =	.045450
171		108.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944

-----  
T.E =

7328.2 7328.2

029	.300000 x	.151500 =	.045450
1449	.020000 x	53.460700 =	1.069214
1444	.007000 x	76.007500 =	.532053
172	108.000000 x	.000000 =	.000000
003	4.000000 x	20.419486 =	81.677944
001	.700000 x	15.741598 =	11.019119

-----  
T.E =

7331 7331

029	1.500000 x	.151500 =	.227250
169	54.000000 x	.000000 =	.000000
003	3.500000 x	20.419486 =	71.468201
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
001	.500000 x	15.741598 =	7.870799

-----  
T.E =

7332 7332

029	2.000000 x	.151500 =	.303000
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
003	4.500000 x	20.419486 =	91.887687
001	.800000 x	15.741598 =	12.593278
170	108.000000 x	.000000 =	.000000

-----  
T.E =

7333 7333

029	.300000 x	.151500 =	.045450
167	1.050000 x	.000000 =	.000000
003	2.500000 x	20.419486 =	51.048715
002	.500000 x	17.312112 =	8.656056
1449	.020000 x	53.460700 =	1.069214

-----  
T.E =

7334 7334

029	.300000 x	.151500 =	.045450
168	1.050000 x	.000000 =	.000000
003	3.000000 x	20.419486 =	61.258458
002	.600000 x	17.312112 =	10.387267
1449	.020000 x	53.460700 =	1.069214

-----  
T.E =

7335	7335			
001		.450000 x	15.741598 =	7.083719
1444		.007000 x	76.007500 =	.532053
1445		.026000 x	61.946500 =	1.610609
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	29.645867
7336	7336			
001		.400000 x	15.741598 =	6.296639
1445		.022000 x	61.946500 =	1.362823
1444		.006000 x	76.007500 =	.456045
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	26.493045
7337	7337			
001		.350000 x	15.741598 =	5.509559
003		.800000 x	20.419486 =	16.335589
1445		.017000 x	61.946500 =	1.053091
1444		.005000 x	76.007500 =	.380038
		-----		
			T.E =	23.278276
7338	7338			
026		.500000 x	.099900 =	.049950
001		.300000 x	15.741598 =	4.722479
1445		.017000 x	61.946500 =	1.053091
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	20.119160
7340	7340			
289		1.100000 x	.904700 =	.995170
003		1.100000 x	20.419486 =	22.461435
1445		.026000 x	61.946500 =	1.610609
1444		.007000 x	76.007500 =	.532053
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	31.895905
7341	7341			
003		.200000 x	20.419486 =	4.083897
1441		.003000 x	27.111000 =	.081333
		-----		
			T.E =	4.165230
7346	7346			
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.083897

7347	7347				
001		.200000 x	15.741598 =	3.148320	
003		.500000 x	20.419486 =	10.209743	
1445		.009000 x	61.946500 =	.557519	
1444		.002000 x	76.007500 =	.152015	
-----					
			T.E =	14.067596	
7351	7351				
001		.200000 x	15.741598 =	3.148320	
003		.600000 x	20.419486 =	12.251692	
1444		.009000 x	76.007500 =	.684068	
-----					
			T.E =	16.084079	
7352	7352				
001		.200000 x	15.741598 =	3.148320	
1444		.012000 x	76.007500 =	.912090	
003		.700000 x	20.419486 =	14.293640	
-----					
			T.E =	18.354050	
7355	7355				
001		.150000 x	15.741598 =	2.361240	
003		.600000 x	20.419486 =	12.251692	
1444		.008000 x	76.007500 =	.608060	
-----					
			T.E =	15.220991	
7356	7356				
001		.100000 x	15.741598 =	1.574160	
003		.550000 x	20.419486 =	11.230717	
1444		.007000 x	76.007500 =	.532053	
-----					
			T.E =	13.336930	
7357	7357				
001		.050000 x	15.741598 =	.787080	
003		.500000 x	20.419486 =	10.209743	
1444		.006000 x	76.007500 =	.456045	
-----					
			T.E =	11.452868	
7359	7359				
021		.100000 x	2.670000 =	.267000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
065		.040000 x	13.610000 =	.544400	
026		20.000000 x	.099900 =	1.998000	
-----					
			T.E =	36.767838	



7360	7360			
021		.050000 x	2.670000 =	.133500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
026		13.000000 x	.099900 =	1.298700
065		.027000 x	13.610000 =	.367470
-----				
			T.E =	28.211789
7361	7361			
021		.050000 x	2.670000 =	.133500
346.1		30.000000 x	.057200 =	1.716000
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
026		14.000000 x	.099900 =	1.398600
065		.015000 x	13.610000 =	.204150
-----				
			T.E =	49.351642
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
346.1		22.000000 x	.057200 =	1.258400
348		8.000000 x	.103600 =	.828800
026		14.000000 x	.099900 =	1.398600
065		.015000 x	13.610000 =	.204150
-----				
			T.E =	49.722842
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
346.2		22.000000 x	.103600 =	2.279200
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.099900 =	1.398600
-----				
			T.E =	50.743642
7363	7363			
021		.050000 x	2.670000 =	.133500
346.1		35.000000 x	.057200 =	2.002000
026		17.000000 x	.099900 =	1.698300
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
065		.020000 x	13.610000 =	.272200
-----				
			T.E =	57.551712

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
026		17.000000 x	.099900 =	1.698300
346.1		24.000000 x	.057200 =	1.372800
065		.020000 x	13.610000 =	.272200
-----				
			T.E =	58.062112
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.099900 =	1.698300
346.2		24.000000 x	.103600 =	2.486400
002		1.200000 x	17.312112 =	20.774534
003		1.600000 x	20.419486 =	32.671178
348		11.000000 x	.103600 =	1.139600
065		.020000 x	13.610000 =	.272200
-----				
			T.E =	59.175712
7366	7366			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
346.1		45.000000 x	.057200 =	2.574000
026		10.000000 x	.099900 =	.999000
-----				
			T.E =	100.117987
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
026		10.000000 x	.099900 =	.999000
346.1		30.000000 x	.057200 =	1.716000
-----				
			T.E =	100.813987
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
346.2		30.000000 x	.103600 =	3.108000
026		10.000000 x	.099900 =	.999000
-----				
			T.E =	102.205987

7371.1	7371.1						
026	-	14.000000 x	.099900 =	-	1.398600		
029		14.000000 x	.151500 =		2.121000		
7361		1.000000 x	49.351642 =		49.351642		
						-----	
						T.E =	50.074042
7371.2	7371.2						
026	-	14.000000 x	.099900 =	-	1.398600		
028		14.000000 x	.000000 =		.000000		
7361		1.000000 x	49.351642 =		49.351642		
						-----	
						T.E =	
7372.1	7372.1						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.1		1.000000 x	49.722842 =		49.722842		
029		14.000000 x	.151500 =		2.121000		
						-----	
						T.E =	50.445242
7372.2	7372.2						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.1		1.000000 x	49.722842 =		49.722842		
028		14.000000 x	.000000 =		.000000		
						-----	
						T.E =	
7372.3	7372.3						
026	-	14.000000 x	.099900 =	-	1.398600		
029		14.000000 x	.151500 =		2.121000		
7362.2		1.000000 x	50.743642 =		50.743642		
						-----	
						T.E =	51.466042
7372.4	7372.4						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.2		1.000000 x	50.743642 =		50.743642		
028		14.000000 x	.000000 =		.000000		
						-----	
						T.E =	
7373.1	7373.1						
026	-	17.000000 x	.099900 =	-	1.698300		
7363		1.000000 x	57.551712 =		57.551712		
029		17.000000 x	.151500 =		2.575500		
						-----	
						T.E =	58.428912

7373.2	7373.2					
026	-	17.000000 x	.099900 =	-	1.698300	
7363		1.000000 x	57.551712 =		57.551712	
028		17.000000 x	.000000 =		.000000	
-----						
			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
029		17.000000 x	.151500 =		2.575500	
-----						
			T.E =		58.939312	
7374.2	7374.2					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
028		17.000000 x	.000000 =		.000000	
-----						
			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.2		1.000000 x	59.175712 =		59.175712	
029		17.000000 x	.151500 =		2.575500	
-----						
			T.E =		60.052912	
7374.4	7374.4					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.2		1.000000 x	59.175712 =		59.175712	
028		17.000000 x	.000000 =		.000000	
-----						
			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.099900 =	-	.999000	
029		10.000000 x	.151500 =		1.515000	
7366		1.000000 x	100.117987 =		100.117987	
-----						
			T.E =		100.633987	
7376.2	7376.2					
026	-	10.000000 x	.099900 =	-	.999000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	100.117987 =		100.117987	
-----						
			T.E =			

7377.1	7377.1				
026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.151500 =		1.515000
7367.1		1.000000 x	100.813987 =		100.813987
-----					
			T.E =		101.329987
7377.2	7377.2				
026	-	10.000000 x	.099900 =	-	.999000
7367.1		1.000000 x	100.813987 =		100.813987
028		10.000000 x	.000000 =		.000000
-----					
			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.151500 =		1.515000
7367.2		1.000000 x	102.205987 =		102.205987
-----					
			T.E =		102.721987
7377.4	7377.4				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.2		1.000000 x	102.205987 =		102.205987
-----					
			T.E =		
7381	7381				
456		.100000 x	1.658300 =		.165830
-----					
			T.E =		.165830
7382	7382				
443		.150000 x	1.987900 =		.298185
447		.050000 x	4.525500 =		.226275
003		.300000 x	20.419486 =		6.125846
-----					
			T.E =		6.650306
7383	7383				
002		.250000 x	17.312112 =		4.328028
003		.150000 x	20.419486 =		3.062923
-----					
			T.E =		7.390951
7384	7384				
003		.500000 x	20.419486 =		10.209743
-----					
			T.E =		10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	12.251692
7387	7387			
261		1.500000 x	.598400 =	.897600
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.351642 =	54.286806
		-----		
			T.E =	75.603892
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.351642 =	29.610985
		-----		
			T.E =	80.659700
7389.1.1	7389.1.1			
7371.1		.300000 x	50.074042 =	15.022213
		-----		
			T.E =	15.022213
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.052912 =	18.015874
		-----		
			T.E =	18.015874
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.445242 =	15.133573
		-----		
			T.E =	15.133573
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.466042 =	15.439813
		-----		
			T.E =	15.439813
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.428912 =	17.528674
		-----		
			T.E =	17.528674
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.939312 =	17.681794
		-----		
			T.E =	17.681794
7389.2.1	7389.2.1			
7371.1		.500000 x	50.074042 =	25.037021
		-----		
			T.E =	25.037021
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.052912 =	30.026456
		-----		
			T.E =	30.026456

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.445242 =	25.222621
		-----		
			T.E =	25.222621
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.466042 =	25.733021
		-----		
			T.E =	25.733021
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.428912 =	29.214456
		-----		
			T.E =	29.214456
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.939312 =	29.469656
		-----		
			T.E =	29.469656
7391	7391			
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.104872



7392	7392				
298.1		1.081080 x	6.920000 =	7.481074	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	15.648868	
7393	7393				
294		.347760 x	3.687800 =	1.282469	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	7.408315	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	6.644872	

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	162 22/12/2011
7416	7416		
003		.800000 x	20.419486 =
		-----	
		T.E =	16.335589
7417	7417		
003		1.800000 x	20.419486 =
		-----	
		T.E =	36.755075
7418	7418		
003		2.600000 x	20.419486 =
		-----	
		T.E =	53.090664
7419	7419		
003		.800000 x	20.419486 =
		-----	
		T.E =	16.335589
7420	7420		
003		1.200000 x	20.419486 =
		-----	
		T.E =	24.503383
7421	7421		
003		.800000 x	20.419486 =
		-----	
		T.E =	16.335589
7422	7422		
003		.350000 x	20.419486 =
		-----	
		T.E =	7.146820
7431	7431		
332		1.150000 x	88.540000 =
1444		.001000 x	76.007500 =
1445		.020000 x	61.946500 =
003		4.000000 x	20.419486 =
		-----	
		T.E =	184.813882
7432	7432		
331		1.150000 x	85.390000 =
1444		.001000 x	76.007500 =
1445		.020000 x	61.946500 =
003		4.400000 x	20.419486 =
		-----	
		T.E =	189.359176

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.100000 x	20.419486 =	104.139379	
		-----			
			T.E =	203.652816	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.100000 x	20.419486 =	124.558865	
		-----			
			T.E =	224.072302	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
003		4.200000 x	20.419486 =	85.761841	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	193.814279	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.600000 x	20.419486 =	93.929636	
		-----			
			T.E =	201.982073	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.300000 x	20.419486 =	108.223276	
		-----			
			T.E =	216.275713	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.300000 x	20.419486 =	128.642762	
		-----			
			T.E =	236.695199	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	
003		4.500000 x	20.419486 =	91.887687	
		-----			
			T.E =	235.768125	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
003		4.900000 x	20.419486 =	100.055481	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	243.935919	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
003		5.600000 x	20.419486 =	114.349122	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	258.229559	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.600000 x	20.419486 =	134.768608	
		-----			
			T.E =	278.649045	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	
		-----			
			T.E =	256.332919	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
003		5.300000 x	20.419486 =	108.223276	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	264.500713	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
003		6.000000 x	20.419486 =	122.516916	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	278.794354	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		7.000000 x	20.419486 =	142.936402	
		-----			
			T.E =	299.213840	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.915000 x	20.419486 =	18.683830	
		-----			
			T.E =	28.635173	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.945000 x	20.419486 =	19.296414	
		-----			
			T.E =	30.101658	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
003		.990000 x	20.419486 =	20.215291	
1444		.000100 x	76.007500 =	.007601	
1445		.002000 x	61.946500 =	.123893	
		-----			
			T.E =	34.603335	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
003		1.050000 x	20.419486 =	21.440460	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
		-----			
			T.E =	37.068204	

7496	7496			
331		.057500 x	85.390000 =	4.909925
003		.488000 x	20.419486 =	9.964709
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
		-----		
			T.E =	14.940381
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
003		.504000 x	20.419486 =	10.291421
		-----		
			T.E =	15.694043
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	20.419486 =	10.781489
1444		.000050 x	76.007500 =	.003800
1445		.001000 x	61.946500 =	.061947
		-----		
			T.E =	17.975510
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	20.419486 =	11.434912
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
		-----		
			T.E =	19.248784
7501	7501			
7433		1.000000 x	203.652816 =	203.652816
		-----		
			T.E =	203.652816
7503	7503			
7443		1.000000 x	216.275713 =	216.275713
		-----		
			T.E =	216.275713
7506	7506			
7453		1.000000 x	258.229559 =	258.229559
		-----		
			T.E =	258.229559
7508	7508			
7463		1.000000 x	278.794354 =	278.794354
		-----		
			T.E =	278.794354

7511	7511				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	20.419486 =	18.683830	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
		-----			
			T.E =	28.635173	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.945000 x	20.419486 =	19.296414	
		-----			
			T.E =	30.101658	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	215.828500	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	20.419486 =	98.013533	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	197.450963	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	232.535295	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		5.000000 x	20.419486 =	102.097430	
		-----			
			T.E =	210.073860	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	61.946500 =	1.238930	
003		5.200000 x	20.419486 =	106.181327	
		-----			
			T.E =	209.241257	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	61.946500 =	1.238930	
003		5.400000 x	20.419486 =	110.265224	
-----					
			T.E =	222.179154	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
1445		.020000 x	61.946500 =	1.238930	
003		5.700000 x	20.419486 =	116.391070	
-----					
			T.E =	270.384500	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	
-----					
			T.E =	291.835295	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
003		3.000000 x	20.419486 =	61.258458	
1445		.010000 x	61.946500 =	.619465	
-----					
			T.E =	101.726923	
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	20.419486 =	81.677944	
1445		.010000 x	61.946500 =	.619465	
-----					
			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
1445		.010000 x	61.946500 =	.619465	
003		3.700000 x	20.419486 =	75.552098	
334		.350000 x	132.830000 =	46.490500	
-----					
			T.E =	137.713863	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
1445		.010000 x	61.946500 =	.619465	
003		4.200000 x	20.419486 =	85.761841	
-----					
			T.E =		



7543	7543			
332		.170000 x	88.540000 =	15.051800
338		.350000 x	.000000 =	.000000
1445		.010000 x	61.946500 =	.619465
003		4.800000 x	20.419486 =	98.013533
-----				
			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402
-----				
			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402
-----				
			T.E =	271.468832
7553	7553			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402
-----				
			T.E =	289.650332
7554	7554			
321		1.150000 x	.000000 =	.000000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	312.307804
7556	7556			
323		1.150000 x	126.500000 =	145.475000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	330.489304

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	170 22/12/2011
7558	7558		
331	.080000 x	85.390000 =	6.831200
1445	.003000 x	61.946500 =	.185840
003	1.500000 x	20.419486 =	30.629229
-----			
		T.E =	37.646269
7559	7559		
331	.080000 x	85.390000 =	6.831200
1445	.003000 x	61.946500 =	.185840
003	1.500000 x	20.419486 =	30.629229
-----			
		T.E =	37.646269
7561	7561		
332	1.150000 x	88.540000 =	101.821000
003	5.200000 x	20.419486 =	106.181327
1445	.020000 x	61.946500 =	1.238930
-----			
		T.E =	209.241257
7562	7562		
334	1.150000 x	132.830000 =	152.754500
003	5.700000 x	20.419486 =	116.391070
1445	.020000 x	61.946500 =	1.238930
-----			
		T.E =	270.384500
7563	7563		
332	1.250000 x	88.540000 =	110.675000
1445	.020000 x	61.946500 =	1.238930
003	5.400000 x	20.419486 =	110.265224
-----			
		T.E =	222.179154
7564	7564		
334	1.250000 x	132.830000 =	166.037500
003	6.100000 x	20.419486 =	124.558865
1445	.020000 x	61.946500 =	1.238930
-----			
		T.E =	291.835295
7565	7565		
003	1.500000 x	20.419486 =	30.629229
-----			
		T.E =	30.629229
7566	7566		
7561	1.500000 x	209.241257 =	313.861886
-----			
		T.E =	313.861886

7567	7567			
7562		1.500000 x	270.384500 =	405.576750
		-----		
			T.E =	405.576750
7568	7568			
7563		1.500000 x	222.179154 =	333.268731
		-----		
			T.E =	333.268731
7569	7569			
7564		1.500000 x	291.835295 =	437.752943
		-----		
			T.E =	437.752943
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.1		.030000 x	.000000 =	.000000
		-----		
			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
327.2		.030000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	263.807958
7572	7572			
328		1.000000 x	.000000 =	.000000
328		.030000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	20.419486 =	77.594047
		-----		
			T.E =	175.792547

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ.	172
		Ημ/νία	22/12/2011
7577	7577		
334		1.150000 x	132.830000 =
003		4.200000 x	20.419486 =
-----			
		T.E =	238.516341
7578	7578		
336		1.150000 x	.000000 =
003		4.700000 x	20.419486 =
-----			
		T.E =	
7581	7581		
326		1.050000 x	63.530000 =
1445		.005000 x	61.946500 =
3211		.020000 x	134.257521 =
003		2.300000 x	20.419486 =
-----			
		T.E =	116.666201
7601	7601		
401		1.100000 x	12.200000 =
003		.500000 x	20.419486 =
457		.500000 x	.827900 =
-----			
		T.E =	24.043693
7602	7602		
403		1.100000 x	14.290000 =
457		.500000 x	.827900 =
003		.550000 x	20.419486 =
-----			
		T.E =	27.363667
7603	7603		
406		1.100000 x	17.660000 =
457		.500000 x	.827900 =
003		.650000 x	20.419486 =
-----			
		T.E =	33.112616
7604.1	7604.1		
409		1.100000 x	21.030000 =
457		.500000 x	.827900 =
003		.750000 x	20.419486 =
-----			
		T.E =	38.861565

7604.2	7604.2			
410		1.100000 x	28.610000 =	31.471000
003		.750000 x	20.419486 =	15.314615
457		.500000 x	.827900 =	.413950
		-----		
			T.E =	47.199565
7606	7606			
401		1.100000 x	12.200000 =	13.420000
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	25.671692
7607	7607			
403		1.100000 x	14.290000 =	15.719000
003		.650000 x	20.419486 =	13.272666
		-----		
			T.E =	28.991666
7608	7608			
406		1.100000 x	17.660000 =	19.426000
003		.750000 x	20.419486 =	15.314615
		-----		
			T.E =	34.740615
7609.1	7609.1			
409		1.100000 x	21.030000 =	23.133000
003		.850000 x	20.419486 =	17.356563
		-----		
			T.E =	40.489563
7609.2	7609.2			
410		1.100000 x	28.610000 =	31.471000
003		.850000 x	20.419486 =	17.356563
		-----		
			T.E =	48.827563
7611	7611			
411		1.100000 x	26.710000 =	29.381000
457		.500000 x	.827900 =	.413950
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	40.004693
7612	7612			
412		1.100000 x	28.830000 =	31.713000
003		.550000 x	20.419486 =	11.230717
457		.500000 x	.827900 =	.413950
		-----		
			T.E =	43.357667

7613	7613				
411		1.100000 x	26.710000 =	29.381000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	41.632692	
7614	7614				
412		1.100000 x	28.830000 =	31.713000	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	44.985666	
7616	7616				
414		1.100000 x	21.030000 =	23.133000	
003		.600000 x	20.419486 =	12.251692	
457		.500000 x	.827900 =	.413950	
		-----			
			T.E =	35.798642	
7617	7617				
415		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.827900 =	.413950	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	36.819616	
7618	7618				
414		1.100000 x	21.030000 =	23.133000	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	37.426640	
7619	7619				
415		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	
		-----			
			T.E =	38.447615	
7621	7621				
418		1.100000 x	29.450000 =	32.395000	
003		1.200000 x	20.419486 =	24.503383	
457		.800000 x	.827900 =	.662320	
		-----			
			T.E =	57.560703	
7622	7622				
419		1.100000 x	29.450000 =	32.395000	
003		1.400000 x	20.419486 =	28.587280	
457		.800000 x	.827900 =	.662320	
		-----			
			T.E =	61.644600	

7626.1	7626.1			
298.2		18.000000 x	5.550000 =	99.900000
003		7.000000 x	20.419486 =	142.936402
421		1.000000 x	97.840000 =	97.840000
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	461.861186
7626.2	7626.2			
298.2		18.000000 x	5.550000 =	99.900000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
422		1.000000 x	134.470000 =	134.470000
		-----		
			T.E =	498.491186
7627.1	7627.1			
298.2		16.000000 x	5.550000 =	88.800000
421		1.000000 x	97.840000 =	97.840000
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	413.029588
7627.2	7627.2			
298.2		16.000000 x	5.550000 =	88.800000
422		1.000000 x	134.470000 =	134.470000
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	449.659588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	7.562559

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	10.269949
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	
7701	7701			
024		.001500 x	45.000000 =	.067500
003		.120000 x	20.419486 =	2.450338
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	3.383444
7702	7702			
024		.001800 x	45.000000 =	.081000
003		.080000 x	20.419486 =	1.633559
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	2.580164
7706	7706			
024		.002000 x	45.000000 =	.090000
002		.080000 x	17.312112 =	1.384969
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	4.537892
7707	7707			
024		.002300 x	45.000000 =	.103500
002		.100000 x	17.312112 =	1.731211
003		.090000 x	20.419486 =	1.837754
		-----		
			T.E =	3.672465



7708	7708			
024		.002500 x	45.000000 =	.112500
002		.120000 x	17.312112 =	2.077453
003		.180000 x	20.419486 =	3.675507
-----				
			T.E =	5.865461
7709	7709			
024		.002800 x	45.000000 =	.126000
003		.120000 x	20.419486 =	2.450338
002		.150000 x	17.312112 =	2.596817
-----				
			T.E =	5.173155
7711	7711			
002		.050000 x	17.312112 =	.865606
003		.200000 x	20.419486 =	4.083897
1485		.200000 x	.855511 =	.171102
-----				
			T.E =	5.120605
7712	7712			
002		.080000 x	17.312112 =	1.384969
1485		.250000 x	.855511 =	.213878
003		.250000 x	20.419486 =	5.104872
-----				
			T.E =	6.703718
7713	7713			
002		.160000 x	17.312112 =	2.769938
003		.300000 x	20.419486 =	6.125846
1485		.280000 x	.855511 =	.239543
-----				
			T.E =	9.135327
7720	7720			
443		.080000 x	1.987900 =	.159032
002		.100000 x	17.312112 =	1.731211
003		.300000 x	20.419486 =	6.125846
1485		.200000 x	.855511 =	.171102
-----				
			T.E =	8.187191
7721	7721			
002		.070000 x	17.312112 =	1.211848
1485		.200000 x	.855511 =	.171102
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	5.466847

ΑΤΟΕ	2ο Τρίμηνο του 2011	Σελ. Ημ/νία	178 22/12/2011
7722.1.1	7722.1.1		
7720	.300000 x	8.187191 =	2.456157
	-----		
		T.E =	2.456157
7722.1.2	7722.1.2		
7721	.300000 x	5.466847 =	1.640054
	-----		
		T.E =	1.640054
7722.2.1	7722.2.1		
7720	.400000 x	8.187191 =	3.274876
	-----		
		T.E =	3.274876
7722.2.2	7722.2.2		
7721	.400000 x	5.466847 =	2.186739
	-----		
		T.E =	2.186739
7725	7725		
471	.300000 x	3.960000 =	1.188000
002	.150000 x	17.312112 =	2.596817
003	.250000 x	20.419486 =	5.104872
	-----		
		T.E =	8.889688
7735	7735		
441	.350000 x	.077700 =	.027195
444	.150000 x	2.207500 =	.331125
003	.150000 x	20.419486 =	3.062923
	-----		
		T.E =	3.421243
7736	7736		
441	.500000 x	.077700 =	.038850
444	.085000 x	2.207500 =	.187638
003	.250000 x	20.419486 =	5.104872
446	.005000 x	2.662500 =	.013313
445	.010000 x	1.600000 =	.016000
	-----		
		T.E =	5.360672
7737	7737		
441	.200000 x	.077700 =	.015540
003	.300000 x	20.419486 =	6.125846
1489	.200000 x	.895520 =	.179104
1488	.600000 x	.784064 =	.470438
	-----		
		T.E =	6.790928

7738	7738			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
1488		.300000 x	.784064 =	.235219
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	6.555709
7739	7739			
441		.100000 x	.077700 =	.007770
003		.150000 x	20.419486 =	3.062923
467		.100000 x	3.397500 =	.339750
-----				
			T.E =	3.410443
7740	7740			
442		.250000 x	.121800 =	.030450
1492		.250000 x	2.841075 =	.710269
003		.250000 x	20.419486 =	5.104872
-----				
			T.E =	5.845590
7741	7741			
442		.250000 x	.121800 =	.030450
003		.250000 x	20.419486 =	5.104872
462		.250000 x	.000000 =	.000000
-----				
			T.E =	
7742	7742			
442		.250000 x	.121800 =	.030450
003		.200000 x	20.419486 =	4.083897
463		.125000 x	4.089100 =	.511138
-----				
			T.E =	4.625485
7743	7743			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.630000 =	.453750
-----				
			T.E =	3.547123
7744	7744			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
465		.125000 x	6.180000 =	.772500
-----				
			T.E =	3.865873

7745	7745			
442		.250000 x	.121800 =	.030450
1489		.200000 x	.895520 =	.179104
1492		.250000 x	2.841075 =	.710269
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	17.255412
7746	7746			
441		.350000 x	.077700 =	.027195
003		.150000 x	20.419486 =	3.062923
443		.090000 x	1.987900 =	.178911
		-----		
			T.E =	3.269029
7747	7747			
441		.350000 x	.077700 =	.027195
003		.250000 x	20.419486 =	5.104872
443		.170000 x	1.987900 =	.337943
		-----		
			T.E =	5.470010
7748	7748			
443		.090000 x	1.987900 =	.178911
445		.030000 x	1.600000 =	.048000
450		.060000 x	2.842800 =	.170568
003		.200000 x	20.419486 =	4.083897
002		.100000 x	17.312112 =	1.731211
		-----		
			T.E =	6.212587
7749	7749			
443		.160000 x	1.987900 =	.318064
445		.050000 x	1.600000 =	.080000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.842800 =	.284280
		-----		
			T.E =	8.384032
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.534505 =	.191813
		-----		
			T.E =	3.254736
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.534505 =	.383626
		-----		
			T.E =	5.488498

7753	7753				
441		1.000000 x	.077700 =		.077700
1491		.200000 x	1.534505 =		.306901
1490		.090000 x	1.594219 =		.143480
003		.650000 x	20.419486 =		13.272666
443		.080000 x	1.987900 =		.159032
		-----			
			T.E =		13.959779
7754	7754				
441		.800000 x	.077700 =		.062160
1491		.200000 x	1.534505 =		.306901
1490		.090000 x	1.594219 =		.143480
1487		.090000 x	.621987 =		.055979
003		.800000 x	20.419486 =		16.335589
		-----			
			T.E =		16.904108
7755	7755				
442		.250000 x	.121800 =		.030450
1492		.160000 x	2.841075 =		.454572
003		1.000000 x	20.419486 =		20.419486
1491		.200000 x	1.534505 =		.306901
		-----			
			T.E =		21.211409
7756	7756				
442		.300000 x	.121800 =		.036540
1492		.300000 x	2.841075 =		.852323
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		8.035683
7761	7761				
441		.650000 x	.077700 =		.050505
003		.800000 x	20.419486 =		16.335589
1489		.200000 x	.895520 =		.179104
1488		.600000 x	.784064 =		.470438
473		.100000 x	2.832500 =		.283250
467		.100000 x	3.397500 =		.339750
		-----			
			T.E =		17.658636
7762	7762				
473		.100000 x	2.832500 =		.283250
003		.200000 x	20.419486 =		4.083897
		-----			
			T.E =		4.367147

7764	7764			
474		.125000 x	3.883100 =	.485388
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.527336
7765	7765			
475		.125000 x	6.416900 =	.802113
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.886010
7766	7766			
442		.275000 x	.121800 =	.033495
003		.880000 x	20.419486 =	17.969148
1492		.275000 x	2.841075 =	.781296
473		.110000 x	2.832500 =	.311575
		-----		
			T.E =	19.095513
7767.1	7767.1			
7755		.150000 x	21.211409 =	3.181711
		-----		
			T.E =	3.181711
7767.2	7767.2			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.841075 =	.454572
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.150000 x	21.471008 =	3.220651
		-----		
7767.3	7767.3			
7755		.250000 x	21.211409 =	5.302852
		-----		
			T.E =	5.302852
7767.4	7767.4			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.250000 x	21.471008 =	5.367752
		-----		

7767.5	7767.5			
7755		.350000 x	21.211409 =	7.423993
		-----		
			T.E =	7.423993
7767.6	7767.6			
442		.250000 x	.121800 =	.030450
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
473		.200000 x	2.832500 =	.566500
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.350000 x	21.471008 =	7.514853
		-----		
7767.7	7767.7			
7755		.450000 x	21.211409 =	9.545134
		-----		
			T.E =	9.545134
7767.8	7767.8			
442		.250000 x	.121800 =	.030450
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.841075 =	.454572
473		.200000 x	2.832500 =	.566500
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.450000 x	21.471008 =	9.661954
		-----		
7768	7768			
460		.200000 x	4.377500 =	.875500
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
460		.030000 x	4.377500 =	.131325
		-----		
			T.E =	17.986044
7769	7769			
460		.200000 x	4.377500 =	.875500
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
460		.030000 x	4.377500 =	.131325
		-----		
			T.E =	8.553145
7770	7770			
460		.090000 x	4.377500 =	.393975
003		.150000 x	20.419486 =	3.062923
002		.150000 x	17.312112 =	2.596817
460		.020000 x	4.377500 =	.087550
		-----		
			T.E =	6.141265

7771	7771				
441		1.000000 x	.077700 =	.077700	
467		.110000 x	3.397500 =	.373725	
003		1.300000 x	20.419486 =	26.545332	
1488		.160000 x	.784064 =	.125450	
1487		.080000 x	.621987 =	.049759	
473		.100000 x	2.832500 =	.283250	
		-----			
			T.E =	27.455216	
7772	7772				
441		1.000000 x	.077700 =	.077700	
003		.500000 x	20.419486 =	10.209743	
458		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
		-----			
			T.E =	11.014233	
7773	7773				
441		1.000000 x	.077700 =	.077700	
003		.600000 x	20.419486 =	12.251692	
459		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
		-----			
			T.E =	13.056182	
7774	7774				
442		.250000 x	.121800 =	.030450	
003		1.000000 x	20.419486 =	20.419486	
1492		.160000 x	2.841075 =	.454572	
473		.200000 x	2.832500 =	.566500	
		-----			
			T.E =	21.471008	
7785.1	7785.1				
441		.350000 x	.077700 =	.027195	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.437300 =	.292476	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	15.102911	
7785.2	7785.2				
441		.350000 x	.077700 =	.027195	
478		.160000 x	3.060000 =	.489600	
003		.700000 x	20.419486 =	14.293640	
476		.120000 x	2.437300 =	.292476	
		-----			
			T.E =	15.102911	



7786.1	7786.1			
441		.350000 x	.077700 =	.027195
1488		.600000 x	.784064 =	.470438
1489		.200000 x	.895520 =	.179104
477		.110000 x	.000000 =	.000000
003		1.000000 x	20.419486 =	20.419486
-----				
			T.E =	
7786.2	7786.2			
441		.350000 x	.077700 =	.027195
1488		.600000 x	.784064 =	.470438
1489		.200000 x	.895520 =	.179104
003		1.000000 x	20.419486 =	20.419486
478		.110000 x	3.060000 =	.336600
-----				
			T.E =	21.432823
7787	7787			
441		1.000000 x	.077700 =	.077700
1488		.160000 x	.784064 =	.125450
1487		.080000 x	.621987 =	.049759
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000
476		.090000 x	2.437300 =	.219357
-----				
			T.E =	
7788	7788			
441		.250000 x	.077700 =	.019425
003		.700000 x	20.419486 =	14.293640
479		1.000000 x	1.876600 =	1.876600
-----				
			T.E =	16.189665
7791	7791			
441		1.000000 x	.077700 =	.077700
003		.500000 x	20.419486 =	10.209743
1491		.200000 x	1.534505 =	.306901
1487		.050000 x	.621987 =	.031099
-----				
			T.E =	10.625443
7792	7792			
482		.150000 x	1.421100 =	.213165
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	10.422908

7793	7793			
480		.500000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	
7794	7794			
482		.150000 x	1.421100 =	.213165
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	10.422908
7797	7797			
201		.000500 x	290.000000 =	.145000
002		.060000 x	17.312112 =	1.038727
-----				
			T.E =	1.183727
7798	7798			
201		.000600 x	290.000000 =	.174000
002		.070000 x	17.312112 =	1.211848
-----				
			T.E =	1.385848
7801	7801			
496		1.200000 x	.905500 =	1.086600
003		.150000 x	20.419486 =	3.062923
-----				
			T.E =	4.149523
7806	7806			
498		1.150000 x	1.011600 =	1.163340
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	7.289186
7807	7807			
499		1.150000 x	1.386800 =	1.594820
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	9.762614
7808	7808			
500		1.150000 x	2.039600 =	2.345540
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	14.597232

7809	7809			
501		1.200000 x	2.763000 =	3.315600
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	19.651189
7810	7810			
502		1.200000 x	3.807000 =	4.568400
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	22.945937
7811	7811			
503		1.200000 x	.905500 =	1.086600
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	17.422189
7812	7812			
504		1.300000 x	1.199100 =	1.558830
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	19.936367
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	31.421692
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.872297
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	25.795486
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	19.507192

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.431700 =	1.574870
003		.150000 x	20.419486 =	3.062923
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	10.707427
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239
		-----		
			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.707427 =	9.101313
		-----		
			T.E =	9.101313
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238
		-----		
			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303
		-----		
			T.E =	10.038303

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.312112 =	.692484
		-----		
			T.E =	2.134484
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	3.121306
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	2.081006
7931	7931			
519		1.050000 x	50.290000 =	52.804500
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	83.433729
7932.1	7932.1			
514		.000000 x	42.680000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7932.2	7932.2			
520		.000000 x	41.070000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7933.1	7933.1			
514		.000000 x	42.680000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7933.2	7933.2			
520		.000000 x	41.070000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000

7934	7934			
535		1.150000 x	6.600000 =	7.590000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	26.455799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.861000 =	.086100
		-----		
			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	9.124160