

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

3ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
008	16.777917
009	.074800
011	55.210000
012	4.530000
013	27.370000
014	268.420000
015	206.720000
016	32.560000
017	380.180000
018.1	2.990000
018.2	4.530000
019.1	2.990000
019.2	4.530000
021	2.670000
022	.070000
024	45.000000
026	.099900
027	.119300
029	.151500
032	36.000000
035	.086500
036	.088800
040	.210000
051	15.400000
052	15.400000
053	.085000
054	.085000
055	.090000
056	10.580000
057	10.580000
058	9.090000
061	13.560000
062	13.560000
065	13.610000
066	35.000000
067	45.500000
081	11.010000
101	
102	
111	.075900
112	.083300
113	.570000
114	
116	.086700
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.690000
132	.960000
142	.340000

146	.370000
155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.256100
181	
201	290.000000
203.2	370.000000
203.4	290.000000
205	450.000000
208	1,435.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,500.000000
223.4	1,580.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	2.000000
237	1.100000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.600000
246	12.000000
249	20.000000
251	.861000
252	2.100000
253	2.652000
254	3.532000
258	7.877500
259	25.290000
260	.545500
261	.598400
262	.545500
264	1.239900
265	.941500
266	.703000

267	1.011500
268	1.171500
271	1.111500
272	1.006500
273	1.236500
274	1.525100
276	.873000
277	1.121500
278	3.780000
279	3.906000
280	1.050000
281	6.069000
282	1.086500
283	1.305700
284	
285	.075000
286	1.788000
288	1.940600
289	.904700
290	3.500000
291	5.000000
293	
294	3.687800
295	6.490000
296	12.990000
297.2	
298.1	7.910000
298.2	6.360000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.735200
352	1.133000
354	.985400
356	.661600
357	1.441300
358	3.338500
360	14.938000
361	1.249900
362	1.397000
363	1.779400
364	1.133000
366	5.000500
370	.294100
371	1.779400

372	2.470800
373	2.735500
375	3.470900
376	.220400
377	.926400
378	14.950000
379	27.450000
380	16.560000
381	74.770000
386	28.630000
388	48.870000
390	1.500000
392	27.420000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.077700
442	.121800
443	1.987900
444	2.207500
445	1.600000
446	2.662500
447	4.525500
450	2.842800
451	1.214200
453	.085000
455	3.090000
456	1.658300
457	.827900
458	5.280000
459	5.280000
460	4.377500
462	
463	4.089100
464	3.630000
465	6.180000
467	3.397500
471	3.960000
473	2.832500
474	3.883100
475	6.416900
476	2.437300
477	
478	3.060000
479	1.876600
480	

481	5.467500
482	1.433300
483	.167500
484	4.160000
485	1.175600
487	13.884000
488	5.500000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	.905500
498	1.011600
499	1.386800
500	2.039600
501	2.763000
502	3.807000
503	.905500
504	1.199100
505	19.170000
506	1.431700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.437500
514	42.680000
515	43.500000
519	50.290000
520	41.070000
521	2.461700
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.600000
536	2.500000
537	1.700000
565.3	3.800000
565.5	5.650000
565.6	7.800000
566.3	5.050000
566.5	7.750000
566.6	10.300000

1101	1101			
001		.500000 x	15.741598 =	7.870799
		-----		
			B.T =	7.870799
1102	1102			
001		1.000000 x	15.741598 =	15.741598
		-----		
			B.T =	15.741598
1103	1103			
001		.300000 x	15.741598 =	4.722479
		-----		
			B.T =	4.722479
1104	1104			
015		1.000000 x	206.720000 =	206.720000
291		2.200000 x	5.000000 =	11.000000
485		83.000000 x	1.175600 =	97.574800
484		5.250000 x	4.160000 =	21.840000
002		7.000000 x	17.312112 =	121.184784
004		7.000000 x	23.886192 =	167.203344
		-----		
			AΘΡΟΙΣΜΑ =	625.522928
	B.T =	.004000 x	625.522928 =	2.502092
		-----		
1111	1111			
006		.060000 x	183.150721 =	10.989043
		-----		
			B.T =	10.989043
1112	1112			
006		.090000 x	183.150721 =	16.483565
		-----		
			B.T =	16.483565
1116	1116			
007		.025000 x	183.150721 =	4.578768
		-----		
			B.T =	4.578768
1117	1117			
007		.110000 x	183.150721 =	20.146579
		-----		
			B.T =	20.146579
1121	1121			
009		4.000000 x	.074800 =	.299200
		-----		
			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000
		-----		
			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600
		-----		
			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639
		-----		
			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408
		-----		
			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617
		-----		
			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565
		-----		
			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800
		-----		
			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200
		-----		
			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000
		-----		
			B.T =	.187000



1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.210000 =	241.500000
		-----		
			B.T =	242.301000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000
		-----		
			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
1407		.320000 x	37.605000 =	12.033600
051		.960000 x	15.400000 =	14.784000
		-----		
			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
1407		.360000 x	37.605000 =	13.537800
051		.900000 x	15.400000 =	13.860000
		-----		
			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100
		-----		
			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.099900 =	14.985000
1407		.250000 x	37.605000 =	9.401250
		-----		
			B.T =	39.704250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
051		.900000 x	15.400000 =	13.860000
1407		.290000 x	37.605000 =	10.905450
		-----		
			B.T =	40.284450

1418	1418			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000

-----  
B.T = 41.616750

1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	15.400000 =	8.316000
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000

-----  
B.T =

1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.086500 =	6.487500
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

-----  
B.T =

1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

-----  
B.T = 152.456250

1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.099900 =	14.985000

-----  
B.T = 163.304700

1428	1428			
021		.200000 x	2.670000 =	.534000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.090000 =	108.000000
051		.200000 x	15.400000 =	3.080000

-----  
B.T = 126.656000

1429	1429			
021		.200000 x	2.670000 =	.534000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.090000 =	108.000000
035		200.000000 x	.086500 =	17.300000
		-----		
			B.T =	140.876000
1431	1431			
021		.300000 x	2.670000 =	.801000
032		.960000 x	36.000000 =	34.560000
1407		.320000 x	37.605000 =	12.033600
		-----		
			B.T =	47.394600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	15.400000 =	9.856000
032		.320000 x	36.000000 =	11.520000
		-----		
			B.T =	34.210600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.086500 =	95.150000
		-----		
			B.T =	96.084500
1437	1437			
021		.200000 x	2.670000 =	.534000
1407		.620000 x	37.605000 =	23.315100
051		.380000 x	15.400000 =	5.852000
035		75.000000 x	.086500 =	6.487500
		-----		
			B.T =	36.188600
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.099900 =	24.975000
		-----		
			B.T =	27.111000
1442	1442			
021		.250000 x	2.670000 =	.667500
026		900.000000 x	.099900 =	89.910000
051		.740000 x	15.400000 =	11.396000
		-----		
			B.T =	101.973500

1443	1443			
021		.250000 x	2.670000 =	.667500
051		.860000 x	15.400000 =	13.244000
026		700.000000 x	.099900 =	69.930000
-----				
			B.T =	83.841500
1444	1444			
021		.250000 x	2.670000 =	.667500
051		1.000000 x	15.400000 =	15.400000
026		600.000000 x	.099900 =	59.940000
-----				
			B.T =	76.007500
1445	1445			
021		.250000 x	2.670000 =	.667500
051		1.060000 x	15.400000 =	16.324000
026		450.000000 x	.099900 =	44.955000
-----				
			B.T =	61.946500
1446	1446			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.099900 =	34.965000
051		1.120000 x	15.400000 =	17.248000
-----				
			B.T =	52.880500
1447	1447			
021		.250000 x	2.670000 =	.667500
051		1.000000 x	15.400000 =	15.400000
026		400.000000 x	.099900 =	39.960000
1407		.080000 x	37.605000 =	3.008400
-----				
			B.T =	59.035900
1448	1448			
021		.250000 x	2.670000 =	.667500
039		5.000000 x	.000000 =	.000000
051		1.000000 x	15.400000 =	15.400000
1407		.080000 x	37.605000 =	3.008400
026		400.000000 x	.099900 =	39.960000
-----				
			B.T =	
1449	1449			
021		.250000 x	2.670000 =	.667500
1407		.040000 x	37.605000 =	1.504200
051		1.060000 x	15.400000 =	16.324000
026		350.000000 x	.099900 =	34.965000
-----				
			B.T =	53.460700

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.151500 =	90.900000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	220.947750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
026		450.000000 x	.099900 =	44.955000
		-----		
			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
029		450.000000 x	.151500 =	68.175000
		-----		
			B.T =	210.972750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	189.987750

1457	1457			
021		.250000 x	2.670000 =	.667500
029		600.000000 x	.151500 =	90.900000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	220.947750
1458	1458			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.151500 =	68.175000
054		1,650.000000 x	.085000 =	140.250000
		-----		
			B.T =	210.972750
1461	1461			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.099900 =	49.950000
053		1,500.000000 x	.085000 =	127.500000
		-----		
			B.T =	181.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
026		400.000000 x	.099900 =	39.960000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	43.500000 =	43.500000
051		.100000 x	15.400000 =	1.540000
		-----		
			B.T =	87.681250
1463	1463			
021		.300000 x	2.670000 =	.801000
026		250.000000 x	.099900 =	24.975000
515		1.050000 x	43.500000 =	45.675000
1407		.050000 x	37.605000 =	1.880250
051		.100000 x	15.400000 =	1.540000
		-----		
			B.T =	74.871250

1464	1464				
021		.200000 x	2.670000 =	.534000	
051		.420000 x	15.400000 =	6.468000	
1407		.120000 x	37.605000 =	4.512600	
519		.600000 x	50.290000 =	30.174000	
026		150.000000 x	.099900 =	14.985000	
			B.T =	56.673600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	50.290000 =	45.261000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.099900 =	44.955000	
			B.T =	94.188150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	50.290000 =	42.243600	
026		450.000000 x	.099900 =	44.955000	
051		.210000 x	15.400000 =	3.234000	
			B.T =	92.094750	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.099900 =	44.955000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	50.290000 =	35.203000	
			B.T =	87.210150	
1471	1471				
251		1.000000 x	.861000 =	.861000	
351		4.000000 x	.735200 =	2.940800	
358		1.000000 x	3.338500 =	3.338500	
364		2.000000 x	1.133000 =	2.266000	
372		.400000 x	2.470800 =	.988320	
370		6.000000 x	.294100 =	1.764600	
			AΘΡΟΙΣΜΑ =	12.159220	
	B.T =	.476190 x	12.159220 =	5.790099	

1472	1472			
251		.600000 x	.861000 =	.516600
351		2.000000 x	.735200 =	1.470400
361		1.000000 x	1.249900 =	1.249900
363		2.000000 x	1.779400 =	3.558800
372		.300000 x	2.470800 =	.741240
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	10.477740
	B.T =	.666667 x	10.477740 =	6.985163
1473	1473			
251		.500000 x	.861000 =	.430500
354		4.000000 x	.985400 =	3.941600
364		2.000000 x	1.133000 =	2.266000
372		.700000 x	2.470800 =	1.729560
370		4.000000 x	.294100 =	1.176400
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	28.672760
	B.T =	.416667 x	28.672760 =	11.946993
1474	1474			
251		.500000 x	.861000 =	.430500
372		.500000 x	2.470800 =	1.235400
370		4.000000 x	.294100 =	1.176400
366		2.000000 x	5.000500 =	10.001000
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
357		4.000000 x	1.441300 =	5.765200
			AΘΡΟΙΣΜΑ =	34.796400
	B.T =	.416667 x	34.796400 =	14.498512
1475	1475			
251		.300000 x	.861000 =	.258300
379		1.000000 x	27.450000 =	27.450000
371		2.000000 x	1.779400 =	3.558800
376		160.000000 x	.220400 =	35.264000
377		6.000000 x	.926400 =	5.558400
378		1.000000 x	14.950000 =	14.950000
375		2.000000 x	3.470900 =	6.941800
354		3.000000 x	.985400 =	2.956200
			AΘΡΟΙΣΜΑ =	96.937500
	B.T =	.416667 x	96.937500 =	40.390657



1476	1476			
251		.500000 x	.861000 =	.430500
373		.200000 x	2.735500 =	.547100
370		6.000000 x	.294100 =	1.764600
352		3.000000 x	1.133000 =	3.399000
			AΘΡΟΙΣΜΑ =	6.141200
	B.T =	.500000 x	6.141200 =	3.070600
1478	1478			
251		3.000000 x	.861000 =	2.583000
372		.500000 x	2.470800 =	1.235400
356		2.000000 x	.661600 =	1.323200
370		6.000000 x	.294100 =	1.764600
			AΘΡΟΙΣΜΑ =	6.906200
	B.T =	.500000 x	6.906200 =	3.453100
1479	1479			
251		6.000000 x	.861000 =	5.166000
370		12.000000 x	.294100 =	3.529200
381		1.000000 x	74.770000 =	74.770000
			AΘΡΟΙΣΜΑ =	83.465200
	B.T =	.454545 x	83.465200 =	37.938689
1480	1480			
251		8.000000 x	.861000 =	6.888000
381		2.000000 x	74.770000 =	149.540000
370		16.000000 x	.294100 =	4.705600
			AΘΡΟΙΣΜΑ =	161.133600
	B.T =	.227273 x	161.133600 =	36.621317
1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.085000 =	.019550
487		.040000 x	13.884000 =	.555360
451		.230000 x	1.214200 =	.279266
			B.T =	.855511
1487	1487			
443		.120000 x	1.987900 =	.238548
451		.170000 x	1.214200 =	.206414
453		.640000 x	.085000 =	.054400
446		.010000 x	2.662500 =	.026625
445		.060000 x	1.600000 =	.096000
			B.T =	.621987

1488	1488			
444		.170000 x	2.207500 =	.375275
453		.500000 x	.085000 =	.042500
451		.170000 x	1.214200 =	.206414
446		.030000 x	2.662500 =	.079875
445		.050000 x	1.600000 =	.080000
		-----		
			B.T =	.784064
1489	1489			
444		.100000 x	2.207500 =	.220750
453		.430000 x	.085000 =	.036550
451		.350000 x	1.214200 =	.424970
446		.020000 x	2.662500 =	.053250
445		.100000 x	1.600000 =	.160000
		-----		
			B.T =	.895520
1490	1490			
444		.300000 x	2.207500 =	.662250
445		.100000 x	1.600000 =	.160000
446		.030000 x	2.662500 =	.079875
451		.570000 x	1.214200 =	.692094
		-----		
			B.T =	1.594219
1491	1491			
444		.270000 x	2.207500 =	.596025
445		.060000 x	1.600000 =	.096000
451		.650000 x	1.214200 =	.789230
446		.020000 x	2.662500 =	.053250
		-----		
			B.T =	1.534505
1492	1492			
444		.200000 x	2.207500 =	.441500
446		.030000 x	2.662500 =	.079875
445		.040000 x	1.600000 =	.064000
455		.730000 x	3.090000 =	2.255700
		-----		
			B.T =	2.841075
1501	1501			
011		1.000000 x	55.210000 =	55.210000
012		2.000000 x	4.530000 =	9.060000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	1.175600 =	17.634000
484		1.750000 x	4.160000 =	7.280000
		-----		
			B.T =	470.306473

1502	1502				
013		1.000000 x	27.370000 =	27.370000	
005		3.500000 x	21.778427 =	76.224495	
001		26.000000 x	15.741598 =	409.281548	
482		15.000000 x	1.433300 =	21.499500	
484		.900000 x	4.160000 =	3.744000	
		-----			
			B.T =	538.119543	
1503	1503				
014		1.000000 x	268.420000 =	268.420000	
002		2.600000 x	17.312112 =	45.011491	
004		7.000000 x	23.886192 =	167.203344	
484		2.600000 x	4.160000 =	10.816000	
485		44.000000 x	1.175600 =	51.726400	
		-----			
			B.T =	543.177235	
1504	1504				
015		1.000000 x	206.720000 =	206.720000	
004		7.000000 x	23.886192 =	167.203344	
002		7.000000 x	17.312112 =	121.184784	
485		83.000000 x	1.175600 =	97.574800	
484		5.250000 x	4.160000 =	21.840000	
291		2.200000 x	5.000000 =	11.000000	
		-----			
			B.T =	625.522928	
1505	1505				
016		1.000000 x	32.560000 =	32.560000	
004		7.000000 x	23.886192 =	167.203344	
002		1.750000 x	17.312112 =	30.296196	
485		17.500000 x	1.175600 =	20.573000	
484		1.750000 x	4.160000 =	7.280000	
		-----			
			B.T =	257.912540	
1506	1506				
017		1.000000 x	380.180000 =	380.180000	
002		3.500000 x	17.312112 =	60.592392	
484		6.000000 x	4.160000 =	24.960000	
004		7.000000 x	23.886192 =	167.203344	
485		70.000000 x	1.175600 =	82.292000	
		-----			
			B.T =	715.227736	
2101	2101				
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	5.193634	

2102	2102			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2108A	2108A			
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	12.118478
2108B	2108B			
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	27.699379

2108E	2108E			
002		4.600000 x	17.312112 =	79.635715
		-----		
			T.E =	79.635715
2108H	2108H			
002		7.600000 x	17.312112 =	131.572051
		-----		
			T.E =	131.572051
2108Z	2108Z			
002		6.600000 x	17.312112 =	114.259939
		-----		
			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491
		-----		
			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603
		-----		
			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163
		-----		
			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827
		-----		
			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1506		.004000 x	715.227736 =	2.860911
1503		.001000 x	543.177235 =	.543177
		-----		
			T.E =	3.923452
2110	2110			
002		.040000 x	17.312112 =	.692484
1501		.005000 x	470.306473 =	2.351532
1506		.004000 x	715.227736 =	2.860911
1503		.001000 x	543.177235 =	.543177
		-----		
			T.E =	6.448105



2111	2111				
002		.100000 x	17.312112 =	1.731211	
1504		.005000 x	625.522928 =	3.127615	
		-----			
			T.E =	4.858826	
2112	2112				
002		.120000 x	17.312112 =	2.077453	
1504		.005500 x	625.522928 =	3.440376	
1501		.004000 x	470.306473 =	1.881226	
		-----			
			T.E =	7.399055	
2113	2113				
002		1.400000 x	17.312112 =	24.236957	
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	29.430590	
2114	2114				
002		1.500000 x	17.312112 =	25.968168	
1501		.005000 x	470.306473 =	2.351532	
002		.400000 x	17.312112 =	6.924845	
		-----			
			T.E =	35.244545	
2115	2115				
481		.300000 x	5.467500 =	1.640250	
003		1.200000 x	20.419486 =	24.503383	
1501		.011000 x	470.306473 =	5.173371	
002		.600000 x	17.312112 =	10.387267	
		-----			
			T.E =	41.704272	
2116	2116				
2115		1.300000 x	41.704272 =	54.215554	
		-----			
			T.E =	54.215554	
2117	2117				
002		.600000 x	17.312112 =	10.387267	
1501		.125000 x	470.306473 =	58.788309	
		-----			
			T.E =	69.175576	
2118	2118				
2117		1.300000 x	69.175576 =	89.928249	
		-----			
			T.E =	89.928249	

2121	2121				
001		.400000 x	15.741598 =	6.296639	
002		1.800000 x	17.312112 =	31.161802	
		-----			
			T.E =	37.458441	
2122	2122				
001		.500000 x	15.741598 =	7.870799	
1501		.005000 x	470.306473 =	2.351532	
002		2.000000 x	17.312112 =	34.624224	
		-----			
			T.E =	44.846555	
2123	2123				
002		.200000 x	17.312112 =	3.462422	
1504		.008300 x	625.522928 =	5.191840	
		-----			
			T.E =	8.654263	
2124	2124				
002		.200000 x	17.312112 =	3.462422	
1501		.005000 x	470.306473 =	2.351532	
1504		.010000 x	625.522928 =	6.255229	
		-----			
			T.E =	12.069184	
2125	2125				
481		.400000 x	5.467500 =	2.187000	
1501		.020000 x	470.306473 =	9.406129	
002		1.000000 x	17.312112 =	17.312112	
003		1.500000 x	20.419486 =	30.629229	
		-----			
			T.E =	59.534470	
2126	2126				
2125		1.300000 x	59.534470 =	77.394811	
		-----			
			T.E =	77.394811	
2127	2127				
002		1.000000 x	17.312112 =	17.312112	
1501		.166600 x	470.306473 =	78.353058	
		-----			
			T.E =	95.665170	
2128	2128				
2127		1.300000 x	95.665170 =	124.364721	
		-----			
			T.E =	124.364721	

2131	2131			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
2132	2132			
1504		.001600 x	625.522928 =	1.000837
		-----		
			T.E =	1.000837
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267
		-----		
			T.E =	12.118478
2134	2134			
1504		.002500 x	625.522928 =	1.563807
		-----		
			T.E =	1.563807
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973
		-----		
			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	44.846555 =	58.300522
		-----		
			T.E =	58.300522
2135.3	2135.3			
2127		1.300000 x	95.665170 =	124.364721
		-----		
			T.E =	124.364721
2135.4	2135.4			
2128		1.300000 x	124.364721 =	161.674137
		-----		
			T.E =	161.674137
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	82.531911

2142	2142				
001		2.000000 x	15.741598 =	31.483196	
1501		.005000 x	470.306473 =	2.351532	
003		3.000000 x	20.419486 =	61.258458	
		-----			
			T.E =	95.093186	
2143	2143				
481		.500000 x	5.467500 =	2.733750	
001		2.000000 x	15.741598 =	31.483196	
003		3.000000 x	20.419486 =	61.258458	
1501		.025000 x	470.306473 =	11.757662	
		-----			
			T.E =	107.233066	
2144	2144				
2143		1.300000 x	107.233066 =	139.402986	
		-----			
			T.E =	139.402986	
2145	2145				
001		2.000000 x	15.741598 =	31.483196	
003		1.000000 x	20.419486 =	20.419486	
1501		.200000 x	470.306473 =	94.061295	
		-----			
			T.E =	145.963977	
2146	2146				
2145		1.300000 x	145.963977 =	189.753170	
		-----			
			T.E =	189.753170	
2151	2151				
001		1.200000 x	15.741598 =	18.889918	
003		.800000 x	20.419486 =	16.335589	
		-----			
			T.E =	35.225506	
2152	2152				
001		1.500000 x	15.741598 =	23.612397	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	44.031883	
2161	2161				
1505		.003300 x	257.912540 =	.851111	
		-----			
			T.E =	.851111	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	625.522928 =	2.502092
		-----		
			T.E =	2.651692
2172	2172			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536
		-----		
			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400
		-----		
			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713
		-----		
			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2185	2185			
018.1		.142800 x	2.990000 =	.426972
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.160000 =	.416000
482		.700000 x	1.433300 =	1.003310
018.1		.042800 x	2.990000 =	.127972
		-----		
			T.E =	10.685625
2186	2186			
018.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	4.530000 =	.193884
482		1.400000 x	1.433300 =	2.006620
484		.200000 x	4.160000 =	.832000
		-----		
			T.E =	12.390759
2187	2187			
019.1		.142800 x	2.990000 =	.426972
485		1.100000 x	1.175600 =	1.293160
019.1		.428000 x	2.990000 =	1.279720
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.160000 =	.416000
		-----		
			T.E =	12.127223
2188	2188			
019.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	1.175600 =	2.116080
484		.200000 x	4.160000 =	.832000
019.2		.042800 x	4.530000 =	.193884
		-----		
			T.E =	12.500219

ΑΤΟΕ	3ο Τρίμηνο του 2011	Σελ. Ημ/νία	31 22/12/2011
2201	2201		
001	1.000000 x	15.741598 =	15.741598
002	2.000000 x	17.312112 =	34.624224
-----			
		T.E =	50.365822
2202	2202		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560
-----			
		T.E =	102.302158
2203	2203		
001	1.000000 x	15.741598 =	15.741598
002	2.500000 x	17.312112 =	43.280280
-----			
		T.E =	59.021878
2204	2204		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560
-----			
		T.E =	102.302158
2206	2206		
001	1.000000 x	15.741598 =	15.741598
003	3.000000 x	20.419486 =	61.258458
-----			
		T.E =	77.000056
2207	2207		
001	1.000000 x	15.741598 =	15.741598
003	6.000000 x	20.419486 =	122.516916
-----			
		T.E =	138.258514
2211	2211		
001	2.000000 x	15.741598 =	31.483196
-----			
		T.E =	31.483196
2212	2212		
001	1.000000 x	15.741598 =	15.741598
-----			
		T.E =	15.741598
2213	2213		
001	2.000000 x	15.741598 =	31.483196
-----			
		T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344
		-----		
			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390
		-----		
			T.E =	.408390



2236	2236			
001		.100000 x	15.741598 =	1.574160
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	6.767793
2237	2237			
001		.200000 x	15.741598 =	3.148320
003		.700000 x	20.419486 =	14.293640
-----				
			T.E =	17.441960
2238	2238			
001		.100000 x	15.741598 =	1.574160
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	8.499005
2239	2239			
001		.200000 x	15.741598 =	3.148320
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	19.483908
2241	2241			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949
-----				
			T.E =	6.764428
2242	2242			
001		.400000 x	15.741598 =	6.296639
003		.150000 x	20.419486 =	3.062923
-----				
			T.E =	9.359562
2243	2243			
001		.500000 x	15.741598 =	7.870799
003		.250000 x	20.419486 =	5.104872
-----				
			T.E =	12.975671
2246	2246			
001		.250000 x	15.741598 =	3.935400
003		.050000 x	20.419486 =	1.020974
-----				
			T.E =	4.956374

2247	2247			
001		.350000 x	15.741598 =	5.509559
003		.100000 x	20.419486 =	2.041949
-----				
			T.E =	7.551508
2248	2248			
001		.450000 x	15.741598 =	7.083719
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	11.167616
2251	2251			
001		.100000 x	15.741598 =	1.574160
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	6.767793
2252	2252			
001		.100000 x	15.741598 =	1.574160
002		.600000 x	17.312112 =	10.387267
-----				
			T.E =	11.961427
2261A	2261A			
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	8.167794
2261B	2261B			
003		.700000 x	20.419486 =	14.293640
-----				
			T.E =	14.293640
2261Γ	2261Γ			
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	18.377537
2261Δ	2261Δ			
003		1.200000 x	20.419486 =	24.503383
-----				
			T.E =	24.503383
2262A	2262A			
003		.550000 x	20.419486 =	11.230717
-----				
			T.E =	11.230717

2262B	2262B			
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049
		-----		
			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818
		-----		
			T.E =	46.964818
2264.2Α	2264.2Α			
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	40.838972
2264.2Β	2264.2Β			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561
		-----		
			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355
		-----		
			T.E =	65.342355
2264.3Α	2264.3Α			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.3Β	2264.3Β			
003		2.850000 x	20.419486 =	58.195535
		-----		
			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304
		-----		
			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073
		-----		
			T.E =	76.573073
2265Α	2265Α			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728
		-----		
			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184
		-----		
			T.E =	33.079567
2266.11	2266.11			
2263Γ		1.000000 x	32.671178 =	32.671178
2263Γ		.350000 x	32.671178 =	11.434912
		-----		
			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322
		-----		
			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912
		-----		
			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617
		-----		
			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322
		-----		
			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686
				-----
			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640
				-----
			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368
				-----
			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096
				-----
			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774
				-----
			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824
				-----
			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368
				-----
			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437
				-----
			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =		67.384304
2264.3Γ		.350000 x	67.384304 =		23.584506
				T.E =	90.968810
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =		76.573073
2264.3Δ		.350000 x	76.573073 =		26.800576
				T.E =	103.373649
2266.25	2266.25				
2265A		1.000000 x	10.209743 =		10.209743
2265A		.350000 x	10.209743 =		3.573410
				T.E =	13.783153
2266.26	2266.26				
2265B		1.000000 x	16.335589 =		16.335589
2265B		.350000 x	16.335589 =		5.717456
				T.E =	22.053045
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =		18.377537
2261Γ		.350000 x	18.377537 =		6.432138
				T.E =	24.809675
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =		24.503383
2261Δ		.350000 x	24.503383 =		8.576184
				T.E =	33.079567
2266.5	2266.5				
2262A		1.000000 x	11.230717 =		11.230717
2262A		.350000 x	11.230717 =		3.930751
				T.E =	15.161468
2266.6	2266.6				
2262B		1.000000 x	18.377537 =		18.377537
2262B		.350000 x	18.377537 =		6.432138
				T.E =	24.809675

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184
		-----		
			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912
		-----		
			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774
		-----		
			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967
		-----		
			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710
		-----		
			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453
		-----		
			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	40.838972



2269B	2269B			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458
2269Γ	2269Γ			
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	81.677944
2270.1	2270.1			
2267		1.000000 x	71.468201 =	71.468201
2267		.600000 x	71.468201 =	42.880921
		-----		
			T.E =	114.349122
2270.2	2270.2			
2268A		1.000000 x	102.097430 =	102.097430
2268A		.600000 x	102.097430 =	61.258458
		-----		
			T.E =	163.355888
2270.3	2270.3			
2268B		1.000000 x	120.474967 =	120.474967
2268B		.600000 x	120.474967 =	72.284980
		-----		
			T.E =	192.759947
2270.4	2270.4			
2268Γ		1.000000 x	130.684710 =	130.684710
2268Γ		.600000 x	130.684710 =	78.410826
		-----		
			T.E =	209.095536
2270.5	2270.5			
2268Δ		1.000000 x	140.894453 =	140.894453
2268Δ		.600000 x	140.894453 =	84.536672
		-----		
			T.E =	225.431125
2271A	2271A			
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.048715
2271B	2271B			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458

2271E	2271E			
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098
		-----		
			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019
		-----		
			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939
		-----		
			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220
		-----		
			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299
		-----		
			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738
		-----		
			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379
		-----		
			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580
		-----		
			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631
		-----		
			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860
		-----		
			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089
		-----		
			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318
		-----		
			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330
		-----		
			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323
		-----		
			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995
		-----		
			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727
		-----		
			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459
		-----		
			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193
		-----		
			T.E =	135.381193
2274.15	2274.15			
2272Ε		1.300000 x	118.433019 =	153.962925
		-----		
			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657
		-----		
			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389
		-----		
			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121
		-----		
			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854
		-----		
			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995
		-----		
			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586
		-----		
			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320
		-----		
			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318
		-----		
			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316
		-----		
			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313
		-----		
			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661
		-----		
			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327
		-----		
			T.E =	106.181327
2274.5	2274.5			
2271Ε		1.300000 x	91.887687 =	119.453993
		-----		
			T.E =	119.453993
2274.6	2274.6			
2271ΣΤ		1.300000 x	102.097430 =	132.726659
		-----		
			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325
		-----		
			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991
		-----		
			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657
		-----		
			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	290.000000 =	9.570000
001		9.000000 x	15.741598 =	141.674382
003		5.000000 x	20.419486 =	102.097430
251		6.000000 x	.861000 =	5.166000
		-----		
			T.E =	267.207812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	5.483634

2303	2303				
001		.250000 x	15.741598 =	3.935400	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	9.040271	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.312112 =	1.731211	
		-----			
			T.E =	1.847211	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	290.000000 =	11.600000	
003		7.000000 x	20.419486 =	142.936402	
001		9.000000 x	15.741598 =	141.674382	
251		6.000000 x	.861000 =	5.166000	
		-----			
			T.E =	312.976784	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	290.000000 =	.580000	
251		.250000 x	.861000 =	.215250	
001		.250000 x	15.741598 =	3.935400	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	8.373572	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.861000 =	.172200	
203.4		.001000 x	290.000000 =	.290000	
003		.100000 x	20.419486 =	2.041949	
001		.200000 x	15.741598 =	3.148320	
		-----			
			T.E =	6.232468	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.419486 =	.612585	
		-----			
			T.E =	1.102085	
2314.2	2314.2				
512		1.000000 x	.437500 =	.437500	
003		.030000 x	20.419486 =	.612585	
		-----			
			T.E =	1.050085	

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		175.000000 x	.099900 =	17.482500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	
-----					
			T.E =	103.260033	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		200.000000 x	.099900 =	19.980000	
-----					
			T.E =	105.391933	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.099900 =	24.975000	
-----					
			T.E =	110.021333	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.099900 =	29.970000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.800000 x	10.580000 =	8.464000	
-----					
			T.E =	114.650733	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	20.419486 =	30.629229	
001		4.000000 x	15.741598 =	62.966392	
026		200.000000 x	.099900 =	19.980000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	
-----					
			T.E =	129.598321	



3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
026		250.000000 x	.099900 =	24.975000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	15.400000 =	6.314000
-----				
			T.E =	129.650502
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.099900 =	29.970000
-----				
			T.E =	160.231243
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.099900 =	14.985000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
052		.420000 x	15.400000 =	6.468000
-----				
			T.E =	117.370190
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000
-----				
			T.E =	107.843233
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.560000 x	15.400000 =	8.624000
-----				
			T.E =	110.051133

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.099900 =	24.975000

-----  
T.E = 114.466933

3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.530000 x	15.400000 =	8.162000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.800000 x	13.560000 =	10.848000

-----  
T.E = 119.036733

3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
026		200.000000 x	.099900 =	19.980000
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000

-----  
T.E = 259.975359

3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
052		.410000 x	15.400000 =	6.314000

-----  
T.E = 264.390159

3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.099900 =	19.980000

-----  
T.E = 193.185046

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
052		.430000 x	15.400000 =	6.622000
-----				
			T.E =	197.907846
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.099900 =	19.980000
-----				
			T.E =	134.257521
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.099900 =	24.975000
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.540000 x	15.400000 =	8.316000
-----				
			T.E =	134.096102
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.099900 =	29.970000
-----				
			T.E =	164.617243
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.099900 =	34.965000
052		.400000 x	15.400000 =	6.160000
062		.600000 x	13.560000 =	8.136000
-----				
			T.E =	176.443742

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.250000 x	13.610000 =	3.402500
027		350.000000 x	.119300 =	41.755000
062		.560000 x	13.560000 =	7.593600
052		.420000 x	15.400000 =	6.468000
-----				
			T.E =	182.727142
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.119300 =	50.702500
062		.550000 x	13.560000 =	7.458000
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
001		4.000000 x	15.741598 =	62.966392
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000
-----				
			T.E =	198.604041
3217	3217			
001		2.500000 x	15.741598 =	39.353995
-----				
			T.E =	39.353995
3218	3218			
001		5.000000 x	15.741598 =	78.707990
-----				
			T.E =	78.707990
3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	128.902738
3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	160.385934
3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916
-----				
			T.E =	169.741710

3222	3222				
001		5.000000 x	15.741598 =		78.707990
003		6.000000 x	20.419486 =		122.516916
		-----			
			T.E =		201.224906
3223A.1	3223A.1				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	538.119543 =		26.905977
003		1.500000 x	20.419486 =		30.629229
		-----			
			AΘΡΟΙΣΜΑ =		89.018402
	T.E =	.500000 x	89.018402 =		44.509201
		-----			
3223A.2	3223A.2				
001		3.000000 x	15.741598 =		47.224794
1502		.050000 x	538.119543 =		26.905977
003		2.000000 x	20.419486 =		40.838972
		-----			
			AΘΡΟΙΣΜΑ =		114.969743
	T.E =	.500000 x	114.969743 =		57.484872
		-----			
3223A.3	3223A.3				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	538.119543 =		26.905977
003		1.500000 x	20.419486 =		30.629229
		-----			
			AΘΡΟΙΣΜΑ =		89.018402
	T.E =	.500000 x	89.018402 =		44.509201
		-----			
3223A.4	3223A.4				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	538.119543 =		26.905977
		-----			
			AΘΡΟΙΣΜΑ =		114.969743
	T.E =	.500000 x	114.969743 =		57.484872
		-----			
3223A.5	3223A.5				
001		3.500000 x	15.741598 =		55.095593
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	538.119543 =		26.905977
		-----			
			AΘΡΟΙΣΜΑ =		122.840542
	T.E =	.500000 x	122.840542 =		61.420271
		-----			

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.119543 =	26.905977
			-----	
			ΑΘΡΟΙΣΜΑ =	122.840542
	T.E =	.500000 x	122.840542 =	61.420271
			-----	
3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
			-----	
			ΑΘΡΟΙΣΜΑ =	130.711341
	T.E =	.500000 x	130.711341 =	65.355671
			-----	
3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	538.119543 =	26.905977
			-----	
			ΑΘΡΟΙΣΜΑ =	89.018402
	T.E =	.250000 x	89.018402 =	22.254601
			-----	
3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.119543 =	26.905977
			-----	
			ΑΘΡΟΙΣΜΑ =	114.969743
	T.E =	.250000 x	114.969743 =	28.742436
			-----	
3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	538.119543 =	26.905977
			-----	
			ΑΘΡΟΙΣΜΑ =	89.018402
	T.E =	.250000 x	89.018402 =	22.254601
			-----	
3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	538.119543 =	26.905977
003		2.000000 x	20.419486 =	40.838972
			-----	
			ΑΘΡΟΙΣΜΑ =	114.969743
	T.E =	.250000 x	114.969743 =	28.742436
			-----	

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.119543 =	26.905977
		-----		
			ΑΘΡΟΙΣΜΑ =	122.840542
	T.E =	.250000 x	122.840542 =	30.710136
		-----		
3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.119543 =	26.905977
		-----		
			ΑΘΡΟΙΣΜΑ =	122.840542
	T.E =	.250000 x	122.840542 =	30.710136
		-----		
3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.119543 =	26.905977
		-----		
			ΑΘΡΟΙΣΜΑ =	130.711341
	T.E =	.250000 x	130.711341 =	32.677835
		-----		
3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.099900 =	14.985000
		-----		
			T.E =	122.029390
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	36.000000 =	5.400000
056		.800000 x	10.580000 =	8.464000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
		-----		
			T.E =	96.089932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
051		.200000 x	15.400000 =	3.080000
001		3.500000 x	15.741598 =	55.095593
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	98.230182
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	36.000000 =	14.400000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
-----				
			T.E =	102.350182
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
032		.400000 x	36.000000 =	14.400000
026		100.000000 x	.099900 =	9.990000
-----				
			T.E =	117.499576
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	36.000000 =	5.760000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
-----				
			T.E =	100.060382
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	15.741598 =	55.095593
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
061		.840000 x	13.560000 =	11.390400
-----				
			T.E =	110.214426



3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
-----				
			T.E =	114.540426
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
032		.420000 x	36.000000 =	15.120000
026		100.000000 x	.099900 =	9.990000
-----				
			T.E =	121.522026
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.099900 =	13.986000
052		.294000 x	15.400000 =	4.527600
-----				
			T.E =	91.562320
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280
026		140.000000 x	.099900 =	13.986000
058		.500000 x	9.090000 =	4.545000
052		.392000 x	15.400000 =	6.036800
-----				
			T.E =	94.823760
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
026		175.000000 x	.099900 =	17.482500
052		.287000 x	15.400000 =	4.419800
-----				
			T.E =	94.802900

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.574000 x	13.560000 =	7.783440
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.099900 =	17.482500
		-----		
			T.E =	97.914820
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.099900 =	13.986000
052		.294000 x	15.400000 =	4.527600
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
		-----		
			T.E =	92.522320
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
		-----		
			T.E =	95.783760
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
056		.574000 x	10.580000 =	6.072920
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	15.741598 =	39.353995
026		175.000000 x	.099900 =	17.482500
052		.287000 x	15.400000 =	4.419800
		-----		
			T.E =	95.762900

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
061		.574000 x	13.560000 =	7.783440
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.099900 =	17.482500
-----				
			T.E =	98.874820
3501	3501			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
001		5.000000 x	15.741598 =	78.707990
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
067		1.050000 x	45.500000 =	47.775000
-----				
			T.E =	181.824862
3502	3502			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.099900 =	9.990000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.050000 x	45.500000 =	47.775000
032		.200000 x	36.000000 =	7.200000
-----				
			T.E =	188.806462
3503	3503			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
067		1.000000 x	45.500000 =	45.500000
032		.200000 x	36.000000 =	7.200000
-----				
			T.E =	190.774362
3504	3504			
021		.200000 x	2.670000 =	.534000
003		3.200000 x	20.419486 =	65.342355
001		5.000000 x	15.741598 =	78.707990
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.090000 =	16.200000
026		250.000000 x	.099900 =	24.975000
-----				
			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
055		420.000000 x	.090000 =	37.800000
003		5.000000 x	20.419486 =	102.097430
001		5.500000 x	15.741598 =	86.578789
517		4.000000 x	.000000 =	.000000
026		250.000000 x	.099900 =	24.975000

-----  
T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	43.500000 =	50.025000
003		2.500000 x	20.419486 =	51.048715
001		5.000000 x	15.741598 =	78.707990
026		200.000000 x	.099900 =	19.980000

-----  
T.E =

200.562705

3511	3511			
021		.200000 x	2.670000 =	.534000
001		5.000000 x	15.741598 =	78.707990
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
032		.200000 x	36.000000 =	7.200000
069		1.050000 x	.000000 =	.000000

-----  
T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
069		1.050000 x	.000000 =	.000000
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.099900 =	9.990000

-----  
T.E =

3513	3513			
001		2.500000 x	15.741598 =	39.353995

-----  
T.E =

39.353995

3514	3514			
001		5.000000 x	15.741598 =	78.707990

-----  
T.E =

78.707990

3801	3801				
201		.001500 x	290.000000 =		.435000
003		.500000 x	20.419486 =		10.209743
001		.400000 x	15.741598 =		6.296639
203.4		.002500 x	290.000000 =		.725000
251		.300000 x	.861000 =		.258300
		-----			
			T.E =		17.924682
3802	3802				
3801		.050000 x	17.924682 =		.896234
		-----			
			T.E =		.896234
3811	3811				
203.4		.004000 x	290.000000 =		1.160000
251		.100000 x	.861000 =		.086100
003		.800000 x	20.419486 =		16.335589
001		.200000 x	15.741598 =		3.148320
		-----			
			T.E =		20.730008
3816	3816				
201		.002500 x	290.000000 =		.725000
003		.600000 x	20.419486 =		12.251692
001		.400000 x	15.741598 =		6.296639
203.4		.003000 x	290.000000 =		.870000
251		.200000 x	.861000 =		.172200
		-----			
			T.E =		20.315531
3817	3817				
3816		.150000 x	20.315531 =		3.047330
		-----			
			T.E =		3.047330
3821	3821				
201		.014000 x	290.000000 =		4.060000
251		.600000 x	.861000 =		.516600
003		2.400000 x	20.419486 =		49.006766
001		.600000 x	15.741598 =		9.444959
203.4		.018000 x	290.000000 =		5.220000
		-----			
			T.E =		68.248325
3822	3822				
3821		.150000 x	68.248325 =		10.237249
		-----			
			T.E =		10.237249

3823	3823				
201		.020000 x	290.000000 =	5.800000	
001		.600000 x	15.741598 =	9.444959	
003		3.000000 x	20.419486 =	61.258458	
251		.180000 x	.861000 =	.154980	
203.4		.025000 x	290.000000 =	7.250000	
		-----			
			T.E =	83.908397	
3824	3824				
3823		.200000 x	83.908397 =	16.781679	
		-----			
			T.E =	16.781679	
3831	3831				
201		.020000 x	290.000000 =	5.800000	
003		4.500000 x	20.419486 =	91.887687	
001		1.100000 x	15.741598 =	17.315758	
251		.800000 x	.861000 =	.688800	
203.4		.024000 x	290.000000 =	6.960000	
		-----			
			T.E =	122.652245	
3832	3832				
3831		.150000 x	122.652245 =	18.397837	
		-----			
			T.E =	18.397837	
3833	3833				
201		.022000 x	290.000000 =	6.380000	
003		6.000000 x	20.419486 =	122.516916	
001		1.100000 x	15.741598 =	17.315758	
251		1.000000 x	.861000 =	.861000	
203.4		.025000 x	290.000000 =	7.250000	
		-----			
			T.E =	154.323674	
3834	3834				
3833		.200000 x	154.323674 =	30.864735	
		-----			
			T.E =	30.864735	
3841	3841				
203.4		.001500 x	290.000000 =	.435000	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	10.644743	

3851	3851			
203.4		.052000 x	290.000000 =	15.080000
251		1.100000 x	.861000 =	.947100
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	42.572432
3852	3852			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	6.764428
3871	3871			
260		1.030000 x	.545500 =	.561865
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	1.582839
3872	3872			
261		1.030000 x	.598400 =	.616352
003		.040000 x	20.419486 =	.816779
		-----		
			T.E =	1.433131
3873	3873			
262		1.030000 x	.545500 =	.561865
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	1.582839
3874	3874			
258		1.450000 x	7.877500 =	11.422375
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	14.485298
3875	3875			
259		1.000000 x	25.290000 =	25.290000
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	31.415846
3876	3876			
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	1.225169

3881.1	3881.1			
111		1,023.391800 x	.075900 =	77.675438
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	156.383428
3881.2	3881.2			
112		627.989998 x	.083300 =	52.311567
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	131.019557
3882	3882			
127		1.050000 x	81.220000 =	85.281000
001		4.000000 x	15.741598 =	62.966392
		-----		
			T.E =	148.247392
4101	4101			
081		1.150000 x	11.010000 =	12.661500
001		1.300000 x	15.741598 =	20.464077
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	73.964549
4102	4102			
081		1.200000 x	11.010000 =	13.212000
001		1.700000 x	15.741598 =	26.760717
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	111.440918
4103	4103			
081		1.150000 x	11.010000 =	12.661500
003		4.000000 x	20.419486 =	81.677944
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	141.564238
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	58.785294
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	20.419486 =	18.377537
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	37.972635



4106	4106			
081		.320000 x	11.010000 =	3.523200
001		.700000 x	15.741598 =	11.019119
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	32.919856
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	105.953654
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	149.766208
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
003		2.500000 x	20.419486 =	51.048715
001		2.900000 x	15.741598 =	45.650634
		-----		
			T.E =	123.460407
4206	4206			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
003		3.100000 x	20.419486 =	63.300407
1417		.350000 x	40.284450 =	14.099558
		-----		
			T.E =	135.712098
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	40.284450 =	14.099558
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	154.089636

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.741598 =	45.650634	
1447		.350000 x	59.035900 =	20.662565	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	130.023414	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		3.100000 x	20.419486 =	63.300407	
001		2.900000 x	15.741598 =	45.650634	
		-----			
			T.E =	142.275106	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
001		2.900000 x	15.741598 =	45.650634	
003		4.000000 x	20.419486 =	81.677944	
		-----			
			T.E =	160.652643	
4221	4221				
001		.800000 x	15.741598 =	12.593278	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	33.012764	
4222	4222				
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	14.464434	
4226	4226				
003		1.300000 x	20.419486 =	26.545332	
		-----			
			T.E =	26.545332	
4251	4251				
083		32.000000 x	.000000 =	.000000	
1412		.200000 x	27.931800 =	5.586360	
001		2.900000 x	15.741598 =	45.650634	
003		4.000000 x	20.419486 =	81.677944	
		-----			
			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
1417		.200000 x	40.284450 =	8.056890
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1445		.200000 x	61.946500 =	12.389300
003		4.000000 x	20.419486 =	81.677944

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
1447		.200000 x	59.035900 =	11.807180
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E =

4301	4301			16.176598
081		1.020000 x	11.010000 =	11.230200
003		4.200000 x	20.419486 =	85.761841
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
1417		.350000 x	40.284450 =	14.099558
003		2.700000 x	20.419486 =	55.132612
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	40.284450 =	14.099558
003		3.300000 x	20.419486 =	67.384304
001		2.900000 x	15.741598 =	45.650634
083		3.000000 x	.000000 =	.000000

-----  
T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
1417		.350000 x	40.284450 =	14.099558
003		4.200000 x	20.419486 =	85.761841
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000

-----  
T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	20.419486 =	55.132612
1447		.350000 x	59.035900 =	20.662565
001		2.900000 x	15.741598 =	45.650634

-----  
T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
1447		.350000 x	59.035900 =	20.662565
003		3.300000 x	20.419486 =	67.384304
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634

-----  
T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	59.035900 =	20.662565
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000

-----  
T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

-----  
T.E = 16.176598

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980
251		4.000000 x	.861000 =	3.444000

-----  
T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
001		10.000000 x	15.741598 =	157.415980
251		4.000000 x	.861000 =	3.444000
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150

-----  
T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
1446		.100000 x	52.880500 =	5.288050
251		4.000000 x	.861000 =	3.444000
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980

-----  
T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
001		11.000000 x	15.741598 =	173.157578
003		32.000000 x	20.419486 =	653.423552
1446		.200000 x	52.880500 =	10.576100
251		8.000000 x	.861000 =	6.888000

-----  
T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578
251		8.000000 x	.861000 =	6.888000

-----  
T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.861000 =	6.888000
001		11.000000 x	15.741598 =	173.157578
			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918
			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794
			T.E =	47.224794
4501	4501			
081		.050000 x	11.010000 =	.550500
003		1.000000 x	20.419486 =	20.419486
002		.500000 x	17.312112 =	8.656056
			T.E =	29.626042
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.300000 x	20.419486 =	26.545332
			T.E =	35.751888
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.400000 x	20.419486 =	28.587280
			T.E =	37.793836
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818
			T.E =	52.708951

4505	4505			
081		.050000 x	11.010000 =	.550500
003		2.700000 x	20.419486 =	55.132612
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	60.876746
4506	4506			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.600000 x	20.419486 =	73.510150
-----				
			T.E =	79.254283
4507	4507			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.200000 x	20.419486 =	65.342355
-----				
			T.E =	71.086489
4508	4508			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.000000 x	20.419486 =	61.258458
-----				
			T.E =	67.002592
4511	4511			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	83.338180
4512	4512			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	87.422078
4515	4515			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	107.841564

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	97.631821
4517	4517			
081		.050000 x	11.010000 =	.550500
003		6.500000 x	20.419486 =	132.726659
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	138.470793
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.700000 x	20.419486 =	116.391070
		-----		
			T.E =	122.135204
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327
		-----		
			T.E =	111.925461
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	77.212335
4522	4522			
081		.050000 x	11.010000 =	.550500
003		2.700000 x	20.419486 =	55.132612
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	60.876746
4525	4525			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	97.631821



4526	4526			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	87.422078
4527	4527			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	128.261050
4528	4528			
081		.050000 x	11.010000 =	.550500
003		5.200000 x	20.419486 =	106.181327
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	111.925461
4529	4529			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.700000 x	20.419486 =	95.971584
		-----		
			T.E =	101.715718
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.599215
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	41.389472
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047
		-----		
			T.E =	78.144547
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	20.419486 =	63.300407
		-----		
			T.E =	63.850907

4537	4537			
081		.050000 x	11.010000 =	.550500
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	112.857673
4538	4538			
081		.050000 x	11.010000 =	.550500
003		4.600000 x	20.419486 =	93.929636
		-----		
			T.E =	94.480136
4539	4539			
081		.050000 x	11.010000 =	.550500
003		4.200000 x	20.419486 =	85.761841
		-----		
			T.E =	86.312341
4541	4541			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	51.599215
4542	4542			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	41.389472
4543	4543			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	82.228444
4544	4544			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	123.067416
4601.1	4601.1			
101		105.000000 x	.000000 =	.000000
1417		.023000 x	40.284450 =	.926542
003		.700000 x	20.419486 =	14.293640
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
001		.600000 x	15.741598 =	9.444959
1447		.023000 x	59.035900 =	1.357826
003		.700000 x	20.419486 =	14.293640

-----  
T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1417		.056000 x	40.284450 =	2.255929
003		1.300000 x	20.419486 =	26.545332

-----  
T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1447		.056000 x	59.035900 =	3.306010
003		1.300000 x	20.419486 =	26.545332

-----  
T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	40.284450 =	3.585316
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

-----  
T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.741598 =	29.909036
1447		.089000 x	59.035900 =	5.254195
003		1.800000 x	20.419486 =	36.755075

-----  
T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.741598 =	99.172067
1417		.332000 x	40.284450 =	13.374437
003		5.500000 x	20.419486 =	112.307173

-----  
T.E =

4604.2 4604.2

101	1,050.000000 x	.000000 =	.000000
001	6.300000 x	15.741598 =	99.172067
1447	.332000 x	59.035900 =	19.599919
003	5.500000 x	20.419486 =	112.307173

T.E =

4611.1 4611.1

102	105.000000 x	.000000 =	.000000
1417	.030000 x	40.284450 =	1.208534
003	.700000 x	20.419486 =	14.293640
001	.700000 x	15.741598 =	11.019119

T.E =

4611.2 4611.2

102	105.000000 x	.000000 =	.000000
001	.700000 x	15.741598 =	11.019119
1447	.030000 x	59.035900 =	1.771077
003	.700000 x	20.419486 =	14.293640

T.E =

4612.1 4612.1

102	210.000000 x	.000000 =	.000000
001	1.400000 x	15.741598 =	22.038237
1417	.070000 x	40.284450 =	2.819912
003	1.300000 x	20.419486 =	26.545332

T.E =

4612.2 4612.2

102	210.000000 x	.000000 =	.000000
001	1.400000 x	15.741598 =	22.038237
1447	.070000 x	59.035900 =	4.132513
003	1.300000 x	20.419486 =	26.545332

T.E =

4613.1 4613.1

102	315.000000 x	.000000 =	.000000
1417	.110000 x	40.284450 =	4.431290
003	1.800000 x	20.419486 =	36.755075
001	2.100000 x	15.741598 =	33.057356

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.741598 =	33.057356
1447		.110000 x	59.035900 =	6.493949
003		1.800000 x	20.419486 =	36.755075

T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1417		.404000 x	40.284450 =	16.274918
003		5.500000 x	20.419486 =	112.307173

T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1447		.404000 x	59.035900 =	23.850504
003		5.500000 x	20.419486 =	112.307173

T.E =

4621.1	4621.1			
111		53.000000 x	.075900 =	4.022700
1417		.010000 x	40.284450 =	.402845
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

T.E =

20.931927

4621.2	4621.2			
111		53.000000 x	.075900 =	4.022700
1447		.010000 x	59.035900 =	.590359
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

T.E =

21.119441

4622.1	4622.1			
111		75.000000 x	.075900 =	5.692500
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743
1417		.020000 x	40.284450 =	.805689

T.E =

23.791651

4622.2	4622.2			
111		75.000000 x	.075900 =	5.692500
003		.500000 x	20.419486 =	10.209743
1447		.020000 x	59.035900 =	1.180718
001		.450000 x	15.741598 =	7.083719
		-----		
			T.E =	24.166680
4623.1	4623.1			
111		150.000000 x	.075900 =	11.385000
1417		.050000 x	40.284450 =	2.014223
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518
		-----		
			T.E =	47.752252
4623.2	4623.2			
111		150.000000 x	.075900 =	11.385000
1447		.050000 x	59.035900 =	2.951795
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518
		-----		
			T.E =	48.689825
4624.1	4624.1			
111		225.000000 x	.075900 =	17.077500
1417		.085000 x	40.284450 =	3.424178
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
		-----		
			T.E =	70.659407
4624.2	4624.2			
111		225.000000 x	.075900 =	17.077500
001		1.500000 x	15.741598 =	23.612397
1447		.085000 x	59.035900 =	5.018052
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	72.253280
4625.1	4625.1			
111		750.000000 x	.075900 =	56.925000
001		5.200000 x	15.741598 =	81.856310
1417		.320000 x	40.284450 =	12.891024
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	239.476123

4625.2	4625.2			
111		750.000000 x	.075900 =	56.925000
001		5.200000 x	15.741598 =	81.856310
1447		.320000 x	59.035900 =	18.891488
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	245.476587
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000
		-----		
			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000
		-----		
			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.791651 =	52.341632
		-----		
			T.E =	52.341632
4633.2	4633.2			
4622.2		2.200000 x	24.166680 =	53.166696
		-----		
			T.E =	53.166696
4634.1	4634.1			
4622.1		1.200000 x	23.791651 =	28.549981
4623.1		1.000000 x	47.752252 =	47.752252
		-----		
			T.E =	76.302233
4634.2	4634.2			
4622.2		1.200000 x	24.166680 =	29.000016
4623.2		1.000000 x	48.689825 =	48.689825
		-----		
			T.E =	77.689841
4661.1	4661.1			
112		43.750000 x	.083300 =	3.644375
1417		.014507 x	40.284450 =	.584407
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	20.735164
4661.2	4661.2			
112		43.750000 x	.083300 =	3.644375
001		.400000 x	15.741598 =	6.296639
1447		.014507 x	59.035900 =	.856434
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	21.007191
4662.1	4662.1			
112		58.333300 x	.083300 =	4.859164
001		.450000 x	15.741598 =	7.083719
1417		.022840 x	40.284450 =	.920097
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	23.072723



4662.2	4662.2			
112		58.333300 x	.083300 =	4.859164
001		.450000 x	15.741598 =	7.083719
1447		.022840 x	59.035900 =	1.348380
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	23.501006
4663.1	4663.1			
112		105.000000 x	.083300 =	8.746500
1417		.043218 x	40.284450 =	1.741013
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438
		-----		
			T.E =	43.032489
4663.2	4663.2			
112		105.000000 x	.083300 =	8.746500
001		.900000 x	15.741598 =	14.167438
1447		.043218 x	59.035900 =	2.551414
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	43.842889
4664.1	4664.1			
112		97.222221 x	.083300 =	8.098611
001		.950000 x	15.741598 =	14.954518
1417		.045077 x	40.284450 =	1.815902
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	44.267543
4664.2	4664.2			
112		97.222221 x	.083300 =	8.098611
001		.950000 x	15.741598 =	14.954518
1447		.045077 x	59.035900 =	2.661161
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	45.112802
4665.1	4665.1			
112		174.999001 x	.083300 =	14.577417
1417		.047530 x	40.284450 =	1.914720
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
		-----		
			T.E =	66.649865

4665.2	4665.2			
112		174.999001 x	.083300 =	14.577417
001		1.500000 x	15.741598 =	23.612397
1447		.047530 x	59.035900 =	2.805976
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	67.541122
4666.1	4666.1			
112		486.111099 x	.083300 =	40.493055
001		5.200000 x	15.741598 =	81.856310
1417		.277862 x	40.284450 =	11.193518
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	221.346672
4666.2	4666.2			
112		486.111000 x	.083300 =	40.493046
001		5.200000 x	15.741598 =	81.856310
1447		.277862 x	59.035900 =	16.403833
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	226.556979
4701	4701			
113		13.000000 x	.570000 =	7.410000
1417		.020000 x	40.284450 =	.805689
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	24.254282
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	24.629311
4703	4703			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1417		.015000 x	40.284450 =	.604267
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
1417		.020000 x	40.284450 =	.805689
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1417		.015000 x	40.284450 =	.604267
003		.350000 x	20.419486 =	7.146820

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820

T.E =

4721.1	4721.1			
128		.080000 x	88.240000 =	7.059200
1417		.004000 x	40.284450 =	.161138
003		.350000 x	20.419486 =	7.146820
001		.300000 x	15.741598 =	4.722479

T.E =

19.089637

4721.2	4721.2				
128		.080000 x	88.240000 =	7.059200	
001		.300000 x	15.741598 =	4.722479	
1447		.004000 x	59.035900 =	.236144	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	19.164643	
4722.1	4722.1				
128		.100000 x	88.240000 =	8.824000	
001		.350000 x	15.741598 =	5.509559	
1417		.005000 x	40.284450 =	.201422	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	21.681802	
4722.2	4722.2				
128		.100000 x	88.240000 =	8.824000	
001		.350000 x	15.741598 =	5.509559	
1447		.005000 x	59.035900 =	.295180	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	21.775559	
4723	4723				
128		.120000 x	88.240000 =	10.588800	
1417		.006000 x	40.284450 =	.241707	
003		.350000 x	20.419486 =	7.146820	
001		.400000 x	15.741598 =	6.296639	
		-----			
			T.E =	24.273966	
4724.1	4724.1				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	
1417		.008000 x	40.284450 =	.322276	
		-----			
			T.E =	28.022709	
4724.2	4724.2				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1447		.008000 x	59.035900 =	.472287	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	28.172721	

4725.1	4725.1			
128		.180000 x	88.240000 =	15.883200
1417		.009000 x	40.284450 =	.362560
001		.450000 x	15.741598 =	7.083719
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	31.497274
4725.2	4725.2			
128		.180000 x	88.240000 =	15.883200
1447		.009000 x	59.035900 =	.531323
003		.400000 x	20.419486 =	8.167794
001		.450000 x	15.741598 =	7.083719
		-----		
			T.E =	31.666037
4801.1	4801.1			
4662.1		1.000000 x	23.072723 =	23.072723
4662.1		.100000 x	23.072723 =	2.307272
		-----		
			T.E =	25.379995
4801.2	4801.2			
4662.2		1.000000 x	23.501006 =	23.501006
4662.2		.100000 x	23.501006 =	2.350101
		-----		
			T.E =	25.851107
4802.1	4802.1			
4664.1		1.000000 x	44.267543 =	44.267543
4664.1		.050000 x	44.267543 =	2.213377
		-----		
			T.E =	46.480920
4802.2	4802.2			
4664.2		1.000000 x	45.112802 =	45.112802
4664.2		.050000 x	45.112802 =	2.255640
		-----		
			T.E =	47.368442
4803.1	4803.1			
4665.1		1.000000 x	66.649865 =	66.649865
4665.1		.030000 x	66.649865 =	1.999496
		-----		
			T.E =	68.649361
4803.2	4803.2			
4665.2		1.000000 x	67.541122 =	67.541122
4665.2		.030000 x	67.541122 =	2.026234
		-----		
			T.E =	69.567356

4811.1	4811.1				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.1		1.000000 x	23.072723 =	23.072723	
		-----			
			T.E =	31.719454	
4811.2	4811.2				
001		.225000 x	15.741598 =	3.541860	
4662.2		1.000000 x	23.501006 =	23.501006	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	32.147737	
4812.1	4812.1				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.1		1.000000 x	44.267543 =	44.267543	
		-----			
			T.E =	61.444058	
4812.2	4812.2				
001		.475000 x	15.741598 =	7.477259	
4664.2		1.000000 x	45.112802 =	45.112802	
003		.475000 x	20.419486 =	9.699256	
		-----			
			T.E =	62.289317	
4813.1	4813.1				
001		.750000 x	15.741598 =	11.806199	
4665.1		1.000000 x	66.649865 =	66.649865	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	91.728729	
4813.2	4813.2				
001		.750000 x	15.741598 =	11.806199	
4665.2		1.000000 x	67.541122 =	67.541122	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	92.619986	
4814.1	4814.1				
001		2.600000 x	15.741598 =	40.928155	
003		2.150000 x	20.419486 =	43.901895	
4666.1		1.000000 x	221.346672 =	221.346672	
		-----			
			T.E =	306.176722	

4814.2	4814.2			
001		2.600000 x	15.741598 =	40.928155
003		2.150000 x	20.419486 =	43.901895
4666.2		1.000000 x	226.556979 =	226.556979
		-----		
			T.E =	311.387029
4821.1	4821.1			
003		.450000 x	20.419486 =	9.188769
4662.1		1.000000 x	23.072723 =	23.072723
		-----		
			T.E =	32.261492
4821.2	4821.2			
003		.450000 x	20.419486 =	9.188769
4662.2		1.000000 x	23.501006 =	23.501006
		-----		
			T.E =	32.689775
4822.1	4822.1			
003		.807500 x	20.419486 =	16.488735
4664.1		1.000000 x	44.267543 =	44.267543
		-----		
			T.E =	60.756278
4822.2	4822.2			
003		.807500 x	20.419486 =	16.488735
4664.2		1.000000 x	45.112802 =	45.112802
		-----		
			T.E =	61.601537
4823.1	4823.1			
003		1.040000 x	20.419486 =	21.236265
4665.1		1.000000 x	66.649865 =	66.649865
		-----		
			T.E =	87.886130
4823.2	4823.2			
003		1.040000 x	20.419486 =	21.236265
4665.2		1.000000 x	67.541122 =	67.541122
		-----		
			T.E =	88.777387
4824.1	4824.1			
003		3.010000 x	20.419486 =	61.462653
4666.1		1.000000 x	221.346672 =	221.346672
		-----		
			T.E =	282.809325

4824.2	4824.2			
003		3.010000 x	20.419486 =	61.462653
4666.2		1.000000 x	226.556979 =	226.556979
		-----		
			T.E =	288.019632
4831.1	4831.1			
003		1.200000 x	20.419486 =	24.503383
4661.1		1.000000 x	20.735164 =	20.735164
		-----		
			T.E =	45.238547
4831.2	4831.2			
003		1.200000 x	20.419486 =	24.503383
4661.2		1.000000 x	21.007191 =	21.007191
		-----		
			T.E =	45.510574
4832.1	4832.1			
003		1.600000 x	20.419486 =	32.671178
4662.1		1.000000 x	23.072723 =	23.072723
		-----		
			T.E =	55.743901
4832.2	4832.2			
003		1.600000 x	20.419486 =	32.671178
4662.2		1.000000 x	23.501006 =	23.501006
		-----		
			T.E =	56.172184
4833.1	4833.1			
002		2.000000 x	17.312112 =	34.624224
4664.1		1.000000 x	44.267543 =	44.267543
		-----		
			T.E =	78.891767
4833.2	4833.2			
002		2.000000 x	17.312112 =	34.624224
4664.2		1.000000 x	45.112802 =	45.112802
		-----		
			T.E =	79.737026
4834.1	4834.1			
003		2.300000 x	20.419486 =	46.964818
4665.1		1.000000 x	66.649865 =	66.649865
		-----		
			T.E =	113.614683



4834.2	4834.2			
003		2.300000 x	20.419486 =	46.964818
4665.2		1.000000 x	67.541122 =	67.541122

T.E = 114.505940

4835	4835			
122		1.050000 x	.000000 =	.000000
1417		.005000 x	40.284450 =	.201422
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.941500 =	1.883000
201		.010000 x	290.000000 =	2.900000

T.E =

4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
1447		.005000 x	59.035900 =	.295180
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.941500 =	1.883000

T.E =

4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
1417		.005000 x	40.284450 =	.201422
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.941500 =	1.883000
001		1.000000 x	15.741598 =	15.741598
201		.010000 x	290.000000 =	2.900000

T.E =

4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.941500 =	1.883000
1447		.005000 x	59.035900 =	.295180
003		1.000000 x	20.419486 =	20.419486
201		.010000 x	290.000000 =	2.900000

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	40.284450 =	.402845
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.941500 =	1.883000
201		.010000 x	290.000000 =	2.900000
		-----		
			T.E =	47.541929
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
201		.010000 x	290.000000 =	2.900000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
1447		.010000 x	59.035900 =	.590359
265		2.000000 x	.941500 =	1.883000
		-----		
			T.E =	49.299957
4841	4841			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
4842	4842			
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	20.419486
4843	4843			
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.104872
4844	4844			
131		1,200.000000 x	.690000 =	828.000000
1401		.250000 x	242.301000 =	60.575250
001		10.000000 x	15.741598 =	157.415980
003		25.000000 x	20.419486 =	510.487150
		-----		
			T.E =	1,556.478380
4845	4845			
132		620.000000 x	.960000 =	595.200000
1401		.180000 x	242.301000 =	43.614180
003		15.000000 x	20.419486 =	306.292290
001		6.000000 x	15.741598 =	94.449588
		-----		
			T.E =	1,039.556058

4851	4851			
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240
		-----		
			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717
		-----		
			T.E =	26.760717
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
003		4.000000 x	20.419486 =	81.677944
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	1,197.419542
5102	5102			
483		1.800000 x	.167500 =	.301500
489		.360000 x	.000000 =	.000000
488		.540000 x	5.500000 =	2.970000
491		1.260000 x	.540000 =	.680400
001		1.000000 x	15.741598 =	15.741598
492		1.440000 x	.540000 =	.777600
		-----		
			T.E =	
5103	5103			
265		1.050000 x	.941500 =	.988575
002		.050000 x	17.312112 =	.865606
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	5.938078
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	34.546119
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
001		2.000000 x	15.741598 =	31.483196
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	51.692939

5106	5106			
214		.050000 x	1,000.000000 =	50.000000
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	132.531911
5201	5201			
201		1.100000 x	290.000000 =	319.000000
003		10.000000 x	20.419486 =	204.194860
002		5.000000 x	17.312112 =	86.560560
251		6.000000 x	.861000 =	5.166000
		-----		
			T.E =	614.921420
5202	5202			
203.2		1.080000 x	370.000000 =	399.600000
251		6.000000 x	.861000 =	5.166000
002		4.500000 x	17.312112 =	77.904504
003		9.000000 x	20.419486 =	183.775374
		-----		
			T.E =	666.445878
5203	5203			
201		1.120000 x	290.000000 =	324.800000
251		12.000000 x	.861000 =	10.332000
003		16.000000 x	20.419486 =	326.711776
002		8.000000 x	17.312112 =	138.496896
		-----		
			T.E =	800.340672
5204	5204			
203.2		1.100000 x	370.000000 =	407.000000
251		12.000000 x	.861000 =	10.332000
003		14.000000 x	20.419486 =	285.872804
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	824.389588
5211	5211			
201		1.100000 x	290.000000 =	319.000000
003		12.000000 x	20.419486 =	245.033832
002		6.000000 x	17.312112 =	103.872672
251		14.000000 x	.861000 =	12.054000
		-----		
			T.E =	679.960504

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
251		14.000000 x	.861000 =	12.054000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	
		-----			
			T.E =	702.409420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.861000 =	6.888000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
		-----			
			T.E =	587.567878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
		-----			
			T.E =	10.215603	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	
251		.100000 x	.861000 =	.086100	
		-----			
			T.E =	12.041845	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.861000 =	.086100	
002		.100000 x	17.312112 =	1.731211	
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	15.521208	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
		-----			
			T.E =	10.955603	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	
-----					
			T.E =	14.041208	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
251		.150000 x	.861000 =	.129150	
-----					
			T.E =	17.909864	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.861000 =	.129150	
002		.100000 x	17.312112 =	1.731211	
003		.250000 x	20.419486 =	5.104872	
-----					
			T.E =	13.625233	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
251		.150000 x	.861000 =	.129150	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	
-----					
			T.E =	16.561475	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.861000 =	.172200	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	
-----					
			T.E =	20.453888	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
251		.080000 x	.861000 =	.068880	
-----					
			T.E =	17.463728	

5237	5237			
203.2		.022000 x	370.000000 =	8.140000
251		.080000 x	.861000 =	.068880
003		.350000 x	20.419486 =	7.146820
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	20.549334
5238	5238			
203.2		.030000 x	370.000000 =	11.100000
251		.100000 x	.861000 =	.086100
003		.350000 x	20.419486 =	7.146820
002		.350000 x	17.312112 =	6.059239
		-----		
			T.E =	24.392159
5241	5241			
203.2		.030000 x	370.000000 =	11.100000
251		.100000 x	.861000 =	.086100
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
		-----		
			T.E =	30.051899
5243	5243			
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	3.062923
5244	5244			
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	7.146820
5246	5246			
220		26.000000 x	.000000 =	.000000
002		.500000 x	17.312112 =	8.656056
251		.200000 x	.861000 =	.172200
		-----		
			T.E =	
5247	5247			
221		30.000000 x	.000000 =	.000000
002		.600000 x	17.312112 =	10.387267
251		.100000 x	.861000 =	.086100
283		.100000 x	1.305700 =	.130570
		-----		
			T.E =	



5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
251		.100000 x	.861000 =	.086100	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	
		-----			
			T.E =	16.130579	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
245		.110000 x	18.600000 =	2.046000	
		-----			
			T.E =	116.834995	
5252.2	5252.2				
246		1.100000 x	12.000000 =	13.200000	
246		.110000 x	12.000000 =	1.320000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	108.848995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
249		.110000 x	20.000000 =	2.200000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
		-----			
			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
219		.060000 x	3.500000 =	.210000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	
		-----			
			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.600000 x	.861000 =	.516600	
203.2		.025000 x	370.000000 =	9.250000	
		-----			
			T.E =	45.751878	

5262	5262				
201		.030000 x	290.000000 =	8.700000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
265		.300000 x	.941500 =	.282450	
252		.200000 x	2.100000 =	.420000	
203.2		.025000 x	370.000000 =	9.250000	
251		.300000 x	.861000 =	.258300	
-----					
			T.E =	56.642348	
5266	5266				
201		.020000 x	290.000000 =	5.800000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
203.2		.015000 x	370.000000 =	5.550000	
251		.600000 x	.861000 =	.516600	
-----					
			T.E =	34.505559	
5267	5267				
201		.030000 x	290.000000 =	8.700000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
265		.300000 x	.941500 =	.282450	
252		.300000 x	2.100000 =	.630000	
203.2		.015000 x	370.000000 =	5.550000	
251		.300000 x	.861000 =	.258300	
-----					
			T.E =	45.606028	
5271	5271				
201		.016000 x	290.000000 =	4.640000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
251		.600000 x	.861000 =	.516600	
203.2		.025000 x	370.000000 =	9.250000	
-----					
			T.E =	33.272399	
5272	5272				
201		.024000 x	290.000000 =	6.960000	
003		.700000 x	20.419486 =	14.293640	
002		.700000 x	17.312112 =	12.118478	
265		.200000 x	.941500 =	.188300	
252		.100000 x	2.100000 =	.210000	
203.2		.025000 x	370.000000 =	9.250000	
251		.300000 x	.861000 =	.258300	
-----					
			T.E =	43.278719	

5273	5273			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
203.2		.015000 x	370.000000 =	5.550000
251		.600000 x	.861000 =	.516600
-----				
			T.E =	29.572399
5274	5274			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
265		.200000 x	.941500 =	.188300
252		.100000 x	2.100000 =	.210000
203.2		.015000 x	370.000000 =	5.550000
251		.300000 x	.861000 =	.258300
-----				
			T.E =	39.578719
5276	5276			
201		1.080000 x	290.000000 =	313.200000
003		19.000000 x	20.419486 =	387.970234
002		19.000000 x	17.312112 =	328.930128
252		18.000000 x	2.100000 =	37.800000
251		6.000000 x	.861000 =	5.166000
-----				
			T.E =	1,073.066362
5277	5277			
203.2		1.080000 x	370.000000 =	399.600000
251		6.000000 x	.861000 =	5.166000
002		18.000000 x	17.312112 =	311.618016
003		18.000000 x	20.419486 =	367.550748
252		18.000000 x	2.100000 =	37.800000
-----				
			T.E =	1,121.734764
5279	5279			
201		1.080000 x	290.000000 =	313.200000
251		12.000000 x	.861000 =	10.332000
002		5.000000 x	17.312112 =	86.560560
003		10.000000 x	20.419486 =	204.194860
-----				
			T.E =	614.287420

5280	5280				
203.2		1.080000 x	370.000000 =	399.600000	
251		12.000000 x	.861000 =	10.332000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
		-----			
			T.E =	700.687420	
5281	5281				
203.2		.014000 x	370.000000 =	5.180000	
002		.250000 x	17.312112 =	4.328028	
251		.040000 x	.861000 =	.034440	
		-----			
			T.E =	9.542468	
5282	5282				
203.2		.020000 x	370.000000 =	7.400000	
251		.060000 x	.861000 =	.051660	
002		.350000 x	17.312112 =	6.059239	
		-----			
			T.E =	13.510899	
5283	5283				
203.2		.026000 x	370.000000 =	9.620000	
251		.080000 x	.861000 =	.068880	
002		.400000 x	17.312112 =	6.924845	
		-----			
			T.E =	16.613725	
5286	5286				
203.2		.008000 x	370.000000 =	2.960000	
003		.120000 x	20.419486 =	2.450338	
251		.030000 x	.861000 =	.025830	
002		.120000 x	17.312112 =	2.077453	
		-----			
			T.E =	7.513622	
5288	5288				
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	6.125846	
5289	5289				
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	20.419486	

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.200000 x	.861000 =	.172200
220		26.000000 x	.000000 =	.000000
-----				
			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.200000 x	.861000 =	.172200
220		26.000000 x	.000000 =	.000000
203.2		.010000 x	370.000000 =	3.700000
-----				
			T.E =	
5293	5293			
203.2		.020000 x	370.000000 =	7.400000
251		.150000 x	.861000 =	.129150
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
203.2		.016000 x	370.000000 =	5.920000
-----				
			T.E =	28.541789
5294	5294			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
203.2		.022000 x	370.000000 =	8.140000
251		.100000 x	.861000 =	.086100
-----				
			T.E =	30.718739
5295	5295			
203.2		.020000 x	370.000000 =	7.400000
251		.050000 x	.861000 =	.043050
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
-----				
			T.E =	16.875950
5301	5301			
226		1.050000 x	13.000000 =	13.650000
251		.250000 x	.861000 =	.215250
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
-----				
			T.E =	36.504209

5302	5302				
227		1.050000 x	13.000000 =	13.650000	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	
251		.200000 x	.861000 =	.172200	
		-----			
			T.E =	32.687999	
5321	5321				
203.2		.012000 x	370.000000 =	4.440000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
251		.500000 x	.861000 =	.430500	
226		1.050000 x	13.000000 =	13.650000	
		-----			
			T.E =	52.478938	
5322	5322				
203.2		.012000 x	370.000000 =	4.440000	
227		1.050000 x	13.000000 =	13.650000	
251		.450000 x	.861000 =	.387450	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
		-----			
			T.E =	48.662728	
5323	5323				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
228		1.050000 x	35.000000 =	36.750000	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.861000 =	.430500	
		-----			
			T.E =	79.352098	
5324	5324				
203.2		.012000 x	370.000000 =	4.440000	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.861000 =	.430500	
		-----			
			T.E =		
5325	5325				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.861000 =	.430500	
230		1.050000 x	.000000 =	.000000	
		-----			
			T.E =		

5326	5326				
203.2		.012000 x	370.000000 =	4.440000	
231		1.050000 x	22.000000 =	23.100000	
251		.500000 x	.861000 =	.430500	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
			T.E =	65.702098	
5341	5341				
203.2		.037000 x	370.000000 =	13.690000	
003		1.100000 x	20.419486 =	22.461435	
232		1.050000 x	45.000000 =	47.250000	
002		1.100000 x	17.312112 =	19.043323	
251		.600000 x	.861000 =	.516600	
			T.E =	102.961358	
5342	5342				
203.2		.037000 x	370.000000 =	13.690000	
232		1.100000 x	45.000000 =	49.500000	
002		1.700000 x	17.312112 =	29.430590	
003		1.700000 x	20.419486 =	34.713126	
251		.600000 x	.861000 =	.516600	
			T.E =	127.850317	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
233		.084000 x	21.300000 =	1.789200	
			T.E =	54.339478	
5351	5351				
035		.200000 x	.086500 =	.017300	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.861000 =	.086100	
236		1.060000 x	2.000000 =	2.120000	
			T.E =	9.769720	
5352	5352				
035		.200000 x	.086500 =	.017300	
251		.100000 x	.861000 =	.086100	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
237		1.060000 x	1.100000 =	1.166000	
			T.E =	8.815720	

5353	5353			
035		.200000 x	.086500 =	.017300
238		1.060000 x	2.600000 =	2.756000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		.100000 x	.861000 =	.086100
-----				
			T.E =	10.405720
5354	5354			
035		.200000 x	.086500 =	.017300
239		1.060000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.861000 =	.086100
-----				
			T.E =	
5355	5355			
035		.200000 x	.086500 =	.017300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.861000 =	.086100
240		1.060000 x	1.400000 =	1.484000
-----				
			T.E =	9.133720
5356	5356			
035		.200000 x	.086500 =	.017300
251		.100000 x	.861000 =	.086100
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
241		1.060000 x	.000000 =	.000000
-----				
			T.E =	
5421	5421			
205		.055000 x	450.000000 =	24.750000
1471		1.000000 x	5.790099 =	5.790099
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
-----				
			T.E =	162.600692
5422	5422			
205		.035000 x	450.000000 =	15.750000
1472		1.000000 x	6.985163 =	6.985163
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336
-----				
			T.E =	135.929957



5426	5426			
205		.095000 x	450.000000 =	42.750000
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916
1473		1.000000 x	11.946993 =	11.946993
1471		1.000000 x	5.790099 =	5.790099
		-----		
			T.E =	286.876680
5427	5427			
205		.105000 x	450.000000 =	47.250000
002		7.000000 x	17.312112 =	121.184784
1474		1.000000 x	14.498512 =	14.498512
1471		1.000000 x	5.790099 =	5.790099
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	331.659797
5428	5428			
205		.075000 x	450.000000 =	33.750000
003		5.500000 x	20.419486 =	112.307173
1474		1.000000 x	14.498512 =	14.498512
1472		1.000000 x	6.985163 =	6.985163
002		5.500000 x	17.312112 =	95.216616
		-----		
			T.E =	262.757464
5431	5431			
205		.070000 x	450.000000 =	31.500000
1475		1.000000 x	40.390657 =	40.390657
208		.030000 x	1,435.000000 =	43.050000
1471		1.000000 x	5.790099 =	5.790099
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	384.851942
5432	5432			
205		.070000 x	450.000000 =	31.500000
1475		.800000 x	40.390657 =	32.312526
1471		1.000000 x	5.790099 =	5.790099
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
380		1.000000 x	16.560000 =	16.560000
		-----		
			T.E =	274.820615

5436	5436			
205		.050000 x	450.000000 =	22.500000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	195.362791
5437	5437			
205		.065000 x	450.000000 =	29.250000
002		5.000000 x	17.312112 =	86.560560
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.070600 =	3.070600
		-----		
			T.E =	220.978590
5438	5438			
205		.050000 x	450.000000 =	22.500000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	176.496992
5441.1	5441.1			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.3		.004000 x	.000000 =	.000000
		-----		
			T.E =	
5441.2	5441.2			
205		.065000 x	450.000000 =	29.250000
223.3		.004000 x	1,500.000000 =	6.000000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	208.112791
5441.3	5441.3			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
243.1		.550000 x	2.700000 =	1.485000
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
		-----		
			T.E =	203.597791

5442.1	5442.1			
205		.080000 x	450.000000 =	36.000000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.070600 =	3.070600
002		5.000000 x	17.312112 =	86.560560

T.E =

5442.2	5442.2			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

233.728590

5442.3	5442.3			
205		.080000 x	450.000000 =	36.000000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
243.1		.055000 x	2.700000 =	.148500

T.E =

227.877090

5443.1	5443.1			
205		.065000 x	450.000000 =	29.250000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	3.070600 =	3.070600
002		4.000000 x	17.312112 =	69.248448
222.3		.004000 x	.000000 =	.000000

T.E =

5443.2	5443.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

189.246992

5443.3	5443.3			
205		.065000 x	450.000000 =	29.250000
243.1		.550000 x	2.700000 =	1.485000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
			T.E =	184.731992
5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
222.2		.010000 x	.000000 =	.000000
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
			T.E =	
5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000
			T.E =	191.496992
5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
205		.040000 x	450.000000 =	18.000000
222.2		.010000 x	.000000 =	.000000
			T.E =	
5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	3.070600 =	3.070600
003		4.500000 x	20.419486 =	91.887687
223.2		.010000 x	1,700.000000 =	17.000000
205		.040000 x	450.000000 =	18.000000
			T.E =	217.112791

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.070600 =	3.070600
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
205		.025000 x	450.000000 =	11.250000
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
1476		1.000000 x	3.070600 =	3.070600
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.010000 x	1,700.000000 =	17.000000

T.E =

172.631193

5449	5449			
205		.045000 x	450.000000 =	20.250000
002		3.000000 x	17.312112 =	51.936336
1476		1.000000 x	3.070600 =	3.070600
003		3.000000 x	20.419486 =	61.258458
243.5		.850000 x	5.900000 =	5.015000

T.E =

141.530394

5451.1	5451.1			
205		.090000 x	450.000000 =	40.500000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.070600 =	3.070600
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5451.2	5451.2			
205		.090000 x	450.000000 =	40.500000
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

238.228590

5451.3	5451.3			
205		.090000 x	450.000000 =	40.500000
243.1		.550000 x	2.700000 =	1.485000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.070600 =	3.070600
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	233.713590
5456	5456			
205		.055000 x	450.000000 =	24.750000
1478		1.000000 x	3.453100 =	3.453100
002		4.000000 x	17.312112 =	69.248448
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	179.129492
5457	5457			
205		.085000 x	450.000000 =	38.250000
003		7.000000 x	20.419486 =	142.936402
1476		1.500000 x	3.070600 =	4.605900
002		7.000000 x	17.312112 =	121.184784
261		2.200000 x	.598400 =	1.316480
		-----		
			T.E =	308.293566
5461.1	5461.1			
205		.065000 x	450.000000 =	29.250000
222.2		.010000 x	.000000 =	.000000
1479		1.000000 x	37.938689 =	37.938689
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
		-----		
			T.E =	
5461.2	5461.2			
205		.065000 x	450.000000 =	29.250000
1479		1.000000 x	37.938689 =	37.938689
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
223.2		.010000 x	1,700.000000 =	17.000000
		-----		
			T.E =	291.712478
5462.1	5462.1			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	36.621317 =	36.621317
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
		-----		
			T.E =	

5462.2	5462.2			
205		.065000 x	450.000000 =	29.250000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
1480		1.000000 x	36.621317 =	36.621317
223.2		.010000 x	1,700.000000 =	17.000000

-----  
T.E = 290.395106

5463.1	5463.1			
205		.055000 x	450.000000 =	24.750000
1479		.500000 x	37.938689 =	18.969345
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
222.2		.010000 x	.000000 =	.000000

-----  
T.E =

5463.2	5463.2			
205		.055000 x	450.000000 =	24.750000
223.2		.010000 x	1,700.000000 =	17.000000
002		6.000000 x	17.312112 =	103.872672
1479		.500000 x	37.938689 =	18.969345
003		6.000000 x	20.419486 =	122.516916

-----  
T.E = 287.108933

5464.1	5464.1			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	37.938689 =	18.969345
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

-----  
T.E =

5464.2	5464.2			
205		.070000 x	450.000000 =	31.500000
223.2		.010000 x	1,700.000000 =	17.000000
003		7.000000 x	20.419486 =	142.936402
1479		.500000 x	37.938689 =	18.969345
002		7.000000 x	17.312112 =	121.184784

-----  
T.E = 331.590531

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
1476		1.000000 x	3.070600 =	3.070600
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,435.000000 =	43.050000

T.E =

5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
002		5.500000 x	17.312112 =	95.216616
1476		1.000000 x	3.070600 =	3.070600
003		5.500000 x	20.419486 =	112.307173
223.2		.005000 x	1,700.000000 =	8.500000
208		.030000 x	1,435.000000 =	43.050000

T.E =

278.794389

5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.900000 x	37.938689 =	34.144820
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
1479		.900000 x	37.938689 =	34.144820
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,700.000000 =	17.000000

T.E =

249.052810

5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
222.2		.012000 x	.000000 =	.000000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
222.2		.000960 x	.000000 =	.000000

T.E =



5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
223.2		.000960 x	1,700.000000 =	1.632000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.012000 x	1,700.000000 =	20.400000
203.2		.001040 x	370.000000 =	.384800
-----				
			T.E =	159.287393
5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000
203.2		.002000 x	370.000000 =	.740000
-----				
			T.E =	
5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
203.2		.002000 x	370.000000 =	.740000
223.2		.010000 x	1,700.000000 =	17.000000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.000800 x	1,700.000000 =	1.360000
-----				
			T.E =	179.276392
5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.500000 x	37.938689 =	18.969345
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
003		4.500000 x	20.419486 =	91.887687
1479		.500000 x	37.938689 =	18.969345
002		4.500000 x	17.312112 =	77.904504
-----				
			T.E =	215.011536

5471	5471				
203.2		.035000 x	370.000000 =		12.950000
251		3.000000 x	.861000 =		2.583000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
		-----			
			T.E =		147.593593
5472.1	5472.1				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
251		3.000000 x	.861000 =		2.583000
222.4		.010000 x	.000000 =		.000000
		-----			
			T.E =		
5472.2	5472.2				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
251		3.000000 x	.861000 =		2.583000
223.4		.010000 x	1,580.000000 =		15.800000
		-----			
			T.E =		160.063593
5501.1	5501.1				
211		.040000 x	750.000000 =		30.000000
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280
252		.100000 x	2.100000 =		.210000
251		.050000 x	.861000 =		.043050
		-----			
			T.E =		175.630760
5501.2	5501.2				
212		.040000 x	1,500.000000 =		60.000000
251		.050000 x	.861000 =		.043050
252		.100000 x	2.100000 =		.210000
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280
		-----			
			T.E =		205.630760
5502	5502				
210		.040000 x	.000000 =		.000000
251		.050000 x	.861000 =		.043050
002		2.000000 x	17.312112 =		34.624224
003		4.000000 x	20.419486 =		81.677944
252		.100000 x	2.100000 =		.210000
		-----			
			T.E =		

5511.1	5511.1			
211		.020000 x	750.000000 =	15.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	2.100000 =	.210000
		-----		
			T.E =	108.251734
5511.2	5511.2			
212		.020000 x	1,500.000000 =	30.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	2.100000 =	.210000
		-----		
			T.E =	123.251734
5512	5512			
205		.020000 x	450.000000 =	9.000000
252		.100000 x	2.100000 =	.210000
002		1.500000 x	17.312112 =	25.968168
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	96.436626
5513.1	5513.1			
211		.020000 x	750.000000 =	15.000000
252		.100000 x	2.100000 =	.210000
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	131.512168
5513.2	5513.2			
212		.020000 x	1,500.000000 =	30.000000
252		.100000 x	2.100000 =	.210000
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	146.512168
5514	5514			
205		.020000 x	450.000000 =	9.000000
003		3.800000 x	20.419486 =	77.594047
002		1.800000 x	17.312112 =	31.161802
252		.100000 x	2.100000 =	.210000
		-----		
			T.E =	117.965848

5521	5521				
205		.030000 x	450.000000 =		13.500000
252		.150000 x	2.100000 =		.315000
002		.800000 x	17.312112 =		13.849690
003		2.000000 x	20.419486 =		40.838972
				T.E =	68.503662
5531.1	5531.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	2.100000 =		.042000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
				T.E =	64.583348
5531.2	5531.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.100000 =		.042000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
				T.E =	72.083348
5531.3	5531.3				
205		.010000 x	450.000000 =		4.500000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
252		.020000 x	2.100000 =		.042000
				T.E =	61.583348
5532.1	5532.1				
211		.010000 x	750.000000 =		7.500000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
252		.020000 x	2.100000 =		.042000
				T.E =	86.112570
5532.2	5532.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.100000 =		.042000
002		1.000000 x	17.312112 =		17.312112
003		3.000000 x	20.419486 =		61.258458
				T.E =	93.612570

5532.3	5532.3			
205		.010000 x	450.000000 =	4.500000
252		.020000 x	2.100000 =	.042000
003		3.000000 x	20.419486 =	61.258458
002		1.000000 x	17.312112 =	17.312112
		-----		
			T.E =	83.112570
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	8.931820
5601	5601			
203.2		.028000 x	370.000000 =	10.360000
251		4.000000 x	.861000 =	3.444000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	108.132995
5602	5602			
203.2		.018000 x	370.000000 =	6.660000
002		2.300000 x	17.312112 =	39.817858
003		2.300000 x	20.419486 =	46.964818
251		3.000000 x	.861000 =	2.583000
		-----		
			T.E =	96.025675
5603	5603			
203.2		.013000 x	370.000000 =	4.810000
003		2.000000 x	20.419486 =	40.838972
002		2.000000 x	17.312112 =	34.624224
251		2.500000 x	.861000 =	2.152500
		-----		
			T.E =	82.425696
5604	5604			
243.5		1.100000 x	5.900000 =	6.490000
003		2.200000 x	20.419486 =	44.922869
002		2.200000 x	17.312112 =	38.086646
243.5		.165000 x	5.900000 =	.973500
		-----		
			T.E =	90.473016

5605	5605				
243.3		1.100000 x	4.500000 =	4.950000	
243.3		.187000 x	4.500000 =	.841500	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	
		-----			
			T.E =	81.254696	
5606	5606				
243.2		1.100000 x	3.800000 =	4.180000	
003		1.800000 x	20.419486 =	36.755075	
243.2		.220000 x	3.800000 =	.836000	
002		1.800000 x	17.312112 =	31.161802	
		-----			
			T.E =	72.932876	
5607	5607				
205		.012000 x	450.000000 =	5.400000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
242		.440000 x	1.500000 =	.660000	
205		.002400 x	450.000000 =	1.080000	
242		2.200000 x	1.500000 =	3.300000	
		-----			
			T.E =	104.768995	
5608.1	5608.1				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	
		-----			
			T.E =		
5608.2	5608.2				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
223.1		.006000 x	2,100.000000 =	12.600000	
223.1		.001200 x	2,100.000000 =	2.520000	
		-----			
			T.E =	153.660593	

5611	5611			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
251		5.000000 x	.861000 =	4.305000
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	295.426186
5612.1	5612.1			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.861000 =	4.305000
222.1		.006000 x	.000000 =	.000000
		-----		
			T.E =	
5612.2	5612.2			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.861000 =	4.305000
223.1		.006000 x	2,100.000000 =	12.600000
		-----		
			T.E =	308.026186
5613.1	5613.1			
205		.015000 x	450.000000 =	6.750000
205		.001500 x	450.000000 =	.675000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
222.2		.003000 x	.000000 =	.000000
		-----		
			T.E =	
5613.2	5613.2			
205		.015000 x	450.000000 =	6.750000
205		.001500 x	450.000000 =	.675000
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
223.2		.003000 x	1,700.000000 =	5.100000
		-----		
			T.E =	69.122397
5614.1	5614.1			
205		.010000 x	450.000000 =	4.500000
222.2		.002000 x	.000000 =	.000000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
205		.001500 x	450.000000 =	.675000
		-----		
			T.E =	

5614.2	5614.2			
205		.010000 x	450.000000 =	4.500000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,700.000000 =	3.400000
205		.001500 x	450.000000 =	.675000
-----				
			T.E =	53.852918
5615.1	5615.1			
205		.008000 x	450.000000 =	3.600000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	450.000000 =	.648000
-----				
			T.E =	
5615.2	5615.2			
205		.008000 x	450.000000 =	3.600000
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	450.000000 =	.648000
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,700.000000 =	1.530000
-----				
			T.E =	43.509598
5616	5616			
205		.003000 x	450.000000 =	1.350000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
205		.007500 x	450.000000 =	3.375000
-----				
			T.E =	42.456598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
521		.250000 x	2.461700 =	.615425
-----				
			T.E =	42.747023
5619	5619			
205		.001400 x	450.000000 =	.630000
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	4.713897



5620	5620			
203.2		.012000 x	370.000000 =	4.440000
251		.020000 x	.861000 =	.017220
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
220		4.200000 x	.000000 =	.000000
-----				
			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.861000 =	13.776000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
-----				
			T.E =	
5622	5622			
211		1.100000 x	750.000000 =	825.000000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
251		16.000000 x	.861000 =	13.776000
-----				
			T.E =	1,970.723940
5626	5626			
205		.030000 x	450.000000 =	13.500000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
251		1.000000 x	.861000 =	.861000
-----				
			T.E =	70.958397
6101	6101			
267		1.050000 x	1.011500 =	1.062075
003		.050000 x	20.419486 =	1.020974
-----				
			T.E =	2.083049
6102	6102			
252		.050000 x	2.100000 =	.105000
267		1.030000 x	1.011500 =	1.041845
003		.060000 x	20.419486 =	1.225169
-----				
			T.E =	2.372014
6103	6103			
268		1.050000 x	1.171500 =	1.230075
003		.050000 x	20.419486 =	1.020974
-----				
			T.E =	2.251049

6104	6104			
252		.050000 x	2.100000 =	.105000
268		1.030000 x	1.171500 =	1.206645
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	2.536814
6111	6111			
266		1.100000 x	.703000 =	.773300
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	3.836223
6116	6116			
280		1.050000 x	1.050000 =	1.102500
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	3.144449
6117	6117			
281		1.050000 x	6.069000 =	6.372450
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	9.435373
6118	6118			
266		1.150000 x	.703000 =	.808450
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	8.354770
6119	6119			
293		1.100000 x	.000000 =	.000000
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	
6120	6120			
289		1.050000 x	.904700 =	.949935
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.991884
6121	6121			
266		1.100000 x	.703000 =	.773300
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	8.319620

6122	6122			
265		1.050000 x	.941500 =	.988575
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	5.072472
6123	6123			
265		.900000 x	.941500 =	.847350
002		.150000 x	17.312112 =	2.596817
265		.090000 x	.941500 =	.084735
003		.150000 x	20.419486 =	3.062923
266		.100000 x	.703000 =	.070300
266		.010000 x	.703000 =	.007030
		-----		
			T.E =	6.669155
6126	6126			
265		1.250000 x	.941500 =	1.176875
003		.200000 x	20.419486 =	4.083897
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	9.344669
6127	6127			
290		4.800000 x	3.500000 =	16.800000
002		.800000 x	17.312112 =	13.849690
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	46.985278
6128	6128			
290		1.200000 x	3.500000 =	4.200000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	11.746320
6201	6201			
264		1.400000 x	1.239900 =	1.735860
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	11.168760
6202	6202			
264		1.300000 x	1.239900 =	1.611870
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	9.158190

6203	6203				
282		1.200000 x	1.086500 =	1.303800	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	14.509859	
6204	6204				
282		1.300000 x	1.086500 =	1.412450	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	16.505089	
6205	6205				
277		1.250000 x	1.121500 =	1.401875	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
		-----			
			T.E =	20.267674	
6221	6221				
265		1.150000 x	.941500 =	1.082725	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	8.629045	
6222	6222				
265		1.200000 x	.941500 =	1.129800	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	14.335859	
6223	6223				
265		1.250000 x	.941500 =	1.176875	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	20.042674	
6224	6224				
271		.720000 x	1.111500 =	.800280	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
282		.480000 x	1.086500 =	.521520	
		-----			
			T.E =	8.868120	

6225	6225			
271		.720000 x	1.111500 =	.800280
003		.250000 x	20.419486 =	5.104872
282		.480000 x	1.086500 =	.521520
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	10.754700
6226	6226			
265		1.200000 x	.941500 =	1.129800
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	27.541919
6227	6227			
265		1.250000 x	.941500 =	1.176875
003		.850000 x	20.419486 =	17.356563
002		.850000 x	17.312112 =	14.715295
		-----		
			T.E =	33.248733
6228	6228			
282		1.250000 x	1.086500 =	1.358125
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	16.450764
6229	6229			
282		1.250000 x	1.086500 =	1.358125
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
		-----		
			T.E =	18.337344
6230	6230			
277		1.100000 x	1.121500 =	1.233650
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	20.099449
6231	6231			
265		1.150000 x	.941500 =	1.082725
002		.250000 x	17.312112 =	4.328028
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	10.515625

6232	6232			
265		1.150000 x	.941500 =	1.082725
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	16.175364
6236	6236			
253		.500000 x	2.652000 =	1.326000
266		2.000000 x	.703000 =	1.406000
386		.350000 x	28.630000 =	10.020500
390		2.100000 x	1.500000 =	3.150000
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
565.3		.350000 x	3.800000 =	1.330000
392		.350000 x	27.420000 =	9.597000
388		.350000 x	48.870000 =	17.104500
276		5.850000 x	.873000 =	5.107050
272		1.500000 x	1.006500 =	1.509750
-----				
			T.E =	118.467676
6237	6237			
253		.850000 x	2.652000 =	2.254200
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.650000 =	1.977500
392		.350000 x	27.420000 =	9.597000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	1.006500 =	5.032500
266		2.100000 x	.703000 =	1.476300
260		9.500000 x	.545500 =	5.182250
-----				
			T.E =	203.571142
6238	6238			
253		.400000 x	2.652000 =	1.060800
265		6.000000 x	.941500 =	5.649000
266		13.000000 x	.703000 =	9.139000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
-----				
			T.E =	204.506790
6239	6239			
277		1.100000 x	1.121500 =	1.233650
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	12.553129

6301	6301			
266		1.250000 x	.703000 =	.878750
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	15.971389
6302	6302			
266		9.000000 x	.703000 =	6.327000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	138.387593
6401	6401			
265		1.150000 x	.941500 =	1.082725
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	8.629045
6402	6402			
265		1.200000 x	.941500 =	1.129800
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	12.449279
6403	6403			
265		1.250000 x	.941500 =	1.176875
002		.350000 x	17.312112 =	6.059239
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	14.382934
6406	6406			
265		1.200000 x	.941500 =	1.129800
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	23.768759
6407	6407			
265		1.250000 x	.941500 =	1.176875
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	27.588994

6411	6411				
565.3		1.650000 x	3.800000 =	6.270000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	19.476059	
6412	6412				
565.5		1.550000 x	5.650000 =	8.757500	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	
		-----			
			T.E =	25.736719	
6413	6413				
565.6		1.450000 x	7.800000 =	11.310000	
002		.550000 x	17.312112 =	9.521662	
003		.550000 x	20.419486 =	11.230717	
		-----			
			T.E =	32.062379	
6416	6416				
566.3		1.600000 x	5.050000 =	8.080000	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	
		-----			
			T.E =	21.286059	
6417	6417				
566.5		1.500000 x	7.750000 =	11.625000	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	
		-----			
			T.E =	28.604219	
6418	6418				
566.6		1.400000 x	10.300000 =	14.420000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	
		-----			
			T.E =	35.172379	
6421	6421				
565.3		1.050000 x	3.800000 =	3.990000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	12.157794	



6422	6422				
565.5		1.050000 x	5.650000 =	5.932500	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	16.142243	
6423	6423				
565.6		1.050000 x	7.800000 =	8.190000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	20.441692	
6426	6426				
566.3		1.050000 x	5.050000 =	5.302500	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	13.470294	
6427	6427				
566.5		1.050000 x	7.750000 =	8.137500	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	18.347243	
6428	6428				
566.6		1.050000 x	10.300000 =	10.815000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	23.066692	
6431	6431				
278		1.100000 x	3.780000 =	4.158000	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	7.220923	
6432	6432				
251		.100000 x	.861000 =	.086100	
003		.250000 x	20.419486 =	5.104872	
279		1.080000 x	3.906000 =	4.218480	
002		.250000 x	17.312112 =	4.328028	
		-----			
			T.E =	13.737480	
6441	6441				
266		1.100000 x	.703000 =	.773300	
002		.100000 x	17.312112 =	1.731211	
003		.100000 x	20.419486 =	2.041949	
		-----			
			T.E =	4.546460	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.419486 =	.816779
		-----		
			T.E =	
6446.2	6446.2			
285		1.100000 x	.075000 =	.082500
003		.040000 x	20.419486 =	.816779
		-----		
			T.E =	.899279
6447	6447			
251		.050000 x	.861000 =	.043050
003		.100000 x	20.419486 =	2.041949
002		.100000 x	17.312112 =	1.731211
286		1.050000 x	1.788000 =	1.877400
		-----		
			T.E =	5.693610
6448	6448			
251		.050000 x	.861000 =	.043050
003		.100000 x	20.419486 =	2.041949
288		1.050000 x	1.940600 =	2.037630
002		.100000 x	17.312112 =	1.731211
		-----		
			T.E =	5.853840
6501	6501			
282		3.000000 x	1.086500 =	3.259500
295		11.000000 x	6.490000 =	71.390000
296		1.000000 x	12.990000 =	12.990000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
		-----		
			T.E =	238.565892
6502	6502			
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
6501		1.000000 x	238.565892 =	238.565892
		-----		
			T.E =	295.163289
6503	6503			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.950000 x	238.565892 =	226.637597
		-----		
			T.E =	275.688675

6504	6504			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.910000 x	238.565892 =	217.094962
		-----		
			T.E =	262.372879
6505	6505			
002		1.000000 x	17.312112 =	17.312112
6501		.870000 x	238.565892 =	207.552326
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	245.283924
6506	6506			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.810000 x	238.565892 =	193.238373
		-----		
			T.E =	230.969971
6507	6507			
002		.900000 x	17.312112 =	15.580901
003		.900000 x	20.419486 =	18.377537
6501		.920000 x	238.565892 =	219.480621
		-----		
			T.E =	253.439059
6508	6508			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.030000 x	238.565892 =	245.722869
		-----		
			T.E =	294.773946
6509	6509			
002		1.000000 x	17.312112 =	17.312112
6501		1.010000 x	238.565892 =	240.951551
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	278.683149
6510	6510			
002		1.200000 x	17.312112 =	20.774534
6501		1.080000 x	238.565892 =	257.651163
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	302.929081

6511	6511			
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
6501		.920000 x	238.565892 =	219.480621
		-----		
			T.E =	276.078018
6512	6512			
002		1.400000 x	17.312112 =	24.236957
6501		.820000 x	238.565892 =	195.624031
003		1.400000 x	20.419486 =	28.587280
		-----		
			T.E =	248.448269
6513	6513			
002		1.300000 x	17.312112 =	22.505746
6501		.780000 x	238.565892 =	186.081396
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	235.132473
6514	6514			
002		1.200000 x	17.312112 =	20.774534
6501		.760000 x	238.565892 =	181.310078
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	226.587996
6515	6515			
002		1.000000 x	17.312112 =	17.312112
6501		.800000 x	238.565892 =	190.852714
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	228.584312
6516	6516			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.220000 x	238.565892 =	291.050388
		-----		
			T.E =	340.101466
6517	6517			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.120000 x	238.565892 =	267.193799
		-----		
			T.E =	312.471717

6518	6518			
002		1.100000 x	17.312112 =	19.043323
003		1.100000 x	20.419486 =	22.461435
6501		.670000 x	238.565892 =	159.839148
		-----		
			T.E =	201.343905
6519	6519			
002		1.300000 x	17.312112 =	22.505746
6501		1.280000 x	238.565892 =	305.364342
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	354.415419
6520	6520			
002		1.200000 x	17.312112 =	20.774534
6501		1.120000 x	238.565892 =	267.193799
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	312.471717
6521	6521			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.210000 x	238.565892 =	288.664729
		-----		
			T.E =	337.715807
6522	6522			
002		1.200000 x	17.312112 =	20.774534
6501		1.190000 x	238.565892 =	283.893411
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	329.171329
6523	6523			
002		1.200000 x	17.312112 =	20.774534
6501		1.280000 x	238.565892 =	305.364342
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	350.642259
6524	6524			
002		1.200000 x	17.312112 =	20.774534
6501		.800000 x	238.565892 =	190.852714
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	236.130631

6525	6525				
002		1.200000 x	17.312112 =	20.774534	
6501		1.040000 x	238.565892 =	248.108528	
003		1.200000 x	20.419486 =	24.503383	
		-----			
			T.E =	293.386445	
6526	6526				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.900000 x	238.565892 =	214.709303	
		-----			
			T.E =	263.760380	
6527	6527				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.120000 x	238.565892 =	267.193799	
		-----			
			T.E =	316.244876	
6528	6528				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.840000 x	238.565892 =	200.395349	
		-----			
			T.E =	245.673267	
6529	6529				
002		1.200000 x	17.312112 =	20.774534	
6501		1.080000 x	238.565892 =	257.651163	
003		1.200000 x	20.419486 =	24.503383	
		-----			
			T.E =	302.929081	
6530	6530				
002		1.000000 x	17.312112 =	17.312112	
6501		.710000 x	238.565892 =	169.381783	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	207.113381	
6531	6531				
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	
6501		.480000 x	238.565892 =	114.511628	
		-----			
			T.E =	137.150587	

6532	6532				
294		6.000000 x	3.687800 =	22.126800	
294		.300000 x	3.687800 =	1.106340	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	
296		1.000000 x	12.990000 =	12.990000	
			T.E =	130.552135	
6541	6541				
282		.350000 x	1.086500 =	.380275	
295		1.050000 x	6.490000 =	6.814500	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
296		.120000 x	12.990000 =	1.558800	
			T.E =	27.619374	
6542	6542				
295		1.050000 x	6.490000 =	6.814500	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
296		.100000 x	12.990000 =	1.299000	
			T.E =	38.298778	
6543	6543				
295		.400000 x	6.490000 =	2.596000	
003		.200000 x	20.419486 =	4.083897	
296		.130000 x	12.990000 =	1.688700	
			T.E =	8.368597	
7101	7101				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.946500 =	.619465	
003		.850000 x	20.419486 =	17.356563	
002		.500000 x	17.312112 =	8.656056	
			T.E =	26.777084	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.946500 =	.619465	
003		.700000 x	20.419486 =	14.293640	
002		.400000 x	17.312112 =	6.924845	
			T.E =	21.982950	

7103	7103				
201		.000500 x	290.000000 =	.145000	
002		.300000 x	17.312112 =	5.193634	
003		.600000 x	20.419486 =	12.251692	
1445		.004000 x	61.946500 =	.247786	
		-----			
			T.E =	17.838111	
7104	7104				
201		.000500 x	290.000000 =	.145000	
003		1.000000 x	20.419486 =	20.419486	
1445		.008000 x	61.946500 =	.495572	
002		.600000 x	17.312112 =	10.387267	
		-----			
			T.E =	31.447325	
7111	7111				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	20.419486 =	12.251692	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	17.909302	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.616750 =	1.123652	
003		.650000 x	20.419486 =	13.272666	
001		.350000 x	15.741598 =	5.509559	
		-----			
			T.E =	20.050877	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.946500 =	1.672556	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	22.875624	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	76.007500 =	2.052203	
001		.300000 x	15.741598 =	4.722479	
003		.800000 x	20.419486 =	16.335589	
		-----			
			T.E =	23.255271	



7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	87.681250 =		1.315219
1446		.006000 x	52.880500 =		.317283
001		.300000 x	15.741598 =		4.722479
1445		.006000 x	61.946500 =		.371679
003		.900000 x	20.419486 =		18.377537
-----					
			T.E =		25.249198
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	15.741598 =		4.722479
1445		.012000 x	61.946500 =		.743358
1465		.015000 x	94.188150 =		1.412822
003		.900000 x	20.419486 =		18.377537
-----					
			T.E =		25.401197
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	92.094750 =		1.381421
1445		.012000 x	61.946500 =		.743358
003		.900000 x	20.419486 =		18.377537
001		.300000 x	15.741598 =		4.722479
-----					
			T.E =		25.369796
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	87.210150 =		1.308152
1445		.012000 x	61.946500 =		.743358
001		.300000 x	15.741598 =		4.722479
003		.900000 x	20.419486 =		18.377537
-----					
			T.E =		25.296527
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	29.264100 =		.614546
1426		.006000 x	152.456250 =		.914738
001		.300000 x	15.741598 =		4.722479
003		.600000 x	20.419486 =		12.251692
-----					
			T.E =		18.648455

7132	7132			
201		.000500 x	290.000000 =	.145000
1427		.006000 x	163.304700 =	.979828
1418		.021000 x	41.616750 =	.873952
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	20.781005
7133	7133			
201		.000500 x	290.000000 =	.145000
1463		.015000 x	74.871250 =	1.123069
1427		.006000 x	163.304700 =	.979828
1418		.006000 x	41.616750 =	.249701
003		.600000 x	20.419486 =	12.251692
001		.350000 x	15.741598 =	5.509559
-----				
			T.E =	20.258848
7134	7134			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
003		.600000 x	20.419486 =	12.251692
1464		.015000 x	56.673600 =	.850104
1427		.006000 x	163.304700 =	.979828
1418		.006000 x	41.616750 =	.249701
-----				
			T.E =	19.985884
7136	7136			
201		.000500 x	290.000000 =	.145000
001		.250000 x	15.741598 =	3.935400
1418		.017000 x	41.616750 =	.707485
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	12.955679
7138	7138			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1418		.027000 x	41.616750 =	1.123652
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	22.326720
7141	7141			
201		.000500 x	290.000000 =	.145000
1445		.027000 x	61.946500 =	1.672556
003		1.000000 x	20.419486 =	20.419486
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	28.533681

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
001		.350000 x	15.741598 =	5.509559
1413		.007000 x	29.264100 =	.204849
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	29.264100 =	.409697
001		.450000 x	15.741598 =	7.083719
1422		.016000 x	.000000 =	.000000
003		.600000 x	20.419486 =	12.251692

-----  
T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
003		.600000 x	20.419486 =	12.251692
001		.450000 x	15.741598 =	7.083719

-----  
T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.014000 x	41.616750 =	.582635
003		.650000 x	20.419486 =	13.272666
1422		.016000 x	.000000 =	.000000

-----  
T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.007000 x	41.616750 =	.291317
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.304700 =	1.143133
003		.650000 x	20.419486 =	13.272666

-----  
T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
1447		.014000 x	59.035900 =	.826503
1448		.016000 x	.000000 =	.000000
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

-----  
T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	59.035900 =	.413251
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719

-----  
T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
1453		.020000 x	187.752750 =	3.755055
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

-----  
T.E = 75.165394

7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
001		.600000 x	15.741598 =	9.444959
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379

-----  
T.E =

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	210.972750 =	4.219455
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
1445		.022000 x	61.946500 =	1.362823
001		.600000 x	15.741598 =	9.444959

-----  
T.E = 75.629794

7164	7164			
201		.000800 x	290.000000 =	.232000
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

-----  
T.E =

7165	7165			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.741598 =	9.444959
002		1.600000 x	17.312112 =	27.699379
1459		.020000 x	210.972750 =	4.219455
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178

-----  
T.E = 75.629794

7166	7166			
201		.000800 x	290.000000 =	.232000
1453		.017000 x	187.752750 =	3.191797
1445		.022000 x	61.946500 =	1.362823
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

-----  
T.E = 57.935336

7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
002		1.200000 x	17.312112 =	20.774534

-----  
T.E =

7168	7168			
201		.000800 x	290.000000 =	.232000
1454		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799
-----				
			T.E =	58.330076
7169	7169			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
-----				
			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
1459		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.946500 =	1.362823
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
-----				
			T.E =	58.330076
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160
-----				
			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229
-----				
			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435
-----				
			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	18.377537

7179	7179			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7181	7181			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
7206	7206			
142		26.000000 x	.340000 =	8.840000
1412		.040000 x	27.931800 =	1.117272
003		.600000 x	20.419486 =	12.251692
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	27.402597
7207	7207			
142		26.000000 x	.340000 =	8.840000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	20.419486 =	10.209743
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	23.936407
7208	7208			
142		26.000000 x	.340000 =	8.840000
002		.200000 x	17.312112 =	3.462422
003		.400000 x	20.419486 =	8.167794
1412		.025000 x	27.931800 =	.698295
		-----		
			T.E =	21.168512
7209	7209			
142		26.000000 x	.340000 =	8.840000
1412		.005000 x	27.931800 =	.139659
002		.150000 x	17.312112 =	2.596817
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	17.702322
7211	7211			
146		15.000000 x	.370000 =	5.550000
1445		.001000 x	61.946500 =	.061947
003		.400000 x	20.419486 =	8.167794
283		.075000 x	1.305700 =	.097928
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	17.340091

7221	7221				
203.2		.001500 x	370.000000 =		.555000
254		.020000 x	3.532000 =		.070640
492		.200000 x	.540000 =		.108000
003		.200000 x	20.419486 =		4.083897
002		.150000 x	17.312112 =		2.596817
506		1.150000 x	1.431700 =		1.646455
				T.E =	9.060809
7222	7222				
254		.050000 x	3.532000 =		.176600
492		.200000 x	.540000 =		.108000
002		.150000 x	17.312112 =		2.596817
003		.250000 x	20.419486 =		5.104872
506		1.200000 x	1.431700 =		1.718040
				T.E =	9.704328
7223	7223				
254		.050000 x	3.532000 =		.176600
493		.200000 x	.730000 =		.146000
003		.200000 x	20.419486 =		4.083897
002		.200000 x	17.312112 =		3.462422
508		1.200000 x	.860000 =		1.032000
				T.E =	8.900920
7231	7231				
274		1.200000 x	1.525100 =		1.830120
003		.250000 x	20.419486 =		5.104872
002		.250000 x	17.312112 =		4.328028
274		.200000 x	1.525100 =		.305020
				T.E =	11.568040
7241	7241				
297.2		.051072 x	.000000 =		.000000
495		.500000 x	.000000 =		.000000
002		1.400000 x	17.312112 =		24.236957
003		1.400000 x	20.419486 =		28.587280
001		.200000 x	15.741598 =		3.148320
				T.E =	



7242	7242			
297.2		.057000 x	.000000 =	.000000
001		.200000 x	15.741598 =	3.148320
003		2.800000 x	20.419486 =	57.174561
002		2.800000 x	17.312112 =	48.473914
495		1.000000 x	.000000 =	.000000
		-----		
			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.861000 =	1.119300
		-----		
			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
251		1.300000 x	.861000 =	1.119300
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.861000 =	1.119300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	
7244	7244			
251		1.200000 x	.861000 =	1.033200
273		1.200000 x	1.236500 =	1.483800
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
		-----		
			T.E =	40.248598
7245	7245			
251		.500000 x	.861000 =	.430500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
273		1.200000 x	1.236500 =	1.483800
		-----		
			T.E =	28.326419

7246	7246			
265		.500000 x	.941500 =	.470750
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
298.1		6.700000 x	7.910000 =	52.997000
		-----		
			T.E =	91.199348
7301	7301			
096		1.050000 x	.000000 =	.000000
1444		.001500 x	76.007500 =	.114011
1445		.025000 x	61.946500 =	1.548663
003		.900000 x	20.419486 =	18.377537
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
1444		.002000 x	76.007500 =	.152015
003		1.000000 x	20.419486 =	20.419486
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
003		2.000000 x	20.419486 =	40.838972
1445		.025000 x	61.946500 =	1.548663
1444		.001000 x	76.007500 =	.076008
		-----		
			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
001		.800000 x	15.741598 =	12.593278
1444		.001500 x	76.007500 =	.114011
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
001		.150000 x	15.741598 =	2.361240
1444		.000200 x	76.007500 =	.015202
1445		.004000 x	61.946500 =	.247786
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1445		.005000 x	61.946500 =	.309733
1417		.033000 x	40.284450 =	1.329387
003		2.200000 x	20.419486 =	44.922869
001		.600000 x	15.741598 =	9.444959
-----				
			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
003		1.100000 x	20.419486 =	22.461435
1417		.033000 x	40.284450 =	1.329387
1445		.005000 x	61.946500 =	.309733
-----				
			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1417		.022000 x	40.284450 =	.886258
1445		.004000 x	61.946500 =	.247786
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1449		.030000 x	53.460700 =	1.603821
003		2.500000 x	20.419486 =	51.048715
-----				
			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
1449		.004000 x	53.460700 =	.213843
003		.300000 x	20.419486 =	6.125846
001		.100000 x	15.741598 =	1.574160
-----				
			T.E =	10.519528
7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.460700 =	1.336518
1444		.002000 x	76.007500 =	.152015
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	25.497704

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1449		.025000 x	53.460700 =	1.336518
001		.300000 x	15.741598 =	4.722479
1444		.001500 x	76.007500 =	.114011
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	29.753597
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	76.007500 =	.076008
001		.100000 x	15.741598 =	1.574160
1449		.025000 x	53.460700 =	1.336518
003		1.300000 x	20.419486 =	26.545332
-----				
			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160
-----				
			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	20.419486 =	30.629229
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	76.007500 =	.076008
1449		.025000 x	53.460700 =	1.336518
003		1.500000 x	20.419486 =	30.629229
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	53.460700 =	.106921
1444		.000100 x	76.007500 =	.007601
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664

-----  
T.E =

7326.1	7326.1			
029		.200000 x	.151500 =	.030300
173		48.000000 x	.256100 =	12.292800
003		3.000000 x	20.419486 =	61.258458
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
001		.500000 x	15.741598 =	7.870799

-----  
T.E =

82.901609

7326.2	7326.2			
029		.200000 x	.151500 =	.030300
174		48.000000 x	.000000 =	.000000
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799

-----  
T.E =

7327	7327			
029		.200000 x	.151500 =	.030300
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944
001		.600000 x	15.741598 =	9.444959
175		95.000000 x	.000000 =	.000000

-----  
T.E =

7328.1	7328.1			
029		.300000 x	.151500 =	.045450
171		108.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944

-----  
T.E =

7328.2      7328.2

029	.300000 x	.151500 =	.045450
1449	.020000 x	53.460700 =	1.069214
1444	.007000 x	76.007500 =	.532053
172	108.000000 x	.000000 =	.000000
003	4.000000 x	20.419486 =	81.677944
001	.700000 x	15.741598 =	11.019119

-----  
T.E =

7331      7331

029	1.500000 x	.151500 =	.227250
169	54.000000 x	.000000 =	.000000
003	3.500000 x	20.419486 =	71.468201
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
001	.500000 x	15.741598 =	7.870799

-----  
T.E =

7332      7332

029	2.000000 x	.151500 =	.303000
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
003	4.500000 x	20.419486 =	91.887687
001	.800000 x	15.741598 =	12.593278
170	108.000000 x	.000000 =	.000000

-----  
T.E =

7333      7333

029	.300000 x	.151500 =	.045450
167	1.050000 x	.000000 =	.000000
003	2.500000 x	20.419486 =	51.048715
002	.500000 x	17.312112 =	8.656056
1449	.020000 x	53.460700 =	1.069214

-----  
T.E =

7334      7334

029	.300000 x	.151500 =	.045450
168	1.050000 x	.000000 =	.000000
003	3.000000 x	20.419486 =	61.258458
002	.600000 x	17.312112 =	10.387267
1449	.020000 x	53.460700 =	1.069214

-----  
T.E =

7335	7335				
001		.450000 x	15.741598 =	7.083719	
1444		.007000 x	76.007500 =	.532053	
1445		.026000 x	61.946500 =	1.610609	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	29.645867	
7336	7336				
001		.400000 x	15.741598 =	6.296639	
1445		.022000 x	61.946500 =	1.362823	
1444		.006000 x	76.007500 =	.456045	
003		.900000 x	20.419486 =	18.377537	
		-----			
			T.E =	26.493045	
7337	7337				
001		.350000 x	15.741598 =	5.509559	
003		.800000 x	20.419486 =	16.335589	
1445		.017000 x	61.946500 =	1.053091	
1444		.005000 x	76.007500 =	.380038	
		-----			
			T.E =	23.278276	
7338	7338				
026		.500000 x	.099900 =	.049950	
001		.300000 x	15.741598 =	4.722479	
1445		.017000 x	61.946500 =	1.053091	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	20.119160	
7340	7340				
289		1.100000 x	.904700 =	.995170	
001		.400000 x	15.741598 =	6.296639	
1445		.026000 x	61.946500 =	1.610609	
1444		.007000 x	76.007500 =	.532053	
003		1.100000 x	20.419486 =	22.461435	
		-----			
			T.E =	31.895905	
7341	7341				
003		.200000 x	20.419486 =	4.083897	
1441		.003000 x	27.111000 =	.081333	
		-----			
			T.E =	4.165230	
7346	7346				
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	4.083897	

7347	7347				
001		.200000 x	15.741598 =	3.148320	
003		.500000 x	20.419486 =	10.209743	
1445		.009000 x	61.946500 =	.557519	
1444		.002000 x	76.007500 =	.152015	
		-----			
			T.E =	14.067596	
7351	7351				
001		.200000 x	15.741598 =	3.148320	
003		.600000 x	20.419486 =	12.251692	
1444		.009000 x	76.007500 =	.684068	
		-----			
			T.E =	16.084079	
7352	7352				
001		.200000 x	15.741598 =	3.148320	
1444		.012000 x	76.007500 =	.912090	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	18.354050	
7355	7355				
001		.150000 x	15.741598 =	2.361240	
003		.600000 x	20.419486 =	12.251692	
1444		.008000 x	76.007500 =	.608060	
		-----			
			T.E =	15.220991	
7356	7356				
001		.100000 x	15.741598 =	1.574160	
003		.550000 x	20.419486 =	11.230717	
1444		.007000 x	76.007500 =	.532053	
		-----			
			T.E =	13.336930	
7357	7357				
001		.050000 x	15.741598 =	.787080	
1444		.006000 x	76.007500 =	.456045	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	11.452868	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.099900 =	1.998000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
065		.040000 x	13.610000 =	.544400	
		-----			
			T.E =	36.767838	



7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.099900 =	1.298700
065		.027000 x	13.610000 =	.367470
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	28.211789
7361	7361			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.099900 =	1.398600
002		1.000000 x	17.312112 =	17.312112
003		1.400000 x	20.419486 =	28.587280
346.1		30.000000 x	.057200 =	1.716000
065		.015000 x	13.610000 =	.204150
		-----		
			T.E =	49.351642
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.099900 =	1.398600
		-----		
			T.E =	49.722842
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.099900 =	1.398600
346.2		22.000000 x	.103600 =	2.279200
002		1.000000 x	17.312112 =	17.312112
003		1.400000 x	20.419486 =	28.587280
348		8.000000 x	.103600 =	.828800
065		.015000 x	13.610000 =	.204150
		-----		
			T.E =	50.743642
7363	7363			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
026		17.000000 x	.099900 =	1.698300
346.1		35.000000 x	.057200 =	2.002000
065		.020000 x	13.610000 =	.272200
		-----		
			T.E =	57.551712

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
346.1		24.000000 x	.057200 =	1.372800
026		17.000000 x	.099900 =	1.698300
065		.020000 x	13.610000 =	.272200
		-----		
			T.E =	58.062112
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.099900 =	1.698300
		-----		
			T.E =	59.175712
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.099900 =	.999000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.880500 =	.528805
002		2.000000 x	17.312112 =	34.624224
346.1		45.000000 x	.057200 =	2.574000
		-----		
			T.E =	100.117987
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
026		10.000000 x	.099900 =	.999000
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
		-----		
			T.E =	100.813987
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.099900 =	.999000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.880500 =	.528805
002		2.000000 x	17.312112 =	34.624224
346.2		30.000000 x	.103600 =	3.108000
		-----		
			T.E =	102.205987

7371.1	7371.1						
026	-	14.000000 x	.099900 =	-	1.398600		
7361		1.000000 x	49.351642 =		49.351642		
029		14.000000 x	.151500 =		2.121000		
						-----	
						T.E =	50.074042
7371.2	7371.2						
026	-	14.000000 x	.099900 =	-	1.398600		
7361		1.000000 x	49.351642 =		49.351642		
028		14.000000 x	.000000 =		.000000		
						-----	
						T.E =	
7372.1	7372.1						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.1		1.000000 x	49.722842 =		49.722842		
029		14.000000 x	.151500 =		2.121000		
						-----	
						T.E =	50.445242
7372.2	7372.2						
026	-	14.000000 x	.099900 =	-	1.398600		
7362.1		1.000000 x	49.722842 =		49.722842		
028		14.000000 x	.000000 =		.000000		
						-----	
						T.E =	
7372.3	7372.3						
026	-	14.000000 x	.099900 =	-	1.398600		
029		14.000000 x	.151500 =		2.121000		
7362.2		1.000000 x	50.743642 =		50.743642		
						-----	
						T.E =	51.466042
7372.4	7372.4						
026	-	14.000000 x	.099900 =	-	1.398600		
028		14.000000 x	.000000 =		.000000		
7362.2		1.000000 x	50.743642 =		50.743642		
						-----	
						T.E =	
7373.1	7373.1						
026	-	17.000000 x	.099900 =	-	1.698300		
029		17.000000 x	.151500 =		2.575500		
7363		1.000000 x	57.551712 =		57.551712		
						-----	
						T.E =	58.428912

7373.2	7373.2					
026	-	17.000000 x	.099900 =	-	1.698300	
7363		1.000000 x	57.551712 =		57.551712	
028		17.000000 x	.000000 =		.000000	
-----						
			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
029		17.000000 x	.151500 =		2.575500	
-----						
			T.E =		58.939312	
7374.2	7374.2					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7364.1		1.000000 x	58.062112 =		58.062112	
-----						
			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.099900 =	-	1.698300	
029		17.000000 x	.151500 =		2.575500	
7364.2		1.000000 x	59.175712 =		59.175712	
-----						
			T.E =		60.052912	
7374.4	7374.4					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	59.175712 =		59.175712	
-----						
			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.099900 =	-	.999000	
7366		1.000000 x	100.117987 =		100.117987	
029		10.000000 x	.151500 =		1.515000	
-----						
			T.E =		100.633987	
7376.2	7376.2					
026	-	10.000000 x	.099900 =	-	.999000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	100.117987 =		100.117987	
-----						
			T.E =			

7377.1	7377.1				
026	-	10.000000 x	.099900 =	-	.999000
7367.1		1.000000 x	100.813987 =		100.813987
029		10.000000 x	.151500 =		1.515000
-----					
			T.E =		101.329987
7377.2	7377.2				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	100.813987 =		100.813987
-----					
			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.151500 =		1.515000
7367.2		1.000000 x	102.205987 =		102.205987
-----					
			T.E =		102.721987
7377.4	7377.4				
026	-	10.000000 x	.099900 =	-	.999000
7367.2		1.000000 x	102.205987 =		102.205987
028		10.000000 x	.000000 =		.000000
-----					
			T.E =		
7381	7381				
456		.100000 x	1.658300 =		.165830
-----					
			T.E =		.165830
7382	7382				
443		.150000 x	1.987900 =		.298185
447		.050000 x	4.525500 =		.226275
003		.300000 x	20.419486 =		6.125846
-----					
			T.E =		6.650306
7383	7383				
002		.250000 x	17.312112 =		4.328028
003		.150000 x	20.419486 =		3.062923
-----					
			T.E =		7.390951
7384	7384				
003		.500000 x	20.419486 =		10.209743
-----					
			T.E =		10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	12.251692
7387	7387			
261		1.500000 x	.598400 =	.897600
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.351642 =	54.286806
		-----		
			T.E =	75.603892
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.351642 =	29.610985
		-----		
			T.E =	80.659700
7389.1.1	7389.1.1			
7371.1		.300000 x	50.074042 =	15.022213
		-----		
			T.E =	15.022213
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.052912 =	18.015874
		-----		
			T.E =	18.015874
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.445242 =	15.133573
		-----		
			T.E =	15.133573
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.466042 =	15.439813
		-----		
			T.E =	15.439813
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.428912 =	17.528674
		-----		
			T.E =	17.528674
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.939312 =	17.681794
		-----		
			T.E =	17.681794
7389.2.1	7389.2.1			
7371.1		.500000 x	50.074042 =	25.037021
		-----		
			T.E =	25.037021
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000
		-----		
			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.052912 =	30.026456
		-----		
			T.E =	30.026456

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.445242 =	25.222621
-----				
			T.E =	25.222621
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.466042 =	25.733021
-----				
			T.E =	25.733021
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.428912 =	29.214456
-----				
			T.E =	29.214456
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000
-----				
			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.939312 =	29.469656
-----				
			T.E =	29.469656
7391	7391			
003		.250000 x	20.419486 =	5.104872
-----				
			T.E =	5.104872



7392	7392				
298.1		1.081080 x	7.910000 =	8.551343	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	16.719137	
7393	7393				
294		.347760 x	3.687800 =	1.282469	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	7.408315	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	6.644872	

ΑΤΟΕ	3ο Τρίμηνο του 2011	Σελ. Ημ/νία	162 22/12/2011
7416	7416		
003	.800000 x	20.419486 =	16.335589
	-----		
		T.E =	16.335589
7417	7417		
003	1.800000 x	20.419486 =	36.755075
	-----		
		T.E =	36.755075
7418	7418		
003	2.600000 x	20.419486 =	53.090664
	-----		
		T.E =	53.090664
7419	7419		
003	.800000 x	20.419486 =	16.335589
	-----		
		T.E =	16.335589
7420	7420		
003	1.200000 x	20.419486 =	24.503383
	-----		
		T.E =	24.503383
7421	7421		
003	.800000 x	20.419486 =	16.335589
	-----		
		T.E =	16.335589
7422	7422		
003	.350000 x	20.419486 =	7.146820
	-----		
		T.E =	7.146820
7431	7431		
332	1.150000 x	88.540000 =	101.821000
003	4.000000 x	20.419486 =	81.677944
1445	.020000 x	61.946500 =	1.238930
1444	.001000 x	76.007500 =	.076008
	-----		
		T.E =	184.813882
7432	7432		
331	1.150000 x	85.390000 =	98.198500
1445	.020000 x	61.946500 =	1.238930
003	4.400000 x	20.419486 =	89.845738
1444	.001000 x	76.007500 =	.076008
	-----		
		T.E =	189.359176

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
003		5.100000 x	20.419486 =	104.139379	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	203.652816	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	
		-----			
			T.E =	224.072302	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =	193.814279	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
003		4.600000 x	20.419486 =	93.929636	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	201.982073	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.300000 x	20.419486 =	108.223276	
		-----			
			T.E =	216.275713	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.300000 x	20.419486 =	128.642762	
		-----			
			T.E =	236.695199	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	20.419486 =	91.887687	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	235.768125	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	
		-----			
			T.E =	243.935919	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
003		5.600000 x	20.419486 =	114.349122	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	258.229559	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
003		6.600000 x	20.419486 =	134.768608	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	278.649045	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	20.419486 =	100.055481	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
		-----			
			T.E =	256.332919	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.300000 x	20.419486 =	108.223276	
		-----			
			T.E =	264.500713	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.000000 x	20.419486 =	122.516916	
-----					
			T.E =	278.794354	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		7.000000 x	20.419486 =	142.936402	
-----					
			T.E =	299.213840	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.915000 x	20.419486 =	18.683830	
-----					
			T.E =	28.635173	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
003		.945000 x	20.419486 =	19.296414	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
-----					
			T.E =	30.101658	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.990000 x	20.419486 =	20.215291	
-----					
			T.E =	34.603335	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
003		1.050000 x	20.419486 =	21.440460	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
-----					
			T.E =	37.068204	

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
003		.488000 x	20.419486 =	9.964709
		-----		
			T.E =	14.940381
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
003		.504000 x	20.419486 =	10.291421
		-----		
			T.E =	15.694043
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	20.419486 =	10.781489
1444		.000050 x	76.007500 =	.003800
1445		.001000 x	61.946500 =	.061947
		-----		
			T.E =	17.975510
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	20.419486 =	11.434912
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
		-----		
			T.E =	19.248784
7501	7501			
7433		1.000000 x	203.652816 =	203.652816
		-----		
			T.E =	203.652816
7503	7503			
7443		1.000000 x	216.275713 =	216.275713
		-----		
			T.E =	216.275713
7506	7506			
7453		1.000000 x	258.229559 =	258.229559
		-----		
			T.E =	258.229559
7508	7508			
7463		1.000000 x	278.794354 =	278.794354
		-----		
			T.E =	278.794354

7511	7511				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	20.419486 =	18.683830	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
		-----			
			T.E =	28.635173	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.945000 x	20.419486 =	19.296414	
		-----			
			T.E =	30.101658	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	215.828500	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	20.419486 =	98.013533	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	197.450963	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	232.535295	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		5.000000 x	20.419486 =	102.097430	
		-----			
			T.E =	210.073860	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	20.419486 =	106.181327	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	209.241257	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
003		5.400000 x	20.419486 =	110.265224	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	222.179154	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	
		-----			
			T.E =	270.384500	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	
		-----			
			T.E =	291.835295	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
003		3.000000 x	20.419486 =	61.258458	
1445		.010000 x	61.946500 =	.619465	
		-----			
			T.E =	101.726923	
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	20.419486 =	81.677944	
1445		.010000 x	61.946500 =	.619465	
		-----			
			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
003		3.700000 x	20.419486 =	75.552098	
1445		.010000 x	61.946500 =	.619465	
		-----			
			T.E =	137.713863	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
1445		.010000 x	61.946500 =	.619465	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =		



7543	7543			
332		.170000 x	88.540000 =	15.051800
003		4.800000 x	20.419486 =	98.013533
1445		.010000 x	61.946500 =	.619465
338		.350000 x	.000000 =	.000000
-----				
			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402
-----				
			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	271.468832
7553	7553			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402
-----				
			T.E =	289.650332
7554	7554			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		9.000000 x	20.419486 =	183.775374
-----				
			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	312.307804
7556	7556			
323		1.150000 x	126.500000 =	145.475000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.946500 =	1.238930
-----				
			T.E =	330.489304

ΑΤΟΕ	3ο Τρίμηνο του 2011	Σελ. Ημ/νία	170 22/12/2011
7558	7558		
331	.080000 x	85.390000 =	6.831200
003	1.500000 x	20.419486 =	30.629229
1445	.003000 x	61.946500 =	.185840
-----			
		T.E =	37.646269
7559	7559		
331	.080000 x	85.390000 =	6.831200
1445	.003000 x	61.946500 =	.185840
003	1.500000 x	20.419486 =	30.629229
-----			
		T.E =	37.646269
7561	7561		
332	1.150000 x	88.540000 =	101.821000
1445	.020000 x	61.946500 =	1.238930
003	5.200000 x	20.419486 =	106.181327
-----			
		T.E =	209.241257
7562	7562		
334	1.150000 x	132.830000 =	152.754500
003	5.700000 x	20.419486 =	116.391070
1445	.020000 x	61.946500 =	1.238930
-----			
		T.E =	270.384500
7563	7563		
332	1.250000 x	88.540000 =	110.675000
1445	.020000 x	61.946500 =	1.238930
003	5.400000 x	20.419486 =	110.265224
-----			
		T.E =	222.179154
7564	7564		
334	1.250000 x	132.830000 =	166.037500
1445	.020000 x	61.946500 =	1.238930
003	6.100000 x	20.419486 =	124.558865
-----			
		T.E =	291.835295
7565	7565		
003	1.500000 x	20.419486 =	30.629229
-----			
		T.E =	30.629229
7566	7566		
7561	1.500000 x	209.241257 =	313.861886
-----			
		T.E =	313.861886

7567	7567			
7562		1.500000 x	270.384500 =	405.576750
		-----		
			T.E =	405.576750
7568	7568			
7563		1.500000 x	222.179154 =	333.268731
		-----		
			T.E =	333.268731
7569	7569			
7564		1.500000 x	291.835295 =	437.752943
		-----		
			T.E =	437.752943
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.2		.030000 x	.000000 =	.000000
		-----		
			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	263.807958
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
328		.030000 x	.000000 =	.000000
		-----		
			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	20.419486 =	77.594047
		-----		
			T.E =	175.792547

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =	238.516341	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	20.419486 =	95.971584	
		-----			
			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	134.257521 =	2.685150	
1445		.005000 x	61.946500 =	.309733	
003		2.300000 x	20.419486 =	46.964818	
		-----			
			T.E =	116.666201	
7601	7601				
401		1.100000 x	12.200000 =	13.420000	
457		.500000 x	.827900 =	.413950	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	24.043693	
7602	7602				
403		1.100000 x	14.290000 =	15.719000	
457		.500000 x	.827900 =	.413950	
003		.550000 x	20.419486 =	11.230717	
		-----			
			T.E =	27.363667	
7603	7603				
406		1.100000 x	17.660000 =	19.426000	
457		.500000 x	.827900 =	.413950	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	33.112616	
7604.1	7604.1				
409		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	
457		.500000 x	.827900 =	.413950	
		-----			
			T.E =	38.861565	

7604.2	7604.2			
410		1.100000 x	28.610000 =	31.471000
003		.750000 x	20.419486 =	15.314615
457		.500000 x	.827900 =	.413950
		-----		
			T.E =	47.199565
7606	7606			
401		1.100000 x	12.200000 =	13.420000
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	25.671692
7607	7607			
403		1.100000 x	14.290000 =	15.719000
003		.650000 x	20.419486 =	13.272666
		-----		
			T.E =	28.991666
7608	7608			
406		1.100000 x	17.660000 =	19.426000
003		.750000 x	20.419486 =	15.314615
		-----		
			T.E =	34.740615
7609.1	7609.1			
409		1.100000 x	21.030000 =	23.133000
003		.850000 x	20.419486 =	17.356563
		-----		
			T.E =	40.489563
7609.2	7609.2			
410		1.100000 x	28.610000 =	31.471000
003		.850000 x	20.419486 =	17.356563
		-----		
			T.E =	48.827563
7611	7611			
411		1.100000 x	26.710000 =	29.381000
457		.500000 x	.827900 =	.413950
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	40.004693
7612	7612			
412		1.100000 x	28.830000 =	31.713000
003		.550000 x	20.419486 =	11.230717
457		.500000 x	.827900 =	.413950
		-----		
			T.E =	43.357667

7613	7613				
411		1.100000 x	26.710000 =	29.381000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	41.632692	
7614	7614				
412		1.100000 x	28.830000 =	31.713000	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	44.985666	
7616	7616				
414		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.827900 =	.413950	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	35.798642	
7617	7617				
415		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.827900 =	.413950	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	36.819616	
7618	7618				
414		1.100000 x	21.030000 =	23.133000	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	37.426640	
7619	7619				
415		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	
		-----			
			T.E =	38.447615	
7621	7621				
418		1.100000 x	29.450000 =	32.395000	
457		.800000 x	.827900 =	.662320	
003		1.200000 x	20.419486 =	24.503383	
		-----			
			T.E =	57.560703	
7622	7622				
419		1.100000 x	29.450000 =	32.395000	
003		1.400000 x	20.419486 =	28.587280	
457		.800000 x	.827900 =	.662320	
		-----			
			T.E =	61.644600	

7626.1	7626.1			
298.2		18.000000 x	6.360000 =	114.480000
421		1.000000 x	97.840000 =	97.840000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	476.441186
7626.2	7626.2			
298.2		18.000000 x	6.360000 =	114.480000
422		1.000000 x	134.470000 =	134.470000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	513.071186
7627.1	7627.1			
298.2		16.000000 x	6.360000 =	101.760000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
421		1.000000 x	97.840000 =	97.840000
		-----		
			T.E =	425.989588
7627.2	7627.2			
298.2		16.000000 x	6.360000 =	101.760000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
422		1.000000 x	134.470000 =	134.470000
		-----		
			T.E =	462.619588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	7.562559

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	10.269949
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	
7701	7701			
024		.001500 x	45.000000 =	.067500
002		.050000 x	17.312112 =	.865606
003		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	3.383444
7702	7702			
024		.001800 x	45.000000 =	.081000
003		.080000 x	20.419486 =	1.633559
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	2.580164
7706	7706			
024		.002000 x	45.000000 =	.090000
003		.150000 x	20.419486 =	3.062923
002		.080000 x	17.312112 =	1.384969
		-----		
			T.E =	4.537892
7707	7707			
024		.002300 x	45.000000 =	.103500
003		.090000 x	20.419486 =	1.837754
002		.100000 x	17.312112 =	1.731211
		-----		
			T.E =	3.672465



7708	7708			
024		.002500 x	45.000000 =	.112500
003		.180000 x	20.419486 =	3.675507
002		.120000 x	17.312112 =	2.077453
-----				
			T.E =	5.865461
7709	7709			
024		.002800 x	45.000000 =	.126000
002		.150000 x	17.312112 =	2.596817
003		.120000 x	20.419486 =	2.450338
-----				
			T.E =	5.173155
7711	7711			
002		.050000 x	17.312112 =	.865606
1485		.200000 x	.855511 =	.171102
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	5.120605
7712	7712			
002		.080000 x	17.312112 =	1.384969
003		.250000 x	20.419486 =	5.104872
1485		.250000 x	.855511 =	.213878
-----				
			T.E =	6.703718
7713	7713			
002		.160000 x	17.312112 =	2.769938
1485		.280000 x	.855511 =	.239543
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	9.135327
7720	7720			
443		.080000 x	1.987900 =	.159032
002		.100000 x	17.312112 =	1.731211
1485		.200000 x	.855511 =	.171102
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	8.187191
7721	7721			
002		.070000 x	17.312112 =	1.211848
1485		.200000 x	.855511 =	.171102
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	5.466847

7722.1.1	7722.1.1			
7720		.300000 x	8.187191 =	2.456157
		-----		
			T.E =	2.456157
7722.1.2	7722.1.2			
7721		.300000 x	5.466847 =	1.640054
		-----		
			T.E =	1.640054
7722.2.1	7722.2.1			
7720		.400000 x	8.187191 =	3.274876
		-----		
			T.E =	3.274876
7722.2.2	7722.2.2			
7721		.400000 x	5.466847 =	2.186739
		-----		
			T.E =	2.186739
7725	7725			
471		.300000 x	3.960000 =	1.188000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
		-----		
			T.E =	8.889688
7735	7735			
441		.350000 x	.077700 =	.027195
444		.150000 x	2.207500 =	.331125
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	3.421243
7736	7736			
441		.500000 x	.077700 =	.038850
444		.085000 x	2.207500 =	.187638
445		.010000 x	1.600000 =	.016000
003		.250000 x	20.419486 =	5.104872
446		.005000 x	2.662500 =	.013313
		-----		
			T.E =	5.360672
7737	7737			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
003		.300000 x	20.419486 =	6.125846
1488		.600000 x	.784064 =	.470438
		-----		
			T.E =	6.790928

7738	7738			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
1488		.300000 x	.784064 =	.235219
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	6.555709
7739	7739			
441		.100000 x	.077700 =	.007770
467		.100000 x	3.397500 =	.339750
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	3.410443
7740	7740			
442		.250000 x	.121800 =	.030450
003		.250000 x	20.419486 =	5.104872
1492		.250000 x	2.841075 =	.710269
		-----		
			T.E =	5.845590
7741	7741			
442		.250000 x	.121800 =	.030450
462		.250000 x	.000000 =	.000000
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	
7742	7742			
442		.250000 x	.121800 =	.030450
003		.200000 x	20.419486 =	4.083897
463		.125000 x	4.089100 =	.511138
		-----		
			T.E =	4.625485
7743	7743			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.630000 =	.453750
		-----		
			T.E =	3.547123
7744	7744			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
465		.125000 x	6.180000 =	.772500
		-----		
			T.E =	3.865873

7745	7745			
442		.250000 x	.121800 =	.030450
1492		.250000 x	2.841075 =	.710269
003		.800000 x	20.419486 =	16.335589
1489		.200000 x	.895520 =	.179104
		-----		
			T.E =	17.255412
7746	7746			
441		.350000 x	.077700 =	.027195
003		.150000 x	20.419486 =	3.062923
443		.090000 x	1.987900 =	.178911
		-----		
			T.E =	3.269029
7747	7747			
441		.350000 x	.077700 =	.027195
443		.170000 x	1.987900 =	.337943
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.470010
7748	7748			
443		.090000 x	1.987900 =	.178911
002		.100000 x	17.312112 =	1.731211
445		.030000 x	1.600000 =	.048000
003		.200000 x	20.419486 =	4.083897
450		.060000 x	2.842800 =	.170568
		-----		
			T.E =	6.212587
7749	7749			
443		.160000 x	1.987900 =	.318064
445		.050000 x	1.600000 =	.080000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.842800 =	.284280
		-----		
			T.E =	8.384032
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.534505 =	.191813
		-----		
			T.E =	3.254736
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.534505 =	.383626
		-----		
			T.E =	5.488498

7753	7753			
441		1.000000 x	.077700 =	.077700
443		.080000 x	1.987900 =	.159032
003		.650000 x	20.419486 =	13.272666
1491		.200000 x	1.534505 =	.306901
1490		.090000 x	1.594219 =	.143480
		-----		
			T.E =	13.959779
7754	7754			
441		.800000 x	.077700 =	.062160
1487		.090000 x	.621987 =	.055979
003		.800000 x	20.419486 =	16.335589
1491		.200000 x	1.534505 =	.306901
1490		.090000 x	1.594219 =	.143480
		-----		
			T.E =	16.904108
7755	7755			
442		.250000 x	.121800 =	.030450
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.841075 =	.454572
1491		.200000 x	1.534505 =	.306901
		-----		
			T.E =	21.211409
7756	7756			
442		.300000 x	.121800 =	.036540
003		.350000 x	20.419486 =	7.146820
1492		.300000 x	2.841075 =	.852323
		-----		
			T.E =	8.035683
7761	7761			
441		.650000 x	.077700 =	.050505
1489		.200000 x	.895520 =	.179104
1488		.600000 x	.784064 =	.470438
003		.800000 x	20.419486 =	16.335589
467		.100000 x	3.397500 =	.339750
473		.100000 x	2.832500 =	.283250
		-----		
			T.E =	17.658636
7762	7762			
473		.100000 x	2.832500 =	.283250
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.367147

7764	7764			
474		.125000 x	3.883100 =	.485388
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.527336
7765	7765			
475		.125000 x	6.416900 =	.802113
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.886010
7766	7766			
442		.275000 x	.121800 =	.033495
473		.110000 x	2.832500 =	.311575
1492		.275000 x	2.841075 =	.781296
003		.880000 x	20.419486 =	17.969148
		-----		
			T.E =	19.095513
7767.1	7767.1			
7755		.150000 x	21.211409 =	3.181711
		-----		
			T.E =	3.181711
7767.2	7767.2			
442		.250000 x	.121800 =	.030450
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
473		.200000 x	2.832500 =	.566500
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.150000 x	21.471008 =	3.220651
		-----		
7767.3	7767.3			
7755		.250000 x	21.211409 =	5.302852
		-----		
			T.E =	5.302852
7767.4	7767.4			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.841075 =	.454572
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.250000 x	21.471008 =	5.367752
		-----		

7767.5	7767.5			
7755		.350000 x	21.211409 =	7.423993
		-----		
			T.E =	7.423993
7767.6	7767.6			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.350000 x	21.471008 =	7.514853
		-----		
7767.7	7767.7			
7755		.450000 x	21.211409 =	9.545134
		-----		
			T.E =	9.545134
7767.8	7767.8			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
		-----		
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.450000 x	21.471008 =	9.661954
		-----		
7768	7768			
460		.200000 x	4.377500 =	.875500
003		.450000 x	20.419486 =	9.188769
460		.030000 x	4.377500 =	.131325
002		.450000 x	17.312112 =	7.790450
		-----		
			T.E =	17.986044
7769	7769			
460		.200000 x	4.377500 =	.875500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
460		.030000 x	4.377500 =	.131325
		-----		
			T.E =	8.553145
7770	7770			
460		.090000 x	4.377500 =	.393975
003		.150000 x	20.419486 =	3.062923
002		.150000 x	17.312112 =	2.596817
460		.020000 x	4.377500 =	.087550
		-----		
			T.E =	6.141265

7771	7771				
441		1.000000 x	.077700 =	.077700	
1488		.160000 x	.784064 =	.125450	
1487		.080000 x	.621987 =	.049759	
003		1.300000 x	20.419486 =	26.545332	
473		.100000 x	2.832500 =	.283250	
467		.110000 x	3.397500 =	.373725	
		-----			
			T.E =	27.455216	
7772	7772				
441		1.000000 x	.077700 =	.077700	
458		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	11.014233	
7773	7773				
441		1.000000 x	.077700 =	.077700	
459		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	13.056182	
7774	7774				
442		.250000 x	.121800 =	.030450	
473		.200000 x	2.832500 =	.566500	
1492		.160000 x	2.841075 =	.454572	
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	21.471008	
7785.1	7785.1				
441		.350000 x	.077700 =	.027195	
003		.700000 x	20.419486 =	14.293640	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.437300 =	.292476	
		-----			
			T.E =		
7785.2	7785.2				
441		.350000 x	.077700 =	.027195	
476		.120000 x	2.437300 =	.292476	
478		.160000 x	3.060000 =	.489600	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	15.102911	



7786.1	7786.1			
441		.350000 x	.077700 =	.027195
1489		.200000 x	.895520 =	.179104
003		1.000000 x	20.419486 =	20.419486
1488		.600000 x	.784064 =	.470438
477		.110000 x	.000000 =	.000000
		-----		
			T.E =	
7786.2	7786.2			
441		.350000 x	.077700 =	.027195
1489		.200000 x	.895520 =	.179104
1488		.600000 x	.784064 =	.470438
003		1.000000 x	20.419486 =	20.419486
478		.110000 x	3.060000 =	.336600
		-----		
			T.E =	21.432823
7787	7787			
441		1.000000 x	.077700 =	.077700
476		.090000 x	2.437300 =	.219357
1488		.160000 x	.784064 =	.125450
1487		.080000 x	.621987 =	.049759
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000
		-----		
			T.E =	
7788	7788			
441		.250000 x	.077700 =	.019425
479		1.000000 x	1.876600 =	1.876600
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	16.189665
7791	7791			
441		1.000000 x	.077700 =	.077700
1487		.050000 x	.621987 =	.031099
1491		.200000 x	1.534505 =	.306901
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.625443
7792	7792			
482		.150000 x	1.433300 =	.214995
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.424738

7793	7793			
480		.500000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	
7794	7794			
482		.150000 x	1.433300 =	.214995
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.424738
7797	7797			
201		.000500 x	290.000000 =	.145000
002		.060000 x	17.312112 =	1.038727
		-----		
			T.E =	1.183727
7798	7798			
201		.000600 x	290.000000 =	.174000
002		.070000 x	17.312112 =	1.211848
		-----		
			T.E =	1.385848
7801	7801			
496		1.200000 x	.905500 =	1.086600
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	4.149523
7806	7806			
498		1.150000 x	1.011600 =	1.163340
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	7.289186
7807	7807			
499		1.150000 x	1.386800 =	1.594820
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	9.762614
7808	7808			
500		1.150000 x	2.039600 =	2.345540
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	14.597232

7809	7809			
501		1.200000 x	2.763000 =	3.315600
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	19.651189
7810	7810			
502		1.200000 x	3.807000 =	4.568400
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	22.945937
7811	7811			
503		1.200000 x	.905500 =	1.086600
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	17.422189
7812	7812			
504		1.300000 x	1.199100 =	1.558830
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	19.936367
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	31.421692
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.872297
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	25.795486
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	19.507192

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.431700 =	1.574870
003		.150000 x	20.419486 =	3.062923
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	10.707427
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239
		-----		
			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.707427 =	9.101313
		-----		
			T.E =	9.101313
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238
		-----		
			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303
		-----		
			T.E =	10.038303

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.312112 =	.692484
		-----		
			T.E =	2.134484
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	3.121306
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	2.081006
7931	7931			
519		1.050000 x	50.290000 =	52.804500
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	83.433729
7932.1	7932.1			
514		.000000 x	42.680000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7932.2	7932.2			
520		.000000 x	41.070000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7933.1	7933.1			
514		.000000 x	42.680000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000
7933.2	7933.2			
520		.000000 x	41.070000 =	.000000
003		.000000 x	20.419486 =	.000000
		-----		
			T.E =	.000000

7934	7934			
535		1.150000 x	6.600000 =	7.590000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	26.455799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.861000 =	.086100
		-----		
			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	9.124160