

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

3ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021		2.670000
029		.149900
051		15.400000
111	Κατχ Τιμή X 1.8117/ 6.46	16.829739
112	Κατχ Τιμή X 1.8117/ 6.46	18.705943
113	Κατχ Τιμή X 1.8117/ 6.46	24.769248
114	Κατχ Τιμή X 1.8117/ 6.67	23.989407
115	Κατχ Τιμή X 1.8117/ 6.67	19.931416
116	Κατχ Τιμή X 1.8117/ 6.46	24.152261
117	Κατχ Τιμή X 1.8117/ 6.67	19.931416
118	Κατχ Τιμή X 1.8117/ 6.67	18.233796
150		.074800
211		.820200
212		.937000
213		1.840000
214		3.800000
221		.097700
224		.070000
231		.680000
241		6.340000
242		5.000000
251		290.000000
252		210.000000
301		4.060000
302		6.700000
360		10.700000
361		27.500000
362		5.250000
363		.580000
364		3.520000
365		22.500000
366		20.630000
367		.118700
368		20.000000
369		12.150000
370		8.000000
371		7.200000
372		1.270000
373		2.040000
374		2.750000
375		1.500000
376		
377		3.190000
378		.540000
379		14.000000
380		.260000
401		254.850000
402		368.170000
403		100.090000
404		201.970000
405		200.190000
406		310.840000
407		52.420000
408		4.300000
409		119.700000
410		110.640000
411		25.980000
412		2.830000
417		127.720000

420	92.370000
428	424.010000
450	109.300000
451	151.480000
452	92.810000
453	86.130000
454	116.440000
455	411.090000

501	501			
211		50.000000 x	.820200 =	41.010000
214		3.000000 x	3.800000 =	11.400000
401		1.000000 x	254.850000 =	254.850000
118		3.000000 x	18.233796 =	54.701388
114		8.000000 x	23.989407 =	191.915256

			ΑΘΡΟΙΣΜΑ =	553.876644

			Η.Δ. =	609.264308
502	502			
211		80.000000 x	.820200 =	65.616000
114		8.000000 x	23.989407 =	191.915256
402		1.000000 x	368.170000 =	368.170000
214		7.000000 x	3.800000 =	26.600000
118		4.000000 x	18.233796 =	72.935184

			ΑΘΡΟΙΣΜΑ =	725.236440

			Η.Δ. =	797.760084
503	503			
211		110.000000 x	.820200 =	90.222000
428		1.000000 x	424.010000 =	424.010000
214		10.000000 x	3.800000 =	38.000000
118		4.000000 x	18.233796 =	72.935184
114		8.000000 x	23.989407 =	191.915256

			ΑΘΡΟΙΣΜΑ =	817.082440

			Η.Δ. =	898.790684
504	504			
211		40.000000 x	.820200 =	32.808000
214		2.000000 x	3.800000 =	7.600000
114		8.000000 x	23.989407 =	191.915256
403		1.000000 x	100.090000 =	100.090000

			ΑΘΡΟΙΣΜΑ =	332.413256

			Η.Δ. =	365.654582
505	505			
211		200.000000 x	.820200 =	164.040000
214		10.000000 x	3.800000 =	38.000000
114		8.000000 x	23.989407 =	191.915256
118		8.000000 x	18.233796 =	145.870368
404		1.000000 x	201.970000 =	201.970000

			ΑΘΡΟΙΣΜΑ =	741.795624

			Η.Δ. =	815.975186

506	506			
211		95.000000 x	.820200 =	77.919000
214		6.000000 x	3.800000 =	22.800000
405		1.000000 x	200.190000 =	200.190000
242		2.500000 x	5.000000 =	12.500000
118		8.000000 x	18.233796 =	145.870368
114		8.000000 x	23.989407 =	191.915256

			ΑΘΡΟΙΣΜΑ =	651.194624

			Η.Δ. =	716.314086
507	507			
211		165.000000 x	.820200 =	135.333000
214		10.000000 x	3.800000 =	38.000000
242		7.000000 x	5.000000 =	35.000000
406		1.000000 x	310.840000 =	310.840000
114		8.000000 x	23.989407 =	191.915256
118		8.000000 x	18.233796 =	145.870368

			ΑΘΡΟΙΣΜΑ =	856.958624

			Η.Δ. =	942.654486
508	508			
211		40.000000 x	.820200 =	32.808000
407		1.000000 x	52.420000 =	52.420000
115		4.000000 x	19.931416 =	79.725664
116		16.000000 x	24.152261 =	386.436176
408		2.000000 x	4.300000 =	8.600000
214		2.000000 x	3.800000 =	7.600000

			ΑΘΡΟΙΣΜΑ =	567.589840

			Η.Δ. =	624.348824
509	509			
211		80.000000 x	.820200 =	65.616000
117		8.000000 x	19.931416 =	159.451328
409		1.000000 x	119.700000 =	119.700000
214		5.000000 x	3.800000 =	19.000000

			ΑΘΡΟΙΣΜΑ =	363.767328

			Η.Δ. =	400.144061
510	510			
211		80.000000 x	.820200 =	65.616000
117		8.000000 x	19.931416 =	159.451328
214		5.000000 x	3.800000 =	19.000000
410		1.000000 x	110.640000 =	110.640000

			ΑΘΡΟΙΣΜΑ =	354.707328

			Η.Δ. =	390.178061

511	511			
212		17.000000 x	.937000 =	15.929000
411		1.000000 x	25.980000 =	25.980000
214		1.000000 x	3.800000 =	3.800000
115		4.000000 x	19.931416 =	79.725664
112		30.000000 x	18.705943 =	561.178290

				ΑΘΡΟΙΣΜΑ = 686.612954

				Η.Δ. = 755.274249
512	512			
211		10.000000 x	.820200 =	8.202000
115		2.000000 x	19.931416 =	39.862832
214		1.000000 x	3.800000 =	3.800000
112		2.000000 x	18.705943 =	37.411886
412		1.000000 x	2.830000 =	2.830000

				ΑΘΡΟΙΣΜΑ = 92.106718

				Η.Δ. = 101.317390
518	518			
211		180.000000 x	.820200 =	147.636000
212		5.000000 x	.937000 =	4.685000
118		8.000000 x	18.233796 =	145.870368
114		8.000000 x	23.989407 =	191.915256
112		8.000000 x	18.705943 =	149.647544
417		1.000000 x	127.720000 =	127.720000
214		12.000000 x	3.800000 =	45.600000

				ΑΘΡΟΙΣΜΑ = 813.074168

				Η.Δ. = 894.381585
521	521			
211		40.000000 x	.820200 =	32.808000
118		4.000000 x	18.233796 =	72.935184
114		8.000000 x	23.989407 =	191.915256
214		3.000000 x	3.800000 =	11.400000
420		1.000000 x	92.370000 =	92.370000

				ΑΘΡΟΙΣΜΑ = 401.428440

				Η.Δ. = 441.571284
550	550			
211		80.000000 x	.820200 =	65.616000
214		5.000000 x	3.800000 =	19.000000
117		8.000000 x	19.931416 =	159.451328
450		1.000000 x	109.300000 =	109.300000

				ΑΘΡΟΙΣΜΑ = 353.367328

				Η.Δ. = 388.704061

560	560			
211		80.000000 x	.820200 =	65.616000
117		8.000000 x	19.931416 =	159.451328
455		1.000000 x	411.090000 =	411.090000
214		7.000000 x	3.800000 =	26.600000

			ΑΘΡΟΙΣΜΑ =	662.757328

			H.Δ. =	729.033061
621	621			
213		.100000 x	1.840000 =	.184000
508		.005000 x	624.348824 =	3.121744
116		.200000 x	24.152261 =	4.830452
111		.800000 x	16.829739 =	13.463791

			B.T =	21.599988
623	623			
213		.100000 x	1.840000 =	.184000
508		.005000 x	624.348824 =	3.121744
504		.005000 x	365.654582 =	1.828273
116		.200000 x	24.152261 =	4.830452
112		.100000 x	18.705943 =	1.870594
518		.010000 x	894.381585 =	8.943816
509		.005000 x	400.144061 =	2.000720

			B.T =	22.779600
625	625			
213		.100000 x	1.840000 =	.184000
116		.200000 x	24.152261 =	4.830452
112		.100000 x	18.705943 =	1.870594
504		.005000 x	365.654582 =	1.828273
509		.005000 x	400.144061 =	2.000720
518		.014300 x	894.381585 =	12.789657
508		.005000 x	624.348824 =	3.121744

			B.T =	26.625441
630	630			
512		.020000 x	101.317390 =	2.026348

			B.T =	2.026348
630.1	630.1			
510		.006000 x	390.178061 =	2.341068

			B.T =	2.341068

641	641			
231		.200000 x	.680000 =	.136000
251		.001500 x	290.000000 =	.435000
111		.200000 x	16.829739 =	3.365948
113		.150000 x	24.769248 =	3.715387
252		.002500 x	210.000000 =	.525000

			B.T =	8.177335
651	651			
221		150.000000 x	.097700 =	14.655000
111		1.500000 x	16.829739 =	25.244609
112		.500000 x	18.705943 =	9.352972
509		.003600 x	400.144061 =	1.440519
509		.011100 x	400.144061 =	4.441599
511		.050000 x	755.274249 =	37.763712
630		.600000 x	2.026348 =	1.215809
625		1.000000 x	26.625441 =	26.625441
224		120.000000 x	.070000 =	8.400000

			B.T =	129.139660
652	652			
221		650.000000 x	.097700 =	63.505000
509		.011000 x	400.144061 =	4.401585
630		.320000 x	2.026348 =	.648431
625		1.000000 x	26.625441 =	26.625441
511		.050000 x	755.274249 =	37.763712
509		.001920 x	400.144061 =	.768277
112		.500000 x	18.705943 =	9.352972
111		1.500000 x	16.829739 =	25.244609

			B.T =	168.310026
1121	1121			
112		.007000 x	18.705943 =	.130942
501		.000100 x	609.264308 =	.060926
503		.002000 x	898.790684 =	1.797581

			T.E =	1.989449
1122	1122			
112		.007000 x	18.705943 =	.130942
503		.000330 x	898.790684 =	.296601
501		.000080 x	609.264308 =	.048741
505		.000600 x	815.975186 =	.489585
507		.001400 x	942.654486 =	1.319716
509		.004447 x	400.144061 =	1.779441

			T.E =	4.065026

1123A	1123A			
112		.007000 x	18.705943 =	.130942
501		.000100 x	609.264308 =	.060926
503		.002000 x	898.790684 =	1.797581
509		.005312 x	400.144061 =	2.125565
506		.001330 x	716.314086 =	.952698

			T.E =	5.067712
1123B	1123B			
509		.001487 x	400.144061 =	.595014

			T.E =	.595014
1140	1140			
112		.010000 x	18.705943 =	.187059
521		.000200 x	441.571284 =	.088314
501		.000100 x	609.264308 =	.060926

			T.E =	.336300
1610	1610			
111		.050000 x	16.829739 =	.841487
1122		.200000 x	4.065026 =	.813005
507		.000200 x	942.654486 =	.188531
501		.000100 x	609.264308 =	.060926
502		.000200 x	797.760084 =	.159552

			T.E =	2.063501
1620	1620			
112		.250000 x	18.705943 =	4.676486
1122		1.000000 x	4.065026 =	4.065026
501		.002000 x	609.264308 =	1.218529

			T.E =	9.960040
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	16.829739 =	4.207435
501		.000100 x	609.264308 =	.060926

			T.E =	14.968361
2111	2111			
112		.010000 x	18.705943 =	.187059
509		.005202 x	400.144061 =	2.081549
507		.001540 x	942.654486 =	1.451688
502		.002000 x	797.760084 =	1.595520
501		.000830 x	609.264308 =	.505689

			T.E =	5.821506

2112	2112			
213		.400000 x	1.840000 =	.736000
502		.002900 x	797.760084 =	2.313504
112		.250000 x	18.705943 =	4.676486
116		.250000 x	24.152261 =	6.038065
507		.002000 x	942.654486 =	1.885309
509		.004896 x	400.144061 =	1.959105
508		.004000 x	624.348824 =	2.497395

			T.E =	20.105865
2251	2251			
111		.600000 x	16.829739 =	10.097843
621		1.050000 x	21.599988 =	22.679987
112		.600000 x	18.705943 =	11.223566
509		.012432 x	400.144061 =	4.974591

			T.E =	48.975988
2252	2252			
111		1.400000 x	16.829739 =	23.561635
621		1.050000 x	21.599988 =	22.679987
113		1.400000 x	24.769248 =	34.676947
509		.012432 x	400.144061 =	4.974591

			T.E =	85.893160
2253	2253			
111		1.500000 x	16.829739 =	25.244609
621		1.050000 x	21.599988 =	22.679987
652		.020000 x	168.310026 =	3.366201
651		.250000 x	129.139660 =	32.284915
509		.012432 x	400.144061 =	4.974591
113		2.500000 x	24.769248 =	61.923120
112		.200000 x	18.705943 =	3.741189

			T.E =	154.214611
2254	2254			
111		.800000 x	16.829739 =	13.463791
652		.100000 x	168.310026 =	16.831003
621		.350000 x	21.599988 =	7.559996
509		.003788 x	400.144061 =	1.515746
113		1.500000 x	24.769248 =	37.153872

			T.E =	76.524407

2522	2522			
221		300.000000 x	.097700 =	29.310000
112		1.400000 x	18.705943 =	26.188320
623		.800000 x	22.779600 =	18.223680
630		.250000 x	2.026348 =	.506587
641		3.000000 x	8.177335 =	24.532005
625		.500000 x	26.625441 =	13.312721
511		.040000 x	755.274249 =	30.210970
509		.008880 x	400.144061 =	3.553279
509		.001500 x	400.144061 =	.600216
509		.005550 x	400.144061 =	2.220800
113		1.600000 x	24.769248 =	39.630797

			T.E =	188.289374
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	188.289374 =	.941447
652		.002000 x	168.310026 =	.336620
113		.400000 x	24.769248 =	9.907699
111		.400000 x	16.829739 =	6.731896

			T.E =	21.977662
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	168.310026 =	2.019720
111		.600000 x	16.829739 =	10.097843
113		.800000 x	24.769248 =	19.815398

			T.E =	38.766962
5110	5110			
111		.100000 x	16.829739 =	1.682974

			T.E =	1.682974
5120	5120			
111		.080000 x	16.829739 =	1.346379

			T.E =	1.346379
5130	5130			
111		.050000 x	16.829739 =	.841487

			T.E =	.841487
5140	5140			
111		.030000 x	16.829739 =	.504892
550		.003750 x	388.704061 =	1.457640

			T.E =	1.962532

5150	5150				
111		.030000 x	16.829739 =		.504892
550		.002500 x	388.704061 =		.971760
			T.E =		1.476652
5160	5160				
213		.400000 x	1.840000 =		.736000
111		.160000 x	16.829739 =		2.692758
508		.001500 x	624.348824 =		.936523
			T.E =		4.365281
5210	5210				
363		.100000 x	.580000 =		.058000
112		.050000 x	18.705943 =		.935297
111		.040000 x	16.829739 =		.673190
			T.E =		1.666487
5220	5220				
363		.100000 x	.580000 =		.058000
112		.030000 x	18.705943 =		.561178
111		.020000 x	16.829739 =		.336595
			T.E =		.955773
5230	5230				
364		1.000000 x	3.520000 =		3.520000
112		.080000 x	18.705943 =		1.496475
			T.E =		5.016475
5240	5240				
112		.080000 x	18.705943 =		1.496475
			T.E =		1.496475
5311	5311				
111		.002000 x	16.829739 =		.033659
630.1		.020000 x	2.341068 =		.046821
510		.000250 x	390.178061 =		.097545
630		.020000 x	2.026348 =		.040527
			T.E =		.218552

5312	5312			
111		.001300 x	16.829739 =	.021879
630.1		.020000 x	2.341068 =	.046821
510		.000163 x	390.178061 =	.063599
630		.020000 x	2.026348 =	.040527

			T.E =	.172826
5321	5321			
111		.004000 x	16.829739 =	.067319

			T.E =	.067319
5322	5322			
111		.003300 x	16.829739 =	.055538

			T.E =	.055538
5330	5330			
111		.022200 x	16.829739 =	.373620

			T.E =	.373620
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	16.829739 =	.055538

			T.E =	.113538
5351	5351			
113		.005000 x	24.769248 =	.123846

			T.E =	.123846
5352	5352			
111		.005000 x	16.829739 =	.084149
113		.014000 x	24.769248 =	.346769

			T.E =	.430918
5353	5353			
111		.010000 x	16.829739 =	.168297
113		.020000 x	24.769248 =	.495385

			T.E =	.663682

5354	5354				
111		.035000 x	16.829739 =		.589041
113		.025000 x	24.769248 =		.619231

			T.E =		1.208272
5361A	5361A				
365		.003000 x	22.500000 =		.067500
630		.000300 x	2.026348 =		.000608
510		.000188 x	390.178061 =		.073353
113		.001500 x	24.769248 =		.037154

			T.E =		.178615
5361B	5361B				
366		.003000 x	20.630000 =		.061890
510		.000188 x	390.178061 =		.073353
630		.000300 x	2.026348 =		.000608
113		.001500 x	24.769248 =		.037154

			T.E =		.173005
5362A	5362A				
365		.005000 x	22.500000 =		.112500
630		.000500 x	2.026348 =		.001013
510		.000313 x	390.178061 =		.122126
113		.002500 x	24.769248 =		.061923

			T.E =		.297562
5362B	5362B				
366		.005000 x	20.630000 =		.103150
630		.000500 x	2.026348 =		.001013
510		.000313 x	390.178061 =		.122126
113		.002500 x	24.769248 =		.061923

			T.E =		.288212
5363A	5363A				
365		.003000 x	22.500000 =		.067500
113		.001000 x	24.769248 =		.024769
510		.000125 x	390.178061 =		.048772
630		.000300 x	2.026348 =		.000608

			T.E =		.141649

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	24.769248 =	.024769
630		.000300 x	2.026348 =	.000608
510		.000125 x	390.178061 =	.048772

			T.E =	.136039
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	24.769248 =	.044585
630		.000500 x	2.026348 =	.001013
510		.000225 x	390.178061 =	.087790

			T.E =	.245888
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	2.026348 =	.001013
510		.000225 x	390.178061 =	.087790
113		.001800 x	24.769248 =	.044585

			T.E =	.236538
5371	5371			
111		17.300000 x	16.829739 =	291.154485
111		9.600000 x	16.829739 =	161.565494

			T.E =	452.719979
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	390.178061 =	39.017806
630		.100000 x	2.026348 =	.202635
113		.800000 x	24.769248 =	19.815398

			T.E =	87.035839
5380	5380			
111		5.000000 x	16.829739 =	84.148695
550		.412500 x	388.704061 =	160.340425

			T.E =	244.489120
5390	5390			
111		.120000 x	16.829739 =	2.019569
111		.030000 x	16.829739 =	.504892

			T.E =	2.524461

5510	5510				
361		15.000000 x	27.500000 =	412.500000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	5.250000 =	157.500000	
550		.375000 x	388.704061 =	145.764023	
113		20.000000 x	24.769248 =	495.384960	
365		2.000000 x	22.500000 =	45.000000	
111		20.000000 x	16.829739 =	336.594780	

			T.E =	1,604.343763	
5521	5521				
111		1.000000 x	16.829739 =	16.829739	
630.1		10.000000 x	2.341068 =	23.410680	
510		.125000 x	390.178061 =	48.772258	
630		10.000000 x	2.026348 =	20.263480	

			T.E =	109.276157	
5522	5522				
111		1.500000 x	16.829739 =	25.244609	

			T.E =	25.244609	
5530	5530				
453		.187500 x	86.130000 =	16.149375	
111		1.000000 x	16.829739 =	16.829739	
111		1.000000 x	16.829739 =	16.829739	

			T.E =	49.808853	
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	16.829739 =	12.622304	

			T.E =	21.322304	
5551	5551				
111		2.000000 x	16.829739 =	33.659478	
111		1.000000 x	16.829739 =	16.829739	

			T.E =	50.489217	
5552	5552				
379		1.000000 x	14.000000 =	14.000000	
630		.100000 x	2.026348 =	.202635	
510		.050000 x	390.178061 =	19.508903	
113		.400000 x	24.769248 =	9.907699	

			T.E =	43.619237	

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	24.769248 =	19.815398
630		.100000 x	2.026348 =	.202635
510		.100000 x	390.178061 =	39.017806

			T.E =	81.535839
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	390.178061 =	39.017806
630		.100000 x	2.026348 =	.202635
113		.800000 x	24.769248 =	19.815398

			T.E =	79.665839
5570	5570			
111		.100000 x	16.829739 =	1.682974
111		.030000 x	16.829739 =	.504892

			T.E =	2.187866
5580	5580			
111		.020000 x	16.829739 =	.336595
111		.030000 x	16.829739 =	.504892

			T.E =	.841487
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	16.829739 =	504.892170
550		.125000 x	388.704061 =	48.588008
367		20,000.000000 x	.118700 =	2,374.000000

			T.E =	2,936.180178
5621	5621			
111		1.000000 x	16.829739 =	16.829739
630		10.000000 x	2.026348 =	20.263480
630.1		10.000000 x	2.341068 =	23.410680
510		.125000 x	390.178061 =	48.772258

			T.E =	109.276157
5622	5622			
111		1.500000 x	16.829739 =	25.244609

			T.E =	25.244609

5630	5630			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	16.829739 =	12.622304

			T.E =	21.322304
5640	5640			
111		10.000000 x	16.829739 =	168.297390
111		2.000000 x	16.829739 =	33.659478

			T.E =	201.956868
5650	5650			
111		.120000 x	16.829739 =	2.019569
111		.030000 x	16.829739 =	.504892

			T.E =	2.524461
5710	5710			
362		40.000000 x	5.250000 =	210.000000
111		5.000000 x	16.829739 =	84.148695
112		1.000000 x	18.705943 =	18.705943
560		.125000 x	729.033061 =	91.129133
510		.125000 x	390.178061 =	48.772258
509		.125000 x	400.144061 =	50.018008
114		1.000000 x	23.989407 =	23.989407
380		800.000000 x	.260000 =	208.000000
363		15.000000 x	.580000 =	8.700000
377		250.000000 x	3.190000 =	797.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,594.963443
5720	5720			
111		.500000 x	16.829739 =	8.414870
510		.062500 x	390.178061 =	24.386129
630		10.000000 x	2.026348 =	20.263480
630.1		10.000000 x	2.341068 =	23.410680

			T.E =	76.475158
5730	5730			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	16.829739 =	12.622304

			T.E =	21.322304