

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

2ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.152800
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.023100
212	1.245400
213	1.949500
214	3.930000
221	.099900
224	.070000
231	.775000
241	7.050000
242	5.000000
251	290.000000
252	270.000000
301	4.060000
302	6.700000
360	10.700000
361	27.500000
362	3.500000
363	.580000
364	3.520000
365	22.500000
366	20.630000
367	.118700
368	20.000000
369	12.150000
370	8.000000
371	7.200000
372	1.270000
373	2.040000
374	2.750000
375	1.500000
376	
377	3.190000
378	.540000
379	14.000000
380	.260000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
417	130.670000

420	94.500000
428	425.280000
450	111.820000
451	154.970000
452	94.950000
453	88.120000
454	119.120000
455	420.570000

501	501				
211		50.000000 x	1.023100 =	51.155000	
214		3.000000 x	3.930000 =	11.790000	
401		1.000000 x	260.720000 =	260.720000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	544.757593

				Η.Δ. =	599.233352
502	502				
211		80.000000 x	1.023100 =	81.848000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.930000 =	27.510000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	709.721612

				Η.Δ. =	780.693773
503	503				
211		110.000000 x	1.023100 =	112.541000	
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.930000 =	39.300000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	808.214612

				Η.Δ. =	889.036073
504	504				
211		40.000000 x	1.023100 =	40.924000	
214		2.000000 x	3.930000 =	7.860000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	100.390000 =	100.390000	

				ΑΘΡΟΙΣΜΑ =	340.263536

				Η.Δ. =	374.289890
505	505				
211		200.000000 x	1.023100 =	204.620000	
214		10.000000 x	3.930000 =	39.300000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	206.630000 =	206.630000	

				ΑΘΡΟΙΣΜΑ =	721.647688

				Η.Δ. =	793.812457

506	506				
211		95.000000 x	1.023100 =		97.194500
214		6.000000 x	3.930000 =		23.580000
405		1.000000 x	200.790000 =		200.790000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
				ΑΘΡΟΙΣΜΑ =	605.162188
				Η.Δ. =	665.678407
507	507				
211		165.000000 x	1.023100 =		168.811500
214		10.000000 x	3.930000 =		39.300000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	311.770000 =		311.770000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				ΑΘΡΟΙΣΜΑ =	825.979188
				Η.Δ. =	908.577107
508	508				
211		40.000000 x	1.023100 =		40.924000
407		1.000000 x	53.630000 =		53.630000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.400000 =		8.800000
214		2.000000 x	3.930000 =		7.860000
				ΑΘΡΟΙΣΜΑ =	525.039484
				Η.Δ. =	577.543432
509	509				
211		80.000000 x	1.023100 =		81.848000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	122.460000 =		122.460000
214		5.000000 x	3.930000 =		19.650000
				ΑΘΡΟΙΣΜΑ =	358.181336
				Η.Δ. =	393.999470
510	510				
211		80.000000 x	1.023100 =		81.848000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	3.930000 =		19.650000
410		1.000000 x	113.190000 =		113.190000
				ΑΘΡΟΙΣΜΑ =	348.911336
				Η.Δ. =	383.802470

511	511				
212		17.000000 x	1.245400 =	21.171800	
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.930000 =	3.930000	
115		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	

				ΑΘΡΟΙΣΜΑ =	658.158868

				Η.Δ. =	723.974755
512	512				
211		10.000000 x	1.023100 =	10.231000	
115		2.000000 x	21.778427 =	43.556854	
214		1.000000 x	3.930000 =	3.930000	
112		2.000000 x	17.312112 =	34.624224	
412		1.000000 x	2.900000 =	2.900000	

				ΑΘΡΟΙΣΜΑ =	95.242078

				Η.Δ. =	104.766286
518	518				
211		180.000000 x	1.023100 =	184.158000	
212		5.000000 x	1.245400 =	6.227000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
417		1.000000 x	130.670000 =	130.670000	
214		12.000000 x	3.930000 =	47.160000	

				ΑΘΡΟΙΣΜΑ =	777.809584

				Η.Δ. =	855.590542
521	521				
211		40.000000 x	1.023100 =	40.924000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	
420		1.000000 x	94.500000 =	94.500000	

				ΑΘΡΟΙΣΜΑ =	378.307612

				Η.Δ. =	416.138373
550	550				
211		80.000000 x	1.023100 =	81.848000	
214		5.000000 x	3.930000 =	19.650000	
117		8.000000 x	16.777917 =	134.223336	
450		1.000000 x	111.820000 =	111.820000	

				ΑΘΡΟΙΣΜΑ =	347.541336

				Η.Δ. =	382.295470

560	560				
211		80.000000 x	1.023100 =	81.848000	
117		8.000000 x	16.777917 =	134.223336	
455		1.000000 x	420.570000 =	420.570000	
214		7.000000 x	3.930000 =	27.510000	
			ΑΘΡΟΙΣΜΑ =	664.151336	
			H.Δ. =	730.566470	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	577.543432 =	2.887717	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.759843	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	577.543432 =	2.887717	
504		.005000 x	374.289890 =	1.871449	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	855.590542 =	8.555905	
509		.005000 x	393.999470 =	1.969997	
			B.T =	21.295128	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	374.289890 =	1.871449	
509		.005000 x	393.999470 =	1.969997	
518		.014300 x	855.590542 =	12.234945	
508		.005000 x	577.543432 =	2.887717	
			B.T =	24.974167	
630	630				
512		.020000 x	104.766286 =	2.095326	
			B.T =	2.095326	
630.1	630.1				
510		.006000 x	383.802470 =	2.302815	
			B.T =	2.302815	

641	641			
231		.200000 x	.775000 =	.155000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	270.000000 =	.675000

			B.T =	7.476243
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	393.999470 =	1.418398
509		.011100 x	393.999470 =	4.373394
511		.050000 x	723.974755 =	36.198738
630		.600000 x	2.095326 =	1.257196
625		1.000000 x	24.974167 =	24.974167
224		120.000000 x	.070000 =	8.400000

			B.T =	123.875346
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	393.999470 =	4.333994
630		.320000 x	2.095326 =	.670504
625		1.000000 x	24.974167 =	24.974167
511		.050000 x	723.974755 =	36.198738
509		.001920 x	393.999470 =	.756479
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	164.137335
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	599.233352 =	.059923
503		.002000 x	889.036073 =	1.778072

			T.E =	1.959180
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	889.036073 =	.293382
501		.000080 x	599.233352 =	.047939
505		.000600 x	793.812457 =	.476287
507		.001400 x	908.577107 =	1.272008
509		.004447 x	393.999470 =	1.752116

			T.E =	3.962916

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	599.233352 =	.059923
503		.002000 x	889.036073 =	1.778072
509		.005312 x	393.999470 =	2.092925
506		.001330 x	665.678407 =	.885352

			T.E =	4.937458
1123B	1123B			
509		.001487 x	393.999470 =	.585877

			T.E =	.585877
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	416.138373 =	.083228
501		.000100 x	599.233352 =	.059923

			T.E =	.316272
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	3.962916 =	.792583
507		.000200 x	908.577107 =	.181715
501		.000100 x	599.233352 =	.059923
502		.000200 x	780.693773 =	.156139

			T.E =	1.977441
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	3.962916 =	3.962916
501		.002000 x	599.233352 =	1.198467

			T.E =	9.489411
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	599.233352 =	.059923

			T.E =	14.695323
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	393.999470 =	2.049585
507		.001540 x	908.577107 =	1.399209
502		.002000 x	780.693773 =	1.561388
501		.000830 x	599.233352 =	.497364

			T.E =	5.680666

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	780.693773 =	2.264012
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	908.577107 =	1.817154
509		.004896 x	393.999470 =	1.929021
508		.004000 x	577.543432 =	2.310174

			T.E =	18.533061
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.759843 =	20.747835
112		.600000 x	17.312112 =	10.387267
509		.012432 x	393.999470 =	4.898201

			T.E =	45.478263
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.759843 =	20.747835
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	393.999470 =	4.898201

			T.E =	76.271554
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.759843 =	20.747835
652		.020000 x	164.137335 =	3.282747
651		.250000 x	123.875346 =	30.968837
509		.012432 x	393.999470 =	4.898201
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.021154
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	164.137335 =	16.413734
621		.350000 x	19.759843 =	6.915945
509		.003788 x	393.999470 =	1.492470
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.044656

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.295128 =	17.036102
630		.250000 x	2.095326 =	.523832
641		3.000000 x	7.476243 =	22.428729
625		.500000 x	24.974167 =	12.487084
511		.040000 x	723.974755 =	28.958990
509		.008880 x	393.999470 =	3.498715
509		.001500 x	393.999470 =	.590999
509		.005550 x	393.999470 =	2.186697
113		1.600000 x	20.419486 =	32.671178

			T.E =	174.589283
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	174.589283 =	.872946
652		.002000 x	164.137335 =	.328275
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.725655
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	164.137335 =	1.969648
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.584196
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	382.295470 =	1.433608

			T.E =	1.905856

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	382.295470 =	.955739

			T.E =	1.427987
5160	5160			
213		.400000 x	1.949500 =	.779800
111		.160000 x	15.741598 =	2.518656
508		.001500 x	577.543432 =	.866315

			T.E =	4.164771
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.553270
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.892195
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	17.312112 =	1.384969

			T.E =	4.904969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.302815 =	.046056
510		.000250 x	383.802470 =	.095951
630		.020000 x	2.095326 =	.041907

			T.E =	.215397

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.302815 =	.046056
510		.000163 x	383.802470 =	.062560
630		.020000 x	2.095326 =	.041907

			T.E =	.170987
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	15.741598 =	.051947

			T.E =	.109947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354				
111		.035000 x	15.741598 =		.550956
113		.025000 x	20.419486 =		.510487

			T.E =		1.061443
5361A	5361A				
365		.003000 x	22.500000 =		.067500
630		.000300 x	2.095326 =		.000629
510		.000188 x	383.802470 =		.072155
113		.001500 x	20.419486 =		.030629

			T.E =		.170913
5361B	5361B				
366		.003000 x	20.630000 =		.061890
510		.000188 x	383.802470 =		.072155
630		.000300 x	2.095326 =		.000629
113		.001500 x	20.419486 =		.030629

			T.E =		.165303
5362A	5362A				
365		.005000 x	22.500000 =		.112500
630		.000500 x	2.095326 =		.001048
510		.000313 x	383.802470 =		.120130
113		.002500 x	20.419486 =		.051049

			T.E =		.284727
5362B	5362B				
366		.005000 x	20.630000 =		.103150
630		.000500 x	2.095326 =		.001048
510		.000313 x	383.802470 =		.120130
113		.002500 x	20.419486 =		.051049

			T.E =		.275377
5363A	5363A				
365		.003000 x	22.500000 =		.067500
113		.001000 x	20.419486 =		.020419
510		.000125 x	383.802470 =		.047975
630		.000300 x	2.095326 =		.000629

			T.E =		.136523

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.095326 =	.000629
510		.000125 x	383.802470 =	.047975

			T.E =	.130913
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.095326 =	.001048
510		.000225 x	383.802470 =	.086356

			T.E =	.236658
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	2.095326 =	.001048
510		.000225 x	383.802470 =	.086356
113		.001800 x	20.419486 =	.036755

			T.E =	.227308
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	383.802470 =	38.380247
630		.100000 x	2.095326 =	.209533
113		.800000 x	20.419486 =	16.335589

			T.E =	82.925368
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	382.295470 =	157.696881

			T.E =	236.404871
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	27.500000 =	412.500000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	3.500000 =	105.000000	
550		.375000 x	382.295470 =	143.360801	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	22.500000 =	45.000000	
111		20.000000 x	15.741598 =	314.831960	

				T.E =	1,440.682481
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.302815 =	23.028150	
510		.125000 x	383.802470 =	47.975309	
630		10.000000 x	2.095326 =	20.953260	

				T.E =	107.698317
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

				T.E =	23.612397
5530	5530				
453		.187500 x	88.120000 =	16.522500	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	48.005696
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

				T.E =	20.506199
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	47.224794
5552	5552				
379		1.000000 x	14.000000 =	14.000000	
630		.100000 x	2.095326 =	.209533	
510		.050000 x	383.802470 =	19.190124	
113		.400000 x	20.419486 =	8.167794	

				T.E =	41.567451

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.095326 =	.209533
510		.100000 x	383.802470 =	38.380247
			T.E =	77.425368
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	383.802470 =	38.380247
630		.100000 x	2.095326 =	.209533
113		.800000 x	20.419486 =	16.335589
			T.E =	75.555368
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248
			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248
			T.E =	.787080
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	382.295470 =	47.786934
367		20,000.000000 x	.118700 =	2,374.000000
			T.E =	2,902.734874
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.095326 =	20.953260
630.1		10.000000 x	2.302815 =	23.028150
510		.125000 x	383.802470 =	47.975309
			T.E =	107.698317
5622	5622			
111		1.500000 x	15.741598 =	23.612397
			T.E =	23.612397

5630	5630				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	
5640	5640				
111		10.000000 x	15.741598 =	157.415980	
111		2.000000 x	15.741598 =	31.483196	

			T.E =	188.899176	
5650	5650				
111		.120000 x	15.741598 =	1.888992	
111		.030000 x	15.741598 =	.472248	

			T.E =	2.361240	
5710	5710				
362		40.000000 x	3.500000 =	140.000000	
111		5.000000 x	15.741598 =	78.707990	
112		1.000000 x	17.312112 =	17.312112	
560		.125000 x	730.566470 =	91.320809	
510		.125000 x	383.802470 =	47.975309	
509		.125000 x	393.999470 =	49.249934	
114		1.000000 x	23.886192 =	23.886192	
380		800.000000 x	.260000 =	208.000000	
363		15.000000 x	.580000 =	8.700000	
377		250.000000 x	3.190000 =	797.500000	
378		100.000000 x	.540000 =	54.000000	

			T.E =	1,516.652345	
5720	5720				
111		.500000 x	15.741598 =	7.870799	
510		.062500 x	383.802470 =	23.987654	
630		10.000000 x	2.095326 =	20.953260	
630.1		10.000000 x	2.302815 =	23.028150	

			T.E =	75.839863	
5730	5730				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.506199	