

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών Έργων

1ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
026	.098900
036	.107500
273	.922500
297.1	2.000000
510	3.020000
511	.620000
513	1.150000
561	2.210000
565.3	3.450000
566.3	4.600000
567.13	18.120000
571.5.1	2.070000
572.1.7	3.860000
575.3	
581.2	9.090000
582.2	23.250000
588.3	
603.3	4.890000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	61.600000
630.1.2	305.000000
634.1.1	87.500000
647.2	19.000000
660.1.1	20.340000
667	139.000000
671.3.8	3,820.000000
672.4.6	4,650.000000
673.1.5	4,870.000000
684.6.2	106.000000
686.1	410.000000
687.1.1	2,300.000000
703.2.2	24.400000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,060.000000
719.1.3	1,000.000000
720.11	7.000000
729.1.2	930.000000
730.2.5	1.850000
732.5.30	69.700000
744.9	66,700.000000
755.10	12,640.000000
757.1.4	16,660.000000
760.1.4	4,420.000000
801.3.2	.187200
801.7.1	1.610000
812.1.2	.109700
812.2.3	1.215100
813.2.3	1.875300
816.3.2	.672000
820.5.1	.550400
820.5.4	2.005700
825.6.1	.381700
826.2.1	1.610000

835.1.2	71.700000
841.3.5	183.000000
842.3.2	77.500000
848.1.2	32.600000
852.1.6	948.000000
855.1.13	2,732.000000
858.1.2	3.060000
859.1.2	4.480000
865.13.10	18,000.000000
865.13.9	15,600.000000
865.8.3	39.000000
867.1.22	75,800.000000
871.7.4	47.160000
872.23.1	4.190000
880.1.2	.740000
885.1.2	18.000000
890.1.1	108.000000
910.2.5	8,100.000000
911.1.17	3,290.000000
912.1.5	3,059.000000
913.1.9	64.800000
914.1.8	114.000000
915.1.6	300.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,300.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,300.000000
931.1.5	360.000000
931.2.4	970.000000
932.4.2	348.000000
933.1.1	14.400000
934.1.1	322.000000
935.1.1	73.540000
950.1.1	4.100000
951.1.7	600.000000
951.2.2	12,340.000000
952.1.4	335.000000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.098900 =	.108790	
297.1		1.200000 x	2.000000 =	2.400000	
582.2		1.300000 x	23.250000 =	30.225000	
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	

				T.E =	81.784867
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	20.419486 =	6.125846	
001		.300000 x	15.741598 =	4.722479	

				T.E =	21.756325
100	100				
931.1.5		1.000000 x	360.000000 =	360.000000	
003		4.000000 x	20.419486 =	81.677944	
002		6.000000 x	17.312112 =	103.872672	

				T.E =	545.550616
101	101				
931.2.4		1.000000 x	970.000000 =	970.000000	
002		9.000000 x	17.312112 =	155.809008	
003		6.000000 x	20.419486 =	122.516916	

				T.E =	1,248.325924
102	102				
820.5.4		1.020000 x	2.005700 =	2.045814	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

				T.E =	9.592134
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	

				T.E =	442.328995
104	104				
933.1.1		1.000000 x	14.400000 =	14.400000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	

				T.E =	59.677918

105	105				
934.1.1		1.000000 x	322.000000 =	322.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	397.463196	
106	106				
951.1.7		1.030000 x	600.000000 =	618.000000	
002		4.000000 x	17.312112 =	69.248448	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	768.926392	
107	107				
952.1.4		1.030000 x	335.000000 =	345.050000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	382.781598	
108	108				
951.2.2		1.030000 x	12,340.000000 =	12,710.200000	
003		6.000000 x	20.419486 =	122.516916	
002		6.000000 x	17.312112 =	103.872672	

			T.E =	12,936.589588	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	

			T.E =	27,747.779176	
11	11				
603.3		1.030000 x	4.890000 =	5.036700	
003		.500000 x	20.419486 =	10.209743	

			T.E =	15.246443	
110	110				
950.1.1		1.050000 x	4.100000 =	4.305000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.851320	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	165.438959	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	61.030639	
14	14				
026		15.000000 x	.098900 =	1.483500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	149.946696	
15	15				
621.1		1.000000 x	61.600000 =	61.600000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
621.1		.100000 x	61.600000 =	6.160000	

			T.E =	143.223196	
16	16				
630.1.2		1.000000 x	305.000000 =	305.000000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	
630.1.2		.050000 x	305.000000 =	15.250000	

			T.E =	433.444794	
17	17				
634.1.1		1.200000 x	87.500000 =	105.000000	
003		2.000000 x	20.419486 =	40.838972	
002		.200000 x	17.312112 =	3.462422	
634.1.1		.050000 x	87.500000 =	4.375000	

			T.E =	153.676394	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	23.083897	

19	19				
660.1.1		1.030000 x	20.340000 =	20.950200	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	28.496520	
2	2				
561		5.320000 x	2.210000 =	11.757200	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	

			T.E =	34.396159	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	292.706392	
21	21				
671.3.8		1.000000 x	3,820.000000 =	3,820.000000	
671.3.8		.100000 x	3,820.000000 =	382.000000	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	

			T.E =	4,956.631960	
22	22				
672.4.6		1.000000 x	4,650.000000 =	4,650.000000	
672.4.6		.100000 x	4,650.000000 =	465.000000	
003		20.000000 x	20.419486 =	408.389720	
002		20.000000 x	17.312112 =	346.242240	

			T.E =	5,869.631960	
23	23				
673.1.5		1.000000 x	4,870.000000 =	4,870.000000	
003		25.000000 x	20.419486 =	510.487150	
002		25.000000 x	17.312112 =	432.802800	
687.1.1		1.000000 x	2,300.000000 =	2,300.000000	
687.1.1		.020000 x	2,300.000000 =	46.000000	
673.1.5		.020000 x	4,870.000000 =	97.400000	

			T.E =	8,256.689950	

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	20.419486 =	20.419486	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	145.851598	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	569.126392	
26	26				
703.2.2		1.020000 x	24.400000 =	24.888000	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

			T.E =	34.320900	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	20.419486 =	204.194860	
002		10.000000 x	17.312112 =	173.121120	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.741598 =	78.707990	

			T.E =	5,698.823970	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	
001		6.000000 x	15.741598 =	94.449588	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,747.188764	
29	29				
718.3.3		1.000000 x	1,060.000000 =	1,060.000000	
002		8.000000 x	17.312112 =	138.496896	
718.3.3		.050000 x	1,060.000000 =	53.000000	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	1,414.852784	

3	3			
026		1.200000 x	.098900 =	.118680
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534

T.E =

30	30			
719.1.3		1.000000 x	1,000.000000 =	1,000.000000
719.1.3		.100000 x	1,000.000000 =	100.000000
003		16.000000 x	20.419486 =	326.711776
002		16.000000 x	17.312112 =	276.993792
001		8.000000 x	15.741598 =	125.932784

T.E = 1,829.638352

31	31			
720.11		1.020000 x	7.000000 =	7.140000
003		.300000 x	20.419486 =	6.125846

T.E = 13.265846

32	32			
729.1.2		1.000000 x	930.000000 =	930.000000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
729.1.2		.030000 x	930.000000 =	27.900000

T.E = 1,033.363196

33	33			
757.1.4		1.000000 x	16,660.000000 =	16,660.000000
757.1.4		.050000 x	16,660.000000 =	833.000000
002		15.000000 x	17.312112 =	259.681680
003		15.000000 x	20.419486 =	306.292290
001		7.000000 x	15.741598 =	110.191186

T.E = 18,169.165156

34	34			
273		1.000000 x	.922500 =	.922500
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
273		.100000 x	.922500 =	.092250

T.E = 12.334229

35	35				
730.2.5		1.050000 x	1.850000 =	1.942500	
003		.120000 x	20.419486 =	2.450338	
002		.120000 x	17.312112 =	2.077453	
730.2.5		.250000 x	1.850000 =	.462500	

			T.E =	6.932792	
36	36				
732.5.30		1.050000 x	69.700000 =	73.185000	
003		.400000 x	20.419486 =	8.167794	
002		.400000 x	17.312112 =	6.924845	

			T.E =	88.277639	
37	37				
744.9		1.000000 x	66,700.000000 =	66,700.000000	
744.9		.020000 x	66,700.000000 =	1,334.000000	
001		10.000000 x	15.741598 =	157.415980	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	

			T.E =	68,946.047940	
38	38				
755.10		1.000000 x	12,640.000000 =	12,640.000000	
755.10		.020000 x	12,640.000000 =	252.800000	
001		10.000000 x	15.741598 =	157.415980	
002		10.000000 x	17.312112 =	173.121120	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	13,427.531960	
39	39				
760.1.4		1.000000 x	4,420.000000 =	4,420.000000	
760.1.4		.050000 x	4,420.000000 =	221.000000	
002		3.500000 x	17.312112 =	60.592392	
003		3.500000 x	20.419486 =	71.468201	

			T.E =	4,773.060593	
4	4				
565.3		1.250000 x	3.450000 =	4.312500	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	26.951459	

40	40				
036		3.000000 x	.107500 =	.322500	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	
510		.350000 x	3.020000 =	1.057000	
511		.250000 x	.620000 =	.155000	
513		.250000 x	1.150000 =	.287500	

			T.E =	18.801219	
41	41				
801.3.2		1.050000 x	.187200 =	.196560	
003		.100000 x	20.419486 =	2.041949	
801.3.2		.105000 x	.187200 =	.019656	
002		.100000 x	17.312112 =	1.731211	

			T.E =	3.989376	
42	42				
801.7.1		1.050000 x	1.610000 =	1.690500	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
801.7.1		.210000 x	1.610000 =	.338100	

			T.E =	9.574920	
43	43				
812.1.2		1.050000 x	.109700 =	.115185	
003		.020000 x	20.419486 =	.408390	
002		.020000 x	17.312112 =	.346242	

			T.E =	.869817	
44	44				
812.2.3		1.050000 x	1.215100 =	1.275855	
003		.060000 x	20.419486 =	1.225169	
002		.060000 x	17.312112 =	1.038727	

			T.E =	3.539751	
45	45				
813.2.3		1.050000 x	1.875300 =	1.969065	
813.2.3		.105000 x	1.875300 =	.196907	
003		.050000 x	20.419486 =	1.020974	
002		.050000 x	17.312112 =	.865606	

			T.E =	4.052551	

46	46				
816.3.2		1.050000 x	.672000 =	.705600	
816.3.2		.157500 x	.672000 =	.105840	
002		.120000 x	17.312112 =	2.077453	
003		.120000 x	20.419486 =	2.450338	

			T.E =	5.339232	
47	47				
820.5.1		1.050000 x	.550400 =	.577920	
820.5.1		.157500 x	.550400 =	.086688	
003		.140000 x	20.419486 =	2.858728	
002		.140000 x	17.312112 =	2.423696	

			T.E =	5.947032	
48	48				
825.6.1		1.050000 x	.381700 =	.400785	
003		.100000 x	20.419486 =	2.041949	
002		.100000 x	17.312112 =	1.731211	
825.6.1		.157500 x	.381700 =	.060118	

			T.E =	4.234063	
49	49				
826.2.1		1.000000 x	1.610000 =	1.610000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	5.693897	
5	5				
566.3		1.250000 x	4.600000 =	5.750000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	28.388959	
50	50				
842.3.2		1.000000 x	77.500000 =	77.500000	
842.3.2		.030000 x	77.500000 =	2.325000	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	

			T.E =	98.690799	
51	51				
841.3.5		1.000000 x	183.000000 =	183.000000	
841.3.5		.030000 x	183.000000 =	5.490000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	226.221598	

52	52				
835.1.2		1.050000 x	71.700000 =	75.285000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	

			T.E =	188.479794	
53	53				
848.1.2		1.020000 x	32.600000 =	33.252000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	37.335897	
54	54				
858.1.2		1.020000 x	3.060000 =	3.121200	
003		.200000 x	20.419486 =	4.083897	

			T.E =	7.205097	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.653497	
56	56				
865.8.3		1.050000 x	39.000000 =	40.950000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	116.413196	
57	57				
865.13.9		1.020000 x	15,600.000000 =	15,912.000000	
002		25.000000 x	17.312112 =	432.802800	
003		25.000000 x	20.419486 =	510.487150	
001		10.000000 x	15.741598 =	157.415980	

			T.E =	17,012.705930	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.312112 =	2,250.574560	
003		130.000000 x	20.419486 =	2,654.533180	
001		130.000000 x	15.741598 =	2,046.407740	

			T.E =	85,025.515480	

59	59				
871.7.4		1.000000 x	47.160000 =	47.160000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
871.7.4		.020000 x	47.160000 =	.943200	

			T.E =	93.381118	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	61.287598	
60	60				
872.23.1		1.020000 x	4.190000 =	4.273800	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
880.1.2		1.000000 x	.740000 =	.740000	

			T.E =	27.652759	
61	61				
885.1.2		1.000000 x	18.000000 =	18.000000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	40.638959	
62	62				
890.1.1		1.000000 x	108.000000 =	108.000000	
890.1.1		.050000 x	108.000000 =	5.400000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	188.863196	
63	63				
910.2.5		1.000000 x	8,100.000000 =	8,100.000000	
002		50.000000 x	17.312112 =	865.605600	
001		30.000000 x	15.741598 =	472.247940	
003		50.000000 x	20.419486 =	1,020.974300	
910.2.5		.020000 x	8,100.000000 =	162.000000	

			T.E =	10,620.827840	

7	7				
571.5.1		1.400000 x	2.070000 =	2.898000	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	

			T.E =	14.217479	
8	8				
572.1.7		1.350000 x	3.860000 =	5.211000	
002		.700000 x	17.312112 =	12.118478	
003		.700000 x	20.419486 =	14.293640	

			T.E =	31.623119	
80	80				
911.1.17		1.050000 x	3,290.000000 =	3,454.500000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	4,586.447940	
81	81				
912.1.5		1.050000 x	3,059.000000 =	3,211.950000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	4,343.897940	
82	82				
913.1.9		1.200000 x	64.800000 =	77.760000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	228.686392	
83	83				
914.1.8		1.100000 x	114.000000 =	125.400000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	200.863196	
84	84				
915.1.6		1.050000 x	300.000000 =	315.000000	
002		8.000000 x	17.312112 =	138.496896	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	616.852784	

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	17.312112 =	346.242240
003		20.000000 x	20.419486 =	408.389720

T.E = 14,510.681960

86	86			
865.13.10		1.020000 x	18,000.000000 =	18,360.000000
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480

T.E = 19,869.263920

87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	20.419486 =	2,450.338320
002		120.000000 x	17.312112 =	2,077.453440

T.E =

88	88			
917.1		.030000 x	7,300.000000 =	219.000000
917.1		1.000000 x	7,300.000000 =	7,300.000000
918.1.1		.030000 x	2,010.000000 =	60.300000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
923.1.1		1.000000 x	61.620000 =	61.620000
003		40.000000 x	20.419486 =	816.779440
002		40.000000 x	17.312112 =	692.484480
923.2.1		1.000000 x	161.400000 =	161.400000
923.2.1		.030000 x	161.400000 =	4.842000
923.1.1		.030000 x	61.620000 =	1.848600
920.1.1		.030000 x	7,479.000000 =	224.370000
918.1.1		1.000000 x	2,010.000000 =	2,010.000000

T.E = 19,031.644520

89	89			
852.1.6		.020000 x	948.000000 =	18.960000
855.1.13		1.000000 x	2,732.000000 =	2,732.000000
855.1.13		.020000 x	2,732.000000 =	54.640000
925.1.1		1.000000 x	4,300.000000 =	4,300.000000
003		60.000000 x	20.419486 =	1,225.169160
002		60.000000 x	17.312112 =	1,038.726720
925.1.1		.020000 x	4,300.000000 =	86.000000
852.1.6		1.000000 x	948.000000 =	948.000000

T.E = 10,403.495880

9

9

575.3
003
002

1.200000 x
.300000 x
.300000 x

.000000 =
20.419486 =
17.312112 =

.000000
6.125846
5.193634

T.E =