

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών

1ο Τρίμηνο του 2012

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.243100
212	1.434100
213	4.550000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.558700
252	2.184000
253	4.500000
254	4.500000
255	.905900
256	4.300000
261	
262	.980000
263	.640000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401			
211		110.000000 x	1.243100 =	136.741000
311		1.000000 x	437.840000 =	437.840000
213		10.000000 x	4.550000 =	45.500000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	851.174612

			Η.Δ. =	936.292073
402	402			
211		180.000000 x	1.243100 =	223.758000
213		12.000000 x	4.550000 =	54.600000
117		8.000000 x	10.001019 =	80.008152
116		8.000000 x	23.886192 =	191.089536
112		8.000000 x	17.312112 =	138.496896
312		1.000000 x	134.530000 =	134.530000
212		5.000000 x	1.434100 =	7.170500

			ΑΘΡΟΙΣΜΑ =	829.653084

			Η.Δ. =	912.618392
403	403			
211		80.000000 x	1.243100 =	99.448000
254		2.500000 x	4.500000 =	11.250000
213		6.000000 x	4.550000 =	27.300000
116		8.000000 x	23.886192 =	191.089536
117		8.000000 x	10.001019 =	80.008152
313		1.000000 x	206.720000 =	206.720000

			ΑΘΡΟΙΣΜΑ =	615.815688

			Η.Δ. =	677.397257
404	404			
211		80.000000 x	1.243100 =	99.448000
212		2.000000 x	1.434100 =	2.868200
118		8.000000 x	21.778427 =	174.227416
119		4.000000 x	10.001019 =	40.004076
314		1.000000 x	4.530000 =	4.530000
112		4.000000 x	17.312112 =	69.248448
213		5.000000 x	4.550000 =	22.750000

			ΑΘΡΟΙΣΜΑ =	413.076140

			Η.Δ. =	454.383754

405	405			
211		40.000000 x	1.243100 =	49.724000
213		2.000000 x	4.550000 =	9.100000
118		4.000000 x	21.778427 =	87.113708
115		16.000000 x	20.419486 =	326.711776
316		2.000000 x	4.530000 =	9.060000
315		1.000000 x	55.210000 =	55.210000

			ΑΘΡΟΙΣΜΑ =	536.919484

			Η.Δ. =	590.611432
406	406			
211		80.000000 x	1.243100 =	99.448000
213		5.000000 x	4.550000 =	22.750000
317		1.000000 x	126.080000 =	126.080000
120		8.000000 x	16.777917 =	134.223336

			ΑΘΡΟΙΣΜΑ =	382.501336

			Η.Δ. =	420.751470
407	407			
212		17.000000 x	1.434100 =	24.379700
112		30.000000 x	17.312112 =	519.363360
118		4.000000 x	21.778427 =	87.113708
213		1.000000 x	4.550000 =	4.550000
318		1.000000 x	27.370000 =	27.370000

			ΑΘΡΟΙΣΜΑ =	662.776768

			Η.Δ. =	729.054445
408	408			
211		30.000000 x	1.243100 =	37.293000
320		1.000000 x	156.740000 =	156.740000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
213		3.000000 x	4.550000 =	13.650000

			ΑΘΡΟΙΣΜΑ =	508.025060

			Η.Δ. =	558.827566
409	409			
211		50.000000 x	1.243100 =	62.155000
213		5.000000 x	4.550000 =	22.750000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
324		1.000000 x	185.200000 =	185.200000

			ΑΘΡΟΙΣΜΑ =	570.447060

			Η.Δ. =	627.491766

410	410			
211		100.000000 x	1.243100 =	124.310000
213		10.000000 x	4.550000 =	45.500000
321		1.000000 x	213.360000 =	213.360000
116		8.000000 x	23.886192 =	191.089536
117		4.000000 x	10.001019 =	40.004076
112		4.000000 x	17.312112 =	69.248448

			ΑΘΡΟΙΣΜΑ =	683.512060

			Η.Δ. =	751.863266
411	411			
211		200.000000 x	1.243100 =	248.620000
325		1.000000 x	317.230000 =	317.230000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
213		20.000000 x	4.550000 =	91.000000

			ΑΘΡΟΙΣΜΑ =	957.192060

			Η.Δ. =	1,052.911266
412	412			
211		40.000000 x	1.243100 =	49.724000
116		8.000000 x	23.886192 =	191.089536
326		1.000000 x	103.360000 =	103.360000
213		2.000000 x	4.550000 =	9.100000

			ΑΘΡΟΙΣΜΑ =	353.273536

			Η.Δ. =	388.600890
413	413			
211		15.000000 x	1.243100 =	18.646500
213		1.500000 x	4.550000 =	6.825000
118		3.000000 x	21.778427 =	65.335281
112		3.000000 x	17.312112 =	51.936336
327		1.000000 x	4.530000 =	4.530000

			ΑΘΡΟΙΣΜΑ =	147.273117

			Η.Δ. =	162.000429
501	501			
211		170.000000 x	1.243100 =	211.327000
213		3.000000 x	4.550000 =	13.650000
351		1.000000 x	451.770000 =	451.770000
380		1.000000 x	568.910000 =	568.910000

			ΑΘΡΟΙΣΜΑ =	1,245.657000

			Η.Δ. =	1,370.222700

502	502				
211		170.000000 x	1.243100 =	211.327000	
213		3.000000 x	4.550000 =	13.650000	
381		1.000000 x	568.910000 =	568.910000	
352		1.000000 x	383.570000 =	383.570000	
			ΑΘΡΟΙΣΜΑ =	1,177.457000	
			Η.Δ. =	1,295.202700	
503	503				
211		170.000000 x	1.243100 =	211.327000	
382		1.000000 x	568.910000 =	568.910000	
353		1.000000 x	451.770000 =	451.770000	
213		3.000000 x	4.550000 =	13.650000	
			ΑΘΡΟΙΣΜΑ =	1,245.657000	
			Η.Δ. =	1,370.222700	
504	504				
211		190.000000 x	1.243100 =	236.189000	
213		6.000000 x	4.550000 =	27.300000	
354		1.000000 x	592.710000 =	592.710000	
383		1.000000 x	654.300000 =	654.300000	
			ΑΘΡΟΙΣΜΑ =	1,510.499000	
			Η.Δ. =	1,661.548900	
505	505				
211		1,250.000000 x	1.243100 =	1,553.875000	
213		7.500000 x	4.550000 =	34.125000	
384		1.000000 x	1,083.720000 =	1,083.720000	
355		1.000000 x	296.440000 =	296.440000	
			ΑΘΡΟΙΣΜΑ =	2,968.160000	
			Η.Δ. =	3,264.976000	
506	506				
211		200.000000 x	1.243100 =	248.620000	
213		2.000000 x	4.550000 =	9.100000	
385		1.000000 x	196.900000 =	196.900000	
356		1.000000 x	48.650000 =	48.650000	
			ΑΘΡΟΙΣΜΑ =	503.270000	
			Η.Δ. =	553.597000	
507	507				
211		2,100.000000 x	1.243100 =	2,610.510000	
386		1.000000 x	519.550000 =	519.550000	
357		1.000000 x	233.080000 =	233.080000	
213		35.000000 x	4.550000 =	159.250000	
			ΑΘΡΟΙΣΜΑ =	3,522.390000	
			Η.Δ. =	3,804.181200	

508	508				
358		1.000000 x	46.930000 =		46.930000
387		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	121.890000
				Η.Δ. =	127.984500
509	509				
359		1.000000 x	97.290000 =		97.290000
388		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	172.250000
				Η.Δ. =	180.862500
510	510				
360		1.000000 x	102.460000 =		102.460000
389		1.000000 x	74.960000 =		74.960000
				ΑΘΡΟΙΣΜΑ =	177.420000
				Η.Δ. =	186.291000
511	511				
509		.800000 x	180.862500 =		144.690000
				Η.Δ. =	144.690000
512	512				
501		.600000 x	1,370.222700 =		822.133620
				Η.Δ. =	822.133620
513	513				
363		1.000000 x	102.610000 =		102.610000
123		8.000000 x	64.260999 =		514.087992
122		8.000000 x	13.510339 =		108.082712
121		8.000000 x	16.585068 =		132.680544
				Η.Δ. =	857.461248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	144.690000 =		2.893800
513		.020000 x	857.461248 =		17.149225
405		.020000 x	590.611432 =		11.812229
				Β.Τ =	32.245154

1111B	1111B			
501		1.000000 x	1,370.222700 =	1,370.222700
506		1.000000 x	553.597000 =	553.597000
509		2.000000 x	180.862500 =	361.725000

			AΘΡΟΙΣΜΑ =	2,285.544700
	B.T =	.002500 x	2,285.544700 =	5.713862

1112A	1112A			
506		1.000000 x	553.597000 =	553.597000
512		1.000000 x	822.133620 =	822.133620

			AΘΡΟΙΣΜΑ =	1,375.730620
	B.T =	.025000 x	1,375.730620 =	34.393266

1112B	1112B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
1113A	1113A			
214		.200000 x	1.949500 =	.389900
405		.025000 x	590.611432 =	14.765286
112		.250000 x	17.312112 =	4.328028
513		.035000 x	857.461248 =	30.011144
511		.035000 x	144.690000 =	5.064150

			B.T =	54.558507
1113B	1113B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
512		.033000 x	822.133620 =	27.130409
506		.033000 x	553.597000 =	18.268701

			B.T =	49.727138
1114B	1114B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	590.611432 =	11.812229

			B.T =	22.314397
1121B	1121B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
1122A	1122A			
506		1.000000 x	553.597000 =	553.597000
512		1.000000 x	822.133620 =	822.133620

			AΘΡΟΙΣΜΑ =	1,375.730620
	B.T =	.012500 x	1,375.730620 =	17.196633

1122B	1122B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
1123A	1123A			
214		.150000 x	1.949500 =	.292425
115		1.000000 x	20.419486 =	20.419486
112		.150000 x	17.312112 =	2.596817
405		.025000 x	590.611432 =	14.765286

			B.T =	38.074014
1123B	1123B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	553.597000 =	11.071940
512		.020000 x	822.133620 =	16.442672

			B.T =	30.111429
1124B	1124B			
1111B		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862

3110A 1	3110A 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.113561 =	.778390
701 2		.800000 x	4.981697 =	3.985358
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
714		1.400000 x	7.221282 =	10.109795
113		1.200000 x	20.419486 =	24.503383
319		.020000 x	22.070000 =	.441400
112		1.200000 x	17.312112 =	20.774534
			B.T =	130.898510
3110A 2	3110A 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	729.054445 =	29.162178
611		.500000 x	26.060320 =	13.030160
606		.800000 x	9.544410 =	7.635528
714		1.400000 x	7.221282 =	10.109795
319		.020000 x	22.070000 =	.441400
			B.T =	138.540899
3110A 3	3110A 3			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
407		.040000 x	729.054445 =	29.162178
714		1.400000 x	7.221282 =	10.109795
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	22.070000 =	.441400
			B.T =	140.722746

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
113		1.200000 x	20.419486 =	24.503383
714		1.400000 x	7.221282 =	10.109795
112		1.200000 x	17.312112 =	20.774534
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 4		.500000 x	4.670341 =	2.335171
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
319		.020000 x	22.070000 =	.441400

			B.T =	148.365135
3110B	3110B			
713 1		1.000000 x	5.866947 =	5.866947
704		1.000000 x	11.733894 =	11.733894

			B.T =	17.600841
3120A 1	3120A 1			
3110A 1		1.000000 x	130.898510 =	130.898510

			B.T =	130.898510
3120A 2	3120A 2			
3110A 2		1.000000 x	138.540899 =	138.540899

			B.T =	138.540899
3120A 3	3120A 3			
3110A 3		1.000000 x	140.722746 =	140.722746

			B.T =	140.722746
3120A 4	3120A 4			
3110A 4		1.000000 x	148.365135 =	148.365135

			B.T =	148.365135
3120B	3120B			
713 2		1.000000 x	6.353438 =	6.353438
705		1.000000 x	12.706875 =	12.706875

			B.T =	19.060313

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
601		.320000 x	23.612397 =	7.555967
701 2		.320000 x	4.981697 =	1.594143
3110A 1		.800000 x	130.898510 =	104.718808
			B.T =	120.165557
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.981697 =	1.594143
601		.320000 x	23.612397 =	7.555967
3110A 2		.800000 x	138.540899 =	110.832719
			B.T =	126.279468
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	140.722746 =	112.578197
601		.320000 x	23.612397 =	7.555967
701 2		.320000 x	4.981697 =	1.594143
			B.T =	128.024946
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
3110A 4		.800000 x	148.365135 =	118.692108
701 2		.320000 x	4.981697 =	1.594143
601		.320000 x	23.612397 =	7.555967
			B.T =	134.138857
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	130.898510 =	104.718808
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
			B.T =	118.953649
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
3110A 2		.800000 x	138.540899 =	110.832719
			B.T =	125.067560

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	140.722746 =	112.578197
609		.320000 x	19.825183 =	6.344059
701 2		.320000 x	4.981697 =	1.594143
			B.T =	126.813038
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
3110A 4		.800000 x	148.365135 =	118.692108
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
			B.T =	132.926949
3210B	3210B			
713 1		1.000000 x	5.866947 =	5.866947
704		1.000000 x	11.733894 =	11.733894
			B.T =	17.600841
3220A 1	3220A 1			
3210A 1		1.000000 x	120.165557 =	120.165557
			B.T =	120.165557
3220A 2	3220A 2			
3210A 2		1.000000 x	126.279468 =	126.279468
			B.T =	126.279468
3220A 3	3220A 3			
3210A 3		1.000000 x	128.024946 =	128.024946
			B.T =	128.024946
3220A 4	3220A 4			
3210A 4		1.000000 x	134.138857 =	134.138857
			B.T =	134.138857
3220A 5	3220A 5			
3210A 5		1.000000 x	118.953649 =	118.953649
			B.T =	118.953649

3220A 6	3220A 6			
3210A 6		1.000000 x	125.067560 =	125.067560
			B.T =	125.067560
3220A 7	3220A 7			
3210A 7		1.000000 x	126.813038 =	126.813038
			B.T =	126.813038
3220A 8	3220A 8			
3210A 8		1.000000 x	132.926949 =	132.926949
			B.T =	132.926949
3220B	3220B			
713 2		1.000000 x	6.353438 =	6.353438
705		1.000000 x	12.706875 =	12.706875
			B.T =	19.060313
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
319		.040000 x	22.070000 =	.882800
701 5		.250000 x	3.113561 =	.778390
701 2		.500000 x	4.981697 =	2.490849
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
714		2.600000 x	7.221282 =	18.775333
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
			B.T =	183.063818
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
319		.040000 x	22.070000 =	.882800
113		2.000000 x	20.419486 =	40.838972
407		.040000 x	729.054445 =	29.162178
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
606		.800000 x	9.544410 =	7.635528
714		2.600000 x	7.221282 =	18.775333
111		2.700000 x	15.741598 =	42.502315
			B.T =	190.706206

3300A 3	3300A 3			
221		300.000000 x	.099900 =	29.970000
319		.040000 x	22.070000 =	.882800
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
407		.040000 x	729.054445 =	29.162178
714		2.600000 x	7.221282 =	18.775333
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315

			B.T =	192.888054
3300A 4	3300A 4			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 4		.500000 x	4.670341 =	2.335171
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
714		2.600000 x	7.221282 =	18.775333
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	22.070000 =	.882800

			B.T =	200.530442
3300B 1	3300B 1			
713 1		1.000000 x	5.866947 =	5.866947
704		1.000000 x	11.733894 =	11.733894

			B.T =	17.600841
3300B 2	3300B 2			
713 2		1.000000 x	6.353438 =	6.353438
705		1.000000 x	12.706875 =	12.706875

			B.T =	19.060313

3400A 1	3400A 1			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.905900 =	4.529500
111		2.700000 x	15.741598 =	42.502315
112		1.000000 x	17.312112 =	17.312112
113		2.000000 x	20.419486 =	40.838972
701 5		.250000 x	3.113561 =	.778390
701 2		.800000 x	4.981697 =	3.985358
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
113		.500000 x	20.419486 =	10.209743
319		.030000 x	22.070000 =	.662100

B.T = 196.119140

3400A 2	3400A 2			
221		300.000000 x	.099900 =	29.970000
319		.030000 x	22.070000 =	.662100
611		.500000 x	26.060320 =	13.030160
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
255		5.000000 x	.905900 =	4.529500

B.T = 203.761528

3400A 3	3400A 3			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
407		.040000 x	729.054445 =	29.162178
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
255		5.000000 x	.905900 =	4.529500

B.T = 205.943376

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.905900 =	4.529500
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 4		.500000 x	4.670341 =	2.335171
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	22.070000 =	.662100
			B.T =	213.585764
3400B 1	3400B 1			
704		1.000000 x	11.733894 =	11.733894
			B.T =	11.733894
3400B 2	3400B 2			
705		1.000000 x	12.706875 =	12.706875
			B.T =	12.706875
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.113561 =	.311356
701 2		.800000 x	4.981697 =	3.985358
701 2		.500000 x	4.981697 =	2.490849
630		.100000 x	3.240009 =	.324001
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
407		.070000 x	729.054445 =	51.033811
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392
			B.T =	199.573617

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	729.054445 =	51.033811
611		.500000 x	26.060320 =	13.030160
701 4		.500000 x	4.670341 =	2.335171
701 5		.100000 x	3.113561 =	.311356
701 2		.800000 x	4.981697 =	3.985358
630		.100000 x	3.240009 =	.324001
606		.800000 x	9.544410 =	7.635528
113		1.500000 x	20.419486 =	30.629229
			B.T =	207.216005
4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.113561 =	.311356
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.100000 x	3.240009 =	.324001
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	729.054445 =	51.033811
113		1.500000 x	20.419486 =	30.629229
			B.T =	209.397853
4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
407		.070000 x	729.054445 =	51.033811
611		.500000 x	26.060320 =	13.030160
701 5		.100000 x	3.113561 =	.311356
701 4		.800000 x	4.670341 =	3.736273
701 4		.500000 x	4.670341 =	2.335171
630		.100000 x	3.240009 =	.324001
610		.800000 x	22.136061 =	17.708849
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392
			B.T =	217.040241
4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
513		1.000000 x	857.461248 =	857.461248
508		1.000000 x	127.984500 =	127.984500
506		1.000000 x	553.597000 =	553.597000
			B.T =	1,677.539644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.981697 =	5.978036
607		1.200000 x	10.464187 =	12.557024
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	166.940621
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.670341 =	5.604409
611		1.200000 x	26.060320 =	31.272384
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.312112 =	86.560560

			B.T =	185.282353
4120B	4120B			
4110B		.040000 x	1,677.539644 =	67.101586

			B.T =	67.101586
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.640000 =	26.880000
407		.050000 x	729.054445 =	36.452722
606		.800000 x	9.544410 =	7.635528
607		.500000 x	10.464187 =	5.232094
701 2		.500000 x	4.981697 =	2.490849
701 2		.800000 x	4.981697 =	3.985358
111		2.000000 x	15.741598 =	31.483196

			B.T =	149.124746
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	729.054445 =	36.452722
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
611		.500000 x	26.060320 =	13.030160
606		.800000 x	9.544410 =	7.635528
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

			B.T =	156.767134

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
407		.050000 x	729.054445 =	36.452722
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

			B.T =	158.948982
4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.670341 =	2.335171
701 4		.800000 x	4.670341 =	3.736273
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.050000 x	729.054445 =	36.452722
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.640000 =	26.880000

			B.T =	166.591370
4130B	4130B			
4120B		1.000000 x	67.101586 =	67.101586

			B.T =	67.101586
4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.113561 =	.467034
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.240009 =	.486001
701 2		1.050000 x	4.981697 =	5.230782
701 2		.300000 x	4.981697 =	1.494509
607		.300000 x	10.464187 =	3.139256
222		10.000000 x	.070000 =	.700000

			B.T =	42.804099
4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.113561 =	.467034
701 4		.300000 x	4.670341 =	1.401102
701 2		1.050000 x	4.981697 =	5.230782
630		.150000 x	3.240009 =	.486001
611		.300000 x	26.060320 =	7.818096
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

			B.T =	47.389533

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
607		.300000 x	10.464187 =	3.139256
630		.150000 x	3.240009 =	.486001
701 5		.150000 x	3.113561 =	.467034
701 2		.300000 x	4.981697 =	1.494509
701 2		1.050000 x	4.981697 =	5.230782
609		1.050000 x	19.825183 =	20.816442
			B.T =	38.827525
4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
222		10.000000 x	.070000 =	.700000
701 2		1.050000 x	4.981697 =	5.230782
701 5		.150000 x	3.113561 =	.467034
701 4		.300000 x	4.670341 =	1.401102
609		1.050000 x	19.825183 =	20.816442
630		.150000 x	3.240009 =	.486001
611		.300000 x	26.060320 =	7.818096
			B.T =	43.412958
4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
112		1.500000 x	17.312112 =	25.968168
			B.T =	143.445697
4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
407		.040000 x	729.054445 =	29.162178
606		.800000 x	9.544410 =	7.635528
607		.500000 x	10.464187 =	5.232094
630		.250000 x	3.240009 =	.810002
701 5		.250000 x	3.113561 =	.778390
701 2		.800000 x	4.981697 =	3.985358
701 2		.500000 x	4.981697 =	2.490849
			B.T =	109.383802

4220A 2	4220A 2			
221		200.000000 x	.099900 =	19.980000
113		1.000000 x	20.419486 =	20.419486
606		.800000 x	9.544410 =	7.635528
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
407		.040000 x	729.054445 =	29.162178
111		1.200000 x	15.741598 =	18.889918

B.T = 117.026190

4220A 3	4220A 3			
221		200.000000 x	.099900 =	19.980000
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
607		.500000 x	10.464187 =	5.232094
407		.040000 x	729.054445 =	29.162178
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918
701 5		.250000 x	3.113561 =	.778390

B.T = 119.208038

4220A 4	4220A 4			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	729.054445 =	29.162178
611		.500000 x	26.060320 =	13.030160
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 4		.800000 x	4.670341 =	3.736273
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
113		1.000000 x	20.419486 =	20.419486

B.T = 126.850426

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
607		.500000 x	10.464187 =	5.232094
701 2		.500000 x	4.981697 =	2.490849
701 5		.250000 x	3.113561 =	.778390
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
606		.800000 x	9.544410 =	7.635528
111		2.000000 x	15.741598 =	31.483196
714		1.150000 x	7.221282 =	8.304474
407		.040000 x	729.054445 =	29.162178
113		1.200000 x	20.419486 =	24.503383

			ΑΘΡΟΙΣΜΑ =	149.350451
	B.T =	.200000 x	149.350451 =	29.870090

4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	156.992840
	B.T =	.200000 x	156.992840 =	31.398568

4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
607		.500000 x	10.464187 =	5.232094
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 2		.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			ΑΘΡΟΙΣΜΑ =	159.174687
	B.T =	.200000 x	159.174687 =	31.834937

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.113561 =	.778390
701 4		.800000 x	4.670341 =	3.736273
701 4		.500000 x	4.670341 =	2.335171
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474

			AΘΡΟΙΣΜΑ =	166.817076
	B.T =	.200000 x	166.817076 =	33.363415

4300B	4300B			
221		2.000000 x	.099900 =	.199800
262		4.000000 x	.980000 =	3.920000
112		.400000 x	17.312112 =	6.924845

			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397

			B.T =	23.612397
602	602			
403		.002500 x	677.397257 =	1.693493

			B.T =	1.693493
603	603			
111		.300000 x	15.741598 =	4.722479
401		.001000 x	936.292073 =	.936292
412		.003300 x	388.600890 =	1.282383

			B.T =	6.941154
604	604			
111		.200000 x	15.741598 =	3.148320
401		.001100 x	936.292073 =	1.029921
412		.004000 x	388.600890 =	1.554404
404		.005000 x	454.383754 =	2.271919

			B.T =	8.004563

605	605			
112		.100000 x	17.312112 =	1.731211
402		.006200 x	912.618392 =	5.658234
412		.004000 x	388.600890 =	1.554404
406		.006200 x	420.751470 =	2.608659
401		.001000 x	936.292073 =	.936292
			B.T =	12.488800
606	606			
111		.100000 x	15.741598 =	1.574160
412		.005000 x	388.600890 =	1.943004
406		.006700 x	420.751470 =	2.819035
404		.005000 x	454.383754 =	2.271919
401		.001000 x	936.292073 =	.936292
			B.T =	9.544410
607	607			
111		.100000 x	15.741598 =	1.574160
412		.005000 x	388.600890 =	1.943004
406		.006700 x	420.751470 =	2.819035
404		.006200 x	454.383754 =	2.817179
401		.001400 x	936.292073 =	1.310809
			B.T =	10.464187
608	608			
111		.100000 x	15.741598 =	1.574160
404		.012500 x	454.383754 =	5.679797
401		.002000 x	936.292073 =	1.872584
412		.005000 x	388.600890 =	1.943004
406		.006700 x	420.751470 =	2.819035
			B.T =	13.888580
609	609			
214		.100000 x	1.949500 =	.194950
111		.800000 x	15.741598 =	12.593278
115		.200000 x	20.419486 =	4.083897
405		.005000 x	590.611432 =	2.953057
			B.T =	19.825183

610	610			
214		.100000 x	1.949500 =	.194950
112		.100000 x	17.312112 =	1.731211
412		.005000 x	388.600890 =	1.943004
406		.005000 x	420.751470 =	2.103757
405		.005000 x	590.611432 =	2.953057
402		.010000 x	912.618392 =	9.126184
115		.200000 x	20.419486 =	4.083897
			B.T =	22.136061
611	611			
214		.100000 x	1.949500 =	.194950
112		.100000 x	17.312112 =	1.731211
115		.200000 x	20.419486 =	4.083897
406		.005000 x	420.751470 =	2.103757
412		.005000 x	388.600890 =	1.943004
405		.005000 x	590.611432 =	2.953057
402		.014300 x	912.618392 =	13.050443
			B.T =	26.060320
612	612			
214		.150000 x	1.949500 =	.292425
408		.010000 x	558.827566 =	5.588276
115		.200000 x	20.419486 =	4.083897
405		.005000 x	590.611432 =	2.953057
111		.300000 x	15.741598 =	4.722479
			AΘΡΟΙΣΜΑ =	17.640134
	B.T =	1.068000 x	17.640134 =	18.839664
613	613			
214		.150000 x	1.949500 =	.292425
409		.010000 x	627.491766 =	6.274918
405		.005000 x	590.611432 =	2.953057
115		.200000 x	20.419486 =	4.083897
111		.500000 x	15.741598 =	7.870799
			AΘΡΟΙΣΜΑ =	21.475096
	B.T =	1.282000 x	21.475096 =	27.531073
614	614			
214		.150000 x	1.949500 =	.292425
111		.500000 x	15.741598 =	7.870799
115		.200000 x	20.419486 =	4.083897
410		.010000 x	751.863266 =	7.518633
405		.005000 x	590.611432 =	2.953057
			AΘΡΟΙΣΜΑ =	22.718811
	B.T =	1.602000 x	22.718811 =	36.395535

615	615			
214		.150000 x	1.949500 =	.292425
410		.010000 x	751.863266 =	7.518633
111		.700000 x	15.741598 =	11.019119
405		.005000 x	590.611432 =	2.953057
115		.200000 x	20.419486 =	4.083897

			ΑΘΡΟΙΣΜΑ =	25.867131
	B.T =	1.832000 x	25.867131 =	47.388583

616	616			
214		.150000 x	1.949500 =	.292425
111		.800000 x	15.741598 =	12.593278
405		.005000 x	590.611432 =	2.953057
411		.010000 x	1,052.911266 =	10.529113
115		.200000 x	20.419486 =	4.083897

			ΑΘΡΟΙΣΜΑ =	30.451770
	B.T =	2.137000 x	30.451770 =	65.075433

617	617			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	553.597000 =	553.597000
503		1.000000 x	1,370.222700 =	1,370.222700

			ΑΘΡΟΙΣΜΑ =	2,850.529396
	B.T =	.006250 x	2,850.529396 =	17.815809

618	618			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	553.597000 =	553.597000
503		1.000000 x	1,370.222700 =	1,370.222700

			ΑΘΡΟΙΣΜΑ =	2,850.529396
	B.T =	.007700 x	2,850.529396 =	21.949076

619	619			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,370.222700 =	1,370.222700
506		1.000000 x	553.597000 =	553.597000
513		1.000000 x	857.461248 =	857.461248

			ΑΘΡΟΙΣΜΑ =	2,850.529396
	B.T =	.010000 x	2,850.529396 =	28.505294

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	857.461248 =	857.461248
506		1.000000 x	553.597000 =	553.597000
503		1.000000 x	1,370.222700 =	1,370.222700

			ΑΘΡΟΙΣΜΑ =	2,850.529396
	B.T =	.012500 x	2,850.529396 =	35.631617

621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	553.597000 =	553.597000
503		1.000000 x	1,370.222700 =	1,370.222700
513		1.000000 x	857.461248 =	857.461248

			ΑΘΡΟΙΣΜΑ =	2,850.529396
	B.T =	.016600 x	2,850.529396 =	47.318788

630	630			
413		.020000 x	162.000429 =	3.240009

			B.T =	3.240009
701 1	701 1			
406		.012580 x	420.751470 =	5.293053

			B.T =	5.293053
701 2	701 2			
406		.011840 x	420.751470 =	4.981697

			B.T =	4.981697
701 3	701 3			
406		.011544 x	420.751470 =	4.857155

			B.T =	4.857155
701 4	701 4			
406		.011100 x	420.751470 =	4.670341

			B.T =	4.670341
701 5	701 5			
406		.007400 x	420.751470 =	3.113561

			B.T =	3.113561

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	553.597000 =	553.597000
513		.300000 x	857.461248 =	257.238374
509		2.000000 x	180.862500 =	361.725000

			ΑΘΡΟΙΣΜΑ =	1,311.057270
	B.T =	.002500 x	1,311.057270 =	3.277643

703	703			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,370.222700 =	1,370.222700
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	553.597000 =	553.597000
513		.300000 x	857.461248 =	257.238374

			ΑΘΡΟΙΣΜΑ =	2,622.888522
	B.T =	.002500 x	2,622.888522 =	6.557221

704	704			
112		4.000000 x	17.312112 =	69.248448
502		1.000000 x	1,295.202700 =	1,295.202700
513		.500000 x	857.461248 =	428.730624
506		1.000000 x	553.597000 =	553.597000

			ΑΘΡΟΙΣΜΑ =	2,346.778772
	B.T =	.005000 x	2,346.778772 =	11.733894

705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	857.461248 =	514.476749
506		1.000000 x	553.597000 =	553.597000
504		1.000000 x	1,661.548900 =	1,661.548900

			ΑΘΡΟΙΣΜΑ =	2,798.871097
	B.T =	.004540 x	2,798.871097 =	12.706875

706	706			
501		1.000000 x	1,370.222700 =	1,370.222700
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	553.597000 =	553.597000

			ΑΘΡΟΙΣΜΑ =	2,285.544700
	B.T =	.002500 x	2,285.544700 =	5.713862

707	707			
505		1.000000 x	3,264.976000 =	3,264.976000
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	553.597000 =	553.597000

			ΑΘΡΟΙΣΜΑ =	4,191.155000
	B.T =	.001000 x	4,191.155000 =	4.191155

708	708			
708A		1.000000 x	17.501630 =	17.501630
708B		1.000000 x	5.713862 =	5.713862

			B.T =	23.215492
708A	708A			
214		.050000 x	1.949500 =	.097475
513		.010000 x	857.461248 =	8.574612
511		.010000 x	144.690000 =	1.446900
405		.012500 x	590.611432 =	7.382643

			B.T =	17.501630
708B	708B			
706		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
709	709			
709A		1.000000 x	17.196633 =	17.196633
709B		1.000000 x	5.713862 =	5.713862

			B.T =	22.910495
709A	709A			
506		1.000000 x	553.597000 =	553.597000
512		1.000000 x	822.133620 =	822.133620

			AΘΡΟΙΣΜΑ =	1,375.730620
	B.T =	.012500 x	1,375.730620 =	17.196633

709B	709B			
706		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
710	710			
710A		1.000000 x	50.230479 =	50.230479
710B		1.000000 x	5.713862 =	5.713862

			B.T =	55.944341
710A	710A			
214		.200000 x	1.949500 =	.389900
405		.025000 x	590.611432 =	14.765286
513		.035000 x	857.461248 =	30.011144
511		.035000 x	144.690000 =	5.064150

			B.T =	50.230479

710B	710B			
706		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
711	711			
711A		1.000000 x	45.811830 =	45.811830
711B		1.000000 x	5.713862 =	5.713862

			B.T =	51.525692
711A	711A			
506		1.000000 x	553.597000 =	553.597000
512		1.000000 x	822.133620 =	822.133620

			AΘΡΟΙΣΜΑ =	1,375.730620
	B.T =	.033300 x	1,375.730620 =	45.811830

711B	711B			
706		1.000000 x	5.713862 =	5.713862

			B.T =	5.713862
712	712			
513		1.000000 x	857.461248 =	857.461248

			AΘΡΟΙΣΜΑ =	857.461248
	B.T =	.004000 x	857.461248 =	3.429845

713 1	713 1			
704		.500000 x	11.733894 =	5.866947

			B.T =	5.866947
713 2	713 2			
705		.500000 x	12.706875 =	6.353438

			B.T =	6.353438
714	714			
714A		1.000000 x	3.448122 =	3.448122
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.221282

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.184000 =	2.184000
113		2.000000 x	20.419486 =	40.838972

			AΘΡΟΙΣΜΑ =	103.547196
	B.T =	.033300 x	103.547196 =	3.448122

714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211

			B.T =	3.773160
1111	1111			
1111A		1.000000 x	32.245154 =	32.245154
1111B		1.000000 x	5.713862 =	5.713862

			T.E =	37.959016
1112	1112			
1112A		1.000000 x	34.393266 =	34.393266
1112B		1.000000 x	5.713862 =	5.713862

			T.E =	40.107128
1113	1113			
1113A		1.000000 x	54.558507 =	54.558507
1113B		1.000000 x	5.713862 =	5.713862

			T.E =	60.272369
1114	1114			
1114A		1.000000 x	49.727138 =	49.727138
1114B		1.000000 x	5.713862 =	5.713862

			T.E =	55.441000
1121	1121			
1121A		1.000000 x	22.314397 =	22.314397
1121B		1.000000 x	5.713862 =	5.713862

			T.E =	28.028259
1122	1122			
1122A		1.000000 x	17.196633 =	17.196633
1122B		1.000000 x	5.713862 =	5.713862

			T.E =	22.910495

1123	1123				
1123A		1.000000 x	38.074014 =		38.074014
1123B		1.000000 x	5.713862 =		5.713862

			T.E =		43.787876
1124	1124				
1124A		1.000000 x	30.111429 =		30.111429
1124B		1.000000 x	5.713862 =		5.713862

			T.E =		35.825291
1210	1210				
707		1.000000 x	4.191155 =		4.191155

			T.E =		4.191155
1220	1220				
708		1.000000 x	23.215492 =		23.215492

			T.E =		23.215492
1230	1230				
709		1.000000 x	22.910495 =		22.910495

			T.E =		22.910495
1311	1311				
712		.250000 x	3.429845 =		.857461

			T.E =		.857461
1312	1312				
712		.250000 x	3.429845 =		.857461
701 1		1.000000 x	5.293053 =		5.293053
602		1.000000 x	1.693493 =		1.693493

			T.E =		7.844007
1313	1313				
712		.250000 x	3.429845 =		.857461
603		1.000000 x	6.941154 =		6.941154
701 2		1.000000 x	4.981697 =		4.981697

			T.E =		12.780312

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.429845 =	.857461	

			T.E =	37.431621	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
602		1.000000 x	1.693493 =	1.693493	
701 1		1.000000 x	5.293053 =	5.293053	

			T.E =	10.448968	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
701 2		1.000000 x	4.981697 =	4.981697	
603		1.000000 x	6.941154 =	6.941154	

			T.E =	15.385273	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
112		.100000 x	17.312112 =	1.731211	
111		.100000 x	15.741598 =	1.574160	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.429845 =	1.714923	
608		1.000000 x	13.888580 =	13.888580	
702		1.000000 x	3.277643 =	3.277643	
701 4		1.000000 x	4.670341 =	4.670341	

			T.E =	23.551487	
2120	2120				
712		.500000 x	3.429845 =	1.714923	
603		1.000000 x	6.941154 =	6.941154	
702		1.000000 x	3.277643 =	3.277643	
701 2		1.000000 x	4.981697 =	4.981697	

			T.E =	16.915417	
2130	2130				
712		.500000 x	3.429845 =	1.714923	
702		1.000000 x	3.277643 =	3.277643	
604		1.000000 x	8.004563 =	8.004563	
701 2		1.000000 x	4.981697 =	4.981697	

			T.E =	17.978826	

2140	2140			
712		.500000 x	3.429845 =	1.714923
701 2		1.000000 x	4.981697 =	4.981697
702		1.000000 x	3.277643 =	3.277643
605		1.000000 x	12.488800 =	12.488800
			T.E =	22.463063
2210	2210			
712		.500000 x	3.429845 =	1.714923
702		1.000000 x	3.277643 =	3.277643
701 2		1.000000 x	4.981697 =	4.981697
609		1.050000 x	19.825183 =	20.816442
			T.E =	30.790705
2220	2220			
712		.500000 x	3.429845 =	1.714923
702		1.000000 x	3.277643 =	3.277643
701 2		1.000000 x	4.981697 =	4.981697
609		1.150000 x	19.825183 =	22.798960
			T.E =	32.773223
2230	2230			
111		.200000 x	15.741598 =	3.148320
609		1.200000 x	19.825183 =	23.790220
701 2		1.000000 x	4.981697 =	4.981697
			T.E =	31.920236
2240	2240			
111		.300000 x	15.741598 =	4.722479
609		1.200000 x	19.825183 =	23.790220
701 2		1.000000 x	4.981697 =	4.981697
			T.E =	33.494396
2310	2310			
612		1.000000 x	18.839664 =	18.839664
701 3		1.000000 x	4.857155 =	4.857155
703		1.000000 x	6.557221 =	6.557221
			T.E =	30.254040
2320	2320			
613		1.000000 x	27.531073 =	27.531073
703		1.000000 x	6.557221 =	6.557221
701 3		1.000000 x	4.857155 =	4.857155
			T.E =	38.945449

2330	2330				
614		1.000000 x	36.395535 =	36.395535	
703		1.000000 x	6.557221 =	6.557221	
701	3	1.000000 x	4.857155 =	4.857155	

			T.E =	47.809911	
2340	2340				
615		1.000000 x	47.388583 =	47.388583	
703		1.000000 x	6.557221 =	6.557221	
701	3	1.000000 x	4.857155 =	4.857155	

			T.E =	58.802959	
2350	2350				
616		1.000000 x	65.075433 =	65.075433	
703		1.000000 x	6.557221 =	6.557221	
701	3	1.000000 x	4.857155 =	4.857155	

			T.E =	76.489809	
2410	2410				
617		1.000000 x	17.815809 =	17.815809	
703		1.000000 x	6.557221 =	6.557221	

			T.E =	24.373030	
2420	2420				
618		1.000000 x	21.949076 =	21.949076	
703		1.000000 x	6.557221 =	6.557221	

			T.E =	28.506297	
2430	2430				
619		1.000000 x	28.505294 =	28.505294	
703		1.000000 x	6.557221 =	6.557221	

			T.E =	35.062515	
2440	2440				
620		1.000000 x	35.631617 =	35.631617	
703		1.000000 x	6.557221 =	6.557221	

			T.E =	42.188838	
2450	2450				
621		1.000000 x	47.318788 =	47.318788	
703		1.000000 x	6.557221 =	6.557221	

			T.E =	53.876009	

3110 1	3110 1				
3110A 1		1.000000 x	130.898510 =		130.898510
3110B		1.000000 x	17.600841 =		17.600841

			T.E =		148.499351
3110 2	3110 2				
3110A 2		1.000000 x	138.540899 =		138.540899
3110B		1.000000 x	17.600841 =		17.600841

			T.E =		156.141740
3110 3	3110 3				
3110A 3		1.000000 x	140.722746 =		140.722746
3110B		1.000000 x	17.600841 =		17.600841

			T.E =		158.323587
3110 4	3110 4				
3110A 4		1.000000 x	148.365135 =		148.365135
3110B		1.000000 x	17.600841 =		17.600841

			T.E =		165.965976
3120 1	3120 1				
3120A 1		1.000000 x	130.898510 =		130.898510
3120B		1.000000 x	19.060313 =		19.060313

			T.E =		149.958823
3120 2	3120 2				
3120A 2		1.000000 x	138.540899 =		138.540899
3120B		1.000000 x	19.060313 =		19.060313

			T.E =		157.601212
3120 3	3120 3				
3120A 3		1.000000 x	140.722746 =		140.722746
3120B		1.000000 x	19.060313 =		19.060313

			T.E =		159.783059
3120 4	3120 4				
3120A 4		1.000000 x	148.365135 =		148.365135
3120B		1.000000 x	19.060313 =		19.060313

			T.E =		167.425448

3210 1	3210 1				
3210A 1		1.000000 x	120.165557 =		120.165557
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		137.766398
3210 2	3210 2				
3210A 2		1.000000 x	126.279468 =		126.279468
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		143.880309
3210 3	3210 3				
3210A 3		1.000000 x	128.024946 =		128.024946
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		145.625787
3210 4	3210 4				
3210A 4		1.000000 x	134.138857 =		134.138857
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		151.739698
3210 5	3210 5				
3210A 5		1.000000 x	118.953649 =		118.953649
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		136.554490
3210 6	3210 6				
3210A 6		1.000000 x	125.067560 =		125.067560
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		142.668401
3210 7	3210 7				
3210A 7		1.000000 x	126.813038 =		126.813038
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		144.413879
3210 8	3210 8				
3210A 8		1.000000 x	132.926949 =		132.926949
3210B		1.000000 x	17.600841 =		17.600841

			T.E =		150.527790

3220 1	3220 1				
3220A 1		1.000000 x	120.165557 =		120.165557
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		139.225870
3220 2	3220 2				
3220A 2		1.000000 x	126.279468 =		126.279468
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		145.339781
3220 3	3220 3				
3220A 3		1.000000 x	128.024946 =		128.024946
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		147.085259
3220 4	3220 4				
3220A 4		1.000000 x	134.138857 =		134.138857
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		153.199170
3220 5	3220 5				
3220A 5		1.000000 x	118.953649 =		118.953649
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		138.013962
3220 6	3220 6				
3220A 6		1.000000 x	125.067560 =		125.067560
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		144.127873
3220 7	3220 7				
3220A 7		1.000000 x	126.813038 =		126.813038
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		145.873351
3220 8	3220 8				
3220A 8		1.000000 x	132.926949 =		132.926949
3220B		1.000000 x	19.060313 =		19.060313

			T.E =		151.987262

ΑΤΛΕ		1ο Τρίμηνο του 2012		Σελ.	41
				Ημ/νία	20/07/2012
3300	1	3300	1		
	3300A 1		1.000000 x	183.063818 =	183.063818
	3300B 1		1.000000 x	17.600841 =	17.600841

				T.E =	200.664659
3300	2	3300	2		
	3300A 1		1.000000 x	183.063818 =	183.063818
	3300B 2		1.000000 x	19.060313 =	19.060313

				T.E =	202.124131
3300	3	3300	3		
	3300A 2		1.000000 x	190.706206 =	190.706206
	3300B 1		1.000000 x	17.600841 =	17.600841

				T.E =	208.307047
3300	4	3300	4		
	3300A 2		1.000000 x	190.706206 =	190.706206
	3300B 2		1.000000 x	19.060313 =	19.060313

				T.E =	209.766519
3300	5	3300	5		
	3300A 3		1.000000 x	192.888054 =	192.888054
	3300B 1		1.000000 x	17.600841 =	17.600841

				T.E =	210.488895
3300	6	3300	6		
	3300A 3		1.000000 x	192.888054 =	192.888054
	3300B 2		1.000000 x	19.060313 =	19.060313

				T.E =	211.948367
3300	7	3300	7		
	3300A 4		1.000000 x	200.530442 =	200.530442
	3300B 1		1.000000 x	17.600841 =	17.600841

				T.E =	218.131283
3300	8	3300	8		
	3300A 4		1.000000 x	200.530442 =	200.530442
	3300B 2		1.000000 x	19.060313 =	19.060313

				T.E =	219.590755

3400 1	3400 1				
3400A 1		1.000000 x	196.119140 =		196.119140
3400B 1		1.000000 x	11.733894 =		11.733894

			T.E =		207.853034
3400 2	3400 2				
3400A 1		1.000000 x	196.119140 =		196.119140
3400B 2		1.000000 x	12.706875 =		12.706875

			T.E =		208.826015
3400 3	3400 3				
3400A 2		1.000000 x	203.761528 =		203.761528
3400B 1		1.000000 x	11.733894 =		11.733894

			T.E =		215.495422
3400 4	3400 4				
3400A 2		1.000000 x	203.761528 =		203.761528
3400B 2		1.000000 x	12.706875 =		12.706875

			T.E =		216.468403
3400 5	3400 5				
3400A 3		1.000000 x	205.943376 =		205.943376
3400B 1		1.000000 x	11.733894 =		11.733894

			T.E =		217.677270
3400 6	3400 6				
3400A 3		1.000000 x	205.943376 =		205.943376
3400B 2		1.000000 x	12.706875 =		12.706875

			T.E =		218.650251
3400 7	3400 7				
3400A 4		1.000000 x	213.585764 =		213.585764
3400B 1		1.000000 x	11.733894 =		11.733894

			T.E =		225.319658
3400 8	3400 8				
3400A 4		1.000000 x	213.585764 =		213.585764
3400B 2		1.000000 x	12.706875 =		12.706875

			T.E =		226.292639

4110 1	4110 1				
4110A 1		1.000000 x	199.573617 =		199.573617
4110B		.025000 x	1,677.539644 =		41.938491

			T.E =		241.512108
4110 2	4110 2				
4110A 2		1.000000 x	207.216005 =		207.216005
4110B		.025000 x	1,677.539644 =		41.938491

			T.E =		249.154496
4110 3	4110 3				
4110A 3		1.000000 x	209.397853 =		209.397853
4110B		.025000 x	1,677.539644 =		41.938491

			T.E =		251.336344
4110 4	4110 4				
4110A 4		1.000000 x	217.040241 =		217.040241
4110B		.025000 x	1,677.539644 =		41.938491

			T.E =		258.978732
4120 1	4120 1				
4120A 1		1.000000 x	166.940621 =		166.940621
4120B		1.000000 x	67.101586 =		67.101586

			T.E =		234.042207
4120 2	4120 2				
4120A 2		1.000000 x	185.282353 =		185.282353
4120B		1.000000 x	67.101586 =		67.101586

			T.E =		252.383939
4130 1	4130 1				
4130A 1		1.000000 x	149.124746 =		149.124746
4130B		1.000000 x	67.101586 =		67.101586

			T.E =		216.226332
4130 2	4130 2				
4130A 2		1.000000 x	156.767134 =		156.767134
4130B		1.000000 x	67.101586 =		67.101586

			T.E =		223.868720

4130 3	4130 3				
4130A 3		1.000000 x	158.948982 =	158.948982	
4130B		1.000000 x	67.101586 =	67.101586	

			T.E =	226.050568	
4130 4	4130 4				
4130A 4		1.000000 x	166.591370 =	166.591370	
4130B		1.000000 x	67.101586 =	67.101586	

			T.E =	233.692956	
4210 1	4210 1				
4210A 1		1.000000 x	42.804099 =	42.804099	
4210B		1.000000 x	143.445697 =	143.445697	

			T.E =	186.249796	
4210 2	4210 2				
4210A 2		1.000000 x	47.389533 =	47.389533	
4210B		1.000000 x	143.445697 =	143.445697	

			T.E =	190.835230	
4210 3	4210 3				
4210A 3		1.000000 x	38.827525 =	38.827525	
4210B		1.000000 x	143.445697 =	143.445697	

			T.E =	182.273222	
4210 4	4210 4				
4210A 4		1.000000 x	43.412958 =	43.412958	
4210B		1.000000 x	143.445697 =	143.445697	

			T.E =	186.858655	
4220B 1	4220B 1				
319		.020000 x	22.070000 =	.441400	
701 2		.320000 x	4.981697 =	1.594143	
601		.320000 x	23.612397 =	7.555967	
4220A 1		.800000 x	109.383802 =	87.507042	
111		.400000 x	15.741598 =	6.296639	
714		1.150000 x	7.221282 =	8.304474	

			T.E =	111.699665	

4220B 2	4220B 2			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	117.026190 =	93.620952
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.981697 =	1.594143
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.221282 =	8.304474

			T.E =	117.813576
4220B 3	4220B 3			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.981697 =	1.594143
601		.320000 x	23.612397 =	7.555967
4220A 3		.800000 x	119.208038 =	95.366430
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639

			T.E =	119.559054
4220B 4	4220B 4			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	126.850426 =	101.480341
701 2		.320000 x	4.981697 =	1.594143
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.221282 =	8.304474

			T.E =	125.672964
4220B 5	4220B 5			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
4220A 1		.800000 x	109.383802 =	87.507042
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.221282 =	8.304474

			T.E =	110.487757
4220B 6	4220B 6			
319		.020000 x	22.070000 =	.441400
4220A 2		.800000 x	117.026190 =	93.620952
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
714		1.150000 x	7.221282 =	8.304474

			T.E =	116.601667

4220B 7	4220B 7			
319		.020000 x	22.070000 =	.441400
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
4220A 3		.800000 x	119.208038 =	95.366430
714		1.150000 x	7.221282 =	8.304474
111		.400000 x	15.741598 =	6.296639
			T.E =	118.347146
4220B 8	4220B 8			
319		.020000 x	22.070000 =	.441400
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.221282 =	8.304474
701 2		.320000 x	4.981697 =	1.594143
609		.320000 x	19.825183 =	6.344059
4220A 4		.800000 x	126.850426 =	101.480341
			T.E =	124.461056
4230 1	4230 1			
221		250.000000 x	.0999900 =	24.975000
701 5		.250000 x	3.113561 =	.778390
701 2		.500000 x	4.981697 =	2.490849
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
407		.040000 x	729.054445 =	29.162178
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
714		1.150000 x	7.221282 =	8.304474
111		2.000000 x	15.741598 =	31.483196
			T.E =	139.801851
4230 2	4230 2			
221		250.000000 x	.0999900 =	24.975000
701 5		.250000 x	3.113561 =	.778390
701 4		.500000 x	4.670341 =	2.335171
701 2		.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
606		.800000 x	9.544410 =	7.635528
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	22.070000 =	.441400
			T.E =	147.444240

4230 3

4230 3

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.113561 =	.778390
701	4	.800000 x	4.670341 =	3.736273
701	2	.500000 x	4.981697 =	2.490849
630		.250000 x	3.240009 =	.810002
610		.800000 x	22.136061 =	17.708849
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.741598 =	31.483196
407		.040000 x	729.054445 =	29.162178
607		.500000 x	10.464187 =	5.232094
714		1.150000 x	7.221282 =	8.304474
113		1.200000 x	20.419486 =	24.503383

T.E =

149.626087

4230 4

4230 4

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.113561 =	.778390
701	4	.500000 x	4.670341 =	2.335171
701	4	.800000 x	4.670341 =	3.736273
630		.250000 x	3.240009 =	.810002
611		.500000 x	26.060320 =	13.030160
610		.800000 x	22.136061 =	17.708849
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

T.E =

157.268476

4240 1

4240 1

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.113561 =	.778390
701	2	.500000 x	4.981697 =	2.490849
701	2	.800000 x	4.981697 =	3.985358
630		.250000 x	3.240009 =	.810002
607		.500000 x	10.464187 =	5.232094
606		.800000 x	9.544410 =	7.635528
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.419486 =	24.503383
407		.040000 x	729.054445 =	29.162178
714		1.150000 x	7.221282 =	8.304474
111		2.000000 x	15.741598 =	31.483196

T.E =

144.796851

4240	2	4240	2		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.113561 = .778390
701	4			.500000 x	4.670341 = 2.335171
701	2			.800000 x	4.981697 = 3.985358
630				.250000 x	3.240009 = .810002
611				.500000 x	26.060320 = 13.030160
606				.800000 x	9.544410 = 7.635528
407				.040000 x	729.054445 = 29.162178
714				1.150000 x	7.221282 = 8.304474
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196
319				.020000 x	22.070000 = .441400

T.E = 152.439240

4240	3	4240	3		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.113561 = .778390
701	4			.800000 x	4.670341 = 3.736273
701	2			.500000 x	4.981697 = 2.490849
630				.250000 x	3.240009 = .810002
610				.800000 x	22.136061 = 17.708849
319				.020000 x	22.070000 = .441400
111				2.000000 x	15.741598 = 31.483196
407				.040000 x	729.054445 = 29.162178
607				.500000 x	10.464187 = 5.232094
714				1.150000 x	7.221282 = 8.304474
113				1.200000 x	20.419486 = 24.503383

T.E = 154.621087

4240	4	4240	4		
221				300.000000 x	.099900 = 29.970000
701	5			.250000 x	3.113561 = .778390
701	4			.500000 x	4.670341 = 2.335171
701	4			.800000 x	4.670341 = 3.736273
630				.250000 x	3.240009 = .810002
611				.500000 x	26.060320 = 13.030160
610				.800000 x	22.136061 = 17.708849
407				.040000 x	729.054445 = 29.162178
714				1.150000 x	7.221282 = 8.304474
319				.020000 x	22.070000 = .441400
113				1.200000 x	20.419486 = 24.503383
111				2.000000 x	15.741598 = 31.483196

T.E = 162.263476

4300	1	4300	1		
4300A	1			1.000000 x	29.870090 = 29.870090
4300B				1.000000 x	11.044645 = 11.044645

T.E = 40.914735

4300	2	4300	2			
	4300A			1.000000 x	31.398568 =	31.398568
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.443213
4300	3	4300	3			
	4300A			1.000000 x	31.834937 =	31.834937
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.879582
4300	4	4300	4			
	4300A			1.000000 x	33.363415 =	33.363415
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	44.408060
4400		4400				
	251			1.050000 x	.558700 =	.586635
	113			.050000 x	20.419486 =	1.020974

					T.E =	1.607609
4500		4500				
	251			1.050000 x	.558700 =	.586635
	113			.100000 x	20.419486 =	2.041949
	114			.100000 x	17.312112 =	1.731211

					T.E =	4.359795
4600		4600				
	256			1.000000 x	4.300000 =	4.300000
	113			.100000 x	20.419486 =	2.041949

					T.E =	6.341949
4700		4700				
	253			1.000000 x	4.500000 =	4.500000
	113			.100000 x	20.419486 =	2.041949

					T.E =	6.541949