

. .& .

3

μ

μ

2

μ

2012

111	15.643441
112	17.205541
113	20.290479
114	17.205541
115	20.290479
116	23.647167
117	10.001019
118	21.561131
119	10.001019
120	16.609513
121	16.419380
122	13.377245
123	63.844308
211	1.271500
212	1.539700
213	4.550000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.559100
252	2.184000
253	4.500000
254	4.500000
255	.894300
256	4.300000
261	
262	.980000
263	.640000
311	437.840000
312	134.530000
313	206.720000
314	4.530000
315	55.210000
316	4.530000
317	126.080000
318	27.370000
319	22.070000
320	156.740000
321	213.360000
322	296.440000
323	337.580000
324	185.200000
325	317.230000
326	103.360000
327	4.530000
351	451.770000
352	383.570000
353	451.770000
354	592.710000
355	296.440000
356	48.650000
357	233.080000
358	46.930000
359	97.290000
360	102.460000

361	78.370000
362	271.240000
363	102.610000
380	568.910000
381	568.910000
382	568.910000
383	654.300000
384	1,083.720000
385	196.900000
386	519.550000
387	74.960000
388	74.960000
389	74.960000

401	401			
211		110.000000 x	1.271500 =	139.865000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.647167 =	189.177336
311		1.000000 x	437.840000 =	437.840000
213		10.000000 x	4.550000 =	45.500000
			=	852.386412
			H. . =	937.625053
402	402			
211		180.000000 x	1.271500 =	228.870000
213		12.000000 x	4.550000 =	54.600000
212		5.000000 x	1.539700 =	7.698500
117		8.000000 x	10.001019 =	80.008152
116		8.000000 x	23.647167 =	189.177336
112		8.000000 x	17.205541 =	137.644328
312		1.000000 x	134.530000 =	134.530000
			=	832.528316
			H. . =	915.781148
403	403			
211		80.000000 x	1.271500 =	101.720000
313		1.000000 x	206.720000 =	206.720000
117		8.000000 x	10.001019 =	80.008152
116		8.000000 x	23.647167 =	189.177336
213		6.000000 x	4.550000 =	27.300000
254		2.500000 x	4.500000 =	11.250000
			=	616.175488
			H. . =	677.793037
404	404			
211		80.000000 x	1.271500 =	101.720000
212		2.000000 x	1.539700 =	3.079400
119		4.000000 x	10.001019 =	40.004076
118		8.000000 x	21.561131 =	172.489048
112		4.000000 x	17.205541 =	68.822164
213		5.000000 x	4.550000 =	22.750000
314		1.000000 x	4.530000 =	4.530000
			=	413.394688
			H. . =	454.734157

405	405			
211		40.000000 x	1.271500 =	50.860000
118		4.000000 x	21.561131 =	86.244524
115		16.000000 x	20.290479 =	324.647664
316		2.000000 x	4.530000 =	9.060000
213		2.000000 x	4.550000 =	9.100000
315		1.000000 x	55.210000 =	55.210000
			=	535.122188
			H. . =	588.634407
406	406			
211		80.000000 x	1.271500 =	101.720000
120		8.000000 x	16.609513 =	132.876104
317		1.000000 x	126.080000 =	126.080000
213		5.000000 x	4.550000 =	22.750000
			=	383.426104
			H. . =	421.768714
407	407			
212		17.000000 x	1.539700 =	26.174900
112		30.000000 x	17.205541 =	516.166230
118		4.000000 x	21.561131 =	86.244524
213		1.000000 x	4.550000 =	4.550000
318		1.000000 x	27.370000 =	27.370000
			=	660.505654
			H. . =	726.556219
408	408			
211		30.000000 x	1.271500 =	38.145000
320		1.000000 x	156.740000 =	156.740000
117		4.000000 x	10.001019 =	40.004076
116		8.000000 x	23.647167 =	189.177336
112		4.000000 x	17.205541 =	68.822164
213		3.000000 x	4.550000 =	13.650000
			=	506.538576
			H. . =	557.192434
409	409			
211		50.000000 x	1.271500 =	63.575000
324		1.000000 x	185.200000 =	185.200000
213		5.000000 x	4.550000 =	22.750000
116		8.000000 x	23.647167 =	189.177336
117		4.000000 x	10.001019 =	40.004076
112		4.000000 x	17.205541 =	68.822164
			=	569.528576
			H. . =	626.481434

410	410				
211		100.000000 x	1.271500 =	127.150000	
213		10.000000 x	4.550000 =	45.500000	
116		8.000000 x	23.647167 =	189.177336	
117		4.000000 x	10.001019 =	40.004076	
112		4.000000 x	17.205541 =	68.822164	
321		1.000000 x	213.360000 =	213.360000	
			=	684.013576	
			H. . =	752.414934	
411	411				
211		200.000000 x	1.271500 =	254.300000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.647167 =	189.177336	
112		4.000000 x	17.205541 =	68.822164	
325		1.000000 x	317.230000 =	317.230000	
213		20.000000 x	4.550000 =	91.000000	
			=	960.533576	
			H. . =	1,056.586934	
412	412				
211		40.000000 x	1.271500 =	50.860000	
326		1.000000 x	103.360000 =	103.360000	
116		8.000000 x	23.647167 =	189.177336	
213		2.000000 x	4.550000 =	9.100000	
			=	352.497336	
			H. . =	387.747070	
413	413				
211		15.000000 x	1.271500 =	19.072500	
213		1.500000 x	4.550000 =	6.825000	
327		1.000000 x	4.530000 =	4.530000	
118		3.000000 x	21.561131 =	64.683393	
112		3.000000 x	17.205541 =	51.616623	
			=	146.727516	
			H. . =	161.400268	
501	501				
211		170.000000 x	1.271500 =	216.155000	
351		1.000000 x	451.770000 =	451.770000	
380		1.000000 x	568.910000 =	568.910000	
213		3.000000 x	4.550000 =	13.650000	
			=	1,250.485000	
			H. . =	1,375.533500	

508	508			
358		1.000000 x	46.930000 =	46.930000
387		1.000000 x	74.960000 =	74.960000

			=	121.890000

			H. . =	127.984500
509	509			
359		1.000000 x	97.290000 =	97.290000
388		1.000000 x	74.960000 =	74.960000

			=	172.250000

			H. . =	180.862500
510	510			
360		1.000000 x	102.460000 =	102.460000
389		1.000000 x	74.960000 =	74.960000

			=	177.420000

			H. . =	186.291000
511	511			
509		.800000 x	180.862500 =	144.690000

			H. . =	144.690000
512	512			
501		.600000 x	1,375.533500 =	825.320100

			H. . =	825.320100
513	513			
363		1.000000 x	102.610000 =	102.610000
123		8.000000 x	63.844308 =	510.754464
121		8.000000 x	16.419380 =	131.355040
122		8.000000 x	13.377245 =	107.017960

			H. . =	851.737464
1111A	1111A			
214		.200000 x	1.949500 =	.389900
511		.020000 x	144.690000 =	2.893800
405		.020000 x	588.634407 =	11.772688
513		.020000 x	851.737464 =	17.034749

			B.T =	32.091137

1111B	1111B			
501		1.000000 x	1,375.533500 =	1,375.533500
506		1.000000 x	559.845000 =	559.845000
509		2.000000 x	180.862500 =	361.725000

			=	2,297.103500
	B.T =	.002500 x	2,297.103500 =	5.742759

1112A	1112A			
506		1.000000 x	559.845000 =	559.845000
512		1.000000 x	825.320100 =	825.320100

			=	1,385.165100
	B.T =	.025000 x	1,385.165100 =	34.629128

1112B	1112B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.205541 =	4.301385
511		.035000 x	144.690000 =	5.064150
513		.035000 x	851.737464 =	29.810811
405		.025000 x	588.634407 =	14.715860

			B.T =	54.282107
1113B	1113B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
1114A	1114A			
112		.250000 x	17.205541 =	4.301385
506		.033000 x	559.845000 =	18.474885
512		.033000 x	825.320100 =	27.235563

			B.T =	50.011834
1114B	1114B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.290479 =	10.145240
405		.020000 x	588.634407 =	11.772688

			B.T =	22.210353
1121B	1121B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
1122A	1122A			
506		1.000000 x	559.845000 =	559.845000
512		1.000000 x	825.320100 =	825.320100
			=	1,385.165100
	B.T =	.012500 x	1,385.165100 =	17.314564

1122B	1122B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
1123A	1123A			
214		.150000 x	1.949500 =	.292425
112		.150000 x	17.205541 =	2.580831
405		.025000 x	588.634407 =	14.715860
115		1.000000 x	20.290479 =	20.290479

			B.T =	37.879595
1123B	1123B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
1124A	1124A			
112		.150000 x	17.205541 =	2.580831
506		.020000 x	559.845000 =	11.196900
512		.020000 x	825.320100 =	16.506402

			B.T =	30.284133
1124B	1124B			
1111B		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759

3110A 1 3110A 1

221		250.000000 x	.099900 =	24.975000
607		.500000 x	10.460957 =	5.230479
701	2	.500000 x	4.993742 =	2.496871
701	5	.250000 x	3.121088 =	.780272
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
606		.800000 x	9.540226 =	7.632181
113		1.200000 x	20.290479 =	24.348575
714		1.400000 x	7.182034 =	10.054848
407		.040000 x	726.556219 =	29.062249
319		.020000 x	22.070000 =	.441400
112		1.200000 x	17.205541 =	20.646649

B.T = 130.470518

3110A 2 3110A 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
611		.500000 x	26.060021 =	13.030011
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
714		1.400000 x	7.182034 =	10.054848
113		1.200000 x	20.290479 =	24.348575
112		1.200000 x	17.205541 =	20.646649
319		.020000 x	22.070000 =	.441400

B.T = 138.113995

3110A 3 3110A 3

221		250.000000 x	.099900 =	24.975000
112		1.200000 x	17.205541 =	20.646649
113		1.200000 x	20.290479 =	24.348575
714		1.400000 x	7.182034 =	10.054848
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.040000 x	726.556219 =	29.062249
319		.020000 x	22.070000 =	.441400

B.T = 140.286379

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
113		1.200000 x	20.290479 =	24.348575
630		.250000 x	3.228005 =	.807001
701 5		.250000 x	3.121088 =	.780272
701 4		.800000 x	4.681633 =	3.745306
701 4		.500000 x	4.681633 =	2.340817
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
407		.040000 x	726.556219 =	29.062249
112		1.200000 x	17.205541 =	20.646649
714		1.400000 x	7.182034 =	10.054848
319		.020000 x	22.070000 =	.441400
			B.T =	147.929857
3110B	3110B			
713 1		1.000000 x	5.887624 =	5.887624
704		1.000000 x	11.775247 =	11.775247
			B.T =	17.662871
3120A 1	3120A 1			
3110A 1		1.000000 x	130.470518 =	130.470518
			B.T =	130.470518
3120A 2	3120A 2			
3110A 2		1.000000 x	138.113995 =	138.113995
			B.T =	138.113995
3120A 3	3120A 3			
3110A 3		1.000000 x	140.286379 =	140.286379
			B.T =	140.286379
3120A 4	3120A 4			
3110A 4		1.000000 x	147.929857 =	147.929857
			B.T =	147.929857
3120B	3120B			
713 2		1.000000 x	6.372331 =	6.372331
705		1.000000 x	12.744661 =	12.744661
			B.T =	19.116992

3210A 1 3210A 1

111	.400000 x	15.643441 =	6.257376
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852
3110A 1	.800000 x	130.470518 =	104.376414

B.T = 119.740640

3210A 2 3210A 2

111	.400000 x	15.643441 =	6.257376
3110A 2	.800000 x	138.113995 =	110.491196
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852

B.T = 125.855422

3210A 3 3210A 3

111	.400000 x	15.643441 =	6.257376
3110A 3	.800000 x	140.286379 =	112.229103
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852

B.T = 127.593329

3210A 4 3210A 4

111	.400000 x	15.643441 =	6.257376
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852
3110A 4	.800000 x	147.929857 =	118.343886

B.T = 133.708111

3210A 5 3210A 5

111	.400000 x	15.643441 =	6.257376
3110A 1	.800000 x	130.470518 =	104.376414
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511

B.T = 118.539299

3210A 6 3210A 6

111	.400000 x	15.643441 =	6.257376
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511
3110A 2	.800000 x	138.113995 =	110.491196

B.T = 124.654081

3210A 7 3210A 7

111	.400000 x	15.643441 =	6.257376
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511
3110A 3	.800000 x	140.286379 =	112.229103

B.T = 126.391988

3210A 8 3210A 8

111	.400000 x	15.643441 =	6.257376
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511
3110A 4	.800000 x	147.929857 =	118.343886

B.T = 132.506770

3210B 3210B

713 1	1.000000 x	5.887624 =	5.887624
704	1.000000 x	11.775247 =	11.775247

B.T = 17.662871

3220A 1 3220A 1

3210A 1	1.000000 x	119.740640 =	119.740640
---------	------------	--------------	------------

B.T = 119.740640

3220A 2 3220A 2

3210A 2	1.000000 x	125.855422 =	125.855422
---------	------------	--------------	------------

B.T = 125.855422

3220A 3 3220A 3

3210A 3	1.000000 x	127.593329 =	127.593329
---------	------------	--------------	------------

B.T = 127.593329

3220A 4 3220A 4

3210A 4	1.000000 x	133.708111 =	133.708111
---------	------------	--------------	------------

B.T = 133.708111

3220A 5 3220A 5

3210A 5	1.000000 x	118.539299 =	118.539299
---------	------------	--------------	------------

B.T = 118.539299

3220A 6 3220A 6

3210A 6 1.000000 x 124.654081 = 124.654081

B.T = 124.654081

3220A 7 3220A 7

3210A 7 1.000000 x 126.391988 = 126.391988

B.T = 126.391988

3220A 8 3220A 8

3210A 8 1.000000 x 132.506770 = 132.506770

B.T = 132.506770

3220B 3220B

713 2 1.000000 x 6.372331 = 6.372331

705 1.000000 x 12.744661 = 12.744661

B.T = 19.116992

3300A 1 3300A 1

221 300.000000 x .099900 = 29.970000

701 5 .250000 x 3.121088 = .780272

701 2 .500000 x 4.993742 = 2.496871

701 2 .800000 x 4.993742 = 3.994994

630 .250000 x 3.228005 = .807001

607 .500000 x 10.460957 = 5.230479

606 .800000 x 9.540226 = 7.632181

407 .040000 x 726.556219 = 29.062249

714 2.600000 x 7.182034 = 18.673288

113 2.000000 x 20.290479 = 40.580958

111 2.700000 x 15.643441 = 42.237291

319 .040000 x 22.070000 = .882800

B.T = 182.348383

3300A 2 3300A 2

221 300.000000 x .099900 = 29.970000

111 2.700000 x 15.643441 = 42.237291

714 2.600000 x 7.182034 = 18.673288

701 5 .250000 x 3.121088 = .780272

701 4 .500000 x 4.681633 = 2.340817

701 2 .800000 x 4.993742 = 3.994994

630 .250000 x 3.228005 = .807001

611 .500000 x 26.060021 = 13.030011

606 .800000 x 9.540226 = 7.632181

407 .040000 x 726.556219 = 29.062249

113 2.000000 x 20.290479 = 40.580958

319 .040000 x 22.070000 = .882800

B.T = 189.991861

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
630		.250000 x	3.228005 =	.807001
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
607		.500000 x	10.460957 =	5.230479
610		.800000 x	22.122162 =	17.697730
407		.040000 x	726.556219 =	29.062249
113		2.000000 x	20.290479 =	40.580958
714		2.600000 x	7.182034 =	18.673288
111		2.700000 x	15.643441 =	42.237291
319		.040000 x	22.070000 =	.882800

B.T =

192.164245

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	4	.500000 x	4.681633 =	2.340817
630		.250000 x	3.228005 =	.807001
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
407		.040000 x	726.556219 =	29.062249
714		2.600000 x	7.182034 =	18.673288
113		2.000000 x	20.290479 =	40.580958
111		2.700000 x	15.643441 =	42.237291
319		.040000 x	22.070000 =	.882800

B.T =

199.807722

3300B 1

3300B 1

713	1	1.000000 x	5.887624 =	5.887624
704		1.000000 x	11.775247 =	11.775247

B.T =

17.662871

3300B 2

3300B 2

713	2	1.000000 x	6.372331 =	6.372331
705		1.000000 x	12.744661 =	12.744661

B.T =

19.116992

3400A 1 3400A 1

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.894300 =	4.471500
111		2.700000 x	15.643441 =	42.237291
112		1.000000 x	17.205541 =	17.205541
113		2.000000 x	20.290479 =	40.580958
701	5	.250000 x	3.121088 =	.780272
701	2	.800000 x	4.993742 =	3.994994
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
607		.500000 x	10.460957 =	5.230479
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
113		.500000 x	20.290479 =	10.145240
319		.030000 x	22.070000 =	.662100

B.T = 195.276675

3400A 2 3400A 2

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.894300 =	4.471500
611		.500000 x	26.060021 =	13.030011
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
113		2.000000 x	20.290479 =	40.580958
113		.500000 x	20.290479 =	10.145240
112		1.000000 x	17.205541 =	17.205541
111		2.700000 x	15.643441 =	42.237291
319		.030000 x	22.070000 =	.662100

B.T = 202.920153

3400A 3 3400A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.040000 x	726.556219 =	29.062249
113		2.000000 x	20.290479 =	40.580958
113		.500000 x	20.290479 =	10.145240
112		1.000000 x	17.205541 =	17.205541
111		2.700000 x	15.643441 =	42.237291
319		.030000 x	22.070000 =	.662100
255		5.000000 x	.894300 =	4.471500

B.T = 205.092537

3400A 4 3400A 4

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.894300 =	4.471500
319		.030000 x	22.070000 =	.662100
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	4	.500000 x	4.681633 =	2.340817
630		.250000 x	3.228005 =	.807001
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
407		.040000 x	726.556219 =	29.062249
113		2.000000 x	20.290479 =	40.580958
113		.500000 x	20.290479 =	10.145240
112		1.000000 x	17.205541 =	17.205541
111		2.700000 x	15.643441 =	42.237291

B.T = 212.736014

3400B 1 3400B 1

704		1.000000 x	11.775247 =	11.775247
-----	--	------------	-------------	-----------

B.T = 11.775247

3400B 2 3400B 2

705		1.000000 x	12.744661 =	12.744661
-----	--	------------	-------------	-----------

B.T = 12.744661

4110A 1 4110A 1

221		350.000000 x	.099900 =	34.965000
113		1.500000 x	20.290479 =	30.435719
407		.070000 x	726.556219 =	50.858935
606		.800000 x	9.540226 =	7.632181
607		.500000 x	10.460957 =	5.230479
701	5	.100000 x	3.121088 =	.312109
701	2	.800000 x	4.993742 =	3.994994
701	2	.500000 x	4.993742 =	2.496871
630		.100000 x	3.228005 =	.322801
111		4.000000 x	15.643441 =	62.573764

B.T = 198.822851

4110A 2 4110A 2

221		350.000000 x	.099900 =	34.965000
407		.070000 x	726.556219 =	50.858935
701	5	.100000 x	3.121088 =	.312109
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.100000 x	3.228005 =	.322801
611		.500000 x	26.060021 =	13.030011
606		.800000 x	9.540226 =	7.632181
113		1.500000 x	20.290479 =	30.435719
111		4.000000 x	15.643441 =	62.573764

B.T = 206.466329

4110A 3 4110A 3

221		350.000000 x	.099900 =	34.965000
701	5	.100000 x	3.121088 =	.312109
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.100000 x	3.228005 =	.322801
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.070000 x	726.556219 =	50.858935
113		1.500000 x	20.290479 =	30.435719
111		4.000000 x	15.643441 =	62.573764

B.T = 208.638713

4110A 4 4110A 4

221		350.000000 x	.099900 =	34.965000
407		.070000 x	726.556219 =	50.858935
611		.500000 x	26.060021 =	13.030011
701	5	.100000 x	3.121088 =	.312109
701	4	.800000 x	4.681633 =	3.745306
701	4	.500000 x	4.681633 =	2.340817
630		.100000 x	3.228005 =	.322801
610		.800000 x	22.122162 =	17.697730
111		4.000000 x	15.643441 =	62.573764
113		1.500000 x	20.290479 =	30.435719

B.T = 216.282190

4110B 4110B

112		8.000000 x	17.205541 =	137.644328
513		1.000000 x	851.737464 =	851.737464
508		1.000000 x	127.984500 =	127.984500
506		1.000000 x	559.845000 =	559.845000

B.T = 1,677.211292

4120A 1 4120A 1

221		350.000000 x	.099900 =	34.965000
701	2	1.200000 x	4.993742 =	5.992490
607		1.200000 x	10.460957 =	12.553148
112		5.000000 x	17.205541 =	86.027705
263		42.000000 x	.640000 =	26.880000

B.T = 166.418344

4120A 2 4120A 2

221		350.000000 x	.099900 =	34.965000
701	4	1.200000 x	4.681633 =	5.617960
611		1.200000 x	26.060021 =	31.272025
263		42.000000 x	.640000 =	26.880000
112		5.000000 x	17.205541 =	86.027705

B.T = 184.762690

4120B 4120B

4110B		.040000 x	1,677.211292 =	67.088452
-------	--	-----------	----------------	-----------

B.T = 67.088452

4130A 1 4130A 1

221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.643441 =	31.286882
701	2	.500000 x	4.993742 =	2.496871
701	2	.800000 x	4.993742 =	3.994994
607		.500000 x	10.460957 =	5.230479
606		.800000 x	9.540226 =	7.632181
407		.050000 x	726.556219 =	36.327811
263		42.000000 x	.640000 =	26.880000

B.T = 148.814217

4130A 2 4130A 2

221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.643441 =	31.286882
407		.050000 x	726.556219 =	36.327811
606		.800000 x	9.540226 =	7.632181
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
611		.500000 x	26.060021 =	13.030011
263		42.000000 x	.640000 =	26.880000

B.T = 156.457694

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.640000 =	26.880000
701 4		.800000 x	4.681633 =	3.745306
701 2		.500000 x	4.993742 =	2.496871
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.050000 x	726.556219 =	36.327811
111		2.000000 x	15.643441 =	31.286882

B.T = 158.630078

4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.681633 =	2.340817
701 4		.800000 x	4.681633 =	3.745306
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
407		.050000 x	726.556219 =	36.327811
111		2.000000 x	15.643441 =	31.286882
263		42.000000 x	.640000 =	26.880000

B.T = 166.273556

4130B	4130B			
4120B		1.000000 x	67.088452 =	67.088452

B.T = 67.088452

4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.121088 =	.468163
701 2		.300000 x	4.993742 =	1.498123
701 2		1.050000 x	4.993742 =	5.243429
630		.150000 x	3.228005 =	.484201
607		.300000 x	10.460957 =	3.138287
601		1.050000 x	23.465162 =	24.638420
222		10.000000 x	.070000 =	.700000

B.T = 42.664123

4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.121088 =	.468163
701 4		.300000 x	4.681633 =	1.404490
630		.150000 x	3.228005 =	.484201
611		.300000 x	26.060021 =	7.818006
601		1.050000 x	23.465162 =	24.638420
701 2		1.050000 x	4.993742 =	5.243429
222		10.000000 x	.070000 =	.700000

B.T = 47.250209

4210A 3 4210A 3

221	65.000000 x	.099900 =	6.493500
607	.300000 x	10.460957 =	3.138287
701 5	.150000 x	3.121088 =	.468163
701 2	.300000 x	4.993742 =	1.498123
701 2	1.050000 x	4.993742 =	5.243429
630	.150000 x	3.228005 =	.484201
609	1.050000 x	19.710971 =	20.696520
222	10.000000 x	.070000 =	.700000

B.T = 38.722222

4210A 4 4210A 4

221	65.000000 x	.099900 =	6.493500
222	10.000000 x	.070000 =	.700000
701 2	1.050000 x	4.993742 =	5.243429
701 5	.150000 x	3.121088 =	.468163
701 4	.300000 x	4.681633 =	1.404490
609	1.050000 x	19.710971 =	20.696520
630	.150000 x	3.228005 =	.484201
611	.300000 x	26.060021 =	7.818006

B.T = 43.308309

4210B 4210B

111	4.000000 x	15.643441 =	62.573764
113	2.500000 x	20.290479 =	50.726198
112	.200000 x	17.205541 =	3.441108
112	1.500000 x	17.205541 =	25.808312

B.T = 142.549381

4220A 1 4220A 1

221	200.000000 x	.099900 =	19.980000
701 2	.800000 x	4.993742 =	3.994994
701 2	.500000 x	4.993742 =	2.496871
630	.250000 x	3.228005 =	.807001
607	.500000 x	10.460957 =	5.230479
606	.800000 x	9.540226 =	7.632181
407	.040000 x	726.556219 =	29.062249
113	1.000000 x	20.290479 =	20.290479
111	1.200000 x	15.643441 =	18.772129
701 5	.250000 x	3.121088 =	.780272

B.T = 109.046654

4220A 2 4220A 2

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.643441 =	18.772129
113		1.000000 x	20.290479 =	20.290479
611		.500000 x	26.060021 =	13.030011
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249

B.T =

116.690132

4220A 3 4220A 3

221		200.000000 x	.099900 =	19.980000
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
111		1.200000 x	15.643441 =	18.772129
407		.040000 x	726.556219 =	29.062249
113		1.000000 x	20.290479 =	20.290479

B.T =

118.862516

4220A 4 4220A 4

221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.643441 =	18.772129
407		.040000 x	726.556219 =	29.062249
611		.500000 x	26.060021 =	13.030011
701	4	.500000 x	4.681633 =	2.340817
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
113		1.000000 x	20.290479 =	20.290479

B.T =

126.505993

4300A 1 4300A 1

221		350.000000 x	.099900 =	34.965000
701	5	.250000 x	3.121088 =	.780272
701	2	.800000 x	4.993742 =	3.994994
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
607		.500000 x	10.460957 =	5.230479
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882

= 148.863842

B.T = .200000 x 148.863842 = 29.772768

4300A 2 4300A 2

221		350.000000 x	.099900 =	34.965000
611		.500000 x	26.060021 =	13.030011
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882

= 156.507319

B.T = .200000 x 156.507319 = 31.301464

4300A 3 4300A 3

221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.643441 =	31.286882
113		1.200000 x	20.290479 =	24.348575
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339

= 158.679703

B.T = .200000 x 158.679703 = 31.735941

4300A 4 4300A 4

221		350.000000 x	.099900 =	34.965000
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575
610		.800000 x	22.122162 =	17.697730
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	4	.500000 x	4.681633 =	2.340817
630		.250000 x	3.228005 =	.807001
611		.500000 x	26.060021 =	13.030011
111		2.000000 x	15.643441 =	31.286882
407		.040000 x	726.556219 =	29.062249

			=	166.323181
B.T =		.200000 x	166.323181 =	33.264636

4300B 4300B

221		2.000000 x	.099900 =	.199800
112		.400000 x	17.205541 =	6.882216
262		4.000000 x	.980000 =	3.920000

			B.T =	11.002016
--	--	--	-------	-----------

601 601

111		1.500000 x	15.643441 =	23.465162
-----	--	------------	-------------	-----------

			B.T =	23.465162
--	--	--	-------	-----------

602 602

403		.002500 x	677.793037 =	1.694483
-----	--	-----------	--------------	----------

			B.T =	1.694483
--	--	--	-------	----------

603 603

111		.300000 x	15.643441 =	4.693032
401		.001000 x	937.625053 =	.937625
412		.003300 x	387.747070 =	1.279565

			B.T =	6.910223
--	--	--	-------	----------

604 604

111		.200000 x	15.643441 =	3.128688
412		.004000 x	387.747070 =	1.550988
404		.005000 x	454.734157 =	2.273671
401		.001100 x	937.625053 =	1.031388

			B.T =	7.984735
--	--	--	-------	----------

605	605			
112		.100000 x	17.205541 =	1.720554
401		.001000 x	937.625053 =	.937625
402		.006200 x	915.781148 =	5.677843
412		.004000 x	387.747070 =	1.550988
406		.006200 x	421.768714 =	2.614966

B.T = 12.501977

606	606			
111		.100000 x	15.643441 =	1.564344
404		.005000 x	454.734157 =	2.273671
412		.005000 x	387.747070 =	1.938735
406		.006700 x	421.768714 =	2.825850
401		.001000 x	937.625053 =	.937625

B.T = 9.540226

607	607			
111		.100000 x	15.643441 =	1.564344
412		.005000 x	387.747070 =	1.938735
406		.006700 x	421.768714 =	2.825850
404		.006200 x	454.734157 =	2.819352
401		.001400 x	937.625053 =	1.312675

B.T = 10.460957

608	608			
111		.100000 x	15.643441 =	1.564344
401		.002000 x	937.625053 =	1.875250
412		.005000 x	387.747070 =	1.938735
406		.006700 x	421.768714 =	2.825850
404		.012500 x	454.734157 =	5.684177

B.T = 13.888357

609	609			
214		.100000 x	1.949500 =	.194950
115		.200000 x	20.290479 =	4.058096
405		.005000 x	588.634407 =	2.943172
111		.800000 x	15.643441 =	12.514753

B.T = 19.710971

610	610			
214		.100000 x	1.949500 =	.194950
412		.005000 x	387.747070 =	1.938735
406		.005000 x	421.768714 =	2.108844
405		.005000 x	588.634407 =	2.943172
402		.010000 x	915.781148 =	9.157811
115		.200000 x	20.290479 =	4.058096
112		.100000 x	17.205541 =	1.720554
			B.T =	22.122162
611	611			
214		.100000 x	1.949500 =	.194950
112		.100000 x	17.205541 =	1.720554
405		.005000 x	588.634407 =	2.943172
412		.005000 x	387.747070 =	1.938735
406		.005000 x	421.768714 =	2.108844
402		.014300 x	915.781148 =	13.095670
115		.200000 x	20.290479 =	4.058096
			B.T =	26.060021
612	612			
214		.150000 x	1.949500 =	.292425
408		.010000 x	557.192434 =	5.571924
405		.005000 x	588.634407 =	2.943172
115		.200000 x	20.290479 =	4.058096
111		.300000 x	15.643441 =	4.693032
			=	17.558649
	B.T =	1.068000 x	17.558649 =	18.752638
613	613			
214		.150000 x	1.949500 =	.292425
409		.010000 x	626.481434 =	6.264814
405		.005000 x	588.634407 =	2.943172
115		.200000 x	20.290479 =	4.058096
111		.500000 x	15.643441 =	7.821721
			=	21.380228
	B.T =	1.282000 x	21.380228 =	27.409452
614	614			
214		.150000 x	1.949500 =	.292425
111		.500000 x	15.643441 =	7.821721
115		.200000 x	20.290479 =	4.058096
410		.010000 x	752.414934 =	7.524149
405		.005000 x	588.634407 =	2.943172
			=	22.639563
	B.T =	1.602000 x	22.639563 =	36.268579

615	615			
214		.150000 x	1.949500 =	.292425
410		.010000 x	752.414934 =	7.524149
111		.700000 x	15.643441 =	10.950409
405		.005000 x	588.634407 =	2.943172
115		.200000 x	20.290479 =	4.058096

			=	25.768251
	B.T =	1.832000 x	25.768251 =	47.207436

616	616			
214		.150000 x	1.949500 =	.292425
111		.800000 x	15.643441 =	12.514753
405		.005000 x	588.634407 =	2.943172
411		.010000 x	1,056.586934 =	10.565869
115		.200000 x	20.290479 =	4.058096

			=	30.374315
	B.T =	2.137000 x	30.374315 =	64.909911

617	617			
112		4.000000 x	17.205541 =	68.822164
513		1.000000 x	851.737464 =	851.737464
506		1.000000 x	559.845000 =	559.845000
503		1.000000 x	1,375.533500 =	1,375.533500

			=	2,855.938128
	B.T =	.006250 x	2,855.938128 =	17.849613

618	618			
112		4.000000 x	17.205541 =	68.822164
513		1.000000 x	851.737464 =	851.737464
506		1.000000 x	559.845000 =	559.845000
503		1.000000 x	1,375.533500 =	1,375.533500

			=	2,855.938128
	B.T =	.007700 x	2,855.938128 =	21.990724

619	619			
112		4.000000 x	17.205541 =	68.822164
503		1.000000 x	1,375.533500 =	1,375.533500
506		1.000000 x	559.845000 =	559.845000
513		1.000000 x	851.737464 =	851.737464

			=	2,855.938128
	B.T =	.010000 x	2,855.938128 =	28.559381

620 620

112	4.000000 x	17.205541 =	68.822164
513	1.000000 x	851.737464 =	851.737464
506	1.000000 x	559.845000 =	559.845000
503	1.000000 x	1,375.533500 =	1,375.533500

		=	2,855.938128
B.T =	.012500 x	2,855.938128 =	35.699227

621 621

112	4.000000 x	17.205541 =	68.822164
506	1.000000 x	559.845000 =	559.845000
503	1.000000 x	1,375.533500 =	1,375.533500
513	1.000000 x	851.737464 =	851.737464

		=	2,855.938128
B.T =	.016600 x	2,855.938128 =	47.408573

630 630

413	.020000 x	161.400268 =	3.228005
-----	-----------	--------------	----------

B.T = 3.228005

701 1 701 1

406	.012580 x	421.768714 =	5.305850
-----	-----------	--------------	----------

B.T = 5.305850

701 2 701 2

406	.011840 x	421.768714 =	4.993742
-----	-----------	--------------	----------

B.T = 4.993742

701 3 701 3

406	.011544 x	421.768714 =	4.868898
-----	-----------	--------------	----------

B.T = 4.868898

701 4 701 4

406	.011100 x	421.768714 =	4.681633
-----	-----------	--------------	----------

B.T = 4.681633

701 5 701 5

406	.007400 x	421.768714 =	3.121088
-----	-----------	--------------	----------

B.T = 3.121088

702	702			
112		8.000000 x	17.205541 =	137.644328
506		1.000000 x	559.845000 =	559.845000
513		.300000 x	851.737464 =	255.521239
509		2.000000 x	180.862500 =	361.725000

			=	1,314.735567
	B.T =	.002500 x	1,314.735567 =	3.286839

703	703			
112		4.000000 x	17.205541 =	68.822164
513		.300000 x	851.737464 =	255.521239
503		1.000000 x	1,375.533500 =	1,375.533500
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	559.845000 =	559.845000

			=	2,632.303903
	B.T =	.002500 x	2,632.303903 =	6.580760

704	704			
112		4.000000 x	17.205541 =	68.822164
513		.500000 x	851.737464 =	425.868732
506		1.000000 x	559.845000 =	559.845000
502		1.000000 x	1,300.513500 =	1,300.513500

			=	2,355.049396
	B.T =	.005000 x	2,355.049396 =	11.775247

705	705			
112		4.000000 x	17.205541 =	68.822164
513		.600000 x	851.737464 =	511.042478
506		1.000000 x	559.845000 =	559.845000
504		1.000000 x	1,667.484500 =	1,667.484500

			=	2,807.194142
	B.T =	.004540 x	2,807.194142 =	12.744661

706	706			
501		1.000000 x	1,375.533500 =	1,375.533500
509		2.000000 x	180.862500 =	361.725000
506		1.000000 x	559.845000 =	559.845000

			=	2,297.103500
	B.T =	.002500 x	2,297.103500 =	5.742759

707	707			
505		1.000000 x	3,304.026000 =	3,304.026000
510		2.000000 x	186.291000 =	372.582000
506		1.000000 x	559.845000 =	559.845000

			=	4,236.453000
	B.T =	.001000 x	4,236.453000 =	4.236453

708	708			
708A		1.000000 x	17.419680 =	17.419680
708B		1.000000 x	5.742759 =	5.742759

			B.T =	23.162439
708A	708A			
214		.050000 x	1.949500 =	.097475
513		.010000 x	851.737464 =	8.517375
511		.010000 x	144.690000 =	1.446900
405		.012500 x	588.634407 =	7.357930

			B.T =	17.419680
708B	708B			
706		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
709	709			
709A		1.000000 x	17.314564 =	17.314564
709B		1.000000 x	5.742759 =	5.742759

			B.T =	23.057323
709A	709A			
506		1.000000 x	559.845000 =	559.845000
512		1.000000 x	825.320100 =	825.320100

			=	1,385.165100
	B.T =	.012500 x	1,385.165100 =	17.314564

709B	709B			
706		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
710	710			
710A		1.000000 x	49.980721 =	49.980721
710B		1.000000 x	5.742759 =	5.742759

			B.T =	55.723480
710A	710A			
214		.200000 x	1.949500 =	.389900
405		.025000 x	588.634407 =	14.715860
513		.035000 x	851.737464 =	29.810811
511		.035000 x	144.690000 =	5.064150

			B.T =	49.980721

710B	710B			
706		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
711	711			
711A		1.000000 x	46.125998 =	46.125998
711B		1.000000 x	5.742759 =	5.742759

			B.T =	51.868757
711A	711A			
506		1.000000 x	559.845000 =	559.845000
512		1.000000 x	825.320100 =	825.320100

			=	1,385.165100
	B.T =	.033300 x	1,385.165100 =	46.125998

711B	711B			
706		1.000000 x	5.742759 =	5.742759

			B.T =	5.742759
712	712			
513		1.000000 x	851.737464 =	851.737464

			=	851.737464
	B.T =	.004000 x	851.737464 =	3.406950

713 1	713 1			
704		.500000 x	11.775247 =	5.887624

			B.T =	5.887624
713 2	713 2			
705		.500000 x	12.744661 =	6.372331

			B.T =	6.372331
714	714			
714A		1.000000 x	3.432432 =	3.432432
714B		1.000000 x	3.749602 =	3.749602

			B.T =	7.182034

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.205541 =	34.411082
252		1.000000 x	2.184000 =	2.184000
113		2.000000 x	20.290479 =	40.580958

			=	103.076040
	B.T =	.033300 x	103.076040 =	3.432432

714B	714B			
113		.100000 x	20.290479 =	2.029048
114		.100000 x	17.205541 =	1.720554

			B.T =	3.749602
1111	1111			
1111A		1.000000 x	32.091137 =	32.091137
1111B		1.000000 x	5.742759 =	5.742759

			T.E =	37.833896
1112	1112			
1112A		1.000000 x	34.629128 =	34.629128
1112B		1.000000 x	5.742759 =	5.742759

			T.E =	40.371887
1113	1113			
1113A		1.000000 x	54.282107 =	54.282107
1113B		1.000000 x	5.742759 =	5.742759

			T.E =	60.024866
1114	1114			
1114A		1.000000 x	50.011834 =	50.011834
1114B		1.000000 x	5.742759 =	5.742759

			T.E =	55.754593
1121	1121			
1121A		1.000000 x	22.210353 =	22.210353
1121B		1.000000 x	5.742759 =	5.742759

			T.E =	27.953112
1122	1122			
1122A		1.000000 x	17.314564 =	17.314564
1122B		1.000000 x	5.742759 =	5.742759

			T.E =	23.057323

1123	1123				
1123A		1.000000 x	37.879595 =	37.879595	
1123B		1.000000 x	5.742759 =	5.742759	

			T.E =	43.622354	
1124	1124				
1124A		1.000000 x	30.284133 =	30.284133	
1124B		1.000000 x	5.742759 =	5.742759	

			T.E =	36.026892	
1210	1210				
707		1.000000 x	4.236453 =	4.236453	

			T.E =	4.236453	
1220	1220				
708		1.000000 x	23.162439 =	23.162439	

			T.E =	23.162439	
1230	1230				
709		1.000000 x	23.057323 =	23.057323	

			T.E =	23.057323	
1311	1311				
712		.250000 x	3.406950 =	.851738	

			T.E =	.851738	
1312	1312				
712		.250000 x	3.406950 =	.851738	
701 1		1.000000 x	5.305850 =	5.305850	
602		1.000000 x	1.694483 =	1.694483	

			T.E =	7.852071	
1313	1313				
712		.250000 x	3.406950 =	.851738	
603		1.000000 x	6.910223 =	6.910223	
701 2		1.000000 x	4.993742 =	4.993742	

			T.E =	12.755703	

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.643441 =	1.564344	
712		.250000 x	3.406950 =	.851738	

			T.E =	37.416082	
1321	1321				
112		.200000 x	17.205541 =	3.441108	
701	1	1.000000 x	5.305850 =	5.305850	
602		1.000000 x	1.694483 =	1.694483	

			T.E =	10.441441	
1322	1322				
112		.200000 x	17.205541 =	3.441108	
603		1.000000 x	6.910223 =	6.910223	
701	2	1.000000 x	4.993742 =	4.993742	

			T.E =	15.345073	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.643441 =	1.564344	
112		.100000 x	17.205541 =	1.720554	

			T.E =	38.284898	
2110	2110				
712		.500000 x	3.406950 =	1.703475	
702		1.000000 x	3.286839 =	3.286839	
608		1.000000 x	13.888357 =	13.888357	
701	4	1.000000 x	4.681633 =	4.681633	

			T.E =	23.560304	
2120	2120				
712		.500000 x	3.406950 =	1.703475	
702		1.000000 x	3.286839 =	3.286839	
701	2	1.000000 x	4.993742 =	4.993742	
603		1.000000 x	6.910223 =	6.910223	

			T.E =	16.894279	
2130	2130				
712		.500000 x	3.406950 =	1.703475	
604		1.000000 x	7.984735 =	7.984735	
701	2	1.000000 x	4.993742 =	4.993742	
702		1.000000 x	3.286839 =	3.286839	

			T.E =	17.968791	

2140 2140

712		.500000 x	3.406950 =	1.703475
605		1.000000 x	12.501977 =	12.501977
702		1.000000 x	3.286839 =	3.286839
701	2	1.000000 x	4.993742 =	4.993742

T.E = 22.486033

2210 2210

712		.500000 x	3.406950 =	1.703475
609		1.050000 x	19.710971 =	20.696520
702		1.000000 x	3.286839 =	3.286839
701	2	1.000000 x	4.993742 =	4.993742

T.E = 30.680576

2220 2220

712		.500000 x	3.406950 =	1.703475
702		1.000000 x	3.286839 =	3.286839
701	2	1.000000 x	4.993742 =	4.993742
609		1.150000 x	19.710971 =	22.667617

T.E = 32.651673

2230 2230

111		.200000 x	15.643441 =	3.128688
609		1.200000 x	19.710971 =	23.653165
701	2	1.000000 x	4.993742 =	4.993742

T.E = 31.775595

2240 2240

111		.300000 x	15.643441 =	4.693032
609		1.200000 x	19.710971 =	23.653165
701	2	1.000000 x	4.993742 =	4.993742

T.E = 33.339940

2310 2310

612		1.000000 x	18.752638 =	18.752638
701	3	1.000000 x	4.868898 =	4.868898
703		1.000000 x	6.580760 =	6.580760

T.E = 30.202296

2320 2320

613		1.000000 x	27.409452 =	27.409452
703		1.000000 x	6.580760 =	6.580760
701	3	1.000000 x	4.868898 =	4.868898

T.E = 38.859110

2330	2330				
614		1.000000 x	36.268579 =	36.268579	
703		1.000000 x	6.580760 =	6.580760	
701	3	1.000000 x	4.868898 =	4.868898	

			T.E =	47.718237	
2340	2340				
615		1.000000 x	47.207436 =	47.207436	
703		1.000000 x	6.580760 =	6.580760	
701	3	1.000000 x	4.868898 =	4.868898	

			T.E =	58.657094	
2350	2350				
616		1.000000 x	64.909911 =	64.909911	
701	3	1.000000 x	4.868898 =	4.868898	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	76.359569	
2410	2410				
617		1.000000 x	17.849613 =	17.849613	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	24.430373	
2420	2420				
618		1.000000 x	21.990724 =	21.990724	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	28.571484	
2430	2430				
619		1.000000 x	28.559381 =	28.559381	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	35.140141	
2440	2440				
620		1.000000 x	35.699227 =	35.699227	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	42.279987	
2450	2450				
621		1.000000 x	47.408573 =	47.408573	
703		1.000000 x	6.580760 =	6.580760	

			T.E =	53.989333	

3110 1 3110 1

3110A 1	1.000000 x	130.470518 =	130.470518
3110B	1.000000 x	17.662871 =	17.662871

T.E = 148.133389

3110 2 3110 2

3110A 2	1.000000 x	138.113995 =	138.113995
3110B	1.000000 x	17.662871 =	17.662871

T.E = 155.776866

3110 3 3110 3

3110A 3	1.000000 x	140.286379 =	140.286379
3110B	1.000000 x	17.662871 =	17.662871

T.E = 157.949250

3110 4 3110 4

3110A 4	1.000000 x	147.929857 =	147.929857
3110B	1.000000 x	17.662871 =	17.662871

T.E = 165.592728

3120 1 3120 1

3120A 1	1.000000 x	130.470518 =	130.470518
3120B	1.000000 x	19.116992 =	19.116992

T.E = 149.587510

3120 2 3120 2

3120A 2	1.000000 x	138.113995 =	138.113995
3120B	1.000000 x	19.116992 =	19.116992

T.E = 157.230987

3120 3 3120 3

3120A 3	1.000000 x	140.286379 =	140.286379
3120B	1.000000 x	19.116992 =	19.116992

T.E = 159.403371

3120 4 3120 4

3120A 4	1.000000 x	147.929857 =	147.929857
3120B	1.000000 x	19.116992 =	19.116992

T.E = 167.046849

3210 1 3210 1

3210A 1	1.000000 x	119.740640 =	119.740640
3210B	1.000000 x	17.662871 =	17.662871

T.E = 137.403511

3210 2 3210 2

3210A 2	1.000000 x	125.855422 =	125.855422
3210B	1.000000 x	17.662871 =	17.662871

T.E = 143.518293

3210 3 3210 3

3210A 3	1.000000 x	127.593329 =	127.593329
3210B	1.000000 x	17.662871 =	17.662871

T.E = 145.256200

3210 4 3210 4

3210A 4	1.000000 x	133.708111 =	133.708111
3210B	1.000000 x	17.662871 =	17.662871

T.E = 151.370982

3210 5 3210 5

3210A 5	1.000000 x	118.539299 =	118.539299
3210B	1.000000 x	17.662871 =	17.662871

T.E = 136.202170

3210 6 3210 6

3210A 6	1.000000 x	124.654081 =	124.654081
3210B	1.000000 x	17.662871 =	17.662871

T.E = 142.316952

3210 7 3210 7

3210A 7	1.000000 x	126.391988 =	126.391988
3210B	1.000000 x	17.662871 =	17.662871

T.E = 144.054859

3210 8 3210 8

3210A 8	1.000000 x	132.506770 =	132.506770
3210B	1.000000 x	17.662871 =	17.662871

T.E = 150.169641

2 μ

2012

. 40
μ/ 20/12/2013

3220 1 3220 1

3220A 1	1.000000 x	119.740640 =	119.740640
3220B	1.000000 x	19.116992 =	19.116992

T.E = 138.857632

3220 2 3220 2

3220A 2	1.000000 x	125.855422 =	125.855422
3220B	1.000000 x	19.116992 =	19.116992

T.E = 144.972414

3220 3 3220 3

3220A 3	1.000000 x	127.593329 =	127.593329
3220B	1.000000 x	19.116992 =	19.116992

T.E = 146.710321

3220 4 3220 4

3220A 4	1.000000 x	133.708111 =	133.708111
3220B	1.000000 x	19.116992 =	19.116992

T.E = 152.825103

3220 5 3220 5

3220A 5	1.000000 x	118.539299 =	118.539299
3220B	1.000000 x	19.116992 =	19.116992

T.E = 137.656291

3220 6 3220 6

3220A 6	1.000000 x	124.654081 =	124.654081
3220B	1.000000 x	19.116992 =	19.116992

T.E = 143.771073

3220 7 3220 7

3220A 7	1.000000 x	126.391988 =	126.391988
3220B	1.000000 x	19.116992 =	19.116992

T.E = 145.508980

3220 8 3220 8

3220A 8	1.000000 x	132.506770 =	132.506770
3220B	1.000000 x	19.116992 =	19.116992

T.E = 151.623762

2 μ

2012

. 41
μ/ 20/12/2013

3300 1 3300 1

3300A 1	1.000000 x	182.348383 =	182.348383
3300B 1	1.000000 x	17.662871 =	17.662871

T.E = 200.011254

3300 2 3300 2

3300A 1	1.000000 x	182.348383 =	182.348383
3300B 2	1.000000 x	19.116992 =	19.116992

T.E = 201.465375

3300 3 3300 3

3300A 2	1.000000 x	189.991861 =	189.991861
3300B 1	1.000000 x	17.662871 =	17.662871

T.E = 207.654732

3300 4 3300 4

3300A 2	1.000000 x	189.991861 =	189.991861
3300B 2	1.000000 x	19.116992 =	19.116992

T.E = 209.108853

3300 5 3300 5

3300A 3	1.000000 x	192.164245 =	192.164245
3300B 1	1.000000 x	17.662871 =	17.662871

T.E = 209.827116

3300 6 3300 6

3300A 3	1.000000 x	192.164245 =	192.164245
3300B 2	1.000000 x	19.116992 =	19.116992

T.E = 211.281237

3300 7 3300 7

3300A 4	1.000000 x	199.807722 =	199.807722
3300B 1	1.000000 x	17.662871 =	17.662871

T.E = 217.470593

3300 8 3300 8

3300A 4	1.000000 x	199.807722 =	199.807722
3300B 2	1.000000 x	19.116992 =	19.116992

T.E = 218.924714

2 μ

2012

. 42
μ/ 20/12/2013

3400 1 3400 1

3400A 1	1.000000 x	195.276675 =	195.276675
3400B 1	1.000000 x	11.775247 =	11.775247

T.E = 207.051922

3400 2 3400 2

3400A 1	1.000000 x	195.276675 =	195.276675
3400B 2	1.000000 x	12.744661 =	12.744661

T.E = 208.021336

3400 3 3400 3

3400A 2	1.000000 x	202.920153 =	202.920153
3400B 1	1.000000 x	11.775247 =	11.775247

T.E = 214.695400

3400 4 3400 4

3400A 2	1.000000 x	202.920153 =	202.920153
3400B 2	1.000000 x	12.744661 =	12.744661

T.E = 215.664814

3400 5 3400 5

3400A 3	1.000000 x	205.092537 =	205.092537
3400B 1	1.000000 x	11.775247 =	11.775247

T.E = 216.867784

3400 6 3400 6

3400A 3	1.000000 x	205.092537 =	205.092537
3400B 2	1.000000 x	12.744661 =	12.744661

T.E = 217.837198

3400 7 3400 7

3400A 4	1.000000 x	212.736014 =	212.736014
3400B 1	1.000000 x	11.775247 =	11.775247

T.E = 224.511261

3400 8 3400 8

3400A 4	1.000000 x	212.736014 =	212.736014
3400B 2	1.000000 x	12.744661 =	12.744661

T.E = 225.480675

2 μ

2012

. 43
μ/ 20/12/2013

4110 1 4110 1

4110A 1	1.000000 x	198.822851 =	198.822851
4110B	.025000 x	1,677.211292 =	41.930282

T.E = 240.753133

4110 2 4110 2

4110A 2	1.000000 x	206.466329 =	206.466329
4110B	.025000 x	1,677.211292 =	41.930282

T.E = 248.396611

4110 3 4110 3

4110A 3	1.000000 x	208.638713 =	208.638713
4110B	.025000 x	1,677.211292 =	41.930282

T.E = 250.568995

4110 4 4110 4

4110A 4	1.000000 x	216.282190 =	216.282190
4110B	.025000 x	1,677.211292 =	41.930282

T.E = 258.212472

4120 1 4120 1

4120A 1	1.000000 x	166.418344 =	166.418344
4120B	1.000000 x	67.088452 =	67.088452

T.E = 233.506796

4120 2 4120 2

4120A 2	1.000000 x	184.762690 =	184.762690
4120B	1.000000 x	67.088452 =	67.088452

T.E = 251.851142

4130 1 4130 1

4130A 1	1.000000 x	148.814217 =	148.814217
4130B	1.000000 x	67.088452 =	67.088452

T.E = 215.902669

4130 2 4130 2

4130A 2	1.000000 x	156.457694 =	156.457694
4130B	1.000000 x	67.088452 =	67.088452

T.E = 223.546146

4130 3	4130 3				
4130A 3		1.000000 x	158.630078 =	158.630078	
4130B		1.000000 x	67.088452 =	67.088452	

			T.E =	225.718530	
4130 4	4130 4				
4130A 4		1.000000 x	166.273556 =	166.273556	
4130B		1.000000 x	67.088452 =	67.088452	

			T.E =	233.362008	
4210 1	4210 1				
4210A 1		1.000000 x	42.664123 =	42.664123	
4210B		1.000000 x	142.549381 =	142.549381	

			T.E =	185.213504	
4210 2	4210 2				
4210A 2		1.000000 x	47.250209 =	47.250209	
4210B		1.000000 x	142.549381 =	142.549381	

			T.E =	189.799590	
4210 3	4210 3				
4210A 3		1.000000 x	38.722222 =	38.722222	
4210B		1.000000 x	142.549381 =	142.549381	

			T.E =	181.271603	
4210 4	4210 4				
4210A 4		1.000000 x	43.308309 =	43.308309	
4210B		1.000000 x	142.549381 =	142.549381	

			T.E =	185.857690	
4220B 1	4220B 1				
319		.020000 x	22.070000 =	.441400	
701 2		.320000 x	4.993742 =	1.597997	
601		.320000 x	23.465162 =	7.508852	
4220A 1		.800000 x	109.046654 =	87.237323	
714		1.150000 x	7.182034 =	8.259339	
111		.400000 x	15.643441 =	6.257376	

			T.E =	111.302288	

4220B 2 4220B 2

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.643441 =	6.257376
714	1.150000 x	7.182034 =	8.259339
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852
4220A 2	.800000 x	116.690132 =	93.352106

T.E = 117.417070

4220B 3 4220B 3

319	.020000 x	22.070000 =	.441400
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852
111	.400000 x	15.643441 =	6.257376
4220A 3	.800000 x	118.862516 =	95.090013
714	1.150000 x	7.182034 =	8.259339

T.E = 119.154978

4220B 4 4220B 4

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.643441 =	6.257376
4220A 4	.800000 x	126.505993 =	101.204794
701 2	.320000 x	4.993742 =	1.597997
601	.320000 x	23.465162 =	7.508852
714	1.150000 x	7.182034 =	8.259339

T.E = 125.269759

4220B 5 4220B 5

319	.020000 x	22.070000 =	.441400
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511
4220A 1	.800000 x	109.046654 =	87.237323
714	1.150000 x	7.182034 =	8.259339
111	.400000 x	15.643441 =	6.257376

T.E = 110.100947

4220B 6 4220B 6

319	.020000 x	22.070000 =	.441400
111	.400000 x	15.643441 =	6.257376
714	1.150000 x	7.182034 =	8.259339
701 2	.320000 x	4.993742 =	1.597997
609	.320000 x	19.710971 =	6.307511
4220A 2	.800000 x	116.690132 =	93.352106

T.E = 116.215729

4220B 7 4220B 7

319		.020000 x	22.070000 =	.441400
701	2	.320000 x	4.993742 =	1.597997
609		.320000 x	19.710971 =	6.307511
111		.400000 x	15.643441 =	6.257376
4220A	3	.800000 x	118.862516 =	95.090013
714		1.150000 x	7.182034 =	8.259339

T.E = 117.953636

4220B 8 4220B 8

319		.020000 x	22.070000 =	.441400
111		.400000 x	15.643441 =	6.257376
4220A	4	.800000 x	126.505993 =	101.204794
701	2	.320000 x	4.993742 =	1.597997
609		.320000 x	19.710971 =	6.307511
714		1.150000 x	7.182034 =	8.259339

T.E = 124.068418

4230 1 4230 1

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.121088 =	.780272
701	2	.500000 x	4.993742 =	2.496871
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
607		.500000 x	10.460957 =	5.230479
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882
319		.020000 x	22.070000 =	.441400

T.E = 139.315242

4230 2 4230 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.643441 =	31.286882
407		.040000 x	726.556219 =	29.062249
611		.500000 x	26.060021 =	13.030011
606		.800000 x	9.540226 =	7.632181
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575

T.E = 146.958719

4230 3 4230 3

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882

T.E = 149.131103

4230 4 4230 4

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	4	.800000 x	4.681633 =	3.745306
630		.250000 x	3.228005 =	.807001
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.290479 =	24.348575
407		.040000 x	726.556219 =	29.062249
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
714		1.150000 x	7.182034 =	8.259339
111		2.000000 x	15.643441 =	31.286882

T.E = 156.774581

4240 1 4240 1

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.121088 =	.780272
701	2	.500000 x	4.993742 =	2.496871
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
607		.500000 x	10.460957 =	5.230479
606		.800000 x	9.540226 =	7.632181
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882
319		.020000 x	22.070000 =	.441400

T.E = 144.310242

4240 2 4240 2

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	2	.800000 x	4.993742 =	3.994994
630		.250000 x	3.228005 =	.807001
319		.020000 x	22.070000 =	.441400
111		2.000000 x	15.643441 =	31.286882
407		.040000 x	726.556219 =	29.062249
611		.500000 x	26.060021 =	13.030011
606		.800000 x	9.540226 =	7.632181
714		1.150000 x	7.182034 =	8.259339
113		1.200000 x	20.290479 =	24.348575

T.E = 151.953719

4240 3 4240 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.121088 =	.780272
701	4	.800000 x	4.681633 =	3.745306
701	2	.500000 x	4.993742 =	2.496871
630		.250000 x	3.228005 =	.807001
610		.800000 x	22.122162 =	17.697730
607		.500000 x	10.460957 =	5.230479
407		.040000 x	726.556219 =	29.062249
714		1.150000 x	7.182034 =	8.259339
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.290479 =	24.348575
111		2.000000 x	15.643441 =	31.286882

T.E = 154.126103

4240 4 4240 4

221		300.000000 x	.099900 =	29.970000
319		.020000 x	22.070000 =	.441400
113		1.200000 x	20.290479 =	24.348575
714		1.150000 x	7.182034 =	8.259339
701	5	.250000 x	3.121088 =	.780272
701	4	.500000 x	4.681633 =	2.340817
701	4	.800000 x	4.681633 =	3.745306
630		.250000 x	3.228005 =	.807001
611		.500000 x	26.060021 =	13.030011
610		.800000 x	22.122162 =	17.697730
407		.040000 x	726.556219 =	29.062249
111		2.000000 x	15.643441 =	31.286882

T.E = 161.769581

4300 1 4300 1

4300A	1	1.000000 x	29.772768 =	29.772768
4300B		1.000000 x	11.002016 =	11.002016

T.E = 40.774784

2 μ

2012

. 49
μ/ 20/12/2013

4300 2 4300 2

4300A 2
4300B

1.000000 x
1.000000 x

31.301464 =
11.002016 =

31.301464
11.002016

T.E =

42.303480

4300 3 4300 3

4300A 3
4300B

1.000000 x
1.000000 x

31.735941 =
11.002016 =

31.735941
11.002016

T.E =

42.737957

4300 4 4300 4

4300A 4
4300B

1.000000 x
1.000000 x

33.264636 =
11.002016 =

33.264636
11.002016

T.E =

44.266652

4400 4400

251
113

1.050000 x
.050000 x

.559100 =
20.290479 =

.587055
1.014524

T.E =

1.601579

4500 4500

251
114
113

1.050000 x
.100000 x
.100000 x

.559100 =
17.205541 =
20.290479 =

.587055
1.720554
2.029048

T.E =

4.336657

4600 4600

256
113

1.000000 x
.100000 x

4.300000 =
20.290479 =

4.300000
2.029048

T.E =

6.329048

4700 4700

253
113

1.000000 x
.100000 x

4.500000 =
20.290479 =

4.500000
2.029048

T.E =

6.529048