

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών

1ο Τρίμηνο του 2012

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
008	16.777917
009	.074800
011	55.210000
012	4.530000
013	27.370000
014	268.420000
015	206.720000
016	32.560000
017	380.180000
018.1	2.990000
018.2	4.530000
019.1	2.990000
019.2	4.530000
021	2.670000
022	.070000
024	45.000000
026	.099900
027	.119300
029	.151500
032	36.000000
035	.088300
036	.090700
040	.210000
051	14.630000
052	14.630000
053	.085000
054	.085000
055	.090000
056	10.050000
057	10.050000
058	8.630000
061	12.880000
062	12.880000
065	12.280000
066	35.000000
067	45.500000
081	10.460000
101	
102	
111	.075900
112	.083300
113	.570000
114	
116	.086700
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.620000
132	.800000
142	.385000

146	.415000
155	2.233400
161	6.360000
163	6.550000
164	
165	
166	
173	.256100
181	
201	290.000000
203.2	370.000000
203.4	290.000000
205	480.000000
208	1,435.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,550.000000
223.4	1,600.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	1.550000
237	1.850000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.000000
246	13.000000
249	20.000000
251	.895000
252	2.184000
253	2.758000
254	3.532000
258	8.017500
259	25.542500
260	.558700
261	.611600
262	.558700
264	1.115900
265	.847400
266	.632700

267	.910400
268	1.054400
271	1.000400
272	.905900
273	1.112900
274	1.372600
276	.785700
277	1.009400
278	4.120200
279	4.257500
280	1.144500
281	6.615200
282	.977800
283	1.305700
284	
285	.078500
286	1.832700
288	1.989100
289	.904700
290	3.670000
291	4.500000
293	
294	3.518600
295	6.490000
296	12.470000
297.2	
298.1	7.120000
298.2	5.760000
321	
322	99.620000
323	113.850000
326	57.180000
327.1	
327.2	
327.3	176.980000
328	
331	76.850000
332	79.680000
333	111.570000
334	119.540000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.735200
352	1.133000
354	.985400
356	.661600
357	1.441300
358	3.338500
360	14.938000
361	1.249900
362	1.397000
363	1.779400
364	1.133000
366	5.000500
370	.294100
371	1.779400

372	2.470800
373	2.735500
375	3.470900
376	.220400
377	.926400
378	14.950000
379	27.450000
380	16.560000
381	74.770000
386	28.630000
388	48.870000
390	1.500000
392	27.420000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.077700
442	.121800
443	1.987900
444	2.207500
445	1.600000
446	2.662500
447	4.525500
450	2.842800
451	1.214200
453	.085000
455	3.090000
456	1.658300
457	.827900
458	5.280000
459	5.280000
460	4.377500
462	
463	4.089100
464	3.630000
465	6.180000
467	3.397500
471	3.960000
473	2.832500
474	3.883100
475	6.416900
476	2.437300
477	
478	3.060000
479	1.876600
480	

481	5.467500
482	1.434100
483	.167500
484	4.550000
485	1.243100
487	13.884000
488	5.500000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	.887400
498	.991400
499	1.359000
500	1.998800
501	2.700000
502	3.780000
503	.887400
504	1.175100
505	19.170000
506	1.431700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.437500
514	42.680000
515	43.500000
519	50.290000
520	41.070000
521	2.461700
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.600000
536	2.500000
537	1.700000
565.3	3.800000
565.5	5.650000
565.6	7.800000
566.3	5.050000
566.5	7.750000
566.6	10.300000

1101	1101			
001		.500000 x	15.741598 =	7.870799
			B.T =	7.870799
1102	1102			
001		1.000000 x	15.741598 =	15.741598
			B.T =	15.741598
1103	1103			
001		.300000 x	15.741598 =	4.722479
			B.T =	4.722479
1104	1104			
015		1.000000 x	206.720000 =	206.720000
291		2.200000 x	4.500000 =	9.900000
004		7.000000 x	23.886192 =	167.203344
	δδδδδ	7.000000 x	17.312112 =	121.184784
484		5.250000 x	4.550000 =	23.887500
485		83.000000 x	1.243100 =	103.177300
			AΘΡΟΙΣΜΑ =	632.072928
	B.T =	.004000 x	632.072928 =	2.528292
1111	1111			
006		.060000 x	183.150721 =	10.989043
			B.T =	10.989043
1112	1112			
006		.090000 x	183.150721 =	16.483565
			B.T =	16.483565
1116	1116			
007		.025000 x	183.150721 =	4.578768
			B.T =	4.578768
1117	1117			
007		.110000 x	183.150721 =	20.146579
			B.T =	20.146579
1121	1121			
009		4.000000 x	.074800 =	.299200
			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000
		-----		
			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600
		-----		
			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639
		-----		
			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408
		-----		
			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617
		-----		
			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565
		-----		
			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800
		-----		
			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200
		-----		
			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000
		-----		
			B.T =	.187000



1401	1401				
021		.300000 x	2.670000 =	.801000	
040		1,150.000000 x	.210000 =	241.500000	
			B.T =	242.301000	
1407	1407				
021		1.500000 x	2.670000 =	4.005000	
022		480.000000 x	.070000 =	33.600000	
			B.T =	37.605000	
1411	1411				
021		.200000 x	2.670000 =	.534000	
051		.960000 x	14.630000 =	14.044800	
1407		.320000 x	37.605000 =	12.033600	
			B.T =	26.612400	
1412	1412				
021		.200000 x	2.670000 =	.534000	
051		.900000 x	14.630000 =	13.167000	
1407		.360000 x	37.605000 =	13.537800	
			B.T =	27.238800	
1413	1413				
021		.200000 x	2.670000 =	.534000	
051		.840000 x	14.630000 =	12.289200	
1407		.420000 x	37.605000 =	15.794100	
			B.T =	28.617300	
1416	1416				
021		.200000 x	2.670000 =	.534000	
1407		.250000 x	37.605000 =	9.401250	
051		.960000 x	14.630000 =	14.044800	
026		150.000000 x	.099900 =	14.985000	
			B.T =	38.965050	
1417	1417				
021		.200000 x	2.670000 =	.534000	
026		150.000000 x	.099900 =	14.985000	
1407		.290000 x	37.605000 =	10.905450	
051		.900000 x	14.630000 =	13.167000	
			B.T =	39.591450	

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	14.630000 =	12.289200
026		150.000000 x	.099900 =	14.985000
		-----		
			B.T =	40.969950
1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	14.630000 =	7.900200
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000
		-----		
			B.T =	
1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.088300 =	6.622500
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	14.630000 =	4.827900
039		5.000000 x	.000000 =	.000000
		-----		
			B.T =	
1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000
		-----		
			B.T =	152.456250
1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.099900 =	14.985000
		-----		
			B.T =	163.304700
1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	14.630000 =	2.926000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000
		-----		
			B.T =	126.502000

1429	1429			
021		.200000 x	2.670000 =	.534000
035		200.000000 x	.088300 =	17.660000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000
				-----
			B.T =	141.236000
1431	1431			
021		.300000 x	2.670000 =	.801000
032		.960000 x	36.000000 =	34.560000
1407		.320000 x	37.605000 =	12.033600
				-----
			B.T =	47.394600
1432	1432			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
051		.640000 x	14.630000 =	9.363200
032		.320000 x	36.000000 =	11.520000
				-----
			B.T =	33.717800
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.088300 =	97.130000
				-----
			B.T =	98.064500
1437	1437			
021		.200000 x	2.670000 =	.534000
035		75.000000 x	.088300 =	6.622500
051		.380000 x	14.630000 =	5.559400
1407		.620000 x	37.605000 =	23.315100
				-----
			B.T =	36.031000
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.099900 =	24.975000
				-----
			B.T =	27.111000
1442	1442			
021		.250000 x	2.670000 =	.667500
051		.740000 x	14.630000 =	10.826200
026		900.000000 x	.099900 =	89.910000
				-----
			B.T =	101.403700

1443	1443			
021		.250000 x	2.670000 =	.667500
051		.860000 x	14.630000 =	12.581800
026		700.000000 x	.099900 =	69.930000
-----				
			B.T =	83.179300
1444	1444			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
051		1.000000 x	14.630000 =	14.630000
-----				
			B.T =	75.237500
1445	1445			
021		.250000 x	2.670000 =	.667500
026		450.000000 x	.099900 =	44.955000
051		1.060000 x	14.630000 =	15.507800
-----				
			B.T =	61.130300
1446	1446			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.099900 =	34.965000
051		1.120000 x	14.630000 =	16.385600
-----				
			B.T =	52.018100
1447	1447			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	14.630000 =	14.630000
026		400.000000 x	.099900 =	39.960000
-----				
			B.T =	58.265900
1448	1448			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	14.630000 =	14.630000
039		5.000000 x	.000000 =	.000000
026		400.000000 x	.099900 =	39.960000
-----				
			B.T =	58.265900
1449	1449			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.099900 =	34.965000
1407		.040000 x	37.605000 =	1.504200
051		1.060000 x	14.630000 =	15.507800
-----				
			B.T =	52.644500

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000
				-----
			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.151500 =	90.900000
				-----
			B.T =	220.947750
1453				
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
026		450.000000 x	.099900 =	44.955000
				-----
			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.151500 =	68.175000
053		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250
				-----
			B.T =	210.972750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
				-----
			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
				-----
			B.T =	189.987750

1457	1457			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
029		600.000000 x	.151500 =	90.900000
		-----		
			B.T =	220.947750
1458	1458			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
028		450.000000 x	.000000 =	.000000
		-----		
			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
054		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.151500 =	68.175000
		-----		
			B.T =	210.972750
1461	1461			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.099900 =	49.950000
		-----		
			B.T =	181.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	43.500000 =	43.500000
051		.100000 x	14.630000 =	1.463000
026		400.000000 x	.099900 =	39.960000
		-----		
			B.T =	87.604250
1463	1463			
021		.300000 x	2.670000 =	.801000
051		.100000 x	14.630000 =	1.463000
1407		.050000 x	37.605000 =	1.880250
515		1.050000 x	43.500000 =	45.675000
026		250.000000 x	.099900 =	24.975000
		-----		
			B.T =	74.794250

1464	1464			
021		.200000 x	2.670000 =	.534000
519		.600000 x	50.290000 =	30.174000
1407		.120000 x	37.605000 =	4.512600
051		.420000 x	14.630000 =	6.144600
026		150.000000 x	.099900 =	14.985000
			B.T =	56.350200
1465	1465			
021		.200000 x	2.670000 =	.534000
1407		.030000 x	37.605000 =	1.128150
519		.900000 x	50.290000 =	45.261000
051		.150000 x	14.630000 =	2.194500
026		450.000000 x	.099900 =	44.955000
			B.T =	94.072650
1466	1466			
021		.200000 x	2.670000 =	.534000
1407		.030000 x	37.605000 =	1.128150
519		.840000 x	50.290000 =	42.243600
026		450.000000 x	.099900 =	44.955000
051		.210000 x	14.630000 =	3.072300
			B.T =	91.933050
1467	1467			
021		.200000 x	2.670000 =	.534000
026		450.000000 x	.099900 =	44.955000
051		.350000 x	14.630000 =	5.120500
1407		.030000 x	37.605000 =	1.128150
519		.700000 x	50.290000 =	35.203000
			B.T =	86.940650
1471	1471			
251		1.000000 x	.895000 =	.895000
351		4.000000 x	.735200 =	2.940800
358		1.000000 x	3.338500 =	3.338500
364		2.000000 x	1.133000 =	2.266000
372		.400000 x	2.470800 =	.988320
370		6.000000 x	.294100 =	1.764600
			AΘΡΟΙΣΜΑ =	12.193220
	B.T =	.476190 x	12.193220 =	5.806289

1472	1472			
251		.600000 x	.895000 =	.537000
351		2.000000 x	.735200 =	1.470400
361		1.000000 x	1.249900 =	1.249900
363		2.000000 x	1.779400 =	3.558800
372		.300000 x	2.470800 =	.741240
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	10.498140
	B.T =	.666667 x	10.498140 =	6.998763
1473	1473			
251		.500000 x	.895000 =	.447500
354		4.000000 x	.985400 =	3.941600
364		2.000000 x	1.133000 =	2.266000
372		.700000 x	2.470800 =	1.729560
370		4.000000 x	.294100 =	1.176400
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
351		4.000000 x	.735200 =	2.940800
			AΘΡΟΙΣΜΑ =	28.689760
	B.T =	.416667 x	28.689760 =	11.954076
1474	1474			
251		.500000 x	.895000 =	.447500
372		.500000 x	2.470800 =	1.235400
370		4.000000 x	.294100 =	1.176400
366		2.000000 x	5.000500 =	10.001000
361		1.000000 x	1.249900 =	1.249900
360		1.000000 x	14.938000 =	14.938000
357		4.000000 x	1.441300 =	5.765200
			AΘΡΟΙΣΜΑ =	34.813400
	B.T =	.416667 x	34.813400 =	14.505595
1475	1475			
251		.300000 x	.895000 =	.268500
379		1.000000 x	27.450000 =	27.450000
371		2.000000 x	1.779400 =	3.558800
376		160.000000 x	.220400 =	35.264000
377		6.000000 x	.926400 =	5.558400
378		1.000000 x	14.950000 =	14.950000
375		2.000000 x	3.470900 =	6.941800
354		3.000000 x	.985400 =	2.956200
			AΘΡΟΙΣΜΑ =	96.947700
	B.T =	.416667 x	96.947700 =	40.394907



1476	1476			
251		.500000 x	.895000 =	.447500
373		.200000 x	2.735500 =	.547100
370		6.000000 x	.294100 =	1.764600
352		3.000000 x	1.133000 =	3.399000
			-----	
			ΑΘΡΟΙΣΜΑ =	6.158200
	B.T =	.500000 x	6.158200 =	3.079100
			-----	
1478	1478			
251		3.000000 x	.895000 =	2.685000
372		.500000 x	2.470800 =	1.235400
356		2.000000 x	.661600 =	1.323200
370		6.000000 x	.294100 =	1.764600
			-----	
			ΑΘΡΟΙΣΜΑ =	7.008200
	B.T =	.500000 x	7.008200 =	3.504100
			-----	
1479	1479			
251		6.000000 x	.895000 =	5.370000
370		12.000000 x	.294100 =	3.529200
381		1.000000 x	74.770000 =	74.770000
			-----	
			ΑΘΡΟΙΣΜΑ =	83.669200
	B.T =	.454545 x	83.669200 =	38.031417
			-----	
1480	1480			
251		8.000000 x	.895000 =	7.160000
381		2.000000 x	74.770000 =	149.540000
370		16.000000 x	.294100 =	4.705600
			-----	
			ΑΘΡΟΙΣΜΑ =	161.405600
	B.T =	.227273 x	161.405600 =	36.683135
			-----	
1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.085000 =	.019550
487		.040000 x	13.884000 =	.555360
451		.230000 x	1.214200 =	.279266
			-----	
			B.T =	.855511
1487	1487			
443		.120000 x	1.987900 =	.238548
451		.170000 x	1.214200 =	.206414
453		.640000 x	.085000 =	.054400
446		.010000 x	2.662500 =	.026625
445		.060000 x	1.600000 =	.096000
			-----	
			B.T =	.621987

1488	1488			
444		.170000 x	2.207500 =	.375275
453		.500000 x	.085000 =	.042500
451		.170000 x	1.214200 =	.206414
446		.030000 x	2.662500 =	.079875
445		.050000 x	1.600000 =	.080000
-----				
			B.T =	.784064
1489	1489			
444		.100000 x	2.207500 =	.220750
453		.430000 x	.085000 =	.036550
451		.350000 x	1.214200 =	.424970
446		.020000 x	2.662500 =	.053250
445		.100000 x	1.600000 =	.160000
-----				
			B.T =	.895520
1490	1490			
444		.300000 x	2.207500 =	.662250
445		.100000 x	1.600000 =	.160000
446		.030000 x	2.662500 =	.079875
451		.570000 x	1.214200 =	.692094
-----				
			B.T =	1.594219
1491	1491			
444		.270000 x	2.207500 =	.596025
445		.060000 x	1.600000 =	.096000
451		.650000 x	1.214200 =	.789230
446		.020000 x	2.662500 =	.053250
-----				
			B.T =	1.534505
1492	1492			
444		.200000 x	2.207500 =	.441500
446		.030000 x	2.662500 =	.079875
445		.040000 x	1.600000 =	.064000
455		.730000 x	3.090000 =	2.255700
-----				
			B.T =	2.841075
1501	1501			
011		1.000000 x	55.210000 =	55.210000
012		2.000000 x	4.530000 =	9.060000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	1.243100 =	18.646500
484		1.750000 x	4.550000 =	7.962500
-----				
			B.T =	472.001473

1502	1502			
013		1.000000 x	27.370000 =	27.370000
005		3.500000 x	21.778427 =	76.224495
001		26.000000 x	15.741598 =	409.281548
482		15.000000 x	1.434100 =	21.511500
484		.900000 x	4.550000 =	4.095000
		-----		
			B.T =	538.482543
1503	1503			
014		1.000000 x	268.420000 =	268.420000
002		2.600000 x	17.312112 =	45.011491
004		7.000000 x	23.886192 =	167.203344
484		2.600000 x	4.550000 =	11.830000
485		44.000000 x	1.243100 =	54.696400
		-----		
			B.T =	547.161235
1504	1504			
015		1.000000 x	206.720000 =	206.720000
004		7.000000 x	23.886192 =	167.203344
002		7.000000 x	17.312112 =	121.184784
485		83.000000 x	1.243100 =	103.177300
484		5.250000 x	4.550000 =	23.887500
291		2.200000 x	4.500000 =	9.900000
		-----		
			B.T =	632.072928
1505	1505			
016		1.000000 x	32.560000 =	32.560000
004		7.000000 x	23.886192 =	167.203344
002		1.750000 x	17.312112 =	30.296196
485		17.500000 x	1.243100 =	21.754250
484		1.750000 x	4.550000 =	7.962500
		-----		
			B.T =	259.776290
1506	1506			
017		1.000000 x	380.180000 =	380.180000
002		3.500000 x	17.312112 =	60.592392
484		6.000000 x	4.550000 =	27.300000
004		7.000000 x	23.886192 =	167.203344
485		70.000000 x	1.243100 =	87.017000
		-----		
			B.T =	722.292736
2101	2101			
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	5.193634

2102	2102			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901
		-----		
			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957
		-----		
			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125
		-----		
			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293
		-----		
			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237
		-----		
			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013
		-----		
			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069
		-----		
			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181
		-----		
			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461
		-----		
			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629
		-----		
			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133
		-----		
			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637
		-----		
			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973
		-----		
			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469
		-----		
			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797
		-----		
			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965
		-----		
			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805
		-----		
			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301
		-----		
			T.E =	231.982301
2108Α	2108Α			
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	12.118478
2108Β	2108Β			
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	27.699379

2108Ε	2108Ε			
002		4.600000 x	17.312112 =	79.635715
		-----		
			T.E =	79.635715
2108Η	2108Η			
002		7.600000 x	17.312112 =	131.572051
		-----		
			T.E =	131.572051
2108Ζ	2108Ζ			
002		6.600000 x	17.312112 =	114.259939
		-----		
			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491
		-----		
			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603
		-----		
			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163
		-----		
			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827
		-----		
			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1506		.004000 x	722.292736 =	2.889171
1503		.001000 x	547.161235 =	.547161
		-----		
			T.E =	3.955696
2110	2110			
002		.040000 x	17.312112 =	.692484
1501		.005000 x	472.001473 =	2.360007
1506		.004000 x	722.292736 =	2.889171
1503		.001000 x	547.161235 =	.547161
		-----		
			T.E =	6.488824



2111	2111				
002		.100000 x	17.312112 =		1.731211
1504		.005000 x	632.072928 =		3.160365
		-----			
			T.E =		4.891576
2112	2112				
002		.120000 x	17.312112 =		2.077453
1504		.005500 x	632.072928 =		3.476401
1501		.004000 x	472.001473 =		1.888006
		-----			
			T.E =		7.441860
2113	2113				
002		1.400000 x	17.312112 =		24.236957
002		.300000 x	17.312112 =		5.193634
		-----			
			T.E =		29.430590
2114	2114				
002		1.500000 x	17.312112 =		25.968168
1501		.005000 x	472.001473 =		2.360007
002		.400000 x	17.312112 =		6.924845
		-----			
			T.E =		35.253020
2115	2115				
481		.300000 x	5.467500 =		1.640250
003		1.200000 x	20.419486 =		24.503383
1501		.011000 x	472.001473 =		5.192016
002		.600000 x	17.312112 =		10.387267
		-----			
			T.E =		41.722917
2116	2116				
2115		1.300000 x	41.722917 =		54.239792
		-----			
			T.E =		54.239792
2117	2117				
002		.600000 x	17.312112 =		10.387267
1501		.125000 x	472.001473 =		59.000184
		-----			
			T.E =		69.387451
2118	2118				
2117		1.300000 x	69.387451 =		90.203686
		-----			
			T.E =		90.203686

2121	2121			
001		.400000 x	15.741598 =	6.296639
002		1.800000 x	17.312112 =	31.161802
		-----		
			T.E =	37.458441
2122	2122			
001		.500000 x	15.741598 =	7.870799
1501		.005000 x	472.001473 =	2.360007
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	44.855030
2123	2123			
002		.200000 x	17.312112 =	3.462422
1504		.008300 x	632.072928 =	5.246205
		-----		
			T.E =	8.708628
2124	2124			
002		.200000 x	17.312112 =	3.462422
1501		.005000 x	472.001473 =	2.360007
1504		.010000 x	632.072928 =	6.320729
		-----		
			T.E =	12.143159
2125	2125			
481		.400000 x	5.467500 =	2.187000
1501		.020000 x	472.001473 =	9.440029
002		1.000000 x	17.312112 =	17.312112
003		1.500000 x	20.419486 =	30.629229
		-----		
			T.E =	59.568370
2126	2126			
2125		1.300000 x	59.568370 =	77.438881
		-----		
			T.E =	77.438881
2127	2127			
002		1.000000 x	17.312112 =	17.312112
1501		.166600 x	472.001473 =	78.635445
		-----		
			T.E =	95.947557
2128	2128			
2127		1.300000 x	95.947557 =	124.731824
		-----		
			T.E =	124.731824

2131	2131			
001		.300000 x	15.741598 =	4.722479
				-----
			T.E =	4.722479
2132	2132			
1504		.001600 x	632.072928 =	1.011317
				-----
			T.E =	1.011317
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267
				-----
			T.E =	12.118478
2134	2134			
1504		.002500 x	632.072928 =	1.580182
				-----
			T.E =	1.580182
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973
				-----
			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	44.855030 =	58.311539
				-----
			T.E =	58.311539
2135.3	2135.3			
2127		1.300000 x	95.947557 =	124.731824
				-----
			T.E =	124.731824
2135.4	2135.4			
2128		1.300000 x	124.731824 =	162.151371
				-----
			T.E =	162.151371
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715
				-----
			T.E =	82.531911

2142	2142			
001		2.000000 x	15.741598 =	31.483196
1501		.005000 x	472.001473 =	2.360007
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	95.101661
2143	2143			
481		.500000 x	5.467500 =	2.733750
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458
1501		.025000 x	472.001473 =	11.800037
		-----		
			T.E =	107.275441
2144	2144			
2143		1.300000 x	107.275441 =	139.458073
		-----		
			T.E =	139.458073
2145	2145			
001		2.000000 x	15.741598 =	31.483196
003		1.000000 x	20.419486 =	20.419486
1501		.200000 x	472.001473 =	94.400295
		-----		
			T.E =	146.302977
2146	2146			
2145		1.300000 x	146.302977 =	190.193870
		-----		
			T.E =	190.193870
2151	2151			
001		1.200000 x	15.741598 =	18.889918
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	35.225506
2152	2152			
001		1.500000 x	15.741598 =	23.612397
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	44.031883
2161	2161			
1505		.003300 x	259.776290 =	.857262
		-----		
			T.E =	.857262

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	632.072928 =	2.528292
		-----		
			T.E =	2.677892
2172	2172			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536
		-----		
			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400
		-----		
			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713
		-----		
			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600
		-----		
			T.E =	.149600
2185	2185			
018.1		.142800 x	2.990000 =	.426972
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.550000 =	.455000
482		.700000 x	1.434100 =	1.003870
018.1		.042800 x	2.990000 =	.127972
		-----		
			T.E =	10.725185
2186	2186			
018.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	4.530000 =	.193884
482		1.400000 x	1.434100 =	2.007740
484		.200000 x	4.550000 =	.910000
		-----		
			T.E =	12.469879
2187	2187			
019.1		.142800 x	2.990000 =	.426972
485		1.100000 x	1.243100 =	1.367410
019.1		.428000 x	2.990000 =	1.279720
005		.400000 x	21.778427 =	8.711371
484		.100000 x	4.550000 =	.455000
		-----		
			T.E =	12.240473
2188	2188			
019.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	1.243100 =	2.237580
484		.200000 x	4.550000 =	.910000
019.2		.042800 x	4.530000 =	.193884
		-----		
			T.E =	12.699719

2201	2201			
001		1.000000 x	15.741598 =	15.741598
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	50.365822
2202	2202			
001		1.000000 x	15.741598 =	15.741598
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	102.302158
2203	2203			
001		1.000000 x	15.741598 =	15.741598
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	59.021878
2204	2204			
001		1.000000 x	15.741598 =	15.741598
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	102.302158
2206	2206			
001		1.000000 x	15.741598 =	15.741598
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	77.000056
2207	2207			
001		1.000000 x	15.741598 =	15.741598
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	138.258514
2211	2211			
001		2.000000 x	15.741598 =	31.483196
		-----		
			T.E =	31.483196
2212	2212			
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	15.741598
2213	2213			
001		2.000000 x	15.741598 =	31.483196
		-----		
			T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379
		-----		
			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280
		-----		
			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990
		-----		
			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560
		-----		
			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344
		-----		
			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390
		-----		
			T.E =	.408390



2236	2236			
001		.100000 x	15.741598 =	1.574160
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	6.767793
2237	2237			
001		.200000 x	15.741598 =	3.148320
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	17.441960
2238	2238			
001		.100000 x	15.741598 =	1.574160
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	8.499005
2239	2239			
001		.200000 x	15.741598 =	3.148320
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	19.483908
2241	2241			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	6.764428
2242	2242			
001		.400000 x	15.741598 =	6.296639
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	9.359562
2243	2243			
001		.500000 x	15.741598 =	7.870799
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	12.975671
2246	2246			
001		.250000 x	15.741598 =	3.935400
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	4.956374

2247	2247			
001		.350000 x	15.741598 =	5.509559
003		.100000 x	20.419486 =	2.041949
-----				
			T.E =	7.551508
2248	2248			
001		.450000 x	15.741598 =	7.083719
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	11.167616
2251	2251			
001		.100000 x	15.741598 =	1.574160
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	6.767793
2252	2252			
001		.100000 x	15.741598 =	1.574160
002		.600000 x	17.312112 =	10.387267
-----				
			T.E =	11.961427
2261A	2261A			
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	8.167794
2261B	2261B			
003		.700000 x	20.419486 =	14.293640
-----				
			T.E =	14.293640
2261Γ	2261Γ			
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	18.377537
2261Δ	2261Δ			
003		1.200000 x	20.419486 =	24.503383
-----				
			T.E =	24.503383
2262A	2262A			
003		.550000 x	20.419486 =	11.230717
-----				
			T.E =	11.230717

2262B	2262B			
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178
		-----		
			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049
		-----		
			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921
		-----		
			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818
		-----		
			T.E =	46.964818
2264.2A	2264.2A			
003		2.000000 x	20.419486 =	40.838972
		-----		
			T.E =	40.838972
2264.2B	2264.2B			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561
		-----		
			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355
		-----		
			T.E =	65.342355
2264.3A	2264.3A			
003		2.400000 x	20.419486 =	49.006766
		-----		
			T.E =	49.006766
2264.3B	2264.3B			
003		2.850000 x	20.419486 =	58.195535
		-----		
			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304
		-----		
			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073
		-----		
			T.E =	76.573073
2265A	2265A			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589
				-----
			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728
				-----
			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184
				-----
			T.E =	33.079567
2266.11	2266.11			
2263Γ		1.000000 x	32.671178 =	32.671178
2263Γ		.350000 x	32.671178 =	11.434912
				-----
			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322
				-----
			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912
				-----
			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617
				-----
			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322
				-----
			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686
-----				
			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640
-----				
			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368
-----				
			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096
-----				
			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774
-----				
			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824
-----				
			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368
-----				
			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437
-----				
			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =	67.384304	
2264.3Γ		.350000 x	67.384304 =	23.584506	
			T.E =	90.968810	
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =	76.573073	
2264.3Δ		.350000 x	76.573073 =	26.800576	
			T.E =	103.373649	
2266.25	2266.25				
2265A		1.000000 x	10.209743 =	10.209743	
2265A		.350000 x	10.209743 =	3.573410	
			T.E =	13.783153	
2266.26	2266.26				
2265B		1.000000 x	16.335589 =	16.335589	
2265B		.350000 x	16.335589 =	5.717456	
			T.E =	22.053045	
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =	18.377537	
2261Γ		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =	24.503383	
2261Δ		.350000 x	24.503383 =	8.576184	
			T.E =	33.079567	
2266.5	2266.5				
2262A		1.000000 x	11.230717 =	11.230717	
2262A		.350000 x	11.230717 =	3.930751	
			T.E =	15.161468	
2266.6	2266.6				
2262B		1.000000 x	18.377537 =	18.377537	
2262B		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184
				-----
			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912
				-----
			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774
				-----
			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201
				-----
			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430
				-----
			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967
				-----
			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710
				-----
			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453
				-----
			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972
				-----
			T.E =	40.838972





2271E	2271E			
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916
		-----		
			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173
		-----		
			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098
		-----		
			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019
		-----		
			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939
		-----		
			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220
		-----		
			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299
		-----		
			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738
		-----		
			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379
		-----		
			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580
		-----		
			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631
		-----		
			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860
		-----		
			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089
		-----		
			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318
		-----		
			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330
		-----		
			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323
		-----		
			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995
		-----		
			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727
		-----		
			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459
		-----		
			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193
		-----		
			T.E =	135.381193
2274.15	2274.15			
2272E		1.300000 x	118.433019 =	153.962925
		-----		
			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657
		-----		
			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389
				-----
			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121
				-----
			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854
				-----
			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995
				-----
			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586
				-----
			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320
				-----
			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318
				-----
			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316
				-----
			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313
				-----
			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661
				-----
			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327
				-----
			T.E =	106.181327
2274.5	2274.5			
2271E		1.300000 x	91.887687 =	119.453993
				-----
			T.E =	119.453993
2274.6	2274.6			
2271ΕΤ		1.300000 x	102.097430 =	132.726659
				-----
			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325
				-----
			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991
				-----
			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657
				-----
			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486
				-----
			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	290.000000 =	9.570000
251		6.000000 x	.895000 =	5.370000
003		5.000000 x	20.419486 =	102.097430
001		9.000000 x	15.741598 =	141.674382
				-----
			T.E =	267.411812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634
				-----
			T.E =	5.483634

2303	2303			
001		.250000 x	15.741598 =	3.935400
003		.250000 x	20.419486 =	5.104872
				-----
			T.E =	9.040271
2304	2304			
201		.000400 x	290.000000 =	.116000
002		.100000 x	17.312112 =	1.731211
				-----
			T.E =	1.847211
2311	2311			
201		.040000 x	290.000000 =	11.600000
203.4		.040000 x	290.000000 =	11.600000
003		7.000000 x	20.419486 =	142.936402
001		9.000000 x	15.741598 =	141.674382
251		6.000000 x	.895000 =	5.370000
				-----
			T.E =	313.180784
2312	2312			
201		.002000 x	290.000000 =	.580000
203.4		.002000 x	290.000000 =	.580000
251		.250000 x	.895000 =	.223750
001		.250000 x	15.741598 =	3.935400
003		.150000 x	20.419486 =	3.062923
				-----
			T.E =	8.382072
2313	2313			
201		.002000 x	290.000000 =	.580000
251		.200000 x	.895000 =	.179000
203.4		.001000 x	290.000000 =	.290000
003		.100000 x	20.419486 =	2.041949
001		.200000 x	15.741598 =	3.148320
				-----
			T.E =	6.239268
2314.1	2314.1			
511		1.000000 x	.489500 =	.489500
003		.030000 x	20.419486 =	.612585
				-----
			T.E =	1.102085
2314.2	2314.2			
512		1.000000 x	.437500 =	.437500
003		.030000 x	20.419486 =	.612585
				-----
			T.E =	1.050085

3101	3101			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
052		.430000 x	14.630000 =	6.290900
056		.860000 x	10.050000 =	8.643000
		-----		
			T.E =	102.473133
3102	3102			
021		.250000 x	2.670000 =	.667500
052		.420000 x	14.630000 =	6.144600
056		.840000 x	10.050000 =	8.442000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		200.000000 x	.099900 =	19.980000
		-----		
			T.E =	104.623333
3103	3103			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.820000 x	10.050000 =	8.241000
052		.410000 x	14.630000 =	5.998300
026		250.000000 x	.099900 =	24.975000
		-----		
			T.E =	109.271033
3104	3104			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.400000 x	14.630000 =	5.852000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.050000 =	8.040000
		-----		
			T.E =	113.918733
3111	3111			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
026		200.000000 x	.099900 =	19.980000
057		.840000 x	10.050000 =	8.442000
052		.420000 x	14.630000 =	6.144600
		-----		
			T.E =	128.829721



3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
026		250.000000 x	.099900 =	24.975000
057		.820000 x	10.050000 =	8.241000
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	14.630000 =	5.998300
			T.E =	128.918352
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.050000 =	8.040000
052		.400000 x	14.630000 =	5.852000
026		300.000000 x	.099900 =	29.970000
			T.E =	159.517393
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.050000 =	8.442000
026		150.000000 x	.099900 =	14.985000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
052		.420000 x	14.630000 =	6.144600
			T.E =	116.601590
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
061		.850000 x	12.880000 =	10.948000
052		.570000 x	14.630000 =	8.339100
			T.E =	106.826333
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
061		.840000 x	12.880000 =	10.819200
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.560000 x	14.630000 =	8.192800
			T.E =	109.048733

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	12.880000 =	10.561600
052		.540000 x	14.630000 =	7.900200
026		250.000000 x	.099900 =	24.975000
-----				
			T.E =	113.493533
3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.530000 x	14.630000 =	7.753900
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.800000 x	12.880000 =	10.304000
-----				
			T.E =	118.084633
3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
026		200.000000 x	.099900 =	19.980000
065		.750000 x	12.280000 =	9.210000
052		.430000 x	14.630000 =	6.290900
-----				
			T.E =	258.646759
3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	12.280000 =	8.964400
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
052		.410000 x	14.630000 =	5.998300
-----				
			T.E =	263.103559
3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.750000 x	12.280000 =	9.210000
052		.430000 x	14.630000 =	6.290900
026		200.000000 x	.099900 =	19.980000
-----				
			T.E =	191.856446

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	12.280000 =	8.964400
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
052		.430000 x	14.630000 =	6.290900
-----				
			T.E =	196.605846
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	12.880000 =	10.819200
052		.560000 x	14.630000 =	8.192800
026		200.000000 x	.099900 =	19.980000
-----				
			T.E =	133.255121
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
062		.820000 x	12.880000 =	10.561600
026		250.000000 x	.099900 =	24.975000
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.540000 x	14.630000 =	7.900200
-----				
			T.E =	133.140852
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
062		.800000 x	12.880000 =	10.304000
052		.530000 x	14.630000 =	7.753900
026		300.000000 x	.099900 =	29.970000
-----				
			T.E =	163.683293
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	12.280000 =	3.315600
026		350.000000 x	.099900 =	34.965000
052		.400000 x	14.630000 =	5.852000
062		.600000 x	12.880000 =	7.728000
-----				
			T.E =	175.386792

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.250000 x	12.280000 =	3.070000
027		350.000000 x	.119300 =	41.755000
062		.560000 x	12.880000 =	7.212800
052		.420000 x	14.630000 =	6.144600
			T.E =	181.708592
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.119300 =	50.702500
062		.550000 x	12.880000 =	7.084000
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
001		4.000000 x	15.741598 =	62.966392
065		.270000 x	12.280000 =	3.315600
052		.350000 x	14.630000 =	5.120500
			T.E =	197.619591
3217	3217			
001		2.500000 x	15.741598 =	39.353995
			T.E =	39.353995
3218	3218			
001		5.000000 x	15.741598 =	78.707990
			T.E =	78.707990
3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944
			T.E =	128.902738
3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944
			T.E =	160.385934
3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916
			T.E =	169.741710

3222	3222			
001		5.000000 x	15.741598 =	78.707990
003		6.000000 x	20.419486 =	122.516916
			T.E =	201.224906
3223A.1	3223A.1			
001		2.000000 x	15.741598 =	31.483196
1502		.050000 x	538.482543 =	26.924127
003		1.500000 x	20.419486 =	30.629229
			AΘΡΟΙΣΜΑ =	89.036552
	T.E =	.500000 x	89.036552 =	44.518276
3223A.2	3223A.2			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	114.987893
	T.E =	.500000 x	114.987893 =	57.493947
3223A.3	3223A.3			
001		2.000000 x	15.741598 =	31.483196
1502		.050000 x	538.482543 =	26.924127
003		1.500000 x	20.419486 =	30.629229
			AΘΡΟΙΣΜΑ =	89.036552
	T.E =	.500000 x	89.036552 =	44.518276
3223A.4	3223A.4			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			AΘΡΟΙΣΜΑ =	114.987893
	T.E =	.500000 x	114.987893 =	57.493947
3223A.5	3223A.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			AΘΡΟΙΣΜΑ =	122.858692
	T.E =	.500000 x	122.858692 =	61.429346

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			-----	
			AΘΡΟΙΣΜΑ =	122.858692
	T.E =	.500000 x	122.858692 =	61.429346
			-----	
3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
			-----	
			AΘΡΟΙΣΜΑ =	130.729491
	T.E =	.500000 x	130.729491 =	65.364746
			-----	
3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	538.482543 =	26.924127
			-----	
			AΘΡΟΙΣΜΑ =	89.036552
	T.E =	.250000 x	89.036552 =	22.259138
			-----	
3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			-----	
			AΘΡΟΙΣΜΑ =	114.987893
	T.E =	.250000 x	114.987893 =	28.746973
			-----	
3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	538.482543 =	26.924127
			-----	
			AΘΡΟΙΣΜΑ =	89.036552
	T.E =	.250000 x	89.036552 =	22.259138
			-----	
3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	538.482543 =	26.924127
003		2.000000 x	20.419486 =	40.838972
			-----	
			AΘΡΟΙΣΜΑ =	114.987893
	T.E =	.250000 x	114.987893 =	28.746973
			-----	

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			AΘΡΟΙΣΜΑ =	122.858692
	T.E =	.250000 x	122.858692 =	30.714673
3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			AΘΡΟΙΣΜΑ =	122.858692
	T.E =	.250000 x	122.858692 =	30.714673
3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	538.482543 =	26.924127
			AΘΡΟΙΣΜΑ =	130.729491
	T.E =	.250000 x	130.729491 =	32.682373
3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
061		.840000 x	12.880000 =	10.819200
052		.560000 x	14.630000 =	8.192800
026		150.000000 x	.099900 =	14.985000
			T.E =	121.026990
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	14.630000 =	4.389000
032		.150000 x	36.000000 =	5.400000
056		.800000 x	10.050000 =	8.040000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
			T.E =	95.434932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
051		.200000 x	14.630000 =	2.926000
001		3.500000 x	15.741598 =	55.095593
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
056		.800000 x	10.050000 =	8.040000
		-----		
			T.E =	97.652182
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	36.000000 =	14.400000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.050000 =	8.040000
		-----		
			T.E =	101.926182
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.050000 =	8.040000
032		.400000 x	36.000000 =	14.400000
026		100.000000 x	.099900 =	9.990000
		-----		
			T.E =	117.075576
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	36.000000 =	5.760000
051		.320000 x	14.630000 =	4.681600
061		.840000 x	12.880000 =	10.819200
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
		-----		
			T.E =	99.242782
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
051		.210000 x	14.630000 =	3.072300
001		3.500000 x	15.741598 =	55.095593
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
061		.840000 x	12.880000 =	10.819200
		-----		
			T.E =	109.481526



3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	12.880000 =	10.819200
-----				
			T.E =	113.969226
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	12.880000 =	10.819200
032		.420000 x	36.000000 =	15.120000
026		100.000000 x	.099900 =	9.990000
-----				
			T.E =	120.950826
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	8.630000 =	4.315000
056		.588000 x	10.050000 =	5.909400
026		140.000000 x	.099900 =	13.986000
052		.294000 x	14.630000 =	4.301220
-----				
			T.E =	90.794300
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	12.880000 =	7.573440
026		140.000000 x	.099900 =	13.986000
058		.500000 x	8.630000 =	4.315000
052		.392000 x	14.630000 =	5.734960
-----				
			T.E =	93.892080
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	8.630000 =	4.315000
056		.574000 x	10.050000 =	5.768700
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
026		175.000000 x	.099900 =	17.482500
052		.287000 x	14.630000 =	4.198810
-----				
			T.E =	94.047690

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.574000 x	12.880000 =	7.393120
058		.500000 x	8.630000 =	4.315000
052		.378000 x	14.630000 =	5.530140
026		175.000000 x	.099900 =	17.482500
			T.E =	97.003440
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.050000 =	5.909400
026		140.000000 x	.099900 =	13.986000
052		.294000 x	14.630000 =	4.301220
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	10.460000 =	5.230000
			T.E =	91.709300
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
061		.588000 x	12.880000 =	7.573440
052		.392000 x	14.630000 =	5.734960
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	10.460000 =	5.230000
			T.E =	94.807080
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
056		.574000 x	10.050000 =	5.768700
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	10.460000 =	5.230000
001		2.500000 x	15.741598 =	39.353995
026		175.000000 x	.099900 =	17.482500
052		.287000 x	14.630000 =	4.198810
			T.E =	94.962690

3407.2

3407.2

021	.175000 x	2.670000 =	.467250
003	1.100000 x	20.419486 =	22.461435
001	2.500000 x	15.741598 =	39.353995
081	.500000 x	10.460000 =	5.230000
061	.574000 x	12.880000 =	7.393120
052	.378000 x	14.630000 =	5.530140
026	175.000000 x	.099900 =	17.482500

T.E =

97.918440

3501

3501

021	.200000 x	2.670000 =	.534000
032	.200000 x	36.000000 =	7.200000
001	5.000000 x	15.741598 =	78.707990
1407	.180000 x	37.605000 =	6.768900
003	2.000000 x	20.419486 =	40.838972
067	1.050000 x	45.500000 =	47.775000

T.E =

181.824862

3502

3502

021	.200000 x	2.670000 =	.534000
026	100.000000 x	.099900 =	9.990000
1407	.100000 x	37.605000 =	3.760500
003	2.000000 x	20.419486 =	40.838972
001	5.000000 x	15.741598 =	78.707990
067	1.050000 x	45.500000 =	47.775000
032	.200000 x	36.000000 =	7.200000

T.E =

188.806462

3503

3503

021	.200000 x	2.670000 =	.534000
026	150.000000 x	.099900 =	14.985000
1407	.080000 x	37.605000 =	3.008400
003	2.000000 x	20.419486 =	40.838972
001	5.000000 x	15.741598 =	78.707990
067	1.000000 x	45.500000 =	45.500000
032	.200000 x	36.000000 =	7.200000

T.E =

190.774362

3504

3504

021	.200000 x	2.670000 =	.534000
003	3.200000 x	20.419486 =	65.342355
001	5.000000 x	15.741598 =	78.707990
517	4.000000 x	.000000 =	.000000
055	180.000000 x	.090000 =	16.200000
026	250.000000 x	.099900 =	24.975000

T.E =

3505	3505			
021		.200000 x	2.670000 =	.534000
055		420.000000 x	.090000 =	37.800000
003		5.000000 x	20.419486 =	102.097430
001		5.500000 x	15.741598 =	86.578789
517		4.000000 x	.000000 =	.000000
026		250.000000 x	.099900 =	24.975000
-----				
			T.E =	
3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	43.500000 =	50.025000
003		2.500000 x	20.419486 =	51.048715
001		5.000000 x	15.741598 =	78.707990
026		200.000000 x	.099900 =	19.980000
-----				
			T.E =	200.562705
3511	3511			
021		.200000 x	2.670000 =	.534000
001		5.000000 x	15.741598 =	78.707990
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
032		.200000 x	36.000000 =	7.200000
069		1.050000 x	.000000 =	.000000
-----				
			T.E =	
3512	3512			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
069		1.050000 x	.000000 =	.000000
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.099900 =	9.990000
-----				
			T.E =	
3513	3513			
001		2.500000 x	15.741598 =	39.353995
-----				
			T.E =	39.353995
3514	3514			
001		5.000000 x	15.741598 =	78.707990
-----				
			T.E =	78.707990

3801	3801			
201		.001500 x	290.000000 =	.435000
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639
203.4		.002500 x	290.000000 =	.725000
251		.300000 x	.895000 =	.268500
-----				
			T.E =	17.934882
3802	3802			
3801		.050000 x	17.934882 =	.896744
-----				
			T.E =	.896744
3811	3811			
203.4		.004000 x	290.000000 =	1.160000
251		.100000 x	.895000 =	.089500
003		.800000 x	20.419486 =	16.335589
001		.200000 x	15.741598 =	3.148320
-----				
			T.E =	20.733408
3816	3816			
201		.002500 x	290.000000 =	.725000
003		.600000 x	20.419486 =	12.251692
001		.400000 x	15.741598 =	6.296639
203.4		.003000 x	290.000000 =	.870000
251		.200000 x	.895000 =	.179000
-----				
			T.E =	20.322331
3817	3817			
3816		.150000 x	20.322331 =	3.048350
-----				
			T.E =	3.048350
3821	3821			
201		.014000 x	290.000000 =	4.060000
251		.600000 x	.895000 =	.537000
003		2.400000 x	20.419486 =	49.006766
001		.600000 x	15.741598 =	9.444959
203.4		.018000 x	290.000000 =	5.220000
-----				
			T.E =	68.268725
3822	3822			
3821		.150000 x	68.268725 =	10.240309
-----				
			T.E =	10.240309

3823	3823				
201		.020000 x	290.000000 =	5.800000	
001		.600000 x	15.741598 =	9.444959	
003		3.000000 x	20.419486 =	61.258458	
251		.180000 x	.895000 =	.161100	
203.4		.025000 x	290.000000 =	7.250000	
		-----			
			T.E =	83.914517	
3824	3824				
3823		.200000 x	83.914517 =	16.782903	
		-----			
			T.E =	16.782903	
3831	3831				
201		.020000 x	290.000000 =	5.800000	
003		4.500000 x	20.419486 =	91.887687	
001		1.100000 x	15.741598 =	17.315758	
251		.800000 x	.895000 =	.716000	
203.4		.024000 x	290.000000 =	6.960000	
		-----			
			T.E =	122.679445	
3832	3832				
3831		.150000 x	122.679445 =	18.401917	
		-----			
			T.E =	18.401917	
3833	3833				
201		.022000 x	290.000000 =	6.380000	
003		6.000000 x	20.419486 =	122.516916	
001		1.100000 x	15.741598 =	17.315758	
251		1.000000 x	.895000 =	.895000	
203.4		.025000 x	290.000000 =	7.250000	
		-----			
			T.E =	154.357674	
3834	3834				
3833		.200000 x	154.357674 =	30.871535	
		-----			
			T.E =	30.871535	
3841	3841				
203.4		.001500 x	290.000000 =	.435000	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	10.644743	

3851	3851				
203.4		.052000 x	290.000000 =	15.080000	
251		1.100000 x	.895000 =	.984500	
003		1.300000 x	20.419486 =	26.545332	
		-----			
			T.E =	42.609832	
3852	3852				
001		.300000 x	15.741598 =	4.722479	
003		.100000 x	20.419486 =	2.041949	
		-----			
			T.E =	6.764428	
3871	3871				
260		1.030000 x	.558700 =	.575461	
003		.050000 x	20.419486 =	1.020974	
		-----			
			T.E =	1.596435	
3872	3872				
261		1.030000 x	.611600 =	.629948	
003		.040000 x	20.419486 =	.816779	
		-----			
			T.E =	1.446727	
3873	3873				
262		1.030000 x	.558700 =	.575461	
003		.050000 x	20.419486 =	1.020974	
		-----			
			T.E =	1.596435	
3874	3874				
258		1.450000 x	8.017500 =	11.625375	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	14.688298	
3875	3875				
259		1.000000 x	25.542500 =	25.542500	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	31.668346	
3876	3876				
003		.060000 x	20.419486 =	1.225169	
		-----			
			T.E =	1.225169	

3881.1	3881.1				
111		1,023.391800 x		.075900 =	77.675438
001		5.000000 x		15.741598 =	78.707990
					-----
				T.E =	156.383428
3881.2	3881.2				
112		627.989998 x		.083300 =	52.311567
001		5.000000 x		15.741598 =	78.707990
					-----
				T.E =	131.019557
3882	3882				
127		1.050000 x		81.220000 =	85.281000
001		4.000000 x		15.741598 =	62.966392
					-----
				T.E =	148.247392
4101	4101				
081		1.150000 x		10.460000 =	12.029000
001		1.300000 x		15.741598 =	20.464077
003		2.000000 x		20.419486 =	40.838972
					-----
				T.E =	73.332049
4102	4102				
081		1.200000 x		10.460000 =	12.552000
001		1.700000 x		15.741598 =	26.760717
003		3.500000 x		20.419486 =	71.468201
					-----
				T.E =	110.780918
4103	4103				
081		1.150000 x		10.460000 =	12.029000
003		4.000000 x		20.419486 =	81.677944
001		3.000000 x		15.741598 =	47.224794
					-----
				T.E =	140.931738
4104	4104				
081		1.050000 x		10.460000 =	10.983000
001		3.000000 x		15.741598 =	47.224794
					-----
				T.E =	58.207794
4105	4105				
081		.350000 x		10.460000 =	3.661000
003		.900000 x		20.419486 =	18.377537
001		1.000000 x		15.741598 =	15.741598
					-----
				T.E =	37.780135



4106	4106			
081		.320000 x	10.460000 =	3.347200
001		.700000 x	15.741598 =	11.019119
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	32.743856
4107	4107			
081		1.200000 x	10.460000 =	12.552000
001		2.000000 x	15.741598 =	31.483196
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	105.293654
4201	4201			
081		1.150000 x	10.460000 =	12.029000
1412		.350000 x	27.238800 =	9.533580
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	148.891158
4205	4205			
081		1.150000 x	10.460000 =	12.029000
1417		.350000 x	39.591450 =	13.857008
003		2.500000 x	20.419486 =	51.048715
001		2.900000 x	15.741598 =	45.650634
		-----		
			T.E =	122.585357
4206	4206			
081		1.150000 x	10.460000 =	12.029000
001		2.900000 x	15.741598 =	45.650634
003		3.100000 x	20.419486 =	63.300407
1417		.350000 x	39.591450 =	13.857008
		-----		
			T.E =	134.837048
4207	4207			
081		1.150000 x	10.460000 =	12.029000
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	39.591450 =	13.857008
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	153.214586

4211	4211			
081		1.150000 x	10.460000 =	12.029000
001		2.900000 x	15.741598 =	45.650634
1447		.350000 x	58.265900 =	20.393065
003		2.500000 x	20.419486 =	51.048715
		-----		
			T.E =	129.121414
4212	4212			
081		1.150000 x	10.460000 =	12.029000
1447		.350000 x	58.265900 =	20.393065
003		3.100000 x	20.419486 =	63.300407
001		2.900000 x	15.741598 =	45.650634
		-----		
			T.E =	141.373106
4213	4213			
081		1.150000 x	10.460000 =	12.029000
1447		.350000 x	58.265900 =	20.393065
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	159.750643
4221	4221			
001		.800000 x	15.741598 =	12.593278
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	33.012764
4222	4222			
001		.400000 x	15.741598 =	6.296639
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	14.464434
4226	4226			
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	26.545332
4251	4251			
083		32.000000 x	.000000 =	.000000
1412		.200000 x	27.238800 =	5.447760
001		2.900000 x	15.741598 =	45.650634
003		4.000000 x	20.419486 =	81.677944
		-----		
			T.E =	

4257	4257			
083		32.000000 x	.000000 =	.000000
1417		.200000 x	39.591450 =	7.918290
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634
-----				
			T.E =	
4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.130300 =	12.226060
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634
-----				
			T.E =	
4262	4262			
083		32.000000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634
1447		.200000 x	58.265900 =	11.653180
-----				
			T.E =	
4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	16.176598
4301	4301			
081		1.020000 x	10.460000 =	10.669200
1412		.350000 x	27.238800 =	9.533580
003		4.200000 x	20.419486 =	85.761841
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000
-----				
			T.E =	
4305	4305			
081		1.080000 x	10.460000 =	11.296800
1417		.350000 x	39.591450 =	13.857008
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000
-----				
			T.E =	

4306	4306			
081		1.050000 x	10.460000 =	10.983000
1417		.350000 x	39.591450 =	13.857008
003		3.300000 x	20.419486 =	67.384304
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
-----				
			T.E =	
4307	4307			
081		1.020000 x	10.460000 =	10.669200
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	39.591450 =	13.857008
003		4.200000 x	20.419486 =	85.761841
083		5.000000 x	.000000 =	.000000
-----				
			T.E =	
4311	4311			
081		1.080000 x	10.460000 =	11.296800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	20.419486 =	55.132612
1447		.350000 x	58.265900 =	20.393065
001		2.900000 x	15.741598 =	45.650634
-----				
			T.E =	
4312	4312			
081		1.050000 x	10.460000 =	10.983000
083		3.000000 x	.000000 =	.000000
1447		.350000 x	58.265900 =	20.393065
003		3.300000 x	20.419486 =	67.384304
001		2.900000 x	15.741598 =	45.650634
-----				
			T.E =	
4313	4313			
081		1.080000 x	10.460000 =	11.296800
1447		.350000 x	58.265900 =	20.393065
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000
-----				
			T.E =	
4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	16.176598

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
001		10.000000 x	15.741598 =	157.415980
003		25.000000 x	20.419486 =	510.487150
1446		.100000 x	52.018100 =	5.201810
251		4.000000 x	.895000 =	3.580000
			T.E =	
4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
1446		.100000 x	52.018100 =	5.201810
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980
251		4.000000 x	.895000 =	3.580000
			T.E =	
4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
251		4.000000 x	.895000 =	3.580000
001		10.000000 x	15.741598 =	157.415980
1446		.100000 x	52.018100 =	5.201810
003		25.000000 x	20.419486 =	510.487150
			T.E =	
4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
1446		.200000 x	52.018100 =	10.403620
251		8.000000 x	.895000 =	7.160000
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578
			T.E =	
4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
251		8.000000 x	.895000 =	7.160000
003		32.000000 x	20.419486 =	653.423552
1446		.200000 x	52.018100 =	10.403620
001		11.000000 x	15.741598 =	173.157578
			T.E =	

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.018100 =	10.403620
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578
251		8.000000 x	.895000 =	7.160000
		-----		
			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918
		-----		
			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794
		-----		
			T.E =	47.224794
4501	4501			
081		.050000 x	10.460000 =	.523000
002		.500000 x	17.312112 =	8.656056
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	29.598542
4502	4502			
081		.050000 x	10.460000 =	.523000
002		.500000 x	17.312112 =	8.656056
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	35.724388
4503	4503			
081		.050000 x	10.460000 =	.523000
002		.500000 x	17.312112 =	8.656056
003		1.400000 x	20.419486 =	28.587280
		-----		
			T.E =	37.766336
4504	4504			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818
		-----		
			T.E =	52.681451

4505	4505			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		2.700000 x	20.419486 =	55.132612
-----				
			T.E =	60.849246
4506	4506			
081		.050000 x	10.460000 =	.523000
003		3.600000 x	20.419486 =	73.510150
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	79.226783
4507	4507			
081		.050000 x	10.460000 =	.523000
003		3.200000 x	20.419486 =	65.342355
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	71.058989
4508	4508			
081		.050000 x	10.460000 =	.523000
003		3.000000 x	20.419486 =	61.258458
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	66.975092
4511	4511			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		3.800000 x	20.419486 =	77.594047
-----				
			T.E =	83.310680
4512	4512			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	87.394578
4515	4515			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	107.814064

4516	4516			
081		.050000 x	10.460000 =	.523000
003		4.500000 x	20.419486 =	91.887687
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	97.604321
4517	4517			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		6.500000 x	20.419486 =	132.726659
		-----		
			T.E =	138.443293
4518	4518			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		5.700000 x	20.419486 =	116.391070
		-----		
			T.E =	122.107704
4519	4519			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327
		-----		
			T.E =	111.897961
4521	4521			
081		.050000 x	10.460000 =	.523000
003		3.500000 x	20.419486 =	71.468201
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	77.184835
4522	4522			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		2.700000 x	20.419486 =	55.132612
		-----		
			T.E =	60.849246
4525	4525			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687
		-----		
			T.E =	97.604321



4526	4526			
081		.050000 x	10.460000 =	.523000
002		.300000 x	17.312112 =	5.193634
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	87.394578
4527	4527			
081		.050000 x	10.460000 =	.523000
003		6.000000 x	20.419486 =	122.516916
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	128.233550
4528	4528			
081		.050000 x	10.460000 =	.523000
003		5.200000 x	20.419486 =	106.181327
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	111.897961
4529	4529			
081		.050000 x	10.460000 =	.523000
003		4.700000 x	20.419486 =	95.971584
002		.300000 x	17.312112 =	5.193634
-----				
			T.E =	101.688218
4531	4531			
081		.050000 x	10.460000 =	.523000
003		2.500000 x	20.419486 =	51.048715
-----				
			T.E =	51.571715
4532	4532			
081		.050000 x	10.460000 =	.523000
003		2.000000 x	20.419486 =	40.838972
-----				
			T.E =	41.361972
4535	4535			
081		.050000 x	10.460000 =	.523000
003		3.800000 x	20.419486 =	77.594047
-----				
			T.E =	78.117047
4536	4536			
081		.050000 x	10.460000 =	.523000
003		3.100000 x	20.419486 =	63.300407
-----				
			T.E =	63.823407

4537	4537				
081		.050000 x	10.460000 =	.523000	
003		5.500000 x	20.419486 =	112.307173	
		-----			
			T.E =	112.830173	
4538	4538				
081		.050000 x	10.460000 =	.523000	
003		4.600000 x	20.419486 =	93.929636	
		-----			
			T.E =	94.452636	
4539	4539				
081		.050000 x	10.460000 =	.523000	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =	86.284841	
4541	4541				
081		.050000 x	10.460000 =	.523000	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	51.571715	
4542	4542				
081		.050000 x	10.460000 =	.523000	
003		2.000000 x	20.419486 =	40.838972	
		-----			
			T.E =	41.361972	
4543	4543				
081		.050000 x	10.460000 =	.523000	
003		4.000000 x	20.419486 =	81.677944	
		-----			
			T.E =	82.200944	
4544	4544				
081		.050000 x	10.460000 =	.523000	
003		6.000000 x	20.419486 =	122.516916	
		-----			
			T.E =	123.039916	
4601.1	4601.1				
101		105.000000 x	.000000 =	.000000	
001		.600000 x	15.741598 =	9.444959	
1417		.023000 x	39.591450 =	.910603	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =		

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	58.265900 =	1.340116
003		.700000 x	20.419486 =	14.293640
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	
4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	39.591450 =	2.217121
003		1.300000 x	20.419486 =	26.545332
001		1.300000 x	15.741598 =	20.464077
		-----		
			T.E =	
4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1447		.056000 x	58.265900 =	3.262890
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	
4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.741598 =	29.909036
1417		.089000 x	39.591450 =	3.523639
003		1.800000 x	20.419486 =	36.755075
		-----		
			T.E =	
4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.741598 =	29.909036
1447		.089000 x	58.265900 =	5.185665
003		1.800000 x	20.419486 =	36.755075
		-----		
			T.E =	
4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	39.591450 =	13.144361
003		5.500000 x	20.419486 =	112.307173
001		6.300000 x	15.741598 =	99.172067
		-----		
			T.E =	

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.741598 =	99.172067
1447		.332000 x	58.265900 =	19.344279
003		5.500000 x	20.419486 =	112.307173
			T.E =	
4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	39.591450 =	1.187744
003		.700000 x	20.419486 =	14.293640
001		.700000 x	15.741598 =	11.019119
			T.E =	
4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
1447		.030000 x	58.265900 =	1.747977
003		.700000 x	20.419486 =	14.293640
001		.700000 x	15.741598 =	11.019119
			T.E =	
4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	39.591450 =	2.771402
003		1.300000 x	20.419486 =	26.545332
001		1.400000 x	15.741598 =	22.038237
			T.E =	
4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.741598 =	22.038237
1447		.070000 x	58.265900 =	4.078613
003		1.300000 x	20.419486 =	26.545332
			T.E =	
4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.741598 =	33.057356
1417		.110000 x	39.591450 =	4.355060
003		1.800000 x	20.419486 =	36.755075
			T.E =	

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.741598 =	33.057356
1447		.110000 x	58.265900 =	6.409249
003		1.800000 x	20.419486 =	36.755075
			T.E =	
4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	39.591450 =	15.994946
003		5.500000 x	20.419486 =	112.307173
001		6.500000 x	15.741598 =	102.320387
			T.E =	
4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1447		.404000 x	58.265900 =	23.539424
003		5.500000 x	20.419486 =	112.307173
			T.E =	
4621.1	4621.1			
111		53.000000 x	.075900 =	4.022700
001		.400000 x	15.741598 =	6.296639
1417		.010000 x	39.591450 =	.395915
003		.500000 x	20.419486 =	10.209743
			T.E =	20.924997
4621.2	4621.2			
111		53.000000 x	.075900 =	4.022700
001		.400000 x	15.741598 =	6.296639
1447		.010000 x	58.265900 =	.582659
003		.500000 x	20.419486 =	10.209743
			T.E =	21.111741
4622.1	4622.1			
111		75.000000 x	.075900 =	5.692500
1417		.020000 x	39.591450 =	.791829
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719
			T.E =	23.777791

4622.2	4622.2			
111		75.000000 x	.075900 =	5.692500
001		.450000 x	15.741598 =	7.083719
1447		.020000 x	58.265900 =	1.165318
003		.500000 x	20.419486 =	10.209743
				-----
			T.E =	24.151280
4623.1	4623.1			
111		150.000000 x	.075900 =	11.385000
001		.950000 x	15.741598 =	14.954518
1417		.050000 x	39.591450 =	1.979573
003		.950000 x	20.419486 =	19.398512
				-----
			T.E =	47.717602
4623.2	4623.2			
111		150.000000 x	.075900 =	11.385000
001		.950000 x	15.741598 =	14.954518
1447		.050000 x	58.265900 =	2.913295
003		.950000 x	20.419486 =	19.398512
				-----
			T.E =	48.651325
4624.1	4624.1			
111		225.000000 x	.075900 =	17.077500
1417		.085000 x	39.591450 =	3.365273
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
				-----
			T.E =	70.600502
4624.2	4624.2			
111		225.000000 x	.075900 =	17.077500
1447		.085000 x	58.265900 =	4.952602
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397
				-----
			T.E =	72.187830
4625.1	4625.1			
111		750.000000 x	.075900 =	56.925000
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310
1417		.320000 x	39.591450 =	12.669264
				-----
			T.E =	239.254363

4625.2	4625.2			
111		750.000000 x	.075900 =	56.925000
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310
1447		.320000 x	58.265900 =	18.645088
				-----
			T.E =	245.230187
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000
				-----
			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000
				-----
			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000
				-----
			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000
				-----
			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000
				-----
			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000
				-----
			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000
				-----
			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000
-----				
			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.777791 =	52.311140
-----				
			T.E =	52.311140
4633.2	4633.2			
4622.2		2.200000 x	24.151280 =	53.132816
-----				
			T.E =	53.132816
4634.1	4634.1			
4622.1		1.200000 x	23.777791 =	28.533349
4623.1		1.000000 x	47.717602 =	47.717602
-----				
			T.E =	76.250951
4634.2	4634.2			
4622.2		1.200000 x	24.151280 =	28.981536
4623.2		1.000000 x	48.651325 =	48.651325
-----				
			T.E =	77.632861
4661.1	4661.1			
112		43.750000 x	.083300 =	3.644375
003		.500000 x	20.419486 =	10.209743
1417		.014507 x	39.591450 =	.574353
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	20.725110
4661.2	4661.2			
112		43.750000 x	.083300 =	3.644375
1447		.014507 x	58.265900 =	.845263
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	20.996021
4662.1	4662.1			
112		58.333300 x	.083300 =	4.859164
1417		.022840 x	39.591450 =	.904269
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	23.056895



4662.2	4662.2			
112		58.333300 x	.083300 =	4.859164
003		.500000 x	20.419486 =	10.209743
1447		.022840 x	58.265900 =	1.330793
001		.450000 x	15.741598 =	7.083719
		-----		
			T.E =	23.483419
4663.1	4663.1			
112		105.000000 x	.083300 =	8.746500
001		.900000 x	15.741598 =	14.167438
003		.900000 x	20.419486 =	18.377537
1417		.043218 x	39.591450 =	1.711063
		-----		
			T.E =	43.002539
4663.2	4663.2			
112		105.000000 x	.083300 =	8.746500
001		.900000 x	15.741598 =	14.167438
1447		.043218 x	58.265900 =	2.518136
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	43.809611
4664.1	4664.1			
112		97.222221 x	.083300 =	8.098611
1417		.045077 x	39.591450 =	1.784664
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518
		-----		
			T.E =	44.236305
4664.2	4664.2			
112		97.222221 x	.083300 =	8.098611
001		.950000 x	15.741598 =	14.954518
1447		.045077 x	58.265900 =	2.626452
003		.950000 x	20.419486 =	19.398512
		-----		
			T.E =	45.078093
4665.1	4665.1			
112		174.999001 x	.083300 =	14.577417
001		1.500000 x	15.741598 =	23.612397
1417		.047530 x	39.591450 =	1.881782
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	66.616927

4665.2	4665.2			
112		174.999001 x	.083300 =	14.577417
001		1.500000 x	15.741598 =	23.612397
1447		.047530 x	58.265900 =	2.769378
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	67.504524
4666.1	4666.1			
112		486.111099 x	.083300 =	40.493055
1417		.277862 x	39.591450 =	11.000959
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310
		-----		
			T.E =	221.154113
4666.2	4666.2			
112		486.111000 x	.083300 =	40.493046
001		5.200000 x	15.741598 =	81.856310
1447		.277862 x	58.265900 =	16.189880
003		4.300000 x	20.419486 =	87.803790
		-----		
			T.E =	226.343025
4701	4701			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.741598 =	7.870799
1417		.020000 x	39.591450 =	.791829
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	24.240422
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	58.265900 =	1.165318
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	24.613911
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	39.591450 =	.593872
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	58.265900 =	.873989
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	
4711	4711			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1417		.020000 x	39.591450 =	.791829
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	
4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	58.265900 =	1.165318
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	
4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	39.591450 =	.593872
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	
4714	4714			
118		13.000000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1447		.015000 x	58.265900 =	.873989
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	
4721.1	4721.1			
128		.080000 x	88.240000 =	7.059200
001		.300000 x	15.741598 =	4.722479
1417		.004000 x	39.591450 =	.158366
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	19.086865

4721.2	4721.2				
128		.080000 x	88.240000 =	7.059200	
001		.300000 x	15.741598 =	4.722479	
1447		.004000 x	58.265900 =	.233064	
003		.350000 x	20.419486 =	7.146820	
-----					
			T.E =	19.161563	
4722.1	4722.1				
128		.100000 x	88.240000 =	8.824000	
1417		.005000 x	39.591450 =	.197957	
003		.350000 x	20.419486 =	7.146820	
001		.350000 x	15.741598 =	5.509559	
-----					
			T.E =	21.678337	
4722.2	4722.2				
128		.100000 x	88.240000 =	8.824000	
1447		.005000 x	58.265900 =	.291330	
001		.350000 x	15.741598 =	5.509559	
003		.350000 x	20.419486 =	7.146820	
-----					
			T.E =	21.771709	
4723	4723				
128		.120000 x	88.240000 =	10.588800	
003		.350000 x	20.419486 =	7.146820	
1417		.006000 x	39.591450 =	.237549	
001		.400000 x	15.741598 =	6.296639	
-----					
			T.E =	24.269808	
4724.1	4724.1				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1417		.008000 x	39.591450 =	.316732	
003		.400000 x	20.419486 =	8.167794	
-----					
			T.E =	28.017165	
4724.2	4724.2				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1447		.008000 x	58.265900 =	.466127	
003		.400000 x	20.419486 =	8.167794	
-----					
			T.E =	28.166561	

4725.1	4725.1				
128		.180000 x	88.240000 =	15.883200	
1417		.009000 x	39.591450 =	.356323	
003		.400000 x	20.419486 =	8.167794	
001		.450000 x	15.741598 =	7.083719	
			T.E =	31.491037	
4725.2	4725.2				
128		.180000 x	88.240000 =	15.883200	
001		.450000 x	15.741598 =	7.083719	
1447		.009000 x	58.265900 =	.524393	
003		.400000 x	20.419486 =	8.167794	
			T.E =	31.659107	
4801.1	4801.1				
4662.1		1.000000 x	23.056895 =	23.056895	
4662.1		.100000 x	23.056895 =	2.305690	
			T.E =	25.362585	
4801.2	4801.2				
4662.2		1.000000 x	23.483419 =	23.483419	
4662.2		.100000 x	23.483419 =	2.348342	
			T.E =	25.831761	
4802.1	4802.1				
4664.1		1.000000 x	44.236305 =	44.236305	
4664.1		.050000 x	44.236305 =	2.211815	
			T.E =	46.448120	
4802.2	4802.2				
4664.2		1.000000 x	45.078093 =	45.078093	
4664.2		.050000 x	45.078093 =	2.253905	
			T.E =	47.331998	
4803.1	4803.1				
4665.1		1.000000 x	66.616927 =	66.616927	
4665.1		.030000 x	66.616927 =	1.998508	
			T.E =	68.615435	
4803.2	4803.2				
4665.2		1.000000 x	67.504524 =	67.504524	
4665.2		.030000 x	67.504524 =	2.025136	
			T.E =	69.529660	

4811.1	4811.1				
001		.225000 x	15.741598 =	3.541860	
4662.1		1.000000 x	23.056895 =	23.056895	
003		.250000 x	20.419486 =	5.104872	
			T.E =	31.703626	
4811.2	4811.2				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.2		1.000000 x	23.483419 =	23.483419	
			T.E =	32.130150	
4812.1	4812.1				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.1		1.000000 x	44.236305 =	44.236305	
			T.E =	61.412820	
4812.2	4812.2				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.2		1.000000 x	45.078093 =	45.078093	
			T.E =	62.254608	
4813.1	4813.1				
001		.750000 x	15.741598 =	11.806199	
4665.1		1.000000 x	66.616927 =	66.616927	
003		.650000 x	20.419486 =	13.272666	
			T.E =	91.695791	
4813.2	4813.2				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.2		1.000000 x	67.504524 =	67.504524	
			T.E =	92.583388	
4814.1	4814.1				
001		2.600000 x	15.741598 =	40.928155	
003		2.150000 x	20.419486 =	43.901895	
4666.1		1.000000 x	221.154113 =	221.154113	
			T.E =	305.984163	

4814.2	4814.2				
001		2.600000 x	15.741598 =	40.928155	
003		2.150000 x	20.419486 =	43.901895	
4666.2		1.000000 x	226.343025 =	226.343025	
			T.E =	311.173075	
4821.1	4821.1				
003		.450000 x	20.419486 =	9.188769	
4662.1		1.000000 x	23.056895 =	23.056895	
			T.E =	32.245664	
4821.2	4821.2				
003		.450000 x	20.419486 =	9.188769	
4662.2		1.000000 x	23.483419 =	23.483419	
			T.E =	32.672188	
4822.1	4822.1				
003		.807500 x	20.419486 =	16.488735	
4664.1		1.000000 x	44.236305 =	44.236305	
			T.E =	60.725040	
4822.2	4822.2				
003		.807500 x	20.419486 =	16.488735	
4664.2		1.000000 x	45.078093 =	45.078093	
			T.E =	61.566828	
4823.1	4823.1				
003		1.040000 x	20.419486 =	21.236265	
4665.1		1.000000 x	66.616927 =	66.616927	
			T.E =	87.853192	
4823.2	4823.2				
003		1.040000 x	20.419486 =	21.236265	
4665.2		1.000000 x	67.504524 =	67.504524	
			T.E =	88.740789	
4824.1	4824.1				
003		3.010000 x	20.419486 =	61.462653	
4666.1		1.000000 x	221.154113 =	221.154113	
			T.E =	282.616766	

4824.2	4824.2				
003		3.010000 x	20.419486 =	61.462653	
4666.2		1.000000 x	226.343025 =	226.343025	
			T.E =	287.805678	
4831.1	4831.1				
003		1.200000 x	20.419486 =	24.503383	
4661.1		1.000000 x	20.725110 =	20.725110	
			T.E =	45.228493	
4831.2	4831.2				
003		1.200000 x	20.419486 =	24.503383	
4661.2		1.000000 x	20.996021 =	20.996021	
			T.E =	45.499404	
4832.1	4832.1				
003		1.600000 x	20.419486 =	32.671178	
4662.1		1.000000 x	23.056895 =	23.056895	
			T.E =	55.728073	
4832.2	4832.2				
003		1.600000 x	20.419486 =	32.671178	
4662.2		1.000000 x	23.483419 =	23.483419	
			T.E =	56.154597	
4833.1	4833.1				
002		2.000000 x	17.312112 =	34.624224	
4664.1		1.000000 x	44.236305 =	44.236305	
			T.E =	78.860529	
4833.2	4833.2				
002		2.000000 x	17.312112 =	34.624224	
4664.2		1.000000 x	45.078093 =	45.078093	
			T.E =	79.702317	
4834.1	4834.1				
003		2.300000 x	20.419486 =	46.964818	
4665.1		1.000000 x	66.616927 =	66.616927	
			T.E =	113.581745	



4834.2	4834.2			
003		2.300000 x	20.419486 =	46.964818
4665.2		1.000000 x	67.504524 =	67.504524
-----				
			T.E =	114.469342
4835	4835			
122		1.050000 x	.000000 =	.000000
1417		.005000 x	39.591450 =	.197957
003		1.000000 x	20.419486 =	20.419486
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.847400 =	1.694800
-----				
			T.E =	
4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
201		.010000 x	290.000000 =	2.900000
1447		.005000 x	58.265900 =	.291330
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.847400 =	1.694800
-----				
			T.E =	
4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
1417		.005000 x	39.591450 =	.197957
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.847400 =	1.694800
201		.010000 x	290.000000 =	2.900000
-----				
			T.E =	
4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
265		2.000000 x	.847400 =	1.694800
1447		.005000 x	58.265900 =	.291330
003		1.000000 x	20.419486 =	20.419486
001		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	39.591450 =	.395915
003		1.000000 x	20.419486 =	20.419486
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
265		2.000000 x	.847400 =	1.694800
			T.E =	47.346799
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
201		.010000 x	290.000000 =	2.900000
1447		.010000 x	58.265900 =	.582659
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.847400 =	1.694800
			T.E =	49.104057
4841	4841			
003		.700000 x	20.419486 =	14.293640
			T.E =	14.293640
4842	4842			
003		1.000000 x	20.419486 =	20.419486
			T.E =	20.419486
4843	4843			
003		.250000 x	20.419486 =	5.104872
			T.E =	5.104872
4844	4844			
131		1,200.000000 x	.620000 =	744.000000
1401		.250000 x	242.301000 =	60.575250
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980
			T.E =	1,472.478380
4845	4845			
132		620.000000 x	.800000 =	496.000000
001		6.000000 x	15.741598 =	94.449588
1401		.180000 x	242.301000 =	43.614180
003		15.000000 x	20.419486 =	306.292290
			T.E =	940.356058

4851	4851			
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240
		-----		
			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278
		-----		
			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320
		-----		
			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479
		-----		
			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639
		-----		
			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799
		-----		
			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959
		-----		
			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717
		-----		
			T.E =	26.760717
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
003		4.000000 x	20.419486 =	81.677944
001		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	1,197.419542
5102	5102			
483		1.800000 x	.167500 =	.301500
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.500000 =	2.970000
489		.360000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
492		1.440000 x	.540000 =	.777600
		-----		
			T.E =	
5103	5103			
265		1.050000 x	.847400 =	.889770
003		.200000 x	20.419486 =	4.083897
002		.050000 x	17.312112 =	.865606
		-----		
			T.E =	5.839273
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	34.546119
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
003		.500000 x	20.419486 =	10.209743
001		2.000000 x	15.741598 =	31.483196
		-----		
			T.E =	51.692939

5106	5106				
214		.050000 x	1,000.000000 =	50.000000	
001		2.000000 x	15.741598 =	31.483196	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	132.531911	
5201	5201				
201		1.100000 x	290.000000 =	319.000000	
002		5.000000 x	17.312112 =	86.560560	
251		6.000000 x	.895000 =	5.370000	
003		10.000000 x	20.419486 =	204.194860	
		-----			
			T.E =	615.125420	
5202	5202				
203.2		1.080000 x	370.000000 =	399.600000	
251		6.000000 x	.895000 =	5.370000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
		-----			
			T.E =	666.649878	
5203	5203				
201		1.120000 x	290.000000 =	324.800000	
003		16.000000 x	20.419486 =	326.711776	
002		8.000000 x	17.312112 =	138.496896	
251		12.000000 x	.895000 =	10.740000	
		-----			
			T.E =	800.748672	
5204	5204				
203.2		1.100000 x	370.000000 =	407.000000	
002		7.000000 x	17.312112 =	121.184784	
003		14.000000 x	20.419486 =	285.872804	
251		12.000000 x	.895000 =	10.740000	
		-----			
			T.E =	824.797588	
5211	5211				
201		1.100000 x	290.000000 =	319.000000	
251		14.000000 x	.895000 =	12.530000	
003		12.000000 x	20.419486 =	245.033832	
002		6.000000 x	17.312112 =	103.872672	
		-----			
			T.E =	680.436504	

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
251		14.000000 x	.895000 =	12.530000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
		-----			
			T.E =	702.885420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	
251		8.000000 x	.895000 =	7.160000	
		-----			
			T.E =	587.839878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.895000 =	.089500	
002		.050000 x	17.312112 =	.865606	
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	10.219003	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
251		.100000 x	.895000 =	.089500	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	
		-----			
			T.E =	12.045245	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.895000 =	.089500	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	
		-----			
			T.E =	15.524608	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	
251		.100000 x	.895000 =	.089500	
		-----			
			T.E =	10.959003	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.895000 =	.089500	
002		.100000 x	17.312112 =	1.731211	
003		.200000 x	20.419486 =	4.083897	
-----					
			T.E =	14.044608	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
251		.150000 x	.895000 =	.134250	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
-----					
			T.E =	17.914964	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.895000 =	.134250	
003		.250000 x	20.419486 =	5.104872	
002		.100000 x	17.312112 =	1.731211	
-----					
			T.E =	13.630333	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	
251		.150000 x	.895000 =	.134250	
-----					
			T.E =	16.566575	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.895000 =	.179000	
002		.150000 x	17.312112 =	2.596817	
003		.250000 x	20.419486 =	5.104872	
-----					
			T.E =	20.460688	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
251		.080000 x	.895000 =	.071600	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
-----					
			T.E =	17.466448	

5237	5237				
203.2		.022000 x	370.000000 =		8.140000
251		.080000 x	.895000 =		.071600
003		.350000 x	20.419486 =		7.146820
002		.300000 x	17.312112 =		5.193634
		-----			
			T.E =		20.552054
5238	5238				
203.2		.030000 x	370.000000 =		11.100000
003		.350000 x	20.419486 =		7.146820
002		.350000 x	17.312112 =		6.059239
251		.100000 x	.895000 =		.089500
		-----			
			T.E =		24.395559
5241	5241				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.895000 =		.089500
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056
		-----			
			T.E =		30.055299
5243	5243				
003		.150000 x	20.419486 =		3.062923
		-----			
			T.E =		3.062923
5244	5244				
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		7.146820
5246	5246				
220		26.000000 x	.000000 =		.000000
251		.200000 x	.895000 =		.179000
002		.500000 x	17.312112 =		8.656056
		-----			
			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
002		.600000 x	17.312112 =		10.387267
283		.100000 x	1.305700 =		.130570
251		.100000 x	.895000 =		.089500
		-----			
			T.E =		



5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	
251		.100000 x	.895000 =	.089500	
		-----			
			T.E =	16.133979	
5252.1	5252.1				
245		1.100000 x	18.000000 =	19.800000	
245		.110000 x	18.000000 =	1.980000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	
		-----			
			T.E =	116.108995	
5252.2	5252.2				
246		1.100000 x	13.000000 =	14.300000	
246		.110000 x	13.000000 =	1.430000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
		-----			
			T.E =	110.058995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
249		.110000 x	20.000000 =	2.200000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
		-----			
			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	
219		.060000 x	3.500000 =	.210000	
		-----			
			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
203.2		.025000 x	370.000000 =	9.250000	
251		.600000 x	.895000 =	.537000	
002		.800000 x	17.312112 =	13.849690	
003		.800000 x	20.419486 =	16.335589	
		-----			
			T.E =	45.772278	

5262	5262				
201		.030000 x	290.000000 =	8.700000	
251		.300000 x	.895000 =	.268500	
252		.200000 x	2.184000 =	.436800	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
265		.300000 x	.847400 =	.254220	
203.2		.025000 x	370.000000 =	9.250000	
-----					
			T.E =	56.641118	
5266	5266				
201		.020000 x	290.000000 =	5.800000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
251		.600000 x	.895000 =	.537000	
203.2		.015000 x	370.000000 =	5.550000	
-----					
			T.E =	34.525959	
5267	5267				
201		.030000 x	290.000000 =	8.700000	
252		.300000 x	2.184000 =	.655200	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
265		.300000 x	.847400 =	.254220	
203.2		.015000 x	370.000000 =	5.550000	
251		.300000 x	.895000 =	.268500	
-----					
			T.E =	45.613198	
5271	5271				
201		.016000 x	290.000000 =	4.640000	
251		.600000 x	.895000 =	.537000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
203.2		.025000 x	370.000000 =	9.250000	
-----					
			T.E =	33.292799	
5272	5272				
201		.024000 x	290.000000 =	6.960000	
203.2		.025000 x	370.000000 =	9.250000	
251		.300000 x	.895000 =	.268500	
002		.700000 x	17.312112 =	12.118478	
003		.700000 x	20.419486 =	14.293640	
265		.200000 x	.847400 =	.169480	
252		.100000 x	2.184000 =	.218400	
-----					
			T.E =	43.278499	

5273	5273				
201		.016000 x	290.000000 =		4.640000
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056
203.2		.015000 x	370.000000 =		5.550000
251		.600000 x	.895000 =		.537000
				T.E =	29.592799
5274	5274				
201		.024000 x	290.000000 =		6.960000
003		.700000 x	20.419486 =		14.293640
002		.700000 x	17.312112 =		12.118478
265		.200000 x	.847400 =		.169480
252		.100000 x	2.184000 =		.218400
251		.300000 x	.895000 =		.268500
203.2		.015000 x	370.000000 =		5.550000
				T.E =	39.578499
5276	5276				
201		1.080000 x	290.000000 =		313.200000
003		19.000000 x	20.419486 =		387.970234
002		19.000000 x	17.312112 =		328.930128
252		18.000000 x	2.184000 =		39.312000
251		6.000000 x	.895000 =		5.370000
				T.E =	1,074.782362
5277	5277				
203.2		1.080000 x	370.000000 =		399.600000
003		18.000000 x	20.419486 =		367.550748
002		18.000000 x	17.312112 =		311.618016
252		18.000000 x	2.184000 =		39.312000
251		6.000000 x	.895000 =		5.370000
				T.E =	1,123.450764
5279	5279				
201		1.080000 x	290.000000 =		313.200000
003		10.000000 x	20.419486 =		204.194860
002		5.000000 x	17.312112 =		86.560560
251		12.000000 x	.895000 =		10.740000
				T.E =	614.695420

5280	5280				
203.2		1.080000 x	370.000000 =	399.600000	
251		12.000000 x	.895000 =	10.740000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	
		-----			
			T.E =	701.095420	
5281	5281				
203.2		.014000 x	370.000000 =	5.180000	
251		.040000 x	.895000 =	.035800	
002		.250000 x	17.312112 =	4.328028	
		-----			
			T.E =	9.543828	
5282	5282				
203.2		.020000 x	370.000000 =	7.400000	
251		.060000 x	.895000 =	.053700	
002		.350000 x	17.312112 =	6.059239	
		-----			
			T.E =	13.512939	
5283	5283				
203.2		.026000 x	370.000000 =	9.620000	
002		.400000 x	17.312112 =	6.924845	
251		.080000 x	.895000 =	.071600	
		-----			
			T.E =	16.616445	
5286	5286				
203.2		.008000 x	370.000000 =	2.960000	
251		.030000 x	.895000 =	.026850	
002		.120000 x	17.312112 =	2.077453	
003		.120000 x	20.419486 =	2.450338	
		-----			
			T.E =	7.514642	
5288	5288				
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	6.125846	
5289	5289				
003		1.000000 x	20.419486 =	20.419486	
		-----			
			T.E =	20.419486	

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
220		26.000000 x	.000000 =	.000000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.200000 x	.895000 =	.179000
-----				
			T.E =	
5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
220		26.000000 x	.000000 =	.000000
251		.200000 x	.895000 =	.179000
203.2		.010000 x	370.000000 =	3.700000
-----				
			T.E =	
5293	5293			
203.2		.020000 x	370.000000 =	7.400000
251		.150000 x	.895000 =	.134250
203.2		.016000 x	370.000000 =	5.920000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	28.546889
5294	5294			
203.2		.020000 x	370.000000 =	7.400000
203.2		.022000 x	370.000000 =	8.140000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.100000 x	.895000 =	.089500
-----				
			T.E =	30.722139
5295	5295			
203.2		.020000 x	370.000000 =	7.400000
251		.050000 x	.895000 =	.044750
002		.250000 x	17.312112 =	4.328028
003		.250000 x	20.419486 =	5.104872
-----				
			T.E =	16.877650
5301	5301			
226		1.050000 x	13.000000 =	13.650000
251		.250000 x	.895000 =	.223750
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
-----				
			T.E =	36.512709

5302	5302				
227		1.050000 x	13.000000 =	13.650000	
251		.200000 x	.895000 =	.179000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
-----					
			T.E =	32.694799	
5321	5321				
203.2		.012000 x	370.000000 =	4.440000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
251		.500000 x	.895000 =	.447500	
226		1.050000 x	13.000000 =	13.650000	
-----					
			T.E =	52.495938	
5322	5322				
203.2		.012000 x	370.000000 =	4.440000	
227		1.050000 x	13.000000 =	13.650000	
251		.450000 x	.895000 =	.402750	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
-----					
			T.E =	48.678028	
5323	5323				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
228		1.050000 x	35.000000 =	36.750000	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.895000 =	.447500	
-----					
			T.E =	79.369098	
5324	5324				
203.2		.012000 x	370.000000 =	4.440000	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.895000 =	.447500	
-----					
			T.E =		
5325	5325				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.895000 =	.447500	
230		1.050000 x	.000000 =	.000000	
-----					
			T.E =		

5326	5326			
203.2		.012000 x	370.000000 =	4.440000
231		1.050000 x	22.000000 =	23.100000
251		.500000 x	.895000 =	.447500
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
		-----		
			T.E =	65.719098
5341	5341			
203.2		.037000 x	370.000000 =	13.690000
003		1.100000 x	20.419486 =	22.461435
232		1.050000 x	45.000000 =	47.250000
002		1.100000 x	17.312112 =	19.043323
251		.600000 x	.895000 =	.537000
		-----		
			T.E =	102.981758
5342	5342			
203.2		.037000 x	370.000000 =	13.690000
232		1.100000 x	45.000000 =	49.500000
002		1.700000 x	17.312112 =	29.430590
003		1.700000 x	20.419486 =	34.713126
251		.600000 x	.895000 =	.537000
		-----		
			T.E =	127.870717
5343	5343			
233		1.050000 x	21.300000 =	22.365000
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
233		.084000 x	21.300000 =	1.789200
		-----		
			T.E =	54.339478
5351	5351			
035		.200000 x	.088300 =	.017660
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.895000 =	.089500
236		1.060000 x	1.550000 =	1.643000
		-----		
			T.E =	9.296480
5352	5352			
035		.200000 x	.088300 =	.017660
251		.100000 x	.895000 =	.089500
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
237		1.060000 x	1.850000 =	1.961000
		-----		
			T.E =	9.614480

5353	5353			
035		.200000 x	.088300 =	.017660
238		1.060000 x	2.600000 =	2.756000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		.100000 x	.895000 =	.089500
-----				
			T.E =	10.409480
5354	5354			
035		.200000 x	.088300 =	.017660
239		1.060000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.895000 =	.089500
-----				
			T.E =	
5355	5355			
035		.200000 x	.088300 =	.017660
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.895000 =	.089500
240		1.060000 x	1.400000 =	1.484000
-----				
			T.E =	9.137480
5356	5356			
035		.200000 x	.088300 =	.017660
251		.100000 x	.895000 =	.089500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
241		1.060000 x	.000000 =	.000000
-----				
			T.E =	
5421	5421			
205		.055000 x	480.000000 =	26.400000
1471		1.000000 x	5.806289 =	5.806289
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
-----				
			T.E =	164.266882
5422	5422			
205		.035000 x	480.000000 =	16.800000
1472		1.000000 x	6.998763 =	6.998763
003		3.000000 x	20.419486 =	61.258458
002		3.000000 x	17.312112 =	51.936336
-----				
			T.E =	136.993557



5426	5426			
205		.095000 x	480.000000 =	45.600000
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916
1473		1.000000 x	11.954076 =	11.954076
1471		1.000000 x	5.806289 =	5.806289
			T.E =	289.749953
5427	5427			
205		.105000 x	480.000000 =	50.400000
002		7.000000 x	17.312112 =	121.184784
1474		1.000000 x	14.505595 =	14.505595
1471		1.000000 x	5.806289 =	5.806289
003		7.000000 x	20.419486 =	142.936402
			T.E =	334.833070
5428	5428			
205		.075000 x	480.000000 =	36.000000
003		5.500000 x	20.419486 =	112.307173
1474		1.000000 x	14.505595 =	14.505595
1472		1.000000 x	6.998763 =	6.998763
002		5.500000 x	17.312112 =	95.216616
			T.E =	265.028147
5431	5431			
205		.070000 x	480.000000 =	33.600000
1475		1.000000 x	40.394907 =	40.394907
208		.030000 x	1,435.000000 =	43.050000
1471		1.000000 x	5.806289 =	5.806289
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
			T.E =	386.972382
5432	5432			
205		.070000 x	480.000000 =	33.600000
1475		.800000 x	40.394907 =	32.315926
1471		1.000000 x	5.806289 =	5.806289
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
380		1.000000 x	16.560000 =	16.560000
			T.E =	276.940205

5436	5436				
205		.050000 x	480.000000 =	24.000000	
002		4.500000 x	17.312112 =	77.904504	
1476		1.000000 x	3.079100 =	3.079100	
003		4.500000 x	20.419486 =	91.887687	
-----					
			T.E =	196.871291	
5437	5437				
205		.065000 x	480.000000 =	31.200000	
002		5.000000 x	17.312112 =	86.560560	
003		5.000000 x	20.419486 =	102.097430	
1476		1.000000 x	3.079100 =	3.079100	
-----					
			T.E =	222.937090	
5438	5438				
205		.050000 x	480.000000 =	24.000000	
002		4.000000 x	17.312112 =	69.248448	
1476		1.000000 x	3.079100 =	3.079100	
003		4.000000 x	20.419486 =	81.677944	
-----					
			T.E =	178.005492	
5441.1	5441.1				
205		.065000 x	480.000000 =	31.200000	
1476		1.000000 x	3.079100 =	3.079100	
003		4.500000 x	20.419486 =	91.887687	
002		4.500000 x	17.312112 =	77.904504	
222.3		.004000 x	.000000 =	.000000	
-----					
			T.E =		
5441.2	5441.2				
205		.065000 x	480.000000 =	31.200000	
223.3		.004000 x	1,550.000000 =	6.200000	
002		4.500000 x	17.312112 =	77.904504	
1476		1.000000 x	3.079100 =	3.079100	
003		4.500000 x	20.419486 =	91.887687	
-----					
			T.E =	210.271291	
5441.3	5441.3				
205		.065000 x	480.000000 =	31.200000	
1476		1.000000 x	3.079100 =	3.079100	
243.1		.550000 x	2.700000 =	1.485000	
003		4.500000 x	20.419486 =	91.887687	
002		4.500000 x	17.312112 =	77.904504	
-----					
			T.E =	205.556291	

5442.1	5442.1			
205		.080000 x	480.000000 =	38.400000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.079100 =	3.079100
002		5.000000 x	17.312112 =	86.560560
-----				
			T.E =	
5442.2	5442.2			
205		.080000 x	480.000000 =	38.400000
1476		1.000000 x	3.079100 =	3.079100
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,550.000000 =	6.200000
-----				
			T.E =	236.337090
5442.3	5442.3			
205		.080000 x	480.000000 =	38.400000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.079100 =	3.079100
003		5.000000 x	20.419486 =	102.097430
243.1		.055000 x	2.700000 =	.148500
-----				
			T.E =	230.285590
5443.1	5443.1			
205		.065000 x	480.000000 =	31.200000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	3.079100 =	3.079100
002		4.000000 x	17.312112 =	69.248448
222.3		.004000 x	.000000 =	.000000
-----				
			T.E =	
5443.2	5443.2			
205		.065000 x	480.000000 =	31.200000
1476		1.000000 x	3.079100 =	3.079100
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.3		.004000 x	1,550.000000 =	6.200000
-----				
			T.E =	191.405492

5443.3	5443.3			
205		.065000 x	480.000000 =	31.200000
243.1		.550000 x	2.700000 =	1.485000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	3.079100 =	3.079100
003		4.000000 x	20.419486 =	81.677944
-----				
			T.E =	186.690492
5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	480.000000 =	12.000000
222.2		.010000 x	.000000 =	.000000
1476		1.000000 x	3.079100 =	3.079100
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
-----				
			T.E =	
5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	480.000000 =	12.000000
1476		1.000000 x	3.079100 =	3.079100
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000
-----				
			T.E =	192.255492
5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.079100 =	3.079100
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
205		.040000 x	480.000000 =	19.200000
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
002		4.500000 x	17.312112 =	77.904504
1476		1.000000 x	3.079100 =	3.079100
003		4.500000 x	20.419486 =	91.887687
223.2		.010000 x	1,700.000000 =	17.000000
205		.040000 x	480.000000 =	19.200000
-----				
			T.E =	218.321291

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	3.079100 =	3.079100
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
205		.025000 x	480.000000 =	12.000000
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	480.000000 =	12.000000
1476		1.000000 x	3.079100 =	3.079100
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.010000 x	1,700.000000 =	17.000000
-----				
			T.E =	173.389693
5449	5449			
205		.045000 x	480.000000 =	21.600000
002		3.000000 x	17.312112 =	51.936336
1476		1.000000 x	3.079100 =	3.079100
003		3.000000 x	20.419486 =	61.258458
243.5		.850000 x	5.900000 =	5.015000
-----				
			T.E =	142.888894
5451.1	5451.1			
205		.090000 x	480.000000 =	43.200000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	3.079100 =	3.079100
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000
-----				
			T.E =	
5451.2	5451.2			
205		.090000 x	480.000000 =	43.200000
1476		1.000000 x	3.079100 =	3.079100
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,550.000000 =	6.200000
-----				
			T.E =	241.137090

5451.3	5451.3			
205		.090000 x	480.000000 =	43.200000
243.1		.550000 x	2.700000 =	1.485000
002		5.000000 x	17.312112 =	86.560560
1476		1.000000 x	3.079100 =	3.079100
003		5.000000 x	20.419486 =	102.097430
			T.E =	236.422090
5456	5456			
205		.055000 x	480.000000 =	26.400000
1478		1.000000 x	3.504100 =	3.504100
002		4.000000 x	17.312112 =	69.248448
003		4.000000 x	20.419486 =	81.677944
			T.E =	180.830492
5457	5457			
205		.085000 x	480.000000 =	40.800000
003		7.000000 x	20.419486 =	142.936402
1476		1.500000 x	3.079100 =	4.618650
002		7.000000 x	17.312112 =	121.184784
261		2.200000 x	.611600 =	1.345520
			T.E =	310.885356
5461.1	5461.1			
205		.065000 x	480.000000 =	31.200000
222.2		.010000 x	.000000 =	.000000
1479		1.000000 x	38.031417 =	38.031417
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
			T.E =	
5461.2	5461.2			
205		.065000 x	480.000000 =	31.200000
1479		1.000000 x	38.031417 =	38.031417
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
223.2		.010000 x	1,700.000000 =	17.000000
			T.E =	293.755206
5462.1	5462.1			
205		.065000 x	480.000000 =	31.200000
1480		1.000000 x	36.683135 =	36.683135
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
			T.E =	

5462.2	5462.2			
205		.065000 x	480.000000 =	31.200000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
1480		1.000000 x	36.683135 =	36.683135
223.2		.010000 x	1,700.000000 =	17.000000
-----				
			T.E =	292.406924
5463.1	5463.1			
205		.055000 x	480.000000 =	26.400000
1479		.500000 x	38.031417 =	19.015709
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5463.2	5463.2			
205		.055000 x	480.000000 =	26.400000
223.2		.010000 x	1,700.000000 =	17.000000
002		6.000000 x	17.312112 =	103.872672
1479		.500000 x	38.031417 =	19.015709
003		6.000000 x	20.419486 =	122.516916
-----				
			T.E =	288.805297
5464.1	5464.1			
205		.070000 x	480.000000 =	33.600000
1479		.500000 x	38.031417 =	19.015709
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
-----				
			T.E =	
5464.2	5464.2			
205		.070000 x	480.000000 =	33.600000
223.2		.010000 x	1,700.000000 =	17.000000
003		7.000000 x	20.419486 =	142.936402
1479		.500000 x	38.031417 =	19.015709
002		7.000000 x	17.312112 =	121.184784
-----				
			T.E =	333.736895

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
1476		1.000000 x	3.079100 =	3.079100
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,435.000000 =	43.050000
-----				
			T.E =	
5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
002		5.500000 x	17.312112 =	95.216616
1476		1.000000 x	3.079100 =	3.079100
003		5.500000 x	20.419486 =	112.307173
223.2		.005000 x	1,700.000000 =	8.500000
208		.030000 x	1,435.000000 =	43.050000
-----				
			T.E =	278.802889
5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.900000 x	38.031417 =	34.228275
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
1479		.900000 x	38.031417 =	34.228275
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,700.000000 =	17.000000
-----				
			T.E =	249.136265
5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
222.2		.000960 x	.000000 =	.000000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
222.2		.012000 x	.000000 =	.000000
-----				
			T.E =	



5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
223.2		.012000 x	1,700.000000 =	20.400000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.000960 x	1,700.000000 =	1.632000
203.2		.001040 x	370.000000 =	.384800
-----				
			T.E =	159.287393
5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.2		.010000 x	.000000 =	.000000
222.2		.000800 x	.000000 =	.000000
203.2		.002000 x	370.000000 =	.740000
-----				
			T.E =	
5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
203.2		.002000 x	370.000000 =	.740000
223.2		.010000 x	1,700.000000 =	17.000000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.000800 x	1,700.000000 =	1.360000
-----				
			T.E =	179.276392
5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.500000 x	38.031417 =	19.015709
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
222.2		.010000 x	.000000 =	.000000
-----				
			T.E =	
5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
003		4.500000 x	20.419486 =	91.887687
1479		.500000 x	38.031417 =	19.015709
002		4.500000 x	17.312112 =	77.904504
-----				
			T.E =	215.057900

5471	5471				
203.2		.035000 x	370.000000 =	12.950000	
251		3.000000 x	.895000 =	2.685000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
-----					
			T.E =	147.695593	
5472.1	5472.1				
203.2		.026000 x	370.000000 =	9.620000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
251		3.000000 x	.895000 =	2.685000	
222.4		.010000 x	.000000 =	.000000	
-----					
			T.E =	160.365593	
5472.2	5472.2				
203.2		.026000 x	370.000000 =	9.620000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
251		3.000000 x	.895000 =	2.685000	
223.4		.010000 x	1,600.000000 =	16.000000	
-----					
			T.E =	175.640860	
5501.1	5501.1				
211		.040000 x	750.000000 =	30.000000	
003		5.000000 x	20.419486 =	102.097430	
002		2.500000 x	17.312112 =	43.280280	
252		.100000 x	2.184000 =	.218400	
251		.050000 x	.895000 =	.044750	
-----					
			T.E =	205.640860	
5501.2	5501.2				
212		.040000 x	1,500.000000 =	60.000000	
251		.050000 x	.895000 =	.044750	
252		.100000 x	2.184000 =	.218400	
003		5.000000 x	20.419486 =	102.097430	
002		2.500000 x	17.312112 =	43.280280	
-----					
			T.E =	205.640860	
5502	5502				
210		.040000 x	.000000 =	.000000	
251		.050000 x	.895000 =	.044750	
002		2.000000 x	17.312112 =	34.624224	
003		4.000000 x	20.419486 =	81.677944	
252		.100000 x	2.184000 =	.218400	
-----					
			T.E =		

5511.1	5511.1			
211		.020000 x	750.000000 =	15.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	2.184000 =	.218400
		-----		
			T.E =	108.260134
5511.2	5511.2			
212		.020000 x	1,500.000000 =	30.000000
003		3.200000 x	20.419486 =	65.342355
002		1.600000 x	17.312112 =	27.699379
252		.100000 x	2.184000 =	.218400
		-----		
			T.E =	123.260134
5512	5512			
205		.020000 x	480.000000 =	9.600000
252		.100000 x	2.184000 =	.218400
002		1.500000 x	17.312112 =	25.968168
003		3.000000 x	20.419486 =	61.258458
		-----		
			T.E =	97.045026
5513.1	5513.1			
211		.020000 x	750.000000 =	15.000000
252		.100000 x	2.184000 =	.218400
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	131.520568
5513.2	5513.2			
212		.020000 x	1,500.000000 =	30.000000
252		.100000 x	2.184000 =	.218400
003		4.000000 x	20.419486 =	81.677944
002		2.000000 x	17.312112 =	34.624224
		-----		
			T.E =	146.520568
5514	5514			
205		.020000 x	480.000000 =	9.600000
003		3.800000 x	20.419486 =	77.594047
002		1.800000 x	17.312112 =	31.161802
252		.100000 x	2.184000 =	.218400
		-----		
			T.E =	118.574248

5521	5521				
205		.030000 x	480.000000 =		14.400000
252		.150000 x	2.184000 =		.327600
002		.800000 x	17.312112 =		13.849690
003		2.000000 x	20.419486 =		40.838972
					-----
			T.E =		69.416262
5531.1	5531.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	2.184000 =		.043680
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
					-----
			T.E =		64.585028
5531.2	5531.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.184000 =		.043680
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
					-----
			T.E =		72.085028
5531.3	5531.3				
205		.010000 x	480.000000 =		4.800000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
252		.020000 x	2.184000 =		.043680
					-----
			T.E =		61.885028
5532.1	5532.1				
211		.010000 x	750.000000 =		7.500000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
252		.020000 x	2.184000 =		.043680
					-----
			T.E =		86.114250
5532.2	5532.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.184000 =		.043680
002		1.000000 x	17.312112 =		17.312112
003		3.000000 x	20.419486 =		61.258458
					-----
			T.E =		93.614250



5605	5605			
243.3		1.100000 x	4.500000 =	4.950000
243.3		.187000 x	4.500000 =	.841500
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
-----				
			T.E =	81.254696
5606	5606			
243.2		1.100000 x	3.800000 =	4.180000
003		1.800000 x	20.419486 =	36.755075
243.2		.220000 x	3.800000 =	.836000
002		1.800000 x	17.312112 =	31.161802
-----				
			T.E =	72.932876
5607	5607			
205		.012000 x	480.000000 =	5.760000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280
242		2.200000 x	1.500000 =	3.300000
205		.002400 x	480.000000 =	1.152000
242		.440000 x	1.500000 =	.660000
-----				
			T.E =	105.200995
5608.1	5608.1			
205		.012000 x	480.000000 =	5.760000
205		.002400 x	480.000000 =	1.152000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
222.1		.006000 x	.000000 =	.000000
222.1		.001200 x	.000000 =	.000000
-----				
			T.E =	
5608.2	5608.2			
205		.012000 x	480.000000 =	5.760000
205		.002400 x	480.000000 =	1.152000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.1		.006000 x	2,100.000000 =	12.600000
223.1		.001200 x	2,100.000000 =	2.520000
-----				
			T.E =	154.092593

5611	5611			
205		.060000 x	480.000000 =	28.800000
003		7.000000 x	20.419486 =	142.936402
251		5.000000 x	.895000 =	4.475000
002		7.000000 x	17.312112 =	121.184784
-----				
			T.E =	297.396186
5612.1	5612.1			
205		.060000 x	480.000000 =	28.800000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.895000 =	4.475000
222.1		.006000 x	.000000 =	.000000
-----				
			T.E =	
5612.2	5612.2			
205		.060000 x	480.000000 =	28.800000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.895000 =	4.475000
223.1		.006000 x	2,100.000000 =	12.600000
-----				
			T.E =	309.996186
5613.1	5613.1			
205		.015000 x	480.000000 =	7.200000
205		.001500 x	480.000000 =	.720000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
222.2		.003000 x	.000000 =	.000000
-----				
			T.E =	
5613.2	5613.2			
205		.015000 x	480.000000 =	7.200000
205		.001500 x	480.000000 =	.720000
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
223.2		.003000 x	1,700.000000 =	5.100000
-----				
			T.E =	69.617397
5614.1	5614.1			
205		.010000 x	480.000000 =	4.800000
222.2		.002000 x	.000000 =	.000000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
205		.001500 x	480.000000 =	.720000
-----				
			T.E =	

5614.2	5614.2			
205		.010000 x	480.000000 =	4.800000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,700.000000 =	3.400000
205		.001500 x	480.000000 =	.720000
-----				
			T.E =	54.197918
5615.1	5615.1			
205		.008000 x	480.000000 =	3.840000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	480.000000 =	.691200
-----				
			T.E =	
5615.2	5615.2			
205		.008000 x	480.000000 =	3.840000
003		1.000000 x	20.419486 =	20.419486
205		.001440 x	480.000000 =	.691200
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,700.000000 =	1.530000
-----				
			T.E =	43.792798
5616	5616			
205		.003000 x	480.000000 =	1.440000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
205		.007500 x	480.000000 =	3.600000
-----				
			T.E =	42.771598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
521		.250000 x	2.461700 =	.615425
-----				
			T.E =	42.747023
5619	5619			
205		.001400 x	480.000000 =	.672000
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	4.755897



5620	5620			
203.2		.012000 x	370.000000 =	4.440000
251		.020000 x	.895000 =	.017900
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634
220		4.200000 x	.000000 =	.000000
			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.895000 =	14.320000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
			T.E =	
5622	5622			
211		1.100000 x	750.000000 =	825.000000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
251		16.000000 x	.895000 =	14.320000
			T.E =	1,971.267940
5626	5626			
205		.030000 x	480.000000 =	14.400000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168
251		1.000000 x	.895000 =	.895000
			T.E =	71.892397
6101	6101			
267		1.050000 x	.910400 =	.955920
003		.050000 x	20.419486 =	1.020974
			T.E =	1.976894
6102	6102			
252		.050000 x	2.184000 =	.109200
267		1.030000 x	.910400 =	.937712
003		.060000 x	20.419486 =	1.225169
			T.E =	2.272081
6103	6103			
268		1.050000 x	1.054400 =	1.107120
003		.050000 x	20.419486 =	1.020974
			T.E =	2.128094

6104	6104				
252		.050000 x	2.184000 =	.109200	
268		1.030000 x	1.054400 =	1.086032	
003		.060000 x	20.419486 =	1.225169	
		-----			
			T.E =	2.420401	
6111	6111				
266		1.100000 x	.632700 =	.695970	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	3.758893	
6116	6116				
280		1.050000 x	1.144500 =	1.201725	
003		.100000 x	20.419486 =	2.041949	
		-----			
			T.E =	3.243674	
6117	6117				
281		1.050000 x	6.615200 =	6.945960	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =	10.008883	
6118	6118				
266		1.150000 x	.632700 =	.727605	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
		-----			
			T.E =	8.273925	
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	20.419486 =	3.062923	
		-----			
			T.E =		
6120	6120				
289		1.050000 x	.904700 =	.949935	
003		.100000 x	20.419486 =	2.041949	
		-----			
			T.E =	2.991884	
6121	6121				
266		1.100000 x	.632700 =	.695970	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	
		-----			
			T.E =	8.242290	

6122	6122				
265		1.050000 x	.847400 =		.889770
003		.200000 x	20.419486 =		4.083897
				T.E =	4.973667
6123	6123				
265		.900000 x	.847400 =		.762660
002		.150000 x	17.312112 =		2.596817
003		.150000 x	20.419486 =		3.062923
266		.100000 x	.632700 =		.063270
266		.010000 x	.632700 =		.006327
265		.090000 x	.847400 =		.076266
				T.E =	6.568263
6126	6126				
265		1.250000 x	.847400 =		1.059250
003		.200000 x	20.419486 =		4.083897
003		.200000 x	20.419486 =		4.083897
				T.E =	9.227044
6127	6127				
290		4.800000 x	3.670000 =		17.616000
002		.800000 x	17.312112 =		13.849690
003		.800000 x	20.419486 =		16.335589
				T.E =	47.801278
6128	6128				
290		1.200000 x	3.670000 =		4.404000
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897
				T.E =	11.950320
6201	6201				
264		1.400000 x	1.115900 =		1.562260
003		.250000 x	20.419486 =		5.104872
002		.250000 x	17.312112 =		4.328028
				T.E =	10.995160
6202	6202				
264		1.300000 x	1.115900 =		1.450670
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897
				T.E =	8.996990

6203	6203				
282		1.200000 x	.977800 =		1.173360
002		.350000 x	17.312112 =		6.059239
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		14.379419
6204	6204				
282		1.300000 x	.977800 =		1.271140
002		.400000 x	17.312112 =		6.924845
003		.400000 x	20.419486 =		8.167794
		-----			
			T.E =		16.363779
6205	6205				
277		1.250000 x	1.009400 =		1.261750
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056
		-----			
			T.E =		20.127549
6221	6221				
265		1.150000 x	.847400 =		.974510
002		.200000 x	17.312112 =		3.462422
003		.200000 x	20.419486 =		4.083897
		-----			
			T.E =		8.520830
6222	6222				
265		1.200000 x	.847400 =		1.016880
002		.350000 x	17.312112 =		6.059239
003		.350000 x	20.419486 =		7.146820
		-----			
			T.E =		14.222939
6223	6223				
265		1.250000 x	.847400 =		1.059250
002		.500000 x	17.312112 =		8.656056
003		.500000 x	20.419486 =		10.209743
		-----			
			T.E =		19.925049
6224	6224				
271		.720000 x	1.000400 =		.720288
003		.200000 x	20.419486 =		4.083897
002		.200000 x	17.312112 =		3.462422
282		.480000 x	.977800 =		.469344
		-----			
			T.E =		8.735952

6225	6225			
271		.720000 x	1.000400 =	.720288
003		.250000 x	20.419486 =	5.104872
282		.480000 x	.977800 =	.469344
002		.250000 x	17.312112 =	4.328028
		-----		
			T.E =	10.622532
6226	6226			
265		1.200000 x	.847400 =	1.016880
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	27.428999
6227	6227			
265		1.250000 x	.847400 =	1.059250
003		.850000 x	20.419486 =	17.356563
002		.850000 x	17.312112 =	14.715295
		-----		
			T.E =	33.131108
6228	6228			
282		1.250000 x	.977800 =	1.222250
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	16.314889
6229	6229			
282		1.250000 x	.977800 =	1.222250
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
		-----		
			T.E =	18.201469
6230	6230			
277		1.100000 x	1.009400 =	1.110340
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	19.976139
6231	6231			
265		1.150000 x	.847400 =	.974510
002		.250000 x	17.312112 =	4.328028
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	10.407410

6232	6232			
265		1.150000 x	.847400 =	.974510
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
-----				
			T.E =	16.067149
6236	6236			
253		.500000 x	2.758000 =	1.379000
266		2.000000 x	.632700 =	1.265400
386		.350000 x	28.630000 =	10.020500
390		2.100000 x	1.500000 =	3.150000
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
565.3		.350000 x	3.800000 =	1.330000
392		.350000 x	27.420000 =	9.597000
388		.350000 x	48.870000 =	17.104500
276		5.850000 x	.785700 =	4.596345
272		1.500000 x	.905900 =	1.358850
-----				
			T.E =	117.718471
6237	6237			
253		.850000 x	2.758000 =	2.344300
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.650000 =	1.977500
392		.350000 x	27.420000 =	9.597000
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.905900 =	4.529500
266		2.100000 x	.632700 =	1.328670
260		9.500000 x	.558700 =	5.307650
-----				
			T.E =	203.136012
6238	6238			
253		.400000 x	2.758000 =	1.103200
265		6.000000 x	.847400 =	5.084400
266		13.000000 x	.632700 =	8.225100
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
-----				
			T.E =	203.070690
6239	6239			
277		1.100000 x	1.009400 =	1.110340
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	12.429819

6301	6301			
266		1.250000 x	.632700 =	.790875
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	15.883514
6302	6302			
266		9.000000 x	.632700 =	5.694300
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201
		-----		
			T.E =	137.754893
6401	6401			
265		1.150000 x	.847400 =	.974510
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
		-----		
			T.E =	8.520830
6402	6402			
265		1.200000 x	.847400 =	1.016880
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	12.336359
6403	6403			
265		1.250000 x	.847400 =	1.059250
002		.350000 x	17.312112 =	6.059239
003		.350000 x	20.419486 =	7.146820
		-----		
			T.E =	14.265309
6406	6406			
265		1.200000 x	.847400 =	1.016880
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	23.655839
6407	6407			
265		1.250000 x	.847400 =	1.059250
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
		-----		
			T.E =	27.471369

6411	6411				
565.3		1.650000 x	3.800000 =	6.270000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	19.476059	
6412	6412				
565.5		1.550000 x	5.650000 =	8.757500	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	
		-----			
			T.E =	25.736719	
6413	6413				
565.6		1.450000 x	7.800000 =	11.310000	
002		.550000 x	17.312112 =	9.521662	
003		.550000 x	20.419486 =	11.230717	
		-----			
			T.E =	32.062379	
6416	6416				
566.3		1.600000 x	5.050000 =	8.080000	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	
		-----			
			T.E =	21.286059	
6417	6417				
566.5		1.500000 x	7.750000 =	11.625000	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	
		-----			
			T.E =	28.604219	
6418	6418				
566.6		1.400000 x	10.300000 =	14.420000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	
		-----			
			T.E =	35.172379	
6421	6421				
565.3		1.050000 x	3.800000 =	3.990000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	12.157794	







6504	6504			
002		1.200000 x	17.312112 =	20.774534
6501		.910000 x	237.719792 =	216.325011
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	261.602928
6505	6505			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.870000 x	237.719792 =	206.816219
		-----		
			T.E =	244.547817
6506	6506			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.810000 x	237.719792 =	192.553032
		-----		
			T.E =	230.284630
6507	6507			
002		.900000 x	17.312112 =	15.580901
003		.900000 x	20.419486 =	18.377537
6501		.920000 x	237.719792 =	218.702209
		-----		
			T.E =	252.660647
6508	6508			
002		1.300000 x	17.312112 =	22.505746
6501		1.030000 x	237.719792 =	244.851386
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	293.902463
6509	6509			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		1.010000 x	237.719792 =	240.096990
		-----		
			T.E =	277.828588
6510	6510			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.080000 x	237.719792 =	256.737375
		-----		
			T.E =	302.015293

6511	6511			
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229
6501		.920000 x	237.719792 =	218.702209
		-----		
			T.E =	275.299606
6512	6512			
002		1.400000 x	17.312112 =	24.236957
6501		.820000 x	237.719792 =	194.930229
003		1.400000 x	20.419486 =	28.587280
		-----		
			T.E =	247.754467
6513	6513			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.780000 x	237.719792 =	185.421438
		-----		
			T.E =	234.472515
6514	6514			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.760000 x	237.719792 =	180.667042
		-----		
			T.E =	225.944960
6515	6515			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.800000 x	237.719792 =	190.175834
		-----		
			T.E =	227.907432
6516	6516			
002		1.300000 x	17.312112 =	22.505746
6501		1.220000 x	237.719792 =	290.018146
003		1.300000 x	20.419486 =	26.545332
		-----		
			T.E =	339.069224
6517	6517			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.120000 x	237.719792 =	266.246167
		-----		
			T.E =	311.524085

6518	6518			
002		1.100000 x	17.312112 =	19.043323
003		1.100000 x	20.419486 =	22.461435
6501		.670000 x	237.719792 =	159.272261
		-----		
			T.E =	200.777018
6519	6519			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.280000 x	237.719792 =	304.281334
		-----		
			T.E =	353.332411
6520	6520			
002		1.200000 x	17.312112 =	20.774534
6501		1.120000 x	237.719792 =	266.246167
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	311.524085
6521	6521			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.210000 x	237.719792 =	287.640948
		-----		
			T.E =	336.692026
6522	6522			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.190000 x	237.719792 =	282.886552
		-----		
			T.E =	328.164470
6523	6523			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.280000 x	237.719792 =	304.281334
		-----		
			T.E =	349.559251
6524	6524			
002		1.200000 x	17.312112 =	20.774534
6501		.800000 x	237.719792 =	190.175834
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	235.453751

6525	6525			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.040000 x	237.719792 =	247.228584
		-----		
			T.E =	292.506501
6526	6526			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.900000 x	237.719792 =	213.947813
		-----		
			T.E =	262.998890
6527	6527			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.120000 x	237.719792 =	266.246167
		-----		
			T.E =	315.297244
6528	6528			
002		1.200000 x	17.312112 =	20.774534
6501		.840000 x	237.719792 =	199.684625
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	244.962543
6529	6529			
002		1.200000 x	17.312112 =	20.774534
6501		1.080000 x	237.719792 =	256.737375
003		1.200000 x	20.419486 =	24.503383
		-----		
			T.E =	302.015293
6530	6530			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.710000 x	237.719792 =	168.781052
		-----		
			T.E =	206.512650
6531	6531			
002		.600000 x	17.312112 =	10.387267
003		.600000 x	20.419486 =	12.251692
6501		.480000 x	237.719792 =	114.105500
		-----		
			T.E =	136.744459

6532	6532			
294		6.000000 x	3.518600 =	21.111600
002		2.500000 x	17.312112 =	43.280280
003		2.500000 x	20.419486 =	51.048715
296		1.000000 x	12.470000 =	12.470000
294		.300000 x	3.518600 =	1.055580
		-----		
			T.E =	128.966175
6541	6541			
282		.350000 x	.977800 =	.342230
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
296		.120000 x	12.470000 =	1.496400
295		1.050000 x	6.490000 =	6.814500
		-----		
			T.E =	27.518929
6542	6542			
295		1.050000 x	6.490000 =	6.814500
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
296		.100000 x	12.470000 =	1.247000
		-----		
			T.E =	38.246778
6543	6543			
295		.400000 x	6.490000 =	2.596000
296		.130000 x	12.470000 =	1.621100
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	8.300997
7101	7101			
201		.000500 x	290.000000 =	.145000
1445		.010000 x	61.130300 =	.611303
003		.850000 x	20.419486 =	17.356563
002		.500000 x	17.312112 =	8.656056
		-----		
			T.E =	26.768922
7102	7102			
201		.000500 x	290.000000 =	.145000
1445		.010000 x	61.130300 =	.611303
003		.700000 x	20.419486 =	14.293640
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	21.974788

7103	7103				
201		.000500 x	290.000000 =	.145000	
002		.300000 x	17.312112 =	5.193634	
003		.600000 x	20.419486 =	12.251692	
1445		.004000 x	61.130300 =	.244521	
		-----			
			T.E =	17.834846	
7104	7104				
201		.000500 x	290.000000 =	.145000	
003		1.000000 x	20.419486 =	20.419486	
1445		.008000 x	61.130300 =	.489042	
002		.600000 x	17.312112 =	10.387267	
		-----			
			T.E =	31.440796	
7111	7111				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	20.419486 =	12.251692	
1413		.027000 x	28.617300 =	.772667	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	17.891838	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	40.969950 =	1.106189	
003		.650000 x	20.419486 =	13.272666	
001		.350000 x	15.741598 =	5.509559	
		-----			
			T.E =	20.033414	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	61.130300 =	1.650518	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	
		-----			
			T.E =	22.853586	
7122	7122				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
003		.800000 x	20.419486 =	16.335589	
1444		.027000 x	75.237500 =	2.031413	
		-----			
			T.E =	23.234481	



7123	7123			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1445		.006000 x	61.130300 =	.366782
1446		.006000 x	52.018100 =	.312109
1462		.015000 x	87.604250 =	1.314064
003		.900000 x	20.419486 =	18.377537
			T.E =	25.237971
7124.1	7124.1			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1465		.015000 x	94.072650 =	1.411090
1445		.012000 x	61.130300 =	.733564
003		.900000 x	20.419486 =	18.377537
			T.E =	25.389670
7124.2	7124.2			
201		.000500 x	290.000000 =	.145000
1466		.015000 x	91.933050 =	1.378996
1445		.012000 x	61.130300 =	.733564
003		.900000 x	20.419486 =	18.377537
001		.300000 x	15.741598 =	4.722479
			T.E =	25.357576
7124.3	7124.3			
201		.000500 x	290.000000 =	.145000
003		.900000 x	20.419486 =	18.377537
1467		.015000 x	86.940650 =	1.304110
1445		.012000 x	61.130300 =	.733564
001		.300000 x	15.741598 =	4.722479
			T.E =	25.282690
7131	7131			
201		.000500 x	290.000000 =	.145000
003		.600000 x	20.419486 =	12.251692
1413		.021000 x	28.617300 =	.600963
1426		.006000 x	152.456250 =	.914738
001		.300000 x	15.741598 =	4.722479
			T.E =	18.634872

7132	7132			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1427		.006000 x	163.304700 =	.979828
1418		.021000 x	40.969950 =	.860369
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	20.767422
7133	7133			
201		.000500 x	290.000000 =	.145000
003		.600000 x	20.419486 =	12.251692
1463		.015000 x	74.794250 =	1.121914
1427		.006000 x	163.304700 =	.979828
1418		.006000 x	40.969950 =	.245820
001		.350000 x	15.741598 =	5.509559
-----				
			T.E =	20.253813
7134	7134			
201		.000500 x	290.000000 =	.145000
003		.600000 x	20.419486 =	12.251692
1418		.006000 x	40.969950 =	.245820
1464		.015000 x	56.350200 =	.845253
1427		.006000 x	163.304700 =	.979828
001		.350000 x	15.741598 =	5.509559
-----				
			T.E =	19.977152
7136	7136			
201		.000500 x	290.000000 =	.145000
001		.250000 x	15.741598 =	3.935400
003		.400000 x	20.419486 =	8.167794
1418		.017000 x	40.969950 =	.696489
-----				
			T.E =	12.944683
7138	7138			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1418		.027000 x	40.969950 =	1.106189
003		.800000 x	20.419486 =	16.335589
-----				
			T.E =	22.309257
7141	7141			
201		.000500 x	290.000000 =	.145000
1445		.027000 x	61.130300 =	1.650518
003		1.000000 x	20.419486 =	20.419486
001		.400000 x	15.741598 =	6.296639
-----				
			T.E =	28.511643

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	28.617300 =	.400642
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	
7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1421		.016000 x	.000000 =	.000000
001		.350000 x	15.741598 =	5.509559
1413		.007000 x	28.617300 =	.200321
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	
7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	28.617300 =	.400642
001		.450000 x	15.741598 =	7.083719
1422		.016000 x	.000000 =	.000000
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	
7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
1422		.016000 x	.000000 =	.000000
1413		.007000 x	28.617300 =	.200321
003		.600000 x	20.419486 =	12.251692
001		.450000 x	15.741598 =	7.083719
-----				
			T.E =	
7150	7150			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.014000 x	40.969950 =	.573579
003		.650000 x	20.419486 =	13.272666
1422		.016000 x	.000000 =	.000000
-----				
			T.E =	

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
1418		.007000 x	40.969950 =	.286790
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.304700 =	1.143133
003		.650000 x	20.419486 =	13.272666
-----				
			T.E =	
7152	7152			
201		.000500 x	290.000000 =	.145000
1447		.014000 x	58.265900 =	.815723
1448		.016000 x	.000000 =	.000000
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719
-----				
			T.E =	
7153	7153			
201		.000500 x	290.000000 =	.145000
1448		.016000 x	.000000 =	.000000
1447		.007000 x	58.265900 =	.407861
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	20.419486 =	14.293640
001		.450000 x	15.741598 =	7.083719
-----				
			T.E =	
7161	7161			
201		.000800 x	290.000000 =	.232000
1445		.022000 x	61.130300 =	1.344867
003		1.600000 x	20.419486 =	32.671178
1453		.020000 x	187.752750 =	3.755055
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959
-----				
			T.E =	75.147437
7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.130300 =	1.344867
001		.600000 x	15.741598 =	9.444959
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
-----				
			T.E =	

7163	7163			
201		.000800 x	290.000000 =	.232000
1454		.020000 x	210.972750 =	4.219455
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
1445		.022000 x	61.130300 =	1.344867
001		.600000 x	15.741598 =	9.444959
			T.E =	75.611837
7164	7164			
201		.000800 x	290.000000 =	.232000
1455		.020000 x	.000000 =	.000000
1445		.022000 x	61.130300 =	1.344867
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959
			T.E =	
7165	7165			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.741598 =	9.444959
002		1.600000 x	17.312112 =	27.699379
1459		.020000 x	210.972750 =	4.219455
1445		.022000 x	61.130300 =	1.344867
003		1.600000 x	20.419486 =	32.671178
			T.E =	75.611837
7166	7166			
201		.000800 x	290.000000 =	.232000
1453		.017000 x	187.752750 =	3.191797
1445		.022000 x	61.130300 =	1.344867
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
			T.E =	57.917380
7167	7167			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
003		1.200000 x	20.419486 =	24.503383
1458		.017000 x	.000000 =	.000000
1445		.022000 x	61.130300 =	1.344867
002		1.200000 x	17.312112 =	20.774534
			T.E =	

7168	7168			
201		.000800 x	290.000000 =	.232000
1454		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.130300 =	1.344867
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799
			T.E =	58.312120
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.130300 =	1.344867
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799
			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
1459		.017000 x	210.972750 =	3.586537
1445		.022000 x	61.130300 =	1.344867
003		1.200000 x	20.419486 =	24.503383
			T.E =	58.312120
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160
			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229
			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435
			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537
			T.E =	18.377537

7179	7179			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7181	7181			
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	14.293640
7206	7206			
142		26.000000 x	.385000 =	10.010000
1412		.040000 x	27.238800 =	1.089552
003		.600000 x	20.419486 =	12.251692
002		.300000 x	17.312112 =	5.193634
		-----		
			T.E =	28.544877
7207	7207			
142		26.000000 x	.385000 =	10.010000
002		.250000 x	17.312112 =	4.328028
003		.500000 x	20.419486 =	10.209743
1412		.020000 x	27.238800 =	.544776
		-----		
			T.E =	25.092547
7208	7208			
142		26.000000 x	.385000 =	10.010000
002		.200000 x	17.312112 =	3.462422
1412		.025000 x	27.238800 =	.680970
003		.400000 x	20.419486 =	8.167794
		-----		
			T.E =	22.321187
7209	7209			
142		26.000000 x	.385000 =	10.010000
002		.150000 x	17.312112 =	2.596817
1412		.005000 x	27.238800 =	.136194
003		.300000 x	20.419486 =	6.125846
		-----		
			T.E =	18.868857
7211	7211			
146		15.000000 x	.415000 =	6.225000
1445		.001000 x	61.130300 =	.061130
003		.400000 x	20.419486 =	8.167794
002		.200000 x	17.312112 =	3.462422
283		.075000 x	1.305700 =	.097928
		-----		
			T.E =	18.014275

7221	7221			
203.2		.001500 x	370.000000 =	.555000
492		.200000 x	.540000 =	.108000
506		1.150000 x	1.431700 =	1.646455
003		.200000 x	20.419486 =	4.083897
002		.150000 x	17.312112 =	2.596817
254		.020000 x	3.532000 =	.070640
-----				
			T.E =	9.060809
7222	7222			
254		.050000 x	3.532000 =	.176600
002		.150000 x	17.312112 =	2.596817
003		.250000 x	20.419486 =	5.104872
506		1.200000 x	1.431700 =	1.718040
492		.200000 x	.540000 =	.108000
-----				
			T.E =	9.704328
7223	7223			
254		.050000 x	3.532000 =	.176600
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
508		1.200000 x	.860000 =	1.032000
493		.200000 x	.730000 =	.146000
-----				
			T.E =	8.900920
7231	7231			
274		1.200000 x	1.372600 =	1.647120
274		.200000 x	1.372600 =	.274520
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028
-----				
			T.E =	11.354540
7241	7241			
297.2		.051072 x	.000000 =	.000000
003		1.400000 x	20.419486 =	28.587280
495		.500000 x	.000000 =	.000000
002		1.400000 x	17.312112 =	24.236957
001		.200000 x	15.741598 =	3.148320
-----				
			T.E =	



7242	7242			
297.2		.057000 x	.000000 =	.000000
002		2.800000 x	17.312112 =	48.473914
001		.200000 x	15.741598 =	3.148320
003		2.800000 x	20.419486 =	57.174561
495		1.000000 x	.000000 =	.000000
-----				
			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.895000 =	1.163500
-----				
			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
251		1.300000 x	.895000 =	1.163500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.895000 =	1.163500
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
-----				
			T.E =	
7244	7244			
251		1.200000 x	.895000 =	1.074000
273		1.200000 x	1.112900 =	1.335480
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
-----				
			T.E =	40.141078
7245	7245			
251		.500000 x	.895000 =	.447500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
273		1.200000 x	1.112900 =	1.335480
-----				
			T.E =	28.195099

7246	7246			
265		.500000 x	.847400 =	.423700
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
298.1		6.700000 x	7.120000 =	47.704000
			T.E =	85.859298
7301	7301			
096		1.050000 x	.000000 =	.000000
1444		.001500 x	75.237500 =	.112856
1445		.025000 x	61.130300 =	1.528258
003		.900000 x	20.419486 =	18.377537
001		.400000 x	15.741598 =	6.296639
			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1445		.025000 x	61.130300 =	1.528258
1444		.002000 x	75.237500 =	.150475
003		1.000000 x	20.419486 =	20.419486
001		.500000 x	15.741598 =	7.870799
			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
001		1.000000 x	15.741598 =	15.741598
003		2.000000 x	20.419486 =	40.838972
1445		.025000 x	61.130300 =	1.528258
1444		.001000 x	75.237500 =	.075238
			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	61.130300 =	1.528258
001		.800000 x	15.741598 =	12.593278
1444		.001500 x	75.237500 =	.112856
003		1.600000 x	20.419486 =	32.671178
			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
001		.150000 x	15.741598 =	2.361240
1444		.000200 x	75.237500 =	.015048
1445		.004000 x	61.130300 =	.244521
003		.300000 x	20.419486 =	6.125846
			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1445		.005000 x	61.130300 =	.305652
1417		.033000 x	39.591450 =	1.306518
003		2.200000 x	20.419486 =	44.922869
001		.600000 x	15.741598 =	9.444959
-----				
			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
003		1.100000 x	20.419486 =	22.461435
1417		.033000 x	39.591450 =	1.306518
1445		.005000 x	61.130300 =	.305652
-----				
			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1417		.022000 x	39.591450 =	.871012
1445		.004000 x	61.130300 =	.244521
003		.900000 x	20.419486 =	18.377537
-----				
			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1449		.030000 x	52.644500 =	1.579335
003		2.500000 x	20.419486 =	51.048715
-----				
			T.E =	
7315	7315			
155		1.050000 x	2.233400 =	2.345070
1449		.004000 x	52.644500 =	.210578
003		.300000 x	20.419486 =	6.125846
001		.100000 x	15.741598 =	1.574160
-----				
			T.E =	10.255654
7316	7316			
161		1.050000 x	6.360000 =	6.678000
1449		.025000 x	52.644500 =	1.316113
1444		.002000 x	75.237500 =	.150475
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	25.118759

7317	7317			
163		1.050000 x	6.550000 =	6.877500
1449		.025000 x	52.644500 =	1.316113
001		.300000 x	15.741598 =	4.722479
1444		.001500 x	75.237500 =	.112856
003		.800000 x	20.419486 =	16.335589
				-----
			T.E =	29.364537
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	75.237500 =	.075238
001		.100000 x	15.741598 =	1.574160
1449		.025000 x	52.644500 =	1.316113
003		1.300000 x	20.419486 =	26.545332
				-----
			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	52.644500 =	1.316113
1444		.001000 x	75.237500 =	.075238
003		1.300000 x	20.419486 =	26.545332
001		.100000 x	15.741598 =	1.574160
				-----
			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	20.419486 =	30.629229
1449		.025000 x	52.644500 =	1.316113
1444		.001000 x	75.237500 =	.075238
001		.400000 x	15.741598 =	6.296639
				-----
			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	75.237500 =	.075238
1449		.025000 x	52.644500 =	1.316113
003		1.500000 x	20.419486 =	30.629229
001		.400000 x	15.741598 =	6.296639
				-----
			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	52.644500 =	.105289
1444		.000100 x	75.237500 =	.007524
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664
			T.E =	
7326.1	7326.1			
029		.200000 x	.151500 =	.030300
173		48.000000 x	.256100 =	12.292800
003		3.000000 x	20.419486 =	61.258458
1449		.020000 x	52.644500 =	1.052890
1444		.005000 x	75.237500 =	.376188
001		.500000 x	15.741598 =	7.870799
			T.E =	82.881435
7326.2	7326.2			
029		.200000 x	.151500 =	.030300
174		48.000000 x	.000000 =	.000000
1449		.020000 x	52.644500 =	1.052890
1444		.005000 x	75.237500 =	.376188
003		3.000000 x	20.419486 =	61.258458
001		.500000 x	15.741598 =	7.870799
			T.E =	
7327	7327			
029		.200000 x	.151500 =	.030300
1449		.020000 x	52.644500 =	1.052890
1444		.007000 x	75.237500 =	.526663
003		4.000000 x	20.419486 =	81.677944
001		.600000 x	15.741598 =	9.444959
175		95.000000 x	.000000 =	.000000
			T.E =	
7328.1	7328.1			
029		.300000 x	.151500 =	.045450
171		108.000000 x	.000000 =	.000000
001		.700000 x	15.741598 =	11.019119
1449		.020000 x	52.644500 =	1.052890
1444		.007000 x	75.237500 =	.526663
003		4.000000 x	20.419486 =	81.677944
			T.E =	

7328.2

7328.2

029	.300000 x	.151500 =	.045450
1449	.020000 x	52.644500 =	1.052890
1444	.007000 x	75.237500 =	.526663
172	108.000000 x	.000000 =	.000000
003	4.000000 x	20.419486 =	81.677944
001	.700000 x	15.741598 =	11.019119

T.E =

7331

7331

029	1.500000 x	.151500 =	.227250
169	54.000000 x	.000000 =	.000000
003	3.500000 x	20.419486 =	71.468201
1449	.020000 x	52.644500 =	1.052890
1444	.005000 x	75.237500 =	.376188
001	.500000 x	15.741598 =	7.870799

T.E =

7332

7332

029	2.000000 x	.151500 =	.303000
1449	.020000 x	52.644500 =	1.052890
1444	.005000 x	75.237500 =	.376188
003	4.500000 x	20.419486 =	91.887687
001	.800000 x	15.741598 =	12.593278
170	108.000000 x	.000000 =	.000000

T.E =

7333

7333

029	.300000 x	.151500 =	.045450
167	1.050000 x	.000000 =	.000000
003	2.500000 x	20.419486 =	51.048715
002	.500000 x	17.312112 =	8.656056
1449	.020000 x	52.644500 =	1.052890

T.E =

7334

7334

029	.300000 x	.151500 =	.045450
168	1.050000 x	.000000 =	.000000
003	3.000000 x	20.419486 =	61.258458
002	.600000 x	17.312112 =	10.387267
1449	.020000 x	52.644500 =	1.052890

T.E =

7335	7335			
001		.450000 x	15.741598 =	7.083719
1444		.007000 x	75.237500 =	.526663
1445		.026000 x	61.130300 =	1.589388
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	29.619255
7336	7336			
001		.400000 x	15.741598 =	6.296639
1445		.022000 x	61.130300 =	1.344867
1444		.006000 x	75.237500 =	.451425
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	26.470468
7337	7337			
001		.350000 x	15.741598 =	5.509559
003		.800000 x	20.419486 =	16.335589
1445		.017000 x	61.130300 =	1.039215
1444		.005000 x	75.237500 =	.376188
		-----		
			T.E =	23.260551
7338	7338			
026		.500000 x	.099900 =	.049950
001		.300000 x	15.741598 =	4.722479
1445		.017000 x	61.130300 =	1.039215
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	20.105285
7340	7340			
289		1.100000 x	.904700 =	.995170
001		.400000 x	15.741598 =	6.296639
1445		.026000 x	61.130300 =	1.589388
1444		.007000 x	75.237500 =	.526663
003		1.100000 x	20.419486 =	22.461435
		-----		
			T.E =	31.869294
7341	7341			
003		.200000 x	20.419486 =	4.083897
1441		.003000 x	27.111000 =	.081333
		-----		
			T.E =	4.165230
7346	7346			
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.083897

7347	7347			
001		.200000 x	15.741598 =	3.148320
003		.500000 x	20.419486 =	10.209743
1445		.009000 x	61.130300 =	.550173
1444		.002000 x	75.237500 =	.150475
-----				
			T.E =	14.058710
7351	7351			
001		.200000 x	15.741598 =	3.148320
003		.600000 x	20.419486 =	12.251692
1444		.009000 x	75.237500 =	.677138
-----				
			T.E =	16.077149
7352	7352			
001		.200000 x	15.741598 =	3.148320
1444		.012000 x	75.237500 =	.902850
003		.700000 x	20.419486 =	14.293640
-----				
			T.E =	18.344810
7355	7355			
001		.150000 x	15.741598 =	2.361240
003		.600000 x	20.419486 =	12.251692
1444		.008000 x	75.237500 =	.601900
-----				
			T.E =	15.214831
7356	7356			
001		.100000 x	15.741598 =	1.574160
003		.550000 x	20.419486 =	11.230717
1444		.007000 x	75.237500 =	.526663
-----				
			T.E =	13.331540
7357	7357			
001		.050000 x	15.741598 =	.787080
1444		.006000 x	75.237500 =	.451425
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	11.448248
7359	7359			
021		.100000 x	2.670000 =	.267000
026		20.000000 x	.099900 =	1.998000
003		.900000 x	20.419486 =	18.377537
002		.900000 x	17.312112 =	15.580901
065		.040000 x	12.280000 =	.491200
-----				
			T.E =	36.714638



7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.099900 =	1.298700
065		.027000 x	12.280000 =	.331560
002		.700000 x	17.312112 =	12.118478
003		.700000 x	20.419486 =	14.293640
-----				
			T.E =	28.175879
7361	7361			
021		.050000 x	2.670000 =	.133500
065		.015000 x	12.280000 =	.184200
346.1		30.000000 x	.057200 =	1.716000
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
026		14.000000 x	.099900 =	1.398600
-----				
			T.E =	49.331692
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	12.280000 =	.184200
026		14.000000 x	.099900 =	1.398600
-----				
			T.E =	49.702892
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
346.2		22.000000 x	.103600 =	2.279200
065		.015000 x	12.280000 =	.184200
026		14.000000 x	.099900 =	1.398600
-----				
			T.E =	50.723692
7363	7363			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.099900 =	1.698300
065		.020000 x	12.280000 =	.245600
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
346.1		35.000000 x	.057200 =	2.002000
-----				
			T.E =	57.525112

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
346.1		24.000000 x	.057200 =	1.372800
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
065		.020000 x	12.280000 =	.245600
026		17.000000 x	.099900 =	1.698300
			T.E =	58.035512
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	12.280000 =	.245600
026		17.000000 x	.099900 =	1.698300
			T.E =	59.149112
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.099900 =	.999000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.018100 =	.520181
002		2.000000 x	17.312112 =	34.624224
346.1		45.000000 x	.057200 =	2.574000
			T.E =	100.109363
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.018100 =	.520181
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
026		10.000000 x	.099900 =	.999000
			T.E =	100.805363
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
346.2		30.000000 x	.103600 =	3.108000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.018100 =	.520181
002		2.000000 x	17.312112 =	34.624224
026		10.000000 x	.099900 =	.999000
			T.E =	102.197363

7371.1	7371.1					
026		-	14.000000 x	.099900 =	-	1.398600
7361			1.000000 x	49.331692 =		49.331692
029			14.000000 x	.151500 =		2.121000
-----						
				T.E =		50.054092
7371.2	7371.2					
026		-	14.000000 x	.099900 =	-	1.398600
028			14.000000 x	.000000 =		.000000
7361			1.000000 x	49.331692 =		49.331692
-----						
				T.E =		
7372.1	7372.1					
026		-	14.000000 x	.099900 =	-	1.398600
029			14.000000 x	.151500 =		2.121000
7362.1			1.000000 x	49.702892 =		49.702892
-----						
				T.E =		50.425292
7372.2	7372.2					
026		-	14.000000 x	.099900 =	-	1.398600
028			14.000000 x	.000000 =		.000000
7362.1			1.000000 x	49.702892 =		49.702892
-----						
				T.E =		
7372.3	7372.3					
026		-	14.000000 x	.099900 =	-	1.398600
7362.2			1.000000 x	50.723692 =		50.723692
029			14.000000 x	.151500 =		2.121000
-----						
				T.E =		51.446092
7372.4	7372.4					
026		-	14.000000 x	.099900 =	-	1.398600
7362.2			1.000000 x	50.723692 =		50.723692
028			14.000000 x	.000000 =		.000000
-----						
				T.E =		
7373.1	7373.1					
026		-	17.000000 x	.099900 =	-	1.698300
029			17.000000 x	.151500 =		2.575500
7363			1.000000 x	57.525112 =		57.525112
-----						
				T.E =		58.402312

7373.2	7373.2					
026		-	17.000000 x	.099900 =	-	1.698300
7363			1.000000 x	57.525112 =		57.525112
028			17.000000 x	.000000 =		.000000
-----						
				T.E =		
7374.1	7374.1					
026		-	17.000000 x	.099900 =	-	1.698300
7364.1			1.000000 x	58.035512 =		58.035512
029			17.000000 x	.151500 =		2.575500
-----						
				T.E =		58.912712
7374.2	7374.2					
026		-	17.000000 x	.099900 =	-	1.698300
7364.1			1.000000 x	58.035512 =		58.035512
028			17.000000 x	.000000 =		.000000
-----						
				T.E =		
7374.3	7374.3					
026		-	17.000000 x	.099900 =	-	1.698300
7364.2			1.000000 x	59.149112 =		59.149112
029			17.000000 x	.151500 =		2.575500
-----						
				T.E =		60.026312
7374.4	7374.4					
026		-	17.000000 x	.099900 =	-	1.698300
7364.2			1.000000 x	59.149112 =		59.149112
028			17.000000 x	.000000 =		.000000
-----						
				T.E =		
7376.1	7376.1					
026		-	10.000000 x	.099900 =	-	.999000
029			10.000000 x	.151500 =		1.515000
7366			1.000000 x	100.109363 =		100.109363
-----						
				T.E =		100.625363
7376.2	7376.2					
026		-	10.000000 x	.099900 =	-	.999000
7366			1.000000 x	100.109363 =		100.109363
028			10.000000 x	.000000 =		.000000
-----						
				T.E =		

7377.1	7377.1				
026		-	10.000000 x	.099900 =	-
7367.1			1.000000 x	100.805363 =	100.805363
029			10.000000 x	.151500 =	1.515000
-----					
				T.E =	101.321363
7377.2	7377.2				
026		-	10.000000 x	.099900 =	-
7367.1			1.000000 x	100.805363 =	100.805363
028			10.000000 x	.000000 =	.000000
-----					
				T.E =	
7377.3	7377.3				
026		-	10.000000 x	.099900 =	-
7367.2			1.000000 x	102.197363 =	102.197363
029			10.000000 x	.151500 =	1.515000
-----					
				T.E =	102.713363
7377.4	7377.4				
026		-	10.000000 x	.099900 =	-
028			10.000000 x	.000000 =	.000000
7367.2			1.000000 x	102.197363 =	102.197363
-----					
				T.E =	
7381	7381				
456			.100000 x	1.658300 =	.165830
-----					
				T.E =	.165830
7382	7382				
443			.150000 x	1.987900 =	.298185
447			.050000 x	4.525500 =	.226275
003			.300000 x	20.419486 =	6.125846
-----					
				T.E =	6.650306
7383	7383				
002			.250000 x	17.312112 =	4.328028
003			.150000 x	20.419486 =	3.062923
-----					
				T.E =	7.390951
7384	7384				
003			.500000 x	20.419486 =	10.209743
-----					
				T.E =	10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	12.251692
7387	7387			
261		1.500000 x	.611600 =	.917400
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.331692 =	54.264861
		-----		
			T.E =	75.601747
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.331692 =	29.599015
		-----		
			T.E =	80.647730
7389.1.1	7389.1.1			
7371.1		.300000 x	50.054092 =	15.016228
		-----		
			T.E =	15.016228
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.026312 =	18.007894
		-----		
			T.E =	18.007894
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000
		-----		
			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000
		-----		
			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.425292 =	15.127588
				-----
			T.E =	15.127588
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000
				-----
			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.446092 =	15.433828
				-----
			T.E =	15.433828
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000
				-----
			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.402312 =	17.520694
				-----
			T.E =	17.520694
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000
				-----
			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.912712 =	17.673814
				-----
			T.E =	17.673814
7389.2.1	7389.2.1			
7371.1		.500000 x	50.054092 =	25.027046
				-----
			T.E =	25.027046
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000
				-----
			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.026312 =	30.013156
				-----
			T.E =	30.013156

ΑΤΟΕ	1ο Τρίμηνο του 2012	Σελ.	160
		Ημ/νία	18/07/2012
7389.2.12	7389.2.12		
7374.4		.500000 x	.000000 =
		-----	
			T.E =
7389.2.2	7389.2.2		
7371.2		.500000 x	.000000 =
		-----	
			T.E =
7389.2.3	7389.2.3		
7372.1		.500000 x	50.425292 =
		-----	
			25.212646
			T.E =
7389.2.4	7389.2.4		
7372.2		.500000 x	.000000 =
		-----	
			T.E =
7389.2.5	7389.2.5		
7372.3		.500000 x	51.446092 =
		-----	
			25.723046
			T.E =
7389.2.6	7389.2.6		
7372.4		.500000 x	.000000 =
		-----	
			T.E =
7389.2.7	7389.2.7		
7373.1		.500000 x	58.402312 =
		-----	
			29.201156
			T.E =
7389.2.8	7389.2.8		
7373.2		.500000 x	.000000 =
		-----	
			T.E =
7389.2.9	7389.2.9		
7374.1		.500000 x	58.912712 =
		-----	
			29.456356
			T.E =
7391	7391		
003		.250000 x	20.419486 =
		-----	
			5.104872
			T.E =
			5.104872



7392	7392				
298.1		1.081080 x	7.120000 =	7.697290	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	15.865084	
7393	7393				
294		.347760 x	3.518600 =	1.223628	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =	7.349474	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	
		-----			
			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	
		-----			
			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	
		-----			
			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	
		-----			
			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	6.644872	

7416	7416			
003		.800000 x	20.419486 =	16.335589
			T.E =	16.335589
7417	7417			
003		1.800000 x	20.419486 =	36.755075
			T.E =	36.755075
7418	7418			
003		2.600000 x	20.419486 =	53.090664
			T.E =	53.090664
7419	7419			
003		.800000 x	20.419486 =	16.335589
			T.E =	16.335589
7420	7420			
003		1.200000 x	20.419486 =	24.503383
			T.E =	24.503383
7421	7421			
003		.800000 x	20.419486 =	16.335589
			T.E =	16.335589
7422	7422			
003		.350000 x	20.419486 =	7.146820
			T.E =	7.146820
7431	7431			
332		1.150000 x	79.680000 =	91.632000
1445		.020000 x	61.130300 =	1.222606
003		4.000000 x	20.419486 =	81.677944
1444		.001000 x	75.237500 =	.075238
			T.E =	174.607788
7432	7432			
331		1.150000 x	76.850000 =	88.377500
1445		.020000 x	61.130300 =	1.222606
1444		.001000 x	75.237500 =	.075238
003		4.400000 x	20.419486 =	89.845738
			T.E =	179.521082

7433	7433				
331		1.150000 x	76.850000 =	88.377500	
003		5.100000 x	20.419486 =	104.139379	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
		-----			
			T.E =	193.814722	
7434	7434				
331		1.150000 x	76.850000 =	88.377500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
		-----			
			T.E =	214.234208	
7441	7441				
331		1.250000 x	76.850000 =	96.062500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =	183.122185	
7442	7442				
331		1.250000 x	76.850000 =	96.062500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		4.600000 x	20.419486 =	93.929636	
		-----			
			T.E =	191.289979	
7443	7443				
331		1.250000 x	76.850000 =	96.062500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
		-----			
			T.E =	205.583619	
7444	7444				
331		1.250000 x	76.850000 =	96.062500	
003		6.300000 x	20.419486 =	128.642762	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
		-----			
			T.E =	226.003105	

7451	7451				
333		1.150000 x	111.570000 =	128.305500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		4.500000 x	20.419486 =	91.887687	
		-----			
			T.E =	221.491031	
7452	7452				
333		1.150000 x	111.570000 =	128.305500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		4.900000 x	20.419486 =	100.055481	
		-----			
			T.E =	229.658825	
7453	7453				
333		1.150000 x	111.570000 =	128.305500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		5.600000 x	20.419486 =	114.349122	
		-----			
			T.E =	243.952465	
7454	7454				
333		1.150000 x	111.570000 =	128.305500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		6.600000 x	20.419486 =	134.768608	
		-----			
			T.E =	264.371951	
7461	7461				
333		1.250000 x	111.570000 =	139.462500	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
003		4.900000 x	20.419486 =	100.055481	
		-----			
			T.E =	240.815825	
7462	7462				
333		1.250000 x	111.570000 =	139.462500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.130300 =	1.222606	
1444		.001000 x	75.237500 =	.075238	
		-----			
			T.E =	248.983619	

7463	7463				
333		1.250000 x	111.570000 =	139.462500	
1444		.001000 x	75.237500 =	.075238	
003		6.000000 x	20.419486 =	122.516916	
1445		.020000 x	61.130300 =	1.222606	
		-----			
			T.E =	263.277260	
7464	7464				
333		1.250000 x	111.570000 =	139.462500	
003		7.000000 x	20.419486 =	142.936402	
1444		.001000 x	75.237500 =	.075238	
1445		.020000 x	61.130300 =	1.222606	
		-----			
			T.E =	283.696746	
7491	7491				
331		.115000 x	76.850000 =	8.837750	
1444		.000100 x	75.237500 =	.007524	
1445		.002000 x	61.130300 =	.122261	
003		.915000 x	20.419486 =	18.683830	
		-----			
			T.E =	27.651364	
7492	7492				
331		.125000 x	76.850000 =	9.606250	
1445		.002000 x	61.130300 =	.122261	
1444		.000100 x	75.237500 =	.007524	
003		.945000 x	20.419486 =	19.296414	
		-----			
			T.E =	29.032449	
7493	7493				
333		.115000 x	111.570000 =	12.830550	
003		.990000 x	20.419486 =	20.215291	
1445		.002000 x	61.130300 =	.122261	
1444		.000100 x	75.237500 =	.007524	
		-----			
			T.E =	33.175625	
7494	7494				
333		.125000 x	111.570000 =	13.946250	
1445		.002000 x	61.130300 =	.122261	
1444		.000100 x	75.237500 =	.007524	
003		1.050000 x	20.419486 =	21.440460	
		-----			
			T.E =	35.516495	

7496	7496			
331		.057500 x	76.850000 =	4.418875
1445		.001000 x	61.130300 =	.061130
1444		.000050 x	75.237500 =	.003762
003		.488000 x	20.419486 =	9.964709
-----				
			T.E =	14.448476
7497	7497			
331		.062500 x	76.850000 =	4.803125
003		.504000 x	20.419486 =	10.291421
1444		.000050 x	75.237500 =	.003762
1445		.001000 x	61.130300 =	.061130
-----				
			T.E =	15.159438
7498	7498			
333		.057500 x	111.570000 =	6.415275
003		.528000 x	20.419486 =	10.781489
1445		.001000 x	61.130300 =	.061130
1444		.000050 x	75.237500 =	.003762
-----				
			T.E =	17.261656
7499	7499			
333		.062500 x	111.570000 =	6.973125
003		.560000 x	20.419486 =	11.434912
1445		.001000 x	61.130300 =	.061130
1444		.000050 x	75.237500 =	.003762
-----				
			T.E =	18.472929
7501	7501			
7433		1.000000 x	193.814722 =	193.814722
-----				
			T.E =	193.814722
7503	7503			
7443		1.000000 x	205.583619 =	205.583619
-----				
			T.E =	205.583619
7506	7506			
7453		1.000000 x	243.952465 =	243.952465
-----				
			T.E =	243.952465
7508	7508			
7463		1.000000 x	263.277260 =	263.277260
-----				
			T.E =	263.277260

7511	7511			
331		.115000 x	76.850000 =	8.837750
1445		.002000 x	61.130300 =	.122261
1444		.000100 x	75.237500 =	.007524
003		.915000 x	20.419486 =	18.683830
			-----	
			T.E =	27.651364
7513	7513			
331		.125000 x	76.850000 =	9.606250
003		.945000 x	20.419486 =	19.296414
1445		.002000 x	61.130300 =	.122261
1444		.000100 x	75.237500 =	.007524
			-----	
			T.E =	29.032449
7521	7521			
331		1.150000 x	76.850000 =	88.377500
003		5.700000 x	20.419486 =	116.391070
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	205.991176
7523	7523			
331		1.150000 x	76.850000 =	88.377500
003		4.800000 x	20.419486 =	98.013533
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	187.613639
7524	7524			
331		1.250000 x	76.850000 =	96.062500
1445		.020000 x	61.130300 =	1.222606
003		6.100000 x	20.419486 =	124.558865
			-----	
			T.E =	221.843971
7526	7526			
331		1.250000 x	76.850000 =	96.062500
1445		.020000 x	61.130300 =	1.222606
003		5.000000 x	20.419486 =	102.097430
			-----	
			T.E =	199.382536
7531	7531			
332		1.150000 x	79.680000 =	91.632000
003		5.200000 x	20.419486 =	106.181327
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	199.035933

7532	7532				
332		1.250000 x	79.680000 =	99.600000	
1445		.020000 x	61.130300 =	1.222606	
003		5.400000 x	20.419486 =	110.265224	
-----					
			T.E =	211.087830	
7533	7533				
334		1.150000 x	119.540000 =	137.471000	
1445		.020000 x	61.130300 =	1.222606	
003		5.700000 x	20.419486 =	116.391070	
-----					
			T.E =	255.084676	
7534	7534				
334		1.250000 x	119.540000 =	149.425000	
1445		.020000 x	61.130300 =	1.222606	
003		6.100000 x	20.419486 =	124.558865	
-----					
			T.E =	275.206471	
7536	7536				
334		.300000 x	119.540000 =	35.862000	
1445		.010000 x	61.130300 =	.611303	
003		3.000000 x	20.419486 =	61.258458	
-----					
			T.E =	97.731761	
7537	7537				
336		.300000 x	.000000 =	.000000	
1445		.010000 x	61.130300 =	.611303	
003		4.000000 x	20.419486 =	81.677944	
-----					
			T.E =		
7541	7541				
332		.170000 x	79.680000 =	13.545600	
334		.350000 x	119.540000 =	41.839000	
1445		.010000 x	61.130300 =	.611303	
003		3.700000 x	20.419486 =	75.552098	
-----					
			T.E =	131.548001	
7542	7542				
332		.170000 x	79.680000 =	13.545600	
336		.350000 x	.000000 =	.000000	
003		4.200000 x	20.419486 =	85.761841	
1445		.010000 x	61.130300 =	.611303	
-----					
			T.E =		



7543	7543			
332		.170000 x	79.680000 =	13.545600
338		.350000 x	.000000 =	.000000
1445		.010000 x	61.130300 =	.611303
003		4.800000 x	20.419486 =	98.013533
			-----	
			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.130300 =	1.222606
003		7.000000 x	20.419486 =	142.936402
			-----	
			T.E =	
7552	7552			
322		1.150000 x	99.620000 =	114.563000
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	258.722008
7553	7553			
323		1.150000 x	113.850000 =	130.927500
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	275.086508
7554	7554			
321		1.150000 x	.000000 =	.000000
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	
7555	7555			
322		1.150000 x	99.620000 =	114.563000
1445		.020000 x	61.130300 =	1.222606
003		9.000000 x	20.419486 =	183.775374
			-----	
			T.E =	299.560980
7556	7556			
323		1.150000 x	113.850000 =	130.927500
003		9.000000 x	20.419486 =	183.775374
1445		.020000 x	61.130300 =	1.222606
			-----	
			T.E =	315.925480



7567	7567				
7562		1.500000 x	255.084676 =	382.627014	
			T.E =	382.627014	
7568	7568				
7563		1.500000 x	211.087830 =	316.631745	
			T.E =	316.631745	
7569	7569				
7564		1.500000 x	275.206471 =	412.809707	
			T.E =	412.809707	
7571.1	7571.1				
327.1		1.000000 x	.000000 =	.000000	
003		3.000000 x	20.419486 =	61.258458	
327.1		.030000 x	.000000 =	.000000	
			T.E =		
7571.2	7571.2				
327.2		1.000000 x	.000000 =	.000000	
003		3.000000 x	20.419486 =	61.258458	
327.2		.030000 x	.000000 =	.000000	
			T.E =		
7571.3	7571.3				
327.3		1.000000 x	176.980000 =	176.980000	
003		3.000000 x	20.419486 =	61.258458	
327.3		.030000 x	176.980000 =	5.309400	
			T.E =	243.547858	
7572	7572				
328		1.000000 x	.000000 =	.000000	
003		4.000000 x	20.419486 =	81.677944	
328		.030000 x	.000000 =	.000000	
			T.E =		
7576	7576				
331		1.150000 x	76.850000 =	88.377500	
003		3.800000 x	20.419486 =	77.594047	
			T.E =	165.971547	

7577	7577				
334		1.150000 x	119.540000 =	137.471000	
003		4.200000 x	20.419486 =	85.761841	
		-----			
			T.E =	223.232841	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	20.419486 =	95.971584	
		-----			
			T.E =		
7581	7581				
326		1.050000 x	57.180000 =	60.039000	
3211		.020000 x	133.255121 =	2.665102	
1445		.005000 x	61.130300 =	.305652	
003		2.300000 x	20.419486 =	46.964818	
		-----			
			T.E =	109.974572	
7601	7601				
401		1.100000 x	12.200000 =	13.420000	
457		.500000 x	.827900 =	.413950	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	24.043693	
7602	7602				
403		1.100000 x	14.290000 =	15.719000	
457		.500000 x	.827900 =	.413950	
003		.550000 x	20.419486 =	11.230717	
		-----			
			T.E =	27.363667	
7603	7603				
406		1.100000 x	17.660000 =	19.426000	
457		.500000 x	.827900 =	.413950	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	33.112616	
7604.1	7604.1				
409		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	
457		.500000 x	.827900 =	.413950	
		-----			
			T.E =	38.861565	

7604.2	7604.2				
410		1.100000 x	28.610000 =	31.471000	
003		.750000 x	20.419486 =	15.314615	
457		.500000 x	.827900 =	.413950	
		-----			
			T.E =	47.199565	
7606	7606				
401		1.100000 x	12.200000 =	13.420000	
003		.600000 x	20.419486 =	12.251692	
		-----			
			T.E =	25.671692	
7607	7607				
403		1.100000 x	14.290000 =	15.719000	
003		.650000 x	20.419486 =	13.272666	
		-----			
			T.E =	28.991666	
7608	7608				
406		1.100000 x	17.660000 =	19.426000	
003		.750000 x	20.419486 =	15.314615	
		-----			
			T.E =	34.740615	
7609.1	7609.1				
409		1.100000 x	21.030000 =	23.133000	
003		.850000 x	20.419486 =	17.356563	
		-----			
			T.E =	40.489563	
7609.2	7609.2				
410		1.100000 x	28.610000 =	31.471000	
003		.850000 x	20.419486 =	17.356563	
		-----			
			T.E =	48.827563	
7611	7611				
411		1.100000 x	26.710000 =	29.381000	
457		.500000 x	.827900 =	.413950	
003		.500000 x	20.419486 =	10.209743	
		-----			
			T.E =	40.004693	
7612	7612				
412		1.100000 x	28.830000 =	31.713000	
003		.550000 x	20.419486 =	11.230717	
457		.500000 x	.827900 =	.413950	
		-----			
			T.E =	43.357667	



7626.1	7626.1			
298.2		18.000000 x	5.760000 =	103.680000
421		1.000000 x	97.840000 =	97.840000
002		7.000000 x	17.312112 =	121.184784
003		7.000000 x	20.419486 =	142.936402
		-----		
			T.E =	465.641186
7626.2	7626.2			
298.2		18.000000 x	5.760000 =	103.680000
422		1.000000 x	134.470000 =	134.470000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
		-----		
			T.E =	502.271186
7627.1	7627.1			
298.2		16.000000 x	5.760000 =	92.160000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
421		1.000000 x	97.840000 =	97.840000
		-----		
			T.E =	416.389588
7627.2	7627.2			
298.2		16.000000 x	5.760000 =	92.160000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
422		1.000000 x	134.470000 =	134.470000
		-----		
			T.E =	453.019588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974
		-----		
			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169
		-----		
			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	7.562559

7638	7638				
430		1.100000 x	7.480000 =	8.228000	
003		.100000 x	20.419486 =	2.041949	
			T.E =	10.269949	
7641	7641				
431		1.000000 x	.000000 =	.000000	
003		.060000 x	20.419486 =	1.225169	
			T.E =		
7642	7642				
432		1.000000 x	.000000 =	.000000	
003		.060000 x	20.419486 =	1.225169	
			T.E =		
7701	7701				
024		.001500 x	45.000000 =	.067500	
002		.050000 x	17.312112 =	.865606	
003		.120000 x	20.419486 =	2.450338	
			T.E =	3.383444	
7702	7702				
024		.001800 x	45.000000 =	.081000	
003		.080000 x	20.419486 =	1.633559	
002		.050000 x	17.312112 =	.865606	
			T.E =	2.580164	
7706	7706				
024		.002000 x	45.000000 =	.090000	
003		.150000 x	20.419486 =	3.062923	
002		.080000 x	17.312112 =	1.384969	
			T.E =	4.537892	
7707	7707				
024		.002300 x	45.000000 =	.103500	
003		.090000 x	20.419486 =	1.837754	
002		.100000 x	17.312112 =	1.731211	
			T.E =	3.672465	



7708	7708				
024		.002500 x	45.000000 =	.112500	
003		.180000 x	20.419486 =	3.675507	
002		.120000 x	17.312112 =	2.077453	
				-----	
				T.E =	5.865461
7709	7709				
024		.002800 x	45.000000 =	.126000	
003		.120000 x	20.419486 =	2.450338	
002		.150000 x	17.312112 =	2.596817	
				-----	
				T.E =	5.173155
7711	7711				
002		.050000 x	17.312112 =	.865606	
1485		.200000 x	.855511 =	.171102	
003		.200000 x	20.419486 =	4.083897	
				-----	
				T.E =	5.120605
7712	7712				
002		.080000 x	17.312112 =	1.384969	
1485		.250000 x	.855511 =	.213878	
003		.250000 x	20.419486 =	5.104872	
				-----	
				T.E =	6.703718
7713	7713				
002		.160000 x	17.312112 =	2.769938	
003		.300000 x	20.419486 =	6.125846	
1485		.280000 x	.855511 =	.239543	
				-----	
				T.E =	9.135327
7720	7720				
443		.080000 x	1.987900 =	.159032	
003		.300000 x	20.419486 =	6.125846	
002		.100000 x	17.312112 =	1.731211	
1485		.200000 x	.855511 =	.171102	
				-----	
				T.E =	8.187191
7721	7721				
002		.070000 x	17.312112 =	1.211848	
003		.200000 x	20.419486 =	4.083897	
1485		.200000 x	.855511 =	.171102	
				-----	
				T.E =	5.466847

7722.1.1	7722.1.1			
7720		.300000 x	8.187191 =	2.456157
				-----
			T.E =	2.456157
7722.1.2	7722.1.2			
7721		.300000 x	5.466847 =	1.640054
				-----
			T.E =	1.640054
7722.2.1	7722.2.1			
7720		.400000 x	8.187191 =	3.274876
				-----
			T.E =	3.274876
7722.2.2	7722.2.2			
7721		.400000 x	5.466847 =	2.186739
				-----
			T.E =	2.186739
7725	7725			
471		.300000 x	3.960000 =	1.188000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
				-----
			T.E =	8.889688
7735	7735			
441		.350000 x	.077700 =	.027195
444		.150000 x	2.207500 =	.331125
003		.150000 x	20.419486 =	3.062923
				-----
			T.E =	3.421243
7736	7736			
441		.500000 x	.077700 =	.038850
444		.085000 x	2.207500 =	.187638
445		.010000 x	1.600000 =	.016000
003		.250000 x	20.419486 =	5.104872
446		.005000 x	2.662500 =	.013313
				-----
			T.E =	5.360672
7737	7737			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
003		.300000 x	20.419486 =	6.125846
1488		.600000 x	.784064 =	.470438
				-----
			T.E =	6.790928

7738	7738			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
1488		.300000 x	.784064 =	.235219
003		.300000 x	20.419486 =	6.125846
			T.E =	6.555709
7739	7739			
441		.100000 x	.077700 =	.007770
467		.100000 x	3.397500 =	.339750
003		.150000 x	20.419486 =	3.062923
			T.E =	3.410443
7740	7740			
442		.250000 x	.121800 =	.030450
003		.250000 x	20.419486 =	5.104872
1492		.250000 x	2.841075 =	.710269
			T.E =	5.845590
7741	7741			
442		.250000 x	.121800 =	.030450
462		.250000 x	.000000 =	.000000
003		.250000 x	20.419486 =	5.104872
			T.E =	5.845590
7742	7742			
442		.250000 x	.121800 =	.030450
003		.200000 x	20.419486 =	4.083897
463		.125000 x	4.089100 =	.511138
			T.E =	4.625485
7743	7743			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.630000 =	.453750
			T.E =	3.547123
7744	7744			
442		.250000 x	.121800 =	.030450
003		.150000 x	20.419486 =	3.062923
465		.125000 x	6.180000 =	.772500
			T.E =	3.865873

7745	7745			
442		.250000 x	.121800 =	.030450
1492		.250000 x	2.841075 =	.710269
003		.800000 x	20.419486 =	16.335589
1489		.200000 x	.895520 =	.179104
		-----		
			T.E =	17.255412
7746	7746			
441		.350000 x	.077700 =	.027195
003		.150000 x	20.419486 =	3.062923
443		.090000 x	1.987900 =	.178911
		-----		
			T.E =	3.269029
7747	7747			
441		.350000 x	.077700 =	.027195
443		.170000 x	1.987900 =	.337943
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.470010
7748	7748			
443		.090000 x	1.987900 =	.178911
002		.100000 x	17.312112 =	1.731211
445		.030000 x	1.600000 =	.048000
003		.200000 x	20.419486 =	4.083897
450		.060000 x	2.842800 =	.170568
		-----		
			T.E =	6.212587
7749	7749			
443		.160000 x	1.987900 =	.318064
445		.050000 x	1.600000 =	.080000
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.842800 =	.284280
		-----		
			T.E =	8.384032
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.534505 =	.191813
		-----		
			T.E =	3.254736
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.534505 =	.383626
		-----		
			T.E =	5.488498

7753	7753			
441		1.000000 x	.077700 =	.077700
003		.650000 x	20.419486 =	13.272666
443		.080000 x	1.987900 =	.159032
1491		.200000 x	1.534505 =	.306901
1490		.090000 x	1.594219 =	.143480
			T.E =	13.959779
7754	7754			
441		.800000 x	.077700 =	.062160
1487		.090000 x	.621987 =	.055979
003		.800000 x	20.419486 =	16.335589
1490		.090000 x	1.594219 =	.143480
1491		.200000 x	1.534505 =	.306901
			T.E =	16.904108
7755	7755			
442		.250000 x	.121800 =	.030450
003		1.000000 x	20.419486 =	20.419486
1491		.200000 x	1.534505 =	.306901
1492		.160000 x	2.841075 =	.454572
			T.E =	21.211409
7756	7756			
442		.300000 x	.121800 =	.036540
003		.350000 x	20.419486 =	7.146820
1492		.300000 x	2.841075 =	.852323
			T.E =	8.035683
7761	7761			
441		.650000 x	.077700 =	.050505
1489		.200000 x	.895520 =	.179104
1488		.600000 x	.784064 =	.470438
003		.800000 x	20.419486 =	16.335589
467		.100000 x	3.397500 =	.339750
473		.100000 x	2.832500 =	.283250
			T.E =	17.658636
7762	7762			
473		.100000 x	2.832500 =	.283250
003		.200000 x	20.419486 =	4.083897
			T.E =	4.367147

7764	7764				
474		.125000 x	3.883100 =	.485388	
003		.100000 x	20.419486 =	2.041949	
			T.E =		2.527336
7765	7765				
475		.125000 x	6.416900 =	.802113	
003		.200000 x	20.419486 =	4.083897	
			T.E =		4.886010
7766	7766				
442		.275000 x	.121800 =	.033495	
473		.110000 x	2.832500 =	.311575	
1492		.275000 x	2.841075 =	.781296	
003		.880000 x	20.419486 =	17.969148	
			T.E =		19.095513
7767.1	7767.1				
7755		.150000 x	21.211409 =	3.181711	
			T.E =		3.181711
7767.2	7767.2				
442		.250000 x	.121800 =	.030450	
1492		.160000 x	2.841075 =	.454572	
003		1.000000 x	20.419486 =	20.419486	
473		.200000 x	2.832500 =	.566500	
			AΘΡΟΙΣΜΑ =		21.471008
	T.E =	.150000 x	21.471008 =		3.220651
7767.3	7767.3				
7755		.250000 x	21.211409 =	5.302852	
			T.E =		5.302852
7767.4	7767.4				
442		.250000 x	.121800 =	.030450	
473		.200000 x	2.832500 =	.566500	
003		1.000000 x	20.419486 =	20.419486	
1492		.160000 x	2.841075 =	.454572	
			AΘΡΟΙΣΜΑ =		21.471008
	T.E =	.250000 x	21.471008 =		5.367752

7767.5	7767.5			
7755		.350000 x	21.211409 =	7.423993
				-----
			T.E =	7.423993
7767.6	7767.6			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
				-----
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.350000 x	21.471008 =	7.514853
				-----
7767.7	7767.7			
7755		.450000 x	21.211409 =	9.545134
				-----
			T.E =	9.545134
7767.8	7767.8			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.419486 =	20.419486
				-----
			AΘΡΟΙΣΜΑ =	21.471008
	T.E =	.450000 x	21.471008 =	9.661954
				-----
7768	7768			
460		.200000 x	4.377500 =	.875500
003		.450000 x	20.419486 =	9.188769
460		.030000 x	4.377500 =	.131325
002		.450000 x	17.312112 =	7.790450
				-----
			T.E =	17.986044
7769	7769			
460		.200000 x	4.377500 =	.875500
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
460		.030000 x	4.377500 =	.131325
				-----
			T.E =	8.553145
7770	7770			
460		.090000 x	4.377500 =	.393975
003		.150000 x	20.419486 =	3.062923
002		.150000 x	17.312112 =	2.596817
460		.020000 x	4.377500 =	.087550
				-----
			T.E =	6.141265

7771	7771				
441		1.000000 x	.077700 =	.077700	
1488		.160000 x	.784064 =	.125450	
1487		.080000 x	.621987 =	.049759	
003		1.300000 x	20.419486 =	26.545332	
473		.100000 x	2.832500 =	.283250	
467		.110000 x	3.397500 =	.373725	
			T.E =	27.455216	
7772	7772				
441		1.000000 x	.077700 =	.077700	
458		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
003		.500000 x	20.419486 =	10.209743	
			T.E =	11.014233	
7773	7773				
441		1.000000 x	.077700 =	.077700	
459		.100000 x	5.280000 =	.528000	
443		.100000 x	1.987900 =	.198790	
003		.600000 x	20.419486 =	12.251692	
			T.E =	13.056182	
7774	7774				
442		.250000 x	.121800 =	.030450	
473		.200000 x	2.832500 =	.566500	
1492		.160000 x	2.841075 =	.454572	
003		1.000000 x	20.419486 =	20.419486	
			T.E =	21.471008	
7785.1	7785.1				
441		.350000 x	.077700 =	.027195	
003		.700000 x	20.419486 =	14.293640	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.437300 =	.292476	
			T.E =		
7785.2	7785.2				
441		.350000 x	.077700 =	.027195	
476		.120000 x	2.437300 =	.292476	
478		.160000 x	3.060000 =	.489600	
003		.700000 x	20.419486 =	14.293640	
			T.E =	15.102911	



7786.1	7786.1			
441		.350000 x	.077700 =	.027195
1489		.200000 x	.895520 =	.179104
003		1.000000 x	20.419486 =	20.419486
1488		.600000 x	.784064 =	.470438
477		.110000 x	.000000 =	.000000
		-----		
			T.E =	
7786.2	7786.2			
441		.350000 x	.077700 =	.027195
1489		.200000 x	.895520 =	.179104
1488		.600000 x	.784064 =	.470438
003		1.000000 x	20.419486 =	20.419486
478		.110000 x	3.060000 =	.336600
		-----		
			T.E =	21.432823
7787	7787			
441		1.000000 x	.077700 =	.077700
476		.090000 x	2.437300 =	.219357
1488		.160000 x	.784064 =	.125450
1487		.080000 x	.621987 =	.049759
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000
		-----		
			T.E =	
7788	7788			
441		.250000 x	.077700 =	.019425
479		1.000000 x	1.876600 =	1.876600
003		.700000 x	20.419486 =	14.293640
		-----		
			T.E =	16.189665
7791	7791			
441		1.000000 x	.077700 =	.077700
1487		.050000 x	.621987 =	.031099
1491		.200000 x	1.534505 =	.306901
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.625443
7792	7792			
482		.150000 x	1.434100 =	.215115
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	10.424858

7793	7793			
480		.500000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
-----				
			T.E =	
7794	7794			
482		.150000 x	1.434100 =	.215115
003		.500000 x	20.419486 =	10.209743
-----				
			T.E =	10.424858
7797	7797			
201		.000500 x	290.000000 =	.145000
002		.060000 x	17.312112 =	1.038727
-----				
			T.E =	1.183727
7798	7798			
201		.000600 x	290.000000 =	.174000
002		.070000 x	17.312112 =	1.211848
-----				
			T.E =	1.385848
7801	7801			
496		1.200000 x	.887400 =	1.064880
003		.150000 x	20.419486 =	3.062923
-----				
			T.E =	4.127803
7806	7806			
498		1.150000 x	.991400 =	1.140110
003		.300000 x	20.419486 =	6.125846
-----				
			T.E =	7.265956
7807	7807			
499		1.150000 x	1.359000 =	1.562850
003		.400000 x	20.419486 =	8.167794
-----				
			T.E =	9.730644
7808	7808			
500		1.150000 x	1.998800 =	2.298620
003		.600000 x	20.419486 =	12.251692
-----				
			T.E =	14.550312

7809	7809			
501		1.200000 x	2.700000 =	3.240000
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	19.575589
7810	7810			
502		1.200000 x	3.780000 =	4.536000
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	22.913537
7811	7811			
503		1.200000 x	.887400 =	1.064880
003		.800000 x	20.419486 =	16.335589
		-----		
			T.E =	17.400469
7812	7812			
504		1.300000 x	1.175100 =	1.527630
003		.900000 x	20.419486 =	18.377537
		-----		
			T.E =	19.905167
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	31.421692
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	4.872297
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	20.419486 =	20.419486
		-----		
			T.E =	25.795486
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	20.419486 =	12.251692
		-----		
			T.E =	19.507192

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.431700 =	1.574870
002		.300000 x	17.312112 =	5.193634
003		.150000 x	20.419486 =	3.062923
		-----		
			T.E =	10.707427
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239
		-----		
			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845
		-----		
			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559
		-----		
			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.707427 =	9.101313
		-----		
			T.E =	9.101313
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238
		-----		
			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303
		-----		
			T.E =	10.038303



7934	7934			
535		1.150000 x	6.600000 =	7.590000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743
		-----		
			T.E =	26.455799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872
		-----		
			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949
		-----		
			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.895000 =	.089500
		-----		
			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160
		-----		
			T.E =	9.124160