

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

2ο Τρίμηνο του 2009

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.67	22.739959
115	Κατχ Τιμή X 1.8117/ 6.67	18.893831
116	Κατχ Τιμή X 1.8117/ 6.46	22.893045
117	Κατχ Τιμή X 1.8117/ 6.67	18.893831
118	Κατχ Τιμή X 1.8117/ 6.67	17.283129
150		.074800
211		.779800
212		.829400
213		1.800000
214		3.800000
221		.097700
221.1		.087500
222		.114100
222.1		.102800
223		.117200
223.1		1.102900
224		.070000
231		.650000
232		1.750000
233		.492800
233.1		.492800
233.2		.523400
233.3		7.500000
234		.641500
234.1		.736500
234.2		.666500
234.3		.699000
235		.553000
236		.513000
237		1.060000
237.1		1.200000
241		6.240000
242		5.000000
243		1.900000
244		2.470000
251		290.000000
252		210.000000
252.1		
252.2		
261		14.500000
261.1		13.000000
261.2		19.900000
261.3		
261.4		
262		25.300000
262.1		
263		31.200000
263.1		
263.2		44.900000
263.3		
264		61.600000
264.1		
265		110.700000
265.1		
271		198.400000
271.1		



281	20.500000
281.1	16.900000
281.2	25.390000
282	28.900000
283	34.900000
283.1	53.400000
284	72.500000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.120000
361.1	11.750000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.300000
361.3	19.280000
361.4	
361.5	36.800000
361.6	49.220000
361.7	76.000000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	



363.25  
363.26  
363.27  
363.28  
363.3  
363.4  
363.5  
363.6  
363.7  
363.8  
363.9  
364.1  
364.10  
364.11  
364.12  
364.13  
364.14  
364.2  
364.3  
364.4  
364.5  
364.6  
364.7  
364.8  
364.9  
365.1  
365.10  
365.11  
365.12  
365.13  
365.14  
365.15  
365.16  
365.17  
365.18  
365.19  
365.2  
365.20  
365.21  
365.22  
365.23  
365.24  
365.25  
365.26  
365.27  
365.28  
365.3  
365.4  
365.5  
365.6  
365.7  
365.8  
365.9  
366.1  
366.10  
366.11  
366.12  
366.13  
366.14



366.15  
366.16  
366.17  
366.18  
366.19  
366.2  
366.20  
366.21  
366.22  
366.23  
366.24  
366.25  
366.26  
366.27  
366.28  
366.3  
366.4  
366.5  
366.6  
366.7  
366.8  
366.9  
367.1  
367.10  
367.11  
367.12  
367.13  
367.14  
367.15  
367.16  
367.17  
367.18  
367.19  
367.2  
367.20  
367.21  
367.22  
367.23  
367.24  
367.25  
367.26  
367.27  
367.28  
367.29  
367.3  
367.30  
367.31  
367.32  
367.33  
367.34  
367.35  
367.36  
367.37  
367.38  
367.39  
367.4  
367.40  
367.41  
367.42





367.43  
367.44  
367.45  
367.46  
367.47  
367.48  
367.49  
367.5  
367.50  
367.51  
367.52  
367.53  
367.54  
367.55  
367.56  
367.6  
367.7  
367.8  
367.9  
368.1  
368.10  
368.11  
368.12  
368.13  
368.14  
368.15  
368.16  
368.17  
368.18  
368.19  
368.2  
368.20  
368.21  
368.22  
368.23  
368.24  
368.25  
368.26  
368.27  
368.28  
368.29  
368.3  
368.30  
368.4  
368.5  
368.6  
368.7  
368.8  
368.9  
369.1  
369.10  
369.11  
369.12  
369.13  
369.14  
369.15  
369.16  
369.17  
369.18



369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000



372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	



377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	





386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	90,675.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	61,603.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	107,490.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	123,215.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	



386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	20,575.000000
387.1	
387.2	
387.3	17,260.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	5,345.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	4,516.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	6,566.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	



390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	12,320.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	48.900000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	6.780000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	8.330000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	88.000000
398.2	42.300000
398.3	49.800000
398.4	71.200000
398.5	5.590000



398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	254.090000
402	367.070000
403	99.790000
404	201.370000
405	199.590000
406	309.910000
407	52.260000
408	4.290000
409	119.340000
410	110.310000
411	25.900000
412	2.830000
413	4.290000
414	5.910000
415	8.320000
416	12.820000
417	127.340000
419	4.290000
420	92.090000
421	30.830000
428	422.740000
429	73.440000
450	79.370000
451	4.610000
452	99.500000
453	
454	92.090000
455	29.610000
456	33.160000
457	433.250000
458	269.790000
459	407.490000
460	503.880000
461	226.250000
462	329.900000
463	41.450000
464	363.070000
465	97.130000
466	45.310000
467	329.900000
468	82.620000
469	82.620000
470	66.630000
471	57.740000
472	25.100000
473	16.140000
474	33.160000
475	1,865.120000
476	80.840000
477	6.580000
478	108.970000
479	175.310000
480	25.760000
481	769.090000





501	501			
401		1.000000 x	254.090000 =	254.090000
211		50.000000 x	.779800 =	38.990000
118		3.000000 x	17.283129 =	51.849387
114		8.000000 x	22.739959 =	181.919672
214		3.000000 x	3.800000 =	11.400000
			-----	
			ΑΘΡΟΙΣΜΑ =	538.249059
			-----	
			Η.Δ. =	592.073965
502	502			
402		1.000000 x	367.070000 =	367.070000
214		7.000000 x	3.800000 =	26.600000
211		80.000000 x	.779800 =	62.384000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
			-----	
			ΑΘΡΟΙΣΜΑ =	707.106188
			-----	
			Η.Δ. =	777.816807
503	503			
428		1.000000 x	422.740000 =	422.740000
214		10.000000 x	3.800000 =	38.000000
114		8.000000 x	22.739959 =	181.919672
211		110.000000 x	.779800 =	85.778000
118		4.000000 x	17.283129 =	69.132516
			-----	
			ΑΘΡΟΙΣΜΑ =	797.570188
			-----	
			Η.Δ. =	877.327207
504	504			
403		1.000000 x	99.790000 =	99.790000
214		2.000000 x	3.800000 =	7.600000
114		8.000000 x	22.739959 =	181.919672
211		40.000000 x	.779800 =	31.192000
			-----	
			ΑΘΡΟΙΣΜΑ =	320.501672
			-----	
			Η.Δ. =	352.551839
505	505			
404		1.000000 x	201.370000 =	201.370000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
214		10.000000 x	3.800000 =	38.000000
211		200.000000 x	.779800 =	155.960000
			-----	
			ΑΘΡΟΙΣΜΑ =	715.514704
			-----	
			Η.Δ. =	787.066174

506	506			
405		1.000000 x	199.590000 =	199.590000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
242		2.500000 x	5.000000 =	12.500000
214		6.000000 x	3.800000 =	22.800000
211		95.000000 x	.779800 =	74.081000
			-----	
			ΑΘΡΟΙΣΜΑ =	629.155704
			-----	
			Η.Δ. =	692.071274
507	507			
406		1.000000 x	309.910000 =	309.910000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
242		7.000000 x	5.000000 =	35.000000
214		10.000000 x	3.800000 =	38.000000
211		165.000000 x	.779800 =	128.667000
			-----	
			ΑΘΡΟΙΣΜΑ =	831.761704
			-----	
			Η.Δ. =	914.937874
508	508			
407		1.000000 x	52.260000 =	52.260000
116		16.000000 x	22.893045 =	366.288720
211		40.000000 x	.779800 =	31.192000
214		2.000000 x	3.800000 =	7.600000
115		4.000000 x	18.893831 =	75.575324
408		2.000000 x	4.290000 =	8.580000
			-----	
			ΑΘΡΟΙΣΜΑ =	541.496044
			-----	
			Η.Δ. =	595.645648
509	509			
409		1.000000 x	119.340000 =	119.340000
117		8.000000 x	18.893831 =	151.150648
214		5.000000 x	3.800000 =	19.000000
211		80.000000 x	.779800 =	62.384000
			-----	
			ΑΘΡΟΙΣΜΑ =	351.874648
			-----	
			Η.Δ. =	387.062113
510	510			
410		1.000000 x	110.310000 =	110.310000
117		8.000000 x	18.893831 =	151.150648
211		80.000000 x	.779800 =	62.384000
214		5.000000 x	3.800000 =	19.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	342.844648
			-----	
			Η.Δ. =	377.129113

511	511			
411		1.000000 x	25.900000 =	25.900000
214		1.000000 x	3.800000 =	3.800000
112		30.000000 x	17.729980 =	531.899400
115		4.000000 x	18.893831 =	75.575324
212		17.000000 x	.829400 =	14.099800
			-----	
			ΑΘΡΟΙΣΜΑ =	651.274524
			-----	
			Η.Δ. =	716.401976
512	512			
412		1.000000 x	2.830000 =	2.830000
214		1.000000 x	3.800000 =	3.800000
115		2.000000 x	18.893831 =	37.787662
112		2.000000 x	17.729980 =	35.459960
211		10.000000 x	.779800 =	7.798000
			-----	
			ΑΘΡΟΙΣΜΑ =	87.675622
			-----	
			Η.Δ. =	96.443184
513	513			
413		1.000000 x	4.290000 =	4.290000
211		15.000000 x	.779800 =	11.697000
115		3.000000 x	18.893831 =	56.681493
112		3.000000 x	17.729980 =	53.189940
214		1.500000 x	3.800000 =	5.700000
			-----	
			ΑΘΡΟΙΣΜΑ =	131.558433
			-----	
			Η.Δ. =	144.714276
514	514			
414		1.000000 x	5.910000 =	5.910000
115		4.000000 x	18.893831 =	75.575324
112		4.000000 x	17.729980 =	70.919920
214		2.000000 x	3.800000 =	7.600000
211		21.000000 x	.779800 =	16.375800
			-----	
			ΑΘΡΟΙΣΜΑ =	176.381044
			-----	
			Η.Δ. =	194.019148
515	515			
415		1.000000 x	8.320000 =	8.320000
112		6.000000 x	17.729980 =	106.379880
115		5.000000 x	18.893831 =	94.469155
214		2.500000 x	3.800000 =	9.500000
211		27.000000 x	.779800 =	21.054600
			-----	
			ΑΘΡΟΙΣΜΑ =	239.723635
			-----	
			Η.Δ. =	263.695999

516	516			
416		1.000000 x	12.820000 =	12.820000
115		6.000000 x	18.893831 =	113.362986
112		8.000000 x	17.729980 =	141.839840
214		3.500000 x	3.800000 =	13.300000
211		33.000000 x	.779800 =	25.733400
		-----		
			ΑΘΡΟΙΣΜΑ =	307.056226
		-----		
			Η.Δ. =	337.761849
517	517			
406		1.000000 x	309.910000 =	309.910000
406		.400000 x	309.910000 =	123.964000
116		8.000000 x	22.893045 =	183.144360
115		8.000000 x	18.893831 =	151.150648
114		8.000000 x	22.739959 =	181.919672
113		2.000000 x	23.479183 =	46.958366
112		16.000000 x	17.729980 =	283.679680
111		16.000000 x	15.951934 =	255.230944
251		.150000 x	290.000000 =	43.500000
214		8.000000 x	3.800000 =	30.400000
211		240.000000 x	.779800 =	187.152000
407		2.000000 x	52.260000 =	104.520000
		-----		
			ΑΘΡΟΙΣΜΑ =	1,901.529670
		-----		
			Η.Δ. =	2,091.682637
518	518			
417		1.000000 x	127.340000 =	127.340000
118		8.000000 x	17.283129 =	138.265032
112		8.000000 x	17.729980 =	141.839840
212		5.000000 x	.829400 =	4.147000
214		12.000000 x	3.800000 =	45.600000
114		8.000000 x	22.739959 =	181.919672
211		180.000000 x	.779800 =	140.364000
		-----		
			ΑΘΡΟΙΣΜΑ =	779.475544
		-----		
			Η.Δ. =	857.423098
520	520			
419		1.000000 x	4.290000 =	4.290000
211		80.000000 x	.779800 =	62.384000
212		2.000000 x	.829400 =	1.658800
118		4.000000 x	17.283129 =	69.132516
115		8.000000 x	18.893831 =	151.150648
112		4.000000 x	17.729980 =	70.919920
214		5.000000 x	3.800000 =	19.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	378.535884
		-----		
			Η.Δ. =	416.389472

521	521			
420		1.000000 x	92.090000 =	92.090000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
214		3.000000 x	3.800000 =	11.400000
211		40.000000 x	.779800 =	31.192000
			-----	
			ΑΘΡΟΙΣΜΑ =	385.734188
			-----	
			Η.Δ. =	424.307607
522	522			
421		1.000000 x	30.830000 =	30.830000
114		8.000000 x	22.739959 =	181.919672
118		2.000000 x	17.283129 =	34.566258
214		2.000000 x	3.800000 =	7.600000
211		20.000000 x	.779800 =	15.596000
			-----	
			ΑΘΡΟΙΣΜΑ =	270.511930
			-----	
			Η.Δ. =	297.563123
529	529			
429		1.000000 x	73.440000 =	73.440000
211		70.000000 x	.779800 =	54.586000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
214		4.000000 x	3.800000 =	15.200000
			-----	
			ΑΘΡΟΙΣΜΑ =	394.278188
			-----	
			Η.Δ. =	433.706007
550	550			
450		1.000000 x	79.370000 =	79.370000
451		4.000000 x	4.610000 =	18.440000
116		32.000000 x	22.893045 =	732.577440
115		4.000000 x	18.893831 =	75.575324
214		4.000000 x	3.800000 =	15.200000
211		90.000000 x	.779800 =	70.182000
			-----	
			ΑΘΡΟΙΣΜΑ =	991.344764
			-----	
			Η.Δ. =	1,090.479240
551	551			
405		1.000000 x	199.590000 =	199.590000
211		95.000000 x	.779800 =	74.081000
214		6.000000 x	3.800000 =	22.800000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
452		1.000000 x	99.500000 =	99.500000
			-----	
			ΑΘΡΟΙΣΜΑ =	716.155704
			-----	
			Η.Δ. =	787.771274

552	552			
453		1.000000 x	.000000 =	.000000
115		8.000000 x	18.893831 =	151.150648
214		1.000000 x	3.800000 =	3.800000
211		18.000000 x	.779800 =	14.036400
		-----		
		ΑΘΡΟΙΣΜΑ =		168.987048
		-----		
		Η.Δ. =		
553	553			
454		1.000000 x	92.090000 =	92.090000
214		4.000000 x	3.800000 =	15.200000
211		100.000000 x	.779800 =	77.980000
		-----		
		ΑΘΡΟΙΣΜΑ =		185.270000
		-----		
		Η.Δ. =		203.797000
554	554			
455		1.000000 x	29.610000 =	29.610000
		-----		
		ΑΘΡΟΙΣΜΑ =		29.610000
		-----		
		Η.Δ. =		32.571000
555	555			
456		1.000000 x	33.160000 =	33.160000
212		17.000000 x	.829400 =	14.099800
112		32.000000 x	17.729980 =	567.359360
115		4.000000 x	18.893831 =	75.575324
214		1.000000 x	3.800000 =	3.800000
		-----		
		ΑΘΡΟΙΣΜΑ =		693.994484
		-----		
		Η.Δ. =		763.393932
556	556			
457		1.000000 x	433.250000 =	433.250000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032
214		18.000000 x	3.800000 =	68.400000
211		200.000000 x	.779800 =	155.960000
		-----		
		ΑΘΡΟΙΣΜΑ =		977.794704
		-----		
		Η.Δ. =		1,075.574174
557	557			
458		1.000000 x	269.790000 =	269.790000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
214		11.000000 x	3.800000 =	41.800000
211		130.000000 x	.779800 =	101.374000
		-----		
		ΑΘΡΟΙΣΜΑ =		733.148704
		-----		
		Η.Δ. =		806.463574

558	558				
459		1.000000 x	407.490000 =	407.490000	
214		12.000000 x	3.800000 =	45.600000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	.779800 =	155.960000	
			-----		
			ΑΘΡΟΙΣΜΑ =	976.734704	
			-----		
			Η.Δ. =	1,074.408174	
559	559				
460		1.000000 x	503.880000 =	503.880000	
211		250.000000 x	.779800 =	194.950000	
214		15.000000 x	3.800000 =	57.000000	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
242		12.000000 x	5.000000 =	60.000000	
			-----		
			ΑΘΡΟΙΣΜΑ =	1,136.014704	
			-----		
			Η.Δ. =	1,249.616174	
560	560				
461		1.000000 x	226.250000 =	226.250000	
114		8.000000 x	22.739959 =	181.919672	
211		160.000000 x	.779800 =	124.768000	
214		8.000000 x	3.800000 =	30.400000	
			-----		
			ΑΘΡΟΙΣΜΑ =	563.337672	
			-----		
			Η.Δ. =	619.671439	
561	561				
462		1.000000 x	329.900000 =	329.900000	
214		12.000000 x	3.800000 =	45.600000	
114		8.000000 x	22.739959 =	181.919672	
211		230.000000 x	.779800 =	179.354000	
			-----		
			ΑΘΡΟΙΣΜΑ =	736.773672	
			-----		
			Η.Δ. =	810.451039	
562	562				
463		1.000000 x	41.450000 =	41.450000	
214		2.400000 x	3.800000 =	9.120000	
211		50.000000 x	.779800 =	38.990000	
			-----		
			ΑΘΡΟΙΣΜΑ =	89.560000	
			-----		
			Η.Δ. =	98.516000	



563	563			
211.1		640.000000 x	.000000 =	.000000
114		16.000000 x	22.739959 =	363.839344
112		24.000000 x	17.729980 =	425.519520
214		16.000000 x	3.800000 =	60.800000
464		1.000000 x	363.070000 =	363.070000
		-----		
			ΑΘΡΟΙΣΜΑ =	1,213.228864
		-----		
			Η.Δ. =	
564	564			
465		1.000000 x	97.130000 =	97.130000
567		3.000000 x	342.371968 =	1,027.115904
111		8.000000 x	15.951934 =	127.615472
115		8.000000 x	18.893831 =	151.150648
115		8.000000 x	18.893831 =	151.150648
		-----		
			ΑΘΡΟΙΣΜΑ =	1,554.162672
		-----		
			Η.Δ. =	1,709.578939
565	565			
450		3.000000 x	79.370000 =	238.110000
465		1.000000 x	97.130000 =	97.130000
115		8.000000 x	18.893831 =	151.150648
115		12.000000 x	18.893831 =	226.725972
		-----		
			Η.Δ. =	713.116620
566	566			
211.1		680.000000 x	.000000 =	.000000
466		1.000000 x	45.310000 =	45.310000
112		1.000000 x	17.729980 =	17.729980
115		2.000000 x	18.893831 =	37.787662
		-----		
			ΑΘΡΟΙΣΜΑ =	100.827642
		-----		
			Η.Δ. =	
567	567			
450		1.000000 x	79.370000 =	79.370000
115		4.000000 x	18.893831 =	75.575324
112		4.000000 x	17.729980 =	70.919920
214		4.000000 x	3.800000 =	15.200000
211		90.000000 x	.779800 =	70.182000
		-----		
			ΑΘΡΟΙΣΜΑ =	311.247244
		-----		
			Η.Δ. =	342.371968

568.1	568.1				
467		1.000000 x	329.900000 =	329.900000	
567		2.000000 x	342.371968 =	684.743936	
512		.240000 x	96.443184 =	23.146364	
510		.072000 x	377.129113 =	27.153296	
118		32.000000 x	17.283129 =	553.060128	
114		8.000000 x	22.739959 =	181.919672	
113		32.000000 x	23.479183 =	751.333856	
214		16.000000 x	3.800000 =	60.800000	
			ΑΘΡΟΙΣΜΑ =	2,612.057252	
			Η.Δ. =	2,873.262978	
568.2	568.2				
450		2.000000 x	79.370000 =	158.740000	
115		8.000000 x	18.893831 =	151.150648	
467		1.000000 x	329.900000 =	329.900000	
114		8.000000 x	22.739959 =	181.919672	
			Η.Δ. =	821.710320	
569.1	569.1				
468		1.000000 x	82.620000 =	82.620000	
214		16.000000 x	3.800000 =	60.800000	
567		2.000000 x	342.371968 =	684.743936	
118		8.000000 x	17.283129 =	138.265032	
114		8.000000 x	22.739959 =	181.919672	
			ΑΘΡΟΙΣΜΑ =	1,148.348640	
			Η.Δ. =	1,263.183504	
569.2	569.2				
450		2.000000 x	79.370000 =	158.740000	
115		8.000000 x	18.893831 =	151.150648	
114		8.000000 x	22.739959 =	181.919672	
468		1.000000 x	82.620000 =	82.620000	
			Η.Δ. =	574.430320	
570.1	570.1				
469		1.000000 x	82.620000 =	82.620000	
211		135.000000 x	.779800 =	105.273000	
114		8.000000 x	22.739959 =	181.919672	
118		4.000000 x	17.283129 =	69.132516	
214		16.000000 x	3.800000 =	60.800000	
			ΑΘΡΟΙΣΜΑ =	499.745188	
			Η.Δ. =	549.719707	

570.2	570.2			
469		1.000000 x	82.620000 =	82.620000
118		4.000000 x	17.283129 =	69.132516
			H.Δ. =	151.752516
571.1	571.1			
470		1.000000 x	66.630000 =	66.630000
114		8.000000 x	22.739959 =	181.919672
214		4.000000 x	3.800000 =	15.200000
211		114.000000 x	.779800 =	88.897200
			AΘΡΟΙΣΜΑ =	352.646872
			H.Δ. =	387.911559
571.2	571.2			
470		1.000000 x	66.630000 =	66.630000
114		8.000000 x	22.739959 =	181.919672
			H.Δ. =	248.549672
572	572			
407		1.000000 x	52.260000 =	52.260000
471		1.000000 x	57.740000 =	57.740000
114		8.000000 x	22.739959 =	181.919672
214		8.000000 x	3.800000 =	30.400000
111		24.000000 x	15.951934 =	382.846416
211		54.000000 x	.779800 =	42.109200
			AΘΡΟΙΣΜΑ =	747.275288
			H.Δ. =	822.002817
573	573			
407		1.000000 x	52.260000 =	52.260000
473		.250000 x	16.140000 =	4.035000
474		.250000 x	33.160000 =	8.290000
474		1.000000 x	33.160000 =	33.160000
473		1.000000 x	16.140000 =	16.140000
115		16.000000 x	18.893831 =	302.301296
111		24.000000 x	15.951934 =	382.846416
214		8.000000 x	3.800000 =	30.400000
211		54.000000 x	.779800 =	42.109200
407		.250000 x	52.260000 =	13.065000
472		.250000 x	25.100000 =	6.275000
472		1.000000 x	25.100000 =	25.100000
			AΘΡΟΙΣΜΑ =	915.981912
			H.Δ. =	1,007.580103

574	574			
475		1.000000 x	1,865.120000 =	1,865.120000
214		30.000000 x	3.800000 =	114.000000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
111		16.000000 x	15.951934 =	255.230944
242		7.000000 x	5.000000 =	35.000000
211		590.000000 x	.779800 =	460.082000
			-----	
			ΑΘΡΟΙΣΜΑ =	3,049.617648
			-----	
			Η.Δ. =	3,354.579413
574.1	574.1			
475		1.000000 x	1,865.120000 =	1,865.120000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032
			-----	
			Η.Δ. =	2,185.304704
575	575			
476		1.000000 x	80.840000 =	80.840000
214		23.000000 x	3.800000 =	87.400000
115		8.000000 x	18.893831 =	151.150648
211		470.000000 x	.779800 =	366.506000
			-----	
			ΑΘΡΟΙΣΜΑ =	685.896648
			-----	
			Η.Δ. =	754.486313
575.1	575.1			
476		1.000000 x	80.840000 =	80.840000
115		8.000000 x	18.893831 =	151.150648
			-----	
			Η.Δ. =	231.990648
576	576			
477		1.000000 x	6.580000 =	6.580000
			-----	
			ΑΘΡΟΙΣΜΑ =	6.580000
			-----	
			Η.Δ. =	7.238000
576.1	576.1			
477		1.000000 x	6.580000 =	6.580000
			-----	
			Η.Δ. =	6.580000

577	577			
478		1.000000 x	108.970000 =	108.970000
242		2.000000 x	5.000000 =	10.000000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032
111		8.000000 x	15.951934 =	127.615472
214		4.000000 x	3.800000 =	15.200000
211		70.000000 x	.779800 =	54.586000
			-----	
			ΑΘΡΟΙΣΜΑ =	636.556176
			-----	
			Η.Δ. =	700.211794
577.1	577.1			
478		1.000000 x	108.970000 =	108.970000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
			-----	
			Η.Δ. =	429.154704
578	578			
479		1.000000 x	175.310000 =	175.310000
211		50.000000 x	.779800 =	38.990000
242		5.000000 x	5.000000 =	25.000000
118		4.000000 x	17.283129 =	69.132516
114		8.000000 x	22.739959 =	181.919672
112		4.000000 x	17.729980 =	70.919920
214		5.000000 x	3.800000 =	19.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	580.272108
			-----	
			Η.Δ. =	638.299319
579	579			
480		1.000000 x	25.760000 =	25.760000
212		28.000000 x	.829400 =	23.223200
117		8.000000 x	18.893831 =	151.150648
214		1.000000 x	3.800000 =	3.800000
			-----	
			ΑΘΡΟΙΣΜΑ =	203.933848
			-----	
			Η.Δ. =	224.327233
580	580			
481		1.000000 x	769.090000 =	769.090000
211		168.000000 x	.779800 =	131.006400
242		2.000000 x	5.000000 =	10.000000
118		8.000000 x	17.283129 =	138.265032
114		8.000000 x	22.739959 =	181.919672
111		16.000000 x	15.951934 =	255.230944
214		8.000000 x	3.800000 =	30.400000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,515.912048
			-----	
			Η.Δ. =	1,667.503253

581	581			
481		1.000000 x	769.090000 =	769.090000
114		8.000000 x	22.739959 =	181.919672
118		8.000000 x	17.283129 =	138.265032
		-----		
			H.Δ. =	1,089.274704
7020.2	7020.2			
111		8.000000 x	15.951934 =	127.615472
571.2		.150000 x	248.549672 =	37.282451
571.1		.350000 x	387.911559 =	135.769046
570.2		.350000 x	151.752516 =	53.113381
570.1		.150000 x	549.719707 =	82.457956
569.2		.670000 x	574.430320 =	384.868314
569.1		.330000 x	1,263.183504 =	416.850556
568.2		.550000 x	821.710320 =	451.940676
568.1		.450000 x	2,873.262978 =	1,292.968340
567		1.000000 x	342.371968 =	342.371968
116		8.000000 x	22.893045 =	183.144360
		-----		
			H.Δ. =	3,508.382520
7021.2	7021.2			
111		8.000000 x	15.951934 =	127.615472
571.2		.240000 x	248.549672 =	59.651921
571.1		.260000 x	387.911559 =	100.857005
570.2		.390000 x	151.752516 =	59.183481
570.1		.110000 x	549.719707 =	60.469168
569.2		.750000 x	574.430320 =	430.822740
116		8.000000 x	22.893045 =	183.144360
567		1.000000 x	342.371968 =	342.371968
568.1		.250000 x	2,873.262978 =	718.315745
569.1		.250000 x	1,263.183504 =	315.795876
568.2		.750000 x	821.710320 =	616.282740
		-----		
			H.Δ. =	3,014.510476
7022.2	7022.2			
111		8.000000 x	15.951934 =	127.615472
571.2		.310000 x	248.549672 =	77.050398
571.1		.190000 x	387.911559 =	73.703196
570.2		.420000 x	151.752516 =	63.736057
570.1		.080000 x	549.719707 =	43.977577
569.2		.820000 x	574.430320 =	471.032862
569.1		.180000 x	1,263.183504 =	227.373031
568.2		.850000 x	821.710320 =	698.453772
568.1		.150000 x	2,873.262978 =	430.989447
567		1.000000 x	342.371968 =	342.371968
116		8.000000 x	22.893045 =	183.144360
		-----		
			H.Δ. =	2,739.448140

613	613			
111		.140000 x	15.951934 =	2.233271
520		.003500 x	416.389472 =	1.457363
503		.000770 x	877.327207 =	.675542
504		.002800 x	352.551839 =	.987145
-----				
			B.T =	5.353321
614	614			
112		.070000 x	17.729980 =	1.241099
504		.002800 x	352.551839 =	.987145
518		.004375 x	857.423098 =	3.751226
509		.004375 x	387.062113 =	1.693397
503		.000700 x	877.327207 =	.614129
-----				
			B.T =	8.286996
621.1	621.1			
213		.100000 x	1.800000 =	.180000
116		.140000 x	22.893045 =	3.205026
504		.003500 x	352.551839 =	1.233931
508		.003500 x	595.645648 =	2.084760
111		.560000 x	15.951934 =	8.933083
-----				
			B.T =	15.636801
622	622			
213		.100000 x	1.800000 =	.180000
112		.070000 x	17.729980 =	1.241099
116		.140000 x	22.893045 =	3.205026
509		.003500 x	387.062113 =	1.354717
508		.003500 x	595.645648 =	2.084760
518		.004340 x	857.423098 =	3.721216
504		.003500 x	352.551839 =	1.233931
-----				
			B.T =	13.020750
6360.1 A1	6360.1 A1			
6304		9.800000 x	6.021472 =	59.010426
6330		.038000 x	185.598536 =	7.052744
6330		.190000 x	185.598536 =	35.263722
6314		.382500 x	2.146154 =	.820904
6314		7.650000 x	2.146154 =	16.418078
-----				
			B.T =	118.565874
6360.1 A2	6360.1 A2			
6304		.450000 x	6.021472 =	2.709662
6310		2.142000 x	1.515305 =	3.245783
6330		.013000 x	185.598536 =	2.412781
-----				
			B.T =	8.368227

6360.1 A3	6360.1 A3			
6304		.960000 x	6.021472 =	5.780613
6329.2		.037000 x	171.305119 =	6.338289
6310		1.974000 x	1.515305 =	2.991212
		-----		
			B.T =	15.110115
6360.1 A4	6360.1 A4			
6304		2.490000 x	6.021472 =	14.993465
6329.2		.109000 x	171.305119 =	18.672258
		-----		
			B.T =	33.665723
6360.1 A5	6360.1 A5			
112		1.700000 x	17.729980 =	30.140966
113		2.975000 x	23.479183 =	69.850569
113		.425000 x	23.479183 =	9.978653
6069.1		.056400 x	11.160776 =	.629468
		-----		
			B.T =	110.599656
6360.2 A1	6360.2 A1			
6304		10.650000 x	6.021472 =	64.128677
6314		.392500 x	2.146154 =	.842365
6314		7.850000 x	2.146154 =	16.847309
6330		.041000 x	185.598536 =	7.609540
6330		.205000 x	185.598536 =	38.047700
		-----		
			B.T =	127.475591
6360.2 A2	6360.2 A2			
6304		.750000 x	6.021472 =	4.516104
6330		.019000 x	185.598536 =	3.526372
6310		2.383500 x	1.515305 =	3.611729
		-----		
			B.T =	11.654206
6360.2 A3	6360.2 A3			
6304		1.140000 x	6.021472 =	6.864478
6310		2.341500 x	1.515305 =	3.548087
6329.2		.054000 x	171.305119 =	9.250476
		-----		
			B.T =	19.663041
6360.2 A4	6360.2 A4			
6304		2.800000 x	6.021472 =	16.860122
6329.2		.118000 x	171.305119 =	20.214004
		-----		
			B.T =	37.074126



6360.2 A5	6360.2 A5			
112		2.550000 x	17.729980 =	45.211449
113		.382500 x	23.479183 =	8.980787
113		2.975000 x	23.479183 =	69.850569
6069.1		.059400 x	11.160776 =	.662950
		-----		
			B.T =	124.705756
6360.3 A1	6360.3 A1			
6304		13.900000 x	6.021472 =	83.698461
6314		.557500 x	2.146154 =	1.196481
6314		11.150000 x	2.146154 =	23.929617
6330		.270000 x	185.598536 =	50.111605
6330		.054000 x	185.598536 =	10.022321
		-----		
			B.T =	168.958484
6360.3 A2	6360.3 A2			
6304		.940000 x	6.021472 =	5.660184
6330		.031000 x	185.598536 =	5.753555
6310		3.360000 x	1.515305 =	5.091425
		-----		
			B.T =	16.505163
6360.3 A3	6360.3 A3			
6304		1.830000 x	6.021472 =	11.019294
6310		10.678500 x	1.515305 =	16.181184
6329.2		.099000 x	171.305119 =	16.959207
		-----		
			B.T =	44.159685
6360.3 A4	6360.3 A4			
6304		3.420000 x	6.021472 =	20.593434
6329.2		.139000 x	171.305119 =	23.811412
		-----		
			B.T =	44.404846
6360.3 A5	6360.3 A5			
112		5.100000 x	17.729980 =	90.422898
113		.340000 x	23.479183 =	7.982922
113		2.975000 x	23.479183 =	69.850569
6069.1		.073800 x	11.160776 =	.823665
		-----		
			B.T =	169.080055

6360.4 A1	6360.4 A1			
6304		16.250000 x	6.021472 =	97.848920
6314		.885000 x	2.146154 =	1.899346
6314		17.700000 x	2.146154 =	37.986926
6330		.075000 x	185.598536 =	13.919890
6330		.375000 x	185.598536 =	69.599451
		-----		
			B.T =	221.254533
6360.4 A2	6360.4 A2			
6304		1.060000 x	6.021472 =	6.382760
6330		.048000 x	185.598536 =	8.908730
6310		4.641000 x	1.515305 =	7.032531
		-----		
			B.T =	22.324021
6360.4 A3	6360.4 A3			
6304		2.270000 x	6.021472 =	13.668741
6310		20.454000 x	1.515305 =	30.994048
6329.2		.125000 x	171.305119 =	21.413140
		-----		
			B.T =	66.075930
6360.4 A4	6360.4 A4			
6304		2.800000 x	6.021472 =	16.860122
6329.2		.118000 x	171.305119 =	20.214004
		-----		
			B.T =	37.074126
6360.4 A5	6360.4 A5			
112		6.800000 x	17.729980 =	120.563864
113		.297500 x	23.479183 =	6.985057
113		4.250000 x	23.479183 =	99.786528
6069.1		.091800 x	11.160776 =	1.024559
		-----		
			B.T =	228.360008
6360.5 A1	6360.5 A1			
6304		17.950000 x	6.021472 =	108.085422
6314		1.050000 x	2.146154 =	2.253462
6314		21.000000 x	2.146154 =	45.069234
6330		.088000 x	185.598536 =	16.332671
6330		.440000 x	185.598536 =	81.663356
		-----		
			B.T =	253.404145
6360.5 A2	6360.5 A2			
6304		1.220000 x	6.021472 =	7.346196
6330		.061000 x	185.598536 =	11.321511
6310		6.048000 x	1.515305 =	9.164565
		-----		
			B.T =	27.832271

6360.5 A3	6360.5 A3			
6304		2.480000 x	6.021472 =	14.933251
6310		22.291500 x	1.515305 =	33.778421
6329.2		.144000 x	171.305119 =	24.667937
		-----		
			B.T =	73.379609
6360.5 A4	6360.5 A4			
6304		3.200000 x	6.021472 =	19.268710
6329.2		.112000 x	171.305119 =	19.186173
		-----		
			B.T =	38.454884
6360.5 A5	6360.5 A5			
112		9.350000 x	17.729980 =	165.775313
113		5.950000 x	23.479183 =	139.701139
113		.255000 x	23.479183 =	5.987192
6069.1		.090600 x	11.160776 =	1.011166
		-----		
			B.T =	312.474810
6360.6 A1	6360.6 A1			
6304		20.350000 x	6.021472 =	122.536955
6314		24.900000 x	2.146154 =	53.439235
6330		.116000 x	185.598536 =	21.529430
6330		.580000 x	185.598536 =	107.647151
6314		1.245000 x	2.146154 =	2.671962
		-----		
			B.T =	307.824733
6360.6 A2	6360.6 A2			
6304		1.530000 x	6.021472 =	9.212852
6330		.092000 x	185.598536 =	17.075065
6310		10.206000 x	1.515305 =	15.465203
		-----		
			B.T =	41.753120
6360.6 A3	6360.6 A3			
6304		2.670000 x	6.021472 =	16.077330
6329.2		.181000 x	171.305119 =	31.006227
6310		25.798500 x	1.515305 =	39.092596
		-----		
			B.T =	86.176153
6360.6 A4	6360.6 A4			
6304		2.800000 x	6.021472 =	16.860122
6329.2		.118000 x	171.305119 =	20.214004
		-----		
			B.T =	37.074126

6360.6 A5

6360.6 A5

112	12.750000 x	17.729980 =	226.057245
113	.212500 x	23.479183 =	4.989326
6069.1	.120000 x	11.160776 =	1.339293
113	7.650000 x	23.479183 =	179.615750

-----  
B.T = 412.001614

641 641

231	.200000 x	.650000 =	.130000
111	.170000 x	15.951934 =	2.711829
251	.001500 x	290.000000 =	.435000
113	.127500 x	23.479183 =	2.993596
252	.002500 x	210.000000 =	.525000

-----  
B.T = 6.795425

651 651

221	150.000000 x	.097700 =	14.655000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	387.062113 =	3.651931
509	.003060 x	387.062113 =	1.184410
T 630	.600000 x	1.639534 =	.983720
T 625	.850000 x	21.675697 =	18.424342
511	.042500 x	716.401976 =	30.447084
112	.425000 x	17.729980 =	7.535242
111	1.275000 x	15.951934 =	20.338716

-----  
B.T = 105.620445

652 652

221	650.000000 x	.097700 =	63.505000
T 630	.320000 x	1.639534 =	.524651
T 625	1.000000 x	21.675697 =	21.675697
511	.042500 x	716.401976 =	30.447084
509	.001632 x	387.062113 =	.631685
509	.009435 x	387.062113 =	3.651931
111	1.275000 x	15.951934 =	20.338716
112	.425000 x	17.729980 =	7.535242

-----  
B.T = 148.310006

652.1 652.1

221	450.000000 x	.097700 =	43.965000
111	1.275000 x	15.951934 =	20.338716
509	.010001 x	387.062113 =	3.871008
T 630	.320000 x	1.639534 =	.524651
T 625	1.060000 x	21.675697 =	22.976239
511	.042500 x	716.401976 =	30.447084
510	.001632 x	377.129113 =	.615475
112	.425000 x	17.729980 =	7.535242

-----  
B.T = 130.273414

652.2	652.2			
221		900.000000 x	.097700 =	87.930000
509		.007548 x	387.062113 =	2.921545
T 630		.320000 x	1.639534 =	.524651
T 625		.800000 x	21.675697 =	17.340558
511		.042500 x	716.401976 =	30.447084
510		.001632 x	377.129113 =	.615475
112		.425000 x	17.729980 =	7.535242
111		1.275000 x	15.951934 =	20.338716
				-----
			B.T =	167.653269
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.097700 =	1.270100
113		.935000 x	23.479183 =	21.953036
				-----
			B.T =	
7001 A	7001 A			
502		.000365 x	777.816807 =	.283903
557		.001094 x	806.463574 =	.882271
				-----
			AΘΡΟΙΣΜΑ =	1.166174
	B.T =	.200000 x	1.166174 =	.233235
				-----
7001 B	7001 B			
558		.000700 x	1,074.408174 =	.752086
				-----
			B.T =	.752086
7001 E	7001 E			
503		.000875 x	877.327207 =	.767661
554		.000875 x	32.571000 =	.028500
				-----
			B.T =	.796161
7001 Γ	7001 Γ			
501		.000700 x	592.073965 =	.414452
502		.000700 x	777.816807 =	.544472
				-----
			B.T =	.958924

7001 Δ	7001 Δ			
502		.000292 x	777.816807 =	.227123
510		.000292 x	377.129113 =	.110122
X 630.1		.060000 x	1.583942 =	.095037
X 630		.060000 x	1.350205 =	.081012
			-----	
			ΑΘΡΟΙΣΜΑ =	.513293
	B.T =	.600000 x	.513293 =	.307976
			-----	
7003 Α	7003 Α			
502		.000365 x	777.816807 =	.283903
557		.001094 x	806.463574 =	.882271
			-----	
			ΑΘΡΟΙΣΜΑ =	1.166174
	B.T =	.100000 x	1.166174 =	.116617
			-----	
7003 Β	7003 Β			
559		.000464 x	1,249.616174 =	.579822
			-----	
			B.T =	.579822
7003 Γ	7003 Γ			
502		.000700 x	777.816807 =	.544472
			-----	
			B.T =	.544472
7003 Δ	7003 Δ			
502		.000875 x	777.816807 =	.680590
562		.000875 x	98.516000 =	.086202
			-----	
			B.T =	.766791
7005 Α	7005 Α			
502		.000365 x	777.816807 =	.283903
557		.001094 x	806.463574 =	.882271
			-----	
			ΑΘΡΟΙΣΜΑ =	1.166174
	B.T =	.100000 x	1.166174 =	.116617
			-----	
7005 Β	7005 Β			
559		.000812 x	1,249.616174 =	1.014688
			-----	
			B.T =	1.014688
7005 Ε	7005 Ε			
502		.000875 x	777.816807 =	.680590
562		.000875 x	98.516000 =	.086202
			-----	
			B.T =	.766791

7005 Γ	7005 Γ			
559		.000232 x	1,249.616174 =	.289911
		-----		
			B.T =	.289911
7005 Δ	7005 Δ			
502		.000700 x	777.816807 =	.544472
		-----		
			B.T =	.544472
7010 Α	7010 Α			
558		.000315 x	1,074.408174 =	.338439
		-----		
			B.T =	.338439
7010 Β	7010 Β			
558		.000473 x	1,074.408174 =	.508195
		-----		
			B.T =	.508195
7010 Ε	7010 Ε			
503		.000875 x	877.327207 =	.767661
553		.000875 x	203.797000 =	.178322
		-----		
			B.T =	.945984
7010 Γ	7010 Γ			
502		.000700 x	777.816807 =	.544472
		-----		
			B.T =	.544472
7010 Δ	7010 Δ			
502		.000292 x	777.816807 =	.227123
510		.000292 x	377.129113 =	.110122
X 630.1		.060000 x	1.583942 =	.095037
X 630		.060000 x	1.350205 =	.081012
		-----		
			AΘΡΟΙΣΜΑ =	.513293
	B.T =	.600000 x	.513293 =	.307976
		-----		
7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
223		350.000000 x	.117200 =	41.020000
509		.007831 x	387.062113 =	3.031083
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.830000 x	18.541816 =	15.389707
T 617		.500000 x	6.092652 =	3.046326
509		.004718 x	387.062113 =	1.826159
		-----		
			B.T =	77.593999

7016.2	7016.2			
570.1		.586500 x	549.719707 =	322.410608
571.1		.586500 x	387.911559 =	227.510129
570.2		1.113500 x	151.752516 =	168.976427
571.2		1.113500 x	248.549672 =	276.760060
			-----	
			ΑΘΡΟΙΣΜΑ =	995.657224
	B.T =	.025000 x	995.657224 =	24.891431
			-----	
7016.3	7016.3			
564		.212500 x	1,709.578939 =	363.285525
565		.637500 x	713.116620 =	454.611845
			-----	
			ΑΘΡΟΙΣΜΑ =	817.897370
	B.T =	.025000 x	817.897370 =	20.447434
			-----	
7016.4	7016.4			
7016.1		1.000000 x	77.593999 =	77.593999
7016.3		1.000000 x	20.447434 =	20.447434
7016.2		1.000000 x	24.891431 =	24.891431
			-----	
			B.T =	122.932864
7016.5	7016.5			
7016.4		.200000 x	122.932864 =	24.586573
			-----	
			B.T =	24.586573
7016.6	7016.6			
7016.4		.250000 x	122.932864 =	30.733216
7016.5		.250000 x	24.586573 =	6.146643
			-----	
			B.T =	36.879859
7016.7	7016.7			
111		5.100000 x	15.951934 =	81.354863
			-----	
			B.T =	81.354863
7016.8	7016.8			
113		5.100000 x	23.479183 =	119.743833
			-----	
			B.T =	119.743833



7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.830000 x	18.541816 =	15.389707
T 617		.500000 x	6.092652 =	3.046326
509		.007831 x	387.062113 =	3.031083
509		.004718 x	387.062113 =	1.826159
223		350.000000 x	.117200 =	41.020000
				-----
			B.T =	77.593999
7017.2	7017.2			
564		.425000 x	1,709.578939 =	726.571049
565		.425000 x	713.116620 =	303.074564
				-----
			ΑΘΡΟΙΣΜΑ =	1,029.645613
	B.T =	.012500 x	1,029.645613 =	12.870570
				-----
7017.3	7017.3			
7017.1		1.000000 x	77.593999 =	77.593999
7017.2		1.000000 x	12.870570 =	12.870570
				-----
			B.T =	90.464569
7017.4	7017.4			
7017.3		.200000 x	90.464569 =	18.092914
				-----
			B.T =	18.092914
7017.5	7017.5			
7017.3		.300000 x	90.464569 =	27.139371
7017.4		.300000 x	18.092914 =	5.427874
				-----
			B.T =	32.567245
7017.6	7017.6			
111		5.100000 x	15.951934 =	81.354863
				-----
			B.T =	81.354863
7017.7	7017.7			
113		2.550000 x	23.479183 =	59.871917
				-----
			B.T =	59.871917

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
223		350.000000 x	.117200 =	41.020000
				-----
			B.T =	78.229728
7019 A2	7019 A2			
555		.012143 x	763.393932 =	9.269893
				-----
			B.T =	9.269893
7019 A3	7019 A3			
570.1		.850000 x	549.719707 =	467.261751
571.1		.850000 x	387.911559 =	329.724825
571.2		.850000 x	248.549672 =	211.267221
570.2		.850000 x	151.752516 =	128.989639
				-----
			ΑΘΡΟΙΣΜΑ =	1,137.243436
	B.T =	.014286 x	1,137.243436 =	16.246660
				-----
7019 A4	7019 A4			
112		2.295000 x	17.729980 =	40.690304
113		1.445000 x	23.479183 =	33.927419
				-----
			B.T =	74.617724
7019 A5	7019 A5			
113		.850000 x	23.479183 =	19.957306
				-----
			B.T =	19.957306
7019 A6	7019 A6			
7019 A1		1.000000 x	78.229728 =	78.229728
7019 A4		1.000000 x	74.617724 =	74.617724
7019 A2		1.000000 x	9.269893 =	9.269893
7019 A3		1.000000 x	16.246660 =	16.246660
7019 A5		1.000000 x	19.957306 =	19.957306
				-----
			B.T =	198.321311
7019 A7	7019 A7			
7019 A6		.100000 x	198.321311 =	19.832131
				-----
			B.T =	19.832131

710	710			
397.3		.006660 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.510000 x	15.951934 =	8.135486
252		.001000 x	210.000000 =	.210000
-----				
			B.T =	
720	720			
566		.000174 x	.000000 =	.000000
-----				
			B.T =	
A 626	A 626			
504		.005025 x	352.551839 =	1.771573
509		.003750 x	387.062113 =	1.451483
-----				
			B.T =	3.223056
T 611	T 611			
111		1.275000 x	15.951934 =	20.338716
-----				
			B.T =	20.338716
T 617	T 617			
111		.085000 x	15.951934 =	1.355914
520		.005270 x	416.389472 =	2.194373
504		.004250 x	352.551839 =	1.498345
503		.001190 x	877.327207 =	1.044019
-----				
			B.T =	6.092652
T 621	T 621			
213		.100000 x	1.800000 =	.180000
508		.004250 x	595.645648 =	2.531494
116		.170000 x	22.893045 =	3.891818
111		.680000 x	15.951934 =	10.847315
-----				
			B.T =	17.450627
T 623	T 623			
213		.100000 x	1.800000 =	.180000
112		.085000 x	17.729980 =	1.507048
509		.004250 x	387.062113 =	1.645014
518		.008500 x	857.423098 =	7.288096
508		.004250 x	595.645648 =	2.531494
504		.004250 x	352.551839 =	1.498345
116		.170000 x	22.893045 =	3.891818
-----				
			B.T =	18.541816

T 625	T 625			
213		.100000 x	1.800000 =	.180000
112		.085000 x	17.729980 =	1.507048
116		.170000 x	22.893045 =	3.891818
518		.012155 x	857.423098 =	10.421978
509		.004250 x	387.062113 =	1.645014
508		.004250 x	595.645648 =	2.531494
504		.004250 x	352.551839 =	1.498345
			B.T =	21.675697
T 630	T 630			
512		.017000 x	96.443184 =	1.639534
			B.T =	1.639534
T 630.1	T 630.1			
510		.005100 x	377.129113 =	1.923358
			B.T =	1.923358
X 611	X 611			
111		1.050000 x	15.951934 =	16.749531
			B.T =	16.749531
X 617	X 617			
111		.070000 x	15.951934 =	1.116635
503		.000980 x	877.327207 =	.859781
520		.004340 x	416.389472 =	1.807130
504		.003500 x	352.551839 =	1.233931
			B.T =	5.017478
X 621	X 621			
213		.100000 x	1.800000 =	.180000
508		.003500 x	595.645648 =	2.084760
116		.140000 x	22.893045 =	3.205026
111		.560000 x	15.951934 =	8.933083
			B.T =	14.402869
X 623	X 623			
213		.100000 x	1.800000 =	.180000
508		.003500 x	595.645648 =	2.084760
518		.007000 x	857.423098 =	6.001962
509		.003500 x	387.062113 =	1.354717
504		.003500 x	352.551839 =	1.233931
116		.140000 x	22.893045 =	3.205026
112		.070000 x	17.729980 =	1.241099
			B.T =	15.301495

X 625	X 625			
213		.100000 x	1.800000 =	.180000
518		.010010 x	857.423098 =	8.582805
509		.003500 x	387.062113 =	1.354717
508		.003500 x	595.645648 =	2.084760
504		.003500 x	352.551839 =	1.233931
116		.140000 x	22.893045 =	3.205026
112		.070000 x	17.729980 =	1.241099
			B.T =	17.882339
X 630	X 630			
512		.014000 x	96.443184 =	1.350205
			B.T =	1.350205
X 630.1	X 630.1			
510		.004200 x	377.129113 =	1.583942
			B.T =	1.583942
2522	2522			
221		300.000000 x	.097700 =	29.310000
112		1.190000 x	17.729980 =	21.098676
113		1.360000 x	23.479183 =	31.931689
509		.004718 x	387.062113 =	1.826159
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.007548 x	387.062113 =	2.921545
509		.001275 x	387.062113 =	.493504
T 625		.500000 x	21.675697 =	10.837849
641		3.000000 x	6.795425 =	20.386275
T 630		.250000 x	1.639534 =	.409884
			T.E =	158.406700
6021	6021			
111		4.250000 x	15.951934 =	67.795720
509		.019380 x	387.062113 =	7.501264
			T.E =	75.296983
6022	6022			
111		2.550000 x	15.951934 =	40.677432
509		.008075 x	387.062113 =	3.125527
			T.E =	43.802958
6051	6051			
502		.000175 x	777.816807 =	.136118
			T.E =	.136118

6052	6052			
501		.000117 x	592.073965 =	.069273
502		.000088 x	777.816807 =	.068448
521		.000088 x	424.307607 =	.037339
-----				
			T.E =	.175060
6053	6053			
502		.000318 x	777.816807 =	.247346
507		.001000 x	914.937874 =	.914938
-----				
			T.E =	1.162284
6054	6054			
112		.004900 x	17.729980 =	.086877
509		.002975 x	387.062113 =	1.151510
507		.001077 x	914.937874 =	.985388
-----				
			T.E =	2.223775
6055	6055			
213		.400000 x	1.800000 =	.720000
503		.001167 x	877.327207 =	1.023841
508		.007000 x	595.645648 =	4.169520
504		.001400 x	352.551839 =	.493573
112		.490000 x	17.729980 =	8.687690
116		.280000 x	22.893045 =	6.410053
-----				
			T.E =	21.504676
6056	6056			
507		.001750 x	914.937874 =	1.601141
-----				
			T.E =	1.601141
6057	6057			
506		.087500 x	692.071274 =	60.556236
-----				
			T.E =	60.556236
6058	6058			
507		.087500 x	914.937874 =	80.057064
-----				
			T.E =	80.057064
6059	6059			
112		.070000 x	17.729980 =	1.241099
-----				
			T.E =	1.241099

6060	6060			
112		.350000 x	17.729980 =	6.205493
		-----		
			T.E =	6.205493
6061	6061			
112		.007000 x	17.729980 =	.124110
507		.001077 x	914.937874 =	.985388
509		.002975 x	387.062113 =	1.151510
501		.000583 x	592.073965 =	.345179
502		.001400 x	777.816807 =	1.088944
		-----		
			T.E =	3.695130
6062	6062			
213		.400000 x	1.800000 =	.720000
509		.002800 x	387.062113 =	1.083774
508		.002800 x	595.645648 =	1.667808
507		.001400 x	914.937874 =	1.280913
502		.002000 x	777.816807 =	1.555634
116		.175000 x	22.893045 =	4.006283
112		.175000 x	17.729980 =	3.102747
		-----		
			T.E =	13.417158
6063	6063			
112		.700000 x	17.729980 =	12.410986
112		.070000 x	17.729980 =	1.241099
509		.003641 x	387.062113 =	1.409293
112		.070000 x	17.729980 =	1.241099
112		.140000 x	17.729980 =	2.482197
		-----		
			T.E =	18.784674
6064	6064			
112		.140000 x	17.729980 =	2.482197
509		.003641 x	387.062113 =	1.409293
507		.014000 x	914.937874 =	12.809130
112		.070000 x	17.729980 =	1.241099
		-----		
			T.E =	17.941719
6065	6065			
506		.002800 x	692.071274 =	1.937800
506		.002100 x	692.071274 =	1.453350
		-----		
			T.E =	3.391149

6066	6066			
111		.070000 x	15.951934 =	1.116635
502		.000700 x	777.816807 =	.544472
-----				
			T.E =	1.661107
6067	6067			
111		.980000 x	15.951934 =	15.632895
X 630		.100000 x	1.350205 =	.135021
X 630.1		.100000 x	1.583942 =	.158394
-----				
			T.E =	15.926310
6068	6068			
111		.560000 x	15.951934 =	8.933083
622		1.351351 x	13.020750 =	17.595604
X 630.1		.200000 x	1.583942 =	.316788
X 630		.200000 x	1.350205 =	.270041
112		.560000 x	17.729980 =	9.928789
509		.016497 x	387.062113 =	6.385364
-----				
			T.E =	43.429668
6068.1	6068.1			
111		.560000 x	15.951934 =	8.933083
X 630.1		.200000 x	1.583942 =	.316788
X 630		.200000 x	1.350205 =	.270041
614		1.351351 x	8.286996 =	11.198640
509		.016497 x	387.062113 =	6.385364
112		.560000 x	17.729980 =	9.928789
-----				
			T.E =	37.032705
6069	6069			
112		.070000 x	17.729980 =	1.241099
509		.012017 x	387.062113 =	4.651325
X 625		1.050000 x	17.882339 =	18.776456
-----				
			T.E =	24.668880
6069.1	6069.1			
112		.070000 x	17.729980 =	1.241099
509		.012017 x	387.062113 =	4.651325
X 617		1.050000 x	5.017478 =	5.268352
-----				
			T.E =	11.160776
6070	6070			
501		.000467 x	592.073965 =	.276499
-----				
			T.E =	.276499



6071	6071			
504		.002333 x	352.551839 =	.822503
509		.002975 x	387.062113 =	1.151510
		-----		
			T.E =	1.974013
6072	6072			
504		.003500 x	352.551839 =	1.233931
509		.002800 x	387.062113 =	1.083774
		-----		
			T.E =	2.317705
6073	6073			
509		.000833 x	387.062113 =	.322423
		-----		
			T.E =	.322423
6074	6074			
509		.000784 x	387.062113 =	.303457
		-----		
			T.E =	.303457
6075	6075			
509		.001096 x	387.062113 =	.424220
		-----		
			T.E =	.424220
6076	6076			
112		.004900 x	17.729980 =	.086877
503		.000700 x	877.327207 =	.614129
509		.003914 x	387.062113 =	1.514961
507		.000840 x	914.937874 =	.768548
		-----		
			T.E =	2.984515
6077	6077			
503		.001400 x	877.327207 =	1.228258
		-----		
			T.E =	1.228258
6078	6078			
112		.004900 x	17.729980 =	.086877
505		.001400 x	787.066174 =	1.101893
501		.000056 x	592.073965 =	.033156
503		.000350 x	877.327207 =	.307065
		-----		
			T.E =	1.528990

6078.1	6078.1			
112		.004900 x	17.729980 =	.086877
501		.000056 x	592.073965 =	.033156
503		.000350 x	877.327207 =	.307065
556		.001400 x	1,075.574174 =	1.505804
		-----		
			T.E =	1.932901
6079	6079			
112		.014000 x	17.729980 =	.248220
501		.000700 x	592.073965 =	.414452
529		.000980 x	433.706007 =	.425032
X 630		.150000 x	1.350205 =	.202531
509		.000630 x	387.062113 =	.243849
502		.000350 x	777.816807 =	.272236
		-----		
			T.E =	1.806319
6080	6080			
112		.014000 x	17.729980 =	.248220
X 630.1		.100000 x	1.583942 =	.158394
X 630		.100000 x	1.350205 =	.135021
529		.000700 x	433.706007 =	.303594
502		.000292 x	777.816807 =	.227123
501		.000583 x	592.073965 =	.345179
		-----		
			T.E =	1.417530
6081.1	6081.1			
111		.420000 x	15.951934 =	6.699812
112		.280000 x	17.729980 =	4.964394
112		.420000 x	17.729980 =	7.446592
506		.007000 x	692.071274 =	4.844499
		-----		
			T.E =	23.955297
6081.2	6081.2			
111		.700000 x	15.951934 =	11.166354
112		.070000 x	17.729980 =	1.241099
6081.1		1.000000 x	23.955297 =	23.955297
		-----		
			T.E =	36.362749
6081.3	6081.3			
111		1.400000 x	15.951934 =	22.332708
6081.1		1.000000 x	23.955297 =	23.955297
112		.140000 x	17.729980 =	2.482197
		-----		
			T.E =	48.770202

6081.4	6081.4			
111		2.100000 x	15.951934 =	33.499061
6081.1		1.000000 x	23.955297 =	23.955297
112		.210000 x	17.729980 =	3.723296
		-----		
			T.E =	61.177654
6082.1	6082.1			
213		.400000 x	1.800000 =	.720000
111		1.400000 x	15.951934 =	22.332708
116		.700000 x	22.893045 =	16.025132
508		.070000 x	595.645648 =	41.695195
116		1.400000 x	22.893045 =	32.050263
		-----		
			T.E =	112.823297
6082.2	6082.2			
111		.700000 x	15.951934 =	11.166354
6082.1		1.000000 x	112.823297 =	112.823297
112		.140000 x	17.729980 =	2.482197
		-----		
			T.E =	126.471848
6082.3	6082.3			
111		1.400000 x	15.951934 =	22.332708
6082.1		1.000000 x	112.823297 =	112.823297
112		.280000 x	17.729980 =	4.964394
		-----		
			T.E =	140.120399
6082.4	6082.4			
111		2.100000 x	15.951934 =	33.499061
112		.420000 x	17.729980 =	7.446592
6082.1		1.000000 x	112.823297 =	112.823297
		-----		
			T.E =	153.768950
6083.1	6083.1			
111		.280000 x	15.951934 =	4.466542
112		.280000 x	17.729980 =	4.964394
506		.005833 x	692.071274 =	4.036852
112		.140000 x	17.729980 =	2.482197
		-----		
			T.E =	15.949985
6083.2	6083.2			
111		.560000 x	15.951934 =	8.933083
6083.1		1.000000 x	15.949985 =	15.949985
112		.070000 x	17.729980 =	1.241099
		-----		
			T.E =	26.124167

6083.3	6083.3				
111		1.120000 x	15.951934 =	17.866166	
112		.140000 x	17.729980 =	2.482197	
6083.1		1.000000 x	15.949985 =	15.949985	
		-----			
			T.E =	36.298348	
6083.4	6083.4				
111		1.680000 x	15.951934 =	26.799249	
112		.210000 x	17.729980 =	3.723296	
6083.1		1.000000 x	15.949985 =	15.949985	
		-----			
			T.E =	46.472530	
6084.1	6084.1				
213		.400000 x	1.800000 =	.720000	
111		1.470000 x	15.951934 =	23.449343	
116		.700000 x	22.893045 =	16.025132	
508		.035000 x	595.645648 =	20.847598	
116		1.050000 x	22.893045 =	24.037697	
		-----			
			T.E =	85.079769	
6084.2	6084.2				
111		.560000 x	15.951934 =	8.933083	
112		.105000 x	17.729980 =	1.861648	
6084.1		1.000000 x	85.079769 =	85.079769	
		-----			
			T.E =	95.874500	
6084.3	6084.3				
111		1.120000 x	15.951934 =	17.866166	
112		.210000 x	17.729980 =	3.723296	
6084.1		1.000000 x	85.079769 =	85.079769	
		-----			
			T.E =	106.669231	
6084.4	6084.4				
111		1.680000 x	15.951934 =	26.799249	
112		.315000 x	17.729980 =	5.584944	
6084.1		1.000000 x	85.079769 =	85.079769	
		-----			
			T.E =	117.463962	
6085.1	6085.1				
111		.140000 x	15.951934 =	2.233271	
506		.004666 x	692.071274 =	3.229205	
502		.001400 x	777.816807 =	1.088944	
112		.140000 x	17.729980 =	2.482197	
		-----			
			T.E =	9.033616	

6085.2	6085.2				
111		.350000 x	15.951934 =	5.583177	
112		.070000 x	17.729980 =	1.241099	
6085.1		1.000000 x	9.033616 =	9.033616	
-----					
			T.E =	15.857892	
6085.3	6085.3				
111		.700000 x	15.951934 =	11.166354	
112		.140000 x	17.729980 =	2.482197	
6085.1		1.000000 x	9.033616 =	9.033616	
-----					
			T.E =	22.682167	
6085.4	6085.4				
111		1.050000 x	15.951934 =	16.749531	
112		.210000 x	17.729980 =	3.723296	
6085.1		1.000000 x	9.033616 =	9.033616	
-----					
			T.E =	29.506443	
6086.1	6086.1				
213		.400000 x	1.800000 =	.720000	
508		.008750 x	595.645648 =	5.211899	
111		1.120000 x	15.951934 =	17.866166	
116		.490000 x	22.893045 =	11.217592	
116		.280000 x	22.893045 =	6.410053	
-----					
			T.E =	41.425710	
6086.2	6086.2				
111		.350000 x	15.951934 =	5.583177	
112		.105000 x	17.729980 =	1.861648	
6086.1		1.000000 x	41.425710 =	41.425710	
-----					
			T.E =	48.870535	
6086.3	6086.3				
111		.700000 x	15.951934 =	11.166354	
6086.1		1.000000 x	41.425710 =	41.425710	
112		.210000 x	17.729980 =	3.723296	
-----					
			T.E =	56.315360	
6086.4	6086.4				
111		1.050000 x	15.951934 =	16.749531	
6086.1		1.000000 x	41.425710 =	41.425710	
112		.315000 x	17.729980 =	5.584944	
-----					
			T.E =	63.760184	

6087	6087			
252		.001000 x	210.000000 =	.210000
113		.210000 x	23.479183 =	4.930628
112		.350000 x	17.729980 =	6.205493
111		.210000 x	15.951934 =	3.349906
-----				
			T.E =	14.696028
6088	6088			
6081.1		1.000000 x	23.955297 =	23.955297
6081.1		.900000 x	23.955297 =	21.559767
-----				
			T.E =	45.515064
6089	6089			
6082.1		1.000000 x	112.823297 =	112.823297
6082.1		.900000 x	112.823297 =	101.540967
-----				
			T.E =	214.364264
6090	6090			
6083.1		1.000000 x	15.949985 =	15.949985
6083.1		1.300000 x	15.949985 =	20.734981
-----				
			T.E =	36.684966
6091	6091			
6084.1		1.000000 x	85.079769 =	85.079769
6084.1		1.300000 x	85.079769 =	110.603700
-----				
			T.E =	195.683469
6100	6100			
231		.200000 x	.650000 =	.130000
111		.175000 x	15.951934 =	2.791588
251		.002000 x	290.000000 =	.580000
113		.105000 x	23.479183 =	2.465314
252.1		.002000 x	.000000 =	.000000
-----				
			T.E =	
6101	6101			
231		15.000000 x	.650000 =	9.750000
252		.018000 x	210.000000 =	3.780000
113		3.500000 x	23.479183 =	82.177141
112		3.500000 x	17.729980 =	62.054930
252.1		.020000 x	.000000 =	.000000
251		.068000 x	290.000000 =	19.720000
-----				
			T.E =	

6102	6102			
244		1.000000 x	2.470000 =	2.470000
112		.002100 x	17.729980 =	.037233
112		.001400 x	17.729980 =	.024822
506		.000070 x	692.071274 =	.048445
509		.000051 x	387.062113 =	.019740
506		.000070 x	692.071274 =	.048445
-----				
			T.E =	2.648685
6103	6103			
244		.125000 x	2.470000 =	.308750
112		.002800 x	17.729980 =	.049644
112		.004200 x	17.729980 =	.074466
509		.000102 x	387.062113 =	.039480
506		.000140 x	692.071274 =	.096890
506		.000140 x	692.071274 =	.096890
-----				
			T.E =	.666120
6104	6104			
236		3.000000 x	.513000 =	1.539000
517		.017500 x	2,091.682637 =	36.604446
111		.280000 x	15.951934 =	4.466542
113		.280000 x	23.479183 =	6.574171
-----				
			T.E =	49.184159
6105	6105			
111		.210000 x	15.951934 =	3.349906
517		.014000 x	2,091.682637 =	29.283557
113		.140000 x	23.479183 =	3.287086
-----				
			T.E =	35.920549
6106	6106			
512		.087500 x	96.443184 =	8.438779
-----				
			T.E =	8.438779
6107	6107			
513		.087500 x	144.714276 =	12.662499
-----				
			T.E =	12.662499
6108	6108			
514		.087500 x	194.019148 =	16.976675
-----				
			T.E =	16.976675

6109	6109			
515		.087500 x	263.695999 =	23.073400
		-----		
			T.E =	23.073400
6110	6110			
516		.087500 x	337.761849 =	29.554162
		-----		
			T.E =	29.554162
6120	6120			
112		.004200 x	17.729980 =	.074466
502		.001750 x	777.816807 =	1.361179
501		.000070 x	592.073965 =	.041445
		-----		
			T.E =	1.477091
6121	6121			
112		.004200 x	17.729980 =	.074466
509		.003113 x	387.062113 =	1.204924
502		.000315 x	777.816807 =	.245012
505		.000420 x	787.066174 =	.330568
507		.000875 x	914.937874 =	.800571
501		.000049 x	592.073965 =	.029012
		-----		
			T.E =	2.684553
6151	6151			
243		1.020000 x	1.900000 =	1.938000
243		.080000 x	1.900000 =	.152000
		-----		
			T.E =	2.090000
6152	6152			
112		.085000 x	17.729980 =	1.507048
113		.085000 x	23.479183 =	1.995731
		-----		
			T.E =	3.502779
6153	6153			
111		.425000 x	15.951934 =	6.779572
T 611		1.050000 x	20.338716 =	21.355652
509		.003570 x	387.062113 =	1.381812
112		.425000 x	17.729980 =	7.535242
		-----		
			T.E =	37.052277



6154	6154			
111		.425000 x	15.951934 =	6.779572
T 621		1.050000 x	17.450627 =	18.323158
112		.425000 x	17.729980 =	7.535242
509		.003570 x	387.062113 =	1.381812
		-----		
			T.E =	34.019784
6155	6155			
111		.680000 x	15.951934 =	10.847315
T 621		.350000 x	17.450627 =	6.107719
652		.100000 x	148.310006 =	14.831001
509		.003220 x	387.062113 =	1.246340
113		1.275000 x	23.479183 =	29.935958
		-----		
			T.E =	62.968333
6156	6156			
251		.000500 x	290.000000 =	.145000
652		.010000 x	148.310006 =	1.483100
113		.680000 x	23.479183 =	15.965844
112		.425000 x	17.729980 =	7.535242
		-----		
			T.E =	25.129186
6157	6157			
111		.420000 x	15.951934 =	6.699812
509		.002940 x	387.062113 =	1.137963
112		.420000 x	17.729980 =	7.446592
X 621		1.050000 x	14.402869 =	15.123012
		-----		
			T.E =	30.407379
6157.1	6157.1			
111		.420000 x	15.951934 =	6.699812
509		.002940 x	387.062113 =	1.137963
X 611		1.050000 x	16.749531 =	17.587008
112		.420000 x	17.729980 =	7.446592
		-----		
			T.E =	32.871374
6158	6158			
111		.560000 x	15.951934 =	8.933083
621.1		1.050000 x	15.636801 =	16.418641
509		.002940 x	387.062113 =	1.137963
504		.001400 x	352.551839 =	.493573
		-----		
			T.E =	26.983259

6201.1	6201.1			
261.1		1.000000 x	13.000000 =	13.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	23.412984
6201.2	6201.2			
261		1.000000 x	14.500000 =	14.500000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	24.912984
6201.3	6201.3			
261.2		1.000000 x	19.900000 =	19.900000
113		.212500 x	23.479183 =	4.989326
111		.340000 x	15.951934 =	5.423658
		-----		
			T.E =	30.312984
6201.4	6201.4			
262		1.000000 x	25.300000 =	25.300000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	35.712984
6201.5	6201.5			
263		1.000000 x	31.200000 =	31.200000
111		.850000 x	15.951934 =	13.559144
113		.637500 x	23.479183 =	14.967979
		-----		
			T.E =	59.727123
6201.6	6201.6			
263.2		1.000000 x	44.900000 =	44.900000
111		.850000 x	15.951934 =	13.559144
113		.637500 x	23.479183 =	14.967979
		-----		
			T.E =	73.427123
6201.7	6201.7			
264		1.000000 x	61.600000 =	61.600000
113		.637500 x	23.479183 =	14.967979
111		.850000 x	15.951934 =	13.559144
		-----		
			T.E =	90.127123

6202.1	6202.1				
281.1		1.000000 x	16.900000 =	16.900000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
		-----			
			T.E =	27.312984	
6202.2	6202.2				
281		1.000000 x	20.500000 =	20.500000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
		-----			
			T.E =	30.912984	
6202.3	6202.3				
281.2		1.000000 x	25.390000 =	25.390000	
111		.340000 x	15.951934 =	5.423658	
113		.212500 x	23.479183 =	4.989326	
		-----			
			T.E =	35.802984	
6202.4	6202.4				
282		1.000000 x	28.900000 =	28.900000	
113		.212500 x	23.479183 =	4.989326	
111		.340000 x	15.951934 =	5.423658	
		-----			
			T.E =	39.312984	
6202.5	6202.5				
283		1.000000 x	34.900000 =	34.900000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
		-----			
			T.E =	63.427123	
6202.6	6202.6				
283.1		1.000000 x	53.400000 =	53.400000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
		-----			
			T.E =	81.927123	
6202.7	6202.7				
284		1.000000 x	72.500000 =	72.500000	
111		.850000 x	15.951934 =	13.559144	
113		.637500 x	23.479183 =	14.967979	
		-----			
			T.E =	101.027123	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.255000 x	15.951934 =	4.067743
		-----		
			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	
6204	6204			
111		.210000 x	15.951934 =	3.349906
X 625		.700000 x	17.882339 =	12.517637
X 623		.400000 x	15.301495 =	6.120598
509		.005439 x	387.062113 =	2.105231
509		.003108 x	387.062113 =	1.202989
112		.420000 x	17.729980 =	7.446592
		-----		
			T.E =	32.742953
6204.1	6204.1			
111		.210000 x	15.951934 =	3.349906
112		.420000 x	17.729980 =	7.446592
509		.008702 x	387.062113 =	3.368215
613		1.050000 x	5.353321 =	5.620987
		-----		
			T.E =	19.785699

6205	6205			
111		.210000 x	15.951934 =	3.349906
112		.070000 x	17.729980 =	1.241099
509		.002800 x	387.062113 =	1.083774
613		1.000000 x	5.353321 =	5.353321
		-----		
			T.E =	11.028100
6251	6251			
509		.002800 x	387.062113 =	1.083774
613		1.000000 x	5.353321 =	5.353321
		-----		
			T.E =	6.437095
6252	6252			
509		.000784 x	387.062113 =	.303457
		-----		
			T.E =	.303457
6253	6253			
112		.210000 x	17.729980 =	3.723296
X 630.1		.200000 x	1.583942 =	.316788
501		.002917 x	592.073965 =	1.727080
521		.007000 x	424.307607 =	2.970153
X 630		.200000 x	1.350205 =	.270041
		-----		
			T.E =	9.007358
6301	6301			
231		.200000 x	.650000 =	.130000
252		.002500 x	210.000000 =	.525000
113		.127500 x	23.479183 =	2.993596
111		.170000 x	15.951934 =	2.711829
251		.001500 x	290.000000 =	.435000
		-----		
			T.E =	6.795425
6302	6302			
231		.300000 x	.650000 =	.195000
251		.002000 x	290.000000 =	.580000
111		.212500 x	15.951934 =	3.389786
252		.004000 x	210.000000 =	.840000
113		1.232500 x	23.479183 =	28.938093
		-----		
			T.E =	33.942879
6303	6303			
6302		.666660 x	33.942879 =	22.628360
		-----		
			T.E =	22.628360

6304	6304			
234.2		.018000 x	.666500 =	.011997
112		.212500 x	17.729980 =	3.767621
113		.010200 x	23.479183 =	.239488
113		.085000 x	23.479183 =	1.995731
235		.012000 x	.553000 =	.006636
		-----		
			T.E =	6.021472
6310	6310			
233		1.050000 x	.492800 =	.517440
113		.042500 x	23.479183 =	.997865
		-----		
			T.E =	1.515305
6311	6311			
233.1		1.050000 x	.492800 =	.517440
113		.042500 x	23.479183 =	.997865
		-----		
			T.E =	1.515305
6312	6312			
233.3		1.010000 x	7.500000 =	7.575000
233.3		.303000 x	7.500000 =	2.272500
113		.085000 x	23.479183 =	1.995731
113		.085000 x	23.479183 =	1.995731
		-----		
			T.E =	13.838961
6313	6313			
233.2		1.050000 x	.523400 =	.549570
113		.025500 x	23.479183 =	.598719
		-----		
			T.E =	1.148289
6314	6314			
233.2		1.050000 x	.523400 =	.549570
113		.068000 x	23.479183 =	1.596584
		-----		
			T.E =	2.146154
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	23.479183 =	.019957
		-----		
			T.E =	1.419957

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	23.479183 =	.019957
			T.E =	.789957
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	23.479183 =	.019957
			T.E =	1.699957
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	23.479183 =	.019957
			T.E =	.999957
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	23.479183 =	.019957
			T.E =	1.199957
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	23.479183 =	.019957
			T.E =	1.599957
6321	6321			
221		140.000000 x	.097700 =	13.678000
111		.765000 x	15.951934 =	12.203230
113		.595000 x	23.479183 =	13.970114
509		.003302 x	387.062113 =	1.278079
509		.003019 x	387.062113 =	1.168541
T 630.1		.175000 x	1.923358 =	.336588
T 630		.175000 x	1.639534 =	.286918
T 625		.350000 x	21.675697 =	7.586494
T 623		.560000 x	18.541816 =	10.383417
T 621		.300000 x	17.450627 =	5.235188
511		.023800 x	716.401976 =	17.050367
509		.005284 x	387.062113 =	2.045236
112		.714000 x	17.729980 =	12.659206
			T.E =	97.881377

6322	6322			
221		140.000000 x	.097700 =	13.678000
509		.003019 x	387.062113 =	1.168541
T 623		.560000 x	18.541816 =	10.383417
T 630.1		.175000 x	1.923358 =	.336588
T 630		.175000 x	1.639534 =	.286918
T 625		.350000 x	21.675697 =	7.586494
511		.023800 x	716.401976 =	17.050367
T 611		.300000 x	20.338716 =	6.101615
509		.003302 x	387.062113 =	1.278079
509		.005284 x	387.062113 =	2.045236
113		.595000 x	23.479183 =	13.970114
111		.765000 x	15.951934 =	12.203230
112		.714000 x	17.729980 =	12.659206
-----				
			T.E =	98.747804
6323	6323			
221		150.000000 x	.097700 =	14.655000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
113		.850000 x	23.479183 =	19.957306
112		1.020000 x	17.729980 =	18.084580
-----				
			T.E =	108.364281
6323.1	6323.1			
221		150.000000 x	.097700 =	14.655000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		1.020000 x	17.729980 =	18.084580
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		.850000 x	23.479183 =	19.957306
-----				
			T.E =	100.572758



6324	6324			
221		200.000000 x	.097700 =	19.540000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
112		1.020000 x	17.729980 =	18.084580
509		.004718 x	387.062113 =	1.826159
113		.850000 x	23.479183 =	19.957306
509		.007548 x	387.062113 =	2.921545

-----  
T.E = 113.249281

6324.1	6324.1			
221		200.000000 x	.097700 =	19.540000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		1.020000 x	17.729980 =	18.084580
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		.850000 x	23.479183 =	19.957306

-----  
T.E = 105.457758

6325	6325			
221		250.000000 x	.097700 =	24.425000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
113		.850000 x	23.479183 =	19.957306
112		1.020000 x	17.729980 =	18.084580

-----  
T.E = 118.134281

6325.1	6325.1			
221		250.000000 x	.097700 =	24.425000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		1.020000 x	17.729980 =	18.084580
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		.850000 x	23.479183 =	19.957306

-----  
T.E = 110.342758

6326	6326			
221		300.000000 x	.097700 =	29.310000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
113		1.360000 x	23.479183 =	31.931689
112		1.190000 x	17.729980 =	21.098676

-----  
T.E = 138.007760

6326.1	6326.1			
221		300.000000 x	.097700 =	29.310000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		1.190000 x	17.729980 =	21.098676
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		1.360000 x	23.479183 =	31.931689

-----  
T.E = 130.216238

6327	6327			
222		300.000000 x	.114100 =	34.230000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
113		1.275000 x	23.479183 =	29.935958
112		2.295000 x	17.729980 =	40.690304
-----				

T.E = 160.523658

6327.1	6327.1			
222		300.000000 x	.114100 =	34.230000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		1.275000 x	23.479183 =	29.935958
-----				

T.E = 152.732135

6328	6328			
221		350.000000 x	.097700 =	34.195000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	387.062113 =	2.921545
113		1.445000 x	23.479183 =	33.927419
509		.004718 x	387.062113 =	1.826159
-----				

T.E = 164.480119

6328.1	6328.1			
221		350.000000 x	.097700 =	34.195000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	387.062113 =	2.921545
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
113		1.445000 x	23.479183 =	33.927419

-----  
T.E = 156.688596

6329	6329			
222		350.000000 x	.114100 =	39.935000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159
113		1.445000 x	23.479183 =	33.927419
112		2.295000 x	17.729980 =	40.690304

-----  
T.E = 170.220119

6329.1	6329.1			
222		350.000000 x	.114100 =	39.935000
112		2.295000 x	17.729980 =	40.690304
113		1.445000 x	23.479183 =	33.927419
509		.007548 x	387.062113 =	2.921545
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159

-----  
T.E = 162.428596

6329.2	6329.2			
223		350.000000 x	.117200 =	41.020000
112		2.295000 x	17.729980 =	40.690304
T 625		.500000 x	21.675697 =	10.837849
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
113		1.445000 x	23.479183 =	33.927419
511		.034000 x	716.401976 =	24.357667
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159

-----  
T.E = 171.305119

6329.3	6329.3			
223		350.000000 x	.117200 =	41.020000
112		2.295000 x	17.729980 =	40.690304
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
511		.034000 x	716.401976 =	24.357667
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159
113		1.445000 x	23.479183 =	33.927419

-----  
T.E = 163.513596

6330	6330			
223		420.000000 x	.117200 =	49.224000
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159
113		1.445000 x	23.479183 =	33.927419
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.042500 x	716.401976 =	30.447084

-----  
T.E = 185.598536

6330.1	6330.1			
223		420.000000 x	.117200 =	49.224000
113		1.445000 x	23.479183 =	33.927419
509		.004718 x	387.062113 =	1.826159
112		2.295000 x	17.729980 =	40.690304
509		.007548 x	387.062113 =	2.921545
511		.042500 x	716.401976 =	30.447084
T 617		.500000 x	6.092652 =	3.046326
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453

-----  
T.E = 177.807013

6331	6331			
222		450.000000 x	.114100 =	51.345000
113		5.525000 x	23.479183 =	129.722486
111		3.825000 x	15.951934 =	61.016148
T 623		.800000 x	18.541816 =	14.833453
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
509		.004718 x	387.062113 =	1.826159
511		.042500 x	716.401976 =	30.447084
509		.007548 x	387.062113 =	2.921545
112		3.400000 x	17.729980 =	60.281932

-----  
T.E = 364.122378

6331.1	6331.1			
222		450.000000 x	.114100 =	51.345000
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
511		.042500 x	716.401976 =	30.447084
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159
113		5.525000 x	23.479183 =	129.722486
112		3.400000 x	17.729980 =	60.281932
111		3.825000 x	15.951934 =	61.016148

-----  
T.E = 356.330855

6351	6351			
221		120.000000 x	.097700 =	11.724000
509		.004246 x	387.062113 =	1.643466
509		.008020 x	387.062113 =	3.104238
6301		1.000000 x	6.795425 =	6.795425
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.450000 x	21.675697 =	9.754064
T 623		.850000 x	18.541816 =	15.760544
511		.034000 x	716.401976 =	24.357667
113		1.275000 x	23.479183 =	29.935958
112		1.275000 x	17.729980 =	22.605725

-----  
T.E = 126.571809

6351.1	6351.1			
221		120.000000 x	.097700 =	11.724000
509		.004246 x	387.062113 =	1.643466
6301		1.000000 x	6.795425 =	6.795425
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.850000 x	18.541816 =	15.760544
T 617		.450000 x	6.092652 =	2.741693
511		.034000 x	716.401976 =	24.357667
509		.008020 x	387.062113 =	3.104238
112		1.275000 x	17.729980 =	22.605725
113		1.275000 x	23.479183 =	29.935958

-----  
T.E = 119.559439

6352	6352			
221		300.000000 x	.097700 =	29.310000
112		2.125000 x	17.729980 =	37.676208
6301		1.000000 x	6.795425 =	6.795425
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 625		.500000 x	21.675697 =	10.837849
T 623		.800000 x	18.541816 =	14.833453
511		.034000 x	716.401976 =	24.357667
509		.004718 x	387.062113 =	1.826159
509		.007548 x	387.062113 =	2.921545
113		2.550000 x	23.479183 =	59.871917

-----  
T.E = 189.320945

6352.1	6352.1			
221		300.000000 x	.097700 =	29.310000
113		2.550000 x	23.479183 =	59.871917
112		2.125000 x	17.729980 =	37.676208
511		.034000 x	716.401976 =	24.357667
6301		1.000000 x	6.795425 =	6.795425
T 630.1		.250000 x	1.923358 =	.480840
T 630		.250000 x	1.639534 =	.409884
T 623		.800000 x	18.541816 =	14.833453
T 617		.500000 x	6.092652 =	3.046326
509		.007548 x	387.062113 =	2.921545
509		.004718 x	387.062113 =	1.826159
			T.E =	181.529422
6360.1	6360.1			
6360.1 A1		1.000000 x	118.565874 =	118.565874
6360.1 A2		1.000000 x	8.368227 =	8.368227
6360.1 A5		1.000000 x	110.599656 =	110.599656
6360.1 A4		1.000000 x	33.665723 =	33.665723
6360.1 A3		1.000000 x	15.110115 =	15.110115
			AΘΡΟΙΣΜΑ =	286.309595
	T.E =	.200000 x	286.309595 =	57.261919
6360.2	6360.2			
6360.2 A1		1.000000 x	127.475591 =	127.475591
6360.2 A2		1.000000 x	11.654206 =	11.654206
6360.2 A3		1.000000 x	19.663041 =	19.663041
6360.2 A4		1.000000 x	37.074126 =	37.074126
6360.2 A5		1.000000 x	124.705756 =	124.705756
			AΘΡΟΙΣΜΑ =	320.572720
	T.E =	.200000 x	320.572720 =	64.114544
6360.3	6360.3			
6360.3 A1		1.000000 x	168.958484 =	168.958484
6360.3 A2		1.000000 x	16.505163 =	16.505163
6360.3 A3		1.000000 x	44.159685 =	44.159685
6360.3 A5		1.000000 x	169.080055 =	169.080055
6360.3 A4		1.000000 x	44.404846 =	44.404846
			AΘΡΟΙΣΜΑ =	443.108233
	T.E =	.200000 x	443.108233 =	88.621647



6360.4	6360.4			
6360.4 A1		1.000000 x	221.254533 =	221.254533
6360.4 A2		1.000000 x	22.324021 =	22.324021
6360.4 A3		1.000000 x	66.075930 =	66.075930
6360.4 A5		1.000000 x	228.360008 =	228.360008
6360.4 A4		1.000000 x	37.074126 =	37.074126
			-----	
			ΑΘΡΟΙΣΜΑ =	575.088618
	T.E =	.200000 x	575.088618 =	115.017724
			-----	
6360.5	6360.5			
6360.5 A1		1.000000 x	253.404145 =	253.404145
6360.5 A2		1.000000 x	27.832271 =	27.832271
6360.5 A3		1.000000 x	73.379609 =	73.379609
6360.5 A5		1.000000 x	312.474810 =	312.474810
6360.5 A4		1.000000 x	38.454884 =	38.454884
			-----	
			ΑΘΡΟΙΣΜΑ =	705.545719
	T.E =	.200000 x	705.545719 =	141.109144
			-----	
6360.6	6360.6			
6360.6 A1		1.000000 x	307.824733 =	307.824733
6360.6 A2		1.000000 x	41.753120 =	41.753120
6360.6 A4		1.000000 x	37.074126 =	37.074126
6360.6 A3		1.000000 x	86.176153 =	86.176153
6360.6 A5		1.000000 x	412.001614 =	412.001614
			-----	
			ΑΘΡΟΙΣΜΑ =	884.829746
	T.E =	.200000 x	884.829746 =	176.965949
			-----	
6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	23.479183 =	.399146
111		.085000 x	15.951934 =	1.355914
			-----	
			T.E =	2.135061
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	23.479183 =	7.982922
111		.340000 x	15.951934 =	5.423658
396.14		.003000 x	48.900000 =	.146700
			-----	
			T.E =	18.064280
6371	6371			
326		.500000 x	1.310000 =	.655000
111		.212500 x	15.951934 =	3.389786
113		.212500 x	23.479183 =	4.989326
			-----	
			T.E =	9.034112

6372	6372			
396.11		1.050000 x	2.560000 =	2.688000
396.13		.700000 x	1.770000 =	1.239000
113		.340000 x	23.479183 =	7.982922
111		.340000 x	15.951934 =	5.423658
-----				
			T.E =	17.333580
6373	6373			
396.12		1.050000 x	3.680000 =	3.864000
396.13		.700000 x	1.770000 =	1.239000
113		.425000 x	23.479183 =	9.978653
111		.425000 x	15.951934 =	6.779572
-----				
			T.E =	21.861225
6401	6401			
327		.500000 x	.540000 =	.270000
113		.212500 x	23.479183 =	4.989326
-----				
			T.E =	5.259326
6402	6402			
252		.000500 x	210.000000 =	.105000
652.2		.005500 x	167.653269 =	.922093
111		.595000 x	15.951934 =	9.491401
113		.595000 x	23.479183 =	13.970114
652		.011500 x	148.310006 =	1.705565
-----				
			T.E =	26.194173
6403	6403			
251		.000500 x	290.000000 =	.145000
111		.850000 x	15.951934 =	13.559144
652.2		.005500 x	167.653269 =	.922093
652		.016500 x	148.310006 =	2.447115
113		.850000 x	23.479183 =	19.957306
-----				
			T.E =	37.030658
6404	6404			
111		1.275000 x	15.951934 =	20.338716
652		.020000 x	148.310006 =	2.966200
113		1.700000 x	23.479183 =	39.914611
-----				
			T.E =	63.219527
6404.1	6404.1			
397.8		54.000000 x	.000000 =	.000000
6404		1.000000 x	63.219527 =	63.219527
-----				
			T.E =	

6405	6405				
111		.425000 x	15.951934 =	6.779572	
652		.020000 x	148.310006 =	2.966200	
113		.850000 x	23.479183 =	19.957306	
-----					
			T.E =	29.703078	
6451.1	6451.1				
386.1		1.000000 x	.000000 =	.000000	
386.1		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.10	6451.10				
386.10		1.000000 x	.000000 =	.000000	
386.10		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.11	6451.11				
386.11		1.000000 x	.000000 =	.000000	
386.11		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.12	6451.12				
386.12		1.000000 x	.000000 =	.000000	
386.12		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.13	6451.13				
386.13		1.000000 x	.000000 =	.000000	
386.13		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.14	6451.14				
386.14		1.000000 x	.000000 =	.000000	
386.14		.150000 x	.000000 =	.000000	
-----					
			T.E =		
6451.15	6451.15				
386.15		1.000000 x	.000000 =	.000000	
386.15		.150000 x	.000000 =	.000000	
-----					
			T.E =		

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000
-----				
			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000
-----				
			T.E =	
6451.9	6451.9			
386.9		1.000000 x	20,575.000000 =	20,575.000000
386.9		.150000 x	20,575.000000 =	3,086.250000
-----				
			T.E =	23,661.250000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000
-----				
			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000
-----				
			T.E =	

6452.19	6452.19			
386.40		1.000000 x	61,603.000000 =	61,603.000000
386.40		.150000 x	61,603.000000 =	9,240.450000
				-----
			T.E =	70,843.450000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000
				-----
			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000
				-----
			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000
-----				
			T.E =	
6452.9	6452.9			
386.30		1.000000 x	90,675.000000 =	90,675.000000
386.30		.150000 x	90,675.000000 =	13,601.250000
-----				
			T.E =	104,276.250000



6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000
-----				
			T.E =	

6453.17	6453.17			
386.64		1.000000 x	123,215.000000 =	123,215.000000
386.64		.150000 x	123,215.000000 =	18,482.250000
-----				
			T.E =	141,697.250000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000
-----				
			T.E =	

6453.6	6453.6			
386.53		1.000000 x	107,490.000000 =	107,490.000000
386.53		.150000 x	107,490.000000 =	16,123.500000
-----				
			T.E =	123,613.500000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000
-----				
			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000
-----				
			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000
-----				
			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000
-----				
			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000
-----				
			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000
-----				
			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000
-----				
			T.E =	
6455.3	6455.3			
387.3		1.000000 x	17,260.000000 =	17,260.000000
387.3		.100000 x	17,260.000000 =	1,726.000000
-----				
			T.E =	18,986.000000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000
-----				
			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000
-----				
T.E =				
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000
-----				
T.E =				
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000
-----				
T.E =				
6456.1	6456.1			
234.2		208.000000 x	.666500 =	138.632000
113		154.700001 x	23.479183 =	3,632.229634
235		338.000000 x	.553000 =	186.914000
-----				
ΑΘΡΟΙΣΜΑ =				3,957.775634
-----				
T.E = 5,936.663450				
6456.2	6456.2			
234.2		336.000000 x	.666500 =	223.944000
113		249.900000 x	23.479183 =	5,867.447832
235		546.000000 x	.553000 =	301.938000
-----				
ΑΘΡΟΙΣΜΑ =				6,393.329832
-----				
T.E = 8,950.661764				
6456.3	6456.3			
234.2		384.000000 x	.666500 =	255.936000
235		624.000000 x	.553000 =	345.072000
113		285.599998 x	23.479183 =	6,705.654618
-----				
ΑΘΡΟΙΣΜΑ =				7,306.662618
-----				
T.E = 10,229.327665				
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	23.479183 =	399.146111
-----				
T.E =				

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000
-----				
			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000
-----				
			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000
-----				
			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.4	6459.4			
389.4		1.000000 x	5,345.000000 =	5,345.000000
389.4		.200000 x	5,345.000000 =	1,069.000000
-----				
			T.E =	6,414.000000



6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000
-----				
			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000
-----				
			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.14	6470.14			
390.14		1.000000 x	4,516.000000 =	4,516.000000
390.14		.150000 x	4,516.000000 =	677.400000
-----				
			T.E =	5,193.400000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.31	6470.31			
390.31		1.000000 x	6,566.000000 =	6,566.000000
390.31		.150000 x	6,566.000000 =	984.900000
-----				
			T.E =	7,550.900000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000
		-----		
			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000
		-----		
			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000
-----				
			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000
-----				
			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000
-----				
			T.E =	



6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000
-----				
			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000
-----				
			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000
-----				
			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000
-----				
			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000
-----				
			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000
-----				
T.E =				
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000
-----				
T.E =				

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000
-----				
			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000
-----				
			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000
-----				
			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000
-----				
			T.E =	



6473.1	6473.1			
393.1		1.000000 x	12,320.000000 =	12,320.000000
393.1		.150000 x	12,320.000000 =	1,848.000000
				-----
			T.E =	14,168.000000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000
				-----
			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000
				-----
			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000
				-----
			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000
				-----
			T.E =	6.320000
6501	6501			
237		1.000000 x	1.060000 =	1.060000
113		.850000 x	23.479183 =	19.957306
				-----
			T.E =	21.017306
6502	6502			
112		.170000 x	17.729980 =	3.014097
517		.042500 x	2,091.682637 =	88.896512
				-----
			T.E =	91.910609
6505	6505			
233		1.050000 x	.492800 =	.517440
113		.042500 x	23.479183 =	.997865
				-----
			T.E =	1.515305

6506	6506			
233.1		1.050000 x	.492800 =	.517440
113		.042500 x	23.479183 =	.997865
		-----		
			T.E =	1.515305
6551.1	6551.1			
221		6.000000 x	.097700 =	.586200
113		.255000 x	23.479183 =	5.987192
111		.255000 x	15.951934 =	4.067743
261		1.000000 x	14.500000 =	14.500000
		-----		
			T.E =	25.141135
6551.2	6551.2			
221		8.000000 x	.097700 =	.781600
262		1.000000 x	25.300000 =	25.300000
111		.297500 x	15.951934 =	4.745700
113		.297500 x	23.479183 =	6.985057
		-----		
			T.E =	37.812357
6551.3	6551.3			
221		10.000000 x	.097700 =	.977000
263		1.000000 x	31.200000 =	31.200000
113		.340000 x	23.479183 =	7.982922
111		.340000 x	15.951934 =	5.423658
		-----		
			T.E =	45.583580
6551.4	6551.4			
221		13.000000 x	.097700 =	1.270100
263.2		1.000000 x	44.900000 =	44.900000
113		.510000 x	23.479183 =	11.974383
111		.510000 x	15.951934 =	8.135486
		-----		
			T.E =	66.279970
6551.5	6551.5			
221		16.000000 x	.097700 =	1.563200
113		.595000 x	23.479183 =	13.970114
111		.595000 x	15.951934 =	9.491401
264		1.000000 x	61.600000 =	61.600000
		-----		
			T.E =	86.624715

6551.6	6551.6			
221		20.000000 x	.097700 =	1.954000
265		1.000000 x	110.700000 =	110.700000
111		.850000 x	15.951934 =	13.559144
113		.850000 x	23.479183 =	19.957306
		-----		
			T.E =	146.170449
6551.7	6551.7			
221		26.000000 x	.097700 =	2.540200
271		1.000000 x	198.400000 =	198.400000
113		1.275000 x	23.479183 =	29.935958
111		1.275000 x	15.951934 =	20.338716
		-----		
			T.E =	251.214874
6552	6552			
221		26.000000 x	.097700 =	2.540200
6304		6.890000 x	6.021472 =	41.487942
6310		32.020000 x	1.515305 =	48.520066
6329.2		.418000 x	171.305119 =	71.605540
111		1.700000 x	15.951934 =	27.118288
113		1.275000 x	23.479183 =	29.935958
		-----		
			T.E =	221.207994
6553	6553			
113		.850000 x	23.479183 =	19.957306
6314		13.730000 x	2.146154 =	29.466694
6329.2		.478000 x	171.305119 =	81.883847
6304		9.290000 x	6.021472 =	55.939475
		-----		
			T.E =	187.247322
6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	23.479183 =	4.689967
112		.276250 x	17.729980 =	4.897907
111		.067150 x	15.951934 =	1.071172
		-----		
			T.E =	
6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.729980 =	54.344162
113		.901000 x	23.479183 =	21.154744
111		1.351500 x	15.951934 =	21.559039
		-----		
			T.E =	

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	23.479183 =	23.489749
112		3.858150 x	17.729980 =	68.404922
111		1.669400 x	15.951934 =	26.630159
-----				
			T.E =	
6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	23.479183 =	28.219630
112		5.523300 x	17.729980 =	97.927999
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
-----				
			T.E =	
6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.951934 =	52.189145
113		1.401650 x	23.479183 =	32.909597
112		6.712450 x	17.729980 =	119.011604
363.13		.224000 x	.000000 =	.000000
-----				
			T.E =	
6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.729980 =	155.014988
113		1.602250 x	23.479183 =	37.619521
111		4.272950 x	15.951934 =	68.161816
363.14		.224000 x	.000000 =	.000000
-----				
			T.E =	
6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	23.479183 =	5.867448
112		.379950 x	17.729980 =	6.736506
111		.104550 x	15.951934 =	1.667775
363.2		.224000 x	.000000 =	.000000
-----				
			T.E =	

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968
113		.300050 x	23.479183 =	7.044929
112		.488750 x	17.729980 =	8.665528

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	23.479183 =	9.399891
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.729980 =	13.563435
111		.266900 x	15.951934 =	4.257571

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.729980 =	18.024298
113		.500650 x	23.479183 =	11.754853
111		.417350 x	15.951934 =	6.657540

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	23.479183 =	14.089858
112		1.484950 x	17.729980 =	26.328134
111		.600950 x	15.951934 =	9.586315
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.951934 =	13.043896
113		.700400 x	23.479183 =	16.444820
112		1.926100 x	17.729980 =	34.149714

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.729980 =	43.176934
111		1.068450 x	15.951934 =	17.043844
-----				
			T.E =	
6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.729980 =	5.470585
113		.266900 x	23.479183 =	6.266594
111		.067150 x	15.951934 =	1.071172
-----				
			T.E =	
6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	23.479183 =	28.199673
112		4.232150 x	17.729980 =	75.035935
111		1.351500 x	15.951934 =	21.559039
365.10		.224000 x	.000000 =	.000000
-----				
			T.E =	
6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	23.479183 =	31.332970
112		5.156950 x	17.729980 =	91.432620
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.951934 =	26.630159
-----				
			T.E =	
6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		1.602250 x	23.479183 =	37.619521
112		7.410300 x	17.729980 =	131.384471
365.12		.224000 x	.000000 =	.000000
-----				
			T.E =	

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.729980 =	161.450084
113		1.869150 x	23.479183 =	43.886115
111		3.271650 x	15.951934 =	52.189145
-----				
			T.E =	
6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	23.479183 =	50.152709
112		11.979050 x	17.729980 =	212.388317
111		4.272950 x	15.951934 =	68.161816
-----				
			T.E =	
6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	23.479183 =	7.823264
112		.452200 x	17.729980 =	8.017497
111		.104550 x	15.951934 =	1.667775
365.2		.224000 x	.000000 =	.000000
-----				
			T.E =	
6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968
113		.400350 x	23.479183 =	9.399891
112		.612850 x	17.729980 =	10.865818
-----				
			T.E =	
6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	23.479183 =	12.533188
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.729980 =	18.657258
111		.266900 x	15.951934 =	4.257571
-----				
			T.E =	

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.729980 =	24.414182
113		.667250 x	23.479183 =	15.666485
111		.417350 x	15.951934 =	6.657540
-----				
			T.E =	
6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
112		1.989000 x	17.729980 =	35.264930
111		.600950 x	15.951934 =	9.586315
365.7		.224000 x	.000000 =	.000000
-----				
			T.E =	
6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.951934 =	13.043896
113		.934150 x	23.479183 =	21.933079
112		2.718300 x	17.729980 =	48.195405
-----				
			T.E =	
6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	23.479183 =	25.066376
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.729980 =	61.050598
111		1.068450 x	15.951934 =	17.043844
-----				
			T.E =	
6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.729980 =	7.068057
113		.333200 x	23.479183 =	7.823264
111		.067150 x	15.951934 =	1.071172
-----				
			T.E =	



6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	23.479183 =	35.244602
112		5.308250 x	17.729980 =	94.115166
111		1.351500 x	15.951934 =	21.559039
367.10		.224000 x	.000000 =	.000000
-----				
			T.E =	
6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	23.479183 =	39.156233
112		6.644450 x	17.729980 =	117.805966
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.951934 =	26.630159
-----				
			T.E =	
6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		2.002600 x	23.479183 =	47.019412
112		9.562500 x	17.729980 =	169.542934
367.12		.224000 x	.000000 =	.000000
-----				
			T.E =	
6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.729980 =	205.486036
113		2.336650 x	23.479183 =	54.862633
111		3.271650 x	15.951934 =	52.189145
-----				
			T.E =	
6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	23.479183 =	62.685897
112		14.965950 x	17.729980 =	265.345994
111		4.272950 x	15.951934 =	68.161816
-----				
			T.E =	

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	23.479183 =	9.779080
112		.523600 x	17.729980 =	9.283418
111		.104550 x	15.951934 =	1.667775
367.2		.224000 x	.000000 =	.000000
-----				
			T.E =	
6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	23.479183 =	11.754853
112		.748000 x	17.729980 =	13.262025
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.951934 =	2.399968
-----				
			T.E =	
6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.951934 =	4.257571
113		.667250 x	23.479183 =	15.666485
112		1.269050 x	17.729980 =	22.500231
367.5		.224000 x	.000000 =	.000000
-----				
			T.E =	
6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.729980 =	32.054917
113		.833850 x	23.479183 =	19.578117
111		.417350 x	15.951934 =	6.657540
-----				
			T.E =	
6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	23.479183 =	23.489749
112		2.597600 x	17.729980 =	46.055396
111		.600950 x	15.951934 =	9.586315
-----				
			T.E =	

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	23.479183 =	27.421338
112		3.439100 x	17.729980 =	60.975174
111		.817700 x	15.951934 =	13.043896
367.8		.224000 x	.000000 =	.000000
-----				
			T.E =	
6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.951934 =	17.043844
113		1.334500 x	23.479183 =	31.332970
112		4.386850 x	17.729980 =	77.778763
-----				
			T.E =	
6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	23.479183 =	9.399891
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.729980 =	8.951867
111		.067150 x	15.951934 =	1.071172
-----				
			T.E =	
6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.729980 =	116.072860
113		1.802000 x	23.479183 =	42.309488
111		1.351500 x	15.951934 =	21.559039
-----				
			T.E =	
6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	23.479183 =	46.999455
112		8.181250 x	17.729980 =	145.053399
111		1.669400 x	15.951934 =	26.630159
367.25		.224000 x	.000000 =	.000000
-----				
			T.E =	

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.951934 =	38.331700
113		2.403800 x	23.479183 =	56.439260
112		11.789500 x	17.729980 =	209.027599

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	23.479183 =	65.839151
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.729980 =	254.615810
111		3.271650 x	15.951934 =	52.189145

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.729980 =	331.867106
113		3.204500 x	23.479183 =	75.239042
111		4.272950 x	15.951934 =	68.161816

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	23.479183 =	11.734896
112		.647700 x	17.729980 =	11.483708
111		.104550 x	15.951934 =	1.667775
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.729980 =	16.547390
113		.600950 x	23.479183 =	14.109815
111		.150450 x	15.951934 =	2.399968

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	23.479183 =	18.799782
112		1.592900 x	17.729980 =	28.242085
111		.266900 x	15.951934 =	4.257571
-----				
			T.E =	
6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	23.479183 =	23.509706
112		2.094400 x	17.729980 =	37.133670
111		.417350 x	15.951934 =	6.657540
-----				
			T.E =	
6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	23.479183 =	28.199673
112		2.952900 x	17.729980 =	52.354858
111		.600950 x	15.951934 =	9.586315
367.21		.224000 x	.000000 =	.000000
-----				
			T.E =	
6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.729980 =	70.560001
113		1.401650 x	23.479183 =	32.909597
111		.817700 x	15.951934 =	13.043896
367.22		.224000 x	.000000 =	.000000
-----				
			T.E =	
6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.951934 =	17.043844
113		1.601400 x	23.479183 =	37.599564
112		5.210500 x	17.729980 =	92.382061
367.23		.224000 x	.000000 =	.000000
-----				
			T.E =	

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
113		.025500 x	23.479183 =	.598719
112		.042500 x	17.729980 =	.753524
111		.042500 x	15.951934 =	.677957
-----				
			T.E =	
6611.1	6611.1			
361.1		1.000000 x	11.750000 =	11.750000
113		.212500 x	23.479183 =	4.989326
112		.510000 x	17.729980 =	9.042290
111		.085000 x	15.951934 =	1.355914
-----				
			T.E =	27.137531
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.951934 =	8.135486
112		2.125000 x	17.729980 =	37.676208
113		.765000 x	23.479183 =	17.961575
-----				
			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.951934 =	10.169358
113		.935000 x	23.479183 =	21.953036
112		2.550000 x	17.729980 =	45.211449
-----				
			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.951934 =	12.203230
113		1.105000 x	23.479183 =	25.944497
112		2.975000 x	17.729980 =	52.746691
-----				
			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	23.479183 =	29.935958
112		3.400000 x	17.729980 =	60.281932
111		.892500 x	15.951934 =	14.237101
-----				
			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.951934 =	16.270973
112		3.825000 x	17.729980 =	67.817174
113		1.445000 x	23.479183 =	33.927419
			-----	
			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.300000 =	15.300000
111		.085000 x	15.951934 =	1.355914
113		.212500 x	23.479183 =	4.989326
112		.552500 x	17.729980 =	9.795814
			-----	
			T.E =	31.441055
6611.3	6611.3			
361.3		1.000000 x	19.280000 =	19.280000
111		.127500 x	15.951934 =	2.033872
113		.255000 x	23.479183 =	5.987192
112		.637500 x	17.729980 =	11.302862
			-----	
			T.E =	38.603926
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	23.479183 =	6.985057
112		.680000 x	17.729980 =	12.056386
111		.170000 x	15.951934 =	2.711829
			-----	
			T.E =	
6611.5	6611.5			
361.5		1.000000 x	36.800000 =	36.800000
111		.212500 x	15.951934 =	3.389786
112		.935000 x	17.729980 =	16.577531
113		.382500 x	23.479183 =	8.980787
			-----	
			T.E =	65.748105
6611.6	6611.6			
361.6		1.000000 x	49.220000 =	49.220000
111		.255000 x	15.951934 =	4.067743
113		.425000 x	23.479183 =	9.978653
112		1.105000 x	17.729980 =	19.591628
			-----	
			T.E =	82.858024

6611.7	6611.7			
361.7		1.000000 x	76.000000 =	76.000000
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		1.275000 x	17.729980 =	22.605725
			-----	
			T.E =	116.003765
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979
112		1.700000 x	17.729980 =	30.140966
111		.382500 x	15.951934 =	6.101615
			-----	
			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.951934 =	6.779572
112		1.870000 x	17.729980 =	33.155063
113		.680000 x	23.479183 =	15.965844
			-----	
			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.951934 =	1.288119
113		.176800 x	23.479183 =	4.151120
112		.055250 x	17.729980 =	.979581
			-----	
			T.E =	11.600420
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.951934 =	2.088108
113		.224400 x	23.479183 =	5.268729
112		.089250 x	17.729980 =	1.582401
			-----	
			T.E =	17.150238
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	23.479183 =	6.027106
112		.116450 x	17.729980 =	2.064656
111		.170850 x	15.951934 =	2.725388
			-----	
			T.E =	21.486350



6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.951934 =	4.257571
112		.182750 x	17.729980 =	3.240154
113		.320450 x	23.479183 =	7.523904
				-----
			T.E =	31.606829
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.951934 =	5.396539
113		.360400 x	23.479183 =	8.461898
112		.228650 x	17.729980 =	4.053960
				-----
			T.E =	38.903997
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.951934 =	8.352433
113		.448800 x	23.479183 =	10.537457
112		.353600 x	17.729980 =	6.269321
				-----
			T.E =	58.146011
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	23.479183 =	11.854639
112		.445400 x	17.729980 =	7.896933
111		.662150 x	15.951934 =	10.562573
				-----
			T.E =	72.756346
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.951934 =	13.423552
112		.567800 x	17.729980 =	10.067083
113		.568650 x	23.479183 =	13.351437
				-----
			T.E =	90.789873
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.951934 =	17.043844
113		.640900 x	23.479183 =	15.047808
112		.717400 x	17.729980 =	12.719488
				-----
			T.E =	112.508540

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
111		.080750 x	15.951934 =	1.288119
113		.205700 x	23.479183 =	4.829668
112		.088400 x	17.729980 =	1.567330
				-----
			T.E =	15.845117
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	23.479183 =	6.146850
112		.141100 x	17.729980 =	2.501700
111		.130900 x	15.951934 =	2.088108
				-----
			T.E =	23.568258
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.951934 =	2.725388
112		.185300 x	17.729980 =	3.285365
113		.299200 x	23.479183 =	7.024972
				-----
			T.E =	29.865725
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.951934 =	4.257571
113		.374000 x	23.479183 =	8.781214
112		.289000 x	17.729980 =	5.123964
				-----
			T.E =	44.223750
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.951934 =	5.396539
113		.420750 x	23.479183 =	9.878866
112		.367200 x	17.729980 =	6.510449
				-----
			T.E =	54.844054
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	23.479183 =	12.293700
112		.564400 x	17.729980 =	10.006801
111		.523600 x	15.951934 =	8.352433
				-----
			T.E =	82.897334

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.951934 =	10.562573
112		.710600 x	17.729980 =	12.598924
113		.589050 x	23.479183 =	13.830413
				-----
			T.E =	103.342910
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.951934 =	13.423552
113		.663850 x	23.479183 =	15.586656
112		.901000 x	17.729980 =	15.974712
				-----
			T.E =	129.349120
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.951934 =	17.043844
113		.748000 x	23.479183 =	17.562429
112		1.145800 x	17.729980 =	20.315011
				-----
			T.E =	161.715284
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	23.479183 =	5.528174
112		.131750 x	17.729980 =	2.335925
111		.080750 x	15.951934 =	1.288119
				-----
			T.E =	21.290217
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.951934 =	2.088108
112		.212500 x	17.729980 =	3.767621
113		.299200 x	23.479183 =	7.024972
				-----
			T.E =	32.036300
6622.3	6622.3			
373.3		1.020000 x	24.500000 =	24.990000
111		.170850 x	15.951934 =	2.725388
113		.341700 x	23.479183 =	8.022837
112		.277950 x	17.729980 =	4.928048
				-----
			T.E =	40.666273

6623	6623			
360.2		1.000000 x	2.120000 =	2.120000
113		.085000 x	23.479183 =	1.995731
111		.042500 x	15.951934 =	.677957
113		.025500 x	23.479183 =	.598719
112		.042500 x	17.729980 =	.753524
-----				
			T.E =	6.145931
6630.1	6630.1			
376.12		1.000000 x	88.960000 =	88.960000
113		2.550000 x	23.479183 =	59.871917
113		.610300 x	23.479183 =	14.329345
113		1.067600 x	23.479183 =	25.066376
112		2.439500 x	17.729980 =	43.252286
111		.855100 x	15.951934 =	13.640499
-----				
			T.E =	245.120423
6630.10	6630.10			
376.21		1.000000 x	487.600000 =	487.600000
111		7.690800 x	15.951934 =	122.683134
113		3.349000 x	23.479183 =	78.631784
113		3.203650 x	23.479183 =	75.219085
113		2.550000 x	23.479183 =	59.871917
112		13.396000 x	17.729980 =	237.510812
-----				
			T.E =	1,061.516731
6630.11	6630.11			
376.22		1.000000 x	528.600000 =	528.600000
111		9.025300 x	15.951934 =	143.970990
113		3.471400 x	23.479183 =	81.505636
113		3.629500 x	23.479183 =	85.217695
113		2.550000 x	23.479183 =	59.871917
112		14.518000 x	17.729980 =	257.403850
-----				
			T.E =	1,156.570087
6630.2	6630.2			
376.13		1.000000 x	98.960000 =	98.960000
113		2.550000 x	23.479183 =	59.871917
113		1.201050 x	23.479183 =	28.199673
113		.680000 x	23.479183 =	15.965844
111		1.081200 x	15.951934 =	17.247231
112		2.720000 x	17.729980 =	48.225546
-----				
			T.E =	268.470210

6630.3	6630.3			
376.14		1.000000 x	109.782000 =	109.782000
113		1.334500 x	23.479183 =	31.332970
113		2.550000 x	23.479183 =	59.871917
113		.760750 x	23.479183 =	17.861788
112		3.043000 x	17.729980 =	53.952329
111		1.334500 x	15.951934 =	21.287856
		-----		
			T.E =	294.088860
6630.4	6630.4			
376.15		1.000000 x	140.650000 =	140.650000
111		1.922700 x	15.951934 =	30.670784
113		.892500 x	23.479183 =	20.955171
113		1.602250 x	23.479183 =	37.619521
113		2.550000 x	23.479183 =	59.871917
112		3.570000 x	17.729980 =	63.296029
		-----		
			T.E =	353.063421
6630.5	6630.5			
376.16		1.000000 x	176.880000 =	176.880000
111		2.617150 x	15.951934 =	41.748604
113		1.164500 x	23.479183 =	27.341509
113		2.550000 x	23.479183 =	59.871917
113		1.869150 x	23.479183 =	43.886115
112		4.658000 x	17.729980 =	82.586247
		-----		
			T.E =	432.314391
6630.6	6630.6			
376.17		1.000000 x	224.520000 =	224.520000
113		2.550000 x	23.479183 =	59.871917
113		2.136050 x	23.479183 =	50.152709
113		1.470500 x	23.479183 =	34.526139
111		3.418700 x	15.951934 =	54.534877
112		5.882000 x	17.729980 =	104.287742
		-----		
			T.E =	527.893383
6630.7	6630.7			
376.18		1.000000 x	302.640000 =	302.640000
113		2.402950 x	23.479183 =	56.419303
113		2.550000 x	23.479183 =	59.871917
113		2.031500 x	23.479183 =	47.697960
112		8.126000 x	17.729980 =	144.073817
111		4.326500 x	15.951934 =	69.016042
		-----		
			T.E =	679.719040

6630.8	6630.8			
376.19		1.000000 x	336.580000 =	336.580000
111		5.340550 x	15.951934 =	85.192101
113		2.261000 x	23.479183 =	53.086433
113		2.669850 x	23.479183 =	62.685897
113		2.550000 x	23.479183 =	59.871917
112		9.044000 x	17.729980 =	160.349939
		-----		
			T.E =	757.766286
6630.9	6630.9			
376.20		1.000000 x	400.990000 =	400.990000
111		6.461700 x	15.951934 =	103.076612
113		2.737000 x	23.479183 =	64.262524
113		2.550000 x	23.479183 =	59.871917
113		2.936750 x	23.479183 =	68.952491
112		10.948000 x	17.729980 =	194.107821
		-----		
			T.E =	891.261364
6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	23.479183 =	59.871917
113		1.667700 x	23.479183 =	39.156233
111		1.334500 x	15.951934 =	21.287856
112		3.043000 x	17.729980 =	53.952329
		-----		
			T.E =	
6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	23.479183 =	59.871917
113		2.002600 x	23.479183 =	47.019412
112		3.570000 x	17.729980 =	63.296029
111		1.922700 x	15.951934 =	30.670784
		-----		
			T.E =	
6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.951934 =	41.748604
112		4.658000 x	17.729980 =	82.586247
113		2.550000 x	23.479183 =	59.871917
113		2.336650 x	23.479183 =	54.862633
		-----		
			T.E =	

6640.4	6640.4			
377.4		1.000000 x	.000000 =	.000000
111		3.418700 x	15.951934 =	54.534877
112		5.882000 x	17.729980 =	104.287742
113		2.669850 x	23.479183 =	62.685897
113		2.550000 x	23.479183 =	59.871917
-----				
			T.E =	
6640.5	6640.5			
377.5		1.000000 x	.000000 =	.000000
111		4.326500 x	15.951934 =	69.016042
113		3.003900 x	23.479183 =	70.529118
113		2.550000 x	23.479183 =	59.871917
112		8.126000 x	17.729980 =	144.073817
-----				
			T.E =	
6640.6	6640.6			
377.6		1.000000 x	.000000 =	.000000
113		2.550000 x	23.479183 =	59.871917
113		3.337100 x	23.479183 =	78.352382
112		9.044000 x	17.729980 =	160.349939
111		5.340550 x	15.951934 =	85.192101
-----				
			T.E =	
6640.7	6640.7			
377.7		1.000000 x	.000000 =	.000000
111		6.461700 x	15.951934 =	103.076612
112		10.948000 x	17.729980 =	194.107821
113		3.671150 x	23.479183 =	86.195603
113		2.550000 x	23.479183 =	59.871917
-----				
			T.E =	
6640.8	6640.8			
377.8		1.000000 x	.000000 =	.000000
111		7.690800 x	15.951934 =	122.683134
112		13.396000 x	17.729980 =	237.510812
113		2.550000 x	23.479183 =	59.871917
113		4.004350 x	23.479183 =	94.018866
-----				
			T.E =	

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.951934 =	143.970990
113		4.339250 x	23.479183 =	101.882045
113		2.550000 x	23.479183 =	59.871917
112		14.518000 x	17.729980 =	257.403850
		-----		
			T.E =	
6641	6641			
233.3		1.000000 x	7.500000 =	7.500000
		-----		
			T.E =	7.500000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000
		-----		
			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000
		-----		
			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000
		-----		
			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000
		-----		
			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000
		-----		
			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000
		-----		
			T.E =	



6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000
-----				
			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000
-----				
			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000
-----				
			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000
-----				
			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000
-----				
			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000
-----				
			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500
-----				
			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000
-----				
			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000
-----				
T.E =				
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000
-----				
T.E =				
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000
-----				
T.E =				
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500
-----				
T.E = 7,765.222500				
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000
-----				
T.E =				
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000
-----				
T.E =				
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000
-----				
T.E =				
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000
-----				
T.E =				

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000
-----				
			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000
-----				
			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000
-----				
			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000
-----				
			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000
-----				
			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000
-----				
			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000
-----				
			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000
-----				
			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000
-----				
			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000
-----				
			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000
-----				
			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000
-----				
			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000
-----				
			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000
-----				
			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000
-----				
			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000
-----				
			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000
-----				
			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000
-----				
			T.E =	



6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000
-----				
			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000
-----				
			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000
-----				
			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000
-----				
			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000
-----				
			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000
-----				
			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000
-----				
			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000
-----				
			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000
-----				
			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000
-----				
			T.E =	1,161.600000
6661.5	6661.5			
380.5		.100000 x	1,420.000000 =	142.000000
380.5		1.000000 x	1,420.000000 =	1,420.000000
-----				
			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000
-----				
			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
-----				
			AΘΡΟΙΣΜΑ =	537.050000
-----				
			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
-----				
			AΘΡΟΙΣΜΑ =	537.050000
-----				
			T.E =	

6662.3	6662.3			
384.1		1.000000 x	537.050000 =	537.050000
384.7		2.000000 x	.000000 =	.000000
384.9		2.000000 x	.000000 =	.000000
384.8		2.000000 x	.000000 =	.000000
384.5		2.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	537.050000
			-----	
			T.E =	
6662.4	6662.4			
384.1		1.000000 x	537.050000 =	537.050000
384.9		2.000000 x	.000000 =	.000000
384.7		2.000000 x	.000000 =	.000000
384.6		2.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	537.050000
			-----	
			T.E =	
6662.5	6662.5			
384.2		1.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000
384.8		3.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.5		3.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	.000000
			-----	
			T.E =	
6662.6	6662.6			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000
384.6		3.000000 x	.000000 =	.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	.000000
			-----	
			T.E =	

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	.000000
		-----		
			T.E =	
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	.000000
		-----		
			T.E =	
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	.000000
		-----		
			T.E =	
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000
		-----		
			ΑΘΡΟΙΣΜΑ =	.000000
		-----		
			T.E =	
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
369.1		.224000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615
		-----		
			T.E =	

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.951934 =	10.847315
-----				
			T.E =	
6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
369.2		.224000 x	.000000 =	.000000
-----				
			T.E =	
6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.951934 =	6.915163
113		.102000 x	23.479183 =	2.394877
-----				
			T.E =	
6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938
-----				
			T.E =	
6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712
-----				
			T.E =	
6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
369.6		.224000 x	.000000 =	.000000
-----				
			T.E =	

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.951934 =	8.813444
113		.195500 x	23.479183 =	4.590180
-----				
			T.E =	
6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	23.479183 =	5.588046
111		.595000 x	15.951934 =	9.491401
-----				
			T.E =	
6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	23.479183 =	6.785484
111		.637500 x	15.951934 =	10.169358
-----				
			T.E =	
6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615
369.11		.224000 x	.000000 =	.000000
-----				
			T.E =	
6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.951934 =	10.847315
113		.340000 x	23.479183 =	7.982922
-----				
			T.E =	
6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
-----				
			T.E =	

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
-----				
			T.E =	
6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938
369.14		.224000 x	.000000 =	.000000
-----				
			T.E =	
6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.951934 =	7.728712
113		.144500 x	23.479183 =	3.392742
-----				
			T.E =	
6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
-----				
			T.E =	
6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444
-----				
			T.E =	
6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	23.479183 =	5.588046
111		.595000 x	15.951934 =	9.491401
369.18		.224000 x	.000000 =	.000000
-----				
			T.E =	

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	23.479183 =	6.785484
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.951934 =	10.169358
-----				
			T.E =	
6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.951934 =	6.101615
113		.068000 x	23.479183 =	1.596584
369.21		.224000 x	.000000 =	.000000
-----				
			T.E =	
6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922
111		.680000 x	15.951934 =	10.847315
-----				
			T.E =	
6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
-----				
			T.E =	
6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
369.23		.224000 x	.000000 =	.000000
-----				
			T.E =	
6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.951934 =	7.321938
113		.119000 x	23.479183 =	2.794023
-----				
			T.E =	



6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.951934 =	9.491401
113		.238000 x	23.479183 =	5.588046

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	23.479183 =	6.785484
111		.637500 x	15.951934 =	10.169358

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
370.8		1.000000 x	.000000 =	.000000
-----				
T.E =				
6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.951934 =	6.915163
113		.102000 x	23.479183 =	2.394877
-----				
T.E =				
6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938
-----				
T.E =				
6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712
-----				
T.E =				
6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
370.8		1.000000 x	.000000 =	.000000
-----				
T.E =				
6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.951934 =	8.813444
113		.195500 x	23.479183 =	4.590180
-----				
T.E =				

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	23.479183 =	1.596584
111		.382500 x	15.951934 =	6.101615
			T.E =	
6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
			T.E =	
6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
370.16		1.000000 x	.000000 =	.000000
			T.E =	
6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.951934 =	7.321938
113		.119000 x	23.479183 =	2.794023
			T.E =	
6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	23.479183 =	3.392742
111		.484500 x	15.951934 =	7.728712
			T.E =	
6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
			T.E =	

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444
370.16		1.000000 x	.000000 =	.000000
-----				
			T.E =	
6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.951934 =	6.101615
113		.068000 x	23.479183 =	1.596584
-----				
			T.E =	
6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	23.479183 =	1.995731
111		.408000 x	15.951934 =	6.508389
-----				
			T.E =	
6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	23.479183 =	2.394877
111		.433500 x	15.951934 =	6.915163
-----				
			T.E =	
6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	23.479183 =	2.794023
111		.459000 x	15.951934 =	7.321938
370.24		1.000000 x	.000000 =	.000000
-----				
			T.E =	
6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.951934 =	7.728712
113		.144500 x	23.479183 =	3.392742
-----				
			T.E =	

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	23.479183 =	3.991461
111		.518500 x	15.951934 =	8.271078
-----				

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	23.479183 =	4.590180
111		.552500 x	15.951934 =	8.813444
-----				

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	138.007760 =	45.197541
113		.026350 x	23.479183 =	.618676
111		.085000 x	15.951934 =	1.355914
-----				

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.951934 =	1.898280
113		.040800 x	23.479183 =	.957951
6326		.352500 x	138.007760 =	48.647735
-----				

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.951934 =	2.576237
6326		.372500 x	138.007760 =	51.407891
113		.051000 x	23.479183 =	1.197438
-----				

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.951934 =	2.711829
6326		.382500 x	138.007760 =	52.787968
113		.063750 x	23.479183 =	1.496798
-----				

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	138.007760 =	53.995536
113		.068000 x	23.479183 =	1.596584
111		.187000 x	15.951934 =	2.983012
		-----		
			T.E =	
6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.951934 =	3.254195
113		.076500 x	23.479183 =	1.796157
6327		.393750 x	160.523658 =	63.206190
		-----		
			T.E =	
6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.951934 =	4.610109
6327		.431250 x	160.523658 =	69.225828
113		.093500 x	23.479183 =	2.195304
		-----		
			T.E =	
6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
6327		.500000 x	160.523658 =	80.261829
113		.119000 x	23.479183 =	2.794023
		-----		
			T.E =	
6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	24.668880 =	9.127486
113		.017000 x	23.479183 =	.399146
111		.161500 x	15.951934 =	2.576237
		-----		
			T.E =	20.783069
6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.951934 =	2.983012
6069		.390000 x	24.668880 =	9.620863
113		.021250 x	23.479183 =	.498933
		-----		
			T.E =	26.699407

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.951934 =	3.254195
6069		.400000 x	24.668880 =	9.867552
113		.026350 x	23.479183 =	.618676
				-----
			T.E =	34.946223
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.951934 =	3.932152
6069		.420000 x	24.668880 =	10.360930
113		.040800 x	23.479183 =	.957951
				-----
			T.E =	49.574032
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	24.668880 =	10.607618
113		.051000 x	23.479183 =	1.197438
111		.289000 x	15.951934 =	4.610109
				-----
			T.E =	60.071166
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	24.668880 =	10.854307
113		.063750 x	23.479183 =	1.496798
111		.297500 x	15.951934 =	4.745700
				-----
			T.E =	72.411405
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	24.668880 =	12.827818
113		.076500 x	23.479183 =	1.796157
111		.357000 x	15.951934 =	5.694840
				-----
			T.E =	109.987016
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306
				-----
			T.E =	42.339306

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306
			-----	
			T.E =	45.846306
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306
			-----	
			T.E =	51.274806
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	23.479183 =	19.957306
			-----	
			T.E =	58.771806
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	23.479183 =	19.957306
375.13		1.000000 x	10.160000 =	10.160000
			-----	
			T.E =	66.405306
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	23.479183 =	.498933
111		.187000 x	15.951934 =	2.983012
375.14		1.000000 x	17.510000 =	17.510000
			-----	
			T.E =	31.151944
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	108.364281 =	9.752785
112		1.190000 x	17.729980 =	21.098676
113		.255000 x	23.479183 =	5.987192
			-----	
			T.E =	



6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	118.134281 =	26.107676
700		.350000 x	.000000 =	.000000
113		.510000 x	23.479183 =	11.974383
112		1.360000 x	17.729980 =	24.112773
-----				
			T.E =	
6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.729980 =	25.619821
113		.595000 x	23.479183 =	13.970114
6325		.234000 x	118.134281 =	27.643422
700		.380000 x	.000000 =	.000000
-----				
			T.E =	
6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	118.134281 =	28.470362
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979
-----				
			T.E =	
6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	108.364281 =	11.920071
112		1.275000 x	17.729980 =	22.605725
700		.250000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922
-----				
			T.E =	
6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	108.364281 =	14.195721
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653
112		1.275000 x	17.729980 =	22.605725
-----				
			T.E =	

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.729980 =	24.112773
113		.510000 x	23.479183 =	11.974383
6323		.154000 x	108.364281 =	16.688099
700		.350000 x	.000000 =	.000000
-----				
			T.E =	
6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	108.364281 =	17.988471
112		1.445000 x	17.729980 =	25.619821
700		.380000 x	.000000 =	.000000
113		.595000 x	23.479183 =	13.970114
-----				
			T.E =	
6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
6323		.173000 x	108.364281 =	18.747021
113		.637500 x	23.479183 =	14.967979
-----				
			T.E =	
6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	118.134281 =	16.302531
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
112		1.190000 x	17.729980 =	21.098676
-----				
			T.E =	
6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.729980 =	22.605725
113		.340000 x	23.479183 =	7.982922
6325		.165000 x	118.134281 =	19.492156
700		.250000 x	.000000 =	.000000
-----				
			T.E =	

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	118.134281 =	22.799916
112		1.275000 x	17.729980 =	22.605725
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653
-----				
			T.E =	
6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	108.364281 =	6.501857
112		1.190000 x	17.729980 =	21.098676
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
-----				
			T.E =	
6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	118.134281 =	15.357457
700		.350000 x	.000000 =	.000000
113		.510000 x	23.479183 =	11.974383
112		1.360000 x	17.729980 =	24.112773
-----				
			T.E =	
6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.729980 =	25.619821
113		.595000 x	23.479183 =	13.970114
6325		.140000 x	118.134281 =	16.538799
700		.380000 x	.000000 =	.000000
-----				
			T.E =	
6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	118.134281 =	17.720142
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
113		.637500 x	23.479183 =	14.967979
-----				
			T.E =	

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	108.364281 =	7.585500
112		1.275000 x	17.729980 =	22.605725
700		.250000 x	.000000 =	.000000
113		.340000 x	23.479183 =	7.982922

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	108.364281 =	8.669142
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653
112		1.275000 x	17.729980 =	22.605725

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.729980 =	24.112773
113		.510000 x	23.479183 =	11.974383
6323		.090000 x	108.364281 =	9.752785
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	108.364281 =	10.836428
112		1.445000 x	17.729980 =	25.619821
700		.380000 x	.000000 =	.000000
113		.595000 x	23.479183 =	13.970114

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.729980 =	26.373345
700		.400000 x	.000000 =	.000000
6323		.110000 x	108.364281 =	11.920071
113		.637500 x	23.479183 =	14.967979

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	118.134281 =	11.813428
700		.200000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
112		1.190000 x	17.729980 =	21.098676
			T.E =	
6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.729980 =	22.605725
113		.340000 x	23.479183 =	7.982922
6325		.110000 x	118.134281 =	12.994771
700		.250000 x	.000000 =	.000000
			T.E =	
6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	118.134281 =	14.176114
112		1.275000 x	17.729980 =	22.605725
700		.300000 x	.000000 =	.000000
113		.425000 x	23.479183 =	9.978653
			T.E =	
6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.729980 =	7.535242
700		.120000 x	.000000 =	.000000
113		.255000 x	23.479183 =	5.987192
			T.E =	
6730.1	6730.1			
261		1.050000 x	14.500000 =	15.225000
6323		.090000 x	108.364281 =	9.752785
652		.002500 x	148.310006 =	.370775
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829
			T.E =	40.075774

6730.10	6730.10			
263		1.050000 x	31.200000 =	32.760000
111		.297500 x	15.951934 =	4.745700
112		.425000 x	17.729980 =	7.535242
6325		.249000 x	118.134281 =	29.415436
652		.004500 x	148.310006 =	.667395
113		.340000 x	23.479183 =	7.982922
			T.E =	83.106695
6730.11	6730.11			
263.2		1.050000 x	44.900000 =	47.145000
6325		.310000 x	118.134281 =	36.621627
652		.005000 x	148.310006 =	.741550
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		.552500 x	17.729980 =	9.795814
			T.E =	111.702032
6730.12	6730.12			
264		1.050000 x	61.600000 =	64.680000
111		.425000 x	15.951934 =	6.779572
113		.595000 x	23.479183 =	13.970114
6325		.370000 x	118.134281 =	43.709684
652		.006500 x	148.310006 =	.964015
112		.680000 x	17.729980 =	12.056386
			T.E =	142.159771
6730.2	6730.2			
261.2		1.050000 x	19.900000 =	20.895000
6323		.110000 x	108.364281 =	11.920071
652		.003000 x	148.310006 =	.444930
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829
			T.E =	47.987215
6730.3	6730.3			
262		1.050000 x	25.300000 =	26.565000
111		.212500 x	15.951934 =	3.389786
112		.382500 x	17.729980 =	6.781717
6323		.131000 x	108.364281 =	14.195721
652		.003500 x	148.310006 =	.519085
113		.297500 x	23.479183 =	6.985057
			T.E =	58.436366

6730.4	6730.4			
263		1.050000 x	31.200000 =	32.760000
6323		.170000 x	108.364281 =	18.421928
652		.004500 x	148.310006 =	.667395
111		.297500 x	15.951934 =	4.745700
113		.340000 x	23.479183 =	7.982922
112		.425000 x	17.729980 =	7.535242
			T.E =	72.113187
6730.5	6730.5			
263.2		1.050000 x	44.900000 =	47.145000
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
6323		.226000 x	108.364281 =	24.490328
652		.005000 x	148.310006 =	.741550
112		.552500 x	17.729980 =	9.795814
			T.E =	99.570732
6730.6	6730.6			
264		1.050000 x	61.600000 =	64.680000
6323		.274000 x	108.364281 =	29.691813
652		.006500 x	148.310006 =	.964015
113		.595000 x	23.479183 =	13.970114
112		.680000 x	17.729980 =	12.056386
111		.425000 x	15.951934 =	6.779572
			T.E =	128.141900
6730.7	6730.7			
261		1.050000 x	14.500000 =	15.225000
111		.170000 x	15.951934 =	2.711829
112		.340000 x	17.729980 =	6.028193
6325		.138000 x	118.134281 =	16.302531
652		.002500 x	148.310006 =	.370775
113		.255000 x	23.479183 =	5.987192
			T.E =	46.625519
6730.8	6730.8			
261.2		1.050000 x	19.900000 =	20.895000
6325		.165000 x	118.134281 =	19.492156
652		.003000 x	148.310006 =	.444930
111		.170000 x	15.951934 =	2.711829
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
			T.E =	55.559300

6730.9	6730.9			
262		1.050000 x	25.300000 =	26.565000
111		.212500 x	15.951934 =	3.389786
113		.297500 x	23.479183 =	6.985057
6325		.193000 x	118.134281 =	22.799916
652		.003500 x	148.310006 =	.519085
112		.382500 x	17.729980 =	6.781717
			T.E =	67.040562
6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	108.364281 =	9.752785
652		.002500 x	148.310006 =	.370775
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829
			T.E =	
6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.951934 =	4.745700
112		.425000 x	17.729980 =	7.535242
6325		.249000 x	118.134281 =	29.415436
652		.004500 x	148.310006 =	.667395
113		.340000 x	23.479183 =	7.982922
			T.E =	
6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	118.134281 =	36.621627
652		.005000 x	148.310006 =	.741550
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
112		.552500 x	17.729980 =	9.795814
			T.E =	
6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.951934 =	6.779572
113		.595000 x	23.479183 =	13.970114
6325		.370000 x	118.134281 =	43.709684
652		.006500 x	148.310006 =	.964015
112		.680000 x	17.729980 =	12.056386
			T.E =	



6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	108.364281 =	11.920071
652		.003000 x	148.310006 =	.444930
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193
111		.170000 x	15.951934 =	2.711829

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.951934 =	3.389786
112		.382500 x	17.729980 =	6.781717
6323		.131000 x	108.364281 =	14.195721
652		.003500 x	148.310006 =	.519085
113		.297500 x	23.479183 =	6.985057

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	108.364281 =	18.421928
652		.004500 x	148.310006 =	.667395
111		.297500 x	15.951934 =	4.745700
113		.340000 x	23.479183 =	7.982922
112		.425000 x	17.729980 =	7.535242

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.951934 =	5.423658
113		.510000 x	23.479183 =	11.974383
6323		.226000 x	108.364281 =	24.490328
652		.005000 x	148.310006 =	.741550
112		.552500 x	17.729980 =	9.795814

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	108.364281 =	29.691813
652		.006500 x	148.310006 =	.964015
113		.595000 x	23.479183 =	13.970114
112		.680000 x	17.729980 =	12.056386
111		.425000 x	15.951934 =	6.779572

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.951934 =	2.711829
112		.340000 x	17.729980 =	6.028193
6325		.138000 x	118.134281 =	16.302531
652		.002500 x	148.310006 =	.370775
113		.255000 x	23.479183 =	5.987192

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	118.134281 =	19.492156
652		.003000 x	148.310006 =	.444930
111		.170000 x	15.951934 =	2.711829
113		.255000 x	23.479183 =	5.987192
112		.340000 x	17.729980 =	6.028193

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.951934 =	3.389786
113		.297500 x	23.479183 =	6.985057
6325		.193000 x	118.134281 =	22.799916
652		.003500 x	148.310006 =	.519085
112		.382500 x	17.729980 =	6.781717

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	23.479183 =	19.957306

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	22.628360 =	42.541317
6326		.940000 x	138.007760 =	129.727294

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	138.007760 =	100.745665

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	138.007760 =	129.727294
		-----		
			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	138.007760 =	100.745665
		-----		
			T.E =	
6742.1	6742.1			
6303		3.040000 x	22.628360 =	68.790214
6328		.400000 x	164.480119 =	65.792048
		-----		
			T.E =	134.582262
6742.10	6742.10			
6303		7.520000 x	22.628360 =	170.165267
6328		2.110000 x	164.480119 =	347.053051
		-----		
			T.E =	517.218318
6742.11	6742.11			
6303		8.030000 x	22.628360 =	181.705731
6328		2.430000 x	164.480119 =	399.686689
		-----		
			T.E =	581.392420
6742.2	6742.2			
6303		3.500000 x	22.628360 =	79.199260
6328		.500000 x	164.480119 =	82.240060
		-----		
			T.E =	161.439320
6742.3	6742.3			
6303		4.020000 x	22.628360 =	90.966007
6328		.630000 x	164.480119 =	103.622475
		-----		
			T.E =	194.588482
6742.4	6742.4			
6303		4.530000 x	22.628360 =	102.506471
6328		.800000 x	164.480119 =	131.584095
		-----		
			T.E =	234.090566

6742.5	6742.5			
6303		5.000000 x	22.628360 =	113.141800
6328		.950000 x	164.480119 =	156.256113
		-----		
			T.E =	269.397913
6742.6	6742.6			
6303		5.530000 x	22.628360 =	125.134831
6328		1.170000 x	164.480119 =	192.441739
		-----		
			T.E =	317.576570
6742.7	6742.7			
6303		6.040000 x	22.628360 =	136.675294
6328		1.410000 x	164.480119 =	231.916968
		-----		
			T.E =	368.592262
6742.8	6742.8			
6303		6.520000 x	22.628360 =	147.536907
6328		1.610000 x	164.480119 =	264.812992
		-----		
			T.E =	412.349899
6742.9	6742.9			
6303		7.040000 x	22.628360 =	159.303654
6328		1.880000 x	164.480119 =	309.222624
		-----		
			T.E =	468.526278
6743.1	6743.1			
6303		3.040000 x	22.628360 =	68.790214
6328		.440000 x	164.480119 =	72.371252
		-----		
			T.E =	141.161467
6743.10	6743.10			
6303		7.520000 x	22.628360 =	170.165267
6328		2.240000 x	164.480119 =	368.435467
		-----		
			T.E =	538.600734
6743.11	6743.11			
6303		8.030000 x	22.628360 =	181.705731
6328		2.570000 x	164.480119 =	422.713906
		-----		
			T.E =	604.419637

6743.12	6743.12			
6303		3.040000 x	22.628360 =	68.790214
6328		.750000 x	164.480119 =	123.360089
		-----		
			T.E =	192.150304
6743.13	6743.13			
6303		3.500000 x	22.628360 =	79.199260
6328		.910000 x	164.480119 =	149.676908
		-----		
			T.E =	228.876168
6743.14	6743.14			
6303		4.020000 x	22.628360 =	90.966007
6328		1.090000 x	164.480119 =	179.283330
		-----		
			T.E =	270.249337
6743.15	6743.15			
6303		4.530000 x	22.628360 =	102.506471
6328		1.300000 x	164.480119 =	213.824155
		-----		
			T.E =	316.330626
6743.16	6743.16			
6303		5.000000 x	22.628360 =	113.141800
6328		1.550000 x	164.480119 =	254.944184
		-----		
			T.E =	368.085984
6743.17	6743.17			
6303		5.530000 x	22.628360 =	125.134831
6328		1.850000 x	164.480119 =	304.288220
		-----		
			T.E =	429.423051
6743.2	6743.2			
6303		3.500000 x	22.628360 =	79.199260
6328		.550000 x	164.480119 =	90.464065
		-----		
			T.E =	169.663325
6743.3	6743.3			
6303		4.020000 x	22.628360 =	90.966007
6328		.690000 x	164.480119 =	113.491282
		-----		
			T.E =	204.457289

6743.4	6743.4			
6303		4.530000 x	22.628360 =	102.506471
6328		.860000 x	164.480119 =	141.452902
		-----		
			T.E =	243.959373
6743.5	6743.5			
6303		5.000000 x	22.628360 =	113.141800
6328		1.020000 x	164.480119 =	167.769721
		-----		
			T.E =	280.911521
6743.6	6743.6			
6303		5.530000 x	22.628360 =	125.134831
6328		1.260000 x	164.480119 =	207.244950
		-----		
			T.E =	332.379781
6743.7	6743.7			
6303		6.040000 x	22.628360 =	136.675294
6328		1.500000 x	164.480119 =	246.720179
		-----		
			T.E =	383.395473
6743.8	6743.8			
6303		6.520000 x	22.628360 =	147.536907
6328		1.720000 x	164.480119 =	282.905805
		-----		
			T.E =	430.442712
6743.9	6743.9			
6303		7.040000 x	22.628360 =	159.303654
6328		2.000000 x	164.480119 =	328.960238
		-----		
			T.E =	488.263892
6744	6744			
111		2.125000 x	15.951934 =	33.897860
111		4.250000 x	15.951934 =	67.795720
113		2.125000 x	23.479183 =	49.893264
113		2.125000 x	23.479183 =	49.893264
112		2.125000 x	17.729980 =	37.676208
		-----		
			T.E =	239.156315

6751	6751			
234.2		.400000 x	.666500 =	.266600
113		.051000 x	23.479183 =	1.197438
113		.170000 x	23.479183 =	3.991461
235		.650000 x	.553000 =	.359450
		-----		
			T.E =	5.814949
6752	6752			
237		1.050000 x	1.060000 =	1.113000
113		.017000 x	23.479183 =	.399146
111		.025500 x	15.951934 =	.406774
		-----		
			T.E =	1.918920
6753	6753			
237		1.050000 x	1.060000 =	1.113000
112		.085000 x	17.729980 =	1.507048
113		.085000 x	23.479183 =	1.995731
		-----		
			T.E =	4.615779
6754	6754			
237.1		1.000000 x	1.200000 =	1.200000
112		.017000 x	17.729980 =	.301410
111		.051000 x	15.951934 =	.813549
113		.212500 x	23.479183 =	4.989326
		-----		
			T.E =	7.304285
6801	6801			
232		.700000 x	1.750000 =	1.225000
251		.008000 x	290.000000 =	2.320000
113		2.550000 x	23.479183 =	59.871917
112		1.700000 x	17.729980 =	30.140966
111		.850000 x	15.951934 =	13.559144
		-----		
			T.E =	107.117027
6802	6802			
231		15.000000 x	.650000 =	9.750000
251		.050000 x	290.000000 =	14.500000
113		2.550000 x	23.479183 =	59.871917
252.1		.050000 x	.000000 =	.000000
111		4.250000 x	15.951934 =	67.795720
		-----		
			T.E =	

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	148.310006 =	1.779720
111		.510000 x	15.951934 =	8.135486
113		.680000 x	23.479183 =	15.965844
		-----		
			T.E =	32.715051
6804	6804			
111		.510000 x	15.951934 =	8.135486
652		.120000 x	148.310006 =	17.797201
113		.680000 x	23.479183 =	15.965844
		-----		
			T.E =	41.898532
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	148.310006 =	.296620
2522		.005000 x	158.406700 =	.792034
113		.340000 x	23.479183 =	7.982922
111		.340000 x	15.951934 =	5.423658
		-----		
			T.E =	18.555233
6806	6806			
111		.340000 x	15.951934 =	5.423658
113		.340000 x	23.479183 =	7.982922
6326		.005000 x	138.007760 =	.690039
652		.002000 x	148.310006 =	.296620
		-----		
			T.E =	14.393239
6807	6807			
111		1.700000 x	15.951934 =	27.118288
		-----		
			T.E =	27.118288
6808	6808			
111		.425000 x	15.951934 =	6.779572
		-----		
			T.E =	6.779572
6810	6810			
241		2.600000 x	6.240000 =	16.224000
113		1.062500 x	23.479183 =	24.946632
113		.850000 x	23.479183 =	19.957306
111		1.062500 x	15.951934 =	16.948930
241		1.300000 x	6.240000 =	8.112000
		-----		
			T.E =	86.188867



6811	6811			
236		6.430000 x	.513000 =	3.298590
113		.850000 x	23.479183 =	19.957306
113		3.400000 x	23.479183 =	79.829222
241		3.150000 x	6.240000 =	19.656000
		-----		
			T.E =	122.741118
6812	6812			
397.1		2.100000 x	6.780000 =	14.238000
111		.425000 x	15.951934 =	6.779572
6324		.250000 x	113.249281 =	28.312320
113		4.250000 x	23.479183 =	99.786528
243		11.900000 x	1.900000 =	22.610000
		-----		
			AΘΡΟΙΣΜΑ =	171.726420
	T.E =	.262500 x	171.726420 =	45.078185
		-----		
7001	7001			
7001 A		1.000000 x	.233235 =	.233235
7001 Δ		1.000000 x	.307976 =	.307976
7001 E		1.000000 x	.796161 =	.796161
7001 Γ		1.000000 x	.958924 =	.958924
7001 B		1.000000 x	.752086 =	.752086
		-----		
			AΘΡΟΙΣΜΑ =	3.048382
		-----		
			T.E =	3.505639
7002	7002			
560		.005104 x	619.671439 =	3.162803
		-----		
			T.E =	3.162803
7003	7003			
7003 A		1.000000 x	.116617 =	.116617
7003 Δ		1.000000 x	.766791 =	.766791
7003 Γ		1.000000 x	.544472 =	.544472
7003 B		1.000000 x	.579822 =	.579822
		-----		
			AΘΡΟΙΣΜΑ =	2.007702
		-----		
			T.E =	2.208472
7004	7004			
561		.003250 x	810.451039 =	2.633966
		-----		
			T.E =	2.633966

7005	7005			
7005 Α		1.000000 x	.116617 =	.116617
7005 Ε		1.000000 x	.766791 =	.766791
7005 Δ		1.000000 x	.544472 =	.544472
7005 Γ		1.000000 x	.289911 =	.289911
7005 Β		1.000000 x	1.014688 =	1.014688
			-----	
			ΑΘΡΟΙΣΜΑ =	2.732479
			-----	
			T.E =	3.005727
7006	7006			
561		.001723 x	810.451039 =	1.396407
561		.000812 x	810.451039 =	.658086
561		.000862 x	810.451039 =	.698609
			-----	
			T.E =	2.753102
7007	7007			
213		.100000 x	1.800000 =	.180000
550		.003500 x	1,090.479240 =	3.816677
518		.001750 x	857.423098 =	1.500490
116		.280000 x	22.893045 =	6.410053
502		.000583 x	777.816807 =	.453467
			-----	
			T.E =	12.360688
7008	7008			
111		.021000 x	15.951934 =	.334991
112		.210000 x	17.729980 =	3.723296
7007		1.100000 x	12.360688 =	13.596757
558		.000972 x	1,074.408174 =	1.044325
507		.000875 x	914.937874 =	.800571
503		.001750 x	877.327207 =	1.535323
			-----	
			T.E =	21.035261
7009	7009			
560		.006417 x	619.671439 =	3.976432
			-----	
			T.E =	3.976432
7010	7010			
7010 Α		1.000000 x	.338439 =	.338439
7010 Δ		1.000000 x	.307976 =	.307976
7010 Ε		1.000000 x	.945984 =	.945984
7010 Γ		1.000000 x	.544472 =	.544472
7010 Β		1.000000 x	.508195 =	.508195
			-----	
			ΑΘΡΟΙΣΜΑ =	2.645066
			-----	
			T.E =	3.041826

7011	7011			
502		.001367 x	777.816807 =	1.063276
502		.000700 x	777.816807 =	.544472
503		.000438 x	877.327207 =	.384269
563		.001367 x	.000000 =	.000000
558		.000729 x	1,074.408174 =	.783244
558		.000729 x	1,074.408174 =	.783244
554		.000438 x	32.571000 =	.014266
			-----	
			ΑΘΡΟΙΣΜΑ =	3.572770
			-----	
			T.E =	
7012	7012			
7008		1.000000 x	21.035261 =	21.035261
			-----	
			ΑΘΡΟΙΣΜΑ =	21.035261
			-----	
			T.E =	23.138787
7013	7013			
7003		1.000000 x	2.208472 =	2.208472
			-----	
			ΑΘΡΟΙΣΜΑ =	2.208472
			-----	
			T.E =	2.429319
7014	7014			
7005		1.000000 x	3.005727 =	3.005727
			-----	
			ΑΘΡΟΙΣΜΑ =	3.005727
			-----	
			T.E =	3.306300
7015	7015			
111		.056000 x	15.951934 =	.893308
7001		.900000 x	3.505639 =	3.155075
X 630		.300000 x	1.350205 =	.405062
X 630.1		.300000 x	1.583942 =	.475183
			-----	
			T.E =	4.928628
7016.9	7016.9			
7016.4		1.000000 x	122.932864 =	122.932864
7016.8		1.000000 x	119.743833 =	119.743833
7016.5		1.000000 x	24.586573 =	24.586573
7016.7		1.000000 x	81.354863 =	81.354863
7016.6		1.000000 x	36.879859 =	36.879859
			-----	
			T.E =	385.497992

7017.8	7017.8				
7017.3		1.000000 x	90.464569 =		90.464569
7017.4		1.000000 x	18.092914 =		18.092914
7017.5		1.000000 x	32.567245 =		32.567245
7017.7		1.000000 x	59.871917 =		59.871917
7017.6		1.000000 x	81.354863 =		81.354863
				T.E =	282.351508
7018	7018				
233.2		1.150000 x	.523400 =		.601910
113		.051000 x	23.479183 =		1.197438
				AΘΡΟΙΣΜΑ =	1.799348
				T.E =	1.979283
7019	7019				
7019 A6		1.000000 x	198.321311 =		198.321311
7019 A7		1.000000 x	19.832131 =		19.832131
				T.E =	218.153442
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	218.153442 =		218.153442
				T.E =	212.253442
7020	7020				
213		.150000 x	1.800000 =		.270000
116		.980000 x	22.893045 =		22.435184
7020.2		.010938 x	3,508.382520 =		38.374688
				T.E =	61.079872
7020.1	7020.1				
570.2		.350000 x	151.752516 =		53.113381
571.2		.070000 x	248.549672 =		17.398477
571.1		.280000 x	387.911559 =		108.615237
				AΘΡΟΙΣΜΑ =	179.127094
	T.E =	.015625 x	179.127094 =		2.798861
7021	7021				
213		.150000 x	1.800000 =		.270000
116		1.120000 x	22.893045 =		25.640210
7021.2		.014583 x	3,014.510476 =		43.960606
				T.E =	69.870817

7021.1	7021.1			
570.2		.350000 x	151.752516 =	53.113381
571.1		.280000 x	387.911559 =	108.615237
571.2		.070000 x	248.549672 =	17.398477
			AΘΡΟΙΣΜΑ =	179.127094
	T.E =	.020833 x	179.127094 =	3.731755
7022	7022			
213		.150000 x	1.800000 =	.270000
116		1.400000 x	22.893045 =	32.050263
7022.2		.020000 x	2,739.448140 =	54.788963
			T.E =	87.109226
7022.1	7022.1			
570.2		.350000 x	151.752516 =	53.113381
571.1		.280000 x	387.911559 =	108.615237
571.2		.070000 x	248.549672 =	17.398477
			AΘΡΟΙΣΜΑ =	179.127094
	T.E =	.028571 x	179.127094 =	5.117840
7023	7023			
398.2		1.050000 x	42.300000 =	44.415000
111		.425000 x	15.951934 =	6.779572
116		.850000 x	22.893045 =	19.459088
550		.012143 x	1,090.479240 =	13.241689
			T.E =	83.895350
7024	7024			
398.3		1.050000 x	49.800000 =	52.290000
111		.425000 x	15.951934 =	6.779572
550		.020238 x	1,090.479240 =	22.069119
116		.850000 x	22.893045 =	19.459088
			T.E =	100.597779
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	148.310006 =	.148310
550		.020238 x	1,090.479240 =	22.069119
116		.850000 x	22.893045 =	19.459088
112		.425000 x	17.729980 =	7.535242
111		.425000 x	15.951934 =	6.779572
233		6.180000 x	.492800 =	3.045504
398.4		1.000000 x	71.200000 =	71.200000
			T.E =	130.247455

7026	7026			
398.5		125.400000 x	5.590000 =	700.986000
236		16.808000 x	.513000 =	8.622504
113		3.400000 x	23.479183 =	79.829222
6310		12.350000 x	1.515305 =	18.714017
113		.909160 x	23.479183 =	21.346334
				-----
			ΑΘΡΟΙΣΜΑ =	829.498077
	T.E =	.007259 x	829.498077 =	6.021327
				-----
7027	7027			
236		1.100000 x	.513000 =	.564300
113		.059500 x	23.479183 =	1.397011
				-----
			T.E =	1.961311
7028	7028			
111		.144500 x	15.951934 =	2.305054
112		.144500 x	17.729980 =	2.561982
6751		.600000 x	5.814949 =	3.488969
6751		.120000 x	5.814949 =	.697794
111		.425000 x	15.951934 =	6.779572
				-----
			ΑΘΡΟΙΣΜΑ =	15.833372
				-----
			T.E =	18.208378
7029	7029			
568.1		.021250 x	2,873.262978 =	61.056838
569.2		.021250 x	574.430320 =	12.206644
571.2		.021250 x	248.549672 =	5.281681
570.2		.021250 x	151.752516 =	3.224741
				-----
			T.E =	81.769904
7030	7030			
398.6		.015385 x	330.000000 =	5.077050
572		.026563 x	822.002817 =	21.834861
				-----
			ΑΘΡΟΙΣΜΑ =	26.911911
				-----
			T.E =	37.676675
7031	7031			
573		.106250 x	1,007.580103 =	107.055386
				-----
			ΑΘΡΟΙΣΜΑ =	107.055386
				-----
			T.E =	123.113694
7032	7032			
573		.212500 x	1,007.580103 =	214.110772
				-----
			ΑΘΡΟΙΣΜΑ =	214.110772
				-----
			T.E =	278.344003

7101.1	7101.1			
398.1		15.000000 x	.225000 =	3.375000
574		.132813 x	3,354.579413 =	445.531756
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
567		.132813 x	342.371968 =	45.471448
				-----
				ΑΘΡΟΙΣΜΑ = 494.752307
				-----
				T.E = 509.594877
7101.2	7101.2			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
574		.148750 x	3,354.579413 =	498.993688
567		.148750 x	342.371968 =	50.927830
				-----
				ΑΘΡΟΙΣΜΑ = 553.670622
				-----
				T.E = 570.280740
7101.3	7101.3			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
574		.159375 x	3,354.579413 =	534.636094
567		.159375 x	342.371968 =	54.565532
				-----
				ΑΘΡΟΙΣΜΑ = 592.950730
				-----
				T.E = 610.739252
7101.4	7101.4			
398.1		15.000000 x	.225000 =	3.375000
567		.170000 x	342.371968 =	58.203235
574		.170000 x	3,354.579413 =	570.278500
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
				-----
				ΑΘΡΟΙΣΜΑ = 632.230838
				-----
				T.E = 651.197764
7101.5	7101.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
567		.191250 x	342.371968 =	65.478639
T 630		.105000 x	1.639534 =	.172151
574		.191250 x	3,354.579413 =	641.563313
				-----
				ΑΘΡΟΙΣΜΑ = 710.791055
				-----
				T.E = 732.114787

7102.1	7102.1			
398.1		15.000000 x	.225000 =	3.375000
567		.302813 x	342.371968 =	103.674683
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
574		.302813 x	3,354.579413 =	1,015.810256
			-----	
			ΑΘΡΟΙΣΜΑ =	1,123.234042
			-----	
			T.E =	1,156.931063
7102.2	7102.2			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
574		.329375 x	3,354.579413 =	1,104.914594
567		.329375 x	342.371968 =	112.768767
			-----	
			ΑΘΡΟΙΣΜΑ =	1,221.432465
			-----	
			T.E =	1,258.075439
7102.3	7102.3			
398.1		15.000000 x	.225000 =	3.375000
567		.361250 x	342.371968 =	123.681873
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
574		.361250 x	3,354.579413 =	1,211.841813
			-----	
			ΑΘΡΟΙΣΜΑ =	1,339.272790
			-----	
			T.E =	1,379.450974
7102.4	7102.4			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
574		.403750 x	3,354.579413 =	1,354.411438
567		.403750 x	342.371968 =	138.232682
			-----	
			ΑΘΡΟΙΣΜΑ =	1,496.393224
			-----	
			T.E =	1,541.285020
7102.5	7102.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
567		.446250 x	342.371968 =	152.783491
574		.446250 x	3,354.579413 =	1,496.981063
			-----	
			ΑΘΡΟΙΣΜΑ =	1,653.513657
			-----	
			T.E =	1,703.119067



7103	7103			
113		3.400000 x	23.479183 =	79.829222
113		.283333 x	23.479183 =	6.652427
115		.070833 x	18.893831 =	1.338307
575		.106250 x	754.486313 =	80.164171
		-----		
			T.E =	167.984127
7104	7104			
113		1.700000 x	23.479183 =	39.914611
576		.106250 x	7.238000 =	.769038
567		.106250 x	342.371968 =	36.377022
		-----		
			T.E =	77.060670
7105	7105			
111		.850000 x	15.951934 =	13.559144
113		.850000 x	23.479183 =	19.957306
576		.106250 x	7.238000 =	.769038
567		.106250 x	342.371968 =	36.377022
		-----		
			T.E =	70.662509
7106.1	7106.1			
577		.265625 x	700.211794 =	185.993758
		-----		
			AΘΡΟΙΣΜΑ =	185.993758
		-----		
			T.E =	195.293446
7106.2	7106.2			
577		.297500 x	700.211794 =	208.313009
		-----		
			AΘΡΟΙΣΜΑ =	208.313009
		-----		
			T.E =	218.728659
7106.3	7106.3			
577		.350625 x	700.211794 =	245.511760
		-----		
			AΘΡΟΙΣΜΑ =	245.511760
		-----		
			T.E =	257.787348
7106.4	7106.4			
577		.425000 x	700.211794 =	297.590012
		-----		
			AΘΡΟΙΣΜΑ =	297.590012
		-----		
			T.E =	312.469513

7106.5	7106.5				
577		.531250 x	700.211794 =		371.987516
		-----			
			ΑΘΡΟΙΣΜΑ =		371.987516
			-----		
			T.E =		390.586891
7107.1	7107.1				
398.7		.030000 x	1,360.000000 =		40.800000
7106.1		1.000000 x	195.293446 =		195.293446
		-----			
			T.E =		236.093446
7107.2	7107.2				
398.7		.030000 x	1,360.000000 =		40.800000
7106.2		1.000000 x	218.728659 =		218.728659
		-----			
			T.E =		259.528659
7107.3	7107.3				
398.7		.030000 x	1,360.000000 =		40.800000
7106.3		1.000000 x	257.787348 =		257.787348
		-----			
			T.E =		298.587348
7107.4	7107.4				
398.7		.030000 x	1,360.000000 =		40.800000
7106.4		1.000000 x	312.469513 =		312.469513
		-----			
			T.E =		353.269513
7107.5	7107.5				
398.7		.030000 x	1,360.000000 =		40.800000
7106.5		1.000000 x	390.586891 =		390.586891
		-----			
			T.E =		431.386891
7108	7108				
398.11		1.000000 x	136.770000 =		136.770000
574		.053125 x	3,354.579413 =		178.212031
		-----			
			T.E =		314.982031
7109	7109				
398.12		1.000000 x	176.880000 =		176.880000
574		.053125 x	3,354.579413 =		178.212031
		-----			
			T.E =		355.092031

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,354.579413 =		178.212031
					-----
				T.E =	340.526131
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,354.579413 =		178.212031
					-----
				T.E =	327.972031
7112	7112				
398.13		1.300000 x	8.330000 =		10.829000
577		.010625 x	700.211794 =		7.439750
					-----
				T.E =	18.268750
7113	7113				
241		1.200000 x	6.240000 =		7.488000
574		.001063 x	3,354.579413 =		3.565918
					-----
				T.E =	11.053918
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	700.211794 =		37.198752
					-----
				T.E =	40.888752
7115	7115				
574		.026563 x	3,354.579413 =		89.107693
					-----
				T.E =	89.107693
7116	7116				
577		.170000 x	700.211794 =		119.036005
					-----
				T.E =	119.036005
7117	7117				
574		.001063 x	3,354.579413 =		3.565918
					-----
				T.E =	3.565918

7118.1	7118.1			
111		27.200000 x	15.951934 =	433.892605
578		.850000 x	638.299319 =	542.554421
574.1		.425000 x	2,185.304704 =	928.754499
		-----		
			T.E =	1,905.201525
7118.2	7118.2			
111		40.800000 x	15.951934 =	650.838907
574.1		.850000 x	2,185.304704 =	1,857.508998
578		.850000 x	638.299319 =	542.554421
		-----		
			T.E =	3,050.902327
7119.1	7119.1			
111		13.600000 x	15.951934 =	216.946302
577.1		.255000 x	429.154704 =	109.434450
		-----		
			T.E =	326.380752
7119.2	7119.2			
111		13.600000 x	15.951934 =	216.946302
577.1		.595000 x	429.154704 =	255.347049
		-----		
			T.E =	472.293351
7120.1	7120.1			
111		10.200000 x	15.951934 =	162.709727
575.1		.425000 x	231.990648 =	98.596025
578		.425000 x	638.299319 =	271.277211
		-----		
			T.E =	532.582963
7120.2	7120.2			
111		17.000000 x	15.951934 =	271.182878
578		1.275000 x	638.299319 =	813.831632
575.1		1.275000 x	231.990648 =	295.788076
		-----		
			T.E =	1,380.802586
7121.1	7121.1			
111		6.800000 x	15.951934 =	108.473151
576.1		.425000 x	6.580000 =	2.796500
578		.425000 x	638.299319 =	271.277211
		-----		
			T.E =	382.546862

7121.2	7121.2			
111		6.800000 x	15.951934 =	108.473151
576.1		.425000 x	6.580000 =	2.796500
578		.425000 x	638.299319 =	271.277211
		-----		
			T.E =	382.546862
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
567		.122188 x	342.371968 =	41.833746
580		.122188 x	1,667.503253 =	203.748887
		-----		
			AΘΡΟΙΣΜΑ =	249.331737
			-----	
			T.E =	256.811689
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
T 630		.105000 x	1.639534 =	.172151
580		.286875 x	1,667.503253 =	478.364996
567		.286875 x	342.371968 =	98.217958
		-----		
			AΘΡΟΙΣΜΑ =	580.332058
			-----	
			T.E =	597.742019
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	342.371968 =	21.826213
T 630		.105000 x	1.639534 =	.172151
T 630.1		.105000 x	1.923358 =	.201953
580		.063750 x	1,667.503253 =	106.303332
		-----		
			T.E =	131.878649
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.923358 =	.201953
567		.127500 x	342.371968 =	43.652426
T 630		.105000 x	1.639534 =	.172151
580		.127500 x	1,667.503253 =	212.606665
		-----		
			T.E =	260.008194
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,667.503253 =	88.586110
		-----		
			T.E =	151.006110

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,667.503253 =		26.576667
-----					
			T.E =		115.133967
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,667.503253 =		26.576667
-----					
			T.E =		95.150367
7129	7129				
6751		1.000000 x	5.814949 =		5.814949
-----					
			T.E =		5.814949