

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

3ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.175600
212	1.433300
213	1.949500
214	4.160000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.861000
232	2.100000
233	.545500
233.1	.545500
233.2	.598400
233.3	8.150000
234	.941500
234.1	1.111500
234.2	1.006500
234.3	1.054000
235	.703000
236	.673000
237	1.218000
237.1	1.380000
241	7.750000
242	5.000000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.440000
361.1	13.520000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	17.490000
361.3	22.200000
361.4	
361.5	42.370000
361.6	56.540000
361.7	87.480000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	7.990000
372.2	12.580000
372.3	16.500000
372.4	25.540000
372.5	32.500000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.490000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.260000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	91.600000
376.10	502.070000
376.11	544.290000
376.12	91.600000
376.13	101.900000
376.14	113.040000
376.15	144.820000
376.16	182.130000
376.17	231.180000
376.18	311.830000
376.19	346.570000
376.2	101.900000
376.20	412.890000
376.21	502.070000
376.22	544.290000
376.3	113.040000
376.4	144.820000
376.5	182.130000
376.6	231.180000
376.7	311.830000
376.8	346.570000
376.9	412.890000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	113,082.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	76,825.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	134,053.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	153,664.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	25,662.000000
387.1	
387.2	
387.3	21,523.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,664.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,629.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	8,188.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	15,362.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.960000
396.12	4.250000
396.13	1.770000
396.14	42.680000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.950000
397.4	.167500
398.1	.250000
398.10	142.840000
398.11	140.870000
398.12	182.180000
398.13	10.300000
398.14	60.360000
398.15	77.960000
398.16	64.290000
398.17	107.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	6.400000

398.6	330.000000
398.7	1,360.000000
398.8	31.620000
398.9	131.840000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
419	4.530000
420	97.290000
421	32.560000
428	437.840000
429	77.590000
450	83.850000
451	4.870000
452	103.060000
453	
454	97.290000
455	31.280000
456	35.040000
457	457.700000
458	285.020000
459	422.050000
460	521.890000
461	239.030000
462	348.520000
463	43.800000
464	383.570000
465	102.610000
466	47.860000
467	348.520000
468	87.280000
469	87.280000
470	70.390000
471	61.000000
472	26.510000
473	17.050000
474	35.040000
475	1,970.400000
476	85.400000
477	6.950000
478	115.120000
479	185.200000
480	27.220000
481	812.490000

501	501				
401		1.000000 x	268.420000 =	268.420000	
211		50.000000 x	1.175600 =	58.780000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	560.772593	

			Η.Δ. =	616.849852	
502	502				
402		1.000000 x	380.180000 =	380.180000	
214		7.000000 x	4.160000 =	29.120000	
211		80.000000 x	1.175600 =	94.048000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	734.441612	

			Η.Δ. =	807.885773	
503	503				
428		1.000000 x	437.840000 =	437.840000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	1.175600 =	129.316000	
118		4.000000 x	10.001019 =	40.004076	

			ΑΘΡΟΙΣΜΑ =	839.849612	

			Η.Δ. =	923.834573	
504	504				
403		1.000000 x	103.360000 =	103.360000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	1.175600 =	47.024000	
214		2.000000 x	4.160000 =	8.320000	

			ΑΘΡΟΙΣΜΑ =	349.793536	

			Η.Δ. =	384.772890	
505	505				
404		1.000000 x	212.730000 =	212.730000	
211		200.000000 x	1.175600 =	235.120000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	4.160000 =	41.600000	

			ΑΘΡΟΙΣΜΑ =	760.547688	

			Η.Δ. =	836.602457	

506	506				
405		1.000000 x	206.720000 =		206.720000
211		95.000000 x	1.175600 =		111.682000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
242		2.500000 x	5.000000 =		12.500000
214		6.000000 x	4.160000 =		24.960000

			ΑΘΡΟΙΣΜΑ =		626.959688

			Η.Δ. =		689.655657
507	507				
406		1.000000 x	320.980000 =		320.980000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
242		7.000000 x	5.000000 =		35.000000
214		10.000000 x	4.160000 =		41.600000
211		165.000000 x	1.175600 =		193.974000

			ΑΘΡΟΙΣΜΑ =		862.651688

			Η.Δ. =		948.916857
508	508				
407		1.000000 x	55.210000 =		55.210000
116		16.000000 x	20.419486 =		326.711776
115		4.000000 x	21.778427 =		87.113708
214		2.000000 x	4.160000 =		8.320000
408		2.000000 x	4.530000 =		9.060000
211		40.000000 x	1.175600 =		47.024000

			ΑΘΡΟΙΣΜΑ =		533.439484

			Η.Δ. =		586.783432
509	509				
409		1.000000 x	126.080000 =		126.080000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	4.160000 =		20.800000
211		80.000000 x	1.175600 =		94.048000

			ΑΘΡΟΙΣΜΑ =		375.151336

			Η.Δ. =		412.666470
510	510				
410		1.000000 x	116.530000 =		116.530000
117		8.000000 x	16.777917 =		134.223336
211		80.000000 x	1.175600 =		94.048000
214		5.000000 x	4.160000 =		20.800000

			ΑΘΡΟΙΣΜΑ =		365.601336

			Η.Δ. =		402.161470

511	511				
411		1.000000 x	27.370000 =	27.370000	
214		1.000000 x	4.160000 =	4.160000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.778427 =	87.113708	
212		17.000000 x	1.433300 =	24.366100	

			ΑΘΡΟΙΣΜΑ =	662.373168	

			Η.Δ. =	728.610485	
512	512				
412		1.000000 x	2.990000 =	2.990000	
214		1.000000 x	4.160000 =	4.160000	
115		2.000000 x	21.778427 =	43.556854	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	1.175600 =	11.756000	

			ΑΘΡΟΙΣΜΑ =	97.087078	

			Η.Δ. =	106.795786	
513	513				
413		1.000000 x	4.530000 =	4.530000	
211		15.000000 x	1.175600 =	17.634000	
115		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	4.160000 =	6.240000	

			ΑΘΡΟΙΣΜΑ =	145.675617	

			Η.Δ. =	160.243179	
514	514				
414		1.000000 x	6.250000 =	6.250000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	4.160000 =	8.320000	
211		21.000000 x	1.175600 =	24.687600	

			ΑΘΡΟΙΣΜΑ =	195.619756	

			Η.Δ. =	215.181732	
515	515				
415		1.000000 x	8.780000 =	8.780000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.778427 =	108.892135	
214		2.500000 x	4.160000 =	10.400000	
211		27.000000 x	1.175600 =	31.741200	

			ΑΘΡΟΙΣΜΑ =	263.686007	

			Η.Δ. =	290.054608	

516	516				
416		1.000000 x	13.540000 =	13.540000	
115		6.000000 x	21.778427 =	130.670562	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	4.160000 =	14.560000	
211		33.000000 x	1.175600 =	38.794800	

				ΑΘΡΟΙΣΜΑ =	336.062258

				Η.Δ. =	369.668484
517	517				
406		1.000000 x	320.980000 =	320.980000	
406		.400000 x	320.980000 =	128.392000	
116		8.000000 x	20.419486 =	163.355888	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	4.160000 =	33.280000	
211		240.000000 x	1.175600 =	282.144000	
407		2.000000 x	55.210000 =	110.420000	
115		8.000000 x	21.778427 =	174.227416	

				ΑΘΡΟΙΣΜΑ =	2,017.087172

				Η.Δ. =	2,218.795889
518	518				
417		1.000000 x	134.530000 =	134.530000	
214		12.000000 x	4.160000 =	49.920000	
212		5.000000 x	1.433300 =	7.166500	
211		180.000000 x	1.175600 =	211.608000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	

				ΑΘΡΟΙΣΜΑ =	812.819084

				Η.Δ. =	894.100992
520	520				
419		1.000000 x	4.530000 =	4.530000	
212		2.000000 x	1.433300 =	2.866600	
211		80.000000 x	1.175600 =	94.048000	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	4.160000 =	20.800000	

				ΑΘΡΟΙΣΜΑ =	405.724540

				Η.Δ. =	446.296994

521	521				
420		1.000000 x	97.290000 =	97.290000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	
211		40.000000 x	1.175600 =	47.024000	
			AΘΡΟΙΣΜΑ =	387.887612	
			H.Δ. =	426.676373	
522	522				
421		1.000000 x	32.560000 =	32.560000	
114		8.000000 x	23.886192 =	191.089536	
118		2.000000 x	10.001019 =	20.002038	
214		2.000000 x	4.160000 =	8.320000	
211		20.000000 x	1.175600 =	23.512000	
			AΘΡΟΙΣΜΑ =	275.483574	
			H.Δ. =	303.031931	
529	529				
429		1.000000 x	77.590000 =	77.590000	
211		70.000000 x	1.175600 =	82.292000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	4.160000 =	16.640000	
			AΘΡΟΙΣΜΑ =	407.615612	
			H.Δ. =	448.377173	
550	550				
450		1.000000 x	83.850000 =	83.850000	
451		4.000000 x	4.870000 =	19.480000	
116		32.000000 x	20.419486 =	653.423552	
115		4.000000 x	21.778427 =	87.113708	
214		4.000000 x	4.160000 =	16.640000	
211		90.000000 x	1.175600 =	105.804000	
			AΘΡΟΙΣΜΑ =	966.311260	
			H.Δ. =	1,062.942386	
551	551				
405		1.000000 x	206.720000 =	206.720000	
211		95.000000 x	1.175600 =	111.682000	
214		6.000000 x	4.160000 =	24.960000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
452		1.000000 x	103.060000 =	103.060000	
			AΘΡΟΙΣΜΑ =	717.519688	
			H.Δ. =	789.271657	

552	552				
453		1.000000 x	.000000 =	.000000	
115		8.000000 x	21.778427 =	174.227416	
214		1.000000 x	4.160000 =	4.160000	
211		18.000000 x	1.175600 =	21.160800	

			ΑΘΡΟΙΣΜΑ =	199.548216	

			Η.Δ. =		
553	553				
454		1.000000 x	97.290000 =	97.290000	
214		4.000000 x	4.160000 =	16.640000	
211		100.000000 x	1.175600 =	117.560000	

			ΑΘΡΟΙΣΜΑ =	231.490000	

			Η.Δ. =	254.639000	
554	554				
455		1.000000 x	31.280000 =	31.280000	

			ΑΘΡΟΙΣΜΑ =	31.280000	

			Η.Δ. =	34.408000	
555	555				
456		1.000000 x	35.040000 =	35.040000	
212		17.000000 x	1.433300 =	24.366100	
112		32.000000 x	17.312112 =	553.987584	
115		4.000000 x	21.778427 =	87.113708	
214		1.000000 x	4.160000 =	4.160000	

			ΑΘΡΟΙΣΜΑ =	704.667392	

			Η.Δ. =	775.134131	
556	556				
457		1.000000 x	457.700000 =	457.700000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
214		18.000000 x	4.160000 =	74.880000	
211		200.000000 x	1.175600 =	235.120000	

			ΑΘΡΟΙΣΜΑ =	1,038.797688	

			Η.Δ. =	1,142.677457	
557	557				
458		1.000000 x	285.020000 =	285.020000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		11.000000 x	4.160000 =	45.760000	
211		130.000000 x	1.175600 =	152.828000	

			ΑΘΡΟΙΣΜΑ =	754.705688	

			Η.Δ. =	830.176257	

558	558				
459		1.000000 x	422.050000 =	422.050000	
214		12.000000 x	4.160000 =	49.920000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	1.175600 =	235.120000	

			ΑΘΡΟΙΣΜΑ =	1,025.687688	

			Η.Δ. =	1,128.256457	
559	559				
460		1.000000 x	521.890000 =	521.890000	
211		250.000000 x	1.175600 =	293.900000	
214		15.000000 x	4.160000 =	62.400000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		12.000000 x	5.000000 =	60.000000	

			ΑΘΡΟΙΣΜΑ =	1,209.287688	

			Η.Δ. =	1,330.216457	
560	560				
461		1.000000 x	239.030000 =	239.030000	
114		8.000000 x	23.886192 =	191.089536	
211		160.000000 x	1.175600 =	188.096000	
214		8.000000 x	4.160000 =	33.280000	

			ΑΘΡΟΙΣΜΑ =	651.495536	

			Η.Δ. =	716.645090	
561	561				
462		1.000000 x	348.520000 =	348.520000	
214		12.000000 x	4.160000 =	49.920000	
114		8.000000 x	23.886192 =	191.089536	
211		230.000000 x	1.175600 =	270.388000	

			ΑΘΡΟΙΣΜΑ =	859.917536	

			Η.Δ. =	945.909290	
562	562				
463		1.000000 x	43.800000 =	43.800000	
214		2.400000 x	4.160000 =	9.984000	
211		50.000000 x	1.175600 =	58.780000	

			ΑΘΡΟΙΣΜΑ =	112.564000	

			Η.Δ. =	123.820400	

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	23.886192 =	382.179072	
112		24.000000 x	17.312112 =	415.490688	
214		16.000000 x	4.160000 =	66.560000	
464		1.000000 x	383.570000 =	383.570000	

		ΑΘΡΟΙΣΜΑ =		1,247.799760	

		H.Δ. =			
564	564				
465		1.000000 x	102.610000 =	102.610000	
567		3.000000 x	398.921772 =	1,196.765316	
111		8.000000 x	15.741598 =	125.932784	
115		8.000000 x	21.778427 =	174.227416	
115		8.000000 x	21.778427 =	174.227416	

		ΑΘΡΟΙΣΜΑ =		1,773.762932	

		H.Δ. =		1,951.139225	
565	565				
450		3.000000 x	83.850000 =	251.550000	
465		1.000000 x	102.610000 =	102.610000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	

		H.Δ. =		789.728540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
112		1.000000 x	17.312112 =	17.312112	
466		1.000000 x	47.860000 =	47.860000	
115		2.000000 x	21.778427 =	43.556854	

		ΑΘΡΟΙΣΜΑ =		108.728966	

		H.Δ. =			
567	567				
450		1.000000 x	83.850000 =	83.850000	
112		4.000000 x	17.312112 =	69.248448	
115		4.000000 x	21.778427 =	87.113708	
214		4.000000 x	4.160000 =	16.640000	
211		90.000000 x	1.175600 =	105.804000	

		ΑΘΡΟΙΣΜΑ =		362.656156	

		H.Δ. =		398.921772	

568.1	568.1				
467		1.000000 x	348.520000 =	348.520000	
567		2.000000 x	398.921772 =	797.843544	
512		.240000 x	106.795786 =	25.630989	
510		.072000 x	402.161470 =	28.955626	
118		32.000000 x	10.001019 =	320.032608	
114		8.000000 x	23.886192 =	191.089536	
113		32.000000 x	20.419486 =	653.423552	
214		16.000000 x	4.160000 =	66.560000	
			AΘΡΟΙΣΜΑ =	2,432.055854	
			H.Δ. =	2,675.261440	
568.2	568.2				
450		2.000000 x	83.850000 =	167.700000	
115		8.000000 x	21.778427 =	174.227416	
467		1.000000 x	348.520000 =	348.520000	
114		8.000000 x	23.886192 =	191.089536	
			H.Δ. =	881.536952	
569.1	569.1				
468		1.000000 x	87.280000 =	87.280000	
214		16.000000 x	4.160000 =	66.560000	
567		2.000000 x	398.921772 =	797.843544	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
			AΘΡΟΙΣΜΑ =	1,222.781232	
			H.Δ. =	1,345.059355	
569.2	569.2				
450		2.000000 x	83.850000 =	167.700000	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
468		1.000000 x	87.280000 =	87.280000	
			H.Δ. =	620.296952	
570.1	570.1				
469		1.000000 x	87.280000 =	87.280000	
211		135.000000 x	1.175600 =	158.706000	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
214		16.000000 x	4.160000 =	66.560000	
			AΘΡΟΙΣΜΑ =	543.639612	
			H.Δ. =	598.003573	

570.2	570.2				
469		1.000000 x	87.280000 =		87.280000
118		4.000000 x	10.001019 =		40.004076
				H.Δ. =	127.284076
571.1	571.1				
470		1.000000 x	70.390000 =		70.390000
114		8.000000 x	23.886192 =		191.089536
214		4.000000 x	4.160000 =		16.640000
211		114.000000 x	1.175600 =		134.018400
				AΘΡΟΙΣΜΑ =	412.137936
				H.Δ. =	453.351730
571.2	571.2				
470		1.000000 x	70.390000 =		70.390000
114		8.000000 x	23.886192 =		191.089536
				H.Δ. =	261.479536
572	572				
407		1.000000 x	55.210000 =		55.210000
471		1.000000 x	61.000000 =		61.000000
114		8.000000 x	23.886192 =		191.089536
214		8.000000 x	4.160000 =		33.280000
111		24.000000 x	15.741598 =		377.798352
211		54.000000 x	1.175600 =		63.482400
				AΘΡΟΙΣΜΑ =	781.860288
				H.Δ. =	860.046317
573	573				
407		1.000000 x	55.210000 =		55.210000
473		.250000 x	17.050000 =		4.262500
474		.250000 x	35.040000 =		8.760000
474		1.000000 x	35.040000 =		35.040000
473		1.000000 x	17.050000 =		17.050000
115		16.000000 x	21.778427 =		348.454832
111		24.000000 x	15.741598 =		377.798352
214		8.000000 x	4.160000 =		33.280000
211		54.000000 x	1.175600 =		63.482400
407		.250000 x	55.210000 =		13.802500
472		.250000 x	26.510000 =		6.627500
472		1.000000 x	26.510000 =		26.510000
				AΘΡΟΙΣΜΑ =	990.278084
				H.Δ. =	1,089.305892

574	574				
475		1.000000 x	1,970.400000 =		1,970.400000
214		30.000000 x	4.160000 =		124.800000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
111		16.000000 x	15.741598 =		251.865568
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	1.175600 =		693.604000
				ΑΘΡΟΙΣΜΑ =	3,346.767256
				Η.Δ. =	3,681.443982
574.1	574.1				
475		1.000000 x	1,970.400000 =		1,970.400000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				Η.Δ. =	2,241.497688
575	575				
476		1.000000 x	85.400000 =		85.400000
214		23.000000 x	4.160000 =		95.680000
115		8.000000 x	21.778427 =		174.227416
211		470.000000 x	1.175600 =		552.532000
				ΑΘΡΟΙΣΜΑ =	907.839416
				Η.Δ. =	998.623358
575.1	575.1				
476		1.000000 x	85.400000 =		85.400000
115		8.000000 x	21.778427 =		174.227416
				Η.Δ. =	259.627416
576	576				
477		1.000000 x	6.950000 =		6.950000
				ΑΘΡΟΙΣΜΑ =	6.950000
				Η.Δ. =	7.645000
576.1	576.1				
477		1.000000 x	6.950000 =		6.950000
				Η.Δ. =	6.950000

577	577				
478		1.000000 x	115.120000 =	115.120000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	4.160000 =	16.640000	
211		70.000000 x	1.175600 =	82.292000	

		ΑΘΡΟΙΣΜΑ =		621.082472	

		H.Δ. =		683.190719	
577.1	577.1				
478		1.000000 x	115.120000 =	115.120000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

		H.Δ. =		386.217688	
578	578				
479		1.000000 x	185.200000 =	185.200000	
211		50.000000 x	1.175600 =	58.780000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	4.160000 =	20.800000	

		ΑΘΡΟΙΣΜΑ =		590.122060	

		H.Δ. =		649.134266	
579	579				
480		1.000000 x	27.220000 =	27.220000	
212		28.000000 x	1.433300 =	40.132400	
117		8.000000 x	16.777917 =	134.223336	
214		1.000000 x	4.160000 =	4.160000	

		ΑΘΡΟΙΣΜΑ =		205.735736	

		H.Δ. =		226.309310	
580	580				
481		1.000000 x	812.490000 =	812.490000	
211		168.000000 x	1.175600 =	197.500800	
242		2.000000 x	5.000000 =	10.000000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
111		16.000000 x	15.741598 =	251.865568	
214		8.000000 x	4.160000 =	33.280000	

		ΑΘΡΟΙΣΜΑ =		1,576.234056	

		H.Δ. =		1,733.857462	

581	581			
481		1.000000 x	812.490000 =	812.490000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
			H.Δ. =	1,083.587688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.150000 x	261.479536 =	39.221930
571.1		.350000 x	453.351730 =	158.673106
570.2		.350000 x	127.284076 =	44.549427
570.1		.150000 x	598.003573 =	89.700536
569.2		.670000 x	620.296952 =	415.598958
569.1		.330000 x	1,345.059355 =	443.869587
568.2		.550000 x	881.536952 =	484.845324
568.1		.450000 x	2,675.261440 =	1,203.867648
567		1.000000 x	398.921772 =	398.921772
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,568.536959
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.240000 x	261.479536 =	62.755089
571.1		.260000 x	453.351730 =	117.871450
570.2		.390000 x	127.284076 =	49.640790
570.1		.110000 x	598.003573 =	65.780393
569.2		.750000 x	620.296952 =	465.222714
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	398.921772 =	398.921772
568.1		.250000 x	2,675.261440 =	668.815360
569.1		.250000 x	1,345.059355 =	336.264839
568.2		.750000 x	881.536952 =	661.152714
			H.Δ. =	3,115.713792
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.310000 x	261.479536 =	81.058656
571.1		.190000 x	453.351730 =	86.136829
570.2		.420000 x	127.284076 =	53.459312
570.1		.080000 x	598.003573 =	47.840286
569.2		.820000 x	620.296952 =	508.643501
569.1		.180000 x	1,345.059355 =	242.110684
568.2		.850000 x	881.536952 =	749.306409
568.1		.150000 x	2,675.261440 =	401.289216
567		1.000000 x	398.921772 =	398.921772
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	2,858.055336

613	613			
111		.140000 x	15.741598 =	2.203824
520		.003500 x	446.296994 =	1.562039
503		.000770 x	923.834573 =	.711353
504		.002800 x	384.772890 =	1.077364

			B.T =	5.554580
614	614			
112		.070000 x	17.312112 =	1.211848
504		.002800 x	384.772890 =	1.077364
518		.004375 x	894.100992 =	3.911692
509		.004375 x	412.666470 =	1.805416
503		.000700 x	923.834573 =	.646684

			B.T =	8.653004
621.1	621.1			
213		.100000 x	1.949500 =	.194950
116		.140000 x	20.419486 =	2.858728
504		.003500 x	384.772890 =	1.346705
508		.003500 x	586.783432 =	2.053742
111		.560000 x	15.741598 =	8.815295

			B.T =	15.269420
622	622			
213		.100000 x	1.949500 =	.194950
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728
509		.003500 x	412.666470 =	1.444333
508		.003500 x	586.783432 =	2.053742
518		.004340 x	894.100992 =	3.880398
504		.003500 x	384.772890 =	1.346705

			B.T =	12.990704
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.649312 =	55.363258
6330		.038000 x	182.178551 =	6.922785
6330		.190000 x	182.178551 =	34.613925
6314		.382500 x	2.016845 =	.771443
6314		7.650000 x	2.016845 =	15.428864

			B.T =	113.100275
6360.1 A2	6360.1 A2			
6304		.450000 x	5.649312 =	2.542190
6310		2.142000 x	1.440603 =	3.085772
6330		.013000 x	182.178551 =	2.368321

			B.T =	7.996283

6360.1 A3	6360.1 A3			
6304		.960000 x	5.649312 =	5.423340
6329.2		.037000 x	167.634362 =	6.202471
6310		1.974000 x	1.440603 =	2.843750

			B.T =	14.469561
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.649312 =	14.066787
6329.2		.109000 x	167.634362 =	18.272145

			B.T =	32.338932
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
113		.425000 x	20.419486 =	8.678282
6069.1		.056400 x	11.726310 =	.661364

			B.T =	99.518207
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.649312 =	60.165173
6314		.392500 x	2.016845 =	.791612
6314		7.850000 x	2.016845 =	15.832233
6330		.041000 x	182.178551 =	7.469321
6330		.205000 x	182.178551 =	37.346603

			B.T =	121.604941
6360.2 A2	6360.2 A2			
6304		.750000 x	5.649312 =	4.236984
6330		.019000 x	182.178551 =	3.461392
6310		2.383500 x	1.440603 =	3.433677

			B.T =	11.132054
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.649312 =	6.440216
6310		2.341500 x	1.440603 =	3.373172
6329.2		.054000 x	167.634362 =	9.052256

			B.T =	18.865643
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.649312 =	15.818074
6329.2		.118000 x	167.634362 =	19.780855

			B.T =	35.598928

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
113		.382500 x	20.419486 =	7.810453
113		2.975000 x	20.419486 =	60.747971
6069.1		.059400 x	11.726310 =	.696543

			B.T =	113.400853
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.649312 =	78.525437
6314		.557500 x	2.016845 =	1.124391
6314		11.150000 x	2.016845 =	22.487822
6330		.270000 x	182.178551 =	49.188209
6330		.054000 x	182.178551 =	9.837642

			B.T =	161.163500
6360.3 A2	6360.3 A2			
6304		.940000 x	5.649312 =	5.310353
6330		.031000 x	182.178551 =	5.647535
6310		3.360000 x	1.440603 =	4.840426

			B.T =	15.798314
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.649312 =	10.338241
6310		10.678500 x	1.440603 =	15.383479
6329.2		.099000 x	167.634362 =	16.595802

			B.T =	42.317522
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.649312 =	19.320647
6329.2		.139000 x	167.634362 =	23.301176

			B.T =	42.621823
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		.340000 x	20.419486 =	6.942625
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.726310 =	.865402

			B.T =	156.847769

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.649312 =	91.801320
6314		.885000 x	2.016845 =	1.784908
6314		17.700000 x	2.016845 =	35.698157
6330		.075000 x	182.178551 =	13.663391
6330		.375000 x	182.178551 =	68.316957

			B.T =	211.264732
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.649312 =	5.988271
6330		.048000 x	182.178551 =	8.744570
6310		4.641000 x	1.440603 =	6.685839

			B.T =	21.418680
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.649312 =	12.823938
6310		20.454000 x	1.440603 =	29.466094
6329.2		.125000 x	167.634362 =	20.954295

			B.T =	63.244327
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.649312 =	15.818074
6329.2		.118000 x	167.634362 =	19.780855

			B.T =	35.598928
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		.297500 x	20.419486 =	6.074797
113		4.250000 x	20.419486 =	86.782816
6069.1		.091800 x	11.726310 =	1.076475

			B.T =	211.656449
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.649312 =	101.405150
6314		1.050000 x	2.016845 =	2.117687
6314		21.000000 x	2.016845 =	42.353745
6330		.088000 x	182.178551 =	16.031712
6330		.440000 x	182.178551 =	80.158562

			B.T =	242.066858
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.649312 =	6.892161
6330		.061000 x	182.178551 =	11.112892
6310		6.048000 x	1.440603 =	8.712767

			B.T =	26.717819

ΑΤΥΠ	3ο Τρίμηνο του 2011	Σελ. Ημ/νία	31 22/12/2011
6360.5 A3	6360.5 A3		
6304	2.480000 x	5.649312 =	14.010294
6310	22.291500 x	1.440603 =	32.113202
6329.2	.144000 x	167.634362 =	24.139348

		B.T =	70.262844
6360.5 A4	6360.5 A4		
6304	3.200000 x	5.649312 =	18.077798
6329.2	.112000 x	167.634362 =	18.775049

		B.T =	36.852847
6360.5 A5	6360.5 A5		
112	9.350000 x	17.312112 =	161.868247
113	5.950000 x	20.419486 =	121.495942
113	.255000 x	20.419486 =	5.206969
6069.1	.090600 x	11.726310 =	1.062404

		B.T =	289.633562
6360.6 A1	6360.6 A1		
6304	20.350000 x	5.649312 =	114.963499
6314	24.900000 x	2.016845 =	50.219441
6330	.116000 x	182.178551 =	21.132712
6330	.580000 x	182.178551 =	105.663560
6314	1.245000 x	2.016845 =	2.510972

		B.T =	294.490183
6360.6 A2	6360.6 A2		
6304	1.530000 x	5.649312 =	8.643447
6330	.092000 x	182.178551 =	16.760427
6310	10.206000 x	1.440603 =	14.702794

		B.T =	40.106668
6360.6 A3	6360.6 A3		
6304	2.670000 x	5.649312 =	15.083663
6329.2	.181000 x	167.634362 =	30.341820
6310	25.798500 x	1.440603 =	37.165396

		B.T =	82.590879
6360.6 A4	6360.6 A4		
6304	2.800000 x	5.649312 =	15.818074
6329.2	.118000 x	167.634362 =	19.780855

		B.T =	35.598928

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	.212500 x	20.419486 =	4.339141
6069.1	.120000 x	11.726310 =	1.407157
113	7.650000 x	20.419486 =	156.209068

B.T = 382.684794

641

641

231	.200000 x	.861000 =	.172200
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
111	.170000 x	15.741598 =	2.676072
252	.002500 x	290.000000 =	.725000

B.T = 6.611756

651

651

221	150.000000 x	.099900 =	14.985000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	412.666470 =	3.893508
509	.003060 x	412.666470 =	1.262759
T 630	.600000 x	1.815528 =	1.089317
T 625	.850000 x	21.888537 =	18.605256
511	.042500 x	728.610485 =	30.965946
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 106.629971

652

652

221	650.000000 x	.099900 =	64.935000
T 630	.320000 x	1.815528 =	.580969
T 625	1.000000 x	21.888537 =	21.888537
511	.042500 x	728.610485 =	30.965946
509	.001632 x	412.666470 =	.673472
509	.009435 x	412.666470 =	3.893508
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648

B.T = 150.365616

652.1

652.1

221	450.000000 x	.099900 =	44.955000
111	1.275000 x	15.741598 =	20.070537
509	.010001 x	412.666470 =	4.127077
T 630	.320000 x	1.815528 =	.580969
T 625	1.060000 x	21.888537 =	23.201849
511	.042500 x	728.610485 =	30.965946
510	.001632 x	402.161470 =	.656328
112	.425000 x	17.312112 =	7.357648

B.T = 131.915354

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
509		.007548 x	412.666470 =	3.114807
T 630		.320000 x	1.815528 =	.580969
T 625		.800000 x	21.888537 =	17.510830
511		.042500 x	728.610485 =	30.965946
510		.001632 x	402.161470 =	.656328
111		1.275000 x	15.741598 =	20.070537
112		.425000 x	17.312112 =	7.357648
			B.T =	170.167063
700	700			
397.4		4.000000 x	.167500 =	.670000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.099900 =	1.298700
113		.935000 x	20.419486 =	19.092219
			B.T =	
7001 A	7001 A			
502		.000365 x	807.885773 =	.294878
557		.001094 x	830.176257 =	.908213
			AΘΡΟΙΣΜΑ =	1.203091
	B.T =	.200000 x	1.203091 =	.240618
7001 B	7001 B			
558		.000700 x	1,128.256457 =	.789780
			B.T =	.789780
7001 E	7001 E			
503		.000875 x	923.834573 =	.808355
554		.000875 x	34.408000 =	.030107
			B.T =	.838462
7001 Γ	7001 Γ			
501		.000700 x	616.849852 =	.431795
502		.000700 x	807.885773 =	.565520
			B.T =	.997315

7001 Δ	7001 Δ			
502		.000292 x	807.885773 =	.235903
510		.000292 x	402.161470 =	.117431
X 630.1		.060000 x	1.689078 =	.101345
X 630		.060000 x	1.495141 =	.089708

			AΘΡΟΙΣΜΑ =	.544387
	B.T =	.600000 x	.544387 =	.326632

7003 Α	7003 Α			
502		.000365 x	807.885773 =	.294878
557		.001094 x	830.176257 =	.908213

			AΘΡΟΙΣΜΑ =	1.203091
	B.T =	.100000 x	1.203091 =	.120309

7003 Β	7003 Β			
559		.000464 x	1,330.216457 =	.617220

			B.T =	.617220
7003 Γ	7003 Γ			
502		.000700 x	807.885773 =	.565520

			B.T =	.565520
7003 Δ	7003 Δ			
502		.000875 x	807.885773 =	.706900
562		.000875 x	123.820400 =	.108343

			B.T =	.815243
7005 Α	7005 Α			
502		.000365 x	807.885773 =	.294878
557		.001094 x	830.176257 =	.908213

			AΘΡΟΙΣΜΑ =	1.203091
	B.T =	.100000 x	1.203091 =	.120309

7005 Β	7005 Β			
559		.000812 x	1,330.216457 =	1.080136

			B.T =	1.080136
7005 Ε	7005 Ε			
502		.000875 x	807.885773 =	.706900
562		.000875 x	123.820400 =	.108343

			B.T =	.815243

7005 Γ	7005 Γ			
559		.000232 x	1,330.216457 =	.308610

			B.T =	.308610
7005 Δ	7005 Δ			
502		.000700 x	807.885773 =	.565520

			B.T =	.565520
7010 Α	7010 Α			
558		.000315 x	1,128.256457 =	.355401

			B.T =	.355401
7010 Β	7010 Β			
558		.000473 x	1,128.256457 =	.533665

			B.T =	.533665
7010 Ε	7010 Ε			
503		.000875 x	923.834573 =	.808355
553		.000875 x	254.639000 =	.222809

			B.T =	1.031164
7010 Γ	7010 Γ			
502		.000700 x	807.885773 =	.565520

			B.T =	.565520
7010 Δ	7010 Δ			
502		.000292 x	807.885773 =	.235903
X 630		.060000 x	1.495141 =	.089708
X 630.1		.060000 x	1.689078 =	.101345
510		.000292 x	402.161470 =	.117431

			AΘΡΟΙΣΜΑ =	.544387
	B.T =	.600000 x	.544387 =	.326632

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.830000 x	18.620597 =	15.455096
T 617		.500000 x	6.424669 =	3.212335
509		.007831 x	412.666470 =	3.231591
509		.004718 x	412.666470 =	1.946960
223		350.000000 x	.119300 =	41.755000

			B.T =	78.957619

7016.2	7016.2			
570.1		.586500 x	598.003573 =	350.729096
570.2		1.113500 x	127.284076 =	141.730819
571.2		1.113500 x	261.479536 =	291.157463
571.1		.586500 x	453.351730 =	265.890790

			ΑΘΡΟΙΣΜΑ =	1,049.508167
	B.T =	.025000 x	1,049.508167 =	26.237704

7016.3	7016.3			
564		.212500 x	1,951.139225 =	414.617085
565		.637500 x	789.728540 =	503.451944

			ΑΘΡΟΙΣΜΑ =	918.069030
	B.T =	.025000 x	918.069030 =	22.951726

7016.4	7016.4			
7016.1		1.000000 x	78.957619 =	78.957619
7016.2		1.000000 x	26.237704 =	26.237704
7016.3		1.000000 x	22.951726 =	22.951726

			B.T =	128.147049
7016.5	7016.5			
7016.4		.200000 x	128.147049 =	25.629410

			B.T =	25.629410
7016.6	7016.6			
7016.4		.250000 x	128.147049 =	32.036762
7016.5		.250000 x	25.629410 =	6.407353

			B.T =	38.444115
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.830000 x	18.620597 =	15.455096
T 617		.500000 x	6.424669 =	3.212335
509		.007831 x	412.666470 =	3.231591
509		.004718 x	412.666470 =	1.946960
223		350.000000 x	.119300 =	41.755000
			B.T =	78.957619
7017.2	7017.2			
564		.425000 x	1,951.139225 =	829.234171
565		.425000 x	789.728540 =	335.634630
			AΘΡΟΙΣΜΑ =	1,164.868800
	B.T =	.012500 x	1,164.868800 =	14.560860
7017.3	7017.3			
7017.1		1.000000 x	78.957619 =	78.957619
7017.2		1.000000 x	14.560860 =	14.560860
			B.T =	93.518479
7017.4	7017.4			
7017.3		.200000 x	93.518479 =	18.703696
			B.T =	18.703696
7017.5	7017.5			
7017.3		.300000 x	93.518479 =	28.055544
7017.4		.300000 x	18.703696 =	5.611109
			B.T =	33.666653
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150
			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689
			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
223		350.000000 x	.119300 =	41.755000

			B.T =	79.524151
7019 A2	7019 A2			
555		.012143 x	775.134131 =	9.412454

			B.T =	9.412454
7019 A3	7019 A3			
570.1		.850000 x	598.003573 =	508.303037
571.1		.850000 x	453.351730 =	385.348971
571.2		.850000 x	261.479536 =	222.257606
570.2		.850000 x	127.284076 =	108.191465

			ΑΘΡΟΙΣΜΑ =	1,224.101078
	B.T =	.014286 x	1,224.101078 =	17.487508

7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563

			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	79.524151 =	79.524151
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A2		1.000000 x	9.412454 =	9.412454
7019 A3		1.000000 x	17.487508 =	17.487508
7019 A5		1.000000 x	17.356563 =	17.356563

			B.T =	193.018130
7019 A7	7019 A7			
7019 A6		.100000 x	193.018130 =	19.301813

			B.T =	19.301813

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
252		.001000 x	290.000000 =	.290000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	384.772890 =	1.933484
509		.003750 x	412.666470 =	1.547499

			B.T =	3.480983
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	446.296994 =	2.351985
504		.004250 x	384.772890 =	1.635285
503		.001190 x	923.834573 =	1.099363

			B.T =	6.424669
T 621	T 621			
213		.100000 x	1.949500 =	.194950
508		.004250 x	586.783432 =	2.493830
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.864379
T 623	T 623			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
508		.004250 x	586.783432 =	2.493830
509		.004250 x	412.666470 =	1.753832
518		.008500 x	894.100992 =	7.599858
504		.004250 x	384.772890 =	1.635285

			B.T =	18.620597

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
504		.004250 x	384.772890 =	1.635285
509		.004250 x	412.666470 =	1.753832
518		.012155 x	894.100992 =	10.867798
508		.004250 x	586.783432 =	2.493830
116		.170000 x	20.419486 =	3.471313

			B.T =	21.888537
T 630	T 630			
512		.017000 x	106.795786 =	1.815528

			B.T =	1.815528
T 630.1	T 630.1			
510		.005100 x	402.161470 =	2.051023

			B.T =	2.051023
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
520		.004340 x	446.296994 =	1.936929
504		.003500 x	384.772890 =	1.346705
503		.000980 x	923.834573 =	.905358

			B.T =	5.290904
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	586.783432 =	2.053742
111		.560000 x	15.741598 =	8.815295
116		.140000 x	20.419486 =	2.858728

			B.T =	13.922715
X 623	X 623			
213		.100000 x	1.949500 =	.194950
504		.003500 x	384.772890 =	1.346705
518		.007000 x	894.100992 =	6.258707
509		.003500 x	412.666470 =	1.444333
508		.003500 x	586.783432 =	2.053742
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	15.369013

X 625	X 625			
213		.100000 x	1.949500 =	.194950
509		.003500 x	412.666470 =	1.444333
518		.010010 x	894.100992 =	8.949951
504		.003500 x	384.772890 =	1.346705
508		.003500 x	586.783432 =	2.053742
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728

			B.T =	18.060257
X 630	X 630			
512		.014000 x	106.795786 =	1.495141

			B.T =	1.495141
X 630.1	X 630.1			
510		.004200 x	402.161470 =	1.689078

			B.T =	1.689078
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	412.666470 =	1.946960
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.007548 x	412.666470 =	3.114807
509		.001275 x	412.666470 =	.526150
T 625		.500000 x	21.888537 =	10.944269
641		3.000000 x	6.611756 =	19.835268
T 630		.250000 x	1.815528 =	.453882

			T.E =	154.832484
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	412.666470 =	7.997476

			T.E =	74.899268
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	412.666470 =	3.332282

			T.E =	43.473357
6051	6051			
502		.000175 x	807.885773 =	.141380

			T.E =	.141380

6052	6052			
501		.000117 x	616.849852 =	.072171
502		.000088 x	807.885773 =	.071094
521		.000088 x	426.676373 =	.037548

			T.E =	.180813
6053	6053			
502		.000318 x	807.885773 =	.256908
507		.001000 x	948.916857 =	.948917

			T.E =	1.205825
6054	6054			
112		.004900 x	17.312112 =	.084829
509		.002975 x	412.666470 =	1.227683
507		.001077 x	948.916857 =	1.021983

			T.E =	2.334496
6055	6055			
213		.400000 x	1.949500 =	.779800
503		.001167 x	923.834573 =	1.078115
508		.007000 x	586.783432 =	4.107484
504		.001400 x	384.772890 =	.538682
112		.490000 x	17.312112 =	8.482935
116		.280000 x	20.419486 =	5.717456

			T.E =	20.704472
6056	6056			
507		.001750 x	948.916857 =	1.660604

			T.E =	1.660604
6057	6057			
506		.087500 x	689.655657 =	60.344870

			T.E =	60.344870
6058	6058			
507		.087500 x	948.916857 =	83.030225

			T.E =	83.030225
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
507		.001077 x	948.916857 =	1.021983
509		.002975 x	412.666470 =	1.227683
501		.000583 x	616.849852 =	.359623
502		.001400 x	807.885773 =	1.131040

			T.E =	3.861515
6062	6062			
213		.400000 x	1.949500 =	.779800
509		.002800 x	412.666470 =	1.155466
508		.002800 x	586.783432 =	1.642994
507		.001400 x	948.916857 =	1.328484
502		.002000 x	807.885773 =	1.615772
116		.175000 x	20.419486 =	3.573410
112		.175000 x	17.312112 =	3.029620

			T.E =	13.125545
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.070000 x	17.312112 =	1.211848
509		.003641 x	412.666470 =	1.502519
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.468388
6064	6064			
112		.140000 x	17.312112 =	2.423696
509		.003641 x	412.666470 =	1.502519
507		.014000 x	948.916857 =	13.284836
112		.070000 x	17.312112 =	1.211848

			T.E =	18.422898
6065	6065			
506		.002800 x	689.655657 =	1.931036
506		.002100 x	689.655657 =	1.448277

			T.E =	3.379313

6066	6066				
111		.070000 x	15.741598 =	1.101912	
502		.000700 x	807.885773 =	.565520	

				T.E =	1.667432
6067	6067				
111		.980000 x	15.741598 =	15.426766	
X 630		.100000 x	1.495141 =	.149514	
X 630.1		.100000 x	1.689078 =	.168908	

				T.E =	15.745188
6068	6068				
111		.560000 x	15.741598 =	8.815295	
622		1.351351 x	12.990704 =	17.555001	
X 630.1		.200000 x	1.689078 =	.337816	
X 630		.200000 x	1.495141 =	.299028	
112		.560000 x	17.312112 =	9.694783	
509		.016497 x	412.666470 =	6.807759	

				T.E =	43.509681
6068.1	6068.1				
111		.560000 x	15.741598 =	8.815295	
X 630.1		.200000 x	1.689078 =	.337816	
X 630		.200000 x	1.495141 =	.299028	
614		1.351351 x	8.653004 =	11.693246	
509		.016497 x	412.666470 =	6.807759	
112		.560000 x	17.312112 =	9.694783	

				T.E =	37.647926
6069	6069				
112		.070000 x	17.312112 =	1.211848	
509		.012017 x	412.666470 =	4.959013	
X 625		1.050000 x	18.060257 =	18.963270	

				T.E =	25.134131
6069.1	6069.1				
112		.070000 x	17.312112 =	1.211848	
509		.012017 x	412.666470 =	4.959013	
X 617		1.050000 x	5.290904 =	5.555449	

				T.E =	11.726310
6070	6070				
501		.000467 x	616.849852 =	.288069	

				T.E =	.288069

6071	6071			
504		.002333 x	384.772890 =	.897675
509		.002975 x	412.666470 =	1.227683

			T.E =	2.125358
6072	6072			
504		.003500 x	384.772890 =	1.346705
509		.002800 x	412.666470 =	1.155466

			T.E =	2.502171
6073	6073			
509		.000833 x	412.666470 =	.343751

			T.E =	.343751
6074	6074			
509		.000784 x	412.666470 =	.323531

			T.E =	.323531
6075	6075			
509		.001096 x	412.666470 =	.452282

			T.E =	.452282
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	923.834573 =	.646684
509		.003914 x	412.666470 =	1.615177
507		.000840 x	948.916857 =	.797090

			T.E =	3.143780
6077	6077			
503		.001400 x	923.834573 =	1.293368

			T.E =	1.293368
6078	6078			
112		.004900 x	17.312112 =	.084829
505		.001400 x	836.602457 =	1.171243
501		.000056 x	616.849852 =	.034544
503		.000350 x	923.834573 =	.323342

			T.E =	1.613958

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
501		.000056 x	616.849852 =	.034544
503		.000350 x	923.834573 =	.323342
556		.001400 x	1,142.677457 =	1.599748

			T.E =	2.042463
6079	6079			
112		.014000 x	17.312112 =	.242370
501		.000700 x	616.849852 =	.431795
529		.000980 x	448.377173 =	.439410
X 630		.150000 x	1.495141 =	.224271
509		.000630 x	412.666470 =	.259980
502		.000350 x	807.885773 =	.282760

			T.E =	1.880585
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.689078 =	.168908
X 630		.100000 x	1.495141 =	.149514
529		.000700 x	448.377173 =	.313864
502		.000292 x	807.885773 =	.235903
501		.000583 x	616.849852 =	.359623

			T.E =	1.470182
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087
506		.007000 x	689.655657 =	4.827590

			T.E =	23.557539
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.557539 =	23.557539

			T.E =	35.788505
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.557539 =	23.557539
112		.140000 x	17.312112 =	2.423696

			T.E =	48.019472

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.557539 =	23.557539
112		.210000 x	17.312112 =	3.635544

			T.E =	60.250438
6082.1	6082.1			
213		.400000 x	1.949500 =	.779800
111		1.400000 x	15.741598 =	22.038237
116		.700000 x	20.419486 =	14.293640
508		.070000 x	586.783432 =	41.074840
116		1.400000 x	20.419486 =	28.587280

			T.E =	106.773798
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
6082.1		1.000000 x	106.773798 =	106.773798
112		.140000 x	17.312112 =	2.423696

			T.E =	120.216612
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	106.773798 =	106.773798
112		.280000 x	17.312112 =	4.847391

			T.E =	133.659427
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
112		.420000 x	17.312112 =	7.271087
6082.1		1.000000 x	106.773798 =	106.773798

			T.E =	147.102241
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.280000 x	17.312112 =	4.847391
506		.005833 x	689.655657 =	4.022761
112		.140000 x	17.312112 =	2.423696

			T.E =	15.701496
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.701496 =	15.701496
112		.070000 x	17.312112 =	1.211848

			T.E =	25.728639

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.701496 =	15.701496

			T.E =	35.755781
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
112		.210000 x	17.312112 =	3.635544
6083.1		1.000000 x	15.701496 =	15.701496

			T.E =	45.782924
6084.1	6084.1			
213		.400000 x	1.949500 =	.779800
111		1.470000 x	15.741598 =	23.140149
116		.700000 x	20.419486 =	14.293640
508		.035000 x	586.783432 =	20.537420
116		1.050000 x	20.419486 =	21.440460

			T.E =	80.191470
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
112		.105000 x	17.312112 =	1.817772
6084.1		1.000000 x	80.191470 =	80.191470

			T.E =	90.824537
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	80.191470 =	80.191470

			T.E =	101.457603
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
112		.315000 x	17.312112 =	5.453315
6084.1		1.000000 x	80.191470 =	80.191470

			T.E =	112.090670
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	689.655657 =	3.217933
502		.001400 x	807.885773 =	1.131040
112		.140000 x	17.312112 =	2.423696

			T.E =	8.976493

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	8.976493 =	8.976493

			T.E =	15.697900
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	8.976493 =	8.976493

			T.E =	22.419307
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	8.976493 =	8.976493

			T.E =	29.140714
6086.1	6086.1			
213		.400000 x	1.949500 =	.779800
508		.008750 x	586.783432 =	5.134355
111		1.120000 x	15.741598 =	17.630590
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456

			T.E =	39.267749
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
112		.105000 x	17.312112 =	1.817772
6086.1		1.000000 x	39.267749 =	39.267749

			T.E =	46.595080
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
6086.1		1.000000 x	39.267749 =	39.267749
112		.210000 x	17.312112 =	3.635544

			T.E =	53.922411
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
6086.1		1.000000 x	39.267749 =	39.267749
112		.315000 x	17.312112 =	5.453315

			T.E =	61.249742

6087	6087				
252		.001000 x	290.000000 =		.290000
113		.210000 x	20.419486 =		4.288092
112		.350000 x	17.312112 =		6.059239
111		.210000 x	15.741598 =		3.305736

			T.E =		13.943067
6088	6088				
6081.1		1.000000 x	23.557539 =		23.557539
6081.1		.900000 x	23.557539 =		21.201785

			T.E =		44.759324
6089	6089				
6082.1		1.000000 x	106.773798 =		106.773798
6082.1		.900000 x	106.773798 =		96.096418

			T.E =		202.870216
6090	6090				
6083.1		1.000000 x	15.701496 =		15.701496
6083.1		1.300000 x	15.701496 =		20.411945

			T.E =		36.113441
6091	6091				
6084.1		1.000000 x	80.191470 =		80.191470
6084.1		1.300000 x	80.191470 =		104.248911

			T.E =		184.440381
6100	6100				
231		.200000 x	.861000 =		.172200
111		.175000 x	15.741598 =		2.754780
251		.002000 x	290.000000 =		.580000
113		.105000 x	20.419486 =		2.144046
252.1		.002000 x	.000000 =		.000000

			T.E =		
6101	6101				
231		15.000000 x	.861000 =		12.915000
252		.018000 x	290.000000 =		5.220000
113		3.500000 x	20.419486 =		71.468201
112		3.500000 x	17.312112 =		60.592392
252.1		.020000 x	.000000 =		.000000
251		.068000 x	290.000000 =		19.720000

			T.E =		

6102	6102			
244		1.000000 x	2.700000 =	2.700000
112		.002100 x	17.312112 =	.036355
112		.001400 x	17.312112 =	.024237
506		.000070 x	689.655657 =	.048276
509		.000051 x	412.666470 =	.021046
506		.000070 x	689.655657 =	.048276

			T.E =	2.878190
6103	6103			
244		.125000 x	2.700000 =	.337500
112		.002800 x	17.312112 =	.048474
112		.004200 x	17.312112 =	.072711
509		.000102 x	412.666470 =	.042092
506		.000140 x	689.655657 =	.096552
506		.000140 x	689.655657 =	.096552

			T.E =	.693880
6104	6104			
236		3.000000 x	.673000 =	2.019000
517		.017500 x	2,218.795889 =	38.828928
111		.280000 x	15.741598 =	4.407647
113		.280000 x	20.419486 =	5.717456

			T.E =	50.973032
6105	6105			
111		.210000 x	15.741598 =	3.305736
517		.014000 x	2,218.795889 =	31.063142
113		.140000 x	20.419486 =	2.858728

			T.E =	37.227606
6106	6106			
512		.087500 x	106.795786 =	9.344631

			T.E =	9.344631
6107	6107			
513		.087500 x	160.243179 =	14.021278

			T.E =	14.021278
6108	6108			
514		.087500 x	215.181732 =	18.828402

			T.E =	18.828402

6109	6109			
515		.087500 x	290.054608 =	25.379778

			T.E =	25.379778
6110	6110			
516		.087500 x	369.668484 =	32.345992

			T.E =	32.345992
6120	6120			
112		.004200 x	17.312112 =	.072711
502		.001750 x	807.885773 =	1.413800
501		.000070 x	616.849852 =	.043179

			T.E =	1.529690
6121	6121			
112		.004200 x	17.312112 =	.072711
509		.003113 x	412.666470 =	1.284631
502		.000315 x	807.885773 =	.254484
505		.000420 x	836.602457 =	.351373
507		.000875 x	948.916857 =	.830302
501		.000049 x	616.849852 =	.030226

			T.E =	2.823727
6151	6151			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000

			T.E =	2.640000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
T 611		1.050000 x	20.070537 =	21.074064
509		.003570 x	412.666470 =	1.473219
112		.425000 x	17.312112 =	7.357648

			T.E =	36.595110

6154	6154				
111		.425000 x	15.741598 =	6.690179	
T 621		1.050000 x	16.864379 =	17.707598	
112		.425000 x	17.312112 =	7.357648	
509		.003570 x	412.666470 =	1.473219	

			T.E =	33.228644	
6155	6155				
111		.680000 x	15.741598 =	10.704287	
T 621		.350000 x	16.864379 =	5.902533	
652		.100000 x	150.365616 =	15.036562	
509		.003220 x	412.666470 =	1.328786	
113		1.275000 x	20.419486 =	26.034845	

			T.E =	59.007012	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	150.365616 =	1.503656	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	

			T.E =	22.891554	
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	412.666470 =	1.213239	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.922715 =	14.618851	

			T.E =	29.714648	
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	412.666470 =	1.213239	
X 611		1.050000 x	16.528678 =	17.355112	
112		.420000 x	17.312112 =	7.271087	

			T.E =	32.450910	
6158	6158				
111		.560000 x	15.741598 =	8.815295	
621.1		1.050000 x	15.269420 =	16.032891	
509		.002940 x	412.666470 =	1.213239	
504		.001400 x	384.772890 =	.538682	

			T.E =	26.600107	

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	90.497781

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	27.291284	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.991284	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	35.991284	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	39.691284	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	62.697781	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	81.897781	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	101.797781	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	18.060257 =	12.642180
X 623		.400000 x	15.369013 =	6.147605
509		.005439 x	412.666470 =	2.244493
509		.003108 x	412.666470 =	1.282567
112		.420000 x	17.312112 =	7.271087

			T.E =	32.893668
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	412.666470 =	3.591024
613		1.050000 x	5.554580 =	5.832309

			T.E =	20.000155

6205	6205				
111		.210000 x	15.741598 =	3.305736	
112		.070000 x	17.312112 =	1.211848	
509		.002800 x	412.666470 =	1.155466	
613		1.000000 x	5.554580 =	5.554580	

			T.E =	11.227630	
6251	6251				
509		.002800 x	412.666470 =	1.155466	
613		1.000000 x	5.554580 =	5.554580	

			T.E =	6.710046	
6252	6252				
509		.000784 x	412.666470 =	.323531	

			T.E =	.323531	
6253	6253				
112		.210000 x	17.312112 =	3.635544	
X 630.1		.200000 x	1.689078 =	.337816	
501		.002917 x	616.849852 =	1.799351	
521		.007000 x	426.676373 =	2.986735	
X 630		.200000 x	1.495141 =	.299028	

			T.E =	9.058473	
6301	6301				
231		.200000 x	.861000 =	.172200	
252		.002500 x	290.000000 =	.725000	
113		.127500 x	20.419486 =	2.603484	
111		.170000 x	15.741598 =	2.676072	
251		.001500 x	290.000000 =	.435000	

			T.E =	6.611756	
6302	6302				
231		.300000 x	.861000 =	.258300	
251		.002000 x	290.000000 =	.580000	
111		.212500 x	15.741598 =	3.345090	
252		.004000 x	290.000000 =	1.160000	
113		1.232500 x	20.419486 =	25.167016	

			T.E =	30.510406	
6303	6303				
6302		.666660 x	30.510406 =	20.340067	

			T.E =	20.340067	

6304	6304			
234.2		.018000 x	1.006500 =	.018117
112		.212500 x	17.312112 =	3.678824
113		.010200 x	20.419486 =	.208279
113		.085000 x	20.419486 =	1.735656
235		.012000 x	.703000 =	.008436

			T.E =	5.649312
6310	6310			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6311	6311			
233.1		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6312	6312			
233.3		1.010000 x	8.150000 =	8.231500
233.3		.303000 x	8.150000 =	2.469450
113		.085000 x	20.419486 =	1.735656
113		.085000 x	20.419486 =	1.735656

			T.E =	14.172263
6313	6313			
233.2		1.050000 x	.598400 =	.628320
113		.025500 x	20.419486 =	.520697

			T.E =	1.149017
6314	6314			
233.2		1.050000 x	.598400 =	.628320
113		.068000 x	20.419486 =	1.388525

			T.E =	2.016845
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	20.419486 =	.017357

			T.E =	1.417357

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
113		.595000 x	20.419486 =	12.149594
509		.003302 x	412.666470 =	1.362625
509		.003019 x	412.666470 =	1.245840
T 630.1		.175000 x	2.051023 =	.358929
T 630		.175000 x	1.815528 =	.317717
T 625		.350000 x	21.888537 =	7.660988
T 623		.560000 x	18.620597 =	10.427534
T 621		.300000 x	16.864379 =	5.059314
511		.023800 x	728.610485 =	17.340930
509		.005284 x	412.666470 =	2.180530
112		.714000 x	17.312112 =	12.360848

			T.E =	96.493171

6322	6322			
221		140.000000 x	.099900 =	13.986000
509		.003019 x	412.666470 =	1.245840
T 623		.560000 x	18.620597 =	10.427534
T 630.1		.175000 x	2.051023 =	.358929
T 630		.175000 x	1.815528 =	.317717
T 625		.350000 x	21.888537 =	7.660988
511		.023800 x	728.610485 =	17.340930
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	412.666470 =	1.362625
509		.005284 x	412.666470 =	2.180530
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 97.455018

6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 106.641825

6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		.850000 x	20.419486 =	17.356563

T.E = 98.909891

6324	6324			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
112		1.020000 x	17.312112 =	17.658354
509		.004718 x	412.666470 =	1.946960
113		.850000 x	20.419486 =	17.356563
509		.007548 x	412.666470 =	3.114807

T.E = 111.636825

6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		.850000 x	20.419486 =	17.356563

T.E = 103.904891

6325	6325			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 116.631825

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		.850000 x	20.419486 =	17.356563

T.E = 108.899891

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
113		1.360000 x	20.419486 =	27.770501
112		1.190000 x	17.312112 =	20.601413

T.E = 134.983822

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		1.360000 x	20.419486 =	27.770501

T.E = 127.251888

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 157.268049

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		1.275000 x	20.419486 =	26.034845

T.E = 149.536115

6328	6328			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	412.666470 =	3.114807
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	412.666470 =	1.946960

T.E = 160.844362

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	412.666470 =	3.114807
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
113		1.445000 x	20.419486 =	29.506157

T.E = 153.112428

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 166.549362

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
509		.007548 x	412.666470 =	3.114807
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960

T.E = 158.817428

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 625		.500000 x	21.888537 =	10.944269
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
113		1.445000 x	20.419486 =	29.506157
511		.034000 x	728.610485 =	24.772756
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960

T.E = 167.634362

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
511		.034000 x	728.610485 =	24.772756
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960
113		1.445000 x	20.419486 =	29.506157

T.E = 159.902428

6330	6330			
223		420.000000 x	.119300 =	50.106000
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960
113		1.445000 x	20.419486 =	29.506157
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.042500 x	728.610485 =	30.965946

T.E = 182.178551

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	412.666470 =	1.946960
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	412.666470 =	3.114807
511		.042500 x	728.610485 =	30.965946
T 617		.500000 x	6.424669 =	3.212335
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478

T.E = 174.446617

6331	6331			
222		450.000000 x	.116200 =	52.290000
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
T 623		.800000 x	18.620597 =	14.896478
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
509		.004718 x	412.666470 =	1.946960
511		.042500 x	728.610485 =	30.965946
509		.007548 x	412.666470 =	3.114807
112		3.400000 x	17.312112 =	58.861181

T.E = 347.015550

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
511		.042500 x	728.610485 =	30.965946
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612

T.E = 339.283616

6351	6351			
221		120.000000 x	.099900 =	11.988000
509		.004246 x	412.666470 =	1.752182
509		.008020 x	412.666470 =	3.309585
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.450000 x	21.888537 =	9.849842
T 623		.850000 x	18.620597 =	15.827507
511		.034000 x	728.610485 =	24.772756
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 123.186054

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
509		.004246 x	412.666470 =	1.752182
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.850000 x	18.620597 =	15.827507
T 617		.450000 x	6.424669 =	2.891101
511		.034000 x	728.610485 =	24.772756
509		.008020 x	412.666470 =	3.309585
112		1.275000 x	17.312112 =	22.072943
113		1.275000 x	20.419486 =	26.034845

T.E = 116.227313

6352	6352			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 625		.500000 x	21.888537 =	10.944269
T 623		.800000 x	18.620597 =	14.896478
511		.034000 x	728.610485 =	24.772756
509		.004718 x	412.666470 =	1.946960
509		.007548 x	412.666470 =	3.114807
113		2.550000 x	20.419486 =	52.069689

T.E = 182.081591

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238
511		.034000 x	728.610485 =	24.772756
6301		1.000000 x	6.611756 =	6.611756
T 630.1		.250000 x	2.051023 =	.512756
T 630		.250000 x	1.815528 =	.453882
T 623		.800000 x	18.620597 =	14.896478
T 617		.500000 x	6.424669 =	3.212335
509		.007548 x	412.666470 =	3.114807
509		.004718 x	412.666470 =	1.946960
			T.E =	174.349657
6360.1	6360.1			
6360.1 A1		1.000000 x	113.100275 =	113.100275
6360.1 A2		1.000000 x	7.996283 =	7.996283
6360.1 A5		1.000000 x	99.518207 =	99.518207
6360.1 A4		1.000000 x	32.338932 =	32.338932
6360.1 A3		1.000000 x	14.469561 =	14.469561
			AΘΡΟΙΣΜΑ =	267.423258
	T.E =	.200000 x	267.423258 =	53.484652
6360.2	6360.2			
6360.2 A1		1.000000 x	121.604941 =	121.604941
6360.2 A2		1.000000 x	11.132054 =	11.132054
6360.2 A3		1.000000 x	18.865643 =	18.865643
6360.2 A4		1.000000 x	35.598928 =	35.598928
6360.2 A5		1.000000 x	113.400853 =	113.400853
			AΘΡΟΙΣΜΑ =	300.602419
	T.E =	.200000 x	300.602419 =	60.120484
6360.3	6360.3			
6360.3 A1		1.000000 x	161.163500 =	161.163500
6360.3 A2		1.000000 x	15.798314 =	15.798314
6360.3 A3		1.000000 x	42.317522 =	42.317522
6360.3 A5		1.000000 x	156.847769 =	156.847769
6360.3 A4		1.000000 x	42.621823 =	42.621823
			AΘΡΟΙΣΜΑ =	418.748928
	T.E =	.200000 x	418.748928 =	83.749786

6360.4	6360.4			
6360.4 A1		1.000000 x	211.264732 =	211.264732
6360.4 A2		1.000000 x	21.418680 =	21.418680
6360.4 A3		1.000000 x	63.244327 =	63.244327
6360.4 A5		1.000000 x	211.656449 =	211.656449
6360.4 A4		1.000000 x	35.598928 =	35.598928

			AΘΡΟΙΣΜΑ =	543.183116
	T.E =	.200000 x	543.183116 =	108.636623

6360.5	6360.5			
6360.5 A1		1.000000 x	242.066858 =	242.066858
6360.5 A2		1.000000 x	26.717819 =	26.717819
6360.5 A3		1.000000 x	70.262844 =	70.262844
6360.5 A5		1.000000 x	289.633562 =	289.633562
6360.5 A4		1.000000 x	36.852847 =	36.852847

			AΘΡΟΙΣΜΑ =	665.533930
	T.E =	.200000 x	665.533930 =	133.106786

6360.6	6360.6			
6360.6 A1		1.000000 x	294.490183 =	294.490183
6360.6 A2		1.000000 x	40.106668 =	40.106668
6360.6 A4		1.000000 x	35.598928 =	35.598928
6360.6 A3		1.000000 x	82.590879 =	82.590879
6360.6 A5		1.000000 x	382.684794 =	382.684794

			AΘΡΟΙΣΜΑ =	835.471452
	T.E =	.200000 x	835.471452 =	167.094290

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	42.680000 =	.128040

			T.E =	16.933809
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	20.419486 =	4.339141
111		.212500 x	15.741598 =	3.345090

			T.E =	8.339230

6372	6372				
396.11		1.050000 x	2.960000 =	3.108000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.741598 =	5.352143	
113		.340000 x	20.419486 =	6.942625	

			T.E =	16.641769	
6373	6373				
396.12		1.050000 x	4.250000 =	4.462500	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	21.069961	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	290.000000 =	.145000	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	150.365616 =	1.729205	
652.2		.005500 x	170.167063 =	.935919	

			T.E =	24.325968	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.741598 =	13.380358	
113		.850000 x	20.419486 =	17.356563	
652.2		.005500 x	170.167063 =	.935919	
652		.016500 x	150.365616 =	2.481033	

			T.E =	34.298873	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
113		1.700000 x	20.419486 =	34.713126	
652		.020000 x	150.365616 =	3.007312	

			T.E =	57.790976	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.790976 =	57.790976	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	150.365616 =	3.007312

			T.E =	27.054055
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	25,662.000000 =	25,662.000000
386.9		.150000 x	25,662.000000 =	3,849.300000

			T.E =	29,511.300000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	76,825.000000 =	76,825.000000
386.40		.150000 x	76,825.000000 =	11,523.750000

			T.E =	88,348.750000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	113,082.000000 =	113,082.000000
386.30		.150000 x	113,082.000000 =	16,962.300000

			T.E =	130,044.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17			
386.64		1.000000 x	153,664.000000 =	153,664.000000
386.64		.150000 x	153,664.000000 =	23,049.600000

			T.E =	176,713.600000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000

			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000

			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000

			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000

			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000

			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000

			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000

			T.E =	

6453.6	6453.6				
386.53		1.000000 x	134,053.000000 =		134,053.000000
386.53		.150000 x	134,053.000000 =		20,107.950000
				T.E =	154,160.950000
6453.7	6453.7				
386.54		1.000000 x	.000000 =		.000000
386.54		.150000 x	.000000 =		.000000
				T.E =	
6453.8	6453.8				
386.55		1.000000 x	.000000 =		.000000
386.55		.150000 x	.000000 =		.000000
				T.E =	
6453.9	6453.9				
386.56		1.000000 x	.000000 =		.000000
386.56		.150000 x	.000000 =		.000000
				T.E =	
6454.1	6454.1				
386.68		1.000000 x	.000000 =		.000000
386.68		.150000 x	.000000 =		.000000
				T.E =	
6454.10	6454.10				
386.77		1.000000 x	.000000 =		.000000
386.77		.150000 x	.000000 =		.000000
				T.E =	
6454.11	6454.11				
386.78		1.000000 x	.000000 =		.000000
386.78		.150000 x	.000000 =		.000000
				T.E =	
6454.12	6454.12				
386.79		1.000000 x	.000000 =		.000000
386.79		.150000 x	.000000 =		.000000
				T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	21,523.000000 =	21,523.000000
387.3		.100000 x	21,523.000000 =	2,152.300000

			T.E =	23,675.300000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	1.006500 =	209.352000
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.703000 =	237.614000

			AΘΡΟΙΣΜΑ =	3,605.860505

			T.E =	5,408.790757
6456.2	6456.2			
234.2		336.000000 x	1.006500 =	338.184000
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.703000 =	383.838000

			AΘΡΟΙΣΜΑ =	5,824.851551

			T.E =	8,154.792172
6456.3	6456.3			
234.2		384.000000 x	1.006500 =	386.496000
235		624.000000 x	.703000 =	438.672000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,656.973161

			T.E =	9,319.762425
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,664.000000 =	6,664.000000
389.4		.200000 x	6,664.000000 =	1,332.800000

			T.E =	7,996.800000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,629.000000 =	5,629.000000
390.14		.150000 x	5,629.000000 =	844.350000

			T.E =	6,473.350000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	8,188.000000 =	8,188.000000
390.31		.150000 x	8,188.000000 =	1,228.200000

			T.E =	9,416.200000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	15,362.000000 =	15,362.000000
393.1		.150000 x	15,362.000000 =	2,304.300000

			T.E =	17,666.300000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.950000 =	6.950000

			T.E =	6.950000
6501	6501			
237		1.000000 x	1.218000 =	1.218000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.574563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,218.795889 =	94.298825

			T.E =	97.241884
6505	6505			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603

6506	6506			
233.1		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6551.1	6551.1			
221		6.000000 x	.099900 =	.599400
113		.255000 x	20.419486 =	5.206969
111		.255000 x	15.741598 =	4.014107
261		1.000000 x	15.100000 =	15.100000

			T.E =	24.920476
6551.2	6551.2			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
111		.297500 x	15.741598 =	4.683125
113		.297500 x	20.419486 =	6.074797

			T.E =	37.857122
6551.3	6551.3			
221		10.000000 x	.099900 =	.999000
263		1.000000 x	32.400000 =	32.400000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	45.693769
6551.4	6551.4			
221		13.000000 x	.099900 =	1.298700
263.2		1.000000 x	46.700000 =	46.700000
113		.510000 x	20.419486 =	10.413938
111		.510000 x	15.741598 =	8.028215

			T.E =	66.440853
6551.5	6551.5			
221		16.000000 x	.099900 =	1.598400
113		.595000 x	20.419486 =	12.149594
111		.595000 x	15.741598 =	9.366251
264		1.000000 x	64.100000 =	64.100000

			T.E =	87.214245

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.834921

6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 255.002782

6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.649312 =	38.923760
6310		32.020000 x	1.440603 =	46.128108
6329.2		.418000 x	167.634362 =	70.071163
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 210.515992

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.016845 =	27.691282
6329.2		.478000 x	167.634362 =	80.129225
6304		9.290000 x	5.649312 =	52.482108

T.E = 177.659178

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
113		.025500 x	20.419486 =	.520697
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	13.520000 =	13.520000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

			T.E =	28.026354
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	17.490000 =	17.490000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

			T.E =	32.732118
6611.3	6611.3			
361.3		1.000000 x	22.200000 =	22.200000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

			T.E =	40.450494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	42.370000 =	42.370000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

			T.E =	69.712368
6611.6	6611.6			
361.6		1.000000 x	56.540000 =	56.540000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

			T.E =	88.362273

6611.7	6611.7			
361.7		1.000000 x	87.480000 =	87.480000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	125.319024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	7.990000 =	8.149800
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.151613
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.540000 =	26.050800
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.892321
6621.5	6621.5			
372.5		1.020000 x	32.500000 =	33.150000
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.423889
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.741598 =	10.423299
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098

			T.E =	101.104384
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.741598 =	13.246555
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213

			T.E =	126.764443
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.741598 =	16.819110
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218

			T.E =	158.723104
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	20.419486 =	4.807768
112		.131750 x	17.312112 =	2.280871
111		.080750 x	15.741598 =	1.271134

			T.E =	20.497773
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.741598 =	2.060575
112		.212500 x	17.312112 =	3.678824
113		.299200 x	20.419486 =	6.109510

			T.E =	31.004509
6622.3	6622.3			
373.3		1.020000 x	24.490000 =	24.979800
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	39.458492

6623	6623				
360.2		1.000000 x	2.440000 =	2.440000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	6.101136	
6630.1	6630.1				
376.12		1.000000 x	91.600000 =	91.600000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	233.625083	
6630.10	6630.10				
376.21		1.000000 x	502.070000 =	502.070000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,040.919968	
6630.11	6630.11				
376.22		1.000000 x	544.290000 =	544.290000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,134.766304	
6630.2	6630.2				
376.13		1.000000 x	101.900000 =	101.900000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	256.488524	

6630.3	6630.3				
376.14		1.000000 x	113.040000 =	113.040000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	281.581537	
6630.4	6630.4				
376.15		1.000000 x	144.820000 =	144.820000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	339.901812	
6630.5	6630.5				
376.16		1.000000 x	182.130000 =	182.130000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	417.983204	
6630.6	6630.6				
376.17		1.000000 x	231.180000 =	231.180000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	512.539230	
6630.7	6630.7				
376.18		1.000000 x	311.830000 =	311.830000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	663.233125	

6630.8	6630.8			
376.19		1.000000 x	346.570000 =	346.570000
111		5.340550 x	15.741598 =	84.068791
113		2.261000 x	20.419486 =	46.168458
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741

T.E = 739.964644

6630.9	6630.9			
376.20		1.000000 x	412.890000 =	412.890000
111		6.461700 x	15.741598 =	101.717484
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
113		2.936750 x	20.419486 =	59.966926
112		10.948000 x	17.312112 =	189.533002

T.E = 872.065234

6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		1.667700 x	20.419486 =	34.053577
111		1.334500 x	15.741598 =	21.007163
112		3.043000 x	17.312112 =	52.680757

T.E =

6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.002600 x	20.419486 =	40.892063
112		3.570000 x	17.312112 =	61.804240
111		1.922700 x	15.741598 =	30.266370

T.E =

6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.741598 =	41.198123
112		4.658000 x	17.312112 =	80.639818
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192

T.E =

6640.4	6640.4			
377.4		1.000000 x	.000000 =	.000000
111		3.418700 x	15.741598 =	53.815801
112		5.882000 x	17.312112 =	101.829843
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689

T.E =

6640.5	6640.5			
377.5		1.000000 x	.000000 =	.000000
111		4.326500 x	15.741598 =	68.106024
113		3.003900 x	20.419486 =	61.338094
113		2.550000 x	20.419486 =	52.069689
112		8.126000 x	17.312112 =	140.678222

T.E =

6640.6	6640.6			
377.6		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		3.337100 x	20.419486 =	68.141867
112		9.044000 x	17.312112 =	156.570741
111		5.340550 x	15.741598 =	84.068791

T.E =

6640.7	6640.7			
377.7		1.000000 x	.000000 =	.000000
111		6.461700 x	15.741598 =	101.717484
112		10.948000 x	17.312112 =	189.533002
113		3.671150 x	20.419486 =	74.962996
113		2.550000 x	20.419486 =	52.069689

T.E =

6640.8	6640.8			
377.8		1.000000 x	.000000 =	.000000
111		7.690800 x	15.741598 =	121.065482
112		13.396000 x	17.312112 =	231.913052
113		2.550000 x	20.419486 =	52.069689
113		4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	8.150000 =	8.150000

			T.E =	8.150000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
369.1		.224000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

		T.E =		

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.289000 x	20.419486 =	5.901231
369.29		.224000 x	.000000 =	.000000

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.8		1.000000 x	.000000 =	.000000

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.408000 x	15.741598 =	6.422572
113		.085000 x	20.419486 =	1.735656

T.E =

6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
113		.026350 x	20.419486 =	.538053
6326		.327500 x	134.983822 =	44.207202
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
6326		.352500 x	134.983822 =	47.581797
113		.040800 x	20.419486 =	.833115
111		.119000 x	15.741598 =	1.873250

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
6326		.372500 x	134.983822 =	50.281474
113		.051000 x	20.419486 =	1.041394
111		.161500 x	15.741598 =	2.542268

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
113		.063750 x	20.419486 =	1.301742
6326		.382500 x	134.983822 =	51.631312

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
111		.187000 x	15.741598 =	2.943679
6326		.391250 x	134.983822 =	52.812420
113		.068000 x	20.419486 =	1.388525

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
6327		.393750 x	157.268049 =	61.924294
113		.076500 x	20.419486 =	1.562091

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
6327		.431250 x	157.268049 =	67.821846
113		.093500 x	20.419486 =	1.909222
111		.289000 x	15.741598 =	4.549322

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	157.268049 =	78.634025
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	25.134131 =	9.299628
111		.161500 x	15.741598 =	2.542268
113		.017000 x	20.419486 =	.347131

T.E =

20.869228

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
6069		.390000 x	25.134131 =	9.802311
111		.187000 x	15.741598 =	2.943679
113		.021250 x	20.419486 =	.433914

T.E =

26.776504

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
6069		.400000 x	25.134131 =	10.053652
113		.026350 x	20.419486 =	.538053
111		.204000 x	15.741598 =	3.211286

			T.E =	35.008792
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
6069		.420000 x	25.134131 =	10.556335
113		.040800 x	20.419486 =	.833115
111		.246500 x	15.741598 =	3.880304

			T.E =	49.592754
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
111		.289000 x	15.741598 =	4.549322
113		.051000 x	20.419486 =	1.041394
6069		.430000 x	25.134131 =	10.807676

			T.E =	60.054392
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
111		.297500 x	15.741598 =	4.683125
6069		.440000 x	25.134131 =	11.059018
113		.063750 x	20.419486 =	1.301742

			T.E =	72.358485
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	25.134131 =	13.069748
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.919789
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
375.14		1.000000 x	17.510000 =	17.510000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679

			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
6323		.090000 x	106.641825 =	9.597764
700		.200000 x	.000000 =	.000000
112		1.190000 x	17.312112 =	20.601413

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	116.631825 =	25.775633
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	116.631825 =	27.291847
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	116.631825 =	28.108270
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	106.641825 =	11.730601
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	106.641825 =	13.970079
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	106.641825 =	16.422841
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	106.641825 =	17.702543
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	106.641825 =	18.449036
113		.637500 x	20.419486 =	13.017422

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	116.631825 =	16.095192
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	116.631825 =	19.244251
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	116.631825 =	22.509942
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	106.641825 =	6.398510
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	116.631825 =	15.162137
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	116.631825 =	16.328456
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	116.631825 =	17.494774
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	106.641825 =	7.464928
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	106.641825 =	8.531346
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	106.641825 =	9.597764
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	106.641825 =	10.664183
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	106.641825 =	11.730601
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	116.631825 =	11.663183
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	116.631825 =	12.829501
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	116.631825 =	13.995819
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	106.641825 =	9.597764
652		.002500 x	150.365616 =	.375914
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

39.597837

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.631825 =	29.041324
652		.004500 x	150.365616 =	.676645
113		.340000 x	20.419486 =	6.942625
			T.E =	82.721368
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	116.631825 =	36.155866
652		.005000 x	150.365616 =	.751828
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	111.273717
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.631825 =	43.153775
652		.006500 x	150.365616 =	.977377
112		.680000 x	17.312112 =	11.772236
			T.E =	142.048161
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	106.641825 =	11.730601
652		.003000 x	150.365616 =	.451097
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	47.685856
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.641825 =	13.970079
652		.003500 x	150.365616 =	.526280
113		.297500 x	20.419486 =	6.074797
			T.E =	58.153128

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	106.641825 =	18.129110
652		.004500 x	150.365616 =	.676645
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

			T.E =	71.809154
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.641825 =	24.101052
652		.005000 x	150.365616 =	.751828
112		.552500 x	17.312112 =	9.564942

			T.E =	99.218904
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	106.641825 =	29.219860
652		.006500 x	150.365616 =	.977377
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

			T.E =	128.114246
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.631825 =	16.095192
652		.002500 x	150.365616 =	.375914
113		.255000 x	20.419486 =	5.206969

			T.E =	46.095265
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	116.631825 =	19.244251
652		.003000 x	150.365616 =	.451097
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

			T.E =	55.199507

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.631825 =	22.509942
652		.003500 x	150.365616 =	.526280
112		.382500 x	17.312112 =	6.621883

T.E = 66.692991

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	106.641825 =	9.597764
652		.002500 x	150.365616 =	.375914
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.631825 =	29.041324
652		.004500 x	150.365616 =	.676645
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	116.631825 =	36.155866
652		.005000 x	150.365616 =	.751828
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.631825 =	43.153775
652		.006500 x	150.365616 =	.977377
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	106.641825 =	11.730601
652		.003000 x	150.365616 =	.451097
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.641825 =	13.970079
652		.003500 x	150.365616 =	.526280
113		.297500 x	20.419486 =	6.074797

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	106.641825 =	18.129110
652		.004500 x	150.365616 =	.676645
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.641825 =	24.101052
652		.005000 x	150.365616 =	.751828
112		.552500 x	17.312112 =	9.564942

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	106.641825 =	29.219860
652		.006500 x	150.365616 =	.977377
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.631825 =	16.095192
652		.002500 x	150.365616 =	.375914
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	116.631825 =	19.244251
652		.003000 x	150.365616 =	.451097
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.631825 =	22.509942
652		.003500 x	150.365616 =	.526280
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	20.340067 =	38.239326
6326		.940000 x	134.983822 =	126.884793

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.983822 =	98.538190

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	134.983822 =	126.884793

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.983822 =	98.538190

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.340067 =	61.833804
6328		.400000 x	160.844362 =	64.337745

			T.E =	126.171548
6742.10	6742.10			
6303		7.520000 x	20.340067 =	152.957304
6328		2.110000 x	160.844362 =	339.381604

			T.E =	492.338908
6742.11	6742.11			
6303		8.030000 x	20.340067 =	163.330738
6328		2.430000 x	160.844362 =	390.851800

			T.E =	554.182538
6742.2	6742.2			
6303		3.500000 x	20.340067 =	71.190235
6328		.500000 x	160.844362 =	80.422181

			T.E =	151.612416
6742.3	6742.3			
6303		4.020000 x	20.340067 =	81.767069
6328		.630000 x	160.844362 =	101.331948

			T.E =	183.099017
6742.4	6742.4			
6303		4.530000 x	20.340067 =	92.140504
6328		.800000 x	160.844362 =	128.675490

			T.E =	220.815993

6742.5	6742.5			
6303		5.000000 x	20.340067 =	101.700335
6328		.950000 x	160.844362 =	152.802144

			T.E =	254.502479
6742.6	6742.6			
6303		5.530000 x	20.340067 =	112.480571
6328		1.170000 x	160.844362 =	188.187904

			T.E =	300.668474
6742.7	6742.7			
6303		6.040000 x	20.340067 =	122.854005
6328		1.410000 x	160.844362 =	226.790550

			T.E =	349.644555
6742.8	6742.8			
6303		6.520000 x	20.340067 =	132.617237
6328		1.610000 x	160.844362 =	258.959423

			T.E =	391.576660
6742.9	6742.9			
6303		7.040000 x	20.340067 =	143.194072
6328		1.880000 x	160.844362 =	302.387401

			T.E =	445.581472
6743.1	6743.1			
6303		3.040000 x	20.340067 =	61.833804
6328		.440000 x	160.844362 =	70.771519

			T.E =	132.605323
6743.10	6743.10			
6303		7.520000 x	20.340067 =	152.957304
6328		2.240000 x	160.844362 =	360.291371

			T.E =	513.248675
6743.11	6743.11			
6303		8.030000 x	20.340067 =	163.330738
6328		2.570000 x	160.844362 =	413.370010

			T.E =	576.700748

6743.12	6743.12			
6303		3.040000 x	20.340067 =	61.833804
6328		.750000 x	160.844362 =	120.633272

			T.E =	182.467075
6743.13	6743.13			
6303		3.500000 x	20.340067 =	71.190235
6328		.910000 x	160.844362 =	146.368369

			T.E =	217.558604
6743.14	6743.14			
6303		4.020000 x	20.340067 =	81.767069
6328		1.090000 x	160.844362 =	175.320355

			T.E =	257.087424
6743.15	6743.15			
6303		4.530000 x	20.340067 =	92.140504
6328		1.300000 x	160.844362 =	209.097671

			T.E =	301.238174
6743.16	6743.16			
6303		5.000000 x	20.340067 =	101.700335
6328		1.550000 x	160.844362 =	249.308761

			T.E =	351.009096
6743.17	6743.17			
6303		5.530000 x	20.340067 =	112.480571
6328		1.850000 x	160.844362 =	297.562070

			T.E =	410.042640
6743.2	6743.2			
6303		3.500000 x	20.340067 =	71.190235
6328		.550000 x	160.844362 =	88.464399

			T.E =	159.654634
6743.3	6743.3			
6303		4.020000 x	20.340067 =	81.767069
6328		.690000 x	160.844362 =	110.982610

			T.E =	192.749679

6743.4	6743.4			
6303		4.530000 x	20.340067 =	92.140504
6328		.860000 x	160.844362 =	138.326151

			T.E =	230.466655
6743.5	6743.5			
6303		5.000000 x	20.340067 =	101.700335
6328		1.020000 x	160.844362 =	164.061249

			T.E =	265.761584
6743.6	6743.6			
6303		5.530000 x	20.340067 =	112.480571
6328		1.260000 x	160.844362 =	202.663896

			T.E =	315.144467
6743.7	6743.7			
6303		6.040000 x	20.340067 =	122.854005
6328		1.500000 x	160.844362 =	241.266543

			T.E =	364.120548
6743.8	6743.8			
6303		6.520000 x	20.340067 =	132.617237
6328		1.720000 x	160.844362 =	276.652303

			T.E =	409.269539
6743.9	6743.9			
6303		7.040000 x	20.340067 =	143.194072
6328		2.000000 x	160.844362 =	321.688724

			T.E =	464.882796
6744	6744			
111		2.125000 x	15.741598 =	33.450896
111		4.250000 x	15.741598 =	66.901792
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408
112		2.125000 x	17.312112 =	36.788238

			T.E =	223.923741

6751	6751				
234.2		.400000 x	1.006500 =	.402600	
113		.051000 x	20.419486 =	1.041394	
113		.170000 x	20.419486 =	3.471313	
235		.650000 x	.703000 =	.456950	

			T.E =	5.372256	
6752	6752				
237		1.050000 x	1.218000 =	1.278900	
113		.017000 x	20.419486 =	.347131	
111		.025500 x	15.741598 =	.401411	

			T.E =	2.027442	
6753	6753				
237		1.050000 x	1.218000 =	1.278900	
112		.085000 x	17.312112 =	1.471530	
113		.085000 x	20.419486 =	1.735656	

			T.E =	4.486086	
6754	6754				
237.1		1.000000 x	1.380000 =	1.380000	
112		.017000 x	17.312112 =	.294306	
111		.051000 x	15.741598 =	.802821	
113		.212500 x	20.419486 =	4.339141	

			T.E =	6.816268	
6801	6801				
232		.700000 x	2.100000 =	1.470000	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	20.419486 =	52.069689	
112		1.700000 x	17.312112 =	29.430590	
111		.850000 x	15.741598 =	13.380358	

			T.E =	98.670638	
6802	6802				
231		15.000000 x	.861000 =	12.915000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	20.419486 =	52.069689	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	15.741598 =	66.901792	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	150.365616 =	1.804387
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.551853
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	150.365616 =	18.043874
113		.680000 x	20.419486 =	13.885250

			T.E =	39.957339
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	150.365616 =	.300731
2522		.005000 x	154.832484 =	.774162
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	17.429662
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	134.983822 =	.674919
652		.002000 x	150.365616 =	.300731

			T.E =	13.270419
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.750000 =	20.150000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.750000 =	10.075000

			T.E =	86.002715

6811	6811			
236		6.430000 x	.673000 =	4.327390
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.750000 =	24.412500

			T.E =	115.522706
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
243		11.900000 x	2.400000 =	28.560000
6324		.250000 x	111.636825 =	27.909206
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179

			AΘΡΟΙΣΜΑ =	164.747201
	T.E =	.262500 x	164.747201 =	43.246140

7001	7001			
7001 Α		1.000000 x	.240618 =	.240618
7001 Β		1.000000 x	.789780 =	.789780
7001 Ε		1.000000 x	.838462 =	.838462
7001 Δ		1.000000 x	.326632 =	.326632
7001 Γ		1.000000 x	.997315 =	.997315

			AΘΡΟΙΣΜΑ =	3.192807

			T.E =	3.671728
7002	7002			
560		.005104 x	716.645090 =	3.657757

			T.E =	3.657757
7003	7003			
7003 Α		1.000000 x	.120309 =	.120309
7003 Β		1.000000 x	.617220 =	.617220
7003 Δ		1.000000 x	.815243 =	.815243
7003 Γ		1.000000 x	.565520 =	.565520

			AΘΡΟΙΣΜΑ =	2.118292

			T.E =	2.330121
7004	7004			
561		.003250 x	945.909290 =	3.074205

			T.E =	3.074205

7005	7005			
7005 Α		1.000000 x	.120309 =	.120309
7005 Γ		1.000000 x	.308610 =	.308610
7005 Ε		1.000000 x	.815243 =	.815243
7005 Δ		1.000000 x	.565520 =	.565520
7005 Β		1.000000 x	1.080136 =	1.080136

			ΑΘΡΟΙΣΜΑ =	2.889818

			T.E =	3.178800
7006	7006			
561		.001723 x	945.909290 =	1.629802
561		.000862 x	945.909290 =	.815374
561		.000812 x	945.909290 =	.768078

			T.E =	3.213254
7007	7007			
213		.100000 x	1.949500 =	.194950
116		.280000 x	20.419486 =	5.717456
550		.003500 x	1,062.942386 =	3.720298
518		.001750 x	894.100992 =	1.564677
502		.000583 x	807.885773 =	.470997

			T.E =	11.668379
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
503		.001750 x	923.834573 =	1.616711
507		.000875 x	948.916857 =	.830302
558		.000972 x	1,128.256457 =	1.096665
7007		1.100000 x	11.668379 =	12.835217

			T.E =	20.345012
7009	7009			
560		.006417 x	716.645090 =	4.598712

			T.E =	4.598712
7010	7010			
7010 Α		1.000000 x	.355401 =	.355401
7010 Β		1.000000 x	.533665 =	.533665
7010 Ε		1.000000 x	1.031164 =	1.031164
7010 Δ		1.000000 x	.326632 =	.326632
7010 Γ		1.000000 x	.565520 =	.565520

			ΑΘΡΟΙΣΜΑ =	2.812382

			T.E =	3.234239

7011	7011			
502		.001367 x	807.885773 =	1.104380
563		.001367 x	.000000 =	.000000
558		.000729 x	1,128.256457 =	.822499
558		.000729 x	1,128.256457 =	.822499
554		.000438 x	34.408000 =	.015071
503		.000438 x	923.834573 =	.404640
502		.000700 x	807.885773 =	.565520

			AΘΡΟΙΣΜΑ =	3.734608

			T.E =	
7012	7012			
7008		1.000000 x	20.345012 =	20.345012

			AΘΡΟΙΣΜΑ =	20.345012

			T.E =	22.379513
7013	7013			
7003		1.000000 x	2.330121 =	2.330121

			AΘΡΟΙΣΜΑ =	2.330121

			T.E =	2.563133
7014	7014			
7005		1.000000 x	3.178800 =	3.178800

			AΘΡΟΙΣΜΑ =	3.178800

			T.E =	3.496680
7015	7015			
111		.056000 x	15.741598 =	.881529
X 630.1		.300000 x	1.689078 =	.506723
7001		.900000 x	3.671728 =	3.304555
X 630		.300000 x	1.495141 =	.448542

			T.E =	5.141350
7016.9	7016.9			
7016.4		1.000000 x	128.147049 =	128.147049
7016.6		1.000000 x	38.444115 =	38.444115
7016.7		1.000000 x	80.282150 =	80.282150
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.629410 =	25.629410

			T.E =	376.642103

7017.8	7017.8				
7017.3		1.000000 x	93.518479 =		93.518479
7017.4		1.000000 x	18.703696 =		18.703696
7017.5		1.000000 x	33.666653 =		33.666653
7017.7		1.000000 x	52.069689 =		52.069689
7017.6		1.000000 x	80.282150 =		80.282150
			T.E =		278.240667
7018	7018				
233.2		1.150000 x	.598400 =		.688160
113		.051000 x	20.419486 =		1.041394
			AΘΡΟΙΣΜΑ =		1.729554
			T.E =		1.902509
7019	7019				
7019 A6		1.000000 x	193.018130 =		193.018130
7019 A7		1.000000 x	19.301813 =		19.301813
			T.E =		212.319943
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	212.319943 =		212.319943
			T.E =		206.419943
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,568.536959 =		39.032657
			T.E =		59.336179
7020.1	7020.1				
570.2		.350000 x	127.284076 =		44.549427
571.2		.070000 x	261.479536 =		18.303568
571.1		.280000 x	453.351730 =		126.938484
			AΘΡΟΙΣΜΑ =		189.791479
	T.E =	.015625 x	189.791479 =		2.965492
7021	7021				
213		.150000 x	1.949500 =		.292425
116		1.120000 x	20.419486 =		22.869824
7021.2		.014583 x	3,115.713792 =		45.436454
			T.E =		68.598704

7021.1	7021.1			
570.2		.350000 x	127.284076 =	44.549427
571.2		.070000 x	261.479536 =	18.303568
571.1		.280000 x	453.351730 =	126.938484
			AΘΡΟΙΣΜΑ =	189.791479
	T.E =	.020833 x	189.791479 =	3.953926
7022	7022			
213		.150000 x	1.949500 =	.292425
116		1.400000 x	20.419486 =	28.587280
7022.2		.020000 x	2,858.055336 =	57.161107
			T.E =	86.040812
7022.1	7022.1			
570.2		.350000 x	127.284076 =	44.549427
571.2		.070000 x	261.479536 =	18.303568
571.1		.280000 x	453.351730 =	126.938484
			AΘΡΟΙΣΜΑ =	189.791479
	T.E =	.028571 x	189.791479 =	5.422532
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
550		.012143 x	1,062.942386 =	12.907309
			T.E =	77.904052
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
111		.425000 x	15.741598 =	6.690179
550		.020238 x	1,062.942386 =	21.511828
116		.850000 x	20.419486 =	17.356563
			T.E =	94.908570
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	150.365616 =	.150366
550		.020238 x	1,062.942386 =	21.511828
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.545500 =	3.371190
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.448393

7026	7026			
398.5		125.400000 x	6.400000 =	802.560000
236		16.808000 x	.673000 =	11.311784
113		.909160 x	20.419486 =	18.564580
113		3.400000 x	20.419486 =	69.426252
6310		12.350000 x	1.440603 =	17.791447

			ΑΘΡΟΙΣΜΑ =	919.654063
	T.E =	.007259 x	919.654063 =	6.675769

7027	7027			
236		1.100000 x	.673000 =	.740300
113		.059500 x	20.419486 =	1.214959

			T.E =	1.955259
7028	7028			
111		.144500 x	15.741598 =	2.274661
6751		.120000 x	5.372256 =	.644671
6751		.600000 x	5.372256 =	3.223354
111		.425000 x	15.741598 =	6.690179
112		.144500 x	17.312112 =	2.501600

			ΑΘΡΟΙΣΜΑ =	15.334465

			T.E =	17.634634
7029	7029			
568.1		.021250 x	2,675.261440 =	56.849306
569.2		.021250 x	620.296952 =	13.181310
570.2		.021250 x	127.284076 =	2.704787
571.2		.021250 x	261.479536 =	5.556440

			T.E =	78.291843
7030	7030			
398.6		.015385 x	330.000000 =	5.077050
572		.026563 x	860.046317 =	22.845410

			ΑΘΡΟΙΣΜΑ =	27.922460

			T.E =	39.091444
7031	7031			
573		.106250 x	1,089.305892 =	115.738751

			ΑΘΡΟΙΣΜΑ =	115.738751

			T.E =	133.099564
7032	7032			
573		.212500 x	1,089.305892 =	231.477502

			ΑΘΡΟΙΣΜΑ =	231.477502

			T.E =	300.920753

7101.1	7101.1			
398.1		15.000000 x	.250000 =	3.750000
574		.132813 x	3,681.443982 =	488.943620
T 630		.105000 x	1.815528 =	.190630
T 630.1		.105000 x	2.051023 =	.215357
567		.132813 x	398.921772 =	52.981997

AΘΡΟΙΣΜΑ =				546.081605

T.E =				562.464053
7101.2	7101.2			
398.1		15.000000 x	.250000 =	3.750000
574		.148750 x	3,681.443982 =	547.614792
T 630.1		.105000 x	2.051023 =	.215357
T 630		.105000 x	1.815528 =	.190630
567		.148750 x	398.921772 =	59.339614

AΘΡΟΙΣΜΑ =				611.110394

T.E =				629.443706
7101.3	7101.3			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.051023 =	.215357
T 630		.105000 x	1.815528 =	.190630
574		.159375 x	3,681.443982 =	586.730135
567		.159375 x	398.921772 =	63.578157

AΘΡΟΙΣΜΑ =				654.464280

T.E =				674.098208
7101.4	7101.4			
398.1		15.000000 x	.250000 =	3.750000
567		.170000 x	398.921772 =	67.816701
574		.170000 x	3,681.443982 =	625.845477
T 630.1		.105000 x	2.051023 =	.215357
T 630		.105000 x	1.815528 =	.190630

AΘΡΟΙΣΜΑ =				697.818166

T.E =				718.752711
7101.5	7101.5			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.051023 =	.215357
567		.191250 x	398.921772 =	76.293789
T 630		.105000 x	1.815528 =	.190630
574		.191250 x	3,681.443982 =	704.076162

AΘΡΟΙΣΜΑ =				784.525938

T.E =				808.061716

7102.1	7102.1				
398.1		15.000000 x	.250000 =		3.750000
567		.302813 x	398.921772 =		120.798699
T 630		.105000 x	1.815528 =		.190630
T 630.1		.105000 x	2.051023 =		.215357
574		.302813 x	3,681.443982 =		1,114.789097
				ΑΘΡΟΙΣΜΑ =	1,239.743783
				T.E =	1,276.936096
7102.2	7102.2				
398.1		15.000000 x	.250000 =		3.750000
T 630.1		.105000 x	2.051023 =		.215357
T 630		.105000 x	1.815528 =		.190630
574		.329375 x	3,681.443982 =		1,212.575612
567		.329375 x	398.921772 =		131.394859
				ΑΘΡΟΙΣΜΑ =	1,348.126458
				T.E =	1,388.570252
7102.3	7102.3				
398.1		15.000000 x	.250000 =		3.750000
567		.361250 x	398.921772 =		144.110490
T 630		.105000 x	1.815528 =		.190630
T 630.1		.105000 x	2.051023 =		.215357
574		.361250 x	3,681.443982 =		1,329.921638
				ΑΘΡΟΙΣΜΑ =	1,478.188116
				T.E =	1,522.533760
7102.4	7102.4				
398.1		15.000000 x	.250000 =		3.750000
T 630.1		.105000 x	2.051023 =		.215357
T 630		.105000 x	1.815528 =		.190630
574		.403750 x	3,681.443982 =		1,486.383008
567		.403750 x	398.921772 =		161.064665
				ΑΘΡΟΙΣΜΑ =	1,651.603661
				T.E =	1,701.151771
7102.5	7102.5				
398.1		15.000000 x	.250000 =		3.750000
T 630.1		.105000 x	2.051023 =		.215357
T 630		.105000 x	1.815528 =		.190630
567		.446250 x	398.921772 =		178.018841
574		.446250 x	3,681.443982 =		1,642.844377
				ΑΘΡΟΙΣΜΑ =	1,825.019206
				T.E =	1,879.769782

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	998.623358 =	106.103732

			T.E =	182.858130
7104	7104			
113		1.700000 x	20.419486 =	34.713126
576		.106250 x	7.645000 =	.812281
567		.106250 x	398.921772 =	42.385438

			T.E =	77.910846
7105	7105			
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563
576		.106250 x	7.645000 =	.812281
567		.106250 x	398.921772 =	42.385438

			T.E =	73.934641
7106.1	7106.1			
577		.265625 x	683.190719 =	181.472535

			AΘΡΟΙΣΜΑ =	181.472535

			T.E =	190.546161
7106.2	7106.2			
577		.297500 x	683.190719 =	203.249239

			AΘΡΟΙΣΜΑ =	203.249239

			T.E =	213.411701
7106.3	7106.3			
577		.350625 x	683.190719 =	239.543746

			AΘΡΟΙΣΜΑ =	239.543746

			T.E =	251.520933
7106.4	7106.4			
577		.425000 x	683.190719 =	290.356056

			AΘΡΟΙΣΜΑ =	290.356056

			T.E =	304.873858

7106.5	7106.5			
577		.531250 x	683.190719 =	362.945069

			ΑΘΡΟΙΣΜΑ =	362.945069

			T.E =	381.092323
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	190.546161 =	190.546161

			T.E =	231.346161
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	213.411701 =	213.411701

			T.E =	254.211701
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	251.520933 =	251.520933

			T.E =	292.320933
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	304.873858 =	304.873858

			T.E =	345.673858
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	381.092323 =	381.092323

			T.E =	421.892323
7108	7108			
398.11		1.000000 x	140.870000 =	140.870000
574		.053125 x	3,681.443982 =	195.576712

			T.E =	336.446712
7109	7109			
398.12		1.000000 x	182.180000 =	182.180000
574		.053125 x	3,681.443982 =	195.576712

			T.E =	377.756712

7110	7110				
398.10		1.170000 x	142.840000 =		167.122800
574		.053125 x	3,681.443982 =		195.576712

			T.E =		362.699512
7111	7111				
398.9		1.170000 x	131.840000 =		154.252800
574		.053125 x	3,681.443982 =		195.576712

			T.E =		349.829512
7112	7112				
398.13		1.300000 x	10.300000 =		13.390000
577		.010625 x	683.190719 =		7.258901

			T.E =		20.648901
7113	7113				
241		1.200000 x	7.750000 =		9.300000
574		.001063 x	3,681.443982 =		3.913375

			T.E =		13.213375
7114	7114				
398.8		.120000 x	31.620000 =		3.794400
577		.053125 x	683.190719 =		36.294507

			T.E =		40.088907
7115	7115				
574		.026563 x	3,681.443982 =		97.790196

			T.E =		97.790196
7116	7116				
577		.170000 x	683.190719 =		116.142422

			T.E =		116.142422
7117	7117				
574		.001063 x	3,681.443982 =		3.913375

			T.E =		3.913375

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	649.134266 =	551.764126
574.1		.425000 x	2,241.497688 =	952.636517

			T.E =	1,932.572109
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,241.497688 =	1,905.273035
578		.850000 x	649.134266 =	551.764126

			T.E =	3,099.294359
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	386.217688 =	98.485510

			T.E =	312.571243
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	386.217688 =	229.799524

			T.E =	443.885257
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
575.1		.425000 x	259.627416 =	110.341652
578		.425000 x	649.134266 =	275.882063

			T.E =	546.788014
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	649.134266 =	827.646189
575.1		1.275000 x	259.627416 =	331.024955

			T.E =	1,426.278311
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	649.134266 =	275.882063

			T.E =	385.878679

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	649.134266 =	275.882063

			T.E =	385.878679
7122	7122			
398.1		15.000000 x	.250000 =	3.750000
T 630		.105000 x	1.815528 =	.190630
T 630.1		.105000 x	2.051023 =	.215357
567		.122188 x	398.921772 =	48.743453
580		.122188 x	1,733.857462 =	211.856576

			AΘΡΟΙΣΜΑ =	264.756017

			T.E =	272.698697
7123	7123			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.051023 =	.215357
T 630		.105000 x	1.815528 =	.190630
580		.286875 x	1,733.857462 =	497.400359
567		.286875 x	398.921772 =	114.440683

			AΘΡΟΙΣΜΑ =	615.997031

			T.E =	634.476942
7124	7124			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.051023 =	.215357
567		.063750 x	398.921772 =	25.431263
T 630		.105000 x	1.815528 =	.190630
580		.063750 x	1,733.857462 =	110.533413

			T.E =	140.120664
7125	7125			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.051023 =	.215357
567		.127500 x	398.921772 =	50.862526
T 630		.105000 x	1.815528 =	.190630
580		.127500 x	1,733.857462 =	221.066826

			T.E =	276.085340
7126	7126			
398.16		1.000000 x	64.290000 =	64.290000
580		.053125 x	1,733.857462 =	92.111178

			T.E =	156.401178

7127	7127				
398.15		1.170000 x	77.960000 =		91.213200
580		.015938 x	1,733.857462 =		27.634220

			T.E =		118.847420
7128	7128				
398.14		1.170000 x	60.360000 =		70.621200
580		.015938 x	1,733.857462 =		27.634220

			T.E =		98.255420
7129	7129				
6751		1.000000 x	5.372256 =		5.372256

			T.E =		5.372256