

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

1ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.152800
051	14.630000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.140600
212	1.362600
213	1.949500
214	4.160000
221	.099900
224	.070000
231	.825000
241	7.750000
242	5.000000
251	290.000000
252	290.000000
301	4.060000
302	6.700000
360	11.600000
361	29.800000
362	3.800000
363	.610000
364	3.710000
365	24.300000
366	22.400000
367	.128500
368	21.100000
369	12.830000
370	8.440000
371	7.600000
372	1.340000
373	2.150000
374	2.900000
375	1.580000
376	
377	3.450000
378	.540000
379	15.150000
380	.280000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
417	130.670000

420	94.500000
428	425.280000
450	111.820000
451	154.970000
452	94.950000
453	88.120000
454	119.120000
455	420.570000

501	501				
211		50.000000 x	1.140600 =	57.030000	
214		3.000000 x	4.160000 =	12.480000	
401		1.000000 x	260.720000 =	260.720000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	551.322593

				Η.Δ. =	606.454852
502	502				
211		80.000000 x	1.140600 =	91.248000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	4.160000 =	29.120000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	720.731612

				Η.Δ. =	792.804773
503	503				
211		110.000000 x	1.140600 =	125.466000	
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	4.160000 =	41.600000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	823.439612

				Η.Δ. =	905.783573
504	504				
211		40.000000 x	1.140600 =	45.624000	
214		2.000000 x	4.160000 =	8.320000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	100.390000 =	100.390000	

				ΑΘΡΟΙΣΜΑ =	345.423536

				Η.Δ. =	379.965890
505	505				
211		200.000000 x	1.140600 =	228.120000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	206.630000 =	206.630000	

				ΑΘΡΟΙΣΜΑ =	747.447688

				Η.Δ. =	822.192457

506	506				
211		95.000000 x	1.140600 =		108.357000
214		6.000000 x	4.160000 =		24.960000
405		1.000000 x	200.790000 =		200.790000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536

		ΑΘΡΟΙΣΜΑ =			617.704688

		H.Δ. =			679.475157
507	507				
211		165.000000 x	1.140600 =		188.199000
214		10.000000 x	4.160000 =		41.600000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	311.770000 =		311.770000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152

		ΑΘΡΟΙΣΜΑ =			847.666688

		H.Δ. =			932.433357
508	508				
211		40.000000 x	1.140600 =		45.624000
407		1.000000 x	53.630000 =		53.630000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.400000 =		8.800000
214		2.000000 x	4.160000 =		8.320000

		ΑΘΡΟΙΣΜΑ =			530.199484

		H.Δ. =			583.219432
509	509				
211		80.000000 x	1.140600 =		91.248000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	122.460000 =		122.460000
214		5.000000 x	4.160000 =		20.800000

		ΑΘΡΟΙΣΜΑ =			368.731336

		H.Δ. =			405.604470
510	510				
211		80.000000 x	1.140600 =		91.248000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	4.160000 =		20.800000
410		1.000000 x	113.190000 =		113.190000

		ΑΘΡΟΙΣΜΑ =			359.461336

		H.Δ. =			395.407470

511	511				
212		17.000000 x	1.362600 =	23.164200	
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	4.160000 =	4.160000	
115		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	

				ΑΘΡΟΙΣΜΑ =	660.381268

				Η.Δ. =	726.419395
512	512				
211		10.000000 x	1.140600 =	11.406000	
115		2.000000 x	21.778427 =	43.556854	
214		1.000000 x	4.160000 =	4.160000	
112		2.000000 x	17.312112 =	34.624224	
412		1.000000 x	2.900000 =	2.900000	

				ΑΘΡΟΙΣΜΑ =	96.647078

				Η.Δ. =	106.311786
518	518				
211		180.000000 x	1.140600 =	205.308000	
212		5.000000 x	1.362600 =	6.813000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
417		1.000000 x	130.670000 =	130.670000	
214		12.000000 x	4.160000 =	49.920000	

				ΑΘΡΟΙΣΜΑ =	802.305584

				Η.Δ. =	882.536142
521	521				
211		40.000000 x	1.140600 =	45.624000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	
420		1.000000 x	94.500000 =	94.500000	

				ΑΘΡΟΙΣΜΑ =	383.697612

				Η.Δ. =	422.067373
550	550				
211		80.000000 x	1.140600 =	91.248000	
214		5.000000 x	4.160000 =	20.800000	
117		8.000000 x	16.777917 =	134.223336	
450		1.000000 x	111.820000 =	111.820000	

				ΑΘΡΟΙΣΜΑ =	358.091336

				Η.Δ. =	393.900470

560	560				
211		80.000000 x	1.140600 =	91.248000	
117		8.000000 x	16.777917 =	134.223336	
455		1.000000 x	420.570000 =	420.570000	
214		7.000000 x	4.160000 =	29.120000	
			AΘΡΟΙΣΜΑ =	675.161336	
			H.Δ. =	742.677470	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	583.219432 =	2.916097	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.788223	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	583.219432 =	2.916097	
504		.005000 x	379.965890 =	1.899829	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	882.536142 =	8.825361	
509		.005000 x	405.604470 =	2.028022	
			B.T =	21.679369	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	379.965890 =	1.899829	
509		.005000 x	405.604470 =	2.028022	
518		.014300 x	882.536142 =	12.620267	
508		.005000 x	583.219432 =	2.916097	
			B.T =	25.474274	
630	630				
512		.020000 x	106.311786 =	2.126236	
			B.T =	2.126236	
630.1	630.1				
510		.006000 x	395.407470 =	2.372445	
			B.T =	2.372445	

641	641			
231		.200000 x	.825000 =	.165000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.536243
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	405.604470 =	1.460176
509		.011100 x	405.604470 =	4.502210
511		.050000 x	726.419395 =	36.320970
630		.600000 x	2.126236 =	1.275742
625		1.000000 x	25.474274 =	25.474274
224		120.000000 x	.070000 =	8.400000

			B.T =	124.686824
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	405.604470 =	4.461649
630		.320000 x	2.126236 =	.680396
625		1.000000 x	25.474274 =	25.474274
511		.050000 x	726.419395 =	36.320970
509		.001920 x	405.604470 =	.778761
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	164.919502
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	606.454852 =	.060645
503		.002000 x	905.783573 =	1.811567

			T.E =	1.993397
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	905.783573 =	.298909
501		.000080 x	606.454852 =	.048516
505		.000600 x	822.192457 =	.493315
507		.001400 x	932.433357 =	1.305407
509		.004447 x	405.604470 =	1.803723

			T.E =	4.071055

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	606.454852 =	.060645
503		.002000 x	905.783573 =	1.811567
509		.005312 x	405.604470 =	2.154571
506		.001330 x	679.475157 =	.903702

			T.E =	5.051670
1123B	1123B			
509		.001487 x	405.604470 =	.603134

			T.E =	.603134
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	422.067373 =	.084413
501		.000100 x	606.454852 =	.060645

			T.E =	.318180
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	4.071055 =	.814211
507		.000200 x	932.433357 =	.186487
501		.000100 x	606.454852 =	.060645
502		.000200 x	792.804773 =	.158561

			T.E =	2.006984
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	4.071055 =	4.071055
501		.002000 x	606.454852 =	1.212910

			T.E =	9.611993
1710	1710			
360		1.000000 x	11.600000 =	11.600000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	606.454852 =	.060645

			T.E =	15.596045
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	405.604470 =	2.109954
507		.001540 x	932.433357 =	1.435947
502		.002000 x	792.804773 =	1.585610
501		.000830 x	606.454852 =	.503358

			T.E =	5.807990

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	792.804773 =	2.299134
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	932.433357 =	1.864867
509		.004896 x	405.604470 =	1.985839
508		.004000 x	583.219432 =	2.332878

			T.E =	18.695417
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.788223 =	20.777634
112		.600000 x	17.312112 =	10.387267
509		.012432 x	405.604470 =	5.042475

			T.E =	45.652335
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.788223 =	20.777634
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	405.604470 =	5.042475

			T.E =	76.445627
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.788223 =	20.777634
652		.020000 x	164.919502 =	3.298390
651		.250000 x	124.686824 =	31.171706
509		.012432 x	405.604470 =	5.042475
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.413739
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	164.919502 =	16.491950
621		.350000 x	19.788223 =	6.925878
509		.003788 x	405.604470 =	1.536430
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.176765

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.679369 =	17.343495
630		.250000 x	2.126236 =	.531559
641		3.000000 x	7.536243 =	22.608729
625		.500000 x	25.474274 =	12.737137
511		.040000 x	726.419395 =	29.056776
509		.008880 x	405.604470 =	3.601768
509		.001500 x	405.604470 =	.608407
509		.005550 x	405.604470 =	2.251105
113		1.600000 x	20.419486 =	32.671178

			T.E =	175.617110
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	175.617110 =	.878086
652		.002000 x	164.919502 =	.329839
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.732358
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	164.919502 =	1.979034
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.593582
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	393.900470 =	1.477127

			T.E =	1.949375

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	393.900470 =	.984751

			T.E =	1.456999
5160	5160			
213		.400000 x	1.949500 =	.779800
111		.160000 x	15.741598 =	2.518656
508		.001500 x	583.219432 =	.874829

			T.E =	4.173285
5210	5210			
363		.100000 x	.610000 =	.061000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.556270
5220	5220			
363		.100000 x	.610000 =	.061000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.895195
5230	5230			
364		1.000000 x	3.710000 =	3.710000
112		.080000 x	17.312112 =	1.384969

			T.E =	5.094969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.372445 =	.047449
510		.000250 x	395.407470 =	.098852
630		.020000 x	2.126236 =	.042525

			T.E =	.220309

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.372445 =	.047449
510		.000163 x	395.407470 =	.064451
630		.020000 x	2.126236 =	.042525

			T.E =	.174889
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.610000 =	.061000
111		.003300 x	15.741598 =	.051947

			T.E =	.112947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354				
111		.035000 x	15.741598 =		.550956
113		.025000 x	20.419486 =		.510487

			T.E =		1.061443
5361A	5361A				
365		.003000 x	24.300000 =		.072900
630		.000300 x	2.126236 =		.000638
510		.000188 x	395.407470 =		.074337
113		.001500 x	20.419486 =		.030629

			T.E =		.178504
5361B	5361B				
366		.003000 x	22.400000 =		.067200
510		.000188 x	395.407470 =		.074337
630		.000300 x	2.126236 =		.000638
113		.001500 x	20.419486 =		.030629

			T.E =		.172804
5362A	5362A				
365		.005000 x	24.300000 =		.121500
630		.000500 x	2.126236 =		.001063
510		.000313 x	395.407470 =		.123763
113		.002500 x	20.419486 =		.051049

			T.E =		.297374
5362B	5362B				
366		.005000 x	22.400000 =		.112000
630		.000500 x	2.126236 =		.001063
510		.000313 x	395.407470 =		.123763
113		.002500 x	20.419486 =		.051049

			T.E =		.287874
5363A	5363A				
365		.003000 x	24.300000 =		.072900
113		.001000 x	20.419486 =		.020419
510		.000125 x	395.407470 =		.049426
630		.000300 x	2.126236 =		.000638

			T.E =		.143383

5363B	5363B			
366		.003000 x	22.400000 =	.067200
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.126236 =	.000638
510		.000125 x	395.407470 =	.049426

			T.E =	.137683
5364A	5364A			
365		.005000 x	24.300000 =	.121500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.126236 =	.001063
510		.000225 x	395.407470 =	.088967

			T.E =	.248285
5364B	5364B			
366		.005000 x	22.400000 =	.112000
630		.000500 x	2.126236 =	.001063
510		.000225 x	395.407470 =	.088967
113		.001800 x	20.419486 =	.036755

			T.E =	.238785
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	15.150000 =	30.300000
510		.100000 x	395.407470 =	39.540747
630		.100000 x	2.126236 =	.212624
113		.800000 x	20.419486 =	16.335589

			T.E =	86.388959
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	393.900470 =	162.483944

			T.E =	241.191934
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	29.800000 =	447.000000	
363		20.000000 x	.610000 =	12.200000	
362		30.000000 x	3.800000 =	114.000000	
550		.375000 x	393.900470 =	147.712676	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	24.300000 =	48.600000	
111		20.000000 x	15.741598 =	314.831960	

			T.E =	1,492.734356	
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.372445 =	23.724450	
510		.125000 x	395.407470 =	49.425934	
630		10.000000 x	2.126236 =	21.262360	

			T.E =	110.154342	
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

			T.E =	23.612397	
5530	5530				
453		.187500 x	88.120000 =	16.522500	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	48.005696	
5540	5540				
363		15.000000 x	.610000 =	9.150000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.956199	
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	47.224794	
5552	5552				
379		1.000000 x	15.150000 =	15.150000	
630		.100000 x	2.126236 =	.212624	
510		.050000 x	395.407470 =	19.770374	
113		.400000 x	20.419486 =	8.167794	

			T.E =	43.300792	

5560A	5560A			
365		1.000000 x	24.300000 =	24.300000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.126236 =	.212624
510		.100000 x	395.407470 =	39.540747

			T.E =	80.388959
5560B	5560B			
366		1.000000 x	22.400000 =	22.400000
510		.100000 x	395.407470 =	39.540747
630		.100000 x	2.126236 =	.212624
113		.800000 x	20.419486 =	16.335589

			T.E =	78.488959
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.610000 =	9.150000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	393.900470 =	49.237559
367		20,000.000000 x	.128500 =	2,570.000000

			T.E =	3,100.635499
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.126236 =	21.262360
630.1		10.000000 x	2.372445 =	23.724450
510		.125000 x	395.407470 =	49.425934

			T.E =	110.154342
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199
5640	5640			
111		10.000000 x	15.741598 =	157.415980
111		2.000000 x	15.741598 =	31.483196

			T.E =	188.899176
5650	5650			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240
5710	5710			
362		40.000000 x	3.800000 =	152.000000
111		5.000000 x	15.741598 =	78.707990
112		1.000000 x	17.312112 =	17.312112
560		.125000 x	742.677470 =	92.834684
510		.125000 x	395.407470 =	49.425934
509		.125000 x	405.604470 =	50.700559
114		1.000000 x	23.886192 =	23.886192
380		800.000000 x	.280000 =	224.000000
363		15.000000 x	.610000 =	9.150000
377		250.000000 x	3.450000 =	862.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,614.517470
5720	5720			
111		.500000 x	15.741598 =	7.870799
510		.062500 x	395.407470 =	24.712967
630		10.000000 x	2.126236 =	21.262360
630.1		10.000000 x	2.372445 =	23.724450

			T.E =	77.570576
5730	5730			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199