

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων

1ο Τρίμηνο του 2012

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.151500
051	14.630000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.243100
212	1.434100
213	1.949500
214	4.550000
221	.099900
224	.070000
231	.895000
241	7.750000
242	4.500000
251	290.000000
252	290.000000
301	3.860000
302	6.360000
360	12.200000
361	31.300000
362	3.900000
363	.630000
364	3.900000
365	25.500000
366	23.500000
367	.134900
368	22.150000
369	13.470000
370	8.860000
371	8.000000
372	1.400000
373	2.250000
374	3.050000
375	1.660000
376	
377	3.600000
378	.540000
379	15.900000
380	.290000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
417	134.530000

420
428
450
451
452
453
454
455

97.290000
437.840000
115.120000
159.550000
97.760000
90.720000
122.640000
432.990000

501	501			
211		50.000000 x	1.243100 =	62.155000
214		3.000000 x	4.550000 =	13.650000
401		1.000000 x	268.420000 =	268.420000
118		3.000000 x	10.001019 =	30.003057
114		8.000000 x	23.886192 =	191.089536

				ΑΘΡΟΙΣΜΑ =
				565.317593

				Η.Δ. =
				621.849352
502	502			
211		80.000000 x	1.243100 =	99.448000
114		8.000000 x	23.886192 =	191.089536
402		1.000000 x	380.180000 =	380.180000
214		7.000000 x	4.550000 =	31.850000
118		4.000000 x	10.001019 =	40.004076

				ΑΘΡΟΙΣΜΑ =
				742.571612

				Η.Δ. =
				816.828773
503	503			
211		110.000000 x	1.243100 =	136.741000
428		1.000000 x	437.840000 =	437.840000
214		10.000000 x	4.550000 =	45.500000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536

				ΑΘΡΟΙΣΜΑ =
				851.174612

				Η.Δ. =
				936.292073
504	504			
211		40.000000 x	1.243100 =	49.724000
214		2.000000 x	4.550000 =	9.100000
114		8.000000 x	23.886192 =	191.089536
403		1.000000 x	103.360000 =	103.360000

				ΑΘΡΟΙΣΜΑ =
				353.273536

				Η.Δ. =
				388.600890
505	505			
211		200.000000 x	1.243100 =	248.620000
214		10.000000 x	4.550000 =	45.500000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
404		1.000000 x	212.730000 =	212.730000

				ΑΘΡΟΙΣΜΑ =
				777.947688

				Η.Δ. =
				855.742457

506	506			
211		95.000000 x	1.243100 =	118.094500
214		6.000000 x	4.550000 =	27.300000
405		1.000000 x	206.720000 =	206.720000
242		2.500000 x	4.500000 =	11.250000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	634.462188

			Η.Δ. =	697.908407
507	507			
211		165.000000 x	1.243100 =	205.111500
214		10.000000 x	4.550000 =	45.500000
242		7.000000 x	4.500000 =	31.500000
406		1.000000 x	320.980000 =	320.980000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152

			ΑΘΡΟΙΣΜΑ =	874.189188

			Η.Δ. =	961.608107
508	508			
211		40.000000 x	1.243100 =	49.724000
407		1.000000 x	55.210000 =	55.210000
115		4.000000 x	21.778427 =	87.113708
116		16.000000 x	20.419486 =	326.711776
408		2.000000 x	4.530000 =	9.060000
214		2.000000 x	4.550000 =	9.100000

			ΑΘΡΟΙΣΜΑ =	536.919484

			Η.Δ. =	590.611432
509	509			
211		80.000000 x	1.243100 =	99.448000
117		8.000000 x	16.777917 =	134.223336
409		1.000000 x	126.080000 =	126.080000
214		5.000000 x	4.550000 =	22.750000

			ΑΘΡΟΙΣΜΑ =	382.501336

			Η.Δ. =	420.751470
510	510			
211		80.000000 x	1.243100 =	99.448000
117		8.000000 x	16.777917 =	134.223336
214		5.000000 x	4.550000 =	22.750000
410		1.000000 x	116.530000 =	116.530000

			ΑΘΡΟΙΣΜΑ =	372.951336

			Η.Δ. =	410.246470

511	511			
212		17.000000 x	1.434100 =	24.379700
411		1.000000 x	27.370000 =	27.370000
214		1.000000 x	4.550000 =	4.550000
115		4.000000 x	21.778427 =	87.113708
112		30.000000 x	17.312112 =	519.363360

			ΑΘΡΟΙΣΜΑ =	662.776768

			Η.Δ. =	729.054445
512	512			
211		10.000000 x	1.243100 =	12.431000
115		2.000000 x	21.778427 =	43.556854
214		1.000000 x	4.550000 =	4.550000
112		2.000000 x	17.312112 =	34.624224
412		1.000000 x	2.990000 =	2.990000

			ΑΘΡΟΙΣΜΑ =	98.152078

			Η.Δ. =	107.967286
518	518			
211		180.000000 x	1.243100 =	223.758000
212		5.000000 x	1.434100 =	7.170500
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
112		8.000000 x	17.312112 =	138.496896
417		1.000000 x	134.530000 =	134.530000
214		12.000000 x	4.550000 =	54.600000

			ΑΘΡΟΙΣΜΑ =	829.653084

			Η.Δ. =	912.618392
521	521			
211		40.000000 x	1.243100 =	49.724000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536
214		3.000000 x	4.550000 =	13.650000
420		1.000000 x	97.290000 =	97.290000

			ΑΘΡΟΙΣΜΑ =	391.757612

			Η.Δ. =	430.933373
550	550			
211		80.000000 x	1.243100 =	99.448000
214		5.000000 x	4.550000 =	22.750000
117		8.000000 x	16.777917 =	134.223336
450		1.000000 x	115.120000 =	115.120000

			ΑΘΡΟΙΣΜΑ =	371.541336

			Η.Δ. =	408.695470

560	560			
211		80.000000 x	1.243100 =	99.448000
117		8.000000 x	16.777917 =	134.223336
455		1.000000 x	432.990000 =	432.990000
214		7.000000 x	4.550000 =	31.850000

			ΑΘΡΟΙΣΜΑ =	698.511336

			Η.Δ. =	768.362470
621	621			
213		.100000 x	1.949500 =	.194950
508		.005000 x	590.611432 =	2.953057
116		.200000 x	20.419486 =	4.083897
111		.800000 x	15.741598 =	12.593278

			B.T =	19.825183
623	623			
213		.100000 x	1.949500 =	.194950
508		.005000 x	590.611432 =	2.953057
504		.005000 x	388.600890 =	1.943004
116		.200000 x	20.419486 =	4.083897
112		.100000 x	17.312112 =	1.731211
518		.010000 x	912.618392 =	9.126184
509		.005000 x	420.751470 =	2.103757

			B.T =	22.136061
625	625			
213		.100000 x	1.949500 =	.194950
116		.200000 x	20.419486 =	4.083897
112		.100000 x	17.312112 =	1.731211
504		.005000 x	388.600890 =	1.943004
509		.005000 x	420.751470 =	2.103757
518		.014300 x	912.618392 =	13.050443
508		.005000 x	590.611432 =	2.953057

			B.T =	26.060320
630	630			
512		.020000 x	107.967286 =	2.159346

			B.T =	2.159346
630.1	630.1			
510		.006000 x	410.246470 =	2.461479

			B.T =	2.461479

641	641			
231		.200000 x	.895000 =	.179000
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.550243
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.011100 x	420.751470 =	4.670341
509		.003600 x	420.751470 =	1.514705
511		.050000 x	729.054445 =	36.452722
630		.600000 x	2.159346 =	1.295608
625		1.000000 x	26.060320 =	26.060320
224		120.000000 x	.070000 =	8.400000

			B.T =	125.647149
652	652			
221		650.000000 x	.099900 =	64.935000
509		.001920 x	420.751470 =	.807843
630		.320000 x	2.159346 =	.690991
625		1.000000 x	26.060320 =	26.060320
511		.050000 x	729.054445 =	36.452722
509		.011000 x	420.751470 =	4.628266
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	165.843595
1121	1121			
112		.007000 x	17.312112 =	.121185
503		.002000 x	936.292073 =	1.872584
501		.000100 x	621.849352 =	.062185

			T.E =	2.055954
1122	1122			
112		.007000 x	17.312112 =	.121185
505		.000600 x	855.742457 =	.513445
509		.004447 x	420.751470 =	1.871082
501		.000080 x	621.849352 =	.049748
507		.001400 x	961.608107 =	1.346251
503		.000330 x	936.292073 =	.308976

			T.E =	4.210688

1123A	1123A			
112		.007000 x	17.312112 =	.121185
503		.002000 x	936.292073 =	1.872584
501		.000100 x	621.849352 =	.062185
509		.005312 x	420.751470 =	2.235032
506		.001330 x	697.908407 =	.928218

			T.E =	5.219204
1123B	1123B			
509		.001487 x	420.751470 =	.625657

			T.E =	.625657
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	430.933373 =	.086187
501		.000100 x	621.849352 =	.062185

			T.E =	.321493
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	4.210688 =	.842138
502		.000200 x	816.828773 =	.163366
501		.000100 x	621.849352 =	.062185
507		.000200 x	961.608107 =	.192322

			T.E =	2.047090
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	4.210688 =	4.210688
501		.002000 x	621.849352 =	1.243699

			T.E =	9.782415
1710	1710			
360		1.000000 x	12.200000 =	12.200000
501		.000100 x	621.849352 =	.062185
111		.250000 x	15.741598 =	3.935400

			T.E =	16.197584
2111	2111			
112		.010000 x	17.312112 =	.173121
		.002000 x	816.828773 =	1.633658
501		.000830 x	621.849352 =	.516135
509		.005202 x	420.751470 =	2.188749
507		.001540 x	961.608107 =	1.480876

			T.E =	5.992539

2112	2112			
213		.400000 x	1.949500 =	.779800
112		.250000 x	17.312112 =	4.328028
508		.004000 x	590.611432 =	2.362446
507		.002000 x	961.608107 =	1.923216
116		.250000 x	20.419486 =	5.104872
509		.004896 x	420.751470 =	2.059999
502		.002900 x	816.828773 =	2.368803
			T.E =	18.927164
2251	2251			
111		.600000 x	15.741598 =	9.444959
112		.600000 x	17.312112 =	10.387267
621		1.050000 x	19.825183 =	20.816442
509		.012432 x	420.751470 =	5.230782
			T.E =	45.879450
2252	2252			
111		1.400000 x	15.741598 =	22.038237
509		.012432 x	420.751470 =	5.230782
621		1.050000 x	19.825183 =	20.816442
113		1.400000 x	20.419486 =	28.587280
			T.E =	76.672742
2253	2253			
111		1.500000 x	15.741598 =	23.612397
113		2.500000 x	20.419486 =	51.048715
621		1.050000 x	19.825183 =	20.816442
652		.020000 x	165.843595 =	3.316872
651		.250000 x	125.647149 =	31.411787
509		.012432 x	420.751470 =	5.230782
112		.200000 x	17.312112 =	3.462422
			T.E =	138.899418
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	165.843595 =	16.584360
621		.350000 x	19.825183 =	6.938814
509		.003788 x	420.751470 =	1.593807
113		1.500000 x	20.419486 =	30.629229
			T.E =	68.339488

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	22.136061 =	17.708849
630		.250000 x	2.159346 =	.539837
641		3.000000 x	7.550243 =	22.650729
625		.500000 x	26.060320 =	13.030160
511		.040000 x	729.054445 =	29.162178
509		.008880 x	420.751470 =	3.736273
509		.001500 x	420.751470 =	.631127
509		.005550 x	420.751470 =	2.335171
113		1.600000 x	20.419486 =	32.671178

			T.E =	176.672457
2921	2921			
301		1.000000 x	3.860000 =	3.860000
2522		.005000 x	176.672457 =	.883362
652		.002000 x	165.843595 =	.331687
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.539483
2922	2922			
302		1.020000 x	6.360000 =	6.487200
652		.012000 x	165.843595 =	1.990123
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.257871
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	408.695470 =	1.532608

			T.E =	2.004856

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	408.695470 =	1.021739

			T.E =	1.493987
5160	5160			
213		.400000 x	1.949500 =	.779800
111		.160000 x	15.741598 =	2.518656
508		.001500 x	590.611432 =	.885917

			T.E =	4.184373
5210	5210			
363		.100000 x	.630000 =	.063000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.558270
5220	5220			
363		.100000 x	.630000 =	.063000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.897195
5230	5230			
364		1.000000 x	3.900000 =	3.900000
112		.080000 x	17.312112 =	1.384969

			T.E =	5.284969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.461479 =	.049230
510		.000250 x	410.246470 =	.102562
630		.020000 x	2.159346 =	.043187

			T.E =	.226461

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.461479 =	.049230
510		.000163 x	410.246470 =	.066870
630		.020000 x	2.159346 =	.043187
			T.E =	.179751
5321	5321			
111		.004000 x	15.741598 =	.062966
			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947
			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463
			T.E =	.349463
5340	5340			
363		.100000 x	.630000 =	.063000
111		.003300 x	15.741598 =	.051947
			T.E =	.114947
5351	5351			
113		.005000 x	20.419486 =	.102097
			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873
			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390
			T.E =	.565806

5354	5354			
111		.035000 x	15.741598 =	.550956
113		.025000 x	20.419486 =	.510487

			T.E =	1.061443
5361A	5361A			
365		.003000 x	25.500000 =	.076500
630		.000300 x	2.159346 =	.000648
510		.000188 x	410.246470 =	.077126
113		.001500 x	20.419486 =	.030629

			T.E =	.184903
5361B	5361B			
366		.003000 x	23.500000 =	.070500
510		.000188 x	410.246470 =	.077126
630		.000300 x	2.159346 =	.000648
113		.001500 x	20.419486 =	.030629

			T.E =	.178903
5362A	5362A			
365		.005000 x	25.500000 =	.127500
630		.000500 x	2.159346 =	.001080
510		.000313 x	410.246470 =	.128407
113		.002500 x	20.419486 =	.051049

			T.E =	.308036
5362B	5362B			
366		.005000 x	23.500000 =	.117500
630		.000500 x	2.159346 =	.001080
510		.000313 x	410.246470 =	.128407
113		.002500 x	20.419486 =	.051049

			T.E =	.298036
5363A	5363A			
365		.003000 x	25.500000 =	.076500
113		.001000 x	20.419486 =	.020419
510		.000125 x	410.246470 =	.051281
630		.000300 x	2.159346 =	.000648

			T.E =	.148848

5363B	5363B			
366		.003000 x	23.500000 =	.070500
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.159346 =	.000648
510		.000125 x	410.246470 =	.051281

			T.E =	.142848
5364A	5364A			
365		.005000 x	25.500000 =	.127500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.159346 =	.001080
510		.000225 x	410.246470 =	.092305

			T.E =	.257640
5364B	5364B			
366		.005000 x	23.500000 =	.117500
630		.000500 x	2.159346 =	.001080
510		.000225 x	410.246470 =	.092305
113		.001800 x	20.419486 =	.036755

			T.E =	.247640
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	15.900000 =	31.800000
510		.100000 x	410.246470 =	41.024647
630		.100000 x	2.159346 =	.215935
113		.800000 x	20.419486 =	16.335589

			T.E =	89.376170
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	408.695470 =	168.586881

			T.E =	247.294871
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	31.300000 =	469.500000	
363		20.000000 x	.630000 =	12.600000	
362		30.000000 x	3.900000 =	117.000000	
550		.375000 x	408.695470 =	153.260801	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	25.500000 =	51.000000	
111		20.000000 x	15.741598 =	314.831960	

			T.E =	1,526.582481	
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.461479 =	24.614790	
510		.125000 x	410.246470 =	51.280809	
630		10.000000 x	2.159346 =	21.593460	

			T.E =	113.230657	
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

			T.E =	23.612397	
5530	5530				
453		.187500 x	90.720000 =	17.010000	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	48.493196	
5540	5540				
363		15.000000 x	.630000 =	9.450000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	21.256199	
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	47.224794	
5552	5552				
379		1.000000 x	15.900000 =	15.900000	
630		.100000 x	2.159346 =	.215935	
510		.050000 x	410.246470 =	20.512324	
113		.400000 x	20.419486 =	8.167794	

			T.E =	44.796053	

5560A	5560A			
365		1.000000 x	25.500000 =	25.500000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.159346 =	.215935
510		.100000 x	410.246470 =	41.024647

			T.E =	83.076170
5560B	5560B			
366		1.000000 x	23.500000 =	23.500000
510		.100000 x	410.246470 =	41.024647
630		.100000 x	2.159346 =	.215935
113		.800000 x	20.419486 =	16.335589

			T.E =	81.076170
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.630000 =	9.450000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	408.695470 =	51.086934
367		20,000.000000 x	.134900 =	2,698.000000

			T.E =	3,230.784874
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.159346 =	21.593460
630.1		10.000000 x	2.461479 =	24.614790
510		.125000 x	410.246470 =	51.280809

			T.E =	113.230657
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630			
363		15.000000 x	.630000 =	9.450000
111		.750000 x	15.741598 =	11.806199

			T.E =	21.256199
5640	5640			
111		10.000000 x	15.741598 =	157.415980
111		2.000000 x	15.741598 =	31.483196

			T.E =	188.899176
5650	5650			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240
5710	5710			
362		40.000000 x	3.900000 =	156.000000
111		5.000000 x	15.741598 =	78.707990
112		1.000000 x	17.312112 =	17.312112
560		.125000 x	768.362470 =	96.045309
510		.125000 x	410.246470 =	51.280809
509		.125000 x	420.751470 =	52.593934
114		1.000000 x	23.886192 =	23.886192
380		800.000000 x	.290000 =	232.000000
363		15.000000 x	.630000 =	9.450000
377		250.000000 x	3.600000 =	900.000000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,671.276345
5720	5720			
111		.500000 x	15.741598 =	7.870799
510		.062500 x	410.246470 =	25.640404
630		10.000000 x	2.159346 =	21.593460
630.1		10.000000 x	2.461479 =	24.614790

			T.E =	79.719453
5730	5730			
363		15.000000 x	.630000 =	9.450000
111		.750000 x	15.741598 =	11.806199

			T.E =	21.256199