

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών Έργων

2ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	Κατχ Τιμή X 1.8117/ 6.46	15.951934
002	Κατχ Τιμή X 1.8117/ 6.46	17.729980
003	Κατχ Τιμή X 1.8117/ 6.46	23.479183
026		.097700
036		.128500
273		.836500
297.1		1.800000
510		3.020000
511		.620000
513		1.100000
561		1.980000
565.3		3.060000
566.3		4.090000
567.13		18.120000
571.5.1		1.510000
572.1.7		3.860000
575.3		
581.2		8.750000
582.2		22.600000
588.3		
603.3		4.890000
605.3.5		136.000000
619.2.2		39.000000
620.1		67.800000
621.1		60.000000
630.1.2		280.000000
634.1.1		85.000000
647.2		17.400000
660.1.1		20.340000
667		139.000000
671.3.8		3,820.000000
672.4.6		4,650.000000
673.1.5		4,870.000000
684.6.2		106.000000
686.1		410.000000
687.1.1		2,300.000000
703.2.2		23.660000
714.2.6		5,140.000000
715.2.9		5,098.000000
718.3.3		1,040.000000
719.1.3		1,000.000000
720.11		7.000000
729.1.2		820.000000
730.2.5		1.850000
732.5.30		66.000000
744.9		56,210.000000
755.10		10,660.000000
757.1.4		14,035.000000
760.1.4		3,725.000000
801.3.2		.172000
801.7.1		1.570000
812.1.2		.083800
812.2.3		.972400
813.2.3		1.410500
816.3.2		.498200
820.5.1		.432100
820.5.4		1.493400
825.6.1		.438600
826.2.1		1.580000

835.1.2	66.200000
841.3.5	180.000000
842.3.2	76.000000
848.1.2	32.000000
852.1.6	930.000000
855.1.13	2,633.000000
858.1.2	2.910000
859.1.2	4.480000
865.13.10	18,000.000000
865.13.9	15,600.000000
865.8.3	38.500000
867.1.22	75,800.000000
871.7.4	47.160000
872.23.1	4.070000
880.1.2	.690000
885.1.2	17.500000
890.1.1	105.000000
910.2.5	7,350.000000
911.1.17	3,290.000000
912.1.5	3,059.000000
913.1.9	64.800000
914.1.8	114.000000
915.1.6	300.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	6,880.000000
918.1.1	1,894.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,100.000000
931.1.5	345.000000
931.2.4	895.000000
932.4.2	348.000000
933.1.1	13.610000
934.1.1	315.000000
935.1.1	71.000000
950.1.1	3.560000
951.1.7	600.000000
951.2.2	12,340.000000
952.1.4	335.000000
953.1.3	26,500.000000

1	1			
026		1.100000 x	.097700 =	.107470
297.1		1.200000 x	1.800000 =	2.160000
582.2		1.300000 x	22.600000 =	29.380000
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938

			T.E =	85.219382
10	10			
581.2		1.200000 x	8.750000 =	10.500000
003		.300000 x	23.479183 =	7.043755
001		.300000 x	15.951934 =	4.785580

			T.E =	22.329335
100	100			
931.1.5		1.000000 x	345.000000 =	345.000000
003		4.000000 x	23.479183 =	93.916732
002		6.000000 x	17.729980 =	106.379880

			T.E =	545.296612
101	101			
931.2.4		1.000000 x	895.000000 =	895.000000
002		9.000000 x	17.729980 =	159.569820
003		6.000000 x	23.479183 =	140.875098

			T.E =	1,195.444918
102	102			
820.5.4		1.020000 x	1.493400 =	1.523268
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	9.765101
103	103			
932.4.2		1.000000 x	348.000000 =	348.000000
002		2.500000 x	17.729980 =	44.324950
003		2.500000 x	23.479183 =	58.697958

			T.E =	451.022908
104	104			
933.1.1		1.000000 x	13.610000 =	13.610000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976

			T.E =	63.060996

105	105			
934.1.1		1.000000 x	315.000000 =	315.000000
002		2.000000 x	17.729980 =	35.459960
003		2.000000 x	23.479183 =	46.958366

			T.E =	397.418326
106	106			
951.1.7		1.030000 x	600.000000 =	618.000000
002		4.000000 x	17.729980 =	70.919920
003		4.000000 x	23.479183 =	93.916732

			T.E =	782.836652
107	107			
952.1.4		1.030000 x	335.000000 =	345.050000
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183

			T.E =	386.259163
108	108			
951.2.2		1.030000 x	12,340.000000 =	12,710.200000
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880

			T.E =	12,957.454978
109	109			
953.1.3		1.030000 x	26,500.000000 =	27,295.000000
003		12.000000 x	23.479183 =	281.750196
002		12.000000 x	17.729980 =	212.759760

			T.E =	27,789.509956
11	11			
603.3		1.030000 x	4.890000 =	5.036700
003		.500000 x	23.479183 =	11.739592

			T.E =	16.776292
110	110			
950.1.1		1.050000 x	3.560000 =	3.738000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	11.979833

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	167.525498	
13	13				
619.2.2		1.030000 x	39.000000 =	40.170000	
002		.400000 x	17.729980 =	7.091992	
003		.400000 x	23.479183 =	9.391673	

			T.E =	56.653665	
14	14				
026		15.000000 x	.097700 =	1.465500	
620.1		1.000000 x	67.800000 =	67.800000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	

			T.E =	151.683826	
15	15				
621.1		1.000000 x	60.000000 =	60.000000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	
621.1		.100000 x	60.000000 =	6.000000	

			T.E =	148.418326	
16	16				
630.1.2		1.000000 x	280.000000 =	280.000000	
003		3.000000 x	23.479183 =	70.437549	
002		3.000000 x	17.729980 =	53.189940	
630.1.2		.050000 x	280.000000 =	14.000000	

			T.E =	417.627489	
17	17				
634.1.1		1.200000 x	85.000000 =	102.000000	
003		2.000000 x	23.479183 =	46.958366	
002		.200000 x	17.729980 =	3.545996	
634.1.1		.050000 x	85.000000 =	4.250000	

			T.E =	156.754362	
18	18				
647.2		1.000000 x	17.400000 =	17.400000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	22.095837	

19	19			
660.1.1		1.030000 x	20.340000 =	20.950200
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	29.192033
2	2			
561		5.320000 x	1.980000 =	10.533600
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988

			T.E =	35.259098
20	20			
667		1.000000 x	139.000000 =	139.000000
667		.020000 x	139.000000 =	2.780000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920

			T.E =	306.616652
21	21			
671.3.8		1.000000 x	3,820.000000 =	3,820.000000
671.3.8		.100000 x	3,820.000000 =	382.000000
002		20.000000 x	17.729980 =	354.599600
003		20.000000 x	23.479183 =	469.583660

			T.E =	5,026.183260
22	22			
672.4.6		1.000000 x	4,650.000000 =	4,650.000000
672.4.6		.100000 x	4,650.000000 =	465.000000
003		20.000000 x	23.479183 =	469.583660
002		20.000000 x	17.729980 =	354.599600

			T.E =	5,939.183260
23	23			
673.1.5		1.000000 x	4,870.000000 =	4,870.000000
003		25.000000 x	23.479183 =	586.979575
002		25.000000 x	17.729980 =	443.249500
687.1.1		1.000000 x	2,300.000000 =	2,300.000000
687.1.1		.020000 x	2,300.000000 =	46.000000
673.1.5		.020000 x	4,870.000000 =	97.400000

			T.E =	8,343.629075

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	23.479183 =	23.479183	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	149.329163	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	23.479183 =	93.916732	
002		4.000000 x	17.729980 =	70.919920	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	583.036652	
26	26				
703.2.2		1.020000 x	23.660000 =	24.133200	
003		.250000 x	23.479183 =	5.869796	
002		.250000 x	17.729980 =	4.432495	

			T.E =	34.435491	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	23.479183 =	234.791830	
002		10.000000 x	17.729980 =	177.299800	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.951934 =	79.759670	

			T.E =	5,734.651300	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	23.479183 =	281.750196	
002		12.000000 x	17.729980 =	212.759760	
001		6.000000 x	15.951934 =	95.711604	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,790.181560	
29	29				
718.3.3		1.000000 x	1,040.000000 =	1,040.000000	
002		8.000000 x	17.729980 =	141.839840	
718.3.3		.050000 x	1,040.000000 =	52.000000	
003		8.000000 x	23.479183 =	187.833464	

			T.E =	1,421.673304	

3	3			
026		1.200000 x	.097700 =	.117240
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976

			T.E =	
30	30			
719.1.3		1.000000 x	1,000.000000 =	1,000.000000
719.1.3		.100000 x	1,000.000000 =	100.000000
003		16.000000 x	23.479183 =	375.666928
002		16.000000 x	17.729980 =	283.679680
001		8.000000 x	15.951934 =	127.615472

			T.E =	1,886.962080
31	31			
720.11		1.020000 x	7.000000 =	7.140000
003		.300000 x	23.479183 =	7.043755

			T.E =	14.183755
32	32			
729.1.2		1.000000 x	820.000000 =	820.000000
002		2.000000 x	17.729980 =	35.459960
003		2.000000 x	23.479183 =	46.958366
729.1.2		.030000 x	820.000000 =	24.600000

			T.E =	927.018326
33	33			
757.1.4		1.000000 x	14,035.000000 =	14,035.000000
757.1.4		.050000 x	14,035.000000 =	701.750000
002		15.000000 x	17.729980 =	265.949700
003		15.000000 x	23.479183 =	352.187745
001		7.000000 x	15.951934 =	111.663538

			T.E =	15,466.550983
34	34			
273		1.000000 x	.836500 =	.836500
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994
273		.100000 x	.836500 =	.083650

			T.E =	13.282899

35	35			
730.2.5		1.050000 x	1.850000 =	1.942500
003		.120000 x	23.479183 =	2.817502
002		.120000 x	17.729980 =	2.127598
730.2.5		.250000 x	1.850000 =	.462500

			T.E =	7.350100
36	36			
732.5.30		1.050000 x	66.000000 =	69.300000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992

			T.E =	85.783665
37	37			
744.9		1.000000 x	56,210.000000 =	56,210.000000
744.9		.020000 x	56,210.000000 =	1,124.200000
001		10.000000 x	15.951934 =	159.519340
002		20.000000 x	17.729980 =	354.599600
003		20.000000 x	23.479183 =	469.583660

			T.E =	58,317.902600
38	38			
755.10		1.000000 x	10,660.000000 =	10,660.000000
755.10		.020000 x	10,660.000000 =	213.200000
001		10.000000 x	15.951934 =	159.519340
002		10.000000 x	17.729980 =	177.299800
003		10.000000 x	23.479183 =	234.791830

			T.E =	11,444.810970
39	39			
760.1.4		1.000000 x	3,725.000000 =	3,725.000000
760.1.4		.050000 x	3,725.000000 =	186.250000
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141

			T.E =	4,055.482071
4	4			
565.3		1.250000 x	3.060000 =	3.825000
002		.600000 x	17.729980 =	10.637988
003		.600000 x	23.479183 =	14.087510

			T.E =	28.550498

40	40			
036		3.000000 x	.128500 =	.385500
003		.450000 x	23.479183 =	10.565632
002		.450000 x	17.729980 =	7.978491
510		.350000 x	3.020000 =	1.057000
511		.250000 x	.620000 =	.155000
513		.250000 x	1.100000 =	.275000

			T.E =	20.416623
41	41			
801.3.2		1.050000 x	.172000 =	.180600
003		.100000 x	23.479183 =	2.347918
801.3.2		.105000 x	.172000 =	.018060
002		.100000 x	17.729980 =	1.772998

			T.E =	4.319576
42	42			
801.7.1		1.050000 x	1.570000 =	1.648500
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
801.7.1		.210000 x	1.570000 =	.329700

			T.E =	10.220033
43	43			
812.1.2		1.050000 x	.083800 =	.087990
003		.020000 x	23.479183 =	.469584
002		.020000 x	17.729980 =	.354600

			T.E =	.912173
44	44			
812.2.3		1.050000 x	.972400 =	1.021020
003		.060000 x	23.479183 =	1.408751
002		.060000 x	17.729980 =	1.063799

			T.E =	3.493570
45	45			
813.2.3		1.050000 x	1.410500 =	1.481025
813.2.3		.105000 x	1.410500 =	.148103
003		.050000 x	23.479183 =	1.173959
002		.050000 x	17.729980 =	.886499

			T.E =	3.689586

46	46			
816.3.2		1.050000 x	.498200 =	.523110
816.3.2		.157500 x	.498200 =	.078467
002		.120000 x	17.729980 =	2.127598
003		.120000 x	23.479183 =	2.817502

			T.E =	5.546676
47	47			
820.5.1		1.050000 x	.432100 =	.453705
820.5.1		.157500 x	.432100 =	.068056
003		.140000 x	23.479183 =	3.287086
002		.140000 x	17.729980 =	2.482197

			T.E =	6.291044
48	48			
825.6.1		1.050000 x	.438600 =	.460530
003		.100000 x	23.479183 =	2.347918
002		.100000 x	17.729980 =	1.772998
825.6.1		.157500 x	.438600 =	.069080

			T.E =	4.650526
49	49			
826.2.1		1.000000 x	1.580000 =	1.580000
003		.200000 x	23.479183 =	4.695837

			T.E =	6.275837
5	5			
566.3		1.250000 x	4.090000 =	5.112500
002		.600000 x	17.729980 =	10.637988
003		.600000 x	23.479183 =	14.087510

			T.E =	29.837998
50	50			
842.3.2		.030000 x	76.000000 =	2.280000
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592
842.3.2		1.000000 x	76.000000 =	76.000000

			T.E =	98.884582
51	51			
841.3.5		1.000000 x	180.000000 =	180.000000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
841.3.5		.030000 x	180.000000 =	5.400000

			T.E =	226.609163

52	52				
835.1.2		1.050000 x	66.200000 =	69.510000	
003		3.000000 x	23.479183 =	70.437549	
002		3.000000 x	17.729980 =	53.189940	

			T.E =	193.137489	
53	53				
848.1.2		1.020000 x	32.000000 =	32.640000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	37.335837	
54	54				
858.1.2		1.020000 x	2.910000 =	2.968200	
003		.200000 x	23.479183 =	4.695837	

			T.E =	7.664037	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	23.479183 =	4.695837	

			T.E =	9.265437	
56	56				
865.8.3		1.050000 x	38.500000 =	40.425000	
003		2.000000 x	23.479183 =	46.958366	
002		2.000000 x	17.729980 =	35.459960	

			T.E =	122.843326	
57	57				
865.13.9		1.020000 x	15,600.000000 =	15,912.000000	
002		25.000000 x	17.729980 =	443.249500	
003		25.000000 x	23.479183 =	586.979575	
001		10.000000 x	15.951934 =	159.519340	

			T.E =	17,101.748415	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.729980 =	2,304.897400	
003		130.000000 x	23.479183 =	3,052.293790	
001		130.000000 x	15.951934 =	2,073.751420	

			T.E =	85,504.942610	

59	59				
871.7.4		1.000000 x	47.160000 =	47.160000	
003		1.200000 x	23.479183 =	28.175020	
002		1.200000 x	17.729980 =	21.275976	
871.7.4		.020000 x	47.160000 =	.943200	

			T.E =	97.554196	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	23.479183 =	23.479183	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	64.765163	
60	60				
872.23.1		1.020000 x	4.070000 =	4.151400	
003		.600000 x	23.479183 =	14.087510	
002		.600000 x	17.729980 =	10.637988	
880.1.2		1.000000 x	.690000 =	.690000	

			T.E =	29.566898	
61	61				
885.1.2		1.000000 x	17.500000 =	17.500000	
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	

			T.E =	42.225498	
62	62				
890.1.1		1.000000 x	105.000000 =	105.000000	
890.1.1		.050000 x	105.000000 =	5.250000	
002		2.000000 x	17.729980 =	35.459960	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	192.668326	
63	63				
910.2.5		1.000000 x	7,350.000000 =	7,350.000000	
002		50.000000 x	17.729980 =	886.499000	
001		30.000000 x	15.951934 =	478.558020	
003		50.000000 x	23.479183 =	1,173.959150	
910.2.5		.020000 x	7,350.000000 =	147.000000	

			T.E =	10,036.016170	

7	7			
571.5.1		1.400000 x	1.510000 =	2.114000
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994

			T.E =	14.476749
8	8			
572.1.7		1.350000 x	3.860000 =	5.211000
002		.700000 x	17.729980 =	12.410986
003		.700000 x	23.479183 =	16.435428

			T.E =	34.057414
80	80			
911.1.17		1.050000 x	3,290.000000 =	3,454.500000
002		30.000000 x	17.729980 =	531.899400
003		30.000000 x	23.479183 =	704.375490

			T.E =	4,690.774890
81	81			
912.1.5		1.050000 x	3,059.000000 =	3,211.950000
002		30.000000 x	17.729980 =	531.899400
003		30.000000 x	23.479183 =	704.375490

			T.E =	4,448.224890
82	82			
913.1.9		1.200000 x	64.800000 =	77.760000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920

			T.E =	242.596652
83	83			
914.1.8		1.100000 x	114.000000 =	125.400000
002		2.000000 x	17.729980 =	35.459960
003		2.000000 x	23.479183 =	46.958366

			T.E =	207.818326
84	84			
915.1.6		1.050000 x	300.000000 =	315.000000
002		8.000000 x	17.729980 =	141.839840
003		8.000000 x	23.479183 =	187.833464

			T.E =	644.673304

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	17.729980 =	354.599600
003		20.000000 x	23.479183 =	469.583660

			T.E =	14,580.233260
86	86			
865.13.10		1.020000 x	18,000.000000 =	18,360.000000
003		40.000000 x	23.479183 =	939.167320
002		40.000000 x	17.729980 =	709.199200

			T.E =	20,008.366520
87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	23.479183 =	2,817.501960
002		120.000000 x	17.729980 =	2,127.597600

			T.E =	
88	88			
917.1		.030000 x	6,880.000000 =	206.400000
917.1		1.000000 x	6,880.000000 =	6,880.000000
918.1.1		.030000 x	1,894.000000 =	56.820000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
923.1.1		1.000000 x	61.620000 =	61.620000
003		40.000000 x	23.479183 =	939.167320
002		40.000000 x	17.729980 =	709.199200
923.2.1		1.000000 x	161.400000 =	161.400000
923.2.1		.030000 x	161.400000 =	4.842000
923.1.1		.030000 x	61.620000 =	1.848600
920.1.1		.030000 x	7,479.000000 =	224.370000
918.1.1		1.000000 x	1,894.000000 =	1,894.000000

			T.E =	18,618.667120
89	89			
852.1.6		.020000 x	930.000000 =	18.600000
855.1.13		1.000000 x	2,633.000000 =	2,633.000000
855.1.13		.020000 x	2,633.000000 =	52.660000
925.1.1		1.000000 x	4,100.000000 =	4,100.000000
003		60.000000 x	23.479183 =	1,408.750980
002		60.000000 x	17.729980 =	1,063.798800
925.1.1		.020000 x	4,100.000000 =	82.000000
852.1.6		1.000000 x	930.000000 =	930.000000

			T.E =	10,288.809780

9

9

575.3
003
002

1.200000 x
.300000 x
.300000 x

.000000 =
23.479183 =
17.729980 =

.000000
7.043755
5.318994

T.E =