

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών Έργων

4ο Τρίμηνο του 2009

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

001	Κατχ Τιμή X 1.8117/ 6.46	16.829739
002	Κατχ Τιμή X 1.8117/ 6.46	18.705943
003	Κατχ Τιμή X 1.8117/ 6.46	24.769248
026		.098900
036		.119500
273		.884000
297.1		2.000000
510		3.020000
511		.620000
513		1.100000
561		2.210000
565.3		3.450000
566.3		4.600000
567.13		18.120000
571.5.1		1.730000
572.1.7		3.860000
575.3		
581.2		9.090000
582.2		22.600000
588.3		
603.3		4.890000
605.3.5		136.000000
619.2.2		44.600000
620.1		67.800000
621.1		60.000000
630.1.2		280.000000
634.1.1		85.000000
647.2		17.400000
660.1.1		20.340000
667		139.000000
671.3.8		3,820.000000
672.4.6		4,650.000000
673.1.5		4,870.000000
684.6.2		106.000000
686.1		410.000000
687.1.1		2,300.000000
703.2.2		23.660000
714.2.6		5,140.000000
715.2.9		5,098.000000
718.3.3		1,060.000000
719.1.3		1,000.000000
720.11		7.000000
729.1.2		890.000000
730.2.5		1.850000
732.5.30		67.000000
744.9		61,300.000000
755.10		11,620.000000
757.1.4		15,310.000000
760.1.4		4,065.000000
801.3.2		.172000
801.7.1		1.570000
812.1.2		.137300
812.2.3		1.532500
813.2.3		2.336400
816.3.2		.851500
820.5.1		.736700
820.5.4		2.526700
825.6.1		.685100
826.2.1		1.610000



835.1.2	70.100000
841.3.5	183.000000
842.3.2	77.500000
848.1.2	32.600000
852.1.6	948.000000
855.1.13	2,633.000000
858.1.2	3.060000
859.1.2	4.480000
865.13.10	18,000.000000
865.13.9	15,600.000000
865.8.3	39.000000
867.1.22	75,800.000000
871.7.4	47.160000
872.23.1	4.070000
880.1.2	.720000
885.1.2	17.500000
890.1.1	105.000000
910.2.5	7,800.000000
911.1.17	3,290.000000
912.1.5	3,059.000000
913.1.9	64.800000
914.1.8	114.000000
915.1.6	300.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,300.000000
918.1.1	1,894.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,300.000000
931.1.5	354.000000
931.2.4	955.000000
932.4.2	348.000000
933.1.1	13.830000
934.1.1	320.000000
935.1.1	73.540000
950.1.1	4.100000
951.1.7	600.000000
951.2.2	12,340.000000
952.1.4	335.000000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.098900 =	.108790	
297.1		1.200000 x	2.000000 =	2.400000	
582.2		1.300000 x	22.600000 =	29.380000	
002		1.300000 x	18.705943 =	24.317726	
003		1.300000 x	24.769248 =	32.200022	
-----					
			T.E =	88.406538	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	24.769248 =	7.430774	
001		.300000 x	16.829739 =	5.048922	
-----					
			T.E =	23.387696	
100	100				
931.1.5		1.000000 x	354.000000 =	354.000000	
003		4.000000 x	24.769248 =	99.076992	
002		6.000000 x	18.705943 =	112.235658	
-----					
			T.E =	565.312650	
101	101				
931.2.4		1.000000 x	955.000000 =	955.000000	
002		9.000000 x	18.705943 =	168.353487	
003		6.000000 x	24.769248 =	148.615488	
-----					
			T.E =	1,271.968975	
102	102				
820.5.4		1.020000 x	2.526700 =	2.577234	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	
-----					
			T.E =	11.272272	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	18.705943 =	46.764858	
003		2.500000 x	24.769248 =	61.923120	
-----					
			T.E =	456.687978	
104	104				
933.1.1		1.000000 x	13.830000 =	13.830000	
003		1.200000 x	24.769248 =	29.723098	
002		1.200000 x	18.705943 =	22.447132	
-----					
			T.E =	66.000229	

105	105				
934.1.1		1.000000 x	320.000000 =	320.000000	
002		2.000000 x	18.705943 =	37.411886	
003		2.000000 x	24.769248 =	49.538496	
		-----			
			T.E =	406.950382	
106	106				
951.1.7		1.030000 x	600.000000 =	618.000000	
002		4.000000 x	18.705943 =	74.823772	
003		4.000000 x	24.769248 =	99.076992	
		-----			
			T.E =	791.900764	
107	107				
952.1.4		1.030000 x	335.000000 =	345.050000	
002		1.000000 x	18.705943 =	18.705943	
003		1.000000 x	24.769248 =	24.769248	
		-----			
			T.E =	388.525191	
108	108				
951.2.2		1.030000 x	12,340.000000 =	12,710.200000	
003		6.000000 x	24.769248 =	148.615488	
002		6.000000 x	18.705943 =	112.235658	
		-----			
			T.E =	12,971.051146	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	24.769248 =	297.230976	
002		12.000000 x	18.705943 =	224.471316	
		-----			
			T.E =	27,816.702292	
11	11				
603.3		1.030000 x	4.890000 =	5.036700	
003		.500000 x	24.769248 =	12.384624	
		-----			
			T.E =	17.421324	
110	110				
950.1.1		1.050000 x	4.100000 =	4.305000	
002		.200000 x	18.705943 =	3.741189	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	13.000038	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
		-----			
			T.E =	168.885115	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	18.705943 =	7.482377	
003		.400000 x	24.769248 =	9.907699	
		-----			
			T.E =	63.328076	
14	14				
026		15.000000 x	.098900 =	1.483500	
620.1		1.000000 x	67.800000 =	67.800000	
003		2.000000 x	24.769248 =	49.538496	
002		2.000000 x	18.705943 =	37.411886	
		-----			
			T.E =	156.233882	
15	15				
621.1		1.000000 x	60.000000 =	60.000000	
003		2.000000 x	24.769248 =	49.538496	
002		2.000000 x	18.705943 =	37.411886	
621.1		.100000 x	60.000000 =	6.000000	
		-----			
			T.E =	152.950382	
16	16				
630.1.2		1.000000 x	280.000000 =	280.000000	
003		3.000000 x	24.769248 =	74.307744	
002		3.000000 x	18.705943 =	56.117829	
630.1.2		.050000 x	280.000000 =	14.000000	
		-----			
			T.E =	424.425573	
17	17				
634.1.1		1.200000 x	85.000000 =	102.000000	
003		2.000000 x	24.769248 =	49.538496	
002		.200000 x	18.705943 =	3.741189	
634.1.1		.050000 x	85.000000 =	4.250000	
		-----			
			T.E =	159.529685	
18	18				
647.2		1.000000 x	17.400000 =	17.400000	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	22.353850	

19	19				
660.1.1		1.030000 x	20.340000 =	20.950200	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
		-----			
			T.E =	29.645238	
2	2				
561		5.320000 x	2.210000 =	11.757200	
003		.600000 x	24.769248 =	14.861549	
002		.600000 x	18.705943 =	11.223566	
		-----			
			T.E =	37.842315	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	24.769248 =	99.076992	
002		4.000000 x	18.705943 =	74.823772	
		-----			
			T.E =	315.680764	
21	21				
671.3.8		1.000000 x	3,820.000000 =	3,820.000000	
671.3.8		.100000 x	3,820.000000 =	382.000000	
002		20.000000 x	18.705943 =	374.118860	
003		20.000000 x	24.769248 =	495.384960	
		-----			
			T.E =	5,071.503820	
22	22				
672.4.6		1.000000 x	4,650.000000 =	4,650.000000	
672.4.6		.100000 x	4,650.000000 =	465.000000	
003		20.000000 x	24.769248 =	495.384960	
002		20.000000 x	18.705943 =	374.118860	
		-----			
			T.E =	5,984.503820	
23	23				
673.1.5		1.000000 x	4,870.000000 =	4,870.000000	
003		25.000000 x	24.769248 =	619.231200	
002		25.000000 x	18.705943 =	467.648575	
687.1.1		1.000000 x	2,300.000000 =	2,300.000000	
687.1.1		.020000 x	2,300.000000 =	46.000000	
673.1.5		.020000 x	4,870.000000 =	97.400000	
		-----			
			T.E =	8,400.279775	

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	24.769248 =	24.769248	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	18.705943 =	18.705943	
-----					
			T.E =	151.595191	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	24.769248 =	99.076992	
002		4.000000 x	18.705943 =	74.823772	
686.1		.020000 x	410.000000 =	8.200000	
-----					
			T.E =	592.100764	
26	26				
703.2.2		1.020000 x	23.660000 =	24.133200	
003		.250000 x	24.769248 =	6.192312	
002		.250000 x	18.705943 =	4.676486	
-----					
			T.E =	35.001998	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	24.769248 =	247.692480	
002		10.000000 x	18.705943 =	187.059430	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	16.829739 =	84.148695	
-----					
			T.E =	5,761.700605	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	24.769248 =	297.230976	
002		12.000000 x	18.705943 =	224.471316	
001		6.000000 x	16.829739 =	100.978434	
715.2.9		.020000 x	5,098.000000 =	101.960000	
-----					
			T.E =	5,822.640726	
29	29				
718.3.3		1.000000 x	1,060.000000 =	1,060.000000	
002		8.000000 x	18.705943 =	149.647544	
718.3.3		.050000 x	1,060.000000 =	53.000000	
003		8.000000 x	24.769248 =	198.153984	
-----					
			T.E =	1,460.801528	

3	3			
026		1.200000 x	.098900 =	.118680
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	24.769248 =	29.723098
002		1.200000 x	18.705943 =	22.447132

T.E =

30	30			
719.1.3		1.000000 x	1,000.000000 =	1,000.000000
719.1.3		.100000 x	1,000.000000 =	100.000000
003		16.000000 x	24.769248 =	396.307968
002		16.000000 x	18.705943 =	299.295088
001		8.000000 x	16.829739 =	134.637912

T.E =

1,930.240968

31	31			
720.11		1.020000 x	7.000000 =	7.140000
003		.300000 x	24.769248 =	7.430774

T.E =

14.570774

32	32			
729.1.2		1.000000 x	890.000000 =	890.000000
002		2.000000 x	18.705943 =	37.411886
003		2.000000 x	24.769248 =	49.538496
729.1.2		.030000 x	890.000000 =	26.700000

T.E =

1,003.650382

33	33			
757.1.4		1.000000 x	15,310.000000 =	15,310.000000
757.1.4		.050000 x	15,310.000000 =	765.500000
002		15.000000 x	18.705943 =	280.589145
003		15.000000 x	24.769248 =	371.538720
001		7.000000 x	16.829739 =	117.808173

T.E =

16,845.436038

34	34			
273		1.000000 x	.884000 =	.884000
003		.300000 x	24.769248 =	7.430774
002		.300000 x	18.705943 =	5.611783
273		.100000 x	.884000 =	.088400

T.E =

14.014957

35	35				
730.2.5		1.050000 x	1.850000 =	1.942500	
003		.120000 x	24.769248 =	2.972310	
002		.120000 x	18.705943 =	2.244713	
730.2.5		.250000 x	1.850000 =	.462500	
-----					
			T.E =	7.622023	
36	36				
732.5.30		1.050000 x	67.000000 =	70.350000	
003		.400000 x	24.769248 =	9.907699	
002		.400000 x	18.705943 =	7.482377	
-----					
			T.E =	87.740076	
37	37				
744.9		1.000000 x	61,300.000000 =	61,300.000000	
744.9		.020000 x	61,300.000000 =	1,226.000000	
001		10.000000 x	16.829739 =	168.297390	
002		20.000000 x	18.705943 =	374.118860	
003		20.000000 x	24.769248 =	495.384960	
-----					
			T.E =	63,563.801210	
38	38				
755.10		1.000000 x	11,620.000000 =	11,620.000000	
755.10		.020000 x	11,620.000000 =	232.400000	
001		10.000000 x	16.829739 =	168.297390	
002		10.000000 x	18.705943 =	187.059430	
003		10.000000 x	24.769248 =	247.692480	
-----					
			T.E =	12,455.449300	
39	39				
760.1.4		1.000000 x	4,065.000000 =	4,065.000000	
760.1.4		.050000 x	4,065.000000 =	203.250000	
002		3.500000 x	18.705943 =	65.470801	
003		3.500000 x	24.769248 =	86.692368	
-----					
			T.E =	4,420.413169	
4	4				
565.3		1.250000 x	3.450000 =	4.312500	
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
-----					
			T.E =	30.397615	

40	40				
036		3.000000 x	.119500 =	.358500	
003		.450000 x	24.769248 =	11.146162	
002		.450000 x	18.705943 =	8.417674	
510		.350000 x	3.020000 =	1.057000	
511		.250000 x	.620000 =	.155000	
513		.250000 x	1.100000 =	.275000	
		-----			
			T.E =	21.409336	
41	41				
801.3.2		1.050000 x	.172000 =	.180600	
003		.100000 x	24.769248 =	2.476925	
801.3.2		.105000 x	.172000 =	.018060	
002		.100000 x	18.705943 =	1.870594	
		-----			
			T.E =	4.546179	
42	42				
801.7.1		1.050000 x	1.570000 =	1.648500	
003		.200000 x	24.769248 =	4.953850	
002		.200000 x	18.705943 =	3.741189	
801.7.1		.210000 x	1.570000 =	.329700	
		-----			
			T.E =	10.673238	
43	43				
812.1.2		1.050000 x	.137300 =	.144165	
003		.020000 x	24.769248 =	.495385	
002		.020000 x	18.705943 =	.374119	
		-----			
			T.E =	1.013669	
44	44				
812.2.3		1.050000 x	1.532500 =	1.609125	
003		.060000 x	24.769248 =	1.486155	
002		.060000 x	18.705943 =	1.122357	
		-----			
			T.E =	4.217636	
45	45				
813.2.3		1.050000 x	2.336400 =	2.453220	
813.2.3		.105000 x	2.336400 =	.245322	
003		.050000 x	24.769248 =	1.238462	
002		.050000 x	18.705943 =	.935297	
		-----			
			T.E =	4.872302	

46	46				
816.3.2		1.050000 x	.851500 =	.894075	
816.3.2		.157500 x	.851500 =	.134111	
002		.120000 x	18.705943 =	2.244713	
003		.120000 x	24.769248 =	2.972310	
		-----			
			T.E =	6.245209	
47	47				
820.5.1		1.050000 x	.736700 =	.773535	
820.5.1		.157500 x	.736700 =	.116030	
003		.140000 x	24.769248 =	3.467695	
002		.140000 x	18.705943 =	2.618832	
		-----			
			T.E =	6.976092	
48	48				
825.6.1		1.050000 x	.685100 =	.719355	
003		.100000 x	24.769248 =	2.476925	
002		.100000 x	18.705943 =	1.870594	
825.6.1		.157500 x	.685100 =	.107903	
		-----			
			T.E =	5.174777	
49	49				
826.2.1		1.000000 x	1.610000 =	1.610000	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	6.563850	
5	5				
566.3		1.250000 x	4.600000 =	5.750000	
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
		-----			
			T.E =	31.835115	
50	50				
842.3.2		1.000000 x	77.500000 =	77.500000	
842.3.2		.030000 x	77.500000 =	2.325000	
002		.500000 x	18.705943 =	9.352972	
003		.500000 x	24.769248 =	12.384624	
		-----			
			T.E =	101.562596	
51	51				
841.3.5		1.000000 x	183.000000 =	183.000000	
841.3.5		.030000 x	183.000000 =	5.490000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
		-----			
			T.E =	231.965191	

52	52				
835.1.2		1.050000 x	70.100000 =	73.605000	
003		3.000000 x	24.769248 =	74.307744	
002		3.000000 x	18.705943 =	56.117829	
		-----			
			T.E =	204.030573	
53	53				
848.1.2		1.020000 x	32.600000 =	33.252000	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	38.205850	
54	54				
858.1.2		1.020000 x	3.060000 =	3.121200	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	8.075050	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	24.769248 =	4.953850	
		-----			
			T.E =	9.523450	
56	56				
865.8.3		1.050000 x	39.000000 =	40.950000	
003		2.000000 x	24.769248 =	49.538496	
002		2.000000 x	18.705943 =	37.411886	
		-----			
			T.E =	127.900382	
57	57				
865.13.9		1.020000 x	15,600.000000 =	15,912.000000	
002		25.000000 x	18.705943 =	467.648575	
003		25.000000 x	24.769248 =	619.231200	
001		10.000000 x	16.829739 =	168.297390	
		-----			
			T.E =	17,167.177165	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	18.705943 =	2,431.772590	
003		130.000000 x	24.769248 =	3,220.002240	
001		130.000000 x	16.829739 =	2,187.866070	
		-----			
			T.E =	85,913.640900	

59	59				
871.7.4		1.000000 x	47.160000 =	47.160000	
003		1.200000 x	24.769248 =	29.723098	
002		1.200000 x	18.705943 =	22.447132	
871.7.4		.020000 x	47.160000 =	.943200	
-----					
			T.E =	100.273429	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	24.769248 =	24.769248	
002		1.000000 x	18.705943 =	18.705943	
-----					
			T.E =	67.031191	
60	60				
872.23.1		1.020000 x	4.070000 =	4.151400	
003		.600000 x	24.769248 =	14.861549	
002		.600000 x	18.705943 =	11.223566	
880.1.2		1.000000 x	.720000 =	.720000	
-----					
			T.E =	30.956515	
61	61				
885.1.2		1.000000 x	17.500000 =	17.500000	
002		.600000 x	18.705943 =	11.223566	
003		.600000 x	24.769248 =	14.861549	
-----					
			T.E =	43.585115	
62	62				
890.1.1		1.000000 x	105.000000 =	105.000000	
890.1.1		.050000 x	105.000000 =	5.250000	
002		2.000000 x	18.705943 =	37.411886	
003		2.000000 x	24.769248 =	49.538496	
-----					
			T.E =	197.200382	
63	63				
910.2.5		1.000000 x	7,800.000000 =	7,800.000000	
002		50.000000 x	18.705943 =	935.297150	
001		30.000000 x	16.829739 =	504.892170	
003		50.000000 x	24.769248 =	1,238.462400	
910.2.5		.020000 x	7,800.000000 =	156.000000	
-----					
			T.E =	10,634.651720	

7	7				
571.5.1		1.400000 x	1.730000 =	2.422000	
003		.300000 x	24.769248 =	7.430774	
002		.300000 x	18.705943 =	5.611783	
		-----			
			T.E =	15.464557	
8	8				
572.1.7		1.350000 x	3.860000 =	5.211000	
002		.700000 x	18.705943 =	13.094160	
003		.700000 x	24.769248 =	17.338474	
		-----			
			T.E =	35.643634	
80	80				
911.1.17		1.050000 x	3,290.000000 =	3,454.500000	
002		30.000000 x	18.705943 =	561.178290	
003		30.000000 x	24.769248 =	743.077440	
		-----			
			T.E =	4,758.755730	
81	81				
912.1.5		1.050000 x	3,059.000000 =	3,211.950000	
002		30.000000 x	18.705943 =	561.178290	
003		30.000000 x	24.769248 =	743.077440	
		-----			
			T.E =	4,516.205730	
82	82				
913.1.9		1.200000 x	64.800000 =	77.760000	
003		4.000000 x	24.769248 =	99.076992	
002		4.000000 x	18.705943 =	74.823772	
		-----			
			T.E =	251.660764	
83	83				
914.1.8		1.100000 x	114.000000 =	125.400000	
002		2.000000 x	18.705943 =	37.411886	
003		2.000000 x	24.769248 =	49.538496	
		-----			
			T.E =	212.350382	
84	84				
915.1.6		1.050000 x	300.000000 =	315.000000	
002		8.000000 x	18.705943 =	149.647544	
003		8.000000 x	24.769248 =	198.153984	
		-----			
			T.E =	662.801528	

85	85				
915.3.10		1.050000 x	13,101.000000 =	13,756.050000	
002		20.000000 x	18.705943 =	374.118860	
003		20.000000 x	24.769248 =	495.384960	
-----					
			T.E =	14,625.553820	
86	86				
865.13.10		1.020000 x	18,000.000000 =	18,360.000000	
003		40.000000 x	24.769248 =	990.769920	
002		40.000000 x	18.705943 =	748.237720	
-----					
			T.E =	20,099.007640	
87	87				
916.1.3		1.030000 x	.000000 =	.000000	
916.3.3		1.010000 x	.000000 =	.000000	
916.2.3		1.020000 x	.000000 =	.000000	
003		120.000000 x	24.769248 =	2,972.309760	
002		120.000000 x	18.705943 =	2,244.713160	
-----					
			T.E =		
88	88				
917.1		.030000 x	7,300.000000 =	219.000000	
917.1		1.000000 x	7,300.000000 =	7,300.000000	
918.1.1		.030000 x	1,894.000000 =	56.820000	
920.1.1		1.000000 x	7,479.000000 =	7,479.000000	
923.1.1		1.000000 x	61.620000 =	61.620000	
003		40.000000 x	24.769248 =	990.769920	
002		40.000000 x	18.705943 =	748.237720	
923.2.1		1.000000 x	161.400000 =	161.400000	
923.2.1		.030000 x	161.400000 =	4.842000	
923.1.1		.030000 x	61.620000 =	1.848600	
920.1.1		.030000 x	7,479.000000 =	224.370000	
918.1.1		1.000000 x	1,894.000000 =	1,894.000000	
-----					
			T.E =	19,141.908240	
89	89				
852.1.6		.020000 x	948.000000 =	18.960000	
855.1.13		1.000000 x	2,633.000000 =	2,633.000000	
855.1.13		.020000 x	2,633.000000 =	52.660000	
925.1.1		1.000000 x	4,300.000000 =	4,300.000000	
003		60.000000 x	24.769248 =	1,486.154880	
002		60.000000 x	18.705943 =	1,122.356580	
925.1.1		.020000 x	4,300.000000 =	86.000000	
852.1.6		1.000000 x	948.000000 =	948.000000	
-----					
			T.E =	10,647.131460	

9 9

575.3	1.200000 x	.000000 =	.000000
003	.300000 x	24.769248 =	7.430774
002	.300000 x	18.705943 =	5.611783

-----  
T.E =