

ΑΤΗΕ

Αναλυτικά Τιμολόγια Ηλεκτρομηχανολογικών Έργων

2ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
026	.099900
036	.088800
273	1.236500
297.1	2.500000
510	3.020000
511	.620000
513	1.150000
561	2.600000
565.3	3.800000
566.3	5.050000
567.13	18.120000
571.5.1	2.770000
572.1.7	3.860000
575.3	
581.2	9.090000
582.2	25.500000
588.3	
603.3	5.340000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	65.000000
630.1.2	305.000000
634.1.1	90.000000
647.2	19.000000
660.1.1	16.000000
667	139.000000
671.3.8	4,200.000000
672.4.6	5,050.000000
673.1.5	5,250.000000
684.6.2	106.000000
686.1	410.000000
687.1.1	2,400.000000
703.2.2	24.900000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,070.000000
719.1.3	1,100.000000
720.11	9.000000
729.1.2	1,040.000000
730.2.5	2.180000
732.5.30	75.000000
744.9	74,900.000000
755.10	14,190.000000
757.1.4	18,710.000000
760.1.4	4,800.000000
801.3.2	.202500
801.7.1	1.800000
812.1.2	.189500
812.2.3	2.047200
813.2.3	3.342100
816.3.2	1.077000
820.5.1	.944000
820.5.4	3.426300
825.6.1	.606200
826.2.1	1.610000

835.1.2	76.500000
841.3.5	183.000000
842.3.2	77.500000
848.1.2	32.600000
852.1.6	948.000000
855.1.13	2,732.000000
858.1.2	3.060000
859.1.2	4.480000
865.13.10	19,950.000000
865.13.9	16,500.000000
865.8.3	41.000000
867.1.22	75,800.000000
871.7.4	49.520000
872.23.1	4.400000
880.1.2	.780000
885.1.2	19.000000
890.1.1	115.000000
910.2.5	9,200.000000
911.1.17	3,430.000000
912.1.5	3,059.000000
913.1.9	68.900000
914.1.8	140.000000
915.1.6	338.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,780.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,600.000000
931.1.5	365.000000
931.2.4	1,070.000000
932.4.2	348.000000
933.1.1	15.500000
934.1.1	324.000000
935.1.1	73.540000
950.1.1	6.200000
951.1.7	701.000000
951.2.2	12,650.000000
952.1.4	335.000000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.099900 =	.109890	
297.1		1.200000 x	2.500000 =	3.000000	
582.2		1.300000 x	25.500000 =	33.150000	
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	85.310967	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	20.419486 =	6.125846	
001		.300000 x	15.741598 =	4.722479	

			T.E =	21.756325	
100	100				
931.1.5		1.000000 x	365.000000 =	365.000000	
003		4.000000 x	20.419486 =	81.677944	
002		6.000000 x	17.312112 =	103.872672	

			T.E =	550.550616	
101	101				
931.2.4		1.000000 x	1,070.000000 =	1,070.000000	
002		9.000000 x	17.312112 =	155.809008	
003		6.000000 x	20.419486 =	122.516916	

			T.E =	1,348.325924	
102	102				
820.5.4		1.020000 x	3.426300 =	3.494826	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.041146	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	442.328995	
104	104				
933.1.1		1.000000 x	15.500000 =	15.500000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	

			T.E =	60.777918	

105	105				
934.1.1		1.000000 x	324.000000 =	324.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	399.463196	
106	106				
951.1.7		1.030000 x	701.000000 =	722.030000	
002		4.000000 x	17.312112 =	69.248448	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	872.956392	
107	107				
952.1.4		1.030000 x	335.000000 =	345.050000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	382.781598	
108	108				
951.2.2		1.030000 x	12,650.000000 =	13,029.500000	
003		6.000000 x	20.419486 =	122.516916	
002		6.000000 x	17.312112 =	103.872672	

			T.E =	13,255.889588	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	

			T.E =	27,747.779176	
11	11				
603.3		1.030000 x	5.340000 =	5.500200	
003		.500000 x	20.419486 =	10.209743	

			T.E =	15.709943	
110	110				
950.1.1		1.050000 x	6.200000 =	6.510000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	14.056320	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	165.438959	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	61.030639	
14	14				
026		15.000000 x	.099900 =	1.498500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	149.961696	
15	15				
621.1		1.000000 x	65.000000 =	65.000000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
621.1		.100000 x	65.000000 =	6.500000	

			T.E =	146.963196	
16	16				
630.1.2		1.000000 x	305.000000 =	305.000000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	
630.1.2		.050000 x	305.000000 =	15.250000	

			T.E =	433.444794	
17	17				
634.1.1		1.200000 x	90.000000 =	108.000000	
003		2.000000 x	20.419486 =	40.838972	
002		.200000 x	17.312112 =	3.462422	
634.1.1		.050000 x	90.000000 =	4.500000	

			T.E =	156.801394	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	23.083897	

19	19				
660.1.1		1.030000 x	16.000000 =	16.480000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	24.026320	
2	2				
561		5.320000 x	2.600000 =	13.832000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	

			T.E =	36.470959	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	292.706392	
21	21				
671.3.8		1.000000 x	4,200.000000 =	4,200.000000	
671.3.8		.100000 x	4,200.000000 =	420.000000	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	

			T.E =	5,374.631960	
22	22				
672.4.6		1.000000 x	5,050.000000 =	5,050.000000	
672.4.6		.100000 x	5,050.000000 =	505.000000	
003		20.000000 x	20.419486 =	408.389720	
002		20.000000 x	17.312112 =	346.242240	

			T.E =	6,309.631960	
23	23				
673.1.5		1.000000 x	5,250.000000 =	5,250.000000	
003		25.000000 x	20.419486 =	510.487150	
002		25.000000 x	17.312112 =	432.802800	
687.1.1		1.000000 x	2,400.000000 =	2,400.000000	
687.1.1		.020000 x	2,400.000000 =	48.000000	
673.1.5		.020000 x	5,250.000000 =	105.000000	

			T.E =	8,746.289950	

24	24				
684.6.2		1.000000 x	106.000000 =	106.000000	
003		1.000000 x	20.419486 =	20.419486	
684.6.2		.020000 x	106.000000 =	2.120000	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	145.851598	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	569.126392	
26	26				
703.2.2		1.020000 x	24.900000 =	25.398000	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

			T.E =	34.830900	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	20.419486 =	204.194860	
002		10.000000 x	17.312112 =	173.121120	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.741598 =	78.707990	

			T.E =	5,698.823970	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	20.419486 =	245.033832	
002		12.000000 x	17.312112 =	207.745344	
001		6.000000 x	15.741598 =	94.449588	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,747.188764	
29	29				
718.3.3		1.000000 x	1,070.000000 =	1,070.000000	
002		8.000000 x	17.312112 =	138.496896	
718.3.3		.050000 x	1,070.000000 =	53.500000	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	1,425.352784	

3	3				
026		1.200000 x	.099900 =	.119880	
588.3		1.300000 x	.000000 =	.000000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	

			T.E =		
30	30				
719.1.3		1.000000 x	1,100.000000 =	1,100.000000	
719.1.3		.100000 x	1,100.000000 =	110.000000	
003		16.000000 x	20.419486 =	326.711776	
002		16.000000 x	17.312112 =	276.993792	
001		8.000000 x	15.741598 =	125.932784	

			T.E =	1,939.638352	
31	31				
720.11		1.020000 x	9.000000 =	9.180000	
003		.300000 x	20.419486 =	6.125846	

			T.E =	15.305846	
32	32				
729.1.2		1.000000 x	1,040.000000 =	1,040.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	
729.1.2		.030000 x	1,040.000000 =	31.200000	

			T.E =	1,146.663196	
33	33				
757.1.4		1.000000 x	18,710.000000 =	18,710.000000	
757.1.4		.050000 x	18,710.000000 =	935.500000	
002		15.000000 x	17.312112 =	259.681680	
003		15.000000 x	20.419486 =	306.292290	
001		7.000000 x	15.741598 =	110.191186	

			T.E =	20,321.665156	
34	34				
273		1.000000 x	1.236500 =	1.236500	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	
273		.100000 x	1.236500 =	.123650	

			T.E =	12.679629	

35	35				
730.2.5		1.050000 x	2.180000 =	2.289000	
003		.120000 x	20.419486 =	2.450338	
002		.120000 x	17.312112 =	2.077453	
730.2.5		.250000 x	2.180000 =	.545000	

			T.E =	7.361792	
36	36				
732.5.30		1.050000 x	75.000000 =	78.750000	
003		.400000 x	20.419486 =	8.167794	
002		.400000 x	17.312112 =	6.924845	

			T.E =	93.842639	
37	37				
744.9		1.000000 x	74,900.000000 =	74,900.000000	
744.9		.020000 x	74,900.000000 =	1,498.000000	
001		10.000000 x	15.741598 =	157.415980	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	

			T.E =	77,310.047940	
38	38				
755.10		1.000000 x	14,190.000000 =	14,190.000000	
755.10		.020000 x	14,190.000000 =	283.800000	
001		10.000000 x	15.741598 =	157.415980	
002		10.000000 x	17.312112 =	173.121120	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	15,008.531960	
39	39				
760.1.4		1.000000 x	4,800.000000 =	4,800.000000	
760.1.4		.050000 x	4,800.000000 =	240.000000	
002		3.500000 x	17.312112 =	60.592392	
003		3.500000 x	20.419486 =	71.468201	

			T.E =	5,172.060593	
4	4				
565.3		1.250000 x	3.800000 =	4.750000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	27.388959	

40	40				
036		3.000000 x	.088800 =	.266400	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	
510		.350000 x	3.020000 =	1.057000	
511		.250000 x	.620000 =	.155000	
513		.250000 x	1.150000 =	.287500	

			T.E =	18.745119	
41	41				
801.3.2		1.050000 x	.202500 =	.212625	
003		.100000 x	20.419486 =	2.041949	
801.3.2		.105000 x	.202500 =	.021263	
002		.100000 x	17.312112 =	1.731211	

			T.E =	4.007047	
42	42				
801.7.1		1.050000 x	1.800000 =	1.890000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
801.7.1		.210000 x	1.800000 =	.378000	

			T.E =	9.814320	
43	43				
812.1.2		1.050000 x	.189500 =	.198975	
003		.020000 x	20.419486 =	.408390	
002		.020000 x	17.312112 =	.346242	

			T.E =	.953607	
44	44				
812.2.3		1.050000 x	2.047200 =	2.149560	
003		.060000 x	20.419486 =	1.225169	
002		.060000 x	17.312112 =	1.038727	

			T.E =	4.413456	
45	45				
813.2.3		1.050000 x	3.342100 =	3.509205	
813.2.3		.105000 x	3.342100 =	.350921	
003		.050000 x	20.419486 =	1.020974	
002		.050000 x	17.312112 =	.865606	

			T.E =	5.746705	

ATHE		2ο Τρίμηνο του 2011		Σελ.	12
				Ημ/νία	22/12/2011
46	46				
816.3.2		1.050000 x	1.077000 =		1.130850
816.3.2		.157500 x	1.077000 =		.169628
002		.120000 x	17.312112 =		2.077453
003		.120000 x	20.419486 =		2.450338

			T.E =		5.828269
47	47				
820.5.1		1.050000 x	.944000 =		.991200
820.5.1		.157500 x	.944000 =		.148680
003		.140000 x	20.419486 =		2.858728
002		.140000 x	17.312112 =		2.423696

			T.E =		6.422304
48	48				
825.6.1		1.050000 x	.606200 =		.636510
003		.100000 x	20.419486 =		2.041949
002		.100000 x	17.312112 =		1.731211
825.6.1		.157500 x	.606200 =		.095477

			T.E =		4.505146
49	49				
826.2.1		1.000000 x	1.610000 =		1.610000
003		.200000 x	20.419486 =		4.083897

			T.E =		5.693897
5	5				
566.3		1.250000 x	5.050000 =		6.312500
002		.600000 x	17.312112 =		10.387267
003		.600000 x	20.419486 =		12.251692

			T.E =		28.951459
50	50				
842.3.2		1.000000 x	77.500000 =		77.500000
842.3.2		.030000 x	77.500000 =		2.325000
002		.500000 x	17.312112 =		8.656056
003		.500000 x	20.419486 =		10.209743

			T.E =		98.690799
51	51				
841.3.5		1.000000 x	183.000000 =		183.000000
841.3.5		.030000 x	183.000000 =		5.490000
003		1.000000 x	20.419486 =		20.419486
002		1.000000 x	17.312112 =		17.312112

			T.E =		226.221598

52	52				
835.1.2		1.050000 x	76.500000 =	80.325000	
003		3.000000 x	20.419486 =	61.258458	
002		3.000000 x	17.312112 =	51.936336	

			T.E =	193.519794	
53	53				
848.1.2		1.020000 x	32.600000 =	33.252000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	37.335897	
54	54				
858.1.2		1.020000 x	3.060000 =	3.121200	
003		.200000 x	20.419486 =	4.083897	

			T.E =	7.205097	
55	55				
859.1.2		1.020000 x	4.480000 =	4.569600	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.653497	
56	56				
865.8.3		1.050000 x	41.000000 =	43.050000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	118.513196	
57	57				
865.13.9		1.020000 x	16,500.000000 =	16,830.000000	
002		25.000000 x	17.312112 =	432.802800	
003		25.000000 x	20.419486 =	510.487150	
001		10.000000 x	15.741598 =	157.415980	

			T.E =	17,930.705930	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
002		130.000000 x	17.312112 =	2,250.574560	
003		130.000000 x	20.419486 =	2,654.533180	
001		130.000000 x	15.741598 =	2,046.407740	

			T.E =	85,025.515480	

59	59				
871.7.4		1.000000 x	49.520000 =	49.520000	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
871.7.4		.020000 x	49.520000 =	.990400	

			T.E =	95.788318	
6	6				
567.13		1.300000 x	18.120000 =	23.556000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	61.287598	
60	60				
872.23.1		1.020000 x	4.400000 =	4.488000	
003		.600000 x	20.419486 =	12.251692	
002		.600000 x	17.312112 =	10.387267	
880.1.2		1.000000 x	.780000 =	.780000	

			T.E =	27.906959	
61	61				
885.1.2		1.000000 x	19.000000 =	19.000000	
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	

			T.E =	41.638959	
62	62				
890.1.1		1.000000 x	115.000000 =	115.000000	
890.1.1		.050000 x	115.000000 =	5.750000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	196.213196	
63	63				
910.2.5		1.000000 x	9,200.000000 =	9,200.000000	
002		50.000000 x	17.312112 =	865.605600	
001		30.000000 x	15.741598 =	472.247940	
003		50.000000 x	20.419486 =	1,020.974300	
910.2.5		.020000 x	9,200.000000 =	184.000000	

			T.E =	11,742.827840	

7	7				
571.5.1		1.400000 x	2.770000 =	3.878000	
003		.300000 x	20.419486 =	6.125846	
002		.300000 x	17.312112 =	5.193634	

			T.E =	15.197479	
8	8				
572.1.7		1.350000 x	3.860000 =	5.211000	
002		.700000 x	17.312112 =	12.118478	
003		.700000 x	20.419486 =	14.293640	

			T.E =	31.623119	
80	80				
911.1.17		1.050000 x	3,430.000000 =	3,601.500000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	4,733.447940	
81	81				
912.1.5		1.050000 x	3,059.000000 =	3,211.950000	
002		30.000000 x	17.312112 =	519.363360	
003		30.000000 x	20.419486 =	612.584580	

			T.E =	4,343.897940	
82	82				
913.1.9		1.200000 x	68.900000 =	82.680000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	

			T.E =	233.606392	
83	83				
914.1.8		1.100000 x	140.000000 =	154.000000	
002		2.000000 x	17.312112 =	34.624224	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	229.463196	
84	84				
915.1.6		1.050000 x	338.000000 =	354.900000	
002		8.000000 x	17.312112 =	138.496896	
003		8.000000 x	20.419486 =	163.355888	

			T.E =	656.752784	

85	85				
915.3.10		1.050000 x	13,101.000000 =	13,756.050000	
002		20.000000 x	17.312112 =	346.242240	
003		20.000000 x	20.419486 =	408.389720	

			T.E =	14,510.681960	
86	86				
865.13.10		1.020000 x	19,950.000000 =	20,349.000000	
003		40.000000 x	20.419486 =	816.779440	
002		40.000000 x	17.312112 =	692.484480	

			T.E =	21,858.263920	
87	87				
916.1.3		1.030000 x	.000000 =	.000000	
916.3.3		1.010000 x	.000000 =	.000000	
916.2.3		1.020000 x	.000000 =	.000000	
003		120.000000 x	20.419486 =	2,450.338320	
002		120.000000 x	17.312112 =	2,077.453440	

			T.E =		
88	88				
917.1		.030000 x	7,780.000000 =	233.400000	
917.1		1.000000 x	7,780.000000 =	7,780.000000	
918.1.1		.030000 x	2,010.000000 =	60.300000	
920.1.1		1.000000 x	7,479.000000 =	7,479.000000	
923.1.1		1.000000 x	61.620000 =	61.620000	
003		40.000000 x	20.419486 =	816.779440	
002		40.000000 x	17.312112 =	692.484480	
923.2.1		1.000000 x	161.400000 =	161.400000	
923.2.1		.030000 x	161.400000 =	4.842000	
923.1.1		.030000 x	61.620000 =	1.848600	
920.1.1		.030000 x	7,479.000000 =	224.370000	
918.1.1		1.000000 x	2,010.000000 =	2,010.000000	

			T.E =	19,526.044520	
89	89				
852.1.6		.020000 x	948.000000 =	18.960000	
855.1.13		1.000000 x	2,732.000000 =	2,732.000000	
855.1.13		.020000 x	2,732.000000 =	54.640000	
925.1.1		1.000000 x	4,600.000000 =	4,600.000000	
003		60.000000 x	20.419486 =	1,225.169160	
002		60.000000 x	17.312112 =	1,038.726720	
925.1.1		.020000 x	4,600.000000 =	92.000000	
852.1.6		1.000000 x	948.000000 =	948.000000	

			T.E =	10,709.495880	

9 9

575.3	1.200000 x	.000000 =	.000000
003	.300000 x	20.419486 =	6.125846
002	.300000 x	17.312112 =	5.193634

 T.E =