

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

1ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	Κατχ Τιμή X 1.8117/ 6.46	15.951934
002	Κατχ Τιμή X 1.8117/ 6.46	17.729980
003	Κατχ Τιμή X 1.8117/ 6.46	23.479183
004	Κατχ Τιμή X 1.8117/ 6.67	22.739959
005	Κατχ Τιμή X 1.8117/ 6.67	18.893831
006	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	158.009496
007	(Κατχ Τιμή + Εξαρτ.Τιμή X .8117)	158.009496
008	Κατχ Τιμή X 1.8117/ 6.67	18.893831
009		.074800
011		52.110000
012		4.280000
013		25.830000
014		253.330000
015		199.000000
016		30.740000
017		365.970000
018.1		2.820000
018.2		4.280000
019.1		2.820000
019.2		4.280000
021		2.670000
022		.070000
024		50.000000
026		.097700
027		.117200
029		.149900
032		37.750000
035		.125600
036		.128500
040		.203400
051		15.400000
052		15.400000
053		.076300
054		.089900
055		.097400
056		10.580000
057		10.580000
058		9.090000
061		13.560000
062		13.560000
065		13.610000
066		39.820000
067		49.210000
081		11.010000
101		
102		
111		.078400
112		.087900
113		.570000
114		
116		.090300
117		
118		
124		5.900000
127		83.240000
128		90.430000
131		.650000
132		.930000
142		.325000

146	.340000
155	2.481600
161	7.120000
163	7.310000
164	
165	
166	
173	.281700
181	
201	290.000000
203.2	335.000000
203.4	210.000000
205	420.000000
208	1,239.000000
210	
211	
212	1,400.000000
214	
219	3.500000
223.1	1,700.000000
223.2	1,450.000000
223.3	1,135.000000
223.4	1,440.000000
225	4.000000
226	11.500000
227	11.500000
228	35.000000
229	
230	
231	20.000000
232	45.000000
233	21.300000
234	2.700000
236	2.600000
237	1.100000
238	2.600000
240	1.600000
241	
242	1.300000
243.1	2.660000
243.2	3.650000
243.3	4.450000
243.5	6.250000
244	
245	18.600000
246	9.000000
249	19.000000
251	.710000
252	1.900000
253	2.350000
254	2.780000
258	7.377000
259	24.070000
260	.536700
261	.555400
262	.536700
264	1.135500
265	.741500
266	.623000

267	.821500
268	.956500
271	.827500
272	.742000
273	.936500
274	1.146500
276	.580400
277	.846500
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	.821500
283	1.000100
284	
285	.062500
286	1.674600
288	1.817600
289	.707000
290	3.300000
291	5.000000
293	
294	3.099000
295	5.649200
296	11.781900
297.2	
298.1	3.570000
298.2	3.110000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.059000
346.2	.106800
348	.106800
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600

372	2.246200
373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	13.560000
403	15.880000
406	19.630000
409	23.370000
410	31.790000
411	29.680000
412	32.030000
414	23.370000
415	23.370000
418	32.720000
419	32.720000
421	108.710000
422	149.410000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.084500
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000

481	5.485000
482	.786500
483	.165000
484	3.800000
485	.802900
487	13.480000
488	5.000000
490	.730000
491	.480000
492	.480000
493	.660000
494	5.480000
495	
496	1.006100
498	1.124000
499	1.540900
500	2.266200
501	3.070000
502	4.230000
503	1.006100
504	1.332400
505	19.170000
506	1.100000
507	1.700000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	48.900000
515	41.230000
519	52.970000
520	47.060000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.060000
565.5	4.530000
565.6	6.290000
566.3	4.090000
566.5	6.240000
566.6	8.330000

1101	1101				
001		.500000 x	15.951934 =		7.975967

			B.T =		7.975967
1102	1102				
001		1.000000 x	15.951934 =		15.951934

			B.T =		15.951934
1103	1103				
001		.300000 x	15.951934 =		4.785580

			B.T =		4.785580
1104	1104				
015		1.000000 x	199.000000 =		199.000000
291		2.200000 x	5.000000 =		11.000000
004		7.000000 x	22.739959 =		159.179713
002		7.000000 x	17.729980 =		124.109860
484		5.250000 x	3.800000 =		19.950000
485		83.000000 x	.802900 =		66.640700

			AΘΡΟΙΣΜΑ =		579.880273
	B.T =	.004000 x	579.880273 =		2.319521

1111	1111				
006		.060000 x	158.009496 =		9.480570

			B.T =		9.480570
1112	1112				
006		.090000 x	158.009496 =		14.220855

			B.T =		14.220855
1116	1116				
007		.025000 x	158.009496 =		3.950237

			B.T =		3.950237
1117	1117				
007		.110000 x	158.009496 =		17.381045

			B.T =		17.381045
1121	1121				
009		4.000000 x	.074800 =		.299200

			B.T =		.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.951934 =	6.380774

			B.T =	6.380774
1127	1127			
001		.130000 x	15.951934 =	2.073751

			B.T =	2.073751
1128	1128			
006		.024000 x	158.009496 =	3.792228

			B.T =	3.792228
1131	1131			
007		.090000 x	158.009496 =	14.220855

			B.T =	14.220855
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000

			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
1407		.320000 x	37.605000 =	12.033600
051		.960000 x	15.400000 =	14.784000

			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800

			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
1407		.420000 x	37.605000 =	15.794100
051		.840000 x	15.400000 =	12.936000

			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.097700 =	14.655000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000

			B.T =	39.374250
1417	1417			
021		.200000 x	2.670000 =	.534000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000
026		150.000000 x	.097700 =	14.655000

			B.T =	39.954450

1418	1418			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.097700 =	14.655000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000

B.T = 41.286750

1421	1421			
021		.200000 x	2.670000 =	.534000
039		4.000000 x	.000000 =	.000000
1407		.540000 x	37.605000 =	20.306700
051		.540000 x	15.400000 =	8.316000

B.T =

1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.125600 =	9.420000
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

B.T =

1426	1426			
021		.200000 x	2.670000 =	.534000
055		1,500.000000 x	.097400 =	146.100000
1407		.450000 x	37.605000 =	16.922250

B.T = 163.556250

1427	1427			
021		.200000 x	2.670000 =	.534000
055		1,500.000000 x	.097400 =	146.100000
1407		.340000 x	37.605000 =	12.785700
026		150.000000 x	.097700 =	14.655000

B.T = 174.074700

1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	15.400000 =	3.080000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.097400 =	116.880000

B.T = 135.536000

1429	1429			
021		.200000 x	2.670000 =	.534000
035		200.000000 x	.125600 =	25.120000
1407		.400000 x	37.605000 =	15.042000
055		1,200.000000 x	.097400 =	116.880000

			B.T =	157.576000
1431	1431			
021		.300000 x	2.670000 =	.801000
1407		.320000 x	37.605000 =	12.033600
032		.960000 x	37.750000 =	36.240000

			B.T =	49.074600
1432	1432			
021		.300000 x	2.670000 =	.801000
051		.640000 x	15.400000 =	9.856000
032		.320000 x	37.750000 =	12.080000
1407		.320000 x	37.605000 =	12.033600

			B.T =	34.770600
1436	1436			
021		.350000 x	2.670000 =	.934500
035		1,100.000000 x	.125600 =	138.160000

			B.T =	139.094500
1437	1437			
021		.200000 x	2.670000 =	.534000
1407		.620000 x	37.605000 =	23.315100
051		.380000 x	15.400000 =	5.852000
035		75.000000 x	.125600 =	9.420000

			B.T =	39.121100
1441	1441			
021		.800000 x	2.670000 =	2.136000
026		250.000000 x	.097700 =	24.425000

			B.T =	26.561000
1442	1442			
021		.250000 x	2.670000 =	.667500
051		.740000 x	15.400000 =	11.396000
026		900.000000 x	.097700 =	87.930000

			B.T =	99.993500

1443	1443			
021		.250000 x	2.670000 =	.667500
051		.860000 x	15.400000 =	13.244000
026		700.000000 x	.097700 =	68.390000

			B.T =	82.301500
1444	1444			
021		.250000 x	2.670000 =	.667500
051		1.000000 x	15.400000 =	15.400000
026		600.000000 x	.097700 =	58.620000

			B.T =	74.687500
1445	1445			
021		.250000 x	2.670000 =	.667500
051		1.060000 x	15.400000 =	16.324000
026		450.000000 x	.097700 =	43.965000

			B.T =	60.956500
1446	1446			
021		.250000 x	2.670000 =	.667500
026		350.000000 x	.097700 =	34.195000
051		1.120000 x	15.400000 =	17.248000

			B.T =	52.110500
1447	1447			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
051		1.000000 x	15.400000 =	15.400000
026		400.000000 x	.097700 =	39.080000

			B.T =	58.155900
1448	1448			
021		.250000 x	2.670000 =	.667500
051		1.000000 x	15.400000 =	15.400000
1407		.080000 x	37.605000 =	3.008400
039		5.000000 x	.000000 =	.000000
026		400.000000 x	.097700 =	39.080000

			B.T =	
1449	1449			
021		.250000 x	2.670000 =	.667500
1407		.040000 x	37.605000 =	1.504200
051		1.060000 x	15.400000 =	16.324000
026		350.000000 x	.097700 =	34.195000

			B.T =	52.690700

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.097700 =	58.620000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.076300 =	114.450000

			B.T =	175.617750
1452	1452			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.149900 =	89.940000
053		1,500.000000 x	.076300 =	114.450000

			B.T =	206.937750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
026		450.000000 x	.097700 =	43.965000
053		1,650.000000 x	.076300 =	125.895000

			B.T =	172.407750
1454	1454			
021		.250000 x	2.670000 =	.667500
053		1,650.000000 x	.076300 =	125.895000
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.149900 =	67.455000

			B.T =	195.897750
1455	1455			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.076300 =	125.895000
028		450.000000 x	.000000 =	.000000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.089900 =	134.850000
026		600.000000 x	.097700 =	58.620000

			B.T =	196.017750

1457	1457			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.089900 =	134.850000
029		600.000000 x	.149900 =	89.940000

			B.T =	227.337750
1458	1458			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
054		1,650.000000 x	.089900 =	148.335000
1407		.050000 x	37.605000 =	1.880250

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.089900 =	148.335000
029		450.000000 x	.149900 =	67.455000

			B.T =	218.337750
1461	1461			
021		.250000 x	2.670000 =	.667500
1407		.080000 x	37.605000 =	3.008400
053		1,500.000000 x	.076300 =	114.450000
026		500.000000 x	.097700 =	48.850000

			B.T =	166.975900
1462	1462			
021		.300000 x	2.670000 =	.801000
026		400.000000 x	.097700 =	39.080000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000

			B.T =	84.531250
1463	1463			
021		.300000 x	2.670000 =	.801000
026		250.000000 x	.097700 =	24.425000
515		1.050000 x	41.230000 =	43.291500
1407		.050000 x	37.605000 =	1.880250
051		.100000 x	15.400000 =	1.540000

			B.T =	71.937750

1464	1464				
021		.200000 x	2.670000 =	.534000	
051		.420000 x	15.400000 =	6.468000	
1407		.120000 x	37.605000 =	4.512600	
519		.600000 x	52.970000 =	31.782000	
026		150.000000 x	.097700 =	14.655000	

			B.T =	57.951600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	52.970000 =	47.673000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.097700 =	43.965000	

			B.T =	95.610150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	52.970000 =	44.494800	
026		450.000000 x	.097700 =	43.965000	
051		.210000 x	15.400000 =	3.234000	

			B.T =	93.355950	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.097700 =	43.965000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	52.970000 =	37.079000	

			B.T =	88.096150	
1471	1471				
251		1.000000 x	.710000 =	.710000	
351		4.000000 x	.668400 =	2.673600	
358		1.000000 x	3.035000 =	3.035000	
364		2.000000 x	1.030000 =	2.060000	
372		.400000 x	2.246200 =	.898480	
370		6.000000 x	.267400 =	1.604400	

			AΘΡΟΙΣΜΑ =	10.981480	
	B.T =	.476190 x	10.981480 =	5.229271	

1472	1472			
251		.600000 x	.710000 =	.426000
351		2.000000 x	.668400 =	1.336800
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	9.481760
	B.T =	.666667 x	9.481760 =	6.321176
1473	1473			
251		.500000 x	.710000 =	.355000
354		4.000000 x	.895800 =	3.583200
364		2.000000 x	1.030000 =	2.060000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	26.030040
	B.T =	.416667 x	26.030040 =	10.845859
1474	1474			
251		.500000 x	.710000 =	.355000
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			AΘΡΟΙΣΜΑ =	31.597000
	B.T =	.416667 x	31.597000 =	13.165427
1475	1475			
251		.300000 x	.710000 =	.213000
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			AΘΡΟΙΣΜΑ =	89.933600
	B.T =	.416667 x	89.933600 =	37.472363

1476	1476			
251		.500000 x	.710000 =	.355000
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000

			ΑΘΡΟΙΣΜΑ =	5.546760
	B.T =	.500000 x	5.546760 =	2.773380

1478	1478			
251		3.000000 x	.710000 =	2.130000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400

			ΑΘΡΟΙΣΜΑ =	6.060500
	B.T =	.500000 x	6.060500 =	3.030250

1479	1479			
251		6.000000 x	.710000 =	4.260000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000

			ΑΘΡΟΙΣΜΑ =	75.438800
	B.T =	.454545 x	75.438800 =	34.290329

1480	1480			
251		8.000000 x	.710000 =	5.680000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400

			ΑΘΡΟΙΣΜΑ =	145.898400
	B.T =	.227273 x	145.898400 =	33.158767

1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.084500 =	.019435
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124

			B.T =	.831094
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.084500 =	.054080
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210

			B.T =	.604686

1488	1488				
444		.170000 x	2.143200 =		.364344
453		.500000 x	.084500 =		.042250
451		.170000 x	1.178800 =		.200396
446		.030000 x	2.540000 =		.076200
445		.050000 x	1.553500 =		.077675

			B.T =		.760865
1489	1489				
444		.100000 x	2.143200 =		.214320
453		.430000 x	.084500 =		.036335
451		.350000 x	1.178800 =		.412580
446		.020000 x	2.540000 =		.050800
445		.100000 x	1.553500 =		.155350

			B.T =		.869385
1490	1490				
444		.300000 x	2.143200 =		.642960
445		.100000 x	1.553500 =		.155350
446		.030000 x	2.540000 =		.076200
451		.570000 x	1.178800 =		.671916

			B.T =		1.546426
1491	1491				
444		.270000 x	2.143200 =		.578664
445		.060000 x	1.553500 =		.093210
451		.650000 x	1.178800 =		.766220
446		.020000 x	2.540000 =		.050800

			B.T =		1.488894
1492	1492				
444		.200000 x	2.143200 =		.428640
446		.030000 x	2.540000 =		.076200
445		.040000 x	1.553500 =		.062140
455		.730000 x	3.000000 =		2.190000

			B.T =		2.756980
1501	1501				
011		1.000000 x	52.110000 =		52.110000
012		2.000000 x	4.280000 =		8.560000
005		3.500000 x	18.893831 =		66.128409
005		14.000000 x	18.893831 =		264.513634
485		15.000000 x	.802900 =		12.043500
484		1.750000 x	3.800000 =		6.650000

			B.T =		410.005543

1502	1502				
013		1.000000 x	25.830000 =	25.830000	
005		3.500000 x	18.893831 =	66.128409	
001		26.000000 x	15.951934 =	414.750284	
482		15.000000 x	.786500 =	11.797500	
484		.900000 x	3.800000 =	3.420000	

			B.T =	521.926193	
1503	1503				
014		1.000000 x	253.330000 =	253.330000	
002		2.600000 x	17.729980 =	46.097948	
004		7.000000 x	22.739959 =	159.179713	
484		2.600000 x	3.800000 =	9.880000	
485		44.000000 x	.802900 =	35.327600	

			B.T =	503.815261	
1504	1504				
015		1.000000 x	199.000000 =	199.000000	
004		7.000000 x	22.739959 =	159.179713	
002		7.000000 x	17.729980 =	124.109860	
485		83.000000 x	.802900 =	66.640700	
484		5.250000 x	3.800000 =	19.950000	
291		2.200000 x	5.000000 =	11.000000	

			B.T =	579.880273	
1505	1505				
016		1.000000 x	30.740000 =	30.740000	
004		7.000000 x	22.739959 =	159.179713	
002		1.750000 x	17.729980 =	31.027465	
485		17.500000 x	.802900 =	14.050750	
484		1.750000 x	3.800000 =	6.650000	

			B.T =	241.647928	
1506	1506				
017		1.000000 x	365.970000 =	365.970000	
004		7.000000 x	22.739959 =	159.179713	
002		3.500000 x	17.729980 =	62.054930	
484		6.000000 x	3.800000 =	22.800000	
485		70.000000 x	.802900 =	56.203000	

			B.T =	666.207643	
2101	2101				
002		.300000 x	17.729980 =	5.318994	

			T.E =	5.318994	

2102	2102			
002		.400000 x	17.729980 =	7.091992

			T.E =	7.091992
2103	2103			
002		.400000 x	17.729980 =	7.091992

			T.E =	7.091992
2104A	2104A			
002		.900000 x	17.729980 =	15.956982

			T.E =	15.956982
2104B	2104B			
002		1.400000 x	17.729980 =	24.821972

			T.E =	24.821972
2104E	2104E			
002		2.900000 x	17.729980 =	51.416942

			T.E =	51.416942
2104H	2104H			
002		4.400000 x	17.729980 =	78.011912

			T.E =	78.011912
2104Z	2104Z			
002		3.900000 x	17.729980 =	69.146922

			T.E =	69.146922
2104Γ	2104Γ			
002		1.900000 x	17.729980 =	33.686962

			T.E =	33.686962
2104Δ	2104Δ			
002		2.400000 x	17.729980 =	42.551952

			T.E =	42.551952
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.729980 =	60.281932

			T.E =	60.281932

2105A	2105A			
002		.900000 x	17.729980 =	15.956982

			T.E =	15.956982
2105B	2105B			
002		1.400000 x	17.729980 =	24.821972

			T.E =	24.821972
2105E	2105E			
002		2.900000 x	17.729980 =	51.416942

			T.E =	51.416942
2105H	2105H			
002		4.400000 x	17.729980 =	78.011912

			T.E =	78.011912
2105Z	2105Z			
002		3.900000 x	17.729980 =	69.146922

			T.E =	69.146922
2105Γ	2105Γ			
002		1.900000 x	17.729980 =	33.686962

			T.E =	33.686962
2105Δ	2105Δ			
002		2.400000 x	17.729980 =	42.551952

			T.E =	42.551952
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.729980 =	60.281932

			T.E =	60.281932
2106A	2106A			
002		5.900000 x	17.729980 =	104.606882

			T.E =	104.606882
2106B	2106B			
002		7.400000 x	17.729980 =	131.201852

			T.E =	131.201852

2106E	2106E			
002		11.900000 x	17.729980 =	210.986762

			T.E =	210.986762
2106H	2106H			
002		16.400000 x	17.729980 =	290.771672

			T.E =	290.771672
2106I	2106I			
002		19.400000 x	17.729980 =	343.961612

			T.E =	343.961612
2106Z	2106Z			
002		14.900000 x	17.729980 =	264.176702

			T.E =	264.176702
2106Γ	2106Γ			
002		8.900000 x	17.729980 =	157.796822

			T.E =	157.796822
2106Δ	2106Δ			
002		10.400000 x	17.729980 =	184.391792

			T.E =	184.391792
2106Θ	2106Θ			
002		17.900000 x	17.729980 =	317.366642

			T.E =	317.366642
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.729980 =	237.581732

			T.E =	237.581732
2107A	2107A			
002		5.900000 x	17.729980 =	104.606882

			T.E =	104.606882
2107B	2107B			
002		7.400000 x	17.729980 =	131.201852

			T.E =	131.201852

2107E	2107E			
002		11.900000 x	17.729980 =	210.986762

			T.E =	210.986762
2107H	2107H			
002		16.400000 x	17.729980 =	290.771672

			T.E =	290.771672
2107I	2107I			
002		19.400000 x	17.729980 =	343.961612

			T.E =	343.961612
2107Z	2107Z			
002		14.900000 x	17.729980 =	264.176702

			T.E =	264.176702
2107Γ	2107Γ			
002		8.900000 x	17.729980 =	157.796822

			T.E =	157.796822
2107Δ	2107Δ			
002		10.400000 x	17.729980 =	184.391792

			T.E =	184.391792
2107Θ	2107Θ			
002		17.900000 x	17.729980 =	317.366642

			T.E =	317.366642
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.729980 =	237.581732

			T.E =	237.581732
2108A	2108A			
002		.700000 x	17.729980 =	12.410986

			T.E =	12.410986
2108B	2108B			
002		1.600000 x	17.729980 =	28.367968

			T.E =	28.367968

2108E	2108E			
002		4.600000 x	17.729980 =	81.557908

			T.E =	81.557908
2108H	2108H			
002		7.600000 x	17.729980 =	134.747848

			T.E =	134.747848
2108Z	2108Z			
002		6.600000 x	17.729980 =	117.017868

			T.E =	117.017868
2108Γ	2108Γ			
002		2.600000 x	17.729980 =	46.097948

			T.E =	46.097948
2108Δ	2108Δ			
002		3.600000 x	17.729980 =	63.827928

			T.E =	63.827928
2108Θ	2108Θ			
002		8.600000 x	17.729980 =	152.477828

			T.E =	152.477828
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.729980 =	99.287888

			T.E =	99.287888
2109	2109			
002		.030000 x	17.729980 =	.531899
1503		.001000 x	503.815261 =	.503815
1506		.004000 x	666.207643 =	2.664831

			T.E =	3.700545
2110	2110			
002		.040000 x	17.729980 =	.709199
1506		.004000 x	666.207643 =	2.664831
1503		.001000 x	503.815261 =	.503815
1501		.005000 x	410.005543 =	2.050028

			T.E =	5.927873

2111	2111				
002		.100000 x	17.729980 =	1.772998	
1504		.005000 x	579.880273 =	2.899401	

			T.E =	4.672399	
2112	2112				
002		.120000 x	17.729980 =	2.127598	
1504		.005500 x	579.880273 =	3.189342	
1501		.004000 x	410.005543 =	1.640022	

			T.E =	6.956961	
2113	2113				
002		1.400000 x	17.729980 =	24.821972	
002		.300000 x	17.729980 =	5.318994	

			T.E =	30.140966	
2114	2114				
002		1.500000 x	17.729980 =	26.594970	
1501		.005000 x	410.005543 =	2.050028	
002		.400000 x	17.729980 =	7.091992	

			T.E =	35.736990	
2115	2115				
481		.300000 x	5.485000 =	1.645500	
1501		.011000 x	410.005543 =	4.510061	
002		.600000 x	17.729980 =	10.637988	
003		1.200000 x	23.479183 =	28.175020	

			T.E =	44.968569	
2116	2116				
2115		1.300000 x	44.968569 =	58.459140	

			T.E =	58.459140	
2117	2117				
002		.600000 x	17.729980 =	10.637988	
1501		.125000 x	410.005543 =	51.250693	

			T.E =	61.888681	
2118	2118				
2117		1.300000 x	61.888681 =	80.455285	

			T.E =	80.455285	

2121	2121				
001		.400000 x	15.951934 =	6.380774	
002		1.800000 x	17.729980 =	31.913964	

			T.E =	38.294738	
2122	2122				
001		.500000 x	15.951934 =	7.975967	
1501		.005000 x	410.005543 =	2.050028	
002		2.000000 x	17.729980 =	35.459960	

			T.E =	45.485955	
2123	2123				
002		.200000 x	17.729980 =	3.545996	
1504		.008300 x	579.880273 =	4.813006	

			T.E =	8.359002	
2124	2124				
002		.200000 x	17.729980 =	3.545996	
1501		.005000 x	410.005543 =	2.050028	
1504		.010000 x	579.880273 =	5.798803	

			T.E =	11.394826	
2125	2125				
481		.400000 x	5.485000 =	2.194000	
1501		.020000 x	410.005543 =	8.200111	
002		1.000000 x	17.729980 =	17.729980	
003		1.500000 x	23.479183 =	35.218775	

			T.E =	63.342865	
2126	2126				
2125		1.300000 x	63.342865 =	82.345725	

			T.E =	82.345725	
2127	2127				
002		1.000000 x	17.729980 =	17.729980	
1501		.166600 x	410.005543 =	68.306923	

			T.E =	86.036903	
2128	2128				
2127		1.300000 x	86.036903 =	111.847974	

			T.E =	111.847974	

2131	2131			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
2132	2132			
1504		.001600 x	579.880273 =	.927808

			T.E =	.927808
2133	2133			
002		.100000 x	17.729980 =	1.772998
002		.600000 x	17.729980 =	10.637988

			T.E =	12.410986
2134	2134			
1504		.002500 x	579.880273 =	1.449701

			T.E =	1.449701
2135.1	2135.1			
2121		1.300000 x	38.294738 =	49.783159

			T.E =	49.783159
2135.2	2135.2			
2122		1.300000 x	45.485955 =	59.131742

			T.E =	59.131742
2135.3	2135.3			
2127		1.300000 x	86.036903 =	111.847974

			T.E =	111.847974
2135.4	2135.4			
2128		1.300000 x	111.847974 =	145.402366

			T.E =	145.402366
2141	2141			
001		2.000000 x	15.951934 =	31.903868
003		2.500000 x	23.479183 =	58.697958

			T.E =	90.601826

2142	2142				
001		2.000000 x	15.951934 =	31.903868	
1501		.005000 x	410.005543 =	2.050028	
003		3.000000 x	23.479183 =	70.437549	

			T.E =	104.391445	
2143	2143				
481		.500000 x	5.485000 =	2.742500	
001		2.000000 x	15.951934 =	31.903868	
003		3.000000 x	23.479183 =	70.437549	
1501		.025000 x	410.005543 =	10.250139	

			T.E =	115.334056	
2144	2144				
2143		1.300000 x	115.334056 =	149.934273	

			T.E =	149.934273	
2145	2145				
001		2.000000 x	15.951934 =	31.903868	
003		1.000000 x	23.479183 =	23.479183	
1501		.200000 x	410.005543 =	82.001109	

			T.E =	137.384160	
2146	2146				
2145		1.300000 x	137.384160 =	178.599408	

			T.E =	178.599408	
2151	2151				
001		1.200000 x	15.951934 =	19.142321	
003		.800000 x	23.479183 =	18.783346	

			T.E =	37.925667	
2152	2152				
001		1.500000 x	15.951934 =	23.927901	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	47.407084	
2161	2161				
1505		.003300 x	241.647928 =	.797438	

			T.E =	.797438	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.951934 =	12.761547

			T.E =	13.028547
2163	2163			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	579.880273 =	2.319521

			T.E =	2.469121
2172	2172			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547
2173	2173			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2174	2174			
007		.050000 x	158.009496 =	7.900475

			T.E =	7.900475
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547

2178	2178			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
2179	2179			
007		.018000 x	158.009496 =	2.844171

			T.E =	2.844171
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.820000 =	.402696
005		.400000 x	18.893831 =	7.557532
484		.100000 x	3.800000 =	.380000
482		.700000 x	.786500 =	.550550
018.1		.042800 x	2.820000 =	.120696

			T.E =	9.011474
2186	2186			
018.2		.142800 x	4.280000 =	.611184
005		.400000 x	18.893831 =	7.557532
018.2		.042800 x	4.280000 =	.183184
482		1.400000 x	.786500 =	1.101100
484		.200000 x	3.800000 =	.760000

			T.E =	10.213000
2187	2187			
019.1		.142800 x	2.820000 =	.402696
485		1.100000 x	.802900 =	.883190
019.1		.428000 x	2.820000 =	1.206960
005		.400000 x	18.893831 =	7.557532
484		.100000 x	3.800000 =	.380000

			T.E =	10.430378
2188	2188			
019.2		.142800 x	4.280000 =	.611184
005		.400000 x	18.893831 =	7.557532
485		1.800000 x	.802900 =	1.445220
484		.200000 x	3.800000 =	.760000
019.2		.042800 x	4.280000 =	.183184

			T.E =	10.557120

ΑΤΟΕ	1ο Τρίμηνο του 2009	Σελ. Ημ/νία	31 19/05/2010
2201	2201		
001	1.000000 x	15.951934 =	15.951934
002	2.000000 x	17.729980 =	35.459960

		T.E =	51.411894
2202	2202		
001	1.000000 x	15.951934 =	15.951934
002	5.000000 x	17.729980 =	88.649900

		T.E =	104.601834
2203	2203		
001	1.000000 x	15.951934 =	15.951934
002	2.500000 x	17.729980 =	44.324950

		T.E =	60.276884
2204	2204		
001	1.000000 x	15.951934 =	15.951934
002	5.000000 x	17.729980 =	88.649900

		T.E =	104.601834
2206	2206		
001	1.000000 x	15.951934 =	15.951934
003	3.000000 x	23.479183 =	70.437549

		T.E =	86.389483
2207	2207		
001	1.000000 x	15.951934 =	15.951934
003	6.000000 x	23.479183 =	140.875098

		T.E =	156.827032
2211	2211		
001	2.000000 x	15.951934 =	31.903868

		T.E =	31.903868
2212	2212		
001	1.000000 x	15.951934 =	15.951934

		T.E =	15.951934
2213	2213		
001	2.000000 x	15.951934 =	31.903868

		T.E =	31.903868

2214	2214			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2221	2221			
001		1.200000 x	15.951934 =	19.142321
002		1.600000 x	17.729980 =	28.367968

			T.E =	47.510289
2222	2222			
001		1.200000 x	15.951934 =	19.142321
002		2.500000 x	17.729980 =	44.324950

			T.E =	63.467271
2223	2223			
001		3.000000 x	15.951934 =	47.855802

			T.E =	47.855802
2224	2224			
001		5.000000 x	15.951934 =	79.759670

			T.E =	79.759670
2226	2226			
001		1.500000 x	15.951934 =	23.927901
002		5.000000 x	17.729980 =	88.649900

			T.E =	112.577801
2227	2227			
001		1.500000 x	15.951934 =	23.927901
002		12.000000 x	17.729980 =	212.759760

			T.E =	236.687661
2231	2231			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
2232	2232			
003		.020000 x	23.479183 =	.469584

			T.E =	.469584

2236	2236				
001		.100000 x	15.951934 =	1.595193	
002		.300000 x	17.729980 =	5.318994	

			T.E =	6.914187	
2237	2237				
001		.200000 x	15.951934 =	3.190387	
003		.700000 x	23.479183 =	16.435428	

			T.E =	19.625815	
2238	2238				
001		.100000 x	15.951934 =	1.595193	
002		.400000 x	17.729980 =	7.091992	

			T.E =	8.687185	
2239	2239				
001		.200000 x	15.951934 =	3.190387	
003		.800000 x	23.479183 =	18.783346	

			T.E =	21.973733	
2241	2241				
001		.300000 x	15.951934 =	4.785580	
003		.100000 x	23.479183 =	2.347918	

			T.E =	7.133499	
2242	2242				
001		.400000 x	15.951934 =	6.380774	
003		.150000 x	23.479183 =	3.521877	

			T.E =	9.902651	
2243	2243				
001		.500000 x	15.951934 =	7.975967	
003		.250000 x	23.479183 =	5.869796	

			T.E =	13.845763	
2246	2246				
001		.250000 x	15.951934 =	3.987984	
003		.050000 x	23.479183 =	1.173959	

			T.E =	5.161943	

2247	2247				
001		.350000 x	15.951934 =	5.583177	
003		.100000 x	23.479183 =	2.347918	

				T.E =	7.931095
2248	2248				
001		.450000 x	15.951934 =	7.178370	
003		.200000 x	23.479183 =	4.695837	

				T.E =	11.874207
2251	2251				
001		.100000 x	15.951934 =	1.595193	
002		.300000 x	17.729980 =	5.318994	

				T.E =	6.914187
2252	2252				
001		.100000 x	15.951934 =	1.595193	
002		.600000 x	17.729980 =	10.637988	

				T.E =	12.233181
2261A	2261A				
003		.400000 x	23.479183 =	9.391673	

				T.E =	9.391673
2261B	2261B				
003		.700000 x	23.479183 =	16.435428	

				T.E =	16.435428
2261Γ	2261Γ				
003		.900000 x	23.479183 =	21.131265	

				T.E =	21.131265
2261Δ	2261Δ				
003		1.200000 x	23.479183 =	28.175020	

				T.E =	28.175020
2262A	2262A				
003		.550000 x	23.479183 =	12.913551	

				T.E =	12.913551

2262B	2262B			
003		.900000 x	23.479183 =	21.131265

			T.E =	21.131265
2262Γ	2262Γ			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
2262Δ	2262Δ			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2263A	2263A			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
2263B	2263B			
003		1.200000 x	23.479183 =	28.175020

			T.E =	28.175020
2263Γ	2263Γ			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2263Δ	2263Δ			
003		2.100000 x	23.479183 =	49.306284

			T.E =	49.306284
2264.1A	2264.1A			
003		1.600000 x	23.479183 =	37.566693

			T.E =	37.566693
2264.1B	2264.1B			
003		1.850000 x	23.479183 =	43.436489

			T.E =	43.436489
2264.1Γ	2264.1Γ			
003		2.100000 x	23.479183 =	49.306284

			T.E =	49.306284

2264.1Δ	2264.1Δ			
003		2.300000 x	23.479183 =	54.002121

			T.E =	54.002121
2264.2Α	2264.2Α			
003		2.000000 x	23.479183 =	46.958366

			T.E =	46.958366
2264.2Β	2264.2Β			
003		2.400000 x	23.479183 =	56.350039

			T.E =	56.350039
2264.2Γ	2264.2Γ			
003		2.800000 x	23.479183 =	65.741712

			T.E =	65.741712
2264.2Δ	2264.2Δ			
003		3.200000 x	23.479183 =	75.133386

			T.E =	75.133386
2264.3Α	2264.3Α			
003		2.400000 x	23.479183 =	56.350039

			T.E =	56.350039
2264.3Β	2264.3Β			
003		2.850000 x	23.479183 =	66.915672

			T.E =	66.915672
2264.3Γ	2264.3Γ			
003		3.300000 x	23.479183 =	77.481304

			T.E =	77.481304
2264.3Δ	2264.3Δ			
003		3.750000 x	23.479183 =	88.046936

			T.E =	88.046936
2265Α	2265Α			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592

2265B	2265B			
003		.800000 x	23.479183 =	18.783346

			T.E =	18.783346
2266.1	2266.1			
2261A		1.000000 x	9.391673 =	9.391673
2261A		.350000 x	9.391673 =	3.287086

			T.E =	12.678759
2266.10	2266.10			
2263B		1.000000 x	28.175020 =	28.175020
2263B		.350000 x	28.175020 =	9.861257

			T.E =	38.036277
2266.11	2266.11			
2263Γ		1.000000 x	37.566693 =	37.566693
2263Γ		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.12	2266.12			
2263Δ		1.000000 x	49.306284 =	49.306284
2263Δ		.350000 x	49.306284 =	17.257199

			T.E =	66.563483
2266.13	2266.13			
2264.1A		1.000000 x	37.566693 =	37.566693
2264.1A		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.14	2266.14			
2264.1B		1.000000 x	43.436489 =	43.436489
2264.1B		.350000 x	43.436489 =	15.202771

			T.E =	58.639260
2266.15	2266.15			
2264.1Γ		1.000000 x	49.306284 =	49.306284
2264.1Γ		.350000 x	49.306284 =	17.257199

			T.E =	66.563483

2266.16	2266.16			
2264.1Δ		1.000000 x	54.002121 =	54.002121
2264.1Δ		.350000 x	54.002121 =	18.900742

			T.E =	72.902863
2266.17	2266.17			
2264.2A		1.000000 x	46.958366 =	46.958366
2264.2A		.350000 x	46.958366 =	16.435428

			T.E =	63.393794
2266.18	2266.18			
2264.2B		1.000000 x	56.350039 =	56.350039
2264.2B		.350000 x	56.350039 =	19.722514

			T.E =	76.072553
2266.19	2266.19			
2264.2Γ		1.000000 x	65.741712 =	65.741712
2264.2Γ		.350000 x	65.741712 =	23.009599

			T.E =	88.751311
2266.2	2266.2			
2261B		1.000000 x	16.435428 =	16.435428
2261B		.350000 x	16.435428 =	5.752400

			T.E =	22.187828
2266.20	2266.20			
2264.2Δ		1.000000 x	75.133386 =	75.133386
2264.2Δ		.350000 x	75.133386 =	26.296685

			T.E =	101.430071
2266.21	2266.21			
2264.3A		1.000000 x	56.350039 =	56.350039
2264.3A		.350000 x	56.350039 =	19.722514

			T.E =	76.072553
2266.22	2266.22			
2264.3B		1.000000 x	66.915672 =	66.915672
2264.3B		.350000 x	66.915672 =	23.420485

			T.E =	90.336157

2266.23	2266.23				
2264.3Γ		1.000000 x	77.481304 =	77.481304	
2264.3Γ		.350000 x	77.481304 =	27.118456	
			T.E =	104.599760	
2266.24	2266.24				
2264.3Δ		1.000000 x	88.046936 =	88.046936	
2264.3Δ		.350000 x	88.046936 =	30.816428	
			T.E =	118.863364	
2266.25	2266.25				
2265A		1.000000 x	11.739592 =	11.739592	
2265A		.350000 x	11.739592 =	4.108857	
			T.E =	15.848449	
2266.26	2266.26				
2265B		1.000000 x	18.783346 =	18.783346	
2265B		.350000 x	18.783346 =	6.574171	
			T.E =	25.357517	
2266.3	2266.3				
2261Γ		1.000000 x	21.131265 =	21.131265	
2261Γ		.350000 x	21.131265 =	7.395943	
			T.E =	28.527208	
2266.4	2266.4				
2261Δ		1.000000 x	28.175020 =	28.175020	
2261Δ		.350000 x	28.175020 =	9.861257	
			T.E =	38.036277	
2266.5	2266.5				
2262A		1.000000 x	12.913551 =	12.913551	
2262A		.350000 x	12.913551 =	4.519743	
			T.E =	17.433294	
2266.6	2266.6				
2262B		1.000000 x	21.131265 =	21.131265	
2262B		.350000 x	21.131265 =	7.395943	
			T.E =	28.527208	

2266.7	2266.7			
2262Γ		1.000000 x	28.175020 =	28.175020
2262Γ		.350000 x	28.175020 =	9.861257

			T.E =	38.036277
2266.8	2266.8			
2262Δ		1.000000 x	37.566693 =	37.566693
2262Δ		.350000 x	37.566693 =	13.148343

			T.E =	50.715036
2266.9	2266.9			
2263A		1.000000 x	16.435428 =	16.435428
2263A		.350000 x	16.435428 =	5.752400

			T.E =	22.187828
2267	2267			
003		3.500000 x	23.479183 =	82.177141

			T.E =	82.177141
2268A	2268A			
003		5.000000 x	23.479183 =	117.395915

			T.E =	117.395915
2268B	2268B			
003		5.900000 x	23.479183 =	138.527180

			T.E =	138.527180
2268Γ	2268Γ			
003		6.400000 x	23.479183 =	150.266771

			T.E =	150.266771
2268Δ	2268Δ			
003		6.900000 x	23.479183 =	162.006363

			T.E =	162.006363
2269A	2269A			
003		2.000000 x	23.479183 =	46.958366

			T.E =	46.958366

2269B	2269B			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549
2269Γ	2269Γ			
003		4.000000 x	23.479183 =	93.916732

			T.E =	93.916732
2270.1	2270.1			
2267		1.000000 x	82.177141 =	82.177141
2267		.600000 x	82.177141 =	49.306285

			T.E =	131.483426
2270.2	2270.2			
2268A		1.000000 x	117.395915 =	117.395915
2268A		.600000 x	117.395915 =	70.437549

			T.E =	187.833464
2270.3	2270.3			
2268B		1.000000 x	138.527180 =	138.527180
2268B		.600000 x	138.527180 =	83.116308

			T.E =	221.643488
2270.4	2270.4			
2268Γ		1.000000 x	150.266771 =	150.266771
2268Γ		.600000 x	150.266771 =	90.160063

			T.E =	240.426834
2270.5	2270.5			
2268Δ		1.000000 x	162.006363 =	162.006363
2268Δ		.600000 x	162.006363 =	97.203818

			T.E =	259.210181
2271A	2271A			
003		2.500000 x	23.479183 =	58.697958

			T.E =	58.697958
2271B	2271B			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549

2271E	2271E			
003		4.500000 x	23.479183 =	105.656324

			T.E =	105.656324
2271H	2271H			
003		6.000000 x	23.479183 =	140.875098

			T.E =	140.875098
2271I	2271I			
003		7.000000 x	23.479183 =	164.354281

			T.E =	164.354281
2271Z	2271Z			
003		5.500000 x	23.479183 =	129.135507

			T.E =	129.135507
2271Γ	2271Γ			
003		3.500000 x	23.479183 =	82.177141

			T.E =	82.177141
2271Δ	2271Δ			
003		4.000000 x	23.479183 =	93.916732

			T.E =	93.916732
2271Θ	2271Θ			
003		6.500000 x	23.479183 =	152.614690

			T.E =	152.614690
2271ΣΤ	2271ΣΤ			
003		5.000000 x	23.479183 =	117.395915

			T.E =	117.395915
2272A	2272A			
003		3.000000 x	23.479183 =	70.437549

			T.E =	70.437549
2272B	2272B			
003		3.700000 x	23.479183 =	86.872977

			T.E =	86.872977

2272E	2272E			
003		5.800000 x	23.479183 =	136.179261

			T.E =	136.179261
2272H	2272H			
003		7.900000 x	23.479183 =	185.485546

			T.E =	185.485546
2272I	2272I			
003		9.300000 x	23.479183 =	218.356402

			T.E =	218.356402
2272Z	2272Z			
003		7.200000 x	23.479183 =	169.050118

			T.E =	169.050118
2272Γ	2272Γ			
003		4.400000 x	23.479183 =	103.308405

			T.E =	103.308405
2272Δ	2272Δ			
003		5.100000 x	23.479183 =	119.743833

			T.E =	119.743833
2272Θ	2272Θ			
003		8.600000 x	23.479183 =	201.920974

			T.E =	201.920974
2272ΣΤ	2272ΣΤ			
003		6.500000 x	23.479183 =	152.614690

			T.E =	152.614690
2273A	2273A			
003		8.500000 x	23.479183 =	199.573056

			T.E =	199.573056
2273B	2273B			
003		10.000000 x	23.479183 =	234.791830

			T.E =	234.791830

2273Γ	2273Γ			
003		11.500000 x	23.479183 =	270.010605

			T.E =	270.010605
2273Δ	2273Δ			
003		13.000000 x	23.479183 =	305.229379

			T.E =	305.229379
2274.1	2274.1			
2271A		1.300000 x	58.697958 =	76.307345

			T.E =	76.307345
2274.10	2274.10			
2271I		1.300000 x	164.354281 =	213.660565

			T.E =	213.660565
2274.11	2274.11			
2272A		1.300000 x	70.437549 =	91.568814

			T.E =	91.568814
2274.12	2274.12			
2272B		1.300000 x	86.872977 =	112.934870

			T.E =	112.934870
2274.13	2274.13			
2272Γ		1.300000 x	103.308405 =	134.300927

			T.E =	134.300927
2274.14	2274.14			
2272Δ		1.300000 x	119.743833 =	155.666983

			T.E =	155.666983
2274.15	2274.15			
2272Ε		1.300000 x	136.179261 =	177.033039

			T.E =	177.033039
2274.16	2274.16			
2272ΣΤ		1.300000 x	152.614690 =	198.399097

			T.E =	198.399097

2274.17	2274.17			
2272Z		1.300000 x	169.050118 =	219.765153

			T.E =	219.765153
2274.18	2274.18			
2272H		1.300000 x	185.485546 =	241.131210

			T.E =	241.131210
2274.19	2274.19			
2272Θ		1.300000 x	201.920974 =	262.497266

			T.E =	262.497266
2274.2	2274.2			
2271B		1.300000 x	70.437549 =	91.568814

			T.E =	91.568814
2274.20	2274.20			
2272I		1.300000 x	218.356402 =	283.863323

			T.E =	283.863323
2274.21	2274.21			
2273A		1.300000 x	199.573056 =	259.444973

			T.E =	259.444973
2274.22	2274.22			
2273B		1.300000 x	234.791830 =	305.229379

			T.E =	305.229379
2274.23	2274.23			
2273Γ		1.300000 x	270.010605 =	351.013787

			T.E =	351.013787
2274.24	2274.24			
2273Δ		1.300000 x	305.229379 =	396.798193

			T.E =	396.798193
2274.3	2274.3			
2271Γ		1.300000 x	82.177141 =	106.830283

			T.E =	106.830283

2274.4	2274.4			
2271Δ		1.300000 x	93.916732 =	122.091752

			T.E =	122.091752
2274.5	2274.5			
2271Ε		1.300000 x	105.656324 =	137.353221

			T.E =	137.353221
2274.6	2274.6			
2271ΣΤ		1.300000 x	117.395915 =	152.614690

			T.E =	152.614690
2274.7	2274.7			
2271Ζ		1.300000 x	129.135507 =	167.876159

			T.E =	167.876159
2274.8	2274.8			
2271Η		1.300000 x	140.875098 =	183.137627

			T.E =	183.137627
2274.9	2274.9			
2271Θ		1.300000 x	152.614690 =	198.399097

			T.E =	198.399097
2275	2275			
003		1.000000 x	23.479183 =	23.479183

			T.E =	23.479183
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	210.000000 =	6.930000
251		6.000000 x	.710000 =	4.260000
003		5.000000 x	23.479183 =	117.395915
001		9.000000 x	15.951934 =	143.567406

			T.E =	280.853321
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.729980 =	5.318994

			T.E =	5.608994

2303	2303				
001		.250000 x	15.951934 =	3.987984	
003		.250000 x	23.479183 =	5.869796	

			T.E =	9.857779	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.729980 =	1.772998	

			T.E =	1.888998	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	210.000000 =	8.400000	
003		7.000000 x	23.479183 =	164.354281	
001		9.000000 x	15.951934 =	143.567406	
251		6.000000 x	.710000 =	4.260000	

			T.E =	332.181687	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	210.000000 =	.420000	
251		.250000 x	.710000 =	.177500	
001		.250000 x	15.951934 =	3.987984	
003		.150000 x	23.479183 =	3.521877	

			T.E =	8.687361	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.710000 =	.142000	
203.4		.001000 x	210.000000 =	.210000	
003		.100000 x	23.479183 =	2.347918	
001		.200000 x	15.951934 =	3.190387	

			T.E =	6.470305	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	23.479183 =	.704375	

			T.E =	1.193875	
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	23.479183 =	.704375	

			T.E =	1.079375	

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
026		175.000000 x	.097700 =	17.097500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	

			T.E =	105.752997	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
026		200.000000 x	.097700 =	19.540000	

			T.E =	107.829897	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.097700 =	24.425000	

			T.E =	112.349297	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.097700 =	29.310000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
056		.800000 x	10.580000 =	8.464000	

			T.E =	116.868697	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	23.479183 =	35.218775	
001		4.000000 x	15.951934 =	63.807736	
026		200.000000 x	.097700 =	19.540000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	

			T.E =	134.589211	

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
026		250.000000 x	.097700 =	24.425000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	23.479183 =	35.218775
001		2.000000 x	15.951934 =	31.903868
052		.410000 x	15.400000 =	6.314000

			T.E =	133.301052
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366
001		3.000000 x	15.951934 =	47.855802
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.097700 =	29.310000

			T.E =	165.511978
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.097700 =	14.655000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.951934 =	79.759670
052		.420000 x	15.400000 =	6.468000

			T.E =	118.091870
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
026		175.000000 x	.097700 =	17.097500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	110.336197
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.097700 =	19.540000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	23.479183 =	16.435428
001		3.500000 x	15.951934 =	55.831769
052		.560000 x	15.400000 =	8.624000

			T.E =	112.489097

3203	3203				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
061		.820000 x	13.560000 =	11.119200	
052		.540000 x	15.400000 =	8.316000	
026		250.000000 x	.097700 =	24.425000	

			T.E =	116.794897	
3204	3204				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.097700 =	29.310000	
052		.530000 x	15.400000 =	8.162000	
003		.700000 x	23.479183 =	16.435428	
001		3.500000 x	15.951934 =	55.831769	
061		.800000 x	13.560000 =	10.848000	

			T.E =	121.254697	
3205	3205				
021		.250000 x	2.670000 =	.667500	
003		5.500000 x	23.479183 =	129.135507	
001		7.000000 x	15.951934 =	111.663538	
026		200.000000 x	.097700 =	19.540000	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	

			T.E =	277.836045	
3206	3206				
021		.250000 x	2.670000 =	.667500	
026		250.000000 x	.097700 =	24.425000	
065		.730000 x	13.610000 =	9.935300	
003		5.500000 x	23.479183 =	129.135507	
001		7.000000 x	15.951934 =	111.663538	
052		.410000 x	15.400000 =	6.314000	

			T.E =	282.140845	
3207	3207				
021		.250000 x	2.670000 =	.667500	
003		3.000000 x	23.479183 =	70.437549	
001		6.000000 x	15.951934 =	95.711604	
065		.750000 x	13.610000 =	10.207500	
052		.430000 x	15.400000 =	6.622000	
026		200.000000 x	.097700 =	19.540000	

			T.E =	203.186153	

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.097700 =	24.425000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	23.479183 =	70.437549
001		6.000000 x	15.951934 =	95.711604
052		.430000 x	15.400000 =	6.622000

			T.E =	207.798953
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	23.479183 =	35.218775
001		4.000000 x	15.951934 =	63.807736
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.097700 =	19.540000

			T.E =	139.248411
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.097700 =	24.425000
003		1.500000 x	23.479183 =	35.218775
001		2.000000 x	15.951934 =	31.903868
052		.540000 x	15.400000 =	8.316000

			T.E =	137.746652
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366
001		3.000000 x	15.951934 =	47.855802
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.097700 =	29.310000

			T.E =	169.897978
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366
001		3.500000 x	15.951934 =	55.831769
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.097700 =	34.195000
052		.400000 x	15.400000 =	6.160000
062		.600000 x	13.560000 =	8.136000

			T.E =	181.719645

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366
001		3.500000 x	15.951934 =	55.831769
065		.250000 x	13.610000 =	3.402500
027		350.000000 x	.117200 =	41.020000
062		.560000 x	13.560000 =	7.593600
052		.420000 x	15.400000 =	6.468000

			T.E =	188.038045
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.117200 =	49.810000
062		.550000 x	13.560000 =	7.458000
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366
001		4.000000 x	15.951934 =	63.807736
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000

			T.E =	203.862612
3217	3217			
001		2.500000 x	15.951934 =	39.879835

			T.E =	39.879835
3218	3218			
001		5.000000 x	15.951934 =	79.759670

			T.E =	79.759670
3219	3219			
001		3.000000 x	15.951934 =	47.855802
003		4.000000 x	23.479183 =	93.916732

			T.E =	141.772534
3220	3220			
001		5.000000 x	15.951934 =	79.759670
003		4.000000 x	23.479183 =	93.916732

			T.E =	173.676402
3221	3221			
001		3.000000 x	15.951934 =	47.855802
003		6.000000 x	23.479183 =	140.875098

			T.E =	188.730900

3222	3222				
001		5.000000 x	15.951934 =		79.759670
003		6.000000 x	23.479183 =		140.875098

			T.E =		220.634768
3223A.1	3223A.1				
001		2.000000 x	15.951934 =		31.903868
1502		.050000 x	521.926193 =		26.096310
003		1.500000 x	23.479183 =		35.218775

			AΘΡΟΙΣΜΑ =		93.218952
	T.E =	.500000 x	93.218952 =		46.609476

3223A.2	3223A.2				
001		3.000000 x	15.951934 =		47.855802
1502		.050000 x	521.926193 =		26.096310
003		2.000000 x	23.479183 =		46.958366

			AΘΡΟΙΣΜΑ =		120.910478
	T.E =	.500000 x	120.910478 =		60.455239

3223A.3	3223A.3				
001		2.000000 x	15.951934 =		31.903868
1502		.050000 x	521.926193 =		26.096310
003		1.500000 x	23.479183 =		35.218775

			AΘΡΟΙΣΜΑ =		93.218952
	T.E =	.500000 x	93.218952 =		46.609476

3223A.4	3223A.4				
001		3.000000 x	15.951934 =		47.855802
003		2.000000 x	23.479183 =		46.958366
1502		.050000 x	521.926193 =		26.096310

			AΘΡΟΙΣΜΑ =		120.910478
	T.E =	.500000 x	120.910478 =		60.455239

3223A.5	3223A.5				
001		3.500000 x	15.951934 =		55.831769
003		2.000000 x	23.479183 =		46.958366
1502		.050000 x	521.926193 =		26.096310

			AΘΡΟΙΣΜΑ =		128.886445
	T.E =	.500000 x	128.886445 =		64.443222

3223A.6	3223A.6			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	128.886445
	T.E =	.500000 x	128.886445 =	64.443222

3223A.7	3223A.7			
001		4.000000 x	15.951934 =	63.807736
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366

			ΑΘΡΟΙΣΜΑ =	136.862412
	T.E =	.500000 x	136.862412 =	68.431206

3223B.1	3223B.1			
001		2.000000 x	15.951934 =	31.903868
003		1.500000 x	23.479183 =	35.218775
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	93.218952
	T.E =	.250000 x	93.218952 =	23.304738

3223B.2	3223B.2			
001		3.000000 x	15.951934 =	47.855802
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	120.910478
	T.E =	.250000 x	120.910478 =	30.227619

3223B.3	3223B.3			
001		2.000000 x	15.951934 =	31.903868
003		1.500000 x	23.479183 =	35.218775
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	93.218952
	T.E =	.250000 x	93.218952 =	23.304738

3223B.4	3223B.4			
001		3.000000 x	15.951934 =	47.855802
1502		.050000 x	521.926193 =	26.096310
003		2.000000 x	23.479183 =	46.958366

			ΑΘΡΟΙΣΜΑ =	120.910478
	T.E =	.250000 x	120.910478 =	30.227619

3223B.5	3223B.5			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	128.886445
	T.E =	.250000 x	128.886445 =	32.221611

3223B.6	3223B.6			
001		3.500000 x	15.951934 =	55.831769
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	128.886445
	T.E =	.250000 x	128.886445 =	32.221611

3223B.7	3223B.7			
001		4.000000 x	15.951934 =	63.807736
003		2.000000 x	23.479183 =	46.958366
1502		.050000 x	521.926193 =	26.096310

			ΑΘΡΟΙΣΜΑ =	136.862412
	T.E =	.250000 x	136.862412 =	34.215603

3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.951934 =	79.759670
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.097700 =	14.655000

			T.E =	122.751070
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	37.750000 =	5.662500
056		.800000 x	10.580000 =	8.464000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769

			T.E =	99.536365

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	37.750000 =	7.550000
051		.200000 x	15.400000 =	3.080000
001		3.500000 x	15.951934 =	55.831769
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	23.479183 =	18.783346
056		.800000 x	10.580000 =	8.464000

			T.E =	101.764115
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	37.750000 =	15.100000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769
056		.800000 x	10.580000 =	8.464000

			T.E =	106.234115
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
056		.800000 x	10.580000 =	8.464000
032		.400000 x	37.750000 =	15.100000
026		100.000000 x	.097700 =	9.770000

			T.E =	122.387389
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	37.750000 =	6.040000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	23.479183 =	18.783346
001		3.500000 x	15.951934 =	55.831769

			T.E =	103.524315
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	37.750000 =	7.927500
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	15.951934 =	55.831769
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	23.479183 =	28.175020
061		.840000 x	13.560000 =	11.390400

			T.E =	114.989739

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	37.750000 =	15.855000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
061		.840000 x	13.560000 =	11.390400

			T.E =	119.683239
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	23.479183 =	28.175020
001		3.500000 x	15.951934 =	55.831769
061		.840000 x	13.560000 =	11.390400
032		.420000 x	37.750000 =	15.855000
026		100.000000 x	.097700 =	9.770000

			T.E =	126.444839
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.097700 =	13.678000
052		.294000 x	15.400000 =	4.527600

			T.E =	95.145826
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
061		.588000 x	13.560000 =	7.973280
026		140.000000 x	.097700 =	13.678000
058		.500000 x	9.090000 =	4.545000
052		.392000 x	15.400000 =	6.036800

			T.E =	98.407266
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
001		2.500000 x	15.951934 =	39.879835
003		1.100000 x	23.479183 =	25.827101
026		175.000000 x	.097700 =	17.097500
052		.287000 x	15.400000 =	4.419800

			T.E =	98.309406

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
061		.574000 x	13.560000 =	7.783440
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.097700 =	17.097500

			T.E =	101.421326
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.097700 =	13.678000
052		.294000 x	15.400000 =	4.527600
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
081		.500000 x	11.010000 =	5.505000

			T.E =	96.105826
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.097700 =	13.678000
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
001		2.500000 x	15.951934 =	39.879835
003		1.100000 x	23.479183 =	25.827101
081		.500000 x	11.010000 =	5.505000

			T.E =	99.367266
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
056		.574000 x	10.580000 =	6.072920
003		1.100000 x	23.479183 =	25.827101
081		.500000 x	11.010000 =	5.505000
001		2.500000 x	15.951934 =	39.879835
026		175.000000 x	.097700 =	17.097500
052		.287000 x	15.400000 =	4.419800

			T.E =	99.269406

3407.2	3407.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	23.479183 =	25.827101
001		2.500000 x	15.951934 =	39.879835
081		.500000 x	11.010000 =	5.505000
061		.574000 x	13.560000 =	7.783440
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.097700 =	17.097500

			T.E =	102.381326
3501	3501			
021		.200000 x	2.670000 =	.534000
032		.200000 x	37.750000 =	7.550000
001		5.000000 x	15.951934 =	79.759670
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	23.479183 =	46.958366
067		1.050000 x	49.210000 =	51.670500

			T.E =	193.241436
3502	3502			
021		.200000 x	2.670000 =	.534000
026		100.000000 x	.097700 =	9.770000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	23.479183 =	46.958366
001		5.000000 x	15.951934 =	79.759670
067		1.050000 x	49.210000 =	51.670500
032		.200000 x	37.750000 =	7.550000

			T.E =	200.003036
3503	3503			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.097700 =	14.655000
1407		.080000 x	37.605000 =	3.008400
003		2.000000 x	23.479183 =	46.958366
001		5.000000 x	15.951934 =	79.759670
067		1.000000 x	49.210000 =	49.210000
032		.200000 x	37.750000 =	7.550000

			T.E =	201.675436
3504	3504			
021		.200000 x	2.670000 =	.534000
003		3.200000 x	23.479183 =	75.133386
001		5.000000 x	15.951934 =	79.759670
517		4.000000 x	.000000 =	.000000
055		180.000000 x	.097400 =	17.532000
026		250.000000 x	.097700 =	24.425000

			T.E =	

3505	3505			
021		.200000 x	2.670000 =	.534000
055		420.000000 x	.097400 =	40.908000
003		5.000000 x	23.479183 =	117.395915
001		5.500000 x	15.951934 =	87.735637
517		4.000000 x	.000000 =	.000000
026		250.000000 x	.097700 =	24.425000

T.E =

3506	3506			
021		.300000 x	2.670000 =	.801000
515		1.150000 x	41.230000 =	47.414500
003		2.500000 x	23.479183 =	58.697958
001		5.000000 x	15.951934 =	79.759670
026		200.000000 x	.097700 =	19.540000

T.E =

206.213128

3511	3511			
021		.200000 x	2.670000 =	.534000
001		5.000000 x	15.951934 =	79.759670
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	23.479183 =	46.958366
032		.200000 x	37.750000 =	7.550000
069		1.050000 x	.000000 =	.000000

T.E =

3512	3512			
021		.200000 x	2.670000 =	.534000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	23.479183 =	46.958366
001		5.000000 x	15.951934 =	79.759670
069		1.050000 x	.000000 =	.000000
032		.200000 x	37.750000 =	7.550000
026		100.000000 x	.097700 =	9.770000

T.E =

3513	3513			
001		2.500000 x	15.951934 =	39.879835

T.E =

39.879835

3514	3514			
001		5.000000 x	15.951934 =	79.759670

T.E =

79.759670

3801	3801				
201		.001500 x	290.000000 =		.435000
003		.500000 x	23.479183 =		11.739592
001		.400000 x	15.951934 =		6.380774
203.4		.002500 x	210.000000 =		.525000
251		.300000 x	.710000 =		.213000

			T.E =		19.293365
3802	3802				
3801		.050000 x	19.293365 =		.964668

			T.E =		.964668
3811	3811				
203.4		.004000 x	210.000000 =		.840000
251		.100000 x	.710000 =		.071000
003		.800000 x	23.479183 =		18.783346
001		.200000 x	15.951934 =		3.190387

			T.E =		22.884733
3816	3816				
201		.002500 x	290.000000 =		.725000
003		.600000 x	23.479183 =		14.087510
001		.400000 x	15.951934 =		6.380774
203.4		.003000 x	210.000000 =		.630000
251		.200000 x	.710000 =		.142000

			T.E =		21.965283
3817	3817				
3816		.150000 x	21.965283 =		3.294792

			T.E =		3.294792
3821	3821				
201		.014000 x	290.000000 =		4.060000
251		.600000 x	.710000 =		.426000
003		2.400000 x	23.479183 =		56.350039
001		.600000 x	15.951934 =		9.571160
203.4		.018000 x	210.000000 =		3.780000

			T.E =		74.187200
3822	3822				
3821		.150000 x	74.187200 =		11.128080

			T.E =		11.128080

3823	3823			
201		.020000 x	290.000000 =	5.800000
001		.600000 x	15.951934 =	9.571160
003		3.000000 x	23.479183 =	70.437549
251		.180000 x	.710000 =	.127800
203.4		.025000 x	210.000000 =	5.250000

			T.E =	91.186509
3824	3824			
3823		.200000 x	91.186509 =	18.237302

			T.E =	18.237302
3831	3831			
201		.020000 x	290.000000 =	5.800000
003		4.500000 x	23.479183 =	105.656324
001		1.100000 x	15.951934 =	17.547127
251		.800000 x	.710000 =	.568000
203.4		.024000 x	210.000000 =	5.040000

			T.E =	134.611451
3832	3832			
3831		.150000 x	134.611451 =	20.191718

			T.E =	20.191718
3833	3833			
201		.022000 x	290.000000 =	6.380000
003		6.000000 x	23.479183 =	140.875098
001		1.100000 x	15.951934 =	17.547127
251		1.000000 x	.710000 =	.710000
203.4		.025000 x	210.000000 =	5.250000

			T.E =	170.762225
3834	3834			
3833		.200000 x	170.762225 =	34.152445

			T.E =	34.152445
3841	3841			
203.4		.001500 x	210.000000 =	.315000
003		.500000 x	23.479183 =	11.739592

			T.E =	12.054592

3851	3851			
203.4		.052000 x	210.000000 =	10.920000
251		1.100000 x	.710000 =	.781000
003		1.300000 x	23.479183 =	30.522938

			T.E =	42.223938
3852	3852			
001		.300000 x	15.951934 =	4.785580
003		.100000 x	23.479183 =	2.347918

			T.E =	7.133499
3871	3871			
260		1.030000 x	.536700 =	.552801
003		.050000 x	23.479183 =	1.173959

			T.E =	1.726760
3872	3872			
261		1.030000 x	.555400 =	.572062
003		.040000 x	23.479183 =	.939167

			T.E =	1.511229
3873	3873			
262		1.030000 x	.536700 =	.552801
003		.050000 x	23.479183 =	1.173959

			T.E =	1.726760
3874	3874			
258		1.450000 x	7.377000 =	10.696650
003		.150000 x	23.479183 =	3.521877

			T.E =	14.218527
3875	3875			
259		1.000000 x	24.070000 =	24.070000
003		.300000 x	23.479183 =	7.043755

			T.E =	31.113755
3876	3876			
003		.060000 x	23.479183 =	1.408751

			T.E =	1.408751

3881.1	3881.1			
111		1,023.391800 x	.078400 =	80.233917
001		5.000000 x	15.951934 =	79.759670

			T.E =	159.993587
3881.2	3881.2			
112		627.989998 x	.087900 =	55.200321
001		5.000000 x	15.951934 =	79.759670

			T.E =	134.959991
3882	3882			
127		1.050000 x	83.240000 =	87.402000
001		4.000000 x	15.951934 =	63.807736

			T.E =	151.209736
4101	4101			
081		1.150000 x	11.010000 =	12.661500
001		1.300000 x	15.951934 =	20.737514
003		2.000000 x	23.479183 =	46.958366

			T.E =	80.357380
4102	4102			
081		1.200000 x	11.010000 =	13.212000
001		1.700000 x	15.951934 =	27.118288
003		3.500000 x	23.479183 =	82.177141

			T.E =	122.507428
4103	4103			
081		1.150000 x	11.010000 =	12.661500
003		4.000000 x	23.479183 =	93.916732
001		3.000000 x	15.951934 =	47.855802

			T.E =	154.434034
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.951934 =	47.855802

			T.E =	59.416302
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	23.479183 =	21.131265
001		1.000000 x	15.951934 =	15.951934

			T.E =	40.936699

4106	4106			
081		.320000 x	11.010000 =	3.523200
001		.700000 x	15.951934 =	11.166354
003		.900000 x	23.479183 =	21.131265

			T.E =	35.820819
4107	4107			
081		1.200000 x	11.010000 =	13.212000
001		2.000000 x	15.951934 =	31.903868
003		3.000000 x	23.479183 =	70.437549

			T.E =	115.553417
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.951934 =	46.260609
003		4.000000 x	23.479183 =	93.916732

			T.E =	162.614971
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	39.954450 =	13.984058
003		2.500000 x	23.479183 =	58.697958
001		2.900000 x	15.951934 =	46.260609

			T.E =	131.604124
4206	4206			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.951934 =	46.260609
003		3.100000 x	23.479183 =	72.785467
1417		.350000 x	39.954450 =	13.984058

			T.E =	145.691633
4207	4207			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.951934 =	46.260609
1417		.350000 x	39.954450 =	13.984058
003		4.000000 x	23.479183 =	93.916732

			T.E =	166.822898

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
001		2.900000 x	15.951934 =	46.260609	
1447		.350000 x	58.155900 =	20.354565	
003		2.500000 x	23.479183 =	58.697958	

			T.E =	137.974631	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.155900 =	20.354565	
003		3.100000 x	23.479183 =	72.785467	
001		2.900000 x	15.951934 =	46.260609	

			T.E =	152.062141	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	58.155900 =	20.354565	
001		2.900000 x	15.951934 =	46.260609	
003		4.000000 x	23.479183 =	93.916732	

			T.E =	173.193406	
4221	4221				
001		.800000 x	15.951934 =	12.761547	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	36.240730	
4222	4222				
001		.400000 x	15.951934 =	6.380774	
003		.400000 x	23.479183 =	9.391673	

			T.E =	15.772447	
4226	4226				
003		1.300000 x	23.479183 =	30.522938	

			T.E =	30.522938	
4251	4251				
083		32.000000 x	.000000 =	.000000	
1412		.200000 x	27.931800 =	5.586360	
001		2.900000 x	15.951934 =	46.260609	
003		4.000000 x	23.479183 =	93.916732	

			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
1417		.200000 x	39.954450 =	7.990890
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	60.956500 =	12.191300
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
003		4.000000 x	23.479183 =	93.916732
001		2.900000 x	15.951934 =	46.260609
1447		.200000 x	58.155900 =	11.631180

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.951934 =	15.951934

T.E =

4301	4301			16.386934
081		1.020000 x	11.010000 =	11.230200
1412		.350000 x	27.931800 =	9.776130
003		4.200000 x	23.479183 =	98.612569
001		2.900000 x	15.951934 =	46.260609
083		5.000000 x	.000000 =	.000000

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
1417		.350000 x	39.954450 =	13.984058
003		2.700000 x	23.479183 =	63.393794
001		2.900000 x	15.951934 =	46.260609
083		2.000000 x	.000000 =	.000000

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
1417		.350000 x	39.954450 =	13.984058
003		3.300000 x	23.479183 =	77.481304
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.951934 =	46.260609

T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
001		2.900000 x	15.951934 =	46.260609
1417		.350000 x	39.954450 =	13.984058
003		4.200000 x	23.479183 =	98.612569
083		5.000000 x	.000000 =	.000000

T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	23.479183 =	63.393794
1447		.350000 x	58.155900 =	20.354565
001		2.900000 x	15.951934 =	46.260609

T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
1447		.350000 x	58.155900 =	20.354565
003		3.300000 x	23.479183 =	77.481304
001		2.900000 x	15.951934 =	46.260609

T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
1447		.350000 x	58.155900 =	20.354565
003		2.700000 x	23.479183 =	63.393794
001		2.900000 x	15.951934 =	46.260609
083		2.000000 x	.000000 =	.000000

T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.951934 =	15.951934

T.E = 16.386934

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
001		10.000000 x	15.951934 =	159.519340
003		25.000000 x	23.479183 =	586.979575
1446		.100000 x	52.110500 =	5.211050
251		4.000000 x	.710000 =	2.840000

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
1446		.100000 x	52.110500 =	5.211050
003		25.000000 x	23.479183 =	586.979575
001		10.000000 x	15.951934 =	159.519340
251		4.000000 x	.710000 =	2.840000

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
251		4.000000 x	.710000 =	2.840000
001		10.000000 x	15.951934 =	159.519340
1446		.100000 x	52.110500 =	5.211050
003		25.000000 x	23.479183 =	586.979575

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
1446		.200000 x	52.110500 =	10.422100
251		8.000000 x	.710000 =	5.680000
003		32.000000 x	23.479183 =	751.333856
001		11.000000 x	15.951934 =	175.471274

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
251		8.000000 x	.710000 =	5.680000
003		32.000000 x	23.479183 =	751.333856
1446		.200000 x	52.110500 =	10.422100
001		11.000000 x	15.951934 =	175.471274

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
1446		.200000 x	52.110500 =	10.422100
003		32.000000 x	23.479183 =	751.333856
001		11.000000 x	15.951934 =	175.471274
251		8.000000 x	.710000 =	5.680000

			T.E =	
4401	4401			
001		1.200000 x	15.951934 =	19.142321

			T.E =	19.142321
4402	4402			
001		3.000000 x	15.951934 =	47.855802

			T.E =	47.855802
4501	4501			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.729980 =	8.864990
003		1.000000 x	23.479183 =	23.479183

			T.E =	32.894673
4502	4502			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.729980 =	8.864990
003		1.300000 x	23.479183 =	30.522938

			T.E =	39.938428
4503	4503			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.729980 =	8.864990
003		1.400000 x	23.479183 =	32.870856

			T.E =	42.286346
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		2.300000 x	23.479183 =	54.002121

			T.E =	59.871615

4505	4505				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.729980 =	5.318994	
003		2.700000 x	23.479183 =	63.393794	

			T.E =	69.263288	
4506	4506				
081		.050000 x	11.010000 =	.550500	
003		3.600000 x	23.479183 =	84.525059	
002		.300000 x	17.729980 =	5.318994	

			T.E =	90.394553	
4507	4507				
081		.050000 x	11.010000 =	.550500	
003		3.200000 x	23.479183 =	75.133386	
002		.300000 x	17.729980 =	5.318994	

			T.E =	81.002880	
4508	4508				
081		.050000 x	11.010000 =	.550500	
003		3.000000 x	23.479183 =	70.437549	
002		.300000 x	17.729980 =	5.318994	

			T.E =	76.307043	
4511	4511				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.729980 =	5.318994	
003		3.800000 x	23.479183 =	89.220895	

			T.E =	95.090389	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.729980 =	5.318994	
003		4.000000 x	23.479183 =	93.916732	

			T.E =	99.786226	
4515	4515				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.729980 =	5.318994	
003		5.000000 x	23.479183 =	117.395915	

			T.E =	123.265409	

4516	4516			
081		.050000 x	11.010000 =	.550500
003		4.500000 x	23.479183 =	105.656324
002		.300000 x	17.729980 =	5.318994

			T.E =	111.525818
4517	4517			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		6.500000 x	23.479183 =	152.614690

			T.E =	158.484184
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		5.700000 x	23.479183 =	133.831343

			T.E =	139.700837
4519	4519			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		5.200000 x	23.479183 =	122.091752

			T.E =	127.961246
4521	4521			
081		.050000 x	11.010000 =	.550500
003		3.500000 x	23.479183 =	82.177141
002		.300000 x	17.729980 =	5.318994

			T.E =	88.046635
4522	4522			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		2.700000 x	23.479183 =	63.393794

			T.E =	69.263288
4525	4525			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		4.500000 x	23.479183 =	105.656324

			T.E =	111.525818

4526	4526			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.729980 =	5.318994
003		4.000000 x	23.479183 =	93.916732

			T.E =	99.786226
4527	4527			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	23.479183 =	140.875098
002		.300000 x	17.729980 =	5.318994

			T.E =	146.744592
4528	4528			
081		.050000 x	11.010000 =	.550500
003		5.200000 x	23.479183 =	122.091752
002		.300000 x	17.729980 =	5.318994

			T.E =	127.961246
4529	4529			
081		.050000 x	11.010000 =	.550500
003		4.700000 x	23.479183 =	110.352160
002		.300000 x	17.729980 =	5.318994

			T.E =	116.221654
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	23.479183 =	58.697958

			T.E =	59.248458
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	23.479183 =	46.958366

			T.E =	47.508866
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	23.479183 =	89.220895

			T.E =	89.771395
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	23.479183 =	72.785467

			T.E =	73.335967

4537	4537			
081		.050000 x	11.010000 =	.550500
003		5.500000 x	23.479183 =	129.135507

			T.E =	129.686007
4538	4538			
081		.050000 x	11.010000 =	.550500
003		4.600000 x	23.479183 =	108.004242

			T.E =	108.554742
4539	4539			
081		.050000 x	11.010000 =	.550500
003		4.200000 x	23.479183 =	98.612569

			T.E =	99.163069
4541	4541			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	23.479183 =	58.697958

			T.E =	59.248458
4542	4542			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	23.479183 =	46.958366

			T.E =	47.508866
4543	4543			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	23.479183 =	93.916732

			T.E =	94.467232
4544	4544			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	23.479183 =	140.875098

			T.E =	141.425598
4601.1	4601.1			
101		105.000000 x	.000000 =	.000000
001		.600000 x	15.951934 =	9.571160
1417		.023000 x	39.954450 =	.918952
003		.700000 x	23.479183 =	16.435428

			T.E =	

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	58.155900 =	1.337586
003		.700000 x	23.479183 =	16.435428
001		.600000 x	15.951934 =	9.571160

T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	39.954450 =	2.237449
003		1.300000 x	23.479183 =	30.522938
001		1.300000 x	15.951934 =	20.737514

T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.951934 =	20.737514
1447		.056000 x	58.155900 =	3.256730
003		1.300000 x	23.479183 =	30.522938

T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.951934 =	30.308675
1417		.089000 x	39.954450 =	3.555946
003		1.800000 x	23.479183 =	42.262529

T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
001		1.900000 x	15.951934 =	30.308675
1447		.089000 x	58.155900 =	5.175875
003		1.800000 x	23.479183 =	42.262529

T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	39.954450 =	13.264877
003		5.500000 x	23.479183 =	129.135507
001		6.300000 x	15.951934 =	100.497184

T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.951934 =	100.497184
1447		.332000 x	58.155900 =	19.307759
003		5.500000 x	23.479183 =	129.135507

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	39.954450 =	1.198634
003		.700000 x	23.479183 =	16.435428
001		.700000 x	15.951934 =	11.166354

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
1447		.030000 x	58.155900 =	1.744677
003		.700000 x	23.479183 =	16.435428
001		.700000 x	15.951934 =	11.166354

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	39.954450 =	2.796812
003		1.300000 x	23.479183 =	30.522938
001		1.400000 x	15.951934 =	22.332708

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.951934 =	22.332708
1447		.070000 x	58.155900 =	4.070913
003		1.300000 x	23.479183 =	30.522938

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.951934 =	33.499061
1417		.110000 x	39.954450 =	4.394990
003		1.800000 x	23.479183 =	42.262529

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
001		2.100000 x	15.951934 =	33.499061
1447		.110000 x	58.155900 =	6.397149
003		1.800000 x	23.479183 =	42.262529

T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	39.954450 =	16.141598
003		5.500000 x	23.479183 =	129.135507
001		6.500000 x	15.951934 =	103.687571

T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.951934 =	103.687571
1447		.404000 x	58.155900 =	23.494984
003		5.500000 x	23.479183 =	129.135507

T.E =

4621.1	4621.1			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	15.951934 =	6.380774
1417		.010000 x	39.954450 =	.399545
003		.500000 x	23.479183 =	11.739592

T.E = 22.675110

4621.2	4621.2			
111		53.000000 x	.078400 =	4.155200
001		.400000 x	15.951934 =	6.380774
1447		.010000 x	58.155900 =	.581559
003		.500000 x	23.479183 =	11.739592

T.E = 22.857124

4622.1	4622.1			
111		75.000000 x	.078400 =	5.880000
1417		.020000 x	39.954450 =	.799089
003		.500000 x	23.479183 =	11.739592
001		.450000 x	15.951934 =	7.178370

T.E = 25.597051

4622.2	4622.2			
111		75.000000 x	.078400 =	5.880000
001		.450000 x	15.951934 =	7.178370
1447		.020000 x	58.155900 =	1.163118
003		.500000 x	23.479183 =	11.739592

			T.E =	25.961080
4623.1	4623.1			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	15.951934 =	15.154337
1417		.050000 x	39.954450 =	1.997723
003		.950000 x	23.479183 =	22.305224

			T.E =	51.217284
4623.2	4623.2			
111		150.000000 x	.078400 =	11.760000
001		.950000 x	15.951934 =	15.154337
1447		.050000 x	58.155900 =	2.907795
003		.950000 x	23.479183 =	22.305224

			T.E =	52.127356
4624.1	4624.1			
111		225.000000 x	.078400 =	17.640000
1417		.085000 x	39.954450 =	3.396128
003		1.300000 x	23.479183 =	30.522938
001		1.500000 x	15.951934 =	23.927901

			T.E =	75.486967
4624.2	4624.2			
111		225.000000 x	.078400 =	17.640000
1447		.085000 x	58.155900 =	4.943252
003		1.300000 x	23.479183 =	30.522938
001		1.500000 x	15.951934 =	23.927901

			T.E =	77.034090
4625.1	4625.1			
111		750.000000 x	.078400 =	58.800000
003		4.300000 x	23.479183 =	100.960487
001		5.200000 x	15.951934 =	82.950057
1417		.320000 x	39.954450 =	12.785424

			T.E =	255.495968

4625.2	4625.2			
111		750.000000 x	.078400 =	58.800000
003		4.300000 x	23.479183 =	100.960487
001		5.200000 x	15.951934 =	82.950057
1447		.320000 x	58.155900 =	18.609888

			T.E =	261.320432
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	25.597051 =	56.313512

			T.E =	56.313512
4633.2	4633.2			
4622.2		2.200000 x	25.961080 =	57.114376

			T.E =	57.114376
4634.1	4634.1			
4622.1		1.200000 x	25.597051 =	30.716461
4623.1		1.000000 x	51.217284 =	51.217284

			T.E =	81.933745
4634.2	4634.2			
4622.2		1.200000 x	25.961080 =	31.153296
4623.2		1.000000 x	52.127356 =	52.127356

			T.E =	83.280652
4661.1	4661.1			
112		43.750000 x	.087900 =	3.845625
003		.500000 x	23.479183 =	11.739592
1417		.014507 x	39.954450 =	.579619
001		.400000 x	15.951934 =	6.380774

			T.E =	22.545609
4661.2	4661.2			
112		43.750000 x	.087900 =	3.845625
1447		.014507 x	58.155900 =	.843668
003		.500000 x	23.479183 =	11.739592
001		.400000 x	15.951934 =	6.380774

			T.E =	22.809658
4662.1	4662.1			
112		58.333300 x	.087900 =	5.127497
1417		.022840 x	39.954450 =	.912560
001		.450000 x	15.951934 =	7.178370
003		.500000 x	23.479183 =	11.739592

			T.E =	24.958019

4662.2	4662.2			
112		58.333300 x	.087900 =	5.127497
003		.500000 x	23.479183 =	11.739592
1447		.022840 x	58.155900 =	1.328281
001		.450000 x	15.951934 =	7.178370

			T.E =	25.373740
4663.1	4663.1			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.951934 =	14.356741
003		.900000 x	23.479183 =	21.131265
1417		.043218 x	39.954450 =	1.726751

			T.E =	46.444257
4663.2	4663.2			
112		105.000000 x	.087900 =	9.229500
001		.900000 x	15.951934 =	14.356741
1447		.043218 x	58.155900 =	2.513382
003		.900000 x	23.479183 =	21.131265

			T.E =	47.230887
4664.1	4664.1			
112		97.222221 x	.087900 =	8.545833
1417		.045077 x	39.954450 =	1.801027
003		.950000 x	23.479183 =	22.305224
001		.950000 x	15.951934 =	15.154337

			T.E =	47.806421
4664.2	4664.2			
112		97.222221 x	.087900 =	8.545833
001		.950000 x	15.951934 =	15.154337
1447		.045077 x	58.155900 =	2.621494
003		.950000 x	23.479183 =	22.305224

			T.E =	48.626888
4665.1	4665.1			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.951934 =	23.927901
1417		.047530 x	39.954450 =	1.899035
003		1.300000 x	23.479183 =	30.522938

			T.E =	71.732286

4665.2	4665.2			
112		174.999001 x	.087900 =	15.382412
001		1.500000 x	15.951934 =	23.927901
1447		.047530 x	58.155900 =	2.764150
003		1.300000 x	23.479183 =	30.522938

			T.E =	72.597401
4666.1	4666.1			
112		486.111099 x	.087900 =	42.729166
1417		.277862 x	39.954450 =	11.101823
003		4.300000 x	23.479183 =	100.960487
001		5.200000 x	15.951934 =	82.950057

			T.E =	237.741533
4666.2	4666.2			
112		486.111000 x	.087900 =	42.729157
001		5.200000 x	15.951934 =	82.950057
1447		.277862 x	58.155900 =	16.159315
003		4.300000 x	23.479183 =	100.960487

			T.E =	242.799015
4701	4701			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.951934 =	7.975967
1417		.020000 x	39.954450 =	.799089
003		.400000 x	23.479183 =	9.391673

			T.E =	25.576729
4702	4702			
113		13.000000 x	.570000 =	7.410000
001		.500000 x	15.951934 =	7.975967
1447		.020000 x	58.155900 =	1.163118
003		.400000 x	23.479183 =	9.391673

			T.E =	25.940758
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	39.954450 =	.599317
003		.350000 x	23.479183 =	8.217714
001		.400000 x	15.951934 =	6.380774

			T.E =	

4704 4704

114	13.000000 x	.000000 =	.000000
001	.400000 x	15.951934 =	6.380774
1447	.015000 x	58.155900 =	.872339
003	.350000 x	23.479183 =	8.217714

T.E =

4711 4711

117	13.000000 x	.000000 =	.000000
001	.500000 x	15.951934 =	7.975967
1417	.020000 x	39.954450 =	.799089
003	.400000 x	23.479183 =	9.391673

T.E =

4712 4712

117	13.000000 x	.000000 =	.000000
001	.500000 x	15.951934 =	7.975967
1447	.020000 x	58.155900 =	1.163118
003	.400000 x	23.479183 =	9.391673

T.E =

4713 4713

118	13.000000 x	.000000 =	.000000
1417	.015000 x	39.954450 =	.599317
003	.350000 x	23.479183 =	8.217714
001	.400000 x	15.951934 =	6.380774

T.E =

4714 4714

118	13.000000 x	.000000 =	.000000
001	.400000 x	15.951934 =	6.380774
1447	.015000 x	58.155900 =	.872339
003	.350000 x	23.479183 =	8.217714

T.E =

4721.1 4721.1

128	.080000 x	90.430000 =	7.234400
001	.300000 x	15.951934 =	4.785580
1417	.004000 x	39.954450 =	.159818
003	.350000 x	23.479183 =	8.217714

T.E =

20.397512

4721.2	4721.2				
128		.080000 x	90.430000 =	7.234400	
001		.300000 x	15.951934 =	4.785580	
1447		.004000 x	58.155900 =	.232624	
003		.350000 x	23.479183 =	8.217714	

			T.E =	20.470318	
4722.1	4722.1				
128		.100000 x	90.430000 =	9.043000	
1417		.005000 x	39.954450 =	.199772	
003		.350000 x	23.479183 =	8.217714	
001		.350000 x	15.951934 =	5.583177	

			T.E =	23.043663	
4722.2	4722.2				
128		.100000 x	90.430000 =	9.043000	
1447		.005000 x	58.155900 =	.290780	
001		.350000 x	15.951934 =	5.583177	
003		.350000 x	23.479183 =	8.217714	

			T.E =	23.134670	
4723	4723				
128		.120000 x	90.430000 =	10.851600	
003		.350000 x	23.479183 =	8.217714	
1417		.006000 x	39.954450 =	.239727	
001		.400000 x	15.951934 =	6.380774	

			T.E =	25.689814	
4724.1	4724.1				
128		.150000 x	90.430000 =	13.564500	
001		.400000 x	15.951934 =	6.380774	
1417		.008000 x	39.954450 =	.319636	
003		.400000 x	23.479183 =	9.391673	

			T.E =	29.656582	
4724.2	4724.2				
128		.150000 x	90.430000 =	13.564500	
001		.400000 x	15.951934 =	6.380774	
1447		.008000 x	58.155900 =	.465247	
003		.400000 x	23.479183 =	9.391673	

			T.E =	29.802194	

4725.1	4725.1			
128		.180000 x	90.430000 =	16.277400
1417		.009000 x	39.954450 =	.359590
003		.400000 x	23.479183 =	9.391673
001		.450000 x	15.951934 =	7.178370

			T.E =	33.207034
4725.2	4725.2			
128		.180000 x	90.430000 =	16.277400
001		.450000 x	15.951934 =	7.178370
1447		.009000 x	58.155900 =	.523403
003		.400000 x	23.479183 =	9.391673

			T.E =	33.370847
4801.1	4801.1			
4662.1		1.000000 x	24.958019 =	24.958019
4662.1		.100000 x	24.958019 =	2.495802

			T.E =	27.453821
4801.2	4801.2			
4662.2		1.000000 x	25.373740 =	25.373740
4662.2		.100000 x	25.373740 =	2.537374

			T.E =	27.911114
4802.1	4802.1			
4664.1		1.000000 x	47.806421 =	47.806421
4664.1		.050000 x	47.806421 =	2.390321

			T.E =	50.196742
4802.2	4802.2			
4664.2		1.000000 x	48.626888 =	48.626888
4664.2		.050000 x	48.626888 =	2.431344

			T.E =	51.058232
4803.1	4803.1			
4665.1		1.000000 x	71.732286 =	71.732286
4665.1		.030000 x	71.732286 =	2.151969

			T.E =	73.884255
4803.2	4803.2			
4665.2		1.000000 x	72.597401 =	72.597401
4665.2		.030000 x	72.597401 =	2.177922

			T.E =	74.775323

4811.1	4811.1				
001		.225000 x	15.951934 =	3.589185	
4662.1		1.000000 x	24.958019 =	24.958019	
003		.250000 x	23.479183 =	5.869796	

			T.E =	34.417000	
4811.2	4811.2				
001		.225000 x	15.951934 =	3.589185	
003		.250000 x	23.479183 =	5.869796	
4662.2		1.000000 x	25.373740 =	25.373740	

			T.E =	34.832721	
4812.1	4812.1				
001		.475000 x	15.951934 =	7.577169	
003		.475000 x	23.479183 =	11.152612	
4664.1		1.000000 x	47.806421 =	47.806421	

			T.E =	66.536202	
4812.2	4812.2				
001		.475000 x	15.951934 =	7.577169	
003		.475000 x	23.479183 =	11.152612	
4664.2		1.000000 x	48.626888 =	48.626888	

			T.E =	67.356669	
4813.1	4813.1				
001		.750000 x	15.951934 =	11.963951	
4665.1		1.000000 x	71.732286 =	71.732286	
003		.650000 x	23.479183 =	15.261469	

			T.E =	98.957705	
4813.2	4813.2				
001		.750000 x	15.951934 =	11.963951	
003		.650000 x	23.479183 =	15.261469	
4665.2		1.000000 x	72.597401 =	72.597401	

			T.E =	99.822820	
4814.1	4814.1				
001		2.600000 x	15.951934 =	41.475028	
003		2.150000 x	23.479183 =	50.480243	
4666.1		1.000000 x	237.741533 =	237.741533	

			T.E =	329.696805	

4814.2	4814.2			
001		2.600000 x	15.951934 =	41.475028
003		2.150000 x	23.479183 =	50.480243
4666.2		1.000000 x	242.799015 =	242.799015

			T.E =	334.754287
4821.1	4821.1			
003		.450000 x	23.479183 =	10.565632
4662.1		1.000000 x	24.958019 =	24.958019

			T.E =	35.523651
4821.2	4821.2			
003		.450000 x	23.479183 =	10.565632
4662.2		1.000000 x	25.373740 =	25.373740

			T.E =	35.939372
4822.1	4822.1			
003		.807500 x	23.479183 =	18.959440
4664.1		1.000000 x	47.806421 =	47.806421

			T.E =	66.765861
4822.2	4822.2			
003		.807500 x	23.479183 =	18.959440
4664.2		1.000000 x	48.626888 =	48.626888

			T.E =	67.586328
4823.1	4823.1			
003		1.040000 x	23.479183 =	24.418350
4665.1		1.000000 x	71.732286 =	71.732286

			T.E =	96.150636
4823.2	4823.2			
003		1.040000 x	23.479183 =	24.418350
4665.2		1.000000 x	72.597401 =	72.597401

			T.E =	97.015751
4824.1	4824.1			
003		3.010000 x	23.479183 =	70.672341
4666.1		1.000000 x	237.741533 =	237.741533

			T.E =	308.413874

4824.2	4824.2				
003		3.010000 x	23.479183 =	70.672341	
4666.2		1.000000 x	242.799015 =	242.799015	
			T.E =	313.471356	
4831.1	4831.1				
003		1.200000 x	23.479183 =	28.175020	
4661.1		1.000000 x	22.545609 =	22.545609	
			T.E =	50.720629	
4831.2	4831.2				
003		1.200000 x	23.479183 =	28.175020	
4661.2		1.000000 x	22.809658 =	22.809658	
			T.E =	50.984678	
4832.1	4832.1				
003		1.600000 x	23.479183 =	37.566693	
4662.1		1.000000 x	24.958019 =	24.958019	
			T.E =	62.524712	
4832.2	4832.2				
003		1.600000 x	23.479183 =	37.566693	
4662.2		1.000000 x	25.373740 =	25.373740	
			T.E =	62.940433	
4833.1	4833.1				
002		2.000000 x	17.729980 =	35.459960	
4664.1		1.000000 x	47.806421 =	47.806421	
			T.E =	83.266381	
4833.2	4833.2				
002		2.000000 x	17.729980 =	35.459960	
4664.2		1.000000 x	48.626888 =	48.626888	
			T.E =	84.086848	
4834.1	4834.1				
003		2.300000 x	23.479183 =	54.002121	
4665.1		1.000000 x	71.732286 =	71.732286	
			T.E =	125.734407	

4834.2	4834.2			
003		2.300000 x	23.479183 =	54.002121
4665.2		1.000000 x	72.597401 =	72.597401

T.E = 126.599522

4835	4835			
122		1.050000 x	.000000 =	.000000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	23.479183 =	23.479183
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.741500 =	1.483000

T.E =

4835.2	4835.2			
122		1.050000 x	.000000 =	.000000
001		1.000000 x	15.951934 =	15.951934
201		.010000 x	290.000000 =	2.900000
1447		.005000 x	58.155900 =	.290780
003		1.000000 x	23.479183 =	23.479183
265		2.000000 x	.741500 =	1.483000

T.E =

4836.1	4836.1			
123		1.050000 x	.000000 =	.000000
1417		.005000 x	39.954450 =	.199772
003		1.000000 x	23.479183 =	23.479183
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.741500 =	1.483000
201		.010000 x	290.000000 =	2.900000

T.E =

4836.2	4836.2			
123		1.050000 x	.000000 =	.000000
201		.010000 x	290.000000 =	2.900000
265		2.000000 x	.741500 =	1.483000
1447		.005000 x	58.155900 =	.290780
003		1.000000 x	23.479183 =	23.479183
001		1.000000 x	15.951934 =	15.951934

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	39.954450 =	.399545
003		1.000000 x	23.479183 =	23.479183
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.951934 =	15.951934
265		2.000000 x	.741500 =	1.483000

			T.E =	50.408662
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
201		.010000 x	290.000000 =	2.900000
1447		.010000 x	58.155900 =	.581559
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
265		2.000000 x	.741500 =	1.483000

			T.E =	52.368722
4841	4841			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
4842	4842			
003		1.000000 x	23.479183 =	23.479183

			T.E =	23.479183
4843	4843			
003		.250000 x	23.479183 =	5.869796

			T.E =	5.869796
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
1401		.250000 x	234.711000 =	58.677750
003		25.000000 x	23.479183 =	586.979575
001		10.000000 x	15.951934 =	159.519340

			T.E =	1,585.176665
4845	4845			
132		620.000000 x	.930000 =	576.600000
001		6.000000 x	15.951934 =	95.711604
1401		.180000 x	234.711000 =	42.247980
003		15.000000 x	23.479183 =	352.187745

			T.E =	1,066.747329

4851	4851			
001		.100000 x	15.951934 =	1.595193

			T.E =	1.595193
4852	4852			
001		.150000 x	15.951934 =	2.392790

			T.E =	2.392790
4853	4853			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
4854	4854			
001		.250000 x	15.951934 =	3.987984

			T.E =	3.987984
4855	4855			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
4856	4856			
001		.800000 x	15.951934 =	12.761547

			T.E =	12.761547
4857	4857			
001		.200000 x	15.951934 =	3.190387

			T.E =	3.190387
4858	4858			
001		.300000 x	15.951934 =	4.785580

			T.E =	4.785580
4859	4859			
001		.400000 x	15.951934 =	6.380774

			T.E =	6.380774
4860	4860			
001		.500000 x	15.951934 =	7.975967

			T.E =	7.975967

4861	4861			
001		.600000 x	15.951934 =	9.571160

			T.E =	9.571160
4862	4862			
001		1.700000 x	15.951934 =	27.118288

			T.E =	27.118288
5101	5101			
214		1.100000 x	.000000 =	.000000
003		4.000000 x	23.479183 =	93.916732
001		1.000000 x	15.951934 =	15.951934

			T.E =	
5102	5102			
483		1.800000 x	.165000 =	.297000
491		1.260000 x	.480000 =	.604800
488		.540000 x	5.000000 =	2.700000
489		.360000 x	.000000 =	.000000
001		1.000000 x	15.951934 =	15.951934
492		1.440000 x	.480000 =	.691200

			T.E =	
5103	5103			
265		1.050000 x	.741500 =	.778575
003		.200000 x	23.479183 =	4.695837
002		.050000 x	17.729980 =	.886499

			T.E =	6.360911
5104	5104			
001		2.000000 x	15.951934 =	31.903868
003		.150000 x	23.479183 =	3.521877

			T.E =	35.425745
5105	5105			
214		.010000 x	.000000 =	.000000
003		.500000 x	23.479183 =	11.739592
001		2.000000 x	15.951934 =	31.903868

			T.E =	

5106	5106			
214		.050000 x	.000000 =	.000000
001		2.000000 x	15.951934 =	31.903868
003		2.500000 x	23.479183 =	58.697958

			T.E =	
5201	5201			
201		1.100000 x	290.000000 =	319.000000
002		5.000000 x	17.729980 =	88.649900
251		6.000000 x	.710000 =	4.260000
003		10.000000 x	23.479183 =	234.791830

			T.E =	646.701730
5202	5202			
203.2		1.080000 x	335.000000 =	361.800000
251		6.000000 x	.710000 =	4.260000
003		9.000000 x	23.479183 =	211.312647
002		4.500000 x	17.729980 =	79.784910

			T.E =	657.157557
5203	5203			
201		1.120000 x	290.000000 =	324.800000
003		16.000000 x	23.479183 =	375.666928
002		8.000000 x	17.729980 =	141.839840
251		12.000000 x	.710000 =	8.520000

			T.E =	850.826768
5204	5204			
203.2		1.100000 x	335.000000 =	368.500000
002		7.000000 x	17.729980 =	124.109860
003		14.000000 x	23.479183 =	328.708562
251		12.000000 x	.710000 =	8.520000

			T.E =	829.838422
5211	5211			
201		1.100000 x	290.000000 =	319.000000
251		14.000000 x	.710000 =	9.940000
003		12.000000 x	23.479183 =	281.750196
002		6.000000 x	17.729980 =	106.379880

			T.E =	717.070076

5212	5212				
203.2		1.080000 x	335.000000 =	361.800000	
251		14.000000 x	.710000 =	9.940000	
003		10.000000 x	23.479183 =	234.791830	
002		5.000000 x	17.729980 =	88.649900	

			T.E =	695.181730	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
003		9.000000 x	23.479183 =	211.312647	
002		4.500000 x	17.729980 =	79.784910	
251		8.000000 x	.710000 =	5.680000	

			T.E =	615.777557	
5221	5221				
203.2		.014000 x	335.000000 =	4.690000	
251		.100000 x	.710000 =	.071000	
002		.050000 x	17.729980 =	.886499	
003		.200000 x	23.479183 =	4.695837	

			T.E =	10.343336	
5222	5222				
203.2		.018000 x	335.000000 =	6.030000	
251		.100000 x	.710000 =	.071000	
003		.200000 x	23.479183 =	4.695837	
002		.070000 x	17.729980 =	1.241099	

			T.E =	12.037935	
5223	5223				
203.2		.026000 x	335.000000 =	8.710000	
251		.100000 x	.710000 =	.071000	
003		.200000 x	23.479183 =	4.695837	
002		.100000 x	17.729980 =	1.772998	

			T.E =	15.249835	
5226	5226				
203.2		.016000 x	335.000000 =	5.360000	
003		.200000 x	23.479183 =	4.695837	
002		.050000 x	17.729980 =	.886499	
251		.100000 x	.710000 =	.071000	

			T.E =	11.013336	

5227	5227				
203.2		.022000 x	335.000000 =	7.370000	
251		.100000 x	.710000 =	.071000	
002		.100000 x	17.729980 =	1.772998	
003		.200000 x	23.479183 =	4.695837	

			T.E =	13.909835	
5228	5228				
203.2		.030000 x	335.000000 =	10.050000	
251		.150000 x	.710000 =	.106500	
003		.200000 x	23.479183 =	4.695837	
002		.150000 x	17.729980 =	2.659497	

			T.E =	17.511834	
5231	5231				
203.2		.018000 x	335.000000 =	6.030000	
251		.150000 x	.710000 =	.106500	
003		.250000 x	23.479183 =	5.869796	
002		.100000 x	17.729980 =	1.772998	

			T.E =	13.779294	
5232	5232				
203.2		.025000 x	335.000000 =	8.375000	
003		.250000 x	23.479183 =	5.869796	
002		.120000 x	17.729980 =	2.127598	
251		.150000 x	.710000 =	.106500	

			T.E =	16.478893	
5233	5233				
203.2		.034000 x	335.000000 =	11.390000	
251		.200000 x	.710000 =	.142000	
002		.150000 x	17.729980 =	2.659497	
003		.250000 x	23.479183 =	5.869796	

			T.E =	20.061293	
5236	5236				
203.2		.016000 x	335.000000 =	5.360000	
251		.080000 x	.710000 =	.056800	
003		.350000 x	23.479183 =	8.217714	
002		.250000 x	17.729980 =	4.432495	

			T.E =	18.067009	

5237	5237				
203.2		.022000 x	335.000000 =		7.370000
251		.080000 x	.710000 =		.056800
003		.350000 x	23.479183 =		8.217714
002		.300000 x	17.729980 =		5.318994

			T.E =		20.963508
5238	5238				
203.2		.030000 x	335.000000 =		10.050000
003		.350000 x	23.479183 =		8.217714
002		.350000 x	17.729980 =		6.205493
251		.100000 x	.710000 =		.071000

			T.E =		24.544207
5241	5241				
203.2		.030000 x	335.000000 =		10.050000
251		.100000 x	.710000 =		.071000
003		.500000 x	23.479183 =		11.739592
002		.500000 x	17.729980 =		8.864990

			T.E =		30.725582
5243	5243				
003		.150000 x	23.479183 =		3.521877

			T.E =		3.521877
5244	5244				
003		.350000 x	23.479183 =		8.217714

			T.E =		8.217714
5246	5246				
220		26.000000 x	.000000 =		.000000
251		.200000 x	.710000 =		.142000
002		.500000 x	17.729980 =		8.864990

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
002		.600000 x	17.729980 =		10.637988
283		.100000 x	1.000100 =		.100010
251		.100000 x	.710000 =		.071000

			T.E =		

5251	5251				
243.3		1.050000 x	4.450000 =	4.672500	
003		.300000 x	23.479183 =	7.043755	
002		.300000 x	17.729980 =	5.318994	
251		.100000 x	.710000 =	.071000	

			T.E =	17.106249	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
245		.110000 x	18.600000 =	2.046000	
002		2.500000 x	17.729980 =	44.324950	
003		2.500000 x	23.479183 =	58.697958	

			T.E =	125.528908	
5252.2	5252.2				
246		1.100000 x	9.000000 =	9.900000	
246		.110000 x	9.000000 =	.990000	
003		2.500000 x	23.479183 =	58.697958	
002		2.500000 x	17.729980 =	44.324950	

			T.E =	113.912908	
5252.3	5252.3				
249		1.100000 x	19.000000 =	20.900000	
249		.110000 x	19.000000 =	2.090000	
003		2.500000 x	23.479183 =	58.697958	
002		2.500000 x	17.729980 =	44.324950	

			T.E =	126.012908	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
003		1.500000 x	23.479183 =	35.218775	
002		1.500000 x	17.729980 =	26.594970	
219		.060000 x	3.500000 =	.210000	

			T.E =	66.223745	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
203.2		.025000 x	335.000000 =	8.375000	
251		.600000 x	.710000 =	.426000	
002		.800000 x	17.729980 =	14.183984	
003		.800000 x	23.479183 =	18.783346	

			T.E =	47.568330	

5262	5262				
201		.030000 x	290.000000 =	8.700000	
251		.300000 x	.710000 =	.213000	
252		.200000 x	1.900000 =	.380000	
003		1.000000 x	23.479183 =	23.479183	
002		1.000000 x	17.729980 =	17.729980	
265		.300000 x	.741500 =	.222450	
203.2		.025000 x	335.000000 =	8.375000	

			T.E =	59.099613	
5266	5266				
201		.020000 x	290.000000 =	5.800000	
003		.600000 x	23.479183 =	14.087510	
002		.600000 x	17.729980 =	10.637988	
251		.600000 x	.710000 =	.426000	
203.2		.015000 x	335.000000 =	5.025000	

			T.E =	35.976498	
5267	5267				
201		.030000 x	290.000000 =	8.700000	
252		.300000 x	1.900000 =	.570000	
003		.800000 x	23.479183 =	18.783346	
002		.800000 x	17.729980 =	14.183984	
265		.300000 x	.741500 =	.222450	
203.2		.015000 x	335.000000 =	5.025000	
251		.300000 x	.710000 =	.213000	

			T.E =	47.697780	
5271	5271				
201		.016000 x	290.000000 =	4.640000	
251		.600000 x	.710000 =	.426000	
003		.500000 x	23.479183 =	11.739592	
002		.500000 x	17.729980 =	8.864990	
203.2		.025000 x	335.000000 =	8.375000	

			T.E =	34.045582	
5272	5272				
201		.024000 x	290.000000 =	6.960000	
203.2		.025000 x	335.000000 =	8.375000	
251		.300000 x	.710000 =	.213000	
002		.700000 x	17.729980 =	12.410986	
003		.700000 x	23.479183 =	16.435428	
265		.200000 x	.741500 =	.148300	
252		.100000 x	1.900000 =	.190000	

			T.E =	44.732714	

5273	5273			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990
203.2		.015000 x	335.000000 =	5.025000
251		.600000 x	.710000 =	.426000

			T.E =	30.695582
5274	5274			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986
265		.200000 x	.741500 =	.148300
252		.100000 x	1.900000 =	.190000
251		.300000 x	.710000 =	.213000
203.2		.015000 x	335.000000 =	5.025000

			T.E =	41.382714
5276	5276			
201		1.080000 x	290.000000 =	313.200000
003		19.000000 x	23.479183 =	446.104477
002		19.000000 x	17.729980 =	336.869620
252		18.000000 x	1.900000 =	34.200000
251		6.000000 x	.710000 =	4.260000

			T.E =	1,134.634097
5277	5277			
203.2		1.080000 x	335.000000 =	361.800000
003		18.000000 x	23.479183 =	422.625294
002		18.000000 x	17.729980 =	319.139640
252		18.000000 x	1.900000 =	34.200000
251		6.000000 x	.710000 =	4.260000

			T.E =	1,142.024934
5279	5279			
201		1.080000 x	290.000000 =	313.200000
003		10.000000 x	23.479183 =	234.791830
002		5.000000 x	17.729980 =	88.649900
251		12.000000 x	.710000 =	8.520000

			T.E =	645.161730

5280	5280			
203.2		1.080000 x	335.000000 =	361.800000
251		12.000000 x	.710000 =	8.520000
002		5.000000 x	17.729980 =	88.649900
003		10.000000 x	23.479183 =	234.791830

			T.E =	693.761730
5281	5281			
203.2		.014000 x	335.000000 =	4.690000
251		.040000 x	.710000 =	.028400
002		.250000 x	17.729980 =	4.432495

			T.E =	9.150895
5282	5282			
203.2		.020000 x	335.000000 =	6.700000
251		.060000 x	.710000 =	.042600
002		.350000 x	17.729980 =	6.205493

			T.E =	12.948093
5283	5283			
203.2		.026000 x	335.000000 =	8.710000
002		.400000 x	17.729980 =	7.091992
251		.080000 x	.710000 =	.056800

			T.E =	15.858792
5286	5286			
203.2		.008000 x	335.000000 =	2.680000
251		.030000 x	.710000 =	.021300
002		.120000 x	17.729980 =	2.127598
003		.120000 x	23.479183 =	2.817502

			T.E =	7.646400
5288	5288			
003		.300000 x	23.479183 =	7.043755

			T.E =	7.043755
5289	5289			
003		1.000000 x	23.479183 =	23.479183

			T.E =	23.479183

5291	5291			
203.2		.020000 x	335.000000 =	6.700000
220		26.000000 x	.000000 =	.000000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992
251		.200000 x	.710000 =	.142000

T.E =

5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988
220		26.000000 x	.000000 =	.000000
251		.200000 x	.710000 =	.142000
203.2		.010000 x	335.000000 =	3.350000

T.E =

5293	5293			
203.2		.020000 x	335.000000 =	6.700000
251		.150000 x	.710000 =	.106500
203.2		.016000 x	335.000000 =	5.360000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992

T.E =

5294	5294			28.650165
203.2		.020000 x	335.000000 =	6.700000
203.2		.022000 x	335.000000 =	7.370000
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992
251		.100000 x	.710000 =	.071000

T.E =

5295	5295			30.624665
203.2		.020000 x	335.000000 =	6.700000
251		.050000 x	.710000 =	.035500
002		.250000 x	17.729980 =	4.432495
003		.250000 x	23.479183 =	5.869796

T.E =

5301	5301			17.037791
226		1.050000 x	11.500000 =	12.075000
251		.250000 x	.710000 =	.177500
003		.600000 x	23.479183 =	14.087510
002		.600000 x	17.729980 =	10.637988

T.E =

36.977998

5302	5302			
227		1.050000 x	11.500000 =	12.075000
251		.200000 x	.710000 =	.142000
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990

			T.E =	32.821582
5321	5321			
203.2		.012000 x	335.000000 =	4.020000
003		.900000 x	23.479183 =	21.131265
002		.900000 x	17.729980 =	15.956982
251		.500000 x	.710000 =	.355000
226		1.050000 x	11.500000 =	12.075000

			T.E =	53.538247
5322	5322			
203.2		.012000 x	335.000000 =	4.020000
227		1.050000 x	11.500000 =	12.075000
251		.450000 x	.710000 =	.319500
003		.800000 x	23.479183 =	18.783346
002		.800000 x	17.729980 =	14.183984

			T.E =	49.381830
5323	5323			
203.2		.012000 x	335.000000 =	4.020000
003		1.000000 x	23.479183 =	23.479183
228		1.050000 x	35.000000 =	36.750000
002		1.000000 x	17.729980 =	17.729980
251		.500000 x	.710000 =	.355000

			T.E =	82.334163
5324	5324			
203.2		.012000 x	335.000000 =	4.020000
229		1.050000 x	.000000 =	.000000
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
251		.500000 x	.710000 =	.355000

			T.E =	
5325	5325			
203.2		.012000 x	335.000000 =	4.020000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
251		.500000 x	.710000 =	.355000
230		1.050000 x	.000000 =	.000000

			T.E =	

5326	5326				
203.2		.012000 x	335.000000 =	4.020000	
231		1.050000 x	20.000000 =	21.000000	
251		.500000 x	.710000 =	.355000	
003		1.000000 x	23.479183 =	23.479183	
002		1.000000 x	17.729980 =	17.729980	

			T.E =	66.584163	
5341	5341				
203.2		.037000 x	335.000000 =	12.395000	
003		1.100000 x	23.479183 =	25.827101	
232		1.050000 x	45.000000 =	47.250000	
002		1.100000 x	17.729980 =	19.502978	
251		.600000 x	.710000 =	.426000	

			T.E =	105.401079	
5342	5342				
203.2		.037000 x	335.000000 =	12.395000	
232		1.100000 x	45.000000 =	49.500000	
002		1.700000 x	17.729980 =	30.140966	
003		1.700000 x	23.479183 =	39.914611	
251		.600000 x	.710000 =	.426000	

			T.E =	132.376577	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
003		.800000 x	23.479183 =	18.783346	
002		.800000 x	17.729980 =	14.183984	
233		.084000 x	21.300000 =	1.789200	

			T.E =	57.121530	
5351	5351				
035		.200000 x	.125600 =	.025120	
003		.200000 x	23.479183 =	4.695837	
002		.200000 x	17.729980 =	3.545996	
251		.100000 x	.710000 =	.071000	
236		1.060000 x	2.600000 =	2.756000	

			T.E =	11.093953	
5352	5352				
035		.200000 x	.125600 =	.025120	
251		.100000 x	.710000 =	.071000	
003		.200000 x	23.479183 =	4.695837	
002		.200000 x	17.729980 =	3.545996	
237		1.060000 x	1.100000 =	1.166000	

			T.E =	9.503953	

5353	5353			
035		.200000 x	.125600 =	.025120
238		1.060000 x	2.600000 =	2.756000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
251		.100000 x	.710000 =	.071000

			T.E =	11.093953
5354	5354			
035		.200000 x	.125600 =	.025120
239		1.060000 x	.000000 =	.000000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		.100000 x	.710000 =	.071000

			T.E =	
5355	5355			
035		.200000 x	.125600 =	.025120
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		.100000 x	.710000 =	.071000
240		1.060000 x	1.600000 =	1.696000

			T.E =	10.033953
5356	5356			
035		.200000 x	.125600 =	.025120
251		.100000 x	.710000 =	.071000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
241		1.060000 x	.000000 =	.000000

			T.E =	
5421	5421			
205		.055000 x	420.000000 =	23.100000
1471		1.000000 x	5.229271 =	5.229271
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930

			T.E =	172.561342
5422	5422			
205		.035000 x	420.000000 =	14.700000
1472		1.000000 x	6.321176 =	6.321176
003		3.000000 x	23.479183 =	70.437549
002		3.000000 x	17.729980 =	53.189940

			T.E =	144.648665

5426	5426			
205		.095000 x	420.000000 =	39.900000
002		6.000000 x	17.729980 =	106.379880
003		6.000000 x	23.479183 =	140.875098
1473		1.000000 x	10.845859 =	10.845859
1471		1.000000 x	5.229271 =	5.229271

T.E = 303.230108

5427	5427			
205		.105000 x	420.000000 =	44.100000
002		7.000000 x	17.729980 =	124.109860
1474		1.000000 x	13.165427 =	13.165427
1471		1.000000 x	5.229271 =	5.229271
003		7.000000 x	23.479183 =	164.354281

T.E = 350.958839

5428	5428			
205		.075000 x	420.000000 =	31.500000
003		5.500000 x	23.479183 =	129.135507
1474		1.000000 x	13.165427 =	13.165427
1472		1.000000 x	6.321176 =	6.321176
002		5.500000 x	17.729980 =	97.514890

T.E = 277.637000

5431	5431			
205		.070000 x	420.000000 =	29.400000
1475		1.000000 x	37.472363 =	37.472363
208		.030000 x	1,239.000000 =	37.170000
1471		1.000000 x	5.229271 =	5.229271
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860

T.E = 397.735775

5432	5432			
205		.070000 x	420.000000 =	29.400000
1475		.800000 x	37.472363 =	29.977890
1471		1.000000 x	5.229271 =	5.229271
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
380		1.000000 x	16.150000 =	16.150000

T.E = 286.802976

5436	5436				
205		.050000 x	420.000000 =	21.000000	
002		4.500000 x	17.729980 =	79.784910	
1476		1.000000 x	2.773380 =	2.773380	
003		4.500000 x	23.479183 =	105.656324	

			T.E =	209.214614	
5437	5437				
205		.065000 x	420.000000 =	27.300000	
002		5.000000 x	17.729980 =	88.649900	
003		5.000000 x	23.479183 =	117.395915	
1476		1.000000 x	2.773380 =	2.773380	

			T.E =	236.119195	
5438	5438				
205		.050000 x	420.000000 =	21.000000	
002		4.000000 x	17.729980 =	70.919920	
1476		1.000000 x	2.773380 =	2.773380	
003		4.000000 x	23.479183 =	93.916732	

			T.E =	188.610032	
5441.1	5441.1				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.773380 =	2.773380	
003		4.500000 x	23.479183 =	105.656324	
002		4.500000 x	17.729980 =	79.784910	
222.3		.004000 x	.000000 =	.000000	

			T.E =		
5441.2	5441.2				
205		.065000 x	420.000000 =	27.300000	
223.3		.004000 x	1,135.000000 =	4.540000	
002		4.500000 x	17.729980 =	79.784910	
1476		1.000000 x	2.773380 =	2.773380	
003		4.500000 x	23.479183 =	105.656324	

			T.E =	220.054614	
5441.3	5441.3				
205		.065000 x	420.000000 =	27.300000	
1476		1.000000 x	2.773380 =	2.773380	
243.1		.550000 x	2.660000 =	1.463000	
003		4.500000 x	23.479183 =	105.656324	
002		4.500000 x	17.729980 =	79.784910	

			T.E =	216.977614	

5442.1	5442.1			
205		.080000 x	420.000000 =	33.600000
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	23.479183 =	117.395915
1476		1.000000 x	2.773380 =	2.773380
002		5.000000 x	17.729980 =	88.649900

T.E =

5442.2	5442.2			
205		.080000 x	420.000000 =	33.600000
1476		1.000000 x	2.773380 =	2.773380
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
223.3		.004000 x	1,135.000000 =	4.540000

T.E =

5442.3	5442.3			246.959195
205		.080000 x	420.000000 =	33.600000
002		5.000000 x	17.729980 =	88.649900
1476		1.000000 x	2.773380 =	2.773380
003		5.000000 x	23.479183 =	117.395915
243.1		.055000 x	2.660000 =	.146300

T.E =

5443.1	5443.1			242.565495
205		.065000 x	420.000000 =	27.300000
003		4.000000 x	23.479183 =	93.916732
1476		1.000000 x	2.773380 =	2.773380
002		4.000000 x	17.729980 =	70.919920
222.3		.004000 x	.000000 =	.000000

T.E =

5443.2	5443.2			
205		.065000 x	420.000000 =	27.300000
1476		1.000000 x	2.773380 =	2.773380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
223.3		.004000 x	1,135.000000 =	4.540000

T.E =

199.450032

5443.3	5443.3			
205		.065000 x	420.000000 =	27.300000
243.1		.550000 x	2.660000 =	1.463000
002		4.000000 x	17.729980 =	70.919920
1476		1.000000 x	2.773380 =	2.773380
003		4.000000 x	23.479183 =	93.916732

T.E = 196.373032

5446.1	5446.1			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
222.2		.010000 x	.000000 =	.000000
1476		1.000000 x	2.773380 =	2.773380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920

T.E =

5446.2	5446.2			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.773380 =	2.773380
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
223.2		.010000 x	1,450.000000 =	14.500000

T.E = 200.985032

5447.1	5447.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.773380 =	2.773380
003		4.500000 x	23.479183 =	105.656324
002		4.500000 x	17.729980 =	79.784910
205		.040000 x	420.000000 =	16.800000
222.2		.010000 x	.000000 =	.000000

T.E =

5447.2	5447.2			
203.2		.025000 x	335.000000 =	8.375000
002		4.500000 x	17.729980 =	79.784910
1476		1.000000 x	2.773380 =	2.773380
003		4.500000 x	23.479183 =	105.656324
223.2		.010000 x	1,450.000000 =	14.500000
205		.040000 x	420.000000 =	16.800000

T.E = 227.889614

5448.1	5448.1			
203.2		.025000 x	335.000000 =	8.375000
1476		1.000000 x	2.773380 =	2.773380
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
205		.025000 x	420.000000 =	10.500000
222.2		.010000 x	.000000 =	.000000

T.E =

5448.2	5448.2			
203.2		.025000 x	335.000000 =	8.375000
205		.025000 x	420.000000 =	10.500000
1476		1.000000 x	2.773380 =	2.773380
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
223.2		.010000 x	1,450.000000 =	14.500000

T.E =

180.380451

5449	5449			
205		.045000 x	420.000000 =	18.900000
002		3.000000 x	17.729980 =	53.189940
1476		1.000000 x	2.773380 =	2.773380
003		3.000000 x	23.479183 =	70.437549
243.5		.850000 x	6.250000 =	5.312500

T.E =

150.613369

5451.1	5451.1			
205		.090000 x	420.000000 =	37.800000
003		5.000000 x	23.479183 =	117.395915
1476		1.000000 x	2.773380 =	2.773380
002		5.000000 x	17.729980 =	88.649900
222.3		.004000 x	.000000 =	.000000

T.E =

5451.2	5451.2			
205		.090000 x	420.000000 =	37.800000
1476		1.000000 x	2.773380 =	2.773380
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
223.3		.004000 x	1,135.000000 =	4.540000

T.E =

251.159195

5451.3	5451.3			
205		.090000 x	420.000000 =	37.800000
243.1		.550000 x	2.660000 =	1.463000
002		5.000000 x	17.729980 =	88.649900
1476		1.000000 x	2.773380 =	2.773380
003		5.000000 x	23.479183 =	117.395915

			T.E =	248.082195
5456	5456			
205		.055000 x	420.000000 =	23.100000
1478		1.000000 x	3.030250 =	3.030250
002		4.000000 x	17.729980 =	70.919920
003		4.000000 x	23.479183 =	93.916732

			T.E =	190.966902
5457	5457			
205		.085000 x	420.000000 =	35.700000
003		7.000000 x	23.479183 =	164.354281
1476		1.500000 x	2.773380 =	4.160070
002		7.000000 x	17.729980 =	124.109860
261		2.200000 x	.555400 =	1.221880

			T.E =	329.546091
5461.1	5461.1			
205		.065000 x	420.000000 =	27.300000
222.2		.010000 x	.000000 =	.000000
1479		1.000000 x	34.290329 =	34.290329
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890

			T.E =	
5461.2	5461.2			
205		.065000 x	420.000000 =	27.300000
1479		1.000000 x	34.290329 =	34.290329
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890
223.2		.010000 x	1,450.000000 =	14.500000

			T.E =	302.740726
5462.1	5462.1			
205		.065000 x	420.000000 =	27.300000
1480		1.000000 x	33.158767 =	33.158767
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890

			T.E =	

5462.2	5462.2			
205		.065000 x	420.000000 =	27.300000
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890
1480		1.000000 x	33.158767 =	33.158767
223.2		.010000 x	1,450.000000 =	14.500000

T.E = 301.609164

5463.1	5463.1			
205		.055000 x	420.000000 =	23.100000
1479		.500000 x	34.290329 =	17.145165
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880
222.2		.010000 x	.000000 =	.000000

T.E =

5463.2	5463.2			
205		.055000 x	420.000000 =	23.100000
223.2		.010000 x	1,450.000000 =	14.500000
002		6.000000 x	17.729980 =	106.379880
1479		.500000 x	34.290329 =	17.145165
003		6.000000 x	23.479183 =	140.875098

T.E = 302.000143

5464.1	5464.1			
205		.070000 x	420.000000 =	29.400000
1479		.500000 x	34.290329 =	17.145165
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860

T.E =

5464.2	5464.2			
205		.070000 x	420.000000 =	29.400000
223.2		.010000 x	1,450.000000 =	14.500000
003		7.000000 x	23.479183 =	164.354281
1479		.500000 x	34.290329 =	17.145165
002		7.000000 x	17.729980 =	124.109860

T.E = 349.509306

5465.1	5465.1			
203.2		.045000 x	335.000000 =	15.075000
1476		1.000000 x	2.773380 =	2.773380
003		5.500000 x	23.479183 =	129.135507
002		5.500000 x	17.729980 =	97.514890
222.2		.005000 x	.000000 =	.000000
208		.030000 x	1,239.000000 =	37.170000

T.E =

5465.2	5465.2			
203.2		.045000 x	335.000000 =	15.075000
002		5.500000 x	17.729980 =	97.514890
1476		1.000000 x	2.773380 =	2.773380
003		5.500000 x	23.479183 =	129.135507
223.2		.005000 x	1,450.000000 =	7.250000
208		.030000 x	1,239.000000 =	37.170000

T.E =

288.918777

5466.1	5466.1			
203.2		.025000 x	335.000000 =	8.375000
1479		.900000 x	34.290329 =	30.861296
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
222.2		.010000 x	.000000 =	.000000

T.E =

5466.2	5466.2			
203.2		.025000 x	335.000000 =	8.375000
1479		.900000 x	34.290329 =	30.861296
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900
223.2		.010000 x	1,450.000000 =	14.500000

T.E =

259.782111

5467.1	5467.1			
203.2		.013000 x	335.000000 =	4.355000
203.2		.001040 x	335.000000 =	.348400
222.2		.012000 x	.000000 =	.000000
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141
222.2		.000960 x	.000000 =	.000000

T.E =

5467.2	5467.2			
203.2		.013000 x	335.000000 =	4.355000
223.2		.000960 x	1,450.000000 =	1.392000
003		3.500000 x	23.479183 =	82.177141
002		3.500000 x	17.729980 =	62.054930
223.2		.012000 x	1,450.000000 =	17.400000
203.2		.001040 x	335.000000 =	.348400

T.E = 167.727471

5468.1	5468.1			
203.2		.025000 x	335.000000 =	8.375000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
222.2		.000800 x	.000000 =	.000000
222.2		.010000 x	.000000 =	.000000
203.2		.002000 x	335.000000 =	.670000

T.E =

5468.2	5468.2			
203.2		.025000 x	335.000000 =	8.375000
203.2		.002000 x	335.000000 =	.670000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
223.2		.000800 x	1,450.000000 =	1.160000

T.E = 189.541652

5469.1	5469.1			
203.2		.025000 x	335.000000 =	8.375000
1479		.500000 x	34.290329 =	17.145165
003		4.500000 x	23.479183 =	105.656324
002		4.500000 x	17.729980 =	79.784910
222.2		.010000 x	.000000 =	.000000

T.E =

5469.2	5469.2			
203.2		.025000 x	335.000000 =	8.375000
223.2		.010000 x	1,450.000000 =	14.500000
003		4.500000 x	23.479183 =	105.656324
1479		.500000 x	34.290329 =	17.145165
002		4.500000 x	17.729980 =	79.784910

T.E = 225.461398

5471	5471				
203.2		.035000 x	335.000000 =		11.725000
251		3.000000 x	.710000 =		2.130000
003		3.500000 x	23.479183 =		82.177141
002		3.500000 x	17.729980 =		62.054930

			T.E =		158.087071
5472.1	5472.1				
203.2		.026000 x	335.000000 =		8.710000
003		3.500000 x	23.479183 =		82.177141
002		3.500000 x	17.729980 =		62.054930
251		3.000000 x	.710000 =		2.130000
222.4		.010000 x	.000000 =		.000000

			T.E =		
5472.2	5472.2				
203.2		.026000 x	335.000000 =		8.710000
003		3.500000 x	23.479183 =		82.177141
002		3.500000 x	17.729980 =		62.054930
251		3.000000 x	.710000 =		2.130000
223.4		.010000 x	1,440.000000 =		14.400000

			T.E =		169.472071
5501.1	5501.1				
211		.040000 x	.000000 =		.000000
003		5.000000 x	23.479183 =		117.395915
002		2.500000 x	17.729980 =		44.324950
252		.100000 x	1.900000 =		.190000
251		.050000 x	.710000 =		.035500

			T.E =		
5501.2	5501.2				
212		.040000 x	1,400.000000 =		56.000000
251		.050000 x	.710000 =		.035500
252		.100000 x	1.900000 =		.190000
003		5.000000 x	23.479183 =		117.395915
002		2.500000 x	17.729980 =		44.324950

			T.E =		217.946365
5502	5502				
210		.040000 x	.000000 =		.000000
251		.050000 x	.710000 =		.035500
002		2.000000 x	17.729980 =		35.459960
003		4.000000 x	23.479183 =		93.916732
252		.100000 x	1.900000 =		.190000

			T.E =		

5511.1	5511.1			
211		.020000 x	.000000 =	.000000
003		3.200000 x	23.479183 =	75.133386
002		1.600000 x	17.729980 =	28.367968
252		.100000 x	1.900000 =	.190000

T.E =

5511.2	5511.2			
212		.020000 x	1,400.000000 =	28.000000
003		3.200000 x	23.479183 =	75.133386
002		1.600000 x	17.729980 =	28.367968
252		.100000 x	1.900000 =	.190000

T.E =

131.691354

5512	5512			
205		.020000 x	420.000000 =	8.400000
252		.100000 x	1.900000 =	.190000
002		1.500000 x	17.729980 =	26.594970
003		3.000000 x	23.479183 =	70.437549

T.E =

105.622519

5513.1	5513.1			
211		.020000 x	.000000 =	.000000
252		.100000 x	1.900000 =	.190000
003		4.000000 x	23.479183 =	93.916732
002		2.000000 x	17.729980 =	35.459960

T.E =

5513.2	5513.2			
212		.020000 x	1,400.000000 =	28.000000
252		.100000 x	1.900000 =	.190000
003		4.000000 x	23.479183 =	93.916732
002		2.000000 x	17.729980 =	35.459960

T.E =

157.566692

5514	5514			
205		.020000 x	420.000000 =	8.400000
003		3.800000 x	23.479183 =	89.220895
002		1.800000 x	17.729980 =	31.913964
252		.100000 x	1.900000 =	.190000

T.E =

129.724859

5521	5521				
205		.030000 x	420.000000 =		12.600000
252		.150000 x	1.900000 =		.285000
002		.800000 x	17.729980 =		14.183984
003		2.000000 x	23.479183 =		46.958366
				T.E =	74.027350
5531.1	5531.1				
211		.010000 x	.000000 =		.000000
252		.020000 x	1.900000 =		.038000
003		2.200000 x	23.479183 =		51.654203
002		.700000 x	17.729980 =		12.410986
				T.E =	
5531.2	5531.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.900000 =		.038000
003		2.200000 x	23.479183 =		51.654203
002		.700000 x	17.729980 =		12.410986
				T.E =	78.103189
5531.3	5531.3				
205		.010000 x	420.000000 =		4.200000
003		2.200000 x	23.479183 =		51.654203
002		.700000 x	17.729980 =		12.410986
252		.020000 x	1.900000 =		.038000
				T.E =	68.303189
5532.1	5532.1				
211		.010000 x	.000000 =		.000000
003		3.000000 x	23.479183 =		70.437549
002		1.000000 x	17.729980 =		17.729980
252		.020000 x	1.900000 =		.038000
				T.E =	
5532.2	5532.2				
212		.010000 x	1,400.000000 =		14.000000
252		.020000 x	1.900000 =		.038000
002		1.000000 x	17.729980 =		17.729980
003		3.000000 x	23.479183 =		70.437549
				T.E =	102.205529

5532.3	5532.3			
205		.010000 x	420.000000 =	4.200000
252		.020000 x	1.900000 =	.038000
003		3.000000 x	23.479183 =	70.437549
002		1.000000 x	17.729980 =	17.729980

			T.E =	92.405529
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	23.479183 =	8.217714

			T.E =	10.002714
5601	5601			
203.2		.028000 x	335.000000 =	9.380000
251		4.000000 x	.710000 =	2.840000
003		2.500000 x	23.479183 =	58.697958
002		2.500000 x	17.729980 =	44.324950

			T.E =	115.242908
5602	5602			
203.2		.018000 x	335.000000 =	6.030000
002		2.300000 x	17.729980 =	40.778954
003		2.300000 x	23.479183 =	54.002121
251		3.000000 x	.710000 =	2.130000

			T.E =	102.941075
5603	5603			
203.2		.013000 x	335.000000 =	4.355000
003		2.000000 x	23.479183 =	46.958366
002		2.000000 x	17.729980 =	35.459960
251		2.500000 x	.710000 =	1.775000

			T.E =	88.548326
5604	5604			
243.5		1.100000 x	6.250000 =	6.875000
003		2.200000 x	23.479183 =	51.654203
002		2.200000 x	17.729980 =	39.005956
243.5		.165000 x	6.250000 =	1.031250

			T.E =	98.566409

5605	5605				
243.3		1.100000 x	4.450000 =	4.895000	
243.3		.187000 x	4.450000 =	.832150	
002		2.000000 x	17.729980 =	35.459960	
003		2.000000 x	23.479183 =	46.958366	

			T.E =	88.145476	
5606	5606				
243.2		1.100000 x	3.650000 =	4.015000	
003		1.800000 x	23.479183 =	42.262529	
243.2		.220000 x	3.650000 =	.803000	
002		1.800000 x	17.729980 =	31.913964	

			T.E =	78.994493	
5607	5607				
205		.012000 x	420.000000 =	5.040000	
003		2.500000 x	23.479183 =	58.697958	
002		2.500000 x	17.729980 =	44.324950	
242		.440000 x	1.300000 =	.572000	
205		.002400 x	420.000000 =	1.008000	
242		2.200000 x	1.300000 =	2.860000	

			T.E =	112.502908	
5608.1	5608.1				
205		.012000 x	420.000000 =	5.040000	
205		.002400 x	420.000000 =	1.008000	
003		3.500000 x	23.479183 =	82.177141	
002		3.500000 x	17.729980 =	62.054930	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	

			T.E =		
5608.2	5608.2				
205		.012000 x	420.000000 =	5.040000	
205		.002400 x	420.000000 =	1.008000	
003		3.500000 x	23.479183 =	82.177141	
002		3.500000 x	17.729980 =	62.054930	
223.1		.006000 x	1,700.000000 =	10.200000	
223.1		.001200 x	1,700.000000 =	2.040000	

			T.E =	162.520071	

5611	5611			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	23.479183 =	164.354281
251		5.000000 x	.710000 =	3.550000
002		7.000000 x	17.729980 =	124.109860

			T.E =	317.214141
5612.1	5612.1			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860
251		5.000000 x	.710000 =	3.550000
222.1		.006000 x	.000000 =	.000000

			T.E =	
5612.2	5612.2			
205		.060000 x	420.000000 =	25.200000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860
251		5.000000 x	.710000 =	3.550000
223.1		.006000 x	1,700.000000 =	10.200000

			T.E =	327.414141
5613.1	5613.1			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
003		1.500000 x	23.479183 =	35.218775
002		1.500000 x	17.729980 =	26.594970
222.2		.003000 x	.000000 =	.000000

			T.E =	
5613.2	5613.2			
205		.015000 x	420.000000 =	6.300000
205		.001500 x	420.000000 =	.630000
002		1.500000 x	17.729980 =	26.594970
003		1.500000 x	23.479183 =	35.218775
223.2		.003000 x	1,450.000000 =	4.350000

			T.E =	73.093745
5614.1	5614.1			
205		.010000 x	420.000000 =	4.200000
222.2		.002000 x	.000000 =	.000000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
205		.001500 x	420.000000 =	.630000

			T.E =	

5614.2	5614.2			
205		.010000 x	420.000000 =	4.200000
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
223.2		.002000 x	1,450.000000 =	2.900000
205		.001500 x	420.000000 =	.630000

			T.E =	57.180996
5615.1	5615.1			
205		.008000 x	420.000000 =	3.360000
222.2		.000900 x	.000000 =	.000000
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
205		.001440 x	420.000000 =	.604800

			T.E =	
5615.2	5615.2			
205		.008000 x	420.000000 =	3.360000
003		1.000000 x	23.479183 =	23.479183
205		.001440 x	420.000000 =	.604800
002		1.000000 x	17.729980 =	17.729980
223.2		.000900 x	1,450.000000 =	1.305000

			T.E =	46.478963
5616	5616			
205		.003000 x	420.000000 =	1.260000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
205		.007500 x	420.000000 =	3.150000

			T.E =	45.619163
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
521		.250000 x	2.390000 =	.597500

			T.E =	46.206663
5619	5619			
205		.001400 x	420.000000 =	.588000
003		.200000 x	23.479183 =	4.695837

			T.E =	5.283837

5620	5620			
203.2		.012000 x	335.000000 =	4.020000
251		.020000 x	.710000 =	.014200
003		.300000 x	23.479183 =	7.043755
002		.300000 x	17.729980 =	5.318994
220		4.200000 x	.000000 =	.000000

T.E =

5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.710000 =	11.360000
003		30.000000 x	23.479183 =	704.375490
002		30.000000 x	17.729980 =	531.899400

T.E =

5622	5622			
211		1.100000 x	.000000 =	.000000
003		30.000000 x	23.479183 =	704.375490
002		30.000000 x	17.729980 =	531.899400
251		16.000000 x	.710000 =	11.360000

T.E =

5626	5626			
205		.030000 x	420.000000 =	12.600000
003		1.500000 x	23.479183 =	35.218775
002		1.500000 x	17.729980 =	26.594970
251		1.000000 x	.710000 =	.710000

T.E = 75.123745

6101	6101			
267		1.050000 x	.821500 =	.862575
003		.050000 x	23.479183 =	1.173959

T.E = 2.036534

6102	6102			
252		.050000 x	1.900000 =	.095000
267		1.030000 x	.821500 =	.846145
003		.060000 x	23.479183 =	1.408751

T.E = 2.349896

6103	6103			
268		1.050000 x	.956500 =	1.004325
003		.050000 x	23.479183 =	1.173959

T.E = 2.178284

6104	6104			
252		.050000 x	1.900000 =	.095000
003		.060000 x	23.479183 =	1.408751
268		1.030000 x	.956500 =	.985195

			T.E =	2.488946
6111	6111			
266		1.100000 x	.623000 =	.685300
003		.150000 x	23.479183 =	3.521877

			T.E =	4.207177
6116	6116			
280		1.050000 x	1.000000 =	1.050000
003		.100000 x	23.479183 =	2.347918

			T.E =	3.397918
6117	6117			
281		1.050000 x	5.780000 =	6.069000
003		.150000 x	23.479183 =	3.521877

			T.E =	9.590877
6118	6118			
266		1.150000 x	.623000 =	.716450
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	8.958283
6119	6119			
293		1.100000 x	.000000 =	.000000
003		.150000 x	23.479183 =	3.521877

			T.E =	
6120	6120			
289		1.050000 x	.707000 =	.742350
003		.100000 x	23.479183 =	2.347918

			T.E =	3.090268
6121	6121			
266		1.100000 x	.623000 =	.685300
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	8.927133

6122	6122				
265		1.050000 x	.741500 =	.778575	
003		.200000 x	23.479183 =	4.695837	

				T.E =	5.474412
6123	6123				
265		.900000 x	.741500 =	.667350	
002		.150000 x	17.729980 =	2.659497	
003		.150000 x	23.479183 =	3.521877	
265		.090000 x	.741500 =	.066735	
266		.010000 x	.623000 =	.006230	
266		.100000 x	.623000 =	.062300	

				T.E =	6.983989
6126	6126				
265		1.250000 x	.741500 =	.926875	
003		.200000 x	23.479183 =	4.695837	
003		.200000 x	23.479183 =	4.695837	

				T.E =	10.318548
6127	6127				
290		4.800000 x	3.300000 =	15.840000	
002		.800000 x	17.729980 =	14.183984	
003		.800000 x	23.479183 =	18.783346	

				T.E =	48.807330
6128	6128				
290		1.200000 x	3.300000 =	3.960000	
002		.200000 x	17.729980 =	3.545996	
003		.200000 x	23.479183 =	4.695837	

				T.E =	12.201833
6201	6201				
264		1.400000 x	1.135500 =	1.589700	
003		.250000 x	23.479183 =	5.869796	
002		.250000 x	17.729980 =	4.432495	

				T.E =	11.891991
6202	6202				
264		1.300000 x	1.135500 =	1.476150	
002		.200000 x	17.729980 =	3.545996	
003		.200000 x	23.479183 =	4.695837	

				T.E =	9.717983

6203	6203			
282		1.200000 x	.821500 =	.985800
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	15.409007
6204	6204			
282		1.300000 x	.821500 =	1.067950
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	17.551615
6205	6205			
277		1.250000 x	.846500 =	1.058125
003		.500000 x	23.479183 =	11.739592
002		.500000 x	17.729980 =	8.864990

			T.E =	21.662707
6221	6221			
265		1.150000 x	.741500 =	.852725
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

			T.E =	9.094558
6222	6222			
265		1.200000 x	.741500 =	.889800
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	15.313007
6223	6223			
265		1.250000 x	.741500 =	.926875
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	21.531457
6224	6224			
271		.720000 x	.827500 =	.595800
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
282		.480000 x	.821500 =	.394320

			T.E =	9.231953

6225	6225			
271		.720000 x	.827500 =	.595800
003		.250000 x	23.479183 =	5.869796
282		.480000 x	.821500 =	.394320
002		.250000 x	17.729980 =	4.432495

			T.E =	11.292411
6226	6226			
265		1.200000 x	.741500 =	.889800
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986

			T.E =	29.736214
6227	6227			
265		1.250000 x	.741500 =	.926875
003		.850000 x	23.479183 =	19.957306
002		.850000 x	17.729980 =	15.070483

			T.E =	35.954664
6228	6228			
282		1.250000 x	.821500 =	1.026875
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	17.510540
6229	6229			
282		1.250000 x	.821500 =	1.026875
003		.450000 x	23.479183 =	10.565632
002		.450000 x	17.729980 =	7.978491

			T.E =	19.570998
6230	6230			
277		1.100000 x	.846500 =	.931150
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	21.535732
6231	6231			
265		1.150000 x	.741500 =	.852725
002		.250000 x	17.729980 =	4.432495
003		.250000 x	23.479183 =	5.869796

			T.E =	11.155016

6232	6232			
265		1.150000 x	.741500 =	.852725
003		.400000 x	23.479183 =	9.391673
002		.400000 x	17.729980 =	7.091992

			T.E =	17.336390
6236	6236			
253		.500000 x	2.350000 =	1.175000
266		2.000000 x	.623000 =	1.246000
386		.350000 x	28.630000 =	10.020500
390		2.100000 x	1.500000 =	3.150000
003		1.800000 x	23.479183 =	42.262529
002		1.800000 x	17.729980 =	31.913964
565.3		.350000 x	3.060000 =	1.071000
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
276		5.850000 x	.580400 =	3.395340
272		1.500000 x	.742000 =	1.113000

			T.E =	121.177333
6237	6237			
253		.850000 x	2.350000 =	1.997500
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920
565.5		.350000 x	4.530000 =	1.585500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.742000 =	3.710000
266		2.100000 x	.623000 =	1.308300
260		9.500000 x	.536700 =	5.098650

			T.E =	214.387102
6238	6238			
253		.400000 x	2.350000 =	.940000
265		6.000000 x	.741500 =	4.449000
266		13.000000 x	.623000 =	8.099000
003		5.000000 x	23.479183 =	117.395915
002		5.000000 x	17.729980 =	88.649900

			T.E =	219.533815
6239	6239			
277		1.100000 x	.846500 =	.931150
002		.300000 x	17.729980 =	5.318994
003		.300000 x	23.479183 =	7.043755

			T.E =	13.293899

6301	6301			
266		1.250000 x	.623000 =	.778750
002		.400000 x	17.729980 =	7.091992
003		.400000 x	23.479183 =	9.391673

			T.E =	17.262415
6302	6302			
266		9.000000 x	.623000 =	5.607000
002		3.500000 x	17.729980 =	62.054930
003		3.500000 x	23.479183 =	82.177141

			T.E =	149.839071
6401	6401			
265		1.150000 x	.741500 =	.852725
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

			T.E =	9.094558
6402	6402			
265		1.200000 x	.741500 =	.889800
002		.300000 x	17.729980 =	5.318994
003		.300000 x	23.479183 =	7.043755

			T.E =	13.252549
6403	6403			
265		1.250000 x	.741500 =	.926875
002		.350000 x	17.729980 =	6.205493
003		.350000 x	23.479183 =	8.217714

			T.E =	15.350082
6406	6406			
265		1.200000 x	.741500 =	.889800
002		.600000 x	17.729980 =	10.637988
003		.600000 x	23.479183 =	14.087510

			T.E =	25.615298
6407	6407			
265		1.250000 x	.741500 =	.926875
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986

			T.E =	29.773289

6411	6411				
565.3		1.650000 x	3.060000 =	5.049000	
002		.350000 x	17.729980 =	6.205493	
003		.350000 x	23.479183 =	8.217714	

			T.E =	19.472207	
6412	6412				
565.5		1.550000 x	4.530000 =	7.021500	
002		.450000 x	17.729980 =	7.978491	
003		.450000 x	23.479183 =	10.565632	

			T.E =	25.565623	
6413	6413				
565.6		1.450000 x	6.290000 =	9.120500	
002		.550000 x	17.729980 =	9.751489	
003		.550000 x	23.479183 =	12.913551	

			T.E =	31.785540	
6416	6416				
566.3		1.600000 x	4.090000 =	6.544000	
003		.350000 x	23.479183 =	8.217714	
002		.350000 x	17.729980 =	6.205493	

			T.E =	20.967207	
6417	6417				
566.5		1.500000 x	6.240000 =	9.360000	
002		.450000 x	17.729980 =	7.978491	
003		.450000 x	23.479183 =	10.565632	

			T.E =	27.904123	
6418	6418				
566.6		1.400000 x	8.330000 =	11.662000	
003		.550000 x	23.479183 =	12.913551	
002		.550000 x	17.729980 =	9.751489	

			T.E =	34.327040	
6421	6421				
565.3		1.050000 x	3.060000 =	3.213000	
003		.400000 x	23.479183 =	9.391673	

			T.E =	12.604673	

6422	6422				
565.5		1.050000 x	4.530000 =	4.756500	
003		.500000 x	23.479183 =	11.739592	

			T.E =	16.496092	
6423	6423				
565.6		1.050000 x	6.290000 =	6.604500	
003		.600000 x	23.479183 =	14.087510	

			T.E =	20.692010	
6426	6426				
566.3		1.050000 x	4.090000 =	4.294500	
003		.400000 x	23.479183 =	9.391673	

			T.E =	13.686173	
6427	6427				
566.5		1.050000 x	6.240000 =	6.552000	
003		.500000 x	23.479183 =	11.739592	

			T.E =	18.291592	
6428	6428				
566.6		1.050000 x	8.330000 =	8.746500	
003		.600000 x	23.479183 =	14.087510	

			T.E =	22.834010	
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	23.479183 =	3.521877	

			T.E =	7.481877	
6432	6432				
251		.100000 x	.710000 =	.071000	
003		.250000 x	23.479183 =	5.869796	
279		1.080000 x	3.720000 =	4.017600	
002		.250000 x	17.729980 =	4.432495	

			T.E =	14.390891	
6441	6441				
266		1.100000 x	.623000 =	.685300	
002		.100000 x	17.729980 =	1.772998	
003		.100000 x	23.479183 =	2.347918	

			T.E =	4.806216	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	23.479183 =	.939167

			T.E =	
6446.2	6446.2			
285		1.100000 x	.062500 =	.068750
003		.040000 x	23.479183 =	.939167

			T.E =	1.007917
6447	6447			
251		.050000 x	.710000 =	.035500
003		.100000 x	23.479183 =	2.347918
002		.100000 x	17.729980 =	1.772998
286		1.050000 x	1.674600 =	1.758330

			T.E =	5.914746
6448	6448			
251		.050000 x	.710000 =	.035500
003		.100000 x	23.479183 =	2.347918
002		.100000 x	17.729980 =	1.772998
288		1.050000 x	1.817600 =	1.908480

			T.E =	6.064896
6501	6501			
282		3.000000 x	.821500 =	2.464500
295		11.000000 x	5.649200 =	62.141200
296		1.000000 x	11.781900 =	11.781900
003		4.000000 x	23.479183 =	93.916732
002		4.000000 x	17.729980 =	70.919920

			T.E =	241.224252
6502	6502			
002		1.500000 x	17.729980 =	26.594970
003		1.500000 x	23.479183 =	35.218775
6501		1.000000 x	241.224252 =	241.224252

			T.E =	303.037997
6503	6503			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		.950000 x	241.224252 =	229.163039

			T.E =	282.734951

6504	6504			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.910000 x	241.224252 =	219.514069

			T.E =	268.965065
6505	6505			
002		1.000000 x	17.729980 =	17.729980
6501		.870000 x	241.224252 =	209.865099
003		1.000000 x	23.479183 =	23.479183

			T.E =	251.074262
6506	6506			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		.810000 x	241.224252 =	195.391644

			T.E =	236.600807
6507	6507			
002		.900000 x	17.729980 =	15.956982
003		.900000 x	23.479183 =	21.131265
6501		.920000 x	241.224252 =	221.926312

			T.E =	259.014559
6508	6508			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.030000 x	241.224252 =	248.460980

			T.E =	302.032891
6509	6509			
002		1.000000 x	17.729980 =	17.729980
6501		1.010000 x	241.224252 =	243.636495
003		1.000000 x	23.479183 =	23.479183

			T.E =	284.845658
6510	6510			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.080000 x	241.224252 =	260.522192

			T.E =	309.973188

6511	6511			
002		1.500000 x	17.729980 =	26.594970
003		1.500000 x	23.479183 =	35.218775
6501		.920000 x	241.224252 =	221.926312

			T.E =	283.740056
6512	6512			
002		1.400000 x	17.729980 =	24.821972
003		1.400000 x	23.479183 =	32.870856
6501		.820000 x	241.224252 =	197.803887

			T.E =	255.496715
6513	6513			
002		1.300000 x	17.729980 =	23.048974
6501		.780000 x	241.224252 =	188.154917
003		1.300000 x	23.479183 =	30.522938

			T.E =	241.726828
6514	6514			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.760000 x	241.224252 =	183.330432

			T.E =	232.781427
6515	6515			
002		1.000000 x	17.729980 =	17.729980
003		1.000000 x	23.479183 =	23.479183
6501		.800000 x	241.224252 =	192.979402

			T.E =	234.188565
6516	6516			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.220000 x	241.224252 =	294.293587

			T.E =	347.865499
6517	6517			
002		1.200000 x	17.729980 =	21.275976
6501		1.120000 x	241.224252 =	270.171162
003		1.200000 x	23.479183 =	28.175020

			T.E =	319.622158

6518	6518			
002		1.100000 x	17.729980 =	19.502978
003		1.100000 x	23.479183 =	25.827101
6501		.670000 x	241.224252 =	161.620249

			T.E =	206.950328
6519	6519			
002		1.300000 x	17.729980 =	23.048974
003		1.300000 x	23.479183 =	30.522938
6501		1.280000 x	241.224252 =	308.767043

			T.E =	362.338954
6520	6520			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.120000 x	241.224252 =	270.171162

			T.E =	319.622158
6521	6521			
002		1.300000 x	17.729980 =	23.048974
6501		1.210000 x	241.224252 =	291.881345
003		1.300000 x	23.479183 =	30.522938

			T.E =	345.453257
6522	6522			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.190000 x	241.224252 =	287.056860

			T.E =	336.507855
6523	6523			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		1.280000 x	241.224252 =	308.767043

			T.E =	358.218038
6524	6524			
002		1.200000 x	17.729980 =	21.275976
003		1.200000 x	23.479183 =	28.175020
6501		.800000 x	241.224252 =	192.979402

			T.E =	242.430397

6525	6525				
002		1.200000 x	17.729980 =	21.275976	
6501		1.040000 x	241.224252 =	250.873222	
003		1.200000 x	23.479183 =	28.175020	

			T.E =	300.324218	
6526	6526				
002		1.300000 x	17.729980 =	23.048974	
003		1.300000 x	23.479183 =	30.522938	
6501		.900000 x	241.224252 =	217.101827	

			T.E =	270.673739	
6527	6527				
002		1.300000 x	17.729980 =	23.048974	
003		1.300000 x	23.479183 =	30.522938	
6501		1.120000 x	241.224252 =	270.171162	

			T.E =	323.743074	
6528	6528				
002		1.200000 x	17.729980 =	21.275976	
003		1.200000 x	23.479183 =	28.175020	
6501		.840000 x	241.224252 =	202.628372	

			T.E =	252.079367	
6529	6529				
002		1.200000 x	17.729980 =	21.275976	
6501		1.080000 x	241.224252 =	260.522192	
003		1.200000 x	23.479183 =	28.175020	

			T.E =	309.973188	
6530	6530				
002		1.000000 x	17.729980 =	17.729980	
6501		.710000 x	241.224252 =	171.269219	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	212.478382	
6531	6531				
002		.600000 x	17.729980 =	10.637988	
003		.600000 x	23.479183 =	14.087510	
6501		.480000 x	241.224252 =	115.787641	

			T.E =	140.513139	

6532	6532				
294		6.000000 x	3.099000 =	18.594000	
294		.300000 x	3.099000 =	.929700	
002		2.500000 x	17.729980 =	44.324950	
003		2.500000 x	23.479183 =	58.697958	
296		1.000000 x	11.781900 =	11.781900	

			T.E =	134.328508	
6541	6541				
282		.350000 x	.821500 =	.287525	
295		1.050000 x	5.649200 =	5.931660	
003		.500000 x	23.479183 =	11.739592	
002		.500000 x	17.729980 =	8.864990	
296		.120000 x	11.781900 =	1.413828	

			T.E =	28.237595	
6542	6542				
295		1.050000 x	5.649200 =	5.931660	
003		.800000 x	23.479183 =	18.783346	
002		.800000 x	17.729980 =	14.183984	
296		.100000 x	11.781900 =	1.178190	

			T.E =	40.077180	
6543	6543				
295		.400000 x	5.649200 =	2.259680	
003		.200000 x	23.479183 =	4.695837	
296		.130000 x	11.781900 =	1.531647	

			T.E =	8.487164	
7101	7101				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	60.956500 =	.609565	
003		.850000 x	23.479183 =	19.957306	
002		.500000 x	17.729980 =	8.864990	

			T.E =	29.576861	
7102	7102				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	60.956500 =	.609565	
003		.700000 x	23.479183 =	16.435428	
002		.400000 x	17.729980 =	7.091992	

			T.E =	24.281985	

7103	7103				
201		.000500 x	290.000000 =	.145000	
002		.300000 x	17.729980 =	5.318994	
003		.600000 x	23.479183 =	14.087510	
1445		.004000 x	60.956500 =	.243826	

			T.E =	19.795330	
7104	7104				
201		.000500 x	290.000000 =	.145000	
003		1.000000 x	23.479183 =	23.479183	
1445		.008000 x	60.956500 =	.487652	
002		.600000 x	17.729980 =	10.637988	

			T.E =	34.749823	
7111	7111				
201		.000500 x	290.000000 =	.145000	
003		.600000 x	23.479183 =	14.087510	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.951934 =	4.785580	

			T.E =	19.808221	
7116	7116				
201		.000500 x	290.000000 =	.145000	
1418		.027000 x	41.286750 =	1.114742	
003		.650000 x	23.479183 =	15.261469	
001		.350000 x	15.951934 =	5.583177	

			T.E =	22.104388	
7121	7121				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	60.956500 =	1.645826	
003		.800000 x	23.479183 =	18.783346	
001		.300000 x	15.951934 =	4.785580	

			T.E =	25.359752	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	74.687500 =	2.016563	
001		.300000 x	15.951934 =	4.785580	
003		.800000 x	23.479183 =	18.783346	

			T.E =	25.730489	

7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	84.531250 =		1.267969
1446		.006000 x	52.110500 =		.312663
001		.300000 x	15.951934 =		4.785580
1445		.006000 x	60.956500 =		.365739
003		.900000 x	23.479183 =		21.131265
				T.E =	28.008216
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	15.951934 =		4.785580
1445		.012000 x	60.956500 =		.731478
1465		.015000 x	95.610150 =		1.434152
003		.900000 x	23.479183 =		21.131265
				T.E =	28.227475
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	93.355950 =		1.400339
1445		.012000 x	60.956500 =		.731478
003		.900000 x	23.479183 =		21.131265
001		.300000 x	15.951934 =		4.785580
				T.E =	28.193662
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	88.096150 =		1.321442
1445		.012000 x	60.956500 =		.731478
001		.300000 x	15.951934 =		4.785580
003		.900000 x	23.479183 =		21.131265
				T.E =	28.114765
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	29.264100 =		.614546
1426		.006000 x	163.556250 =		.981338
001		.300000 x	15.951934 =		4.785580
003		.600000 x	23.479183 =		14.087510
				T.E =	20.613974

7132	7132				
201		.000500 x	290.000000 =	.145000	
1427		.006000 x	174.074700 =	1.044448	
1418		.021000 x	41.286750 =	.867022	
001		.350000 x	15.951934 =	5.583177	
003		.650000 x	23.479183 =	15.261469	

			T.E =	22.901116	
7133	7133				
201		.000500 x	290.000000 =	.145000	
1463		.015000 x	71.937750 =	1.079066	
1427		.006000 x	174.074700 =	1.044448	
1418		.006000 x	41.286750 =	.247721	
003		.600000 x	23.479183 =	14.087510	
001		.350000 x	15.951934 =	5.583177	

			T.E =	22.186922	
7134	7134				
201		.000500 x	290.000000 =	.145000	
001		.350000 x	15.951934 =	5.583177	
003		.600000 x	23.479183 =	14.087510	
1464		.015000 x	57.951600 =	.869274	
1427		.006000 x	174.074700 =	1.044448	
1418		.006000 x	41.286750 =	.247721	

			T.E =	21.977129	
7136	7136				
201		.000500 x	290.000000 =	.145000	
001		.250000 x	15.951934 =	3.987984	
1418		.017000 x	41.286750 =	.701875	
003		.400000 x	23.479183 =	9.391673	

			T.E =	14.226531	
7138	7138				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.951934 =	4.785580	
1418		.027000 x	41.286750 =	1.114742	
003		.800000 x	23.479183 =	18.783346	

			T.E =	24.828669	
7141	7141				
201		.000500 x	290.000000 =	.145000	
1445		.027000 x	60.956500 =	1.645826	
003		1.000000 x	23.479183 =	23.479183	
001		.400000 x	15.951934 =	6.380774	

			T.E =	31.650782	

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
001		.350000 x	15.951934 =	5.583177
003		.650000 x	23.479183 =	15.261469

T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	163.556250 =	1.144894
1421		.016000 x	.000000 =	.000000
001		.350000 x	15.951934 =	5.583177
1413		.007000 x	29.264100 =	.204849
003		.650000 x	23.479183 =	15.261469

T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1413		.014000 x	29.264100 =	.409697
001		.450000 x	15.951934 =	7.178370
1422		.016000 x	.000000 =	.000000
003		.600000 x	23.479183 =	14.087510

T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	163.556250 =	1.144894
1422		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849
003		.600000 x	23.479183 =	14.087510
001		.450000 x	15.951934 =	7.178370

T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
1418		.014000 x	41.286750 =	.578015
003		.650000 x	23.479183 =	15.261469
001		.350000 x	15.951934 =	5.583177

T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.951934 =	5.583177
1427		.007000 x	174.074700 =	1.218523
1422		.016000 x	.000000 =	.000000
1418		.007000 x	41.286750 =	.289007
003		.650000 x	23.479183 =	15.261469

T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.951934 =	7.178370
1447		.014000 x	58.155900 =	.814183
1448		.016000 x	.000000 =	.000000
003		.700000 x	23.479183 =	16.435428

T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.951934 =	7.178370
1448		.016000 x	.000000 =	.000000
1447		.007000 x	58.155900 =	.407091
1426		.007000 x	163.556250 =	1.144894
003		.700000 x	23.479183 =	16.435428

T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1453		.020000 x	172.407750 =	3.448155
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	23.479183 =	37.566693
002		1.600000 x	17.729980 =	28.367968
001		.600000 x	15.951934 =	9.571160

T.E = 80.527019

7162	7162			
201		.000800 x	290.000000 =	.232000
001		.600000 x	15.951934 =	9.571160
002		1.600000 x	17.729980 =	28.367968
1458		.020000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.600000 x	23.479183 =	37.566693

T.E =

7163	7163				
201		.000800 x	290.000000 =		.232000
1454		.020000 x	195.897750 =		3.917955
1445		.022000 x	60.956500 =		1.341043
001		.600000 x	15.951934 =		9.571160
003		1.600000 x	23.479183 =		37.566693
002		1.600000 x	17.729980 =		28.367968

			T.E =		80.996819
7164	7164				
201		.000800 x	290.000000 =		.232000
001		.600000 x	15.951934 =		9.571160
003		1.600000 x	23.479183 =		37.566693
1455		.020000 x	.000000 =		.000000
1445		.022000 x	60.956500 =		1.341043
002		1.600000 x	17.729980 =		28.367968

			T.E =		
7165	7165				
201		.000800 x	290.000000 =		.232000
1459		.020000 x	218.337750 =		4.366755
1445		.022000 x	60.956500 =		1.341043
003		1.600000 x	23.479183 =		37.566693
002		1.600000 x	17.729980 =		28.367968
001		.600000 x	15.951934 =		9.571160

			T.E =		81.445619
7166	7166				
201		.000800 x	290.000000 =		.232000
001		.500000 x	15.951934 =		7.975967
003		1.200000 x	23.479183 =		28.175020
1445		.022000 x	60.956500 =		1.341043
1453		.017000 x	172.407750 =		2.930932
002		1.200000 x	17.729980 =		21.275976

			T.E =		61.930937
7167	7167				
201		.000800 x	290.000000 =		.232000
001		.500000 x	15.951934 =		7.975967
1458		.017000 x	.000000 =		.000000
1445		.022000 x	60.956500 =		1.341043
003		1.200000 x	23.479183 =		28.175020
002		1.200000 x	17.729980 =		21.275976

			T.E =		

7168	7168			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.951934 =	7.975967
1454		.017000 x	195.897750 =	3.330262
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976

			T.E =	62.330267
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	60.956500 =	1.341043
003		1.200000 x	23.479183 =	28.175020
002		1.200000 x	17.729980 =	21.275976
001		.500000 x	15.951934 =	7.975967

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
003		1.200000 x	23.479183 =	28.175020
1459		.017000 x	218.337750 =	3.711742
1445		.022000 x	60.956500 =	1.341043
002		1.200000 x	17.729980 =	21.275976
001		.500000 x	15.951934 =	7.975967

			T.E =	62.711747
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.951934 =	1.595193

			T.E =	1.798193
7176	7176			
003		1.500000 x	23.479183 =	35.218775

			T.E =	35.218775
7177	7177			
003		1.100000 x	23.479183 =	25.827101

			T.E =	25.827101
7178	7178			
003		.900000 x	23.479183 =	21.131265

			T.E =	21.131265

7179	7179			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592
7181	7181			
003		.700000 x	23.479183 =	16.435428

			T.E =	16.435428
7206	7206			
142		26.000000 x	.325000 =	8.450000
1412		.040000 x	27.931800 =	1.117272
002		.300000 x	17.729980 =	5.318994
003		.600000 x	23.479183 =	14.087510

			T.E =	28.973776
7207	7207			
142		26.000000 x	.325000 =	8.450000
1412		.020000 x	27.931800 =	.558636
003		.500000 x	23.479183 =	11.739592
002		.250000 x	17.729980 =	4.432495

			T.E =	25.180723
7208	7208			
142		26.000000 x	.325000 =	8.450000
003		.400000 x	23.479183 =	9.391673
1412		.025000 x	27.931800 =	.698295
002		.200000 x	17.729980 =	3.545996

			T.E =	22.085964
7209	7209			
142		26.000000 x	.325000 =	8.450000
1412		.005000 x	27.931800 =	.139659
003		.300000 x	23.479183 =	7.043755
002		.150000 x	17.729980 =	2.659497

			T.E =	18.292911
7211	7211			
146		15.000000 x	.340000 =	5.100000
1445		.001000 x	60.956500 =	.060957
003		.400000 x	23.479183 =	9.391673
002		.200000 x	17.729980 =	3.545996
283		.075000 x	1.000100 =	.075008

			T.E =	18.173633

7221	7221				
203.2		.001500 x	335.000000 =		.502500
003		.200000 x	23.479183 =		4.695837
254		.020000 x	2.780000 =		.055600
002		.150000 x	17.729980 =		2.659497
506		1.150000 x	1.100000 =		1.265000
492		.200000 x	.480000 =		.096000
				T.E =	9.274434
7222	7222				
254		.050000 x	2.780000 =		.139000
003		.250000 x	23.479183 =		5.869796
002		.150000 x	17.729980 =		2.659497
506		1.200000 x	1.100000 =		1.320000
492		.200000 x	.480000 =		.096000
				T.E =	10.084293
7223	7223				
254		.050000 x	2.780000 =		.139000
493		.200000 x	.660000 =		.132000
002		.200000 x	17.729980 =		3.545996
003		.200000 x	23.479183 =		4.695837
508		1.200000 x	.860000 =		1.032000
				T.E =	9.544833
7231	7231				
274		1.200000 x	1.146500 =		1.375800
003		.250000 x	23.479183 =		5.869796
002		.250000 x	17.729980 =		4.432495
274		.200000 x	1.146500 =		.229300
				T.E =	11.907391
7241	7241				
297.2		.051072 x	.000000 =		.000000
495		.500000 x	.000000 =		.000000
002		1.400000 x	17.729980 =		24.821972
003		1.400000 x	23.479183 =		32.870856
001		.200000 x	15.951934 =		3.190387
				T.E =	

7242	7242			
297.2		.057000 x	.000000 =	.000000
495		1.000000 x	.000000 =	.000000
003		2.800000 x	23.479183 =	65.741712
002		2.800000 x	17.729980 =	49.643944
001		.200000 x	15.951934 =	3.190387

T.E =

7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996
251		1.300000 x	.710000 =	.923000

T.E =

7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
251		1.300000 x	.710000 =	.923000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837

T.E =

7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
251		1.300000 x	.710000 =	.923000
003		.200000 x	23.479183 =	4.695837
002		.200000 x	17.729980 =	3.545996

T.E =

7244	7244			
251		1.200000 x	.710000 =	.852000
273		1.200000 x	.936500 =	1.123800
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980

T.E =

7245	7245			43.184963
251		.500000 x	.710000 =	.355000
003		.700000 x	23.479183 =	16.435428
002		.700000 x	17.729980 =	12.410986
273		1.200000 x	.936500 =	1.123800

T.E =

30.325214

7246	7246			
265		.500000 x	.741500 =	.370750
003		1.000000 x	23.479183 =	23.479183
002		1.000000 x	17.729980 =	17.729980
298.1		6.700000 x	3.570000 =	23.919000

			T.E =	65.498913
7301	7301			
096		1.050000 x	.000000 =	.000000
1444		.001500 x	74.687500 =	.112031
1445		.025000 x	60.956500 =	1.523913
003		.900000 x	23.479183 =	21.131265
001		.400000 x	15.951934 =	6.380774

			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
1445		.025000 x	60.956500 =	1.523913
1444		.002000 x	74.687500 =	.149375
003		1.000000 x	23.479183 =	23.479183
001		.500000 x	15.951934 =	7.975967

			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
001		1.000000 x	15.951934 =	15.951934
003		2.000000 x	23.479183 =	46.958366
1445		.025000 x	60.956500 =	1.523913
1444		.001000 x	74.687500 =	.074688

			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	60.956500 =	1.523913
001		.800000 x	15.951934 =	12.761547
1444		.001500 x	74.687500 =	.112031
003		1.600000 x	23.479183 =	37.566693

			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
001		.150000 x	15.951934 =	2.392790
1444		.000200 x	74.687500 =	.014938
1445		.004000 x	60.956500 =	.243826
003		.300000 x	23.479183 =	7.043755

			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1445		.005000 x	60.956500 =	.304783
1417		.033000 x	39.954450 =	1.318497
003		2.200000 x	23.479183 =	51.654203
001		.600000 x	15.951934 =	9.571160

			T.E =	
7312	7312			
099		1.050000 x	.000000 =	.000000
001		.500000 x	15.951934 =	7.975967
003		1.100000 x	23.479183 =	25.827101
1417		.033000 x	39.954450 =	1.318497
1445		.005000 x	60.956500 =	.304783

			T.E =	
7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.951934 =	6.380774
1417		.022000 x	39.954450 =	.878998
1445		.004000 x	60.956500 =	.243826
003		.900000 x	23.479183 =	21.131265

			T.E =	
7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.951934 =	7.975967
1449		.030000 x	52.690700 =	1.580721
003		2.500000 x	23.479183 =	58.697958

			T.E =	
7315	7315			
155		1.050000 x	2.481600 =	2.605680
1449		.004000 x	52.690700 =	.210763
003		.300000 x	23.479183 =	7.043755
001		.100000 x	15.951934 =	1.595193

			T.E =	11.455391
7316	7316			
161		1.050000 x	7.120000 =	7.476000
1449		.025000 x	52.690700 =	1.317268
1444		.002000 x	74.687500 =	.149375
001		.300000 x	15.951934 =	4.785580
003		.600000 x	23.479183 =	14.087510

			T.E =	27.815733

7317	7317			
163		1.050000 x	7.310000 =	7.675500
1449		.025000 x	52.690700 =	1.317268
001		.300000 x	15.951934 =	4.785580
1444		.001500 x	74.687500 =	.112031
003		.800000 x	23.479183 =	18.783346

T.E = 32.673725

7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	74.687500 =	.074688
001		.100000 x	15.951934 =	1.595193
1449		.025000 x	52.690700 =	1.317268
003		1.300000 x	23.479183 =	30.522938

T.E =

7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	52.690700 =	1.317268
1444		.001000 x	74.687500 =	.074688
003		1.300000 x	23.479183 =	30.522938
001		.100000 x	15.951934 =	1.595193

T.E =

7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	23.479183 =	35.218775
1449		.025000 x	52.690700 =	1.317268
1444		.001000 x	74.687500 =	.074688
001		.400000 x	15.951934 =	6.380774

T.E =

7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	74.687500 =	.074688
1449		.025000 x	52.690700 =	1.317268
003		1.500000 x	23.479183 =	35.218775
001		.400000 x	15.951934 =	6.380774

T.E =

7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	52.690700 =	.105381
1444		.000100 x	74.687500 =	.007469
003		.200000 x	23.479183 =	4.695837
001		.040000 x	15.951934 =	.638077

T.E =

7326.1	7326.1			
029		.200000 x	.149900 =	.029980
173		48.000000 x	.281700 =	13.521600
003		3.000000 x	23.479183 =	70.437549
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
001		.500000 x	15.951934 =	7.975967

T.E =

93.392348

7326.2	7326.2			
029		.200000 x	.149900 =	.029980
174		48.000000 x	.000000 =	.000000
1449		.020000 x	52.690700 =	1.053814
1444		.005000 x	74.687500 =	.373438
003		3.000000 x	23.479183 =	70.437549
001		.500000 x	15.951934 =	7.975967

T.E =

7327	7327			
029		.200000 x	.149900 =	.029980
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	23.479183 =	93.916732
001		.600000 x	15.951934 =	9.571160
175		95.000000 x	.000000 =	.000000

T.E =

7328.1	7328.1			
029		.300000 x	.149900 =	.044970
171		108.000000 x	.000000 =	.000000
001		.700000 x	15.951934 =	11.166354
1449		.020000 x	52.690700 =	1.053814
1444		.007000 x	74.687500 =	.522813
003		4.000000 x	23.479183 =	93.916732

T.E =

7328.2

7328.2

029	.300000 x	.149900 =	.044970
1449	.020000 x	52.690700 =	1.053814
1444	.007000 x	74.687500 =	.522813
172	108.000000 x	.000000 =	.000000
003	4.000000 x	23.479183 =	93.916732
001	.700000 x	15.951934 =	11.166354

T.E =

7331

7331

029	1.500000 x	.149900 =	.224850
169	54.000000 x	.000000 =	.000000
003	3.500000 x	23.479183 =	82.177141
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
001	.500000 x	15.951934 =	7.975967

T.E =

7332

7332

029	2.000000 x	.149900 =	.299800
1449	.020000 x	52.690700 =	1.053814
1444	.005000 x	74.687500 =	.373438
003	4.500000 x	23.479183 =	105.656324
001	.800000 x	15.951934 =	12.761547
170	108.000000 x	.000000 =	.000000

T.E =

7333

7333

029	.300000 x	.149900 =	.044970
167	1.050000 x	.000000 =	.000000
003	2.500000 x	23.479183 =	58.697958
002	.500000 x	17.729980 =	8.864990
1449	.020000 x	52.690700 =	1.053814

T.E =

7334

7334

029	.300000 x	.149900 =	.044970
168	1.050000 x	.000000 =	.000000
003	3.000000 x	23.479183 =	70.437549
002	.600000 x	17.729980 =	10.637988
1449	.020000 x	52.690700 =	1.053814

T.E =

7335	7335				
001		.450000 x	15.951934 =	7.178370	
1444		.007000 x	74.687500 =	.522813	
1445		.026000 x	60.956500 =	1.584869	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	32.765235	
7336	7336				
001		.400000 x	15.951934 =	6.380774	
1445		.022000 x	60.956500 =	1.341043	
1444		.006000 x	74.687500 =	.448125	
003		.900000 x	23.479183 =	21.131265	

			T.E =	29.301206	
7337	7337				
001		.350000 x	15.951934 =	5.583177	
003		.800000 x	23.479183 =	18.783346	
1445		.017000 x	60.956500 =	1.036261	
1444		.005000 x	74.687500 =	.373438	

			T.E =	25.776221	
7338	7338				
026		.500000 x	.097700 =	.048850	
001		.300000 x	15.951934 =	4.785580	
1445		.017000 x	60.956500 =	1.036261	
003		.700000 x	23.479183 =	16.435428	

			T.E =	22.306119	
7340	7340				
289		1.100000 x	.707000 =	.777700	
001		.400000 x	15.951934 =	6.380774	
1445		.026000 x	60.956500 =	1.584869	
1444		.007000 x	74.687500 =	.522813	
003		1.100000 x	23.479183 =	25.827101	

			T.E =	35.093256	
7341	7341				
003		.200000 x	23.479183 =	4.695837	
1441		.003000 x	26.561000 =	.079683	

			T.E =	4.775520	
7346	7346				
003		.200000 x	23.479183 =	4.695837	

			T.E =	4.695837	

7347	7347				
001		.200000 x	15.951934 =	3.190387	
003		.500000 x	23.479183 =	11.739592	
1445		.009000 x	60.956500 =	.548609	
1444		.002000 x	74.687500 =	.149375	

			T.E =	15.627962	
7351	7351				
001		.200000 x	15.951934 =	3.190387	
003		.600000 x	23.479183 =	14.087510	
1444		.009000 x	74.687500 =	.672188	

			T.E =	17.950084	
7352	7352				
001		.200000 x	15.951934 =	3.190387	
1444		.012000 x	74.687500 =	.896250	
003		.700000 x	23.479183 =	16.435428	

			T.E =	20.522065	
7355	7355				
001		.150000 x	15.951934 =	2.392790	
003		.600000 x	23.479183 =	14.087510	
1444		.008000 x	74.687500 =	.597500	

			T.E =	17.077800	
7356	7356				
001		.100000 x	15.951934 =	1.595193	
003		.550000 x	23.479183 =	12.913551	
1444		.007000 x	74.687500 =	.522813	

			T.E =	15.031557	
7357	7357				
001		.050000 x	15.951934 =	.797597	
1444		.006000 x	74.687500 =	.448125	
003		.500000 x	23.479183 =	11.739592	

			T.E =	12.985313	
7359	7359				
021		.100000 x	2.670000 =	.267000	
026		20.000000 x	.097700 =	1.954000	
003		.900000 x	23.479183 =	21.131265	
002		.900000 x	17.729980 =	15.956982	
065		.040000 x	13.610000 =	.544400	

			T.E =	39.853647	

7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.097700 =	1.270100
065		.027000 x	13.610000 =	.367470
002		.700000 x	17.729980 =	12.410986
003		.700000 x	23.479183 =	16.435428

			T.E =	30.617484
7361	7361			
021		.050000 x	2.670000 =	.133500
065		.015000 x	13.610000 =	.204150
346.1		30.000000 x	.059000 =	1.770000
003		1.400000 x	23.479183 =	32.870856
002		1.000000 x	17.729980 =	17.729980
026		14.000000 x	.097700 =	1.367800

			T.E =	54.076286
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	23.479183 =	32.870856
002		1.000000 x	17.729980 =	17.729980
348		8.000000 x	.106800 =	.854400
346.1		22.000000 x	.059000 =	1.298000
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	54.458686
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	23.479183 =	32.870856
002		1.000000 x	17.729980 =	17.729980
348		8.000000 x	.106800 =	.854400
346.2		22.000000 x	.106800 =	2.349600
065		.015000 x	13.610000 =	.204150
026		14.000000 x	.097700 =	1.367800

			T.E =	55.510286
7363	7363			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.097700 =	1.660900
065		.020000 x	13.610000 =	.272200
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
346.1		35.000000 x	.059000 =	2.065000

			T.E =	62.974269

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
346.1		24.000000 x	.059000 =	1.416000
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
348		11.000000 x	.106800 =	1.174800
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.097700 =	1.660900

			T.E =	63.500069
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	23.479183 =	37.566693
002		1.200000 x	17.729980 =	21.275976
348		11.000000 x	.106800 =	1.174800
346.2		24.000000 x	.106800 =	2.563200
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.097700 =	1.660900

			T.E =	64.647269
7366	7366			
021		.050000 x	2.670000 =	.133500
026		10.000000 x	.097700 =	.977000
003		3.000000 x	23.479183 =	70.437549
1446		.010000 x	52.110500 =	.521105
002		2.000000 x	17.729980 =	35.459960
346.1		45.000000 x	.059000 =	2.655000

			T.E =	110.184114
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.110500 =	.521105
003		3.000000 x	23.479183 =	70.437549
002		2.000000 x	17.729980 =	35.459960
348		15.000000 x	.106800 =	1.602000
346.1		30.000000 x	.059000 =	1.770000
026		10.000000 x	.097700 =	.977000

			T.E =	110.901114
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
346.2		30.000000 x	.106800 =	3.204000
348		15.000000 x	.106800 =	1.602000
003		3.000000 x	23.479183 =	70.437549
1446		.010000 x	52.110500 =	.521105
002		2.000000 x	17.729980 =	35.459960
026		10.000000 x	.097700 =	.977000

			T.E =	112.335114

7371.1	7371.1						
026	-	14.000000 x	.097700 =	-	1.367800		
7361		1.000000 x	54.076286 =		54.076286		
029		14.000000 x	.149900 =		2.098600		

						T.E =	54.807086
7371.2	7371.2						
026	-	14.000000 x	.097700 =	-	1.367800		
028		14.000000 x	.000000 =		.000000		
7361		1.000000 x	54.076286 =		54.076286		

						T.E =	
7372.1	7372.1						
026	-	14.000000 x	.097700 =	-	1.367800		
029		14.000000 x	.149900 =		2.098600		
7362.1		1.000000 x	54.458686 =		54.458686		

						T.E =	55.189486
7372.2	7372.2						
026	-	14.000000 x	.097700 =	-	1.367800		
028		14.000000 x	.000000 =		.000000		
7362.1		1.000000 x	54.458686 =		54.458686		

						T.E =	
7372.3	7372.3						
026	-	14.000000 x	.097700 =	-	1.367800		
7362.2		1.000000 x	55.510286 =		55.510286		
029		14.000000 x	.149900 =		2.098600		

						T.E =	56.241086
7372.4	7372.4						
026	-	14.000000 x	.097700 =	-	1.367800		
028		14.000000 x	.000000 =		.000000		
7362.2		1.000000 x	55.510286 =		55.510286		

						T.E =	
7373.1	7373.1						
026	-	17.000000 x	.097700 =	-	1.660900		
029		17.000000 x	.149900 =		2.548300		
7363		1.000000 x	62.974269 =		62.974269		

						T.E =	63.861669

7373.2	7373.2					
026	-	17.000000 x	.097700 =	-	1.660900	
028		17.000000 x	.000000 =		.000000	
7363		1.000000 x	62.974269 =		62.974269	

						T.E =
7374.1	7374.1					
026	-	17.000000 x	.097700 =	-	1.660900	
7364.1		1.000000 x	63.500069 =		63.500069	
029		17.000000 x	.149900 =		2.548300	

						T.E =
7374.2	7374.2					64.387469
026	-	17.000000 x	.097700 =	-	1.660900	
028		17.000000 x	.000000 =		.000000	
7364.1		1.000000 x	63.500069 =		63.500069	

						T.E =
7374.3	7374.3					
026	-	17.000000 x	.097700 =	-	1.660900	
029		17.000000 x	.149900 =		2.548300	
7364.2		1.000000 x	64.647269 =		64.647269	

						T.E =
7374.4	7374.4					65.534669
026	-	17.000000 x	.097700 =	-	1.660900	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	64.647269 =		64.647269	

						T.E =
7376.1	7376.1					
026	-	10.000000 x	.097700 =	-	.977000	
7366		1.000000 x	110.184114 =		110.184114	
029		10.000000 x	.149900 =		1.499000	

						T.E =
7376.2	7376.2					110.706114
026	-	10.000000 x	.097700 =	-	.977000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	110.184114 =		110.184114	

						T.E =

7377.1	7377.1				
026	-	10.000000 x	.097700 =	-	.977000
7367.1		1.000000 x	110.901114 =		110.901114
029		10.000000 x	.149900 =		1.499000

			T.E =		111.423114
7377.2	7377.2				
026	-	10.000000 x	.097700 =	-	.977000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	110.901114 =		110.901114

			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.097700 =	-	.977000
029		10.000000 x	.149900 =		1.499000
7367.2		1.000000 x	112.335114 =		112.335114

			T.E =		112.857114
7377.4	7377.4				
026	-	10.000000 x	.097700 =	-	.977000
7367.2		1.000000 x	112.335114 =		112.335114
028		10.000000 x	.000000 =		.000000

			T.E =		
7381	7381				
456		.100000 x	1.610000 =		.161000

			T.E =		.161000
7382	7382				
443		.150000 x	1.930000 =		.289500
447		.050000 x	4.393700 =		.219685
003		.300000 x	23.479183 =		7.043755

			T.E =		7.552940
7383	7383				
002		.250000 x	17.729980 =		4.432495
003		.150000 x	23.479183 =		3.521877

			T.E =		7.954372
7384	7384				
003		.500000 x	23.479183 =		11.739592

			T.E =		11.739592

7385	7385			
003		.500000 x	23.479183 =	11.739592

			T.E =	11.739592
7386	7386			
003		.600000 x	23.479183 =	14.087510

			T.E =	14.087510
7387	7387			
261		1.500000 x	.555400 =	.833100
003		1.000000 x	23.479183 =	23.479183
7361		1.100000 x	54.076286 =	59.483915

			T.E =	83.796198
7388	7388			
003		2.500000 x	23.479183 =	58.697958
7361		.600000 x	54.076286 =	32.445772

			T.E =	91.143729
7389.1.1	7389.1.1			
7371.1		.300000 x	54.807086 =	16.442126

			T.E =	16.442126
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	65.534669 =	19.660401

			T.E =	19.660401
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	55.189486 =	16.556846

			T.E =	16.556846
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	56.241086 =	16.872326

			T.E =	16.872326
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	63.861669 =	19.158501

			T.E =	19.158501
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	64.387469 =	19.316241

			T.E =	19.316241
7389.2.1	7389.2.1			
7371.1		.500000 x	54.807086 =	27.403543

			T.E =	27.403543
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	65.534669 =	32.767335

			T.E =	32.767335

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	55.189486 =	27.594743

			T.E =	27.594743
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	56.241086 =	28.120543

			T.E =	28.120543
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	63.861669 =	31.930835

			T.E =	31.930835
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	64.387469 =	32.193735

			T.E =	32.193735
7391	7391			
003		.250000 x	23.479183 =	5.869796

			T.E =	5.869796

7392	7392				
298.1		1.081080 x	3.570000 =	3.859456	
003		.400000 x	23.479183 =	9.391673	

			T.E =	13.251129	
7393	7393				
294		.347760 x	3.099000 =	1.077708	
003		.300000 x	23.479183 =	7.043755	

			T.E =	8.121463	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	23.479183 =	9.391673	

			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	23.479183 =	7.043755	

			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.729980 =	6.205493	
003		.350000 x	23.479183 =	8.217714	

			T.E =	23.423207	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	23.479183 =	16.435428	

			T.E =	25.060428	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.729980 =	7.091992	
003		.400000 x	23.479183 =	9.391673	

			T.E =	24.872465	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	23.479183 =	5.869796	

			T.E =	7.409796	

ΑΤΟΕ	1ο Τρίμηνο του 2009	Σελ. Ημ/νία	162 19/05/2010
7416	7416		
003	.800000 x	23.479183 =	18.783346

		T.E =	18.783346
7417	7417		
003	1.800000 x	23.479183 =	42.262529

		T.E =	42.262529
7418	7418		
003	2.600000 x	23.479183 =	61.045876

		T.E =	61.045876
7419	7419		
003	.800000 x	23.479183 =	18.783346

		T.E =	18.783346
7420	7420		
003	1.200000 x	23.479183 =	28.175020

		T.E =	28.175020
7421	7421		
003	.800000 x	23.479183 =	18.783346

		T.E =	18.783346
7422	7422		
003	.350000 x	23.479183 =	8.217714

		T.E =	8.217714
7431	7431		
332	1.150000 x	88.540000 =	101.821000
003	4.000000 x	23.479183 =	93.916732
1444	.001000 x	74.687500 =	.074688
1445	.020000 x	60.956500 =	1.219130

		T.E =	197.031550
7432	7432		
331	1.150000 x	85.390000 =	98.198500
1444	.001000 x	74.687500 =	.074688
1445	.020000 x	60.956500 =	1.219130
003	4.400000 x	23.479183 =	103.308405

		T.E =	202.800723

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	60.956500 =	1.219130	
003		5.100000 x	23.479183 =	119.743833	
1444		.001000 x	74.687500 =	.074688	

			T.E =	219.236151	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.100000 x	23.479183 =	143.223016	

			T.E =	242.715334	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
003		4.200000 x	23.479183 =	98.612569	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	206.643886	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
003		4.600000 x	23.479183 =	108.004242	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	

			T.E =	216.035559	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.300000 x	23.479183 =	124.439670	

			T.E =	232.470987	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.300000 x	23.479183 =	147.918853	

			T.E =	255.950170	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
003		4.500000 x	23.479183 =	105.656324	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
			T.E =	249.515641	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
003		4.900000 x	23.479183 =	115.047997	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
			T.E =	258.907314	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		5.600000 x	23.479183 =	131.483425	
			T.E =	275.342742	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.600000 x	23.479183 =	154.962608	
			T.E =	298.821925	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
003		4.900000 x	23.479183 =	115.047997	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
			T.E =	271.304314	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
003		5.300000 x	23.479183 =	124.439670	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
			T.E =	280.695987	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		6.000000 x	23.479183 =	140.875098	

			T.E =	297.131416	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	60.956500 =	1.219130	
1444		.001000 x	74.687500 =	.074688	
003		7.000000 x	23.479183 =	164.354281	

			T.E =	320.610599	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		.915000 x	23.479183 =	21.483452	

			T.E =	31.432684	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
003		.945000 x	23.479183 =	22.187828	
1444		.000100 x	74.687500 =	.007469	
1445		.002000 x	60.956500 =	.121913	

			T.E =	32.990960	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		.990000 x	23.479183 =	23.244391	

			T.E =	37.630323	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		1.050000 x	23.479183 =	24.653142	

			T.E =	40.278774	

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734
003		.488000 x	23.479183 =	11.457841

			T.E =	16.432457
7497	7497			
331		.062500 x	85.390000 =	5.336875
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734
003		.504000 x	23.479183 =	11.833508

			T.E =	17.235074
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	23.479183 =	12.397009
1444		.000050 x	74.687500 =	.003734
1445		.001000 x	60.956500 =	.060957

			T.E =	19.589974
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	23.479183 =	13.148342
1445		.001000 x	60.956500 =	.060957
1444		.000050 x	74.687500 =	.003734

			T.E =	20.961158
7501	7501			
7433		1.000000 x	219.236151 =	219.236151

			T.E =	219.236151
7503	7503			
7443		1.000000 x	232.470987 =	232.470987

			T.E =	232.470987
7506	7506			
7453		1.000000 x	275.342742 =	275.342742

			T.E =	275.342742
7508	7508			
7463		1.000000 x	297.131416 =	297.131416

			T.E =	297.131416

7511	7511				
331		.115000 x	85.390000 =	9.819850	
003		.915000 x	23.479183 =	21.483452	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	

			T.E =	31.432684	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	60.956500 =	.121913	
1444		.000100 x	74.687500 =	.007469	
003		.945000 x	23.479183 =	22.187828	

			T.E =	32.990960	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	23.479183 =	133.831343	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	233.248973	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	23.479183 =	112.700078	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	212.117708	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
003		6.100000 x	23.479183 =	143.223016	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	251.179646	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	60.956500 =	1.219130	
003		5.000000 x	23.479183 =	117.395915	

			T.E =	225.352545	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
1445		.020000 x	60.956500 =	1.219130	
003		5.200000 x	23.479183 =	122.091752	

			T.E =	225.131882	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	60.956500 =	1.219130	
003		5.400000 x	23.479183 =	126.787588	

			T.E =	238.681718	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	23.479183 =	133.831343	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	287.804973	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	23.479183 =	143.223016	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	310.479646	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
1445		.010000 x	60.956500 =	.609565	
003		3.000000 x	23.479183 =	70.437549	

			T.E =	110.896114	
7537	7537				
336		.300000 x	.000000 =	.000000	
003		4.000000 x	23.479183 =	93.916732	
1445		.010000 x	60.956500 =	.609565	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
1445		.010000 x	60.956500 =	.609565	
003		3.700000 x	23.479183 =	86.872977	

			T.E =	149.024842	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
1445		.010000 x	60.956500 =	.609565	
003		4.200000 x	23.479183 =	98.612569	
336		.350000 x	.000000 =	.000000	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
003		4.800000 x	23.479183 =	112.700078
1445		.010000 x	60.956500 =	.609565
338		.350000 x	.000000 =	.000000

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	292.866911
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	23.479183 =	164.354281
1445		.020000 x	60.956500 =	1.219130

			T.E =	311.048411
7554	7554			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	339.825277
7556	7556			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	60.956500 =	1.219130
003		9.000000 x	23.479183 =	211.312647

			T.E =	358.006777

7558	7558				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	60.956500 =	.182870	
003		1.500000 x	23.479183 =	35.218775	

			T.E =	42.232844	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	23.479183 =	35.218775	
1445		.003000 x	60.956500 =	.182870	

			T.E =	42.232844	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	23.479183 =	122.091752	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	225.131882	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
1445		.020000 x	60.956500 =	1.219130	
003		5.700000 x	23.479183 =	133.831343	

			T.E =	287.804973	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	60.956500 =	1.219130	
003		5.400000 x	23.479183 =	126.787588	

			T.E =	238.681718	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	23.479183 =	143.223016	
1445		.020000 x	60.956500 =	1.219130	

			T.E =	310.479646	
7565	7565				
003		1.500000 x	23.479183 =	35.218775	

			T.E =	35.218775	
7566	7566				
7561		1.500000 x	225.131882 =	337.697823	

			T.E =	337.697823	

7567	7567			
7562		1.500000 x	287.804973 =	431.707460

			T.E =	431.707460
7568	7568			
7563		1.500000 x	238.681718 =	358.022577

			T.E =	358.022577
7569	7569			
7564		1.500000 x	310.479646 =	465.719469

			T.E =	465.719469
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	23.479183 =	70.437549

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	23.479183 =	70.437549
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	23.479183 =	70.437549

			T.E =	272.987049
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	23.479183 =	93.916732
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	23.479183 =	89.220895

			T.E =	187.419395

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	23.479183 =	98.612569	
			T.E =	251.367069	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	23.479183 =	110.352160	
			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	139.248411 =	2.784968	
1445		.005000 x	60.956500 =	.304783	
003		2.300000 x	23.479183 =	54.002121	
			T.E =	123.798372	
7601	7601				
401		1.100000 x	13.560000 =	14.916000	
457		.500000 x	.803800 =	.401900	
003		.500000 x	23.479183 =	11.739592	
			T.E =	27.057492	
7602	7602				
403		1.100000 x	15.880000 =	17.468000	
457		.500000 x	.803800 =	.401900	
003		.550000 x	23.479183 =	12.913551	
			T.E =	30.783451	
7603	7603				
406		1.100000 x	19.630000 =	21.593000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	23.479183 =	15.261469	
			T.E =	37.256369	
7604.1	7604.1				
409		1.100000 x	23.370000 =	25.707000	
003		.750000 x	23.479183 =	17.609387	
457		.500000 x	.803800 =	.401900	
			T.E =	43.718287	

7604.2	7604.2			
410		1.100000 x	31.790000 =	34.969000
003		.750000 x	23.479183 =	17.609387
457		.500000 x	.803800 =	.401900

			T.E =	52.980287
7606	7606			
401		1.100000 x	13.560000 =	14.916000
003		.600000 x	23.479183 =	14.087510

			T.E =	29.003510
7607	7607			
403		1.100000 x	15.880000 =	17.468000
003		.650000 x	23.479183 =	15.261469

			T.E =	32.729469
7608	7608			
406		1.100000 x	19.630000 =	21.593000
003		.750000 x	23.479183 =	17.609387

			T.E =	39.202387
7609.1	7609.1			
409		1.100000 x	23.370000 =	25.707000
003		.850000 x	23.479183 =	19.957306

			T.E =	45.664306
7609.2	7609.2			
410		1.100000 x	31.790000 =	34.969000
003		.850000 x	23.479183 =	19.957306

			T.E =	54.926306
7611	7611			
411		1.100000 x	29.680000 =	32.648000
457		.500000 x	.803800 =	.401900
003		.500000 x	23.479183 =	11.739592

			T.E =	44.789492
7612	7612			
412		1.100000 x	32.030000 =	35.233000
003		.550000 x	23.479183 =	12.913551
457		.500000 x	.803800 =	.401900

			T.E =	48.548451

7613	7613				
411		1.100000 x	29.680000 =	32.648000	
003		.600000 x	23.479183 =	14.087510	

				T.E =	46.735510
7614	7614				
412		1.100000 x	32.030000 =	35.233000	
003		.650000 x	23.479183 =	15.261469	

				T.E =	50.494469
7616	7616				
414		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.600000 x	23.479183 =	14.087510	

				T.E =	40.196410
7617	7617				
415		1.100000 x	23.370000 =	25.707000	
457		.500000 x	.803800 =	.401900	
003		.650000 x	23.479183 =	15.261469	

				T.E =	41.370369
7618	7618				
414		1.100000 x	23.370000 =	25.707000	
003		.700000 x	23.479183 =	16.435428	

				T.E =	42.142428
7619	7619				
415		1.100000 x	23.370000 =	25.707000	
003		.750000 x	23.479183 =	17.609387	

				T.E =	43.316387
7621	7621				
418		1.100000 x	32.720000 =	35.992000	
457		.800000 x	.803800 =	.643040	
003		1.200000 x	23.479183 =	28.175020	

				T.E =	64.810060
7622	7622				
419		1.100000 x	32.720000 =	35.992000	
003		1.400000 x	23.479183 =	32.870856	
457		.800000 x	.803800 =	.643040	

				T.E =	69.505896

7626.1	7626.1			
298.2		18.000000 x	3.110000 =	55.980000
421		1.000000 x	108.710000 =	108.710000
002		7.000000 x	17.729980 =	124.109860
003		7.000000 x	23.479183 =	164.354281

			T.E =	453.154141
7626.2	7626.2			
298.2		18.000000 x	3.110000 =	55.980000
422		1.000000 x	149.410000 =	149.410000
003		7.000000 x	23.479183 =	164.354281
002		7.000000 x	17.729980 =	124.109860

			T.E =	493.854141
7627.1	7627.1			
298.2		16.000000 x	3.110000 =	49.760000
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880
421		1.000000 x	108.710000 =	108.710000

			T.E =	405.724978
7627.2	7627.2			
298.2		16.000000 x	3.110000 =	49.760000
003		6.000000 x	23.479183 =	140.875098
002		6.000000 x	17.729980 =	106.379880
422		1.000000 x	149.410000 =	149.410000

			T.E =	446.424978
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	23.479183 =	1.173959

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	23.479183 =	1.408751

			T.E =	6.237751
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	23.479183 =	1.878335

			T.E =	7.807335

7638	7638			
430		1.100000 x	7.480000 =	8.228000
003		.100000 x	23.479183 =	2.347918

			T.E =	10.575918
7641	7641			
431		1.000000 x	.000000 =	.000000
003		.060000 x	23.479183 =	1.408751

			T.E =	
7642	7642			
432		1.000000 x	.000000 =	.000000
003		.060000 x	23.479183 =	1.408751

			T.E =	
7701	7701			
024		.001500 x	50.000000 =	.075000
002		.050000 x	17.729980 =	.886499
003		.120000 x	23.479183 =	2.817502

			T.E =	3.779001
7702	7702			
024		.001800 x	50.000000 =	.090000
003		.080000 x	23.479183 =	1.878335
002		.050000 x	17.729980 =	.886499

			T.E =	2.854834
7706	7706			
024		.002000 x	50.000000 =	.100000
003		.150000 x	23.479183 =	3.521877
002		.080000 x	17.729980 =	1.418398

			T.E =	5.040276
7707	7707			
024		.002300 x	50.000000 =	.115000
003		.090000 x	23.479183 =	2.113126
002		.100000 x	17.729980 =	1.772998

			T.E =	4.001124

7708	7708			
024		.002500 x	50.000000 =	.125000
003		.180000 x	23.479183 =	4.226253
002		.120000 x	17.729980 =	2.127598

			T.E =	6.478851
7709	7709			
024		.002800 x	50.000000 =	.140000
003		.120000 x	23.479183 =	2.817502
002		.150000 x	17.729980 =	2.659497

			T.E =	5.616999
7711	7711			
002		.050000 x	17.729980 =	.886499
1485		.200000 x	.831094 =	.166219
003		.200000 x	23.479183 =	4.695837

			T.E =	5.748554
7712	7712			
002		.080000 x	17.729980 =	1.418398
1485		.250000 x	.831094 =	.207774
003		.250000 x	23.479183 =	5.869796

			T.E =	7.495968
7713	7713			
002		.160000 x	17.729980 =	2.836797
003		.300000 x	23.479183 =	7.043755
1485		.280000 x	.831094 =	.232706

			T.E =	10.113258
7720	7720			
443		.080000 x	1.930000 =	.154400
003		.300000 x	23.479183 =	7.043755
002		.100000 x	17.729980 =	1.772998
1485		.200000 x	.831094 =	.166219

			T.E =	9.137372
7721	7721			
002		.070000 x	17.729980 =	1.241099
003		.200000 x	23.479183 =	4.695837
1485		.200000 x	.831094 =	.166219

			T.E =	6.103154

7722.1.1	7722.1.1			
7720		.300000 x	9.137372 =	2.741212

			T.E =	2.741212
7722.1.2	7722.1.2			
7721		.300000 x	6.103154 =	1.830946

			T.E =	1.830946
7722.2.1	7722.2.1			
7720		.400000 x	9.137372 =	3.654949

			T.E =	3.654949
7722.2.2	7722.2.2			
7721		.400000 x	6.103154 =	2.441262

			T.E =	2.441262
7725	7725			
471		.300000 x	4.100000 =	1.230000
003		.250000 x	23.479183 =	5.869796
002		.150000 x	17.729980 =	2.659497

			T.E =	9.759293
7735	7735			
441		.350000 x	.075500 =	.026425
444		.150000 x	2.143200 =	.321480
003		.150000 x	23.479183 =	3.521877

			T.E =	3.869782
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
445		.010000 x	1.553500 =	.015535
003		.250000 x	23.479183 =	5.869796
446		.005000 x	2.540000 =	.012700

			T.E =	6.117953
7737	7737			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.869385 =	.173877
003		.300000 x	23.479183 =	7.043755
1488		.600000 x	.760865 =	.456519

			T.E =	7.689251

7738	7738			
441		.200000 x	.075500 =	.015100
1489		.200000 x	.869385 =	.173877
1488		.300000 x	.760865 =	.228260
003		.300000 x	23.479183 =	7.043755

			T.E =	7.460991
7739	7739			
441		.100000 x	.075500 =	.007550
467		.100000 x	3.380000 =	.338000
003		.150000 x	23.479183 =	3.521877

			T.E =	3.867427
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	23.479183 =	5.869796
1492		.250000 x	2.756980 =	.689245

			T.E =	6.588616
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	23.479183 =	5.869796

			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
003		.200000 x	23.479183 =	4.695837
463		.125000 x	3.970000 =	.496250

			T.E =	5.221662
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	23.479183 =	3.521877
464		.125000 x	3.720000 =	.465000

			T.E =	4.016452
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	23.479183 =	3.521877
465		.125000 x	5.870000 =	.733750

			T.E =	4.285202

7745	7745			
442		.250000 x	.118300 =	.029575
1492		.250000 x	2.756980 =	.689245
003		.800000 x	23.479183 =	18.783346
1489		.200000 x	.869385 =	.173877

			T.E =	19.676043
7746	7746			
441		.350000 x	.075500 =	.026425
003		.150000 x	23.479183 =	3.521877
443		.090000 x	1.930000 =	.173700

			T.E =	3.722002
7747	7747			
441		.350000 x	.075500 =	.026425
443		.170000 x	1.930000 =	.328100
003		.250000 x	23.479183 =	5.869796

			T.E =	6.224321
7748	7748			
443		.090000 x	1.930000 =	.173700
002		.100000 x	17.729980 =	1.772998
445		.030000 x	1.553500 =	.046605
003		.200000 x	23.479183 =	4.695837
450		.060000 x	2.760000 =	.165600

			T.E =	6.854740
7749	7749			
443		.160000 x	1.930000 =	.308800
445		.050000 x	1.553500 =	.077675
003		.250000 x	23.479183 =	5.869796
002		.150000 x	17.729980 =	2.659497
450		.100000 x	2.760000 =	.276000

			T.E =	9.191768
7751	7751			
003		.150000 x	23.479183 =	3.521877
1491		.125000 x	1.488894 =	.186112

			T.E =	3.707989
7752	7752			
003		.250000 x	23.479183 =	5.869796
1491		.250000 x	1.488894 =	.372224

			T.E =	6.242019

7753	7753				
441		1.000000 x	.075500 =	.075500	
003		.650000 x	23.479183 =	15.261469	
443		.080000 x	1.930000 =	.154400	
1491		.200000 x	1.488894 =	.297779	
1490		.090000 x	1.546426 =	.139178	

			T.E =	15.928326	
7754	7754				
441		.800000 x	.075500 =	.060400	
1487		.090000 x	.604686 =	.054422	
003		.800000 x	23.479183 =	18.783346	
1490		.090000 x	1.546426 =	.139178	
1491		.200000 x	1.488894 =	.297779	

			T.E =	19.335125	
7755	7755				
442		.250000 x	.118300 =	.029575	
003		1.000000 x	23.479183 =	23.479183	
1491		.200000 x	1.488894 =	.297779	
1492		.160000 x	2.756980 =	.441117	

			T.E =	24.247654	
7756	7756				
442		.300000 x	.118300 =	.035490	
003		.350000 x	23.479183 =	8.217714	
1492		.300000 x	2.756980 =	.827094	

			T.E =	9.080298	
7761	7761				
441		.650000 x	.075500 =	.049075	
1489		.200000 x	.869385 =	.173877	
1488		.600000 x	.760865 =	.456519	
003		.800000 x	23.479183 =	18.783346	
467		.100000 x	3.380000 =	.338000	
473		.100000 x	2.750000 =	.275000	

			T.E =	20.075817	
7762	7762				
473		.100000 x	2.750000 =	.275000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	4.970837	

7764	7764				
474		.125000 x	3.770000 =		.471250
003		.100000 x	23.479183 =		2.347918

			T.E =		2.819168
7765	7765				
475		.125000 x	6.230000 =		.778750
003		.200000 x	23.479183 =		4.695837

			T.E =		5.474587
7766	7766				
442		.275000 x	.118300 =		.032533
473		.110000 x	2.750000 =		.302500
1492		.275000 x	2.756980 =		.758170
003		.880000 x	23.479183 =		20.661681

			T.E =		21.754883
7767.1	7767.1				
7755		.150000 x	24.247654 =		3.637148

			T.E =		3.637148
7767.2	7767.2				
442		.250000 x	.118300 =		.029575
1492		.160000 x	2.756980 =		.441117
003		1.000000 x	23.479183 =		23.479183
473		.200000 x	2.750000 =		.550000

			AΘΡΟΙΣΜΑ =		24.499875
	T.E =	.150000 x	24.499875 =		3.674981

7767.3	7767.3				
7755		.250000 x	24.247654 =		6.061914

			T.E =		6.061914
7767.4	7767.4				
442		.250000 x	.118300 =		.029575
473		.200000 x	2.750000 =		.550000
003		1.000000 x	23.479183 =		23.479183
1492		.160000 x	2.756980 =		.441117

			AΘΡΟΙΣΜΑ =		24.499875
	T.E =	.250000 x	24.499875 =		6.124969

7767.5	7767.5			
7755		.350000 x	24.247654 =	8.486679

			T.E =	8.486679
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
003		1.000000 x	23.479183 =	23.479183
1492		.160000 x	2.756980 =	.441117
473		.200000 x	2.750000 =	.550000

			AΘΡΟΙΣΜΑ =	24.499875
	T.E =	.350000 x	24.499875 =	8.574956

7767.7	7767.7			
7755		.450000 x	24.247654 =	10.911444

			T.E =	10.911444
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	23.479183 =	23.479183

			AΘΡΟΙΣΜΑ =	24.499875
	T.E =	.450000 x	24.499875 =	11.024944

7768	7768			
460		.200000 x	4.250000 =	.850000
003		.450000 x	23.479183 =	10.565632
460		.030000 x	4.250000 =	.127500
002		.450000 x	17.729980 =	7.978491

			T.E =	19.521623
7769	7769			
460		.200000 x	4.250000 =	.850000
002		.200000 x	17.729980 =	3.545996
003		.200000 x	23.479183 =	4.695837
460		.030000 x	4.250000 =	.127500

			T.E =	9.219333
7770	7770			
460		.090000 x	4.250000 =	.382500
003		.150000 x	23.479183 =	3.521877
002		.150000 x	17.729980 =	2.659497
460		.020000 x	4.250000 =	.085000

			T.E =	6.648874

7771	7771				
441		1.000000 x	.075500 =	.075500	
1488		.160000 x	.760865 =	.121738	
1487		.080000 x	.604686 =	.048375	
003		1.300000 x	23.479183 =	30.522938	
473		.100000 x	2.750000 =	.275000	
467		.110000 x	3.380000 =	.371800	

			T.E =	31.415351	
7772	7772				
441		1.000000 x	.075500 =	.075500	
458		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.500000 x	23.479183 =	11.739592	

			T.E =	12.511092	
7773	7773				
441		1.000000 x	.075500 =	.075500	
459		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	
003		.600000 x	23.479183 =	14.087510	

			T.E =	14.859010	
7774	7774				
442		.250000 x	.118300 =	.029575	
473		.200000 x	2.750000 =	.550000	
1492		.160000 x	2.756980 =	.441117	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	24.499875	
7785.1	7785.1				
441		.350000 x	.075500 =	.026425	
003		.700000 x	23.479183 =	16.435428	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.366400 =	.283968	

			T.E =		
7785.2	7785.2				
441		.350000 x	.075500 =	.026425	
476		.120000 x	2.366400 =	.283968	
478		.160000 x	2.937600 =	.470016	
003		.700000 x	23.479183 =	16.435428	

			T.E =	17.215837	

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.869385 =	.173877
003		1.000000 x	23.479183 =	23.479183
1488		.600000 x	.760865 =	.456519
477		.110000 x	.000000 =	.000000

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.869385 =	.173877
1488		.600000 x	.760865 =	.456519
003		1.000000 x	23.479183 =	23.479183
478		.110000 x	2.937600 =	.323136

			T.E =	24.459140
7787	7787			
441		1.000000 x	.075500 =	.075500
476		.090000 x	2.366400 =	.212976
1488		.160000 x	.760865 =	.121738
1487		.080000 x	.604686 =	.048375
003		1.000000 x	23.479183 =	23.479183
477		.160000 x	.000000 =	.000000

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
479		1.000000 x	1.815600 =	1.815600
003		.700000 x	23.479183 =	16.435428

			T.E =	18.269903
7791	7791			
441		1.000000 x	.075500 =	.075500
1487		.050000 x	.604686 =	.030234
1491		.200000 x	1.488894 =	.297779
003		.500000 x	23.479183 =	11.739592

			T.E =	12.143105
7792	7792			
482		.150000 x	.786500 =	.117975
003		.500000 x	23.479183 =	11.739592

			T.E =	11.857567

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	23.479183 =	4.695837	

			T.E =	6.378837	
7794	7794				
482		.150000 x	.786500 =	.117975	
003		.500000 x	23.479183 =	11.739592	

			T.E =	11.857567	
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	17.729980 =	1.063799	

			T.E =	1.208799	
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	17.729980 =	1.241099	

			T.E =	1.415099	
7801	7801				
496		1.200000 x	1.006100 =	1.207320	
003		.150000 x	23.479183 =	3.521877	

			T.E =	4.729197	
7806	7806				
498		1.150000 x	1.124000 =	1.292600	
003		.300000 x	23.479183 =	7.043755	

			T.E =	8.336355	
7807	7807				
499		1.150000 x	1.540900 =	1.772035	
003		.400000 x	23.479183 =	9.391673	

			T.E =	11.163708	
7808	7808				
500		1.150000 x	2.266200 =	2.606130	
003		.600000 x	23.479183 =	14.087510	

			T.E =	16.693640	

7809	7809				
501		1.200000 x	3.070000 =	3.684000	
003		.800000 x	23.479183 =	18.783346	

			T.E =	22.467346	
7810	7810				
502		1.200000 x	4.230000 =	5.076000	
003		.900000 x	23.479183 =	21.131265	

			T.E =	26.207265	
7811	7811				
503		1.200000 x	1.006100 =	1.207320	
003		.800000 x	23.479183 =	18.783346	

			T.E =	19.990666	
7812	7812				
504		1.300000 x	1.332400 =	1.732120	
003		.900000 x	23.479183 =	21.131265	

			T.E =	22.863385	
7813	7813				
505		1.000000 x	19.170000 =	19.170000	
003		.600000 x	23.479183 =	14.087510	

			T.E =	33.257510	
7901	7901				
490		1.080000 x	.730000 =	.788400	
003		.200000 x	23.479183 =	4.695837	

			T.E =	5.484237	
7902	7902				
527		1.050000 x	5.120000 =	5.376000	
003		1.000000 x	23.479183 =	23.479183	

			T.E =	28.855183	
7903	7903				
528		1.050000 x	6.910000 =	7.255500	
003		.600000 x	23.479183 =	14.087510	

			T.E =	21.343010	

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	23.479183 =	11.739592

			T.E =	17.493592
7911	7911			
493		1.200000 x	.660000 =	.792000
506		1.100000 x	1.100000 =	1.210000
002		.300000 x	17.729980 =	5.318994
003		.150000 x	23.479183 =	3.521877

			T.E =	10.842871
7912	7912			
493		1.200000 x	.660000 =	.792000
507		1.100000 x	1.700000 =	1.870000
003		.150000 x	23.479183 =	3.521877
002		.350000 x	17.729980 =	6.205493

			T.E =	12.389370
7913	7913			
493		1.200000 x	.660000 =	.792000
508		1.100000 x	.860000 =	.946000
003		.150000 x	23.479183 =	3.521877
002		.400000 x	17.729980 =	7.091992

			T.E =	12.351869
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	23.479183 =	1.878335

			T.E =	2.329335
7915.1	7915.1			
7911		.850000 x	10.842871 =	9.216440

			T.E =	9.216440
7915.2	7915.2			
7912		.850000 x	12.389370 =	10.530965

			T.E =	10.530965
7915.3	7915.3			
7913		.850000 x	12.351869 =	10.499089

			T.E =	10.499089

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.729980 =	.709199

			T.E =	2.151199
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.729980 =	.886499

			T.E =	3.142199
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.729980 =	.886499

			T.E =	2.101899
7931	7931			
519		1.050000 x	52.970000 =	55.618500
003		1.500000 x	23.479183 =	35.218775

			T.E =	90.837275
7932.1	7932.1			
514		.000000 x	48.900000 =	.000000
003		.000000 x	23.479183 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	47.060000 =	.000000
003		.000000 x	23.479183 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	48.900000 =	.000000
003		.000000 x	23.479183 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	47.060000 =	.000000
003		.000000 x	23.479183 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	17.729980 =	8.864990
003		.500000 x	23.479183 =	11.739592

			T.E =	27.504582
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	23.479183 =	5.869796

			T.E =	6.244796
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	23.479183 =	2.347918

			T.E =	3.097918
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.729980 =	5.318994
003		.300000 x	23.479183 =	7.043755
251		.100000 x	.710000 =	.071000

			T.E =	
7941	7941			
067		.040000 x	49.210000 =	1.968400
001		.100000 x	15.951934 =	1.595193

			T.E =	3.563593
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.951934 =	1.595193

			T.E =	9.145193