

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

1ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	.865500
212	.984000
213	1.895000
214	3.490000
221	.098900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.695000
232	1.785000
233	.559800
233.1	.559800
233.2	.591200
233.3	7.650000
234	.716500
234.1	.831500
234.2	.742500
234.3	.778000
235	.553000
236	.523000
237	1.090000
237.1	1.235000
241	7.050000
242	5.000000
243	1.900000
244	2.540000
251	290.000000
252	240.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.180000
361.1	12.080000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.630000
361.3	19.830000
361.4	
361.5	37.840000
361.6	50.600000
361.7	78.130000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	97,056.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	65,938.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	115,055.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	131,886.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	22,025.000000
387.1	
387.2	
387.3	18,474.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	5,720.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	4,833.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	7,028.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	13,185.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	36.950000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	9.400000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	93.000000
398.2	42.300000
398.3	48.000000
398.4	64.000000
398.5	5.780000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
419	4.400000
420	94.500000
421	31.630000
428	425.280000
429	75.360000
450	81.440000
451	4.730000
452	100.100000
453	
454	94.500000
455	30.380000
456	34.030000
457	444.570000
458	276.840000
459	409.940000
460	506.910000
461	232.170000
462	338.520000
463	42.540000
464	372.560000
465	99.670000
466	46.490000
467	338.520000
468	84.780000
469	84.780000
470	68.370000
471	59.250000
472	25.750000
473	16.560000
474	34.030000
475	1,913.860000
476	82.950000
477	6.750000
478	111.820000
479	179.890000
480	26.440000
481	789.180000

501	501				
401		1.000000 x	260.720000 =	260.720000	
211		50.000000 x	.865500 =	43.275000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.490000 =	10.470000	

			ΑΘΡΟΙΣΜΑ =	535.557593	

			Η.Δ. =	589.113352	
502	502				
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.490000 =	24.430000	
211		80.000000 x	.865500 =	69.240000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	694.033612	

			Η.Δ. =	763.436973	
503	503				
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.490000 =	34.900000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	.865500 =	95.205000	
118		4.000000 x	10.001019 =	40.004076	

			ΑΘΡΟΙΣΜΑ =	786.478612	

			Η.Δ. =	865.126473	
504	504				
403		1.000000 x	100.390000 =	100.390000	
214		2.000000 x	3.490000 =	6.980000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	.865500 =	34.620000	

			ΑΘΡΟΙΣΜΑ =	333.079536	

			Η.Δ. =	366.387490	
505	505				
404		1.000000 x	206.630000 =	206.630000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	3.490000 =	34.900000	
211		200.000000 x	.865500 =	173.100000	

			ΑΘΡΟΙΣΜΑ =	685.727688	

			Η.Δ. =	754.300457	

506	506				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	3.490000 =	20.940000	
211		95.000000 x	.865500 =	82.222500	

			ΑΘΡΟΙΣΜΑ =	587.550188	

			Η.Δ. =	646.305207	
507	507				
406		1.000000 x	311.770000 =	311.770000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	3.490000 =	34.900000	
211		165.000000 x	.865500 =	142.807500	

			ΑΘΡΟΙΣΜΑ =	795.575188	

			Η.Δ. =	875.132707	
508	508				
407		1.000000 x	53.630000 =	53.630000	
116		16.000000 x	20.419486 =	326.711776	
211		40.000000 x	.865500 =	34.620000	
214		2.000000 x	3.490000 =	6.980000	
115		4.000000 x	21.778427 =	87.113708	
408		2.000000 x	4.400000 =	8.800000	

			ΑΘΡΟΙΣΜΑ =	517.855484	

			Η.Δ. =	569.641032	
509	509				
409		1.000000 x	122.460000 =	122.460000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	3.490000 =	17.450000	
211		80.000000 x	.865500 =	69.240000	

			ΑΘΡΟΙΣΜΑ =	343.373336	

			Η.Δ. =	377.710670	
510	510				
410		1.000000 x	113.190000 =	113.190000	
117		8.000000 x	16.777917 =	134.223336	
211		80.000000 x	.865500 =	69.240000	
214		5.000000 x	3.490000 =	17.450000	

			ΑΘΡΟΙΣΜΑ =	334.103336	

			Η.Δ. =	367.513670	

511	511				
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.490000 =	3.490000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.778427 =	87.113708	
212		17.000000 x	.984000 =	16.728000	

			ΑΘΡΟΙΣΜΑ =	653.275068	

			Η.Δ. =	718.602575	
512	512				
412		1.000000 x	2.900000 =	2.900000	
214		1.000000 x	3.490000 =	3.490000	
115		2.000000 x	21.778427 =	43.556854	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	.865500 =	8.655000	

			ΑΘΡΟΙΣΜΑ =	93.226078	

			Η.Δ. =	102.548686	
513	513				
413		1.000000 x	4.400000 =	4.400000	
211		15.000000 x	.865500 =	12.982500	
115		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	3.490000 =	5.235000	

			ΑΘΡΟΙΣΜΑ =	139.889117	

			Η.Δ. =	153.878029	
514	514				
414		1.000000 x	6.070000 =	6.070000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	3.490000 =	6.980000	
211		21.000000 x	.865500 =	18.175500	

			ΑΘΡΟΙΣΜΑ =	187.587656	

			Η.Δ. =	206.346422	
515	515				
415		1.000000 x	8.530000 =	8.530000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.778427 =	108.892135	
214		2.500000 x	3.490000 =	8.725000	
211		27.000000 x	.865500 =	23.368500	

			ΑΘΡΟΙΣΜΑ =	253.388307	

			Η.Δ. =	278.727138	

516	516				
416		1.000000 x	13.150000 =	13.150000	
115		6.000000 x	21.778427 =	130.670562	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	3.490000 =	12.215000	
211		33.000000 x	.865500 =	28.561500	

				ΑΘΡΟΙΣΜΑ =	323.093958

				Η.Δ. =	355.403354
517	517				
406		1.000000 x	311.770000 =	311.770000	
406		.400000 x	311.770000 =	124.708000	
116		8.000000 x	20.419486 =	163.355888	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	3.490000 =	27.920000	
211		240.000000 x	.865500 =	207.720000	
407		2.000000 x	53.630000 =	107.260000	

				ΑΘΡΟΙΣΜΑ =	1,921.249172

				Η.Δ. =	2,113.374089
518	518				
417		1.000000 x	130.670000 =	130.670000	
118		8.000000 x	10.001019 =	80.008152	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	.984000 =	4.920000	
214		12.000000 x	3.490000 =	41.880000	
114		8.000000 x	23.886192 =	191.089536	
211		180.000000 x	.865500 =	155.790000	

				ΑΘΡΟΙΣΜΑ =	742.854584

				Η.Δ. =	817.140042
520	520				
419		1.000000 x	4.400000 =	4.400000	
211		80.000000 x	.865500 =	69.240000	
212		2.000000 x	.984000 =	1.968000	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.490000 =	17.450000	

				ΑΘΡΟΙΣΜΑ =	376.537940

				Η.Δ. =	414.191734

521	521				
420		1.000000 x	94.500000 =	94.500000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.490000 =	10.470000	
211		40.000000 x	.865500 =	34.620000	

		ΑΘΡΟΙΣΜΑ =		370.683612	

		H.Δ. =		407.751973	
522	522				
421		1.000000 x	31.630000 =	31.630000	
114		8.000000 x	23.886192 =	191.089536	
118		2.000000 x	10.001019 =	20.002038	
211		20.000000 x	.865500 =	17.310000	
214		2.000000 x	3.490000 =	6.980000	

		ΑΘΡΟΙΣΜΑ =		267.011574	

		H.Δ. =		293.712731	
529	529				
429		1.000000 x	75.360000 =	75.360000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	3.490000 =	13.960000	
211		70.000000 x	.865500 =	60.585000	

		ΑΘΡΟΙΣΜΑ =		380.998612	

		H.Δ. =		419.098473	
550	550				
450		1.000000 x	81.440000 =	81.440000	
451		4.000000 x	4.730000 =	18.920000	
116		32.000000 x	20.419486 =	653.423552	
115		4.000000 x	21.778427 =	87.113708	
214		4.000000 x	3.490000 =	13.960000	
211		90.000000 x	.865500 =	77.895000	

		ΑΘΡΟΙΣΜΑ =		932.752260	

		H.Δ. =		1,026.027486	
551	551				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		6.000000 x	3.490000 =	20.940000	
211		95.000000 x	.865500 =	82.222500	
452		1.000000 x	100.100000 =	100.100000	

		ΑΘΡΟΙΣΜΑ =		675.150188	

		H.Δ. =		742.665207	

552	552				
453		1.000000 x	.000000 =	.000000	
211		18.000000 x	.865500 =	15.579000	
115		8.000000 x	21.778427 =	174.227416	
214		1.000000 x	3.490000 =	3.490000	

		ΑΘΡΟΙΣΜΑ =		193.296416	

		H.Δ. =			
553	553				
454		1.000000 x	94.500000 =	94.500000	
214		4.000000 x	3.490000 =	13.960000	
211		100.000000 x	.865500 =	86.550000	

		ΑΘΡΟΙΣΜΑ =		195.010000	

		H.Δ. =		214.511000	
554	554				
455		1.000000 x	30.380000 =	30.380000	

		ΑΘΡΟΙΣΜΑ =		30.380000	

		H.Δ. =		33.418000	
555	555				
456		1.000000 x	34.030000 =	34.030000	
115		4.000000 x	21.778427 =	87.113708	
112		32.000000 x	17.312112 =	553.987584	
214		1.000000 x	3.490000 =	3.490000	
212		17.000000 x	.984000 =	16.728000	

		ΑΘΡΟΙΣΜΑ =		695.349292	

		H.Δ. =		764.884221	
556	556				
457		1.000000 x	444.570000 =	444.570000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
211		200.000000 x	.865500 =	173.100000	
214		18.000000 x	3.490000 =	62.820000	

		ΑΘΡΟΙΣΜΑ =		951.587688	

		H.Δ. =		1,046.746457	
557	557				
458		1.000000 x	276.840000 =	276.840000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
214		11.000000 x	3.490000 =	38.390000	
211		130.000000 x	.865500 =	112.515000	

		ΑΘΡΟΙΣΜΑ =		698.842688	

		H.Δ. =		768.726957	

558	558				
459		1.000000 x	409.940000 =	409.940000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
214		12.000000 x	3.490000 =	41.880000	
211		200.000000 x	.865500 =	173.100000	

				ΑΘΡΟΙΣΜΑ =	943.517688

				Η.Δ. =	1,037.869457
559	559				
460		1.000000 x	506.910000 =	506.910000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		12.000000 x	5.000000 =	60.000000	
214		15.000000 x	3.490000 =	52.350000	
211		250.000000 x	.865500 =	216.375000	

				ΑΘΡΟΙΣΜΑ =	1,106.732688

				Η.Δ. =	1,217.405957
560	560				
461		1.000000 x	232.170000 =	232.170000	
211		160.000000 x	.865500 =	138.480000	
214		8.000000 x	3.490000 =	27.920000	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	589.659536

				Η.Δ. =	648.625490
561	561				
462		1.000000 x	338.520000 =	338.520000	
211		230.000000 x	.865500 =	199.065000	
214		12.000000 x	3.490000 =	41.880000	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	770.554536

				Η.Δ. =	847.609990
562	562				
463		1.000000 x	42.540000 =	42.540000	
214		2.400000 x	3.490000 =	8.376000	
211		50.000000 x	.865500 =	43.275000	

				ΑΘΡΟΙΣΜΑ =	94.191000

				Η.Δ. =	103.610100

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	23.886192 =	382.179072	
112		24.000000 x	17.312112 =	415.490688	
214		16.000000 x	3.490000 =	55.840000	
464		1.000000 x	372.560000 =	372.560000	

		ΑΘΡΟΙΣΜΑ =		1,226.069760	

		H.Δ. =			
564	564				
465		1.000000 x	99.670000 =	99.670000	
567		3.000000 x	362.622872 =	1,087.868616	
111		8.000000 x	15.741598 =	125.932784	
115		8.000000 x	21.778427 =	174.227416	
115		8.000000 x	21.778427 =	174.227416	

		ΑΘΡΟΙΣΜΑ =		1,661.926232	

		H.Δ. =		1,828.118855	
565	565				
450		3.000000 x	81.440000 =	244.320000	
465		1.000000 x	99.670000 =	99.670000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	

		H.Δ. =		779.558540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	46.490000 =	46.490000	
112		1.000000 x	17.312112 =	17.312112	
115		2.000000 x	21.778427 =	43.556854	

		ΑΘΡΟΙΣΜΑ =		107.358966	

		H.Δ. =			
567	567				
450		1.000000 x	81.440000 =	81.440000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		4.000000 x	3.490000 =	13.960000	
211		90.000000 x	.865500 =	77.895000	

		ΑΘΡΟΙΣΜΑ =		329.657156	

		H.Δ. =		362.622872	

568.1	568.1				
467		1.000000 x	338.520000 =	338.520000	
567		2.000000 x	362.622872 =	725.245744	
512		.240000 x	102.548686 =	24.611685	
510		.072000 x	367.513670 =	26.460984	
118		32.000000 x	10.001019 =	320.032608	
114		8.000000 x	23.886192 =	191.089536	
113		32.000000 x	20.419486 =	653.423552	
214		16.000000 x	3.490000 =	55.840000	

				ΑΘΡΟΙΣΜΑ =	2,335.224109

				Η.Δ. =	2,568.746520
568.2	568.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
467		1.000000 x	338.520000 =	338.520000	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	866.716952
569.1	569.1				
468		1.000000 x	84.780000 =	84.780000	
214		16.000000 x	3.490000 =	55.840000	
567		2.000000 x	362.622872 =	725.245744	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	1,136.963432

				Η.Δ. =	1,250.659775
569.2	569.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
468		1.000000 x	84.780000 =	84.780000	

				Η.Δ. =	612.976952
570.1	570.1				
469		1.000000 x	84.780000 =	84.780000	
211		135.000000 x	.865500 =	116.842500	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
214		16.000000 x	3.490000 =	55.840000	

				ΑΘΡΟΙΣΜΑ =	488.556112

				Η.Δ. =	537.411723

570.2	570.2				
469		1.000000 x	84.780000 =	84.780000	
118		4.000000 x	10.001019 =	40.004076	

			H.Δ. =	124.784076	
571.1	571.1				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	3.490000 =	13.960000	
211		114.000000 x	.865500 =	98.667000	

			AΘΡΟΙΣΜΑ =	372.086536	

			H.Δ. =	409.295190	
571.2	571.2				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	

			H.Δ. =	259.459536	
572	572				
407		1.000000 x	53.630000 =	53.630000	
471		1.000000 x	59.250000 =	59.250000	
114		8.000000 x	23.886192 =	191.089536	
214		8.000000 x	3.490000 =	27.920000	
111		24.000000 x	15.741598 =	377.798352	
211		54.000000 x	.865500 =	46.737000	

			AΘΡΟΙΣΜΑ =	756.424888	

			H.Δ. =	832.067377	
573	573				
407		1.000000 x	53.630000 =	53.630000	
473		.250000 x	16.560000 =	4.140000	
474		.250000 x	34.030000 =	8.507500	
474		1.000000 x	34.030000 =	34.030000	
473		1.000000 x	16.560000 =	16.560000	
115		16.000000 x	21.778427 =	348.454832	
111		24.000000 x	15.741598 =	377.798352	
214		8.000000 x	3.490000 =	27.920000	
211		54.000000 x	.865500 =	46.737000	
407		.250000 x	53.630000 =	13.407500	
472		.250000 x	25.750000 =	6.437500	
472		1.000000 x	25.750000 =	25.750000	

			AΘΡΟΙΣΜΑ =	963.372684	

			H.Δ. =	1,059.709952	

574	574				
475		1.000000 x	1,913.860000 =		1,913.860000
214		30.000000 x	3.490000 =		104.700000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
111		16.000000 x	15.741598 =		251.865568
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	.865500 =		510.645000

			ΑΘΡΟΙΣΜΑ =		3,087.168256

			Η.Δ. =		3,395.885082
574.1	574.1				
475		1.000000 x	1,913.860000 =		1,913.860000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152

			Η.Δ. =		2,184.957688
575	575				
476		1.000000 x	82.950000 =		82.950000
214		23.000000 x	3.490000 =		80.270000
115		8.000000 x	21.778427 =		174.227416
211		470.000000 x	.865500 =		406.785000

			ΑΘΡΟΙΣΜΑ =		744.232416

			Η.Δ. =		818.655658
575.1	575.1				
476		1.000000 x	82.950000 =		82.950000
115		8.000000 x	21.778427 =		174.227416

			Η.Δ. =		257.177416
576	576				
477		1.000000 x	6.750000 =		6.750000

			ΑΘΡΟΙΣΜΑ =		6.750000

			Η.Δ. =		7.425000
576.1	576.1				
477		1.000000 x	6.750000 =		6.750000

			Η.Δ. =		6.750000

577	577				
478		1.000000 x	111.820000 =	111.820000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	3.490000 =	13.960000	
211		70.000000 x	.865500 =	60.585000	

				ΑΘΡΟΙΣΜΑ =	593.395472

				Η.Δ. =	652.735019
577.1	577.1				
478		1.000000 x	111.820000 =	111.820000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	382.917688
578	578				
479		1.000000 x	179.890000 =	179.890000	
211		50.000000 x	.865500 =	43.275000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.490000 =	17.450000	

				ΑΘΡΟΙΣΜΑ =	565.957060

				Η.Δ. =	622.552766
579	579				
480		1.000000 x	26.440000 =	26.440000	
212		28.000000 x	.984000 =	27.552000	
117		8.000000 x	16.777917 =	134.223336	
214		1.000000 x	3.490000 =	3.490000	

				ΑΘΡΟΙΣΜΑ =	191.705336

				Η.Δ. =	210.875870
580	580				
481		1.000000 x	789.180000 =	789.180000	
214		8.000000 x	3.490000 =	27.920000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
211		168.000000 x	.865500 =	145.404000	
111		16.000000 x	15.741598 =	251.865568	

				ΑΘΡΟΙΣΜΑ =	1,495.467256

				Η.Δ. =	1,645.013982

581	581			
481		1.000000 x	789.180000 =	789.180000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
			H.Δ. =	1,060.277688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.150000 x	259.459536 =	38.918930
571.1		.350000 x	409.295190 =	143.253317
570.2		.350000 x	124.784076 =	43.674427
570.1		.150000 x	537.411723 =	80.611758
569.2		.670000 x	612.976952 =	410.694558
569.1		.330000 x	1,250.659775 =	412.717726
568.2		.550000 x	866.716952 =	476.694324
568.1		.450000 x	2,568.746520 =	1,155.935934
567		1.000000 x	362.622872 =	362.622872
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,414.412517
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.240000 x	259.459536 =	62.270289
571.1		.260000 x	409.295190 =	106.416749
570.2		.390000 x	124.784076 =	48.665790
570.1		.110000 x	537.411723 =	59.115290
569.2		.750000 x	612.976952 =	459.732714
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	362.622872 =	362.622872
568.1		.250000 x	2,568.746520 =	642.186630
569.1		.250000 x	1,250.659775 =	312.664944
568.2		.750000 x	866.716952 =	650.037714
			H.Δ. =	2,993.001663
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.310000 x	259.459536 =	80.432456
571.1		.190000 x	409.295190 =	77.766086
570.2		.420000 x	124.784076 =	52.409312
570.1		.080000 x	537.411723 =	42.992938
569.2		.820000 x	612.976952 =	502.641101
569.1		.180000 x	1,250.659775 =	225.118760
568.2		.850000 x	866.716952 =	736.709409
568.1		.150000 x	2,568.746520 =	385.311978
567		1.000000 x	362.622872 =	362.622872
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	2,755.293583

613	613			
111		.140000 x	15.741598 =	2.203824
503		.000770 x	865.126473 =	.666147
520		.003500 x	414.191734 =	1.449671
504		.002800 x	366.387490 =	1.025885

			B.T =	5.345527
614	614			
112		.070000 x	17.312112 =	1.211848
509		.004375 x	377.710670 =	1.652484
518		.004375 x	817.140042 =	3.574988
504		.002800 x	366.387490 =	1.025885
503		.000700 x	865.126473 =	.605589

			B.T =	8.070793
621.1	621.1			
213		.100000 x	1.895000 =	.189500
116		.140000 x	20.419486 =	2.858728
111		.560000 x	15.741598 =	8.815295
508		.003500 x	569.641032 =	1.993744
504		.003500 x	366.387490 =	1.282356

			B.T =	15.139623
622	622			
213		.100000 x	1.895000 =	.189500
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848
508		.003500 x	569.641032 =	1.993744
504		.003500 x	366.387490 =	1.282356
518		.004340 x	817.140042 =	3.546388
509		.003500 x	377.710670 =	1.321987

			B.T =	12.404551
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.642760 =	55.299048
6330		.038000 x	179.874650 =	6.835237
6330		.190000 x	179.874650 =	34.176184
6314		.382500 x	2.009285 =	.768552
6314		7.650000 x	2.009285 =	15.371030

			B.T =	112.450050
6360.1 A2	6360.1 A2			
6304		.450000 x	5.642760 =	2.539242
6310		2.142000 x	1.455618 =	3.117934
6330		.013000 x	179.874650 =	2.338370

			B.T =	7.995546

6360.1 A3	6360.1 A3			
6304		.960000 x	5.642760 =	5.417050
6329.2		.037000 x	165.415528 =	6.120375
6310		1.974000 x	1.455618 =	2.873390

			B.T =	14.410814
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.642760 =	14.050472
6329.2		.109000 x	165.415528 =	18.030293

			B.T =	32.080765
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
6069.1		.056400 x	11.031965 =	.622203
113		.425000 x	20.419486 =	8.678282

			B.T =	99.479046
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.642760 =	60.095394
6330		.041000 x	179.874650 =	7.374861
6330		.205000 x	179.874650 =	36.874303
6314		.392500 x	2.009285 =	.788644
6314		7.850000 x	2.009285 =	15.772887

			B.T =	120.906090
6360.2 A2	6360.2 A2			
6304		.750000 x	5.642760 =	4.232070
6330		.019000 x	179.874650 =	3.417618
6310		2.383500 x	1.455618 =	3.469466

			B.T =	11.119154
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.642760 =	6.432746
6310		2.341500 x	1.455618 =	3.408330
6329.2		.054000 x	165.415528 =	8.932439

			B.T =	18.773514
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.642760 =	15.799728
6329.2		.118000 x	165.415528 =	19.519032

			B.T =	35.318760

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
113		2.975000 x	20.419486 =	60.747971
6069.1		.059400 x	11.031965 =	.655299
113		.382500 x	20.419486 =	7.810453

			B.T =	113.359609
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.642760 =	78.434364
6314		11.150000 x	2.009285 =	22.403528
6330		.270000 x	179.874650 =	48.566156
6330		.054000 x	179.874650 =	9.713231
6314		.557500 x	2.009285 =	1.120176

			B.T =	160.237455
6360.3 A2	6360.3 A2			
6304		.940000 x	5.642760 =	5.304194
6310		3.360000 x	1.455618 =	4.890876
6330		.031000 x	179.874650 =	5.576114

			B.T =	15.771185
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.642760 =	10.326251
6329.2		.099000 x	165.415528 =	16.376137
6310		10.678500 x	1.455618 =	15.543817

			B.T =	42.246205
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.642760 =	19.298239
6329.2		.139000 x	165.415528 =	22.992758

			B.T =	42.290998
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		.340000 x	20.419486 =	6.942625
6069.1		.073800 x	11.031965 =	.814159
113		2.975000 x	20.419486 =	60.747971

			B.T =	156.796526

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.642760 =	91.694850
6330		.375000 x	179.874650 =	67.452994
6330		.075000 x	179.874650 =	13.490599
6314		17.700000 x	2.009285 =	35.564345
6314		.885000 x	2.009285 =	1.778217

			B.T =	209.981004
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.642760 =	5.981326
6330		.048000 x	179.874650 =	8.633983
6310		4.641000 x	1.455618 =	6.755523

			B.T =	21.370832
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.642760 =	12.809065
6329.2		.125000 x	165.415528 =	20.676941
6310		20.454000 x	1.455618 =	29.773211

			B.T =	63.259217
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.642760 =	15.799728
6329.2		.118000 x	165.415528 =	19.519032

			B.T =	35.318760
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		.297500 x	20.419486 =	6.074797
113		4.250000 x	20.419486 =	86.782816
6069.1		.091800 x	11.031965 =	1.012734

			B.T =	211.592709
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.642760 =	101.287542
6330		.088000 x	179.874650 =	15.828969
6330		.440000 x	179.874650 =	79.144846
6314		1.050000 x	2.009285 =	2.109749
6314		21.000000 x	2.009285 =	42.194985

			B.T =	240.566091
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.642760 =	6.884167
6310		6.048000 x	1.455618 =	8.803578
6330		.061000 x	179.874650 =	10.972354

			B.T =	26.660099

ΑΤΥΠ	1ο Τρίμηνο του 2010	Σελ.	31
		Ημ/νία	15/07/2011
6360.5 A3	6360.5 A3		
6304	2.480000 x	5.642760 =	13.994045
6310	22.291500 x	1.455618 =	32.447909
6329.2	.144000 x	165.415528 =	23.819836

		B.T =	70.261789
6360.5 A4	6360.5 A4		
6304	3.200000 x	5.642760 =	18.056832
6329.2	.112000 x	165.415528 =	18.526539

		B.T =	36.583371
6360.5 A5	6360.5 A5		
112	9.350000 x	17.312112 =	161.868247
113	.255000 x	20.419486 =	5.206969
6069.1	.090600 x	11.031965 =	.999496
113	5.950000 x	20.419486 =	121.495942

		B.T =	289.570654
6360.6 A1	6360.6 A1		
6304	20.350000 x	5.642760 =	114.830166
6314	24.900000 x	2.009285 =	50.031197
6330	.580000 x	179.874650 =	104.327297
6330	.116000 x	179.874650 =	20.865459
6314	1.245000 x	2.009285 =	2.501560

		B.T =	292.555679
6360.6 A2	6360.6 A2		
6304	1.530000 x	5.642760 =	8.633423
6330	.092000 x	179.874650 =	16.548468
6310	10.206000 x	1.455618 =	14.856037

		B.T =	40.037928
6360.6 A3	6360.6 A3		
6304	2.670000 x	5.642760 =	15.066169
6329.2	.181000 x	165.415528 =	29.940211
6310	25.798500 x	1.455618 =	37.552761

		B.T =	82.559141
6360.6 A4	6360.6 A4		
6304	2.800000 x	5.642760 =	15.799728
6329.2	.118000 x	165.415528 =	19.519032

		B.T =	35.318760

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	7.650000 x	20.419486 =	156.209068
6069.1	.120000 x	11.031965 =	1.323836
113	.212500 x	20.419486 =	4.339141

B.T = 382.601472

641

641

231	.200000 x	.695000 =	.139000
111	.170000 x	15.741598 =	2.676072
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
252	.002500 x	240.000000 =	.600000

B.T = 6.453556

651

651

221	150.000000 x	.098900 =	14.835000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	377.710670 =	3.563700
509	.003060 x	377.710670 =	1.155795
T 630	.600000 x	1.743328 =	1.045997
T 625	.850000 x	20.648071 =	17.550860
511	.042500 x	718.602575 =	30.540609
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 104.520146

652

652

221	650.000000 x	.098900 =	64.285000
T 630	.320000 x	1.743328 =	.557865
T 625	1.000000 x	20.648071 =	20.648071
511	.042500 x	718.602575 =	30.540609
509	.001632 x	377.710670 =	.616424
509	.009435 x	377.710670 =	3.563700
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 147.639854

652.1

652.1

221	450.000000 x	.098900 =	44.505000
111	1.275000 x	15.741598 =	20.070537
510	.001632 x	367.513670 =	.599782
511	.042500 x	718.602575 =	30.540609
T 630	.320000 x	1.743328 =	.557865
T 625	1.060000 x	20.648071 =	21.886955
509	.010001 x	377.710670 =	3.777484
112	.425000 x	17.312112 =	7.357648

B.T = 129.295881

652.2	652.2			
221		900.000000 x	.098900 =	89.010000
509		.007548 x	377.710670 =	2.850960
T 630		.320000 x	1.743328 =	.557865
T 625		.800000 x	20.648071 =	16.518457
511		.042500 x	718.602575 =	30.540609
510		.001632 x	367.513670 =	.599782
111		1.275000 x	15.741598 =	20.070537
112		.425000 x	17.312112 =	7.357648

			B.T =	167.505859
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.098900 =	1.285700
113		.935000 x	20.419486 =	19.092219

			B.T =	
7001 A	7001 A			
502		.000365 x	763.436973 =	.278654
557		.001094 x	768.726957 =	.840987

			AΘΡΟΙΣΜΑ =	1.119642
	B.T =	.200000 x	1.119642 =	.223928

7001 B	7001 B			
558		.000700 x	1,037.869457 =	.726509

			B.T =	.726509
7001 E	7001 E			
503		.000875 x	865.126473 =	.756986
554		.000875 x	33.418000 =	.029241

			B.T =	.786226
7001 Γ	7001 Γ			
501		.000700 x	589.113352 =	.412379
502		.000700 x	763.436973 =	.534406

			B.T =	.946785

7001 Δ	7001 Δ			
502		.000292 x	763.436973 =	.222924
510		.000292 x	367.513670 =	.107314
X 630.1		.060000 x	1.543557 =	.092613
X 630		.060000 x	1.435682 =	.086141

			AΘΡΟΙΣΜΑ =	.508992
	B.T =	.600000 x	.508992 =	.305395

7003 Α	7003 Α			
502		.000365 x	763.436973 =	.278654
557		.001094 x	768.726957 =	.840987

			AΘΡΟΙΣΜΑ =	1.119642
	B.T =	.100000 x	1.119642 =	.111964

7003 Β	7003 Β			
559		.000464 x	1,217.405957 =	.564876

			B.T =	.564876
7003 Γ	7003 Γ			
502		.000700 x	763.436973 =	.534406

			B.T =	.534406
7003 Δ	7003 Δ			
502		.000875 x	763.436973 =	.668007
562		.000875 x	103.610100 =	.090659

			B.T =	.758666
7005 Α	7005 Α			
502		.000365 x	763.436973 =	.278654
557		.001094 x	768.726957 =	.840987

			AΘΡΟΙΣΜΑ =	1.119642
	B.T =	.100000 x	1.119642 =	.111964

7005 Β	7005 Β			
559		.000812 x	1,217.405957 =	.988534

			B.T =	.988534
7005 Ε	7005 Ε			
502		.000875 x	763.436973 =	.668007
562		.000875 x	103.610100 =	.090659

			B.T =	.758666

7005 Γ	7005 Γ			
559		.000232 x	1,217.405957 =	.282438

			B.T =	.282438
7005 Δ	7005 Δ			
502		.000700 x	763.436973 =	.534406

			B.T =	.534406
7010 Α	7010 Α			
558		.000315 x	1,037.869457 =	.326929

			B.T =	.326929
7010 Β	7010 Β			
558		.000473 x	1,037.869457 =	.490912

			B.T =	.490912
7010 Ε	7010 Ε			
503		.000875 x	865.126473 =	.756986
553		.000875 x	214.511000 =	.187697

			B.T =	.944683
7010 Γ	7010 Γ			
502		.000700 x	763.436973 =	.534406

			B.T =	.534406
7010 Δ	7010 Δ			
502		.000292 x	763.436973 =	.222924
510		.000292 x	367.513670 =	.107314
X 630.1		.060000 x	1.543557 =	.092613
X 630		.060000 x	1.435682 =	.086141

			AΘΡΟΙΣΜΑ =	.508992
	B.T =	.600000 x	.508992 =	.305395

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
223		350.000000 x	.119300 =	41.755000
509		.007831 x	377.710670 =	2.957852
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.830000 x	17.661424 =	14.658982
T 617		.500000 x	6.107474 =	3.053737
509		.004718 x	377.710670 =	1.782039

			B.T =	77.502022

7016.2	7016.2			
570.1		.586500 x	537.411723 =	315.191976
571.1		.586500 x	409.295190 =	240.051629
570.2		1.113500 x	124.784076 =	138.947069
571.2		1.113500 x	259.459536 =	288.908193

			ΑΘΡΟΙΣΜΑ =	983.098866
	B.T =	.025000 x	983.098866 =	24.577472

7016.3	7016.3			
564		.212500 x	1,828.118855 =	388.475257
565		.637500 x	779.558540 =	496.968569

			ΑΘΡΟΙΣΜΑ =	885.443826
	B.T =	.025000 x	885.443826 =	22.136096

7016.4	7016.4			
7016.1		1.000000 x	77.502022 =	77.502022
7016.3		1.000000 x	22.136096 =	22.136096
7016.2		1.000000 x	24.577472 =	24.577472

			B.T =	124.215590
7016.5	7016.5			
7016.4		.200000 x	124.215590 =	24.843118

			B.T =	24.843118
7016.6	7016.6			
7016.4		.250000 x	124.215590 =	31.053898
7016.5		.250000 x	24.843118 =	6.210780

			B.T =	37.264677
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.830000 x	17.661424 =	14.658982
T 617		.500000 x	6.107474 =	3.053737
509		.007831 x	377.710670 =	2.957852
509		.004718 x	377.710670 =	1.782039
223		350.000000 x	.119300 =	41.755000

			B.T =	77.502022
7017.2	7017.2			
564		.425000 x	1,828.118855 =	776.950513
565		.425000 x	779.558540 =	331.312380

			AΘΡΟΙΣΜΑ =	1,108.262893
	B.T =	.012500 x	1,108.262893 =	13.853286

7017.3	7017.3			
7017.1		1.000000 x	77.502022 =	77.502022
7017.2		1.000000 x	13.853286 =	13.853286

			B.T =	91.355308
7017.4	7017.4			
7017.3		.200000 x	91.355308 =	18.271062

			B.T =	18.271062
7017.5	7017.5			
7017.3		.300000 x	91.355308 =	27.406592
7017.4		.300000 x	18.271062 =	5.481319

			B.T =	32.887911
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689

			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
223		350.000000 x	.119300 =	41.755000

			B.T =	77.645586
7019 A2	7019 A2			
555		.012143 x	764.884221 =	9.287989

			B.T =	9.287989
7019 A3	7019 A3			
570.1		.850000 x	537.411723 =	456.799965
571.1		.850000 x	409.295190 =	347.900912
571.2		.850000 x	259.459536 =	220.540606
570.2		.850000 x	124.784076 =	106.066465

			ΑΘΡΟΙΣΜΑ =	1,131.307946
	B.T =	.014286 x	1,131.307946 =	16.161865

7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563

			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	77.645586 =	77.645586
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A2		1.000000 x	9.287989 =	9.287989
7019 A3		1.000000 x	16.161865 =	16.161865
7019 A5		1.000000 x	17.356563 =	17.356563

			B.T =	189.689457
7019 A7	7019 A7			
7019 A6		.100000 x	189.689457 =	18.968946

			B.T =	18.968946

710	710			
397.3		.006660 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.510000 x	15.741598 =	8.028215
252		.001000 x	240.000000 =	.240000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	366.387490 =	1.841097
509		.003750 x	377.710670 =	1.416415

			B.T =	3.257512
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	414.191734 =	2.182790
504		.004250 x	366.387490 =	1.557147
503		.001190 x	865.126473 =	1.029501

			B.T =	6.107474
T 621	T 621			
213		.100000 x	1.895000 =	.189500
508		.004250 x	569.641032 =	2.420974
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.786074
T 623	T 623			
213		.100000 x	1.895000 =	.189500
508		.004250 x	569.641032 =	2.420974
518		.008500 x	817.140042 =	6.945690
509		.004250 x	377.710670 =	1.605270
504		.004250 x	366.387490 =	1.557147
116		.170000 x	20.419486 =	3.471313
112		.085000 x	17.312112 =	1.471530

			B.T =	17.661424

T 625	T 625			
213		.100000 x	1.895000 =	.189500
116		.170000 x	20.419486 =	3.471313
518		.012155 x	817.140042 =	9.932337
509		.004250 x	377.710670 =	1.605270
508		.004250 x	569.641032 =	2.420974
504		.004250 x	366.387490 =	1.557147
112		.085000 x	17.312112 =	1.471530

			B.T =	20.648071
T 630	T 630			
512		.017000 x	102.548686 =	1.743328

			B.T =	1.743328
T 630.1	T 630.1			
510		.005100 x	367.513670 =	1.874320

			B.T =	1.874320
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
504		.003500 x	366.387490 =	1.282356
520		.004340 x	414.191734 =	1.797592
503		.000980 x	865.126473 =	.847824

			B.T =	5.029684
X 621	X 621			
213		.100000 x	1.895000 =	.189500
111		.560000 x	15.741598 =	8.815295
508		.003500 x	569.641032 =	1.993744
116		.140000 x	20.419486 =	2.858728

			B.T =	13.857267
X 623	X 623			
213		.100000 x	1.895000 =	.189500
518		.007000 x	817.140042 =	5.719980
509		.003500 x	377.710670 =	1.321987
508		.003500 x	569.641032 =	1.993744
504		.003500 x	366.387490 =	1.282356
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	14.578143

X 625	X 625			
213		.100000 x	1.895000 =	.189500
518		.010010 x	817.140042 =	8.179572
112		.070000 x	17.312112 =	1.211848
504		.003500 x	366.387490 =	1.282356
509		.003500 x	377.710670 =	1.321987
508		.003500 x	569.641032 =	1.993744
116		.140000 x	20.419486 =	2.858728

			B.T =	17.037735
X 630	X 630			
512		.014000 x	102.548686 =	1.435682

			B.T =	1.435682
X 630.1	X 630.1			
510		.004200 x	367.513670 =	1.543557

			B.T =	1.543557
2522	2522			
221		300.000000 x	.098900 =	29.670000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	377.710670 =	1.782039
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.007548 x	377.710670 =	2.850960
509		.001275 x	377.710670 =	.481581
T 625		.500000 x	20.648071 =	10.324036
641		3.000000 x	6.453556 =	19.360668
T 630		.250000 x	1.743328 =	.435832

			T.E =	151.838657
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	377.710670 =	7.320033

			T.E =	74.221824
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	377.710670 =	3.050014

			T.E =	43.191089
6051	6051			
502		.000175 x	763.436973 =	.133601

			T.E =	.133601

6052	6052			
501		.000117 x	589.113352 =	.068926
502		.000088 x	763.436973 =	.067182
521		.000088 x	407.751973 =	.035882

			T.E =	.171991
6053	6053			
502		.000318 x	763.436973 =	.242773
507		.001000 x	875.132707 =	.875133

			T.E =	1.117906
6054	6054			
112		.004900 x	17.312112 =	.084829
509		.002975 x	377.710670 =	1.123689
507		.001077 x	875.132707 =	.942518

			T.E =	2.151037
6055	6055			
213		.400000 x	1.895000 =	.758000
503		.001167 x	865.126473 =	1.009603
508		.007000 x	569.641032 =	3.987487
504		.001400 x	366.387490 =	.512942
112		.490000 x	17.312112 =	8.482935
116		.280000 x	20.419486 =	5.717456

			T.E =	20.468423
6056	6056			
507		.001750 x	875.132707 =	1.531482

			T.E =	1.531482
6057	6057			
506		.087500 x	646.305207 =	56.551706

			T.E =	56.551706
6058	6058			
507		.087500 x	875.132707 =	76.574112

			T.E =	76.574112
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
507		.001077 x	875.132707 =	.942518
509		.002975 x	377.710670 =	1.123689
501		.000583 x	589.113352 =	.343453
502		.001400 x	763.436973 =	1.068812

			T.E =	3.599657
6062	6062			
213		.400000 x	1.895000 =	.758000
509		.002800 x	377.710670 =	1.057590
508		.002800 x	569.641032 =	1.594995
507		.001400 x	875.132707 =	1.225186
502		.002000 x	763.436973 =	1.526874
116		.175000 x	20.419486 =	3.573410
112		.175000 x	17.312112 =	3.029620

			T.E =	12.765674
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.070000 x	17.312112 =	1.211848
509		.003641 x	377.710670 =	1.375245
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.341114
6064	6064			
112		.140000 x	17.312112 =	2.423696
509		.003641 x	377.710670 =	1.375245
507		.014000 x	875.132707 =	12.251858
112		.070000 x	17.312112 =	1.211848

			T.E =	17.262646
6065	6065			
506		.002800 x	646.305207 =	1.809655
506		.002100 x	646.305207 =	1.357241

			T.E =	3.166896

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	763.436973 =	.534406

			T.E =	1.636318
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630		.100000 x	1.435682 =	.143568
X 630.1		.100000 x	1.543557 =	.154356

			T.E =	15.724690
6068	6068			
111		.560000 x	15.741598 =	8.815295
622		1.351351 x	12.404551 =	16.762902
X 630.1		.200000 x	1.543557 =	.308711
X 630		.200000 x	1.435682 =	.287136
112		.560000 x	17.312112 =	9.694783
509		.016497 x	377.710670 =	6.231093

			T.E =	42.099921
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
X 630.1		.200000 x	1.543557 =	.308711
X 630		.200000 x	1.435682 =	.287136
614		1.351351 x	8.070793 =	10.906474
509		.016497 x	377.710670 =	6.231093
112		.560000 x	17.312112 =	9.694783

			T.E =	36.243493
6069	6069			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	377.710670 =	4.538949
X 625		1.050000 x	17.037735 =	17.889622

			T.E =	23.640419
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	377.710670 =	4.538949
X 617		1.050000 x	5.029684 =	5.281168

			T.E =	11.031965
6070	6070			
501		.000467 x	589.113352 =	.275116

			T.E =	.275116

6071	6071			
504		.002333 x	366.387490 =	.854782
509		.002975 x	377.710670 =	1.123689

			T.E =	1.978471
6072	6072			
504		.003500 x	366.387490 =	1.282356
509		.002800 x	377.710670 =	1.057590

			T.E =	2.339946
6073	6073			
509		.000833 x	377.710670 =	.314633

			T.E =	.314633
6074	6074			
509		.000784 x	377.710670 =	.296125

			T.E =	.296125
6075	6075			
509		.001096 x	377.710670 =	.413971

			T.E =	.413971
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	865.126473 =	.605589
509		.003914 x	377.710670 =	1.478360
507		.000840 x	875.132707 =	.735111

			T.E =	2.903889
6077	6077			
503		.001400 x	865.126473 =	1.211177

			T.E =	1.211177
6078	6078			
112		.004900 x	17.312112 =	.084829
505		.001400 x	754.300457 =	1.056021
501		.000056 x	589.113352 =	.032990
503		.000350 x	865.126473 =	.302794

			T.E =	1.476635

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
501		.000056 x	589.113352 =	.032990
503		.000350 x	865.126473 =	.302794
556		.001400 x	1,046.746457 =	1.465445

			T.E =	1.886059
6079	6079			
112		.014000 x	17.312112 =	.242370
501		.000700 x	589.113352 =	.412379
529		.000980 x	419.098473 =	.410717
X 630		.150000 x	1.435682 =	.215352
509		.000630 x	377.710670 =	.237958
502		.000350 x	763.436973 =	.267203

			T.E =	1.785978
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.543557 =	.154356
X 630		.100000 x	1.435682 =	.143568
529		.000700 x	419.098473 =	.293369
502		.000292 x	763.436973 =	.222924
501		.000583 x	589.113352 =	.343453

			T.E =	1.400039
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087
506		.007000 x	646.305207 =	4.524136

			T.E =	23.254086
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.254086 =	23.254086

			T.E =	35.485052
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.254086 =	23.254086
112		.140000 x	17.312112 =	2.423696

			T.E =	47.716019

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.254086 =	23.254086
112		.210000 x	17.312112 =	3.635544

			T.E =	59.946985
6082.1	6082.1			
213		.400000 x	1.895000 =	.758000
111		1.400000 x	15.741598 =	22.038237
116		.700000 x	20.419486 =	14.293640
508		.070000 x	569.641032 =	39.874872
116		1.400000 x	20.419486 =	28.587280

			T.E =	105.552030
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
6082.1		1.000000 x	105.552030 =	105.552030
112		.140000 x	17.312112 =	2.423696

			T.E =	118.994844
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	105.552030 =	105.552030
112		.280000 x	17.312112 =	4.847391

			T.E =	132.437659
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
112		.420000 x	17.312112 =	7.271087
6082.1		1.000000 x	105.552030 =	105.552030

			T.E =	145.880473
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.280000 x	17.312112 =	4.847391
506		.005833 x	646.305207 =	3.769898
112		.140000 x	17.312112 =	2.423696

			T.E =	15.448633
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.448633 =	15.448633
112		.070000 x	17.312112 =	1.211848

			T.E =	25.475776

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.448633 =	15.448633

			T.E =	35.502918
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
112		.210000 x	17.312112 =	3.635544
6083.1		1.000000 x	15.448633 =	15.448633

			T.E =	45.530061
6084.1	6084.1			
213		.400000 x	1.895000 =	.758000
111		1.470000 x	15.741598 =	23.140149
116		.700000 x	20.419486 =	14.293640
508		.035000 x	569.641032 =	19.937436
116		1.050000 x	20.419486 =	21.440460

			T.E =	79.569686
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
112		.105000 x	17.312112 =	1.817772
6084.1		1.000000 x	79.569686 =	79.569686

			T.E =	90.202753
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	79.569686 =	79.569686

			T.E =	100.835819
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
112		.315000 x	17.312112 =	5.453315
6084.1		1.000000 x	79.569686 =	79.569686

			T.E =	111.468886
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	646.305207 =	3.015660
502		.001400 x	763.436973 =	1.068812
112		.140000 x	17.312112 =	2.423696

			T.E =	8.711991

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	8.711991 =	8.711991

			T.E =	15.433398
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	8.711991 =	8.711991

			T.E =	22.154805
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	8.711991 =	8.711991

			T.E =	28.876212
6086.1	6086.1			
213		.400000 x	1.895000 =	.758000
508		.008750 x	569.641032 =	4.984359
111		1.120000 x	15.741598 =	17.630590
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456

			T.E =	39.095953
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
112		.105000 x	17.312112 =	1.817772
6086.1		1.000000 x	39.095953 =	39.095953

			T.E =	46.423284
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
6086.1		1.000000 x	39.095953 =	39.095953
112		.210000 x	17.312112 =	3.635544

			T.E =	53.750615
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
6086.1		1.000000 x	39.095953 =	39.095953
112		.315000 x	17.312112 =	5.453315

			T.E =	61.077946

6087	6087				
252		.001000 x	240.000000 =	.240000	
113		.210000 x	20.419486 =	4.288092	
112		.350000 x	17.312112 =	6.059239	
111		.210000 x	15.741598 =	3.305736	

			T.E =	13.893067	
6088	6088				
6081.1		1.000000 x	23.254086 =	23.254086	
6081.1		.900000 x	23.254086 =	20.928677	

			T.E =	44.182763	
6089	6089				
6082.1		1.000000 x	105.552030 =	105.552030	
6082.1		.900000 x	105.552030 =	94.996827	

			T.E =	200.548857	
6090	6090				
6083.1		1.000000 x	15.448633 =	15.448633	
6083.1		1.300000 x	15.448633 =	20.083223	

			T.E =	35.531856	
6091	6091				
6084.1		1.000000 x	79.569686 =	79.569686	
6084.1		1.300000 x	79.569686 =	103.440592	

			T.E =	183.010278	
6100	6100				
231		.200000 x	.695000 =	.139000	
111		.175000 x	15.741598 =	2.754780	
251		.002000 x	290.000000 =	.580000	
113		.105000 x	20.419486 =	2.144046	
252.1		.002000 x	.000000 =	.000000	

			T.E =		
6101	6101				
231		15.000000 x	.695000 =	10.425000	
252		.018000 x	240.000000 =	4.320000	
113		3.500000 x	20.419486 =	71.468201	
112		3.500000 x	17.312112 =	60.592392	
252.1		.020000 x	.000000 =	.000000	
251		.068000 x	290.000000 =	19.720000	

			T.E =		

6102	6102			
244		1.000000 x	2.540000 =	2.540000
112		.002100 x	17.312112 =	.036355
506		.000070 x	646.305207 =	.045241
506		.000070 x	646.305207 =	.045241
509		.000051 x	377.710670 =	.019263
112		.001400 x	17.312112 =	.024237

			T.E =	2.710338
6103	6103			
244		.125000 x	2.540000 =	.317500
112		.002800 x	17.312112 =	.048474
509		.000102 x	377.710670 =	.038526
506		.000140 x	646.305207 =	.090483
506		.000140 x	646.305207 =	.090483
112		.004200 x	17.312112 =	.072711

			T.E =	.658177
6104	6104			
236		3.000000 x	.523000 =	1.569000
111		.280000 x	15.741598 =	4.407647
517		.017500 x	2,113.374089 =	36.984047
113		.280000 x	20.419486 =	5.717456

			T.E =	48.678150
6105	6105			
111		.210000 x	15.741598 =	3.305736
517		.014000 x	2,113.374089 =	29.587237
113		.140000 x	20.419486 =	2.858728

			T.E =	35.751701
6106	6106			
512		.087500 x	102.548686 =	8.973010

			T.E =	8.973010
6107	6107			
513		.087500 x	153.878029 =	13.464328

			T.E =	13.464328
6108	6108			
514		.087500 x	206.346422 =	18.055312

			T.E =	18.055312

6109	6109			
515		.087500 x	278.727138 =	24.388625

			T.E =	24.388625
6110	6110			
516		.087500 x	355.403354 =	31.097793

			T.E =	31.097793
6120	6120			
112		.004200 x	17.312112 =	.072711
501		.000070 x	589.113352 =	.041238
502		.001750 x	763.436973 =	1.336015

			T.E =	1.449964
6121	6121			
112		.004200 x	17.312112 =	.072711
501		.000049 x	589.113352 =	.028867
509		.003113 x	377.710670 =	1.175813
507		.000875 x	875.132707 =	.765741
505		.000420 x	754.300457 =	.316806
502		.000315 x	763.436973 =	.240483

			T.E =	2.600421
6151	6151			
243		1.020000 x	1.900000 =	1.938000
243		.080000 x	1.900000 =	.152000

			T.E =	2.090000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
112		.425000 x	17.312112 =	7.357648
509		.003570 x	377.710670 =	1.348427
T 611		1.050000 x	20.070537 =	21.074064

			T.E =	36.470318

6154	6154				
111		.425000 x	15.741598 =	6.690179	
112		.425000 x	17.312112 =	7.357648	
T 621		1.050000 x	16.786074 =	17.625378	
509		.003570 x	377.710670 =	1.348427	

				T.E =	33.021632
6155	6155				
111		.680000 x	15.741598 =	10.704287	
652		.100000 x	147.639854 =	14.763985	
113		1.275000 x	20.419486 =	26.034845	
T 621		.350000 x	16.786074 =	5.875126	
509		.003220 x	377.710670 =	1.216228	

				T.E =	58.594471
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	147.639854 =	1.476399	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	

				T.E =	22.864297
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	377.710670 =	1.110469	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.857267 =	14.550130	

				T.E =	29.543158
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	377.710670 =	1.110469	
X 611		1.050000 x	16.528678 =	17.355112	
112		.420000 x	17.312112 =	7.271087	

				T.E =	32.348139
6158	6158				
111		.560000 x	15.741598 =	8.815295	
621.1		1.050000 x	15.139623 =	15.896604	
509		.002940 x	377.710670 =	1.110469	
504		.001400 x	366.387490 =	.512942	

				T.E =	26.335311

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	90.497781

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	27.291284	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.991284	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	35.991284	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	39.691284	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	62.697781	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	81.897781	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	101.797781	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	17.037735 =	11.926415
X 623		.400000 x	14.578143 =	5.831257
509		.005439 x	377.710670 =	2.054368
509		.003108 x	377.710670 =	1.173925
112		.420000 x	17.312112 =	7.271087

			T.E =	31.562787
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	377.710670 =	3.286838
613		1.050000 x	5.345527 =	5.612803

			T.E =	19.476464

6205	6205				
111		.210000 x	15.741598 =	3.305736	
112		.070000 x	17.312112 =	1.211848	
509		.002800 x	377.710670 =	1.057590	
613		1.000000 x	5.345527 =	5.345527	

			T.E =	10.920700	
6251	6251				
509		.002800 x	377.710670 =	1.057590	
613		1.000000 x	5.345527 =	5.345527	

			T.E =	6.403117	
6252	6252				
509		.000784 x	377.710670 =	.296125	

			T.E =	.296125	
6253	6253				
112		.210000 x	17.312112 =	3.635544	
X 630.1		.200000 x	1.543557 =	.308711	
X 630		.200000 x	1.435682 =	.287136	
521		.007000 x	407.751973 =	2.854264	
501		.002917 x	589.113352 =	1.718444	

			T.E =	8.804099	
6301	6301				
231		.200000 x	.695000 =	.139000	
252		.002500 x	240.000000 =	.600000	
111		.170000 x	15.741598 =	2.676072	
113		.127500 x	20.419486 =	2.603484	
251		.001500 x	290.000000 =	.435000	

			T.E =	6.453556	
6302	6302				
231		.300000 x	.695000 =	.208500	
251		.002000 x	290.000000 =	.580000	
252		.004000 x	240.000000 =	.960000	
111		.212500 x	15.741598 =	3.345090	
113		1.232500 x	20.419486 =	25.167016	

			T.E =	30.260606	
6303	6303				
6302		.666660 x	30.260606 =	20.173536	

			T.E =	20.173536	

6304	6304				
234.2		.018000 x	.742500 =	.013365	
112		.212500 x	17.312112 =	3.678824	
113		.085000 x	20.419486 =	1.735656	
113		.010200 x	20.419486 =	.208279	
235		.012000 x	.553000 =	.006636	

			T.E =	5.642760	
6310	6310				
233		1.050000 x	.559800 =	.587790	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.455618	
6311	6311				
233.1		1.050000 x	.559800 =	.587790	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.455618	
6312	6312				
233.3		1.010000 x	7.650000 =	7.726500	
233.3		.303000 x	7.650000 =	2.317950	
113		.085000 x	20.419486 =	1.735656	
113		.085000 x	20.419486 =	1.735656	

			T.E =	13.515763	
6313	6313				
233.2		1.050000 x	.591200 =	.620760	
113		.025500 x	20.419486 =	.520697	

			T.E =	1.141457	
6314	6314				
233.2		1.050000 x	.591200 =	.620760	
113		.068000 x	20.419486 =	1.388525	

			T.E =	2.009285	
6320.1	6320.1				
396.1		1.000000 x	1.400000 =	1.400000	
113		.000850 x	20.419486 =	.017357	

			T.E =	1.417357	

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.098900 =	13.846000
111		.765000 x	15.741598 =	12.042322
113		.595000 x	20.419486 =	12.149594
509		.003302 x	377.710670 =	1.247201
509		.003019 x	377.710670 =	1.140309
T 630.1		.175000 x	1.874320 =	.328006
T 630		.175000 x	1.743328 =	.305082
T 625		.350000 x	20.648071 =	7.226825
T 623		.560000 x	17.661424 =	9.890397
T 621		.300000 x	16.786074 =	5.035822
511		.023800 x	718.602575 =	17.102741
509		.005284 x	377.710670 =	1.995823
112		.714000 x	17.312112 =	12.360848

			T.E =	94.670971

6322	6322			
221		140.000000 x	.098900 =	13.846000
509		.003019 x	377.710670 =	1.140309
T 623		.560000 x	17.661424 =	9.890397
T 630.1		.175000 x	1.874320 =	.328006
T 630		.175000 x	1.743328 =	.305082
T 625		.350000 x	20.648071 =	7.226825
511		.023800 x	718.602575 =	17.102741
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	377.710670 =	1.247201
509		.005284 x	377.710670 =	1.995823
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 95.656310

6323	6323			
221		150.000000 x	.098900 =	14.835000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 104.272991

6323.1	6323.1			
221		150.000000 x	.098900 =	14.835000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	377.710670 =	2.850960
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
113		.850000 x	20.419486 =	17.356563

T.E = 97.002692

6324	6324			
221		200.000000 x	.098900 =	19.780000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
112		1.020000 x	17.312112 =	17.658354
509		.004718 x	377.710670 =	1.782039
113		.850000 x	20.419486 =	17.356563
509		.007548 x	377.710670 =	2.850960

T.E = 109.217991

6324.1	6324.1			
221		200.000000 x	.098900 =	19.780000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	377.710670 =	2.850960
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
113		.850000 x	20.419486 =	17.356563

T.E = 101.947692

6325	6325			
221		250.000000 x	.098900 =	24.725000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 114.162991

6325.1

6325.1

221	250.000000 x	.098900 =	24.725000
T 630.1	.250000 x	1.874320 =	.468580
T 630	.250000 x	1.743328 =	.435832
T 623	.800000 x	17.661424 =	14.129139
T 617	.500000 x	6.107474 =	3.053737
112	1.020000 x	17.312112 =	17.658354
509	.007548 x	377.710670 =	2.850960
511	.034000 x	718.602575 =	24.432488
509	.004718 x	377.710670 =	1.782039
113	.850000 x	20.419486 =	17.356563

T.E =

106.892692

6326

6326

221	300.000000 x	.098900 =	29.670000
T 630.1	.250000 x	1.874320 =	.468580
T 630	.250000 x	1.743328 =	.435832
T 625	.500000 x	20.648071 =	10.324036
T 623	.800000 x	17.661424 =	14.129139
511	.034000 x	718.602575 =	24.432488
509	.004718 x	377.710670 =	1.782039
509	.007548 x	377.710670 =	2.850960
113	1.360000 x	20.419486 =	27.770501
112	1.190000 x	17.312112 =	20.601413

T.E =

132.464988

6326.1

6326.1

221	300.000000 x	.098900 =	29.670000
T 630.1	.250000 x	1.874320 =	.468580
T 630	.250000 x	1.743328 =	.435832
T 623	.800000 x	17.661424 =	14.129139
T 617	.500000 x	6.107474 =	3.053737
112	1.190000 x	17.312112 =	20.601413
509	.007548 x	377.710670 =	2.850960
511	.034000 x	718.602575 =	24.432488
509	.004718 x	377.710670 =	1.782039
113	1.360000 x	20.419486 =	27.770501

T.E =

125.194689

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 155.049215

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	377.710670 =	2.850960
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
113		1.275000 x	20.419486 =	26.034845

T.E = 147.778917

6328	6328			
221		350.000000 x	.098900 =	34.615000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	377.710670 =	2.850960
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	377.710670 =	1.782039

T.E = 158.275528

6328.1	6328.1			
221		350.000000 x	.098900 =	34.615000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	377.710670 =	2.850960
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
113		1.445000 x	20.419486 =	29.506157

T.E = 151.005229

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 164.330528

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
511		.034000 x	718.602575 =	24.432488
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 157.060229

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039

T.E = 165.415528

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
T 630		.250000 x	1.743328 =	.435832
T 630.1		.250000 x	1.874320 =	.468580
511		.034000 x	718.602575 =	24.432488
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

T.E = 158.145229

6330	6330			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.042500 x	718.602575 =	30.540609
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

T.E = 179.874650

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	377.710670 =	1.782039
511		.042500 x	718.602575 =	30.540609
509		.007548 x	377.710670 =	2.850960
112		2.295000 x	17.312112 =	39.731297

T.E = 172.604351

6331	6331			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.042500 x	718.602575 =	30.540609
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612

T.E = 344.711649

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
511		.042500 x	718.602575 =	30.540609
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181

T.E = 337.441350

6351	6351			
221		120.000000 x	.098900 =	11.868000
6301		1.000000 x	6.453556 =	6.453556
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.450000 x	20.648071 =	9.291632
511		.034000 x	718.602575 =	24.432488
509		.008020 x	377.710670 =	3.029240
113		1.275000 x	20.419486 =	26.034845
T 623		.850000 x	17.661424 =	15.012210
509		.004246 x	377.710670 =	1.603760
112		1.275000 x	17.312112 =	22.072943

T.E = 120.703084

6351.1	6351.1			
221		120.000000 x	.098900 =	11.868000
6301		1.000000 x	6.453556 =	6.453556
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.850000 x	17.661424 =	15.012210
T 617		.450000 x	6.107474 =	2.748363
511		.034000 x	718.602575 =	24.432488
509		.008020 x	377.710670 =	3.029240
509		.004246 x	377.710670 =	1.603760
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 114.159816

6352	6352			
221		300.000000 x	.098900 =	29.670000
6301		1.000000 x	6.453556 =	6.453556
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 625		.500000 x	20.648071 =	10.324036
T 623		.800000 x	17.661424 =	14.129139
511		.034000 x	718.602575 =	24.432488
509		.004718 x	377.710670 =	1.782039
509		.007548 x	377.710670 =	2.850960
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238

T.E = 179.404557

6352.1	6352.1			
221		300.000000 x	.098900 =	29.670000
112		2.125000 x	17.312112 =	36.788238
113		2.550000 x	20.419486 =	52.069689
6301		1.000000 x	6.453556 =	6.453556
T 630.1		.250000 x	1.874320 =	.468580
T 630		.250000 x	1.743328 =	.435832
T 623		.800000 x	17.661424 =	14.129139
T 617		.500000 x	6.107474 =	3.053737
511		.034000 x	718.602575 =	24.432488
509		.007548 x	377.710670 =	2.850960
509		.004718 x	377.710670 =	1.782039
			T.E =	172.134258
6360.1	6360.1			
6360.1 A1		1.000000 x	112.450050 =	112.450050
6360.1 A5		1.000000 x	99.479046 =	99.479046
6360.1 A4		1.000000 x	32.080765 =	32.080765
6360.1 A3		1.000000 x	14.410814 =	14.410814
6360.1 A2		1.000000 x	7.995546 =	7.995546
			AΘΡΟΙΣΜΑ =	266.416221
	T.E =	.200000 x	266.416221 =	53.283244
6360.2	6360.2			
6360.2 A1		1.000000 x	120.906090 =	120.906090
6360.2 A2		1.000000 x	11.119154 =	11.119154
6360.2 A3		1.000000 x	18.773514 =	18.773514
6360.2 A5		1.000000 x	113.359609 =	113.359609
6360.2 A4		1.000000 x	35.318760 =	35.318760
			AΘΡΟΙΣΜΑ =	299.477127
	T.E =	.200000 x	299.477127 =	59.895425
6360.3	6360.3			
6360.3 A1		1.000000 x	160.237455 =	160.237455
6360.3 A2		1.000000 x	15.771185 =	15.771185
6360.3 A3		1.000000 x	42.246205 =	42.246205
6360.3 A5		1.000000 x	156.796526 =	156.796526
6360.3 A4		1.000000 x	42.290998 =	42.290998
			AΘΡΟΙΣΜΑ =	417.342369
	T.E =	.200000 x	417.342369 =	83.468474

6360.4	6360.4			
6360.4 A1		1.000000 x	209.981004 =	209.981004
6360.4 A3		1.000000 x	63.259217 =	63.259217
6360.4 A2		1.000000 x	21.370832 =	21.370832
6360.4 A4		1.000000 x	35.318760 =	35.318760
6360.4 A5		1.000000 x	211.592709 =	211.592709

			AΘΡΟΙΣΜΑ =	541.522522
	T.E =	.200000 x	541.522522 =	108.304504

6360.5	6360.5			
6360.5 A1		1.000000 x	240.566091 =	240.566091
6360.5 A2		1.000000 x	26.660099 =	26.660099
6360.5 A5		1.000000 x	289.570654 =	289.570654
6360.5 A4		1.000000 x	36.583371 =	36.583371
6360.5 A3		1.000000 x	70.261789 =	70.261789

			AΘΡΟΙΣΜΑ =	663.642004
	T.E =	.200000 x	663.642004 =	132.728401

6360.6	6360.6			
6360.6 A1		1.000000 x	292.555679 =	292.555679
6360.6 A5		1.000000 x	382.601472 =	382.601472
6360.6 A4		1.000000 x	35.318760 =	35.318760
6360.6 A3		1.000000 x	82.559141 =	82.559141
6360.6 A2		1.000000 x	40.037928 =	40.037928

			AΘΡΟΙΣΜΑ =	833.072980
	T.E =	.200000 x	833.072980 =	166.614596

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	36.950000 =	.110850

			T.E =	16.916619
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	20.419486 =	4.339141
111		.212500 x	15.741598 =	3.345090

			T.E =	8.339230

6372	6372				
396.11		1.050000 x	2.560000 =	2.688000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.741598 =	5.352143	
113		.340000 x	20.419486 =	6.942625	

			T.E =	16.221769	
6373	6373				
396.12		1.050000 x	3.680000 =	3.864000	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	20.471461	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	240.000000 =	.120000	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	147.639854 =	1.697858	
652.2		.005500 x	167.505859 =	.921282	

			T.E =	24.254986	
6403	6403				
251		.000500 x	290.000000 =	.145000	
113		.850000 x	20.419486 =	17.356563	
652.2		.005500 x	167.505859 =	.921282	
652		.016500 x	147.639854 =	2.436058	
111		.850000 x	15.741598 =	13.380358	

			T.E =	34.239261	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
652		.020000 x	147.639854 =	2.952797	
113		1.700000 x	20.419486 =	34.713126	

			T.E =	57.736461	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.736461 =	57.736461	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	147.639854 =	2.952797

			T.E =	26.999539
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	22,025.000000 =	22,025.000000
386.9		.150000 x	22,025.000000 =	3,303.750000

			T.E =	25,328.750000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	65,938.000000 =	65,938.000000
386.40		.150000 x	65,938.000000 =	9,890.700000

			T.E =	75,828.700000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	97,056.000000 =	97,056.000000
386.30		.150000 x	97,056.000000 =	14,558.400000

			T.E =	111,614.400000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17			
386.64		1.000000 x	131,886.000000 =	131,886.000000
386.64		.150000 x	131,886.000000 =	19,782.900000
			T.E =	151,668.900000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000
			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000
			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000
			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000
			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000
			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000
			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000
			T.E =	

6453.6	6453.6			
386.53		1.000000 x	115,055.000000 =	115,055.000000
386.53		.150000 x	115,055.000000 =	17,258.250000

			T.E =	132,313.250000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	18,474.000000 =	18,474.000000
387.3		.100000 x	18,474.000000 =	1,847.400000

			T.E =	20,321.400000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.742500 =	154.440000
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.553000 =	186.914000

			AΘΡΟΙΣΜΑ =	3,500.248505

			T.E =	5,250.372757
6456.2	6456.2			
234.2		336.000000 x	.742500 =	249.480000
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.553000 =	301.938000

			AΘΡΟΙΣΜΑ =	5,654.247551

			T.E =	7,915.946572
6456.3	6456.3			
234.2		384.000000 x	.742500 =	285.120000
235		624.000000 x	.553000 =	345.072000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,461.997161

			T.E =	9,046.796025
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	5,720.000000 =	5,720.000000
389.4		.200000 x	5,720.000000 =	1,144.000000

			T.E =	6,864.000000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	4,833.000000 =	4,833.000000
390.14		.150000 x	4,833.000000 =	724.950000

			T.E =	5,557.950000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	7,028.000000 =	7,028.000000
390.31		.150000 x	7,028.000000 =	1,054.200000

			T.E =	8,082.200000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	13,185.000000 =	13,185.000000
393.1		.150000 x	13,185.000000 =	1,977.750000

			T.E =	15,162.750000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000

			T.E =	6.320000
6501	6501			
237		1.000000 x	1.090000 =	1.090000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.446563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,113.374089 =	89.818399

			T.E =	92.761458
6505	6505			
233		1.050000 x	.559800 =	.587790
113		.042500 x	20.419486 =	.867828

			T.E =	1.455618

6506	6506				
233.1		1.050000 x	.559800 =	.587790	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.455618	
6551.1	6551.1				
221		6.000000 x	.098900 =	.593400	
113		.255000 x	20.419486 =	5.206969	
111		.255000 x	15.741598 =	4.014107	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	24.914476	
6551.2	6551.2				
221		8.000000 x	.098900 =	.791200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	15.741598 =	4.683125	
113		.297500 x	20.419486 =	6.074797	

			T.E =	37.849122	
6551.3	6551.3				
221		10.000000 x	.098900 =	.989000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.683769	
6551.4	6551.4				
221		13.000000 x	.098900 =	1.285700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	20.419486 =	10.413938	
111		.510000 x	15.741598 =	8.028215	

			T.E =	66.427853	
6551.5	6551.5				
221		16.000000 x	.098900 =	1.582400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.198245	

6551.6	6551.6			
221		20.000000 x	.098900 =	1.978000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.814921

6551.7	6551.7			
221		26.000000 x	.098900 =	2.571400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 254.976782

6552	6552			
221		26.000000 x	.098900 =	2.571400
6304		6.890000 x	5.642760 =	38.878616
6310		32.020000 x	1.455618 =	46.608888
6329.2		.418000 x	165.415528 =	69.143691
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 209.998157

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.009285 =	27.587483
6329.2		.478000 x	165.415528 =	79.068622
6304		9.290000 x	5.642760 =	52.421240

T.E = 176.433909

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
113		.025500 x	20.419486 =	.520697
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	12.080000 =	12.080000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

			T.E =	26.586354
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.630000 =	15.630000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

			T.E =	30.872118
6611.3	6611.3			
361.3		1.000000 x	19.830000 =	19.830000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

			T.E =	38.080494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	37.840000 =	37.840000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

			T.E =	65.182368
6611.6	6611.6			
361.6		1.000000 x	50.600000 =	50.600000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

			T.E =	82.422273

6611.7	6611.7			
361.7		1.000000 x	78.130000 =	78.130000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	115.969024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.161813
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.902521
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.332089
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.741598 =	10.423299
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098

			T.E =	101.104384
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.741598 =	13.246555
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213

			T.E =	126.764443
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.741598 =	16.819110
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218

			T.E =	158.723104
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	20.419486 =	4.807768
112		.131750 x	17.312112 =	2.280871
111		.080750 x	15.741598 =	1.271134

			T.E =	20.497773
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.741598 =	2.060575
112		.212500 x	17.312112 =	3.678824
113		.299200 x	20.419486 =	6.109510

			T.E =	31.004509
6622.3	6622.3			
373.3		1.020000 x	24.500000 =	24.990000
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	39.468692

6623	6623				
360.2		1.000000 x	2.180000 =	2.180000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	5.841136	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	230.985083	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,026.449968	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,119.076304	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	253.548524	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	278.323537	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	335.731812	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	412.733204	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	505.879230	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	654.043125	

6630.8	6630.8				
376.19		1.000000 x	336.580000 =	336.580000	
111		5.340550 x	15.741598 =	84.068791	
113		2.261000 x	20.419486 =	46.168458	
113		2.669850 x	20.419486 =	54.516965	
113		2.550000 x	20.419486 =	52.069689	
112		9.044000 x	17.312112 =	156.570741	

			T.E =	729.974644	
6630.9	6630.9				
376.20		1.000000 x	400.990000 =	400.990000	
111		6.461700 x	15.741598 =	101.717484	
113		2.737000 x	20.419486 =	55.888133	
113		2.550000 x	20.419486 =	52.069689	
113		2.936750 x	20.419486 =	59.966926	
112		10.948000 x	17.312112 =	189.533002	

			T.E =	860.165234	
6640.1	6640.1				
377.1		1.000000 x	.000000 =	.000000	
113		2.550000 x	20.419486 =	52.069689	
113		1.667700 x	20.419486 =	34.053577	
111		1.334500 x	15.741598 =	21.007163	
112		3.043000 x	17.312112 =	52.680757	

			T.E =		
6640.2	6640.2				
377.2		1.000000 x	.000000 =	.000000	
113		2.550000 x	20.419486 =	52.069689	
113		2.002600 x	20.419486 =	40.892063	
112		3.570000 x	17.312112 =	61.804240	
111		1.922700 x	15.741598 =	30.266370	

			T.E =		
6640.3	6640.3				
377.3		1.000000 x	.000000 =	.000000	
111		2.617150 x	15.741598 =	41.198123	
112		4.658000 x	17.312112 =	80.639818	
113		2.550000 x	20.419486 =	52.069689	
113		2.336650 x	20.419486 =	47.713192	

			T.E =		

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.741598 =	53.815801
112	5.882000 x	17.312112 =	101.829843
113	2.669850 x	20.419486 =	54.516965
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.741598 =	68.106024
113	3.003900 x	20.419486 =	61.338094
113	2.550000 x	20.419486 =	52.069689
112	8.126000 x	17.312112 =	140.678222

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	20.419486 =	52.069689
113	3.337100 x	20.419486 =	68.141867
112	9.044000 x	17.312112 =	156.570741
111	5.340550 x	15.741598 =	84.068791

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.741598 =	101.717484
112	10.948000 x	17.312112 =	189.533002
113	3.671150 x	20.419486 =	74.962996
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.741598 =	121.065482
112	13.396000 x	17.312112 =	231.913052
113	2.550000 x	20.419486 =	52.069689
113	4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	7.650000 =	7.650000

			T.E =	7.650000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		.100000 x	.000000 =	.000000
381.7		1.000000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7 6662.7

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.5	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.8	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.8 6662.8

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.6	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.1 6663.1

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.4	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.2 6663.2

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6701.1 6701.1

368.1	1.020000 x	.000000 =	.000000
369.1	.224000 x	.000000 =	.000000
113	.068000 x	20.419486 =	1.388525
111	.382500 x	15.741598 =	6.021161

T.E =

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

			T.E =	
6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251
113		.238000 x	20.419486 =	4.859838

			T.E =	
6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

			T.E =	
6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

			T.E =	

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

			T.E =	
6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	132.464988 =	43.382284
113		.026350 x	20.419486 =	.538053
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.741598 =	1.873250
113		.040800 x	20.419486 =	.833115
6326		.352500 x	132.464988 =	46.693908

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.741598 =	2.542268
6326		.372500 x	132.464988 =	49.343208
113		.051000 x	20.419486 =	1.041394

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
6326		.382500 x	132.464988 =	50.667858
113		.063750 x	20.419486 =	1.301742

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	132.464988 =	51.826927
113		.068000 x	20.419486 =	1.388525
111		.187000 x	15.741598 =	2.943679

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
113		.076500 x	20.419486 =	1.562091
6327		.393750 x	155.049215 =	61.050628

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.741598 =	4.549322
6327		.431250 x	155.049215 =	66.864974
113		.093500 x	20.419486 =	1.909222

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	155.049215 =	77.524608
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	23.640419 =	8.746955
113		.017000 x	20.419486 =	.347131
111		.161500 x	15.741598 =	2.542268

T.E = 20.316554

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.741598 =	2.943679
6069		.390000 x	23.640419 =	9.219763
113		.021250 x	20.419486 =	.433914

T.E = 26.193956

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.741598 =	3.211286
6069		.400000 x	23.640419 =	9.456168
113		.026350 x	20.419486 =	.538053

			T.E =	34.411307
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
6069		.420000 x	23.640419 =	9.928976
113		.040800 x	20.419486 =	.833115

			T.E =	48.965395
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	23.640419 =	10.165380
113		.051000 x	20.419486 =	1.041394
111		.289000 x	15.741598 =	4.549322

			T.E =	59.412096
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	23.640419 =	10.401784
113		.063750 x	20.419486 =	1.301742
111		.297500 x	15.741598 =	4.683125

			T.E =	71.701252
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	23.640419 =	12.293018
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.143059
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	17.510000 =	17.510000

			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	104.272991 =	9.384569
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	114.162991 =	25.230021
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	114.162991 =	26.714140
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	114.162991 =	27.513281
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	104.272991 =	11.470029
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	104.272991 =	13.659762
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	104.272991 =	16.058041
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	104.272991 =	17.309317
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	104.272991 =	18.039227
113		.637500 x	20.419486 =	13.017422

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	114.162991 =	15.754493
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	114.162991 =	18.836894
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	114.162991 =	22.033457
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	104.272991 =	6.256379
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	114.162991 =	14.841189
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	114.162991 =	15.982819
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	114.162991 =	17.124449
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	104.272991 =	7.299109
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	104.272991 =	8.341839
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	104.272991 =	9.384569
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	104.272991 =	10.427299
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	104.272991 =	11.470029
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	114.162991 =	11.416299
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	114.162991 =	12.557929
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	114.162991 =	13.699559
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	104.272991 =	9.384569
652		.002500 x	147.639854 =	.369100
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E = 39.377827

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	114.162991 =	28.426585
652		.004500 x	147.639854 =	.664379
113		.340000 x	20.419486 =	6.942625

			T.E =	82.094362
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	114.162991 =	35.390527
652		.005000 x	147.639854 =	.738199
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

			T.E =	110.494750
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	114.162991 =	42.240307
652		.006500 x	147.639854 =	.959659
112		.680000 x	17.312112 =	11.772236

			T.E =	141.116975
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	104.272991 =	11.470029
652		.003000 x	147.639854 =	.442920
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	47.417107
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	104.272991 =	13.659762
652		.003500 x	147.639854 =	.516739
113		.297500 x	20.419486 =	6.074797

			T.E =	57.833271

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	104.272991 =	17.726408
652		.004500 x	147.639854 =	.664379
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648
			T.E =	71.394186
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	104.272991 =	23.565696
652		.005000 x	147.639854 =	.738199
112		.552500 x	17.312112 =	9.564942
			T.E =	98.669918
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	104.272991 =	28.570800
652		.006500 x	147.639854 =	.959659
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179
			T.E =	127.447468
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	114.162991 =	15.754493
652		.002500 x	147.639854 =	.369100
113		.255000 x	20.419486 =	5.206969
			T.E =	45.747751
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	114.162991 =	18.836894
652		.003000 x	147.639854 =	.442920
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
			T.E =	54.783972

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	114.162991 =	22.033457
652		.003500 x	147.639854 =	.516739
112		.382500 x	17.312112 =	6.621883

T.E = 66.206966

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	104.272991 =	9.384569
652		.002500 x	147.639854 =	.369100
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	114.162991 =	28.426585
652		.004500 x	147.639854 =	.664379
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	114.162991 =	35.390527
652		.005000 x	147.639854 =	.738199
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	114.162991 =	42.240307
652		.006500 x	147.639854 =	.959659
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2 6731.2

261.4	1.050000 x	.000000 =	.000000
6323	.110000 x	104.272991 =	11.470029
652	.003000 x	147.639854 =	.442920
113	.255000 x	20.419486 =	5.206969
112	.340000 x	17.312112 =	5.886118
111	.170000 x	15.741598 =	2.676072

T.E =

6731.3 6731.3

262.1	1.050000 x	.000000 =	.000000
111	.212500 x	15.741598 =	3.345090
112	.382500 x	17.312112 =	6.621883
6323	.131000 x	104.272991 =	13.659762
652	.003500 x	147.639854 =	.516739
113	.297500 x	20.419486 =	6.074797

T.E =

6731.4 6731.4

263.1	1.050000 x	.000000 =	.000000
6323	.170000 x	104.272991 =	17.726408
652	.004500 x	147.639854 =	.664379
111	.297500 x	15.741598 =	4.683125
113	.340000 x	20.419486 =	6.942625
112	.425000 x	17.312112 =	7.357648

T.E =

6731.5 6731.5

263.3	1.050000 x	.000000 =	.000000
111	.340000 x	15.741598 =	5.352143
113	.510000 x	20.419486 =	10.413938
6323	.226000 x	104.272991 =	23.565696
652	.005000 x	147.639854 =	.738199
112	.552500 x	17.312112 =	9.564942

T.E =

6731.6 6731.6

264.1	1.050000 x	.000000 =	.000000
6323	.274000 x	104.272991 =	28.570800
652	.006500 x	147.639854 =	.959659
113	.595000 x	20.419486 =	12.149594
112	.680000 x	17.312112 =	11.772236
111	.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	114.162991 =	15.754493
652		.002500 x	147.639854 =	.369100
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	114.162991 =	18.836894
652		.003000 x	147.639854 =	.442920
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	114.162991 =	22.033457
652		.003500 x	147.639854 =	.516739
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	132.464988 =	124.517089
6303		1.880000 x	20.173536 =	37.926248

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	132.464988 =	96.699441

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	132.464988 =	124.517089

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	132.464988 =	96.699441

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.173536 =	61.327549
6328		.400000 x	158.275528 =	63.310211

			T.E =	124.637761
6742.10	6742.10			
6303		7.520000 x	20.173536 =	151.704991
6328		2.110000 x	158.275528 =	333.961364

			T.E =	485.666355
6742.11	6742.11			
6303		8.030000 x	20.173536 =	161.993494
6328		2.430000 x	158.275528 =	384.609533

			T.E =	546.603027
6742.2	6742.2			
6303		3.500000 x	20.173536 =	70.607376
6328		.500000 x	158.275528 =	79.137764

			T.E =	149.745140
6742.3	6742.3			
6303		4.020000 x	20.173536 =	81.097615
6328		.630000 x	158.275528 =	99.713583

			T.E =	180.811197
6742.4	6742.4			
6303		4.530000 x	20.173536 =	91.386118
6328		.800000 x	158.275528 =	126.620422

			T.E =	218.006540

6742.5	6742.5			
6303		5.000000 x	20.173536 =	100.867680
6328		.950000 x	158.275528 =	150.361752

			T.E =	251.229432
6742.6	6742.6			
6303		5.530000 x	20.173536 =	111.559654
6328		1.170000 x	158.275528 =	185.182368

			T.E =	296.742022
6742.7	6742.7			
6303		6.040000 x	20.173536 =	121.848157
6328		1.410000 x	158.275528 =	223.168494

			T.E =	345.016652
6742.8	6742.8			
6303		6.520000 x	20.173536 =	131.531455
6328		1.610000 x	158.275528 =	254.823600

			T.E =	386.355055
6742.9	6742.9			
6303		7.040000 x	20.173536 =	142.021693
6328		1.880000 x	158.275528 =	297.557993

			T.E =	439.579686
6743.1	6743.1			
6303		3.040000 x	20.173536 =	61.327549
6328		.440000 x	158.275528 =	69.641232

			T.E =	130.968782
6743.10	6743.10			
6303		7.520000 x	20.173536 =	151.704991
6328		2.240000 x	158.275528 =	354.537183

			T.E =	506.242173
6743.11	6743.11			
6303		8.030000 x	20.173536 =	161.993494
6328		2.570000 x	158.275528 =	406.768107

			T.E =	568.761601

6743.12	6743.12			
6303		3.040000 x	20.173536 =	61.327549
6328		.750000 x	158.275528 =	118.706646

			T.E =	180.034195
6743.13	6743.13			
6303		3.500000 x	20.173536 =	70.607376
6328		.910000 x	158.275528 =	144.030730

			T.E =	214.638106
6743.14	6743.14			
6303		4.020000 x	20.173536 =	81.097615
6328		1.090000 x	158.275528 =	172.520326

			T.E =	253.617940
6743.15	6743.15			
6303		4.530000 x	20.173536 =	91.386118
6328		1.300000 x	158.275528 =	205.758186

			T.E =	297.144304
6743.16	6743.16			
6303		5.000000 x	20.173536 =	100.867680
6328		1.550000 x	158.275528 =	245.327068

			T.E =	346.194748
6743.17	6743.17			
6303		5.530000 x	20.173536 =	111.559654
6328		1.850000 x	158.275528 =	292.809727

			T.E =	404.369381
6743.2	6743.2			
6303		3.500000 x	20.173536 =	70.607376
6328		.550000 x	158.275528 =	87.051540

			T.E =	157.658916
6743.3	6743.3			
6303		4.020000 x	20.173536 =	81.097615
6328		.690000 x	158.275528 =	109.210114

			T.E =	190.307729

6743.4	6743.4			
6303		4.530000 x	20.173536 =	91.386118
6328		.860000 x	158.275528 =	136.116954

			T.E =	227.503072
6743.5	6743.5			
6303		5.000000 x	20.173536 =	100.867680
6328		1.020000 x	158.275528 =	161.441039

			T.E =	262.308719
6743.6	6743.6			
6303		5.530000 x	20.173536 =	111.559654
6328		1.260000 x	158.275528 =	199.427165

			T.E =	310.986819
6743.7	6743.7			
6303		6.040000 x	20.173536 =	121.848157
6328		1.500000 x	158.275528 =	237.413292

			T.E =	359.261449
6743.8	6743.8			
6303		6.520000 x	20.173536 =	131.531455
6328		1.720000 x	158.275528 =	272.233908

			T.E =	403.765363
6743.9	6743.9			
6303		7.040000 x	20.173536 =	142.021693
6328		2.000000 x	158.275528 =	316.551056

			T.E =	458.572749
6744	6744			
111		2.125000 x	15.741598 =	33.450896
111		4.250000 x	15.741598 =	66.901792
112		2.125000 x	17.312112 =	36.788238
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408

			T.E =	223.923741

6751	6751				
234.2		.400000 x	.742500 =	.297000	
235		.650000 x	.553000 =	.359450	
113		.170000 x	20.419486 =	3.471313	
113		.051000 x	20.419486 =	1.041394	

			T.E =	5.169156	
6752	6752				
237		1.050000 x	1.090000 =	1.144500	
113		.017000 x	20.419486 =	.347131	
111		.025500 x	15.741598 =	.401411	

			T.E =	1.893042	
6753	6753				
237		1.050000 x	1.090000 =	1.144500	
112		.085000 x	17.312112 =	1.471530	
113		.085000 x	20.419486 =	1.735656	

			T.E =	4.351686	
6754	6754				
237.1		1.000000 x	1.235000 =	1.235000	
112		.017000 x	17.312112 =	.294306	
111		.051000 x	15.741598 =	.802821	
113		.212500 x	20.419486 =	4.339141	

			T.E =	6.671268	
6801	6801				
232		.700000 x	1.785000 =	1.249500	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	20.419486 =	52.069689	
112		1.700000 x	17.312112 =	29.430590	
111		.850000 x	15.741598 =	13.380358	

			T.E =	98.450138	
6802	6802				
231		15.000000 x	.695000 =	10.425000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	20.419486 =	52.069689	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	15.741598 =	66.901792	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	147.639854 =	1.771678
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.519144
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	147.639854 =	17.716782
113		.680000 x	20.419486 =	13.885250

			T.E =	39.630248
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	147.639854 =	.295280
2522		.005000 x	151.838657 =	.759193
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	17.409242
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	132.464988 =	.662325
652		.002000 x	147.639854 =	.295280

			T.E =	13.252373
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.050000 =	18.330000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.050000 =	9.165000

			T.E =	83.272715

6811	6811			
236		6.430000 x	.523000 =	3.362890
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.050000 =	22.207500

			T.E =	112.353206
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
243		11.900000 x	1.900000 =	22.610000
6324		.250000 x	109.217991 =	27.304498
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179

			AΘΡΟΙΣΜΑ =	158.192492
	T.E =	.262500 x	158.192492 =	41.525529

7001	7001			
7001 A		1.000000 x	.223928 =	.223928
7001 Δ		1.000000 x	.305395 =	.305395
7001 Ε		1.000000 x	.786226 =	.786226
7001 Γ		1.000000 x	.946785 =	.946785
7001 Β		1.000000 x	.726509 =	.726509

			AΘΡΟΙΣΜΑ =	2.988843

			T.E =	3.437169
7002	7002			
560		.005104 x	648.625490 =	3.310585

			T.E =	3.310585
7003	7003			
7003 A		1.000000 x	.111964 =	.111964
7003 Δ		1.000000 x	.758666 =	.758666
7003 Γ		1.000000 x	.534406 =	.534406
7003 Β		1.000000 x	.564876 =	.564876

			AΘΡΟΙΣΜΑ =	1.969912

			T.E =	2.166903
7004	7004			
561		.003250 x	847.609990 =	2.754732

			T.E =	2.754732

7005	7005			
7005 Α		1.000000 x	.111964 =	.111964
7005 Ε		1.000000 x	.758666 =	.758666
7005 Δ		1.000000 x	.534406 =	.534406
7005 Γ		1.000000 x	.282438 =	.282438
7005 Β		1.000000 x	.988534 =	.988534

			ΑΘΡΟΙΣΜΑ =	2.676008

			T.E =	2.943609
7006	7006			
561		.001723 x	847.609990 =	1.460432
561		.000812 x	847.609990 =	.688259
561		.000862 x	847.609990 =	.730640

			T.E =	2.879331
7007	7007			
213		.100000 x	1.895000 =	.189500
550		.003500 x	1,026.027486 =	3.591096
518		.001750 x	817.140042 =	1.429995
502		.000583 x	763.436973 =	.445084
116		.280000 x	20.419486 =	5.717456

			T.E =	11.373131
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
7007		1.100000 x	11.373131 =	12.510444
558		.000972 x	1,037.869457 =	1.008809
507		.000875 x	875.132707 =	.765741
503		.001750 x	865.126473 =	1.513971

			T.E =	19.765083
7009	7009			
560		.006417 x	648.625490 =	4.162230

			T.E =	4.162230
7010	7010			
7010 Α		1.000000 x	.326929 =	.326929
7010 Δ		1.000000 x	.305395 =	.305395
7010 Ε		1.000000 x	.944683 =	.944683
7010 Γ		1.000000 x	.534406 =	.534406
7010 Β		1.000000 x	.490912 =	.490912

			ΑΘΡΟΙΣΜΑ =	2.602325

			T.E =	2.992674

7011	7011			
502		.001367 x	763.436973 =	1.043618
502		.000700 x	763.436973 =	.534406
503		.000438 x	865.126473 =	.378925
563		.001367 x	.000000 =	.000000
558		.000729 x	1,037.869457 =	.756607
558		.000729 x	1,037.869457 =	.756607
554		.000438 x	33.418000 =	.014637

			ΑΘΡΟΙΣΜΑ =	3.484800

			T.E =	
7012	7012			
7008		1.000000 x	19.765083 =	19.765083

			ΑΘΡΟΙΣΜΑ =	19.765083

			T.E =	21.741591
7013	7013			
7003		1.000000 x	2.166903 =	2.166903

			ΑΘΡΟΙΣΜΑ =	2.166903

			T.E =	2.383593
7014	7014			
7005		1.000000 x	2.943609 =	2.943609

			ΑΘΡΟΙΣΜΑ =	2.943609

			T.E =	3.237970
7015	7015			
111		.056000 x	15.741598 =	.881529
7001		.900000 x	3.437169 =	3.093452
X 630		.300000 x	1.435682 =	.430705
X 630.1		.300000 x	1.543557 =	.463067

			T.E =	4.868753
7016.9	7016.9			
7016.4		1.000000 x	124.215590 =	124.215590
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	24.843118 =	24.843118
7016.7		1.000000 x	80.282150 =	80.282150
7016.6		1.000000 x	37.264677 =	37.264677

			T.E =	370.744914

7017.8	7017.8				
7017.3		1.000000 x	91.355308 =		91.355308
7017.4		1.000000 x	18.271062 =		18.271062
7017.5		1.000000 x	32.887911 =		32.887911
7017.7		1.000000 x	52.069689 =		52.069689
7017.6		1.000000 x	80.282150 =		80.282150

			T.E =		274.866120
7018	7018				
233.2		1.150000 x	.591200 =		.679880
113		.051000 x	20.419486 =		1.041394

			AΘΡΟΙΣΜΑ =		1.721274

			T.E =		1.893401
7019	7019				
7019 A6		1.000000 x	189.689457 =		189.689457
7019 A7		1.000000 x	18.968946 =		18.968946

			T.E =		208.658403
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	208.658403 =		208.658403

			T.E =		202.758403
7020	7020				
213		.150000 x	1.895000 =		.284250
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,414.412517 =		37.346844

			T.E =		57.642190
7020.1	7020.1				
570.2		.350000 x	124.784076 =		43.674427
571.2		.070000 x	259.459536 =		18.162168
571.1		.280000 x	409.295190 =		114.602653

			AΘΡΟΙΣΜΑ =		176.439247
	T.E =	.015625 x	176.439247 =		2.756863

7021	7021				
213		.150000 x	1.895000 =		.284250
116		1.120000 x	20.419486 =		22.869824
7021.2		.014583 x	2,993.001663 =		43.646943

			T.E =		66.801018

7021.1	7021.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	409.295190 =	114.602653
			AΘΡΟΙΣΜΑ =	176.439247
	T.E =	.020833 x	176.439247 =	3.675759
7022	7022			
213		.150000 x	1.895000 =	.284250
116		1.400000 x	20.419486 =	28.587280
7022.2		.020000 x	2,755.293583 =	55.105872
			T.E =	83.977402
7022.1	7022.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	409.295190 =	114.602653
			AΘΡΟΙΣΜΑ =	176.439247
	T.E =	.028571 x	176.439247 =	5.041046
7023	7023			
398.2		1.050000 x	42.300000 =	44.415000
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
550		.012143 x	1,026.027486 =	12.459052
			T.E =	80.920794
7024	7024			
398.3		1.050000 x	48.000000 =	50.400000
116		.850000 x	20.419486 =	17.356563
550		.020238 x	1,026.027486 =	20.764744
111		.425000 x	15.741598 =	6.690179
			T.E =	95.211487
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	147.639854 =	.147640
550		.020238 x	1,026.027486 =	20.764744
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.559800 =	3.459564
398.4		1.000000 x	64.000000 =	64.000000
			T.E =	119.786958

7026	7026				
398.5		125.400000 x	5.780000 =	724.812000	
236		16.808000 x	.523000 =	8.790584	
113		3.400000 x	20.419486 =	69.426252	
6310		12.350000 x	1.455618 =	17.976882	
113		.909160 x	20.419486 =	18.564580	
			AΘΡΟΙΣΜΑ =	839.570299	
	T.E =	.007259 x	839.570299 =	6.094441	
7027	7027				
236		1.100000 x	.523000 =	.575300	
113		.059500 x	20.419486 =	1.214959	
			T.E =	1.790259	
7028	7028				
111		.144500 x	15.741598 =	2.274661	
112		.144500 x	17.312112 =	2.501600	
6751		.600000 x	5.169156 =	3.101494	
6751		.120000 x	5.169156 =	.620299	
111		.425000 x	15.741598 =	6.690179	
			AΘΡΟΙΣΜΑ =	15.188233	
			T.E =	17.466467	
7029	7029				
568.1		.021250 x	2,568.746520 =	54.585864	
569.2		.021250 x	612.976952 =	13.025760	
571.2		.021250 x	259.459536 =	5.513515	
570.2		.021250 x	124.784076 =	2.651662	
			T.E =	75.776801	
7030	7030				
398.6		.015385 x	330.000000 =	5.077050	
572		.026563 x	832.067377 =	22.102206	
			AΘΡΟΙΣΜΑ =	27.179256	
			T.E =	38.050958	
7031	7031				
573		.106250 x	1,059.709952 =	112.594182	
			AΘΡΟΙΣΜΑ =	112.594182	
			T.E =	129.483310	
7032	7032				
573		.212500 x	1,059.709952 =	225.188365	
			AΘΡΟΙΣΜΑ =	225.188365	
			T.E =	292.744874	

7101.1	7101.1				
398.1		15.000000 x	.225000 =		3.375000
574		.132813 x	3,395.885082 =		451.017685
T 630		.105000 x	1.743328 =		.183049
T 630.1		.105000 x	1.874320 =		.196804
567		.132813 x	362.622872 =		48.161031
				ΑΘΡΟΙΣΜΑ =	502.933570
				T.E =	518.021577
7101.2	7101.2				
398.1		15.000000 x	.225000 =		3.375000
T 630		.105000 x	1.743328 =		.183049
T 630.1		.105000 x	1.874320 =		.196804
574		.148750 x	3,395.885082 =		505.137906
567		.148750 x	362.622872 =		53.940152
				ΑΘΡΟΙΣΜΑ =	562.832911
				T.E =	579.717899
7101.3	7101.3				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.874320 =		.196804
T 630		.105000 x	1.743328 =		.183049
574		.159375 x	3,395.885082 =		541.219185
567		.159375 x	362.622872 =		57.793020
				ΑΘΡΟΙΣΜΑ =	602.767058
				T.E =	620.850070
7101.4	7101.4				
398.1		15.000000 x	.225000 =		3.375000
567		.170000 x	362.622872 =		61.645888
574		.170000 x	3,395.885082 =		577.300464
T 630.1		.105000 x	1.874320 =		.196804
T 630		.105000 x	1.743328 =		.183049
				ΑΘΡΟΙΣΜΑ =	642.701205
				T.E =	661.982241
7101.5	7101.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.874320 =		.196804
567		.191250 x	362.622872 =		69.351624
T 630		.105000 x	1.743328 =		.183049
574		.191250 x	3,395.885082 =		649.463022
				ΑΘΡΟΙΣΜΑ =	722.569499
				T.E =	744.246584

7102.1	7102.1				
398.1		15.000000 x	.225000 =		3.375000
567		.302813 x	362.622872 =		109.806920
T 630		.105000 x	1.743328 =		.183049
T 630.1		.105000 x	1.874320 =		.196804
574		.302813 x	3,395.885082 =		1,028.318149
			AΘΡΟΙΣΜΑ =		1,141.879922
			T.E =		1,176.136320
7102.2	7102.2				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.874320 =		.196804
T 630		.105000 x	1.743328 =		.183049
574		.329375 x	3,395.885082 =		1,118.519649
567		.329375 x	362.622872 =		119.438908
			AΘΡΟΙΣΜΑ =		1,241.713410
			T.E =		1,278.964813
7102.3	7102.3				
398.1		15.000000 x	.225000 =		3.375000
567		.361250 x	362.622872 =		130.997513
T 630		.105000 x	1.743328 =		.183049
T 630.1		.105000 x	1.874320 =		.196804
574		.361250 x	3,395.885082 =		1,226.763486
			AΘΡΟΙΣΜΑ =		1,361.515851
			T.E =		1,402.361327
7102.4	7102.4				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.874320 =		.196804
T 630		.105000 x	1.743328 =		.183049
574		.403750 x	3,395.885082 =		1,371.088602
567		.403750 x	362.622872 =		146.408985
			AΘΡΟΙΣΜΑ =		1,521.252439
			T.E =		1,566.890013
7102.5	7102.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.874320 =		.196804
T 630		.105000 x	1.743328 =		.183049
567		.446250 x	362.622872 =		161.820457
574		.446250 x	3,395.885082 =		1,515.413718
			AΘΡΟΙΣΜΑ =		1,680.989028
			T.E =		1,731.418698

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	818.655658 =	86.982164

			T.E =	163.736562
7104	7104			
113		1.700000 x	20.419486 =	34.713126
576		.106250 x	7.425000 =	.788906
567		.106250 x	362.622872 =	38.528680

			T.E =	74.030713
7105	7105			
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563
576		.106250 x	7.425000 =	.788906
567		.106250 x	362.622872 =	38.528680

			T.E =	70.054508
7106.1	7106.1			
577		.265625 x	652.735019 =	173.382739

			AΘΡΟΙΣΜΑ =	173.382739

			T.E =	182.051876
7106.2	7106.2			
577		.297500 x	652.735019 =	194.188668

			AΘΡΟΙΣΜΑ =	194.188668

			T.E =	203.898102
7106.3	7106.3			
577		.350625 x	652.735019 =	228.865216

			AΘΡΟΙΣΜΑ =	228.865216

			T.E =	240.308477
7106.4	7106.4			
577		.425000 x	652.735019 =	277.412383

			AΘΡΟΙΣΜΑ =	277.412383

			T.E =	291.283002

7106.5	7106.5			
577		.531250 x	652.735019 =	346.765479

			ΑΘΡΟΙΣΜΑ =	346.765479

			T.E =	364.103753
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	182.051876 =	182.051876

			T.E =	222.851876
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	203.898102 =	203.898102

			T.E =	244.698102
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	240.308477 =	240.308477

			T.E =	281.108477
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	291.283002 =	291.283002

			T.E =	332.083002
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	364.103753 =	364.103753

			T.E =	404.903753
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,395.885082 =	180.406395

			T.E =	317.176395
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,395.885082 =	180.406395

			T.E =	357.286395

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,395.885082 =		180.406395

			T.E =		342.720495
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,395.885082 =		180.406395

			T.E =		330.166395
7112	7112				
398.13		1.300000 x	9.400000 =		12.220000
577		.010625 x	652.735019 =		6.935310

			T.E =		19.155310
7113	7113				
241		1.200000 x	7.050000 =		8.460000
574		.001063 x	3,395.885082 =		3.609826

			T.E =		12.069826
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	652.735019 =		34.676548

			T.E =		38.366548
7115	7115				
574		.026563 x	3,395.885082 =		90.204895

			T.E =		90.204895
7116	7116				
577		.170000 x	652.735019 =		110.964953

			T.E =		110.964953
7117	7117				
574		.001063 x	3,395.885082 =		3.609826

			T.E =		3.609826

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	622.552766 =	529.169851
574.1		.425000 x	2,184.957688 =	928.607017

			T.E =	1,885.948334
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,184.957688 =	1,857.214035
578		.850000 x	622.552766 =	529.169851

			T.E =	3,028.641084
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	382.917688 =	97.644010

			T.E =	311.729743
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	382.917688 =	227.836024

			T.E =	441.921757
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
575.1		.425000 x	257.177416 =	109.300402
578		.425000 x	622.552766 =	264.584926

			T.E =	534.449627
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	622.552766 =	793.754777
575.1		1.275000 x	257.177416 =	327.901205

			T.E =	1,389.263148
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	622.552766 =	264.584926

			T.E =	374.496542

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	622.552766 =	264.584926
			T.E =	374.496542
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.743328 =	.183049
T 630.1		.105000 x	1.874320 =	.196804
567		.122188 x	362.622872 =	44.308163
580		.122188 x	1,645.013982 =	201.000968
			AΘΡΟΙΣΜΑ =	249.063985
			T.E =	256.535905
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.874320 =	.196804
T 630		.105000 x	1.743328 =	.183049
580		.286875 x	1,645.013982 =	471.913386
567		.286875 x	362.622872 =	104.027436
			AΘΡΟΙΣΜΑ =	579.695676
			T.E =	597.086546
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	362.622872 =	23.117208
T 630		.105000 x	1.743328 =	.183049
T 630.1		.105000 x	1.874320 =	.196804
580		.063750 x	1,645.013982 =	104.869641
			T.E =	131.741702
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.874320 =	.196804
567		.127500 x	362.622872 =	46.234416
T 630		.105000 x	1.743328 =	.183049
580		.127500 x	1,645.013982 =	209.739283
			T.E =	259.728552
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,645.013982 =	87.391368
			T.E =	149.811368

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,645.013982 =		26.218233

			T.E =		114.775533
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,645.013982 =		26.218233

			T.E =		94.791933
7129	7129				
6751		1.000000 x	5.169156 =		5.169156

			T.E =		5.169156