

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

1ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.140600
212	1.362600
213	1.949500
214	4.160000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.825000
232	2.020000
233	.556800
233.1	.556800
233.2	.609600
233.3	8.000000
234	.912400
234.1	1.088400
234.2	.967200
234.3	1.012500
235	.664600
236	.643700
237	1.165000
237.1	1.320000
241	7.750000
242	5.000000
243	2.250000
244	2.590000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.330000
361.1	12.930000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	16.730000
361.3	21.230000
361.4	
361.5	40.530000
361.6	54.080000
361.7	83.670000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	111,963.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	76,065.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	132,726.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	152,143.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	25,408.000000
387.1	
387.2	
387.3	21,310.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,598.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,574.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	8,107.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	15,210.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.960000
396.12	4.250000
396.13	1.770000
396.14	38.800000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.950000
397.4	.167500
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	10.300000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	93.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	6.180000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
419	4.400000
420	94.500000
421	31.630000
428	425.280000
429	75.360000
450	81.440000
451	4.730000
452	100.100000
453	
454	94.500000
455	30.380000
456	34.030000
457	444.570000
458	276.840000
459	409.940000
460	506.910000
461	232.170000
462	338.520000
463	42.540000
464	372.560000
465	99.670000
466	46.490000
467	338.520000
468	84.780000
469	84.780000
470	68.370000
471	59.250000
472	25.750000
473	16.560000
474	34.030000
475	1,913.860000
476	82.950000
477	6.750000
478	111.820000
479	179.890000
480	26.440000
481	789.180000

501	501				
401		1.000000 x	260.720000 =	260.720000	
211		50.000000 x	1.140600 =	57.030000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	551.322593	

			Η.Δ. =	606.454852	
502	502				
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	4.160000 =	29.120000	
211		80.000000 x	1.140600 =	91.248000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	720.731612	

			Η.Δ. =	792.804773	
503	503				
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	1.140600 =	125.466000	
118		4.000000 x	10.001019 =	40.004076	

			ΑΘΡΟΙΣΜΑ =	823.439612	

			Η.Δ. =	905.783573	
504	504				
403		1.000000 x	100.390000 =	100.390000	
214		2.000000 x	4.160000 =	8.320000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	1.140600 =	45.624000	

			ΑΘΡΟΙΣΜΑ =	345.423536	

			Η.Δ. =	379.965890	
505	505				
404		1.000000 x	206.630000 =	206.630000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	4.160000 =	41.600000	
211		200.000000 x	1.140600 =	228.120000	

			ΑΘΡΟΙΣΜΑ =	747.447688	

			Η.Δ. =	822.192457	

506	506				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	4.160000 =	24.960000	
211		95.000000 x	1.140600 =	108.357000	

			ΑΘΡΟΙΣΜΑ =	617.704688	

			Η.Δ. =	679.475157	
507	507				
406		1.000000 x	311.770000 =	311.770000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	4.160000 =	41.600000	
211		165.000000 x	1.140600 =	188.199000	

			ΑΘΡΟΙΣΜΑ =	847.666688	

			Η.Δ. =	932.433357	
508	508				
407		1.000000 x	53.630000 =	53.630000	
116		16.000000 x	20.419486 =	326.711776	
211		40.000000 x	1.140600 =	45.624000	
214		2.000000 x	4.160000 =	8.320000	
115		4.000000 x	21.778427 =	87.113708	
408		2.000000 x	4.400000 =	8.800000	

			ΑΘΡΟΙΣΜΑ =	530.199484	

			Η.Δ. =	583.219432	
509	509				
409		1.000000 x	122.460000 =	122.460000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	4.160000 =	20.800000	
211		80.000000 x	1.140600 =	91.248000	

			ΑΘΡΟΙΣΜΑ =	368.731336	

			Η.Δ. =	405.604470	
510	510				
410		1.000000 x	113.190000 =	113.190000	
117		8.000000 x	16.777917 =	134.223336	
211		80.000000 x	1.140600 =	91.248000	
214		5.000000 x	4.160000 =	20.800000	

			ΑΘΡΟΙΣΜΑ =	359.461336	

			Η.Δ. =	395.407470	

511	511				
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	4.160000 =	4.160000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.778427 =	87.113708	
212		17.000000 x	1.362600 =	23.164200	

				ΑΘΡΟΙΣΜΑ =	660.381268

				Η.Δ. =	726.419395
512	512				
412		1.000000 x	2.900000 =	2.900000	
214		1.000000 x	4.160000 =	4.160000	
115		2.000000 x	21.778427 =	43.556854	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	1.140600 =	11.406000	

				ΑΘΡΟΙΣΜΑ =	96.647078

				Η.Δ. =	106.311786
513	513				
413		1.000000 x	4.400000 =	4.400000	
211		15.000000 x	1.140600 =	17.109000	
115		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	4.160000 =	6.240000	

				ΑΘΡΟΙΣΜΑ =	145.020617

				Η.Δ. =	159.522679
514	514				
414		1.000000 x	6.070000 =	6.070000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	4.160000 =	8.320000	
211		21.000000 x	1.140600 =	23.952600	

				ΑΘΡΟΙΣΜΑ =	194.704756

				Η.Δ. =	214.175232
515	515				
415		1.000000 x	8.530000 =	8.530000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.778427 =	108.892135	
214		2.500000 x	4.160000 =	10.400000	
211		27.000000 x	1.140600 =	30.796200	

				ΑΘΡΟΙΣΜΑ =	262.491007

				Η.Δ. =	288.740108

516	516				
416		1.000000 x	13.150000 =	13.150000	
115		6.000000 x	21.778427 =	130.670562	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	4.160000 =	14.560000	
211		33.000000 x	1.140600 =	37.639800	

				ΑΘΡΟΙΣΜΑ =	334.517258

				Η.Δ. =	367.968984
517	517				
406		1.000000 x	311.770000 =	311.770000	
406		.400000 x	311.770000 =	124.708000	
116		8.000000 x	20.419486 =	163.355888	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	4.160000 =	33.280000	
211		240.000000 x	1.140600 =	273.744000	
407		2.000000 x	53.630000 =	107.260000	

				ΑΘΡΟΙΣΜΑ =	1,992.633172

				Η.Δ. =	2,191.896489
518	518				
417		1.000000 x	130.670000 =	130.670000	
118		8.000000 x	10.001019 =	80.008152	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.362600 =	6.813000	
214		12.000000 x	4.160000 =	49.920000	
114		8.000000 x	23.886192 =	191.089536	
211		180.000000 x	1.140600 =	205.308000	

				ΑΘΡΟΙΣΜΑ =	802.305584

				Η.Δ. =	882.536142
520	520				
419		1.000000 x	4.400000 =	4.400000	
211		80.000000 x	1.140600 =	91.248000	
212		2.000000 x	1.362600 =	2.725200	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.778427 =	174.227416	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	4.160000 =	20.800000	

				ΑΘΡΟΙΣΜΑ =	402.653140

				Η.Δ. =	442.918454

521	521				
420		1.000000 x	94.500000 =	94.500000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	
211		40.000000 x	1.140600 =	45.624000	

				ΑΘΡΟΙΣΜΑ =	383.697612

				Η.Δ. =	422.067373
522	522				
421		1.000000 x	31.630000 =	31.630000	
114		8.000000 x	23.886192 =	191.089536	
118		2.000000 x	10.001019 =	20.002038	
214		2.000000 x	4.160000 =	8.320000	
211		20.000000 x	1.140600 =	22.812000	

				ΑΘΡΟΙΣΜΑ =	273.853574

				Η.Δ. =	301.238931
529	529				
429		1.000000 x	75.360000 =	75.360000	
211		70.000000 x	1.140600 =	79.842000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	4.160000 =	16.640000	

				ΑΘΡΟΙΣΜΑ =	402.935612

				Η.Δ. =	443.229173
550	550				
450		1.000000 x	81.440000 =	81.440000	
451		4.000000 x	4.730000 =	18.920000	
116		32.000000 x	20.419486 =	653.423552	
115		4.000000 x	21.778427 =	87.113708	
214		4.000000 x	4.160000 =	16.640000	
211		90.000000 x	1.140600 =	102.654000	

				ΑΘΡΟΙΣΜΑ =	960.191260

				Η.Δ. =	1,056.210386
551	551				
405		1.000000 x	200.790000 =	200.790000	
211		95.000000 x	1.140600 =	108.357000	
214		6.000000 x	4.160000 =	24.960000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
452		1.000000 x	100.100000 =	100.100000	

				ΑΘΡΟΙΣΜΑ =	705.304688

				Η.Δ. =	775.835157

552	552				
453		1.000000 x	.000000 =	.000000	
115		8.000000 x	21.778427 =	174.227416	
214		1.000000 x	4.160000 =	4.160000	
211		18.000000 x	1.140600 =	20.530800	

			ΑΘΡΟΙΣΜΑ =	198.918216	

			H.Δ. =		
553	553				
454		1.000000 x	94.500000 =	94.500000	
214		4.000000 x	4.160000 =	16.640000	
211		100.000000 x	1.140600 =	114.060000	

			ΑΘΡΟΙΣΜΑ =	225.200000	

			H.Δ. =	247.720000	
554	554				
455		1.000000 x	30.380000 =	30.380000	

			ΑΘΡΟΙΣΜΑ =	30.380000	

			H.Δ. =	33.418000	
555	555				
456		1.000000 x	34.030000 =	34.030000	
212		17.000000 x	1.362600 =	23.164200	
112		32.000000 x	17.312112 =	553.987584	
115		4.000000 x	21.778427 =	87.113708	
214		1.000000 x	4.160000 =	4.160000	

			ΑΘΡΟΙΣΜΑ =	702.455492	

			H.Δ. =	772.701041	
556	556				
457		1.000000 x	444.570000 =	444.570000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
214		18.000000 x	4.160000 =	74.880000	
211		200.000000 x	1.140600 =	228.120000	

			ΑΘΡΟΙΣΜΑ =	1,018.667688	

			H.Δ. =	1,120.534457	
557	557				
458		1.000000 x	276.840000 =	276.840000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		11.000000 x	4.160000 =	45.760000	
211		130.000000 x	1.140600 =	148.278000	

			ΑΘΡΟΙΣΜΑ =	741.975688	

			H.Δ. =	816.173257	

558	558				
459		1.000000 x	409.940000 =	409.940000	
214		12.000000 x	4.160000 =	49.920000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	1.140600 =	228.120000	

				ΑΘΡΟΙΣΜΑ =	1,006.577688

				Η.Δ. =	1,107.235457
559	559				
460		1.000000 x	506.910000 =	506.910000	
211		250.000000 x	1.140600 =	285.150000	
214		15.000000 x	4.160000 =	62.400000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		12.000000 x	5.000000 =	60.000000	

				ΑΘΡΟΙΣΜΑ =	1,185.557688

				Η.Δ. =	1,304.113457
560	560				
461		1.000000 x	232.170000 =	232.170000	
114		8.000000 x	23.886192 =	191.089536	
211		160.000000 x	1.140600 =	182.496000	
214		8.000000 x	4.160000 =	33.280000	

				ΑΘΡΟΙΣΜΑ =	639.035536

				Η.Δ. =	702.939090
561	561				
462		1.000000 x	338.520000 =	338.520000	
214		12.000000 x	4.160000 =	49.920000	
114		8.000000 x	23.886192 =	191.089536	
211		230.000000 x	1.140600 =	262.338000	

				ΑΘΡΟΙΣΜΑ =	841.867536

				Η.Δ. =	926.054290
562	562				
463		1.000000 x	42.540000 =	42.540000	
214		2.400000 x	4.160000 =	9.984000	
211		50.000000 x	1.140600 =	57.030000	

				ΑΘΡΟΙΣΜΑ =	109.554000

				Η.Δ. =	120.509400

563	563			
211.1		640.000000 x	.000000 =	.000000
114		16.000000 x	23.886192 =	382.179072
112		24.000000 x	17.312112 =	415.490688
214		16.000000 x	4.160000 =	66.560000
464		1.000000 x	372.560000 =	372.560000

		ΑΘΡΟΙΣΜΑ =		1,236.789760

		H.Δ. =		
564	564			
465		1.000000 x	99.670000 =	99.670000
567		3.000000 x	392.805772 =	1,178.417316
111		8.000000 x	15.741598 =	125.932784
115		8.000000 x	21.778427 =	174.227416
115		8.000000 x	21.778427 =	174.227416

		ΑΘΡΟΙΣΜΑ =		1,752.474932

		H.Δ. =		1,927.722425
565	565			
450		3.000000 x	81.440000 =	244.320000
465		1.000000 x	99.670000 =	99.670000
115		8.000000 x	21.778427 =	174.227416
115		12.000000 x	21.778427 =	261.341124

		H.Δ. =		779.558540
566	566			
211.1		680.000000 x	.000000 =	.000000
466		1.000000 x	46.490000 =	46.490000
112		1.000000 x	17.312112 =	17.312112
115		2.000000 x	21.778427 =	43.556854

		ΑΘΡΟΙΣΜΑ =		107.358966

		H.Δ. =		
567	567			
450		1.000000 x	81.440000 =	81.440000
115		4.000000 x	21.778427 =	87.113708
112		4.000000 x	17.312112 =	69.248448
214		4.000000 x	4.160000 =	16.640000
211		90.000000 x	1.140600 =	102.654000

		ΑΘΡΟΙΣΜΑ =		357.096156

		H.Δ. =		392.805772

568.1	568.1				
467		1.000000 x	338.520000 =	338.520000	
567		2.000000 x	392.805772 =	785.611544	
512		.240000 x	106.311786 =	25.514829	
510		.072000 x	395.407470 =	28.469338	
118		32.000000 x	10.001019 =	320.032608	
114		8.000000 x	23.886192 =	191.089536	
113		32.000000 x	20.419486 =	653.423552	
214		16.000000 x	4.160000 =	66.560000	

			ΑΘΡΟΙΣΜΑ =	2,409.221406	

			Η.Δ. =	2,650.143547	
568.2	568.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
467		1.000000 x	338.520000 =	338.520000	
114		8.000000 x	23.886192 =	191.089536	

			Η.Δ. =	866.716952	
569.1	569.1				
468		1.000000 x	84.780000 =	84.780000	
214		16.000000 x	4.160000 =	66.560000	
567		2.000000 x	392.805772 =	785.611544	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

			ΑΘΡΟΙΣΜΑ =	1,208.049232	

			Η.Δ. =	1,328.854155	
569.2	569.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.778427 =	174.227416	
114		8.000000 x	23.886192 =	191.089536	
468		1.000000 x	84.780000 =	84.780000	

			Η.Δ. =	612.976952	
570.1	570.1				
469		1.000000 x	84.780000 =	84.780000	
211		135.000000 x	1.140600 =	153.981000	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
214		16.000000 x	4.160000 =	66.560000	

			ΑΘΡΟΙΣΜΑ =	536.414612	

			Η.Δ. =	590.056073	

570.2	570.2				
469		1.000000 x	84.780000 =	84.780000	
118		4.000000 x	10.001019 =	40.004076	

			H.Δ. =	124.784076	
571.1	571.1				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	4.160000 =	16.640000	
211		114.000000 x	1.140600 =	130.028400	

			ΑΘΡΟΙΣΜΑ =	406.127936	

			H.Δ. =	446.740730	
571.2	571.2				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	

			H.Δ. =	259.459536	
572	572				
407		1.000000 x	53.630000 =	53.630000	
471		1.000000 x	59.250000 =	59.250000	
114		8.000000 x	23.886192 =	191.089536	
214		8.000000 x	4.160000 =	33.280000	
111		24.000000 x	15.741598 =	377.798352	
211		54.000000 x	1.140600 =	61.592400	

			ΑΘΡΟΙΣΜΑ =	776.640288	

			H.Δ. =	854.304317	
573	573				
407		1.000000 x	53.630000 =	53.630000	
473		.250000 x	16.560000 =	4.140000	
474		.250000 x	34.030000 =	8.507500	
474		1.000000 x	34.030000 =	34.030000	
473		1.000000 x	16.560000 =	16.560000	
115		16.000000 x	21.778427 =	348.454832	
111		24.000000 x	15.741598 =	377.798352	
214		8.000000 x	4.160000 =	33.280000	
211		54.000000 x	1.140600 =	61.592400	
407		.250000 x	53.630000 =	13.407500	
472		.250000 x	25.750000 =	6.437500	
472		1.000000 x	25.750000 =	25.750000	

			ΑΘΡΟΙΣΜΑ =	983.588084	

			H.Δ. =	1,081.946892	

574	574				
475		1.000000 x	1,913.860000 =		1,913.860000
214		30.000000 x	4.160000 =		124.800000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
111		16.000000 x	15.741598 =		251.865568
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	1.140600 =		672.954000
				ΑΘΡΟΙΣΜΑ =	3,269.577256
				Η.Δ. =	3,596.534982
574.1	574.1				
475		1.000000 x	1,913.860000 =		1,913.860000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				Η.Δ. =	2,184.957688
575	575				
476		1.000000 x	82.950000 =		82.950000
214		23.000000 x	4.160000 =		95.680000
115		8.000000 x	21.778427 =		174.227416
211		470.000000 x	1.140600 =		536.082000
				ΑΘΡΟΙΣΜΑ =	888.939416
				Η.Δ. =	977.833358
575.1	575.1				
476		1.000000 x	82.950000 =		82.950000
115		8.000000 x	21.778427 =		174.227416
				Η.Δ. =	257.177416
576	576				
477		1.000000 x	6.750000 =		6.750000
				ΑΘΡΟΙΣΜΑ =	6.750000
				Η.Δ. =	7.425000
576.1	576.1				
477		1.000000 x	6.750000 =		6.750000
				Η.Δ. =	6.750000

577	577				
478		1.000000 x	111.820000 =	111.820000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	4.160000 =	16.640000	
211		70.000000 x	1.140600 =	79.842000	

				ΑΘΡΟΙΣΜΑ =	615.332472

				Η.Δ. =	676.865719
577.1	577.1				
478		1.000000 x	111.820000 =	111.820000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	382.917688
578	578				
479		1.000000 x	179.890000 =	179.890000	
211		50.000000 x	1.140600 =	57.030000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	4.160000 =	20.800000	

				ΑΘΡΟΙΣΜΑ =	583.062060

				Η.Δ. =	641.368266
579	579				
480		1.000000 x	26.440000 =	26.440000	
212		28.000000 x	1.362600 =	38.152800	
117		8.000000 x	16.777917 =	134.223336	
214		1.000000 x	4.160000 =	4.160000	

				ΑΘΡΟΙΣΜΑ =	202.976136

				Η.Δ. =	223.273750
580	580				
481		1.000000 x	789.180000 =	789.180000	
211		168.000000 x	1.140600 =	191.620800	
242		2.000000 x	5.000000 =	10.000000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
111		16.000000 x	15.741598 =	251.865568	
214		8.000000 x	4.160000 =	33.280000	

				ΑΘΡΟΙΣΜΑ =	1,547.044056

				Η.Δ. =	1,701.748462

581	581				
481		1.000000 x	789.180000 =		789.180000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				H.Δ. =	1,060.277688
7020.2	7020.2				
111		8.000000 x	15.741598 =		125.932784
571.2		.150000 x	259.459536 =		38.918930
571.1		.350000 x	446.740730 =		156.359256
570.2		.350000 x	124.784076 =		43.674427
570.1		.150000 x	590.056073 =		88.508411
569.2		.670000 x	612.976952 =		410.694558
569.1		.330000 x	1,328.854155 =		438.521871
568.2		.550000 x	866.716952 =		476.694324
568.1		.450000 x	2,650.143547 =		1,192.564596
567		1.000000 x	392.805772 =		392.805772
116		8.000000 x	20.419486 =		163.355888
				H.Δ. =	3,528.030816
7021.2	7021.2				
111		8.000000 x	15.741598 =		125.932784
571.2		.240000 x	259.459536 =		62.270289
571.1		.260000 x	446.740730 =		116.152590
570.2		.390000 x	124.784076 =		48.665790
570.1		.110000 x	590.056073 =		64.906168
569.2		.750000 x	612.976952 =		459.732714
116		8.000000 x	20.419486 =		163.355888
567		1.000000 x	392.805772 =		392.805772
568.1		.250000 x	2,650.143547 =		662.535887
569.1		.250000 x	1,328.854155 =		332.213539
568.2		.750000 x	866.716952 =		650.037714
				H.Δ. =	3,078.609134
7022.2	7022.2				
111		8.000000 x	15.741598 =		125.932784
571.2		.310000 x	259.459536 =		80.432456
571.1		.190000 x	446.740730 =		84.880739
570.2		.420000 x	124.784076 =		52.409312
570.1		.080000 x	590.056073 =		47.204486
569.2		.820000 x	612.976952 =		502.641101
569.1		.180000 x	1,328.854155 =		239.193748
568.2		.850000 x	866.716952 =		736.709409
568.1		.150000 x	2,650.143547 =		397.521532
567		1.000000 x	392.805772 =		392.805772
116		8.000000 x	20.419486 =		163.355888
				H.Δ. =	2,823.087226

613	613			
111		.140000 x	15.741598 =	2.203824
520		.003500 x	442.918454 =	1.550215
504		.002800 x	379.965890 =	1.063904
503		.000770 x	905.783573 =	.697453

			B.T =	5.515396
614	614			
112		.070000 x	17.312112 =	1.211848
503		.000700 x	905.783573 =	.634049
518		.004375 x	882.536142 =	3.861096
509		.004375 x	405.604470 =	1.774520
504		.002800 x	379.965890 =	1.063904

			B.T =	8.545416
621.1	621.1			
213		.100000 x	1.949500 =	.194950
116		.140000 x	20.419486 =	2.858728
504		.003500 x	379.965890 =	1.329881
508		.003500 x	583.219432 =	2.041268
111		.560000 x	15.741598 =	8.815295

			B.T =	15.240122
622	622			
213		.100000 x	1.949500 =	.194950
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728
509		.003500 x	405.604470 =	1.419616
508		.003500 x	583.219432 =	2.041268
518		.004340 x	882.536142 =	3.830207
504		.003500 x	379.965890 =	1.329881

			B.T =	12.886497
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.648144 =	55.351811
6330		.038000 x	181.753945 =	6.906650
6330		.190000 x	181.753945 =	34.533250
6314		.382500 x	2.028605 =	.775941
6314		7.650000 x	2.028605 =	15.518828

			B.T =	113.086480
6360.1 A2	6360.1 A2			
6304		.450000 x	5.648144 =	2.541665
6310		2.142000 x	1.452468 =	3.111186
6330		.013000 x	181.753945 =	2.362801

			B.T =	8.015653

6360.1 A3	6360.1 A3			
6304		.960000 x	5.648144 =	5.422218
6329.2		.037000 x	167.228380 =	6.187450
6310		1.974000 x	1.452468 =	2.867172

			B.T =	14.476840
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.648144 =	14.063879
6329.2		.109000 x	167.228380 =	18.227893

			B.T =	32.291772
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
113		.425000 x	20.419486 =	8.678282
6069.1		.056400 x	11.589809 =	.653665

			B.T =	99.510508
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.648144 =	60.152734
6314		.392500 x	2.028605 =	.796227
6314		7.850000 x	2.028605 =	15.924549
6330		.041000 x	181.753945 =	7.451912
6330		.205000 x	181.753945 =	37.259559

			B.T =	121.584981
6360.2 A2	6360.2 A2			
6304		.750000 x	5.648144 =	4.236108
6330		.019000 x	181.753945 =	3.453325
6310		2.383500 x	1.452468 =	3.461957

			B.T =	11.151390
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.648144 =	6.438884
6310		2.341500 x	1.452468 =	3.400954
6329.2		.054000 x	167.228380 =	9.030333

			B.T =	18.870171
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.648144 =	15.814803
6329.2		.118000 x	167.228380 =	19.732949

			B.T =	35.547752

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
113		.382500 x	20.419486 =	7.810453
113		2.975000 x	20.419486 =	60.747971
6069.1		.059400 x	11.589809 =	.688435

			B.T =	113.392744
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.648144 =	78.509202
6314		.557500 x	2.028605 =	1.130947
6314		11.150000 x	2.028605 =	22.618946
6330		.270000 x	181.753945 =	49.073565
6330		.054000 x	181.753945 =	9.814713

			B.T =	161.147373
6360.3 A2	6360.3 A2			
6304		.940000 x	5.648144 =	5.309255
6330		.031000 x	181.753945 =	5.634372
6310		3.360000 x	1.452468 =	4.880292

			B.T =	15.823920
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.648144 =	10.336104
6310		10.678500 x	1.452468 =	15.510180
6329.2		.099000 x	167.228380 =	16.555610

			B.T =	42.401893
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.648144 =	19.316652
6329.2		.139000 x	167.228380 =	23.244745

			B.T =	42.561397
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		.340000 x	20.419486 =	6.942625
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.589809 =	.855328

			B.T =	156.837695

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.648144 =	91.782340
6314		.885000 x	2.028605 =	1.795315
6314		17.700000 x	2.028605 =	35.906309
6330		.075000 x	181.753945 =	13.631546
6330		.375000 x	181.753945 =	68.157729

			B.T =	211.273239
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.648144 =	5.987033
6330		.048000 x	181.753945 =	8.724189
6310		4.641000 x	1.452468 =	6.740904

			B.T =	21.452126
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.648144 =	12.821287
6310		20.454000 x	1.452468 =	29.708780
6329.2		.125000 x	167.228380 =	20.903548

			B.T =	63.433615
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.648144 =	15.814803
6329.2		.118000 x	167.228380 =	19.732949

			B.T =	35.547752
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		.297500 x	20.419486 =	6.074797
113		4.250000 x	20.419486 =	86.782816
6069.1		.091800 x	11.589809 =	1.063944

			B.T =	211.643919
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.648144 =	101.384185
6314		1.050000 x	2.028605 =	2.130035
6314		21.000000 x	2.028605 =	42.600705
6330		.088000 x	181.753945 =	15.994347
6330		.440000 x	181.753945 =	79.971736

			B.T =	242.081008
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.648144 =	6.890736
6330		.061000 x	181.753945 =	11.086991
6310		6.048000 x	1.452468 =	8.784526

			B.T =	26.762253

6360.5 A3	6360.5 A3			
6304		2.480000 x	5.648144 =	14.007397
6310		22.291500 x	1.452468 =	32.377690
6329.2		.144000 x	167.228380 =	24.080887

			B.T =	70.465974
6360.5 A4	6360.5 A4			
6304		3.200000 x	5.648144 =	18.074061
6329.2		.112000 x	167.228380 =	18.729579

			B.T =	36.803639
6360.5 A5	6360.5 A5			
112		9.350000 x	17.312112 =	161.868247
113		5.950000 x	20.419486 =	121.495942
113		.255000 x	20.419486 =	5.206969
6069.1		.090600 x	11.589809 =	1.050037

			B.T =	289.621195
6360.6 A1	6360.6 A1			
6304		20.350000 x	5.648144 =	114.939730
6314		24.900000 x	2.028605 =	50.512265
6330		.116000 x	181.753945 =	21.083458
6330		.580000 x	181.753945 =	105.417288
6314		1.245000 x	2.028605 =	2.525613

			B.T =	294.478354
6360.6 A2	6360.6 A2			
6304		1.530000 x	5.648144 =	8.641660
6330		.092000 x	181.753945 =	16.721363
6310		10.206000 x	1.452468 =	14.823888

			B.T =	40.186912
6360.6 A3	6360.6 A3			
6304		2.670000 x	5.648144 =	15.080544
6329.2		.181000 x	167.228380 =	30.268337
6310		25.798500 x	1.452468 =	37.471496

			B.T =	82.820377
6360.6 A4	6360.6 A4			
6304		2.800000 x	5.648144 =	15.814803
6329.2		.118000 x	167.228380 =	19.732949

			B.T =	35.547752

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	.212500 x	20.419486 =	4.339141
6069.1	.120000 x	11.589809 =	1.390777
113	7.650000 x	20.419486 =	156.209068

B.T = 382.668414

641

641

231	.200000 x	.825000 =	.165000
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
111	.170000 x	15.741598 =	2.676072
252	.002500 x	290.000000 =	.725000

B.T = 6.604556

651

651

221	150.000000 x	.099900 =	14.985000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	405.604470 =	3.826878
509	.003060 x	405.604470 =	1.241150
T 630	.600000 x	1.807300 =	1.084380
T 625	.850000 x	21.682376 =	18.430020
511	.042500 x	726.419395 =	30.872824
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 106.268437

652

652

221	650.000000 x	.099900 =	64.935000
T 630	.320000 x	1.807300 =	.578336
T 625	1.000000 x	21.682376 =	21.682376
511	.042500 x	726.419395 =	30.872824
509	.001632 x	405.604470 =	.661946
509	.009435 x	405.604470 =	3.826878
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648

B.T = 149.985546

652.1

652.1

221	450.000000 x	.099900 =	44.955000
111	1.275000 x	15.741598 =	20.070537
509	.010001 x	405.604470 =	4.056450
T 630	.320000 x	1.807300 =	.578336
T 625	1.060000 x	21.682376 =	22.983319
511	.042500 x	726.419395 =	30.872824
510	.001632 x	395.407470 =	.645305
112	.425000 x	17.312112 =	7.357648

B.T = 131.519419

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
509		.007548 x	405.604470 =	3.061503
T 630		.320000 x	1.807300 =	.578336
T 625		.800000 x	21.682376 =	17.345901
511		.042500 x	726.419395 =	30.872824
510		.001632 x	395.407470 =	.645305
111		1.275000 x	15.741598 =	20.070537
112		.425000 x	17.312112 =	7.357648

			B.T =	169.842054
700	700			
397.4		4.000000 x	.167500 =	.670000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.099900 =	1.298700
113		.935000 x	20.419486 =	19.092219

			B.T =	
7001 A	7001 A			
502		.000365 x	792.804773 =	.289374
557		.001094 x	816.173257 =	.892894

			AΘΡΟΙΣΜΑ =	1.182267
	B.T =	.200000 x	1.182267 =	.236453

7001 B	7001 B			
558		.000700 x	1,107.235457 =	.775065

			B.T =	.775065
7001 E	7001 E			
503		.000875 x	905.783573 =	.792561
554		.000875 x	33.418000 =	.029241

			B.T =	.821801
7001 Γ	7001 Γ			
501		.000700 x	606.454852 =	.424518
502		.000700 x	792.804773 =	.554963

			B.T =	.979482

7001 Δ	7001 Δ			
502		.000292 x	792.804773 =	.231499
510		.000292 x	395.407470 =	.115459
X 630.1		.060000 x	1.660711 =	.099643
X 630		.060000 x	1.488365 =	.089302

			AΘΡΟΙΣΜΑ =	.535903
	B.T =	.600000 x	.535903 =	.321542

7003 Α	7003 Α			
502		.000365 x	792.804773 =	.289374
557		.001094 x	816.173257 =	.892894

			AΘΡΟΙΣΜΑ =	1.182267
	B.T =	.100000 x	1.182267 =	.118227

7003 Β	7003 Β			
559		.000464 x	1,304.113457 =	.605109

			B.T =	.605109
7003 Γ	7003 Γ			
502		.000700 x	792.804773 =	.554963

			B.T =	.554963
7003 Δ	7003 Δ			
502		.000875 x	792.804773 =	.693704
562		.000875 x	120.509400 =	.105446

			B.T =	.799150
7005 Α	7005 Α			
502		.000365 x	792.804773 =	.289374
557		.001094 x	816.173257 =	.892894

			AΘΡΟΙΣΜΑ =	1.182267
	B.T =	.100000 x	1.182267 =	.118227

7005 Β	7005 Β			
559		.000812 x	1,304.113457 =	1.058940

			B.T =	1.058940
7005 Ε	7005 Ε			
502		.000875 x	792.804773 =	.693704
562		.000875 x	120.509400 =	.105446

			B.T =	.799150

7005 Γ	7005 Γ			
559		.000232 x	1,304.113457 =	.302554

			B.T =	.302554
7005 Δ	7005 Δ			
502		.000700 x	792.804773 =	.554963

			B.T =	.554963
7010 Α	7010 Α			
558		.000315 x	1,107.235457 =	.348779

			B.T =	.348779
7010 Β	7010 Β			
558		.000473 x	1,107.235457 =	.523722

			B.T =	.523722
7010 Ε	7010 Ε			
503		.000875 x	905.783573 =	.792561
553		.000875 x	247.720000 =	.216755

			B.T =	1.009316
7010 Γ	7010 Γ			
502		.000700 x	792.804773 =	.554963

			B.T =	.554963
7010 Δ	7010 Δ			
502		.000292 x	792.804773 =	.231499
X 630		.060000 x	1.488365 =	.089302
X 630.1		.060000 x	1.660711 =	.099643
510		.000292 x	395.407470 =	.115459

			AΘΡΟΙΣΜΑ =	.535903
	B.T =	.600000 x	.535903 =	.321542

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.830000 x	18.456706 =	15.319066
T 617		.500000 x	6.364954 =	3.182477
509		.007831 x	405.604470 =	3.176289
509		.004718 x	405.604470 =	1.913642
223		350.000000 x	.119300 =	41.755000

			B.T =	78.692443

7016.2	7016.2			
570.1		.586500 x	590.056073 =	346.067887
570.2		1.113500 x	124.784076 =	138.947069
571.2		1.113500 x	259.459536 =	288.908193
571.1		.586500 x	446.740730 =	262.013438

			AΘΡΟΙΣΜΑ =	1,035.936587
	B.T =	.025000 x	1,035.936587 =	25.898415

7016.3	7016.3			
564		.212500 x	1,927.722425 =	409.641015
565		.637500 x	779.558540 =	496.968569

			AΘΡΟΙΣΜΑ =	906.609585
	B.T =	.025000 x	906.609585 =	22.665240

7016.4	7016.4			
7016.1		1.000000 x	78.692443 =	78.692443
7016.2		1.000000 x	25.898415 =	25.898415
7016.3		1.000000 x	22.665240 =	22.665240

			B.T =	127.256098
7016.5	7016.5			
7016.4		.200000 x	127.256098 =	25.451220

			B.T =	25.451220
7016.6	7016.6			
7016.4		.250000 x	127.256098 =	31.814025
7016.5		.250000 x	25.451220 =	6.362805

			B.T =	38.176830
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.830000 x	18.456706 =	15.319066
T 617		.500000 x	6.364954 =	3.182477
509		.007831 x	405.604470 =	3.176289
509		.004718 x	405.604470 =	1.913642
223		350.000000 x	.119300 =	41.755000

			B.T =	78.692443
7017.2	7017.2			
564		.425000 x	1,927.722425 =	819.282031
565		.425000 x	779.558540 =	331.312380

			ΑΘΡΟΙΣΜΑ =	1,150.594410
	B.T =	.012500 x	1,150.594410 =	14.382430

7017.3	7017.3			
7017.1		1.000000 x	78.692443 =	78.692443
7017.2		1.000000 x	14.382430 =	14.382430

			B.T =	93.074873
7017.4	7017.4			
7017.3		.200000 x	93.074873 =	18.614975

			B.T =	18.614975
7017.5	7017.5			
7017.3		.300000 x	93.074873 =	27.922462
7017.4		.300000 x	18.614975 =	5.584493

			B.T =	33.506954
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689

			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
509		.004718 x	405.604470 =	1.913642
509		.007548 x	405.604470 =	3.061503
223		350.000000 x	.119300 =	41.755000

			B.T =	79.192667
7019 A2	7019 A2			
555		.012143 x	772.701041 =	9.382909

			B.T =	9.382909
7019 A3	7019 A3			
570.1		.850000 x	590.056073 =	501.547662
571.1		.850000 x	446.740730 =	379.729621
571.2		.850000 x	259.459536 =	220.540606
570.2		.850000 x	124.784076 =	106.066465

			ΑΘΡΟΙΣΜΑ =	1,207.884353
	B.T =	.014286 x	1,207.884353 =	17.255836

7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563

			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	79.192667 =	79.192667
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A2		1.000000 x	9.382909 =	9.382909
7019 A3		1.000000 x	17.255836 =	17.255836
7019 A5		1.000000 x	17.356563 =	17.356563

			B.T =	192.425429
7019 A7	7019 A7			
7019 A6		.100000 x	192.425429 =	19.242543

			B.T =	19.242543

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
252		.001000 x	290.000000 =	.290000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	379.965890 =	1.909329
509		.003750 x	405.604470 =	1.521017

			B.T =	3.430345
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	442.918454 =	2.334180
504		.004250 x	379.965890 =	1.614855
503		.001190 x	905.783573 =	1.077882

			B.T =	6.364954
T 621	T 621			
213		.100000 x	1.949500 =	.194950
508		.004250 x	583.219432 =	2.478683
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.849232
T 623	T 623			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
509		.004250 x	405.604470 =	1.723819
518		.008500 x	882.536142 =	7.501557
508		.004250 x	583.219432 =	2.478683
504		.004250 x	379.965890 =	1.614855
116		.170000 x	20.419486 =	3.471313

			B.T =	18.456706

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
518		.012155 x	882.536142 =	10.727227
509		.004250 x	405.604470 =	1.723819
508		.004250 x	583.219432 =	2.478683
504		.004250 x	379.965890 =	1.614855

			B.T =	21.682376
T 630	T 630			
512		.017000 x	106.311786 =	1.807300

			B.T =	1.807300
T 630.1	T 630.1			
510		.005100 x	395.407470 =	2.016578

			B.T =	2.016578
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
503		.000980 x	905.783573 =	.887668
520		.004340 x	442.918454 =	1.922266
504		.003500 x	379.965890 =	1.329881

			B.T =	5.241726
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	583.219432 =	2.041268
116		.140000 x	20.419486 =	2.858728
111		.560000 x	15.741598 =	8.815295

			B.T =	13.910241
X 623	X 623			
213		.100000 x	1.949500 =	.194950
508		.003500 x	583.219432 =	2.041268
518		.007000 x	882.536142 =	6.177753
509		.003500 x	405.604470 =	1.419616
504		.003500 x	379.965890 =	1.329881
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	15.234043

X 625	X 625			
213		.100000 x	1.949500 =	.194950
518		.010010 x	882.536142 =	8.834187
509		.003500 x	405.604470 =	1.419616
508		.003500 x	583.219432 =	2.041268
504		.003500 x	379.965890 =	1.329881
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	17.890477
X 630	X 630			
512		.014000 x	106.311786 =	1.488365

			B.T =	1.488365
X 630.1	X 630.1			
510		.004200 x	395.407470 =	1.660711

			B.T =	1.660711
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	405.604470 =	1.913642
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.007548 x	405.604470 =	3.061503
509		.001275 x	405.604470 =	.517146
T 625		.500000 x	21.682376 =	10.841188
641		3.000000 x	6.604556 =	19.813668
T 630		.250000 x	1.807300 =	.451825

			T.E =	154.404510
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	405.604470 =	7.860615

			T.E =	74.762406
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	405.604470 =	3.275256

			T.E =	43.416331
6051	6051			
502		.000175 x	792.804773 =	.138741

			T.E =	.138741

6052	6052			
501		.000117 x	606.454852 =	.070955
502		.000088 x	792.804773 =	.069767
521		.000088 x	422.067373 =	.037142

			T.E =	.177864
6053	6053			
502		.000318 x	792.804773 =	.252112
507		.001000 x	932.433357 =	.932433

			T.E =	1.184545
6054	6054			
112		.004900 x	17.312112 =	.084829
509		.002975 x	405.604470 =	1.206673
507		.001077 x	932.433357 =	1.004231

			T.E =	2.295733
6055	6055			
213		.400000 x	1.949500 =	.779800
503		.001167 x	905.783573 =	1.057049
508		.007000 x	583.219432 =	4.082536
504		.001400 x	379.965890 =	.531952
112		.490000 x	17.312112 =	8.482935
116		.280000 x	20.419486 =	5.717456

			T.E =	20.651729
6056	6056			
507		.001750 x	932.433357 =	1.631758

			T.E =	1.631758
6057	6057			
506		.087500 x	679.475157 =	59.454076

			T.E =	59.454076
6058	6058			
507		.087500 x	932.433357 =	81.587919

			T.E =	81.587919
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
507		.001077 x	932.433357 =	1.004231
509		.002975 x	405.604470 =	1.206673
501		.000583 x	606.454852 =	.353563
502		.001400 x	792.804773 =	1.109927

			T.E =	3.795579
6062	6062			
213		.400000 x	1.949500 =	.779800
509		.002800 x	405.604470 =	1.135693
508		.002800 x	583.219432 =	1.633014
507		.001400 x	932.433357 =	1.305407
502		.002000 x	792.804773 =	1.585610
116		.175000 x	20.419486 =	3.573410
112		.175000 x	17.312112 =	3.029620

			T.E =	13.042553
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.070000 x	17.312112 =	1.211848
509		.003641 x	405.604470 =	1.476806
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.442676
6064	6064			
112		.140000 x	17.312112 =	2.423696
509		.003641 x	405.604470 =	1.476806
507		.014000 x	932.433357 =	13.054067
112		.070000 x	17.312112 =	1.211848

			T.E =	18.166416
6065	6065			
506		.002800 x	679.475157 =	1.902530
506		.002100 x	679.475157 =	1.426898

			T.E =	3.329428

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	792.804773 =	.554963

			T.E =	1.656875
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630		.100000 x	1.488365 =	.148837
X 630.1		.100000 x	1.660711 =	.166071

			T.E =	15.741674
6068	6068			
111		.560000 x	15.741598 =	8.815295
622		1.351351 x	12.886497 =	17.414181
X 630.1		.200000 x	1.660711 =	.332142
X 630		.200000 x	1.488365 =	.297673
112		.560000 x	17.312112 =	9.694783
509		.016497 x	405.604470 =	6.691257

			T.E =	43.245330
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
X 630.1		.200000 x	1.660711 =	.332142
X 630		.200000 x	1.488365 =	.297673
614		1.351351 x	8.545416 =	11.547856
509		.016497 x	405.604470 =	6.691257
112		.560000 x	17.312112 =	9.694783

			T.E =	37.379006
6069	6069			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	405.604470 =	4.874149
X 625		1.050000 x	17.890477 =	18.785001

			T.E =	24.870998
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	405.604470 =	4.874149
X 617		1.050000 x	5.241726 =	5.503812

			T.E =	11.589809
6070	6070			
501		.000467 x	606.454852 =	.283214

			T.E =	.283214

6071	6071			
504		.002333 x	379.965890 =	.886460
509		.002975 x	405.604470 =	1.206673

			T.E =	2.093134
6072	6072			
504		.003500 x	379.965890 =	1.329881
509		.002800 x	405.604470 =	1.135693

			T.E =	2.465573
6073	6073			
509		.000833 x	405.604470 =	.337869

			T.E =	.337869
6074	6074			
509		.000784 x	405.604470 =	.317994

			T.E =	.317994
6075	6075			
509		.001096 x	405.604470 =	.444542

			T.E =	.444542
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	905.783573 =	.634049
509		.003914 x	405.604470 =	1.587536
507		.000840 x	932.433357 =	.783244

			T.E =	3.089658
6077	6077			
503		.001400 x	905.783573 =	1.268097

			T.E =	1.268097
6078	6078			
112		.004900 x	17.312112 =	.084829
505		.001400 x	822.192457 =	1.151069
501		.000056 x	606.454852 =	.033961
503		.000350 x	905.783573 =	.317024

			T.E =	1.586885

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
501		.000056 x	606.454852 =	.033961
503		.000350 x	905.783573 =	.317024
556		.001400 x	1,120.534457 =	1.568748

			T.E =	2.004563
6079	6079			
112		.014000 x	17.312112 =	.242370
501		.000700 x	606.454852 =	.424518
529		.000980 x	443.229173 =	.434365
X 630		.150000 x	1.488365 =	.223255
509		.000630 x	405.604470 =	.255531
502		.000350 x	792.804773 =	.277482

			T.E =	1.857520
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.660711 =	.166071
X 630		.100000 x	1.488365 =	.148837
529		.000700 x	443.229173 =	.310260
502		.000292 x	792.804773 =	.231499
501		.000583 x	606.454852 =	.353563

			T.E =	1.452600
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087
506		.007000 x	679.475157 =	4.756326

			T.E =	23.486276
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.486276 =	23.486276

			T.E =	35.717242
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.486276 =	23.486276
112		.140000 x	17.312112 =	2.423696

			T.E =	47.948209

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.486276 =	23.486276
112		.210000 x	17.312112 =	3.635544

			T.E =	60.179175
6082.1	6082.1			
213		.400000 x	1.949500 =	.779800
111		1.400000 x	15.741598 =	22.038237
116		.700000 x	20.419486 =	14.293640
508		.070000 x	583.219432 =	40.825360
116		1.400000 x	20.419486 =	28.587280

			T.E =	106.524318
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
6082.1		1.000000 x	106.524318 =	106.524318
112		.140000 x	17.312112 =	2.423696

			T.E =	119.967132
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	106.524318 =	106.524318
112		.280000 x	17.312112 =	4.847391

			T.E =	133.409947
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
112		.420000 x	17.312112 =	7.271087
6082.1		1.000000 x	106.524318 =	106.524318

			T.E =	146.852761
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.280000 x	17.312112 =	4.847391
506		.005833 x	679.475157 =	3.963379
112		.140000 x	17.312112 =	2.423696

			T.E =	15.642113
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.642113 =	15.642113
112		.070000 x	17.312112 =	1.211848

			T.E =	25.669256

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.642113 =	15.642113

			T.E =	35.696398
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
112		.210000 x	17.312112 =	3.635544
6083.1		1.000000 x	15.642113 =	15.642113

			T.E =	45.723541
6084.1	6084.1			
213		.400000 x	1.949500 =	.779800
111		1.470000 x	15.741598 =	23.140149
116		.700000 x	20.419486 =	14.293640
508		.035000 x	583.219432 =	20.412680
116		1.050000 x	20.419486 =	21.440460

			T.E =	80.066730
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
112		.105000 x	17.312112 =	1.817772
6084.1		1.000000 x	80.066730 =	80.066730

			T.E =	90.699797
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	80.066730 =	80.066730

			T.E =	101.332863
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
112		.315000 x	17.312112 =	5.453315
6084.1		1.000000 x	80.066730 =	80.066730

			T.E =	111.965930
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	679.475157 =	3.170431
502		.001400 x	792.804773 =	1.109927
112		.140000 x	17.312112 =	2.423696

			T.E =	8.907877

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	8.907877 =	8.907877

			T.E =	15.629284
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	8.907877 =	8.907877

			T.E =	22.350691
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	8.907877 =	8.907877

			T.E =	29.072098
6086.1	6086.1			
213		.400000 x	1.949500 =	.779800
508		.008750 x	583.219432 =	5.103170
111		1.120000 x	15.741598 =	17.630590
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456

			T.E =	39.236564
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
112		.105000 x	17.312112 =	1.817772
6086.1		1.000000 x	39.236564 =	39.236564

			T.E =	46.563895
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
6086.1		1.000000 x	39.236564 =	39.236564
112		.210000 x	17.312112 =	3.635544

			T.E =	53.891226
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
6086.1		1.000000 x	39.236564 =	39.236564
112		.315000 x	17.312112 =	5.453315

			T.E =	61.218557

6087	6087				
252		.001000 x	290.000000 =	.290000	
113		.210000 x	20.419486 =	4.288092	
112		.350000 x	17.312112 =	6.059239	
111		.210000 x	15.741598 =	3.305736	

			T.E =	13.943067	
6088	6088				
6081.1		1.000000 x	23.486276 =	23.486276	
6081.1		.900000 x	23.486276 =	21.137648	

			T.E =	44.623924	
6089	6089				
6082.1		1.000000 x	106.524318 =	106.524318	
6082.1		.900000 x	106.524318 =	95.871886	

			T.E =	202.396204	
6090	6090				
6083.1		1.000000 x	15.642113 =	15.642113	
6083.1		1.300000 x	15.642113 =	20.334747	

			T.E =	35.976860	
6091	6091				
6084.1		1.000000 x	80.066730 =	80.066730	
6084.1		1.300000 x	80.066730 =	104.086749	

			T.E =	184.153479	
6100	6100				
231		.200000 x	.825000 =	.165000	
111		.175000 x	15.741598 =	2.754780	
251		.002000 x	290.000000 =	.580000	
113		.105000 x	20.419486 =	2.144046	
252.1		.002000 x	.000000 =	.000000	

			T.E =		
6101	6101				
231		15.000000 x	.825000 =	12.375000	
252		.018000 x	290.000000 =	5.220000	
113		3.500000 x	20.419486 =	71.468201	
112		3.500000 x	17.312112 =	60.592392	
252.1		.020000 x	.000000 =	.000000	
251		.068000 x	290.000000 =	19.720000	

			T.E =		

6102	6102			
244		1.000000 x	2.590000 =	2.590000
509		.000051 x	405.604470 =	.020686
112		.001400 x	17.312112 =	.024237
506		.000070 x	679.475157 =	.047563
506		.000070 x	679.475157 =	.047563
112		.002100 x	17.312112 =	.036355

			T.E =	2.766405
6103	6103			
244		.125000 x	2.590000 =	.323750
509		.000102 x	405.604470 =	.041372
506		.000140 x	679.475157 =	.095127
506		.000140 x	679.475157 =	.095127
112		.002800 x	17.312112 =	.048474
112		.004200 x	17.312112 =	.072711

			T.E =	.676559
6104	6104			
236		3.000000 x	.643700 =	1.931100
113		.280000 x	20.419486 =	5.717456
111		.280000 x	15.741598 =	4.407647
517		.017500 x	2,191.896489 =	38.358189

			T.E =	50.414392
6105	6105			
111		.210000 x	15.741598 =	3.305736
517		.014000 x	2,191.896489 =	30.686551
113		.140000 x	20.419486 =	2.858728

			T.E =	36.851014
6106	6106			
512		.087500 x	106.311786 =	9.302281

			T.E =	9.302281
6107	6107			
513		.087500 x	159.522679 =	13.958234

			T.E =	13.958234
6108	6108			
514		.087500 x	214.175232 =	18.740333

			T.E =	18.740333

6109	6109				
515		.087500 x	288.740108 =		25.264759

			T.E =		25.264759
6110	6110				
516		.087500 x	367.968984 =		32.197286

			T.E =		32.197286
6120	6120				
112		.004200 x	17.312112 =		.072711
502		.001750 x	792.804773 =		1.387408
501		.000070 x	606.454852 =		.042452

			T.E =		1.502571
6121	6121				
112		.004200 x	17.312112 =		.072711
507		.000875 x	932.433357 =		.815879
509		.003113 x	405.604470 =		1.262647
505		.000420 x	822.192457 =		.345321
501		.000049 x	606.454852 =		.029716
502		.000315 x	792.804773 =		.249734

			T.E =		2.776007
6151	6151				
243		1.020000 x	2.250000 =		2.295000
243		.080000 x	2.250000 =		.180000

			T.E =		2.475000
6152	6152				
112		.085000 x	17.312112 =		1.471530
113		.085000 x	20.419486 =		1.735656

			T.E =		3.207186
6153	6153				
111		.425000 x	15.741598 =		6.690179
T 611		1.050000 x	20.070537 =		21.074064
509		.003570 x	405.604470 =		1.448008
112		.425000 x	17.312112 =		7.357648

			T.E =		36.569899

6154	6154				
111		.425000 x	15.741598 =	6.690179	
T 621		1.050000 x	16.849232 =	17.691694	
112		.425000 x	17.312112 =	7.357648	
509		.003570 x	405.604470 =	1.448008	
			T.E =	33.187528	
6155	6155				
111		.680000 x	15.741598 =	10.704287	
T 621		.350000 x	16.849232 =	5.897231	
652		.100000 x	149.985546 =	14.998555	
509		.003220 x	405.604470 =	1.306046	
113		1.275000 x	20.419486 =	26.034845	
			T.E =	58.940963	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	149.985546 =	1.499855	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	
			T.E =	22.887754	
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	405.604470 =	1.192477	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.910241 =	14.605753	
			T.E =	29.680788	
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	405.604470 =	1.192477	
X 611		1.050000 x	16.528678 =	17.355112	
112		.420000 x	17.312112 =	7.271087	
			T.E =	32.430147	
6158	6158				
111		.560000 x	15.741598 =	8.815295	
621.1		1.050000 x	15.240122 =	16.002128	
509		.002940 x	405.604470 =	1.192477	
504		.001400 x	379.965890 =	.531952	
			T.E =	26.541852	

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	90.497781

6202.1	6202.1			
281.1		1.000000 x	17.600000 =	17.600000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	27.291284
6202.2	6202.2			
281		1.000000 x	21.300000 =	21.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	30.991284
6202.3	6202.3			
281.2		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6202.4	6202.4			
282		1.000000 x	30.000000 =	30.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	39.691284
6202.5	6202.5			
283		1.000000 x	36.300000 =	36.300000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	62.697781
6202.6	6202.6			
283.1		1.000000 x	55.500000 =	55.500000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	81.897781
6202.7	6202.7			
284		1.000000 x	75.400000 =	75.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	101.797781

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	17.890477 =	12.523334
X 623		.400000 x	15.234043 =	6.093617
509		.005439 x	405.604470 =	2.206083
509		.003108 x	405.604470 =	1.260619
112		.420000 x	17.312112 =	7.271087

			T.E =	32.660475
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	405.604470 =	3.529570
613		1.050000 x	5.515396 =	5.791166

			T.E =	19.897559

6205	6205			
111		.210000 x	15.741598 =	3.305736
112		.070000 x	17.312112 =	1.211848
509		.002800 x	405.604470 =	1.135693
613		1.000000 x	5.515396 =	5.515396

			T.E =	11.168672
6251	6251			
509		.002800 x	405.604470 =	1.135693
613		1.000000 x	5.515396 =	5.515396

			T.E =	6.651089
6252	6252			
509		.000784 x	405.604470 =	.317994

			T.E =	.317994
6253	6253			
112		.210000 x	17.312112 =	3.635544
X 630.1		.200000 x	1.660711 =	.332142
501		.002917 x	606.454852 =	1.769029
521		.007000 x	422.067373 =	2.954472
X 630		.200000 x	1.488365 =	.297673

			T.E =	8.988859
6301	6301			
231		.200000 x	.825000 =	.165000
252		.002500 x	290.000000 =	.725000
113		.127500 x	20.419486 =	2.603484
111		.170000 x	15.741598 =	2.676072
251		.001500 x	290.000000 =	.435000

			T.E =	6.604556
6302	6302			
231		.300000 x	.825000 =	.247500
251		.002000 x	290.000000 =	.580000
111		.212500 x	15.741598 =	3.345090
252		.004000 x	290.000000 =	1.160000
113		1.232500 x	20.419486 =	25.167016

			T.E =	30.499606
6303	6303			
6302		.666660 x	30.499606 =	20.332867

			T.E =	20.332867

6304	6304				
234.2		.018000 x	.967200 =	.017410	
112		.212500 x	17.312112 =	3.678824	
113		.010200 x	20.419486 =	.208279	
113		.085000 x	20.419486 =	1.735656	
235		.012000 x	.664600 =	.007975	

			T.E =	5.648144	
6310	6310				
233		1.050000 x	.556800 =	.584640	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.452468	
6311	6311				
233.1		1.050000 x	.556800 =	.584640	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.452468	
6312	6312				
233.3		1.010000 x	8.000000 =	8.080000	
233.3		.303000 x	8.000000 =	2.424000	
113		.085000 x	20.419486 =	1.735656	
113		.085000 x	20.419486 =	1.735656	

			T.E =	13.975313	
6313	6313				
233.2		1.050000 x	.609600 =	.640080	
113		.025500 x	20.419486 =	.520697	

			T.E =	1.160777	
6314	6314				
233.2		1.050000 x	.609600 =	.640080	
113		.068000 x	20.419486 =	1.388525	

			T.E =	2.028605	
6320.1	6320.1				
396.1		1.000000 x	1.400000 =	1.400000	
113		.000850 x	20.419486 =	.017357	

			T.E =	1.417357	

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
113		.595000 x	20.419486 =	12.149594
509		.003302 x	405.604470 =	1.339306
509		.003019 x	405.604470 =	1.224520
T 630.1		.175000 x	2.016578 =	.352901
T 630		.175000 x	1.807300 =	.316278
T 625		.350000 x	21.682376 =	7.588832
T 623		.560000 x	18.456706 =	10.335755
T 621		.300000 x	16.849232 =	5.054770
511		.023800 x	726.419395 =	17.288782
509		.005284 x	405.604470 =	2.143214
112		.714000 x	17.312112 =	12.360848

			T.E =	96.183121

6322	6322			
221		140.000000 x	.099900 =	13.986000
509		.003019 x	405.604470 =	1.224520
T 623		.560000 x	18.456706 =	10.335755
T 630.1		.175000 x	2.016578 =	.352901
T 630		.175000 x	1.807300 =	.316278
T 625		.350000 x	21.682376 =	7.588832
511		.023800 x	726.419395 =	17.288782
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	405.604470 =	1.339306
509		.005284 x	405.604470 =	2.143214
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 97.149513

6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
509		.007548 x	405.604470 =	3.061503
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 106.235843

6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	405.604470 =	3.061503
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
113		.850000 x	20.419486 =	17.356563

T.E = 98.577132

6324	6324			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
112		1.020000 x	17.312112 =	17.658354
509		.004718 x	405.604470 =	1.913642
113		.850000 x	20.419486 =	17.356563
509		.007548 x	405.604470 =	3.061503

T.E = 111.230843

6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	405.604470 =	3.061503
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
113		.850000 x	20.419486 =	17.356563

T.E = 103.572132

6325	6325			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
509		.007548 x	405.604470 =	3.061503
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 116.225843

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	405.604470 =	3.061503
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
113		.850000 x	20.419486 =	17.356563

T.E = 108.567132

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
509		.007548 x	405.604470 =	3.061503
113		1.360000 x	20.419486 =	27.770501
112		1.190000 x	17.312112 =	20.601413

T.E = 134.577840

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	405.604470 =	3.061503
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
113		1.360000 x	20.419486 =	27.770501

T.E = 126.919129

6327

6327

222	300.000000 x	.116200 =	34.860000
T 630.1	.250000 x	2.016578 =	.504145
T 630	.250000 x	1.807300 =	.451825
T 625	.500000 x	21.682376 =	10.841188
T 623	.800000 x	18.456706 =	14.765365
511	.034000 x	726.419395 =	24.698259
509	.004718 x	405.604470 =	1.913642
509	.007548 x	405.604470 =	3.061503
113	1.275000 x	20.419486 =	26.034845
112	2.295000 x	17.312112 =	39.731297

T.E =

156.862068

6327.1

6327.1

222	300.000000 x	.116200 =	34.860000
T 630.1	.250000 x	2.016578 =	.504145
T 630	.250000 x	1.807300 =	.451825
T 623	.800000 x	18.456706 =	14.765365
T 617	.500000 x	6.364954 =	3.182477
112	2.295000 x	17.312112 =	39.731297
509	.007548 x	405.604470 =	3.061503
511	.034000 x	726.419395 =	24.698259
509	.004718 x	405.604470 =	1.913642
113	1.275000 x	20.419486 =	26.034845

T.E =

149.203357

6328

6328

221	350.000000 x	.099900 =	34.965000
T 630.1	.250000 x	2.016578 =	.504145
T 630	.250000 x	1.807300 =	.451825
T 625	.500000 x	21.682376 =	10.841188
T 623	.800000 x	18.456706 =	14.765365
511	.034000 x	726.419395 =	24.698259
112	2.295000 x	17.312112 =	39.731297
509	.007548 x	405.604470 =	3.061503
113	1.445000 x	20.419486 =	29.506157
509	.004718 x	405.604470 =	1.913642

T.E =

160.438380

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	405.604470 =	3.061503
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
113		1.445000 x	20.419486 =	29.506157

T.E = 152.779669

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 166.143380

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
509		.007548 x	405.604470 =	3.061503
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642

T.E = 158.484669

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 625		.500000 x	21.682376 =	10.841188
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
113		1.445000 x	20.419486 =	29.506157
511		.034000 x	726.419395 =	24.698259
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642

T.E = 167.228380

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
511		.034000 x	726.419395 =	24.698259
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642
113		1.445000 x	20.419486 =	29.506157

T.E = 159.569669

6330	6330			
223		420.000000 x	.119300 =	50.106000
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642
113		1.445000 x	20.419486 =	29.506157
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.042500 x	726.419395 =	30.872824

T.E = 181.753945

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	405.604470 =	1.913642
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	405.604470 =	3.061503
511		.042500 x	726.419395 =	30.872824
T 617		.500000 x	6.364954 =	3.182477
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365

T.E = 174.095234

6331	6331			
222		450.000000 x	.116200 =	52.290000
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
T 623		.800000 x	18.456706 =	14.765365
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
509		.004718 x	405.604470 =	1.913642
511		.042500 x	726.419395 =	30.872824
509		.007548 x	405.604470 =	3.061503
112		3.400000 x	17.312112 =	58.861181

T.E = 346.590944

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
511		.042500 x	726.419395 =	30.872824
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612

T.E = 338.932233

6351	6351			
221		120.000000 x	.099900 =	11.988000
509		.004246 x	405.604470 =	1.722197
509		.008020 x	405.604470 =	3.252948
6301		1.000000 x	6.604556 =	6.604556
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.450000 x	21.682376 =	9.757069
T 623		.850000 x	18.456706 =	15.688200
511		.034000 x	726.419395 =	24.698259
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 122.774986

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
509		.004246 x	405.604470 =	1.722197
6301		1.000000 x	6.604556 =	6.604556
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.850000 x	18.456706 =	15.688200
T 617		.450000 x	6.364954 =	2.864229
511		.034000 x	726.419395 =	24.698259
509		.008020 x	405.604470 =	3.252948
112		1.275000 x	17.312112 =	22.072943
113		1.275000 x	20.419486 =	26.034845

T.E = 115.882146

6352	6352			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
6301		1.000000 x	6.604556 =	6.604556
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 625		.500000 x	21.682376 =	10.841188
T 623		.800000 x	18.456706 =	14.765365
511		.034000 x	726.419395 =	24.698259
509		.004718 x	405.604470 =	1.913642
509		.007548 x	405.604470 =	3.061503
113		2.550000 x	20.419486 =	52.069689

T.E = 181.668409

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238
511		.034000 x	726.419395 =	24.698259
6301		1.000000 x	6.604556 =	6.604556
T 630.1		.250000 x	2.016578 =	.504145
T 630		.250000 x	1.807300 =	.451825
T 623		.800000 x	18.456706 =	14.765365
T 617		.500000 x	6.364954 =	3.182477
509		.007548 x	405.604470 =	3.061503
509		.004718 x	405.604470 =	1.913642
			T.E =	174.009698
6360.1	6360.1			
6360.1 A1		1.000000 x	113.086480 =	113.086480
6360.1 A2		1.000000 x	8.015653 =	8.015653
6360.1 A5		1.000000 x	99.510508 =	99.510508
6360.1 A4		1.000000 x	32.291772 =	32.291772
6360.1 A3		1.000000 x	14.476840 =	14.476840
			AΘΡΟΙΣΜΑ =	267.381253
	T.E =	.200000 x	267.381253 =	53.476251
6360.2	6360.2			
6360.2 A1		1.000000 x	121.584981 =	121.584981
6360.2 A2		1.000000 x	11.151390 =	11.151390
6360.2 A3		1.000000 x	18.870171 =	18.870171
6360.2 A4		1.000000 x	35.547752 =	35.547752
6360.2 A5		1.000000 x	113.392744 =	113.392744
			AΘΡΟΙΣΜΑ =	300.547038
	T.E =	.200000 x	300.547038 =	60.109408
6360.3	6360.3			
6360.3 A1		1.000000 x	161.147373 =	161.147373
6360.3 A2		1.000000 x	15.823920 =	15.823920
6360.3 A3		1.000000 x	42.401893 =	42.401893
6360.3 A5		1.000000 x	156.837695 =	156.837695
6360.3 A4		1.000000 x	42.561397 =	42.561397
			AΘΡΟΙΣΜΑ =	418.772278
	T.E =	.200000 x	418.772278 =	83.754456

6360.4	6360.4			
6360.4 A1		1.000000 x	211.273239 =	211.273239
6360.4 A2		1.000000 x	21.452126 =	21.452126
6360.4 A3		1.000000 x	63.433615 =	63.433615
6360.4 A5		1.000000 x	211.643919 =	211.643919
6360.4 A4		1.000000 x	35.547752 =	35.547752

			AΘΡΟΙΣΜΑ =	543.350651
	T.E =	.200000 x	543.350651 =	108.670130

6360.5	6360.5			
6360.5 A1		1.000000 x	242.081008 =	242.081008
6360.5 A2		1.000000 x	26.762253 =	26.762253
6360.5 A3		1.000000 x	70.465974 =	70.465974
6360.5 A5		1.000000 x	289.621195 =	289.621195
6360.5 A4		1.000000 x	36.803639 =	36.803639

			AΘΡΟΙΣΜΑ =	665.734069
	T.E =	.200000 x	665.734069 =	133.146814

6360.6	6360.6			
6360.6 A1		1.000000 x	294.478354 =	294.478354
6360.6 A2		1.000000 x	40.186912 =	40.186912
6360.6 A4		1.000000 x	35.547752 =	35.547752
6360.6 A3		1.000000 x	82.820377 =	82.820377
6360.6 A5		1.000000 x	382.668414 =	382.668414

			AΘΡΟΙΣΜΑ =	835.701809
	T.E =	.200000 x	835.701809 =	167.140362

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	38.800000 =	.116400

			T.E =	16.922169
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	20.419486 =	4.339141
111		.212500 x	15.741598 =	3.345090

			T.E =	8.339230

6372	6372				
396.11		1.050000 x	2.960000 =	3.108000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.741598 =	5.352143	
113		.340000 x	20.419486 =	6.942625	

			T.E =	16.641769	
6373	6373				
396.12		1.050000 x	4.250000 =	4.462500	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	21.069961	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	290.000000 =	.145000	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	149.985546 =	1.724834	
652.2		.005500 x	169.842054 =	.934131	

			T.E =	24.319810	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.741598 =	13.380358	
113		.850000 x	20.419486 =	17.356563	
652.2		.005500 x	169.842054 =	.934131	
652		.016500 x	149.985546 =	2.474762	

			T.E =	34.290814	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
113		1.700000 x	20.419486 =	34.713126	
652		.020000 x	149.985546 =	2.999711	

			T.E =	57.783375	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.783375 =	57.783375	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	149.985546 =	2.999711

			T.E =	27.046453
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	25,408.000000 =	25,408.000000
386.9		.150000 x	25,408.000000 =	3,811.200000

			T.E =	29,219.200000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	76,065.000000 =	76,065.000000
386.40		.150000 x	76,065.000000 =	11,409.750000

			T.E =	87,474.750000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	111,963.000000 =	111,963.000000
386.30		.150000 x	111,963.000000 =	16,794.450000

			T.E =	128,757.450000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17			
386.64		1.000000 x	152,143.000000 =	152,143.000000
386.64		.150000 x	152,143.000000 =	22,821.450000

			T.E =	174,964.450000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000

			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000

			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000

			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000

			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000

			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000

			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000

			T.E =	

6453.6	6453.6			
386.53		1.000000 x	132,726.000000 =	132,726.000000
386.53		.150000 x	132,726.000000 =	19,908.900000

			T.E =	152,634.900000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	21,310.000000 =	21,310.000000
387.3		.100000 x	21,310.000000 =	2,131.000000

			T.E =	23,441.000000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.967200 =	201.177600
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.664600 =	224.634800

			ΑΘΡΟΙΣΜΑ =	3,584.706905

			T.E =	5,377.060357
6456.2	6456.2			
234.2		336.000000 x	.967200 =	324.979200
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.664600 =	362.871600

			ΑΘΡΟΙΣΜΑ =	5,790.680351

			T.E =	8,106.952492
6456.3	6456.3			
234.2		384.000000 x	.967200 =	371.404800
235		624.000000 x	.664600 =	414.710400
113		285.599998 x	20.419486 =	5,831.805161

			ΑΘΡΟΙΣΜΑ =	6,617.920361

			T.E =	9,265.088505
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,598.000000 =	6,598.000000
389.4		.200000 x	6,598.000000 =	1,319.600000

			T.E =	7,917.600000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,574.000000 =	5,574.000000
390.14		.150000 x	5,574.000000 =	836.100000

			T.E =	6,410.100000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	8,107.000000 =	8,107.000000
390.31		.150000 x	8,107.000000 =	1,216.050000

			T.E =	9,323.050000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	15,210.000000 =	15,210.000000
393.1		.150000 x	15,210.000000 =	2,281.500000

			T.E =	17,491.500000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.950000 =	6.950000

			T.E =	6.950000
6501	6501			
237		1.000000 x	1.165000 =	1.165000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.521563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,191.896489 =	93.155601

			T.E =	96.098660
6505	6505			
233		1.050000 x	.556800 =	.584640
113		.042500 x	20.419486 =	.867828

			T.E =	1.452468

6506	6506				
233.1		1.050000 x	.556800 =	.584640	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.452468	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
111		.255000 x	15.741598 =	4.014107	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	15.741598 =	4.683125	
113		.297500 x	20.419486 =	6.074797	

			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	20.419486 =	10.413938	
111		.510000 x	15.741598 =	8.028215	

			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.834921

6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 255.002782

6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.648144 =	38.915712
6310		32.020000 x	1.452468 =	46.508025
6329.2		.418000 x	167.228380 =	69.901463
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 210.718162

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.028605 =	27.852747
6329.2		.478000 x	167.228380 =	79.935166
6304		9.290000 x	5.648144 =	52.471258

T.E = 177.615733

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
113		.025500 x	20.419486 =	.520697
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

T.E =

6611.1	6611.1			
361.1		1.000000 x	12.930000 =	12.930000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

T.E = 27.436354

6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

T.E =

6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

T.E =

6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

T.E =

6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

T.E =

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

T.E =

6611.2	6611.2			
361.2		1.000000 x	16.730000 =	16.730000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

T.E =

31.972118

6611.3	6611.3			
361.3		1.000000 x	21.230000 =	21.230000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

T.E =

39.480494

6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

T.E =

6611.5	6611.5			
361.5		1.000000 x	40.530000 =	40.530000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

T.E =

67.872368

6611.6	6611.6			
361.6		1.000000 x	54.080000 =	54.080000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

T.E =

85.902273

6611.7	6611.7			
361.7		1.000000 x	83.670000 =	83.670000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

T.E = 121.509024

6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

T.E =

6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

T.E =

6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

T.E = 11.019393

6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

T.E = 16.398814

6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

T.E = 20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.161813
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.902521
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.332089
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	15.741598 =	10.423299
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098

			T.E =	101.104384
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	15.741598 =	13.246555
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213

			T.E =	126.764443
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	15.741598 =	16.819110
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218

			T.E =	158.723104
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	20.419486 =	4.807768
112		.131750 x	17.312112 =	2.280871
111		.080750 x	15.741598 =	1.271134

			T.E =	20.497773
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.741598 =	2.060575
112		.212500 x	17.312112 =	3.678824
113		.299200 x	20.419486 =	6.109510

			T.E =	31.004509
6622.3	6622.3			
373.3		1.020000 x	24.500000 =	24.990000
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	39.468692

6623	6623				
360.2		1.000000 x	2.330000 =	2.330000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	5.991136	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	230.985083	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,026.449968	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,119.076304	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	253.548524	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	278.323537	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	335.731812	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	412.733204	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	505.879230	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	654.043125	

6630.8	6630.8			
376.19		1.000000 x	336.580000 =	336.580000
111		5.340550 x	15.741598 =	84.068791
113		2.261000 x	20.419486 =	46.168458
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741

T.E = 729.974644

6630.9	6630.9			
376.20		1.000000 x	400.990000 =	400.990000
111		6.461700 x	15.741598 =	101.717484
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
113		2.936750 x	20.419486 =	59.966926
112		10.948000 x	17.312112 =	189.533002

T.E = 860.165234

6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		1.667700 x	20.419486 =	34.053577
111		1.334500 x	15.741598 =	21.007163
112		3.043000 x	17.312112 =	52.680757

T.E =

6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.002600 x	20.419486 =	40.892063
112		3.570000 x	17.312112 =	61.804240
111		1.922700 x	15.741598 =	30.266370

T.E =

6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	15.741598 =	41.198123
112		4.658000 x	17.312112 =	80.639818
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192

T.E =

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.741598 =	53.815801
112	5.882000 x	17.312112 =	101.829843
113	2.669850 x	20.419486 =	54.516965
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.741598 =	68.106024
113	3.003900 x	20.419486 =	61.338094
113	2.550000 x	20.419486 =	52.069689
112	8.126000 x	17.312112 =	140.678222

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	20.419486 =	52.069689
113	3.337100 x	20.419486 =	68.141867
112	9.044000 x	17.312112 =	156.570741
111	5.340550 x	15.741598 =	84.068791

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.741598 =	101.717484
112	10.948000 x	17.312112 =	189.533002
113	3.671150 x	20.419486 =	74.962996
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.741598 =	121.065482
112	13.396000 x	17.312112 =	231.913052
113	2.550000 x	20.419486 =	52.069689
113	4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	8.000000 =	8.000000

			T.E =	8.000000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28 6654.28

383.28 1.000000 x .000000 = .000000
383.28 .050000 x .000000 = .000000

T.E =

6654.29 6654.29

383.29 1.000000 x .000000 = .000000
383.29 .050000 x .000000 = .000000

T.E =

6654.3 6654.3

383.3 1.000000 x .000000 = .000000
383.3 .050000 x .000000 = .000000
383.3 .050000 x .000000 = .000000

T.E =

6654.30 6654.30

383.30 1.000000 x .000000 = .000000
383.30 .050000 x .000000 = .000000

T.E =

6654.31 6654.31

383.31 1.000000 x .000000 = .000000
383.31 .050000 x .000000 = .000000

T.E =

6654.32 6654.32

383.32 1.000000 x .000000 = .000000
383.32 .050000 x .000000 = .000000

T.E =

6654.33 6654.33

383.33 1.000000 x .000000 = .000000
383.33 .050000 x .000000 = .000000

T.E =

6654.34 6654.34

383.34 1.000000 x .000000 = .000000
383.34 .050000 x .000000 = .000000

T.E =

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7 6662.7

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.5	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.8	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.8 6662.8

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.6	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.1 6663.1

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.4	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.2 6663.2

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6701.1 6701.1

368.1	1.020000 x	.000000 =	.000000
369.1	.224000 x	.000000 =	.000000
113	.068000 x	20.419486 =	1.388525
111	.382500 x	15.741598 =	6.021161

T.E =

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251
113		.238000 x	20.419486 =	4.859838

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

			T.E =	
6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

			T.E =	

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.16		1.000000 x	.000000 =	.000000

T.E =

6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

T.E =

6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	134.577840 =	44.074243
113		.026350 x	20.419486 =	.538053
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.741598 =	1.873250
113		.040800 x	20.419486 =	.833115
6326		.352500 x	134.577840 =	47.438689

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.741598 =	2.542268
6326		.372500 x	134.577840 =	50.130245
113		.051000 x	20.419486 =	1.041394

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
6326		.382500 x	134.577840 =	51.476024
113		.063750 x	20.419486 =	1.301742

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	134.577840 =	52.653580
113		.068000 x	20.419486 =	1.388525
111		.187000 x	15.741598 =	2.943679

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
113		.076500 x	20.419486 =	1.562091
6327		.393750 x	156.862068 =	61.764439

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.741598 =	4.549322
6327		.431250 x	156.862068 =	67.646767
113		.093500 x	20.419486 =	1.909222

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	156.862068 =	78.431034
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	24.870998 =	9.202269
113		.017000 x	20.419486 =	.347131
111		.161500 x	15.741598 =	2.542268

T.E =

20.771869

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.741598 =	2.943679
6069		.390000 x	24.870998 =	9.699689
113		.021250 x	20.419486 =	.433914

T.E =

26.673882

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.741598 =	3.211286
6069		.400000 x	24.870998 =	9.948399
113		.026350 x	20.419486 =	.538053

			T.E =	34.903539
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
6069		.420000 x	24.870998 =	10.445819
113		.040800 x	20.419486 =	.833115

			T.E =	49.482238
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	24.870998 =	10.694529
113		.051000 x	20.419486 =	1.041394
111		.289000 x	15.741598 =	4.549322

			T.E =	59.941245
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	24.870998 =	10.943239
113		.063750 x	20.419486 =	1.301742
111		.297500 x	15.741598 =	4.683125

			T.E =	72.242707
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	24.870998 =	12.932919
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.782960
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563
			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563
			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563
			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000
			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	17.510000 =	17.510000
			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	106.235843 =	9.561226
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969
			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	116.225843 =	25.685911
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	116.225843 =	27.196847
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	116.225843 =	28.010428
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	106.235843 =	11.685943
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	106.235843 =	13.916895
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	106.235843 =	16.360320
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	106.235843 =	17.635150
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	106.235843 =	18.378801
113		.637500 x	20.419486 =	13.017422

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	116.225843 =	16.039166
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	116.225843 =	19.177264
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	116.225843 =	22.431588
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	106.235843 =	6.374151
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	116.225843 =	15.109360
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	116.225843 =	16.271618
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	116.225843 =	17.433876
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	106.235843 =	7.436509
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	106.235843 =	8.498867
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	106.235843 =	9.561226
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	106.235843 =	10.623584
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	106.235843 =	11.685943
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	116.225843 =	11.622584
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	116.225843 =	12.784843
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	116.225843 =	13.947101
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	106.235843 =	9.561226
652		.002500 x	149.985546 =	.374964
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

39.560348

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
112		.425000 x	17.312112 =	7.357648
652		.004500 x	149.985546 =	.674935
6325		.249000 x	116.225843 =	28.940235
113		.340000 x	20.419486 =	6.942625
111		.297500 x	15.741598 =	4.683125

			T.E =	82.618568
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	116.225843 =	36.030011
113		.510000 x	20.419486 =	10.413938
652		.005000 x	149.985546 =	.749928
112		.552500 x	17.312112 =	9.564942
111		.340000 x	15.741598 =	5.352143

			T.E =	111.145962
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
6325		.370000 x	116.225843 =	43.003562
652		.006500 x	149.985546 =	.974906
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

			T.E =	141.895477
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	106.235843 =	11.685943
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
652		.003000 x	149.985546 =	.449957
113		.255000 x	20.419486 =	5.206969

			T.E =	47.640058
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
6323		.131000 x	106.235843 =	13.916895
652		.003500 x	149.985546 =	.524949
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
112		.382500 x	17.312112 =	6.621883

			T.E =	58.098614

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
6323		.170000 x	106.235843 =	18.060093
652		.004500 x	149.985546 =	.674935
112		.425000 x	17.312112 =	7.357648

			T.E =	71.738427
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
6323		.226000 x	106.235843 =	24.009301
652		.005000 x	149.985546 =	.749928
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
111		.340000 x	15.741598 =	5.352143

			T.E =	99.125251
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	106.235843 =	29.108621
652		.006500 x	149.985546 =	.974906
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

			T.E =	128.000537
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.225843 =	16.039166
652		.002500 x	149.985546 =	.374964
113		.255000 x	20.419486 =	5.206969

			T.E =	46.038289
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
113		.255000 x	20.419486 =	5.206969
6325		.165000 x	116.225843 =	19.177264
652		.003000 x	149.985546 =	.449957

			T.E =	55.131379

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
652		.003500 x	149.985546 =	.524949
6325		.193000 x	116.225843 =	22.431588
113		.297500 x	20.419486 =	6.074797
112		.382500 x	17.312112 =	6.621883

T.E = 66.613307

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	106.235843 =	9.561226
652		.002500 x	149.985546 =	.374964
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.225843 =	28.940235
652		.004500 x	149.985546 =	.674935
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	116.225843 =	36.030011
652		.005000 x	149.985546 =	.749928
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.225843 =	43.003562
652		.006500 x	149.985546 =	.974906
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	106.235843 =	11.685943
652		.003000 x	149.985546 =	.449957
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.235843 =	13.916895
652		.003500 x	149.985546 =	.524949
113		.297500 x	20.419486 =	6.074797

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	106.235843 =	18.060093
652		.004500 x	149.985546 =	.674935
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.235843 =	24.009301
652		.005000 x	149.985546 =	.749928
112		.552500 x	17.312112 =	9.564942

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	106.235843 =	29.108621
652		.006500 x	149.985546 =	.974906
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.225843 =	16.039166
652		.002500 x	149.985546 =	.374964
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	116.225843 =	19.177264
652		.003000 x	149.985546 =	.449957
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.225843 =	22.431588
652		.003500 x	149.985546 =	.524949
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	20.332867 =	38.225790
6326		.940000 x	134.577840 =	126.503170

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.577840 =	98.241823

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	134.577840 =	126.503170

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.577840 =	98.241823

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.332867 =	61.811916
6328		.400000 x	160.438380 =	64.175352

			T.E =	125.987268
6742.10	6742.10			
6303		7.520000 x	20.332867 =	152.903160
6328		2.110000 x	160.438380 =	338.524982

			T.E =	491.428142
6742.11	6742.11			
6303		8.030000 x	20.332867 =	163.272922
6328		2.430000 x	160.438380 =	389.865263

			T.E =	553.138185
6742.2	6742.2			
6303		3.500000 x	20.332867 =	71.165035
6328		.500000 x	160.438380 =	80.219190

			T.E =	151.384225
6742.3	6742.3			
6303		4.020000 x	20.332867 =	81.738125
6328		.630000 x	160.438380 =	101.076179

			T.E =	182.814305
6742.4	6742.4			
6303		4.530000 x	20.332867 =	92.107888
6328		.800000 x	160.438380 =	128.350704

			T.E =	220.458592

6742.5	6742.5			
6303		5.000000 x	20.332867 =	101.664335
6328		.950000 x	160.438380 =	152.416461

			T.E =	254.080796
6742.6	6742.6			
6303		5.530000 x	20.332867 =	112.440755
6328		1.170000 x	160.438380 =	187.712905

			T.E =	300.153659
6742.7	6742.7			
6303		6.040000 x	20.332867 =	122.810517
6328		1.410000 x	160.438380 =	226.218116

			T.E =	349.028632
6742.8	6742.8			
6303		6.520000 x	20.332867 =	132.570293
6328		1.610000 x	160.438380 =	258.305792

			T.E =	390.876085
6742.9	6742.9			
6303		7.040000 x	20.332867 =	143.143384
6328		1.880000 x	160.438380 =	301.624154

			T.E =	444.767538
6743.1	6743.1			
6303		3.040000 x	20.332867 =	61.811916
6328		.440000 x	160.438380 =	70.592887

			T.E =	132.404803
6743.10	6743.10			
6303		7.520000 x	20.332867 =	152.903160
6328		2.240000 x	160.438380 =	359.381971

			T.E =	512.285131
6743.11	6743.11			
6303		8.030000 x	20.332867 =	163.272922
6328		2.570000 x	160.438380 =	412.326637

			T.E =	575.599559

6743.12	6743.12			
6303		3.040000 x	20.332867 =	61.811916
6328		.750000 x	160.438380 =	120.328785

			T.E =	182.140701
6743.13	6743.13			
6303		3.500000 x	20.332867 =	71.165035
6328		.910000 x	160.438380 =	145.998926

			T.E =	217.163960
6743.14	6743.14			
6303		4.020000 x	20.332867 =	81.738125
6328		1.090000 x	160.438380 =	174.877834

			T.E =	256.615960
6743.15	6743.15			
6303		4.530000 x	20.332867 =	92.107888
6328		1.300000 x	160.438380 =	208.569894

			T.E =	300.677782
6743.16	6743.16			
6303		5.000000 x	20.332867 =	101.664335
6328		1.550000 x	160.438380 =	248.679489

			T.E =	350.343824
6743.17	6743.17			
6303		5.530000 x	20.332867 =	112.440755
6328		1.850000 x	160.438380 =	296.811003

			T.E =	409.251758
6743.2	6743.2			
6303		3.500000 x	20.332867 =	71.165035
6328		.550000 x	160.438380 =	88.241109

			T.E =	159.406144
6743.3	6743.3			
6303		4.020000 x	20.332867 =	81.738125
6328		.690000 x	160.438380 =	110.702482

			T.E =	192.440608

6743.4	6743.4			
6303		4.530000 x	20.332867 =	92.107888
6328		.860000 x	160.438380 =	137.977007

			T.E =	230.084894
6743.5	6743.5			
6303		5.000000 x	20.332867 =	101.664335
6328		1.020000 x	160.438380 =	163.647148

			T.E =	265.311483
6743.6	6743.6			
6303		5.530000 x	20.332867 =	112.440755
6328		1.260000 x	160.438380 =	202.152359

			T.E =	314.593113
6743.7	6743.7			
6303		6.040000 x	20.332867 =	122.810517
6328		1.500000 x	160.438380 =	240.657570

			T.E =	363.468087
6743.8	6743.8			
6303		6.520000 x	20.332867 =	132.570293
6328		1.720000 x	160.438380 =	275.954014

			T.E =	408.524306
6743.9	6743.9			
6303		7.040000 x	20.332867 =	143.143384
6328		2.000000 x	160.438380 =	320.876760

			T.E =	464.020144
6744	6744			
111		2.125000 x	15.741598 =	33.450896
111		4.250000 x	15.741598 =	66.901792
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408
112		2.125000 x	17.312112 =	36.788238

			T.E =	223.923741

6751	6751				
234.2		.400000 x	.967200 =	.386880	
113		.051000 x	20.419486 =	1.041394	
113		.170000 x	20.419486 =	3.471313	
235		.650000 x	.664600 =	.431990	

			T.E =	5.331576	
6752	6752				
237		1.050000 x	1.165000 =	1.223250	
113		.017000 x	20.419486 =	.347131	
111		.025500 x	15.741598 =	.401411	

			T.E =	1.971792	
6753	6753				
237		1.050000 x	1.165000 =	1.223250	
112		.085000 x	17.312112 =	1.471530	
113		.085000 x	20.419486 =	1.735656	

			T.E =	4.430436	
6754	6754				
237.1		1.000000 x	1.320000 =	1.320000	
112		.017000 x	17.312112 =	.294306	
111		.051000 x	15.741598 =	.802821	
113		.212500 x	20.419486 =	4.339141	

			T.E =	6.756268	
6801	6801				
232		.700000 x	2.020000 =	1.414000	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	20.419486 =	52.069689	
112		1.700000 x	17.312112 =	29.430590	
111		.850000 x	15.741598 =	13.380358	

			T.E =	98.614638	
6802	6802				
231		15.000000 x	.825000 =	12.375000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	20.419486 =	52.069689	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	15.741598 =	66.901792	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	149.985546 =	1.799827
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.547292
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	149.985546 =	17.998266
113		.680000 x	20.419486 =	13.885250

			T.E =	39.911731
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	149.985546 =	.299971
2522		.005000 x	154.404510 =	.772023
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	17.426762
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	134.577840 =	.672889
652		.002000 x	149.985546 =	.299971

			T.E =	13.267629
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.750000 =	20.150000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.750000 =	10.075000

			T.E =	86.002715

6811	6811			
236		6.430000 x	.643700 =	4.138991
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.750000 =	24.412500

			T.E =	115.334307
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
243		11.900000 x	2.250000 =	26.775000
6324		.250000 x	111.230843 =	27.807711
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179

			AΘΡΟΙΣΜΑ =	162.860705
	T.E =	.262500 x	162.860705 =	42.750935

7001	7001			
7001 A		1.000000 x	.236453 =	.236453
7001 B		1.000000 x	.775065 =	.775065
7001 E		1.000000 x	.821801 =	.821801
7001 Δ		1.000000 x	.321542 =	.321542
7001 Γ		1.000000 x	.979482 =	.979482

			AΘΡΟΙΣΜΑ =	3.134343

			T.E =	3.604494
7002	7002			
560		.005104 x	702.939090 =	3.587801

			T.E =	3.587801
7003	7003			
7003 A		1.000000 x	.118227 =	.118227
7003 B		1.000000 x	.605109 =	.605109
7003 Δ		1.000000 x	.799150 =	.799150
7003 Γ		1.000000 x	.554963 =	.554963

			AΘΡΟΙΣΜΑ =	2.077449

			T.E =	2.285194
7004	7004			
561		.003250 x	926.054290 =	3.009676

			T.E =	3.009676

7005	7005			
7005 Α		1.000000 x	.118227 =	.118227
7005 Γ		1.000000 x	.302554 =	.302554
7005 Ε		1.000000 x	.799150 =	.799150
7005 Δ		1.000000 x	.554963 =	.554963
7005 Β		1.000000 x	1.058940 =	1.058940

			ΑΘΡΟΙΣΜΑ =	2.833834

			T.E =	3.117217
7006	7006			
561		.001723 x	926.054290 =	1.595592
561		.000862 x	926.054290 =	.798259
561		.000812 x	926.054290 =	.751956

			T.E =	3.145806
7007	7007			
213		.100000 x	1.949500 =	.194950
116		.280000 x	20.419486 =	5.717456
550		.003500 x	1,056.210386 =	3.696736
518		.001750 x	882.536142 =	1.544438
502		.000583 x	792.804773 =	.462205

			T.E =	11.615786
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
503		.001750 x	905.783573 =	1.585121
507		.000875 x	932.433357 =	.815879
558		.000972 x	1,107.235457 =	1.076233
7007		1.100000 x	11.615786 =	12.777365

			T.E =	20.220715
7009	7009			
560		.006417 x	702.939090 =	4.510760

			T.E =	4.510760
7010	7010			
7010 Α		1.000000 x	.348779 =	.348779
7010 Β		1.000000 x	.523722 =	.523722
7010 Ε		1.000000 x	1.009316 =	1.009316
7010 Δ		1.000000 x	.321542 =	.321542
7010 Γ		1.000000 x	.554963 =	.554963

			ΑΘΡΟΙΣΜΑ =	2.758322

			T.E =	3.172070

7011	7011			
502		.001367 x	792.804773 =	1.083764
563		.001367 x	.000000 =	.000000
558		.000729 x	1,107.235457 =	.807175
558		.000729 x	1,107.235457 =	.807175
554		.000438 x	33.418000 =	.014637
503		.000438 x	905.783573 =	.396733
502		.000700 x	792.804773 =	.554963

			ΑΘΡΟΙΣΜΑ =	3.664447

			T.E =	
7012	7012			
7008		1.000000 x	20.220715 =	20.220715

			ΑΘΡΟΙΣΜΑ =	20.220715

			T.E =	22.242787
7013	7013			
7003		1.000000 x	2.285194 =	2.285194

			ΑΘΡΟΙΣΜΑ =	2.285194

			T.E =	2.513713
7014	7014			
7005		1.000000 x	3.117217 =	3.117217

			ΑΘΡΟΙΣΜΑ =	3.117217

			T.E =	3.428939
7015	7015			
111		.056000 x	15.741598 =	.881529
X 630.1		.300000 x	1.660711 =	.498213
7001		.900000 x	3.604494 =	3.244045
X 630		.300000 x	1.488365 =	.446510

			T.E =	5.070297
7016.9	7016.9			
7016.4		1.000000 x	127.256098 =	127.256098
7016.6		1.000000 x	38.176830 =	38.176830
7016.7		1.000000 x	80.282150 =	80.282150
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.451220 =	25.451220

			T.E =	375.305677

7017.8	7017.8				
7017.3		1.000000 x	93.074873 =		93.074873
7017.4		1.000000 x	18.614975 =		18.614975
7017.5		1.000000 x	33.506954 =		33.506954
7017.7		1.000000 x	52.069689 =		52.069689
7017.6		1.000000 x	80.282150 =		80.282150

			T.E =		277.548641
7018	7018				
233.2		1.150000 x	.609600 =		.701040
113		.051000 x	20.419486 =		1.041394

			AΘΡΟΙΣΜΑ =		1.742434

			T.E =		1.916677
7019	7019				
7019 A6		1.000000 x	192.425429 =		192.425429
7019 A7		1.000000 x	19.242543 =		19.242543

			T.E =		211.667972
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	211.667972 =		211.667972

			T.E =		205.767972
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,528.030816 =		38.589601

			T.E =		58.893122
7020.1	7020.1				
570.2		.350000 x	124.784076 =		43.674427
571.2		.070000 x	259.459536 =		18.162168
571.1		.280000 x	446.740730 =		125.087404

			AΘΡΟΙΣΜΑ =		186.923999
	T.E =	.015625 x	186.923999 =		2.920687

7021	7021				
213		.150000 x	1.949500 =		.292425
116		1.120000 x	20.419486 =		22.869824
7021.2		.014583 x	3,078.609134 =		44.895357

			T.E =		68.057606

7021.1	7021.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	446.740730 =	125.087404
			AΘΡΟΙΣΜΑ =	186.923999
	T.E =	.020833 x	186.923999 =	3.894188
7022	7022			
213		.150000 x	1.949500 =	.292425
116		1.400000 x	20.419486 =	28.587280
7022.2		.020000 x	2,823.087226 =	56.461745
			T.E =	85.341450
7022.1	7022.1			
570.2		.350000 x	124.784076 =	43.674427
571.2		.070000 x	259.459536 =	18.162168
571.1		.280000 x	446.740730 =	125.087404
			AΘΡΟΙΣΜΑ =	186.923999
	T.E =	.028571 x	186.923999 =	5.340606
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
550		.012143 x	1,056.210386 =	12.825563
			T.E =	77.822305
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
116		.850000 x	20.419486 =	17.356563
550		.020238 x	1,056.210386 =	21.375586
111		.425000 x	15.741598 =	6.690179
			T.E =	94.772328
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	149.985546 =	.149986
550		.020238 x	1,056.210386 =	21.375586
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.556800 =	3.441024
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.381605

7026	7026			
398.5		125.400000 x	6.180000 =	774.972000
236		16.808000 x	.643700 =	10.819310
113		.909160 x	20.419486 =	18.564580
113		3.400000 x	20.419486 =	69.426252
6310		12.350000 x	1.452468 =	17.937980
			AΘΡΟΙΣΜΑ =	891.720122
	T.E =	.007259 x	891.720122 =	6.472996
7027	7027			
236		1.100000 x	.643700 =	.708070
113		.059500 x	20.419486 =	1.214959
			T.E =	1.923029
7028	7028			
111		.144500 x	15.741598 =	2.274661
6751		.120000 x	5.331576 =	.639789
6751		.600000 x	5.331576 =	3.198946
111		.425000 x	15.741598 =	6.690179
112		.144500 x	17.312112 =	2.501600
			AΘΡΟΙΣΜΑ =	15.305175
			T.E =	17.600951
7029	7029			
568.1		.021250 x	2,650.143547 =	56.315550
569.2		.021250 x	612.976952 =	13.025760
570.2		.021250 x	124.784076 =	2.651662
571.2		.021250 x	259.459536 =	5.513515
			T.E =	77.506487
7030	7030			
398.6		.015385 x	330.000000 =	5.077050
572		.026563 x	854.304317 =	22.692886
			AΘΡΟΙΣΜΑ =	27.769936
			T.E =	38.877910
7031	7031			
573		.106250 x	1,081.946892 =	114.956857
			AΘΡΟΙΣΜΑ =	114.956857
			T.E =	132.200386
7032	7032			
573		.212500 x	1,081.946892 =	229.913715
			AΘΡΟΙΣΜΑ =	229.913715
			T.E =	298.887829

7101.1	7101.1				
398.1		15.000000 x	.225000 =		3.375000
574		.132813 x	3,596.534982 =		477.666601
T 630		.105000 x	1.807300 =		.189767
T 630.1		.105000 x	2.016578 =		.211741
567		.132813 x	392.805772 =		52.169713

			AΘΡΟΙΣΜΑ =		533.612821

			T.E =		549.621205
7101.2	7101.2				
398.1		15.000000 x	.225000 =		3.375000
574		.148750 x	3,596.534982 =		534.984579
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767
567		.148750 x	392.805772 =		58.429859

			AΘΡΟΙΣΜΑ =		597.190944

			T.E =		615.106673
7101.3	7101.3				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767
574		.159375 x	3,596.534982 =		573.197763
567		.159375 x	392.805772 =		62.603420

			AΘΡΟΙΣΜΑ =		639.577690

			T.E =		658.765021
7101.4	7101.4				
398.1		15.000000 x	.225000 =		3.375000
567		.170000 x	392.805772 =		66.776981
574		.170000 x	3,596.534982 =		611.410947
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767

			AΘΡΟΙΣΜΑ =		681.964435

			T.E =		702.423368
7101.5	7101.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.016578 =		.211741
567		.191250 x	392.805772 =		75.124104
T 630		.105000 x	1.807300 =		.189767
574		.191250 x	3,596.534982 =		687.837315

			AΘΡΟΙΣΜΑ =		766.737926

			T.E =		789.740064

7102.1	7102.1				
398.1		15.000000 x	.225000 =		3.375000
567		.302813 x	392.805772 =		118.946694
T 630		.105000 x	1.807300 =		.189767
T 630.1		.105000 x	2.016578 =		.211741
574		.302813 x	3,596.534982 =		1,089.077548
				ΑΘΡΟΙΣΜΑ =	1,211.800749
				T.E =	1,248.154771
7102.2	7102.2				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767
574		.329375 x	3,596.534982 =		1,184.608710
567		.329375 x	392.805772 =		129.380401
				ΑΘΡΟΙΣΜΑ =	1,317.765618
				T.E =	1,357.298587
7102.3	7102.3				
398.1		15.000000 x	.225000 =		3.375000
567		.361250 x	392.805772 =		141.901085
T 630		.105000 x	1.807300 =		.189767
T 630.1		.105000 x	2.016578 =		.211741
574		.361250 x	3,596.534982 =		1,299.248262
				ΑΘΡΟΙΣΜΑ =	1,444.925855
				T.E =	1,488.273630
7102.4	7102.4				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767
574		.403750 x	3,596.534982 =		1,452.100999
567		.403750 x	392.805772 =		158.595330
				ΑΘΡΟΙΣΜΑ =	1,614.472837
				T.E =	1,662.907022
7102.5	7102.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	2.016578 =		.211741
T 630		.105000 x	1.807300 =		.189767
567		.446250 x	392.805772 =		175.289576
574		.446250 x	3,596.534982 =		1,604.953736
				ΑΘΡΟΙΣΜΑ =	1,784.019819
				T.E =	1,837.540413

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	977.833358 =	103.894794

			T.E =	180.649192
7104	7104			
113		1.700000 x	20.419486 =	34.713126
576		.106250 x	7.425000 =	.788906
567		.106250 x	392.805772 =	41.735613

			T.E =	77.237646
7105	7105			
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563
576		.106250 x	7.425000 =	.788906
567		.106250 x	392.805772 =	41.735613

			T.E =	73.261441
7106.1	7106.1			
577		.265625 x	676.865719 =	179.792457

			AΘΡΟΙΣΜΑ =	179.792457

			T.E =	188.782079
7106.2	7106.2			
577		.297500 x	676.865719 =	201.367551

			AΘΡΟΙΣΜΑ =	201.367551

			T.E =	211.435929
7106.3	7106.3			
577		.350625 x	676.865719 =	237.326043

			AΘΡΟΙΣΜΑ =	237.326043

			T.E =	249.192345
7106.4	7106.4			
577		.425000 x	676.865719 =	287.667931

			AΘΡΟΙΣΜΑ =	287.667931

			T.E =	302.051327

7106.5	7106.5			
577		.531250 x	676.865719 =	359.584913

			ΑΘΡΟΙΣΜΑ =	359.584913

			T.E =	377.564159
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	188.782079 =	188.782079

			T.E =	229.582079
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	211.435929 =	211.435929

			T.E =	252.235929
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	249.192345 =	249.192345

			T.E =	289.992345
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	302.051327 =	302.051327

			T.E =	342.851327
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	377.564159 =	377.564159

			T.E =	418.364159
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,596.534982 =	191.065921

			T.E =	327.835921
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,596.534982 =	191.065921

			T.E =	367.945921

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,596.534982 =		191.065921

			T.E =		353.380021
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,596.534982 =		191.065921

			T.E =		340.825921
7112	7112				
398.13		1.300000 x	10.300000 =		13.390000
577		.010625 x	676.865719 =		7.191698

			T.E =		20.581698
7113	7113				
241		1.200000 x	7.750000 =		9.300000
574		.001063 x	3,596.534982 =		3.823117

			T.E =		13.123117
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	676.865719 =		35.958491

			T.E =		39.648491
7115	7115				
574		.026563 x	3,596.534982 =		95.534759

			T.E =		95.534759
7116	7116				
577		.170000 x	676.865719 =		115.067172

			T.E =		115.067172
7117	7117				
574		.001063 x	3,596.534982 =		3.823117

			T.E =		3.823117

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	641.368266 =	545.163026
574.1		.425000 x	2,184.957688 =	928.607017

			T.E =	1,901.941509
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,184.957688 =	1,857.214035
578		.850000 x	641.368266 =	545.163026

			T.E =	3,044.634259
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	382.917688 =	97.644010

			T.E =	311.729743
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	382.917688 =	227.836024

			T.E =	441.921757
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
575.1		.425000 x	257.177416 =	109.300402
578		.425000 x	641.368266 =	272.581513

			T.E =	542.446214
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	641.368266 =	817.744539
575.1		1.275000 x	257.177416 =	327.901205

			T.E =	1,413.252911
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	641.368266 =	272.581513

			T.E =	382.493129

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	641.368266 =	272.581513

			T.E =	382.493129
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.807300 =	.189767
T 630.1		.105000 x	2.016578 =	.211741
567		.122188 x	392.805772 =	47.996152
580		.122188 x	1,701.748462 =	207.933241

			AΘΡΟΙΣΜΑ =	259.705900

			T.E =	267.497077
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.016578 =	.211741
T 630		.105000 x	1.807300 =	.189767
580		.286875 x	1,701.748462 =	488.189090
567		.286875 x	392.805772 =	112.686156

			AΘΡΟΙΣΜΑ =	604.651753

			T.E =	622.791306
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	392.805772 =	25.041368
T 630		.105000 x	1.807300 =	.189767
T 630.1		.105000 x	2.016578 =	.211741
580		.063750 x	1,701.748462 =	108.486464

			T.E =	137.304340
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	2.016578 =	.211741
567		.127500 x	392.805772 =	50.082736
T 630		.105000 x	1.807300 =	.189767
580		.127500 x	1,701.748462 =	216.972929

			T.E =	270.832172
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,701.748462 =	90.405387

			T.E =	152.825387

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,701.748462 =		27.122467

			T.E =		115.679767
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,701.748462 =		27.122467

			T.E =		95.696167
7129	7129				
6751		1.000000 x	5.331576 =		5.331576

			T.E =		5.331576