

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

3ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.151500
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.175600
212	1.433300
213	1.949500
214	4.160000
221	.099900
224	.070000
231	.861000
241	7.750000
242	5.000000
251	290.000000
252	290.000000
301	4.060000
302	6.700000
360	11.600000
361	29.800000
362	3.800000
363	.610000
364	3.710000
365	24.300000
366	22.400000
367	.128500
368	21.100000
369	12.830000
370	8.440000
371	7.600000
372	1.340000
373	2.150000
374	2.900000
375	1.580000
376	
377	3.450000
378	.540000
379	15.150000
380	.280000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
417	134.530000

420	97.290000
428	437.840000
450	115.120000
451	159.550000
452	97.760000
453	90.720000
454	122.640000
455	432.990000

501	501				
211		50.000000 x	1.175600 =	58.780000	
214		3.000000 x	4.160000 =	12.480000	
401		1.000000 x	268.420000 =	268.420000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	560.772593

				Η.Δ. =	616.849852
502	502				
211		80.000000 x	1.175600 =	94.048000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	380.180000 =	380.180000	
214		7.000000 x	4.160000 =	29.120000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	734.441612

				Η.Δ. =	807.885773
503	503				
211		110.000000 x	1.175600 =	129.316000	
428		1.000000 x	437.840000 =	437.840000	
214		10.000000 x	4.160000 =	41.600000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	839.849612

				Η.Δ. =	923.834573
504	504				
211		40.000000 x	1.175600 =	47.024000	
214		2.000000 x	4.160000 =	8.320000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	103.360000 =	103.360000	

				ΑΘΡΟΙΣΜΑ =	349.793536

				Η.Δ. =	384.772890
505	505				
211		200.000000 x	1.175600 =	235.120000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	212.730000 =	212.730000	

				ΑΘΡΟΙΣΜΑ =	760.547688

				Η.Δ. =	836.602457

506	506				
211		95.000000 x	1.175600 =	111.682000	
214		6.000000 x	4.160000 =	24.960000	
405		1.000000 x	206.720000 =	206.720000	
242		2.500000 x	5.000000 =	12.500000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
			ΑΘΡΟΙΣΜΑ =	626.959688	
			Η.Δ. =	689.655657	
507	507				
211		165.000000 x	1.175600 =	193.974000	
214		10.000000 x	4.160000 =	41.600000	
242		7.000000 x	5.000000 =	35.000000	
406		1.000000 x	320.980000 =	320.980000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
			ΑΘΡΟΙΣΜΑ =	862.651688	
			Η.Δ. =	948.916857	
508	508				
211		40.000000 x	1.175600 =	47.024000	
407		1.000000 x	55.210000 =	55.210000	
115		4.000000 x	21.778427 =	87.113708	
116		16.000000 x	20.419486 =	326.711776	
408		2.000000 x	4.530000 =	9.060000	
214		2.000000 x	4.160000 =	8.320000	
			ΑΘΡΟΙΣΜΑ =	533.439484	
			Η.Δ. =	586.783432	
509	509				
211		80.000000 x	1.175600 =	94.048000	
117		8.000000 x	16.777917 =	134.223336	
409		1.000000 x	126.080000 =	126.080000	
214		5.000000 x	4.160000 =	20.800000	
			ΑΘΡΟΙΣΜΑ =	375.151336	
			Η.Δ. =	412.666470	
510	510				
211		80.000000 x	1.175600 =	94.048000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	4.160000 =	20.800000	
410		1.000000 x	116.530000 =	116.530000	
			ΑΘΡΟΙΣΜΑ =	365.601336	
			Η.Δ. =	402.161470	

511	511				
212		17.000000 x	1.433300 =	24.366100	
411		1.000000 x	27.370000 =	27.370000	
214		1.000000 x	4.160000 =	4.160000	
115		4.000000 x	21.778427 =	87.113708	
112		30.000000 x	17.312112 =	519.363360	

				ΑΘΡΟΙΣΜΑ =	662.373168

				Η.Δ. =	728.610485
512	512				
211		10.000000 x	1.175600 =	11.756000	
115		2.000000 x	21.778427 =	43.556854	
214		1.000000 x	4.160000 =	4.160000	
112		2.000000 x	17.312112 =	34.624224	
412		1.000000 x	2.990000 =	2.990000	

				ΑΘΡΟΙΣΜΑ =	97.087078

				Η.Δ. =	106.795786
518	518				
211		180.000000 x	1.175600 =	211.608000	
212		5.000000 x	1.433300 =	7.166500	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
417		1.000000 x	134.530000 =	134.530000	
214		12.000000 x	4.160000 =	49.920000	

				ΑΘΡΟΙΣΜΑ =	812.819084

				Η.Δ. =	894.100992
521	521				
211		40.000000 x	1.175600 =	47.024000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	4.160000 =	12.480000	
420		1.000000 x	97.290000 =	97.290000	

				ΑΘΡΟΙΣΜΑ =	387.887612

				Η.Δ. =	426.676373
550	550				
211		80.000000 x	1.175600 =	94.048000	
214		5.000000 x	4.160000 =	20.800000	
117		8.000000 x	16.777917 =	134.223336	
450		1.000000 x	115.120000 =	115.120000	

				ΑΘΡΟΙΣΜΑ =	364.191336

				Η.Δ. =	400.610470

560	560				
211		80.000000 x	1.175600 =	94.048000	
117		8.000000 x	16.777917 =	134.223336	
455		1.000000 x	432.990000 =	432.990000	
214		7.000000 x	4.160000 =	29.120000	
			AΘΡΟΙΣΜΑ =	690.381336	
			H.Δ. =	759.419470	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	586.783432 =	2.933917	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.806043	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	586.783432 =	2.933917	
504		.005000 x	384.772890 =	1.923864	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	894.100992 =	8.941010	
509		.005000 x	412.666470 =	2.063332	
			B.T =	21.872182	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	384.772890 =	1.923864	
509		.005000 x	412.666470 =	2.063332	
518		.014300 x	894.100992 =	12.785644	
508		.005000 x	586.783432 =	2.933917	
			B.T =	25.716817	
630	630				
512		.020000 x	106.795786 =	2.135916	
			B.T =	2.135916	
630.1	630.1				
510		.006000 x	402.161470 =	2.412969	
			B.T =	2.412969	

641	641			
231		.200000 x	.861000 =	.172200
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.543443
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	412.666470 =	1.485599
509		.011100 x	412.666470 =	4.580598
511		.050000 x	728.610485 =	36.430524
630		.600000 x	2.135916 =	1.281550
625		1.000000 x	25.716817 =	25.716817
224		120.000000 x	.070000 =	8.400000

			B.T =	125.148541
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	412.666470 =	4.539331
630		.320000 x	2.135916 =	.683493
625		1.000000 x	25.716817 =	25.716817
511		.050000 x	728.610485 =	36.430524
509		.001920 x	412.666470 =	.792320
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	165.365938
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	616.849852 =	.061685
503		.002000 x	923.834573 =	1.847669

			T.E =	2.030539
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	923.834573 =	.304865
501		.000080 x	616.849852 =	.049348
505		.000600 x	836.602457 =	.501961
507		.001400 x	948.916857 =	1.328484
509		.004447 x	412.666470 =	1.835128

			T.E =	4.140971

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	616.849852 =	.061685
503		.002000 x	923.834573 =	1.847669
509		.005312 x	412.666470 =	2.192084
506		.001330 x	689.655657 =	.917242

			T.E =	5.139865
1123B	1123B			
509		.001487 x	412.666470 =	.613635

			T.E =	.613635
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	426.676373 =	.085335
501		.000100 x	616.849852 =	.061685

			T.E =	.320141
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	4.140971 =	.828194
507		.000200 x	948.916857 =	.189783
501		.000100 x	616.849852 =	.061685
502		.000200 x	807.885773 =	.161577

			T.E =	2.028320
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	4.140971 =	4.140971
501		.002000 x	616.849852 =	1.233700

			T.E =	9.702699
1710	1710			
360		1.000000 x	11.600000 =	11.600000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	616.849852 =	.061685

			T.E =	15.597084
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	412.666470 =	2.146691
507		.001540 x	948.916857 =	1.461332
502		.002000 x	807.885773 =	1.615772
501		.000830 x	616.849852 =	.511985

			T.E =	5.908901

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	807.885773 =	2.342869
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	948.916857 =	1.897834
509		.004896 x	412.666470 =	2.020415
508		.004000 x	586.783432 =	2.347134

			T.E =	18.820951
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.806043 =	20.796345
112		.600000 x	17.312112 =	10.387267
509		.012432 x	412.666470 =	5.130270

			T.E =	45.758841
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.806043 =	20.796345
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	412.666470 =	5.130270

			T.E =	76.552132
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.806043 =	20.796345
652		.020000 x	165.365938 =	3.307319
651		.250000 x	125.148541 =	31.287135
509		.012432 x	412.666470 =	5.130270
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.644603
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	165.365938 =	16.536594
621		.350000 x	19.806043 =	6.932115
509		.003788 x	412.666470 =	1.563181
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.254397

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.872182 =	17.497746
630		.250000 x	2.135916 =	.533979
641		3.000000 x	7.543443 =	22.630329
625		.500000 x	25.716817 =	12.858409
511		.040000 x	728.610485 =	29.144419
509		.008880 x	412.666470 =	3.664478
509		.001500 x	412.666470 =	.619000
509		.005550 x	412.666470 =	2.290299
113		1.600000 x	20.419486 =	32.671178

			T.E =	176.116793
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	176.116793 =	.880584
652		.002000 x	165.365938 =	.330732
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.735749
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	165.365938 =	1.984391
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.598939
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	400.610470 =	1.502289

			T.E =	1.974537

5150	5150			
111		.030000 x	15.741598 =	.472248
550		.002500 x	400.610470 =	1.001526

			T.E =	1.473774
5160	5160			
213		.400000 x	1.949500 =	.779800
111		.160000 x	15.741598 =	2.518656
508		.001500 x	586.783432 =	.880175

			T.E =	4.178631
5210	5210			
363		.100000 x	.610000 =	.061000
112		.050000 x	17.312112 =	.865606
111		.040000 x	15.741598 =	.629664

			T.E =	1.556270
5220	5220			
363		.100000 x	.610000 =	.061000
112		.030000 x	17.312112 =	.519363
111		.020000 x	15.741598 =	.314832

			T.E =	.895195
5230	5230			
364		1.000000 x	3.710000 =	3.710000
112		.080000 x	17.312112 =	1.384969

			T.E =	5.094969
5240	5240			
112		.080000 x	17.312112 =	1.384969

			T.E =	1.384969
5311	5311			
111		.002000 x	15.741598 =	.031483
630.1		.020000 x	2.412969 =	.048259
510		.000250 x	402.161470 =	.100540
630		.020000 x	2.135916 =	.042718

			T.E =	.223001

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.412969 =	.048259
510		.000163 x	402.161470 =	.065552
630		.020000 x	2.135916 =	.042718

			T.E =	.176994
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.610000 =	.061000
111		.003300 x	15.741598 =	.051947

			T.E =	.112947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354				
111		.035000 x	15.741598 =		.550956
113		.025000 x	20.419486 =		.510487

			T.E =		1.061443
5361A	5361A				
365		.003000 x	24.300000 =		.072900
630		.000300 x	2.135916 =		.000641
510		.000188 x	402.161470 =		.075606
113		.001500 x	20.419486 =		.030629

			T.E =		.179776
5361B	5361B				
366		.003000 x	22.400000 =		.067200
510		.000188 x	402.161470 =		.075606
630		.000300 x	2.135916 =		.000641
113		.001500 x	20.419486 =		.030629

			T.E =		.174076
5362A	5362A				
365		.005000 x	24.300000 =		.121500
630		.000500 x	2.135916 =		.001068
510		.000313 x	402.161470 =		.125877
113		.002500 x	20.419486 =		.051049

			T.E =		.299493
5362B	5362B				
366		.005000 x	22.400000 =		.112000
630		.000500 x	2.135916 =		.001068
510		.000313 x	402.161470 =		.125877
113		.002500 x	20.419486 =		.051049

			T.E =		.289993
5363A	5363A				
365		.003000 x	24.300000 =		.072900
113		.001000 x	20.419486 =		.020419
510		.000125 x	402.161470 =		.050270
630		.000300 x	2.135916 =		.000641

			T.E =		.144230

5363B	5363B			
366		.003000 x	22.400000 =	.067200
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.135916 =	.000641
510		.000125 x	402.161470 =	.050270

			T.E =	.138530
5364A	5364A			
365		.005000 x	24.300000 =	.121500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.135916 =	.001068
510		.000225 x	402.161470 =	.090486

			T.E =	.249809
5364B	5364B			
366		.005000 x	22.400000 =	.112000
630		.000500 x	2.135916 =	.001068
510		.000225 x	402.161470 =	.090486
113		.001800 x	20.419486 =	.036755

			T.E =	.240309
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	15.150000 =	30.300000
510		.100000 x	402.161470 =	40.216147
630		.100000 x	2.135916 =	.213592
113		.800000 x	20.419486 =	16.335589

			T.E =	87.065327
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	400.610470 =	165.251819

			T.E =	243.959809
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	29.800000 =	447.000000	
363		20.000000 x	.610000 =	12.200000	
362		30.000000 x	3.800000 =	114.000000	
550		.375000 x	400.610470 =	150.228926	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	24.300000 =	48.600000	
111		20.000000 x	15.741598 =	314.831960	

				T.E =	1,495.250606
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.412969 =	24.129690	
510		.125000 x	402.161470 =	50.270184	
630		10.000000 x	2.135916 =	21.359160	

				T.E =	111.500632
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

				T.E =	23.612397
5530	5530				
453		.187500 x	90.720000 =	17.010000	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	48.493196
5540	5540				
363		15.000000 x	.610000 =	9.150000	
111		.750000 x	15.741598 =	11.806199	

				T.E =	20.956199
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

				T.E =	47.224794
5552	5552				
379		1.000000 x	15.150000 =	15.150000	
630		.100000 x	2.135916 =	.213592	
510		.050000 x	402.161470 =	20.108074	
113		.400000 x	20.419486 =	8.167794	

				T.E =	43.639460

5560A	5560A			
365		1.000000 x	24.300000 =	24.300000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.135916 =	.213592
510		.100000 x	402.161470 =	40.216147

			T.E =	81.065327
5560B	5560B			
366		1.000000 x	22.400000 =	22.400000
510		.100000 x	402.161470 =	40.216147
630		.100000 x	2.135916 =	.213592
113		.800000 x	20.419486 =	16.335589

			T.E =	79.165327
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248

			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248

			T.E =	.787080
5610	5610			
363		15.000000 x	.610000 =	9.150000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	400.610470 =	50.076309
367		20,000.000000 x	.128500 =	2,570.000000

			T.E =	3,101.474249
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.135916 =	21.359160
630.1		10.000000 x	2.412969 =	24.129690
510		.125000 x	402.161470 =	50.270184

			T.E =	111.500632
5622	5622			
111		1.500000 x	15.741598 =	23.612397

			T.E =	23.612397

5630	5630			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199
5640	5640			
111		10.000000 x	15.741598 =	157.415980
111		2.000000 x	15.741598 =	31.483196

			T.E =	188.899176
5650	5650			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240
5710	5710			
362		40.000000 x	3.800000 =	152.000000
111		5.000000 x	15.741598 =	78.707990
112		1.000000 x	17.312112 =	17.312112
560		.125000 x	759.419470 =	94.927434
510		.125000 x	402.161470 =	50.270184
509		.125000 x	412.666470 =	51.583309
114		1.000000 x	23.886192 =	23.886192
380		800.000000 x	.280000 =	224.000000
363		15.000000 x	.610000 =	9.150000
377		250.000000 x	3.450000 =	862.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,618.337220
5720	5720			
111		.500000 x	15.741598 =	7.870799
510		.062500 x	402.161470 =	25.135092
630		10.000000 x	2.135916 =	21.359160
630.1		10.000000 x	2.412969 =	24.129690

			T.E =	78.494741
5730	5730			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199