

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

2ο Τρίμηνο του 2009

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	Κατχ Τιμή X 1.8117/ 6.46	15.951934
112	Κατχ Τιμή X 1.8117/ 6.46	17.729980
113	Κατχ Τιμή X 1.8117/ 6.46	23.479183
114	Κατχ Τιμή X 1.8117/ 6.46	17.729980
115	Κατχ Τιμή X 1.8117/ 6.46	22.893045
116	Κατχ Τιμή X 1.8117/ 6.67	22.739959
117	Κατχ Τιμή X 1.8117/ 6.67	17.283129
118	Κατχ Τιμή X 1.8117/ 6.67	18.893831
119	Κατχ Τιμή X 1.8117/ 6.67	17.171765
120	Κατχ Τιμή X 1.8117/ 6.67	18.893831
121	Κατχ Τιμή X 1.8117/ 6.67	16.481852
122	Κατχ Τιμή X 1.8117/ 6.67	17.345601
123	Κατχ Τιμή X 1.8117/ 4.00	59.183710
211		.779800
212		.829400
213		3.800000
214		1.800000
221		.097700
222		.070000
231		35.000000
232		35.000000
241		290.000000
242		335.000000
251		.492800
252		1.750000
253		3.500000
254		5.000000
255		.666500
256		3.300000
261		
262		.980000
263		.540000
311		422.740000
312		127.340000
313		199.590000
314		4.290000
315		52.260000
316		4.290000
317		119.340000
318		25.900000
319		20.900000
320		148.360000
321		201.960000
322		280.600000
323		319.540000
324		175.310000
325		300.280000
326		99.790000
327		4.290000
351		427.630000
352		363.070000
353		427.630000
354		561.040000
355		280.600000
356		46.050000
357		220.620000
358		44.420000
359		92.090000
360		96.990000



361	74.180000
362	256.750000
363	97.130000
380	513.510000
381	513.510000
382	513.510000
383	590.590000
384	978.180000
385	177.730000
386	468.950000
387	67.660000
388	67.660000
389	67.660000

401	401			
211		110.000000 x	.779800 =	85.778000
213		10.000000 x	3.800000 =	38.000000
117		4.000000 x	17.283129 =	69.132516
116		8.000000 x	22.739959 =	181.919672
311		1.000000 x	422.740000 =	422.740000
		-----		
			ΑΘΡΟΙΣΜΑ =	797.570188
		-----		
			Η.Δ. =	877.327207
402	402			
211		180.000000 x	.779800 =	140.364000
312		1.000000 x	127.340000 =	127.340000
112		8.000000 x	17.729980 =	141.839840
212		5.000000 x	.829400 =	4.147000
213		12.000000 x	3.800000 =	45.600000
116		8.000000 x	22.739959 =	181.919672
117		8.000000 x	17.283129 =	138.265032
		-----		
			ΑΘΡΟΙΣΜΑ =	779.475544
		-----		
			Η.Δ. =	857.423098
403	403			
211		80.000000 x	.779800 =	62.384000
254		2.500000 x	5.000000 =	12.500000
213		6.000000 x	3.800000 =	22.800000
117		8.000000 x	17.283129 =	138.265032
116		8.000000 x	22.739959 =	181.919672
313		1.000000 x	199.590000 =	199.590000
		-----		
			ΑΘΡΟΙΣΜΑ =	617.458704
		-----		
			Η.Δ. =	679.204574
404	404			
211		80.000000 x	.779800 =	62.384000
213		5.000000 x	3.800000 =	19.000000
212		2.000000 x	.829400 =	1.658800
119		4.000000 x	17.171765 =	68.687060
118		8.000000 x	18.893831 =	151.150648
112		4.000000 x	17.729980 =	70.919920
314		1.000000 x	4.290000 =	4.290000
		-----		
			ΑΘΡΟΙΣΜΑ =	378.090428
		-----		
			Η.Δ. =	415.899471

405	405			
211		40.000000 x	.779800 =	31.192000
213		2.000000 x	3.800000 =	7.600000
115		16.000000 x	22.893045 =	366.288720
118		4.000000 x	18.893831 =	75.575324
316		2.000000 x	4.290000 =	8.580000
315		1.000000 x	52.260000 =	52.260000
		-----		
		ΑΘΡΟΙΣΜΑ =		541.496044
		-----		
		Η.Δ. =		595.645648
406	406			
211		80.000000 x	.779800 =	62.384000
213		5.000000 x	3.800000 =	19.000000
317		1.000000 x	119.340000 =	119.340000
120		8.000000 x	18.893831 =	151.150648
		-----		
		ΑΘΡΟΙΣΜΑ =		351.874648
		-----		
		Η.Δ. =		387.062113
407	407			
212		17.000000 x	.829400 =	14.099800
318		1.000000 x	25.900000 =	25.900000
112		30.000000 x	17.729980 =	531.899400
213		1.000000 x	3.800000 =	3.800000
118		4.000000 x	18.893831 =	75.575324
		-----		
		ΑΘΡΟΙΣΜΑ =		651.274524
		-----		
		Η.Δ. =		716.401976
408	408			
211		30.000000 x	.779800 =	23.394000
112		4.000000 x	17.729980 =	70.919920
116		8.000000 x	22.739959 =	181.919672
117		4.000000 x	17.283129 =	69.132516
320		1.000000 x	148.360000 =	148.360000
213		3.000000 x	3.800000 =	11.400000
		-----		
		ΑΘΡΟΙΣΜΑ =		505.126108
		-----		
		Η.Δ. =		555.638719
409	409			
211		50.000000 x	.779800 =	38.990000
112		4.000000 x	17.729980 =	70.919920
117		4.000000 x	17.283129 =	69.132516
116		8.000000 x	22.739959 =	181.919672
324		1.000000 x	175.310000 =	175.310000
213		5.000000 x	3.800000 =	19.000000
		-----		
		ΑΘΡΟΙΣΜΑ =		555.272108
		-----		
		Η.Δ. =		610.799319

410	410			
211		100.000000 x	.779800 =	77.980000
117		4.000000 x	17.283129 =	69.132516
116		8.000000 x	22.739959 =	181.919672
112		4.000000 x	17.729980 =	70.919920
321		1.000000 x	201.960000 =	201.960000
213		10.000000 x	3.800000 =	38.000000
			-----	
			ΑΘΡΟΙΣΜΑ =	639.912108
			-----	
			Η.Δ. =	703.903319
411	411			
211		200.000000 x	.779800 =	155.960000
117		4.000000 x	17.283129 =	69.132516
116		8.000000 x	22.739959 =	181.919672
112		4.000000 x	17.729980 =	70.919920
213		20.000000 x	3.800000 =	76.000000
325		1.000000 x	300.280000 =	300.280000
			-----	
			ΑΘΡΟΙΣΜΑ =	854.212108
			-----	
			Η.Δ. =	939.633319
412	412			
211		40.000000 x	.779800 =	31.192000
116		8.000000 x	22.739959 =	181.919672
326		1.000000 x	99.790000 =	99.790000
213		2.000000 x	3.800000 =	7.600000
			-----	
			ΑΘΡΟΙΣΜΑ =	320.501672
			-----	
			Η.Δ. =	352.551839
413	413			
211		15.000000 x	.779800 =	11.697000
213		1.500000 x	3.800000 =	5.700000
118		3.000000 x	18.893831 =	56.681493
112		3.000000 x	17.729980 =	53.189940
327		1.000000 x	4.290000 =	4.290000
			-----	
			ΑΘΡΟΙΣΜΑ =	131.558433
			-----	
			Η.Δ. =	144.714276
501	501			
211		170.000000 x	.779800 =	132.566000
380		1.000000 x	513.510000 =	513.510000
213		3.000000 x	3.800000 =	11.400000
351		1.000000 x	427.630000 =	427.630000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,085.106000
			-----	
			Η.Δ. =	1,193.616600

502	502			
211		170.000000 x	.779800 =	132.566000
381		1.000000 x	513.510000 =	513.510000
352		1.000000 x	363.070000 =	363.070000
213		3.000000 x	3.800000 =	11.400000
		-----		
			ΑΘΡΟΙΣΜΑ =	1,020.546000
		-----		
			Η.Δ. =	1,122.600600
503	503			
211		170.000000 x	.779800 =	132.566000
213		3.000000 x	3.800000 =	11.400000
353		1.000000 x	427.630000 =	427.630000
382		1.000000 x	513.510000 =	513.510000
		-----		
			ΑΘΡΟΙΣΜΑ =	1,085.106000
		-----		
			Η.Δ. =	1,193.616600
504	504			
211		190.000000 x	.779800 =	148.162000
213		6.000000 x	3.800000 =	22.800000
383		1.000000 x	590.590000 =	590.590000
354		1.000000 x	561.040000 =	561.040000
		-----		
			ΑΘΡΟΙΣΜΑ =	1,322.592000
		-----		
			Η.Δ. =	1,454.851200
505	505			
211		1,250.000000 x	.779800 =	974.750000
213		7.500000 x	3.800000 =	28.500000
384		1.000000 x	978.180000 =	978.180000
355		1.000000 x	280.600000 =	280.600000
		-----		
			ΑΘΡΟΙΣΜΑ =	2,262.030000
		-----		
			Η.Δ. =	2,488.233000
506	506			
211		200.000000 x	.779800 =	155.960000
385		1.000000 x	177.730000 =	177.730000
356		1.000000 x	46.050000 =	46.050000
213		2.000000 x	3.800000 =	7.600000
		-----		
			ΑΘΡΟΙΣΜΑ =	387.340000
		-----		
			Η.Δ. =	426.074000
507	507			
211		2,100.000000 x	.779800 =	1,637.580000
213		35.000000 x	3.800000 =	133.000000
386		1.000000 x	468.950000 =	468.950000
357		1.000000 x	220.620000 =	220.620000
		-----		
			ΑΘΡΟΙΣΜΑ =	2,460.150000
		-----		
			Η.Δ. =	2,656.962000



508	508			
358		1.000000 x	44.420000 =	44.420000
387		1.000000 x	67.660000 =	67.660000
			-----	
			ΑΘΡΟΙΣΜΑ =	112.080000
			-----	
			Η.Δ. =	117.684000
509	509			
359		1.000000 x	92.090000 =	92.090000
388		1.000000 x	67.660000 =	67.660000
			-----	
			ΑΘΡΟΙΣΜΑ =	159.750000
			-----	
			Η.Δ. =	167.737500
510	510			
360		1.000000 x	96.990000 =	96.990000
389		1.000000 x	67.660000 =	67.660000
			-----	
			ΑΘΡΟΙΣΜΑ =	164.650000
			-----	
			Η.Δ. =	172.882500
511	511			
509		.800000 x	167.737500 =	134.190000
			-----	
			Η.Δ. =	134.190000
512	512			
501		.600000 x	1,193.616600 =	716.169960
			-----	
			Η.Δ. =	716.169960
513	513			
363		1.000000 x	97.130000 =	97.130000
121		8.000000 x	16.481852 =	131.854816
122		8.000000 x	17.345601 =	138.764808
123		8.000000 x	59.183710 =	473.469680
			-----	
			Η.Δ. =	841.219304
1111A	1111A			
214		.200000 x	1.800000 =	.360000
511		.020000 x	134.190000 =	2.683800
405		.020000 x	595.645648 =	11.912913
513		.020000 x	841.219304 =	16.824386
			-----	
			Β.Τ =	31.781099

1111B	1111B			
501		1.000000 x	1,193.616600 =	1,193.616600
506		1.000000 x	426.074000 =	426.074000
509		2.000000 x	167.737500 =	335.475000
			-----	
			AΘΡΟΙΣΜΑ =	1,955.165600
	B.T =	.002500 x	1,955.165600 =	4.887914
			-----	
1112A	1112A			
506		1.000000 x	426.074000 =	426.074000
512		1.000000 x	716.169960 =	716.169960
			-----	
			AΘΡΟΙΣΜΑ =	1,142.243960
	B.T =	.025000 x	1,142.243960 =	28.556099
			-----	
1112B	1112B			
1111B		1.000000 x	4.887914 =	4.887914
			-----	
			B.T =	4.887914
1113A	1113A			
214		.200000 x	1.800000 =	.360000
112		.250000 x	17.729980 =	4.432495
511		.035000 x	134.190000 =	4.696650
513		.035000 x	841.219304 =	29.442676
405		.025000 x	595.645648 =	14.891141
			-----	
			B.T =	53.822962
1113B	1113B			
1111B		1.000000 x	4.887914 =	4.887914
			-----	
			B.T =	4.887914
1114A	1114A			
112		.250000 x	17.729980 =	4.432495
506		.033000 x	426.074000 =	14.060442
512		.033000 x	716.169960 =	23.633609
			-----	
			B.T =	42.126546
1114B	1114B			
1111B		1.000000 x	4.887914 =	4.887914
			-----	
			B.T =	4.887914

1121A	1121A			
214		.150000 x	1.800000 =	.270000
115		.500000 x	22.893045 =	11.446523
405		.020000 x	595.645648 =	11.912913
		-----		
			B.T =	23.629435
1121B	1121B			
1111B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914
1122A	1122A			
506		1.000000 x	426.074000 =	426.074000
512		1.000000 x	716.169960 =	716.169960
		-----		
			ΑΘΡΟΙΣΜΑ =	1,142.243960
	B.T =	.012500 x	1,142.243960 =	14.278050
		-----		
1122B	1122B			
1111B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914
1123A	1123A			
214		.150000 x	1.800000 =	.270000
112		.150000 x	17.729980 =	2.659497
405		.025000 x	595.645648 =	14.891141
115		1.000000 x	22.893045 =	22.893045
		-----		
			B.T =	40.713683
1123B	1123B			
1111B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914
1124A	1124A			
112		.150000 x	17.729980 =	2.659497
506		.020000 x	426.074000 =	8.521480
512		.020000 x	716.169960 =	14.323399
		-----		
			B.T =	25.504376
1124B	1124B			
1111B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914

3110A 1	3110A 1			
221		250.000000 x	.097700 =	24.425000
607		.500000 x	9.758104 =	4.879052
701 2		.500000 x	4.582815 =	2.291408
701 5		.250000 x	2.864260 =	.716065
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
606		.800000 x	8.908093 =	7.126474
113		1.200000 x	23.479183 =	28.175020
714		1.400000 x	7.704606 =	10.786448
407		.040000 x	716.401976 =	28.656079
319		.020000 x	20.900000 =	.418000
112		1.200000 x	17.729980 =	21.275976
-----				
			B.T =	133.139345
3110A 2	3110A 2			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		1.400000 x	7.704606 =	10.786448
113		1.200000 x	23.479183 =	28.175020
112		1.200000 x	17.729980 =	21.275976
319		.020000 x	20.900000 =	.418000
-----				
			B.T =	140.851608
3110A 3	3110A 3			
221		250.000000 x	.097700 =	24.425000
112		1.200000 x	17.729980 =	21.275976
113		1.200000 x	23.479183 =	28.175020
714		1.400000 x	7.704606 =	10.786448
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
319		.020000 x	20.900000 =	.418000
-----				
			B.T =	143.209439

3110A 4	3110A 4			
221		250.000000 x	.097700 =	24.425000
113		1.200000 x	23.479183 =	28.175020
630		.250000 x	2.894286 =	.723572
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 4		.500000 x	4.296389 =	2.148195
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
407		.040000 x	716.401976 =	28.656079
112		1.200000 x	17.729980 =	21.275976
714		1.400000 x	7.704606 =	10.786448
319		.020000 x	20.900000 =	.418000
			-----	
			B.T =	150.921702
3110B	3110B			
713 1		1.000000 x	5.100511 =	5.100511
704		1.000000 x	10.201021 =	10.201021
			-----	
			B.T =	15.301532
3120A 1	3120A 1			
3110A 1		1.000000 x	133.139345 =	133.139345
			-----	
			B.T =	133.139345
3120A 2	3120A 2			
3110A 2		1.000000 x	140.851608 =	140.851608
			-----	
			B.T =	140.851608
3120A 3	3120A 3			
3110A 3		1.000000 x	143.209439 =	143.209439
			-----	
			B.T =	143.209439
3120A 4	3120A 4			
3110A 4		1.000000 x	150.921702 =	150.921702
			-----	
			B.T =	150.921702
3120B	3120B			
713 2		1.000000 x	5.576429 =	5.576429
705		1.000000 x	11.152858 =	11.152858
			-----	
			B.T =	16.729287

3210A 1	3210A 1			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
3110A 1		.800000 x	133.139345 =	106.511476
				-----
			B.T =	122.015679
3210A 2	3210A 2			
111		.400000 x	15.951934 =	6.380774
3110A 2		.800000 x	140.851608 =	112.681286
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
				-----
			B.T =	128.185489
3210A 3	3210A 3			
111		.400000 x	15.951934 =	6.380774
3110A 3		.800000 x	143.209439 =	114.567551
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
				-----
			B.T =	130.071754
3210A 4	3210A 4			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
3110A 4		.800000 x	150.921702 =	120.737362
				-----
			B.T =	136.241564
3210A 5	3210A 5			
111		.400000 x	15.951934 =	6.380774
3110A 1		.800000 x	133.139345 =	106.511476
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
				-----
			B.T =	120.918233
3210A 6	3210A 6			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
3110A 2		.800000 x	140.851608 =	112.681286
				-----
			B.T =	127.088044

3210A 7	3210A 7			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
3110A 3		.800000 x	143.209439 =	114.567551
			B.T =	128.974308
3210A 8	3210A 8			
111		.400000 x	15.951934 =	6.380774
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
3110A 4		.800000 x	150.921702 =	120.737362
			B.T =	135.144119
3210B	3210B			
713 1		1.000000 x	5.100511 =	5.100511
704		1.000000 x	10.201021 =	10.201021
			B.T =	15.301532
3220A 1	3220A 1			
3210A 1		1.000000 x	122.015679 =	122.015679
			B.T =	122.015679
3220A 2	3220A 2			
3210A 2		1.000000 x	128.185489 =	128.185489
			B.T =	128.185489
3220A 3	3220A 3			
3210A 3		1.000000 x	130.071754 =	130.071754
			B.T =	130.071754
3220A 4	3220A 4			
3210A 4		1.000000 x	136.241564 =	136.241564
			B.T =	136.241564
3220A 5	3220A 5			
3210A 5		1.000000 x	120.918233 =	120.918233
			B.T =	120.918233

3220A 6	3220A 6			
3210A 6		1.000000 x	127.088044 =	127.088044
				-----
			B.T =	127.088044
3220A 7	3220A 7			
3210A 7		1.000000 x	128.974308 =	128.974308
				-----
			B.T =	128.974308
3220A 8	3220A 8			
3210A 8		1.000000 x	135.144119 =	135.144119
				-----
			B.T =	135.144119
3220B	3220B			
713 2		1.000000 x	5.576429 =	5.576429
705		1.000000 x	11.152858 =	11.152858
				-----
			B.T =	16.729287
3300A 1	3300A 1			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.864260 =	.716065
701 2		.500000 x	4.582815 =	2.291408
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		2.600000 x	7.704606 =	20.031976
113		2.000000 x	23.479183 =	46.958366
111		2.700000 x	15.951934 =	43.070222
319		.040000 x	20.900000 =	.836000
				-----
			B.T =	188.265465
3300A 2	3300A 2			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
319		.040000 x	20.900000 =	.836000
113		2.000000 x	23.479183 =	46.958366
407		.040000 x	716.401976 =	28.656079
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
714		2.600000 x	7.704606 =	20.031976
111		2.700000 x	15.951934 =	43.070222
				-----
			B.T =	195.977727



3300A 3	3300A 3			
221		300.000000 x	.097700 =	29.310000
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
714		2.600000 x	7.704606 =	20.031976
319		.040000 x	20.900000 =	.836000
113		2.000000 x	23.479183 =	46.958366
111		2.700000 x	15.951934 =	43.070222
-----				
			B.T =	198.335558
3300A 4	3300A 4			
221		300.000000 x	.097700 =	29.310000
113		2.000000 x	23.479183 =	46.958366
714		2.600000 x	7.704606 =	20.031976
111		2.700000 x	15.951934 =	43.070222
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 4		.500000 x	4.296389 =	2.148195
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
407		.040000 x	716.401976 =	28.656079
319		.040000 x	20.900000 =	.836000
-----				
			B.T =	206.047821
3300B 1	3300B 1			
713 1		1.000000 x	5.100511 =	5.100511
704		1.000000 x	10.201021 =	10.201021
-----				
			B.T =	15.301532
3300B 2	3300B 2			
713 2		1.000000 x	5.576429 =	5.576429
705		1.000000 x	11.152858 =	11.152858
-----				
			B.T =	16.729287

3400A 1	3400A 1			
221		300.000000 x	.097700 =	29.310000
255		5.000000 x	.666500 =	3.332500
701 5		.250000 x	2.864260 =	.716065
701 2		.800000 x	4.582815 =	3.666252
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
111		2.700000 x	15.951934 =	43.070222
319		.030000 x	20.900000 =	.627000

-----  
B.T = 200.826561

3400A 2	3400A 2			
221		300.000000 x	.097700 =	29.310000
407		.040000 x	716.401976 =	28.656079
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
111		2.700000 x	15.951934 =	43.070222
319		.030000 x	20.900000 =	.627000
255		5.000000 x	.666500 =	3.332500

-----  
B.T = 208.538823

3400A 3	3400A 3			
221		300.000000 x	.097700 =	29.310000
111		2.700000 x	15.951934 =	43.070222
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
319		.030000 x	20.900000 =	.627000
255		5.000000 x	.666500 =	3.332500

-----  
B.T = 210.896654

3400A 4	3400A 4			
221		300.000000 x	.097700 =	29.310000
407		.040000 x	716.401976 =	28.656079
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 4		.500000 x	4.296389 =	2.148195
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
113		2.000000 x	23.479183 =	46.958366
113		.500000 x	23.479183 =	11.739592
112		1.000000 x	17.729980 =	17.729980
111		2.700000 x	15.951934 =	43.070222
319		.030000 x	20.900000 =	.627000
255		5.000000 x	.666500 =	3.332500
			B.T =	218.608917
3400B 1	3400B 1			
704		1.000000 x	10.201021 =	10.201021
			B.T =	10.201021
3400B 2	3400B 2			
705		1.000000 x	11.152858 =	11.152858
			B.T =	11.152858
4110A 1	4110A 1			
221		350.000000 x	.097700 =	34.195000
111		4.000000 x	15.951934 =	63.807736
701 5		.100000 x	2.864260 =	.286426
701 2		.800000 x	4.582815 =	3.666252
701 2		.500000 x	4.582815 =	2.291408
630		.100000 x	2.894286 =	.289429
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.070000 x	716.401976 =	50.148138
113		1.500000 x	23.479183 =	35.218775
			B.T =	201.908689

4110A 2	4110A 2			
221		350.000000 x	.097700 =	34.195000
701 5		.100000 x	2.864260 =	.286426
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.100000 x	2.894286 =	.289429
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
407		.070000 x	716.401976 =	50.148138
113		1.500000 x	23.479183 =	35.218775
111		4.000000 x	15.951934 =	63.807736
			B.T =	209.620952
4110A 3	4110A 3			
221		350.000000 x	.097700 =	34.195000
407		.070000 x	716.401976 =	50.148138
701 5		.100000 x	2.864260 =	.286426
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.100000 x	2.894286 =	.289429
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
113		1.500000 x	23.479183 =	35.218775
111		4.000000 x	15.951934 =	63.807736
			B.T =	211.978783
4110A 4	4110A 4			
221		350.000000 x	.097700 =	34.195000
407		.070000 x	716.401976 =	50.148138
610		.800000 x	21.782136 =	17.425709
701 5		.100000 x	2.864260 =	.286426
701 4		.800000 x	4.296389 =	3.437111
701 4		.500000 x	4.296389 =	2.148195
630		.100000 x	2.894286 =	.289429
611		.500000 x	25.469055 =	12.734528
113		1.500000 x	23.479183 =	35.218775
111		4.000000 x	15.951934 =	63.807736
			B.T =	219.691045
4110B	4110B			
112		8.000000 x	17.729980 =	141.839840
508		1.000000 x	117.684000 =	117.684000
513		1.000000 x	841.219304 =	841.219304
506		1.000000 x	426.074000 =	426.074000
			B.T =	1,526.817144

4120A 1	4120A 1			
221		350.000000 x	.097700 =	34.195000
701 2		1.200000 x	4.582815 =	5.499378
607		1.200000 x	9.758104 =	11.709725
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.729980 =	88.649900
		-----		
			B.T =	162.734003
4120A 2	4120A 2			
221		350.000000 x	.097700 =	34.195000
701 4		1.200000 x	4.296389 =	5.155667
611		1.200000 x	25.469055 =	30.562866
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.729980 =	88.649900
		-----		
			B.T =	181.243433
4120B	4120B			
4110B		.040000 x	1,526.817144 =	61.072686
		-----		
			B.T =	61.072686
4130A 1	4130A 1			
221		350.000000 x	.097700 =	34.195000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	716.401976 =	35.820099
606		.800000 x	8.908093 =	7.126474
607		.500000 x	9.758104 =	4.879052
701 2		.500000 x	4.582815 =	2.291408
701 2		.800000 x	4.582815 =	3.666252
111		2.000000 x	15.951934 =	31.903868
		-----		
			B.T =	142.562153
4130A 2	4130A 2			
221		350.000000 x	.097700 =	34.195000
407		.050000 x	716.401976 =	35.820099
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
111		2.000000 x	15.951934 =	31.903868
263		42.000000 x	.540000 =	22.680000
		-----		
			B.T =	150.274415

4130A 3	4130A 3			
221		350.000000 x	.097700 =	34.195000
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.050000 x	716.401976 =	35.820099
111		2.000000 x	15.951934 =	31.903868
263		42.000000 x	.540000 =	22.680000
			B.T =	152.632246
4130A 4	4130A 4			
221		350.000000 x	.097700 =	34.195000
701 4		.500000 x	4.296389 =	2.148195
701 4		.800000 x	4.296389 =	3.437111
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
407		.050000 x	716.401976 =	35.820099
263		42.000000 x	.540000 =	22.680000
111		2.000000 x	15.951934 =	31.903868
			B.T =	160.344509
4130B	4130B			
4120B		1.000000 x	61.072686 =	61.072686
			B.T =	61.072686
4210A 1	4210A 1			
221		65.000000 x	.097700 =	6.350500
630		.150000 x	2.894286 =	.434143
701 5		.150000 x	2.864260 =	.429639
701 2		.300000 x	4.582815 =	1.374845
701 2		1.050000 x	4.582815 =	4.811956
222		10.000000 x	.070000 =	.700000
607		.300000 x	9.758104 =	2.927431
601		1.050000 x	23.927901 =	25.124296
			B.T =	42.152809
4210A 2	4210A 2			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.864260 =	.429639
701 4		.300000 x	4.296389 =	1.288917
630		.150000 x	2.894286 =	.434143
611		.300000 x	25.469055 =	7.640717
701 2		1.050000 x	4.582815 =	4.811956
222		10.000000 x	.070000 =	.700000
601		1.050000 x	23.927901 =	25.124296
			B.T =	46.780167

4210A 3	4210A 3			
221		65.000000 x	.097700 =	6.350500
701 5		.150000 x	2.864260 =	.429639
701 2		.300000 x	4.582815 =	1.374845
701 2		1.050000 x	4.582815 =	4.811956
630		.150000 x	2.894286 =	.434143
609		1.050000 x	20.498384 =	21.523303
607		.300000 x	9.758104 =	2.927431
222		10.000000 x	.070000 =	.700000
-----				
			B.T =	38.551817
4210A 4	4210A 4			
221		65.000000 x	.097700 =	6.350500
222		10.000000 x	.070000 =	.700000
701 5		.150000 x	2.864260 =	.429639
701 4		.300000 x	4.296389 =	1.288917
701 2		1.050000 x	4.582815 =	4.811956
630		.150000 x	2.894286 =	.434143
611		.300000 x	25.469055 =	7.640717
609		1.050000 x	20.498384 =	21.523303
-----				
			B.T =	43.179174
4210B	4210B			
111		4.000000 x	15.951934 =	63.807736
112		1.500000 x	17.729980 =	26.594970
113		2.500000 x	23.479183 =	58.697958
112		.200000 x	17.729980 =	3.545996
-----				
			B.T =	152.646660
4220A 1	4220A 1			
221		200.000000 x	.097700 =	19.540000
701 2		.800000 x	4.582815 =	3.666252
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
113		1.000000 x	23.479183 =	23.479183
111		1.200000 x	15.951934 =	19.142321
701 5		.250000 x	2.864260 =	.716065
-----				
			B.T =	110.220405

4220A 2	4220A 2			
221		200.000000 x	.097700 =	19.540000
111		1.200000 x	15.951934 =	19.142321
113		1.000000 x	23.479183 =	23.479183
611		.500000 x	25.469055 =	12.734528
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079

-----  
B.T = 117.932668

4220A 3	4220A 3			
221		200.000000 x	.097700 =	19.540000
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
111		1.200000 x	15.951934 =	19.142321
407		.040000 x	716.401976 =	28.656079
113		1.000000 x	23.479183 =	23.479183
701 5		.250000 x	2.864260 =	.716065

-----  
B.T = 120.290499

4220A 4	4220A 4			
221		200.000000 x	.097700 =	19.540000
111		1.200000 x	15.951934 =	19.142321
407		.040000 x	716.401976 =	28.656079
611		.500000 x	25.469055 =	12.734528
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 4		.800000 x	4.296389 =	3.437111
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
113		1.000000 x	23.479183 =	23.479183

-----  
B.T = 128.002761



4300A 1	4300A 1			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.864260 =	.716065
701 2		.800000 x	4.582815 =	3.666252
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868
			-----	
			ΑΘΡΟΙΣΜΑ =	151.193086
	B.T =	.200000 x	151.193086 =	30.238617
			-----	
4300A 2	4300A 2			
221		350.000000 x	.097700 =	34.195000
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868
			-----	
			ΑΘΡΟΙΣΜΑ =	158.905348
	B.T =	.200000 x	158.905348 =	31.781070
			-----	
4300A 3	4300A 3			
221		350.000000 x	.097700 =	34.195000
113		1.200000 x	23.479183 =	28.175020
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 2		.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
111		2.000000 x	15.951934 =	31.903868
			-----	
			ΑΘΡΟΙΣΜΑ =	161.263180
	B.T =	.200000 x	161.263180 =	32.252636
			-----	

4300A 4	4300A 4			
221		350.000000 x	.097700 =	34.195000
113		1.200000 x	23.479183 =	28.175020
611		.500000 x	25.469055 =	12.734528
701 5		.250000 x	2.864260 =	.716065
701 4		.800000 x	4.296389 =	3.437111
701 4		.500000 x	4.296389 =	2.148195
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
111		2.000000 x	15.951934 =	31.903868
			-----	
			ΑΘΡΟΙΣΜΑ =	168.975442
	B.T =	.200000 x	168.975442 =	33.795088
			-----	
4300B	4300B			
221		2.000000 x	.097700 =	.195400
112		.400000 x	17.729980 =	7.091992
262		4.000000 x	.980000 =	3.920000
			-----	
			B.T =	11.207392
601	601			
111		1.500000 x	15.951934 =	23.927901
			-----	
			B.T =	23.927901
602	602			
403		.002500 x	679.204574 =	1.698011
			-----	
			B.T =	1.698011
603	603			
111		.300000 x	15.951934 =	4.785580
412		.003300 x	352.551839 =	1.163421
401		.001000 x	877.327207 =	.877327
			-----	
			B.T =	6.826328
604	604			
111		.200000 x	15.951934 =	3.190387
404		.005000 x	415.899471 =	2.079497
401		.001100 x	877.327207 =	.965060
412		.004000 x	352.551839 =	1.410207
			-----	
			B.T =	7.645151

605	605			
112		.100000 x	17.729980 =	1.772998
401		.001000 x	877.327207 =	.877327
402		.006200 x	857.423098 =	5.316023
412		.004000 x	352.551839 =	1.410207
406		.006200 x	387.062113 =	2.399785
-----				
			B.T =	11.776341
606	606			
111		.100000 x	15.951934 =	1.595193
401		.001000 x	877.327207 =	.877327
412		.005000 x	352.551839 =	1.762759
406		.006700 x	387.062113 =	2.593316
404		.005000 x	415.899471 =	2.079497
-----				
			B.T =	8.908093
607	607			
111		.100000 x	15.951934 =	1.595193
412		.005000 x	352.551839 =	1.762759
401		.001400 x	877.327207 =	1.228258
406		.006700 x	387.062113 =	2.593316
404		.006200 x	415.899471 =	2.578577
-----				
			B.T =	9.758104
608	608			
111		.100000 x	15.951934 =	1.595193
412		.005000 x	352.551839 =	1.762759
406		.006700 x	387.062113 =	2.593316
404		.012500 x	415.899471 =	5.198743
401		.002000 x	877.327207 =	1.754654
-----				
			B.T =	12.904667
609	609			
214		.100000 x	1.800000 =	.180000
405		.005000 x	595.645648 =	2.978228
115		.200000 x	22.893045 =	4.578609
111		.800000 x	15.951934 =	12.761547
-----				
			B.T =	20.498384

610	610			
214		.100000 x	1.800000 =	.180000
412		.005000 x	352.551839 =	1.762759
406		.005000 x	387.062113 =	1.935311
405		.005000 x	595.645648 =	2.978228
402		.010000 x	857.423098 =	8.574231
112		.100000 x	17.729980 =	1.772998
115		.200000 x	22.893045 =	4.578609
			B.T =	21.782136
611	611			
214		.100000 x	1.800000 =	.180000
112		.100000 x	17.729980 =	1.772998
405		.005000 x	595.645648 =	2.978228
412		.005000 x	352.551839 =	1.762759
406		.005000 x	387.062113 =	1.935311
402		.014300 x	857.423098 =	12.261150
115		.200000 x	22.893045 =	4.578609
			B.T =	25.469055
612	612			
214		.150000 x	1.800000 =	.270000
408		.010000 x	555.638719 =	5.556387
405		.005000 x	595.645648 =	2.978228
115		.200000 x	22.893045 =	4.578609
111		.300000 x	15.951934 =	4.785580
			AΘΡΟΙΣΜΑ =	18.168805
	B.T =	1.068000 x	18.168805 =	19.404283
613	613			
214		.150000 x	1.800000 =	.270000
409		.010000 x	610.799319 =	6.107993
405		.005000 x	595.645648 =	2.978228
115		.200000 x	22.893045 =	4.578609
111		.500000 x	15.951934 =	7.975967
			AΘΡΟΙΣΜΑ =	21.910797
	B.T =	1.282000 x	21.910797 =	28.089642
614	614			
214		.150000 x	1.800000 =	.270000
111		.500000 x	15.951934 =	7.975967
115		.200000 x	22.893045 =	4.578609
410		.010000 x	703.903319 =	7.039033
405		.005000 x	595.645648 =	2.978228
			AΘΡΟΙΣΜΑ =	22.841837
	B.T =	1.602000 x	22.841837 =	36.592624

615	615			
214		.150000 x	1.800000 =	.270000
410		.010000 x	703.903319 =	7.039033
111		.700000 x	15.951934 =	11.166354
405		.005000 x	595.645648 =	2.978228
115		.200000 x	22.893045 =	4.578609
			-----	
			ΑΘΡΟΙΣΜΑ =	26.032224
	B.T =	1.832000 x	26.032224 =	47.691035
			-----	
616	616			
214		.150000 x	1.800000 =	.270000
111		.800000 x	15.951934 =	12.761547
405		.005000 x	595.645648 =	2.978228
411		.010000 x	939.633319 =	9.396333
115		.200000 x	22.893045 =	4.578609
			-----	
			ΑΘΡΟΙΣΜΑ =	29.984718
	B.T =	2.137000 x	29.984718 =	64.077342
			-----	
617	617			
112		4.000000 x	17.729980 =	70.919920
513		1.000000 x	841.219304 =	841.219304
506		1.000000 x	426.074000 =	426.074000
503		1.000000 x	1,193.616600 =	1,193.616600
			-----	
			ΑΘΡΟΙΣΜΑ =	2,531.829824
	B.T =	.006250 x	2,531.829824 =	15.823936
			-----	
618	618			
112		4.000000 x	17.729980 =	70.919920
513		1.000000 x	841.219304 =	841.219304
506		1.000000 x	426.074000 =	426.074000
503		1.000000 x	1,193.616600 =	1,193.616600
			-----	
			ΑΘΡΟΙΣΜΑ =	2,531.829824
	B.T =	.007700 x	2,531.829824 =	19.495090
			-----	
619	619			
112		4.000000 x	17.729980 =	70.919920
503		1.000000 x	1,193.616600 =	1,193.616600
506		1.000000 x	426.074000 =	426.074000
513		1.000000 x	841.219304 =	841.219304
			-----	
			ΑΘΡΟΙΣΜΑ =	2,531.829824
	B.T =	.010000 x	2,531.829824 =	25.318298
			-----	

620	620			
112		4.000000 x	17.729980 =	70.919920
513		1.000000 x	841.219304 =	841.219304
506		1.000000 x	426.074000 =	426.074000
503		1.000000 x	1,193.616600 =	1,193.616600
			-----	
			ΑΘΡΟΙΣΜΑ =	2,531.829824
	B.T =	.012500 x	2,531.829824 =	31.647873
			-----	
621	621			
112		4.000000 x	17.729980 =	70.919920
506		1.000000 x	426.074000 =	426.074000
503		1.000000 x	1,193.616600 =	1,193.616600
513		1.000000 x	841.219304 =	841.219304
			-----	
			ΑΘΡΟΙΣΜΑ =	2,531.829824
	B.T =	.016600 x	2,531.829824 =	42.028375
			-----	
630	630			
413		.020000 x	144.714276 =	2.894286
			-----	
			B.T =	2.894286
701 1	701 1			
406		.012580 x	387.062113 =	4.869241
			-----	
			B.T =	4.869241
701 2	701 2			
406		.011840 x	387.062113 =	4.582815
			-----	
			B.T =	4.582815
701 3	701 3			
406		.011544 x	387.062113 =	4.468245
			-----	
			B.T =	4.468245
701 4	701 4			
406		.011100 x	387.062113 =	4.296389
			-----	
			B.T =	4.296389
701 5	701 5			
406		.007400 x	387.062113 =	2.864260
			-----	
			B.T =	2.864260

702	702			
112		8.000000 x	17.729980 =	141.839840
506		1.000000 x	426.074000 =	426.074000
513		.300000 x	841.219304 =	252.365791
509		2.000000 x	167.737500 =	335.475000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,155.754631
	B.T =	.002500 x	1,155.754631 =	2.889387
			-----	
703	703			
112		4.000000 x	17.729980 =	70.919920
513		.300000 x	841.219304 =	252.365791
503		1.000000 x	1,193.616600 =	1,193.616600
510		2.000000 x	172.882500 =	345.765000
506		1.000000 x	426.074000 =	426.074000
			-----	
			ΑΘΡΟΙΣΜΑ =	2,288.741311
	B.T =	.002500 x	2,288.741311 =	5.721853
			-----	
704	704			
112		4.000000 x	17.729980 =	70.919920
513		.500000 x	841.219304 =	420.609652
506		1.000000 x	426.074000 =	426.074000
502		1.000000 x	1,122.600600 =	1,122.600600
			-----	
			ΑΘΡΟΙΣΜΑ =	2,040.204172
	B.T =	.005000 x	2,040.204172 =	10.201021
			-----	
705	705			
112		4.000000 x	17.729980 =	70.919920
513		.600000 x	841.219304 =	504.731582
506		1.000000 x	426.074000 =	426.074000
504		1.000000 x	1,454.851200 =	1,454.851200
			-----	
			ΑΘΡΟΙΣΜΑ =	2,456.576702
	B.T =	.004540 x	2,456.576702 =	11.152858
			-----	
706	706			
501		1.000000 x	1,193.616600 =	1,193.616600
509		2.000000 x	167.737500 =	335.475000
506		1.000000 x	426.074000 =	426.074000
			-----	
			ΑΘΡΟΙΣΜΑ =	1,955.165600
	B.T =	.002500 x	1,955.165600 =	4.887914
			-----	
707	707			
505		1.000000 x	2,488.233000 =	2,488.233000
510		2.000000 x	172.882500 =	345.765000
506		1.000000 x	426.074000 =	426.074000
			-----	
			ΑΘΡΟΙΣΜΑ =	3,260.072000
	B.T =	.001000 x	3,260.072000 =	3.260072
			-----	

708	708			
708A		1.000000 x	17.289664 =	17.289664
708B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	22.177578
708A	708A			
214		.050000 x	1.800000 =	.090000
513		.010000 x	841.219304 =	8.412193
511		.010000 x	134.190000 =	1.341900
405		.012500 x	595.645648 =	7.445571
		-----		
			B.T =	17.289664
708B	708B			
706		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914
709	709			
709A		1.000000 x	14.278050 =	14.278050
709B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	19.165964
709A	709A			
506		1.000000 x	426.074000 =	426.074000
512		1.000000 x	716.169960 =	716.169960
		-----		
			AΘΡΟΙΣΜΑ =	1,142.243960
	B.T =	.012500 x	1,142.243960 =	14.278050
		-----		
709B	709B			
706		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	4.887914
710	710			
710A		1.000000 x	49.390467 =	49.390467
710B		1.000000 x	4.887914 =	4.887914
		-----		
			B.T =	54.278381
710A	710A			
214		.200000 x	1.800000 =	.360000
405		.025000 x	595.645648 =	14.891141
513		.035000 x	841.219304 =	29.442676
511		.035000 x	134.190000 =	4.696650
		-----		
			B.T =	49.390467



710B	710B			
706		1.000000 x	4.887914 =	4.887914
				-----
			B.T =	4.887914
711	711			
711A		1.000000 x	38.036724 =	38.036724
711B		1.000000 x	4.887914 =	4.887914
				-----
			B.T =	42.924638
711A	711A			
506		1.000000 x	426.074000 =	426.074000
512		1.000000 x	716.169960 =	716.169960
				-----
			AΘΡΟΙΣΜΑ =	1,142.243960
	B.T =	.033300 x	1,142.243960 =	38.036724
				-----
711B	711B			
706		1.000000 x	4.887914 =	4.887914
				-----
			B.T =	4.887914
712	712			
513		1.000000 x	841.219304 =	841.219304
				-----
			AΘΡΟΙΣΜΑ =	841.219304
	B.T =	.004000 x	841.219304 =	3.364877
				-----
713 1	713 1			
704		.500000 x	10.201021 =	5.100511
				-----
			B.T =	5.100511
713 2	713 2			
705		.500000 x	11.152858 =	5.576429
				-----
			B.T =	5.576429
714	714			
714A		1.000000 x	3.583690 =	3.583690
714B		1.000000 x	4.120916 =	4.120916
				-----
			B.T =	7.704606

714A	714A			
242		.070000 x	335.000000 =	23.450000
114		2.000000 x	17.729980 =	35.459960
252		1.000000 x	1.750000 =	1.750000
113		2.000000 x	23.479183 =	46.958366
			AΘΡΟΙΣΜΑ =	107.618326
	B.T =	.033300 x	107.618326 =	3.583690
714B	714B			
113		.100000 x	23.479183 =	2.347918
114		.100000 x	17.729980 =	1.772998
			B.T =	4.120916
1111	1111			
1111A		1.000000 x	31.781099 =	31.781099
1111B		1.000000 x	4.887914 =	4.887914
			T.E =	36.669013
1112	1112			
1112A		1.000000 x	28.556099 =	28.556099
1112B		1.000000 x	4.887914 =	4.887914
			T.E =	33.444013
1113	1113			
1113A		1.000000 x	53.822962 =	53.822962
1113B		1.000000 x	4.887914 =	4.887914
			T.E =	58.710876
1114	1114			
1114A		1.000000 x	42.126546 =	42.126546
1114B		1.000000 x	4.887914 =	4.887914
			T.E =	47.014460
1121	1121			
1121A		1.000000 x	23.629435 =	23.629435
1121B		1.000000 x	4.887914 =	4.887914
			T.E =	28.517349
1122	1122			
1122A		1.000000 x	14.278050 =	14.278050
1122B		1.000000 x	4.887914 =	4.887914
			T.E =	19.165964

1123	1123			
1123A		1.000000 x	40.713683 =	40.713683
1123B		1.000000 x	4.887914 =	4.887914
		-----		
			T.E =	45.601597
1124	1124			
1124A		1.000000 x	25.504376 =	25.504376
1124B		1.000000 x	4.887914 =	4.887914
		-----		
			T.E =	30.392290
1210	1210			
707		1.000000 x	3.260072 =	3.260072
		-----		
			T.E =	3.260072
1220	1220			
708		1.000000 x	22.177578 =	22.177578
		-----		
			T.E =	22.177578
1230	1230			
709		1.000000 x	19.165964 =	19.165964
		-----		
			T.E =	19.165964
1311	1311			
712		.250000 x	3.364877 =	.841219
		-----		
			T.E =	.841219
1312	1312			
712		.250000 x	3.364877 =	.841219
701 1		1.000000 x	4.869241 =	4.869241
602		1.000000 x	1.698011 =	1.698011
		-----		
			T.E =	7.408471
1313	1313			
712		.250000 x	3.364877 =	.841219
603		1.000000 x	6.826328 =	6.826328
701 2		1.000000 x	4.582815 =	4.582815
		-----		
			T.E =	12.250362

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.951934 =	1.595193	
712		.250000 x	3.364877 =	.841219	
		-----			
			T.E =	37.436413	
1321	1321				
112		.200000 x	17.729980 =	3.545996	
701	1	1.000000 x	4.869241 =	4.869241	
602		1.000000 x	1.698011 =	1.698011	
		-----			
			T.E =	10.113248	
1322	1322				
112		.200000 x	17.729980 =	3.545996	
603		1.000000 x	6.826328 =	6.826328	
701	2	1.000000 x	4.582815 =	4.582815	
		-----			
			T.E =	14.955139	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.951934 =	1.595193	
112		.100000 x	17.729980 =	1.772998	
		-----			
			T.E =	38.368191	
2110	2110				
712		.500000 x	3.364877 =	1.682439	
702		1.000000 x	2.889387 =	2.889387	
608		1.000000 x	12.904667 =	12.904667	
701	4	1.000000 x	4.296389 =	4.296389	
		-----			
			T.E =	21.772882	
2120	2120				
712		.500000 x	3.364877 =	1.682439	
702		1.000000 x	2.889387 =	2.889387	
701	2	1.000000 x	4.582815 =	4.582815	
603		1.000000 x	6.826328 =	6.826328	
		-----			
			T.E =	15.980969	
2130	2130				
712		.500000 x	3.364877 =	1.682439	
604		1.000000 x	7.645151 =	7.645151	
701	2	1.000000 x	4.582815 =	4.582815	
702		1.000000 x	2.889387 =	2.889387	
		-----			
			T.E =	16.799792	

2140	2140			
712		.500000 x	3.364877 =	1.682439
605		1.000000 x	11.776341 =	11.776341
702		1.000000 x	2.889387 =	2.889387
701 2		1.000000 x	4.582815 =	4.582815
-----				
			T.E =	20.930982
2210	2210			
712		.500000 x	3.364877 =	1.682439
609		1.050000 x	20.498384 =	21.523303
702		1.000000 x	2.889387 =	2.889387
701 2		1.000000 x	4.582815 =	4.582815
-----				
			T.E =	30.677944
2220	2220			
712		.500000 x	3.364877 =	1.682439
702		1.000000 x	2.889387 =	2.889387
701 2		1.000000 x	4.582815 =	4.582815
609		1.150000 x	20.498384 =	23.573142
-----				
			T.E =	32.727782
2230	2230			
111		.200000 x	15.951934 =	3.190387
609		1.200000 x	20.498384 =	24.598061
701 2		1.000000 x	4.582815 =	4.582815
-----				
			T.E =	32.371263
2240	2240			
111		.300000 x	15.951934 =	4.785580
609		1.200000 x	20.498384 =	24.598061
701 2		1.000000 x	4.582815 =	4.582815
-----				
			T.E =	33.966456
2310	2310			
612		1.000000 x	19.404283 =	19.404283
701 3		1.000000 x	4.468245 =	4.468245
703		1.000000 x	5.721853 =	5.721853
-----				
			T.E =	29.594381
2320	2320			
613		1.000000 x	28.089642 =	28.089642
703		1.000000 x	5.721853 =	5.721853
701 3		1.000000 x	4.468245 =	4.468245
-----				
			T.E =	38.279740

2330	2330				
614		1.000000 x	36.592624 =		36.592624
703		1.000000 x	5.721853 =		5.721853
701 3		1.000000 x	4.468245 =		4.468245
			-----		
			T.E =		46.782722
2340	2340				
615		1.000000 x	47.691035 =		47.691035
703		1.000000 x	5.721853 =		5.721853
701 3		1.000000 x	4.468245 =		4.468245
			-----		
			T.E =		57.881133
2350	2350				
616		1.000000 x	64.077342 =		64.077342
701 3		1.000000 x	4.468245 =		4.468245
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		74.267440
2410	2410				
617		1.000000 x	15.823936 =		15.823936
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		21.545789
2420	2420				
618		1.000000 x	19.495090 =		19.495090
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		25.216943
2430	2430				
619		1.000000 x	25.318298 =		25.318298
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		31.040151
2440	2440				
620		1.000000 x	31.647873 =		31.647873
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		37.369726
2450	2450				
621		1.000000 x	42.028375 =		42.028375
703		1.000000 x	5.721853 =		5.721853
			-----		
			T.E =		47.750228

3110 1	3110 1				
3110A 1		1.000000 x	133.139345 =		133.139345
3110B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		148.440877
3110 2	3110 2				
3110A 2		1.000000 x	140.851608 =		140.851608
3110B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		156.153140
3110 3	3110 3				
3110A 3		1.000000 x	143.209439 =		143.209439
3110B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		158.510971
3110 4	3110 4				
3110A 4		1.000000 x	150.921702 =		150.921702
3110B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		166.223234
3120 1	3120 1				
3120A 1		1.000000 x	133.139345 =		133.139345
3120B		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		149.868632
3120 2	3120 2				
3120A 2		1.000000 x	140.851608 =		140.851608
3120B		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		157.580895
3120 3	3120 3				
3120A 3		1.000000 x	143.209439 =		143.209439
3120B		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		159.938726
3120 4	3120 4				
3120A 4		1.000000 x	150.921702 =		150.921702
3120B		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		167.650989

3210 1	3210 1				
3210A 1		1.000000 x	122.015679 =		122.015679
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		137.317211
3210 2	3210 2				
3210A 2		1.000000 x	128.185489 =		128.185489
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		143.487021
3210 3	3210 3				
3210A 3		1.000000 x	130.071754 =		130.071754
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		145.373286
3210 4	3210 4				
3210A 4		1.000000 x	136.241564 =		136.241564
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		151.543096
3210 5	3210 5				
3210A 5		1.000000 x	120.918233 =		120.918233
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		136.219765
3210 6	3210 6				
3210A 6		1.000000 x	127.088044 =		127.088044
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		142.389576
3210 7	3210 7				
3210A 7		1.000000 x	128.974308 =		128.974308
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		144.275840
3210 8	3210 8				
3210A 8		1.000000 x	135.144119 =		135.144119
3210B		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		150.445651



3220 1	3220 1				
3220A 1		1.000000 x	122.015679 =		122.015679
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		138.744966
3220 2	3220 2				
3220A 2		1.000000 x	128.185489 =		128.185489
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		144.914776
3220 3	3220 3				
3220A 3		1.000000 x	130.071754 =		130.071754
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		146.801041
3220 4	3220 4				
3220A 4		1.000000 x	136.241564 =		136.241564
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		152.970851
3220 5	3220 5				
3220A 5		1.000000 x	120.918233 =		120.918233
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		137.647520
3220 6	3220 6				
3220A 6		1.000000 x	127.088044 =		127.088044
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		143.817331
3220 7	3220 7				
3220A 7		1.000000 x	128.974308 =		128.974308
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		145.703595
3220 8	3220 8				
3220A 8		1.000000 x	135.144119 =		135.144119
3220B		1.000000 x	16.729287 =		16.729287
		-----			
			T.E =		151.873406

3300 1	3300 1				
3300A 1		1.000000 x	188.265465 =		188.265465
3300B 1		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		203.566997
3300 2	3300 2				
3300A 1		1.000000 x	188.265465 =		188.265465
3300B 2		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		204.994752
3300 3	3300 3				
3300A 2		1.000000 x	195.977727 =		195.977727
3300B 1		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		211.279259
3300 4	3300 4				
3300A 2		1.000000 x	195.977727 =		195.977727
3300B 2		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		212.707014
3300 5	3300 5				
3300A 3		1.000000 x	198.335558 =		198.335558
3300B 1		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		213.637090
3300 6	3300 6				
3300A 3		1.000000 x	198.335558 =		198.335558
3300B 2		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		215.064845
3300 7	3300 7				
3300A 4		1.000000 x	206.047821 =		206.047821
3300B 1		1.000000 x	15.301532 =		15.301532
-----					
			T.E =		221.349353
3300 8	3300 8				
3300A 4		1.000000 x	206.047821 =		206.047821
3300B 2		1.000000 x	16.729287 =		16.729287
-----					
			T.E =		222.777108

ΑΤΛΕ		2ο Τρίμηνο του 2009		Σελ.	42
				Ημ/νία	26/05/2010
3400	1	3400	1		
	3400A		1.000000 x	200.826561 =	200.826561
	3400B		1.000000 x	10.201021 =	10.201021
-----					
				T.E =	211.027582
3400	2	3400	2		
	3400A		1.000000 x	200.826561 =	200.826561
	3400B		1.000000 x	11.152858 =	11.152858
-----					
				T.E =	211.979419
3400	3	3400	3		
	3400A		1.000000 x	208.538823 =	208.538823
	3400B		1.000000 x	10.201021 =	10.201021
-----					
				T.E =	218.739844
3400	4	3400	4		
	3400A		1.000000 x	208.538823 =	208.538823
	3400B		1.000000 x	11.152858 =	11.152858
-----					
				T.E =	219.691681
3400	5	3400	5		
	3400A		1.000000 x	210.896654 =	210.896654
	3400B		1.000000 x	10.201021 =	10.201021
-----					
				T.E =	221.097675
3400	6	3400	6		
	3400A		1.000000 x	210.896654 =	210.896654
	3400B		1.000000 x	11.152858 =	11.152858
-----					
				T.E =	222.049512
3400	7	3400	7		
	3400A		1.000000 x	218.608917 =	218.608917
	3400B		1.000000 x	10.201021 =	10.201021
-----					
				T.E =	228.809938
3400	8	3400	8		
	3400A		1.000000 x	218.608917 =	218.608917
	3400B		1.000000 x	11.152858 =	11.152858
-----					
				T.E =	229.761775

4110 1	4110 1				
4110A 1		1.000000 x	201.908689 =	201.908689	
4110B		.025000 x	1,526.817144 =	38.170429	
			T.E =	240.079118	
4110 2	4110 2				
4110A 2		1.000000 x	209.620952 =	209.620952	
4110B		.025000 x	1,526.817144 =	38.170429	
			T.E =	247.791381	
4110 3	4110 3				
4110A 3		1.000000 x	211.978783 =	211.978783	
4110B		.025000 x	1,526.817144 =	38.170429	
			T.E =	250.149212	
4110 4	4110 4				
4110A 4		1.000000 x	219.691045 =	219.691045	
4110B		.025000 x	1,526.817144 =	38.170429	
			T.E =	257.861474	
4120 1	4120 1				
4120A 1		1.000000 x	162.734003 =	162.734003	
4120B		1.000000 x	61.072686 =	61.072686	
			T.E =	223.806689	
4120 2	4120 2				
4120A 2		1.000000 x	181.243433 =	181.243433	
4120B		1.000000 x	61.072686 =	61.072686	
			T.E =	242.316119	
4130 1	4130 1				
4130A 1		1.000000 x	142.562153 =	142.562153	
4130B		1.000000 x	61.072686 =	61.072686	
			T.E =	203.634839	
4130 2	4130 2				
4130A 2		1.000000 x	150.274415 =	150.274415	
4130B		1.000000 x	61.072686 =	61.072686	
			T.E =	211.347101	

4130 3	4130 3				
4130A 3		1.000000 x	152.632246 =	152.632246	
4130B		1.000000 x	61.072686 =	61.072686	
			-----		
			T.E =	213.704932	
4130 4	4130 4				
4130A 4		1.000000 x	160.344509 =	160.344509	
4130B		1.000000 x	61.072686 =	61.072686	
			-----		
			T.E =	221.417195	
4210 1	4210 1				
4210A 1		1.000000 x	42.152809 =	42.152809	
4210B		1.000000 x	152.646660 =	152.646660	
			-----		
			T.E =	194.799469	
4210 2	4210 2				
4210A 2		1.000000 x	46.780167 =	46.780167	
4210B		1.000000 x	152.646660 =	152.646660	
			-----		
			T.E =	199.426827	
4210 3	4210 3				
4210A 3		1.000000 x	38.551817 =	38.551817	
4210B		1.000000 x	152.646660 =	152.646660	
			-----		
			T.E =	191.198477	
4210 4	4210 4				
4210A 4		1.000000 x	43.179174 =	43.179174	
4210B		1.000000 x	152.646660 =	152.646660	
			-----		
			T.E =	195.825834	
4220B 1	4220B 1				
319		.020000 x	20.900000 =	.418000	
701 2		.320000 x	4.582815 =	1.466501	
601		.320000 x	23.927901 =	7.656928	
4220A 1		.800000 x	110.220405 =	88.176324	
714		1.150000 x	7.704606 =	8.860297	
111		.400000 x	15.951934 =	6.380774	
			-----		
			T.E =	112.958824	

4220B 2	4220B 2			
319		.020000 x	20.900000 =	.418000
111		.400000 x	15.951934 =	6.380774
714		1.150000 x	7.704606 =	8.860297
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
4220A 2		.800000 x	117.932668 =	94.346134
-----				
			T.E =	119.128634
4220B 3	4220B 3			
319		.020000 x	20.900000 =	.418000
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
111		.400000 x	15.951934 =	6.380774
4220A 3		.800000 x	120.290499 =	96.232399
714		1.150000 x	7.704606 =	8.860297
-----				
			T.E =	121.014899
4220B 4	4220B 4			
319		.020000 x	20.900000 =	.418000
111		.400000 x	15.951934 =	6.380774
4220A 4		.800000 x	128.002761 =	102.402209
701 2		.320000 x	4.582815 =	1.466501
601		.320000 x	23.927901 =	7.656928
714		1.150000 x	7.704606 =	8.860297
-----				
			T.E =	127.184708
4220B 5	4220B 5			
319		.020000 x	20.900000 =	.418000
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
4220A 1		.800000 x	110.220405 =	88.176324
714		1.150000 x	7.704606 =	8.860297
111		.400000 x	15.951934 =	6.380774
-----				
			T.E =	111.861378
4220B 6	4220B 6			
319		.020000 x	20.900000 =	.418000
111		.400000 x	15.951934 =	6.380774
714		1.150000 x	7.704606 =	8.860297
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
4220A 2		.800000 x	117.932668 =	94.346134
-----				
			T.E =	118.031189

4220B 7	4220B 7			
319		.020000 x	20.900000 =	.418000
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
111		.400000 x	15.951934 =	6.380774
4220A 3		.800000 x	120.290499 =	96.232399
714		1.150000 x	7.704606 =	8.860297

-----  
T.E = 119.917453

4220B 8	4220B 8			
319		.020000 x	20.900000 =	.418000
111		.400000 x	15.951934 =	6.380774
4220A 4		.800000 x	128.002761 =	102.402209
701 2		.320000 x	4.582815 =	1.466501
609		.320000 x	20.498384 =	6.559483
714		1.150000 x	7.704606 =	8.860297

-----  
T.E = 126.087263

4230 1	4230 1			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.864260 =	.716065
701 2		.500000 x	4.582815 =	2.291408
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868
319		.020000 x	20.900000 =	.418000

-----  
T.E = 141.841086

4230 2	4230 2			
221		250.000000 x	.097700 =	24.425000
701 5		.250000 x	2.864260 =	.716065
701 4		.500000 x	4.296389 =	2.148195
701 2		.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
319		.020000 x	20.900000 =	.418000
111		2.000000 x	15.951934 =	31.903868
407		.040000 x	716.401976 =	28.656079
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020

-----  
T.E = 149.553348

4230 3      4230 3

221		250.000000 x	.097700 =	24.425000
701	5	.250000 x	2.864260 =	.716065
701	4	.800000 x	4.296389 =	3.437111
701	2	.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
319		.020000 x	20.900000 =	.418000
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868

-----  
T.E = 151.911180

4230 4      4230 4

221		250.000000 x	.097700 =	24.425000
701	5	.250000 x	2.864260 =	.716065
701	4	.500000 x	4.296389 =	2.148195
701	4	.800000 x	4.296389 =	3.437111
630		.250000 x	2.894286 =	.723572
319		.020000 x	20.900000 =	.418000
113		1.200000 x	23.479183 =	28.175020
407		.040000 x	716.401976 =	28.656079
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
714		1.150000 x	7.704606 =	8.860297
111		2.000000 x	15.951934 =	31.903868

-----  
T.E = 159.623442

4240 1      4240 1

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.864260 =	.716065
701	2	.500000 x	4.582815 =	2.291408
701	2	.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
607		.500000 x	9.758104 =	4.879052
606		.800000 x	8.908093 =	7.126474
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868
319		.020000 x	20.900000 =	.418000

-----  
T.E = 146.726086



4240 2      4240 2

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.864260 =	.716065
701	4	.500000 x	4.296389 =	2.148195
701	2	.800000 x	4.582815 =	3.666252
630		.250000 x	2.894286 =	.723572
319		.020000 x	20.900000 =	.418000
111		2.000000 x	15.951934 =	31.903868
407		.040000 x	716.401976 =	28.656079
611		.500000 x	25.469055 =	12.734528
606		.800000 x	8.908093 =	7.126474
714		1.150000 x	7.704606 =	8.860297
113		1.200000 x	23.479183 =	28.175020

-----  
T.E = 154.438348

4240 3      4240 3

221		300.000000 x	.097700 =	29.310000
701	5	.250000 x	2.864260 =	.716065
701	4	.800000 x	4.296389 =	3.437111
701	2	.500000 x	4.582815 =	2.291408
630		.250000 x	2.894286 =	.723572
610		.800000 x	21.782136 =	17.425709
607		.500000 x	9.758104 =	4.879052
407		.040000 x	716.401976 =	28.656079
714		1.150000 x	7.704606 =	8.860297
319		.020000 x	20.900000 =	.418000
113		1.200000 x	23.479183 =	28.175020
111		2.000000 x	15.951934 =	31.903868

-----  
T.E = 156.796180

4240 4      4240 4

221		300.000000 x	.097700 =	29.310000
319		.020000 x	20.900000 =	.418000
113		1.200000 x	23.479183 =	28.175020
714		1.150000 x	7.704606 =	8.860297
701	5	.250000 x	2.864260 =	.716065
701	4	.500000 x	4.296389 =	2.148195
701	4	.800000 x	4.296389 =	3.437111
630		.250000 x	2.894286 =	.723572
611		.500000 x	25.469055 =	12.734528
610		.800000 x	21.782136 =	17.425709
407		.040000 x	716.401976 =	28.656079
111		2.000000 x	15.951934 =	31.903868

-----  
T.E = 164.508442

4300 1      4300 1

4300A	1	1.000000 x	30.238617 =	30.238617
4300B		1.000000 x	11.207392 =	11.207392

-----  
T.E = 41.446009

4300	2	4300	2			
	4300A	2		1.000000 x	31.781070 =	31.781070
	4300B			1.000000 x	11.207392 =	11.207392
-----						
					T.E =	42.988462
4300	3	4300	3			
	4300A	3		1.000000 x	32.252636 =	32.252636
	4300B			1.000000 x	11.207392 =	11.207392
-----						
					T.E =	43.460028
4300	4	4300	4			
	4300A	4		1.000000 x	33.795088 =	33.795088
	4300B			1.000000 x	11.207392 =	11.207392
-----						
					T.E =	45.002480
4400		4400				
	251			1.050000 x	.492800 =	.517440
	113			.050000 x	23.479183 =	1.173959
-----						
					T.E =	1.691399
4500		4500				
	251			1.050000 x	.492800 =	.517440
	113			.100000 x	23.479183 =	2.347918
	114			.100000 x	17.729980 =	1.772998
-----						
					T.E =	4.638356
4600		4600				
	256			1.000000 x	3.300000 =	3.300000
	113			.100000 x	23.479183 =	2.347918
-----						
					T.E =	5.647918
4700		4700				
	253			1.000000 x	3.500000 =	3.500000
	113			.100000 x	23.479183 =	2.347918
-----						
					T.E =	5.847918