

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

4ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	Κατχ Τιμή X 1.8117/ 6.46	16.829739
112	Κατχ Τιμή X 1.8117/ 6.46	18.705943
113	Κατχ Τιμή X 1.8117/ 6.46	24.769248
114	Κατχ Τιμή X 1.8117/ 6.46	18.705943
115	Κατχ Τιμή X 1.8117/ 6.46	24.152261
116	Κατχ Τιμή X 1.8117/ 6.67	23.989407
117	Κατχ Τιμή X 1.8117/ 6.67	18.233796
118	Κατχ Τιμή X 1.8117/ 6.67	19.931416
119	Κατχ Τιμή X 1.8117/ 6.67	18.117000
120	Κατχ Τιμή X 1.8117/ 6.67	19.931416
121	Κατχ Τιμή X 1.8117/ 6.67	17.389061
122	Κατχ Τιμή X 1.8117/ 6.67	18.298985
123	Κατχ Τιμή X 1.8117/ 4.00	62.435711
211		.826000
212		.961300
213		3.490000
214		1.895000
221		.098900
222		.070000
231		35.000000
232		35.000000
241		290.000000
242		335.000000
251		.528700
252		1.785000
253		3.700000
254		5.000000
255		.719000
256		3.500000
261		
262		.980000
263		.540000
311		425.280000
312		128.110000
313		200.790000
314		4.310000
315		52.580000
316		4.310000
317		120.060000
318		26.060000
319		21.020000
320		149.250000
321		203.180000
322		282.280000
323		321.460000
324		176.370000
325		302.090000
326		100.390000
327		4.310000
351		430.200000
352		365.250000
353		430.200000
354		564.410000
355		282.280000
356		46.320000
357		221.950000
358		44.690000
359		92.650000
360		97.570000

361	74.630000
362	258.290000
363	97.710000
380	541.750000
381	541.750000
382	541.750000
383	623.070000
384	1,031.980000
385	187.500000
386	494.740000
387	71.380000
388	71.380000
389	71.380000

401	401			
211		110.000000 x	.826000 =	90.860000
213		10.000000 x	3.490000 =	34.900000
311		1.000000 x	425.280000 =	425.280000
117		4.000000 x	18.233796 =	72.935184
116		8.000000 x	23.989407 =	191.915256

			ΑΘΡΟΙΣΜΑ =	815.890440

			Η.Δ. =	897.479484
402	402			
211		180.000000 x	.826000 =	148.680000
213		12.000000 x	3.490000 =	41.880000
117		8.000000 x	18.233796 =	145.870368
116		8.000000 x	23.989407 =	191.915256
112		8.000000 x	18.705943 =	149.647544
312		1.000000 x	128.110000 =	128.110000
212		5.000000 x	.961300 =	4.806500

			ΑΘΡΟΙΣΜΑ =	810.909668

			Η.Δ. =	892.000635
403	403			
211		80.000000 x	.826000 =	66.080000
254		2.500000 x	5.000000 =	12.500000
213		6.000000 x	3.490000 =	20.940000
116		8.000000 x	23.989407 =	191.915256
117		8.000000 x	18.233796 =	145.870368
313		1.000000 x	200.790000 =	200.790000

			ΑΘΡΟΙΣΜΑ =	638.095624

			Η.Δ. =	701.905186
404	404			
211		80.000000 x	.826000 =	66.080000
212		2.000000 x	.961300 =	1.922600
118		8.000000 x	19.931416 =	159.451328
119		4.000000 x	18.117000 =	72.468000
314		1.000000 x	4.310000 =	4.310000
112		4.000000 x	18.705943 =	74.823772
213		5.000000 x	3.490000 =	17.450000

			ΑΘΡΟΙΣΜΑ =	396.505700

			Η.Δ. =	436.156270

405	405				
211		40.000000 x	.826000 =		33.040000
213		2.000000 x	3.490000 =		6.980000
118		4.000000 x	19.931416 =		79.725664
115		16.000000 x	24.152261 =		386.436176
316		2.000000 x	4.310000 =		8.620000
315		1.000000 x	52.580000 =		52.580000
			AΘΡΟΙΣΜΑ =		567.381840
			H.Δ. =		624.120024
406	406				
211		80.000000 x	.826000 =		66.080000
213		5.000000 x	3.490000 =		17.450000
317		1.000000 x	120.060000 =		120.060000
120		8.000000 x	19.931416 =		159.451328
			AΘΡΟΙΣΜΑ =		363.041328
			H.Δ. =		399.345461
407	407				
212		17.000000 x	.961300 =		16.342100
112		30.000000 x	18.705943 =		561.178290
118		4.000000 x	19.931416 =		79.725664
213		1.000000 x	3.490000 =		3.490000
318		1.000000 x	26.060000 =		26.060000
			AΘΡΟΙΣΜΑ =		686.796054
			H.Δ. =		755.475659
408	408				
211		30.000000 x	.826000 =		24.780000
320		1.000000 x	149.250000 =		149.250000
117		4.000000 x	18.233796 =		72.935184
116		8.000000 x	23.989407 =		191.915256
112		4.000000 x	18.705943 =		74.823772
213		3.000000 x	3.490000 =		10.470000
			AΘΡΟΙΣΜΑ =		524.174212
			H.Δ. =		576.591633
409	409				
211		50.000000 x	.826000 =		41.300000
213		5.000000 x	3.490000 =		17.450000
117		4.000000 x	18.233796 =		72.935184
116		8.000000 x	23.989407 =		191.915256
112		4.000000 x	18.705943 =		74.823772
324		1.000000 x	176.370000 =		176.370000
			AΘΡΟΙΣΜΑ =		574.794212
			H.Δ. =		632.273633

410	410				
211		100.000000 x	.826000 =	82.600000	
213		10.000000 x	3.490000 =	34.900000	
321		1.000000 x	203.180000 =	203.180000	
116		8.000000 x	23.989407 =	191.915256	
117		4.000000 x	18.233796 =	72.935184	
112		4.000000 x	18.705943 =	74.823772	
			ΑΘΡΟΙΣΜΑ =	660.354212	
			Η.Δ. =	726.389633	
411	411				
211		200.000000 x	.826000 =	165.200000	
325		1.000000 x	302.090000 =	302.090000	
117		4.000000 x	18.233796 =	72.935184	
116		8.000000 x	23.989407 =	191.915256	
112		4.000000 x	18.705943 =	74.823772	
213		20.000000 x	3.490000 =	69.800000	
			ΑΘΡΟΙΣΜΑ =	876.764212	
			Η.Δ. =	964.440633	
412	412				
211		40.000000 x	.826000 =	33.040000	
116		8.000000 x	23.989407 =	191.915256	
326		1.000000 x	100.390000 =	100.390000	
213		2.000000 x	3.490000 =	6.980000	
			ΑΘΡΟΙΣΜΑ =	332.325256	
			Η.Δ. =	365.557782	
413	413				
211		15.000000 x	.826000 =	12.390000	
213		1.500000 x	3.490000 =	5.235000	
118		3.000000 x	19.931416 =	59.794248	
112		3.000000 x	18.705943 =	56.117829	
327		1.000000 x	4.310000 =	4.310000	
			ΑΘΡΟΙΣΜΑ =	137.847077	
			Η.Δ. =	151.631785	
501	501				
211		170.000000 x	.826000 =	140.420000	
380		1.000000 x	541.750000 =	541.750000	
213		3.000000 x	3.490000 =	10.470000	
351		1.000000 x	430.200000 =	430.200000	
			ΑΘΡΟΙΣΜΑ =	1,122.840000	
			Η.Δ. =	1,235.124000	

502	502				
211		170.000000 x	.826000 =	140.420000	
381		1.000000 x	541.750000 =	541.750000	
213		3.000000 x	3.490000 =	10.470000	
352		1.000000 x	365.250000 =	365.250000	

			ΑΘΡΟΙΣΜΑ =	1,057.890000	

			Η.Δ. =	1,163.679000	
503	503				
211		170.000000 x	.826000 =	140.420000	
382		1.000000 x	541.750000 =	541.750000	
353		1.000000 x	430.200000 =	430.200000	
213		3.000000 x	3.490000 =	10.470000	

			ΑΘΡΟΙΣΜΑ =	1,122.840000	

			Η.Δ. =	1,235.124000	
504	504				
211		190.000000 x	.826000 =	156.940000	
213		6.000000 x	3.490000 =	20.940000	
354		1.000000 x	564.410000 =	564.410000	
383		1.000000 x	623.070000 =	623.070000	

			ΑΘΡΟΙΣΜΑ =	1,365.360000	

			Η.Δ. =	1,501.896000	
505	505				
211		1,250.000000 x	.826000 =	1,032.500000	
213		7.500000 x	3.490000 =	26.175000	
384		1.000000 x	1,031.980000 =	1,031.980000	
355		1.000000 x	282.280000 =	282.280000	

			ΑΘΡΟΙΣΜΑ =	2,372.935000	

			Η.Δ. =	2,610.228500	
506	506				
211		200.000000 x	.826000 =	165.200000	
213		2.000000 x	3.490000 =	6.980000	
385		1.000000 x	187.500000 =	187.500000	
356		1.000000 x	46.320000 =	46.320000	

			ΑΘΡΟΙΣΜΑ =	406.000000	

			Η.Δ. =	446.600000	
507	507				
211		2,100.000000 x	.826000 =	1,734.600000	
386		1.000000 x	494.740000 =	494.740000	
357		1.000000 x	221.950000 =	221.950000	
213		35.000000 x	3.490000 =	122.150000	

			ΑΘΡΟΙΣΜΑ =	2,573.440000	

			Η.Δ. =	2,779.315200	

508	508				
358		1.000000 x	44.690000 =		44.690000
387		1.000000 x	71.380000 =		71.380000
				ΑΘΡΟΙΣΜΑ =	116.070000
				Η.Δ. =	121.873500
509	509				
359		1.000000 x	92.650000 =		92.650000
388		1.000000 x	71.380000 =		71.380000
				ΑΘΡΟΙΣΜΑ =	164.030000
				Η.Δ. =	172.231500
510	510				
360		1.000000 x	97.570000 =		97.570000
389		1.000000 x	71.380000 =		71.380000
				ΑΘΡΟΙΣΜΑ =	168.950000
				Η.Δ. =	177.397500
511	511				
509		.800000 x	172.231500 =		137.785200
				Η.Δ. =	137.785200
512	512				
501		.600000 x	1,235.124000 =		741.074400
				Η.Δ. =	741.074400
513	513				
363		1.000000 x	97.710000 =		97.710000
123		8.000000 x	62.435711 =		499.485688
122		8.000000 x	18.298985 =		146.391880
121		8.000000 x	17.389061 =		139.112488
				Η.Δ. =	882.700056
1111A	1111A				
214		.200000 x	1.895000 =		.379000
511		.020000 x	137.785200 =		2.755704
405		.020000 x	624.120024 =		12.482400
513		.020000 x	882.700056 =		17.654001
				Β.Τ =	33.271106

1111B	1111B			
501		1.000000 x	1,235.124000 =	1,235.124000
506		1.000000 x	446.600000 =	446.600000
509		2.000000 x	172.231500 =	344.463000

			ΑΘΡΟΙΣΜΑ =	2,026.187000
	B.T =	.002500 x	2,026.187000 =	5.065468

1112A	1112A			
506		1.000000 x	446.600000 =	446.600000
512		1.000000 x	741.074400 =	741.074400

			ΑΘΡΟΙΣΜΑ =	1,187.674400
	B.T =	.025000 x	1,187.674400 =	29.691860

1112B	1112B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
1113A	1113A			
214		.200000 x	1.895000 =	.379000
112		.250000 x	18.705943 =	4.676486
511		.035000 x	137.785200 =	4.822482
513		.035000 x	882.700056 =	30.894502
405		.025000 x	624.120024 =	15.603001

			B.T =	56.375470
1113B	1113B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
1114A	1114A			
112		.250000 x	18.705943 =	4.676486
506		.033000 x	446.600000 =	14.737800
512		.033000 x	741.074400 =	24.455455

			B.T =	43.869741
1114B	1114B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468

1121A	1121A			
214		.150000 x	1.895000 =	.284250
115		.500000 x	24.152261 =	12.076131
405		.020000 x	624.120024 =	12.482400

			B.T =	24.842781
1121B	1121B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
1122A	1122A			
506		1.000000 x	446.600000 =	446.600000
512		1.000000 x	741.074400 =	741.074400

			AΘΡΟΙΣΜΑ =	1,187.674400
	B.T =	.012500 x	1,187.674400 =	14.845930

1122B	1122B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
1123A	1123A			
214		.150000 x	1.895000 =	.284250
112		.150000 x	18.705943 =	2.805891
405		.025000 x	624.120024 =	15.603001
115		1.000000 x	24.152261 =	24.152261

			B.T =	42.845403
1123B	1123B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
1124A	1124A			
112		.150000 x	18.705943 =	2.805891
506		.020000 x	446.600000 =	8.932000
512		.020000 x	741.074400 =	14.821488

			B.T =	26.559379
1124B	1124B			
1111B		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468

3110A 1	3110A 1			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.955156 =	.738789
701 2		.800000 x	4.728250 =	3.782600
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
714		1.400000 x	8.083292 =	11.316609
113		1.200000 x	24.769248 =	29.723098
112		1.200000 x	18.705943 =	22.447132
319		.020000 x	21.020000 =	.420400

B.T = 138.980157

3110A 2	3110A 2			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.955156 =	.738789
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
319		.020000 x	21.020000 =	.420400
112		1.200000 x	18.705943 =	22.447132
407		.040000 x	755.475659 =	30.219026
611		.500000 x	26.591272 =	13.295636
606		.800000 x	9.264638 =	7.411710
714		1.400000 x	8.083292 =	11.316609
113		1.200000 x	24.769248 =	29.723098

B.T = 147.054526

3110A 3	3110A 3			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
407		.040000 x	755.475659 =	30.219026
714		1.400000 x	8.083292 =	11.316609
319		.020000 x	21.020000 =	.420400
113		1.200000 x	24.769248 =	29.723098
112		1.200000 x	18.705943 =	22.447132

B.T = 149.536570

3110A 4	3110A 4			
221		250.000000 x	.098900 =	24.725000
714		1.400000 x	8.083292 =	11.316609
319		.020000 x	21.020000 =	.420400
113		1.200000 x	24.769248 =	29.723098
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 4		.500000 x	4.432735 =	2.216368
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
610		.800000 x	22.755669 =	18.204535
407		.040000 x	755.475659 =	30.219026
112		1.200000 x	18.705943 =	22.447132

			B.T =	157.610939
3110B	3110B			
713 1		1.000000 x	5.316132 =	5.316132
704		1.000000 x	10.632264 =	10.632264

			B.T =	15.948396
3120A 1	3120A 1			
3110A 1		1.000000 x	138.980157 =	138.980157

			B.T =	138.980157
3120A 2	3120A 2			
3110A 2		1.000000 x	147.054526 =	147.054526

			B.T =	147.054526
3120A 3	3120A 3			
3110A 3		1.000000 x	149.536570 =	149.536570

			B.T =	149.536570
3120A 4	3120A 4			
3110A 4		1.000000 x	157.610939 =	157.610939

			B.T =	157.610939
3120B	3120B			
713 2		1.000000 x	5.795174 =	5.795174
705		1.000000 x	11.590347 =	11.590347

			B.T =	17.385521

3210A 1	3210A 1			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275
3110A 1		.800000 x	138.980157 =	111.184126

			B.T =	127.507336
3210A 2	3210A 2			
111		.400000 x	16.829739 =	6.731896
3110A 2		.800000 x	147.054526 =	117.643621
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275

			B.T =	133.966831
3210A 3	3210A 3			
111		.400000 x	16.829739 =	6.731896
3110A 3		.800000 x	149.536570 =	119.629256
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275

			B.T =	135.952466
3210A 4	3210A 4			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275
3110A 4		.800000 x	157.610939 =	126.088751

			B.T =	142.411962
3210A 5	3210A 5			
111		.400000 x	16.829739 =	6.731896
3110A 1		.800000 x	138.980157 =	111.184126
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390

			B.T =	126.342451
3210A 6	3210A 6			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
3110A 2		.800000 x	147.054526 =	117.643621

			B.T =	132.801946

3210A 7	3210A 7			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
3110A 3		.800000 x	149.536570 =	119.629256

			B.T =	134.787582
3210A 8	3210A 8			
111		.400000 x	16.829739 =	6.731896
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
3110A 4		.800000 x	157.610939 =	126.088751

			B.T =	141.247077
3210B	3210B			
713 1		1.000000 x	5.316132 =	5.316132
704		1.000000 x	10.632264 =	10.632264

			B.T =	15.948396
3220A 1	3220A 1			
3210A 1		1.000000 x	127.507336 =	127.507336

			B.T =	127.507336
3220A 2	3220A 2			
3210A 2		1.000000 x	133.966831 =	133.966831

			B.T =	133.966831
3220A 3	3220A 3			
3210A 3		1.000000 x	135.952466 =	135.952466

			B.T =	135.952466
3220A 4	3220A 4			
3210A 4		1.000000 x	142.411962 =	142.411962

			B.T =	142.411962
3220A 5	3220A 5			
3210A 5		1.000000 x	126.342451 =	126.342451

			B.T =	126.342451

3220A 6	3220A 6			
3210A 6		1.000000 x	132.801946 =	132.801946

			B.T =	132.801946
3220A 7	3220A 7			
3210A 7		1.000000 x	134.787582 =	134.787582

			B.T =	134.787582
3220A 8	3220A 8			
3210A 8		1.000000 x	141.247077 =	141.247077

			B.T =	141.247077
3220B	3220B			
713 2		1.000000 x	5.795174 =	5.795174
705		1.000000 x	11.590347 =	11.590347

			B.T =	17.385521
3300A 1	3300A 1			
221		300.000000 x	.098900 =	29.670000
701 5		.250000 x	2.955156 =	.738789
701 2		.500000 x	4.728250 =	2.364125
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
714		2.600000 x	8.083292 =	21.016559
113		2.000000 x	24.769248 =	49.538496
111		2.700000 x	16.829739 =	45.440295
319		.040000 x	21.020000 =	.840800

			B.T =	196.854069
3300A 2	3300A 2			
221		300.000000 x	.098900 =	29.670000
111		2.700000 x	16.829739 =	45.440295
714		2.600000 x	8.083292 =	21.016559
701 5		.250000 x	2.955156 =	.738789
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
113		2.000000 x	24.769248 =	49.538496
319		.040000 x	21.020000 =	.840800

			B.T =	204.928439

3300A 3

3300A 3

221		300.000000 x	.098900 =	29.670000
630		.250000 x	3.032636 =	.758159
701	5	.250000 x	2.955156 =	.738789
701	4	.800000 x	4.432735 =	3.546188
701	2	.500000 x	4.728250 =	2.364125
607		.500000 x	10.147018 =	5.073509
610		.800000 x	22.755669 =	18.204535
407		.040000 x	755.475659 =	30.219026
113		2.000000 x	24.769248 =	49.538496
714		2.600000 x	8.083292 =	21.016559
111		2.700000 x	16.829739 =	45.440295
319		.040000 x	21.020000 =	.840800

B.T =

207.410482

3300A 4

3300A 4

221		300.000000 x	.098900 =	29.670000
701	5	.250000 x	2.955156 =	.738789
701	4	.800000 x	4.432735 =	3.546188
701	4	.500000 x	4.432735 =	2.216368
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
610		.800000 x	22.755669 =	18.204535
407		.040000 x	755.475659 =	30.219026
714		2.600000 x	8.083292 =	21.016559
113		2.000000 x	24.769248 =	49.538496
111		2.700000 x	16.829739 =	45.440295
319		.040000 x	21.020000 =	.840800

B.T =

215.484852

3300B 1

3300B 1

713	1	1.000000 x	5.316132 =	5.316132
704		1.000000 x	10.632264 =	10.632264

B.T =

15.948396

3300B 2

3300B 2

713	2	1.000000 x	5.795174 =	5.795174
705		1.000000 x	11.590347 =	11.590347

B.T =

17.385521

3400A 1

3400A 1

221		300.000000 x	.098900 =	29.670000
255		5.000000 x	.719000 =	3.595000
111		2.700000 x	16.829739 =	45.440295
112		1.000000 x	18.705943 =	18.705943
113		2.000000 x	24.769248 =	49.538496
701	5	.250000 x	2.955156 =	.738789
701	2	.800000 x	4.728250 =	3.782600
701	2	.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
113		.500000 x	24.769248 =	12.384624
319		.030000 x	21.020000 =	.630600

B.T =

210.312877

3400A 2

3400A 2

221		300.000000 x	.098900 =	29.670000
255		5.000000 x	.719000 =	3.595000
611		.500000 x	26.591272 =	13.295636
701	5	.250000 x	2.955156 =	.738789
701	4	.500000 x	4.432735 =	2.216368
701	2	.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	21.020000 =	.630600

B.T =

218.387247

3400A 3

3400A 3

221		300.000000 x	.098900 =	29.670000
701	5	.250000 x	2.955156 =	.738789
701	4	.800000 x	4.432735 =	3.546188
701	2	.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
407		.040000 x	755.475659 =	30.219026
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	21.020000 =	.630600
255		5.000000 x	.719000 =	3.595000

B.T =

220.869290

3400A 4	3400A 4			
221		300.000000 x	.098900 =	29.670000
255		5.000000 x	.719000 =	3.595000
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 4		.500000 x	4.432735 =	2.216368
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
610		.800000 x	22.755669 =	18.204535
407		.040000 x	755.475659 =	30.219026
113		2.000000 x	24.769248 =	49.538496
113		.500000 x	24.769248 =	12.384624
112		1.000000 x	18.705943 =	18.705943
111		2.700000 x	16.829739 =	45.440295
319		.030000 x	21.020000 =	.630600

			B.T =	228.943659
3400B 1	3400B 1			
704		1.000000 x	10.632264 =	10.632264

			B.T =	10.632264
3400B 2	3400B 2			
705		1.000000 x	11.590347 =	11.590347

			B.T =	11.590347
4110A 1	4110A 1			
221		350.000000 x	.098900 =	34.615000
701 5		.100000 x	2.955156 =	.295516
701 2		.800000 x	4.728250 =	3.782600
701 2		.500000 x	4.728250 =	2.364125
630		.100000 x	3.032636 =	.303264
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.070000 x	755.475659 =	52.883296
113		1.500000 x	24.769248 =	37.153872
111		4.000000 x	16.829739 =	67.318956

			B.T =	211.201848

4110A 2	4110A 2			
221		350.000000 x	.098900 =	34.615000
111		4.000000 x	16.829739 =	67.318956
407		.070000 x	755.475659 =	52.883296
611		.500000 x	26.591272 =	13.295636
701 4		.500000 x	4.432735 =	2.216368
701 5		.100000 x	2.955156 =	.295516
701 2		.800000 x	4.728250 =	3.782600
630		.100000 x	3.032636 =	.303264
606		.800000 x	9.264638 =	7.411710
113		1.500000 x	24.769248 =	37.153872

B.T = 219.276217

4110A 3	4110A 3			
221		350.000000 x	.098900 =	34.615000
701 5		.100000 x	2.955156 =	.295516
701 4		.800000 x	4.432735 =	3.546188
701 2		.500000 x	4.728250 =	2.364125
630		.100000 x	3.032636 =	.303264
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
111		4.000000 x	16.829739 =	67.318956
407		.070000 x	755.475659 =	52.883296
113		1.500000 x	24.769248 =	37.153872

B.T = 221.758261

4110A 4	4110A 4			
221		350.000000 x	.098900 =	34.615000
407		.070000 x	755.475659 =	52.883296
611		.500000 x	26.591272 =	13.295636
701 5		.100000 x	2.955156 =	.295516
701 4		.800000 x	4.432735 =	3.546188
701 4		.500000 x	4.432735 =	2.216368
630		.100000 x	3.032636 =	.303264
610		.800000 x	22.755669 =	18.204535
113		1.500000 x	24.769248 =	37.153872
111		4.000000 x	16.829739 =	67.318956

B.T = 229.832630

4110B	4110B			
112		8.000000 x	18.705943 =	149.647544
513		1.000000 x	882.700056 =	882.700056
508		1.000000 x	121.873500 =	121.873500
506		1.000000 x	446.600000 =	446.600000

B.T = 1,600.821100

4120A 1	4120A 1			
221		350.000000 x	.098900 =	34.615000
701 2		1.200000 x	4.728250 =	5.673900
607		1.200000 x	10.147018 =	12.176422
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	18.705943 =	93.529715

			B.T =	168.675037
4120A 2	4120A 2			
221		350.000000 x	.098900 =	34.615000
701 4		1.200000 x	4.432735 =	5.319282
611		1.200000 x	26.591272 =	31.909526
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	18.705943 =	93.529715

			B.T =	188.053523
4120B	4120B			
4110B		.040000 x	1,600.821100 =	64.032844

			B.T =	64.032844
4130A 1	4130A 1			
221		350.000000 x	.098900 =	34.615000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	755.475659 =	37.773783
606		.800000 x	9.264638 =	7.411710
607		.500000 x	10.147018 =	5.073509
701 2		.500000 x	4.728250 =	2.364125
701 2		.800000 x	4.728250 =	3.782600
111		2.000000 x	16.829739 =	33.659478

			B.T =	147.360205
4130A 2	4130A 2			
221		350.000000 x	.098900 =	34.615000
407		.050000 x	755.475659 =	37.773783
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
611		.500000 x	26.591272 =	13.295636
606		.800000 x	9.264638 =	7.411710
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

			B.T =	155.434575

4130A 3	4130A 3			
221		350.000000 x	.098900 =	34.615000
701 4		.800000 x	4.432735 =	3.546188
701 2		.500000 x	4.728250 =	2.364125
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
407		.050000 x	755.475659 =	37.773783
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

B.T = 157.916618

4130A 4	4130A 4			
221		350.000000 x	.098900 =	34.615000
701 4		.500000 x	4.432735 =	2.216368
701 4		.800000 x	4.432735 =	3.546188
611		.500000 x	26.591272 =	13.295636
610		.800000 x	22.755669 =	18.204535
407		.050000 x	755.475659 =	37.773783
111		2.000000 x	16.829739 =	33.659478
263		42.000000 x	.540000 =	22.680000

B.T = 165.990988

4130B	4130B			
4120B		1.000000 x	64.032844 =	64.032844

B.T = 64.032844

4210A 1	4210A 1			
221		65.000000 x	.098900 =	6.428500
701 5		.150000 x	2.955156 =	.443273
601		1.050000 x	25.244609 =	26.506839
630		.150000 x	3.032636 =	.454895
701 2		1.050000 x	4.728250 =	4.964663
701 2		.300000 x	4.728250 =	1.418475
607		.300000 x	10.147018 =	3.044105
222		10.000000 x	.070000 =	.700000

B.T = 43.960751

4210A 2	4210A 2			
221		65.000000 x	.098900 =	6.428500
701 5		.150000 x	2.955156 =	.443273
701 4		.300000 x	4.432735 =	1.329821
701 2		1.050000 x	4.728250 =	4.964663
630		.150000 x	3.032636 =	.454895
611		.300000 x	26.591272 =	7.977382
601		1.050000 x	25.244609 =	26.506839
222		10.000000 x	.070000 =	.700000

B.T = 48.805373

4210A 3	4210A 3			
221		65.000000 x	.098900 =	6.428500
701 2		.300000 x	4.728250 =	1.418475
609		1.050000 x	21.604344 =	22.684561
222		10.000000 x	.070000 =	.700000
701 5		.150000 x	2.955156 =	.443273
701 2		1.050000 x	4.728250 =	4.964663
630		.150000 x	3.032636 =	.454895
607		.300000 x	10.147018 =	3.044105

B.T = 40.138473

4210A 4	4210A 4			
221		65.000000 x	.098900 =	6.428500
701 5		.150000 x	2.955156 =	.443273
701 4		.300000 x	4.432735 =	1.329821
701 2		1.050000 x	4.728250 =	4.964663
630		.150000 x	3.032636 =	.454895
222		10.000000 x	.070000 =	.700000
611		.300000 x	26.591272 =	7.977382
609		1.050000 x	21.604344 =	22.684561

B.T = 44.983095

4210B	4210B			
111		4.000000 x	16.829739 =	67.318956
112		.200000 x	18.705943 =	3.741189
113		2.500000 x	24.769248 =	61.923120
112		1.500000 x	18.705943 =	28.058915

B.T = 161.042179

4220A 1	4220A 1			
221		200.000000 x	.098900 =	19.780000
701 2		.800000 x	4.728250 =	3.782600
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
113		1.000000 x	24.769248 =	24.769248
111		1.200000 x	16.829739 =	20.195687
701 5		.250000 x	2.955156 =	.738789

B.T = 115.092854

4220A 2	4220A 2			
221		200.000000 x	.098900 =	19.780000
111		1.200000 x	16.829739 =	20.195687
113		1.000000 x	24.769248 =	24.769248
611		.500000 x	26.591272 =	13.295636
701 5		.250000 x	2.955156 =	.738789
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026

B.T = 123.167223

4220A 3	4220A 3			
221		200.000000 x	.098900 =	19.780000
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
111		1.200000 x	16.829739 =	20.195687
407		.040000 x	755.475659 =	30.219026
113		1.000000 x	24.769248 =	24.769248

B.T = 125.649266

4220A 4	4220A 4			
221		200.000000 x	.098900 =	19.780000
111		1.200000 x	16.829739 =	20.195687
407		.040000 x	755.475659 =	30.219026
611		.500000 x	26.591272 =	13.295636
701 4		.500000 x	4.432735 =	2.216368
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
630		.250000 x	3.032636 =	.758159
610		.800000 x	22.755669 =	18.204535
113		1.000000 x	24.769248 =	24.769248

B.T = 133.723636

4300A 1	4300A 1			
221		350.000000 x	.098900 =	34.615000
111		2.000000 x	16.829739 =	33.659478
113		1.200000 x	24.769248 =	29.723098
701 5		.250000 x	2.955156 =	.738789
701 2		.800000 x	4.728250 =	3.782600
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
714		1.150000 x	8.083292 =	9.295786

			ΑΘΡΟΙΣΜΑ =	157.641280
	B.T =	.200000 x	157.641280 =	31.528256

4300A 2	4300A 2			
221		350.000000 x	.098900 =	34.615000
701 5		.250000 x	2.955156 =	.738789
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
714		1.150000 x	8.083292 =	9.295786
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	165.715650
	B.T =	.200000 x	165.715650 =	33.143130

4300A 3	4300A 3			
221		350.000000 x	.098900 =	34.615000
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 2		.500000 x	4.728250 =	2.364125
630		.250000 x	3.032636 =	.758159
610		.800000 x	22.755669 =	18.204535
607		.500000 x	10.147018 =	5.073509
407		.040000 x	755.475659 =	30.219026
714		1.150000 x	8.083292 =	9.295786
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	168.197693
	B.T =	.200000 x	168.197693 =	33.639539

4300A 4	4300A 4			
221		350.000000 x	.098900 =	34.615000
701 5		.250000 x	2.955156 =	.738789
701 4		.800000 x	4.432735 =	3.546188
701 4		.500000 x	4.432735 =	2.216368
714		1.150000 x	8.083292 =	9.295786
113		1.200000 x	24.769248 =	29.723098
610		.800000 x	22.755669 =	18.204535
630		.250000 x	3.032636 =	.758159
611		.500000 x	26.591272 =	13.295636
407		.040000 x	755.475659 =	30.219026
111		2.000000 x	16.829739 =	33.659478

			ΑΘΡΟΙΣΜΑ =	176.272062
	B.T =	.200000 x	176.272062 =	35.254412

4300B	4300B			
221		2.000000 x	.098900 =	.197800
112		.400000 x	18.705943 =	7.482377
262		4.000000 x	.980000 =	3.920000

			B.T =	11.600177
601	601			
111		1.500000 x	16.829739 =	25.244609

			B.T =	25.244609
602	602			
403		.002500 x	701.905186 =	1.754763

			B.T =	1.754763
603	603			
111		.300000 x	16.829739 =	5.048922
401		.001000 x	897.479484 =	.897479
412		.003300 x	365.557782 =	1.206341

			B.T =	7.152742
604	604			
111		.200000 x	16.829739 =	3.365948
404		.005000 x	436.156270 =	2.180781
401		.001100 x	897.479484 =	.987227
412		.004000 x	365.557782 =	1.462231

			B.T =	7.996188

605	605				
112		.100000 x	18.705943 =	1.870594	
401		.001000 x	897.479484 =	.897479	
406		.006200 x	399.345461 =	2.475942	
412		.004000 x	365.557782 =	1.462231	
402		.006200 x	892.000635 =	5.530404	

			B.T =	12.236651	
606	606				
111		.100000 x	16.829739 =	1.682974	
412		.005000 x	365.557782 =	1.827789	
406		.006700 x	399.345461 =	2.675615	
401		.001000 x	897.479484 =	.897479	
404		.005000 x	436.156270 =	2.180781	

			B.T =	9.264638	
607	607				
111		.100000 x	16.829739 =	1.682974	
412		.005000 x	365.557782 =	1.827789	
406		.006700 x	399.345461 =	2.675615	
404		.006200 x	436.156270 =	2.704169	
401		.001400 x	897.479484 =	1.256471	

			B.T =	10.147018	
608	608				
111		.100000 x	16.829739 =	1.682974	
412		.005000 x	365.557782 =	1.827789	
406		.006700 x	399.345461 =	2.675615	
404		.012500 x	436.156270 =	5.451953	
401		.002000 x	897.479484 =	1.794959	

			B.T =	13.433290	
609	609				
214		.100000 x	1.895000 =	.189500	
111		.800000 x	16.829739 =	13.463791	
405		.005000 x	624.120024 =	3.120600	
115		.200000 x	24.152261 =	4.830452	

			B.T =	21.604344	

610	610				
214		.100000 x	1.895000 =	.189500	
112		.100000 x	18.705943 =	1.870594	
115		.200000 x	24.152261 =	4.830452	
402		.010000 x	892.000635 =	8.920006	
412		.005000 x	365.557782 =	1.827789	
406		.005000 x	399.345461 =	1.996727	
405		.005000 x	624.120024 =	3.120600	
			B.T =	22.755669	
611	611				
214		.100000 x	1.895000 =	.189500	
112		.100000 x	18.705943 =	1.870594	
402		.014300 x	892.000635 =	12.755609	
115		.200000 x	24.152261 =	4.830452	
406		.005000 x	399.345461 =	1.996727	
412		.005000 x	365.557782 =	1.827789	
405		.005000 x	624.120024 =	3.120600	
			B.T =	26.591272	
612	612				
214		.150000 x	1.895000 =	.284250	
111		.300000 x	16.829739 =	5.048922	
408		.010000 x	576.591633 =	5.765916	
405		.005000 x	624.120024 =	3.120600	
115		.200000 x	24.152261 =	4.830452	
			AΘΡΟΙΣΜΑ =	19.050140	
	B.T =	1.068000 x	19.050140 =	20.345550	
613	613				
214		.150000 x	1.895000 =	.284250	
409		.010000 x	632.273633 =	6.322736	
405		.005000 x	624.120024 =	3.120600	
115		.200000 x	24.152261 =	4.830452	
111		.500000 x	16.829739 =	8.414870	
			AΘΡΟΙΣΜΑ =	22.972908	
	B.T =	1.282000 x	22.972908 =	29.451268	
614	614				
214		.150000 x	1.895000 =	.284250	
111		.500000 x	16.829739 =	8.414870	
115		.200000 x	24.152261 =	4.830452	
410		.010000 x	726.389633 =	7.263896	
405		.005000 x	624.120024 =	3.120600	
			AΘΡΟΙΣΜΑ =	23.914068	
	B.T =	1.602000 x	23.914068 =	38.310337	

615	615				
214		.150000 x	1.895000 =	.284250	
410		.010000 x	726.389633 =	7.263896	
111		.700000 x	16.829739 =	11.780817	
405		.005000 x	624.120024 =	3.120600	
115		.200000 x	24.152261 =	4.830452	

			ΑΘΡΟΙΣΜΑ =	27.280016	
	B.T =	1.832000 x	27.280016 =	49.976989	

616	616				
214		.150000 x	1.895000 =	.284250	
111		.800000 x	16.829739 =	13.463791	
405		.005000 x	624.120024 =	3.120600	
411		.010000 x	964.440633 =	9.644406	
115		.200000 x	24.152261 =	4.830452	

			ΑΘΡΟΙΣΜΑ =	31.343500	
	B.T =	2.137000 x	31.343500 =	66.981059	

617	617				
112		4.000000 x	18.705943 =	74.823772	
513		1.000000 x	882.700056 =	882.700056	
506		1.000000 x	446.600000 =	446.600000	
503		1.000000 x	1,235.124000 =	1,235.124000	

			ΑΘΡΟΙΣΜΑ =	2,639.247828	
	B.T =	.006250 x	2,639.247828 =	16.495299	

618	618				
112		4.000000 x	18.705943 =	74.823772	
513		1.000000 x	882.700056 =	882.700056	
506		1.000000 x	446.600000 =	446.600000	
503		1.000000 x	1,235.124000 =	1,235.124000	

			ΑΘΡΟΙΣΜΑ =	2,639.247828	
	B.T =	.007700 x	2,639.247828 =	20.322208	

619	619				
112		4.000000 x	18.705943 =	74.823772	
503		1.000000 x	1,235.124000 =	1,235.124000	
506		1.000000 x	446.600000 =	446.600000	
513		1.000000 x	882.700056 =	882.700056	

			ΑΘΡΟΙΣΜΑ =	2,639.247828	
	B.T =	.010000 x	2,639.247828 =	26.392478	

620	620			
112		4.000000 x	18.705943 =	74.823772
513		1.000000 x	882.700056 =	882.700056
506		1.000000 x	446.600000 =	446.600000
503		1.000000 x	1,235.124000 =	1,235.124000

			ΑΘΡΟΙΣΜΑ =	2,639.247828
	B.T =	.012500 x	2,639.247828 =	32.990598

621	621			
112		4.000000 x	18.705943 =	74.823772
506		1.000000 x	446.600000 =	446.600000
503		1.000000 x	1,235.124000 =	1,235.124000
513		1.000000 x	882.700056 =	882.700056

			ΑΘΡΟΙΣΜΑ =	2,639.247828
	B.T =	.016600 x	2,639.247828 =	43.811514

630	630			
413		.020000 x	151.631785 =	3.032636

			B.T =	3.032636
701 1	701 1			
406		.012580 x	399.345461 =	5.023766

			B.T =	5.023766
701 2	701 2			
406		.011840 x	399.345461 =	4.728250

			B.T =	4.728250
701 3	701 3			
406		.011544 x	399.345461 =	4.610044

			B.T =	4.610044
701 4	701 4			
406		.011100 x	399.345461 =	4.432735

			B.T =	4.432735
701 5	701 5			
406		.007400 x	399.345461 =	2.955156

			B.T =	2.955156

702	702			
112		8.000000 x	18.705943 =	149.647544
506		1.000000 x	446.600000 =	446.600000
513		.300000 x	882.700056 =	264.810017
509		2.000000 x	172.231500 =	344.463000

			ΑΘΡΟΙΣΜΑ =	1,205.520561
	B.T =	.002500 x	1,205.520561 =	3.013801

703	703			
112		4.000000 x	18.705943 =	74.823772
513		.300000 x	882.700056 =	264.810017
503		1.000000 x	1,235.124000 =	1,235.124000
510		2.000000 x	177.397500 =	354.795000
506		1.000000 x	446.600000 =	446.600000

			ΑΘΡΟΙΣΜΑ =	2,376.152789
	B.T =	.002500 x	2,376.152789 =	5.940382

704	704			
112		4.000000 x	18.705943 =	74.823772
513		.500000 x	882.700056 =	441.350028
506		1.000000 x	446.600000 =	446.600000
502		1.000000 x	1,163.679000 =	1,163.679000

			ΑΘΡΟΙΣΜΑ =	2,126.452800
	B.T =	.005000 x	2,126.452800 =	10.632264

705	705			
112		4.000000 x	18.705943 =	74.823772
513		.600000 x	882.700056 =	529.620034
506		1.000000 x	446.600000 =	446.600000
504		1.000000 x	1,501.896000 =	1,501.896000

			ΑΘΡΟΙΣΜΑ =	2,552.939806
	B.T =	.004540 x	2,552.939806 =	11.590347

706	706			
501		1.000000 x	1,235.124000 =	1,235.124000
509		2.000000 x	172.231500 =	344.463000
506		1.000000 x	446.600000 =	446.600000

			ΑΘΡΟΙΣΜΑ =	2,026.187000
	B.T =	.002500 x	2,026.187000 =	5.065468

707	707			
505		1.000000 x	2,610.228500 =	2,610.228500
510		2.000000 x	177.397500 =	354.795000
506		1.000000 x	446.600000 =	446.600000

			ΑΘΡΟΙΣΜΑ =	3,411.623500
	B.T =	.001000 x	3,411.623500 =	3.411624

708	708			
708A		1.000000 x	18.101103 =	18.101103
708B		1.000000 x	5.065468 =	5.065468

			B.T =	23.166571
708A	708A			
214		.050000 x	1.895000 =	.094750
513		.010000 x	882.700056 =	8.827001
511		.010000 x	137.785200 =	1.377852
405		.012500 x	624.120024 =	7.801500

			B.T =	18.101103
708B	708B			
706		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
709	709			
709A		1.000000 x	14.845930 =	14.845930
709B		1.000000 x	5.065468 =	5.065468

			B.T =	19.911398
709A	709A			
506		1.000000 x	446.600000 =	446.600000
512		1.000000 x	741.074400 =	741.074400

			AΘΡΟΙΣΜΑ =	1,187.674400
	B.T =	.012500 x	1,187.674400 =	14.845930

709B	709B			
706		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
710	710			
710A		1.000000 x	51.698985 =	51.698985
710B		1.000000 x	5.065468 =	5.065468

			B.T =	56.764453
710A	710A			
214		.200000 x	1.895000 =	.379000
405		.025000 x	624.120024 =	15.603001
513		.035000 x	882.700056 =	30.894502
511		.035000 x	137.785200 =	4.822482

			B.T =	51.698985

710B	710B			
706		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
711	711			
711A		1.000000 x	39.549558 =	39.549558
711B		1.000000 x	5.065468 =	5.065468

			B.T =	44.615026
711A	711A			
506		1.000000 x	446.600000 =	446.600000
512		1.000000 x	741.074400 =	741.074400

			AΘΡΟΙΣΜΑ =	1,187.674400
	B.T =	.033300 x	1,187.674400 =	39.549558

711B	711B			
706		1.000000 x	5.065468 =	5.065468

			B.T =	5.065468
712	712			
513		1.000000 x	882.700056 =	882.700056

			AΘΡΟΙΣΜΑ =	882.700056
	B.T =	.004000 x	882.700056 =	3.530800

713 1	713 1			
704		.500000 x	10.632264 =	5.316132

			B.T =	5.316132
713 2	713 2			
705		.500000 x	11.590347 =	5.795174

			B.T =	5.795174
714	714			
714A		1.000000 x	3.735773 =	3.735773
714B		1.000000 x	4.347519 =	4.347519

			B.T =	8.083292

714A	714A			
242		.070000 x	335.000000 =	23.450000
114		2.000000 x	18.705943 =	37.411886
252		1.000000 x	1.785000 =	1.785000
113		2.000000 x	24.769248 =	49.538496

			AΘΡΟΙΣΜΑ =	112.185382
	B.T =	.033300 x	112.185382 =	3.735773

714B	714B			
113		.100000 x	24.769248 =	2.476925
114		.100000 x	18.705943 =	1.870594

			B.T =	4.347519
1111	1111			
1111A		1.000000 x	33.271106 =	33.271106
1111B		1.000000 x	5.065468 =	5.065468

			T.E =	38.336574
1112	1112			
1112A		1.000000 x	29.691860 =	29.691860
1112B		1.000000 x	5.065468 =	5.065468

			T.E =	34.757328
1113	1113			
1113A		1.000000 x	56.375470 =	56.375470
1113B		1.000000 x	5.065468 =	5.065468

			T.E =	61.440938
1114	1114			
1114A		1.000000 x	43.869741 =	43.869741
1114B		1.000000 x	5.065468 =	5.065468

			T.E =	48.935209
1121	1121			
1121A		1.000000 x	24.842781 =	24.842781
1121B		1.000000 x	5.065468 =	5.065468

			T.E =	29.908249
1122	1122			
1122A		1.000000 x	14.845930 =	14.845930
1122B		1.000000 x	5.065468 =	5.065468

			T.E =	19.911398

1123	1123				
1123A		1.000000 x	42.845403 =	42.845403	
1123B		1.000000 x	5.065468 =	5.065468	

			T.E =	47.910871	
1124	1124				
1124A		1.000000 x	26.559379 =	26.559379	
1124B		1.000000 x	5.065468 =	5.065468	

			T.E =	31.624847	
1210	1210				
707		1.000000 x	3.411624 =	3.411624	

			T.E =	3.411624	
1220	1220				
708		1.000000 x	23.166571 =	23.166571	

			T.E =	23.166571	
1230	1230				
709		1.000000 x	19.911398 =	19.911398	

			T.E =	19.911398	
1311	1311				
712		.250000 x	3.530800 =	.882700	

			T.E =	.882700	
1312	1312				
712		.250000 x	3.530800 =	.882700	
701 1		1.000000 x	5.023766 =	5.023766	
602		1.000000 x	1.754763 =	1.754763	

			T.E =	7.661229	
1313	1313				
712		.250000 x	3.530800 =	.882700	
603		1.000000 x	7.152742 =	7.152742	
701 2		1.000000 x	4.728250 =	4.728250	

			T.E =	12.763692	

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	16.829739 =	1.682974	
712		.250000 x	3.530800 =	.882700	

			T.E =	37.565674	
1321	1321				
112		.200000 x	18.705943 =	3.741189	
701	1	1.000000 x	5.023766 =	5.023766	
602		1.000000 x	1.754763 =	1.754763	

			T.E =	10.519718	
1322	1322				
112		.200000 x	18.705943 =	3.741189	
603		1.000000 x	7.152742 =	7.152742	
701	2	1.000000 x	4.728250 =	4.728250	

			T.E =	15.622181	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	16.829739 =	1.682974	
112		.100000 x	18.705943 =	1.870594	

			T.E =	38.553568	
2110	2110				
712		.500000 x	3.530800 =	1.765400	
702		1.000000 x	3.013801 =	3.013801	
608		1.000000 x	13.433290 =	13.433290	
701	4	1.000000 x	4.432735 =	4.432735	

			T.E =	22.645226	
2120	2120				
712		.500000 x	3.530800 =	1.765400	
702		1.000000 x	3.013801 =	3.013801	
701	2	1.000000 x	4.728250 =	4.728250	
603		1.000000 x	7.152742 =	7.152742	

			T.E =	16.660193	
2130	2130				
712		.500000 x	3.530800 =	1.765400	
604		1.000000 x	7.996188 =	7.996188	
701	2	1.000000 x	4.728250 =	4.728250	
702		1.000000 x	3.013801 =	3.013801	

			T.E =	17.503639	

2140	2140				
712		.500000 x	3.530800 =	1.765400	
605		1.000000 x	12.236651 =	12.236651	
702		1.000000 x	3.013801 =	3.013801	
701	2	1.000000 x	4.728250 =	4.728250	

			T.E =	21.744102	
2210	2210				
712		.500000 x	3.530800 =	1.765400	
609		1.050000 x	21.604344 =	22.684561	
702		1.000000 x	3.013801 =	3.013801	
701	2	1.000000 x	4.728250 =	4.728250	

			T.E =	32.192012	
2220	2220				
712		.500000 x	3.530800 =	1.765400	
702		1.000000 x	3.013801 =	3.013801	
701	2	1.000000 x	4.728250 =	4.728250	
609		1.150000 x	21.604344 =	24.844996	

			T.E =	34.352447	
2230	2230				
111		.200000 x	16.829739 =	3.365948	
609		1.200000 x	21.604344 =	25.925213	
701	2	1.000000 x	4.728250 =	4.728250	

			T.E =	34.019411	
2240	2240				
111		.300000 x	16.829739 =	5.048922	
609		1.200000 x	21.604344 =	25.925213	
701	2	1.000000 x	4.728250 =	4.728250	

			T.E =	35.702385	
2310	2310				
612		1.000000 x	20.345550 =	20.345550	
701	3	1.000000 x	4.610044 =	4.610044	
703		1.000000 x	5.940382 =	5.940382	

			T.E =	30.895976	
2320	2320				
613		1.000000 x	29.451268 =	29.451268	
703		1.000000 x	5.940382 =	5.940382	
701	3	1.000000 x	4.610044 =	4.610044	

			T.E =	40.001694	

2330	2330				
614		1.000000 x	38.310337 =	38.310337	
703		1.000000 x	5.940382 =	5.940382	
701	3	1.000000 x	4.610044 =	4.610044	

				T.E =	48.860763
2340	2340				
615		1.000000 x	49.976989 =	49.976989	
703		1.000000 x	5.940382 =	5.940382	
701	3	1.000000 x	4.610044 =	4.610044	

				T.E =	60.527415
2350	2350				
616		1.000000 x	66.981059 =	66.981059	
703		1.000000 x	5.940382 =	5.940382	
701	3	1.000000 x	4.610044 =	4.610044	

				T.E =	77.531485
2410	2410				
617		1.000000 x	16.495299 =	16.495299	
703		1.000000 x	5.940382 =	5.940382	

				T.E =	22.435681
2420	2420				
618		1.000000 x	20.322208 =	20.322208	
703		1.000000 x	5.940382 =	5.940382	

				T.E =	26.262590
2430	2430				
619		1.000000 x	26.392478 =	26.392478	
703		1.000000 x	5.940382 =	5.940382	

				T.E =	32.332860
2440	2440				
620		1.000000 x	32.990598 =	32.990598	
703		1.000000 x	5.940382 =	5.940382	

				T.E =	38.930980
2450	2450				
621		1.000000 x	43.811514 =	43.811514	
703		1.000000 x	5.940382 =	5.940382	

				T.E =	49.751896

3110 1	3110 1				
3110A 1		1.000000 x	138.980157 =		138.980157
3110B		1.000000 x	15.948396 =		15.948396

			T.E =		154.928553
3110 2	3110 2				
3110A 2		1.000000 x	147.054526 =		147.054526
3110B		1.000000 x	15.948396 =		15.948396

			T.E =		163.002922
3110 3	3110 3				
3110A 3		1.000000 x	149.536570 =		149.536570
3110B		1.000000 x	15.948396 =		15.948396

			T.E =		165.484966
3110 4	3110 4				
3110A 4		1.000000 x	157.610939 =		157.610939
3110B		1.000000 x	15.948396 =		15.948396

			T.E =		173.559335
3120 1	3120 1				
3120A 1		1.000000 x	138.980157 =		138.980157
3120B		1.000000 x	17.385521 =		17.385521

			T.E =		156.365678
3120 2	3120 2				
3120A 2		1.000000 x	147.054526 =		147.054526
3120B		1.000000 x	17.385521 =		17.385521

			T.E =		164.440047
3120 3	3120 3				
3120A 3		1.000000 x	149.536570 =		149.536570
3120B		1.000000 x	17.385521 =		17.385521

			T.E =		166.922091
3120 4	3120 4				
3120A 4		1.000000 x	157.610939 =		157.610939
3120B		1.000000 x	17.385521 =		17.385521

			T.E =		174.996460

3210 1	3210 1				
3210A 1		1.000000 x	127.507336 =		127.507336
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		143.455732
3210 2	3210 2				
3210A 2		1.000000 x	133.966831 =		133.966831
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		149.915227
3210 3	3210 3				
3210A 3		1.000000 x	135.952466 =		135.952466
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		151.900862
3210 4	3210 4				
3210A 4		1.000000 x	142.411962 =		142.411962
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		158.360358
3210 5	3210 5				
3210A 5		1.000000 x	126.342451 =		126.342451
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		142.290847
3210 6	3210 6				
3210A 6		1.000000 x	132.801946 =		132.801946
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		148.750342
3210 7	3210 7				
3210A 7		1.000000 x	134.787582 =		134.787582
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		150.735978
3210 8	3210 8				
3210A 8		1.000000 x	141.247077 =		141.247077
3210B		1.000000 x	15.948396 =		15.948396

			T.E =		157.195473

3220	1	3220	1			
	3220A	1		1.000000 x	127.507336 =	127.507336
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	144.892857
3220	2	3220	2			
	3220A	2		1.000000 x	133.966831 =	133.966831
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	151.352352
3220	3	3220	3			
	3220A	3		1.000000 x	135.952466 =	135.952466
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	153.337987
3220	4	3220	4			
	3220A	4		1.000000 x	142.411962 =	142.411962
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	159.797483
3220	5	3220	5			
	3220A	5		1.000000 x	126.342451 =	126.342451
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	143.727972
3220	6	3220	6			
	3220A	6		1.000000 x	132.801946 =	132.801946
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	150.187467
3220	7	3220	7			
	3220A	7		1.000000 x	134.787582 =	134.787582
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	152.173103
3220	8	3220	8			
	3220A	8		1.000000 x	141.247077 =	141.247077
	3220B			1.000000 x	17.385521 =	17.385521

					T.E =	158.632598

3300 1	3300 1				
3300A 1		1.000000 x	196.854069 =	196.854069	
3300B 1		1.000000 x	15.948396 =	15.948396	

				T.E =	212.802465
3300 2	3300 2				
3300A 1		1.000000 x	196.854069 =	196.854069	
3300B 2		1.000000 x	17.385521 =	17.385521	

				T.E =	214.239590
3300 3	3300 3				
3300A 2		1.000000 x	204.928439 =	204.928439	
3300B 1		1.000000 x	15.948396 =	15.948396	

				T.E =	220.876835
3300 4	3300 4				
3300A 2		1.000000 x	204.928439 =	204.928439	
3300B 2		1.000000 x	17.385521 =	17.385521	

				T.E =	222.313960
3300 5	3300 5				
3300A 3		1.000000 x	207.410482 =	207.410482	
3300B 1		1.000000 x	15.948396 =	15.948396	

				T.E =	223.358878
3300 6	3300 6				
3300A 3		1.000000 x	207.410482 =	207.410482	
3300B 2		1.000000 x	17.385521 =	17.385521	

				T.E =	224.796003
3300 7	3300 7				
3300A 4		1.000000 x	215.484852 =	215.484852	
3300B 1		1.000000 x	15.948396 =	15.948396	

				T.E =	231.433248
3300 8	3300 8				
3300A 4		1.000000 x	215.484852 =	215.484852	
3300B 2		1.000000 x	17.385521 =	17.385521	

				T.E =	232.870373

3400 1	3400 1				
3400A 1		1.000000 x	210.312877 =	210.312877	
3400B 1		1.000000 x	10.632264 =	10.632264	

			T.E =	220.945141	
3400 2	3400 2				
3400A 1		1.000000 x	210.312877 =	210.312877	
3400B 2		1.000000 x	11.590347 =	11.590347	

			T.E =	221.903224	
3400 3	3400 3				
3400A 2		1.000000 x	218.387247 =	218.387247	
3400B 1		1.000000 x	10.632264 =	10.632264	

			T.E =	229.019511	
3400 4	3400 4				
3400A 2		1.000000 x	218.387247 =	218.387247	
3400B 2		1.000000 x	11.590347 =	11.590347	

			T.E =	229.977594	
3400 5	3400 5				
3400A 3		1.000000 x	220.869290 =	220.869290	
3400B 1		1.000000 x	10.632264 =	10.632264	

			T.E =	231.501554	
3400 6	3400 6				
3400A 3		1.000000 x	220.869290 =	220.869290	
3400B 2		1.000000 x	11.590347 =	11.590347	

			T.E =	232.459637	
3400 7	3400 7				
3400A 4		1.000000 x	228.943659 =	228.943659	
3400B 1		1.000000 x	10.632264 =	10.632264	

			T.E =	239.575923	
3400 8	3400 8				
3400A 4		1.000000 x	228.943659 =	228.943659	
3400B 2		1.000000 x	11.590347 =	11.590347	

			T.E =	240.534006	

4110	1	4110	1				
	4110A	1		1.000000 x	211.201848 =		211.201848
	4110B			.025000 x	1,600.821100 =		40.020528

						T.E =	251.222376
4110	2	4110	2				
	4110A	2		1.000000 x	219.276217 =		219.276217
	4110B			.025000 x	1,600.821100 =		40.020528

						T.E =	259.296745
4110	3	4110	3				
	4110A	3		1.000000 x	221.758261 =		221.758261
	4110B			.025000 x	1,600.821100 =		40.020528

						T.E =	261.778789
4110	4	4110	4				
	4110A	4		1.000000 x	229.832630 =		229.832630
	4110B			.025000 x	1,600.821100 =		40.020528

						T.E =	269.853158
4120	1	4120	1				
	4120A	1		1.000000 x	168.675037 =		168.675037
	4120B			1.000000 x	64.032844 =		64.032844

						T.E =	232.707881
4120	2	4120	2				
	4120A	2		1.000000 x	188.053523 =		188.053523
	4120B			1.000000 x	64.032844 =		64.032844

						T.E =	252.086367
4130	1	4130	1				
	4130A	1		1.000000 x	147.360205 =		147.360205
	4130B			1.000000 x	64.032844 =		64.032844

						T.E =	211.393049
4130	2	4130	2				
	4130A	2		1.000000 x	155.434575 =		155.434575
	4130B			1.000000 x	64.032844 =		64.032844

						T.E =	219.467419

4130	3	4130	3			
4130A	3			1.000000 x	157.916618 =	157.916618
4130B				1.000000 x	64.032844 =	64.032844

T.E =						221.949462
4130	4	4130	4			
4130A	4			1.000000 x	165.990988 =	165.990988
4130B				1.000000 x	64.032844 =	64.032844

T.E =						230.023832
4210	1	4210	1			
4210A	1			1.000000 x	43.960751 =	43.960751
4210B				1.000000 x	161.042179 =	161.042179

T.E =						205.002930
4210	2	4210	2			
4210A	2			1.000000 x	48.805373 =	48.805373
4210B				1.000000 x	161.042179 =	161.042179

T.E =						209.847552
4210	3	4210	3			
4210A	3			1.000000 x	40.138473 =	40.138473
4210B				1.000000 x	161.042179 =	161.042179

T.E =						201.180652
4210	4	4210	4			
4210A	4			1.000000 x	44.983095 =	44.983095
4210B				1.000000 x	161.042179 =	161.042179

T.E =						206.025274
4220B	1	4220B	1			
319				.020000 x	21.020000 =	.420400
701	2			.320000 x	4.728250 =	1.513040
601				.320000 x	25.244609 =	8.078275
4220A	1			.800000 x	115.092854 =	92.074283
714				1.150000 x	8.083292 =	9.295786
111				.400000 x	16.829739 =	6.731896

T.E =						118.113679

4220B 2	4220B 2			
319		.020000 x	21.020000 =	.420400
111		.400000 x	16.829739 =	6.731896
714		1.150000 x	8.083292 =	9.295786
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275
4220A 2		.800000 x	123.167223 =	98.533778

T.E = 124.573175

4220B 3	4220B 3			
319		.020000 x	21.020000 =	.420400
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275
111		.400000 x	16.829739 =	6.731896
4220A 3		.800000 x	125.649266 =	100.519413
714		1.150000 x	8.083292 =	9.295786

T.E = 126.558809

4220B 4	4220B 4			
319		.020000 x	21.020000 =	.420400
111		.400000 x	16.829739 =	6.731896
4220A 4		.800000 x	133.723636 =	106.978909
701 2		.320000 x	4.728250 =	1.513040
601		.320000 x	25.244609 =	8.078275
714		1.150000 x	8.083292 =	9.295786

T.E = 133.018305

4220B 5	4220B 5			
319		.020000 x	21.020000 =	.420400
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
4220A 1		.800000 x	115.092854 =	92.074283
714		1.150000 x	8.083292 =	9.295786
111		.400000 x	16.829739 =	6.731896

T.E = 116.948795

4220B 6	4220B 6			
319		.020000 x	21.020000 =	.420400
111		.400000 x	16.829739 =	6.731896
714		1.150000 x	8.083292 =	9.295786
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
4220A 2		.800000 x	123.167223 =	98.533778

T.E = 123.408290

4220B 7	4220B 7			
319		.020000 x	21.020000 =	.420400
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
111		.400000 x	16.829739 =	6.731896
4220A 3		.800000 x	125.649266 =	100.519413
714		1.150000 x	8.083292 =	9.295786

			T.E =	125.393924
4220B 8	4220B 8			
319		.020000 x	21.020000 =	.420400
111		.400000 x	16.829739 =	6.731896
4220A 4		.800000 x	133.723636 =	106.978909
701 2		.320000 x	4.728250 =	1.513040
609		.320000 x	21.604344 =	6.913390
714		1.150000 x	8.083292 =	9.295786

			T.E =	131.853420
4230 1	4230 1			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.955156 =	.738789
701 2		.500000 x	4.728250 =	2.364125
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
607		.500000 x	10.147018 =	5.073509
606		.800000 x	9.264638 =	7.411710
407		.040000 x	755.475659 =	30.219026
714		1.150000 x	8.083292 =	9.295786
113		1.200000 x	24.769248 =	29.723098
111		2.000000 x	16.829739 =	33.659478
319		.020000 x	21.020000 =	.420400

			T.E =	148.171680
4230 2	4230 2			
221		250.000000 x	.098900 =	24.725000
701 5		.250000 x	2.955156 =	.738789
701 4		.500000 x	4.432735 =	2.216368
701 2		.800000 x	4.728250 =	3.782600
630		.250000 x	3.032636 =	.758159
319		.020000 x	21.020000 =	.420400
111		2.000000 x	16.829739 =	33.659478
407		.040000 x	755.475659 =	30.219026
611		.500000 x	26.591272 =	13.295636
606		.800000 x	9.264638 =	7.411710
714		1.150000 x	8.083292 =	9.295786
113		1.200000 x	24.769248 =	29.723098

			T.E =	156.246050

4230	3	4230	3			
221				250.000000 x	.098900 =	24.725000
701	5			.250000 x	2.955156 =	.738789
701	4			.800000 x	4.432735 =	3.546188
701	2			.500000 x	4.728250 =	2.364125
630				.250000 x	3.032636 =	.758159
610				.800000 x	22.755669 =	18.204535
607				.500000 x	10.147018 =	5.073509
407				.040000 x	755.475659 =	30.219026
714				1.150000 x	8.083292 =	9.295786
319				.020000 x	21.020000 =	.420400
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478

T.E = 158.728093

4230	4	4230	4			
221				250.000000 x	.098900 =	24.725000
701	5			.250000 x	2.955156 =	.738789
701	4			.500000 x	4.432735 =	2.216368
701	4			.800000 x	4.432735 =	3.546188
630				.250000 x	3.032636 =	.758159
319				.020000 x	21.020000 =	.420400
113				1.200000 x	24.769248 =	29.723098
407				.040000 x	755.475659 =	30.219026
611				.500000 x	26.591272 =	13.295636
610				.800000 x	22.755669 =	18.204535
714				1.150000 x	8.083292 =	9.295786
111				2.000000 x	16.829739 =	33.659478

T.E = 166.802462

4240	1	4240	1			
221				300.000000 x	.098900 =	29.670000
701	5			.250000 x	2.955156 =	.738789
701	2			.500000 x	4.728250 =	2.364125
701	2			.800000 x	4.728250 =	3.782600
630				.250000 x	3.032636 =	.758159
607				.500000 x	10.147018 =	5.073509
606				.800000 x	9.264638 =	7.411710
407				.040000 x	755.475659 =	30.219026
714				1.150000 x	8.083292 =	9.295786
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478
319				.020000 x	21.020000 =	.420400

T.E = 153.116680

4240	2	4240	2			
221				300.000000 x	.098900 =	29.670000
606				.800000 x	9.264638 =	7.411710
701	5			.250000 x	2.955156 =	.738789
701	4			.500000 x	4.432735 =	2.216368
701	2			.800000 x	4.728250 =	3.782600
630				.250000 x	3.032636 =	.758159
611				.500000 x	26.591272 =	13.295636
407				.040000 x	755.475659 =	30.219026
714				1.150000 x	8.083292 =	9.295786
113				1.200000 x	24.769248 =	29.723098
111				2.000000 x	16.829739 =	33.659478
319				.020000 x	21.020000 =	.420400

T.E = 161.191050

4240	3	4240	3			
221				300.000000 x	.098900 =	29.670000
319				.020000 x	21.020000 =	.420400
111				2.000000 x	16.829739 =	33.659478
701	5			.250000 x	2.955156 =	.738789
701	4			.800000 x	4.432735 =	3.546188
701	2			.500000 x	4.728250 =	2.364125
630				.250000 x	3.032636 =	.758159
610				.800000 x	22.755669 =	18.204535
607				.500000 x	10.147018 =	5.073509
407				.040000 x	755.475659 =	30.219026
714				1.150000 x	8.083292 =	9.295786
113				1.200000 x	24.769248 =	29.723098

T.E = 163.673093

4240	4	4240	4			
221				300.000000 x	.098900 =	29.670000
630				.250000 x	3.032636 =	.758159
701	5			.250000 x	2.955156 =	.738789
701	4			.500000 x	4.432735 =	2.216368
701	4			.800000 x	4.432735 =	3.546188
611				.500000 x	26.591272 =	13.295636
610				.800000 x	22.755669 =	18.204535
407				.040000 x	755.475659 =	30.219026
111				2.000000 x	16.829739 =	33.659478
714				1.150000 x	8.083292 =	9.295786
113				1.200000 x	24.769248 =	29.723098
319				.020000 x	21.020000 =	.420400

T.E = 171.747462

4300	1	4300	1			
4300A	1			1.000000 x	31.528256 =	31.528256
4300B				1.000000 x	11.600177 =	11.600177

T.E = 43.128433

4300	2	4300	2			
4300A	2			1.000000 x	33.143130 =	33.143130
4300B				1.000000 x	11.600177 =	11.600177

					T.E =	44.743307
4300	3	4300	3			
4300A	3			1.000000 x	33.639539 =	33.639539
4300B				1.000000 x	11.600177 =	11.600177

					T.E =	45.239716
4300	4	4300	4			
4300A	4			1.000000 x	35.254412 =	35.254412
4300B				1.000000 x	11.600177 =	11.600177

					T.E =	46.854589
4400		4400				
251				1.050000 x	.528700 =	.555135
113				.050000 x	24.769248 =	1.238462

					T.E =	1.793597
4500		4500				
251				1.050000 x	.528700 =	.555135
114				.100000 x	18.705943 =	1.870594
113				.100000 x	24.769248 =	2.476925

					T.E =	4.902654
4600		4600				
256				1.000000 x	3.500000 =	3.500000
113				.100000 x	24.769248 =	2.476925

					T.E =	5.976925
4700		4700				
253				1.000000 x	3.700000 =	3.700000
113				.100000 x	24.769248 =	2.476925

					T.E =	6.176925