

ΑΤΛΕ

Αναλυτικά Τιμολόγια Λιμενικών Έργων

1ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	17.312112
115	20.419486
116	23.886192
117	10.001019
118	21.778427
119	10.001019
120	16.777917
121	16.585068
122	13.510339
123	64.260999
211	1.140600
212	1.362600
213	4.160000
214	1.949500
221	.099900
222	.070000
231	36.000000
232	35.000000
241	290.000000
242	370.000000
251	.556800
252	2.020000
253	4.150000
254	5.000000
255	.967200
256	3.930000
261	
262	.980000
263	.540000
311	425.280000
312	130.670000
313	200.790000
314	4.400000
315	53.630000
316	4.400000
317	122.460000
318	26.580000
319	21.440000
320	152.240000
321	207.240000
322	287.930000
323	327.890000
324	179.890000
325	308.130000
326	100.390000
327	4.400000
351	438.810000
352	372.560000
353	438.810000
354	575.700000
355	287.930000
356	47.250000
357	226.390000
358	45.580000
359	94.500000
360	99.520000

361	76.120000
362	263.460000
363	99.670000
380	552.590000
381	552.590000
382	552.590000
383	635.530000
384	1,052.620000
385	191.250000
386	504.640000
387	72.810000
388	72.810000
389	72.810000

401	401				
211		110.000000 x	1.140600 =	125.466000	
213		10.000000 x	4.160000 =	41.600000	
311		1.000000 x	425.280000 =	425.280000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
			ΑΘΡΟΙΣΜΑ =	823.439612	
			Η.Δ. =	905.783573	
402	402				
211		180.000000 x	1.140600 =	205.308000	
213		12.000000 x	4.160000 =	49.920000	
117		8.000000 x	10.001019 =	80.008152	
116		8.000000 x	23.886192 =	191.089536	
112		8.000000 x	17.312112 =	138.496896	
312		1.000000 x	130.670000 =	130.670000	
212		5.000000 x	1.362600 =	6.813000	
			ΑΘΡΟΙΣΜΑ =	802.305584	
			Η.Δ. =	882.536142	
403	403				
211		80.000000 x	1.140600 =	91.248000	
254		2.500000 x	5.000000 =	12.500000	
213		6.000000 x	4.160000 =	24.960000	
116		8.000000 x	23.886192 =	191.089536	
117		8.000000 x	10.001019 =	80.008152	
313		1.000000 x	200.790000 =	200.790000	
			ΑΘΡΟΙΣΜΑ =	600.595688	
			Η.Δ. =	660.655257	
404	404				
211		80.000000 x	1.140600 =	91.248000	
212		2.000000 x	1.362600 =	2.725200	
118		8.000000 x	21.778427 =	174.227416	
119		4.000000 x	10.001019 =	40.004076	
314		1.000000 x	4.400000 =	4.400000	
112		4.000000 x	17.312112 =	69.248448	
213		5.000000 x	4.160000 =	20.800000	
			ΑΘΡΟΙΣΜΑ =	402.653140	
			Η.Δ. =	442.918454	

405	405				
211		40.000000 x	1.140600 =	45.624000	
213		2.000000 x	4.160000 =	8.320000	
118		4.000000 x	21.778427 =	87.113708	
115		16.000000 x	20.419486 =	326.711776	
316		2.000000 x	4.400000 =	8.800000	
315		1.000000 x	53.630000 =	53.630000	

			ΑΘΡΟΙΣΜΑ =	530.199484	

			Η.Δ. =	583.219432	
406	406				
211		80.000000 x	1.140600 =	91.248000	
213		5.000000 x	4.160000 =	20.800000	
317		1.000000 x	122.460000 =	122.460000	
120		8.000000 x	16.777917 =	134.223336	

			ΑΘΡΟΙΣΜΑ =	368.731336	

			Η.Δ. =	405.604470	
407	407				
212		17.000000 x	1.362600 =	23.164200	
112		30.000000 x	17.312112 =	519.363360	
118		4.000000 x	21.778427 =	87.113708	
213		1.000000 x	4.160000 =	4.160000	
318		1.000000 x	26.580000 =	26.580000	

			ΑΘΡΟΙΣΜΑ =	660.381268	

			Η.Δ. =	726.419395	
408	408				
211		30.000000 x	1.140600 =	34.218000	
320		1.000000 x	152.240000 =	152.240000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	499.280060	

			Η.Δ. =	549.208066	
409	409				
211		50.000000 x	1.140600 =	57.030000	
213		5.000000 x	4.160000 =	20.800000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
324		1.000000 x	179.890000 =	179.890000	

			ΑΘΡΟΙΣΜΑ =	558.062060	

			Η.Δ. =	613.868266	

410	410				
211		100.000000 x	1.140600 =	114.060000	
213		10.000000 x	4.160000 =	41.600000	
321		1.000000 x	207.240000 =	207.240000	
116		8.000000 x	23.886192 =	191.089536	
117		4.000000 x	10.001019 =	40.004076	
112		4.000000 x	17.312112 =	69.248448	

			ΑΘΡΟΙΣΜΑ =	663.242060	

			Η.Δ. =	729.566266	
411	411				
211		200.000000 x	1.140600 =	228.120000	
325		1.000000 x	308.130000 =	308.130000	
117		4.000000 x	10.001019 =	40.004076	
116		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
213		20.000000 x	4.160000 =	83.200000	

			ΑΘΡΟΙΣΜΑ =	919.792060	

			Η.Δ. =	1,011.771266	
412	412				
211		40.000000 x	1.140600 =	45.624000	
116		8.000000 x	23.886192 =	191.089536	
326		1.000000 x	100.390000 =	100.390000	
213		2.000000 x	4.160000 =	8.320000	

			ΑΘΡΟΙΣΜΑ =	345.423536	

			Η.Δ. =	379.965890	
413	413				
211		15.000000 x	1.140600 =	17.109000	
213		1.500000 x	4.160000 =	6.240000	
118		3.000000 x	21.778427 =	65.335281	
112		3.000000 x	17.312112 =	51.936336	
327		1.000000 x	4.400000 =	4.400000	

			ΑΘΡΟΙΣΜΑ =	145.020617	

			Η.Δ. =	159.522679	
501	501				
211		170.000000 x	1.140600 =	193.902000	
380		1.000000 x	552.590000 =	552.590000	
213		3.000000 x	4.160000 =	12.480000	
351		1.000000 x	438.810000 =	438.810000	

			ΑΘΡΟΙΣΜΑ =	1,197.782000	

			Η.Δ. =	1,317.560200	

502	502				
211		170.000000 x	1.140600 =	193.902000	
381		1.000000 x	552.590000 =	552.590000	
213		3.000000 x	4.160000 =	12.480000	
352		1.000000 x	372.560000 =	372.560000	

			ΑΘΡΟΙΣΜΑ =	1,131.532000	

			Η.Δ. =	1,244.685200	
503	503				
211		170.000000 x	1.140600 =	193.902000	
382		1.000000 x	552.590000 =	552.590000	
353		1.000000 x	438.810000 =	438.810000	
213		3.000000 x	4.160000 =	12.480000	

			ΑΘΡΟΙΣΜΑ =	1,197.782000	

			Η.Δ. =	1,317.560200	
504	504				
211		190.000000 x	1.140600 =	216.714000	
213		6.000000 x	4.160000 =	24.960000	
354		1.000000 x	575.700000 =	575.700000	
383		1.000000 x	635.530000 =	635.530000	

			ΑΘΡΟΙΣΜΑ =	1,452.904000	

			Η.Δ. =	1,598.194400	
505	505				
211		1,250.000000 x	1.140600 =	1,425.750000	
213		7.500000 x	4.160000 =	31.200000	
384		1.000000 x	1,052.620000 =	1,052.620000	
355		1.000000 x	287.930000 =	287.930000	

			ΑΘΡΟΙΣΜΑ =	2,797.500000	

			Η.Δ. =	3,077.250000	
506	506				
211		200.000000 x	1.140600 =	228.120000	
213		2.000000 x	4.160000 =	8.320000	
385		1.000000 x	191.250000 =	191.250000	
356		1.000000 x	47.250000 =	47.250000	

			ΑΘΡΟΙΣΜΑ =	474.940000	

			Η.Δ. =	522.434000	
507	507				
211		2,100.000000 x	1.140600 =	2,395.260000	
386		1.000000 x	504.640000 =	504.640000	
357		1.000000 x	226.390000 =	226.390000	
213		35.000000 x	4.160000 =	145.600000	

			ΑΘΡΟΙΣΜΑ =	3,271.890000	

			Η.Δ. =	3,533.641200	

508	508				
358		1.000000 x	45.580000 =		45.580000
387		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	118.390000
				Η.Δ. =	124.309500
509	509				
359		1.000000 x	94.500000 =		94.500000
388		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	167.310000
				Η.Δ. =	175.675500
510	510				
360		1.000000 x	99.520000 =		99.520000
389		1.000000 x	72.810000 =		72.810000
				ΑΘΡΟΙΣΜΑ =	172.330000
				Η.Δ. =	180.946500
511	511				
509		.800000 x	175.675500 =		140.540400
				Η.Δ. =	140.540400
512	512				
501		.600000 x	1,317.560200 =		790.536120
				Η.Δ. =	790.536120
513	513				
363		1.000000 x	99.670000 =		99.670000
123		8.000000 x	64.260999 =		514.087992
122		8.000000 x	13.510339 =		108.082712
121		8.000000 x	16.585068 =		132.680544
				Η.Δ. =	854.521248
1111A	1111A				
214		.200000 x	1.949500 =		.389900
511		.020000 x	140.540400 =		2.810808
405		.020000 x	583.219432 =		11.664389
513		.020000 x	854.521248 =		17.090425
				Β.Τ =	31.955522

1111B	1111B			
501		1.000000 x	1,317.560200 =	1,317.560200
506		1.000000 x	522.434000 =	522.434000
509		2.000000 x	175.675500 =	351.351000

			ΑΘΡΟΙΣΜΑ =	2,191.345200
	B.T =	.002500 x	2,191.345200 =	5.478363

1112A	1112A			
506		1.000000 x	522.434000 =	522.434000
512		1.000000 x	790.536120 =	790.536120

			ΑΘΡΟΙΣΜΑ =	1,312.970120
	B.T =	.025000 x	1,312.970120 =	32.824253

1112B	1112B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
1113A	1113A			
214		.200000 x	1.949500 =	.389900
112		.250000 x	17.312112 =	4.328028
511		.035000 x	140.540400 =	4.918914
513		.035000 x	854.521248 =	29.908244
405		.025000 x	583.219432 =	14.580486

			B.T =	54.125571
1113B	1113B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
1114A	1114A			
112		.250000 x	17.312112 =	4.328028
506		.033000 x	522.434000 =	17.240322
512		.033000 x	790.536120 =	26.087692

			B.T =	47.656042
1114B	1114B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363

1121A	1121A			
214		.150000 x	1.949500 =	.292425
115		.500000 x	20.419486 =	10.209743
405		.020000 x	583.219432 =	11.664389

			B.T =	22.166557
1121B	1121B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
1122A	1122A			
506		1.000000 x	522.434000 =	522.434000
512		1.000000 x	790.536120 =	790.536120

			AΘΡΟΙΣΜΑ =	1,312.970120
	B.T =	.012500 x	1,312.970120 =	16.412127

1122B	1122B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
1123A	1123A			
214		.150000 x	1.949500 =	.292425
112		.150000 x	17.312112 =	2.596817
405		.025000 x	583.219432 =	14.580486
115		1.000000 x	20.419486 =	20.419486

			B.T =	37.889214
1123B	1123B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
1124A	1124A			
112		.150000 x	17.312112 =	2.596817
506		.020000 x	522.434000 =	10.448680
512		.020000 x	790.536120 =	15.810722

			B.T =	28.856219
1124B	1124B			
1111B		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363

3110A 1

3110A 1

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.001473 =	.750368
701	2	.800000 x	4.802357 =	3.841886
701	2	.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
714		1.400000 x	7.215820 =	10.102148
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534
319		.020000 x	21.440000 =	.428800

B.T =

130.184085

3110A 2

3110A 2

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.001473 =	.750368
701	4	.500000 x	4.502210 =	2.251105
701	2	.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
319		.020000 x	21.440000 =	.428800
112		1.200000 x	17.312112 =	20.774534
407		.040000 x	726.419395 =	29.056776
611		.500000 x	25.474274 =	12.737137
606		.800000 x	9.311915 =	7.449532
714		1.400000 x	7.215820 =	10.102148
113		1.200000 x	20.419486 =	24.503383

B.T =

137.668283

3110A 3

3110A 3

221		250.000000 x	.099900 =	24.975000
701	5	.250000 x	3.001473 =	.750368
701	4	.800000 x	4.502210 =	3.601768
701	2	.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
407		.040000 x	726.419395 =	29.056776
714		1.400000 x	7.215820 =	10.102148
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
112		1.200000 x	17.312112 =	20.774534

B.T =

139.837930

3110A 4	3110A 4			
221		250.000000 x	.099900 =	24.975000
714		1.400000 x	7.215820 =	10.102148
319		.020000 x	21.440000 =	.428800
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.001473 =	.750368
701 4		.800000 x	4.502210 =	3.601768
701 4		.500000 x	4.502210 =	2.251105
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
610		.800000 x	21.679369 =	17.343495
407		.040000 x	726.419395 =	29.056776
112		1.200000 x	17.312112 =	20.774534
			B.T =	147.322128
3110B	3110B			
713 1		1.000000 x	5.659071 =	5.659071
704		1.000000 x	11.318141 =	11.318141
			B.T =	16.977212
3120A 1	3120A 1			
3110A 1		1.000000 x	130.184085 =	130.184085
			B.T =	130.184085
3120A 2	3120A 2			
3110A 2		1.000000 x	137.668283 =	137.668283
			B.T =	137.668283
3120A 3	3120A 3			
3110A 3		1.000000 x	139.837930 =	139.837930
			B.T =	139.837930
3120A 4	3120A 4			
3110A 4		1.000000 x	147.322128 =	147.322128
			B.T =	147.322128
3120B	3120B			
713 2		1.000000 x	6.134879 =	6.134879
705		1.000000 x	12.269757 =	12.269757
			B.T =	18.404636

3210A 1	3210A 1			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967
3110A 1		.800000 x	130.184085 =	104.147268

			B.T =	119.536628
3210A 2	3210A 2			
111		.400000 x	15.741598 =	6.296639
3110A 2		.800000 x	137.668283 =	110.134626
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967

			B.T =	125.523987
3210A 3	3210A 3			
111		.400000 x	15.741598 =	6.296639
3110A 3		.800000 x	139.837930 =	111.870344
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967

			B.T =	127.259704
3210A 4	3210A 4			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967
3110A 4		.800000 x	147.322128 =	117.857702

			B.T =	133.247063
3210A 5	3210A 5			
111		.400000 x	15.741598 =	6.296639
3110A 1		.800000 x	130.184085 =	104.147268
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231

			B.T =	118.312893
3210A 6	3210A 6			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
3110A 2		.800000 x	137.668283 =	110.134626

			B.T =	124.300251

3210A 7	3210A 7			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
3110A 3		.800000 x	139.837930 =	111.870344

			B.T =	126.035969
3210A 8	3210A 8			
111		.400000 x	15.741598 =	6.296639
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
3110A 4		.800000 x	147.322128 =	117.857702

			B.T =	132.023327
3210B	3210B			
713 1		1.000000 x	5.659071 =	5.659071
704		1.000000 x	11.318141 =	11.318141

			B.T =	16.977212
3220A 1	3220A 1			
3210A 1		1.000000 x	119.536628 =	119.536628

			B.T =	119.536628
3220A 2	3220A 2			
3210A 2		1.000000 x	125.523987 =	125.523987

			B.T =	125.523987
3220A 3	3220A 3			
3210A 3		1.000000 x	127.259704 =	127.259704

			B.T =	127.259704
3220A 4	3220A 4			
3210A 4		1.000000 x	133.247063 =	133.247063

			B.T =	133.247063
3220A 5	3220A 5			
3210A 5		1.000000 x	118.312893 =	118.312893

			B.T =	118.312893

3220A 6	3220A 6			
3210A 6		1.000000 x	124.300251 =	124.300251

			B.T =	124.300251
3220A 7	3220A 7			
3210A 7		1.000000 x	126.035969 =	126.035969

			B.T =	126.035969
3220A 8	3220A 8			
3210A 8		1.000000 x	132.023327 =	132.023327

			B.T =	132.023327
3220B	3220B			
713 2		1.000000 x	6.134879 =	6.134879
705		1.000000 x	12.269757 =	12.269757

			B.T =	18.404636
3300A 1	3300A 1			
221		300.000000 x	.099900 =	29.970000
701 5		.250000 x	3.001473 =	.750368
701 2		.500000 x	4.802357 =	2.401179
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
714		2.600000 x	7.215820 =	18.761132
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	21.440000 =	.857600

			B.T =	182.330238
3300A 2	3300A 2			
221		300.000000 x	.099900 =	29.970000
111		2.700000 x	15.741598 =	42.502315
714		2.600000 x	7.215820 =	18.761132
701 5		.250000 x	3.001473 =	.750368
701 4		.500000 x	4.502210 =	2.251105
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
113		2.000000 x	20.419486 =	40.838972
319		.040000 x	21.440000 =	.857600

			B.T =	189.814436

3300A 3

3300A 3

221		300.000000 x	.099900 =	29.970000
630		.250000 x	3.190454 =	.797614
701	5	.250000 x	3.001473 =	.750368
701	4	.800000 x	4.502210 =	3.601768
701	2	.500000 x	4.802357 =	2.401179
607		.500000 x	10.205731 =	5.102866
610		.800000 x	21.679369 =	17.343495
407		.040000 x	726.419395 =	29.056776
113		2.000000 x	20.419486 =	40.838972
714		2.600000 x	7.215820 =	18.761132
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	21.440000 =	.857600

B.T =

191.984083

3300A 4

3300A 4

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.001473 =	.750368
701	4	.800000 x	4.502210 =	3.601768
701	4	.500000 x	4.502210 =	2.251105
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
610		.800000 x	21.679369 =	17.343495
407		.040000 x	726.419395 =	29.056776
714		2.600000 x	7.215820 =	18.761132
113		2.000000 x	20.419486 =	40.838972
111		2.700000 x	15.741598 =	42.502315
319		.040000 x	21.440000 =	.857600

B.T =

199.468281

3300B 1

3300B 1

713	1	1.000000 x	5.659071 =	5.659071
704		1.000000 x	11.318141 =	11.318141

B.T =

16.977212

3300B 2

3300B 2

713	2	1.000000 x	6.134879 =	6.134879
705		1.000000 x	12.269757 =	12.269757

B.T =

18.404636

3400A 1

3400A 1

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.967200 =	4.836000
111		2.700000 x	15.741598 =	42.502315
112		1.000000 x	17.312112 =	17.312112
113		2.000000 x	20.419486 =	40.838972
701	5	.250000 x	3.001473 =	.750368
701	2	.800000 x	4.802357 =	3.841886
701	2	.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
113		.500000 x	20.419486 =	10.209743
319		.030000 x	21.440000 =	.643200

B.T =

195.712561

3400A 2

3400A 2

221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.967200 =	4.836000
611		.500000 x	25.474274 =	12.737137
701	5	.250000 x	3.001473 =	.750368
701	4	.500000 x	4.502210 =	2.251105
701	2	.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200

B.T =

203.196759

3400A 3

3400A 3

221		300.000000 x	.099900 =	29.970000
701	5	.250000 x	3.001473 =	.750368
701	4	.800000 x	4.502210 =	3.601768
701	2	.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
407		.040000 x	726.419395 =	29.056776
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200
255		5.000000 x	.967200 =	4.836000

B.T =

205.366406

3400A 4	3400A 4			
221		300.000000 x	.099900 =	29.970000
255		5.000000 x	.967200 =	4.836000
701 5		.250000 x	3.001473 =	.750368
701 4		.800000 x	4.502210 =	3.601768
701 4		.500000 x	4.502210 =	2.251105
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
610		.800000 x	21.679369 =	17.343495
407		.040000 x	726.419395 =	29.056776
113		2.000000 x	20.419486 =	40.838972
113		.500000 x	20.419486 =	10.209743
112		1.000000 x	17.312112 =	17.312112
111		2.700000 x	15.741598 =	42.502315
319		.030000 x	21.440000 =	.643200

			B.T =	212.850604
3400B 1	3400B 1			
704		1.000000 x	11.318141 =	11.318141

			B.T =	11.318141
3400B 2	3400B 2			
705		1.000000 x	12.269757 =	12.269757

			B.T =	12.269757
4110A 1	4110A 1			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.001473 =	.300147
701 2		.800000 x	4.802357 =	3.841886
701 2		.500000 x	4.802357 =	2.401179
630		.100000 x	3.190454 =	.319045
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.070000 x	726.419395 =	50.849358
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

			B.T =	198.824633

4110A 2	4110A 2			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
407		.070000 x	726.419395 =	50.849358
611		.500000 x	25.474274 =	12.737137
701 4		.500000 x	4.502210 =	2.251105
701 5		.100000 x	3.001473 =	.300147
701 2		.800000 x	4.802357 =	3.841886
630		.100000 x	3.190454 =	.319045
606		.800000 x	9.311915 =	7.449532
113		1.500000 x	20.419486 =	30.629229

B.T = 206.308831

4110A 3	4110A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.100000 x	3.001473 =	.300147
701 4		.800000 x	4.502210 =	3.601768
701 2		.500000 x	4.802357 =	2.401179
630		.100000 x	3.190454 =	.319045
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
407		.070000 x	726.419395 =	50.849358
113		1.500000 x	20.419486 =	30.629229
111		4.000000 x	15.741598 =	62.966392

B.T = 208.478479

4110A 4	4110A 4			
221		350.000000 x	.099900 =	34.965000
111		4.000000 x	15.741598 =	62.966392
611		.500000 x	25.474274 =	12.737137
701 5		.100000 x	3.001473 =	.300147
701 4		.800000 x	4.502210 =	3.601768
701 4		.500000 x	4.502210 =	2.251105
630		.100000 x	3.190454 =	.319045
610		.800000 x	21.679369 =	17.343495
407		.070000 x	726.419395 =	50.849358
113		1.500000 x	20.419486 =	30.629229

B.T = 215.962677

4110B	4110B			
112		8.000000 x	17.312112 =	138.496896
513		1.000000 x	854.521248 =	854.521248
508		1.000000 x	124.309500 =	124.309500
506		1.000000 x	522.434000 =	522.434000

B.T = 1,639.761644

4120A 1	4120A 1			
221		350.000000 x	.099900 =	34.965000
701 2		1.200000 x	4.802357 =	5.762828
607		1.200000 x	10.205731 =	12.246877
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.312112 =	86.560560

			B.T =	162.215266
4120A 2	4120A 2			
221		350.000000 x	.099900 =	34.965000
701 4		1.200000 x	4.502210 =	5.402652
611		1.200000 x	25.474274 =	30.569129
263		42.000000 x	.540000 =	22.680000
112		5.000000 x	17.312112 =	86.560560

			B.T =	180.177341
4120B	4120B			
4110B		.040000 x	1,639.761644 =	65.590466

			B.T =	65.590466
4130A 1	4130A 1			
221		350.000000 x	.099900 =	34.965000
263		42.000000 x	.540000 =	22.680000
407		.050000 x	726.419395 =	36.320970
606		.800000 x	9.311915 =	7.449532
607		.500000 x	10.205731 =	5.102866
701 2		.500000 x	4.802357 =	2.401179
701 2		.800000 x	4.802357 =	3.841886
111		2.000000 x	15.741598 =	31.483196

			B.T =	144.244627
4130A 2	4130A 2			
221		350.000000 x	.099900 =	34.965000
407		.050000 x	726.419395 =	36.320970
701 4		.500000 x	4.502210 =	2.251105
701 2		.800000 x	4.802357 =	3.841886
611		.500000 x	25.474274 =	12.737137
606		.800000 x	9.311915 =	7.449532
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

			B.T =	151.728825

4130A 3	4130A 3			
221		350.000000 x	.099900 =	34.965000
701 4		.800000 x	4.502210 =	3.601768
701 2		.500000 x	4.802357 =	2.401179
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
407		.050000 x	726.419395 =	36.320970
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

			B.T =	153.898473
4130A 4	4130A 4			
221		350.000000 x	.099900 =	34.965000
701 4		.500000 x	4.502210 =	2.251105
701 4		.800000 x	4.502210 =	3.601768
611		.500000 x	25.474274 =	12.737137
610		.800000 x	21.679369 =	17.343495
407		.050000 x	726.419395 =	36.320970
111		2.000000 x	15.741598 =	31.483196
263		42.000000 x	.540000 =	22.680000

			B.T =	161.382671
4130B	4130B			
4120B		1.000000 x	65.590466 =	65.590466

			B.T =	65.590466
4210A 1	4210A 1			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.001473 =	.450221
601		1.050000 x	23.612397 =	24.793017
630		.150000 x	3.190454 =	.478568
701 2		1.050000 x	4.802357 =	5.042475
701 2		.300000 x	4.802357 =	1.440707
607		.300000 x	10.205731 =	3.061719
222		10.000000 x	.070000 =	.700000

			B.T =	42.460207
4210A 2	4210A 2			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.001473 =	.450221
701 4		.300000 x	4.502210 =	1.350663
701 2		1.050000 x	4.802357 =	5.042475
630		.150000 x	3.190454 =	.478568
611		.300000 x	25.474274 =	7.642282
601		1.050000 x	23.612397 =	24.793017
222		10.000000 x	.070000 =	.700000

			B.T =	46.950726

4210A 3	4210A 3			
221		65.000000 x	.099900 =	6.493500
701 2		.300000 x	4.802357 =	1.440707
609		1.050000 x	19.788223 =	20.777634
222		10.000000 x	.070000 =	.700000
701 5		.150000 x	3.001473 =	.450221
701 2		1.050000 x	4.802357 =	5.042475
630		.150000 x	3.190454 =	.478568
607		.300000 x	10.205731 =	3.061719

B.T = 38.444824

4210A 4	4210A 4			
221		65.000000 x	.099900 =	6.493500
701 5		.150000 x	3.001473 =	.450221
701 4		.300000 x	4.502210 =	1.350663
701 2		1.050000 x	4.802357 =	5.042475
630		.150000 x	3.190454 =	.478568
222		10.000000 x	.070000 =	.700000
611		.300000 x	25.474274 =	7.642282
609		1.050000 x	19.788223 =	20.777634

B.T = 42.935343

4210B	4210B			
111		4.000000 x	15.741598 =	62.966392
112		.200000 x	17.312112 =	3.462422
113		2.500000 x	20.419486 =	51.048715
112		1.500000 x	17.312112 =	25.968168

B.T = 143.445697

4220A 1	4220A 1			
221		200.000000 x	.099900 =	19.980000
701 5		.250000 x	3.001473 =	.750368
701 2		.800000 x	4.802357 =	3.841886
701 2		.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
113		1.000000 x	20.419486 =	20.419486
111		1.200000 x	15.741598 =	18.889918

B.T = 108.689623

4220A 2	4220A 2			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
113		1.000000 x	20.419486 =	20.419486
611		.500000 x	25.474274 =	12.737137
701 4		.500000 x	4.502210 =	2.251105
701 5		.250000 x	3.001473 =	.750368
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776

B.T = 116.173821

4220A 3	4220A 3			
221		200.000000 x	.099900 =	19.980000
701 4		.800000 x	4.502210 =	3.601768
701 2		.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	726.419395 =	29.056776
113		1.000000 x	20.419486 =	20.419486
701 5		.250000 x	3.001473 =	.750368

B.T = 118.343468

4220A 4	4220A 4			
221		200.000000 x	.099900 =	19.980000
111		1.200000 x	15.741598 =	18.889918
407		.040000 x	726.419395 =	29.056776
611		.500000 x	25.474274 =	12.737137
701 5		.250000 x	3.001473 =	.750368
701 4		.500000 x	4.502210 =	2.251105
701 4		.800000 x	4.502210 =	3.601768
630		.250000 x	3.190454 =	.797614
610		.800000 x	21.679369 =	17.343495
113		1.000000 x	20.419486 =	20.419486

B.T = 125.827666

4300A 1	4300A 1			
221		350.000000 x	.099900 =	34.965000
111		2.000000 x	15.741598 =	31.483196
113		1.200000 x	20.419486 =	24.503383
701 5		.250000 x	3.001473 =	.750368
701 2		.800000 x	4.802357 =	3.841886
701 2		.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
714		1.150000 x	7.215820 =	8.298193

			AΘΡΟΙΣΜΑ =	148.649991
B.T =		.200000 x	148.649991 =	29.729998

4300A 2	4300A 2			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.001473 =	.750368
701 4		.500000 x	4.502210 =	2.251105
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			AΘΡΟΙΣΜΑ =	156.134189
B.T =		.200000 x	156.134189 =	31.226838

4300A 3	4300A 3			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.001473 =	.750368
701 4		.800000 x	4.502210 =	3.601768
701 2		.500000 x	4.802357 =	2.401179
630		.250000 x	3.190454 =	.797614
610		.800000 x	21.679369 =	17.343495
607		.500000 x	10.205731 =	5.102866
407		.040000 x	726.419395 =	29.056776
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196

			AΘΡΟΙΣΜΑ =	158.303837
B.T =		.200000 x	158.303837 =	31.660767

4300A 4	4300A 4			
221		350.000000 x	.099900 =	34.965000
701 5		.250000 x	3.001473 =	.750368
701 4		.800000 x	4.502210 =	3.601768
701 4		.500000 x	4.502210 =	2.251105
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
610		.800000 x	21.679369 =	17.343495
630		.250000 x	3.190454 =	.797614
611		.500000 x	25.474274 =	12.737137
407		.040000 x	726.419395 =	29.056776
111		2.000000 x	15.741598 =	31.483196
			ΑΘΡΟΙΣΜΑ =	165.788035
	B.T =	.200000 x	165.788035 =	33.157607
4300B	4300B			
221		2.000000 x	.099900 =	.199800
112		.400000 x	17.312112 =	6.924845
262		4.000000 x	.980000 =	3.920000
			B.T =	11.044645
601	601			
111		1.500000 x	15.741598 =	23.612397
			B.T =	23.612397
602	602			
403		.002500 x	660.655257 =	1.651638
			B.T =	1.651638
603	603			
111		.300000 x	15.741598 =	4.722479
401		.001000 x	905.783573 =	.905784
412		.003300 x	379.965890 =	1.253887
			B.T =	6.882150
604	604			
111		.200000 x	15.741598 =	3.148320
401		.001100 x	905.783573 =	.996362
412		.004000 x	379.965890 =	1.519864
404		.005000 x	442.918454 =	2.214592
			B.T =	7.879137

605	605				
112		.100000 x	17.312112 =		1.731211
402		.006200 x	882.536142 =		5.471724
406		.006200 x	405.604470 =		2.514748
412		.004000 x	379.965890 =		1.519864
401		.001000 x	905.783573 =		.905784
				B.T =	12.143330
606	606				
111		.100000 x	15.741598 =		1.574160
412		.005000 x	379.965890 =		1.899829
406		.006700 x	405.604470 =		2.717550
404		.005000 x	442.918454 =		2.214592
401		.001000 x	905.783573 =		.905784
				B.T =	9.311915
607	607				
111		.100000 x	15.741598 =		1.574160
412		.005000 x	379.965890 =		1.899829
406		.006700 x	405.604470 =		2.717550
404		.006200 x	442.918454 =		2.746094
401		.001400 x	905.783573 =		1.268097
				B.T =	10.205731
608	608				
111		.100000 x	15.741598 =		1.574160
404		.012500 x	442.918454 =		5.536481
401		.002000 x	905.783573 =		1.811567
412		.005000 x	379.965890 =		1.899829
406		.006700 x	405.604470 =		2.717550
				B.T =	13.539587
609	609				
214		.100000 x	1.949500 =		.194950
111		.800000 x	15.741598 =		12.593278
115		.200000 x	20.419486 =		4.083897
405		.005000 x	583.219432 =		2.916097
				B.T =	19.788223

610	610				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
412		.005000 x	379.965890 =	1.899829	
406		.005000 x	405.604470 =	2.028022	
405		.005000 x	583.219432 =	2.916097	
402		.010000 x	882.536142 =	8.825361	
115		.200000 x	20.419486 =	4.083897	
			B.T =	21.679369	
611	611				
214		.100000 x	1.949500 =	.194950	
112		.100000 x	17.312112 =	1.731211	
115		.200000 x	20.419486 =	4.083897	
406		.005000 x	405.604470 =	2.028022	
412		.005000 x	379.965890 =	1.899829	
405		.005000 x	583.219432 =	2.916097	
402		.014300 x	882.536142 =	12.620267	
			B.T =	25.474274	
612	612				
214		.150000 x	1.949500 =	.292425	
408		.010000 x	549.208066 =	5.492081	
115		.200000 x	20.419486 =	4.083897	
405		.005000 x	583.219432 =	2.916097	
111		.300000 x	15.741598 =	4.722479	
			AΘΡΟΙΣΜΑ =	17.506979	
	B.T =	1.068000 x	17.506979 =	18.697454	
613	613				
214		.150000 x	1.949500 =	.292425	
409		.010000 x	613.868266 =	6.138683	
405		.005000 x	583.219432 =	2.916097	
115		.200000 x	20.419486 =	4.083897	
111		.500000 x	15.741598 =	7.870799	
			AΘΡΟΙΣΜΑ =	21.301901	
	B.T =	1.282000 x	21.301901 =	27.309037	
614	614				
214		.150000 x	1.949500 =	.292425	
111		.500000 x	15.741598 =	7.870799	
115		.200000 x	20.419486 =	4.083897	
410		.010000 x	729.566266 =	7.295663	
405		.005000 x	583.219432 =	2.916097	
			AΘΡΟΙΣΜΑ =	22.458881	
	B.T =	1.602000 x	22.458881 =	35.979127	

615	615				
214		.150000 x	1.949500 =	.292425	
410		.010000 x	729.566266 =	7.295663	
111		.700000 x	15.741598 =	11.019119	
405		.005000 x	583.219432 =	2.916097	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	25.607201	
	B.T =	1.832000 x	25.607201 =	46.912392	
616	616				
214		.150000 x	1.949500 =	.292425	
111		.800000 x	15.741598 =	12.593278	
405		.005000 x	583.219432 =	2.916097	
411		.010000 x	1,011.771266 =	10.117713	
115		.200000 x	20.419486 =	4.083897	
			AΘΡΟΙΣΜΑ =	30.003410	
	B.T =	2.137000 x	30.003410 =	64.117288	
617	617				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	522.434000 =	522.434000	
503		1.000000 x	1,317.560200 =	1,317.560200	
			AΘΡΟΙΣΜΑ =	2,763.763896	
	B.T =	.006250 x	2,763.763896 =	17.273524	
618	618				
112		4.000000 x	17.312112 =	69.248448	
513		1.000000 x	854.521248 =	854.521248	
506		1.000000 x	522.434000 =	522.434000	
503		1.000000 x	1,317.560200 =	1,317.560200	
			AΘΡΟΙΣΜΑ =	2,763.763896	
	B.T =	.007700 x	2,763.763896 =	21.280982	
619	619				
112		4.000000 x	17.312112 =	69.248448	
503		1.000000 x	1,317.560200 =	1,317.560200	
506		1.000000 x	522.434000 =	522.434000	
513		1.000000 x	854.521248 =	854.521248	
			AΘΡΟΙΣΜΑ =	2,763.763896	
	B.T =	.010000 x	2,763.763896 =	27.637639	

620	620			
112		4.000000 x	17.312112 =	69.248448
513		1.000000 x	854.521248 =	854.521248
506		1.000000 x	522.434000 =	522.434000
503		1.000000 x	1,317.560200 =	1,317.560200

			ΑΘΡΟΙΣΜΑ =	2,763.763896
	B.T =	.012500 x	2,763.763896 =	34.547049

621	621			
112		4.000000 x	17.312112 =	69.248448
506		1.000000 x	522.434000 =	522.434000
503		1.000000 x	1,317.560200 =	1,317.560200
513		1.000000 x	854.521248 =	854.521248

			ΑΘΡΟΙΣΜΑ =	2,763.763896
	B.T =	.016600 x	2,763.763896 =	45.878481

630	630			
413		.020000 x	159.522679 =	3.190454

			B.T =	3.190454
701 1	701 1			
406		.012580 x	405.604470 =	5.102504

			B.T =	5.102504
701 2	701 2			
406		.011840 x	405.604470 =	4.802357

			B.T =	4.802357
701 3	701 3			
406		.011544 x	405.604470 =	4.682298

			B.T =	4.682298
701 4	701 4			
406		.011100 x	405.604470 =	4.502210

			B.T =	4.502210
701 5	701 5			
406		.007400 x	405.604470 =	3.001473

			B.T =	3.001473

702	702			
112		8.000000 x	17.312112 =	138.496896
506		1.000000 x	522.434000 =	522.434000
513		.300000 x	854.521248 =	256.356374
509		2.000000 x	175.675500 =	351.351000

			ΑΘΡΟΙΣΜΑ =	1,268.638270
	B.T =	.002500 x	1,268.638270 =	3.171596

703	703			
112		4.000000 x	17.312112 =	69.248448
503		1.000000 x	1,317.560200 =	1,317.560200
510		2.000000 x	180.946500 =	361.893000
506		1.000000 x	522.434000 =	522.434000
513		.300000 x	854.521248 =	256.356374

			ΑΘΡΟΙΣΜΑ =	2,527.492022
	B.T =	.002500 x	2,527.492022 =	6.318730

704	704			
112		4.000000 x	17.312112 =	69.248448
502		1.000000 x	1,244.685200 =	1,244.685200
513		.500000 x	854.521248 =	427.260624
506		1.000000 x	522.434000 =	522.434000

			ΑΘΡΟΙΣΜΑ =	2,263.628272
	B.T =	.005000 x	2,263.628272 =	11.318141

705	705			
112		4.000000 x	17.312112 =	69.248448
513		.600000 x	854.521248 =	512.712749
506		1.000000 x	522.434000 =	522.434000
504		1.000000 x	1,598.194400 =	1,598.194400

			ΑΘΡΟΙΣΜΑ =	2,702.589597
	B.T =	.004540 x	2,702.589597 =	12.269757

706	706			
501		1.000000 x	1,317.560200 =	1,317.560200
509		2.000000 x	175.675500 =	351.351000
506		1.000000 x	522.434000 =	522.434000

			ΑΘΡΟΙΣΜΑ =	2,191.345200
	B.T =	.002500 x	2,191.345200 =	5.478363

707	707			
505		1.000000 x	3,077.250000 =	3,077.250000
510		2.000000 x	180.946500 =	361.893000
506		1.000000 x	522.434000 =	522.434000

			ΑΘΡΟΙΣΜΑ =	3,961.577000
	B.T =	.001000 x	3,961.577000 =	3.961577

708	708			
708A		1.000000 x	17.338334 =	17.338334
708B		1.000000 x	5.478363 =	5.478363

			B.T =	22.816697
708A	708A			
214		.050000 x	1.949500 =	.097475
513		.010000 x	854.521248 =	8.545212
511		.010000 x	140.540400 =	1.405404
405		.012500 x	583.219432 =	7.290243

			B.T =	17.338334
708B	708B			
706		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
709	709			
709A		1.000000 x	16.412127 =	16.412127
709B		1.000000 x	5.478363 =	5.478363

			B.T =	21.890490
709A	709A			
506		1.000000 x	522.434000 =	522.434000
512		1.000000 x	790.536120 =	790.536120

			AΘΡΟΙΣΜΑ =	1,312.970120
	B.T =	.012500 x	1,312.970120 =	16.412127

709B	709B			
706		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
710	710			
710A		1.000000 x	49.797543 =	49.797543
710B		1.000000 x	5.478363 =	5.478363

			B.T =	55.275906
710A	710A			
214		.200000 x	1.949500 =	.389900
405		.025000 x	583.219432 =	14.580486
513		.035000 x	854.521248 =	29.908244
511		.035000 x	140.540400 =	4.918914

			B.T =	49.797543

710B	710B			
706		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
711	711			
711A		1.000000 x	43.721905 =	43.721905
711B		1.000000 x	5.478363 =	5.478363

			B.T =	49.200268
711A	711A			
506		1.000000 x	522.434000 =	522.434000
512		1.000000 x	790.536120 =	790.536120

			AΘΡΟΙΣΜΑ =	1,312.970120
	B.T =	.033300 x	1,312.970120 =	43.721905

711B	711B			
706		1.000000 x	5.478363 =	5.478363

			B.T =	5.478363
712	712			
513		1.000000 x	854.521248 =	854.521248

			AΘΡΟΙΣΜΑ =	854.521248
	B.T =	.004000 x	854.521248 =	3.418085

713 1	713 1			
704		.500000 x	11.318141 =	5.659071

			B.T =	5.659071
713 2	713 2			
705		.500000 x	12.269757 =	6.134879

			B.T =	6.134879
714	714			
714A		1.000000 x	3.442660 =	3.442660
714B		1.000000 x	3.773160 =	3.773160

			B.T =	7.215820

714A	714A			
242		.070000 x	370.000000 =	25.900000
114		2.000000 x	17.312112 =	34.624224
252		1.000000 x	2.020000 =	2.020000
113		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	103.383196
	B.T =	.033300 x	103.383196 =	3.442660
714B	714B			
113		.100000 x	20.419486 =	2.041949
114		.100000 x	17.312112 =	1.731211
			B.T =	3.773160
1111	1111			
1111A		1.000000 x	31.955522 =	31.955522
1111B		1.000000 x	5.478363 =	5.478363
			T.E =	37.433885
1112	1112			
1112A		1.000000 x	32.824253 =	32.824253
1112B		1.000000 x	5.478363 =	5.478363
			T.E =	38.302616
1113	1113			
1113A		1.000000 x	54.125571 =	54.125571
1113B		1.000000 x	5.478363 =	5.478363
			T.E =	59.603934
1114	1114			
1114A		1.000000 x	47.656042 =	47.656042
1114B		1.000000 x	5.478363 =	5.478363
			T.E =	53.134405
1121	1121			
1121A		1.000000 x	22.166557 =	22.166557
1121B		1.000000 x	5.478363 =	5.478363
			T.E =	27.644920
1122	1122			
1122A		1.000000 x	16.412127 =	16.412127
1122B		1.000000 x	5.478363 =	5.478363
			T.E =	21.890490

1123	1123				
1123A		1.000000 x	37.889214 =		37.889214
1123B		1.000000 x	5.478363 =		5.478363

			T.E =		43.367577
1124	1124				
1124A		1.000000 x	28.856219 =		28.856219
1124B		1.000000 x	5.478363 =		5.478363

			T.E =		34.334582
1210	1210				
707		1.000000 x	3.961577 =		3.961577

			T.E =		3.961577
1220	1220				
708		1.000000 x	22.816697 =		22.816697

			T.E =		22.816697
1230	1230				
709		1.000000 x	21.890490 =		21.890490

			T.E =		21.890490
1311	1311				
712		.250000 x	3.418085 =		.854521

			T.E =		.854521
1312	1312				
712		.250000 x	3.418085 =		.854521
701 1		1.000000 x	5.102504 =		5.102504
602		1.000000 x	1.651638 =		1.651638

			T.E =		7.608663
1313	1313				
712		.250000 x	3.418085 =		.854521
603		1.000000 x	6.882150 =		6.882150
701 2		1.000000 x	4.802357 =		4.802357

			T.E =		12.539028

1314	1314				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
712		.250000 x	3.418085 =	.854521	

			T.E =	37.428681	
1321	1321				
112		.200000 x	17.312112 =	3.462422	
701	1	1.000000 x	5.102504 =	5.102504	
602		1.000000 x	1.651638 =	1.651638	

			T.E =	10.216564	
1322	1322				
112		.200000 x	17.312112 =	3.462422	
603		1.000000 x	6.882150 =	6.882150	
701	2	1.000000 x	4.802357 =	4.802357	

			T.E =	15.146929	
1323	1323				
232		1.000000 x	35.000000 =	35.000000	
111		.100000 x	15.741598 =	1.574160	
112		.100000 x	17.312112 =	1.731211	

			T.E =	38.305371	
2110	2110				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.171596 =	3.171596	
608		1.000000 x	13.539587 =	13.539587	
701	4	1.000000 x	4.502210 =	4.502210	

			T.E =	22.922436	
2120	2120				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.171596 =	3.171596	
701	2	1.000000 x	4.802357 =	4.802357	
603		1.000000 x	6.882150 =	6.882150	

			T.E =	16.565146	
2130	2130				
712		.500000 x	3.418085 =	1.709043	
604		1.000000 x	7.879137 =	7.879137	
701	2	1.000000 x	4.802357 =	4.802357	
702		1.000000 x	3.171596 =	3.171596	

			T.E =	17.562133	

2140	2140				
712		.500000 x	3.418085 =	1.709043	
605		1.000000 x	12.143330 =	12.143330	
702		1.000000 x	3.171596 =	3.171596	
701	2	1.000000 x	4.802357 =	4.802357	

				T.E =	21.826326
2210	2210				
712		.500000 x	3.418085 =	1.709043	
609		1.050000 x	19.788223 =	20.777634	
702		1.000000 x	3.171596 =	3.171596	
701	2	1.000000 x	4.802357 =	4.802357	

				T.E =	30.460630
2220	2220				
712		.500000 x	3.418085 =	1.709043	
702		1.000000 x	3.171596 =	3.171596	
701	2	1.000000 x	4.802357 =	4.802357	
609		1.150000 x	19.788223 =	22.756456	

				T.E =	32.439452
2230	2230				
111		.200000 x	15.741598 =	3.148320	
609		1.200000 x	19.788223 =	23.745868	
701	2	1.000000 x	4.802357 =	4.802357	

				T.E =	31.696544
2240	2240				
111		.300000 x	15.741598 =	4.722479	
609		1.200000 x	19.788223 =	23.745868	
701	2	1.000000 x	4.802357 =	4.802357	

				T.E =	33.270704
2310	2310				
612		1.000000 x	18.697454 =	18.697454	
701	3	1.000000 x	4.682298 =	4.682298	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	29.698482
2320	2320				
613		1.000000 x	27.309037 =	27.309037	
703		1.000000 x	6.318730 =	6.318730	
701	3	1.000000 x	4.682298 =	4.682298	

				T.E =	38.310065

2330	2330				
614		1.000000 x	35.979127 =	35.979127	
703		1.000000 x	6.318730 =	6.318730	
701	3	1.000000 x	4.682298 =	4.682298	

				T.E =	46.980155
2340	2340				
615		1.000000 x	46.912392 =	46.912392	
703		1.000000 x	6.318730 =	6.318730	
701	3	1.000000 x	4.682298 =	4.682298	

				T.E =	57.913420
2350	2350				
616		1.000000 x	64.117288 =	64.117288	
703		1.000000 x	6.318730 =	6.318730	
701	3	1.000000 x	4.682298 =	4.682298	

				T.E =	75.118316
2410	2410				
617		1.000000 x	17.273524 =	17.273524	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	23.592254
2420	2420				
618		1.000000 x	21.280982 =	21.280982	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	27.599712
2430	2430				
619		1.000000 x	27.637639 =	27.637639	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	33.956369
2440	2440				
620		1.000000 x	34.547049 =	34.547049	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	40.865779
2450	2450				
621		1.000000 x	45.878481 =	45.878481	
703		1.000000 x	6.318730 =	6.318730	

				T.E =	52.197211

3110	1	3110	1			
	3110A 1			1.000000 x	130.184085 =	130.184085
	3110B			1.000000 x	16.977212 =	16.977212

					T.E =	147.161297
3110	2	3110	2			
	3110A 2			1.000000 x	137.668283 =	137.668283
	3110B			1.000000 x	16.977212 =	16.977212

					T.E =	154.645495
3110	3	3110	3			
	3110A 3			1.000000 x	139.837930 =	139.837930
	3110B			1.000000 x	16.977212 =	16.977212

					T.E =	156.815142
3110	4	3110	4			
	3110A 4			1.000000 x	147.322128 =	147.322128
	3110B			1.000000 x	16.977212 =	16.977212

					T.E =	164.299340
3120	1	3120	1			
	3120A 1			1.000000 x	130.184085 =	130.184085
	3120B			1.000000 x	18.404636 =	18.404636

					T.E =	148.588721
3120	2	3120	2			
	3120A 2			1.000000 x	137.668283 =	137.668283
	3120B			1.000000 x	18.404636 =	18.404636

					T.E =	156.072919
3120	3	3120	3			
	3120A 3			1.000000 x	139.837930 =	139.837930
	3120B			1.000000 x	18.404636 =	18.404636

					T.E =	158.242566
3120	4	3120	4			
	3120A 4			1.000000 x	147.322128 =	147.322128
	3120B			1.000000 x	18.404636 =	18.404636

					T.E =	165.726764

3210 1	3210 1				
3210A 1		1.000000 x	119.536628 =		119.536628
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		136.513840
3210 2	3210 2				
3210A 2		1.000000 x	125.523987 =		125.523987
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		142.501199
3210 3	3210 3				
3210A 3		1.000000 x	127.259704 =		127.259704
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		144.236916
3210 4	3210 4				
3210A 4		1.000000 x	133.247063 =		133.247063
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		150.224275
3210 5	3210 5				
3210A 5		1.000000 x	118.312893 =		118.312893
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		135.290105
3210 6	3210 6				
3210A 6		1.000000 x	124.300251 =		124.300251
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		141.277463
3210 7	3210 7				
3210A 7		1.000000 x	126.035969 =		126.035969
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		143.013181
3210 8	3210 8				
3210A 8		1.000000 x	132.023327 =		132.023327
3210B		1.000000 x	16.977212 =		16.977212

			T.E =		149.000539

3220	1	3220	1			
	3220A 1			1.000000 x	119.536628 =	119.536628
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	137.941264
3220	2	3220	2			
	3220A 2			1.000000 x	125.523987 =	125.523987
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	143.928623
3220	3	3220	3			
	3220A 3			1.000000 x	127.259704 =	127.259704
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	145.664340
3220	4	3220	4			
	3220A 4			1.000000 x	133.247063 =	133.247063
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	151.651699
3220	5	3220	5			
	3220A 5			1.000000 x	118.312893 =	118.312893
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	136.717529
3220	6	3220	6			
	3220A 6			1.000000 x	124.300251 =	124.300251
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	142.704887
3220	7	3220	7			
	3220A 7			1.000000 x	126.035969 =	126.035969
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	144.440605
3220	8	3220	8			
	3220A 8			1.000000 x	132.023327 =	132.023327
	3220B			1.000000 x	18.404636 =	18.404636

					T.E =	150.427963

3300	1	3300	1			
	3300A	1		1.000000 x	182.330238 =	182.330238
	3300B	1		1.000000 x	16.977212 =	16.977212

					T.E =	199.307450
3300	2	3300	2			
	3300A	1		1.000000 x	182.330238 =	182.330238
	3300B	2		1.000000 x	18.404636 =	18.404636

					T.E =	200.734874
3300	3	3300	3			
	3300A	2		1.000000 x	189.814436 =	189.814436
	3300B	1		1.000000 x	16.977212 =	16.977212

					T.E =	206.791648
3300	4	3300	4			
	3300A	2		1.000000 x	189.814436 =	189.814436
	3300B	2		1.000000 x	18.404636 =	18.404636

					T.E =	208.219072
3300	5	3300	5			
	3300A	3		1.000000 x	191.984083 =	191.984083
	3300B	1		1.000000 x	16.977212 =	16.977212

					T.E =	208.961295
3300	6	3300	6			
	3300A	3		1.000000 x	191.984083 =	191.984083
	3300B	2		1.000000 x	18.404636 =	18.404636

					T.E =	210.388719
3300	7	3300	7			
	3300A	4		1.000000 x	199.468281 =	199.468281
	3300B	1		1.000000 x	16.977212 =	16.977212

					T.E =	216.445493
3300	8	3300	8			
	3300A	4		1.000000 x	199.468281 =	199.468281
	3300B	2		1.000000 x	18.404636 =	18.404636

					T.E =	217.872917

3400 1	3400 1				
3400A 1		1.000000 x	195.712561 =	195.712561	
3400B 1		1.000000 x	11.318141 =	11.318141	

			T.E =	207.030702	
3400 2	3400 2				
3400A 1		1.000000 x	195.712561 =	195.712561	
3400B 2		1.000000 x	12.269757 =	12.269757	

			T.E =	207.982318	
3400 3	3400 3				
3400A 2		1.000000 x	203.196759 =	203.196759	
3400B 1		1.000000 x	11.318141 =	11.318141	

			T.E =	214.514900	
3400 4	3400 4				
3400A 2		1.000000 x	203.196759 =	203.196759	
3400B 2		1.000000 x	12.269757 =	12.269757	

			T.E =	215.466516	
3400 5	3400 5				
3400A 3		1.000000 x	205.366406 =	205.366406	
3400B 1		1.000000 x	11.318141 =	11.318141	

			T.E =	216.684547	
3400 6	3400 6				
3400A 3		1.000000 x	205.366406 =	205.366406	
3400B 2		1.000000 x	12.269757 =	12.269757	

			T.E =	217.636163	
3400 7	3400 7				
3400A 4		1.000000 x	212.850604 =	212.850604	
3400B 1		1.000000 x	11.318141 =	11.318141	

			T.E =	224.168745	
3400 8	3400 8				
3400A 4		1.000000 x	212.850604 =	212.850604	
3400B 2		1.000000 x	12.269757 =	12.269757	

			T.E =	225.120361	

4110	1	4110	1			
	4110A 1			1.000000 x	198.824633 =	198.824633
	4110B			.025000 x	1,639.761644 =	40.994041

					T.E =	239.818674
4110	2	4110	2			
	4110A 2			1.000000 x	206.308831 =	206.308831
	4110B			.025000 x	1,639.761644 =	40.994041

					T.E =	247.302872
4110	3	4110	3			
	4110A 3			1.000000 x	208.478479 =	208.478479
	4110B			.025000 x	1,639.761644 =	40.994041

					T.E =	249.472520
4110	4	4110	4			
	4110A 4			1.000000 x	215.962677 =	215.962677
	4110B			.025000 x	1,639.761644 =	40.994041

					T.E =	256.956718
4120	1	4120	1			
	4120A 1			1.000000 x	162.215266 =	162.215266
	4120B			1.000000 x	65.590466 =	65.590466

					T.E =	227.805732
4120	2	4120	2			
	4120A 2			1.000000 x	180.177341 =	180.177341
	4120B			1.000000 x	65.590466 =	65.590466

					T.E =	245.767807
4130	1	4130	1			
	4130A 1			1.000000 x	144.244627 =	144.244627
	4130B			1.000000 x	65.590466 =	65.590466

					T.E =	209.835093
4130	2	4130	2			
	4130A 2			1.000000 x	151.728825 =	151.728825
	4130B			1.000000 x	65.590466 =	65.590466

					T.E =	217.319291

4130	3	4130	3				
4130A	3			1.000000 x	153.898473 =	153.898473	
4130B				1.000000 x	65.590466 =	65.590466	

						T.E =	219.488939
4130	4	4130	4				
4130A	4			1.000000 x	161.382671 =	161.382671	
4130B				1.000000 x	65.590466 =	65.590466	

						T.E =	226.973137
4210	1	4210	1				
4210A	1			1.000000 x	42.460207 =	42.460207	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	185.905904
4210	2	4210	2				
4210A	2			1.000000 x	46.950726 =	46.950726	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	190.396423
4210	3	4210	3				
4210A	3			1.000000 x	38.444824 =	38.444824	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	181.890521
4210	4	4210	4				
4210A	4			1.000000 x	42.935343 =	42.935343	
4210B				1.000000 x	143.445697 =	143.445697	

						T.E =	186.381040
4220B	1	4220B	1				
319				.020000 x	21.440000 =	.428800	
701	2			.320000 x	4.802357 =	1.536754	
601				.320000 x	23.612397 =	7.555967	
4220A	1			.800000 x	108.689623 =	86.951698	
714				1.150000 x	7.215820 =	8.298193	
111				.400000 x	15.741598 =	6.296639	

						T.E =	111.068052

4220B 2	4220B 2			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.215820 =	8.298193
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967
4220A 2		.800000 x	116.173821 =	92.939057

T.E = 117.055410

4220B 3	4220B 3			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	118.343468 =	94.674774
714		1.150000 x	7.215820 =	8.298193

T.E = 118.791128

4220B 4	4220B 4			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	125.827666 =	100.662133
701 2		.320000 x	4.802357 =	1.536754
601		.320000 x	23.612397 =	7.555967
714		1.150000 x	7.215820 =	8.298193

T.E = 124.778486

4220B 5	4220B 5			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
4220A 1		.800000 x	108.689623 =	86.951698
714		1.150000 x	7.215820 =	8.298193
111		.400000 x	15.741598 =	6.296639

T.E = 109.844316

4220B 6	4220B 6			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
714		1.150000 x	7.215820 =	8.298193
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
4220A 2		.800000 x	116.173821 =	92.939057

T.E = 115.831675

4220B 7	4220B 7			
319		.020000 x	21.440000 =	.428800
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
111		.400000 x	15.741598 =	6.296639
4220A 3		.800000 x	118.343468 =	94.674774
714		1.150000 x	7.215820 =	8.298193

T.E = 117.567392

4220B 8	4220B 8			
319		.020000 x	21.440000 =	.428800
111		.400000 x	15.741598 =	6.296639
4220A 4		.800000 x	125.827666 =	100.662133
701 2		.320000 x	4.802357 =	1.536754
609		.320000 x	19.788223 =	6.332231
714		1.150000 x	7.215820 =	8.298193

T.E = 123.554751

4230 1	4230 1			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.001473 =	.750368
701 2		.500000 x	4.802357 =	2.401179
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
607		.500000 x	10.205731 =	5.102866
606		.800000 x	9.311915 =	7.449532
407		.040000 x	726.419395 =	29.056776
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383
111		2.000000 x	15.741598 =	31.483196
319		.020000 x	21.440000 =	.428800

T.E = 139.088791

4230 2	4230 2			
221		250.000000 x	.099900 =	24.975000
701 5		.250000 x	3.001473 =	.750368
701 4		.500000 x	4.502210 =	2.251105
701 2		.800000 x	4.802357 =	3.841886
630		.250000 x	3.190454 =	.797614
319		.020000 x	21.440000 =	.428800
111		2.000000 x	15.741598 =	31.483196
407		.040000 x	726.419395 =	29.056776
611		.500000 x	25.474274 =	12.737137
606		.800000 x	9.311915 =	7.449532
714		1.150000 x	7.215820 =	8.298193
113		1.200000 x	20.419486 =	24.503383

T.E = 146.572989

4230	3	4230	3			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	3.001473 =	.750368
701	4			.800000 x	4.502210 =	3.601768
701	2			.500000 x	4.802357 =	2.401179
630				.250000 x	3.190454 =	.797614
610				.800000 x	21.679369 =	17.343495
607				.500000 x	10.205731 =	5.102866
407				.040000 x	726.419395 =	29.056776
714				1.150000 x	7.215820 =	8.298193
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196

T.E = 148.742637

4230	4	4230	4			
221				250.000000 x	.099900 =	24.975000
701	5			.250000 x	3.001473 =	.750368
701	4			.500000 x	4.502210 =	2.251105
701	4			.800000 x	4.502210 =	3.601768
630				.250000 x	3.190454 =	.797614
319				.020000 x	21.440000 =	.428800
113				1.200000 x	20.419486 =	24.503383
407				.040000 x	726.419395 =	29.056776
611				.500000 x	25.474274 =	12.737137
610				.800000 x	21.679369 =	17.343495
714				1.150000 x	7.215820 =	8.298193
111				2.000000 x	15.741598 =	31.483196

T.E = 156.226835

4240	1	4240	1			
221				300.000000 x	.099900 =	29.970000
701	5			.250000 x	3.001473 =	.750368
701	2			.500000 x	4.802357 =	2.401179
701	2			.800000 x	4.802357 =	3.841886
630				.250000 x	3.190454 =	.797614
607				.500000 x	10.205731 =	5.102866
606				.800000 x	9.311915 =	7.449532
407				.040000 x	726.419395 =	29.056776
714				1.150000 x	7.215820 =	8.298193
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	21.440000 =	.428800

T.E = 144.083791

4240	2	4240	2			
221				300.000000 x	.099900 =	29.970000
606				.800000 x	9.311915 =	7.449532
701	5			.250000 x	3.001473 =	.750368
701	4			.500000 x	4.502210 =	2.251105
701	2			.800000 x	4.802357 =	3.841886
630				.250000 x	3.190454 =	.797614
611				.500000 x	25.474274 =	12.737137
407				.040000 x	726.419395 =	29.056776
714				1.150000 x	7.215820 =	8.298193
113				1.200000 x	20.419486 =	24.503383
111				2.000000 x	15.741598 =	31.483196
319				.020000 x	21.440000 =	.428800

T.E = 151.567989

4240	3	4240	3			
221				300.000000 x	.099900 =	29.970000
319				.020000 x	21.440000 =	.428800
111				2.000000 x	15.741598 =	31.483196
701	5			.250000 x	3.001473 =	.750368
701	4			.800000 x	4.502210 =	3.601768
701	2			.500000 x	4.802357 =	2.401179
630				.250000 x	3.190454 =	.797614
610				.800000 x	21.679369 =	17.343495
607				.500000 x	10.205731 =	5.102866
407				.040000 x	726.419395 =	29.056776
714				1.150000 x	7.215820 =	8.298193
113				1.200000 x	20.419486 =	24.503383

T.E = 153.737637

4240	4	4240	4			
221				300.000000 x	.099900 =	29.970000
630				.250000 x	3.190454 =	.797614
701	5			.250000 x	3.001473 =	.750368
701	4			.500000 x	4.502210 =	2.251105
701	4			.800000 x	4.502210 =	3.601768
611				.500000 x	25.474274 =	12.737137
610				.800000 x	21.679369 =	17.343495
407				.040000 x	726.419395 =	29.056776
111				2.000000 x	15.741598 =	31.483196
714				1.150000 x	7.215820 =	8.298193
113				1.200000 x	20.419486 =	24.503383
319				.020000 x	21.440000 =	.428800

T.E = 161.221835

4300	1	4300	1			
4300A	1			1.000000 x	29.729998 =	29.729998
4300B				1.000000 x	11.044645 =	11.044645

T.E = 40.774643

4300	2	4300	2			
	4300A	2		1.000000 x	31.226838 =	31.226838
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.271483
4300	3	4300	3			
	4300A	3		1.000000 x	31.660767 =	31.660767
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	42.705412
4300	4	4300	4			
	4300A	4		1.000000 x	33.157607 =	33.157607
	4300B			1.000000 x	11.044645 =	11.044645

					T.E =	44.202252
4400		4400				
	251			1.050000 x	.556800 =	.584640
	113			.050000 x	20.419486 =	1.020974

					T.E =	1.605614
4500		4500				
	251			1.050000 x	.556800 =	.584640
	114			.100000 x	17.312112 =	1.731211
	113			.100000 x	20.419486 =	2.041949

					T.E =	4.357800
4600		4600				
	256			1.000000 x	3.930000 =	3.930000
	113			.100000 x	20.419486 =	2.041949

					T.E =	5.971949
4700		4700				
	253			1.000000 x	4.150000 =	4.150000
	113			.100000 x	20.419486 =	2.041949

					T.E =	6.191949