

ΑΤΟΕ

Αναλυτικά Τιμολόγια Οικοδομικών Έργων

4ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

001	15.741598
002	17.312112
003	20.419486
004	23.886192
005	21.778427
006	183.150721
007	183.150721
009	.074800
011	53.630000
012	4.400000
013	26.580000
014	260.720000
015	200.790000
016	31.630000
017	369.270000
018.1	2.900000
018.2	4.400000
019.1	2.900000
019.2	4.400000
021	2.670000
022	.070000
024	50.000000
026	.099900
027	.119300
029	.152800
032	36.000000
035	.086500
036	.088800
040	.203400
051	15.400000
052	15.400000
053	.085000
054	.085000
055	.090000
056	10.580000
057	10.580000
058	9.090000
061	13.560000
062	13.560000
065	13.610000
066	35.000000
067	45.500000
081	11.010000
101	
102	
111	.075900
112	.083300
113	.570000
114	
116	.086700
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.650000
132	.930000
142	.350000
146	.380000

155	2.481600
161	6.700000
163	6.900000
164	
165	
166	
173	.255300
181	
201	290.000000
203.2	370.000000
203.4	290.000000
205	450.000000
208	1,450.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,500.000000
223.4	1,580.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	2.000000
237	1.100000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.600000
246	12.000000
249	20.000000
251	.825000
252	2.020000
253	2.550000
254	3.363800
258	7.777500
259	25.040000
260	.538600
261	.591400
262	.538600
264	1.116300
265	.869000
266	.633000
267	.917500

268	1.079000
271	1.046500
272	.939000
273	1.202500
274	1.483200
276	.840700
277	1.056500
278	3.600000
279	3.720000
280	1.000000
281	5.780000
282	1.011500
283	1.148200
284	
285	.065700
286	1.737300
288	1.885600
289	.828600
290	3.300000
291	5.000000
293	
294	3.518600
295	6.185800
296	12.370900
297.2	
298.1	6.130000
298.2	5.300000
321	
322	110.690000
323	126.500000
326	63.530000
327.1	
327.2	
327.3	196.650000
328	
331	85.390000
332	88.540000
333	123.970000
334	132.830000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.668400
352	1.030000
354	.895800
356	.601500
357	1.310300
358	3.035000
360	13.580000
361	1.136300
362	1.270000
363	1.617600
364	1.030000
366	4.545900
370	.267400
371	1.617600
372	2.246200

373	2.486800
375	3.155400
376	.200400
377	.842200
378	13.590000
379	26.780000
380	16.150000
381	67.970000
386	28.630000
388	48.870000
390	1.500000
392	24.930000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.075500
442	.118300
443	1.930000
444	2.143200
445	1.553500
446	2.540000
447	4.393700
450	2.760000
451	1.178800
453	.085000
455	3.000000
456	1.610000
457	.803800
458	5.030000
459	5.030000
460	4.250000
462	
463	3.970000
464	3.720000
465	5.870000
467	3.380000
471	4.100000
473	2.750000
474	3.770000
475	6.230000
476	2.366400
477	
478	2.937600
479	1.815600
480	3.366000
481	5.467500

482	1.291000
483	.167500
484	3.930000
485	1.056100
487	13.480000
488	5.500000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	1.905500
498	1.011600
499	1.386800
500	2.039600
501	2.763000
502	3.807000
503	.905500
504	1.199100
505	19.170000
506	1.290700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.375000
514	38.800000
515	41.230000
519	47.670000
520	37.340000
521	2.390000
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	6.000000
536	2.500000
537	1.700000
565.3	3.450000
565.5	5.150000
565.6	7.100000
566.3	4.600000
566.5	7.050000
566.6	9.400000

1101	1101				
001		.500000 x	15.741598 =		7.870799

			B.T =		7.870799
1102	1102				
001		1.000000 x	15.741598 =		15.741598

			B.T =		15.741598
1103	1103				
001		.300000 x	15.741598 =		4.722479

			B.T =		4.722479
1104	1104				
015		1.000000 x	200.790000 =		200.790000
291		2.200000 x	5.000000 =		11.000000
004		7.000000 x	23.886192 =		167.203344
002		7.000000 x	17.312112 =		121.184784
484		5.250000 x	3.930000 =		20.632500
485		83.000000 x	1.056100 =		87.656300

			AΘΡΟΙΣΜΑ =		608.466928
	B.T =	.004000 x	608.466928 =		2.433868

1111	1111				
006		.060000 x	183.150721 =		10.989043

			B.T =		10.989043
1112	1112				
006		.090000 x	183.150721 =		16.483565

			B.T =		16.483565
1116	1116				
007		.025000 x	183.150721 =		4.578768

			B.T =		4.578768
1117	1117				
007		.110000 x	183.150721 =		20.146579

			B.T =		20.146579
1121	1121				
009		4.000000 x	.074800 =		.299200

			B.T =		.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.741598 =	6.296639

			B.T =	6.296639
1127	1127			
001		.130000 x	15.741598 =	2.046408

			B.T =	2.046408
1128	1128			
006		.024000 x	183.150721 =	4.395617

			B.T =	4.395617
1131	1131			
007		.090000 x	183.150721 =	16.483565

			B.T =	16.483565
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.203400 =	233.910000

			B.T =	234.711000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	15.400000 =	14.784000
1407		.320000 x	37.605000 =	12.033600

			B.T =	27.351600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	15.400000 =	13.860000
1407		.360000 x	37.605000 =	13.537800

			B.T =	27.931800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	15.400000 =	12.936000
1407		.420000 x	37.605000 =	15.794100

			B.T =	29.264100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	15.400000 =	14.784000
026		150.000000 x	.099900 =	14.985000

			B.T =	39.704250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	15.400000 =	13.860000

			B.T =	40.284450

1418	1418			
021		.200000 x	2.670000 =	.534000
1407		.350000 x	37.605000 =	13.161750
051		.840000 x	15.400000 =	12.936000
026		150.000000 x	.099900 =	14.985000

			B.T =	41.616750
1421	1421			
021		.200000 x	2.670000 =	.534000
051		.540000 x	15.400000 =	8.316000
1407		.540000 x	37.605000 =	20.306700
039		4.000000 x	.000000 =	.000000

			B.T =	
1422	1422			
021		.250000 x	2.670000 =	.667500
035		75.000000 x	.086500 =	6.487500
1407		.620000 x	37.605000 =	23.315100
051		.330000 x	15.400000 =	5.082000
039		5.000000 x	.000000 =	.000000

			B.T =	
1426	1426			
021		.200000 x	2.670000 =	.534000
1407		.450000 x	37.605000 =	16.922250
055		1,500.000000 x	.090000 =	135.000000

			B.T =	152.456250
1427	1427			
021		.200000 x	2.670000 =	.534000
1407		.340000 x	37.605000 =	12.785700
055		1,500.000000 x	.090000 =	135.000000
026		150.000000 x	.099900 =	14.985000

			B.T =	163.304700
1428	1428			
021		.200000 x	2.670000 =	.534000
051		.200000 x	15.400000 =	3.080000
055		1,200.000000 x	.090000 =	108.000000
1407		.400000 x	37.605000 =	15.042000

			B.T =	126.656000

1429	1429				
021		.200000 x	2.670000 =	.534000	
035		200.000000 x	.086500 =	17.300000	
055		1,200.000000 x	.090000 =	108.000000	
1407		.400000 x	37.605000 =	15.042000	

			B.T =	140.876000	
1431	1431				
021		.300000 x	2.670000 =	.801000	
032		.960000 x	36.000000 =	34.560000	
1407		.320000 x	37.605000 =	12.033600	

			B.T =	47.394600	
1432	1432				
021		.300000 x	2.670000 =	.801000	
1407		.320000 x	37.605000 =	12.033600	
051		.640000 x	15.400000 =	9.856000	
032		.320000 x	36.000000 =	11.520000	

			B.T =	34.210600	
1436	1436				
021		.350000 x	2.670000 =	.934500	
035		1,100.000000 x	.086500 =	95.150000	

			B.T =	96.084500	
1437	1437				
021		.200000 x	2.670000 =	.534000	
035		75.000000 x	.086500 =	6.487500	
051		.380000 x	15.400000 =	5.852000	
1407		.620000 x	37.605000 =	23.315100	

			B.T =	36.188600	
1441	1441				
021		.800000 x	2.670000 =	2.136000	
026		250.000000 x	.099900 =	24.975000	

			B.T =	27.111000	
1442	1442				
021		.250000 x	2.670000 =	.667500	
051		.740000 x	15.400000 =	11.396000	
026		900.000000 x	.099900 =	89.910000	

			B.T =	101.973500	

1443	1443				
021		.250000 x	2.670000 =	.667500	
051		.860000 x	15.400000 =	13.244000	
026		700.000000 x	.099900 =	69.930000	

			B.T =	83.841500	
1444	1444				
021		.250000 x	2.670000 =	.667500	
026		600.000000 x	.099900 =	59.940000	
051		1.000000 x	15.400000 =	15.400000	

			B.T =	76.007500	
1445	1445				
021		.250000 x	2.670000 =	.667500	
026		450.000000 x	.099900 =	44.955000	
051		1.060000 x	15.400000 =	16.324000	

			B.T =	61.946500	
1446	1446				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
051		1.120000 x	15.400000 =	17.248000	

			B.T =	52.880500	
1447	1447				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
026		400.000000 x	.099900 =	39.960000	

			B.T =	59.035900	
1448	1448				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	15.400000 =	15.400000	
039		5.000000 x	.000000 =	.000000	
026		400.000000 x	.099900 =	39.960000	

			B.T =		
1449	1449				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
1407		.040000 x	37.605000 =	1.504200	
051		1.060000 x	15.400000 =	16.324000	

			B.T =	53.460700	

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.152800 =	91.680000

			B.T =	221.727750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
026		450.000000 x	.099900 =	44.955000

			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.152800 =	68.760000
053		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250

			B.T =	211.557750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000

			B.T =	
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750

1457	1457			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000
029		600.000000 x	.152800 =	91.680000

			B.T =	221.727750
1458	1458			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
054		1,650.000000 x	.085000 =	140.250000
028		450.000000 x	.000000 =	.000000

			B.T =	
1459	1459			
021		.250000 x	2.670000 =	.667500
054		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250
029		450.000000 x	.152800 =	68.760000

			B.T =	211.557750
1461	1461			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
1407		.080000 x	37.605000 =	3.008400
026		500.000000 x	.099900 =	49.950000

			B.T =	181.125900
1462	1462			
021		.300000 x	2.670000 =	.801000
1407		.050000 x	37.605000 =	1.880250
515		1.000000 x	41.230000 =	41.230000
051		.100000 x	15.400000 =	1.540000
026		400.000000 x	.099900 =	39.960000

			B.T =	85.411250
1463	1463			
021		.300000 x	2.670000 =	.801000
051		.100000 x	15.400000 =	1.540000
1407		.050000 x	37.605000 =	1.880250
515		1.050000 x	41.230000 =	43.291500
026		250.000000 x	.099900 =	24.975000

			B.T =	72.487750

1464	1464				
021		.200000 x	2.670000 =	.534000	
519		.600000 x	47.670000 =	28.602000	
1407		.120000 x	37.605000 =	4.512600	
051		.420000 x	15.400000 =	6.468000	
026		150.000000 x	.099900 =	14.985000	

			B.T =	55.101600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	47.670000 =	42.903000	
051		.150000 x	15.400000 =	2.310000	
026		450.000000 x	.099900 =	44.955000	

			B.T =	91.830150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	47.670000 =	40.042800	
026		450.000000 x	.099900 =	44.955000	
051		.210000 x	15.400000 =	3.234000	

			B.T =	89.893950	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.099900 =	44.955000	
051		.350000 x	15.400000 =	5.390000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	47.670000 =	33.369000	

			B.T =	85.376150	
1471	1471				
251		1.000000 x	.825000 =	.825000	
351		4.000000 x	.668400 =	2.673600	
358		1.000000 x	3.035000 =	3.035000	
364		2.000000 x	1.030000 =	2.060000	
372		.400000 x	2.246200 =	.898480	
370		6.000000 x	.267400 =	1.604400	

			ΑΘΡΟΙΣΜΑ =	11.096480	
	B.T =	.476190 x	11.096480 =	5.284033	

1472	1472			
251		.600000 x	.825000 =	.495000
351		2.000000 x	.668400 =	1.336800
361		1.000000 x	1.136300 =	1.136300
363		2.000000 x	1.617600 =	3.235200
372		.300000 x	2.246200 =	.673860
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	9.550760
	B.T =	.666667 x	9.550760 =	6.367177
1473	1473			
251		.500000 x	.825000 =	.412500
354		4.000000 x	.895800 =	3.583200
364		2.000000 x	1.030000 =	2.060000
372		.700000 x	2.246200 =	1.572340
370		4.000000 x	.267400 =	1.069600
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
351		4.000000 x	.668400 =	2.673600
			AΘΡΟΙΣΜΑ =	26.087540
	B.T =	.416667 x	26.087540 =	10.869817
1474	1474			
251		.500000 x	.825000 =	.412500
372		.500000 x	2.246200 =	1.123100
370		4.000000 x	.267400 =	1.069600
366		2.000000 x	4.545900 =	9.091800
361		1.000000 x	1.136300 =	1.136300
360		1.000000 x	13.580000 =	13.580000
357		4.000000 x	1.310300 =	5.241200
			AΘΡΟΙΣΜΑ =	31.654500
	B.T =	.416667 x	31.654500 =	13.189386
1475	1475			
251		.300000 x	.825000 =	.247500
379		1.000000 x	26.780000 =	26.780000
371		2.000000 x	1.617600 =	3.235200
376		160.000000 x	.200400 =	32.064000
377		6.000000 x	.842200 =	5.053200
378		1.000000 x	13.590000 =	13.590000
375		2.000000 x	3.155400 =	6.310800
354		3.000000 x	.895800 =	2.687400
			AΘΡΟΙΣΜΑ =	89.968100
	B.T =	.416667 x	89.968100 =	37.486738

1476	1476			
251		.500000 x	.825000 =	.412500
373		.200000 x	2.486800 =	.497360
370		6.000000 x	.267400 =	1.604400
352		3.000000 x	1.030000 =	3.090000

			ΑΘΡΟΙΣΜΑ =	5.604260
	B.T =	.500000 x	5.604260 =	2.802130

1478	1478			
251		3.000000 x	.825000 =	2.475000
372		.500000 x	2.246200 =	1.123100
356		2.000000 x	.601500 =	1.203000
370		6.000000 x	.267400 =	1.604400

			ΑΘΡΟΙΣΜΑ =	6.405500
	B.T =	.500000 x	6.405500 =	3.202750

1479	1479			
251		6.000000 x	.825000 =	4.950000
370		12.000000 x	.267400 =	3.208800
381		1.000000 x	67.970000 =	67.970000

			ΑΘΡΟΙΣΜΑ =	76.128800
	B.T =	.454545 x	76.128800 =	34.603965

1480	1480			
251		8.000000 x	.825000 =	6.600000
381		2.000000 x	67.970000 =	135.940000
370		16.000000 x	.267400 =	4.278400

			ΑΘΡΟΙΣΜΑ =	146.818400
	B.T =	.227273 x	146.818400 =	33.367858

1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.085000 =	.019550
487		.040000 x	13.480000 =	.539200
451		.230000 x	1.178800 =	.271124

			B.T =	.831209
1487	1487			
443		.120000 x	1.930000 =	.231600
451		.170000 x	1.178800 =	.200396
453		.640000 x	.085000 =	.054400
446		.010000 x	2.540000 =	.025400
445		.060000 x	1.553500 =	.093210

			B.T =	.605006

1488	1488			
444		.170000 x	2.143200 =	.364344
453		.500000 x	.085000 =	.042500
451		.170000 x	1.178800 =	.200396
446		.030000 x	2.540000 =	.076200
445		.050000 x	1.553500 =	.077675

			B.T =	.761115
1489	1489			
444		.100000 x	2.143200 =	.214320
453		.430000 x	.085000 =	.036550
451		.350000 x	1.178800 =	.412580
446		.020000 x	2.540000 =	.050800
445		.100000 x	1.553500 =	.155350

			B.T =	.869600
1490	1490			
444		.300000 x	2.143200 =	.642960
445		.100000 x	1.553500 =	.155350
446		.030000 x	2.540000 =	.076200
451		.570000 x	1.178800 =	.671916

			B.T =	1.546426
1491	1491			
444		.270000 x	2.143200 =	.578664
445		.060000 x	1.553500 =	.093210
451		.650000 x	1.178800 =	.766220
446		.020000 x	2.540000 =	.050800

			B.T =	1.488894
1492	1492			
444		.200000 x	2.143200 =	.428640
446		.030000 x	2.540000 =	.076200
445		.040000 x	1.553500 =	.062140
455		.730000 x	3.000000 =	2.190000

			B.T =	2.756980
1501	1501			
011		1.000000 x	53.630000 =	53.630000
012		2.000000 x	4.400000 =	8.800000
005		3.500000 x	21.778427 =	76.224495
005		14.000000 x	21.778427 =	304.897978
485		15.000000 x	1.056100 =	15.841500
484		1.750000 x	3.930000 =	6.877500

			B.T =	466.271473

1502	1502				
013		1.000000 x	26.580000 =	26.580000	
005		3.500000 x	21.778427 =	76.224495	
001		26.000000 x	15.741598 =	409.281548	
482		15.000000 x	1.291000 =	19.365000	
484		.900000 x	3.930000 =	3.537000	

			B.T =	534.988043	
1503	1503				
014		1.000000 x	260.720000 =	260.720000	
002		2.600000 x	17.312112 =	45.011491	
004		7.000000 x	23.886192 =	167.203344	
484		2.600000 x	3.930000 =	10.218000	
485		44.000000 x	1.056100 =	46.468400	

			B.T =	529.621235	
1504	1504				
015		1.000000 x	200.790000 =	200.790000	
004		7.000000 x	23.886192 =	167.203344	
002		7.000000 x	17.312112 =	121.184784	
485		83.000000 x	1.056100 =	87.656300	
484		5.250000 x	3.930000 =	20.632500	
291		2.200000 x	5.000000 =	11.000000	

			B.T =	608.466928	
1505	1505				
016		1.000000 x	31.630000 =	31.630000	
004		7.000000 x	23.886192 =	167.203344	
002		1.750000 x	17.312112 =	30.296196	
485		17.500000 x	1.056100 =	18.481750	
484		1.750000 x	3.930000 =	6.877500	

			B.T =	254.488790	
1506	1506				
017		1.000000 x	369.270000 =	369.270000	
002		3.500000 x	17.312112 =	60.592392	
484		6.000000 x	3.930000 =	23.580000	
004		7.000000 x	23.886192 =	167.203344	
485		70.000000 x	1.056100 =	73.927000	

			B.T =	694.572736	
2101	2101				
002		.300000 x	17.312112 =	5.193634	

			T.E =	5.193634	

2102	2102			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2103	2103			
002		.400000 x	17.312112 =	6.924845

			T.E =	6.924845
2104A	2104A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2104B	2104B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2104E	2104E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2104H	2104H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2104Z	2104Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2104Γ	2104Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2104Δ	2104Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2104ΣΤ	2104ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181

2105A	2105A			
002		.900000 x	17.312112 =	15.580901

			T.E =	15.580901
2105B	2105B			
002		1.400000 x	17.312112 =	24.236957

			T.E =	24.236957
2105E	2105E			
002		2.900000 x	17.312112 =	50.205125

			T.E =	50.205125
2105H	2105H			
002		4.400000 x	17.312112 =	76.173293

			T.E =	76.173293
2105Z	2105Z			
002		3.900000 x	17.312112 =	67.517237

			T.E =	67.517237
2105Γ	2105Γ			
002		1.900000 x	17.312112 =	32.893013

			T.E =	32.893013
2105Δ	2105Δ			
002		2.400000 x	17.312112 =	41.549069

			T.E =	41.549069
2105ΣΤ	2105ΣΤ			
002		3.400000 x	17.312112 =	58.861181

			T.E =	58.861181
2106A	2106A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2106B	2106B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2106E	2106E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2106H	2106H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2106I	2106I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2106Z	2106Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2106Γ	2106Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2106Δ	2106Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2106Θ	2106Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2106ΣΤ	2106ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2107A	2107A			
002		5.900000 x	17.312112 =	102.141461

			T.E =	102.141461
2107B	2107B			
002		7.400000 x	17.312112 =	128.109629

			T.E =	128.109629

2107E	2107E			
002		11.900000 x	17.312112 =	206.014133

			T.E =	206.014133
2107H	2107H			
002		16.400000 x	17.312112 =	283.918637

			T.E =	283.918637
2107I	2107I			
002		19.400000 x	17.312112 =	335.854973

			T.E =	335.854973
2107Z	2107Z			
002		14.900000 x	17.312112 =	257.950469

			T.E =	257.950469
2107Γ	2107Γ			
002		8.900000 x	17.312112 =	154.077797

			T.E =	154.077797
2107Δ	2107Δ			
002		10.400000 x	17.312112 =	180.045965

			T.E =	180.045965
2107Θ	2107Θ			
002		17.900000 x	17.312112 =	309.886805

			T.E =	309.886805
2107ΣΤ	2107ΣΤ			
002		13.400000 x	17.312112 =	231.982301

			T.E =	231.982301
2108A	2108A			
002		.700000 x	17.312112 =	12.118478

			T.E =	12.118478
2108B	2108B			
002		1.600000 x	17.312112 =	27.699379

			T.E =	27.699379

2108E	2108E			
002		4.600000 x	17.312112 =	79.635715

			T.E =	79.635715
2108H	2108H			
002		7.600000 x	17.312112 =	131.572051

			T.E =	131.572051
2108Z	2108Z			
002		6.600000 x	17.312112 =	114.259939

			T.E =	114.259939
2108Γ	2108Γ			
002		2.600000 x	17.312112 =	45.011491

			T.E =	45.011491
2108Δ	2108Δ			
002		3.600000 x	17.312112 =	62.323603

			T.E =	62.323603
2108Θ	2108Θ			
002		8.600000 x	17.312112 =	148.884163

			T.E =	148.884163
2108ΣΤ	2108ΣΤ			
002		5.600000 x	17.312112 =	96.947827

			T.E =	96.947827
2109	2109			
002		.030000 x	17.312112 =	.519363
1503		.001000 x	529.621235 =	.529621
1506		.004000 x	694.572736 =	2.778291

			T.E =	3.827276
2110	2110			
002		.040000 x	17.312112 =	.692484
1501		.005000 x	466.271473 =	2.331357
1503		.001000 x	529.621235 =	.529621
1506		.004000 x	694.572736 =	2.778291

			T.E =	6.331754

2111	2111				
002		.100000 x	17.312112 =	1.731211	
1504		.005000 x	608.466928 =	3.042335	

			T.E =	4.773546	
2112	2112				
002		.120000 x	17.312112 =	2.077453	
1501		.004000 x	466.271473 =	1.865086	
1504		.005500 x	608.466928 =	3.346568	

			T.E =	7.289107	
2113	2113				
002		1.400000 x	17.312112 =	24.236957	
002		.300000 x	17.312112 =	5.193634	

			T.E =	29.430590	
2114	2114				
002		1.500000 x	17.312112 =	25.968168	
1501		.005000 x	466.271473 =	2.331357	
002		.400000 x	17.312112 =	6.924845	

			T.E =	35.224370	
2115	2115				
481		.300000 x	5.467500 =	1.640250	
002		.600000 x	17.312112 =	10.387267	
003		1.200000 x	20.419486 =	24.503383	
1501		.011000 x	466.271473 =	5.128986	

			T.E =	41.659887	
2116	2116				
2115		1.300000 x	41.659887 =	54.157853	

			T.E =	54.157853	
2117	2117				
002		.600000 x	17.312112 =	10.387267	
1501		.125000 x	466.271473 =	58.283934	

			T.E =	68.671201	
2118	2118				
2117		1.300000 x	68.671201 =	89.272561	

			T.E =	89.272561	

2121	2121				
001		.400000 x	15.741598 =	6.296639	
002		1.800000 x	17.312112 =	31.161802	

			T.E =	37.458441	
2122	2122				
001		.500000 x	15.741598 =	7.870799	
1501		.005000 x	466.271473 =	2.331357	
002		2.000000 x	17.312112 =	34.624224	

			T.E =	44.826380	
2123	2123				
002		.200000 x	17.312112 =	3.462422	
1504		.008300 x	608.466928 =	5.050276	

			T.E =	8.512698	
2124	2124				
002		.200000 x	17.312112 =	3.462422	
1501		.005000 x	466.271473 =	2.331357	
1504		.010000 x	608.466928 =	6.084669	

			T.E =	11.878449	
2125	2125				
481		.400000 x	5.467500 =	2.187000	
1501		.020000 x	466.271473 =	9.325429	
002		1.000000 x	17.312112 =	17.312112	
003		1.500000 x	20.419486 =	30.629229	

			T.E =	59.453770	
2126	2126				
2125		1.300000 x	59.453770 =	77.289901	

			T.E =	77.289901	
2127	2127				
002		1.000000 x	17.312112 =	17.312112	
1501		.166600 x	466.271473 =	77.680827	

			T.E =	94.992939	
2128	2128				
2127		1.300000 x	94.992939 =	123.490821	

			T.E =	123.490821	

2131	2131			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2132	2132			
1504		.001600 x	608.466928 =	.973547

			T.E =	.973547
2133	2133			
002		.100000 x	17.312112 =	1.731211
002		.600000 x	17.312112 =	10.387267

			T.E =	12.118478
2134	2134			
1504		.002500 x	608.466928 =	1.521167

			T.E =	1.521167
2135.1	2135.1			
2121		1.300000 x	37.458441 =	48.695973

			T.E =	48.695973
2135.2	2135.2			
2122		1.300000 x	44.826380 =	58.274294

			T.E =	58.274294
2135.3	2135.3			
2127		1.300000 x	94.992939 =	123.490821

			T.E =	123.490821
2135.4	2135.4			
2128		1.300000 x	123.490821 =	160.538067

			T.E =	160.538067
2141	2141			
001		2.000000 x	15.741598 =	31.483196
003		2.500000 x	20.419486 =	51.048715

			T.E =	82.531911

2142	2142				
001		2.000000 x	15.741598 =	31.483196	
1501		.005000 x	466.271473 =	2.331357	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	95.073011	
2143	2143				
481		.500000 x	5.467500 =	2.733750	
001		2.000000 x	15.741598 =	31.483196	
003		3.000000 x	20.419486 =	61.258458	
1501		.025000 x	466.271473 =	11.656787	

			T.E =	107.132191	
2144	2144				
2143		1.300000 x	107.132191 =	139.271848	

			T.E =	139.271848	
2145	2145				
001		2.000000 x	15.741598 =	31.483196	
003		1.000000 x	20.419486 =	20.419486	
1501		.200000 x	466.271473 =	93.254295	

			T.E =	145.156977	
2146	2146				
2145		1.300000 x	145.156977 =	188.704070	

			T.E =	188.704070	
2151	2151				
001		1.200000 x	15.741598 =	18.889918	
003		.800000 x	20.419486 =	16.335589	

			T.E =	35.225506	
2152	2152				
001		1.500000 x	15.741598 =	23.612397	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	44.031883	
2161	2161				
1505		.003300 x	254.488790 =	.839813	

			T.E =	.839813	

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.741598 =	12.593278

			T.E =	12.860278
2163	2163			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	608.466928 =	2.433868

			T.E =	2.583468
2172	2172			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
2173	2173			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2174	2174			
007		.050000 x	183.150721 =	9.157536

			T.E =	9.157536
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278

2178	2178			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
2179	2179			
007		.018000 x	183.150721 =	3.296713

			T.E =	3.296713
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.900000 =	.414120
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.930000 =	.393000
482		.700000 x	1.291000 =	.903700
018.1		.042800 x	2.900000 =	.124120

			T.E =	10.546311
2186	2186			
018.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
018.2		.042800 x	4.400000 =	.188320
482		1.400000 x	1.291000 =	1.807400
484		.200000 x	3.930000 =	.786000

			T.E =	12.121411
2187	2187			
019.1		.142800 x	2.900000 =	.414120
485		1.100000 x	1.056100 =	1.161710
019.1		.428000 x	2.900000 =	1.241200
005		.400000 x	21.778427 =	8.711371
484		.100000 x	3.930000 =	.393000

			T.E =	11.921401
2188	2188			
019.2		.142800 x	4.400000 =	.628320
005		.400000 x	21.778427 =	8.711371
485		1.800000 x	1.056100 =	1.900980
484		.200000 x	3.930000 =	.786000
019.2		.042800 x	4.400000 =	.188320

			T.E =	12.214991

ΑΤΟΕ	4ο Τρίμηνο του 2010	Σελ. Ημ/νία	31 16/07/2011
2201	2201		
001	1.000000 x	15.741598 =	15.741598
002	2.000000 x	17.312112 =	34.624224

		T.E =	50.365822
2202	2202		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2203	2203		
001	1.000000 x	15.741598 =	15.741598
002	2.500000 x	17.312112 =	43.280280

		T.E =	59.021878
2204	2204		
001	1.000000 x	15.741598 =	15.741598
002	5.000000 x	17.312112 =	86.560560

		T.E =	102.302158
2206	2206		
001	1.000000 x	15.741598 =	15.741598
003	3.000000 x	20.419486 =	61.258458

		T.E =	77.000056
2207	2207		
001	1.000000 x	15.741598 =	15.741598
003	6.000000 x	20.419486 =	122.516916

		T.E =	138.258514
2211	2211		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196
2212	2212		
001	1.000000 x	15.741598 =	15.741598

		T.E =	15.741598
2213	2213		
001	2.000000 x	15.741598 =	31.483196

		T.E =	31.483196

2214	2214			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2221	2221			
001		1.200000 x	15.741598 =	18.889918
002		1.600000 x	17.312112 =	27.699379

			T.E =	46.589297
2222	2222			
001		1.200000 x	15.741598 =	18.889918
002		2.500000 x	17.312112 =	43.280280

			T.E =	62.170198
2223	2223			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
2224	2224			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
2226	2226			
001		1.500000 x	15.741598 =	23.612397
002		5.000000 x	17.312112 =	86.560560

			T.E =	110.172957
2227	2227			
001		1.500000 x	15.741598 =	23.612397
002		12.000000 x	17.312112 =	207.745344

			T.E =	231.357741
2231	2231			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
2232	2232			
003		.020000 x	20.419486 =	.408390

			T.E =	.408390

2236	2236				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

			T.E =	6.767793	
2237	2237				
001		.200000 x	15.741598 =	3.148320	
003		.700000 x	20.419486 =	14.293640	

			T.E =	17.441960	
2238	2238				
001		.100000 x	15.741598 =	1.574160	
002		.400000 x	17.312112 =	6.924845	

			T.E =	8.499005	
2239	2239				
001		.200000 x	15.741598 =	3.148320	
003		.800000 x	20.419486 =	16.335589	

			T.E =	19.483908	
2241	2241				
001		.300000 x	15.741598 =	4.722479	
003		.100000 x	20.419486 =	2.041949	

			T.E =	6.764428	
2242	2242				
001		.400000 x	15.741598 =	6.296639	
003		.150000 x	20.419486 =	3.062923	

			T.E =	9.359562	
2243	2243				
001		.500000 x	15.741598 =	7.870799	
003		.250000 x	20.419486 =	5.104872	

			T.E =	12.975671	
2246	2246				
001		.250000 x	15.741598 =	3.935400	
003		.050000 x	20.419486 =	1.020974	

			T.E =	4.956374	

2247	2247				
001		.350000 x	15.741598 =	5.509559	
003		.100000 x	20.419486 =	2.041949	

			T.E =	7.551508	
2248	2248				
001		.450000 x	15.741598 =	7.083719	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.167616	
2251	2251				
001		.100000 x	15.741598 =	1.574160	
002		.300000 x	17.312112 =	5.193634	

			T.E =	6.767793	
2252	2252				
001		.100000 x	15.741598 =	1.574160	
002		.600000 x	17.312112 =	10.387267	

			T.E =	11.961427	
2261A	2261A				
003		.400000 x	20.419486 =	8.167794	

			T.E =	8.167794	
2261B	2261B				
003		.700000 x	20.419486 =	14.293640	

			T.E =	14.293640	
2261Γ	2261Γ				
003		.900000 x	20.419486 =	18.377537	

			T.E =	18.377537	
2261Δ	2261Δ				
003		1.200000 x	20.419486 =	24.503383	

			T.E =	24.503383	
2262A	2262A				
003		.550000 x	20.419486 =	11.230717	

			T.E =	11.230717	

2262B	2262B			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537
2262Γ	2262Γ			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2262Δ	2262Δ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263A	2263A			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
2263B	2263B			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
2263Γ	2263Γ			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2263Δ	2263Δ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921
2264.1A	2264.1A			
003		1.600000 x	20.419486 =	32.671178

			T.E =	32.671178
2264.1B	2264.1B			
003		1.850000 x	20.419486 =	37.776049

			T.E =	37.776049
2264.1Γ	2264.1Γ			
003		2.100000 x	20.419486 =	42.880921

			T.E =	42.880921

2264.1Δ	2264.1Δ			
003		2.300000 x	20.419486 =	46.964818

			T.E =	46.964818
2264.2Α	2264.2Α			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972
2264.2Β	2264.2Β			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.2Γ	2264.2Γ			
003		2.800000 x	20.419486 =	57.174561

			T.E =	57.174561
2264.2Δ	2264.2Δ			
003		3.200000 x	20.419486 =	65.342355

			T.E =	65.342355
2264.3Α	2264.3Α			
003		2.400000 x	20.419486 =	49.006766

			T.E =	49.006766
2264.3Β	2264.3Β			
003		2.850000 x	20.419486 =	58.195535

			T.E =	58.195535
2264.3Γ	2264.3Γ			
003		3.300000 x	20.419486 =	67.384304

			T.E =	67.384304
2264.3Δ	2264.3Δ			
003		3.750000 x	20.419486 =	76.573073

			T.E =	76.573073
2265Α	2265Α			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743

2265B	2265B			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
2266.1	2266.1			
2261A		1.000000 x	8.167794 =	8.167794
2261A		.350000 x	8.167794 =	2.858728

			T.E =	11.026522
2266.10	2266.10			
2263B		1.000000 x	24.503383 =	24.503383
2263B		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.11	2266.11			
2263Γ		1.000000 x	32.671178 =	32.671178
2263Γ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.12	2266.12			
2263Δ		1.000000 x	42.880921 =	42.880921
2263Δ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243
2266.13	2266.13			
2264.1A		1.000000 x	32.671178 =	32.671178
2264.1A		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.14	2266.14			
2264.1B		1.000000 x	37.776049 =	37.776049
2264.1B		.350000 x	37.776049 =	13.221617

			T.E =	50.997666
2266.15	2266.15			
2264.1Γ		1.000000 x	42.880921 =	42.880921
2264.1Γ		.350000 x	42.880921 =	15.008322

			T.E =	57.889243

2266.16	2266.16			
2264.1Δ		1.000000 x	46.964818 =	46.964818
2264.1Δ		.350000 x	46.964818 =	16.437686

			T.E =	63.402504
2266.17	2266.17			
2264.2A		1.000000 x	40.838972 =	40.838972
2264.2A		.350000 x	40.838972 =	14.293640

			T.E =	55.132612
2266.18	2266.18			
2264.2B		1.000000 x	49.006766 =	49.006766
2264.2B		.350000 x	49.006766 =	17.152368

			T.E =	66.159134
2266.19	2266.19			
2264.2Γ		1.000000 x	57.174561 =	57.174561
2264.2Γ		.350000 x	57.174561 =	20.011096

			T.E =	77.185657
2266.2	2266.2			
2261B		1.000000 x	14.293640 =	14.293640
2261B		.350000 x	14.293640 =	5.002774

			T.E =	19.296414
2266.20	2266.20			
2264.2Δ		1.000000 x	65.342355 =	65.342355
2264.2Δ		.350000 x	65.342355 =	22.869824

			T.E =	88.212179
2266.21	2266.21			
2264.3A		1.000000 x	49.006766 =	49.006766
2264.3A		.350000 x	49.006766 =	17.152368

			T.E =	66.159134
2266.22	2266.22			
2264.3B		1.000000 x	58.195535 =	58.195535
2264.3B		.350000 x	58.195535 =	20.368437

			T.E =	78.563972

2266.23	2266.23				
2264.3Γ		1.000000 x	67.384304 =	67.384304	
2264.3Γ		.350000 x	67.384304 =	23.584506	
			T.E =	90.968810	
2266.24	2266.24				
2264.3Δ		1.000000 x	76.573073 =	76.573073	
2264.3Δ		.350000 x	76.573073 =	26.800576	
			T.E =	103.373649	
2266.25	2266.25				
2265A		1.000000 x	10.209743 =	10.209743	
2265A		.350000 x	10.209743 =	3.573410	
			T.E =	13.783153	
2266.26	2266.26				
2265B		1.000000 x	16.335589 =	16.335589	
2265B		.350000 x	16.335589 =	5.717456	
			T.E =	22.053045	
2266.3	2266.3				
2261Γ		1.000000 x	18.377537 =	18.377537	
2261Γ		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	
2266.4	2266.4				
2261Δ		1.000000 x	24.503383 =	24.503383	
2261Δ		.350000 x	24.503383 =	8.576184	
			T.E =	33.079567	
2266.5	2266.5				
2262A		1.000000 x	11.230717 =	11.230717	
2262A		.350000 x	11.230717 =	3.930751	
			T.E =	15.161468	
2266.6	2266.6				
2262B		1.000000 x	18.377537 =	18.377537	
2262B		.350000 x	18.377537 =	6.432138	
			T.E =	24.809675	

2266.7	2266.7			
2262Γ		1.000000 x	24.503383 =	24.503383
2262Γ		.350000 x	24.503383 =	8.576184

			T.E =	33.079567
2266.8	2266.8			
2262Δ		1.000000 x	32.671178 =	32.671178
2262Δ		.350000 x	32.671178 =	11.434912

			T.E =	44.106090
2266.9	2266.9			
2263A		1.000000 x	14.293640 =	14.293640
2263A		.350000 x	14.293640 =	5.002774

			T.E =	19.296414
2267	2267			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2268A	2268A			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2268B	2268B			
003		5.900000 x	20.419486 =	120.474967

			T.E =	120.474967
2268Γ	2268Γ			
003		6.400000 x	20.419486 =	130.684710

			T.E =	130.684710
2268Δ	2268Δ			
003		6.900000 x	20.419486 =	140.894453

			T.E =	140.894453
2269A	2269A			
003		2.000000 x	20.419486 =	40.838972

			T.E =	40.838972

2269B	2269B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2269Γ	2269Γ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2270.1	2270.1			
2267		1.000000 x	71.468201 =	71.468201
2267		.600000 x	71.468201 =	42.880921

			T.E =	114.349122
2270.2	2270.2			
2268A		1.000000 x	102.097430 =	102.097430
2268A		.600000 x	102.097430 =	61.258458

			T.E =	163.355888
2270.3	2270.3			
2268B		1.000000 x	120.474967 =	120.474967
2268B		.600000 x	120.474967 =	72.284980

			T.E =	192.759947
2270.4	2270.4			
2268Γ		1.000000 x	130.684710 =	130.684710
2268Γ		.600000 x	130.684710 =	78.410826

			T.E =	209.095536
2270.5	2270.5			
2268Δ		1.000000 x	140.894453 =	140.894453
2268Δ		.600000 x	140.894453 =	84.536672

			T.E =	225.431125
2271A	2271A			
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.048715
2271B	2271B			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458

2271E	2271E			
003		4.500000 x	20.419486 =	91.887687

			T.E =	91.887687
2271H	2271H			
003		6.000000 x	20.419486 =	122.516916

			T.E =	122.516916
2271I	2271I			
003		7.000000 x	20.419486 =	142.936402

			T.E =	142.936402
2271Z	2271Z			
003		5.500000 x	20.419486 =	112.307173

			T.E =	112.307173
2271Γ	2271Γ			
003		3.500000 x	20.419486 =	71.468201

			T.E =	71.468201
2271Δ	2271Δ			
003		4.000000 x	20.419486 =	81.677944

			T.E =	81.677944
2271Θ	2271Θ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2271ΣΤ	2271ΣΤ			
003		5.000000 x	20.419486 =	102.097430

			T.E =	102.097430
2272A	2272A			
003		3.000000 x	20.419486 =	61.258458

			T.E =	61.258458
2272B	2272B			
003		3.700000 x	20.419486 =	75.552098

			T.E =	75.552098

2272E	2272E			
003		5.800000 x	20.419486 =	118.433019

			T.E =	118.433019
2272H	2272H			
003		7.900000 x	20.419486 =	161.313939

			T.E =	161.313939
2272I	2272I			
003		9.300000 x	20.419486 =	189.901220

			T.E =	189.901220
2272Z	2272Z			
003		7.200000 x	20.419486 =	147.020299

			T.E =	147.020299
2272Γ	2272Γ			
003		4.400000 x	20.419486 =	89.845738

			T.E =	89.845738
2272Δ	2272Δ			
003		5.100000 x	20.419486 =	104.139379

			T.E =	104.139379
2272Θ	2272Θ			
003		8.600000 x	20.419486 =	175.607580

			T.E =	175.607580
2272ΣΤ	2272ΣΤ			
003		6.500000 x	20.419486 =	132.726659

			T.E =	132.726659
2273A	2273A			
003		8.500000 x	20.419486 =	173.565631

			T.E =	173.565631
2273B	2273B			
003		10.000000 x	20.419486 =	204.194860

			T.E =	204.194860

2273Γ	2273Γ			
003		11.500000 x	20.419486 =	234.824089

			T.E =	234.824089
2273Δ	2273Δ			
003		13.000000 x	20.419486 =	265.453318

			T.E =	265.453318
2274.1	2274.1			
2271A		1.300000 x	51.048715 =	66.363330

			T.E =	66.363330
2274.10	2274.10			
2271I		1.300000 x	142.936402 =	185.817323

			T.E =	185.817323
2274.11	2274.11			
2272A		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.12	2274.12			
2272B		1.300000 x	75.552098 =	98.217727

			T.E =	98.217727
2274.13	2274.13			
2272Γ		1.300000 x	89.845738 =	116.799459

			T.E =	116.799459
2274.14	2274.14			
2272Δ		1.300000 x	104.139379 =	135.381193

			T.E =	135.381193
2274.15	2274.15			
2272Ε		1.300000 x	118.433019 =	153.962925

			T.E =	153.962925
2274.16	2274.16			
2272ΣΤ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657

2274.17	2274.17			
2272Z		1.300000 x	147.020299 =	191.126389

			T.E =	191.126389
2274.18	2274.18			
2272H		1.300000 x	161.313939 =	209.708121

			T.E =	209.708121
2274.19	2274.19			
2272Θ		1.300000 x	175.607580 =	228.289854

			T.E =	228.289854
2274.2	2274.2			
2271B		1.300000 x	61.258458 =	79.635995

			T.E =	79.635995
2274.20	2274.20			
2272I		1.300000 x	189.901220 =	246.871586

			T.E =	246.871586
2274.21	2274.21			
2273A		1.300000 x	173.565631 =	225.635320

			T.E =	225.635320
2274.22	2274.22			
2273B		1.300000 x	204.194860 =	265.453318

			T.E =	265.453318
2274.23	2274.23			
2273Γ		1.300000 x	234.824089 =	305.271316

			T.E =	305.271316
2274.24	2274.24			
2273Δ		1.300000 x	265.453318 =	345.089313

			T.E =	345.089313
2274.3	2274.3			
2271Γ		1.300000 x	71.468201 =	92.908661

			T.E =	92.908661

2274.4	2274.4			
2271Δ		1.300000 x	81.677944 =	106.181327

			T.E =	106.181327
2274.5	2274.5			
2271Ε		1.300000 x	91.887687 =	119.453993

			T.E =	119.453993
2274.6	2274.6			
2271ΣΤ		1.300000 x	102.097430 =	132.726659

			T.E =	132.726659
2274.7	2274.7			
2271Ζ		1.300000 x	112.307173 =	145.999325

			T.E =	145.999325
2274.8	2274.8			
2271Η		1.300000 x	122.516916 =	159.271991

			T.E =	159.271991
2274.9	2274.9			
2271Θ		1.300000 x	132.726659 =	172.544657

			T.E =	172.544657
2275	2275			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486
2301	2301			
201		.030000 x	290.000000 =	8.700000
203.4		.033000 x	290.000000 =	9.570000
251		6.000000 x	.825000 =	4.950000
003		5.000000 x	20.419486 =	102.097430
001		9.000000 x	15.741598 =	141.674382

			T.E =	266.991812
2302	2302			
201		.001000 x	290.000000 =	.290000
002		.300000 x	17.312112 =	5.193634

			T.E =	5.483634

2303	2303				
001		.250000 x	15.741598 =	3.935400	
003		.250000 x	20.419486 =	5.104872	

			T.E =	9.040271	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.312112 =	1.731211	

			T.E =	1.847211	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	290.000000 =	11.600000	
003		7.000000 x	20.419486 =	142.936402	
001		9.000000 x	15.741598 =	141.674382	
251		6.000000 x	.825000 =	4.950000	

			T.E =	312.760784	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	290.000000 =	.580000	
251		.250000 x	.825000 =	.206250	
001		.250000 x	15.741598 =	3.935400	
003		.150000 x	20.419486 =	3.062923	

			T.E =	8.364572	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.825000 =	.165000	
203.4		.001000 x	290.000000 =	.290000	
003		.100000 x	20.419486 =	2.041949	
001		.200000 x	15.741598 =	3.148320	

			T.E =	6.225268	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.419486 =	.612585	

			T.E =	1.102085	
2314.2	2314.2				
512		1.000000 x	.375000 =	.375000	
003		.030000 x	20.419486 =	.612585	

			T.E =	.987585	

3101	3101				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		175.000000 x	.099900 =	17.482500	
052		.430000 x	15.400000 =	6.622000	
056		.860000 x	10.580000 =	9.098800	

			T.E =	103.260033	
3102	3102				
021		.250000 x	2.670000 =	.667500	
052		.420000 x	15.400000 =	6.468000	
056		.840000 x	10.580000 =	8.887200	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
026		200.000000 x	.099900 =	19.980000	

			T.E =	105.391933	
3103	3103				
021		.250000 x	2.670000 =	.667500	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.820000 x	10.580000 =	8.675600	
052		.410000 x	15.400000 =	6.314000	
026		250.000000 x	.099900 =	24.975000	

			T.E =	110.021333	
3104	3104				
021		.250000 x	2.670000 =	.667500	
026		300.000000 x	.099900 =	29.970000	
052		.400000 x	15.400000 =	6.160000	
003		.700000 x	20.419486 =	14.293640	
001		3.500000 x	15.741598 =	55.095593	
056		.800000 x	10.580000 =	8.464000	

			T.E =	114.650733	
3111	3111				
021		.250000 x	2.670000 =	.667500	
003		1.500000 x	20.419486 =	30.629229	
001		4.000000 x	15.741598 =	62.966392	
026		200.000000 x	.099900 =	19.980000	
057		.840000 x	10.580000 =	8.887200	
052		.420000 x	15.400000 =	6.468000	

			T.E =	129.598321	

3112	3112			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
026		250.000000 x	.099900 =	24.975000
057		.820000 x	10.580000 =	8.675600
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.410000 x	15.400000 =	6.314000

			T.E =	129.493927
3113	3113			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
057		.800000 x	10.580000 =	8.464000
052		.400000 x	15.400000 =	6.160000
026		300.000000 x	.099900 =	29.970000

			T.E =	160.074668
3131	3131			
021		.300000 x	2.670000 =	.801000
056		.840000 x	10.580000 =	8.887200
026		150.000000 x	.099900 =	14.985000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
052		.420000 x	15.400000 =	6.468000

			T.E =	117.370190
3201	3201			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
026		175.000000 x	.099900 =	17.482500
061		.850000 x	13.560000 =	11.526000
052		.570000 x	15.400000 =	8.778000

			T.E =	107.843233
3202	3202			
021		.250000 x	2.670000 =	.667500
026		200.000000 x	.099900 =	19.980000
061		.840000 x	13.560000 =	11.390400
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
052		.560000 x	15.400000 =	8.624000

			T.E =	110.051133

3203	3203			
021		.250000 x	2.670000 =	.667500
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.820000 x	13.560000 =	11.119200
052		.540000 x	15.400000 =	8.316000
026		250.000000 x	.099900 =	24.975000

T.E = 114.466933

3204	3204			
021		.250000 x	2.670000 =	.667500
026		300.000000 x	.099900 =	29.970000
052		.530000 x	15.400000 =	8.162000
003		.700000 x	20.419486 =	14.293640
001		3.500000 x	15.741598 =	55.095593
061		.800000 x	13.560000 =	10.848000

T.E = 119.036733

3205	3205			
021		.250000 x	2.670000 =	.667500
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
026		200.000000 x	.099900 =	19.980000
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000

T.E = 259.975359

3206	3206			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		5.500000 x	20.419486 =	112.307173
001		7.000000 x	15.741598 =	110.191186
052		.410000 x	15.400000 =	6.314000

T.E = 264.390159

3207	3207			
021		.250000 x	2.670000 =	.667500
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
065		.750000 x	13.610000 =	10.207500
052		.430000 x	15.400000 =	6.622000
026		200.000000 x	.099900 =	19.980000

T.E = 193.185046

3208	3208			
021		.250000 x	2.670000 =	.667500
026		250.000000 x	.099900 =	24.975000
065		.730000 x	13.610000 =	9.935300
003		3.000000 x	20.419486 =	61.258458
001		6.000000 x	15.741598 =	94.449588
052		.430000 x	15.400000 =	6.622000

			T.E =	197.907846
3211	3211			
021		.250000 x	2.670000 =	.667500
003		1.500000 x	20.419486 =	30.629229
001		4.000000 x	15.741598 =	62.966392
062		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		200.000000 x	.099900 =	19.980000

			T.E =	134.257521
3212	3212			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
062		.820000 x	13.560000 =	11.119200
026		250.000000 x	.099900 =	24.975000
003		1.500000 x	20.419486 =	30.629229
001		2.000000 x	15.741598 =	31.483196
052		.540000 x	15.400000 =	8.316000

			T.E =	133.939527
3213	3213			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
001		3.000000 x	15.741598 =	47.224794
062		.800000 x	13.560000 =	10.848000
052		.530000 x	15.400000 =	8.162000
026		300.000000 x	.099900 =	29.970000

			T.E =	164.460668
3214	3214			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.270000 x	13.610000 =	3.674700
026		350.000000 x	.099900 =	34.965000
052		.400000 x	15.400000 =	6.160000
062		.600000 x	13.560000 =	8.136000

			T.E =	176.287167

3215	3215			
021		.250000 x	2.670000 =	.667500
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
001		3.500000 x	15.741598 =	55.095593
065		.250000 x	13.610000 =	3.402500
027		350.000000 x	.119300 =	41.755000
062		.560000 x	13.560000 =	7.593600
052		.420000 x	15.400000 =	6.468000

			T.E =	182.570567
3216	3216			
021		.250000 x	2.670000 =	.667500
027		425.000000 x	.119300 =	50.702500
062		.550000 x	13.560000 =	7.458000
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
001		4.000000 x	15.741598 =	62.966392
065		.270000 x	13.610000 =	3.674700
052		.350000 x	15.400000 =	5.390000

			T.E =	198.447466
3217	3217			
001		2.500000 x	15.741598 =	39.353995

			T.E =	39.353995
3218	3218			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990
3219	3219			
001		3.000000 x	15.741598 =	47.224794
003		4.000000 x	20.419486 =	81.677944

			T.E =	128.902738
3220	3220			
001		5.000000 x	15.741598 =	78.707990
003		4.000000 x	20.419486 =	81.677944

			T.E =	160.385934
3221	3221			
001		3.000000 x	15.741598 =	47.224794
003		6.000000 x	20.419486 =	122.516916

			T.E =	169.741710

3222	3222				
001		5.000000 x	15.741598 =		78.707990
003		6.000000 x	20.419486 =		122.516916

			T.E =		201.224906
3223A.1	3223A.1				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	534.988043 =		26.749402
003		1.500000 x	20.419486 =		30.629229

			AΘΡΟΙΣΜΑ =		88.861827
	T.E =	.500000 x	88.861827 =		44.430914

3223A.2	3223A.2				
001		3.000000 x	15.741598 =		47.224794
1502		.050000 x	534.988043 =		26.749402
003		2.000000 x	20.419486 =		40.838972

			AΘΡΟΙΣΜΑ =		114.813168
	T.E =	.500000 x	114.813168 =		57.406584

3223A.3	3223A.3				
001		2.000000 x	15.741598 =		31.483196
1502		.050000 x	534.988043 =		26.749402
003		1.500000 x	20.419486 =		30.629229

			AΘΡΟΙΣΜΑ =		88.861827
	T.E =	.500000 x	88.861827 =		44.430914

3223A.4	3223A.4				
001		3.000000 x	15.741598 =		47.224794
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	534.988043 =		26.749402

			AΘΡΟΙΣΜΑ =		114.813168
	T.E =	.500000 x	114.813168 =		57.406584

3223A.5	3223A.5				
001		3.500000 x	15.741598 =		55.095593
003		2.000000 x	20.419486 =		40.838972
1502		.050000 x	534.988043 =		26.749402

			AΘΡΟΙΣΜΑ =		122.683967
	T.E =	.500000 x	122.683967 =		61.341984

3223A.6	3223A.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	534.988043 =	26.749402
			AΘΡΟΙΣΜΑ =	122.683967
	T.E =	.500000 x	122.683967 =	61.341984
3223A.7	3223A.7			
001		4.000000 x	15.741598 =	62.966392
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	130.554766
	T.E =	.500000 x	130.554766 =	65.277383
3223B.1	3223B.1			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	534.988043 =	26.749402
			AΘΡΟΙΣΜΑ =	88.861827
	T.E =	.250000 x	88.861827 =	22.215457
3223B.2	3223B.2			
001		3.000000 x	15.741598 =	47.224794
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	534.988043 =	26.749402
			AΘΡΟΙΣΜΑ =	114.813168
	T.E =	.250000 x	114.813168 =	28.703292
3223B.3	3223B.3			
001		2.000000 x	15.741598 =	31.483196
003		1.500000 x	20.419486 =	30.629229
1502		.050000 x	534.988043 =	26.749402
			AΘΡΟΙΣΜΑ =	88.861827
	T.E =	.250000 x	88.861827 =	22.215457
3223B.4	3223B.4			
001		3.000000 x	15.741598 =	47.224794
1502		.050000 x	534.988043 =	26.749402
003		2.000000 x	20.419486 =	40.838972
			AΘΡΟΙΣΜΑ =	114.813168
	T.E =	.250000 x	114.813168 =	28.703292

3223B.5	3223B.5			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	534.988043 =	26.749402

			ΑΘΡΟΙΣΜΑ =	122.683967
	T.E =	.250000 x	122.683967 =	30.670992

3223B.6	3223B.6			
001		3.500000 x	15.741598 =	55.095593
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	534.988043 =	26.749402

			ΑΘΡΟΙΣΜΑ =	122.683967
	T.E =	.250000 x	122.683967 =	30.670992

3223B.7	3223B.7			
001		4.000000 x	15.741598 =	62.966392
003		2.000000 x	20.419486 =	40.838972
1502		.050000 x	534.988043 =	26.749402

			ΑΘΡΟΙΣΜΑ =	130.554766
	T.E =	.250000 x	130.554766 =	32.638692

3231	3231			
021		.300000 x	2.670000 =	.801000
1407		.200000 x	37.605000 =	7.521000
001		5.000000 x	15.741598 =	78.707990
061		.840000 x	13.560000 =	11.390400
052		.560000 x	15.400000 =	8.624000
026		150.000000 x	.099900 =	14.985000

			T.E =	122.029390
3301	3301			
021		.200000 x	2.670000 =	.534000
051		.300000 x	15.400000 =	4.620000
032		.150000 x	36.000000 =	5.400000
056		.800000 x	10.580000 =	8.464000
1407		.150000 x	37.605000 =	5.640750
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593

			T.E =	96.089932

3302	3302			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
051		.200000 x	15.400000 =	3.080000
001		3.500000 x	15.741598 =	55.095593
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
056		.800000 x	10.580000 =	8.464000

			T.E =	98.230182
3303	3303			
021		.200000 x	2.670000 =	.534000
032		.400000 x	36.000000 =	14.400000
1407		.200000 x	37.605000 =	7.521000
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000

			T.E =	102.350182
3304	3304			
021		.200000 x	2.670000 =	.534000
1407		.120000 x	37.605000 =	4.512600
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
056		.800000 x	10.580000 =	8.464000
032		.400000 x	36.000000 =	14.400000
026		100.000000 x	.099900 =	9.990000

			T.E =	117.499576
3311	3311			
021		.200000 x	2.670000 =	.534000
032		.160000 x	36.000000 =	5.760000
051		.320000 x	15.400000 =	4.928000
061		.840000 x	13.560000 =	11.390400
1407		.160000 x	37.605000 =	6.016800
003		.800000 x	20.419486 =	16.335589
001		3.500000 x	15.741598 =	55.095593

			T.E =	100.060382
3312	3312			
021		.200000 x	2.670000 =	.534000
032		.210000 x	36.000000 =	7.560000
051		.210000 x	15.400000 =	3.234000
001		3.500000 x	15.741598 =	55.095593
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
061		.840000 x	13.560000 =	11.390400

			T.E =	110.214426

3313	3313			
021		.200000 x	2.670000 =	.534000
032		.420000 x	36.000000 =	15.120000
1407		.210000 x	37.605000 =	7.897050
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400

			T.E =	114.540426
3314	3314			
021		.200000 x	2.670000 =	.534000
1407		.130000 x	37.605000 =	4.888650
003		1.200000 x	20.419486 =	24.503383
001		3.500000 x	15.741598 =	55.095593
061		.840000 x	13.560000 =	11.390400
032		.420000 x	36.000000 =	15.120000
026		100.000000 x	.099900 =	9.990000

			T.E =	121.522026
3401.1	3401.1			
021		.175000 x	2.670000 =	.467250
052		.294000 x	15.400000 =	4.527600
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
058		.500000 x	9.090000 =	4.545000
056		.588000 x	10.580000 =	6.221040
026		140.000000 x	.099900 =	13.986000

			T.E =	91.562320
3401.2	3401.2			
021		.175000 x	2.670000 =	.467250
026		140.000000 x	.099900 =	13.986000
052		.392000 x	15.400000 =	6.036800
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.588000 x	13.560000 =	7.973280
058		.500000 x	9.090000 =	4.545000

			T.E =	94.823760
3402.1	3402.1			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
052		.287000 x	15.400000 =	4.419800
058		.500000 x	9.090000 =	4.545000
056		.574000 x	10.580000 =	6.072920
026		175.000000 x	.099900 =	17.482500

			T.E =	94.802900

3402.2	3402.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
061		.574000 x	13.560000 =	7.783440
058		.500000 x	9.090000 =	4.545000
052		.378000 x	15.400000 =	5.821200
026		175.000000 x	.099900 =	17.482500

			T.E =	97.914820
3406.1	3406.1			
021		.175000 x	2.670000 =	.467250
056		.588000 x	10.580000 =	6.221040
052		.294000 x	15.400000 =	4.527600
001		2.500000 x	15.741598 =	39.353995
003		1.100000 x	20.419486 =	22.461435
081		.500000 x	11.010000 =	5.505000
026		140.000000 x	.099900 =	13.986000

			T.E =	92.522320
3406.2	3406.2			
021		.175000 x	2.670000 =	.467250
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000
061		.588000 x	13.560000 =	7.973280
052		.392000 x	15.400000 =	6.036800
026		140.000000 x	.099900 =	13.986000

			T.E =	95.783760
3407.1	3407.1			
021		.175000 x	2.670000 =	.467250
026		175.000000 x	.099900 =	17.482500
052		.287000 x	15.400000 =	4.419800
056		.574000 x	10.580000 =	6.072920
003		1.100000 x	20.419486 =	22.461435
001		2.500000 x	15.741598 =	39.353995
081		.500000 x	11.010000 =	5.505000

			T.E =	95.762900

3407.2

3407.2

021	.175000 x	2.670000 =	.467250
026	175.000000 x	.099900 =	17.482500
052	.378000 x	15.400000 =	5.821200
001	2.500000 x	15.741598 =	39.353995
003	1.100000 x	20.419486 =	22.461435
081	.500000 x	11.010000 =	5.505000
061	.574000 x	13.560000 =	7.783440

T.E =

98.874820

3501

3501

021	.200000 x	2.670000 =	.534000
003	2.000000 x	20.419486 =	40.838972
1407	.180000 x	37.605000 =	6.768900
001	5.000000 x	15.741598 =	78.707990
032	.200000 x	36.000000 =	7.200000
067	1.050000 x	45.500000 =	47.775000

T.E =

181.824862

3502

3502

021	.200000 x	2.670000 =	.534000
1407	.100000 x	37.605000 =	3.760500
003	2.000000 x	20.419486 =	40.838972
001	5.000000 x	15.741598 =	78.707990
067	1.050000 x	45.500000 =	47.775000
032	.200000 x	36.000000 =	7.200000
026	100.000000 x	.099900 =	9.990000

T.E =

188.806462

3503

3503

021	.200000 x	2.670000 =	.534000
026	150.000000 x	.099900 =	14.985000
032	.200000 x	36.000000 =	7.200000
003	2.000000 x	20.419486 =	40.838972
1407	.080000 x	37.605000 =	3.008400
001	5.000000 x	15.741598 =	78.707990
067	1.000000 x	45.500000 =	45.500000

T.E =

190.774362

3504

3504

021	.200000 x	2.670000 =	.534000
003	3.200000 x	20.419486 =	65.342355
001	5.000000 x	15.741598 =	78.707990
026	250.000000 x	.099900 =	24.975000
517	4.000000 x	.000000 =	.000000
055	180.000000 x	.090000 =	16.200000

T.E =

3505	3505			
021		.200000 x	2.670000 =	.534000
026		250.000000 x	.099900 =	24.975000
517		4.000000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
001		5.500000 x	15.741598 =	86.578789
055		420.000000 x	.090000 =	37.800000

			T.E =	
3506	3506			
021		.300000 x	2.670000 =	.801000
003		2.500000 x	20.419486 =	51.048715
001		5.000000 x	15.741598 =	78.707990
515		1.150000 x	41.230000 =	47.414500
026		200.000000 x	.099900 =	19.980000

			T.E =	197.952205
3511	3511			
021		.200000 x	2.670000 =	.534000
069		1.050000 x	.000000 =	.000000
1407		.180000 x	37.605000 =	6.768900
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990
032		.200000 x	36.000000 =	7.200000

			T.E =	
3512	3512			
021		.200000 x	2.670000 =	.534000
032		.200000 x	36.000000 =	7.200000
026		100.000000 x	.099900 =	9.990000
069		1.050000 x	.000000 =	.000000
1407		.100000 x	37.605000 =	3.760500
003		2.000000 x	20.419486 =	40.838972
001		5.000000 x	15.741598 =	78.707990

			T.E =	
3513	3513			
001		2.500000 x	15.741598 =	39.353995

			T.E =	39.353995
3514	3514			
001		5.000000 x	15.741598 =	78.707990

			T.E =	78.707990

3801	3801				
201		.001500 x	290.000000 =		.435000
003		.500000 x	20.419486 =		10.209743
001		.400000 x	15.741598 =		6.296639
203.4		.002500 x	290.000000 =		.725000
251		.300000 x	.825000 =		.247500

			T.E =		17.913882
3802	3802				
3801		.050000 x	17.913882 =		.895694

			T.E =		.895694
3811	3811				
203.4		.004000 x	290.000000 =		1.160000
001		.200000 x	15.741598 =		3.148320
003		.800000 x	20.419486 =		16.335589
251		.100000 x	.825000 =		.082500

			T.E =		20.726408
3816	3816				
201		.002500 x	290.000000 =		.725000
203.4		.003000 x	290.000000 =		.870000
251		.200000 x	.825000 =		.165000
003		.600000 x	20.419486 =		12.251692
001		.400000 x	15.741598 =		6.296639

			T.E =		20.308331
3817	3817				
3816		.150000 x	20.308331 =		3.046250

			T.E =		3.046250
3821	3821				
201		.014000 x	290.000000 =		4.060000
203.4		.018000 x	290.000000 =		5.220000
003		2.400000 x	20.419486 =		49.006766
001		.600000 x	15.741598 =		9.444959
251		.600000 x	.825000 =		.495000

			T.E =		68.226725
3822	3822				
3821		.150000 x	68.226725 =		10.234009

			T.E =		10.234009

3823	3823			
201		.020000 x	290.000000 =	5.800000
003		3.000000 x	20.419486 =	61.258458
001		.600000 x	15.741598 =	9.444959
251		.180000 x	.825000 =	.148500
203.4		.025000 x	290.000000 =	7.250000

			T.E =	83.901917
3824	3824			
3823		.200000 x	83.901917 =	16.780383

			T.E =	16.780383
3831	3831			
201		.020000 x	290.000000 =	5.800000
003		4.500000 x	20.419486 =	91.887687
001		1.100000 x	15.741598 =	17.315758
251		.800000 x	.825000 =	.660000
203.4		.024000 x	290.000000 =	6.960000

			T.E =	122.623445
3832	3832			
3831		.150000 x	122.623445 =	18.393517

			T.E =	18.393517
3833	3833			
201		.022000 x	290.000000 =	6.380000
251		1.000000 x	.825000 =	.825000
203.4		.025000 x	290.000000 =	7.250000
003		6.000000 x	20.419486 =	122.516916
001		1.100000 x	15.741598 =	17.315758

			T.E =	154.287674
3834	3834			
3833		.200000 x	154.287674 =	30.857535

			T.E =	30.857535
3841	3841			
203.4		.001500 x	290.000000 =	.435000
003		.500000 x	20.419486 =	10.209743

			T.E =	10.644743

3851	3851			
203.4		.052000 x	290.000000 =	15.080000
003		1.300000 x	20.419486 =	26.545332
251		1.100000 x	.825000 =	.907500

			T.E =	42.532832
3852	3852			
001		.300000 x	15.741598 =	4.722479
003		.100000 x	20.419486 =	2.041949

			T.E =	6.764428
3871	3871			
260		1.030000 x	.538600 =	.554758
003		.050000 x	20.419486 =	1.020974

			T.E =	1.575732
3872	3872			
261		1.030000 x	.591400 =	.609142
003		.040000 x	20.419486 =	.816779

			T.E =	1.425921
3873	3873			
262		1.030000 x	.538600 =	.554758
003		.050000 x	20.419486 =	1.020974

			T.E =	1.575732
3874	3874			
258		1.450000 x	7.777500 =	11.277375
003		.150000 x	20.419486 =	3.062923

			T.E =	14.340298
3875	3875			
259		1.000000 x	25.040000 =	25.040000
003		.300000 x	20.419486 =	6.125846

			T.E =	31.165846
3876	3876			
003		.060000 x	20.419486 =	1.225169

			T.E =	1.225169

3881.1	3881.1			
111		1,023.391800 x	.075900 =	77.675438
001		5.000000 x	15.741598 =	78.707990

			T.E =	156.383428
3881.2	3881.2			
112		627.989998 x	.083300 =	52.311567
001		5.000000 x	15.741598 =	78.707990

			T.E =	131.019557
3882	3882			
127		1.050000 x	81.220000 =	85.281000
001		4.000000 x	15.741598 =	62.966392

			T.E =	148.247392
4101	4101			
081		1.150000 x	11.010000 =	12.661500
003		2.000000 x	20.419486 =	40.838972
001		1.300000 x	15.741598 =	20.464077

			T.E =	73.964549
4102	4102			
081		1.200000 x	11.010000 =	13.212000
001		1.700000 x	15.741598 =	26.760717
003		3.500000 x	20.419486 =	71.468201

			T.E =	111.440918
4103	4103			
081		1.150000 x	11.010000 =	12.661500
003		4.000000 x	20.419486 =	81.677944
001		3.000000 x	15.741598 =	47.224794

			T.E =	141.564238
4104	4104			
081		1.050000 x	11.010000 =	11.560500
001		3.000000 x	15.741598 =	47.224794

			T.E =	58.785294
4105	4105			
081		.350000 x	11.010000 =	3.853500
003		.900000 x	20.419486 =	18.377537
001		1.000000 x	15.741598 =	15.741598

			T.E =	37.972635

4106	4106			
081		.320000 x	11.010000 =	3.523200
001		.700000 x	15.741598 =	11.019119
003		.900000 x	20.419486 =	18.377537

			T.E =	32.919856
4107	4107			
081		1.200000 x	11.010000 =	13.212000
003		3.000000 x	20.419486 =	61.258458
001		2.000000 x	15.741598 =	31.483196

			T.E =	105.953654
4201	4201			
081		1.150000 x	11.010000 =	12.661500
1412		.350000 x	27.931800 =	9.776130
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

			T.E =	149.766208
4205	4205			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
003		2.500000 x	20.419486 =	51.048715
001		2.900000 x	15.741598 =	45.650634

			T.E =	123.460407
4206	4206			
081		1.150000 x	11.010000 =	12.661500
001		2.900000 x	15.741598 =	45.650634
003		3.100000 x	20.419486 =	63.300407
1417		.350000 x	40.284450 =	14.099558

			T.E =	135.712098
4207	4207			
081		1.150000 x	11.010000 =	12.661500
1417		.350000 x	40.284450 =	14.099558
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

			T.E =	154.089636

4211	4211				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		2.500000 x	20.419486 =	51.048715	
001		2.900000 x	15.741598 =	45.650634	

			T.E =	130.023414	
4212	4212				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		3.100000 x	20.419486 =	63.300407	
001		2.900000 x	15.741598 =	45.650634	

			T.E =	142.275106	
4213	4213				
081		1.150000 x	11.010000 =	12.661500	
1447		.350000 x	59.035900 =	20.662565	
003		4.000000 x	20.419486 =	81.677944	
001		2.900000 x	15.741598 =	45.650634	

			T.E =	160.652643	
4221	4221				
001		.800000 x	15.741598 =	12.593278	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	33.012764	
4222	4222				
001		.400000 x	15.741598 =	6.296639	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.464434	
4226	4226				
003		1.300000 x	20.419486 =	26.545332	

			T.E =	26.545332	
4251	4251				
083		32.000000 x	.000000 =	.000000	
001		2.900000 x	15.741598 =	45.650634	
1412		.200000 x	27.931800 =	5.586360	
003		4.000000 x	20.419486 =	81.677944	

			T.E =		

4257	4257			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1417		.200000 x	40.284450 =	8.056890
003		4.000000 x	20.419486 =	81.677944

T.E =

4261	4261			
083		32.000000 x	.000000 =	.000000
1445		.200000 x	61.946500 =	12.389300
003		4.000000 x	20.419486 =	81.677944
001		2.900000 x	15.741598 =	45.650634

T.E =

4262	4262			
083		32.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1447		.200000 x	59.035900 =	11.807180
003		4.000000 x	20.419486 =	81.677944

T.E =

4265	4265			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E =

4301	4301			16.176598
081		1.020000 x	11.010000 =	11.230200
003		4.200000 x	20.419486 =	85.761841
1412		.350000 x	27.931800 =	9.776130
001		2.900000 x	15.741598 =	45.650634
083		5.000000 x	.000000 =	.000000

T.E =

4305	4305			
081		1.080000 x	11.010000 =	11.890800
1417		.350000 x	40.284450 =	14.099558
003		2.700000 x	20.419486 =	55.132612
001		2.900000 x	15.741598 =	45.650634
083		2.000000 x	.000000 =	.000000

T.E =

4306	4306			
081		1.050000 x	11.010000 =	11.560500
083		3.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1417		.350000 x	40.284450 =	14.099558
003		3.300000 x	20.419486 =	67.384304

T.E =

4307	4307			
081		1.020000 x	11.010000 =	11.230200
1417		.350000 x	40.284450 =	14.099558
083		5.000000 x	.000000 =	.000000
003		4.200000 x	20.419486 =	85.761841
001		2.900000 x	15.741598 =	45.650634

T.E =

4311	4311			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
003		2.700000 x	20.419486 =	55.132612
1447		.350000 x	59.035900 =	20.662565
001		2.900000 x	15.741598 =	45.650634

T.E =

4312	4312			
081		1.050000 x	11.010000 =	11.560500
1447		.350000 x	59.035900 =	20.662565
003		3.300000 x	20.419486 =	67.384304
001		2.900000 x	15.741598 =	45.650634
083		3.000000 x	.000000 =	.000000

T.E =

4313	4313			
081		1.080000 x	11.010000 =	11.890800
083		2.000000 x	.000000 =	.000000
001		2.900000 x	15.741598 =	45.650634
1447		.350000 x	59.035900 =	20.662565
003		2.700000 x	20.419486 =	55.132612

T.E =

4321	4321			
201		.001500 x	290.000000 =	.435000
001		1.000000 x	15.741598 =	15.741598

T.E = 16.176598

4351.1	4351.1			
088		1.250000 x	.000000 =	.000000
001		10.000000 x	15.741598 =	157.415980
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150
251		4.000000 x	.825000 =	3.300000

T.E =

4351.2	4351.2			
089		1.250000 x	.000000 =	.000000
251		4.000000 x	.825000 =	3.300000
1446		.100000 x	52.880500 =	5.288050
003		25.000000 x	20.419486 =	510.487150
001		10.000000 x	15.741598 =	157.415980

T.E =

4351.3	4351.3			
090		1.250000 x	.000000 =	.000000
251		4.000000 x	.825000 =	3.300000
003		25.000000 x	20.419486 =	510.487150
1446		.100000 x	52.880500 =	5.288050
001		10.000000 x	15.741598 =	157.415980

T.E =

4356.1	4356.1			
092		1.250000 x	.000000 =	.000000
251		8.000000 x	.825000 =	6.600000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
001		11.000000 x	15.741598 =	173.157578

T.E =

4356.2	4356.2			
093		1.250000 x	.000000 =	.000000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552
251		8.000000 x	.825000 =	6.600000
001		11.000000 x	15.741598 =	173.157578

T.E =

4356.3	4356.3			
094		1.250000 x	.000000 =	.000000
001		11.000000 x	15.741598 =	173.157578
251		8.000000 x	.825000 =	6.600000
1446		.200000 x	52.880500 =	10.576100
003		32.000000 x	20.419486 =	653.423552

			T.E =	
4401	4401			
001		1.200000 x	15.741598 =	18.889918

			T.E =	18.889918
4402	4402			
001		3.000000 x	15.741598 =	47.224794

			T.E =	47.224794
4501	4501			
081		.050000 x	11.010000 =	.550500
002		.500000 x	17.312112 =	8.656056
003		1.000000 x	20.419486 =	20.419486

			T.E =	29.626042
4502	4502			
081		.050000 x	11.010000 =	.550500
003		1.300000 x	20.419486 =	26.545332
002		.500000 x	17.312112 =	8.656056

			T.E =	35.751888
4503	4503			
081		.050000 x	11.010000 =	.550500
003		1.400000 x	20.419486 =	28.587280
002		.500000 x	17.312112 =	8.656056

			T.E =	37.793836
4504	4504			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.300000 x	20.419486 =	46.964818

			T.E =	52.708951

4505	4505				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		2.700000 x	20.419486 =	55.132612	

			T.E =	60.876746	
4506	4506				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.600000 x	20.419486 =	73.510150	

			T.E =	79.254283	
4507	4507				
081		.050000 x	11.010000 =	.550500	
003		3.200000 x	20.419486 =	65.342355	
002		.300000 x	17.312112 =	5.193634	

			T.E =	71.086489	
4508	4508				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	67.002592	
4511	4511				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		3.800000 x	20.419486 =	77.594047	

			T.E =	83.338180	
4512	4512				
081		.050000 x	11.010000 =	.550500	
002		.300000 x	17.312112 =	5.193634	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	87.422078	
4515	4515				
081		.050000 x	11.010000 =	.550500	
003		5.000000 x	20.419486 =	102.097430	
002		.300000 x	17.312112 =	5.193634	

			T.E =	107.841564	

4516	4516			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687

			T.E =	97.631821
4517	4517			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		6.500000 x	20.419486 =	132.726659

			T.E =	138.470793
4518	4518			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.700000 x	20.419486 =	116.391070

			T.E =	122.135204
4519	4519			
081		.050000 x	11.010000 =	.550500
003		5.200000 x	20.419486 =	106.181327
002		.300000 x	17.312112 =	5.193634

			T.E =	111.925461
4521	4521			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		3.500000 x	20.419486 =	71.468201

			T.E =	77.212335
4522	4522			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		2.700000 x	20.419486 =	55.132612

			T.E =	60.876746
4525	4525			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		4.500000 x	20.419486 =	91.887687

			T.E =	97.631821

4526	4526			
081		.050000 x	11.010000 =	.550500
003		4.000000 x	20.419486 =	81.677944
002		.300000 x	17.312112 =	5.193634

			T.E =	87.422078
4527	4527			
081		.050000 x	11.010000 =	.550500
003		6.000000 x	20.419486 =	122.516916
002		.300000 x	17.312112 =	5.193634

			T.E =	128.261050
4528	4528			
081		.050000 x	11.010000 =	.550500
002		.300000 x	17.312112 =	5.193634
003		5.200000 x	20.419486 =	106.181327

			T.E =	111.925461
4529	4529			
081		.050000 x	11.010000 =	.550500
003		4.700000 x	20.419486 =	95.971584
002		.300000 x	17.312112 =	5.193634

			T.E =	101.715718
4531	4531			
081		.050000 x	11.010000 =	.550500
003		2.500000 x	20.419486 =	51.048715

			T.E =	51.599215
4532	4532			
081		.050000 x	11.010000 =	.550500
003		2.000000 x	20.419486 =	40.838972

			T.E =	41.389472
4535	4535			
081		.050000 x	11.010000 =	.550500
003		3.800000 x	20.419486 =	77.594047

			T.E =	78.144547
4536	4536			
081		.050000 x	11.010000 =	.550500
003		3.100000 x	20.419486 =	63.300407

			T.E =	63.850907

4537	4537				
081		.050000 x	11.010000 =	.550500	
003		5.500000 x	20.419486 =	112.307173	

			T.E =	112.857673	
4538	4538				
081		.050000 x	11.010000 =	.550500	
003		4.600000 x	20.419486 =	93.929636	

			T.E =	94.480136	
4539	4539				
081		.050000 x	11.010000 =	.550500	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	86.312341	
4541	4541				
081		.050000 x	11.010000 =	.550500	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	51.599215	
4542	4542				
081		.050000 x	11.010000 =	.550500	
003		2.000000 x	20.419486 =	40.838972	

			T.E =	41.389472	
4543	4543				
081		.050000 x	11.010000 =	.550500	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	82.228444	
4544	4544				
081		.050000 x	11.010000 =	.550500	
003		6.000000 x	20.419486 =	122.516916	

			T.E =	123.067416	
4601.1	4601.1				
101		105.000000 x	.000000 =	.000000	
003		.700000 x	20.419486 =	14.293640	
1417		.023000 x	40.284450 =	.926542	
001		.600000 x	15.741598 =	9.444959	

			T.E =		

4601.2	4601.2			
101		105.000000 x	.000000 =	.000000
1447		.023000 x	59.035900 =	1.357826
003		.700000 x	20.419486 =	14.293640
001		.600000 x	15.741598 =	9.444959

T.E =

4602.1	4602.1			
101		210.000000 x	.000000 =	.000000
1417		.056000 x	40.284450 =	2.255929
001		1.300000 x	15.741598 =	20.464077
003		1.300000 x	20.419486 =	26.545332

T.E =

4602.2	4602.2			
101		210.000000 x	.000000 =	.000000
001		1.300000 x	15.741598 =	20.464077
1447		.056000 x	59.035900 =	3.306010
003		1.300000 x	20.419486 =	26.545332

T.E =

4603.1	4603.1			
101		315.000000 x	.000000 =	.000000
1417		.089000 x	40.284450 =	3.585316
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

T.E =

4603.2	4603.2			
101		315.000000 x	.000000 =	.000000
1447		.089000 x	59.035900 =	5.254195
003		1.800000 x	20.419486 =	36.755075
001		1.900000 x	15.741598 =	29.909036

T.E =

4604.1	4604.1			
101		1,050.000000 x	.000000 =	.000000
1417		.332000 x	40.284450 =	13.374437
001		6.300000 x	15.741598 =	99.172067
003		5.500000 x	20.419486 =	112.307173

T.E =

4604.2	4604.2			
101		1,050.000000 x	.000000 =	.000000
001		6.300000 x	15.741598 =	99.172067
1447		.332000 x	59.035900 =	19.599919
003		5.500000 x	20.419486 =	112.307173

T.E =

4611.1	4611.1			
102		105.000000 x	.000000 =	.000000
1417		.030000 x	40.284450 =	1.208534
001		.700000 x	15.741598 =	11.019119
003		.700000 x	20.419486 =	14.293640

T.E =

4611.2	4611.2			
102		105.000000 x	.000000 =	.000000
1447		.030000 x	59.035900 =	1.771077
003		.700000 x	20.419486 =	14.293640
001		.700000 x	15.741598 =	11.019119

T.E =

4612.1	4612.1			
102		210.000000 x	.000000 =	.000000
1417		.070000 x	40.284450 =	2.819912
001		1.400000 x	15.741598 =	22.038237
003		1.300000 x	20.419486 =	26.545332

T.E =

4612.2	4612.2			
102		210.000000 x	.000000 =	.000000
001		1.400000 x	15.741598 =	22.038237
1447		.070000 x	59.035900 =	4.132513
003		1.300000 x	20.419486 =	26.545332

T.E =

4613.1	4613.1			
102		315.000000 x	.000000 =	.000000
1417		.110000 x	40.284450 =	4.431290
003		1.800000 x	20.419486 =	36.755075
001		2.100000 x	15.741598 =	33.057356

T.E =

4613.2	4613.2			
102		315.000000 x	.000000 =	.000000
1447		.110000 x	59.035900 =	6.493949
003		1.800000 x	20.419486 =	36.755075
001		2.100000 x	15.741598 =	33.057356

T.E =

4614.1	4614.1			
102		1,050.000000 x	.000000 =	.000000
1417		.404000 x	40.284450 =	16.274918
001		6.500000 x	15.741598 =	102.320387
003		5.500000 x	20.419486 =	112.307173

T.E =

4614.2	4614.2			
102		1,050.000000 x	.000000 =	.000000
001		6.500000 x	15.741598 =	102.320387
1447		.404000 x	59.035900 =	23.850504
003		5.500000 x	20.419486 =	112.307173

T.E =

4621.1	4621.1			
111		53.000000 x	.075900 =	4.022700
1417		.010000 x	40.284450 =	.402845
001		.400000 x	15.741598 =	6.296639
003		.500000 x	20.419486 =	10.209743

T.E =

20.931927

4621.2	4621.2			
111		53.000000 x	.075900 =	4.022700
1447		.010000 x	59.035900 =	.590359
003		.500000 x	20.419486 =	10.209743
001		.400000 x	15.741598 =	6.296639

T.E =

21.119441

4622.1	4622.1			
111		75.000000 x	.075900 =	5.692500
1417		.020000 x	40.284450 =	.805689
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743

T.E =

23.791651

4622.2	4622.2			
111		75.000000 x	.075900 =	5.692500
001		.450000 x	15.741598 =	7.083719
1447		.020000 x	59.035900 =	1.180718
003		.500000 x	20.419486 =	10.209743

			T.E =	24.166680
4623.1	4623.1			
111		150.000000 x	.075900 =	11.385000
1417		.050000 x	40.284450 =	2.014223
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512

			T.E =	47.752252
4623.2	4623.2			
111		150.000000 x	.075900 =	11.385000
1447		.050000 x	59.035900 =	2.951795
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518

			T.E =	48.689825
4624.1	4624.1			
111		225.000000 x	.075900 =	17.077500
1417		.085000 x	40.284450 =	3.424178
003		1.300000 x	20.419486 =	26.545332
001		1.500000 x	15.741598 =	23.612397

			T.E =	70.659407
4624.2	4624.2			
111		225.000000 x	.075900 =	17.077500
1447		.085000 x	59.035900 =	5.018052
001		1.500000 x	15.741598 =	23.612397
003		1.300000 x	20.419486 =	26.545332

			T.E =	72.253280
4625.1	4625.1			
111		750.000000 x	.075900 =	56.925000
1417		.320000 x	40.284450 =	12.891024
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310

			T.E =	239.476123

4625.2	4625.2			
111		750.000000 x	.075900 =	56.925000
1447		.320000 x	59.035900 =	18.891488
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310

			T.E =	245.476587
4631.1	4631.1			
4601.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.2	4631.2			
4601.2		2.200000 x	.000000 =	.000000

			T.E =	
4631.3	4631.3			
4611.1		2.200000 x	.000000 =	.000000

			T.E =	
4631.4	4631.4			
4611.2		2.200000 x	.000000 =	.000000

			T.E =	
4632.1	4632.1			
4601.1		1.200000 x	.000000 =	.000000
4602.1		1.000000 x	.000000 =	.000000

			T.E =	
4632.2	4632.2			
4601.2		1.200000 x	.000000 =	.000000
4602.2		1.000000 x	.000000 =	.000000

			T.E =	
4632.3	4632.3			
4611.1		1.200000 x	.000000 =	.000000
4612.1		1.000000 x	.000000 =	.000000

			T.E =	

4632.4	4632.4			
4611.2		1.200000 x	.000000 =	.000000
4612.2		1.000000 x	.000000 =	.000000

			T.E =	
4633.1	4633.1			
4622.1		2.200000 x	23.791651 =	52.341632

			T.E =	52.341632
4633.2	4633.2			
4622.2		2.200000 x	24.166680 =	53.166696

			T.E =	53.166696
4634.1	4634.1			
4622.1		1.200000 x	23.791651 =	28.549981
4623.1		1.000000 x	47.752252 =	47.752252

			T.E =	76.302233
4634.2	4634.2			
4622.2		1.200000 x	24.166680 =	29.000016
4623.2		1.000000 x	48.689825 =	48.689825

			T.E =	77.689841
4661.1	4661.1			
112		43.750000 x	.083300 =	3.644375
1417		.014507 x	40.284450 =	.584407
001		.400000 x	15.741598 =	6.296639
003		.500000 x	20.419486 =	10.209743

			T.E =	20.735164
4661.2	4661.2			
112		43.750000 x	.083300 =	3.644375
001		.400000 x	15.741598 =	6.296639
1447		.014507 x	59.035900 =	.856434
003		.500000 x	20.419486 =	10.209743

			T.E =	21.007191
4662.1	4662.1			
112		58.333300 x	.083300 =	4.859164
1417		.022840 x	40.284450 =	.920097
001		.450000 x	15.741598 =	7.083719
003		.500000 x	20.419486 =	10.209743

			T.E =	23.072723

4662.2	4662.2			
112		58.333300 x	.083300 =	4.859164
1447		.022840 x	59.035900 =	1.348380
003		.500000 x	20.419486 =	10.209743
001		.450000 x	15.741598 =	7.083719

			T.E =	23.501006
4663.1	4663.1			
112		105.000000 x	.083300 =	8.746500
1417		.043218 x	40.284450 =	1.741013
003		.900000 x	20.419486 =	18.377537
001		.900000 x	15.741598 =	14.167438

			T.E =	43.032489
4663.2	4663.2			
112		105.000000 x	.083300 =	8.746500
1447		.043218 x	59.035900 =	2.551414
001		.900000 x	15.741598 =	14.167438
003		.900000 x	20.419486 =	18.377537

			T.E =	43.842889
4664.1	4664.1			
112		97.222221 x	.083300 =	8.098611
1417		.045077 x	40.284450 =	1.815902
001		.950000 x	15.741598 =	14.954518
003		.950000 x	20.419486 =	19.398512

			T.E =	44.267543
4664.2	4664.2			
112		97.222221 x	.083300 =	8.098611
1447		.045077 x	59.035900 =	2.661161
003		.950000 x	20.419486 =	19.398512
001		.950000 x	15.741598 =	14.954518

			T.E =	45.112802
4665.1	4665.1			
112		174.999001 x	.083300 =	14.577417
1417		.047530 x	40.284450 =	1.914720
001		1.500000 x	15.741598 =	23.612397
003		1.300000 x	20.419486 =	26.545332

			T.E =	66.649865

4665.2	4665.2			
112		174.999001 x	.083300 =	14.577417
001		1.500000 x	15.741598 =	23.612397
1447		.047530 x	59.035900 =	2.805976
003		1.300000 x	20.419486 =	26.545332

			T.E =	67.541122
4666.1	4666.1			
112		486.111099 x	.083300 =	40.493055
1417		.277862 x	40.284450 =	11.193518
001		5.200000 x	15.741598 =	81.856310
003		4.300000 x	20.419486 =	87.803790

			T.E =	221.346672
4666.2	4666.2			
112		486.111000 x	.083300 =	40.493046
1447		.277862 x	59.035900 =	16.403833
003		4.300000 x	20.419486 =	87.803790
001		5.200000 x	15.741598 =	81.856310

			T.E =	226.556979
4701	4701			
113		13.000000 x	.570000 =	7.410000
1417		.020000 x	40.284450 =	.805689
003		.400000 x	20.419486 =	8.167794
001		.500000 x	15.741598 =	7.870799

			T.E =	24.254282
4702	4702			
113		13.000000 x	.570000 =	7.410000
1447		.020000 x	59.035900 =	1.180718
001		.500000 x	15.741598 =	7.870799
003		.400000 x	20.419486 =	8.167794

			T.E =	24.629311
4703	4703			
114		13.000000 x	.000000 =	.000000
1417		.015000 x	40.284450 =	.604267
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

			T.E =	

4704	4704			
114		13.000000 x	.000000 =	.000000
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

T.E =

4711	4711			
117		13.000000 x	.000000 =	.000000
1417		.020000 x	40.284450 =	.805689
001		.500000 x	15.741598 =	7.870799
003		.400000 x	20.419486 =	8.167794

T.E =

4712	4712			
117		13.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1447		.020000 x	59.035900 =	1.180718
003		.400000 x	20.419486 =	8.167794

T.E =

4713	4713			
118		13.000000 x	.000000 =	.000000
1417		.015000 x	40.284450 =	.604267
001		.400000 x	15.741598 =	6.296639
003		.350000 x	20.419486 =	7.146820

T.E =

4714	4714			
118		13.000000 x	.000000 =	.000000
1447		.015000 x	59.035900 =	.885539
003		.350000 x	20.419486 =	7.146820
001		.400000 x	15.741598 =	6.296639

T.E =

4721.1	4721.1			
128		.080000 x	88.240000 =	7.059200
1417		.004000 x	40.284450 =	.161138
001		.300000 x	15.741598 =	4.722479
003		.350000 x	20.419486 =	7.146820

T.E =

19.089637

4721.2	4721.2				
128		.080000 x	88.240000 =	7.059200	
001		.300000 x	15.741598 =	4.722479	
1447		.004000 x	59.035900 =	.236144	
003		.350000 x	20.419486 =	7.146820	

			T.E =	19.164643	
4722.1	4722.1				
128		.100000 x	88.240000 =	8.824000	
1417		.005000 x	40.284450 =	.201422	
001		.350000 x	15.741598 =	5.509559	
003		.350000 x	20.419486 =	7.146820	

			T.E =	21.681802	
4722.2	4722.2				
128		.100000 x	88.240000 =	8.824000	
1447		.005000 x	59.035900 =	.295180	
003		.350000 x	20.419486 =	7.146820	
001		.350000 x	15.741598 =	5.509559	

			T.E =	21.775559	
4723	4723				
128		.120000 x	88.240000 =	10.588800	
1417		.006000 x	40.284450 =	.241707	
001		.400000 x	15.741598 =	6.296639	
003		.350000 x	20.419486 =	7.146820	

			T.E =	24.273966	
4724.1	4724.1				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1417		.008000 x	40.284450 =	.322276	
003		.400000 x	20.419486 =	8.167794	

			T.E =	28.022709	
4724.2	4724.2				
128		.150000 x	88.240000 =	13.236000	
001		.400000 x	15.741598 =	6.296639	
1447		.008000 x	59.035900 =	.472287	
003		.400000 x	20.419486 =	8.167794	

			T.E =	28.172721	

4725.1	4725.1			
128		.180000 x	88.240000 =	15.883200
1417		.009000 x	40.284450 =	.362560
003		.400000 x	20.419486 =	8.167794
001		.450000 x	15.741598 =	7.083719

			T.E =	31.497274
4725.2	4725.2			
128		.180000 x	88.240000 =	15.883200
001		.450000 x	15.741598 =	7.083719
1447		.009000 x	59.035900 =	.531323
003		.400000 x	20.419486 =	8.167794

			T.E =	31.666037
4801.1	4801.1			
4662.1		1.000000 x	23.072723 =	23.072723
4662.1		.100000 x	23.072723 =	2.307272

			T.E =	25.379995
4801.2	4801.2			
4662.2		1.000000 x	23.501006 =	23.501006
4662.2		.100000 x	23.501006 =	2.350101

			T.E =	25.851107
4802.1	4802.1			
4664.1		1.000000 x	44.267543 =	44.267543
4664.1		.050000 x	44.267543 =	2.213377

			T.E =	46.480920
4802.2	4802.2			
4664.2		1.000000 x	45.112802 =	45.112802
4664.2		.050000 x	45.112802 =	2.255640

			T.E =	47.368442
4803.1	4803.1			
4665.1		1.000000 x	66.649865 =	66.649865
4665.1		.030000 x	66.649865 =	1.999496

			T.E =	68.649361
4803.2	4803.2			
4665.2		1.000000 x	67.541122 =	67.541122
4665.2		.030000 x	67.541122 =	2.026234

			T.E =	69.567356

4811.1	4811.1				
001		.225000 x	15.741598 =	3.541860	
4662.1		1.000000 x	23.072723 =	23.072723	
003		.250000 x	20.419486 =	5.104872	

			T.E =	31.719454	
4811.2	4811.2				
001		.225000 x	15.741598 =	3.541860	
003		.250000 x	20.419486 =	5.104872	
4662.2		1.000000 x	23.501006 =	23.501006	

			T.E =	32.147737	
4812.1	4812.1				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.1		1.000000 x	44.267543 =	44.267543	

			T.E =	61.444058	
4812.2	4812.2				
001		.475000 x	15.741598 =	7.477259	
003		.475000 x	20.419486 =	9.699256	
4664.2		1.000000 x	45.112802 =	45.112802	

			T.E =	62.289317	
4813.1	4813.1				
001		.750000 x	15.741598 =	11.806199	
4665.1		1.000000 x	66.649865 =	66.649865	
003		.650000 x	20.419486 =	13.272666	

			T.E =	91.728729	
4813.2	4813.2				
001		.750000 x	15.741598 =	11.806199	
003		.650000 x	20.419486 =	13.272666	
4665.2		1.000000 x	67.541122 =	67.541122	

			T.E =	92.619986	
4814.1	4814.1				
001		2.600000 x	15.741598 =	40.928155	
003		2.150000 x	20.419486 =	43.901895	
4666.1		1.000000 x	221.346672 =	221.346672	

			T.E =	306.176722	

4814.2	4814.2			
001		2.600000 x	15.741598 =	40.928155
003		2.150000 x	20.419486 =	43.901895
4666.2		1.000000 x	226.556979 =	226.556979

			T.E =	311.387029
4821.1	4821.1			
003		.450000 x	20.419486 =	9.188769
4662.1		1.000000 x	23.072723 =	23.072723

			T.E =	32.261492
4821.2	4821.2			
003		.450000 x	20.419486 =	9.188769
4662.2		1.000000 x	23.501006 =	23.501006

			T.E =	32.689775
4822.1	4822.1			
003		.807500 x	20.419486 =	16.488735
4664.1		1.000000 x	44.267543 =	44.267543

			T.E =	60.756278
4822.2	4822.2			
003		.807500 x	20.419486 =	16.488735
4664.2		1.000000 x	45.112802 =	45.112802

			T.E =	61.601537
4823.1	4823.1			
003		1.040000 x	20.419486 =	21.236265
4665.1		1.000000 x	66.649865 =	66.649865

			T.E =	87.886130
4823.2	4823.2			
003		1.040000 x	20.419486 =	21.236265
4665.2		1.000000 x	67.541122 =	67.541122

			T.E =	88.777387
4824.1	4824.1			
003		3.010000 x	20.419486 =	61.462653
4666.1		1.000000 x	221.346672 =	221.346672

			T.E =	282.809325

4824.2	4824.2			
003		3.010000 x	20.419486 =	61.462653
4666.2		1.000000 x	226.556979 =	226.556979

			T.E =	288.019632
4831.1	4831.1			
003		1.200000 x	20.419486 =	24.503383
4661.1		1.000000 x	20.735164 =	20.735164

			T.E =	45.238547
4831.2	4831.2			
003		1.200000 x	20.419486 =	24.503383
4661.2		1.000000 x	21.007191 =	21.007191

			T.E =	45.510574
4832.1	4832.1			
003		1.600000 x	20.419486 =	32.671178
4662.1		1.000000 x	23.072723 =	23.072723

			T.E =	55.743901
4832.2	4832.2			
003		1.600000 x	20.419486 =	32.671178
4662.2		1.000000 x	23.501006 =	23.501006

			T.E =	56.172184
4833.1	4833.1			
002		2.000000 x	17.312112 =	34.624224
4664.1		1.000000 x	44.267543 =	44.267543

			T.E =	78.891767
4833.2	4833.2			
002		2.000000 x	17.312112 =	34.624224
4664.2		1.000000 x	45.112802 =	45.112802

			T.E =	79.737026
4834.1	4834.1			
003		2.300000 x	20.419486 =	46.964818
4665.1		1.000000 x	66.649865 =	66.649865

			T.E =	113.614683

4834.2 4834.2

003	2.300000 x	20.419486 =	46.964818
4665.2	1.000000 x	67.541122 =	67.541122

T.E = 114.505940

4835 4835

122	1.050000 x	.000000 =	.000000
265	2.000000 x	.869000 =	1.738000
003	1.000000 x	20.419486 =	20.419486
1417	.005000 x	40.284450 =	.201422
001	1.000000 x	15.741598 =	15.741598
201	.010000 x	290.000000 =	2.900000

T.E =

4835.2 4835.2

122	1.050000 x	.000000 =	.000000
1447	.005000 x	59.035900 =	.295180
003	1.000000 x	20.419486 =	20.419486
001	1.000000 x	15.741598 =	15.741598
265	2.000000 x	.869000 =	1.738000
201	.010000 x	290.000000 =	2.900000

T.E =

4836.1 4836.1

123	1.050000 x	.000000 =	.000000
1417	.005000 x	40.284450 =	.201422
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.869000 =	1.738000
003	1.000000 x	20.419486 =	20.419486
001	1.000000 x	15.741598 =	15.741598

T.E =

4836.2 4836.2

123	1.050000 x	.000000 =	.000000
1447	.005000 x	59.035900 =	.295180
003	1.000000 x	20.419486 =	20.419486
201	.010000 x	290.000000 =	2.900000
001	1.000000 x	15.741598 =	15.741598
265	2.000000 x	.869000 =	1.738000

T.E =

4837.1	4837.1			
124		1.050000 x	5.900000 =	6.195000
1417		.010000 x	40.284450 =	.402845
201		.010000 x	290.000000 =	2.900000
001		1.000000 x	15.741598 =	15.741598
003		1.000000 x	20.419486 =	20.419486
265		2.000000 x	.869000 =	1.738000

			T.E =	47.396929
4837.2	4837.2			
124		1.050000 x	5.900000 =	6.195000
1447		.010000 x	59.035900 =	.590359
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
265		2.000000 x	.869000 =	1.738000
201		.010000 x	290.000000 =	2.900000

			T.E =	49.154957
4841	4841			
003		.700000 x	20.419486 =	14.293640

			T.E =	14.293640
4842	4842			
003		1.000000 x	20.419486 =	20.419486

			T.E =	20.419486
4843	4843			
003		.250000 x	20.419486 =	5.104872

			T.E =	5.104872
4844	4844			
131		1,200.000000 x	.650000 =	780.000000
003		25.000000 x	20.419486 =	510.487150
1401		.250000 x	234.711000 =	58.677750
001		10.000000 x	15.741598 =	157.415980

			T.E =	1,506.580880
4845	4845			
132		620.000000 x	.930000 =	576.600000
1401		.180000 x	234.711000 =	42.247980
003		15.000000 x	20.419486 =	306.292290
001		6.000000 x	15.741598 =	94.449588

			T.E =	1,019.589858

4851	4851			
001		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
4852	4852			
001		.150000 x	15.741598 =	2.361240

			T.E =	2.361240
4853	4853			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4854	4854			
001		.250000 x	15.741598 =	3.935400

			T.E =	3.935400
4855	4855			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4856	4856			
001		.800000 x	15.741598 =	12.593278

			T.E =	12.593278
4857	4857			
001		.200000 x	15.741598 =	3.148320

			T.E =	3.148320
4858	4858			
001		.300000 x	15.741598 =	4.722479

			T.E =	4.722479
4859	4859			
001		.400000 x	15.741598 =	6.296639

			T.E =	6.296639
4860	4860			
001		.500000 x	15.741598 =	7.870799

			T.E =	7.870799

4861	4861			
001		.600000 x	15.741598 =	9.444959

			T.E =	9.444959
4862	4862			
001		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
001		1.000000 x	15.741598 =	15.741598
003		4.000000 x	20.419486 =	81.677944

			T.E =	1,197.419542
5102	5102			
483		1.800000 x	.167500 =	.301500
001		1.000000 x	15.741598 =	15.741598
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400
488		.540000 x	5.500000 =	2.970000
489		.360000 x	.000000 =	.000000

			T.E =	
5103	5103			
265		1.050000 x	.869000 =	.912450
003		.200000 x	20.419486 =	4.083897
002		.050000 x	17.312112 =	.865606

			T.E =	5.861953
5104	5104			
001		2.000000 x	15.741598 =	31.483196
003		.150000 x	20.419486 =	3.062923

			T.E =	34.546119
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
003		.500000 x	20.419486 =	10.209743
001		2.000000 x	15.741598 =	31.483196

			T.E =	51.692939

5106	5106				
214		.050000 x	1,000.000000 =	50.000000	
003		2.500000 x	20.419486 =	51.048715	
001		2.000000 x	15.741598 =	31.483196	

			T.E =	132.531911	
5201	5201				
201		1.100000 x	290.000000 =	319.000000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	
251		6.000000 x	.825000 =	4.950000	

			T.E =	614.705420	
5202	5202				
203.2		1.080000 x	370.000000 =	399.600000	
251		6.000000 x	.825000 =	4.950000	
002		4.500000 x	17.312112 =	77.904504	
003		9.000000 x	20.419486 =	183.775374	

			T.E =	666.229878	
5203	5203				
201		1.120000 x	290.000000 =	324.800000	
251		12.000000 x	.825000 =	9.900000	
003		16.000000 x	20.419486 =	326.711776	
002		8.000000 x	17.312112 =	138.496896	

			T.E =	799.908672	
5204	5204				
203.2		1.100000 x	370.000000 =	407.000000	
251		12.000000 x	.825000 =	9.900000	
003		14.000000 x	20.419486 =	285.872804	
002		7.000000 x	17.312112 =	121.184784	

			T.E =	823.957588	
5211	5211				
201		1.100000 x	290.000000 =	319.000000	
003		12.000000 x	20.419486 =	245.033832	
002		6.000000 x	17.312112 =	103.872672	
251		14.000000 x	.825000 =	11.550000	

			T.E =	679.456504	

5212	5212				
203.2		1.080000 x	370.000000 =	399.600000	
251		14.000000 x	.825000 =	11.550000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	701.905420	
5213	5213				
201		1.100000 x	290.000000 =	319.000000	
251		8.000000 x	.825000 =	6.600000	
003		9.000000 x	20.419486 =	183.775374	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	587.279878	
5221	5221				
203.2		.014000 x	370.000000 =	5.180000	
251		.100000 x	.825000 =	.082500	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	

			T.E =	10.212003	
5222	5222				
203.2		.018000 x	370.000000 =	6.660000	
003		.200000 x	20.419486 =	4.083897	
002		.070000 x	17.312112 =	1.211848	
251		.100000 x	.825000 =	.082500	

			T.E =	12.038245	
5223	5223				
203.2		.026000 x	370.000000 =	9.620000	
251		.100000 x	.825000 =	.082500	
002		.100000 x	17.312112 =	1.731211	
003		.200000 x	20.419486 =	4.083897	

			T.E =	15.517608	
5226	5226				
203.2		.016000 x	370.000000 =	5.920000	
251		.100000 x	.825000 =	.082500	
003		.200000 x	20.419486 =	4.083897	
002		.050000 x	17.312112 =	.865606	

			T.E =	10.952003	

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.825000 =	.082500	
003		.200000 x	20.419486 =	4.083897	
002		.100000 x	17.312112 =	1.731211	

			T.E =	14.037608	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
251		.150000 x	.825000 =	.123750	

			T.E =	17.904464	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.825000 =	.123750	
002		.100000 x	17.312112 =	1.731211	
003		.250000 x	20.419486 =	5.104872	

			T.E =	13.619833	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
251		.150000 x	.825000 =	.123750	
003		.250000 x	20.419486 =	5.104872	
002		.120000 x	17.312112 =	2.077453	

			T.E =	16.556075	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.825000 =	.165000	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	

			T.E =	20.446688	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.419486 =	7.146820	
002		.250000 x	17.312112 =	4.328028	
251		.080000 x	.825000 =	.066000	

			T.E =	17.460848	

5237	5237				
203.2		.022000 x	370.000000 =		8.140000
251		.080000 x	.825000 =		.066000
002		.300000 x	17.312112 =		5.193634
003		.350000 x	20.419486 =		7.146820

			T.E =		20.546454
5238	5238				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.825000 =		.082500
003		.350000 x	20.419486 =		7.146820
002		.350000 x	17.312112 =		6.059239

			T.E =		24.388559
5241	5241				
203.2		.030000 x	370.000000 =		11.100000
251		.100000 x	.825000 =		.082500
003		.500000 x	20.419486 =		10.209743
002		.500000 x	17.312112 =		8.656056

			T.E =		30.048299
5243	5243				
003		.150000 x	20.419486 =		3.062923

			T.E =		3.062923
5244	5244				
003		.350000 x	20.419486 =		7.146820

			T.E =		7.146820
5246	5246				
220		26.000000 x	.000000 =		.000000
002		.500000 x	17.312112 =		8.656056
251		.200000 x	.825000 =		.165000

			T.E =		
5247	5247				
221		30.000000 x	.000000 =		.000000
251		.100000 x	.825000 =		.082500
002		.600000 x	17.312112 =		10.387267
283		.100000 x	1.148200 =		.114820

			T.E =		

5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
002		.300000 x	17.312112 =	5.193634	
003		.300000 x	20.419486 =	6.125846	
251		.100000 x	.825000 =	.082500	

			T.E =	16.126979	
5252.1	5252.1				
245		1.100000 x	18.600000 =	20.460000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
245		.110000 x	18.600000 =	2.046000	

			T.E =	116.834995	
5252.2	5252.2				
246		1.100000 x	12.000000 =	13.200000	
246		.110000 x	12.000000 =	1.320000	
002		2.500000 x	17.312112 =	43.280280	
003		2.500000 x	20.419486 =	51.048715	

			T.E =	108.848995	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
249		.110000 x	20.000000 =	2.200000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	

			T.E =	118.528995	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
219		.060000 x	3.500000 =	.210000	
003		1.500000 x	20.419486 =	30.629229	
002		1.500000 x	17.312112 =	25.968168	

			T.E =	61.007397	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.600000 x	.825000 =	.495000	
203.2		.025000 x	370.000000 =	9.250000	

			T.E =	45.730278	

5262	5262			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.825000 =	.247500
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
265		.300000 x	.869000 =	.260700
252		.200000 x	2.020000 =	.404000
203.2		.025000 x	370.000000 =	9.250000

			T.E =	56.593798
5266	5266			
201		.020000 x	290.000000 =	5.800000
203.2		.015000 x	370.000000 =	5.550000
251		.600000 x	.825000 =	.495000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267

			T.E =	34.483959
5267	5267			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.825000 =	.247500
003		.800000 x	20.419486 =	16.335589
002		.800000 x	17.312112 =	13.849690
252		.300000 x	2.020000 =	.606000
265		.300000 x	.869000 =	.260700
203.2		.015000 x	370.000000 =	5.550000

			T.E =	45.549478
5271	5271			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	20.419486 =	10.209743
002		.500000 x	17.312112 =	8.656056
251		.600000 x	.825000 =	.495000
203.2		.025000 x	370.000000 =	9.250000

			T.E =	33.250799
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
252		.100000 x	2.020000 =	.202000
265		.200000 x	.869000 =	.173800
251		.300000 x	.825000 =	.247500
203.2		.025000 x	370.000000 =	9.250000

			T.E =	43.245419

5273	5273				
201		.016000 x	290.000000 =	4.640000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
251		.600000 x	.825000 =	.495000	
203.2		.015000 x	370.000000 =	5.550000	

			T.E =	29.550799	
5274	5274				
201		.024000 x	290.000000 =	6.960000	
252		.100000 x	2.020000 =	.202000	
003		.700000 x	20.419486 =	14.293640	
002		.700000 x	17.312112 =	12.118478	
265		.200000 x	.869000 =	.173800	
203.2		.015000 x	370.000000 =	5.550000	
251		.300000 x	.825000 =	.247500	

			T.E =	39.545419	
5276	5276				
201		1.080000 x	290.000000 =	313.200000	
252		18.000000 x	2.020000 =	36.360000	
003		19.000000 x	20.419486 =	387.970234	
002		19.000000 x	17.312112 =	328.930128	
251		6.000000 x	.825000 =	4.950000	

			T.E =	1,071.410362	
5277	5277				
203.2		1.080000 x	370.000000 =	399.600000	
252		18.000000 x	2.020000 =	36.360000	
251		6.000000 x	.825000 =	4.950000	
002		18.000000 x	17.312112 =	311.618016	
003		18.000000 x	20.419486 =	367.550748	

			T.E =	1,120.078764	
5279	5279				
201		1.080000 x	290.000000 =	313.200000	
251		12.000000 x	.825000 =	9.900000	
002		5.000000 x	17.312112 =	86.560560	
003		10.000000 x	20.419486 =	204.194860	

			T.E =	613.855420	

5280	5280				
203.2		1.080000 x	370.000000 =	399.600000	
251		12.000000 x	.825000 =	9.900000	
003		10.000000 x	20.419486 =	204.194860	
002		5.000000 x	17.312112 =	86.560560	

			T.E =	700.255420	
5281	5281				
203.2		.014000 x	370.000000 =	5.180000	
002		.250000 x	17.312112 =	4.328028	
251		.040000 x	.825000 =	.033000	

			T.E =	9.541028	
5282	5282				
203.2		.020000 x	370.000000 =	7.400000	
251		.060000 x	.825000 =	.049500	
002		.350000 x	17.312112 =	6.059239	

			T.E =	13.508739	
5283	5283				
203.2		.026000 x	370.000000 =	9.620000	
251		.080000 x	.825000 =	.066000	
002		.400000 x	17.312112 =	6.924845	

			T.E =	16.610845	
5286	5286				
203.2		.008000 x	370.000000 =	2.960000	
003		.120000 x	20.419486 =	2.450338	
251		.030000 x	.825000 =	.024750	
002		.120000 x	17.312112 =	2.077453	

			T.E =	7.512542	
5288	5288				
003		.300000 x	20.419486 =	6.125846	

			T.E =	6.125846	
5289	5289				
003		1.000000 x	20.419486 =	20.419486	

			T.E =	20.419486	

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
220		26.000000 x	.000000 =	.000000
251		.200000 x	.825000 =	.165000

T.E =

5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.200000 x	.825000 =	.165000
203.2		.010000 x	370.000000 =	3.700000
220		26.000000 x	.000000 =	.000000

T.E =

5293	5293			
203.2		.020000 x	370.000000 =	7.400000
203.2		.016000 x	370.000000 =	5.920000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.150000 x	.825000 =	.123750

T.E =

5294	5294			28.536389
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.419486 =	8.167794
002		.400000 x	17.312112 =	6.924845
251		.100000 x	.825000 =	.082500
203.2		.022000 x	370.000000 =	8.140000

T.E =

5295	5295			30.715139
203.2		.020000 x	370.000000 =	7.400000
251		.050000 x	.825000 =	.041250
003		.250000 x	20.419486 =	5.104872
002		.250000 x	17.312112 =	4.328028

T.E =

5301	5301			16.874150
226		1.050000 x	13.000000 =	13.650000
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267
251		.250000 x	.825000 =	.206250

T.E =

36.495209

5302	5302				
227		1.050000 x	13.000000 =	13.650000	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
251		.200000 x	.825000 =	.165000	

			T.E =	32.680799	
5321	5321				
203.2		.012000 x	370.000000 =	4.440000	
003		.900000 x	20.419486 =	18.377537	
002		.900000 x	17.312112 =	15.580901	
226		1.050000 x	13.000000 =	13.650000	
251		.500000 x	.825000 =	.412500	

			T.E =	52.460938	
5322	5322				
203.2		.012000 x	370.000000 =	4.440000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	
251		.450000 x	.825000 =	.371250	
227		1.050000 x	13.000000 =	13.650000	

			T.E =	48.646528	
5323	5323				
203.2		.012000 x	370.000000 =	4.440000	
228		1.050000 x	35.000000 =	36.750000	
251		.500000 x	.825000 =	.412500	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	

			T.E =	79.334098	
5324	5324				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
229		1.050000 x	.000000 =	.000000	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.825000 =	.412500	

			T.E =		
5325	5325				
203.2		.012000 x	370.000000 =	4.440000	
230		1.050000 x	.000000 =	.000000	
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
251		.500000 x	.825000 =	.412500	

			T.E =		

5326	5326				
203.2		.012000 x	370.000000 =	4.440000	
003		1.000000 x	20.419486 =	20.419486	
002		1.000000 x	17.312112 =	17.312112	
251		.500000 x	.825000 =	.412500	
231		1.050000 x	22.000000 =	23.100000	

			T.E =	65.684098	
5341	5341				
203.2		.037000 x	370.000000 =	13.690000	
003		1.100000 x	20.419486 =	22.461435	
251		.600000 x	.825000 =	.495000	
002		1.100000 x	17.312112 =	19.043323	
232		1.050000 x	45.000000 =	47.250000	

			T.E =	102.939758	
5342	5342				
203.2		.037000 x	370.000000 =	13.690000	
003		1.700000 x	20.419486 =	34.713126	
002		1.700000 x	17.312112 =	29.430590	
251		.600000 x	.825000 =	.495000	
232		1.100000 x	45.000000 =	49.500000	

			T.E =	127.828717	
5343	5343				
233		1.050000 x	21.300000 =	22.365000	
002		.800000 x	17.312112 =	13.849690	
003		.800000 x	20.419486 =	16.335589	
233		.084000 x	21.300000 =	1.789200	

			T.E =	54.339478	
5351	5351				
035		.200000 x	.086500 =	.017300	
236		1.060000 x	2.000000 =	2.120000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.825000 =	.082500	

			T.E =	9.766120	
5352	5352				
035		.200000 x	.086500 =	.017300	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
251		.100000 x	.825000 =	.082500	
237		1.060000 x	1.100000 =	1.166000	

			T.E =	8.812120	

5353	5353			
035		.200000 x	.086500 =	.017300
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.825000 =	.082500
238		1.060000 x	2.600000 =	2.756000

			T.E =	10.402120
5354	5354			
035		.200000 x	.086500 =	.017300
239		1.060000 x	.000000 =	.000000
251		.100000 x	.825000 =	.082500
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422

			T.E =	
5355	5355			
035		.200000 x	.086500 =	.017300
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
240		1.060000 x	1.400000 =	1.484000
251		.100000 x	.825000 =	.082500

			T.E =	9.130120
5356	5356			
035		.200000 x	.086500 =	.017300
002		.200000 x	17.312112 =	3.462422
251		.100000 x	.825000 =	.082500
003		.200000 x	20.419486 =	4.083897
241		1.060000 x	.000000 =	.000000

			T.E =	
5421	5421			
205		.055000 x	450.000000 =	24.750000
1471		1.000000 x	5.284033 =	5.284033
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	162.094626
5422	5422			
205		.035000 x	450.000000 =	15.750000
1472		1.000000 x	6.367177 =	6.367177
002		3.000000 x	17.312112 =	51.936336
003		3.000000 x	20.419486 =	61.258458

			T.E =	135.311971

5426	5426			
205		.095000 x	450.000000 =	42.750000
1473		1.000000 x	10.869817 =	10.869817
1471		1.000000 x	5.284033 =	5.284033
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916

T.E = 285.293438

5427	5427			
205		.105000 x	450.000000 =	47.250000
1474		1.000000 x	13.189386 =	13.189386
1471		1.000000 x	5.284033 =	5.284033
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

T.E = 329.844605

5428	5428			
205		.075000 x	450.000000 =	33.750000
002		5.500000 x	17.312112 =	95.216616
003		5.500000 x	20.419486 =	112.307173
1474		1.000000 x	13.189386 =	13.189386
1472		1.000000 x	6.367177 =	6.367177

T.E = 260.830352

5431	5431			
205		.070000 x	450.000000 =	31.500000
208		.030000 x	1,450.000000 =	43.500000
002		7.000000 x	17.312112 =	121.184784
1475		1.000000 x	37.486738 =	37.486738
1471		1.000000 x	5.284033 =	5.284033
003		7.000000 x	20.419486 =	142.936402

T.E = 381.891957

5432	5432			
205		.070000 x	450.000000 =	31.500000
002		5.000000 x	17.312112 =	86.560560
1475		.800000 x	37.486738 =	29.989390
1471		1.000000 x	5.284033 =	5.284033
003		5.000000 x	20.419486 =	102.097430
380		1.000000 x	16.150000 =	16.150000

T.E = 271.581413

5436	5436				
205		.050000 x	450.000000 =	22.500000	
1476		1.000000 x	2.802130 =	2.802130	
003		4.500000 x	20.419486 =	91.887687	
002		4.500000 x	17.312112 =	77.904504	

			T.E =	195.094321	
5437	5437				
205		.065000 x	450.000000 =	29.250000	
003		5.000000 x	20.419486 =	102.097430	
002		5.000000 x	17.312112 =	86.560560	
1476		1.000000 x	2.802130 =	2.802130	

			T.E =	220.710120	
5438	5438				
205		.050000 x	450.000000 =	22.500000	
003		4.000000 x	20.419486 =	81.677944	
002		4.000000 x	17.312112 =	69.248448	
1476		1.000000 x	2.802130 =	2.802130	

			T.E =	176.228522	
5441.1	5441.1				
205		.065000 x	450.000000 =	29.250000	
002		4.500000 x	17.312112 =	77.904504	
003		4.500000 x	20.419486 =	91.887687	
1476		1.000000 x	2.802130 =	2.802130	
223.3		.004000 x	.000000 =	.000000	

			T.E =		
5441.2	5441.2				
205		.065000 x	450.000000 =	29.250000	
1476		1.000000 x	2.802130 =	2.802130	
003		4.500000 x	20.419486 =	91.887687	
002		4.500000 x	17.312112 =	77.904504	
223.3		.004000 x	1,500.000000 =	6.000000	

			T.E =	207.844321	
5441.3	5441.3				
205		.065000 x	450.000000 =	29.250000	
243.1		.550000 x	2.700000 =	1.485000	
002		4.500000 x	17.312112 =	77.904504	
1476		1.000000 x	2.802130 =	2.802130	
003		4.500000 x	20.419486 =	91.887687	

			T.E =	203.329321	

5442.1	5442.1			
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	2.802130 =	2.802130
222.3		.004000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

T.E =

5442.2	5442.2			
205		.080000 x	450.000000 =	36.000000
223.3		.004000 x	1,500.000000 =	6.000000
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	2.802130 =	2.802130
002		5.000000 x	17.312112 =	86.560560

T.E =

5442.3	5442.3			233.460120
205		.080000 x	450.000000 =	36.000000
1476		1.000000 x	2.802130 =	2.802130
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
243.1		.055000 x	2.700000 =	.148500

T.E =

5443.1	5443.1			227.608620
205		.065000 x	450.000000 =	29.250000
222.3		.004000 x	.000000 =	.000000
002		4.000000 x	17.312112 =	69.248448
1476		1.000000 x	2.802130 =	2.802130
003		4.000000 x	20.419486 =	81.677944

T.E =

5443.2	5443.2			
205		.065000 x	450.000000 =	29.250000
1476		1.000000 x	2.802130 =	2.802130
223.3		.004000 x	1,500.000000 =	6.000000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

T.E =

188.978522

5443.3	5443.3			
205		.065000 x	450.000000 =	29.250000
243.1		.550000 x	2.700000 =	1.485000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	2.802130 =	2.802130
002		4.000000 x	17.312112 =	69.248448

T.E = 184.463522

5446.1	5446.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.802130 =	2.802130
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
205		.025000 x	450.000000 =	11.250000
222.2		.010000 x	.000000 =	.000000

T.E =

5446.2	5446.2			
203.2		.025000 x	370.000000 =	9.250000
205		.025000 x	450.000000 =	11.250000
003		4.000000 x	20.419486 =	81.677944
1476		1.000000 x	2.802130 =	2.802130
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000

T.E = 191.228522

5447.1	5447.1			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.802130 =	2.802130
002		4.500000 x	17.312112 =	77.904504
003		4.500000 x	20.419486 =	91.887687
222.2		.010000 x	.000000 =	.000000
205		.040000 x	450.000000 =	18.000000

T.E =

5447.2	5447.2			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.802130 =	2.802130
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504
223.2		.010000 x	1,700.000000 =	17.000000
205		.040000 x	450.000000 =	18.000000

T.E = 216.844321

5448.1	5448.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
002		3.500000 x	17.312112 =	60.592392
1476		1.000000 x	2.802130 =	2.802130
003		3.500000 x	20.419486 =	71.468201
205		.025000 x	450.000000 =	11.250000

T.E =

5448.2	5448.2			
203.2		.025000 x	370.000000 =	9.250000
1476		1.000000 x	2.802130 =	2.802130
003		3.500000 x	20.419486 =	71.468201
205		.025000 x	450.000000 =	11.250000
002		3.500000 x	17.312112 =	60.592392
223.2		.010000 x	1,700.000000 =	17.000000

T.E =

172.362723

5449	5449			
205		.045000 x	450.000000 =	20.250000
003		3.000000 x	20.419486 =	61.258458
1476		1.000000 x	2.802130 =	2.802130
002		3.000000 x	17.312112 =	51.936336
243.5		.850000 x	5.900000 =	5.015000

T.E =

141.261924

5451.1	5451.1			
205		.090000 x	450.000000 =	40.500000
1476		1.000000 x	2.802130 =	2.802130
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
222.3		.004000 x	.000000 =	.000000

T.E =

5451.2	5451.2			
205		.090000 x	450.000000 =	40.500000
1476		1.000000 x	2.802130 =	2.802130
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
223.3		.004000 x	1,500.000000 =	6.000000

T.E =

237.960120

5451.3	5451.3			
205		.090000 x	450.000000 =	40.500000
243.1		.550000 x	2.700000 =	1.485000
002		5.000000 x	17.312112 =	86.560560
003		5.000000 x	20.419486 =	102.097430
1476		1.000000 x	2.802130 =	2.802130

			T.E =	233.445120
5456	5456			
205		.055000 x	450.000000 =	24.750000
1478		1.000000 x	3.202750 =	3.202750
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448

			T.E =	178.879142
5457	5457			
205		.085000 x	450.000000 =	38.250000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
1476		1.500000 x	2.802130 =	4.203195
261		2.200000 x	.591400 =	1.301080

			T.E =	307.875461
5461.1	5461.1			
205		.065000 x	450.000000 =	29.250000
1479		1.000000 x	34.603965 =	34.603965
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
222.2		.010000 x	.000000 =	.000000

			T.E =	
5461.2	5461.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,700.000000 =	17.000000
002		5.500000 x	17.312112 =	95.216616
1479		1.000000 x	34.603965 =	34.603965
003		5.500000 x	20.419486 =	112.307173

			T.E =	288.377754
5462.1	5462.1			
205		.065000 x	450.000000 =	29.250000
1480		1.000000 x	33.367858 =	33.367858
222.2		.010000 x	.000000 =	.000000
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616

			T.E =	

5462.2	5462.2			
205		.065000 x	450.000000 =	29.250000
223.2		.010000 x	1,700.000000 =	17.000000
003		5.500000 x	20.419486 =	112.307173
1480		1.000000 x	33.367858 =	33.367858
002		5.500000 x	17.312112 =	95.216616

T.E = 287.141647

5463.1	5463.1			
205		.055000 x	450.000000 =	24.750000
1479		.500000 x	34.603965 =	17.301983
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672
222.2		.010000 x	.000000 =	.000000

T.E =

5463.2	5463.2			
205		.055000 x	450.000000 =	24.750000
223.2		.010000 x	1,700.000000 =	17.000000
003		6.000000 x	20.419486 =	122.516916
1479		.500000 x	34.603965 =	17.301983
002		6.000000 x	17.312112 =	103.872672

T.E = 285.441571

5464.1	5464.1			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	34.603965 =	17.301983
222.2		.010000 x	.000000 =	.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

T.E =

5464.2	5464.2			
205		.070000 x	450.000000 =	31.500000
1479		.500000 x	34.603965 =	17.301983
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
223.2		.010000 x	1,700.000000 =	17.000000

T.E = 329.923169

5465.1	5465.1			
203.2		.045000 x	370.000000 =	16.650000
222.2		.005000 x	.000000 =	.000000
1476		1.000000 x	2.802130 =	2.802130
003		5.500000 x	20.419486 =	112.307173
002		5.500000 x	17.312112 =	95.216616
208		.030000 x	1,450.000000 =	43.500000

T.E =

5465.2	5465.2			
203.2		.045000 x	370.000000 =	16.650000
223.2		.005000 x	1,700.000000 =	8.500000
208		.030000 x	1,450.000000 =	43.500000
002		5.500000 x	17.312112 =	95.216616
003		5.500000 x	20.419486 =	112.307173
1476		1.000000 x	2.802130 =	2.802130

T.E =

278.975919

5466.1	5466.1			
203.2		.025000 x	370.000000 =	9.250000
222.2		.010000 x	.000000 =	.000000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560
1479		.900000 x	34.603965 =	31.143569

T.E =

5466.2	5466.2			
203.2		.025000 x	370.000000 =	9.250000
002		5.000000 x	17.312112 =	86.560560
223.2		.010000 x	1,700.000000 =	17.000000
1479		.900000 x	34.603965 =	31.143569
003		5.000000 x	20.419486 =	102.097430

T.E =

246.051559

5467.1	5467.1			
203.2		.013000 x	370.000000 =	4.810000
203.2		.001040 x	370.000000 =	.384800
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
222.2		.000960 x	.000000 =	.000000
222.2		.012000 x	.000000 =	.000000

T.E =

5467.2	5467.2			
203.2		.013000 x	370.000000 =	4.810000
223.2		.000960 x	1,700.000000 =	1.632000
003		3.500000 x	20.419486 =	71.468201
002		3.500000 x	17.312112 =	60.592392
223.2		.012000 x	1,700.000000 =	20.400000
203.2		.001040 x	370.000000 =	.384800

T.E = 159.287393

5468.1	5468.1			
203.2		.025000 x	370.000000 =	9.250000
203.2		.002000 x	370.000000 =	.740000
222.2		.000800 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
222.2		.010000 x	.000000 =	.000000

T.E =

5468.2	5468.2			
203.2		.025000 x	370.000000 =	9.250000
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
223.2		.010000 x	1,700.000000 =	17.000000
203.2		.002000 x	370.000000 =	.740000
223.2		.000800 x	1,700.000000 =	1.360000

T.E = 179.276392

5469.1	5469.1			
203.2		.025000 x	370.000000 =	9.250000
1479		.500000 x	34.603965 =	17.301983
003		4.500000 x	20.419486 =	91.887687
222.2		.010000 x	.000000 =	.000000
002		4.500000 x	17.312112 =	77.904504

T.E =

5469.2	5469.2			
203.2		.025000 x	370.000000 =	9.250000
223.2		.010000 x	1,700.000000 =	17.000000
1479		.500000 x	34.603965 =	17.301983
003		4.500000 x	20.419486 =	91.887687
002		4.500000 x	17.312112 =	77.904504

T.E = 213.344174

5471	5471				
203.2		.035000 x	370.000000 =		12.950000
251		3.000000 x	.825000 =		2.475000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392

			T.E =		147.485593
5472.1	5472.1				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
251		3.000000 x	.825000 =		2.475000
222.4		.010000 x	.000000 =		.000000

			T.E =		
5472.2	5472.2				
203.2		.026000 x	370.000000 =		9.620000
003		3.500000 x	20.419486 =		71.468201
002		3.500000 x	17.312112 =		60.592392
223.4		.010000 x	1,580.000000 =		15.800000
251		3.000000 x	.825000 =		2.475000

			T.E =		159.955593
5501.1	5501.1				
211		.040000 x	750.000000 =		30.000000
251		.050000 x	.825000 =		.041250
252		.100000 x	2.020000 =		.202000
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280

			T.E =		175.620960
5501.2	5501.2				
212		.040000 x	1,500.000000 =		60.000000
251		.050000 x	.825000 =		.041250
003		5.000000 x	20.419486 =		102.097430
002		2.500000 x	17.312112 =		43.280280
252		.100000 x	2.020000 =		.202000

			T.E =		205.620960
5502	5502				
210		.040000 x	.000000 =		.000000
252		.100000 x	2.020000 =		.202000
002		2.000000 x	17.312112 =		34.624224
003		4.000000 x	20.419486 =		81.677944
251		.050000 x	.825000 =		.041250

			T.E =		

5511.1	5511.1				
211		.020000 x	750.000000 =	15.000000	
003		3.200000 x	20.419486 =	65.342355	
002		1.600000 x	17.312112 =	27.699379	
252		.100000 x	2.020000 =	.202000	

			T.E =	108.243734	
5511.2	5511.2				
212		.020000 x	1,500.000000 =	30.000000	
252		.100000 x	2.020000 =	.202000	
003		3.200000 x	20.419486 =	65.342355	
002		1.600000 x	17.312112 =	27.699379	

			T.E =	123.243734	
5512	5512				
205		.020000 x	450.000000 =	9.000000	
003		3.000000 x	20.419486 =	61.258458	
002		1.500000 x	17.312112 =	25.968168	
252		.100000 x	2.020000 =	.202000	

			T.E =	96.428626	
5513.1	5513.1				
211		.020000 x	750.000000 =	15.000000	
003		4.000000 x	20.419486 =	81.677944	
002		2.000000 x	17.312112 =	34.624224	
252		.100000 x	2.020000 =	.202000	

			T.E =	131.504168	
5513.2	5513.2				
212		.020000 x	1,500.000000 =	30.000000	
252		.100000 x	2.020000 =	.202000	
002		2.000000 x	17.312112 =	34.624224	
003		4.000000 x	20.419486 =	81.677944	

			T.E =	146.504168	
5514	5514				
205		.020000 x	450.000000 =	9.000000	
252		.100000 x	2.020000 =	.202000	
003		3.800000 x	20.419486 =	77.594047	
002		1.800000 x	17.312112 =	31.161802	

			T.E =	117.957848	

5521	5521				
205		.030000 x	450.000000 =		13.500000
252		.150000 x	2.020000 =		.303000
003		2.000000 x	20.419486 =		40.838972
002		.800000 x	17.312112 =		13.849690

			T.E =		68.491662
5531.1	5531.1				
211		.010000 x	750.000000 =		7.500000
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478
252		.020000 x	2.020000 =		.040400

			T.E =		64.581748
5531.2	5531.2				
212		.010000 x	1,500.000000 =		15.000000
252		.020000 x	2.020000 =		.040400
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478

			T.E =		72.081748
5531.3	5531.3				
205		.010000 x	450.000000 =		4.500000
252		.020000 x	2.020000 =		.040400
003		2.200000 x	20.419486 =		44.922869
002		.700000 x	17.312112 =		12.118478

			T.E =		61.581748
5532.1	5532.1				
211		.010000 x	750.000000 =		7.500000
252		.020000 x	2.020000 =		.040400
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112

			T.E =		86.110970
5532.2	5532.2				
212		.010000 x	1,500.000000 =		15.000000
003		3.000000 x	20.419486 =		61.258458
002		1.000000 x	17.312112 =		17.312112
252		.020000 x	2.020000 =		.040400

			T.E =		93.610970

5532.3	5532.3			
205		.010000 x	450.000000 =	4.500000
003		3.000000 x	20.419486 =	61.258458
002		1.000000 x	17.312112 =	17.312112
252		.020000 x	2.020000 =	.040400

			T.E =	83.110970
5533	5533			
537		1.050000 x	1.700000 =	1.785000
003		.350000 x	20.419486 =	7.146820

			T.E =	8.931820
5601	5601			
203.2		.028000 x	370.000000 =	10.360000
251		4.000000 x	.825000 =	3.300000
003		2.500000 x	20.419486 =	51.048715
002		2.500000 x	17.312112 =	43.280280

			T.E =	107.988995
5602	5602			
203.2		.018000 x	370.000000 =	6.660000
003		2.300000 x	20.419486 =	46.964818
002		2.300000 x	17.312112 =	39.817858
251		3.000000 x	.825000 =	2.475000

			T.E =	95.917675
5603	5603			
203.2		.013000 x	370.000000 =	4.810000
002		2.000000 x	17.312112 =	34.624224
003		2.000000 x	20.419486 =	40.838972
251		2.500000 x	.825000 =	2.062500

			T.E =	82.335696
5604	5604			
243.5		1.100000 x	5.900000 =	6.490000
003		2.200000 x	20.419486 =	44.922869
002		2.200000 x	17.312112 =	38.086646
243.5		.165000 x	5.900000 =	.973500

			T.E =	90.473016

5605	5605				
243.3		1.100000 x	4.500000 =	4.950000	
003		2.000000 x	20.419486 =	40.838972	
002		2.000000 x	17.312112 =	34.624224	
243.3		.187000 x	4.500000 =	.841500	

			T.E =	81.254696	
5606	5606				
243.2		1.100000 x	3.800000 =	4.180000	
243.2		.220000 x	3.800000 =	.836000	
002		1.800000 x	17.312112 =	31.161802	
003		1.800000 x	20.419486 =	36.755075	

			T.E =	72.932876	
5607	5607				
205		.012000 x	450.000000 =	5.400000	
205		.002400 x	450.000000 =	1.080000	
242		2.200000 x	1.500000 =	3.300000	
003		2.500000 x	20.419486 =	51.048715	
002		2.500000 x	17.312112 =	43.280280	
242		.440000 x	1.500000 =	.660000	

			T.E =	104.768995	
5608.1	5608.1				
205		.012000 x	450.000000 =	5.400000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
222.1		.001200 x	.000000 =	.000000	
222.1		.006000 x	.000000 =	.000000	
205		.002400 x	450.000000 =	1.080000	

			T.E =		
5608.2	5608.2				
205		.012000 x	450.000000 =	5.400000	
223.1		.006000 x	2,100.000000 =	12.600000	
223.1		.001200 x	2,100.000000 =	2.520000	
003		3.500000 x	20.419486 =	71.468201	
002		3.500000 x	17.312112 =	60.592392	
205		.002400 x	450.000000 =	1.080000	

			T.E =	153.660593	

5611	5611			
205		.060000 x	450.000000 =	27.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.825000 =	4.125000

			T.E =	295.246186
5612.1	5612.1			
205		.060000 x	450.000000 =	27.000000
222.1		.006000 x	.000000 =	.000000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784
251		5.000000 x	.825000 =	4.125000

			T.E =	
5612.2	5612.2			
205		.060000 x	450.000000 =	27.000000
251		5.000000 x	.825000 =	4.125000
223.1		.006000 x	2,100.000000 =	12.600000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

			T.E =	307.846186
5613.1	5613.1			
205		.015000 x	450.000000 =	6.750000
222.2		.003000 x	.000000 =	.000000
205		.001500 x	450.000000 =	.675000
002		1.500000 x	17.312112 =	25.968168
003		1.500000 x	20.419486 =	30.629229

			T.E =	
5613.2	5613.2			
205		.015000 x	450.000000 =	6.750000
223.2		.003000 x	1,700.000000 =	5.100000
205		.001500 x	450.000000 =	.675000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168

			T.E =	69.122397
5614.1	5614.1			
205		.010000 x	450.000000 =	4.500000
205		.001500 x	450.000000 =	.675000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
222.2		.002000 x	.000000 =	.000000

			T.E =	

5614.2	5614.2			
205		.010000 x	450.000000 =	4.500000
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
223.2		.002000 x	1,700.000000 =	3.400000
205		.001500 x	450.000000 =	.675000

			T.E =	53.852918
5615.1	5615.1			
205		.008000 x	450.000000 =	3.600000
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
222.2		.000900 x	.000000 =	.000000
205		.001440 x	450.000000 =	.648000

			T.E =	
5615.2	5615.2			
205		.008000 x	450.000000 =	3.600000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
223.2		.000900 x	1,700.000000 =	1.530000
205		.001440 x	450.000000 =	.648000

			T.E =	43.509598
5616	5616			
205		.003000 x	450.000000 =	1.350000
205		.007500 x	450.000000 =	3.375000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	42.456598
5617	5617			
225		1.100000 x	4.000000 =	4.400000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
521		.250000 x	2.390000 =	.597500

			T.E =	42.729098
5619	5619			
205		.001400 x	450.000000 =	.630000
003		.200000 x	20.419486 =	4.083897

			T.E =	4.713897

5620	5620			
203.2		.012000 x	370.000000 =	4.440000
251		.020000 x	.825000 =	.016500
220		4.200000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846

			T.E =	
5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.825000 =	13.200000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360

			T.E =	
5622	5622			
211		1.100000 x	750.000000 =	825.000000
003		30.000000 x	20.419486 =	612.584580
002		30.000000 x	17.312112 =	519.363360
251		16.000000 x	.825000 =	13.200000

			T.E =	1,970.147940
5626	5626			
205		.030000 x	450.000000 =	13.500000
251		1.000000 x	.825000 =	.825000
003		1.500000 x	20.419486 =	30.629229
002		1.500000 x	17.312112 =	25.968168

			T.E =	70.922397
6101	6101			
267		1.050000 x	.917500 =	.963375
003		.050000 x	20.419486 =	1.020974

			T.E =	1.984349
6102	6102			
252		.050000 x	2.020000 =	.101000
003		.060000 x	20.419486 =	1.225169
267		1.030000 x	.917500 =	.945025

			T.E =	2.271194
6103	6103			
268		1.050000 x	1.079000 =	1.132950
003		.050000 x	20.419486 =	1.020974

			T.E =	2.153924

6104	6104				
252		.050000 x	2.020000 =	.101000	
003		.060000 x	20.419486 =	1.225169	
268		1.030000 x	1.079000 =	1.111370	

			T.E =	2.437539	
6111	6111				
266		1.100000 x	.633000 =	.696300	
003		.150000 x	20.419486 =	3.062923	

			T.E =	3.759223	
6116	6116				
280		1.050000 x	1.000000 =	1.050000	
003		.100000 x	20.419486 =	2.041949	

			T.E =	3.091949	
6117	6117				
281		1.050000 x	5.780000 =	6.069000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	9.131923	
6118	6118				
266		1.150000 x	.633000 =	.727950	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	

			T.E =	8.274270	
6119	6119				
293		1.100000 x	.000000 =	.000000	
003		.150000 x	20.419486 =	3.062923	

			T.E =		
6120	6120				
289		1.050000 x	.828600 =	.870030	
003		.100000 x	20.419486 =	2.041949	

			T.E =	2.911979	
6121	6121				
266		1.100000 x	.633000 =	.696300	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.242620	

6122	6122				
265		1.050000 x	.869000 =	.912450	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.996347	
6123	6123				
265		.900000 x	.869000 =	.782100	
265		.090000 x	.869000 =	.078210	
003		.150000 x	20.419486 =	3.062923	
002		.150000 x	17.312112 =	2.596817	
266		.010000 x	.633000 =	.006330	
266		.100000 x	.633000 =	.063300	

			T.E =	6.589680	
6126	6126				
265		1.250000 x	.869000 =	1.086250	
003		.200000 x	20.419486 =	4.083897	
003		.200000 x	20.419486 =	4.083897	

			T.E =	9.254044	
6127	6127				
290		4.800000 x	3.300000 =	15.840000	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	46.025278	
6128	6128				
290		1.200000 x	3.300000 =	3.960000	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	11.506320	
6201	6201				
264		1.400000 x	1.116300 =	1.562820	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	

			T.E =	10.995720	
6202	6202				
264		1.300000 x	1.116300 =	1.451190	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.997510	

6203	6203				
282		1.200000 x	1.011500 =	1.213800	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	

			T.E =	14.419859	
6204	6204				
282		1.300000 x	1.011500 =	1.314950	
003		.400000 x	20.419486 =	8.167794	
002		.400000 x	17.312112 =	6.924845	

			T.E =	16.407589	
6205	6205				
277		1.250000 x	1.056500 =	1.320625	
002		.500000 x	17.312112 =	8.656056	
003		.500000 x	20.419486 =	10.209743	

			T.E =	20.186424	
6221	6221				
265		1.150000 x	.869000 =	.999350	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	

			T.E =	8.545670	
6222	6222				
265		1.200000 x	.869000 =	1.042800	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	14.248859	
6223	6223				
265		1.250000 x	.869000 =	1.086250	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =	19.952049	
6224	6224				
271		.720000 x	1.046500 =	.753480	
002		.200000 x	17.312112 =	3.462422	
003		.200000 x	20.419486 =	4.083897	
282		.480000 x	1.011500 =	.485520	

			T.E =	8.785320	

6225	6225				
271		.720000 x	1.046500 =	.753480	
002		.250000 x	17.312112 =	4.328028	
003		.250000 x	20.419486 =	5.104872	
282		.480000 x	1.011500 =	.485520	

			T.E =	10.671900	
6226	6226				
265		1.200000 x	.869000 =	1.042800	
003		.700000 x	20.419486 =	14.293640	
002		.700000 x	17.312112 =	12.118478	

			T.E =	27.454919	
6227	6227				
265		1.250000 x	.869000 =	1.086250	
002		.850000 x	17.312112 =	14.715295	
003		.850000 x	20.419486 =	17.356563	

			T.E =	33.158108	
6228	6228				
282		1.250000 x	1.011500 =	1.264375	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	16.357014	
6229	6229				
282		1.250000 x	1.011500 =	1.264375	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	

			T.E =	18.243594	
6230	6230				
277		1.100000 x	1.056500 =	1.162150	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	

			T.E =	20.027949	
6231	6231				
265		1.150000 x	.869000 =	.999350	
002		.250000 x	17.312112 =	4.328028	
003		.250000 x	20.419486 =	5.104872	

			T.E =	10.432250	

6232	6232			
265		1.150000 x	.869000 =	.999350
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794

			T.E =	16.091989
6236	6236			
253		.500000 x	2.550000 =	1.275000
266		2.000000 x	.633000 =	1.266000
388		.350000 x	48.870000 =	17.104500
003		1.800000 x	20.419486 =	36.755075
002		1.800000 x	17.312112 =	31.161802
392		.350000 x	24.930000 =	8.725500
565.3		.350000 x	3.450000 =	1.207500
390		2.100000 x	1.500000 =	3.150000
386		.350000 x	28.630000 =	10.020500
276		5.850000 x	.840700 =	4.918095
272		1.500000 x	.939000 =	1.408500

			T.E =	116.992471
6237	6237			
253		.850000 x	2.550000 =	2.167500
260		9.500000 x	.538600 =	5.116700
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
565.5		.350000 x	5.150000 =	1.802500
392		.350000 x	24.930000 =	8.725500
388		.350000 x	48.870000 =	17.104500
386		.350000 x	28.630000 =	10.020500
272		5.000000 x	.939000 =	4.695000
266		2.100000 x	.633000 =	1.329300

			T.E =	201.887892
6238	6238			
253		.400000 x	2.550000 =	1.020000
266		13.000000 x	.633000 =	8.229000
265		6.000000 x	.869000 =	5.214000
003		5.000000 x	20.419486 =	102.097430
002		5.000000 x	17.312112 =	86.560560

			T.E =	203.120990
6239	6239			
277		1.100000 x	1.056500 =	1.162150
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846

			T.E =	12.481629

6301	6301			
266		1.250000 x	.633000 =	.791250
002		.400000 x	17.312112 =	6.924845
003		.400000 x	20.419486 =	8.167794

			T.E =	15.883889
6302	6302			
266		9.000000 x	.633000 =	5.697000
002		3.500000 x	17.312112 =	60.592392
003		3.500000 x	20.419486 =	71.468201

			T.E =	137.757593
6401	6401			
265		1.150000 x	.869000 =	.999350
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422

			T.E =	8.545670
6402	6402			
265		1.200000 x	.869000 =	1.042800
003		.300000 x	20.419486 =	6.125846
002		.300000 x	17.312112 =	5.193634

			T.E =	12.362279
6403	6403			
265		1.250000 x	.869000 =	1.086250
002		.350000 x	17.312112 =	6.059239
003		.350000 x	20.419486 =	7.146820

			T.E =	14.292309
6406	6406			
265		1.200000 x	.869000 =	1.042800
003		.600000 x	20.419486 =	12.251692
002		.600000 x	17.312112 =	10.387267

			T.E =	23.681759
6407	6407			
265		1.250000 x	.869000 =	1.086250
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478

			T.E =	27.498369

6411	6411				
565.3		1.650000 x	3.450000 =	5.692500	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	18.898559	
6412	6412				
565.5		1.550000 x	5.150000 =	7.982500	
002		.450000 x	17.312112 =	7.790450	
003		.450000 x	20.419486 =	9.188769	

			T.E =	24.961719	
6413	6413				
565.6		1.450000 x	7.100000 =	10.295000	
002		.550000 x	17.312112 =	9.521662	
003		.550000 x	20.419486 =	11.230717	

			T.E =	31.047379	
6416	6416				
566.3		1.600000 x	4.600000 =	7.360000	
003		.350000 x	20.419486 =	7.146820	
002		.350000 x	17.312112 =	6.059239	

			T.E =	20.566059	
6417	6417				
566.5		1.500000 x	7.050000 =	10.575000	
003		.450000 x	20.419486 =	9.188769	
002		.450000 x	17.312112 =	7.790450	

			T.E =	27.554219	
6418	6418				
566.6		1.400000 x	9.400000 =	13.160000	
003		.550000 x	20.419486 =	11.230717	
002		.550000 x	17.312112 =	9.521662	

			T.E =	33.912379	
6421	6421				
565.3		1.050000 x	3.450000 =	3.622500	
003		.400000 x	20.419486 =	8.167794	

			T.E =	11.790294	

6422	6422				
565.5		1.050000 x	5.150000 =	5.407500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	15.617243	
6423	6423				
565.6		1.050000 x	7.100000 =	7.455000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.706692	
6426	6426				
566.3		1.050000 x	4.600000 =	4.830000	
003		.400000 x	20.419486 =	8.167794	

			T.E =	12.997794	
6427	6427				
566.5		1.050000 x	7.050000 =	7.402500	
003		.500000 x	20.419486 =	10.209743	

			T.E =	17.612243	
6428	6428				
566.6		1.050000 x	9.400000 =	9.870000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	22.121692	
6431	6431				
278		1.100000 x	3.600000 =	3.960000	
003		.150000 x	20.419486 =	3.062923	

			T.E =	7.022923	
6432	6432				
251		.100000 x	.825000 =	.082500	
002		.250000 x	17.312112 =	4.328028	
279		1.080000 x	3.720000 =	4.017600	
003		.250000 x	20.419486 =	5.104872	

			T.E =	13.533000	
6441	6441				
266		1.100000 x	.633000 =	.696300	
003		.100000 x	20.419486 =	2.041949	
002		.100000 x	17.312112 =	1.731211	

			T.E =	4.469460	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.419486 =	.816779

			T.E =	
6446.2	6446.2			
285		1.100000 x	.065700 =	.072270
003		.040000 x	20.419486 =	.816779

			T.E =	.889049
6447	6447			
251		.050000 x	.825000 =	.041250
286		1.050000 x	1.737300 =	1.824165
003		.100000 x	20.419486 =	2.041949
002		.100000 x	17.312112 =	1.731211

			T.E =	5.638575
6448	6448			
251		.050000 x	.825000 =	.041250
002		.100000 x	17.312112 =	1.731211
288		1.050000 x	1.885600 =	1.979880
003		.100000 x	20.419486 =	2.041949

			T.E =	5.794290
6501	6501			
282		3.000000 x	1.011500 =	3.034500
295		11.000000 x	6.185800 =	68.043800
003		4.000000 x	20.419486 =	81.677944
002		4.000000 x	17.312112 =	69.248448
296		1.000000 x	12.370900 =	12.370900

			T.E =	234.375592
6502	6502			
002		1.500000 x	17.312112 =	25.968168
6501		1.000000 x	234.375592 =	234.375592
003		1.500000 x	20.419486 =	30.629229

			T.E =	290.972989
6503	6503			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		.950000 x	234.375592 =	222.656812

			T.E =	271.707890

6504	6504			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.910000 x	234.375592 =	213.281789

			T.E =	258.559706
6505	6505			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		.870000 x	234.375592 =	203.906765

			T.E =	241.638363
6506	6506			
002		1.000000 x	17.312112 =	17.312112
6501		.810000 x	234.375592 =	189.844230
003		1.000000 x	20.419486 =	20.419486

			T.E =	227.575828
6507	6507			
002		.900000 x	17.312112 =	15.580901
003		.900000 x	20.419486 =	18.377537
6501		.920000 x	234.375592 =	215.625545

			T.E =	249.583983
6508	6508			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.030000 x	234.375592 =	241.406860

			T.E =	290.457937
6509	6509			
002		1.000000 x	17.312112 =	17.312112
003		1.000000 x	20.419486 =	20.419486
6501		1.010000 x	234.375592 =	236.719348

			T.E =	274.450946
6510	6510			
002		1.200000 x	17.312112 =	20.774534
6501		1.080000 x	234.375592 =	253.125639
003		1.200000 x	20.419486 =	24.503383

			T.E =	298.403557

6511	6511				
002		1.500000 x	17.312112 =	25.968168	
003		1.500000 x	20.419486 =	30.629229	
6501		.920000 x	234.375592 =	215.625545	

			T.E =	272.222942	
6512	6512				
002		1.400000 x	17.312112 =	24.236957	
003		1.400000 x	20.419486 =	28.587280	
6501		.820000 x	234.375592 =	192.187985	

			T.E =	245.012223	
6513	6513				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		.780000 x	234.375592 =	182.812962	

			T.E =	231.864039	
6514	6514				
002		1.200000 x	17.312112 =	20.774534	
6501		.760000 x	234.375592 =	178.125450	
003		1.200000 x	20.419486 =	24.503383	

			T.E =	223.403368	
6515	6515				
002		1.000000 x	17.312112 =	17.312112	
003		1.000000 x	20.419486 =	20.419486	
6501		.800000 x	234.375592 =	187.500474	

			T.E =	225.232072	
6516	6516				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.220000 x	234.375592 =	285.938222	

			T.E =	334.989300	
6517	6517				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.120000 x	234.375592 =	262.500663	

			T.E =	307.778581	

6518	6518			
002		1.100000 x	17.312112 =	19.043323
6501		.670000 x	234.375592 =	157.031647
003		1.100000 x	20.419486 =	22.461435

			T.E =	198.536404
6519	6519			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.280000 x	234.375592 =	300.000758

			T.E =	349.051835
6520	6520			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.120000 x	234.375592 =	262.500663

			T.E =	307.778581
6521	6521			
002		1.300000 x	17.312112 =	22.505746
003		1.300000 x	20.419486 =	26.545332
6501		1.210000 x	234.375592 =	283.594466

			T.E =	332.645544
6522	6522			
002		1.200000 x	17.312112 =	20.774534
6501		1.190000 x	234.375592 =	278.906954
003		1.200000 x	20.419486 =	24.503383

			T.E =	324.184872
6523	6523			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		1.280000 x	234.375592 =	300.000758

			T.E =	345.278675
6524	6524			
002		1.200000 x	17.312112 =	20.774534
003		1.200000 x	20.419486 =	24.503383
6501		.800000 x	234.375592 =	187.500474

			T.E =	232.778391

6525	6525				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.040000 x	234.375592 =	243.750616	

			T.E =	289.028533	
6526	6526				
002		1.300000 x	17.312112 =	22.505746	
6501		.900000 x	234.375592 =	210.938033	
003		1.300000 x	20.419486 =	26.545332	

			T.E =	259.989110	
6527	6527				
002		1.300000 x	17.312112 =	22.505746	
003		1.300000 x	20.419486 =	26.545332	
6501		1.120000 x	234.375592 =	262.500663	

			T.E =	311.551740	
6528	6528				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		.840000 x	234.375592 =	196.875497	

			T.E =	242.153415	
6529	6529				
002		1.200000 x	17.312112 =	20.774534	
003		1.200000 x	20.419486 =	24.503383	
6501		1.080000 x	234.375592 =	253.125639	

			T.E =	298.403557	
6530	6530				
002		1.000000 x	17.312112 =	17.312112	
6501		.710000 x	234.375592 =	166.406670	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	204.138268	
6531	6531				
002		.600000 x	17.312112 =	10.387267	
003		.600000 x	20.419486 =	12.251692	
6501		.480000 x	234.375592 =	112.500284	

			T.E =	135.139243	

6532	6532				
294		6.000000 x	3.518600 =	21.111600	
003		2.500000 x	20.419486 =	51.048715	
296		1.000000 x	12.370900 =	12.370900	
002		2.500000 x	17.312112 =	43.280280	
294		.300000 x	3.518600 =	1.055580	

			T.E =	128.867075	
6541	6541				
282		.350000 x	1.011500 =	.354025	
003		.500000 x	20.419486 =	10.209743	
002		.500000 x	17.312112 =	8.656056	
295		1.050000 x	6.185800 =	6.495090	
296		.120000 x	12.370900 =	1.484508	

			T.E =	27.199422	
6542	6542				
295		1.050000 x	6.185800 =	6.495090	
296		.100000 x	12.370900 =	1.237090	
003		.800000 x	20.419486 =	16.335589	
002		.800000 x	17.312112 =	13.849690	

			T.E =	37.917458	
6543	6543				
295		.400000 x	6.185800 =	2.474320	
003		.200000 x	20.419486 =	4.083897	
296		.130000 x	12.370900 =	1.608217	

			T.E =	8.166434	
7101	7101				
201		.000500 x	290.000000 =	.145000	
1445		.010000 x	61.946500 =	.619465	
002		.500000 x	17.312112 =	8.656056	
003		.850000 x	20.419486 =	17.356563	

			T.E =	26.777084	
7102	7102				
201		.000500 x	290.000000 =	.145000	
002		.400000 x	17.312112 =	6.924845	
1445		.010000 x	61.946500 =	.619465	
003		.700000 x	20.419486 =	14.293640	

			T.E =	21.982950	

7103	7103				
201		.000500 x	290.000000 =	.145000	
1445		.004000 x	61.946500 =	.247786	
002		.300000 x	17.312112 =	5.193634	
003		.600000 x	20.419486 =	12.251692	

			T.E =	17.838111	
7104	7104				
201		.000500 x	290.000000 =	.145000	
1445		.008000 x	61.946500 =	.495572	
003		1.000000 x	20.419486 =	20.419486	
002		.600000 x	17.312112 =	10.387267	

			T.E =	31.447325	
7111	7111				
201		.000500 x	290.000000 =	.145000	
1413		.027000 x	29.264100 =	.790131	
001		.300000 x	15.741598 =	4.722479	
003		.600000 x	20.419486 =	12.251692	

			T.E =	17.909302	
7116	7116				
201		.000500 x	290.000000 =	.145000	
001		.350000 x	15.741598 =	5.509559	
1418		.027000 x	41.616750 =	1.123652	
003		.650000 x	20.419486 =	13.272666	

			T.E =	20.050877	
7121	7121				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1445		.027000 x	61.946500 =	1.672556	
003		.800000 x	20.419486 =	16.335589	

			T.E =	22.875624	
7122	7122				
201		.000500 x	290.000000 =	.145000	
1444		.027000 x	76.007500 =	2.052203	
003		.800000 x	20.419486 =	16.335589	
001		.300000 x	15.741598 =	4.722479	

			T.E =	23.255271	

7123	7123			
201		.000500 x	290.000000 =	.145000
1462		.015000 x	85.411250 =	1.281169
1446		.006000 x	52.880500 =	.317283
001		.300000 x	15.741598 =	4.722479
003		.900000 x	20.419486 =	18.377537
1445		.006000 x	61.946500 =	.371679

			T.E =	25.215148
7124.1	7124.1			
201		.000500 x	290.000000 =	.145000
1465		.015000 x	91.830150 =	1.377452
001		.300000 x	15.741598 =	4.722479
1445		.012000 x	61.946500 =	.743358
003		.900000 x	20.419486 =	18.377537

			T.E =	25.365827
7124.2	7124.2			
201		.000500 x	290.000000 =	.145000
001		.300000 x	15.741598 =	4.722479
1445		.012000 x	61.946500 =	.743358
1466		.015000 x	89.893950 =	1.348409
003		.900000 x	20.419486 =	18.377537

			T.E =	25.336784
7124.3	7124.3			
201		.000500 x	290.000000 =	.145000
1467		.015000 x	85.376150 =	1.280642
1445		.012000 x	61.946500 =	.743358
003		.900000 x	20.419486 =	18.377537
001		.300000 x	15.741598 =	4.722479

			T.E =	25.269017
7131	7131			
201		.000500 x	290.000000 =	.145000
1426		.006000 x	152.456250 =	.914738
1413		.021000 x	29.264100 =	.614546
001		.300000 x	15.741598 =	4.722479
003		.600000 x	20.419486 =	12.251692

			T.E =	18.648455

7132	7132				
201		.000500 x	290.000000 =	.145000	
1427		.006000 x	163.304700 =	.979828	
001		.350000 x	15.741598 =	5.509559	
1418		.021000 x	41.616750 =	.873952	
003		.650000 x	20.419486 =	13.272666	

			T.E =	20.781005	
7133	7133				
201		.000500 x	290.000000 =	.145000	
1463		.015000 x	72.487750 =	1.087316	
1418		.006000 x	41.616750 =	.249701	
001		.350000 x	15.741598 =	5.509559	
1427		.006000 x	163.304700 =	.979828	
003		.600000 x	20.419486 =	12.251692	

			T.E =	20.223096	
7134	7134				
201		.000500 x	290.000000 =	.145000	
1464		.015000 x	55.101600 =	.826524	
1427		.006000 x	163.304700 =	.979828	
1418		.006000 x	41.616750 =	.249701	
003		.600000 x	20.419486 =	12.251692	
001		.350000 x	15.741598 =	5.509559	

			T.E =	19.962304	
7136	7136				
201		.000500 x	290.000000 =	.145000	
001		.250000 x	15.741598 =	3.935400	
003		.400000 x	20.419486 =	8.167794	
1418		.017000 x	41.616750 =	.707485	

			T.E =	12.955679	
7138	7138				
201		.000500 x	290.000000 =	.145000	
001		.300000 x	15.741598 =	4.722479	
1418		.027000 x	41.616750 =	1.123652	
003		.800000 x	20.419486 =	16.335589	

			T.E =	22.326720	
7141	7141				
201		.000500 x	290.000000 =	.145000	
001		.400000 x	15.741598 =	6.296639	
1445		.027000 x	61.946500 =	1.672556	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	28.533681	

7146	7146			
201		.000500 x	290.000000 =	.145000
1421		.016000 x	.000000 =	.000000
1413		.014000 x	29.264100 =	.409697
003		.650000 x	20.419486 =	13.272666
001		.350000 x	15.741598 =	5.509559

T.E =

7147	7147			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
1421		.016000 x	.000000 =	.000000
1413		.007000 x	29.264100 =	.204849

T.E =

7148	7148			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
001		.450000 x	15.741598 =	7.083719
1413		.014000 x	29.264100 =	.409697
003		.600000 x	20.419486 =	12.251692

T.E =

7149	7149			
201		.000500 x	290.000000 =	.145000
1426		.007000 x	152.456250 =	1.067194
001		.450000 x	15.741598 =	7.083719
1413		.007000 x	29.264100 =	.204849
1422		.016000 x	.000000 =	.000000
003		.600000 x	20.419486 =	12.251692

T.E =

7150	7150			
201		.000500 x	290.000000 =	.145000
1422		.016000 x	.000000 =	.000000
1418		.014000 x	41.616750 =	.582635
003		.650000 x	20.419486 =	13.272666
001		.350000 x	15.741598 =	5.509559

T.E =

7151	7151			
201		.000500 x	290.000000 =	.145000
001		.350000 x	15.741598 =	5.509559
003		.650000 x	20.419486 =	13.272666
1422		.016000 x	.000000 =	.000000
1427		.007000 x	163.304700 =	1.143133
1418		.007000 x	41.616750 =	.291317

T.E =

7152	7152			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.741598 =	7.083719
003		.700000 x	20.419486 =	14.293640
1447		.014000 x	59.035900 =	.826503
1448		.016000 x	.000000 =	.000000

T.E =

7153	7153			
201		.000500 x	290.000000 =	.145000
001		.450000 x	15.741598 =	7.083719
1447		.007000 x	59.035900 =	.413251
1448		.016000 x	.000000 =	.000000
1426		.007000 x	152.456250 =	1.067194
003		.700000 x	20.419486 =	14.293640

T.E =

7161	7161			
201		.000800 x	290.000000 =	.232000
1453		.020000 x	187.752750 =	3.755055
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
002		1.600000 x	17.312112 =	27.699379
001		.600000 x	15.741598 =	9.444959

T.E = 75.165394

7162	7162			
201		.000800 x	290.000000 =	.232000
1458		.020000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.600000 x	20.419486 =	32.671178
001		.600000 x	15.741598 =	9.444959
002		1.600000 x	17.312112 =	27.699379

T.E =

7163	7163				
201		.000800 x	290.000000 =	.232000	
002		1.600000 x	17.312112 =	27.699379	
1454		.020000 x	211.557750 =	4.231155	
1445		.022000 x	61.946500 =	1.362823	
003		1.600000 x	20.419486 =	32.671178	
001		.600000 x	15.741598 =	9.444959	

			T.E =	75.641494	
7164	7164				
201		.000800 x	290.000000 =	.232000	
001		.600000 x	15.741598 =	9.444959	
003		1.600000 x	20.419486 =	32.671178	
1455		.020000 x	.000000 =	.000000	
1445		.022000 x	61.946500 =	1.362823	
002		1.600000 x	17.312112 =	27.699379	

			T.E =	75.641494	
7165	7165				
201		.000800 x	290.000000 =	.232000	
001		.600000 x	15.741598 =	9.444959	
1459		.020000 x	211.557750 =	4.231155	
1445		.022000 x	61.946500 =	1.362823	
003		1.600000 x	20.419486 =	32.671178	
002		1.600000 x	17.312112 =	27.699379	

			T.E =	75.641494	
7166	7166				
201		.000800 x	290.000000 =	.232000	
1453		.017000 x	187.752750 =	3.191797	
1445		.022000 x	61.946500 =	1.362823	
003		1.200000 x	20.419486 =	24.503383	
002		1.200000 x	17.312112 =	20.774534	
001		.500000 x	15.741598 =	7.870799	

			T.E =	57.935336	
7167	7167				
201		.000800 x	290.000000 =	.232000	
002		1.200000 x	17.312112 =	20.774534	
1445		.022000 x	61.946500 =	1.362823	
1458		.017000 x	.000000 =	.000000	
003		1.200000 x	20.419486 =	24.503383	
001		.500000 x	15.741598 =	7.870799	

			T.E =		

7168	7168			
201		.000800 x	290.000000 =	.232000
003		1.200000 x	20.419486 =	24.503383
1454		.017000 x	211.557750 =	3.596482
1445		.022000 x	61.946500 =	1.362823
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799

			T.E =	58.340021
7169	7169			
201		.000800 x	290.000000 =	.232000
1455		.017000 x	.000000 =	.000000
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383
002		1.200000 x	17.312112 =	20.774534
001		.500000 x	15.741598 =	7.870799

			T.E =	
7170	7170			
201		.000800 x	290.000000 =	.232000
001		.500000 x	15.741598 =	7.870799
002		1.200000 x	17.312112 =	20.774534
1459		.017000 x	211.557750 =	3.596482
1445		.022000 x	61.946500 =	1.362823
003		1.200000 x	20.419486 =	24.503383

			T.E =	58.340021
7171	7171			
201		.000700 x	290.000000 =	.203000
001		.100000 x	15.741598 =	1.574160

			T.E =	1.777160
7176	7176			
003		1.500000 x	20.419486 =	30.629229

			T.E =	30.629229
7177	7177			
003		1.100000 x	20.419486 =	22.461435

			T.E =	22.461435
7178	7178			
003		.900000 x	20.419486 =	18.377537

			T.E =	18.377537

7179	7179				
003		.500000 x	20.419486 =		10.209743

			T.E =		10.209743
7181	7181				
003		.700000 x	20.419486 =		14.293640

			T.E =		14.293640
7206	7206				
142		26.000000 x	.350000 =		9.100000
002		.300000 x	17.312112 =		5.193634
1412		.040000 x	27.931800 =		1.117272
003		.600000 x	20.419486 =		12.251692

			T.E =		27.662597
7207	7207				
142		26.000000 x	.350000 =		9.100000
1412		.020000 x	27.931800 =		.558636
002		.250000 x	17.312112 =		4.328028
003		.500000 x	20.419486 =		10.209743

			T.E =		24.196407
7208	7208				
142		26.000000 x	.350000 =		9.100000
1412		.025000 x	27.931800 =		.698295
003		.400000 x	20.419486 =		8.167794
002		.200000 x	17.312112 =		3.462422

			T.E =		21.428512
7209	7209				
142		26.000000 x	.350000 =		9.100000
1412		.005000 x	27.931800 =		.139659
003		.300000 x	20.419486 =		6.125846
002		.150000 x	17.312112 =		2.596817

			T.E =		17.962322
7211	7211				
146		15.000000 x	.380000 =		5.700000
283		.075000 x	1.148200 =		.086115
003		.400000 x	20.419486 =		8.167794
1445		.001000 x	61.946500 =		.061947
002		.200000 x	17.312112 =		3.462422

			T.E =		17.478278

7221	7221				
203.2		.001500 x	370.000000 =	.555000	
506		1.150000 x	1.290700 =	1.484305	
254		.020000 x	3.363800 =	.067276	
003		.200000 x	20.419486 =	4.083897	
002		.150000 x	17.312112 =	2.596817	
492		.200000 x	.540000 =	.108000	

			T.E =	8.895295	
7222	7222				
254		.050000 x	3.363800 =	.168190	
492		.200000 x	.540000 =	.108000	
003		.250000 x	20.419486 =	5.104872	
002		.150000 x	17.312112 =	2.596817	
506		1.200000 x	1.290700 =	1.548840	

			T.E =	9.526718	
7223	7223				
254		.050000 x	3.363800 =	.168190	
493		.200000 x	.730000 =	.146000	
003		.200000 x	20.419486 =	4.083897	
002		.200000 x	17.312112 =	3.462422	
508		1.200000 x	.860000 =	1.032000	

			T.E =	8.892510	
7231	7231				
274		1.200000 x	1.483200 =	1.779840	
003		.250000 x	20.419486 =	5.104872	
002		.250000 x	17.312112 =	4.328028	
274		.200000 x	1.483200 =	.296640	

			T.E =	11.509380	
7241	7241				
297.2		.051072 x	.000000 =	.000000	
003		1.400000 x	20.419486 =	28.587280	
002		1.400000 x	17.312112 =	24.236957	
495		.500000 x	.000000 =	.000000	
001		.200000 x	15.741598 =	3.148320	

			T.E =		

7242	7242			
297.2		.057000 x	.000000 =	.000000
002		2.800000 x	17.312112 =	48.473914
003		2.800000 x	20.419486 =	57.174561
495		1.000000 x	.000000 =	.000000
001		.200000 x	15.741598 =	3.148320

			T.E =	
7243.1	7243.1			
179		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.825000 =	1.072500

			T.E =	
7243.2	7243.2			
180		1.200000 x	.000000 =	.000000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
251		1.300000 x	.825000 =	1.072500

			T.E =	
7243.3	7243.3			
181		1.200000 x	.000000 =	.000000
002		.200000 x	17.312112 =	3.462422
003		.200000 x	20.419486 =	4.083897
251		1.300000 x	.825000 =	1.072500

			T.E =	
7244	7244			
251		1.200000 x	.825000 =	.990000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112
273		1.200000 x	1.202500 =	1.443000

			T.E =	40.164598
7245	7245			
251		.500000 x	.825000 =	.412500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
273		1.200000 x	1.202500 =	1.443000

			T.E =	28.267619

7246	7246			
265		.500000 x	.869000 =	.434500
298.1		6.700000 x	6.130000 =	41.071000
003		1.000000 x	20.419486 =	20.419486
002		1.000000 x	17.312112 =	17.312112

			T.E =	79.237098
7301	7301			
096		1.050000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
001		.400000 x	15.741598 =	6.296639
1444		.001500 x	76.007500 =	.114011
003		.900000 x	20.419486 =	18.377537

			T.E =	
7302	7302			
097		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1444		.002000 x	76.007500 =	.152015
1445		.025000 x	61.946500 =	1.548663
003		1.000000 x	20.419486 =	20.419486

			T.E =	
7303	7303			
096		1.100000 x	.000000 =	.000000
1445		.025000 x	61.946500 =	1.548663
1444		.001000 x	76.007500 =	.076008
003		2.000000 x	20.419486 =	40.838972
001		1.000000 x	15.741598 =	15.741598

			T.E =	
7304	7304			
096		1.100000 x	.000000 =	.000000
001		.800000 x	15.741598 =	12.593278
1444		.001500 x	76.007500 =	.114011
1445		.025000 x	61.946500 =	1.548663
003		1.600000 x	20.419486 =	32.671178

			T.E =	
7305	7305			
096		.160000 x	.000000 =	.000000
1445		.004000 x	61.946500 =	.247786
001		.150000 x	15.741598 =	2.361240
1444		.000200 x	76.007500 =	.015202
003		.300000 x	20.419486 =	6.125846

			T.E =	

7311	7311			
098		1.150000 x	.000000 =	.000000
1417		.033000 x	40.284450 =	1.329387
001		.600000 x	15.741598 =	9.444959
1445		.005000 x	61.946500 =	.309733
003		2.200000 x	20.419486 =	44.922869

T.E =

7312	7312			
099		1.050000 x	.000000 =	.000000
1445		.005000 x	61.946500 =	.309733
1417		.033000 x	40.284450 =	1.329387
003		1.100000 x	20.419486 =	22.461435
001		.500000 x	15.741598 =	7.870799

T.E =

7313	7313			
152		1.050000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
003		.900000 x	20.419486 =	18.377537
1445		.004000 x	61.946500 =	.247786
1417		.022000 x	40.284450 =	.886258

T.E =

7314	7314			
154		1.050000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
003		2.500000 x	20.419486 =	51.048715
1449		.030000 x	53.460700 =	1.603821

T.E =

7315	7315			
155		1.050000 x	2.481600 =	2.605680
001		.100000 x	15.741598 =	1.574160
1449		.004000 x	53.460700 =	.213843
003		.300000 x	20.419486 =	6.125846

T.E = 10.519528

7316	7316			
161		1.050000 x	6.700000 =	7.035000
1449		.025000 x	53.460700 =	1.336518
1444		.002000 x	76.007500 =	.152015
003		.600000 x	20.419486 =	12.251692
001		.300000 x	15.741598 =	4.722479

T.E = 25.497704

7317	7317			
163		1.050000 x	6.900000 =	7.245000
1449		.025000 x	53.460700 =	1.336518
1444		.001500 x	76.007500 =	.114011
001		.300000 x	15.741598 =	4.722479
003		.800000 x	20.419486 =	16.335589

			T.E =	29.753597
7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
003		1.300000 x	20.419486 =	26.545332
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
001		.100000 x	15.741598 =	1.574160

			T.E =	
7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
001		.100000 x	15.741598 =	1.574160
1444		.001000 x	76.007500 =	.076008
1449		.025000 x	53.460700 =	1.336518
003		1.300000 x	20.419486 =	26.545332

			T.E =	
7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
001		.400000 x	15.741598 =	6.296639
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.500000 x	20.419486 =	30.629229

			T.E =	
7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	53.460700 =	1.336518
1444		.001000 x	76.007500 =	.076008
003		1.500000 x	20.419486 =	30.629229
001		.400000 x	15.741598 =	6.296639

			T.E =	

7324	7324			
166		1.050000 x	.000000 =	.000000
1449		.002000 x	53.460700 =	.106921
1444		.000100 x	76.007500 =	.007601
003		.200000 x	20.419486 =	4.083897
001		.040000 x	15.741598 =	.629664

			T.E =	
7326.1	7326.1			
029		.200000 x	.152800 =	.030560
173		48.000000 x	.255300 =	12.254400
003		3.000000 x	20.419486 =	61.258458
1449		.020000 x	53.460700 =	1.069214
1444		.005000 x	76.007500 =	.380038
001		.500000 x	15.741598 =	7.870799

			T.E =	82.863469
7326.2	7326.2			
029		.200000 x	.152800 =	.030560
174		48.000000 x	.000000 =	.000000
001		.500000 x	15.741598 =	7.870799
1444		.005000 x	76.007500 =	.380038
1449		.020000 x	53.460700 =	1.069214
003		3.000000 x	20.419486 =	61.258458

			T.E =	
7327	7327			
029		.200000 x	.152800 =	.030560
175		95.000000 x	.000000 =	.000000
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944
001		.600000 x	15.741598 =	9.444959

			T.E =	
7328.1	7328.1			
029		.300000 x	.152800 =	.045840
1449		.020000 x	53.460700 =	1.069214
1444		.007000 x	76.007500 =	.532053
003		4.000000 x	20.419486 =	81.677944
001		.700000 x	15.741598 =	11.019119
171		108.000000 x	.000000 =	.000000

			T.E =	

7328.2

7328.2

029	.300000 x	.152800 =	.045840
172	108.000000 x	.000000 =	.000000
001	.700000 x	15.741598 =	11.019119
1449	.020000 x	53.460700 =	1.069214
1444	.007000 x	76.007500 =	.532053
003	4.000000 x	20.419486 =	81.677944

T.E =

7331

7331

029	1.500000 x	.152800 =	.229200
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
169	54.000000 x	.000000 =	.000000
003	3.500000 x	20.419486 =	71.468201
001	.500000 x	15.741598 =	7.870799

T.E =

7332

7332

029	2.000000 x	.152800 =	.305600
170	108.000000 x	.000000 =	.000000
003	4.500000 x	20.419486 =	91.887687
1449	.020000 x	53.460700 =	1.069214
1444	.005000 x	76.007500 =	.380038
001	.800000 x	15.741598 =	12.593278

T.E =

7333

7333

029	.300000 x	.152800 =	.045840
1449	.020000 x	53.460700 =	1.069214
003	2.500000 x	20.419486 =	51.048715
002	.500000 x	17.312112 =	8.656056
167	1.050000 x	.000000 =	.000000

T.E =

7334

7334

029	.300000 x	.152800 =	.045840
168	1.050000 x	.000000 =	.000000
003	3.000000 x	20.419486 =	61.258458
1449	.020000 x	53.460700 =	1.069214
002	.600000 x	17.312112 =	10.387267

T.E =

7335	7335				
001		.450000 x	15.741598 =	7.083719	
1445		.026000 x	61.946500 =	1.610609	
003		1.000000 x	20.419486 =	20.419486	
1444		.007000 x	76.007500 =	.532053	

			T.E =	29.645867	
7336	7336				
001		.400000 x	15.741598 =	6.296639	
003		.900000 x	20.419486 =	18.377537	
1445		.022000 x	61.946500 =	1.362823	
1444		.006000 x	76.007500 =	.456045	

			T.E =	26.493045	
7337	7337				
001		.350000 x	15.741598 =	5.509559	
003		.800000 x	20.419486 =	16.335589	
1445		.017000 x	61.946500 =	1.053091	
1444		.005000 x	76.007500 =	.380038	

			T.E =	23.278276	
7338	7338				
026		.500000 x	.099900 =	.049950	
001		.300000 x	15.741598 =	4.722479	
1445		.017000 x	61.946500 =	1.053091	
003		.700000 x	20.419486 =	14.293640	

			T.E =	20.119160	
7340	7340				
289		1.100000 x	.828600 =	.911460	
001		.400000 x	15.741598 =	6.296639	
1445		.026000 x	61.946500 =	1.610609	
1444		.007000 x	76.007500 =	.532053	
003		1.100000 x	20.419486 =	22.461435	

			T.E =	31.812195	
7341	7341				
003		.200000 x	20.419486 =	4.083897	
1441		.003000 x	27.111000 =	.081333	

			T.E =	4.165230	
7346	7346				
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.083897	

7347	7347				
001		.200000 x	15.741598 =	3.148320	
003		.500000 x	20.419486 =	10.209743	
1444		.002000 x	76.007500 =	.152015	
1445		.009000 x	61.946500 =	.557519	
			T.E =	14.067596	
7351	7351				
001		.200000 x	15.741598 =	3.148320	
003		.600000 x	20.419486 =	12.251692	
1444		.009000 x	76.007500 =	.684068	
			T.E =	16.084079	
7352	7352				
001		.200000 x	15.741598 =	3.148320	
1444		.012000 x	76.007500 =	.912090	
003		.700000 x	20.419486 =	14.293640	
			T.E =	18.354050	
7355	7355				
001		.150000 x	15.741598 =	2.361240	
1444		.008000 x	76.007500 =	.608060	
003		.600000 x	20.419486 =	12.251692	
			T.E =	15.220991	
7356	7356				
001		.100000 x	15.741598 =	1.574160	
003		.550000 x	20.419486 =	11.230717	
1444		.007000 x	76.007500 =	.532053	
			T.E =	13.336930	
7357	7357				
001		.050000 x	15.741598 =	.787080	
003		.500000 x	20.419486 =	10.209743	
1444		.006000 x	76.007500 =	.456045	
			T.E =	11.452868	
7359	7359				
021		.100000 x	2.670000 =	.267000	
002		.900000 x	17.312112 =	15.580901	
003		.900000 x	20.419486 =	18.377537	
065		.040000 x	13.610000 =	.544400	
026		20.000000 x	.099900 =	1.998000	
			T.E =	36.767838	

7360	7360			
021		.050000 x	2.670000 =	.133500
003		.700000 x	20.419486 =	14.293640
002		.700000 x	17.312112 =	12.118478
065		.027000 x	13.610000 =	.367470
026		13.000000 x	.099900 =	1.298700

			T.E =	28.211789
7361	7361			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
346.1		30.000000 x	.057200 =	1.716000
026		14.000000 x	.099900 =	1.398600
065		.015000 x	13.610000 =	.204150

			T.E =	49.351642
7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
348		8.000000 x	.103600 =	.828800
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
026		14.000000 x	.099900 =	1.398600
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	13.610000 =	.204150

			T.E =	49.722842
7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.419486 =	28.587280
002		1.000000 x	17.312112 =	17.312112
348		8.000000 x	.103600 =	.828800
346.2		22.000000 x	.103600 =	2.279200
026		14.000000 x	.099900 =	1.398600
065		.015000 x	13.610000 =	.204150

			T.E =	50.743642
7363	7363			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
346.1		35.000000 x	.057200 =	2.002000
065		.020000 x	13.610000 =	.272200
026		17.000000 x	.099900 =	1.698300

			T.E =	57.551712

7364.1	7364.1			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.099900 =	1.698300
065		.020000 x	13.610000 =	.272200
346.1		24.000000 x	.057200 =	1.372800
348		11.000000 x	.103600 =	1.139600
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534

			T.E =	58.062112
7364.2	7364.2			
021		.050000 x	2.670000 =	.133500
026		17.000000 x	.099900 =	1.698300
346.2		24.000000 x	.103600 =	2.486400
065		.020000 x	13.610000 =	.272200
003		1.600000 x	20.419486 =	32.671178
002		1.200000 x	17.312112 =	20.774534
348		11.000000 x	.103600 =	1.139600

			T.E =	59.175712
7366	7366			
021		.050000 x	2.670000 =	.133500
002		2.000000 x	17.312112 =	34.624224
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
026		10.000000 x	.099900 =	.999000
346.1		45.000000 x	.057200 =	2.574000

			T.E =	100.117987
7367.1	7367.1			
021		.050000 x	2.670000 =	.133500
1446		.010000 x	52.880500 =	.528805
003		3.000000 x	20.419486 =	61.258458
002		2.000000 x	17.312112 =	34.624224
348		15.000000 x	.103600 =	1.554000
346.1		30.000000 x	.057200 =	1.716000
026		10.000000 x	.099900 =	.999000

			T.E =	100.813987
7367.2	7367.2			
021		.050000 x	2.670000 =	.133500
346.2		30.000000 x	.103600 =	3.108000
348		15.000000 x	.103600 =	1.554000
003		3.000000 x	20.419486 =	61.258458
1446		.010000 x	52.880500 =	.528805
002		2.000000 x	17.312112 =	34.624224
026		10.000000 x	.099900 =	.999000

			T.E =	102.205987

7371.1	7371.1					
026	-	14.000000 x	.099900 =	-	1.398600	
7361		1.000000 x	49.351642 =		49.351642	
029		14.000000 x	.152800 =		2.139200	

			T.E =		50.092242	
7371.2	7371.2					
026	-	14.000000 x	.099900 =	-	1.398600	
028		14.000000 x	.000000 =		.000000	
7361		1.000000 x	49.351642 =		49.351642	

			T.E =			
7372.1	7372.1					
026	-	14.000000 x	.099900 =	-	1.398600	
029		14.000000 x	.152800 =		2.139200	
7362.1		1.000000 x	49.722842 =		49.722842	

			T.E =		50.463442	
7372.2	7372.2					
026	-	14.000000 x	.099900 =	-	1.398600	
028		14.000000 x	.000000 =		.000000	
7362.1		1.000000 x	49.722842 =		49.722842	

			T.E =			
7372.3	7372.3					
026	-	14.000000 x	.099900 =	-	1.398600	
7362.2		1.000000 x	50.743642 =		50.743642	
029		14.000000 x	.152800 =		2.139200	

			T.E =		51.484242	
7372.4	7372.4					
026	-	14.000000 x	.099900 =	-	1.398600	
028		14.000000 x	.000000 =		.000000	
7362.2		1.000000 x	50.743642 =		50.743642	

			T.E =			
7373.1	7373.1					
026	-	17.000000 x	.099900 =	-	1.698300	
029		17.000000 x	.152800 =		2.597600	
7363		1.000000 x	57.551712 =		57.551712	

			T.E =		58.451012	

7373.2	7373.2					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7363		1.000000 x	57.551712 =		57.551712	

			T.E =			
7374.1	7374.1					
026	-	17.000000 x	.099900 =	-	1.698300	
7364.1		1.000000 x	58.062112 =		58.062112	
029		17.000000 x	.152800 =		2.597600	

			T.E =		58.961412	
7374.2	7374.2					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7364.1		1.000000 x	58.062112 =		58.062112	

			T.E =			
7374.3	7374.3					
026	-	17.000000 x	.099900 =	-	1.698300	
029		17.000000 x	.152800 =		2.597600	
7364.2		1.000000 x	59.175712 =		59.175712	

			T.E =		60.075012	
7374.4	7374.4					
026	-	17.000000 x	.099900 =	-	1.698300	
028		17.000000 x	.000000 =		.000000	
7364.2		1.000000 x	59.175712 =		59.175712	

			T.E =			
7376.1	7376.1					
026	-	10.000000 x	.099900 =	-	.999000	
7366		1.000000 x	100.117987 =		100.117987	
029		10.000000 x	.152800 =		1.528000	

			T.E =		100.646987	
7376.2	7376.2					
026	-	10.000000 x	.099900 =	-	.999000	
028		10.000000 x	.000000 =		.000000	
7366		1.000000 x	100.117987 =		100.117987	

			T.E =			

7377.1	7377.1				
026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.152800 =		1.528000
7367.1		1.000000 x	100.813987 =		100.813987

			T.E =		101.342987
7377.2	7377.2				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	100.813987 =		100.813987

			T.E =		
7377.3	7377.3				
026	-	10.000000 x	.099900 =	-	.999000
7367.2		1.000000 x	102.205987 =		102.205987
029		10.000000 x	.152800 =		1.528000

			T.E =		102.734987
7377.4	7377.4				
026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.2		1.000000 x	102.205987 =		102.205987

			T.E =		
7381	7381				
456		.100000 x	1.610000 =		.161000

			T.E =		.161000
7382	7382				
443		.150000 x	1.930000 =		.289500
447		.050000 x	4.393700 =		.219685
003		.300000 x	20.419486 =		6.125846

			T.E =		6.635031
7383	7383				
002		.250000 x	17.312112 =		4.328028
003		.150000 x	20.419486 =		3.062923

			T.E =		7.390951
7384	7384				
003		.500000 x	20.419486 =		10.209743

			T.E =		10.209743

7385	7385			
003		.500000 x	20.419486 =	10.209743

			T.E =	10.209743
7386	7386			
003		.600000 x	20.419486 =	12.251692

			T.E =	12.251692
7387	7387			
261		1.500000 x	.591400 =	.887100
003		1.000000 x	20.419486 =	20.419486
7361		1.100000 x	49.351642 =	54.286806

			T.E =	75.593392
7388	7388			
003		2.500000 x	20.419486 =	51.048715
7361		.600000 x	49.351642 =	29.610985

			T.E =	80.659700
7389.1.1	7389.1.1			
7371.1		.300000 x	50.092242 =	15.027673

			T.E =	15.027673
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	60.075012 =	18.022504

			T.E =	18.022504
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.463442 =	15.139033

			T.E =	15.139033
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.484242 =	15.445273

			T.E =	15.445273
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.451012 =	17.535304

			T.E =	17.535304
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.961412 =	17.688424

			T.E =	17.688424
7389.2.1	7389.2.1			
7371.1		.500000 x	50.092242 =	25.046121

			T.E =	25.046121
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	60.075012 =	30.037506

			T.E =	30.037506

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.463442 =	25.231721

			T.E =	25.231721
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.484242 =	25.742121

			T.E =	25.742121
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.451012 =	29.225506

			T.E =	29.225506
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.961412 =	29.480706

			T.E =	29.480706
7391	7391			
003		.250000 x	20.419486 =	5.104872

			T.E =	5.104872

7392	7392				
298.1		1.081080 x	6.130000 =	6.627020	
003		.400000 x	20.419486 =	8.167794	

			T.E =	14.794815	
7393	7393				
294		.347760 x	3.518600 =	1.223628	
003		.300000 x	20.419486 =	6.125846	

			T.E =	7.349474	
7394	7394				
297.2		1.423800 x	.000000 =	.000000	
003		.400000 x	20.419486 =	8.167794	

			T.E =		
7395	7395				
522		1.100000 x	.000000 =	.000000	
003		.300000 x	20.419486 =	6.125846	

			T.E =		
7396	7396				
523		1.200000 x	7.500000 =	9.000000	
002		.350000 x	17.312112 =	6.059239	
003		.350000 x	20.419486 =	7.146820	

			T.E =	22.206059	
7397	7397				
524		1.150000 x	7.500000 =	8.625000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	22.918640	
7398	7398				
525		1.070000 x	7.840000 =	8.388800	
002		.400000 x	17.312112 =	6.924845	
003		.400000 x	20.419486 =	8.167794	

			T.E =	23.481439	
7399	7399				
526		1.100000 x	1.400000 =	1.540000	
003		.250000 x	20.419486 =	5.104872	

			T.E =	6.644872	

7416	7416			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7417	7417			
003		1.800000 x	20.419486 =	36.755075

			T.E =	36.755075
7418	7418			
003		2.600000 x	20.419486 =	53.090664

			T.E =	53.090664
7419	7419			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7420	7420			
003		1.200000 x	20.419486 =	24.503383

			T.E =	24.503383
7421	7421			
003		.800000 x	20.419486 =	16.335589

			T.E =	16.335589
7422	7422			
003		.350000 x	20.419486 =	7.146820

			T.E =	7.146820
7431	7431			
332		1.150000 x	88.540000 =	101.821000
1445		.020000 x	61.946500 =	1.238930
003		4.000000 x	20.419486 =	81.677944
1444		.001000 x	76.007500 =	.076008

			T.E =	184.813882
7432	7432			
331		1.150000 x	85.390000 =	98.198500
1445		.020000 x	61.946500 =	1.238930
1444		.001000 x	76.007500 =	.076008
003		4.400000 x	20.419486 =	89.845738

			T.E =	189.359176

7433	7433				
331		1.150000 x	85.390000 =	98.198500	
003		5.100000 x	20.419486 =	104.139379	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	203.652816	
7434	7434				
331		1.150000 x	85.390000 =	98.198500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	224.072302	
7441	7441				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	193.814279	
7442	7442				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.600000 x	20.419486 =	93.929636	

			T.E =	201.982073	
7443	7443				
331		1.250000 x	85.390000 =	106.737500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	216.275713	
7444	7444				
331		1.250000 x	85.390000 =	106.737500	
003		6.300000 x	20.419486 =	128.642762	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	236.695199	

7451	7451				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.500000 x	20.419486 =	91.887687	

			T.E =	235.768125	
7452	7452				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	

			T.E =	243.935919	
7453	7453				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		5.600000 x	20.419486 =	114.349122	

			T.E =	258.229559	
7454	7454				
333		1.150000 x	123.970000 =	142.565500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		6.600000 x	20.419486 =	134.768608	

			T.E =	278.649045	
7461	7461				
333		1.250000 x	123.970000 =	154.962500	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	
003		4.900000 x	20.419486 =	100.055481	

			T.E =	256.332919	
7462	7462				
333		1.250000 x	123.970000 =	154.962500	
003		5.300000 x	20.419486 =	108.223276	
1445		.020000 x	61.946500 =	1.238930	
1444		.001000 x	76.007500 =	.076008	

			T.E =	264.500713	

7463	7463				
333		1.250000 x	123.970000 =	154.962500	
1444		.001000 x	76.007500 =	.076008	
003		6.000000 x	20.419486 =	122.516916	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	278.794354	
7464	7464				
333		1.250000 x	123.970000 =	154.962500	
003		7.000000 x	20.419486 =	142.936402	
1444		.001000 x	76.007500 =	.076008	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	299.213840	
7491	7491				
331		.115000 x	85.390000 =	9.819850	
1444		.000100 x	76.007500 =	.007601	
1445		.002000 x	61.946500 =	.123893	
003		.915000 x	20.419486 =	18.683830	

			T.E =	28.635173	
7492	7492				
331		.125000 x	85.390000 =	10.673750	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.945000 x	20.419486 =	19.296414	

			T.E =	30.101658	
7493	7493				
333		.115000 x	123.970000 =	14.256550	
003		.990000 x	20.419486 =	20.215291	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	

			T.E =	34.603335	
7494	7494				
333		.125000 x	123.970000 =	15.496250	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		1.050000 x	20.419486 =	21.440460	

			T.E =	37.068204	

7496	7496			
331		.057500 x	85.390000 =	4.909925
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800
003		.488000 x	20.419486 =	9.964709

			T.E =	14.940381
7497	7497			
331		.062500 x	85.390000 =	5.336875
003		.504000 x	20.419486 =	10.291421
1444		.000050 x	76.007500 =	.003800
1445		.001000 x	61.946500 =	.061947

			T.E =	15.694043
7498	7498			
333		.057500 x	123.970000 =	7.128275
003		.528000 x	20.419486 =	10.781489
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800

			T.E =	17.975510
7499	7499			
333		.062500 x	123.970000 =	7.748125
003		.560000 x	20.419486 =	11.434912
1445		.001000 x	61.946500 =	.061947
1444		.000050 x	76.007500 =	.003800

			T.E =	19.248784
7501	7501			
7433		1.000000 x	203.652816 =	203.652816

			T.E =	203.652816
7503	7503			
7443		1.000000 x	216.275713 =	216.275713

			T.E =	216.275713
7506	7506			
7453		1.000000 x	258.229559 =	258.229559

			T.E =	258.229559
7508	7508			
7463		1.000000 x	278.794354 =	278.794354

			T.E =	278.794354

7511	7511				
331		.115000 x	85.390000 =	9.819850	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	
003		.915000 x	20.419486 =	18.683830	

			T.E =	28.635173	
7513	7513				
331		.125000 x	85.390000 =	10.673750	
003		.945000 x	20.419486 =	19.296414	
1445		.002000 x	61.946500 =	.123893	
1444		.000100 x	76.007500 =	.007601	

			T.E =	30.101658	
7521	7521				
331		1.150000 x	85.390000 =	98.198500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	215.828500	
7523	7523				
331		1.150000 x	85.390000 =	98.198500	
003		4.800000 x	20.419486 =	98.013533	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	197.450963	
7524	7524				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	232.535295	
7526	7526				
331		1.250000 x	85.390000 =	106.737500	
1445		.020000 x	61.946500 =	1.238930	
003		5.000000 x	20.419486 =	102.097430	

			T.E =	210.073860	
7531	7531				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	20.419486 =	106.181327	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	209.241257	

7532	7532				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	61.946500 =	1.238930	
003		5.400000 x	20.419486 =	110.265224	

			T.E =	222.179154	
7533	7533				
334		1.150000 x	132.830000 =	152.754500	
1445		.020000 x	61.946500 =	1.238930	
003		5.700000 x	20.419486 =	116.391070	

			T.E =	270.384500	
7534	7534				
334		1.250000 x	132.830000 =	166.037500	
1445		.020000 x	61.946500 =	1.238930	
003		6.100000 x	20.419486 =	124.558865	

			T.E =	291.835295	
7536	7536				
334		.300000 x	132.830000 =	39.849000	
1445		.010000 x	61.946500 =	.619465	
003		3.000000 x	20.419486 =	61.258458	

			T.E =	101.726923	
7537	7537				
336		.300000 x	.000000 =	.000000	
1445		.010000 x	61.946500 =	.619465	
003		4.000000 x	20.419486 =	81.677944	

			T.E =		
7541	7541				
332		.170000 x	88.540000 =	15.051800	
334		.350000 x	132.830000 =	46.490500	
1445		.010000 x	61.946500 =	.619465	
003		3.700000 x	20.419486 =	75.552098	

			T.E =	137.713863	
7542	7542				
332		.170000 x	88.540000 =	15.051800	
336		.350000 x	.000000 =	.000000	
003		4.200000 x	20.419486 =	85.761841	
1445		.010000 x	61.946500 =	.619465	

			T.E =		

7543	7543			
332		.170000 x	88.540000 =	15.051800
338		.350000 x	.000000 =	.000000
1445		.010000 x	61.946500 =	.619465
003		4.800000 x	20.419486 =	98.013533

			T.E =	
7551	7551			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402

			T.E =	
7552	7552			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	61.946500 =	1.238930
003		7.000000 x	20.419486 =	142.936402

			T.E =	271.468832
7553	7553			
323		1.150000 x	126.500000 =	145.475000
003		7.000000 x	20.419486 =	142.936402
1445		.020000 x	61.946500 =	1.238930

			T.E =	289.650332
7554	7554			
321		1.150000 x	.000000 =	.000000
1445		.020000 x	61.946500 =	1.238930
003		9.000000 x	20.419486 =	183.775374

			T.E =	
7555	7555			
322		1.150000 x	110.690000 =	127.293500
1445		.020000 x	61.946500 =	1.238930
003		9.000000 x	20.419486 =	183.775374

			T.E =	312.307804
7556	7556			
323		1.150000 x	126.500000 =	145.475000
1445		.020000 x	61.946500 =	1.238930
003		9.000000 x	20.419486 =	183.775374

			T.E =	330.489304

7558	7558				
331		.080000 x	85.390000 =	6.831200	
1445		.003000 x	61.946500 =	.185840	
003		1.500000 x	20.419486 =	30.629229	

			T.E =	37.646269	
7559	7559				
331		.080000 x	85.390000 =	6.831200	
003		1.500000 x	20.419486 =	30.629229	
1445		.003000 x	61.946500 =	.185840	

			T.E =	37.646269	
7561	7561				
332		1.150000 x	88.540000 =	101.821000	
003		5.200000 x	20.419486 =	106.181327	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	209.241257	
7562	7562				
334		1.150000 x	132.830000 =	152.754500	
003		5.700000 x	20.419486 =	116.391070	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	270.384500	
7563	7563				
332		1.250000 x	88.540000 =	110.675000	
1445		.020000 x	61.946500 =	1.238930	
003		5.400000 x	20.419486 =	110.265224	

			T.E =	222.179154	
7564	7564				
334		1.250000 x	132.830000 =	166.037500	
003		6.100000 x	20.419486 =	124.558865	
1445		.020000 x	61.946500 =	1.238930	

			T.E =	291.835295	
7565	7565				
003		1.500000 x	20.419486 =	30.629229	

			T.E =	30.629229	
7566	7566				
7561		1.500000 x	209.241257 =	313.861886	

			T.E =	313.861886	

7567	7567			
7562		1.500000 x	270.384500 =	405.576750

			T.E =	405.576750
7568	7568			
7563		1.500000 x	222.179154 =	333.268731

			T.E =	333.268731
7569	7569			
7564		1.500000 x	291.835295 =	437.752943

			T.E =	437.752943
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	20.419486 =	61.258458
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	196.650000 =	196.650000
327.3		.030000 x	196.650000 =	5.899500
003		3.000000 x	20.419486 =	61.258458

			T.E =	263.807958
7572	7572			
328		1.000000 x	.000000 =	.000000
328		.030000 x	.000000 =	.000000
003		4.000000 x	20.419486 =	81.677944

			T.E =	
7576	7576			
331		1.150000 x	85.390000 =	98.198500
003		3.800000 x	20.419486 =	77.594047

			T.E =	175.792547

7577	7577				
334		1.150000 x	132.830000 =	152.754500	
003		4.200000 x	20.419486 =	85.761841	

			T.E =	238.516341	
7578	7578				
336		1.150000 x	.000000 =	.000000	
003		4.700000 x	20.419486 =	95.971584	

			T.E =		
7581	7581				
326		1.050000 x	63.530000 =	66.706500	
3211		.020000 x	134.257521 =	2.685150	
1445		.005000 x	61.946500 =	.309733	
003		2.300000 x	20.419486 =	46.964818	

			T.E =	116.666201	
7601	7601				
401		1.100000 x	12.200000 =	13.420000	
003		.500000 x	20.419486 =	10.209743	
457		.500000 x	.803800 =	.401900	

			T.E =	24.031643	
7602	7602				
403		1.100000 x	14.290000 =	15.719000	
003		.550000 x	20.419486 =	11.230717	
457		.500000 x	.803800 =	.401900	

			T.E =	27.351617	
7603	7603				
406		1.100000 x	17.660000 =	19.426000	
003		.650000 x	20.419486 =	13.272666	
457		.500000 x	.803800 =	.401900	

			T.E =	33.100566	
7604.1	7604.1				
409		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.803800 =	.401900	
003		.750000 x	20.419486 =	15.314615	

			T.E =	38.849515	

7604.2	7604.2			
410		1.100000 x	28.610000 =	31.471000
457		.500000 x	.803800 =	.401900
003		.750000 x	20.419486 =	15.314615

			T.E =	47.187515
7606	7606			
401		1.100000 x	12.200000 =	13.420000
003		.600000 x	20.419486 =	12.251692

			T.E =	25.671692
7607	7607			
403		1.100000 x	14.290000 =	15.719000
003		.650000 x	20.419486 =	13.272666

			T.E =	28.991666
7608	7608			
406		1.100000 x	17.660000 =	19.426000
003		.750000 x	20.419486 =	15.314615

			T.E =	34.740615
7609.1	7609.1			
409		1.100000 x	21.030000 =	23.133000
003		.850000 x	20.419486 =	17.356563

			T.E =	40.489563
7609.2	7609.2			
410		1.100000 x	28.610000 =	31.471000
003		.850000 x	20.419486 =	17.356563

			T.E =	48.827563
7611	7611			
411		1.100000 x	26.710000 =	29.381000
457		.500000 x	.803800 =	.401900
003		.500000 x	20.419486 =	10.209743

			T.E =	39.992643
7612	7612			
412		1.100000 x	28.830000 =	31.713000
003		.550000 x	20.419486 =	11.230717
457		.500000 x	.803800 =	.401900

			T.E =	43.345617

7613	7613				
411		1.100000 x	26.710000 =	29.381000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	41.632692	
7614	7614				
412		1.100000 x	28.830000 =	31.713000	
003		.650000 x	20.419486 =	13.272666	

			T.E =	44.985666	
7616	7616				
414		1.100000 x	21.030000 =	23.133000	
003		.600000 x	20.419486 =	12.251692	
457		.500000 x	.803800 =	.401900	

			T.E =	35.786592	
7617	7617				
415		1.100000 x	21.030000 =	23.133000	
003		.650000 x	20.419486 =	13.272666	
457		.500000 x	.803800 =	.401900	

			T.E =	36.807566	
7618	7618				
414		1.100000 x	21.030000 =	23.133000	
003		.700000 x	20.419486 =	14.293640	

			T.E =	37.426640	
7619	7619				
415		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.419486 =	15.314615	

			T.E =	38.447615	
7621	7621				
418		1.100000 x	29.450000 =	32.395000	
003		1.200000 x	20.419486 =	24.503383	
457		.800000 x	.803800 =	.643040	

			T.E =	57.541423	
7622	7622				
419		1.100000 x	29.450000 =	32.395000	
003		1.400000 x	20.419486 =	28.587280	
457		.800000 x	.803800 =	.643040	

			T.E =	61.625320	

7626.1	7626.1			
298.2		18.000000 x	5.300000 =	95.400000
002		7.000000 x	17.312112 =	121.184784
421		1.000000 x	97.840000 =	97.840000
003		7.000000 x	20.419486 =	142.936402

			T.E =	457.361186
7626.2	7626.2			
298.2		18.000000 x	5.300000 =	95.400000
422		1.000000 x	134.470000 =	134.470000
003		7.000000 x	20.419486 =	142.936402
002		7.000000 x	17.312112 =	121.184784

			T.E =	493.991186
7627.1	7627.1			
298.2		16.000000 x	5.300000 =	84.800000
421		1.000000 x	97.840000 =	97.840000
003		6.000000 x	20.419486 =	122.516916
002		6.000000 x	17.312112 =	103.872672

			T.E =	409.029588
7627.2	7627.2			
298.2		16.000000 x	5.300000 =	84.800000
002		6.000000 x	17.312112 =	103.872672
003		6.000000 x	20.419486 =	122.516916
422		1.000000 x	134.470000 =	134.470000

			T.E =	445.659588
7631	7631			
426		1.100000 x	.000000 =	.000000
003		.050000 x	20.419486 =	1.020974

			T.E =	
7636	7636			
428		1.100000 x	4.390000 =	4.829000
003		.060000 x	20.419486 =	1.225169

			T.E =	6.054169
7637	7637			
429		1.100000 x	5.390000 =	5.929000
003		.080000 x	20.419486 =	1.633559

			T.E =	7.562559

7638	7638				
430		1.100000 x	7.480000 =	8.228000	
003		.100000 x	20.419486 =	2.041949	

			T.E =	10.269949	
7641	7641				
431		1.000000 x	.000000 =	.000000	
003		.060000 x	20.419486 =	1.225169	

			T.E =		
7642	7642				
432		1.000000 x	.000000 =	.000000	
003		.060000 x	20.419486 =	1.225169	

			T.E =		
7701	7701				
024		.001500 x	50.000000 =	.075000	
003		.120000 x	20.419486 =	2.450338	
002		.050000 x	17.312112 =	.865606	

			T.E =	3.390944	
7702	7702				
024		.001800 x	50.000000 =	.090000	
003		.080000 x	20.419486 =	1.633559	
002		.050000 x	17.312112 =	.865606	

			T.E =	2.589164	
7706	7706				
024		.002000 x	50.000000 =	.100000	
003		.150000 x	20.419486 =	3.062923	
002		.080000 x	17.312112 =	1.384969	

			T.E =	4.547892	
7707	7707				
024		.002300 x	50.000000 =	.115000	
002		.100000 x	17.312112 =	1.731211	
003		.090000 x	20.419486 =	1.837754	

			T.E =	3.683965	

7708	7708			
024		.002500 x	50.000000 =	.125000
002		.120000 x	17.312112 =	2.077453
003		.180000 x	20.419486 =	3.675507

			T.E =	5.877961
7709	7709			
024		.002800 x	50.000000 =	.140000
002		.150000 x	17.312112 =	2.596817
003		.120000 x	20.419486 =	2.450338

			T.E =	5.187155
7711	7711			
002		.050000 x	17.312112 =	.865606
1485		.200000 x	.831209 =	.166242
003		.200000 x	20.419486 =	4.083897

			T.E =	5.115745
7712	7712			
002		.080000 x	17.312112 =	1.384969
1485		.250000 x	.831209 =	.207802
003		.250000 x	20.419486 =	5.104872

			T.E =	6.697643
7713	7713			
002		.160000 x	17.312112 =	2.769938
1485		.280000 x	.831209 =	.232739
003		.300000 x	20.419486 =	6.125846

			T.E =	9.128522
7720	7720			
443		.080000 x	1.930000 =	.154400
1485		.200000 x	.831209 =	.166242
003		.300000 x	20.419486 =	6.125846
002		.100000 x	17.312112 =	1.731211

			T.E =	8.177699
7721	7721			
002		.070000 x	17.312112 =	1.211848
1485		.200000 x	.831209 =	.166242
003		.200000 x	20.419486 =	4.083897

			T.E =	5.461987

7722.1.1	7722.1.1			
7720		.300000 x	8.177699 =	2.453310

			T.E =	2.453310
7722.1.2	7722.1.2			
7721		.300000 x	5.461987 =	1.638596

			T.E =	1.638596
7722.2.1	7722.2.1			
7720		.400000 x	8.177699 =	3.271080

			T.E =	3.271080
7722.2.2	7722.2.2			
7721		.400000 x	5.461987 =	2.184795

			T.E =	2.184795
7725	7725			
471		.300000 x	4.100000 =	1.230000
002		.150000 x	17.312112 =	2.596817
003		.250000 x	20.419486 =	5.104872

			T.E =	8.931688
7735	7735			
441		.350000 x	.075500 =	.026425
003		.150000 x	20.419486 =	3.062923
444		.150000 x	2.143200 =	.321480

			T.E =	3.410828
7736	7736			
441		.500000 x	.075500 =	.037750
444		.085000 x	2.143200 =	.182172
003		.250000 x	20.419486 =	5.104872
445		.010000 x	1.553500 =	.015535
446		.005000 x	2.540000 =	.012700

			T.E =	5.353029
7737	7737			
441		.200000 x	.075500 =	.015100
003		.300000 x	20.419486 =	6.125846
1489		.200000 x	.869600 =	.173920
1488		.600000 x	.761115 =	.456669

			T.E =	6.771535

7738	7738			
441		.200000 x	.075500 =	.015100
003		.300000 x	20.419486 =	6.125846
1489		.200000 x	.869600 =	.173920
1488		.300000 x	.761115 =	.228335

			T.E =	6.543200
7739	7739			
441		.100000 x	.075500 =	.007550
003		.150000 x	20.419486 =	3.062923
467		.100000 x	3.380000 =	.338000

			T.E =	3.408473
7740	7740			
442		.250000 x	.118300 =	.029575
003		.250000 x	20.419486 =	5.104872
1492		.250000 x	2.756980 =	.689245

			T.E =	5.823692
7741	7741			
442		.250000 x	.118300 =	.029575
462		.250000 x	.000000 =	.000000
003		.250000 x	20.419486 =	5.104872

			T.E =	
7742	7742			
442		.250000 x	.118300 =	.029575
463		.125000 x	3.970000 =	.496250
003		.200000 x	20.419486 =	4.083897

			T.E =	4.609722
7743	7743			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
464		.125000 x	3.720000 =	.465000

			T.E =	3.557498
7744	7744			
442		.250000 x	.118300 =	.029575
003		.150000 x	20.419486 =	3.062923
465		.125000 x	5.870000 =	.733750

			T.E =	3.826248

7745	7745			
442		.250000 x	.118300 =	.029575
1489		.200000 x	.869600 =	.173920
1492		.250000 x	2.756980 =	.689245
003		.800000 x	20.419486 =	16.335589

			T.E =	17.228329
7746	7746			
441		.350000 x	.075500 =	.026425
443		.090000 x	1.930000 =	.173700
003		.150000 x	20.419486 =	3.062923

			T.E =	3.263048
7747	7747			
441		.350000 x	.075500 =	.026425
003		.250000 x	20.419486 =	5.104872
443		.170000 x	1.930000 =	.328100

			T.E =	5.459397
7748	7748			
443		.090000 x	1.930000 =	.173700
450		.060000 x	2.760000 =	.165600
003		.200000 x	20.419486 =	4.083897
002		.100000 x	17.312112 =	1.731211
445		.030000 x	1.553500 =	.046605

			T.E =	6.201013
7749	7749			
443		.160000 x	1.930000 =	.308800
445		.050000 x	1.553500 =	.077675
003		.250000 x	20.419486 =	5.104872
002		.150000 x	17.312112 =	2.596817
450		.100000 x	2.760000 =	.276000

			T.E =	8.364163
7751	7751			
003		.150000 x	20.419486 =	3.062923
1491		.125000 x	1.488894 =	.186112

			T.E =	3.249035
7752	7752			
003		.250000 x	20.419486 =	5.104872
1491		.250000 x	1.488894 =	.372224

			T.E =	5.477095

7753	7753			
441		1.000000 x	.075500 =	.075500
443		.080000 x	1.930000 =	.154400
003		.650000 x	20.419486 =	13.272666
1491		.200000 x	1.488894 =	.297779
1490		.090000 x	1.546426 =	.139178

			T.E =	13.939523
7754	7754			
441		.800000 x	.075500 =	.060400
1487		.090000 x	.605006 =	.054451
003		.800000 x	20.419486 =	16.335589
1491		.200000 x	1.488894 =	.297779
1490		.090000 x	1.546426 =	.139178

			T.E =	16.887396
7755	7755			
442		.250000 x	.118300 =	.029575
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.756980 =	.441117
1491		.200000 x	1.488894 =	.297779

			T.E =	21.187957
7756	7756			
442		.300000 x	.118300 =	.035490
003		.350000 x	20.419486 =	7.146820
1492		.300000 x	2.756980 =	.827094

			T.E =	8.009404
7761	7761			
441		.650000 x	.075500 =	.049075
1489		.200000 x	.869600 =	.173920
1488		.600000 x	.761115 =	.456669
003		.800000 x	20.419486 =	16.335589
473		.100000 x	2.750000 =	.275000
467		.100000 x	3.380000 =	.338000

			T.E =	17.628253
7762	7762			
473		.100000 x	2.750000 =	.275000
003		.200000 x	20.419486 =	4.083897

			T.E =	4.358897

7764	7764			
474		.125000 x	3.770000 =	.471250
003		.100000 x	20.419486 =	2.041949

			T.E =	2.513199
7765	7765			
475		.125000 x	6.230000 =	.778750
003		.200000 x	20.419486 =	4.083897

			T.E =	4.862647
7766	7766			
442		.275000 x	.118300 =	.032533
473		.110000 x	2.750000 =	.302500
003		.880000 x	20.419486 =	17.969148
1492		.275000 x	2.756980 =	.758170

			T.E =	19.062350
7767.1	7767.1			
7755		.150000 x	21.187957 =	3.178194

			T.E =	3.178194
7767.2	7767.2			
442		.250000 x	.118300 =	.029575
003		1.000000 x	20.419486 =	20.419486
1492		.160000 x	2.756980 =	.441117
473		.200000 x	2.750000 =	.550000

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.150000 x	21.440178 =	3.216027

7767.3	7767.3			
7755		.250000 x	21.187957 =	5.296989

			T.E =	5.296989
7767.4	7767.4			
442		.250000 x	.118300 =	.029575
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486
473		.200000 x	2.750000 =	.550000

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.250000 x	21.440178 =	5.360044

7767.5	7767.5			
7755		.350000 x	21.187957 =	7.415785

			T.E =	7.415785
7767.6	7767.6			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.350000 x	21.440178 =	7.504062

7767.7	7767.7			
7755		.450000 x	21.187957 =	9.534581

			T.E =	9.534581
7767.8	7767.8			
442		.250000 x	.118300 =	.029575
473		.200000 x	2.750000 =	.550000
1492		.160000 x	2.756980 =	.441117
003		1.000000 x	20.419486 =	20.419486

			AΘΡΟΙΣΜΑ =	21.440178
	T.E =	.450000 x	21.440178 =	9.648080

7768	7768			
460		.200000 x	4.250000 =	.850000
003		.450000 x	20.419486 =	9.188769
002		.450000 x	17.312112 =	7.790450
460		.030000 x	4.250000 =	.127500

			T.E =	17.956719
7769	7769			
460		.200000 x	4.250000 =	.850000
003		.200000 x	20.419486 =	4.083897
002		.200000 x	17.312112 =	3.462422
460		.030000 x	4.250000 =	.127500

			T.E =	8.523820
7770	7770			
460		.090000 x	4.250000 =	.382500
460		.020000 x	4.250000 =	.085000
002		.150000 x	17.312112 =	2.596817
003		.150000 x	20.419486 =	3.062923

			T.E =	6.127240

7771	7771				
441		1.000000 x	.075500 =	.075500	
1488		.160000 x	.761115 =	.121778	
1487		.080000 x	.605006 =	.048400	
473		.100000 x	2.750000 =	.275000	
003		1.300000 x	20.419486 =	26.545332	
467		.110000 x	3.380000 =	.371800	

			T.E =	27.437811	
7772	7772				
441		1.000000 x	.075500 =	.075500	
458		.100000 x	5.030000 =	.503000	
003		.500000 x	20.419486 =	10.209743	
443		.100000 x	1.930000 =	.193000	

			T.E =	10.981243	
7773	7773				
441		1.000000 x	.075500 =	.075500	
003		.600000 x	20.419486 =	12.251692	
459		.100000 x	5.030000 =	.503000	
443		.100000 x	1.930000 =	.193000	

			T.E =	13.023192	
7774	7774				
442		.250000 x	.118300 =	.029575	
1492		.160000 x	2.756980 =	.441117	
003		1.000000 x	20.419486 =	20.419486	
473		.200000 x	2.750000 =	.550000	

			T.E =	21.440178	
7785.1	7785.1				
441		.350000 x	.075500 =	.026425	
477		.160000 x	.000000 =	.000000	
476		.120000 x	2.366400 =	.283968	
003		.700000 x	20.419486 =	14.293640	

			T.E =		
7785.2	7785.2				
441		.350000 x	.075500 =	.026425	
478		.160000 x	2.937600 =	.470016	
476		.120000 x	2.366400 =	.283968	
003		.700000 x	20.419486 =	14.293640	

			T.E =	15.074049	

7786.1	7786.1			
441		.350000 x	.075500 =	.026425
1488		.600000 x	.761115 =	.456669
1489		.200000 x	.869600 =	.173920
477		.110000 x	.000000 =	.000000
003		1.000000 x	20.419486 =	20.419486

			T.E =	
7786.2	7786.2			
441		.350000 x	.075500 =	.026425
1489		.200000 x	.869600 =	.173920
1488		.600000 x	.761115 =	.456669
478		.110000 x	2.937600 =	.323136
003		1.000000 x	20.419486 =	20.419486

			T.E =	21.399636
7787	7787			
441		1.000000 x	.075500 =	.075500
1488		.160000 x	.761115 =	.121778
1487		.080000 x	.605006 =	.048400
003		1.000000 x	20.419486 =	20.419486
477		.160000 x	.000000 =	.000000
476		.090000 x	2.366400 =	.212976

			T.E =	
7788	7788			
441		.250000 x	.075500 =	.018875
003		.700000 x	20.419486 =	14.293640
479		1.000000 x	1.815600 =	1.815600

			T.E =	16.128115
7791	7791			
441		1.000000 x	.075500 =	.075500
003		.500000 x	20.419486 =	10.209743
1491		.200000 x	1.488894 =	.297779
1487		.050000 x	.605006 =	.030250

			T.E =	10.613272
7792	7792			
482		.150000 x	1.291000 =	.193650
003		.500000 x	20.419486 =	10.209743

			T.E =	10.403393

7793	7793				
480		.500000 x	3.366000 =	1.683000	
003		.200000 x	20.419486 =	4.083897	

			T.E =	5.766897	
7794	7794				
482		.150000 x	1.291000 =	.193650	
003		.500000 x	20.419486 =	10.209743	

			T.E =	10.403393	
7797	7797				
201		.000500 x	290.000000 =	.145000	
002		.060000 x	17.312112 =	1.038727	

			T.E =	1.183727	
7798	7798				
201		.000600 x	290.000000 =	.174000	
002		.070000 x	17.312112 =	1.211848	

			T.E =	1.385848	
7801	7801				
496		1.200000 x	1.905500 =	2.286600	
003		.150000 x	20.419486 =	3.062923	

			T.E =	5.349523	
7806	7806				
498		1.150000 x	1.011600 =	1.163340	
003		.300000 x	20.419486 =	6.125846	

			T.E =	7.289186	
7807	7807				
499		1.150000 x	1.386800 =	1.594820	
003		.400000 x	20.419486 =	8.167794	

			T.E =	9.762614	
7808	7808				
500		1.150000 x	2.039600 =	2.345540	
003		.600000 x	20.419486 =	12.251692	

			T.E =	14.597232	

7809	7809				
501		1.200000 x	2.763000 =	3.315600	
003		.800000 x	20.419486 =	16.335589	

			T.E =	19.651189	
7810	7810				
502		1.200000 x	3.807000 =	4.568400	
003		.900000 x	20.419486 =	18.377537	

			T.E =	22.945937	
7811	7811				
503		1.200000 x	.905500 =	1.086600	
003		.800000 x	20.419486 =	16.335589	

			T.E =	17.422189	
7812	7812				
504		1.300000 x	1.199100 =	1.558830	
003		.900000 x	20.419486 =	18.377537	

			T.E =	19.936367	
7813	7813				
505		1.000000 x	19.170000 =	19.170000	
003		.600000 x	20.419486 =	12.251692	

			T.E =	31.421692	
7901	7901				
490		1.080000 x	.730000 =	.788400	
003		.200000 x	20.419486 =	4.083897	

			T.E =	4.872297	
7902	7902				
527		1.050000 x	5.120000 =	5.376000	
003		1.000000 x	20.419486 =	20.419486	

			T.E =	25.795486	
7903	7903				
528		1.050000 x	6.910000 =	7.255500	
003		.600000 x	20.419486 =	12.251692	

			T.E =	19.507192	

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.419486 =	10.209743

			T.E =	15.963743
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.290700 =	1.419770
003		.150000 x	20.419486 =	3.062923
002		.300000 x	17.312112 =	5.193634

			T.E =	10.552327
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.419486 =	3.062923
002		.350000 x	17.312112 =	6.059239

			T.E =	12.066162
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.419486 =	3.062923
002		.400000 x	17.312112 =	6.924845

			T.E =	11.809768
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.419486 =	1.633559

			T.E =	2.084559
7915.1	7915.1			
7911		.850000 x	10.552327 =	8.969478

			T.E =	8.969478
7915.2	7915.2			
7912		.850000 x	12.066162 =	10.256238

			T.E =	10.256238
7915.3	7915.3			
7913		.850000 x	11.809768 =	10.038303

			T.E =	10.038303

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.312112 =	.692484

			T.E =	2.134484
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.312112 =	.865606

			T.E =	3.121306
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.312112 =	.865606

			T.E =	2.081006
7931	7931			
519		1.050000 x	47.670000 =	50.053500
003		1.500000 x	20.419486 =	30.629229

			T.E =	80.682729
7932.1	7932.1			
514		.000000 x	38.800000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	37.340000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	38.800000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	37.340000 =	.000000
003		.000000 x	20.419486 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	6.000000 =	6.900000
002		.500000 x	17.312112 =	8.656056
003		.500000 x	20.419486 =	10.209743

			T.E =	25.765799
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.419486 =	5.104872

			T.E =	5.479872
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.419486 =	2.041949

			T.E =	2.791949
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.312112 =	5.193634
003		.300000 x	20.419486 =	6.125846
251		.100000 x	.825000 =	.082500

			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.741598 =	1.574160

			T.E =	3.394160
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.741598 =	1.574160

			T.E =	9.124160