

. .& .

3

μ

μ

2

μ

2012

001	15.643441
002	17.205541
003	20.290479
004	23.647167
005	21.561131
006	181.786626
007	181.786626
008	16.609513
009	.074800
011	55.210000
012	4.530000
013	27.370000
014	268.420000
015	206.720000
016	32.560000
017	380.180000
018.1	2.990000
018.2	4.530000
019.1	2.990000
019.2	4.530000
021	2.670000
022	.070000
024	45.000000
026	.099900
027	.119300
029	.151500
032	36.000000
035	.088300
036	.090700
040	.210000
051	13.900000
052	13.900000
053	.085000
054	.085000
055	.090000
056	9.550000
057	9.550000
058	8.200000
061	12.240000
062	12.240000
065	11.660000
066	35.000000
067	45.500000
081	9.940000
101	
102	
111	.072100
112	.079100
113	.570000
114	
116	.082400
117	
118	
124	5.900000
127	81.220000
128	88.240000
131	.620000
132	.880000
142	.385000

146	.415000
155	2.233400
161	6.360000
163	6.550000
164	
165	
166	
173	.256100
181	
201	290.000000
203.2	370.000000
203.4	290.000000
205	480.000000
208	1,435.000000
210	
211	750.000000
212	1,500.000000
214	1,000.000000
219	3.500000
223.1	2,100.000000
223.2	1,700.000000
223.3	1,550.000000
223.4	1,600.000000
225	4.000000
226	13.000000
227	13.000000
228	35.000000
229	
230	
231	22.000000
232	45.000000
233	21.300000
234	2.700000
236	1.550000
237	1.850000
238	2.600000
240	1.400000
241	
242	1.500000
243.1	2.700000
243.2	3.800000
243.3	4.500000
243.5	5.900000
244	
245	18.000000
246	13.000000
249	20.000000
251	.927000
252	2.184000
253	2.758000
254	3.532000
258	7.930000
259	25.592500
260	.559100
261	.611900
262	.559100
264	1.097900
265	.857700
266	.622500

267	.931000
268	1.041000
271	.971000
272	.894300
273	1.084300
274	1.441200
276	.765500
277	1.007600
278	4.120200
279	4.257500
280	1.144500
281	6.615200
282	.961000
283	1.305700
284	
285	.086000
286	1.898100
288	2.060000
289	.972500
290	3.670000
291	4.500000
293	
294	3.518600
295	6.490000
296	12.470000
297.2	
298.1	7.020000
298.2	5.730000
321	
322	99.620000
323	113.850000
326	57.180000
327.1	
327.2	
327.3	176.980000
328	
331	76.850000
332	79.680000
333	111.570000
334	119.540000
336	
338	
346.1	.057200
346.2	.103600
348	.103600
351	.735200
352	1.133000
354	.985400
356	.661600
357	1.441300
358	3.338500
360	14.938000
361	1.249900
362	1.397000
363	1.779400
364	1.133000
366	5.000500
370	.294100
371	1.779400

372	2.470800
373	2.735500
375	3.470900
376	.220400
377	.926400
378	14.950000
379	27.450000
380	16.560000
381	74.770000
386	28.630000
388	48.870000
390	1.500000
392	27.420000
401	12.200000
403	14.290000
406	17.660000
409	21.030000
410	28.610000
411	26.710000
412	28.830000
414	21.030000
415	21.030000
418	29.450000
419	29.450000
421	97.840000
422	134.470000
428	4.390000
429	5.390000
430	7.480000
441	.077700
442	.121800
443	1.987900
444	2.207500
445	1.600000
446	2.662500
447	4.525500
450	2.842800
451	1.214200
453	.085000
455	3.090000
456	1.658300
457	.827900
458	5.280000
459	5.280000
460	4.377500
462	
463	4.089100
464	3.630000
465	6.180000
467	3.397500
471	3.960000
473	2.832500
474	3.883100
475	6.416900
476	2.437300
477	
478	3.060000
479	1.876600
480	

481	5.467500
482	1.539700
483	.167500
484	4.550000
485	1.271500
487	13.884000
488	5.500000
490	.730000
491	.540000
492	.540000
493	.730000
494	5.480000
495	
496	.887400
498	.991400
499	1.359000
500	1.998800
501	2.700000
502	3.780000
503	.887400
504	1.175100
505	19.170000
506	1.431700
507	1.880000
508	.860000
509	.410000
510	3.020000
511	.489500
512	.437500
514	45.650000
515	45.970000
519	53.140000
520	43.930000
521	2.461700
523	7.500000
524	7.500000
525	7.840000
526	1.400000
527	5.120000
528	6.910000
529	1.400000
530	2.190000
531	1.180000
535	7.050000
536	2.500000
537	1.700000
565.3	3.800000
565.5	5.650000
565.6	7.800000
566.3	5.050000
566.5	7.750000
566.6	10.300000

1101	1101			
001		.500000 x	15.643441 =	7.821721

			B.T =	7.821721
1102	1102			
001		1.000000 x	15.643441 =	15.643441

			B.T =	15.643441
1103	1103			
001		.300000 x	15.643441 =	4.693032

			B.T =	4.693032
1104	1104			
015		1.000000 x	206.720000 =	206.720000
291		2.200000 x	4.500000 =	9.900000
004		7.000000 x	23.647167 =	165.530169
002		7.000000 x	17.205541 =	120.438787
484		5.250000 x	4.550000 =	23.887500
485		83.000000 x	1.271500 =	105.534500

			=	632.010956
	B.T =	.004000 x	632.010956 =	2.528044

1111	1111			
006		.060000 x	181.786626 =	10.907198

			B.T =	10.907198
1112	1112			
006		.090000 x	181.786626 =	16.360796

			B.T =	16.360796
1116	1116			
007		.025000 x	181.786626 =	4.544666

			B.T =	4.544666
1117	1117			
007		.110000 x	181.786626 =	19.996529

			B.T =	19.996529
1121	1121			
009		4.000000 x	.074800 =	.299200

			B.T =	.299200

1122	1122			
009		5.000000 x	.074800 =	.374000

			B.T =	.374000
1123	1123			
009		2.000000 x	.074800 =	.149600

			B.T =	.149600
1126	1126			
001		.400000 x	15.643441 =	6.257376

			B.T =	6.257376
1127	1127			
001		.130000 x	15.643441 =	2.033647

			B.T =	2.033647
1128	1128			
006		.024000 x	181.786626 =	4.362879

			B.T =	4.362879
1131	1131			
007		.090000 x	181.786626 =	16.360796

			B.T =	16.360796
1136	1136			
009		1.000000 x	.074800 =	.074800

			B.T =	.074800
1137	1137			
009		1.500000 x	.074800 =	.112200

			B.T =	.112200
1138	1138			
009		2.500000 x	.074800 =	.187000

			B.T =	.187000

1401	1401			
021		.300000 x	2.670000 =	.801000
040		1,150.000000 x	.210000 =	241.500000

			B.T =	242.301000
1407	1407			
021		1.500000 x	2.670000 =	4.005000
022		480.000000 x	.070000 =	33.600000

			B.T =	37.605000
1411	1411			
021		.200000 x	2.670000 =	.534000
051		.960000 x	13.900000 =	13.344000
1407		.320000 x	37.605000 =	12.033600

			B.T =	25.911600
1412	1412			
021		.200000 x	2.670000 =	.534000
051		.900000 x	13.900000 =	12.510000
1407		.360000 x	37.605000 =	13.537800

			B.T =	26.581800
1413	1413			
021		.200000 x	2.670000 =	.534000
051		.840000 x	13.900000 =	11.676000
1407		.420000 x	37.605000 =	15.794100

			B.T =	28.004100
1416	1416			
021		.200000 x	2.670000 =	.534000
1407		.250000 x	37.605000 =	9.401250
051		.960000 x	13.900000 =	13.344000
026		150.000000 x	.099900 =	14.985000

			B.T =	38.264250
1417	1417			
021		.200000 x	2.670000 =	.534000
026		150.000000 x	.099900 =	14.985000
1407		.290000 x	37.605000 =	10.905450
051		.900000 x	13.900000 =	12.510000

			B.T =	38.934450

1418 1418

021	.200000 x	2.670000 =	.534000
1407	.350000 x	37.605000 =	13.161750
051	.840000 x	13.900000 =	11.676000
026	150.000000 x	.099900 =	14.985000

B.T = 40.356750

1421 1421

021	.200000 x	2.670000 =	.534000
051	.540000 x	13.900000 =	7.506000
1407	.540000 x	37.605000 =	20.306700
039	4.000000 x	.000000 =	.000000

B.T =

1422 1422

021	.250000 x	2.670000 =	.667500
035	75.000000 x	.088300 =	6.622500
1407	.620000 x	37.605000 =	23.315100
051	.330000 x	13.900000 =	4.587000
039	5.000000 x	.000000 =	.000000

B.T =

1426 1426

021	.200000 x	2.670000 =	.534000
1407	.450000 x	37.605000 =	16.922250
055	1,500.000000 x	.090000 =	135.000000

B.T = 152.456250

1427 1427

021	.200000 x	2.670000 =	.534000
1407	.340000 x	37.605000 =	12.785700
055	1,500.000000 x	.090000 =	135.000000
026	150.000000 x	.099900 =	14.985000

B.T = 163.304700

1428 1428

021	.200000 x	2.670000 =	.534000
051	.200000 x	13.900000 =	2.780000
055	1,200.000000 x	.090000 =	108.000000
1407	.400000 x	37.605000 =	15.042000

B.T = 126.356000

1429	1429				
021		.200000 x	2.670000 =	.534000	
035		200.000000 x	.088300 =	17.660000	
055		1,200.000000 x	.090000 =	108.000000	
1407		.400000 x	37.605000 =	15.042000	

			B.T =	141.236000	
1431	1431				
021		.300000 x	2.670000 =	.801000	
032		.960000 x	36.000000 =	34.560000	
1407		.320000 x	37.605000 =	12.033600	

			B.T =	47.394600	
1432	1432				
021		.300000 x	2.670000 =	.801000	
1407		.320000 x	37.605000 =	12.033600	
051		.640000 x	13.900000 =	8.896000	
032		.320000 x	36.000000 =	11.520000	

			B.T =	33.250600	
1436	1436				
021		.350000 x	2.670000 =	.934500	
035		1,100.000000 x	.088300 =	97.130000	

			B.T =	98.064500	
1437	1437				
021		.200000 x	2.670000 =	.534000	
035		75.000000 x	.088300 =	6.622500	
051		.380000 x	13.900000 =	5.282000	
1407		.620000 x	37.605000 =	23.315100	

			B.T =	35.753600	
1441	1441				
021		.800000 x	2.670000 =	2.136000	
026		250.000000 x	.099900 =	24.975000	

			B.T =	27.111000	
1442	1442				
021		.250000 x	2.670000 =	.667500	
051		.740000 x	13.900000 =	10.286000	
026		900.000000 x	.099900 =	89.910000	

			B.T =	100.863500	

1443	1443				
021		.250000 x	2.670000 =	.667500	
051		.860000 x	13.900000 =	11.954000	
026		700.000000 x	.099900 =	69.930000	

			B.T =	82.551500	
1444	1444				
021		.250000 x	2.670000 =	.667500	
026		600.000000 x	.099900 =	59.940000	
051		1.000000 x	13.900000 =	13.900000	

			B.T =	74.507500	
1445	1445				
021		.250000 x	2.670000 =	.667500	
026		450.000000 x	.099900 =	44.955000	
051		1.060000 x	13.900000 =	14.734000	

			B.T =	60.356500	
1446	1446				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
051		1.120000 x	13.900000 =	15.568000	

			B.T =	51.200500	
1447	1447				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	13.900000 =	13.900000	
026		400.000000 x	.099900 =	39.960000	

			B.T =	57.535900	
1448	1448				
021		.250000 x	2.670000 =	.667500	
1407		.080000 x	37.605000 =	3.008400	
051		1.000000 x	13.900000 =	13.900000	
039		5.000000 x	.000000 =	.000000	
026		400.000000 x	.099900 =	39.960000	

			B.T =	57.535900	
1449	1449				
021		.250000 x	2.670000 =	.667500	
026		350.000000 x	.099900 =	34.965000	
1407		.040000 x	37.605000 =	1.504200	
051		1.060000 x	13.900000 =	14.734000	

			B.T =	51.870700	

1451	1451			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
053		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750
1452	1452			
021		.250000 x	2.670000 =	.667500
053		1,500.000000 x	.085000 =	127.500000
1407		.050000 x	37.605000 =	1.880250
029		600.000000 x	.151500 =	90.900000

			B.T =	220.947750
1453	1453			
021		.250000 x	2.670000 =	.667500
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000
026		450.000000 x	.099900 =	44.955000

			B.T =	187.752750
1454	1454			
021		.250000 x	2.670000 =	.667500
029		450.000000 x	.151500 =	68.175000
053		1,650.000000 x	.085000 =	140.250000
1407		.050000 x	37.605000 =	1.880250

			B.T =	210.972750
1455	1455			
021		.250000 x	2.670000 =	.667500
028		450.000000 x	.000000 =	.000000
1407		.050000 x	37.605000 =	1.880250
053		1,650.000000 x	.085000 =	140.250000

			B.T =	210.972750
1456	1456			
021		.250000 x	2.670000 =	.667500
026		600.000000 x	.099900 =	59.940000
1407		.050000 x	37.605000 =	1.880250
054		1,500.000000 x	.085000 =	127.500000

			B.T =	189.987750

1457 1457

021	.250000 x	2.670000 =	.667500
1407	.050000 x	37.605000 =	1.880250
054	1,500.000000 x	.085000 =	127.500000
029	600.000000 x	.151500 =	90.900000

B.T = 220.947750

1458 1458

021	.250000 x	2.670000 =	.667500
1407	.050000 x	37.605000 =	1.880250
054	1,650.000000 x	.085000 =	140.250000
028	450.000000 x	.000000 =	.000000

B.T =

1459 1459

021	.250000 x	2.670000 =	.667500
054	1,650.000000 x	.085000 =	140.250000
1407	.050000 x	37.605000 =	1.880250
029	450.000000 x	.151500 =	68.175000

B.T = 210.972750

1461 1461

021	.250000 x	2.670000 =	.667500
053	1,500.000000 x	.085000 =	127.500000
1407	.080000 x	37.605000 =	3.008400
026	500.000000 x	.099900 =	49.950000

B.T = 181.125900

1462 1462

021	.300000 x	2.670000 =	.801000
1407	.050000 x	37.605000 =	1.880250
515	1.000000 x	45.970000 =	45.970000
051	.100000 x	13.900000 =	1.390000
026	400.000000 x	.099900 =	39.960000

B.T = 90.001250

1463 1463

021	.300000 x	2.670000 =	.801000
051	.100000 x	13.900000 =	1.390000
1407	.050000 x	37.605000 =	1.880250
515	1.050000 x	45.970000 =	48.268500
026	250.000000 x	.099900 =	24.975000

B.T = 77.314750

1464	1464				
021		.200000 x	2.670000 =	.534000	
519		.600000 x	53.140000 =	31.884000	
1407		.120000 x	37.605000 =	4.512600	
051		.420000 x	13.900000 =	5.838000	
026		150.000000 x	.099900 =	14.985000	

			B.T =	57.753600	
1465	1465				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.900000 x	53.140000 =	47.826000	
051		.150000 x	13.900000 =	2.085000	
026		450.000000 x	.099900 =	44.955000	

			B.T =	96.528150	
1466	1466				
021		.200000 x	2.670000 =	.534000	
1407		.030000 x	37.605000 =	1.128150	
519		.840000 x	53.140000 =	44.637600	
026		450.000000 x	.099900 =	44.955000	
051		.210000 x	13.900000 =	2.919000	

			B.T =	94.173750	
1467	1467				
021		.200000 x	2.670000 =	.534000	
026		450.000000 x	.099900 =	44.955000	
051		.350000 x	13.900000 =	4.865000	
1407		.030000 x	37.605000 =	1.128150	
519		.700000 x	53.140000 =	37.198000	

			B.T =	88.680150	
1471	1471				
251		1.000000 x	.927000 =	.927000	
351		4.000000 x	.735200 =	2.940800	
358		1.000000 x	3.338500 =	3.338500	
364		2.000000 x	1.133000 =	2.266000	
372		.400000 x	2.470800 =	.988320	
370		6.000000 x	.294100 =	1.764600	

			=	12.225220	
	B.T =	.476190 x	12.225220 =	5.821528	

1472 1472

251	.600000 x	.927000 =	.556200
351	2.000000 x	.735200 =	1.470400
361	1.000000 x	1.249900 =	1.249900
363	2.000000 x	1.779400 =	3.558800
372	.300000 x	2.470800 =	.741240
351	4.000000 x	.735200 =	2.940800

		=	10.517340
B.T =	.666667 x	10.517340 =	7.011564

1473 1473

251	.500000 x	.927000 =	.463500
354	4.000000 x	.985400 =	3.941600
364	2.000000 x	1.133000 =	2.266000
372	.700000 x	2.470800 =	1.729560
370	4.000000 x	.294100 =	1.176400
361	1.000000 x	1.249900 =	1.249900
360	1.000000 x	14.938000 =	14.938000
351	4.000000 x	.735200 =	2.940800

		=	28.705760
B.T =	.416667 x	28.705760 =	11.960743

1474 1474

251	.500000 x	.927000 =	.463500
372	.500000 x	2.470800 =	1.235400
370	4.000000 x	.294100 =	1.176400
366	2.000000 x	5.000500 =	10.001000
361	1.000000 x	1.249900 =	1.249900
360	1.000000 x	14.938000 =	14.938000
357	4.000000 x	1.441300 =	5.765200

		=	34.829400
B.T =	.416667 x	34.829400 =	14.512262

1475 1475

251	.300000 x	.927000 =	.278100
379	1.000000 x	27.450000 =	27.450000
371	2.000000 x	1.779400 =	3.558800
376	160.000000 x	.220400 =	35.264000
377	6.000000 x	.926400 =	5.558400
378	1.000000 x	14.950000 =	14.950000
375	2.000000 x	3.470900 =	6.941800
354	3.000000 x	.985400 =	2.956200

		=	96.957300
B.T =	.416667 x	96.957300 =	40.398907

1476	1476			
251		.500000 x	.927000 =	.463500
373		.200000 x	2.735500 =	.547100
370		6.000000 x	.294100 =	1.764600
352		3.000000 x	1.133000 =	3.399000

			=	6.174200
	B.T =	.500000 x	6.174200 =	3.087100

1478	1478			
251		3.000000 x	.927000 =	2.781000
372		.500000 x	2.470800 =	1.235400
356		2.000000 x	.661600 =	1.323200
370		6.000000 x	.294100 =	1.764600

			=	7.104200
	B.T =	.500000 x	7.104200 =	3.552100

1479	1479			
251		6.000000 x	.927000 =	5.562000
370		12.000000 x	.294100 =	3.529200
381		1.000000 x	74.770000 =	74.770000

			=	83.861200
	B.T =	.454545 x	83.861200 =	38.118689

1480	1480			
251		8.000000 x	.927000 =	7.416000
381		2.000000 x	74.770000 =	149.540000
370		16.000000 x	.294100 =	4.705600

			=	161.661600
	B.T =	.227273 x	161.661600 =	36.741317

1485	1485			
021		.000500 x	2.670000 =	.001335
453		.230000 x	.085000 =	.019550
487		.040000 x	13.884000 =	.555360
451		.230000 x	1.214200 =	.279266

			B.T =	.855511
1487	1487			
443		.120000 x	1.987900 =	.238548
451		.170000 x	1.214200 =	.206414
453		.640000 x	.085000 =	.054400
446		.010000 x	2.662500 =	.026625
445		.060000 x	1.600000 =	.096000

			B.T =	.621987

1488 1488

444	.170000 x	2.207500 =	.375275
453	.500000 x	.085000 =	.042500
451	.170000 x	1.214200 =	.206414
446	.030000 x	2.662500 =	.079875
445	.050000 x	1.600000 =	.080000

B.T = .784064

1489 1489

444	.100000 x	2.207500 =	.220750
453	.430000 x	.085000 =	.036550
451	.350000 x	1.214200 =	.424970
446	.020000 x	2.662500 =	.053250
445	.100000 x	1.600000 =	.160000

B.T = .895520

1490 1490

444	.300000 x	2.207500 =	.662250
445	.100000 x	1.600000 =	.160000
446	.030000 x	2.662500 =	.079875
451	.570000 x	1.214200 =	.692094

B.T = 1.594219

1491 1491

444	.270000 x	2.207500 =	.596025
445	.060000 x	1.600000 =	.096000
451	.650000 x	1.214200 =	.789230
446	.020000 x	2.662500 =	.053250

B.T = 1.534505

1492 1492

444	.200000 x	2.207500 =	.441500
446	.030000 x	2.662500 =	.079875
445	.040000 x	1.600000 =	.064000
455	.730000 x	3.090000 =	2.255700

B.T = 2.841075

1501 1501

011	1.000000 x	55.210000 =	55.210000
012	2.000000 x	4.530000 =	9.060000
005	3.500000 x	21.561131 =	75.463959
005	14.000000 x	21.561131 =	301.855834
485	15.000000 x	1.271500 =	19.072500
484	1.750000 x	4.550000 =	7.962500

B.T = 468.624793

1502 1502

013	1.000000 x	27.370000 =	27.370000
005	3.500000 x	21.561131 =	75.463959
001	26.000000 x	15.643441 =	406.729466
482	15.000000 x	1.539700 =	23.095500
484	.900000 x	4.550000 =	4.095000

B.T = 536.753925

1503 1503

014	1.000000 x	268.420000 =	268.420000
002	2.600000 x	17.205541 =	44.734407
004	7.000000 x	23.647167 =	165.530169
484	2.600000 x	4.550000 =	11.830000
485	44.000000 x	1.271500 =	55.946000

B.T = 546.460576

1504 1504

015	1.000000 x	206.720000 =	206.720000
004	7.000000 x	23.647167 =	165.530169
002	7.000000 x	17.205541 =	120.438787
485	83.000000 x	1.271500 =	105.534500
484	5.250000 x	4.550000 =	23.887500
291	2.200000 x	4.500000 =	9.900000

B.T = 632.010956

1505 1505

016	1.000000 x	32.560000 =	32.560000
004	7.000000 x	23.647167 =	165.530169
002	1.750000 x	17.205541 =	30.109697
485	17.500000 x	1.271500 =	22.251250
484	1.750000 x	4.550000 =	7.962500

B.T = 258.413616

1506 1506

017	1.000000 x	380.180000 =	380.180000
002	3.500000 x	17.205541 =	60.219394
484	6.000000 x	4.550000 =	27.300000
004	7.000000 x	23.647167 =	165.530169
485	70.000000 x	1.271500 =	89.005000

B.T = 722.234563

2101 2101

002	.300000 x	17.205541 =	5.161662
-----	-----------	-------------	----------

T.E = 5.161662

2102	2102			
002		.400000 x	17.205541 =	6.882216

			T.E =	6.882216
2103	2103			
002		.400000 x	17.205541 =	6.882216

			T.E =	6.882216
2104A	2104A			
002		.900000 x	17.205541 =	15.484987

			T.E =	15.484987
2104B	2104B			
002		1.400000 x	17.205541 =	24.087757

			T.E =	24.087757
2104E	2104E			
002		2.900000 x	17.205541 =	49.896069

			T.E =	49.896069
2104H	2104H			
002		4.400000 x	17.205541 =	75.704380

			T.E =	75.704380
2104Z	2104Z			
002		3.900000 x	17.205541 =	67.101610

			T.E =	67.101610
2104	2104			
002		1.900000 x	17.205541 =	32.690528

			T.E =	32.690528
2104	2104			
002		2.400000 x	17.205541 =	41.293298

			T.E =	41.293298
2104 T	2104 T			
002		3.400000 x	17.205541 =	58.498839

			T.E =	58.498839

2105A	2105A			
002		.900000 x	17.205541 =	15.484987

			T.E =	15.484987
2105B	2105B			
002		1.400000 x	17.205541 =	24.087757

			T.E =	24.087757
2105E	2105E			
002		2.900000 x	17.205541 =	49.896069

			T.E =	49.896069
2105H	2105H			
002		4.400000 x	17.205541 =	75.704380

			T.E =	75.704380
2105Z	2105Z			
002		3.900000 x	17.205541 =	67.101610

			T.E =	67.101610
2105	2105			
002		1.900000 x	17.205541 =	32.690528

			T.E =	32.690528
2105	2105			
002		2.400000 x	17.205541 =	41.293298

			T.E =	41.293298
2105 T	2105 T			
002		3.400000 x	17.205541 =	58.498839

			T.E =	58.498839
2106A	2106A			
002		5.900000 x	17.205541 =	101.512692

			T.E =	101.512692
2106B	2106B			
002		7.400000 x	17.205541 =	127.321003

			T.E =	127.321003

2106E	2106E			
002		11.900000 x	17.205541 =	204.745938

			T.E =	204.745938
2106H	2106H			
002		16.400000 x	17.205541 =	282.170872

			T.E =	282.170872
2106I	2106I			
002		19.400000 x	17.205541 =	333.787495

			T.E =	333.787495
2106Z	2106Z			
002		14.900000 x	17.205541 =	256.362561

			T.E =	256.362561
2106	2106			
002		8.900000 x	17.205541 =	153.129315

			T.E =	153.129315
2106	2106			
002		10.400000 x	17.205541 =	178.937626

			T.E =	178.937626
2106	2106			
002		17.900000 x	17.205541 =	307.979184

			T.E =	307.979184
2106 T	2106 T			
002		13.400000 x	17.205541 =	230.554249

			T.E =	230.554249
2107A	2107A			
002		5.900000 x	17.205541 =	101.512692

			T.E =	101.512692
2107B	2107B			
002		7.400000 x	17.205541 =	127.321003

			T.E =	127.321003

2107E	2107E			
002		11.900000 x	17.205541 =	204.745938

			T.E =	204.745938
2107H	2107H			
002		16.400000 x	17.205541 =	282.170872

			T.E =	282.170872
2107I	2107I			
002		19.400000 x	17.205541 =	333.787495

			T.E =	333.787495
2107Z	2107Z			
002		14.900000 x	17.205541 =	256.362561

			T.E =	256.362561
2107	2107			
002		8.900000 x	17.205541 =	153.129315

			T.E =	153.129315
2107	2107			
002		10.400000 x	17.205541 =	178.937626

			T.E =	178.937626
2107	2107			
002		17.900000 x	17.205541 =	307.979184

			T.E =	307.979184
2107 T	2107 T			
002		13.400000 x	17.205541 =	230.554249

			T.E =	230.554249
2108A	2108A			
002		.700000 x	17.205541 =	12.043879

			T.E =	12.043879
2108B	2108B			
002		1.600000 x	17.205541 =	27.528866

			T.E =	27.528866

2108E	2108E			
002		4.600000 x	17.205541 =	79.145489

			T.E =	79.145489
2108H	2108H			
002		7.600000 x	17.205541 =	130.762112

			T.E =	130.762112
2108Z	2108Z			
002		6.600000 x	17.205541 =	113.556571

			T.E =	113.556571
2108	2108			
002		2.600000 x	17.205541 =	44.734407

			T.E =	44.734407
2108	2108			
002		3.600000 x	17.205541 =	61.939948

			T.E =	61.939948
2108	2108			
002		8.600000 x	17.205541 =	147.967653

			T.E =	147.967653
2108 T	2108 T			
002		5.600000 x	17.205541 =	96.351030

			T.E =	96.351030
2109	2109			
002		.030000 x	17.205541 =	.516166
1506		.004000 x	722.234563 =	2.888938
1503		.001000 x	546.460576 =	.546461

			T.E =	3.951565
2110	2110			
002		.040000 x	17.205541 =	.688222
1501		.005000 x	468.624793 =	2.343124
1506		.004000 x	722.234563 =	2.888938
1503		.001000 x	546.460576 =	.546461

			T.E =	6.466744

2111	2111			
002		.100000 x	17.205541 =	1.720554
1504		.005000 x	632.010956 =	3.160055

			T.E =	4.880609
2112	2112			
002		.120000 x	17.205541 =	2.064665
1504		.005500 x	632.010956 =	3.476060
1501		.004000 x	468.624793 =	1.874499

			T.E =	7.415224
2113	2113			
002		1.400000 x	17.205541 =	24.087757
002		.300000 x	17.205541 =	5.161662

			T.E =	29.249420
2114	2114			
002		1.500000 x	17.205541 =	25.808312
1501		.005000 x	468.624793 =	2.343124
002		.400000 x	17.205541 =	6.882216

			T.E =	35.033652
2115	2115			
481		.300000 x	5.467500 =	1.640250
003		1.200000 x	20.290479 =	24.348575
1501		.011000 x	468.624793 =	5.154873
002		.600000 x	17.205541 =	10.323325

			T.E =	41.467022
2116	2116			
2115		1.300000 x	41.467022 =	53.907129

			T.E =	53.907129
2117	2117			
002		.600000 x	17.205541 =	10.323325
1501		.125000 x	468.624793 =	58.578099

			T.E =	68.901424
2118	2118			
2117		1.300000 x	68.901424 =	89.571851

			T.E =	89.571851

2121	2121			
001		.400000 x	15.643441 =	6.257376
002		1.800000 x	17.205541 =	30.969974

			T.E =	37.227350
2122	2122			
001		.500000 x	15.643441 =	7.821721
1501		.005000 x	468.624793 =	2.343124
002		2.000000 x	17.205541 =	34.411082

			T.E =	44.575926
2123	2123			
002		.200000 x	17.205541 =	3.441108
1504		.008300 x	632.010956 =	5.245691

			T.E =	8.686799
2124	2124			
002		.200000 x	17.205541 =	3.441108
1501		.005000 x	468.624793 =	2.343124
1504		.010000 x	632.010956 =	6.320110

			T.E =	12.104342
2125	2125			
481		.400000 x	5.467500 =	2.187000
1501		.020000 x	468.624793 =	9.372496
002		1.000000 x	17.205541 =	17.205541
003		1.500000 x	20.290479 =	30.435719

			T.E =	59.200755
2126	2126			
2125		1.300000 x	59.200755 =	76.960982

			T.E =	76.960982
2127	2127			
002		1.000000 x	17.205541 =	17.205541
1501		.166600 x	468.624793 =	78.072891

			T.E =	95.278432
2128	2128			
2127		1.300000 x	95.278432 =	123.861962

			T.E =	123.861962

2131	2131			
001		.300000 x	15.643441 =	4.693032

			T.E =	4.693032
2132	2132			
1504		.001600 x	632.010956 =	1.011218

			T.E =	1.011218
2133	2133			
002		.100000 x	17.205541 =	1.720554
002		.600000 x	17.205541 =	10.323325

			T.E =	12.043879
2134	2134			
1504		.002500 x	632.010956 =	1.580027

			T.E =	1.580027
2135.1	2135.1			
2121		1.300000 x	37.227350 =	48.395555

			T.E =	48.395555
2135.2	2135.2			
2122		1.300000 x	44.575926 =	57.948704

			T.E =	57.948704
2135.3	2135.3			
2127		1.300000 x	95.278432 =	123.861962

			T.E =	123.861962
2135.4	2135.4			
2128		1.300000 x	123.861962 =	161.020551

			T.E =	161.020551
2141	2141			
001		2.000000 x	15.643441 =	31.286882
003		2.500000 x	20.290479 =	50.726198

			T.E =	82.013080

2142	2142			
001		2.000000 x	15.643441 =	31.286882
1501		.005000 x	468.624793 =	2.343124
003		3.000000 x	20.290479 =	60.871437

			T.E =	94.501443
2143	2143			
481		.500000 x	5.467500 =	2.733750
001		2.000000 x	15.643441 =	31.286882
003		3.000000 x	20.290479 =	60.871437
1501		.025000 x	468.624793 =	11.715620

			T.E =	106.607689
2144	2144			
2143		1.300000 x	106.607689 =	138.589996

			T.E =	138.589996
2145	2145			
001		2.000000 x	15.643441 =	31.286882
003		1.000000 x	20.290479 =	20.290479
1501		.200000 x	468.624793 =	93.724959

			T.E =	145.302320
2146	2146			
2145		1.300000 x	145.302320 =	188.893016

			T.E =	188.893016
2151	2151			
001		1.200000 x	15.643441 =	18.772129
003		.800000 x	20.290479 =	16.232383

			T.E =	35.004512
2152	2152			
001		1.500000 x	15.643441 =	23.465162
003		1.000000 x	20.290479 =	20.290479

			T.E =	43.755641
2161	2161			
1505		.003300 x	258.413616 =	.852765

			T.E =	.852765

2162	2162			
021		.100000 x	2.670000 =	.267000
001		.800000 x	15.643441 =	12.514753

			T.E =	12.781753
2163	2163			
001		.300000 x	15.643441 =	4.693032

			T.E =	4.693032
2171	2171			
009		2.000000 x	.074800 =	.149600
1504		.004000 x	632.010956 =	2.528044

			T.E =	2.677644
2172	2172			
001		.800000 x	15.643441 =	12.514753

			T.E =	12.514753
2173	2173			
001		.600000 x	15.643441 =	9.386065

			T.E =	9.386065
2174	2174			
007		.050000 x	181.786626 =	9.089331

			T.E =	9.089331
2175	2175			
009		5.500000 x	.074800 =	.411400

			T.E =	.411400
2176	2176			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2177	2177			
001		.800000 x	15.643441 =	12.514753

			T.E =	12.514753

2178	2178			
001		.200000 x	15.643441 =	3.128688

			T.E =	3.128688
2179	2179			
007		.018000 x	181.786626 =	3.272159

			T.E =	3.272159
2180	2180			
009		2.000000 x	.074800 =	.149600

			T.E =	.149600
2185	2185			
018.1		.142800 x	2.990000 =	.426972
005		.400000 x	21.561131 =	8.624452
484		.100000 x	4.550000 =	.455000
482		.700000 x	1.539700 =	1.077790
018.1		.042800 x	2.990000 =	.127972

			T.E =	10.712186
2186	2186			
018.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.561131 =	8.624452
018.2		.042800 x	4.530000 =	.193884
482		1.400000 x	1.539700 =	2.155580
484		.200000 x	4.550000 =	.910000

			T.E =	12.530800
2187	2187			
019.1		.142800 x	2.990000 =	.426972
485		1.100000 x	1.271500 =	1.398650
019.1		.428000 x	2.990000 =	1.279720
005		.400000 x	21.561131 =	8.624452
484		.100000 x	4.550000 =	.455000

			T.E =	12.184794
2188	2188			
019.2		.142800 x	4.530000 =	.646884
005		.400000 x	21.561131 =	8.624452
485		1.800000 x	1.271500 =	2.288700
484		.200000 x	4.550000 =	.910000
019.2		.042800 x	4.530000 =	.193884

			T.E =	12.663920

2201	2201			
001		1.000000 x	15.643441 =	15.643441
002		2.000000 x	17.205541 =	34.411082

			T.E =	50.054523
2202	2202			
001		1.000000 x	15.643441 =	15.643441
002		5.000000 x	17.205541 =	86.027705

			T.E =	101.671146
2203	2203			
001		1.000000 x	15.643441 =	15.643441
002		2.500000 x	17.205541 =	43.013853

			T.E =	58.657294
2204	2204			
001		1.000000 x	15.643441 =	15.643441
002		5.000000 x	17.205541 =	86.027705

			T.E =	101.671146
2206	2206			
001		1.000000 x	15.643441 =	15.643441
003		3.000000 x	20.290479 =	60.871437

			T.E =	76.514878
2207	2207			
001		1.000000 x	15.643441 =	15.643441
003		6.000000 x	20.290479 =	121.742874

			T.E =	137.386315
2211	2211			
001		2.000000 x	15.643441 =	31.286882

			T.E =	31.286882
2212	2212			
001		1.000000 x	15.643441 =	15.643441

			T.E =	15.643441
2213	2213			
001		2.000000 x	15.643441 =	31.286882

			T.E =	31.286882

2214	2214				
001		.600000 x	15.643441 =	9.386065	

			T.E =	9.386065	
2221	2221				
001		1.200000 x	15.643441 =	18.772129	
002		1.600000 x	17.205541 =	27.528866	

			T.E =	46.300995	
2222	2222				
001		1.200000 x	15.643441 =	18.772129	
002		2.500000 x	17.205541 =	43.013853	

			T.E =	61.785982	
2223	2223				
001		3.000000 x	15.643441 =	46.930323	

			T.E =	46.930323	
2224	2224				
001		5.000000 x	15.643441 =	78.217205	

			T.E =	78.217205	
2226	2226				
001		1.500000 x	15.643441 =	23.465162	
002		5.000000 x	17.205541 =	86.027705	

			T.E =	109.492867	
2227	2227				
001		1.500000 x	15.643441 =	23.465162	
002		12.000000 x	17.205541 =	206.466492	

			T.E =	229.931654	
2231	2231				
001		.600000 x	15.643441 =	9.386065	

			T.E =	9.386065	
2232	2232				
003		.020000 x	20.290479 =	.405810	

			T.E =	.405810	

2236	2236			
001		.100000 x	15.643441 =	1.564344
002		.300000 x	17.205541 =	5.161662

			T.E =	6.726006
2237	2237			
001		.200000 x	15.643441 =	3.128688
003		.700000 x	20.290479 =	14.203335

			T.E =	17.332024
2238	2238			
001		.100000 x	15.643441 =	1.564344
002		.400000 x	17.205541 =	6.882216

			T.E =	8.446561
2239	2239			
001		.200000 x	15.643441 =	3.128688
003		.800000 x	20.290479 =	16.232383

			T.E =	19.361071
2241	2241			
001		.300000 x	15.643441 =	4.693032
003		.100000 x	20.290479 =	2.029048

			T.E =	6.722080
2242	2242			
001		.400000 x	15.643441 =	6.257376
003		.150000 x	20.290479 =	3.043572

			T.E =	9.300948
2243	2243			
001		.500000 x	15.643441 =	7.821721
003		.250000 x	20.290479 =	5.072620

			T.E =	12.894340
2246	2246			
001		.250000 x	15.643441 =	3.910860
003		.050000 x	20.290479 =	1.014524

			T.E =	4.925384

2247	2247			
001		.350000 x	15.643441 =	5.475204
003		.100000 x	20.290479 =	2.029048

			T.E =	7.504252
2248	2248			
001		.450000 x	15.643441 =	7.039548
003		.200000 x	20.290479 =	4.058096

			T.E =	11.097644
2251	2251			
001		.100000 x	15.643441 =	1.564344
002		.300000 x	17.205541 =	5.161662

			T.E =	6.726006
2252	2252			
001		.100000 x	15.643441 =	1.564344
002		.600000 x	17.205541 =	10.323325

			T.E =	11.887669
2261A	2261A			
003		.400000 x	20.290479 =	8.116192

			T.E =	8.116192
2261B	2261B			
003		.700000 x	20.290479 =	14.203335

			T.E =	14.203335
2261	2261			
003		.900000 x	20.290479 =	18.261431

			T.E =	18.261431
2261	2261			
003		1.200000 x	20.290479 =	24.348575

			T.E =	24.348575
2262A	2262A			
003		.550000 x	20.290479 =	11.159763

			T.E =	11.159763

2262B	2262B			
003		.900000 x	20.290479 =	18.261431

			T.E =	18.261431
2262	2262			
003		1.200000 x	20.290479 =	24.348575

			T.E =	24.348575
2262	2262			
003		1.600000 x	20.290479 =	32.464766

			T.E =	32.464766
2263A	2263A			
003		.700000 x	20.290479 =	14.203335

			T.E =	14.203335
2263B	2263B			
003		1.200000 x	20.290479 =	24.348575

			T.E =	24.348575
2263	2263			
003		1.600000 x	20.290479 =	32.464766

			T.E =	32.464766
2263	2263			
003		2.100000 x	20.290479 =	42.610006

			T.E =	42.610006
2264.1A	2264.1A			
003		1.600000 x	20.290479 =	32.464766

			T.E =	32.464766
2264.1B	2264.1B			
003		1.850000 x	20.290479 =	37.537386

			T.E =	37.537386
2264.1	2264.1			
003		2.100000 x	20.290479 =	42.610006

			T.E =	42.610006

2264.1

2264.1

003

2.300000 x

20.290479 =

46.668102

T.E =

46.668102

2264.2A

2264.2A

003

2.000000 x

20.290479 =

40.580958

T.E =

40.580958

2264.2B

2264.2B

003

2.400000 x

20.290479 =

48.697150

T.E =

48.697150

2264.2

2264.2

003

2.800000 x

20.290479 =

56.813341

T.E =

56.813341

2264.2

2264.2

003

3.200000 x

20.290479 =

64.929533

T.E =

64.929533

2264.3A

2264.3A

003

2.400000 x

20.290479 =

48.697150

T.E =

48.697150

2264.3B

2264.3B

003

2.850000 x

20.290479 =

57.827865

T.E =

57.827865

2264.3

2264.3

003

3.300000 x

20.290479 =

66.958581

T.E =

66.958581

2264.3

2264.3

003

3.750000 x

20.290479 =

76.089296

T.E =

76.089296

2265A

2265A

003

.500000 x

20.290479 =

10.145240

T.E =

10.145240

2265B	2265B			
003		.800000 x	20.290479 =	16.232383

			T.E =	16.232383
2266.1	2266.1			
2261A		1.000000 x	8.116192 =	8.116192
2261A		.350000 x	8.116192 =	2.840667

			T.E =	10.956859
2266.10	2266.10			
2263B		1.000000 x	24.348575 =	24.348575
2263B		.350000 x	24.348575 =	8.522001

			T.E =	32.870576
2266.11	2266.11			
2263		1.000000 x	32.464766 =	32.464766
2263		.350000 x	32.464766 =	11.362668

			T.E =	43.827434
2266.12	2266.12			
2263		1.000000 x	42.610006 =	42.610006
2263		.350000 x	42.610006 =	14.913502

			T.E =	57.523508
2266.13	2266.13			
2264.1A		1.000000 x	32.464766 =	32.464766
2264.1A		.350000 x	32.464766 =	11.362668

			T.E =	43.827434
2266.14	2266.14			
2264.1B		1.000000 x	37.537386 =	37.537386
2264.1B		.350000 x	37.537386 =	13.138085

			T.E =	50.675471
2266.15	2266.15			
2264.1		1.000000 x	42.610006 =	42.610006
2264.1		.350000 x	42.610006 =	14.913502

			T.E =	57.523508

2266.16 2266.16

2264.1

1.000000 x

46.668102 =

46.668102

2264.1

.350000 x

46.668102 =

16.333836

T.E =

63.001938

2266.17 2266.17

2264.2A

1.000000 x

40.580958 =

40.580958

2264.2A

.350000 x

40.580958 =

14.203335

T.E =

54.784293

2266.18 2266.18

2264.2B

1.000000 x

48.697150 =

48.697150

2264.2B

.350000 x

48.697150 =

17.044003

T.E =

65.741153

2266.19 2266.19

2264.2

1.000000 x

56.813341 =

56.813341

2264.2

.350000 x

56.813341 =

19.884669

T.E =

76.698010

2266.2 2266.2

2261B

1.000000 x

14.203335 =

14.203335

2261B

.350000 x

14.203335 =

4.971167

T.E =

19.174502

2266.20 2266.20

2264.2

1.000000 x

64.929533 =

64.929533

2264.2

.350000 x

64.929533 =

22.725337

T.E =

87.654870

2266.21 2266.21

2264.3A

1.000000 x

48.697150 =

48.697150

2264.3A

.350000 x

48.697150 =

17.044003

T.E =

65.741153

2266.22 2266.22

2264.3B

1.000000 x

57.827865 =

57.827865

2264.3B

.350000 x

57.827865 =

20.239753

T.E =

78.067618

2266.23 2266.23

2264.3	1.000000 x	66.958581 =	66.958581
2264.3	.350000 x	66.958581 =	23.435503

T.E = 90.394084

2266.24 2266.24

2264.3	1.000000 x	76.089296 =	76.089296
2264.3	.350000 x	76.089296 =	26.631254

T.E = 102.720550

2266.25 2266.25

2265A	1.000000 x	10.145240 =	10.145240
2265A	.350000 x	10.145240 =	3.550834

T.E = 13.696074

2266.26 2266.26

2265B	1.000000 x	16.232383 =	16.232383
2265B	.350000 x	16.232383 =	5.681334

T.E = 21.913717

2266.3 2266.3

2261	1.000000 x	18.261431 =	18.261431
2261	.350000 x	18.261431 =	6.391501

T.E = 24.652932

2266.4 2266.4

2261	1.000000 x	24.348575 =	24.348575
2261	.350000 x	24.348575 =	8.522001

T.E = 32.870576

2266.5 2266.5

2262A	1.000000 x	11.159763 =	11.159763
2262A	.350000 x	11.159763 =	3.905917

T.E = 15.065680

2266.6 2266.6

2262B	1.000000 x	18.261431 =	18.261431
2262B	.350000 x	18.261431 =	6.391501

T.E = 24.652932

2266.7 2266.7

2262	1.000000 x	24.348575 =	24.348575
2262	.350000 x	24.348575 =	8.522001

T.E = 32.870576

2266.8 2266.8

2262	1.000000 x	32.464766 =	32.464766
2262	.350000 x	32.464766 =	11.362668

T.E = 43.827434

2266.9 2266.9

2263A	1.000000 x	14.203335 =	14.203335
2263A	.350000 x	14.203335 =	4.971167

T.E = 19.174502

2267 2267

003	3.500000 x	20.290479 =	71.016677
-----	------------	-------------	-----------

T.E = 71.016677

2268A 2268A

003	5.000000 x	20.290479 =	101.452395
-----	------------	-------------	------------

T.E = 101.452395

2268B 2268B

003	5.900000 x	20.290479 =	119.713826
-----	------------	-------------	------------

T.E = 119.713826

2268 2268

003	6.400000 x	20.290479 =	129.859066
-----	------------	-------------	------------

T.E = 129.859066

2268 2268

003	6.900000 x	20.290479 =	140.004305
-----	------------	-------------	------------

T.E = 140.004305

2269A 2269A

003	2.000000 x	20.290479 =	40.580958
-----	------------	-------------	-----------

T.E = 40.580958

2269B	2269B			
003		3.000000 x	20.290479 =	60.871437

			T.E =	60.871437
2269	2269			
003		4.000000 x	20.290479 =	81.161916

			T.E =	81.161916
2270.1	2270.1			
2267		1.000000 x	71.016677 =	71.016677
2267		.600000 x	71.016677 =	42.610006

			T.E =	113.626683
2270.2	2270.2			
2268A		1.000000 x	101.452395 =	101.452395
2268A		.600000 x	101.452395 =	60.871437

			T.E =	162.323832
2270.3	2270.3			
2268B		1.000000 x	119.713826 =	119.713826
2268B		.600000 x	119.713826 =	71.828296

			T.E =	191.542122
2270.4	2270.4			
2268		1.000000 x	129.859066 =	129.859066
2268		.600000 x	129.859066 =	77.915440

			T.E =	207.774506
2270.5	2270.5			
2268		1.000000 x	140.004305 =	140.004305
2268		.600000 x	140.004305 =	84.002583

			T.E =	224.006888
2271A	2271A			
003		2.500000 x	20.290479 =	50.726198

			T.E =	50.726198
2271B	2271B			
003		3.000000 x	20.290479 =	60.871437

			T.E =	60.871437

2271E	2271E			
003		4.500000 x	20.290479 =	91.307156

			T.E =	91.307156
2271H	2271H			
003		6.000000 x	20.290479 =	121.742874

			T.E =	121.742874
2271I	2271I			
003		7.000000 x	20.290479 =	142.033353

			T.E =	142.033353
2271Z	2271Z			
003		5.500000 x	20.290479 =	111.597635

			T.E =	111.597635
2271	2271			
003		3.500000 x	20.290479 =	71.016677

			T.E =	71.016677
2271	2271			
003		4.000000 x	20.290479 =	81.161916

			T.E =	81.161916
2271	2271			
003		6.500000 x	20.290479 =	131.888114

			T.E =	131.888114
2271 T	2271 T			
003		5.000000 x	20.290479 =	101.452395

			T.E =	101.452395
2272A	2272A			
003		3.000000 x	20.290479 =	60.871437

			T.E =	60.871437
2272B	2272B			
003		3.700000 x	20.290479 =	75.074772

			T.E =	75.074772

2272E	2272E			
003		5.800000 x	20.290479 =	117.684778

			T.E =	117.684778
2272H	2272H			
003		7.900000 x	20.290479 =	160.294784

			T.E =	160.294784
2272I	2272I			
003		9.300000 x	20.290479 =	188.701455

			T.E =	188.701455
2272Z	2272Z			
003		7.200000 x	20.290479 =	146.091449

			T.E =	146.091449
2272	2272			
003		4.400000 x	20.290479 =	89.278108

			T.E =	89.278108
2272	2272			
003		5.100000 x	20.290479 =	103.481443

			T.E =	103.481443
2272	2272			
003		8.600000 x	20.290479 =	174.498119

			T.E =	174.498119
2272 T	2272 T			
003		6.500000 x	20.290479 =	131.888114

			T.E =	131.888114
2273A	2273A			
003		8.500000 x	20.290479 =	172.469072

			T.E =	172.469072
2273B	2273B			
003		10.000000 x	20.290479 =	202.904790

			T.E =	202.904790

2273	2273			
003		11.500000 x	20.290479 =	233.340509

			T.E =	233.340509
2273	2273			
003		13.000000 x	20.290479 =	263.776227

			T.E =	263.776227
2274.1	2274.1			
2271A		1.300000 x	50.726198 =	65.944057

			T.E =	65.944057
2274.10	2274.10			
2271I		1.300000 x	142.033353 =	184.643359

			T.E =	184.643359
2274.11	2274.11			
2272A		1.300000 x	60.871437 =	79.132868

			T.E =	79.132868
2274.12	2274.12			
2272B		1.300000 x	75.074772 =	97.597204

			T.E =	97.597204
2274.13	2274.13			
2272		1.300000 x	89.278108 =	116.061540

			T.E =	116.061540
2274.14	2274.14			
2272		1.300000 x	103.481443 =	134.525876

			T.E =	134.525876
2274.15	2274.15			
2272E		1.300000 x	117.684778 =	152.990211

			T.E =	152.990211
2274.16	2274.16			
2272 T		1.300000 x	131.888114 =	171.454548

			T.E =	171.454548

2

μ

2012

.
μ/

45

08/01/2014

2274.17

2274.17

2272Z

1.300000 x

146.091449 =

189.918884

T.E =

189.918884

2274.18

2274.18

2272H

1.300000 x

160.294784 =

208.383219

T.E =

208.383219

2274.19

2274.19

2272

1.300000 x

174.498119 =

226.847555

T.E =

226.847555

2274.2

2274.2

2271B

1.300000 x

60.871437 =

79.132868

T.E =

79.132868

2274.20

2274.20

2272I

1.300000 x

188.701455 =

245.311892

T.E =

245.311892

2274.21

2274.21

2273A

1.300000 x

172.469072 =

224.209794

T.E =

224.209794

2274.22

2274.22

2273B

1.300000 x

202.904790 =

263.776227

T.E =

263.776227

2274.23

2274.23

2273

1.300000 x

233.340509 =

303.342662

T.E =

303.342662

2274.24

2274.24

2273

1.300000 x

263.776227 =

342.909095

T.E =

342.909095

2274.3

2274.3

2271

1.300000 x

71.016677 =

92.321680

T.E =

92.321680

2 μ

2012

. 46
μ/ 08/01/2014

2274.4 2274.4

2271 1.300000 x 81.161916 = 105.510491

T.E = 105.510491

2274.5 2274.5

2271E 1.300000 x 91.307156 = 118.699303

T.E = 118.699303

2274.6 2274.6

2271 T 1.300000 x 101.452395 = 131.888114

T.E = 131.888114

2274.7 2274.7

2271Z 1.300000 x 111.597635 = 145.076926

T.E = 145.076926

2274.8 2274.8

2271H 1.300000 x 121.742874 = 158.265736

T.E = 158.265736

2274.9 2274.9

2271 1.300000 x 131.888114 = 171.454548

T.E = 171.454548

2275 2275

003 1.000000 x 20.290479 = 20.290479

T.E = 20.290479

2301 2301

201 .030000 x 290.000000 = 8.700000

203.4 .033000 x 290.000000 = 9.570000

251 6.000000 x .927000 = 5.562000

003 5.000000 x 20.290479 = 101.452395

001 9.000000 x 15.643441 = 140.790969

T.E = 266.075364

2302 2302

201 .001000 x 290.000000 = .290000

002 .300000 x 17.205541 = 5.161662

T.E = 5.451662

2303	2303				
001		.250000 x	15.643441 =	3.910860	
003		.250000 x	20.290479 =	5.072620	

			T.E =	8.983480	
2304	2304				
201		.000400 x	290.000000 =	.116000	
002		.100000 x	17.205541 =	1.720554	

			T.E =	1.836554	
2311	2311				
201		.040000 x	290.000000 =	11.600000	
203.4		.040000 x	290.000000 =	11.600000	
003		7.000000 x	20.290479 =	142.033353	
001		9.000000 x	15.643441 =	140.790969	
251		6.000000 x	.927000 =	5.562000	

			T.E =	311.586322	
2312	2312				
201		.002000 x	290.000000 =	.580000	
203.4		.002000 x	290.000000 =	.580000	
251		.250000 x	.927000 =	.231750	
001		.250000 x	15.643441 =	3.910860	
003		.150000 x	20.290479 =	3.043572	

			T.E =	8.346182	
2313	2313				
201		.002000 x	290.000000 =	.580000	
251		.200000 x	.927000 =	.185400	
203.4		.001000 x	290.000000 =	.290000	
003		.100000 x	20.290479 =	2.029048	
001		.200000 x	15.643441 =	3.128688	

			T.E =	6.213136	
2314.1	2314.1				
511		1.000000 x	.489500 =	.489500	
003		.030000 x	20.290479 =	.608714	

			T.E =	1.098214	
2314.2	2314.2				
512		1.000000 x	.437500 =	.437500	
003		.030000 x	20.290479 =	.608714	

			T.E =	1.046214	

3101 3101

021	.250000 x	2.670000 =	.667500
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
026	175.000000 x	.099900 =	17.482500
052	.430000 x	13.900000 =	5.977000
056	.860000 x	9.550000 =	8.213000

T.E = 101.295379

3102 3102

021	.250000 x	2.670000 =	.667500
052	.420000 x	13.900000 =	5.838000
056	.840000 x	9.550000 =	8.022000
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
026	200.000000 x	.099900 =	19.980000

T.E = 103.462879

3103 3103

021	.250000 x	2.670000 =	.667500
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
056	.820000 x	9.550000 =	7.831000
052	.410000 x	13.900000 =	5.699000
026	250.000000 x	.099900 =	24.975000

T.E = 108.127879

3104 3104

021	.250000 x	2.670000 =	.667500
026	300.000000 x	.099900 =	29.970000
052	.400000 x	13.900000 =	5.560000
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
056	.800000 x	9.550000 =	7.640000

T.E = 112.792879

3111 3111

021	.250000 x	2.670000 =	.667500
003	1.500000 x	20.290479 =	30.435719
001	4.000000 x	15.643441 =	62.573764
026	200.000000 x	.099900 =	19.980000
057	.840000 x	9.550000 =	8.022000
052	.420000 x	13.900000 =	5.838000

T.E = 127.516983

3112 3112

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
026	250.000000 x	.099900 =	24.975000
057	.820000 x	9.550000 =	7.831000
003	1.500000 x	20.290479 =	30.435719
001	2.000000 x	15.643441 =	31.286882
052	.410000 x	13.900000 =	5.699000

T.E = 127.732797

3113 3113

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958
001	3.000000 x	15.643441 =	46.930323
057	.800000 x	9.550000 =	7.640000
052	.400000 x	13.900000 =	5.560000
026	300.000000 x	.099900 =	29.970000

T.E = 158.186477

3131 3131

021	.300000 x	2.670000 =	.801000
056	.840000 x	9.550000 =	8.022000
026	150.000000 x	.099900 =	14.985000
1407	.200000 x	37.605000 =	7.521000
001	5.000000 x	15.643441 =	78.217205
052	.420000 x	13.900000 =	5.838000

T.E = 115.384205

3201 3201

021	.250000 x	2.670000 =	.667500
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
026	175.000000 x	.099900 =	17.482500
061	.850000 x	12.240000 =	10.404000
052	.570000 x	13.900000 =	7.923000

T.E = 105.432379

3202 3202

021	.250000 x	2.670000 =	.667500
026	200.000000 x	.099900 =	19.980000
061	.840000 x	12.240000 =	10.281600
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
052	.560000 x	13.900000 =	7.784000

T.E = 107.668479

3203 3203

021	.250000 x	2.670000 =	.667500
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
061	.820000 x	12.240000 =	10.036800
052	.540000 x	13.900000 =	7.506000
026	250.000000 x	.099900 =	24.975000

T.E = 112.140679

3204 3204

021	.250000 x	2.670000 =	.667500
026	300.000000 x	.099900 =	29.970000
052	.530000 x	13.900000 =	7.367000
003	.700000 x	20.290479 =	14.203335
001	3.500000 x	15.643441 =	54.752044
061	.800000 x	12.240000 =	9.792000

T.E = 116.751879

3205 3205

021	.250000 x	2.670000 =	.667500
003	5.500000 x	20.290479 =	111.597635
001	7.000000 x	15.643441 =	109.504087
026	200.000000 x	.099900 =	19.980000
065	.750000 x	11.660000 =	8.745000
052	.430000 x	13.900000 =	5.977000

T.E = 256.471222

3206 3206

021	.250000 x	2.670000 =	.667500
026	250.000000 x	.099900 =	24.975000
065	.730000 x	11.660000 =	8.511800
003	5.500000 x	20.290479 =	111.597635
001	7.000000 x	15.643441 =	109.504087
052	.410000 x	13.900000 =	5.699000

T.E = 260.955022

3207 3207

021	.250000 x	2.670000 =	.667500
003	3.000000 x	20.290479 =	60.871437
001	6.000000 x	15.643441 =	93.860646
065	.750000 x	11.660000 =	8.745000
052	.430000 x	13.900000 =	5.977000
026	200.000000 x	.099900 =	19.980000

T.E = 190.101583

3208 3208

021	.250000 x	2.670000 =	.667500
026	250.000000 x	.099900 =	24.975000
065	.730000 x	11.660000 =	8.511800
003	3.000000 x	20.290479 =	60.871437
001	6.000000 x	15.643441 =	93.860646
052	.430000 x	13.900000 =	5.977000

T.E = 194.863383

3211 3211

021	.250000 x	2.670000 =	.667500
003	1.500000 x	20.290479 =	30.435719
001	4.000000 x	15.643441 =	62.573764
062	.840000 x	12.240000 =	10.281600
052	.560000 x	13.900000 =	7.784000
026	200.000000 x	.099900 =	19.980000

T.E = 131.722583

3212 3212

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
062	.820000 x	12.240000 =	10.036800
026	250.000000 x	.099900 =	24.975000
003	1.500000 x	20.290479 =	30.435719
001	2.000000 x	15.643441 =	31.286882
052	.540000 x	13.900000 =	7.506000

T.E = 131.745597

3213 3213

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958
001	3.000000 x	15.643441 =	46.930323
062	.800000 x	12.240000 =	9.792000
052	.530000 x	13.900000 =	7.367000
026	300.000000 x	.099900 =	29.970000

T.E = 162.145477

3214 3214

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958
001	3.500000 x	15.643441 =	54.752044
065	.270000 x	11.660000 =	3.148200
026	350.000000 x	.099900 =	34.965000
052	.400000 x	13.900000 =	5.560000
062	.600000 x	12.240000 =	7.344000

T.E = 173.855398

3215 3215

021	.250000 x	2.670000 =	.667500
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958
001	3.500000 x	15.643441 =	54.752044
065	.250000 x	11.660000 =	2.915000
027	350.000000 x	.119300 =	41.755000
062	.560000 x	12.240000 =	6.854400
052	.420000 x	13.900000 =	5.838000

T.E = 180.200598

3216 3216

021	.250000 x	2.670000 =	.667500
027	425.000000 x	.119300 =	50.702500
062	.550000 x	12.240000 =	6.732000
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958
001	4.000000 x	15.643441 =	62.573764
065	.270000 x	11.660000 =	3.148200
052	.350000 x	13.900000 =	4.865000

T.E = 196.107618

3217 3217

001	2.500000 x	15.643441 =	39.108603
-----	------------	-------------	-----------

T.E = 39.108603

3218 3218

001	5.000000 x	15.643441 =	78.217205
-----	------------	-------------	-----------

T.E = 78.217205

3219 3219

001	3.000000 x	15.643441 =	46.930323
003	4.000000 x	20.290479 =	81.161916

T.E = 128.092239

3220 3220

001	5.000000 x	15.643441 =	78.217205
003	4.000000 x	20.290479 =	81.161916

T.E = 159.379121

3221 3221

001	3.000000 x	15.643441 =	46.930323
003	6.000000 x	20.290479 =	121.742874

T.E = 168.673197

3222	3222				
001		5.000000 x	15.643441 =	78.217205	
003		6.000000 x	20.290479 =	121.742874	

			T.E =	199.960079	
3223A.1	3223A.1				
001		2.000000 x	15.643441 =	31.286882	
1502		.050000 x	536.753925 =	26.837696	
003		1.500000 x	20.290479 =	30.435719	

			=	88.560297	
	T.E =	.500000 x	88.560297 =	44.280148	

3223A.2	3223A.2				
001		3.000000 x	15.643441 =	46.930323	
1502		.050000 x	536.753925 =	26.837696	
003		2.000000 x	20.290479 =	40.580958	

			=	114.348977	
	T.E =	.500000 x	114.348977 =	57.174489	

3223A.3	3223A.3				
001		2.000000 x	15.643441 =	31.286882	
1502		.050000 x	536.753925 =	26.837696	
003		1.500000 x	20.290479 =	30.435719	

			=	88.560297	
	T.E =	.500000 x	88.560297 =	44.280148	

3223A.4	3223A.4				
001		3.000000 x	15.643441 =	46.930323	
003		2.000000 x	20.290479 =	40.580958	
1502		.050000 x	536.753925 =	26.837696	

			=	114.348977	
	T.E =	.500000 x	114.348977 =	57.174489	

3223A.5	3223A.5				
001		3.500000 x	15.643441 =	54.752044	
003		2.000000 x	20.290479 =	40.580958	
1502		.050000 x	536.753925 =	26.837696	

			=	122.170698	
	T.E =	.500000 x	122.170698 =	61.085349	

3223A.6 3223A.6

001	3.500000 x	15.643441 =	54.752044
003	2.000000 x	20.290479 =	40.580958
1502	.050000 x	536.753925 =	26.837696

		=	122.170698
T.E =	.500000 x	122.170698 =	61.085349

3223A.7 3223A.7

001	4.000000 x	15.643441 =	62.573764
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958

		=	129.992418
T.E =	.500000 x	129.992418 =	64.996209

3223B.1 3223B.1

001	2.000000 x	15.643441 =	31.286882
003	1.500000 x	20.290479 =	30.435719
1502	.050000 x	536.753925 =	26.837696

		=	88.560297
T.E =	.250000 x	88.560297 =	22.140074

3223B.2 3223B.2

001	3.000000 x	15.643441 =	46.930323
003	2.000000 x	20.290479 =	40.580958
1502	.050000 x	536.753925 =	26.837696

		=	114.348977
T.E =	.250000 x	114.348977 =	28.587244

3223B.3 3223B.3

001	2.000000 x	15.643441 =	31.286882
003	1.500000 x	20.290479 =	30.435719
1502	.050000 x	536.753925 =	26.837696

		=	88.560297
T.E =	.250000 x	88.560297 =	22.140074

3223B.4 3223B.4

001	3.000000 x	15.643441 =	46.930323
1502	.050000 x	536.753925 =	26.837696
003	2.000000 x	20.290479 =	40.580958

		=	114.348977
T.E =	.250000 x	114.348977 =	28.587244

3223B.5 3223B.5

001	3.500000 x	15.643441 =	54.752044
003	2.000000 x	20.290479 =	40.580958
1502	.050000 x	536.753925 =	26.837696

		=	122.170698
T.E =	.250000 x	122.170698 =	30.542674

3223B.6 3223B.6

001	3.500000 x	15.643441 =	54.752044
003	2.000000 x	20.290479 =	40.580958
1502	.050000 x	536.753925 =	26.837696

		=	122.170698
T.E =	.250000 x	122.170698 =	30.542674

3223B.7 3223B.7

001	4.000000 x	15.643441 =	62.573764
003	2.000000 x	20.290479 =	40.580958
1502	.050000 x	536.753925 =	26.837696

		=	129.992418
T.E =	.250000 x	129.992418 =	32.498105

3231 3231

021	.300000 x	2.670000 =	.801000
1407	.200000 x	37.605000 =	7.521000
001	5.000000 x	15.643441 =	78.217205
061	.840000 x	12.240000 =	10.281600
052	.560000 x	13.900000 =	7.784000
026	150.000000 x	.099900 =	14.985000

T.E = 119.589805

3301 3301

021	.200000 x	2.670000 =	.534000
051	.300000 x	13.900000 =	4.170000
032	.150000 x	36.000000 =	5.400000
056	.800000 x	9.550000 =	7.640000
1407	.150000 x	37.605000 =	5.640750
003	.800000 x	20.290479 =	16.232383
001	3.500000 x	15.643441 =	54.752044

T.E = 94.369177

3302 3302

021	.200000 x	2.670000 =	.534000
032	.200000 x	36.000000 =	7.200000
051	.200000 x	13.900000 =	2.780000
001	3.500000 x	15.643441 =	54.752044
1407	.200000 x	37.605000 =	7.521000
003	.800000 x	20.290479 =	16.232383
056	.800000 x	9.550000 =	7.640000

T.E = 96.659427

3303 3303

021	.200000 x	2.670000 =	.534000
032	.400000 x	36.000000 =	14.400000
1407	.200000 x	37.605000 =	7.521000
003	.800000 x	20.290479 =	16.232383
001	3.500000 x	15.643441 =	54.752044
056	.800000 x	9.550000 =	7.640000

T.E = 101.079427

3304 3304

021	.200000 x	2.670000 =	.534000
1407	.120000 x	37.605000 =	4.512600
003	1.200000 x	20.290479 =	24.348575
001	3.500000 x	15.643441 =	54.752044
056	.800000 x	9.550000 =	7.640000
026	100.000000 x	.099900 =	9.990000
032	.400000 x	36.000000 =	14.400000

T.E = 116.177218

3311 3311

021	.200000 x	2.670000 =	.534000
051	.320000 x	13.900000 =	4.448000
061	.840000 x	12.240000 =	10.281600
003	.800000 x	20.290479 =	16.232383
1407	.160000 x	37.605000 =	6.016800
001	3.500000 x	15.643441 =	54.752044
032	.160000 x	36.000000 =	5.760000

T.E = 98.024827

3312 3312

021	.200000 x	2.670000 =	.534000
1407	.210000 x	37.605000 =	7.897050
003	1.200000 x	20.290479 =	24.348575
001	3.500000 x	15.643441 =	54.752044
061	.840000 x	12.240000 =	10.281600
051	.210000 x	13.900000 =	2.919000
032	.210000 x	36.000000 =	7.560000

T.E = 108.292268

3313 3313

021	.200000 x	2.670000 =	.534000
061	.840000 x	12.240000 =	10.281600
003	1.200000 x	20.290479 =	24.348575
1407	.210000 x	37.605000 =	7.897050
001	3.500000 x	15.643441 =	54.752044
032	.420000 x	36.000000 =	15.120000

T.E = 112.933268

3314 3314

021	.200000 x	2.670000 =	.534000
026	100.000000 x	.099900 =	9.990000
1407	.130000 x	37.605000 =	4.888650
003	1.200000 x	20.290479 =	24.348575
001	3.500000 x	15.643441 =	54.752044
061	.840000 x	12.240000 =	10.281600
032	.420000 x	36.000000 =	15.120000

T.E = 119.914868

3401.1 3401.1

021	.175000 x	2.670000 =	.467250
003	1.100000 x	20.290479 =	22.319527
001	2.500000 x	15.643441 =	39.108603
058	.500000 x	8.200000 =	4.100000
056	.588000 x	9.550000 =	5.615400
052	.294000 x	13.900000 =	4.086600
026	140.000000 x	.099900 =	13.986000

T.E = 89.683379

3401.2 3401.2

021	.175000 x	2.670000 =	.467250
026	140.000000 x	.099900 =	13.986000
052	.392000 x	13.900000 =	5.448800
058	.500000 x	8.200000 =	4.100000
003	1.100000 x	20.290479 =	22.319527
001	2.500000 x	15.643441 =	39.108603
061	.588000 x	12.240000 =	7.197120

T.E = 92.627299

3402.1 3402.1

021	.175000 x	2.670000 =	.467250
026	175.000000 x	.099900 =	17.482500
056	.574000 x	9.550000 =	5.481700
052	.287000 x	13.900000 =	3.989300
001	2.500000 x	15.643441 =	39.108603
003	1.100000 x	20.290479 =	22.319527
058	.500000 x	8.200000 =	4.100000

T.E = 92.948879

3402.2 3402.2

021	.175000 x	2.670000 =	.467250
026	175.000000 x	.099900 =	17.482500
003	1.100000 x	20.290479 =	22.319527
061	.574000 x	12.240000 =	7.025760
001	2.500000 x	15.643441 =	39.108603
058	.500000 x	8.200000 =	4.100000
052	.378000 x	13.900000 =	5.254200

T.E = 95.757839

3406.1 3406.1

021	.175000 x	2.670000 =	.467250
003	1.100000 x	20.290479 =	22.319527
001	2.500000 x	15.643441 =	39.108603
081	.500000 x	9.940000 =	4.970000
056	.588000 x	9.550000 =	5.615400
052	.294000 x	13.900000 =	4.086600
026	140.000000 x	.099900 =	13.986000

T.E = 90.553379

3406.2 3406.2

021	.175000 x	2.670000 =	.467250
026	140.000000 x	.099900 =	13.986000
061	.588000 x	12.240000 =	7.197120
001	2.500000 x	15.643441 =	39.108603
003	1.100000 x	20.290479 =	22.319527
081	.500000 x	9.940000 =	4.970000
052	.392000 x	13.900000 =	5.448800

T.E = 93.497299

3407.1 3407.1

021	.175000 x	2.670000 =	.467250
003	1.100000 x	20.290479 =	22.319527
001	2.500000 x	15.643441 =	39.108603
081	.500000 x	9.940000 =	4.970000
026	175.000000 x	.099900 =	17.482500
056	.574000 x	9.550000 =	5.481700
052	.287000 x	13.900000 =	3.989300

T.E = 93.818879

3407.2 3407.2

021	.175000 x	2.670000 =	.467250
026	175.000000 x	.099900 =	17.482500
061	.574000 x	12.240000 =	7.025760
001	2.500000 x	15.643441 =	39.108603
003	1.100000 x	20.290479 =	22.319527
081	.500000 x	9.940000 =	4.970000
052	.378000 x	13.900000 =	5.254200

T.E = 96.627839

3501 3501

021	.200000 x	2.670000 =	.534000
1407	.180000 x	37.605000 =	6.768900
003	2.000000 x	20.290479 =	40.580958
001	5.000000 x	15.643441 =	78.217205
067	1.050000 x	45.500000 =	47.775000
032	.200000 x	36.000000 =	7.200000

T.E = 181.076063

3502 3502

021	.200000 x	2.670000 =	.534000
026	100.000000 x	.099900 =	9.990000
067	1.050000 x	45.500000 =	47.775000
003	2.000000 x	20.290479 =	40.580958
1407	.100000 x	37.605000 =	3.760500
001	5.000000 x	15.643441 =	78.217205
032	.200000 x	36.000000 =	7.200000

T.E = 188.057663

3503 3503

021	.200000 x	2.670000 =	.534000
032	.200000 x	36.000000 =	7.200000
1407	.080000 x	37.605000 =	3.008400
003	2.000000 x	20.290479 =	40.580958
001	5.000000 x	15.643441 =	78.217205
067	1.000000 x	45.500000 =	45.500000
026	150.000000 x	.099900 =	14.985000

T.E = 190.025563

3504 3504

021	.200000 x	2.670000 =	.534000
003	3.200000 x	20.290479 =	64.929533
001	5.000000 x	15.643441 =	78.217205
517	4.000000 x	.000000 =	.000000
055	180.000000 x	.090000 =	16.200000
026	250.000000 x	.099900 =	24.975000

T.E =

3505 3505

021	.200000 x	2.670000 =	.534000
026	250.000000 x	.099900 =	24.975000
055	420.000000 x	.090000 =	37.800000
001	5.500000 x	15.643441 =	86.038926
003	5.000000 x	20.290479 =	101.452395
517	4.000000 x	.000000 =	.000000

T.E =

3506 3506

021	.300000 x	2.670000 =	.801000
026	200.000000 x	.099900 =	19.980000
515	1.150000 x	45.970000 =	52.865500
003	2.500000 x	20.290479 =	50.726198
001	5.000000 x	15.643441 =	78.217205

T.E =

202.589903

3511 3511

021	.200000 x	2.670000 =	.534000
069	1.050000 x	.000000 =	.000000
003	2.000000 x	20.290479 =	40.580958
1407	.180000 x	37.605000 =	6.768900
001	5.000000 x	15.643441 =	78.217205
032	.200000 x	36.000000 =	7.200000

T.E =

3512 3512

021	.200000 x	2.670000 =	.534000
1407	.100000 x	37.605000 =	3.760500
003	2.000000 x	20.290479 =	40.580958
001	5.000000 x	15.643441 =	78.217205
069	1.050000 x	.000000 =	.000000
032	.200000 x	36.000000 =	7.200000
026	100.000000 x	.099900 =	9.990000

T.E =

3513 3513

001	2.500000 x	15.643441 =	39.108603
-----	------------	-------------	-----------

T.E =

39.108603

3514 3514

001	5.000000 x	15.643441 =	78.217205
-----	------------	-------------	-----------

T.E =

78.217205

3801	3801			
201		.001500 x	290.000000 =	.435000
003		.500000 x	20.290479 =	10.145240
001		.400000 x	15.643441 =	6.257376
203.4		.002500 x	290.000000 =	.725000
251		.300000 x	.927000 =	.278100

			T.E =	17.840716
3802	3802			
3801		.050000 x	17.840716 =	.892036

			T.E =	.892036
3811	3811			
203.4		.004000 x	290.000000 =	1.160000
251		.100000 x	.927000 =	.092700
003		.800000 x	20.290479 =	16.232383
001		.200000 x	15.643441 =	3.128688

			T.E =	20.613771
3816	3816			
201		.002500 x	290.000000 =	.725000
003		.600000 x	20.290479 =	12.174287
001		.400000 x	15.643441 =	6.257376
203.4		.003000 x	290.000000 =	.870000
251		.200000 x	.927000 =	.185400

			T.E =	20.212064
3817	3817			
3816		.150000 x	20.212064 =	3.031810

			T.E =	3.031810
3821	3821			
201		.014000 x	290.000000 =	4.060000
251		.600000 x	.927000 =	.556200
003		2.400000 x	20.290479 =	48.697150
001		.600000 x	15.643441 =	9.386065
203.4		.018000 x	290.000000 =	5.220000

			T.E =	67.919414
3822	3822			
3821		.150000 x	67.919414 =	10.187912

			T.E =	10.187912

3823	3823				
201		.020000 x	290.000000 =	5.800000	
001		.600000 x	15.643441 =	9.386065	
003		3.000000 x	20.290479 =	60.871437	
251		.180000 x	.927000 =	.166860	
203.4		.025000 x	290.000000 =	7.250000	

			T.E =	83.474362	
3824	3824				
3823		.200000 x	83.474362 =	16.694872	

			T.E =	16.694872	
3831	3831				
201		.020000 x	290.000000 =	5.800000	
003		4.500000 x	20.290479 =	91.307156	
001		1.100000 x	15.643441 =	17.207785	
251		.800000 x	.927000 =	.741600	
203.4		.024000 x	290.000000 =	6.960000	

			T.E =	122.016541	
3832	3832				
3831		.150000 x	122.016541 =	18.302481	

			T.E =	18.302481	
3833	3833				
201		.022000 x	290.000000 =	6.380000	
003		6.000000 x	20.290479 =	121.742874	
001		1.100000 x	15.643441 =	17.207785	
251		1.000000 x	.927000 =	.927000	
203.4		.025000 x	290.000000 =	7.250000	

			T.E =	153.507659	
3834	3834				
3833		.200000 x	153.507659 =	30.701532	

			T.E =	30.701532	
3841	3841				
203.4		.001500 x	290.000000 =	.435000	
003		.500000 x	20.290479 =	10.145240	

			T.E =	10.580240	

3851	3851			
203.4		.052000 x	290.000000 =	15.080000
251		1.100000 x	.927000 =	1.019700
003		1.300000 x	20.290479 =	26.377623

			T.E =	42.477323
3852	3852			
001		.300000 x	15.643441 =	4.693032
003		.100000 x	20.290479 =	2.029048

			T.E =	6.722080
3871	3871			
260		1.030000 x	.559100 =	.575873
003		.050000 x	20.290479 =	1.014524

			T.E =	1.590397
3872	3872			
261		1.030000 x	.611900 =	.630257
003		.040000 x	20.290479 =	.811619

			T.E =	1.441876
3873	3873			
262		1.030000 x	.559100 =	.575873
003		.050000 x	20.290479 =	1.014524

			T.E =	1.590397
3874	3874			
258		1.450000 x	7.930000 =	11.498500
003		.150000 x	20.290479 =	3.043572

			T.E =	14.542072
3875	3875			
259		1.000000 x	25.592500 =	25.592500
003		.300000 x	20.290479 =	6.087144

			T.E =	31.679644
3876	3876			
003		.060000 x	20.290479 =	1.217429

			T.E =	1.217429

3881.1 3881.1

111		1,023.391800 x	.072100 =	73.786549
001		5.000000 x	15.643441 =	78.217205

T.E = 152.003754

3881.2 3881.2

112		627.989998 x	.079100 =	49.674009
001		5.000000 x	15.643441 =	78.217205

T.E = 127.891214

3882 3882

127		1.050000 x	81.220000 =	85.281000
001		4.000000 x	15.643441 =	62.573764

T.E = 147.854764

4101 4101

081		1.150000 x	9.940000 =	11.431000
001		1.300000 x	15.643441 =	20.336473
003		2.000000 x	20.290479 =	40.580958

T.E = 72.348431

4102 4102

081		1.200000 x	9.940000 =	11.928000
001		1.700000 x	15.643441 =	26.593850
003		3.500000 x	20.290479 =	71.016677

T.E = 109.538526

4103 4103

081		1.150000 x	9.940000 =	11.431000
003		4.000000 x	20.290479 =	81.161916
001		3.000000 x	15.643441 =	46.930323

T.E = 139.523239

4104 4104

081		1.050000 x	9.940000 =	10.437000
001		3.000000 x	15.643441 =	46.930323

T.E = 57.367323

4105 4105

081		.350000 x	9.940000 =	3.479000
003		.900000 x	20.290479 =	18.261431
001		1.000000 x	15.643441 =	15.643441

T.E = 37.383872

4106	4106			
081		.320000 x	9.940000 =	3.180800
001		.700000 x	15.643441 =	10.950409
003		.900000 x	20.290479 =	18.261431

			T.E =	32.392640
4107	4107			
081		1.200000 x	9.940000 =	11.928000
001		2.000000 x	15.643441 =	31.286882
003		3.000000 x	20.290479 =	60.871437

			T.E =	104.086319
4201	4201			
081		1.150000 x	9.940000 =	11.431000
1412		.350000 x	26.581800 =	9.303630
001		2.900000 x	15.643441 =	45.365979
003		4.000000 x	20.290479 =	81.161916

			T.E =	147.262525
4205	4205			
081		1.150000 x	9.940000 =	11.431000
1417		.350000 x	38.934450 =	13.627058
003		2.500000 x	20.290479 =	50.726198
001		2.900000 x	15.643441 =	45.365979

			T.E =	121.150234
4206	4206			
081		1.150000 x	9.940000 =	11.431000
001		2.900000 x	15.643441 =	45.365979
003		3.100000 x	20.290479 =	62.900485
1417		.350000 x	38.934450 =	13.627058

			T.E =	133.324521
4207	4207			
081		1.150000 x	9.940000 =	11.431000
001		2.900000 x	15.643441 =	45.365979
1417		.350000 x	38.934450 =	13.627058
003		4.000000 x	20.290479 =	81.161916

			T.E =	151.585952

4211	4211			
081		1.150000 x	9.940000 =	11.431000
001		2.900000 x	15.643441 =	45.365979
1447		.350000 x	57.535900 =	20.137565
003		2.500000 x	20.290479 =	50.726198

T.E = 127.660741

4212	4212			
081		1.150000 x	9.940000 =	11.431000
1447		.350000 x	57.535900 =	20.137565
003		3.100000 x	20.290479 =	62.900485
001		2.900000 x	15.643441 =	45.365979

T.E = 139.835029

4213	4213			
081		1.150000 x	9.940000 =	11.431000
1447		.350000 x	57.535900 =	20.137565
001		2.900000 x	15.643441 =	45.365979
003		4.000000 x	20.290479 =	81.161916

T.E = 158.096460

4221	4221			
001		.800000 x	15.643441 =	12.514753
003		1.000000 x	20.290479 =	20.290479

T.E = 32.805232

4222	4222			
001		.400000 x	15.643441 =	6.257376
003		.400000 x	20.290479 =	8.116192

T.E = 14.373568

4226	4226			
003		1.300000 x	20.290479 =	26.377623

T.E = 26.377623

4251	4251			
083		32.000000 x	.000000 =	.000000
1412		.200000 x	26.581800 =	5.316360
001		2.900000 x	15.643441 =	45.365979
003		4.000000 x	20.290479 =	81.161916

T.E =

4257 4257

083	32.000000 x	.000000 =	.000000
1417	.200000 x	38.934450 =	7.786890
003	4.000000 x	20.290479 =	81.161916
001	2.900000 x	15.643441 =	45.365979

T.E =

4261 4261

083	32.000000 x	.000000 =	.000000
1445	.200000 x	60.356500 =	12.071300
003	4.000000 x	20.290479 =	81.161916
001	2.900000 x	15.643441 =	45.365979

T.E =

4262 4262

083	32.000000 x	.000000 =	.000000
003	4.000000 x	20.290479 =	81.161916
001	2.900000 x	15.643441 =	45.365979
1447	.200000 x	57.535900 =	11.507180

T.E =

4265 4265

201	.001500 x	290.000000 =	.435000
001	1.000000 x	15.643441 =	15.643441

T.E =

16.078441

4301 4301

081	1.020000 x	9.940000 =	10.138800
1412	.350000 x	26.581800 =	9.303630
003	4.200000 x	20.290479 =	85.220012
001	2.900000 x	15.643441 =	45.365979
083	5.000000 x	.000000 =	.000000

T.E =

4305 4305

081	1.080000 x	9.940000 =	10.735200
1417	.350000 x	38.934450 =	13.627058
003	2.700000 x	20.290479 =	54.784293
001	2.900000 x	15.643441 =	45.365979
083	2.000000 x	.000000 =	.000000

T.E =

4306 4306

081	1.050000 x	9.940000 =	10.437000
1417	.350000 x	38.934450 =	13.627058
003	3.300000 x	20.290479 =	66.958581
083	3.000000 x	.000000 =	.000000
001	2.900000 x	15.643441 =	45.365979

T.E =

4307 4307

081	1.020000 x	9.940000 =	10.138800
001	2.900000 x	15.643441 =	45.365979
1417	.350000 x	38.934450 =	13.627058
003	4.200000 x	20.290479 =	85.220012
083	5.000000 x	.000000 =	.000000

T.E =

4311 4311

081	1.080000 x	9.940000 =	10.735200
083	2.000000 x	.000000 =	.000000
003	2.700000 x	20.290479 =	54.784293
1447	.350000 x	57.535900 =	20.137565
001	2.900000 x	15.643441 =	45.365979

T.E =

4312 4312

081	1.050000 x	9.940000 =	10.437000
083	3.000000 x	.000000 =	.000000
1447	.350000 x	57.535900 =	20.137565
003	3.300000 x	20.290479 =	66.958581
001	2.900000 x	15.643441 =	45.365979

T.E =

4313 4313

081	1.080000 x	9.940000 =	10.735200
1447	.350000 x	57.535900 =	20.137565
003	2.700000 x	20.290479 =	54.784293
001	2.900000 x	15.643441 =	45.365979
083	2.000000 x	.000000 =	.000000

T.E =

4321 4321

201	.001500 x	290.000000 =	.435000
001	1.000000 x	15.643441 =	15.643441

T.E = 16.078441

4351.1

4351.1

088	1.250000 x	.000000 =	.000000
001	10.000000 x	15.643441 =	156.434410
003	25.000000 x	20.290479 =	507.261975
1446	.100000 x	51.200500 =	5.120050
251	4.000000 x	.927000 =	3.708000

T.E =

4351.2

4351.2

089	1.250000 x	.000000 =	.000000
1446	.100000 x	51.200500 =	5.120050
003	25.000000 x	20.290479 =	507.261975
001	10.000000 x	15.643441 =	156.434410
251	4.000000 x	.927000 =	3.708000

T.E =

4351.3

4351.3

090	1.250000 x	.000000 =	.000000
251	4.000000 x	.927000 =	3.708000
001	10.000000 x	15.643441 =	156.434410
1446	.100000 x	51.200500 =	5.120050
003	25.000000 x	20.290479 =	507.261975

T.E =

4356.1

4356.1

092	1.250000 x	.000000 =	.000000
1446	.200000 x	51.200500 =	10.240100
251	8.000000 x	.927000 =	7.416000
003	32.000000 x	20.290479 =	649.295328
001	11.000000 x	15.643441 =	172.077851

T.E =

4356.2

4356.2

093	1.250000 x	.000000 =	.000000
251	8.000000 x	.927000 =	7.416000
003	32.000000 x	20.290479 =	649.295328
1446	.200000 x	51.200500 =	10.240100
001	11.000000 x	15.643441 =	172.077851

T.E =

4356.3 4356.3

094	1.250000 x	.000000 =	.000000
1446	.200000 x	51.200500 =	10.240100
003	32.000000 x	20.290479 =	649.295328
001	11.000000 x	15.643441 =	172.077851
251	8.000000 x	.927000 =	7.416000

T.E =

4401 4401

001	1.200000 x	15.643441 =	18.772129
-----	------------	-------------	-----------

T.E =

4402 4402

001	3.000000 x	15.643441 =	46.930323
-----	------------	-------------	-----------

T.E =

4501 4501

081	.050000 x	9.940000 =	.497000
002	.500000 x	17.205541 =	8.602771
003	1.000000 x	20.290479 =	20.290479

T.E =

4502 4502

081	.050000 x	9.940000 =	.497000
002	.500000 x	17.205541 =	8.602771
003	1.300000 x	20.290479 =	26.377623

T.E =

4503 4503

081	.050000 x	9.940000 =	.497000
002	.500000 x	17.205541 =	8.602771
003	1.400000 x	20.290479 =	28.406671

T.E =

4504 4504

081	.050000 x	9.940000 =	.497000
002	.300000 x	17.205541 =	5.161662
003	2.300000 x	20.290479 =	46.668102

T.E =

52.326764

4505	4505			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		2.700000 x	20.290479 =	54.784293

			T.E =	60.442956
4506	4506			
081		.050000 x	9.940000 =	.497000
003		3.600000 x	20.290479 =	73.045724
002		.300000 x	17.205541 =	5.161662

			T.E =	78.704387
4507	4507			
081		.050000 x	9.940000 =	.497000
003		3.200000 x	20.290479 =	64.929533
002		.300000 x	17.205541 =	5.161662

			T.E =	70.588195
4508	4508			
081		.050000 x	9.940000 =	.497000
003		3.000000 x	20.290479 =	60.871437
002		.300000 x	17.205541 =	5.161662

			T.E =	66.530099
4511	4511			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		3.800000 x	20.290479 =	77.103820

			T.E =	82.762483
4512	4512			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		4.000000 x	20.290479 =	81.161916

			T.E =	86.820578
4515	4515			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		5.000000 x	20.290479 =	101.452395

			T.E =	107.111057

4516	4516			
081		.050000 x	9.940000 =	.497000
003		4.500000 x	20.290479 =	91.307156
002		.300000 x	17.205541 =	5.161662

			T.E =	96.965818
4517	4517			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		6.500000 x	20.290479 =	131.888114

			T.E =	137.546776
4518	4518			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		5.700000 x	20.290479 =	115.655730

			T.E =	121.314393
4519	4519			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		5.200000 x	20.290479 =	105.510491

			T.E =	111.169153
4521	4521			
081		.050000 x	9.940000 =	.497000
003		3.500000 x	20.290479 =	71.016677
002		.300000 x	17.205541 =	5.161662

			T.E =	76.675339
4522	4522			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		2.700000 x	20.290479 =	54.784293

			T.E =	60.442956
4525	4525			
081		.050000 x	9.940000 =	.497000
002		.300000 x	17.205541 =	5.161662
003		4.500000 x	20.290479 =	91.307156

			T.E =	96.965818

4526 4526

081	.050000 x	9.940000 =	.497000
002	.300000 x	17.205541 =	5.161662
003	4.000000 x	20.290479 =	81.161916

T.E = 86.820578

4527 4527

081	.050000 x	9.940000 =	.497000
003	6.000000 x	20.290479 =	121.742874
002	.300000 x	17.205541 =	5.161662

T.E = 127.401536

4528 4528

081	.050000 x	9.940000 =	.497000
003	5.200000 x	20.290479 =	105.510491
002	.300000 x	17.205541 =	5.161662

T.E = 111.169153

4529 4529

081	.050000 x	9.940000 =	.497000
003	4.700000 x	20.290479 =	95.365251
002	.300000 x	17.205541 =	5.161662

T.E = 101.023914

4531 4531

081	.050000 x	9.940000 =	.497000
003	2.500000 x	20.290479 =	50.726198

T.E = 51.223198

4532 4532

081	.050000 x	9.940000 =	.497000
003	2.000000 x	20.290479 =	40.580958

T.E = 41.077958

4535 4535

081	.050000 x	9.940000 =	.497000
003	3.800000 x	20.290479 =	77.103820

T.E = 77.600820

4536 4536

081	.050000 x	9.940000 =	.497000
003	3.100000 x	20.290479 =	62.900485

T.E = 63.397485

4537 4537

081	.050000 x	9.940000 =	.497000
003	5.500000 x	20.290479 =	111.597635

T.E = 112.094635

4538 4538

081	.050000 x	9.940000 =	.497000
003	4.600000 x	20.290479 =	93.336203

T.E = 93.833203

4539 4539

081	.050000 x	9.940000 =	.497000
003	4.200000 x	20.290479 =	85.220012

T.E = 85.717012

4541 4541

081	.050000 x	9.940000 =	.497000
003	2.500000 x	20.290479 =	50.726198

T.E = 51.223198

4542 4542

081	.050000 x	9.940000 =	.497000
003	2.000000 x	20.290479 =	40.580958

T.E = 41.077958

4543 4543

081	.050000 x	9.940000 =	.497000
003	4.000000 x	20.290479 =	81.161916

T.E = 81.658916

4544 4544

081	.050000 x	9.940000 =	.497000
003	6.000000 x	20.290479 =	121.742874

T.E = 122.239874

4601.1 4601.1

101	105.000000 x	.000000 =	.000000
003	.700000 x	20.290479 =	14.203335
1417	.023000 x	38.934450 =	.895492
001	.600000 x	15.643441 =	9.386065

T.E =

2

μ

2012

.
μ/

75

08/01/2014

4601.2 4601.2

101	105.000000 x	.000000 =	.000000
1447	.023000 x	57.535900 =	1.323326
003	.700000 x	20.290479 =	14.203335
001	.600000 x	15.643441 =	9.386065

T.E =

4602.1 4602.1

101	210.000000 x	.000000 =	.000000
1417	.056000 x	38.934450 =	2.180329
003	1.300000 x	20.290479 =	26.377623
001	1.300000 x	15.643441 =	20.336473

T.E =

4602.2 4602.2

101	210.000000 x	.000000 =	.000000
001	1.300000 x	15.643441 =	20.336473
1447	.056000 x	57.535900 =	3.222010
003	1.300000 x	20.290479 =	26.377623

T.E =

4603.1 4603.1

101	315.000000 x	.000000 =	.000000
1417	.089000 x	38.934450 =	3.465166
003	1.800000 x	20.290479 =	36.522862
001	1.900000 x	15.643441 =	29.722538

T.E =

4603.2 4603.2

101	315.000000 x	.000000 =	.000000
1447	.089000 x	57.535900 =	5.120695
003	1.800000 x	20.290479 =	36.522862
001	1.900000 x	15.643441 =	29.722538

T.E =

4604.1 4604.1

101	1,050.000000 x	.000000 =	.000000
1417	.332000 x	38.934450 =	12.926237
003	5.500000 x	20.290479 =	111.597635
001	6.300000 x	15.643441 =	98.553678

T.E =

2

μ

2012

.
μ/

76

08/01/2014

4604.2 4604.2

101	1,050.000000 x	.000000 =	.000000
001	6.300000 x	15.643441 =	98.553678
1447	.332000 x	57.535900 =	19.101919
003	5.500000 x	20.290479 =	111.597635

T.E =

4611.1 4611.1

102	105.000000 x	.000000 =	.000000
001	.700000 x	15.643441 =	10.950409
1417	.030000 x	38.934450 =	1.168034
003	.700000 x	20.290479 =	14.203335

T.E =

4611.2 4611.2

102	105.000000 x	.000000 =	.000000
001	.700000 x	15.643441 =	10.950409
1447	.030000 x	57.535900 =	1.726077
003	.700000 x	20.290479 =	14.203335

T.E =

4612.1 4612.1

102	210.000000 x	.000000 =	.000000
1417	.070000 x	38.934450 =	2.725412
003	1.300000 x	20.290479 =	26.377623
001	1.400000 x	15.643441 =	21.900817

T.E =

4612.2 4612.2

102	210.000000 x	.000000 =	.000000
001	1.400000 x	15.643441 =	21.900817
1447	.070000 x	57.535900 =	4.027513
003	1.300000 x	20.290479 =	26.377623

T.E =

4613.1 4613.1

102	315.000000 x	.000000 =	.000000
1417	.110000 x	38.934450 =	4.282790
003	1.800000 x	20.290479 =	36.522862
001	2.100000 x	15.643441 =	32.851226

T.E =

4613.2 4613.2

102	315.000000 x	.000000 =	.000000
1447	.110000 x	57.535900 =	6.328949
003	1.800000 x	20.290479 =	36.522862
001	2.100000 x	15.643441 =	32.851226

T.E =

4614.1 4614.1

102	1,050.000000 x	.000000 =	.000000
1417	.404000 x	38.934450 =	15.729518
003	5.500000 x	20.290479 =	111.597635
001	6.500000 x	15.643441 =	101.682367

T.E =

4614.2 4614.2

102	1,050.000000 x	.000000 =	.000000
001	6.500000 x	15.643441 =	101.682367
1447	.404000 x	57.535900 =	23.244504
003	5.500000 x	20.290479 =	111.597635

T.E =

4621.1 4621.1

111	53.000000 x	.072100 =	3.821300
001	.400000 x	15.643441 =	6.257376
1417	.010000 x	38.934450 =	.389345
003	.500000 x	20.290479 =	10.145240

T.E = 20.613260

4621.2 4621.2

111	53.000000 x	.072100 =	3.821300
001	.400000 x	15.643441 =	6.257376
1447	.010000 x	57.535900 =	.575359
003	.500000 x	20.290479 =	10.145240

T.E = 20.799275

4622.1 4622.1

111	75.000000 x	.072100 =	5.407500
1417	.020000 x	38.934450 =	.778689
003	.500000 x	20.290479 =	10.145240
001	.450000 x	15.643441 =	7.039548

T.E = 23.370977

4622.2 4622.2

111	75.000000 x	.072100 =	5.407500
001	.450000 x	15.643441 =	7.039548
1447	.020000 x	57.535900 =	1.150718
003	.500000 x	20.290479 =	10.145240

T.E = 23.743006

4623.1 4623.1

111	150.000000 x	.072100 =	10.815000
001	.950000 x	15.643441 =	14.861269
1417	.050000 x	38.934450 =	1.946723
003	.950000 x	20.290479 =	19.275955

T.E = 46.898947

4623.2 4623.2

111	150.000000 x	.072100 =	10.815000
001	.950000 x	15.643441 =	14.861269
1447	.050000 x	57.535900 =	2.876795
003	.950000 x	20.290479 =	19.275955

T.E = 47.829019

4624.1 4624.1

111	225.000000 x	.072100 =	16.222500
1417	.085000 x	38.934450 =	3.309428
003	1.300000 x	20.290479 =	26.377623
001	1.500000 x	15.643441 =	23.465162

T.E = 69.374712

4624.2 4624.2

111	225.000000 x	.072100 =	16.222500
001	1.500000 x	15.643441 =	23.465162
1447	.085000 x	57.535900 =	4.890552
003	1.300000 x	20.290479 =	26.377623

T.E = 70.955836

4625.1 4625.1

111	750.000000 x	.072100 =	54.075000
001	5.200000 x	15.643441 =	81.345893
1417	.320000 x	38.934450 =	12.459024
003	4.300000 x	20.290479 =	87.249060

T.E = 235.128977

4625.2 4625.2

111	750.000000 x	.072100 =	54.075000
001	5.200000 x	15.643441 =	81.345893
1447	.320000 x	57.535900 =	18.411488
003	4.300000 x	20.290479 =	87.249060

T.E = 241.081441

4631.1 4631.1

4601.1	2.200000 x	.000000 =	.000000
--------	------------	-----------	---------

T.E =

4631.2 4631.2

4601.2	2.200000 x	.000000 =	.000000
--------	------------	-----------	---------

T.E =

4631.3 4631.3

4611.1	2.200000 x	.000000 =	.000000
--------	------------	-----------	---------

T.E =

4631.4 4631.4

4611.2	2.200000 x	.000000 =	.000000
--------	------------	-----------	---------

T.E =

4632.1 4632.1

4601.1	1.200000 x	.000000 =	.000000
4602.1	1.000000 x	.000000 =	.000000

T.E =

4632.2 4632.2

4601.2	1.200000 x	.000000 =	.000000
4602.2	1.000000 x	.000000 =	.000000

T.E =

4632.3 4632.3

4611.1	1.200000 x	.000000 =	.000000
4612.1	1.000000 x	.000000 =	.000000

T.E =

4632.4 4632.4

4611.2	1.200000 x	.000000 =	.000000
4612.2	1.000000 x	.000000 =	.000000

T.E =

4633.1 4633.1

4622.1	2.200000 x	23.370977 =	51.416149
--------	------------	-------------	-----------

T.E =

4633.2 4633.2

4622.2	2.200000 x	23.743006 =	52.234613
--------	------------	-------------	-----------

T.E =

4634.1 4634.1

4622.1	1.200000 x	23.370977 =	28.045172
4623.1	1.000000 x	46.898947 =	46.898947

T.E =

4634.2 4634.2

4622.2	1.200000 x	23.743006 =	28.491607
4623.2	1.000000 x	47.829019 =	47.829019

T.E =

4661.1 4661.1

112	43.750000 x	.079100 =	3.460625
1417	.014507 x	38.934450 =	.564822
003	.500000 x	20.290479 =	10.145240
001	.400000 x	15.643441 =	6.257376

T.E =

4661.2 4661.2

112	43.750000 x	.079100 =	3.460625
001	.400000 x	15.643441 =	6.257376
1447	.014507 x	57.535900 =	.834673
003	.500000 x	20.290479 =	10.145240

T.E =

4662.1 4662.1

112	58.333300 x	.079100 =	4.614164
001	.450000 x	15.643441 =	7.039548
1417	.022840 x	38.934450 =	.889263
003	.500000 x	20.290479 =	10.145240

T.E =

22.688215

4662.2 4662.2

112	58.333300 x	.079100 =	4.614164
001	.450000 x	15.643441 =	7.039548
1447	.022840 x	57.535900 =	1.314120
003	.500000 x	20.290479 =	10.145240

T.E = 23.113072

4663.1 4663.1

112	105.000000 x	.079100 =	8.305500
1417	.043218 x	38.934450 =	1.682669
003	.900000 x	20.290479 =	18.261431
001	.900000 x	15.643441 =	14.079097

T.E = 42.328697

4663.2 4663.2

112	105.000000 x	.079100 =	8.305500
001	.900000 x	15.643441 =	14.079097
1447	.043218 x	57.535900 =	2.486587
003	.900000 x	20.290479 =	18.261431

T.E = 43.132615

4664.1 4664.1

112	97.222221 x	.079100 =	7.690278
001	.950000 x	15.643441 =	14.861269
1417	.045077 x	38.934450 =	1.755048
003	.950000 x	20.290479 =	19.275955

T.E = 43.582550

4664.2 4664.2

112	97.222221 x	.079100 =	7.690278
001	.950000 x	15.643441 =	14.861269
1447	.045077 x	57.535900 =	2.593546
003	.950000 x	20.290479 =	19.275955

T.E = 44.421047

4665.1 4665.1

112	174.999001 x	.079100 =	13.842421
1417	.047530 x	38.934450 =	1.850554
003	1.300000 x	20.290479 =	26.377623
001	1.500000 x	15.643441 =	23.465162

T.E = 65.535760

4665.2 4665.2

112	174.999001 x	.079100 =	13.842421
001	1.500000 x	15.643441 =	23.465162
1447	.047530 x	57.535900 =	2.734681
003	1.300000 x	20.290479 =	26.377623

T.E = 66.419887

4666.1 4666.1

112	486.111099 x	.079100 =	38.451388
001	5.200000 x	15.643441 =	81.345893
1417	.277862 x	38.934450 =	10.818404
003	4.300000 x	20.290479 =	87.249060

T.E = 217.864745

4666.2 4666.2

112	486.111000 x	.079100 =	38.451380
001	5.200000 x	15.643441 =	81.345893
1447	.277862 x	57.535900 =	15.987040
003	4.300000 x	20.290479 =	87.249060

T.E = 223.033373

4701 4701

113	13.000000 x	.570000 =	7.410000
1417	.020000 x	38.934450 =	.778689
003	.400000 x	20.290479 =	8.116192
001	.500000 x	15.643441 =	7.821721

T.E = 24.126601

4702 4702

113	13.000000 x	.570000 =	7.410000
001	.500000 x	15.643441 =	7.821721
1447	.020000 x	57.535900 =	1.150718
003	.400000 x	20.290479 =	8.116192

T.E = 24.498630

4703 4703

114	13.000000 x	.000000 =	.000000
001	.400000 x	15.643441 =	6.257376
1417	.015000 x	38.934450 =	.584017
003	.350000 x	20.290479 =	7.101668

T.E =

4704 4704

114	13.000000 x	.000000 =	.000000
001	.400000 x	15.643441 =	6.257376
1447	.015000 x	57.535900 =	.863039
003	.350000 x	20.290479 =	7.101668

T.E =

4711 4711

117	13.000000 x	.000000 =	.000000
1417	.020000 x	38.934450 =	.778689
003	.400000 x	20.290479 =	8.116192
001	.500000 x	15.643441 =	7.821721

T.E =

4712 4712

117	13.000000 x	.000000 =	.000000
001	.500000 x	15.643441 =	7.821721
1447	.020000 x	57.535900 =	1.150718
003	.400000 x	20.290479 =	8.116192

T.E =

4713 4713

118	13.000000 x	.000000 =	.000000
001	.400000 x	15.643441 =	6.257376
1417	.015000 x	38.934450 =	.584017
003	.350000 x	20.290479 =	7.101668

T.E =

4714 4714

118	13.000000 x	.000000 =	.000000
001	.400000 x	15.643441 =	6.257376
1447	.015000 x	57.535900 =	.863039
003	.350000 x	20.290479 =	7.101668

T.E =

4721.1 4721.1

128	.080000 x	88.240000 =	7.059200
1417	.004000 x	38.934450 =	.155738
003	.350000 x	20.290479 =	7.101668
001	.300000 x	15.643441 =	4.693032

T.E =

19.009638

4721.2 4721.2

128	.080000 x	88.240000 =	7.059200
001	.300000 x	15.643441 =	4.693032
1447	.004000 x	57.535900 =	.230144
003	.350000 x	20.290479 =	7.101668

T.E = 19.084044

4722.1 4722.1

128	.100000 x	88.240000 =	8.824000
001	.350000 x	15.643441 =	5.475204
1417	.005000 x	38.934450 =	.194672
003	.350000 x	20.290479 =	7.101668

T.E = 21.595544

4722.2 4722.2

128	.100000 x	88.240000 =	8.824000
001	.350000 x	15.643441 =	5.475204
1447	.005000 x	57.535900 =	.287680
003	.350000 x	20.290479 =	7.101668

T.E = 21.688552

4723 4723

128	.120000 x	88.240000 =	10.588800
1417	.006000 x	38.934450 =	.233607
003	.350000 x	20.290479 =	7.101668
001	.400000 x	15.643441 =	6.257376

T.E = 24.181451

4724.1 4724.1

128	.150000 x	88.240000 =	13.236000
001	.400000 x	15.643441 =	6.257376
003	.400000 x	20.290479 =	8.116192
1417	.008000 x	38.934450 =	.311476

T.E = 27.921044

4724.2 4724.2

128	.150000 x	88.240000 =	13.236000
001	.400000 x	15.643441 =	6.257376
1447	.008000 x	57.535900 =	.460287
003	.400000 x	20.290479 =	8.116192

T.E = 28.069855

4725.1 4725.1

128	.180000 x	88.240000 =	15.883200
1417	.009000 x	38.934450 =	.350410
001	.450000 x	15.643441 =	7.039548
003	.400000 x	20.290479 =	8.116192

T.E = 31.389350

4725.2 4725.2

128	.180000 x	88.240000 =	15.883200
1447	.009000 x	57.535900 =	.517823
003	.400000 x	20.290479 =	8.116192
001	.450000 x	15.643441 =	7.039548

T.E = 31.556763

4801.1 4801.1

4662.1	1.000000 x	22.688215 =	22.688215
4662.1	.100000 x	22.688215 =	2.268822

T.E = 24.957037

4801.2 4801.2

4662.2	1.000000 x	23.113072 =	23.113072
4662.2	.100000 x	23.113072 =	2.311307

T.E = 25.424379

4802.1 4802.1

4664.1	1.000000 x	43.582550 =	43.582550
4664.1	.050000 x	43.582550 =	2.179128

T.E = 45.761678

4802.2 4802.2

4664.2	1.000000 x	44.421047 =	44.421047
4664.2	.050000 x	44.421047 =	2.221052

T.E = 46.642099

4803.1 4803.1

4665.1	1.000000 x	65.535760 =	65.535760
4665.1	.030000 x	65.535760 =	1.966073

T.E = 67.501833

4803.2 4803.2

4665.2	1.000000 x	66.419887 =	66.419887
4665.2	.030000 x	66.419887 =	1.992597

T.E = 68.412484

4811.1 4811.1

001	.225000 x	15.643441 =	3.519774
003	.250000 x	20.290479 =	5.072620
4662.1	1.000000 x	22.688215 =	22.688215

T.E = 31.280609

4811.2 4811.2

001	.225000 x	15.643441 =	3.519774
4662.2	1.000000 x	23.113072 =	23.113072
003	.250000 x	20.290479 =	5.072620

T.E = 31.705466

4812.1 4812.1

001	.475000 x	15.643441 =	7.430634
003	.475000 x	20.290479 =	9.637978
4664.1	1.000000 x	43.582550 =	43.582550

T.E = 60.651162

4812.2 4812.2

001	.475000 x	15.643441 =	7.430634
4664.2	1.000000 x	44.421047 =	44.421047
003	.475000 x	20.290479 =	9.637978

T.E = 61.489659

4813.1 4813.1

001	.750000 x	15.643441 =	11.732581
4665.1	1.000000 x	65.535760 =	65.535760
003	.650000 x	20.290479 =	13.188811

T.E = 90.457152

4813.2 4813.2

001	.750000 x	15.643441 =	11.732581
4665.2	1.000000 x	66.419887 =	66.419887
003	.650000 x	20.290479 =	13.188811

T.E = 91.341279

4814.1 4814.1

001	2.600000 x	15.643441 =	40.672947
003	2.150000 x	20.290479 =	43.624530
4666.1	1.000000 x	217.864745 =	217.864745

T.E = 302.162221

4814.2 4814.2

001	2.600000 x	15.643441 =	40.672947
003	2.150000 x	20.290479 =	43.624530
4666.2	1.000000 x	223.033373 =	223.033373

T.E = 307.330849

4821.1 4821.1

003	.450000 x	20.290479 =	9.130716
4662.1	1.000000 x	22.688215 =	22.688215

T.E = 31.818931

4821.2 4821.2

003	.450000 x	20.290479 =	9.130716
4662.2	1.000000 x	23.113072 =	23.113072

T.E = 32.243788

4822.1 4822.1

003	.807500 x	20.290479 =	16.384562
4664.1	1.000000 x	43.582550 =	43.582550

T.E = 59.967112

4822.2 4822.2

003	.807500 x	20.290479 =	16.384562
4664.2	1.000000 x	44.421047 =	44.421047

T.E = 60.805609

4823.1 4823.1

003	1.040000 x	20.290479 =	21.102098
4665.1	1.000000 x	65.535760 =	65.535760

T.E = 86.637858

4823.2 4823.2

003	1.040000 x	20.290479 =	21.102098
4665.2	1.000000 x	66.419887 =	66.419887

T.E = 87.521985

4824.1 4824.1

003	3.010000 x	20.290479 =	61.074342
4666.1	1.000000 x	217.864745 =	217.864745

T.E = 278.939087

4824.2 4824.2

003	3.010000 x	20.290479 =	61.074342
4666.2	1.000000 x	223.033373 =	223.033373

T.E = 284.107715

4831.1 4831.1

003	1.200000 x	20.290479 =	24.348575
4661.1	1.000000 x	20.428063 =	20.428063

T.E = 44.776638

4831.2 4831.2

003	1.200000 x	20.290479 =	24.348575
4661.2	1.000000 x	20.697914 =	20.697914

T.E = 45.046489

4832.1 4832.1

003	1.600000 x	20.290479 =	32.464766
4662.1	1.000000 x	22.688215 =	22.688215

T.E = 55.152981

4832.2 4832.2

003	1.600000 x	20.290479 =	32.464766
4662.2	1.000000 x	23.113072 =	23.113072

T.E = 55.577838

4833.1 4833.1

002	2.000000 x	17.205541 =	34.411082
4664.1	1.000000 x	43.582550 =	43.582550

T.E = 77.993632

4833.2 4833.2

002	2.000000 x	17.205541 =	34.411082
4664.2	1.000000 x	44.421047 =	44.421047

T.E = 78.832129

4834.1 4834.1

003	2.300000 x	20.290479 =	46.668102
4665.1	1.000000 x	65.535760 =	65.535760

T.E = 112.203862

4834.2 4834.2

003	2.300000 x	20.290479 =	46.668102
4665.2	1.000000 x	66.419887 =	66.419887

T.E = 113.087989

4835 4835

122	1.050000 x	.000000 =	.000000
1417	.005000 x	38.934450 =	.194672
003	1.000000 x	20.290479 =	20.290479
001	1.000000 x	15.643441 =	15.643441
265	2.000000 x	.857700 =	1.715400
201	.010000 x	290.000000 =	2.900000

T.E =

4835.2 4835.2

122	1.050000 x	.000000 =	.000000
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.857700 =	1.715400
1447	.005000 x	57.535900 =	.287680
003	1.000000 x	20.290479 =	20.290479
001	1.000000 x	15.643441 =	15.643441

T.E =

4836.1 4836.1

123	1.050000 x	.000000 =	.000000
1417	.005000 x	38.934450 =	.194672
003	1.000000 x	20.290479 =	20.290479
201	.010000 x	290.000000 =	2.900000
001	1.000000 x	15.643441 =	15.643441
265	2.000000 x	.857700 =	1.715400

T.E =

4836.2 4836.2

123	1.050000 x	.000000 =	.000000
201	.010000 x	290.000000 =	2.900000
001	1.000000 x	15.643441 =	15.643441
1447	.005000 x	57.535900 =	.287680
003	1.000000 x	20.290479 =	20.290479
265	2.000000 x	.857700 =	1.715400

T.E =

4837.1 4837.1

124	1.050000 x	5.900000 =	6.195000
1417	.010000 x	38.934450 =	.389345
003	1.000000 x	20.290479 =	20.290479
001	1.000000 x	15.643441 =	15.643441
265	2.000000 x	.857700 =	1.715400
201	.010000 x	290.000000 =	2.900000

T.E = 47.133665

4837.2 4837.2

124	1.050000 x	5.900000 =	6.195000
003	1.000000 x	20.290479 =	20.290479
1447	.010000 x	57.535900 =	.575359
002	1.000000 x	17.205541 =	17.205541
201	.010000 x	290.000000 =	2.900000
265	2.000000 x	.857700 =	1.715400

T.E = 48.881779

4841 4841

003	.700000 x	20.290479 =	14.203335
-----	-----------	-------------	-----------

T.E = 14.203335

4842 4842

003	1.000000 x	20.290479 =	20.290479
-----	------------	-------------	-----------

T.E = 20.290479

4843 4843

003	.250000 x	20.290479 =	5.072620
-----	-----------	-------------	----------

T.E = 5.072620

4844 4844

131	1,200.000000 x	.620000 =	744.000000
001	10.000000 x	15.643441 =	156.434410
1401	.250000 x	242.301000 =	60.575250
003	25.000000 x	20.290479 =	507.261975

T.E = 1,468.271635

4845 4845

132	620.000000 x	.880000 =	545.600000
003	15.000000 x	20.290479 =	304.357185
001	6.000000 x	15.643441 =	93.860646
1401	.180000 x	242.301000 =	43.614180

T.E = 987.432011

4851	4851			
001		.100000 x	15.643441 =	1.564344

			T.E =	1.564344
4852	4852			
001		.150000 x	15.643441 =	2.346516

			T.E =	2.346516
4853	4853			
001		.200000 x	15.643441 =	3.128688

			T.E =	3.128688
4854	4854			
001		.250000 x	15.643441 =	3.910860

			T.E =	3.910860
4855	4855			
001		.300000 x	15.643441 =	4.693032

			T.E =	4.693032
4856	4856			
001		.800000 x	15.643441 =	12.514753

			T.E =	12.514753
4857	4857			
001		.200000 x	15.643441 =	3.128688

			T.E =	3.128688
4858	4858			
001		.300000 x	15.643441 =	4.693032

			T.E =	4.693032
4859	4859			
001		.400000 x	15.643441 =	6.257376

			T.E =	6.257376
4860	4860			
001		.500000 x	15.643441 =	7.821721

			T.E =	7.821721

4861	4861			
001		.600000 x	15.643441 =	9.386065

			T.E =	9.386065
4862	4862			
001		1.700000 x	15.643441 =	26.593850

			T.E =	26.593850
5101	5101			
214		1.100000 x	1,000.000000 =	1,100.000000
003		4.000000 x	20.290479 =	81.161916
001		1.000000 x	15.643441 =	15.643441

			T.E =	1,196.805357
5102	5102			
483		1.800000 x	.167500 =	.301500
488		.540000 x	5.500000 =	2.970000
489		.360000 x	.000000 =	.000000
001		1.000000 x	15.643441 =	15.643441
492		1.440000 x	.540000 =	.777600
491		1.260000 x	.540000 =	.680400

			T.E =	
5103	5103			
265		1.050000 x	.857700 =	.900585
003		.200000 x	20.290479 =	4.058096
002		.050000 x	17.205541 =	.860277

			T.E =	5.818958
5104	5104			
001		2.000000 x	15.643441 =	31.286882
003		.150000 x	20.290479 =	3.043572

			T.E =	34.330454
5105	5105			
214		.010000 x	1,000.000000 =	10.000000
003		.500000 x	20.290479 =	10.145240
001		2.000000 x	15.643441 =	31.286882

			T.E =	51.432122

5106	5106			
214		.050000 x	1,000.000000 =	50.000000
003		2.500000 x	20.290479 =	50.726198
001		2.000000 x	15.643441 =	31.286882

			T.E =	132.013080
5201	5201			
201		1.100000 x	290.000000 =	319.000000
003		10.000000 x	20.290479 =	202.904790
002		5.000000 x	17.205541 =	86.027705
251		6.000000 x	.927000 =	5.562000

			T.E =	613.494495
5202	5202			
203.2		1.080000 x	370.000000 =	399.600000
002		4.500000 x	17.205541 =	77.424935
003		9.000000 x	20.290479 =	182.614311
251		6.000000 x	.927000 =	5.562000

			T.E =	665.201246
5203	5203			
201		1.120000 x	290.000000 =	324.800000
251		12.000000 x	.927000 =	11.124000
003		16.000000 x	20.290479 =	324.647664
002		8.000000 x	17.205541 =	137.644328

			T.E =	798.215992
5204	5204			
203.2		1.100000 x	370.000000 =	407.000000
251		12.000000 x	.927000 =	11.124000
003		14.000000 x	20.290479 =	284.066706
002		7.000000 x	17.205541 =	120.438787

			T.E =	822.629493
5211	5211			
201		1.100000 x	290.000000 =	319.000000
003		12.000000 x	20.290479 =	243.485748
002		6.000000 x	17.205541 =	103.233246
251		14.000000 x	.927000 =	12.978000

			T.E =	678.696994

5212	5212			
203.2		1.080000 x	370.000000 =	399.600000
251		14.000000 x	.927000 =	12.978000
002		5.000000 x	17.205541 =	86.027705
003		10.000000 x	20.290479 =	202.904790

			T.E =	701.510495
5213	5213			
201		1.100000 x	290.000000 =	319.000000
251		8.000000 x	.927000 =	7.416000
003		9.000000 x	20.290479 =	182.614311
002		4.500000 x	17.205541 =	77.424935

			T.E =	586.455246
5221	5221			
203.2		.014000 x	370.000000 =	5.180000
251		.100000 x	.927000 =	.092700
003		.200000 x	20.290479 =	4.058096
002		.050000 x	17.205541 =	.860277

			T.E =	10.191073
5222	5222			
203.2		.018000 x	370.000000 =	6.660000
003		.200000 x	20.290479 =	4.058096
002		.070000 x	17.205541 =	1.204388
251		.100000 x	.927000 =	.092700

			T.E =	12.015184
5223	5223			
203.2		.026000 x	370.000000 =	9.620000
251		.100000 x	.927000 =	.092700
002		.100000 x	17.205541 =	1.720554
003		.200000 x	20.290479 =	4.058096

			T.E =	15.491350
5226	5226			
203.2		.016000 x	370.000000 =	5.920000
251		.100000 x	.927000 =	.092700
003		.200000 x	20.290479 =	4.058096
002		.050000 x	17.205541 =	.860277

			T.E =	10.931073

5227	5227				
203.2		.022000 x	370.000000 =	8.140000	
251		.100000 x	.927000 =	.092700	
003		.200000 x	20.290479 =	4.058096	
002		.100000 x	17.205541 =	1.720554	

			T.E =	14.011350	
5228	5228				
203.2		.030000 x	370.000000 =	11.100000	
003		.200000 x	20.290479 =	4.058096	
002		.150000 x	17.205541 =	2.580831	
251		.150000 x	.927000 =	.139050	

			T.E =	17.877977	
5231	5231				
203.2		.018000 x	370.000000 =	6.660000	
251		.150000 x	.927000 =	.139050	
002		.100000 x	17.205541 =	1.720554	
003		.250000 x	20.290479 =	5.072620	

			T.E =	13.592224	
5232	5232				
203.2		.025000 x	370.000000 =	9.250000	
251		.150000 x	.927000 =	.139050	
003		.250000 x	20.290479 =	5.072620	
002		.120000 x	17.205541 =	2.064665	

			T.E =	16.526335	
5233	5233				
203.2		.034000 x	370.000000 =	12.580000	
251		.200000 x	.927000 =	.185400	
003		.250000 x	20.290479 =	5.072620	
002		.150000 x	17.205541 =	2.580831	

			T.E =	20.418851	
5236	5236				
203.2		.016000 x	370.000000 =	5.920000	
003		.350000 x	20.290479 =	7.101668	
002		.250000 x	17.205541 =	4.301385	
251		.080000 x	.927000 =	.074160	

			T.E =	17.397213	

5237 5237

203.2	.022000 x	370.000000 =	8.140000
251	.080000 x	.927000 =	.074160
002	.300000 x	17.205541 =	5.161662
003	.350000 x	20.290479 =	7.101668

T.E = 20.477490

5238 5238

203.2	.030000 x	370.000000 =	11.100000
251	.100000 x	.927000 =	.092700
003	.350000 x	20.290479 =	7.101668
002	.350000 x	17.205541 =	6.021939

T.E = 24.316307

5241 5241

203.2	.030000 x	370.000000 =	11.100000
251	.100000 x	.927000 =	.092700
003	.500000 x	20.290479 =	10.145240
002	.500000 x	17.205541 =	8.602771

T.E = 29.940710

5243 5243

003	.150000 x	20.290479 =	3.043572
-----	-----------	-------------	----------

T.E = 3.043572

5244 5244

003	.350000 x	20.290479 =	7.101668
-----	-----------	-------------	----------

T.E = 7.101668

5246 5246

220	26.000000 x	.000000 =	.000000
002	.500000 x	17.205541 =	8.602771
251	.200000 x	.927000 =	.185400

T.E =

5247 5247

221	30.000000 x	.000000 =	.000000
251	.100000 x	.927000 =	.092700
002	.600000 x	17.205541 =	10.323325
283	.100000 x	1.305700 =	.130570

T.E =

5251	5251				
243.3		1.050000 x	4.500000 =	4.725000	
002		.300000 x	17.205541 =	5.161662	
003		.300000 x	20.290479 =	6.087144	
251		.100000 x	.927000 =	.092700	

			T.E =	16.066506	
5252.1	5252.1				
245		1.100000 x	18.000000 =	19.800000	
003		2.500000 x	20.290479 =	50.726198	
002		2.500000 x	17.205541 =	43.013853	
245		.110000 x	18.000000 =	1.980000	

			T.E =	115.520050	
5252.2	5252.2				
246		1.100000 x	13.000000 =	14.300000	
246		.110000 x	13.000000 =	1.430000	
002		2.500000 x	17.205541 =	43.013853	
003		2.500000 x	20.290479 =	50.726198	

			T.E =	109.470050	
5252.3	5252.3				
249		1.100000 x	20.000000 =	22.000000	
249		.110000 x	20.000000 =	2.200000	
003		2.500000 x	20.290479 =	50.726198	
002		2.500000 x	17.205541 =	43.013853	

			T.E =	117.940050	
5256	5256				
219		1.200000 x	3.500000 =	4.200000	
219		.060000 x	3.500000 =	.210000	
003		1.500000 x	20.290479 =	30.435719	
002		1.500000 x	17.205541 =	25.808312	

			T.E =	60.654030	
5261	5261				
201		.020000 x	290.000000 =	5.800000	
003		.800000 x	20.290479 =	16.232383	
002		.800000 x	17.205541 =	13.764433	
251		.600000 x	.927000 =	.556200	
203.2		.025000 x	370.000000 =	9.250000	

			T.E =	45.603016	

5262	5262			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.927000 =	.278100
003		1.000000 x	20.290479 =	20.290479
002		1.000000 x	17.205541 =	17.205541
265		.300000 x	.857700 =	.257310
252		.200000 x	2.184000 =	.436800
203.2		.025000 x	370.000000 =	9.250000

			T.E =	56.418230
5266	5266			
201		.020000 x	290.000000 =	5.800000
203.2		.015000 x	370.000000 =	5.550000
251		.600000 x	.927000 =	.556200
003		.600000 x	20.290479 =	12.174287
002		.600000 x	17.205541 =	10.323325

			T.E =	34.403812
5267	5267			
201		.030000 x	290.000000 =	8.700000
251		.300000 x	.927000 =	.278100
003		.800000 x	20.290479 =	16.232383
002		.800000 x	17.205541 =	13.764433
252		.300000 x	2.184000 =	.655200
265		.300000 x	.857700 =	.257310
203.2		.015000 x	370.000000 =	5.550000

			T.E =	45.437426
5271	5271			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	20.290479 =	10.145240
002		.500000 x	17.205541 =	8.602771
251		.600000 x	.927000 =	.556200
203.2		.025000 x	370.000000 =	9.250000

			T.E =	33.194210
5272	5272			
201		.024000 x	290.000000 =	6.960000
003		.700000 x	20.290479 =	14.203335
002		.700000 x	17.205541 =	12.043879
252		.100000 x	2.184000 =	.218400
265		.200000 x	.857700 =	.171540
251		.300000 x	.927000 =	.278100
203.2		.025000 x	370.000000 =	9.250000

			T.E =	43.125254

5273	5273			
201		.016000 x	290.000000 =	4.640000
003		.500000 x	20.290479 =	10.145240
002		.500000 x	17.205541 =	8.602771
251		.600000 x	.927000 =	.556200
203.2		.015000 x	370.000000 =	5.550000

T.E = 29.494210

5274	5274			
201		.024000 x	290.000000 =	6.960000
252		.100000 x	2.184000 =	.218400
003		.700000 x	20.290479 =	14.203335
002		.700000 x	17.205541 =	12.043879
265		.200000 x	.857700 =	.171540
203.2		.015000 x	370.000000 =	5.550000
251		.300000 x	.927000 =	.278100

T.E = 39.425254

5276	5276			
201		1.080000 x	290.000000 =	313.200000
252		18.000000 x	2.184000 =	39.312000
003		19.000000 x	20.290479 =	385.519101
002		19.000000 x	17.205541 =	326.905279
251		6.000000 x	.927000 =	5.562000

T.E = 1,070.498380

5277	5277			
203.2		1.080000 x	370.000000 =	399.600000
252		18.000000 x	2.184000 =	39.312000
251		6.000000 x	.927000 =	5.562000
002		18.000000 x	17.205541 =	309.699738
003		18.000000 x	20.290479 =	365.228622

T.E = 1,119.402360

5279	5279			
201		1.080000 x	290.000000 =	313.200000
251		12.000000 x	.927000 =	11.124000
002		5.000000 x	17.205541 =	86.027705
003		10.000000 x	20.290479 =	202.904790

T.E = 613.256495

5280	5280			
203.2		1.080000 x	370.000000 =	399.600000
251		12.000000 x	.927000 =	11.124000
003		10.000000 x	20.290479 =	202.904790
002		5.000000 x	17.205541 =	86.027705

			T.E =	699.656495
5281	5281			
203.2		.014000 x	370.000000 =	5.180000
002		.250000 x	17.205541 =	4.301385
251		.040000 x	.927000 =	.037080

			T.E =	9.518465
5282	5282			
203.2		.020000 x	370.000000 =	7.400000
251		.060000 x	.927000 =	.055620
002		.350000 x	17.205541 =	6.021939

			T.E =	13.477559
5283	5283			
203.2		.026000 x	370.000000 =	9.620000
251		.080000 x	.927000 =	.074160
002		.400000 x	17.205541 =	6.882216

			T.E =	16.576376
5286	5286			
203.2		.008000 x	370.000000 =	2.960000
003		.120000 x	20.290479 =	2.434857
251		.030000 x	.927000 =	.027810
002		.120000 x	17.205541 =	2.064665

			T.E =	7.487332
5288	5288			
003		.300000 x	20.290479 =	6.087144

			T.E =	6.087144
5289	5289			
003		1.000000 x	20.290479 =	20.290479

			T.E =	20.290479

5291	5291			
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.290479 =	8.116192
002		.400000 x	17.205541 =	6.882216
220		26.000000 x	.000000 =	.000000
251		.200000 x	.927000 =	.185400

T.E =

5292	5292			
201		.010000 x	290.000000 =	2.900000
003		.600000 x	20.290479 =	12.174287
002		.600000 x	17.205541 =	10.323325
251		.200000 x	.927000 =	.185400
203.2		.010000 x	370.000000 =	3.700000
220		26.000000 x	.000000 =	.000000

T.E =

5293	5293			
203.2		.020000 x	370.000000 =	7.400000
203.2		.016000 x	370.000000 =	5.920000
003		.400000 x	20.290479 =	8.116192
002		.400000 x	17.205541 =	6.882216
251		.150000 x	.927000 =	.139050

T.E =

5294	5294			28.457458
203.2		.020000 x	370.000000 =	7.400000
003		.400000 x	20.290479 =	8.116192
002		.400000 x	17.205541 =	6.882216
203.2		.022000 x	370.000000 =	8.140000
251		.100000 x	.927000 =	.092700

T.E =

5295	5295			30.631108
203.2		.020000 x	370.000000 =	7.400000
251		.050000 x	.927000 =	.046350
003		.250000 x	20.290479 =	5.072620
002		.250000 x	17.205541 =	4.301385

T.E =

5301	5301			16.820355
226		1.050000 x	13.000000 =	13.650000
251		.250000 x	.927000 =	.231750
003		.600000 x	20.290479 =	12.174287
002		.600000 x	17.205541 =	10.323325

T.E =

36.379362

5302	5302			
227		1.050000 x	13.000000 =	13.650000
002		.500000 x	17.205541 =	8.602771
003		.500000 x	20.290479 =	10.145240
251		.200000 x	.927000 =	.185400

			T.E =	32.583410
5321	5321			
203.2		.012000 x	370.000000 =	4.440000
003		.900000 x	20.290479 =	18.261431
002		.900000 x	17.205541 =	15.484987
251		.500000 x	.927000 =	.463500
226		1.050000 x	13.000000 =	13.650000

			T.E =	52.299918
5322	5322			
203.2		.012000 x	370.000000 =	4.440000
227		1.050000 x	13.000000 =	13.650000
251		.450000 x	.927000 =	.417150
003		.800000 x	20.290479 =	16.232383
002		.800000 x	17.205541 =	13.764433

			T.E =	48.503966
5323	5323			
203.2		.012000 x	370.000000 =	4.440000
003		1.000000 x	20.290479 =	20.290479
228		1.050000 x	35.000000 =	36.750000
002		1.000000 x	17.205541 =	17.205541
251		.500000 x	.927000 =	.463500

			T.E =	79.149520
5324	5324			
203.2		.012000 x	370.000000 =	4.440000
229		1.050000 x	.000000 =	.000000
002		1.000000 x	17.205541 =	17.205541
003		1.000000 x	20.290479 =	20.290479
251		.500000 x	.927000 =	.463500

			T.E =	
5325	5325			
203.2		.012000 x	370.000000 =	4.440000
003		1.000000 x	20.290479 =	20.290479
002		1.000000 x	17.205541 =	17.205541
251		.500000 x	.927000 =	.463500
230		1.050000 x	.000000 =	.000000

			T.E =	

5326	5326			
203.2		.012000 x	370.000000 =	4.440000
231		1.050000 x	22.000000 =	23.100000
251		.500000 x	.927000 =	.463500
003		1.000000 x	20.290479 =	20.290479
002		1.000000 x	17.205541 =	17.205541

			T.E =	65.499520
5341	5341			
203.2		.037000 x	370.000000 =	13.690000
003		1.100000 x	20.290479 =	22.319527
232		1.050000 x	45.000000 =	47.250000
002		1.100000 x	17.205541 =	18.926095
251		.600000 x	.927000 =	.556200

			T.E =	102.741822
5342	5342			
203.2		.037000 x	370.000000 =	13.690000
232		1.100000 x	45.000000 =	49.500000
002		1.700000 x	17.205541 =	29.249420
003		1.700000 x	20.290479 =	34.493814
251		.600000 x	.927000 =	.556200

			T.E =	127.489434
5343	5343			
233		1.050000 x	21.300000 =	22.365000
003		.800000 x	20.290479 =	16.232383
002		.800000 x	17.205541 =	13.764433
233		.084000 x	21.300000 =	1.789200

			T.E =	54.151016
5351	5351			
035		.200000 x	.088300 =	.017660
003		.200000 x	20.290479 =	4.058096
002		.200000 x	17.205541 =	3.441108
251		.100000 x	.927000 =	.092700
236		1.060000 x	1.550000 =	1.643000

			T.E =	9.252564
5352	5352			
035		.200000 x	.088300 =	.017660
251		.100000 x	.927000 =	.092700
003		.200000 x	20.290479 =	4.058096
002		.200000 x	17.205541 =	3.441108
237		1.060000 x	1.850000 =	1.961000

			T.E =	9.570564

5353 5353

035	.200000 x	.088300 =	.017660
238	1.060000 x	2.600000 =	2.756000
002	.200000 x	17.205541 =	3.441108
003	.200000 x	20.290479 =	4.058096
251	.100000 x	.927000 =	.092700

T.E = 10.365564

5354 5354

035	.200000 x	.088300 =	.017660
239	1.060000 x	.000000 =	.000000
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108
251	.100000 x	.927000 =	.092700

T.E =

5355 5355

035	.200000 x	.088300 =	.017660
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108
251	.100000 x	.927000 =	.092700
240	1.060000 x	1.400000 =	1.484000

T.E = 9.093564

5356 5356

035	.200000 x	.088300 =	.017660
251	.100000 x	.927000 =	.092700
002	.200000 x	17.205541 =	3.441108
003	.200000 x	20.290479 =	4.058096
241	1.060000 x	.000000 =	.000000

T.E =

5421 5421

205	.055000 x	480.000000 =	26.400000
1471	1.000000 x	5.821528 =	5.821528
003	3.500000 x	20.290479 =	71.016677
002	3.500000 x	17.205541 =	60.219394

T.E = 163.457598

5422 5422

205	.035000 x	480.000000 =	16.800000
1472	1.000000 x	7.011564 =	7.011564
003	3.000000 x	20.290479 =	60.871437
002	3.000000 x	17.205541 =	51.616623

T.E = 136.299624

5426	5426			
205		.095000 x	480.000000 =	45.600000
002		6.000000 x	17.205541 =	103.233246
003		6.000000 x	20.290479 =	121.742874
1473		1.000000 x	11.960743 =	11.960743
1471		1.000000 x	5.821528 =	5.821528

T.E = 288.358391

5427	5427			
205		.105000 x	480.000000 =	50.400000
002		7.000000 x	17.205541 =	120.438787
1474		1.000000 x	14.512262 =	14.512262
1471		1.000000 x	5.821528 =	5.821528
003		7.000000 x	20.290479 =	142.033353

T.E = 333.205930

5428	5428			
205		.075000 x	480.000000 =	36.000000
003		5.500000 x	20.290479 =	111.597635
1474		1.000000 x	14.512262 =	14.512262
1472		1.000000 x	7.011564 =	7.011564
002		5.500000 x	17.205541 =	94.630476

T.E = 263.751936

5431	5431			
205		.070000 x	480.000000 =	33.600000
1475		1.000000 x	40.398907 =	40.398907
208		.030000 x	1,435.000000 =	43.050000
1471		1.000000 x	5.821528 =	5.821528
003		7.000000 x	20.290479 =	142.033353
002		7.000000 x	17.205541 =	120.438787

T.E = 385.342575

5432	5432			
205		.070000 x	480.000000 =	33.600000
1475		.800000 x	40.398907 =	32.319126
1471		1.000000 x	5.821528 =	5.821528
003		5.000000 x	20.290479 =	101.452395
002		5.000000 x	17.205541 =	86.027705
380		1.000000 x	16.560000 =	16.560000

T.E = 275.780754

5436 5436

205	.050000 x	480.000000 =	24.000000
002	4.500000 x	17.205541 =	77.424935
1476	1.000000 x	3.087100 =	3.087100
003	4.500000 x	20.290479 =	91.307156

T.E = 195.819190

5437 5437

205	.065000 x	480.000000 =	31.200000
002	5.000000 x	17.205541 =	86.027705
003	5.000000 x	20.290479 =	101.452395
1476	1.000000 x	3.087100 =	3.087100

T.E = 221.767200

5438 5438

205	.050000 x	480.000000 =	24.000000
002	4.000000 x	17.205541 =	68.822164
1476	1.000000 x	3.087100 =	3.087100
003	4.000000 x	20.290479 =	81.161916

T.E = 177.071180

5441.1 5441.1

205	.065000 x	480.000000 =	31.200000
1476	1.000000 x	3.087100 =	3.087100
003	4.500000 x	20.290479 =	91.307156
002	4.500000 x	17.205541 =	77.424935
222.3	.004000 x	.000000 =	.000000

T.E =

5441.2 5441.2

205	.065000 x	480.000000 =	31.200000
223.3	.004000 x	1,550.000000 =	6.200000
002	4.500000 x	17.205541 =	77.424935
1476	1.000000 x	3.087100 =	3.087100
003	4.500000 x	20.290479 =	91.307156

T.E = 209.219190

5441.3 5441.3

205	.065000 x	480.000000 =	31.200000
1476	1.000000 x	3.087100 =	3.087100
243.1	.550000 x	2.700000 =	1.485000
003	4.500000 x	20.290479 =	91.307156
002	4.500000 x	17.205541 =	77.424935

T.E = 204.504190

5442.1 5442.1

205	.080000 x	480.000000 =	38.400000
222.3	.004000 x	.000000 =	.000000
003	5.000000 x	20.290479 =	101.452395
1476	1.000000 x	3.087100 =	3.087100
002	5.000000 x	17.205541 =	86.027705

T.E =

5442.2 5442.2

205	.080000 x	480.000000 =	38.400000
1476	1.000000 x	3.087100 =	3.087100
003	5.000000 x	20.290479 =	101.452395
002	5.000000 x	17.205541 =	86.027705
223.3	.004000 x	1,550.000000 =	6.200000

T.E = 235.167200

5442.3 5442.3

205	.080000 x	480.000000 =	38.400000
002	5.000000 x	17.205541 =	86.027705
1476	1.000000 x	3.087100 =	3.087100
003	5.000000 x	20.290479 =	101.452395
243.1	.055000 x	2.700000 =	.148500

T.E = 229.115700

5443.1 5443.1

205	.065000 x	480.000000 =	31.200000
003	4.000000 x	20.290479 =	81.161916
1476	1.000000 x	3.087100 =	3.087100
002	4.000000 x	17.205541 =	68.822164
222.3	.004000 x	.000000 =	.000000

T.E =

5443.2 5443.2

205	.065000 x	480.000000 =	31.200000
1476	1.000000 x	3.087100 =	3.087100
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164
223.3	.004000 x	1,550.000000 =	6.200000

T.E = 190.471180

5443.3 5443.3

205	.065000 x	480.000000 =	31.200000
243.1	.550000 x	2.700000 =	1.485000
002	4.000000 x	17.205541 =	68.822164
1476	1.000000 x	3.087100 =	3.087100
003	4.000000 x	20.290479 =	81.161916

T.E = 185.756180

5446.1 5446.1

203.2	.025000 x	370.000000 =	9.250000
205	.025000 x	480.000000 =	12.000000
222.2	.010000 x	.000000 =	.000000
1476	1.000000 x	3.087100 =	3.087100
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164

T.E =

5446.2 5446.2

203.2	.025000 x	370.000000 =	9.250000
205	.025000 x	480.000000 =	12.000000
1476	1.000000 x	3.087100 =	3.087100
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164
223.2	.010000 x	1,700.000000 =	17.000000

T.E = 191.321180

5447.1 5447.1

203.2	.025000 x	370.000000 =	9.250000
1476	1.000000 x	3.087100 =	3.087100
003	4.500000 x	20.290479 =	91.307156
002	4.500000 x	17.205541 =	77.424935
205	.040000 x	480.000000 =	19.200000
222.2	.010000 x	.000000 =	.000000

T.E =

5447.2 5447.2

203.2	.025000 x	370.000000 =	9.250000
002	4.500000 x	17.205541 =	77.424935
1476	1.000000 x	3.087100 =	3.087100
003	4.500000 x	20.290479 =	91.307156
223.2	.010000 x	1,700.000000 =	17.000000
205	.040000 x	480.000000 =	19.200000

T.E = 217.269190

5448.1 5448.1

203.2	.025000 x	370.000000 =	9.250000
1476	1.000000 x	3.087100 =	3.087100
003	3.500000 x	20.290479 =	71.016677
002	3.500000 x	17.205541 =	60.219394
205	.025000 x	480.000000 =	12.000000
222.2	.010000 x	.000000 =	.000000

T.E =

5448.2 5448.2

203.2	.025000 x	370.000000 =	9.250000
205	.025000 x	480.000000 =	12.000000
1476	1.000000 x	3.087100 =	3.087100
003	3.500000 x	20.290479 =	71.016677
002	3.500000 x	17.205541 =	60.219394
223.2	.010000 x	1,700.000000 =	17.000000

T.E =

172.573170

5449 5449

205	.045000 x	480.000000 =	21.600000
002	3.000000 x	17.205541 =	51.616623
1476	1.000000 x	3.087100 =	3.087100
003	3.000000 x	20.290479 =	60.871437
243.5	.850000 x	5.900000 =	5.015000

T.E =

142.190160

5451.1 5451.1

205	.090000 x	480.000000 =	43.200000
003	5.000000 x	20.290479 =	101.452395
1476	1.000000 x	3.087100 =	3.087100
002	5.000000 x	17.205541 =	86.027705
222.3	.004000 x	.000000 =	.000000

T.E =

5451.2 5451.2

205	.090000 x	480.000000 =	43.200000
1476	1.000000 x	3.087100 =	3.087100
003	5.000000 x	20.290479 =	101.452395
002	5.000000 x	17.205541 =	86.027705
223.3	.004000 x	1,550.000000 =	6.200000

T.E =

239.967200

5451.3 5451.3

205	.090000 x	480.000000 =	43.200000
243.1	.550000 x	2.700000 =	1.485000
002	5.000000 x	17.205541 =	86.027705
1476	1.000000 x	3.087100 =	3.087100
003	5.000000 x	20.290479 =	101.452395

T.E = 235.252200

5456 5456

205	.055000 x	480.000000 =	26.400000
1478	1.000000 x	3.552100 =	3.552100
002	4.000000 x	17.205541 =	68.822164
003	4.000000 x	20.290479 =	81.161916

T.E = 179.936180

5457 5457

205	.085000 x	480.000000 =	40.800000
003	7.000000 x	20.290479 =	142.033353
1476	1.500000 x	3.087100 =	4.630650
002	7.000000 x	17.205541 =	120.438787
261	2.200000 x	.611900 =	1.346180

T.E = 309.248970

5461.1 5461.1

205	.065000 x	480.000000 =	31.200000
222.2	.010000 x	.000000 =	.000000
1479	1.000000 x	38.118689 =	38.118689
003	5.500000 x	20.290479 =	111.597635
002	5.500000 x	17.205541 =	94.630476

T.E =

5461.2 5461.2

205	.065000 x	480.000000 =	31.200000
1479	1.000000 x	38.118689 =	38.118689
003	5.500000 x	20.290479 =	111.597635
002	5.500000 x	17.205541 =	94.630476
223.2	.010000 x	1,700.000000 =	17.000000

T.E = 292.546799

5462.1 5462.1

205	.065000 x	480.000000 =	31.200000
1480	1.000000 x	36.741317 =	36.741317
222.2	.010000 x	.000000 =	.000000
003	5.500000 x	20.290479 =	111.597635
002	5.500000 x	17.205541 =	94.630476

T.E =

5462.2 5462.2

205	.065000 x	480.000000 =	31.200000
003	5.500000 x	20.290479 =	111.597635
002	5.500000 x	17.205541 =	94.630476
1480	1.000000 x	36.741317 =	36.741317
223.2	.010000 x	1,700.000000 =	17.000000

T.E = 291.169427

5463.1 5463.1

205	.055000 x	480.000000 =	26.400000
1479	.500000 x	38.118689 =	19.059345
003	6.000000 x	20.290479 =	121.742874
002	6.000000 x	17.205541 =	103.233246
222.2	.010000 x	.000000 =	.000000

T.E =

5463.2 5463.2

205	.055000 x	480.000000 =	26.400000
223.2	.010000 x	1,700.000000 =	17.000000
002	6.000000 x	17.205541 =	103.233246
1479	.500000 x	38.118689 =	19.059345
003	6.000000 x	20.290479 =	121.742874

T.E = 287.435465

5464.1 5464.1

205	.070000 x	480.000000 =	33.600000
1479	.500000 x	38.118689 =	19.059345
222.2	.010000 x	.000000 =	.000000
003	7.000000 x	20.290479 =	142.033353
002	7.000000 x	17.205541 =	120.438787

T.E =

5464.2 5464.2

205	.070000 x	480.000000 =	33.600000
223.2	.010000 x	1,700.000000 =	17.000000
003	7.000000 x	20.290479 =	142.033353
1479	.500000 x	38.118689 =	19.059345
002	7.000000 x	17.205541 =	120.438787

T.E = 332.131485

5465.1 5465.1

203.2	.045000 x	370.000000 =	16.650000
1476	1.000000 x	3.087100 =	3.087100
003	5.500000 x	20.290479 =	111.597635
002	5.500000 x	17.205541 =	94.630476
222.2	.005000 x	.000000 =	.000000
208	.030000 x	1,435.000000 =	43.050000

T.E =

5465.2 5465.2

203.2	.045000 x	370.000000 =	16.650000
002	5.500000 x	17.205541 =	94.630476
1476	1.000000 x	3.087100 =	3.087100
003	5.500000 x	20.290479 =	111.597635
223.2	.005000 x	1,700.000000 =	8.500000
208	.030000 x	1,435.000000 =	43.050000

T.E =

277.515210

5466.1 5466.1

203.2	.025000 x	370.000000 =	9.250000
1479	.900000 x	38.118689 =	34.306820
003	5.000000 x	20.290479 =	101.452395
002	5.000000 x	17.205541 =	86.027705
222.2	.010000 x	.000000 =	.000000

T.E =

5466.2 5466.2

203.2	.025000 x	370.000000 =	9.250000
1479	.900000 x	38.118689 =	34.306820
003	5.000000 x	20.290479 =	101.452395
002	5.000000 x	17.205541 =	86.027705
223.2	.010000 x	1,700.000000 =	17.000000

T.E =

248.036920

5467.1 5467.1

203.2	.013000 x	370.000000 =	4.810000
203.2	.001040 x	370.000000 =	.384800
222.2	.000960 x	.000000 =	.000000
002	3.500000 x	17.205541 =	60.219394
003	3.500000 x	20.290479 =	71.016677
222.2	.012000 x	.000000 =	.000000

T.E =

5467.2 5467.2

203.2	.013000 x	370.000000 =	4.810000
223.2	.012000 x	1,700.000000 =	20.400000
003	3.500000 x	20.290479 =	71.016677
002	3.500000 x	17.205541 =	60.219394
223.2	.000960 x	1,700.000000 =	1.632000
203.2	.001040 x	370.000000 =	.384800

T.E = 158.462870

5468.1 5468.1

203.2	.025000 x	370.000000 =	9.250000
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164
222.2	.010000 x	.000000 =	.000000
222.2	.000800 x	.000000 =	.000000
203.2	.002000 x	370.000000 =	.740000

T.E =

5468.2 5468.2

203.2	.025000 x	370.000000 =	9.250000
203.2	.002000 x	370.000000 =	.740000
223.2	.010000 x	1,700.000000 =	17.000000
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164
223.2	.000800 x	1,700.000000 =	1.360000

T.E = 178.334080

5469.1 5469.1

203.2	.025000 x	370.000000 =	9.250000
1479	.500000 x	38.118689 =	19.059345
003	4.500000 x	20.290479 =	91.307156
002	4.500000 x	17.205541 =	77.424935
222.2	.010000 x	.000000 =	.000000

T.E =

5469.2 5469.2

203.2	.025000 x	370.000000 =	9.250000
1479	.500000 x	38.118689 =	19.059345
003	4.500000 x	20.290479 =	91.307156
002	4.500000 x	17.205541 =	77.424935
223.2	.010000 x	1,700.000000 =	17.000000

T.E = 214.041435

5471	5471			
203.2		.035000 x	370.000000 =	12.950000
003		3.500000 x	20.290479 =	71.016677
002		3.500000 x	17.205541 =	60.219394
251		3.000000 x	.927000 =	2.781000

			T.E =	146.967070
5472.1	5472.1			
203.2		.026000 x	370.000000 =	9.620000
251		3.000000 x	.927000 =	2.781000
003		3.500000 x	20.290479 =	71.016677
002		3.500000 x	17.205541 =	60.219394
222.4		.010000 x	.000000 =	.000000

			T.E =	
5472.2	5472.2			
203.2		.026000 x	370.000000 =	9.620000
003		3.500000 x	20.290479 =	71.016677
002		3.500000 x	17.205541 =	60.219394
251		3.000000 x	.927000 =	2.781000
223.4		.010000 x	1,600.000000 =	16.000000

			T.E =	159.637070
5501.1	5501.1			
211		.040000 x	750.000000 =	30.000000
002		2.500000 x	17.205541 =	43.013853
003		5.000000 x	20.290479 =	101.452395
252		.100000 x	2.184000 =	.218400
251		.050000 x	.927000 =	.046350

			T.E =	174.730998
5501.2	5501.2			
212		.040000 x	1,500.000000 =	60.000000
251		.050000 x	.927000 =	.046350
252		.100000 x	2.184000 =	.218400
003		5.000000 x	20.290479 =	101.452395
002		2.500000 x	17.205541 =	43.013853

			T.E =	204.730998
5502	5502			
210		.040000 x	.000000 =	.000000
251		.050000 x	.927000 =	.046350
002		2.000000 x	17.205541 =	34.411082
003		4.000000 x	20.290479 =	81.161916
252		.100000 x	2.184000 =	.218400

			T.E =	

5511.1

5511.1

211	.020000 x	750.000000 =	15.000000
003	3.200000 x	20.290479 =	64.929533
002	1.600000 x	17.205541 =	27.528866
252	.100000 x	2.184000 =	.218400

T.E = 107.676798

5511.2

5511.2

212	.020000 x	1,500.000000 =	30.000000
003	3.200000 x	20.290479 =	64.929533
002	1.600000 x	17.205541 =	27.528866
252	.100000 x	2.184000 =	.218400

T.E = 122.676798

5512

5512

205	.020000 x	480.000000 =	9.600000
252	.100000 x	2.184000 =	.218400
002	1.500000 x	17.205541 =	25.808312
003	3.000000 x	20.290479 =	60.871437

T.E = 96.498149

5513.1

5513.1

211	.020000 x	750.000000 =	15.000000
252	.100000 x	2.184000 =	.218400
003	4.000000 x	20.290479 =	81.161916
002	2.000000 x	17.205541 =	34.411082

T.E = 130.791398

5513.2

5513.2

212	.020000 x	1,500.000000 =	30.000000
252	.100000 x	2.184000 =	.218400
003	4.000000 x	20.290479 =	81.161916
002	2.000000 x	17.205541 =	34.411082

T.E = 145.791398

5514

5514

205	.020000 x	480.000000 =	9.600000
003	3.800000 x	20.290479 =	77.103820
002	1.800000 x	17.205541 =	30.969974
252	.100000 x	2.184000 =	.218400

T.E = 117.892194

5521	5521				
205		.030000 x	480.000000 =	14.400000	
252		.150000 x	2.184000 =	.327600	
002		.800000 x	17.205541 =	13.764433	
003		2.000000 x	20.290479 =	40.580958	

			T.E =	69.072991	
5531.1	5531.1				
211		.010000 x	750.000000 =	7.500000	
252		.020000 x	2.184000 =	.043680	
003		2.200000 x	20.290479 =	44.639054	
002		.700000 x	17.205541 =	12.043879	

			T.E =	64.226613	
5531.2	5531.2				
212		.010000 x	1,500.000000 =	15.000000	
252		.020000 x	2.184000 =	.043680	
003		2.200000 x	20.290479 =	44.639054	
002		.700000 x	17.205541 =	12.043879	

			T.E =	71.726613	
5531.3	5531.3				
205		.010000 x	480.000000 =	4.800000	
003		2.200000 x	20.290479 =	44.639054	
002		.700000 x	17.205541 =	12.043879	
252		.020000 x	2.184000 =	.043680	

			T.E =	61.526613	
5532.1	5532.1				
211		.010000 x	750.000000 =	7.500000	
003		3.000000 x	20.290479 =	60.871437	
002		1.000000 x	17.205541 =	17.205541	
252		.020000 x	2.184000 =	.043680	

			T.E =	85.620658	
5532.2	5532.2				
212		.010000 x	1,500.000000 =	15.000000	
252		.020000 x	2.184000 =	.043680	
002		1.000000 x	17.205541 =	17.205541	
003		3.000000 x	20.290479 =	60.871437	

			T.E =	93.120658	

5532.3 5532.3

205	.010000 x	480.000000 =	4.800000
252	.020000 x	2.184000 =	.043680
003	3.000000 x	20.290479 =	60.871437
002	1.000000 x	17.205541 =	17.205541

T.E = 82.920658

5533 5533

537	1.050000 x	1.700000 =	1.785000
003	.350000 x	20.290479 =	7.101668

T.E = 8.886668

5601 5601

203.2	.028000 x	370.000000 =	10.360000
251	4.000000 x	.927000 =	3.708000
003	2.500000 x	20.290479 =	50.726198
002	2.500000 x	17.205541 =	43.013853

T.E = 107.808050

5602 5602

203.2	.018000 x	370.000000 =	6.660000
002	2.300000 x	17.205541 =	39.572744
003	2.300000 x	20.290479 =	46.668102
251	3.000000 x	.927000 =	2.781000

T.E = 95.681846

5603 5603

203.2	.013000 x	370.000000 =	4.810000
003	2.000000 x	20.290479 =	40.580958
002	2.000000 x	17.205541 =	34.411082
251	2.500000 x	.927000 =	2.317500

T.E = 82.119540

5604 5604

243.5	1.100000 x	5.900000 =	6.490000
003	2.200000 x	20.290479 =	44.639054
002	2.200000 x	17.205541 =	37.852190
243.5	.165000 x	5.900000 =	.973500

T.E = 89.954744

5605	5605			
243.3		1.100000 x	4.500000 =	4.950000
243.3		.187000 x	4.500000 =	.841500
002		2.000000 x	17.205541 =	34.411082
003		2.000000 x	20.290479 =	40.580958

			T.E =	80.783540
5606	5606			
243.2		1.100000 x	3.800000 =	4.180000
003		1.800000 x	20.290479 =	36.522862
243.2		.220000 x	3.800000 =	.836000
002		1.800000 x	17.205541 =	30.969974

			T.E =	72.508836
5607	5607			
205		.012000 x	480.000000 =	5.760000
003		2.500000 x	20.290479 =	50.726198
002		2.500000 x	17.205541 =	43.013853
242		2.200000 x	1.500000 =	3.300000
205		.002400 x	480.000000 =	1.152000
242		.440000 x	1.500000 =	.660000

			T.E =	104.612050
5608.1	5608.1			
205		.012000 x	480.000000 =	5.760000
205		.002400 x	480.000000 =	1.152000
003		3.500000 x	20.290479 =	71.016677
002		3.500000 x	17.205541 =	60.219394
222.1		.006000 x	.000000 =	.000000
222.1		.001200 x	.000000 =	.000000

			T.E =	
5608.2	5608.2			
205		.012000 x	480.000000 =	5.760000
205		.002400 x	480.000000 =	1.152000
003		3.500000 x	20.290479 =	71.016677
002		3.500000 x	17.205541 =	60.219394
223.1		.006000 x	2,100.000000 =	12.600000
223.1		.001200 x	2,100.000000 =	2.520000

			T.E =	153.268070

5611 5611

205	.060000 x	480.000000 =	28.800000
003	7.000000 x	20.290479 =	142.033353
251	5.000000 x	.927000 =	4.635000
002	7.000000 x	17.205541 =	120.438787

T.E = 295.907140

5612.1 5612.1

205	.060000 x	480.000000 =	28.800000
003	7.000000 x	20.290479 =	142.033353
002	7.000000 x	17.205541 =	120.438787
251	5.000000 x	.927000 =	4.635000
222.1	.006000 x	.000000 =	.000000

T.E =

5612.2 5612.2

205	.060000 x	480.000000 =	28.800000
003	7.000000 x	20.290479 =	142.033353
002	7.000000 x	17.205541 =	120.438787
251	5.000000 x	.927000 =	4.635000
223.1	.006000 x	2,100.000000 =	12.600000

T.E = 308.507140

5613.1 5613.1

205	.015000 x	480.000000 =	7.200000
205	.001500 x	480.000000 =	.720000
003	1.500000 x	20.290479 =	30.435719
002	1.500000 x	17.205541 =	25.808312
222.2	.003000 x	.000000 =	.000000

T.E =

5613.2 5613.2

205	.015000 x	480.000000 =	7.200000
205	.001500 x	480.000000 =	.720000
002	1.500000 x	17.205541 =	25.808312
003	1.500000 x	20.290479 =	30.435719
223.2	.003000 x	1,700.000000 =	5.100000

T.E = 69.264030

5614.1 5614.1

205	.010000 x	480.000000 =	4.800000
222.2	.002000 x	.000000 =	.000000
003	1.200000 x	20.290479 =	24.348575
002	1.200000 x	17.205541 =	20.646649
205	.001500 x	480.000000 =	.720000

T.E =

5614.2 5614.2

205	.010000 x	480.000000 =	4.800000
003	1.200000 x	20.290479 =	24.348575
002	1.200000 x	17.205541 =	20.646649
223.2	.002000 x	1,700.000000 =	3.400000
205	.001500 x	480.000000 =	.720000

T.E = 53.915224

5615.1 5615.1

205	.008000 x	480.000000 =	3.840000
222.2	.000900 x	.000000 =	.000000
002	1.000000 x	17.205541 =	17.205541
003	1.000000 x	20.290479 =	20.290479
205	.001440 x	480.000000 =	.691200

T.E =

5615.2 5615.2

205	.008000 x	480.000000 =	3.840000
003	1.000000 x	20.290479 =	20.290479
205	.001440 x	480.000000 =	.691200
002	1.000000 x	17.205541 =	17.205541
223.2	.000900 x	1,700.000000 =	1.530000

T.E = 43.557220

5616 5616

205	.003000 x	480.000000 =	1.440000
003	1.000000 x	20.290479 =	20.290479
002	1.000000 x	17.205541 =	17.205541
205	.007500 x	480.000000 =	3.600000

T.E = 42.536020

5617 5617

225	1.100000 x	4.000000 =	4.400000
003	1.000000 x	20.290479 =	20.290479
002	1.000000 x	17.205541 =	17.205541
521	.250000 x	2.461700 =	.615425

T.E = 42.511445

5619 5619

205	.001400 x	480.000000 =	.672000
003	.200000 x	20.290479 =	4.058096

T.E = 4.730096

5620	5620			
203.2		.012000 x	370.000000 =	4.440000
251		.020000 x	.927000 =	.018540
003		.300000 x	20.290479 =	6.087144
002		.300000 x	17.205541 =	5.161662
220		4.200000 x	.000000 =	.000000

T.E =

5621	5621			
210		1.100000 x	.000000 =	.000000
251		16.000000 x	.927000 =	14.832000
003		30.000000 x	20.290479 =	608.714370
002		30.000000 x	17.205541 =	516.166230

T.E =

5622	5622			
211		1.100000 x	750.000000 =	825.000000
003		30.000000 x	20.290479 =	608.714370
002		30.000000 x	17.205541 =	516.166230
251		16.000000 x	.927000 =	14.832000

T.E = 1,964.712600

5626	5626			
205		.030000 x	480.000000 =	14.400000
003		1.500000 x	20.290479 =	30.435719
002		1.500000 x	17.205541 =	25.808312
251		1.000000 x	.927000 =	.927000

T.E = 71.571030

6101	6101			
267		1.050000 x	.931000 =	.977550
003		.050000 x	20.290479 =	1.014524

T.E = 1.992074

6102	6102			
252		.050000 x	2.184000 =	.109200
267		1.030000 x	.931000 =	.958930
003		.060000 x	20.290479 =	1.217429

T.E = 2.285559

6103	6103			
268		1.050000 x	1.041000 =	1.093050
003		.050000 x	20.290479 =	1.014524

T.E = 2.107574

6104	6104			
252		.050000 x	2.184000 =	.109200
268		1.030000 x	1.041000 =	1.072230
003		.060000 x	20.290479 =	1.217429

			T.E =	2.398859
6111	6111			
266		1.100000 x	.622500 =	.684750
003		.150000 x	20.290479 =	3.043572

			T.E =	3.728322
6116	6116			
280		1.050000 x	1.144500 =	1.201725
003		.100000 x	20.290479 =	2.029048

			T.E =	3.230773
6117	6117			
281		1.050000 x	6.615200 =	6.945960
003		.150000 x	20.290479 =	3.043572

			T.E =	9.989532
6118	6118			
266		1.150000 x	.622500 =	.715875
003		.200000 x	20.290479 =	4.058096
002		.200000 x	17.205541 =	3.441108

			T.E =	8.215079
6119	6119			
293		1.100000 x	.000000 =	.000000
003		.150000 x	20.290479 =	3.043572

			T.E =	
6120	6120			
289		1.050000 x	.972500 =	1.021125
003		.100000 x	20.290479 =	2.029048

			T.E =	3.050173
6121	6121			
266		1.100000 x	.622500 =	.684750
002		.200000 x	17.205541 =	3.441108
003		.200000 x	20.290479 =	4.058096

			T.E =	8.183954

6122	6122			
265		1.050000 x	.857700 =	.900585
003		.200000 x	20.290479 =	4.058096

			T.E =	4.958681
6123	6123			
265		.900000 x	.857700 =	.771930
002		.150000 x	17.205541 =	2.580831
003		.150000 x	20.290479 =	3.043572
266		.100000 x	.622500 =	.062250
266		.010000 x	.622500 =	.006225
265		.090000 x	.857700 =	.077193

			T.E =	6.542001
6126	6126			
265		1.250000 x	.857700 =	1.072125
003		.200000 x	20.290479 =	4.058096
003		.200000 x	20.290479 =	4.058096

			T.E =	9.188317
6127	6127			
290		4.800000 x	3.670000 =	17.616000
002		.800000 x	17.205541 =	13.764433
003		.800000 x	20.290479 =	16.232383

			T.E =	47.612816
6128	6128			
290		1.200000 x	3.670000 =	4.404000
002		.200000 x	17.205541 =	3.441108
003		.200000 x	20.290479 =	4.058096

			T.E =	11.903204
6201	6201			
264		1.400000 x	1.097900 =	1.537060
003		.250000 x	20.290479 =	5.072620
002		.250000 x	17.205541 =	4.301385

			T.E =	10.911065
6202	6202			
264		1.300000 x	1.097900 =	1.427270
002		.200000 x	17.205541 =	3.441108
003		.200000 x	20.290479 =	4.058096

			T.E =	8.926474

6203	6203			
282		1.200000 x	.961000 =	1.153200
002		.350000 x	17.205541 =	6.021939
003		.350000 x	20.290479 =	7.101668

			T.E =	14.276807
6204	6204			
282		1.300000 x	.961000 =	1.249300
002		.400000 x	17.205541 =	6.882216
003		.400000 x	20.290479 =	8.116192

			T.E =	16.247708
6205	6205			
277		1.250000 x	1.007600 =	1.259500
003		.500000 x	20.290479 =	10.145240
002		.500000 x	17.205541 =	8.602771

			T.E =	20.007510
6221	6221			
265		1.150000 x	.857700 =	.986355
002		.200000 x	17.205541 =	3.441108
003		.200000 x	20.290479 =	4.058096

			T.E =	8.485559
6222	6222			
265		1.200000 x	.857700 =	1.029240
002		.350000 x	17.205541 =	6.021939
003		.350000 x	20.290479 =	7.101668

			T.E =	14.152847
6223	6223			
265		1.250000 x	.857700 =	1.072125
002		.500000 x	17.205541 =	8.602771
003		.500000 x	20.290479 =	10.145240

			T.E =	19.820135
6224	6224			
271		.720000 x	.971000 =	.699120
003		.200000 x	20.290479 =	4.058096
002		.200000 x	17.205541 =	3.441108
282		.480000 x	.961000 =	.461280

			T.E =	8.659604

6225	6225			
271		.720000 x	.971000 =	.699120
003		.250000 x	20.290479 =	5.072620
282		.480000 x	.961000 =	.461280
002		.250000 x	17.205541 =	4.301385

			T.E =	10.534405
6226	6226			
265		1.200000 x	.857700 =	1.029240
003		.700000 x	20.290479 =	14.203335
002		.700000 x	17.205541 =	12.043879

			T.E =	27.276454
6227	6227			
265		1.250000 x	.857700 =	1.072125
003		.850000 x	20.290479 =	17.246907
002		.850000 x	17.205541 =	14.624710

			T.E =	32.943742
6228	6228			
282		1.250000 x	.961000 =	1.201250
002		.400000 x	17.205541 =	6.882216
003		.400000 x	20.290479 =	8.116192

			T.E =	16.199658
6229	6229			
282		1.250000 x	.961000 =	1.201250
003		.450000 x	20.290479 =	9.130716
002		.450000 x	17.205541 =	7.742493

			T.E =	18.074459
6230	6230			
277		1.100000 x	1.007600 =	1.108360
002		.500000 x	17.205541 =	8.602771
003		.500000 x	20.290479 =	10.145240

			T.E =	19.856370
6231	6231			
265		1.150000 x	.857700 =	.986355
002		.250000 x	17.205541 =	4.301385
003		.250000 x	20.290479 =	5.072620

			T.E =	10.360360

6232 6232

265	1.150000 x	.857700 =	.986355
003	.400000 x	20.290479 =	8.116192
002	.400000 x	17.205541 =	6.882216

T.E = 15.984763

6236 6236

253	.500000 x	2.758000 =	1.379000
266	2.000000 x	.622500 =	1.245000
386	.350000 x	28.630000 =	10.020500
390	2.100000 x	1.500000 =	3.150000
003	1.800000 x	20.290479 =	36.522862
002	1.800000 x	17.205541 =	30.969974
565.3	.350000 x	3.800000 =	1.330000
392	.350000 x	27.420000 =	9.597000
388	.350000 x	48.870000 =	17.104500
276	5.850000 x	.765500 =	4.478175
272	1.500000 x	.894300 =	1.341450

T.E = 117.138461

6237 6237

253	.850000 x	2.758000 =	2.344300
003	4.000000 x	20.290479 =	81.161916
002	4.000000 x	17.205541 =	68.822164
565.5	.350000 x	5.650000 =	1.977500
392	.350000 x	27.420000 =	9.597000
388	.350000 x	48.870000 =	17.104500
386	.350000 x	28.630000 =	10.020500
272	5.000000 x	.894300 =	4.471500
266	2.100000 x	.622500 =	1.307250
260	9.500000 x	.559100 =	5.311450

T.E = 202.118080

6238 6238

253	.400000 x	2.758000 =	1.103200
265	6.000000 x	.857700 =	5.146200
266	13.000000 x	.622500 =	8.092500
003	5.000000 x	20.290479 =	101.452395
002	5.000000 x	17.205541 =	86.027705

T.E = 201.822000

6239 6239

277	1.100000 x	1.007600 =	1.108360
002	.300000 x	17.205541 =	5.161662
003	.300000 x	20.290479 =	6.087144

T.E = 12.357166

6301 6301

266	1.250000 x	.622500 =	.778125
002	.400000 x	17.205541 =	6.882216
003	.400000 x	20.290479 =	8.116192

T.E = 15.776533

6302 6302

266	9.000000 x	.622500 =	5.602500
002	3.500000 x	17.205541 =	60.219394
003	3.500000 x	20.290479 =	71.016677

T.E = 136.838570

6401 6401

265	1.150000 x	.857700 =	.986355
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108

T.E = 8.485559

6402 6402

265	1.200000 x	.857700 =	1.029240
002	.300000 x	17.205541 =	5.161662
003	.300000 x	20.290479 =	6.087144

T.E = 12.278046

6403 6403

265	1.250000 x	.857700 =	1.072125
002	.350000 x	17.205541 =	6.021939
003	.350000 x	20.290479 =	7.101668

T.E = 14.195732

6406 6406

265	1.200000 x	.857700 =	1.029240
002	.600000 x	17.205541 =	10.323325
003	.600000 x	20.290479 =	12.174287

T.E = 23.526852

6407 6407

265	1.250000 x	.857700 =	1.072125
003	.700000 x	20.290479 =	14.203335
002	.700000 x	17.205541 =	12.043879

T.E = 27.319339

6411	6411				
565.3		1.650000 x	3.800000 =	6.270000	
002		.350000 x	17.205541 =	6.021939	
003		.350000 x	20.290479 =	7.101668	

			T.E =	19.393607	
6412	6412				
565.5		1.550000 x	5.650000 =	8.757500	
002		.450000 x	17.205541 =	7.742493	
003		.450000 x	20.290479 =	9.130716	

			T.E =	25.630709	
6413	6413				
565.6		1.450000 x	7.800000 =	11.310000	
002		.550000 x	17.205541 =	9.463048	
003		.550000 x	20.290479 =	11.159763	

			T.E =	31.932811	
6416	6416				
566.3		1.600000 x	5.050000 =	8.080000	
003		.350000 x	20.290479 =	7.101668	
002		.350000 x	17.205541 =	6.021939	

			T.E =	21.203607	
6417	6417				
566.5		1.500000 x	7.750000 =	11.625000	
002		.450000 x	17.205541 =	7.742493	
003		.450000 x	20.290479 =	9.130716	

			T.E =	28.498209	
6418	6418				
566.6		1.400000 x	10.300000 =	14.420000	
003		.550000 x	20.290479 =	11.159763	
002		.550000 x	17.205541 =	9.463048	

			T.E =	35.042811	
6421	6421				
565.3		1.050000 x	3.800000 =	3.990000	
003		.400000 x	20.290479 =	8.116192	

			T.E =	12.106192	

6422	6422				
565.5		1.050000 x	5.650000 =	5.932500	
003		.500000 x	20.290479 =	10.145240	

			T.E =	16.077740	
6423	6423				
565.6		1.050000 x	7.800000 =	8.190000	
003		.600000 x	20.290479 =	12.174287	

			T.E =	20.364287	
6426	6426				
566.3		1.050000 x	5.050000 =	5.302500	
003		.400000 x	20.290479 =	8.116192	

			T.E =	13.418692	
6427	6427				
566.5		1.050000 x	7.750000 =	8.137500	
003		.500000 x	20.290479 =	10.145240	

			T.E =	18.282740	
6428	6428				
566.6		1.050000 x	10.300000 =	10.815000	
003		.600000 x	20.290479 =	12.174287	

			T.E =	22.989287	
6431	6431				
278		1.100000 x	4.120200 =	4.532220	
003		.150000 x	20.290479 =	3.043572	

			T.E =	7.575792	
6432	6432				
251		.100000 x	.927000 =	.092700	
003		.250000 x	20.290479 =	5.072620	
279		1.080000 x	4.257500 =	4.598100	
002		.250000 x	17.205541 =	4.301385	

			T.E =	14.064805	
6441	6441				
266		1.100000 x	.622500 =	.684750	
002		.100000 x	17.205541 =	1.720554	
003		.100000 x	20.290479 =	2.029048	

			T.E =	4.434352	

6446.1	6446.1			
284		1.100000 x	.000000 =	.000000
003		.040000 x	20.290479 =	.811619

			T.E =	
6446.2	6446.2			
285		1.100000 x	.086000 =	.094600
003		.040000 x	20.290479 =	.811619

			T.E =	.906219
6447	6447			
251		.050000 x	.927000 =	.046350
003		.100000 x	20.290479 =	2.029048
002		.100000 x	17.205541 =	1.720554
286		1.050000 x	1.898100 =	1.993005

			T.E =	5.788957
6448	6448			
251		.050000 x	.927000 =	.046350
003		.100000 x	20.290479 =	2.029048
002		.100000 x	17.205541 =	1.720554
288		1.050000 x	2.060000 =	2.163000

			T.E =	5.958952
6501	6501			
282		3.000000 x	.961000 =	2.883000
295		11.000000 x	6.490000 =	71.390000
296		1.000000 x	12.470000 =	12.470000
003		4.000000 x	20.290479 =	81.161916
002		4.000000 x	17.205541 =	68.822164

			T.E =	236.727080
6502	6502			
002		1.500000 x	17.205541 =	25.808312
003		1.500000 x	20.290479 =	30.435719
6501		1.000000 x	236.727080 =	236.727080

			T.E =	292.971110
6503	6503			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		.950000 x	236.727080 =	224.890726

			T.E =	273.635552

6504	6504			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		.910000 x	236.727080 =	215.421643

			T.E =	260.416867
6505	6505			
002		1.000000 x	17.205541 =	17.205541
6501		.870000 x	236.727080 =	205.952560
003		1.000000 x	20.290479 =	20.290479

			T.E =	243.448580
6506	6506			
002		1.000000 x	17.205541 =	17.205541
003		1.000000 x	20.290479 =	20.290479
6501		.810000 x	236.727080 =	191.748935

			T.E =	229.244955
6507	6507			
002		.900000 x	17.205541 =	15.484987
003		.900000 x	20.290479 =	18.261431
6501		.920000 x	236.727080 =	217.788914

			T.E =	251.535332
6508	6508			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		1.030000 x	236.727080 =	243.828892

			T.E =	292.573718
6509	6509			
002		1.000000 x	17.205541 =	17.205541
6501		1.010000 x	236.727080 =	239.094351
003		1.000000 x	20.290479 =	20.290479

			T.E =	276.590371
6510	6510			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		1.080000 x	236.727080 =	255.665246

			T.E =	300.660470

6511	6511			
002		1.500000 x	17.205541 =	25.808312
003		1.500000 x	20.290479 =	30.435719
6501		.920000 x	236.727080 =	217.788914

			T.E =	274.032944
6512	6512			
002		1.400000 x	17.205541 =	24.087757
003		1.400000 x	20.290479 =	28.406671
6501		.820000 x	236.727080 =	194.116206

			T.E =	246.610634
6513	6513			
002		1.300000 x	17.205541 =	22.367203
6501		.780000 x	236.727080 =	184.647122
003		1.300000 x	20.290479 =	26.377623

			T.E =	233.391948
6514	6514			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		.760000 x	236.727080 =	179.912581

			T.E =	224.907805
6515	6515			
002		1.000000 x	17.205541 =	17.205541
003		1.000000 x	20.290479 =	20.290479
6501		.800000 x	236.727080 =	189.381664

			T.E =	226.877684
6516	6516			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		1.220000 x	236.727080 =	288.807038

			T.E =	337.551864
6517	6517			
002		1.200000 x	17.205541 =	20.646649
6501		1.120000 x	236.727080 =	265.134330
003		1.200000 x	20.290479 =	24.348575

			T.E =	310.129554

6518	6518			
002		1.100000 x	17.205541 =	18.926095
003		1.100000 x	20.290479 =	22.319527
6501		.670000 x	236.727080 =	158.607144

			T.E =	199.852766
6519	6519			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		1.280000 x	236.727080 =	303.010662

			T.E =	351.755488
6520	6520			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		1.120000 x	236.727080 =	265.134330

			T.E =	310.129554
6521	6521			
002		1.300000 x	17.205541 =	22.367203
6501		1.210000 x	236.727080 =	286.439767
003		1.300000 x	20.290479 =	26.377623

			T.E =	335.184593
6522	6522			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		1.190000 x	236.727080 =	281.705225

			T.E =	326.700449
6523	6523			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		1.280000 x	236.727080 =	303.010662

			T.E =	348.005886
6524	6524			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		.800000 x	236.727080 =	189.381664

			T.E =	234.376888

6525	6525			
002		1.200000 x	17.205541 =	20.646649
6501		1.040000 x	236.727080 =	246.196163
003		1.200000 x	20.290479 =	24.348575

			T.E =	291.191387
6526	6526			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		.900000 x	236.727080 =	213.054372

			T.E =	261.799198
6527	6527			
002		1.300000 x	17.205541 =	22.367203
003		1.300000 x	20.290479 =	26.377623
6501		1.120000 x	236.727080 =	265.134330

			T.E =	313.879156
6528	6528			
002		1.200000 x	17.205541 =	20.646649
003		1.200000 x	20.290479 =	24.348575
6501		.840000 x	236.727080 =	198.850747

			T.E =	243.845971
6529	6529			
002		1.200000 x	17.205541 =	20.646649
6501		1.080000 x	236.727080 =	255.665246
003		1.200000 x	20.290479 =	24.348575

			T.E =	300.660470
6530	6530			
002		1.000000 x	17.205541 =	17.205541
6501		.710000 x	236.727080 =	168.076227
003		1.000000 x	20.290479 =	20.290479

			T.E =	205.572247
6531	6531			
002		.600000 x	17.205541 =	10.323325
003		.600000 x	20.290479 =	12.174287
6501		.480000 x	236.727080 =	113.628998

			T.E =	136.126610

6532	6532			
294		6.000000 x	3.518600 =	21.111600
294		.300000 x	3.518600 =	1.055580
002		2.500000 x	17.205541 =	43.013853
003		2.500000 x	20.290479 =	50.726198
296		1.000000 x	12.470000 =	12.470000

			T.E =	128.377230
6541	6541			
282		.350000 x	.961000 =	.336350
295		1.050000 x	6.490000 =	6.814500
003		.500000 x	20.290479 =	10.145240
002		.500000 x	17.205541 =	8.602771
296		.120000 x	12.470000 =	1.496400

			T.E =	27.395260
6542	6542			
295		1.050000 x	6.490000 =	6.814500
003		.800000 x	20.290479 =	16.232383
002		.800000 x	17.205541 =	13.764433
296		.100000 x	12.470000 =	1.247000

			T.E =	38.058316
6543	6543			
295		.400000 x	6.490000 =	2.596000
003		.200000 x	20.290479 =	4.058096
296		.130000 x	12.470000 =	1.621100

			T.E =	8.275196
7101	7101			
201		.000500 x	290.000000 =	.145000
1445		.010000 x	60.356500 =	.603565
003		.850000 x	20.290479 =	17.246907
002		.500000 x	17.205541 =	8.602771

			T.E =	26.598243
7102	7102			
201		.000500 x	290.000000 =	.145000
1445		.010000 x	60.356500 =	.603565
003		.700000 x	20.290479 =	14.203335
002		.400000 x	17.205541 =	6.882216

			T.E =	21.834117

7103 7103

201	.000500 x	290.000000 =	.145000
002	.300000 x	17.205541 =	5.161662
003	.600000 x	20.290479 =	12.174287
1445	.004000 x	60.356500 =	.241426

T.E = 17.722376

7104 7104

201	.000500 x	290.000000 =	.145000
003	1.000000 x	20.290479 =	20.290479
1445	.008000 x	60.356500 =	.482852
002	.600000 x	17.205541 =	10.323325

T.E = 31.241656

7111 7111

201	.000500 x	290.000000 =	.145000
003	.600000 x	20.290479 =	12.174287
1413	.027000 x	28.004100 =	.756111
001	.300000 x	15.643441 =	4.693032

T.E = 17.768430

7116 7116

201	.000500 x	290.000000 =	.145000
1418	.027000 x	40.356750 =	1.089632
003	.650000 x	20.290479 =	13.188811
001	.350000 x	15.643441 =	5.475204

T.E = 19.898648

7121 7121

201	.000500 x	290.000000 =	.145000
1445	.027000 x	60.356500 =	1.629626
003	.800000 x	20.290479 =	16.232383
001	.300000 x	15.643441 =	4.693032

T.E = 22.700041

7122 7122

201	.000500 x	290.000000 =	.145000
1444	.027000 x	74.507500 =	2.011703
001	.300000 x	15.643441 =	4.693032
003	.800000 x	20.290479 =	16.232383

T.E = 23.082118

7123	7123				
201		.000500 x	290.000000 =		.145000
1462		.015000 x	90.001250 =		1.350019
1446		.006000 x	51.200500 =		.307203
001		.300000 x	15.643441 =		4.693032
1445		.006000 x	60.356500 =		.362139
003		.900000 x	20.290479 =		18.261431

			T.E =		25.118824
7124.1	7124.1				
201		.000500 x	290.000000 =		.145000
001		.300000 x	15.643441 =		4.693032
1445		.012000 x	60.356500 =		.724278
1465		.015000 x	96.528150 =		1.447922
003		.900000 x	20.290479 =		18.261431

			T.E =		25.271664
7124.2	7124.2				
201		.000500 x	290.000000 =		.145000
1466		.015000 x	94.173750 =		1.412606
1445		.012000 x	60.356500 =		.724278
003		.900000 x	20.290479 =		18.261431
001		.300000 x	15.643441 =		4.693032

			T.E =		25.236348
7124.3	7124.3				
201		.000500 x	290.000000 =		.145000
1467		.015000 x	88.680150 =		1.330202
1445		.012000 x	60.356500 =		.724278
001		.300000 x	15.643441 =		4.693032
003		.900000 x	20.290479 =		18.261431

			T.E =		25.153944
7131	7131				
201		.000500 x	290.000000 =		.145000
1413		.021000 x	28.004100 =		.588086
1426		.006000 x	152.456250 =		.914738
001		.300000 x	15.643441 =		4.693032
003		.600000 x	20.290479 =		12.174287

			T.E =		18.515143

7132 7132

201	.000500 x	290.000000 =	.145000
1427	.006000 x	163.304700 =	.979828
1418	.021000 x	40.356750 =	.847492
001	.350000 x	15.643441 =	5.475204
003	.650000 x	20.290479 =	13.188811

T.E = 20.636336

7133 7133

201	.000500 x	290.000000 =	.145000
1463	.015000 x	77.314750 =	1.159721
1427	.006000 x	163.304700 =	.979828
1418	.006000 x	40.356750 =	.242141
003	.600000 x	20.290479 =	12.174287
001	.350000 x	15.643441 =	5.475204

T.E = 20.176182

7134 7134

201	.000500 x	290.000000 =	.145000
001	.350000 x	15.643441 =	5.475204
003	.600000 x	20.290479 =	12.174287
1464	.015000 x	57.753600 =	.866304
1427	.006000 x	163.304700 =	.979828
1418	.006000 x	40.356750 =	.242141

T.E = 19.882764

7136 7136

201	.000500 x	290.000000 =	.145000
001	.250000 x	15.643441 =	3.910860
1418	.017000 x	40.356750 =	.686065
003	.400000 x	20.290479 =	8.116192

T.E = 12.858117

7138 7138

201	.000500 x	290.000000 =	.145000
001	.300000 x	15.643441 =	4.693032
1418	.027000 x	40.356750 =	1.089632
003	.800000 x	20.290479 =	16.232383

T.E = 22.160048

7141 7141

201	.000500 x	290.000000 =	.145000
1445	.027000 x	60.356500 =	1.629626
003	1.000000 x	20.290479 =	20.290479
001	.400000 x	15.643441 =	6.257376

T.E = 28.322481

7146 7146

201	.000500 x	290.000000 =	.145000
1421	.016000 x	.000000 =	.000000
1413	.014000 x	28.004100 =	.392057
001	.350000 x	15.643441 =	5.475204
003	.650000 x	20.290479 =	13.188811

T.E =

7147 7147

201	.000500 x	290.000000 =	.145000
1426	.007000 x	152.456250 =	1.067194
1421	.016000 x	.000000 =	.000000
001	.350000 x	15.643441 =	5.475204
1413	.007000 x	28.004100 =	.196029
003	.650000 x	20.290479 =	13.188811

T.E =

7148 7148

201	.000500 x	290.000000 =	.145000
1413	.014000 x	28.004100 =	.392057
001	.450000 x	15.643441 =	7.039548
1422	.016000 x	.000000 =	.000000
003	.600000 x	20.290479 =	12.174287

T.E =

7149 7149

201	.000500 x	290.000000 =	.145000
1426	.007000 x	152.456250 =	1.067194
1422	.016000 x	.000000 =	.000000
1413	.007000 x	28.004100 =	.196029
003	.600000 x	20.290479 =	12.174287
001	.450000 x	15.643441 =	7.039548

T.E =

7150 7150

201	.000500 x	290.000000 =	.145000
001	.350000 x	15.643441 =	5.475204
1418	.014000 x	40.356750 =	.564995
003	.650000 x	20.290479 =	13.188811
1422	.016000 x	.000000 =	.000000

T.E =

7151 7151

201	.000500 x	290.000000 =	.145000
001	.350000 x	15.643441 =	5.475204
1418	.007000 x	40.356750 =	.282497
1422	.016000 x	.000000 =	.000000
1427	.007000 x	163.304700 =	1.143133
003	.650000 x	20.290479 =	13.188811

T.E =

7152 7152

201	.000500 x	290.000000 =	.145000
1447	.014000 x	57.535900 =	.805503
1448	.016000 x	.000000 =	.000000
003	.700000 x	20.290479 =	14.203335
001	.450000 x	15.643441 =	7.039548

T.E =

7153 7153

201	.000500 x	290.000000 =	.145000
1448	.016000 x	.000000 =	.000000
1447	.007000 x	57.535900 =	.402751
1426	.007000 x	152.456250 =	1.067194
003	.700000 x	20.290479 =	14.203335
001	.450000 x	15.643441 =	7.039548

T.E =

7161 7161

201	.000800 x	290.000000 =	.232000
1445	.022000 x	60.356500 =	1.327843
003	1.600000 x	20.290479 =	32.464766
1453	.020000 x	187.752750 =	3.755055
002	1.600000 x	17.205541 =	27.528866
001	.600000 x	15.643441 =	9.386065

T.E =

74.694595

7162 7162

201	.000800 x	290.000000 =	.232000
1458	.020000 x	.000000 =	.000000
1445	.022000 x	60.356500 =	1.327843
001	.600000 x	15.643441 =	9.386065
003	1.600000 x	20.290479 =	32.464766
002	1.600000 x	17.205541 =	27.528866

T.E =

7163 7163

201	.000800 x	290.000000 =	.232000
1454	.020000 x	210.972750 =	4.219455
003	1.600000 x	20.290479 =	32.464766
002	1.600000 x	17.205541 =	27.528866
1445	.022000 x	60.356500 =	1.327843
001	.600000 x	15.643441 =	9.386065

T.E = 75.158995

7164 7164

201	.000800 x	290.000000 =	.232000
1455	.020000 x	.000000 =	.000000
1445	.022000 x	60.356500 =	1.327843
003	1.600000 x	20.290479 =	32.464766
002	1.600000 x	17.205541 =	27.528866
001	.600000 x	15.643441 =	9.386065

T.E =

7165 7165

201	.000800 x	290.000000 =	.232000
001	.600000 x	15.643441 =	9.386065
002	1.600000 x	17.205541 =	27.528866
1459	.020000 x	210.972750 =	4.219455
1445	.022000 x	60.356500 =	1.327843
003	1.600000 x	20.290479 =	32.464766

T.E = 75.158995

7166 7166

201	.000800 x	290.000000 =	.232000
1453	.017000 x	187.752750 =	3.191797
1445	.022000 x	60.356500 =	1.327843
001	.500000 x	15.643441 =	7.821721
003	1.200000 x	20.290479 =	24.348575
002	1.200000 x	17.205541 =	20.646649

T.E = 57.568584

7167 7167

201	.000800 x	290.000000 =	.232000
001	.500000 x	15.643441 =	7.821721
003	1.200000 x	20.290479 =	24.348575
1458	.017000 x	.000000 =	.000000
1445	.022000 x	60.356500 =	1.327843
002	1.200000 x	17.205541 =	20.646649

T.E =

7168 7168

201	.000800 x	290.000000 =	.232000
1454	.017000 x	210.972750 =	3.586537
1445	.022000 x	60.356500 =	1.327843
003	1.200000 x	20.290479 =	24.348575
002	1.200000 x	17.205541 =	20.646649
001	.500000 x	15.643441 =	7.821721

T.E = 57.963324

7169 7169

201	.000800 x	290.000000 =	.232000
001	.500000 x	15.643441 =	7.821721
002	1.200000 x	17.205541 =	20.646649
1455	.017000 x	.000000 =	.000000
1445	.022000 x	60.356500 =	1.327843
003	1.200000 x	20.290479 =	24.348575

T.E =

7170 7170

201	.000800 x	290.000000 =	.232000
1459	.017000 x	210.972750 =	3.586537
1445	.022000 x	60.356500 =	1.327843
001	.500000 x	15.643441 =	7.821721
002	1.200000 x	17.205541 =	20.646649
003	1.200000 x	20.290479 =	24.348575

T.E = 57.963324

7171 7171

201	.000700 x	290.000000 =	.203000
001	.100000 x	15.643441 =	1.564344

T.E = 1.767344

7176 7176

003	1.500000 x	20.290479 =	30.435719
-----	------------	-------------	-----------

T.E = 30.435719

7177 7177

003	1.100000 x	20.290479 =	22.319527
-----	------------	-------------	-----------

T.E = 22.319527

7178 7178

003	.900000 x	20.290479 =	18.261431
-----	-----------	-------------	-----------

T.E = 18.261431

7179	7179			
003		.500000 x	20.290479 =	10.145240

			T.E =	10.145240
7181	7181			
003		.700000 x	20.290479 =	14.203335

			T.E =	14.203335
7206	7206			
142		26.000000 x	.385000 =	10.010000
1412		.040000 x	26.581800 =	1.063272
003		.600000 x	20.290479 =	12.174287
002		.300000 x	17.205541 =	5.161662

			T.E =	28.409222
7207	7207			
142		26.000000 x	.385000 =	10.010000
1412		.020000 x	26.581800 =	.531636
003		.500000 x	20.290479 =	10.145240
002		.250000 x	17.205541 =	4.301385

			T.E =	24.988261
7208	7208			
142		26.000000 x	.385000 =	10.010000
002		.200000 x	17.205541 =	3.441108
003		.400000 x	20.290479 =	8.116192
1412		.025000 x	26.581800 =	.664545

			T.E =	22.231845
7209	7209			
142		26.000000 x	.385000 =	10.010000
1412		.005000 x	26.581800 =	.132909
002		.150000 x	17.205541 =	2.580831
003		.300000 x	20.290479 =	6.087144

			T.E =	18.810884
7211	7211			
146		15.000000 x	.415000 =	6.225000
1445		.001000 x	60.356500 =	.060357
003		.400000 x	20.290479 =	8.116192
283		.075000 x	1.305700 =	.097928
002		.200000 x	17.205541 =	3.441108

			T.E =	17.940584

7221 7221

203.2	.001500 x	370.000000 =	.555000
254	.020000 x	3.532000 =	.070640
492	.200000 x	.540000 =	.108000
003	.200000 x	20.290479 =	4.058096
002	.150000 x	17.205541 =	2.580831
506	1.150000 x	1.431700 =	1.646455

T.E = 9.019022

7222 7222

254	.050000 x	3.532000 =	.176600
492	.200000 x	.540000 =	.108000
002	.150000 x	17.205541 =	2.580831
003	.250000 x	20.290479 =	5.072620
506	1.200000 x	1.431700 =	1.718040

T.E = 9.656091

7223 7223

254	.050000 x	3.532000 =	.176600
493	.200000 x	.730000 =	.146000
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108
508	1.200000 x	.860000 =	1.032000

T.E = 8.853804

7231 7231

274	1.200000 x	1.441200 =	1.729440
003	.250000 x	20.290479 =	5.072620
002	.250000 x	17.205541 =	4.301385
274	.200000 x	1.441200 =	.288240

T.E = 11.391685

7241 7241

297.2	.051072 x	.000000 =	.000000
495	.500000 x	.000000 =	.000000
002	1.400000 x	17.205541 =	24.087757
003	1.400000 x	20.290479 =	28.406671
001	.200000 x	15.643441 =	3.128688

T.E =

7242 7242

297.2	.057000 x	.000000 =	.000000
001	.200000 x	15.643441 =	3.128688
003	2.800000 x	20.290479 =	56.813341
002	2.800000 x	17.205541 =	48.175515
495	1.000000 x	.000000 =	.000000

T.E =

7243.1 7243.1

179	1.200000 x	.000000 =	.000000
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108
251	1.300000 x	.927000 =	1.205100

T.E =

7243.2 7243.2

180	1.200000 x	.000000 =	.000000
251	1.300000 x	.927000 =	1.205100
002	.200000 x	17.205541 =	3.441108
003	.200000 x	20.290479 =	4.058096

T.E =

7243.3 7243.3

181	1.200000 x	.000000 =	.000000
251	1.300000 x	.927000 =	1.205100
003	.200000 x	20.290479 =	4.058096
002	.200000 x	17.205541 =	3.441108

T.E =

7244 7244

251	1.200000 x	.927000 =	1.112400
273	1.200000 x	1.084300 =	1.301160
003	1.000000 x	20.290479 =	20.290479
002	1.000000 x	17.205541 =	17.205541

T.E =

39.909580

7245 7245

251	.500000 x	.927000 =	.463500
003	.700000 x	20.290479 =	14.203335
002	.700000 x	17.205541 =	12.043879
273	1.200000 x	1.084300 =	1.301160

T.E =

28.011874

7246 7246

265	.500000 x	.857700 =	.428850
003	1.000000 x	20.290479 =	20.290479
002	1.000000 x	17.205541 =	17.205541
298.1	6.700000 x	7.020000 =	47.034000

T.E = 84.958870

7301 7301

096	1.050000 x	.000000 =	.000000
1444	.001500 x	74.507500 =	.111761
1445	.025000 x	60.356500 =	1.508913
003	.900000 x	20.290479 =	18.261431
001	.400000 x	15.643441 =	6.257376

T.E =

7302 7302

097	1.050000 x	.000000 =	.000000
1445	.025000 x	60.356500 =	1.508913
1444	.002000 x	74.507500 =	.149015
003	1.000000 x	20.290479 =	20.290479
001	.500000 x	15.643441 =	7.821721

T.E =

7303 7303

096	1.100000 x	.000000 =	.000000
001	1.000000 x	15.643441 =	15.643441
003	2.000000 x	20.290479 =	40.580958
1445	.025000 x	60.356500 =	1.508913
1444	.001000 x	74.507500 =	.074508

T.E =

7304 7304

096	1.100000 x	.000000 =	.000000
1445	.025000 x	60.356500 =	1.508913
001	.800000 x	15.643441 =	12.514753
1444	.001500 x	74.507500 =	.111761
003	1.600000 x	20.290479 =	32.464766

T.E =

7305 7305

096	.160000 x	.000000 =	.000000
001	.150000 x	15.643441 =	2.346516
1444	.000200 x	74.507500 =	.014902
1445	.004000 x	60.356500 =	.241426
003	.300000 x	20.290479 =	6.087144

T.E =

7311 7311

098	1.150000 x	.000000 =	.000000
1445	.005000 x	60.356500 =	.301783
1417	.033000 x	38.934450 =	1.284837
003	2.200000 x	20.290479 =	44.639054
001	.600000 x	15.643441 =	9.386065

T.E =

7312 7312

099	1.050000 x	.000000 =	.000000
001	.500000 x	15.643441 =	7.821721
003	1.100000 x	20.290479 =	22.319527
1417	.033000 x	38.934450 =	1.284837
1445	.005000 x	60.356500 =	.301783

T.E =

7313 7313

152	1.050000 x	.000000 =	.000000
001	.400000 x	15.643441 =	6.257376
1417	.022000 x	38.934450 =	.856558
1445	.004000 x	60.356500 =	.241426
003	.900000 x	20.290479 =	18.261431

T.E =

7314 7314

154	1.050000 x	.000000 =	.000000
001	.500000 x	15.643441 =	7.821721
1449	.030000 x	51.870700 =	1.556121
003	2.500000 x	20.290479 =	50.726198

T.E =

7315 7315

155	1.050000 x	2.233400 =	2.345070
1449	.004000 x	51.870700 =	.207483
003	.300000 x	20.290479 =	6.087144
001	.100000 x	15.643441 =	1.564344

T.E =

10.204041

7316 7316

161	1.050000 x	6.360000 =	6.678000
1449	.025000 x	51.870700 =	1.296768
1444	.002000 x	74.507500 =	.149015
001	.300000 x	15.643441 =	4.693032
003	.600000 x	20.290479 =	12.174287

T.E =

24.991102

7317	7317			
163		1.050000 x	6.550000 =	6.877500
1449		.025000 x	51.870700 =	1.296768
001		.300000 x	15.643441 =	4.693032
1444		.001500 x	74.507500 =	.111761
003		.800000 x	20.290479 =	16.232383

T.E = 29.211444

7321.1	7321.1			
164		1.030000 x	.000000 =	.000000
1444		.001000 x	74.507500 =	.074508
001		.100000 x	15.643441 =	1.564344
1449		.025000 x	51.870700 =	1.296768
003		1.300000 x	20.290479 =	26.377623

T.E =

7321.2	7321.2			
165		1.030000 x	.000000 =	.000000
1449		.025000 x	51.870700 =	1.296768
1444		.001000 x	74.507500 =	.074508
003		1.300000 x	20.290479 =	26.377623
001		.100000 x	15.643441 =	1.564344

T.E =

7322.1	7322.1			
164		1.030000 x	.000000 =	.000000
003		1.500000 x	20.290479 =	30.435719
1449		.025000 x	51.870700 =	1.296768
1444		.001000 x	74.507500 =	.074508
001		.400000 x	15.643441 =	6.257376

T.E =

7322.2	7322.2			
165		1.030000 x	.000000 =	.000000
1444		.001000 x	74.507500 =	.074508
1449		.025000 x	51.870700 =	1.296768
003		1.500000 x	20.290479 =	30.435719
001		.400000 x	15.643441 =	6.257376

T.E =

7324 7324

166	1.050000 x	.000000 =	.000000
1449	.002000 x	51.870700 =	.103741
1444	.000100 x	74.507500 =	.007451
003	.200000 x	20.290479 =	4.058096
001	.040000 x	15.643441 =	.625738

T.E =

7326.1 7326.1

029	.200000 x	.151500 =	.030300
173	48.000000 x	.256100 =	12.292800
003	3.000000 x	20.290479 =	60.871437
1449	.020000 x	51.870700 =	1.037414
1444	.005000 x	74.507500 =	.372538
001	.500000 x	15.643441 =	7.821721

T.E =

82.426209

7326.2 7326.2

029	.200000 x	.151500 =	.030300
174	48.000000 x	.000000 =	.000000
1449	.020000 x	51.870700 =	1.037414
1444	.005000 x	74.507500 =	.372538
003	3.000000 x	20.290479 =	60.871437
001	.500000 x	15.643441 =	7.821721

T.E =

7327 7327

029	.200000 x	.151500 =	.030300
1449	.020000 x	51.870700 =	1.037414
1444	.007000 x	74.507500 =	.521553
003	4.000000 x	20.290479 =	81.161916
001	.600000 x	15.643441 =	9.386065
175	95.000000 x	.000000 =	.000000

T.E =

7328.1 7328.1

029	.300000 x	.151500 =	.045450
171	108.000000 x	.000000 =	.000000
001	.700000 x	15.643441 =	10.950409
1449	.020000 x	51.870700 =	1.037414
1444	.007000 x	74.507500 =	.521553
003	4.000000 x	20.290479 =	81.161916

T.E =

7328.2 7328.2

029	.300000 x	.151500 =	.045450
1449	.020000 x	51.870700 =	1.037414
1444	.007000 x	74.507500 =	.521553
172	108.000000 x	.000000 =	.000000
003	4.000000 x	20.290479 =	81.161916
001	.700000 x	15.643441 =	10.950409

T.E =

7331 7331

029	1.500000 x	.151500 =	.227250
169	54.000000 x	.000000 =	.000000
003	3.500000 x	20.290479 =	71.016677
1449	.020000 x	51.870700 =	1.037414
1444	.005000 x	74.507500 =	.372538
001	.500000 x	15.643441 =	7.821721

T.E =

7332 7332

029	2.000000 x	.151500 =	.303000
1449	.020000 x	51.870700 =	1.037414
1444	.005000 x	74.507500 =	.372538
003	4.500000 x	20.290479 =	91.307156
001	.800000 x	15.643441 =	12.514753
170	108.000000 x	.000000 =	.000000

T.E =

7333 7333

029	.300000 x	.151500 =	.045450
167	1.050000 x	.000000 =	.000000
003	2.500000 x	20.290479 =	50.726198
002	.500000 x	17.205541 =	8.602771
1449	.020000 x	51.870700 =	1.037414

T.E =

7334 7334

029	.300000 x	.151500 =	.045450
168	1.050000 x	.000000 =	.000000
003	3.000000 x	20.290479 =	60.871437
002	.600000 x	17.205541 =	10.323325
1449	.020000 x	51.870700 =	1.037414

T.E =

7335 7335

001	.450000 x	15.643441 =	7.039548
1444	.007000 x	74.507500 =	.521553
1445	.026000 x	60.356500 =	1.569269
003	1.000000 x	20.290479 =	20.290479

T.E = 29.420849

7336 7336

001	.400000 x	15.643441 =	6.257376
1445	.022000 x	60.356500 =	1.327843
1444	.006000 x	74.507500 =	.447045
003	.900000 x	20.290479 =	18.261431

T.E = 26.293696

7337 7337

001	.350000 x	15.643441 =	5.475204
003	.800000 x	20.290479 =	16.232383
1445	.017000 x	60.356500 =	1.026061
1444	.005000 x	74.507500 =	.372538

T.E = 23.106186

7338 7338

026	.500000 x	.099900 =	.049950
001	.300000 x	15.643441 =	4.693032
1445	.017000 x	60.356500 =	1.026061
003	.700000 x	20.290479 =	14.203335

T.E = 19.972378

7340 7340

289	1.100000 x	.972500 =	1.069750
001	.400000 x	15.643441 =	6.257376
1445	.026000 x	60.356500 =	1.569269
1444	.007000 x	74.507500 =	.521553
003	1.100000 x	20.290479 =	22.319527

T.E = 31.737475

7341 7341

003	.200000 x	20.290479 =	4.058096
1441	.003000 x	27.111000 =	.081333

T.E = 4.139429

7346 7346

003	.200000 x	20.290479 =	4.058096
-----	-----------	-------------	----------

T.E = 4.058096

7347 7347

001	.200000 x	15.643441 =	3.128688
003	.500000 x	20.290479 =	10.145240
1445	.009000 x	60.356500 =	.543209
1444	.002000 x	74.507500 =	.149015

T.E = 13.966151

7351 7351

001	.200000 x	15.643441 =	3.128688
003	.600000 x	20.290479 =	12.174287
1444	.009000 x	74.507500 =	.670568

T.E = 15.973543

7352 7352

001	.200000 x	15.643441 =	3.128688
1444	.012000 x	74.507500 =	.894090
003	.700000 x	20.290479 =	14.203335

T.E = 18.226114

7355 7355

001	.150000 x	15.643441 =	2.346516
003	.600000 x	20.290479 =	12.174287
1444	.008000 x	74.507500 =	.596060

T.E = 15.116864

7356 7356

001	.100000 x	15.643441 =	1.564344
003	.550000 x	20.290479 =	11.159763
1444	.007000 x	74.507500 =	.521553

T.E = 13.245660

7357 7357

001	.050000 x	15.643441 =	.782172
1444	.006000 x	74.507500 =	.447045
003	.500000 x	20.290479 =	10.145240

T.E = 11.374457

7359 7359

021	.100000 x	2.670000 =	.267000
026	20.000000 x	.099900 =	1.998000
003	.900000 x	20.290479 =	18.261431
002	.900000 x	17.205541 =	15.484987
065	.040000 x	11.660000 =	.466400

T.E = 36.477818

7360	7360			
021		.050000 x	2.670000 =	.133500
026		13.000000 x	.099900 =	1.298700
065		.027000 x	11.660000 =	.314820
003		.700000 x	20.290479 =	14.203335
002		.700000 x	17.205541 =	12.043879

T.E = 27.994234

7361	7361			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.099900 =	1.398600
002		1.000000 x	17.205541 =	17.205541
003		1.400000 x	20.290479 =	28.406671
346.1		30.000000 x	.057200 =	1.716000
065		.015000 x	11.660000 =	.174900

T.E = 49.035212

7362.1	7362.1			
021		.050000 x	2.670000 =	.133500
003		1.400000 x	20.290479 =	28.406671
002		1.000000 x	17.205541 =	17.205541
348		8.000000 x	.103600 =	.828800
346.1		22.000000 x	.057200 =	1.258400
065		.015000 x	11.660000 =	.174900
026		14.000000 x	.099900 =	1.398600

T.E = 49.406412

7362.2	7362.2			
021		.050000 x	2.670000 =	.133500
026		14.000000 x	.099900 =	1.398600
346.2		22.000000 x	.103600 =	2.279200
002		1.000000 x	17.205541 =	17.205541
003		1.400000 x	20.290479 =	28.406671
348		8.000000 x	.103600 =	.828800
065		.015000 x	11.660000 =	.174900

T.E = 50.427212

7363	7363			
021		.050000 x	2.670000 =	.133500
003		1.600000 x	20.290479 =	32.464766
002		1.200000 x	17.205541 =	20.646649
026		17.000000 x	.099900 =	1.698300
346.1		35.000000 x	.057200 =	2.002000
065		.020000 x	11.660000 =	.233200

T.E = 57.178416

7364.1 7364.1

021	.050000 x	2.670000 =	.133500
003	1.600000 x	20.290479 =	32.464766
002	1.200000 x	17.205541 =	20.646649
348	11.000000 x	.103600 =	1.139600
346.1	24.000000 x	.057200 =	1.372800
026	17.000000 x	.099900 =	1.698300
065	.020000 x	11.660000 =	.233200

T.E = 57.688816

7364.2 7364.2

021	.050000 x	2.670000 =	.133500
003	1.600000 x	20.290479 =	32.464766
002	1.200000 x	17.205541 =	20.646649
348	11.000000 x	.103600 =	1.139600
346.2	24.000000 x	.103600 =	2.486400
065	.020000 x	11.660000 =	.233200
026	17.000000 x	.099900 =	1.698300

T.E = 58.802416

7366 7366

021	.050000 x	2.670000 =	.133500
026	10.000000 x	.099900 =	.999000
003	3.000000 x	20.290479 =	60.871437
1446	.010000 x	51.200500 =	.512005
002	2.000000 x	17.205541 =	34.411082
346.1	45.000000 x	.057200 =	2.574000

T.E = 99.501024

7367.1 7367.1

021	.050000 x	2.670000 =	.133500
1446	.010000 x	51.200500 =	.512005
003	3.000000 x	20.290479 =	60.871437
002	2.000000 x	17.205541 =	34.411082
026	10.000000 x	.099900 =	.999000
348	15.000000 x	.103600 =	1.554000
346.1	30.000000 x	.057200 =	1.716000

T.E = 100.197024

7367.2 7367.2

021	.050000 x	2.670000 =	.133500
026	10.000000 x	.099900 =	.999000
348	15.000000 x	.103600 =	1.554000
003	3.000000 x	20.290479 =	60.871437
1446	.010000 x	51.200500 =	.512005
002	2.000000 x	17.205541 =	34.411082
346.2	30.000000 x	.103600 =	3.108000

T.E = 101.589024

7371.1 7371.1

026	-	14.000000 x	.099900 =	-	1.398600
7361		1.000000 x	49.035212 =		49.035212
029		14.000000 x	.151500 =		2.121000

T.E = 49.757612

7371.2 7371.2

026	-	14.000000 x	.099900 =	-	1.398600
7361		1.000000 x	49.035212 =		49.035212
028		14.000000 x	.000000 =		.000000

T.E =

7372.1 7372.1

026	-	14.000000 x	.099900 =	-	1.398600
7362.1		1.000000 x	49.406412 =		49.406412
029		14.000000 x	.151500 =		2.121000

T.E = 50.128812

7372.2 7372.2

026	-	14.000000 x	.099900 =	-	1.398600
7362.1		1.000000 x	49.406412 =		49.406412
028		14.000000 x	.000000 =		.000000

T.E =

7372.3 7372.3

026	-	14.000000 x	.099900 =	-	1.398600
029		14.000000 x	.151500 =		2.121000
7362.2		1.000000 x	50.427212 =		50.427212

T.E = 51.149612

7372.4 7372.4

026	-	14.000000 x	.099900 =	-	1.398600
028		14.000000 x	.000000 =		.000000
7362.2		1.000000 x	50.427212 =		50.427212

T.E =

7373.1 7373.1

026	-	17.000000 x	.099900 =	-	1.698300
7363		1.000000 x	57.178416 =		57.178416
029		17.000000 x	.151500 =		2.575500

T.E = 58.055616

2

μ

2012

.
μ/

156

08/01/2014

7373.2 7373.2

026	-	17.000000 x	.099900 =	-	1.698300
028		17.000000 x	.000000 =		.000000
7363		1.000000 x	57.178416 =		57.178416

T.E =

7374.1 7374.1

026	-	17.000000 x	.099900 =	-	1.698300
7364.1		1.000000 x	57.688816 =		57.688816
029		17.000000 x	.151500 =		2.575500

T.E =

58.566016

7374.2 7374.2

026	-	17.000000 x	.099900 =	-	1.698300
7364.1		1.000000 x	57.688816 =		57.688816
028		17.000000 x	.000000 =		.000000

T.E =

7374.3 7374.3

026	-	17.000000 x	.099900 =	-	1.698300
029		17.000000 x	.151500 =		2.575500
7364.2		1.000000 x	58.802416 =		58.802416

T.E =

59.679616

7374.4 7374.4

026	-	17.000000 x	.099900 =	-	1.698300
028		17.000000 x	.000000 =		.000000
7364.2		1.000000 x	58.802416 =		58.802416

T.E =

7376.1 7376.1

026	-	10.000000 x	.099900 =	-	.999000
7366		1.000000 x	99.501024 =		99.501024
029		10.000000 x	.151500 =		1.515000

T.E =

100.017024

7376.2 7376.2

026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7366		1.000000 x	99.501024 =		99.501024

T.E =

2

μ

2012

.
μ/

157

08/01/2014

7377.1 7377.1

026	-	10.000000 x	.099900 =	-	.999000
7367.1		1.000000 x	100.197024 =		100.197024
029		10.000000 x	.151500 =		1.515000

T.E = 100.713024

7377.2 7377.2

026	-	10.000000 x	.099900 =	-	.999000
028		10.000000 x	.000000 =		.000000
7367.1		1.000000 x	100.197024 =		100.197024

T.E =

7377.3 7377.3

026	-	10.000000 x	.099900 =	-	.999000
029		10.000000 x	.151500 =		1.515000
7367.2		1.000000 x	101.589024 =		101.589024

T.E = 102.105024

7377.4 7377.4

026	-	10.000000 x	.099900 =	-	.999000
7367.2		1.000000 x	101.589024 =		101.589024
028		10.000000 x	.000000 =		.000000

T.E =

7381 7381

456		.100000 x	1.658300 =		.165830
-----	--	-----------	------------	--	---------

T.E = .165830

7382 7382

443		.150000 x	1.987900 =		.298185
447		.050000 x	4.525500 =		.226275
003		.300000 x	20.290479 =		6.087144

T.E = 6.611604

7383 7383

002		.250000 x	17.205541 =		4.301385
003		.150000 x	20.290479 =		3.043572

T.E = 7.344957

7384 7384

003		.500000 x	20.290479 =		10.145240
-----	--	-----------	-------------	--	-----------

T.E = 10.145240

7385	7385			
003		.500000 x	20.290479 =	10.145240

			T.E =	10.145240
7386	7386			
003		.600000 x	20.290479 =	12.174287

			T.E =	12.174287
7387	7387			
261		1.500000 x	.611900 =	.917850
003		1.000000 x	20.290479 =	20.290479
7361		1.100000 x	49.035212 =	53.938733

			T.E =	75.147062
7388	7388			
003		2.500000 x	20.290479 =	50.726198
7361		.600000 x	49.035212 =	29.421127

			T.E =	80.147325
7389.1.1	7389.1.1			
7371.1		.300000 x	49.757612 =	14.927284

			T.E =	14.927284
7389.1.10	7389.1.10			
7374.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.11	7389.1.11			
7374.3		.300000 x	59.679616 =	17.903885

			T.E =	17.903885
7389.1.12	7389.1.12			
7374.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.2	7389.1.2			
7371.2		.300000 x	.000000 =	.000000

			T.E =	

7389.1.3	7389.1.3			
7372.1		.300000 x	50.128812 =	15.038644

			T.E =	15.038644
7389.1.4	7389.1.4			
7372.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.5	7389.1.5			
7372.3		.300000 x	51.149612 =	15.344884

			T.E =	15.344884
7389.1.6	7389.1.6			
7372.4		.300000 x	.000000 =	.000000

			T.E =	
7389.1.7	7389.1.7			
7373.1		.300000 x	58.055616 =	17.416685

			T.E =	17.416685
7389.1.8	7389.1.8			
7373.2		.300000 x	.000000 =	.000000

			T.E =	
7389.1.9	7389.1.9			
7374.1		.300000 x	58.566016 =	17.569805

			T.E =	17.569805
7389.2.1	7389.2.1			
7371.1		.500000 x	49.757612 =	24.878806

			T.E =	24.878806
7389.2.10	7389.2.10			
7374.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.11	7389.2.11			
7374.3		.500000 x	59.679616 =	29.839808

			T.E =	29.839808

7389.2.12	7389.2.12			
7374.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.2	7389.2.2			
7371.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.3	7389.2.3			
7372.1		.500000 x	50.128812 =	25.064406

			T.E =	25.064406
7389.2.4	7389.2.4			
7372.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.5	7389.2.5			
7372.3		.500000 x	51.149612 =	25.574806

			T.E =	25.574806
7389.2.6	7389.2.6			
7372.4		.500000 x	.000000 =	.000000

			T.E =	
7389.2.7	7389.2.7			
7373.1		.500000 x	58.055616 =	29.027808

			T.E =	29.027808
7389.2.8	7389.2.8			
7373.2		.500000 x	.000000 =	.000000

			T.E =	
7389.2.9	7389.2.9			
7374.1		.500000 x	58.566016 =	29.283008

			T.E =	29.283008
7391	7391			
003		.250000 x	20.290479 =	5.072620

			T.E =	5.072620

7392	7392			
298.1		1.081080 x	7.020000 =	7.589182
003		.400000 x	20.290479 =	8.116192

			T.E =	15.705373
7393	7393			
294		.347760 x	3.518600 =	1.223628
003		.300000 x	20.290479 =	6.087144

			T.E =	7.310772
7394	7394			
297.2		1.423800 x	.000000 =	.000000
003		.400000 x	20.290479 =	8.116192

			T.E =	
7395	7395			
522		1.100000 x	.000000 =	.000000
003		.300000 x	20.290479 =	6.087144

			T.E =	
7396	7396			
523		1.200000 x	7.500000 =	9.000000
002		.350000 x	17.205541 =	6.021939
003		.350000 x	20.290479 =	7.101668

			T.E =	22.123607
7397	7397			
524		1.150000 x	7.500000 =	8.625000
003		.700000 x	20.290479 =	14.203335

			T.E =	22.828335
7398	7398			
525		1.070000 x	7.840000 =	8.388800
002		.400000 x	17.205541 =	6.882216
003		.400000 x	20.290479 =	8.116192

			T.E =	23.387208
7399	7399			
526		1.100000 x	1.400000 =	1.540000
003		.250000 x	20.290479 =	5.072620

			T.E =	6.612620

7416	7416			
003		.800000 x	20.290479 =	16.232383

			T.E =	16.232383
7417	7417			
003		1.800000 x	20.290479 =	36.522862

			T.E =	36.522862
7418	7418			
003		2.600000 x	20.290479 =	52.755245

			T.E =	52.755245
7419	7419			
003		.800000 x	20.290479 =	16.232383

			T.E =	16.232383
7420	7420			
003		1.200000 x	20.290479 =	24.348575

			T.E =	24.348575
7421	7421			
003		.800000 x	20.290479 =	16.232383

			T.E =	16.232383
7422	7422			
003		.350000 x	20.290479 =	7.101668

			T.E =	7.101668
7431	7431			
332		1.150000 x	79.680000 =	91.632000
003		4.000000 x	20.290479 =	81.161916
1445		.020000 x	60.356500 =	1.207130
1444		.001000 x	74.507500 =	.074508

			T.E =	174.075554
7432	7432			
331		1.150000 x	76.850000 =	88.377500
1445		.020000 x	60.356500 =	1.207130
003		4.400000 x	20.290479 =	89.278108
1444		.001000 x	74.507500 =	.074508

			T.E =	178.937245

7433 7433

331	1.150000 x	76.850000 =	88.377500
003	5.100000 x	20.290479 =	103.481443
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508

T.E = 193.140580

7434 7434

331	1.150000 x	76.850000 =	88.377500
1444	.001000 x	74.507500 =	.074508
1445	.020000 x	60.356500 =	1.207130
003	6.100000 x	20.290479 =	123.771922

T.E = 213.431059

7441 7441

331	1.250000 x	76.850000 =	96.062500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	4.200000 x	20.290479 =	85.220012

T.E = 182.564149

7442 7442

331	1.250000 x	76.850000 =	96.062500
003	4.600000 x	20.290479 =	93.336203
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508

T.E = 190.680341

7443 7443

331	1.250000 x	76.850000 =	96.062500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	5.300000 x	20.290479 =	107.539539

T.E = 204.883676

7444 7444

331	1.250000 x	76.850000 =	96.062500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	6.300000 x	20.290479 =	127.830018

T.E = 225.174155

7451 7451

333	1.150000 x	111.570000 =	128.305500
003	4.500000 x	20.290479 =	91.307156
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508

T.E = 220.894293

7452 7452

333	1.150000 x	111.570000 =	128.305500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	4.900000 x	20.290479 =	99.423347

T.E = 229.010485

7453 7453

333	1.150000 x	111.570000 =	128.305500
003	5.600000 x	20.290479 =	113.626682
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508

T.E = 243.213820

7454 7454

333	1.150000 x	111.570000 =	128.305500
003	6.600000 x	20.290479 =	133.917161
1444	.001000 x	74.507500 =	.074508
1445	.020000 x	60.356500 =	1.207130

T.E = 263.504299

7461 7461

333	1.250000 x	111.570000 =	139.462500
003	4.900000 x	20.290479 =	99.423347
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508

T.E = 240.167485

7462 7462

333	1.250000 x	111.570000 =	139.462500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	5.300000 x	20.290479 =	107.539539

T.E = 248.283676

7463 7463

333	1.250000 x	111.570000 =	139.462500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	6.000000 x	20.290479 =	121.742874

T.E = 262.487012

7464 7464

333	1.250000 x	111.570000 =	139.462500
1445	.020000 x	60.356500 =	1.207130
1444	.001000 x	74.507500 =	.074508
003	7.000000 x	20.290479 =	142.033353

T.E = 282.777491

7491 7491

331	.115000 x	76.850000 =	8.837750
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451
003	.915000 x	20.290479 =	18.565788

T.E = 27.531702

7492 7492

331	.125000 x	76.850000 =	9.606250
003	.945000 x	20.290479 =	19.174503
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451

T.E = 28.908916

7493 7493

333	.115000 x	111.570000 =	12.830550
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451
003	.990000 x	20.290479 =	20.087574

T.E = 33.046288

7494 7494

333	.125000 x	111.570000 =	13.946250
003	1.050000 x	20.290479 =	21.305003
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451

T.E = 35.379417

7496	7496				
331		.057500 x	76.850000 =	4.418875	
1445		.001000 x	60.356500 =	.060357	
1444		.000050 x	74.507500 =	.003725	
003		.488000 x	20.290479 =	9.901754	

			T.E =	14.384711	
7497	7497				
331		.062500 x	76.850000 =	4.803125	
1445		.001000 x	60.356500 =	.060357	
1444		.000050 x	74.507500 =	.003725	
003		.504000 x	20.290479 =	10.226401	

			T.E =	15.093608	
7498	7498				
333		.057500 x	111.570000 =	6.415275	
003		.528000 x	20.290479 =	10.713373	
1444		.000050 x	74.507500 =	.003725	
1445		.001000 x	60.356500 =	.060357	

			T.E =	17.192730	
7499	7499				
333		.062500 x	111.570000 =	6.973125	
003		.560000 x	20.290479 =	11.362668	
1445		.001000 x	60.356500 =	.060357	
1444		.000050 x	74.507500 =	.003725	

			T.E =	18.399875	
7501	7501				
7433		1.000000 x	193.140580 =	193.140580	

			T.E =	193.140580	
7503	7503				
7443		1.000000 x	204.883676 =	204.883676	

			T.E =	204.883676	
7506	7506				
7453		1.000000 x	243.213820 =	243.213820	

			T.E =	243.213820	
7508	7508				
7463		1.000000 x	262.487012 =	262.487012	

			T.E =	262.487012	

7511 7511

331	.115000 x	76.850000 =	8.837750
003	.915000 x	20.290479 =	18.565788
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451

T.E = 27.531702

7513 7513

331	.125000 x	76.850000 =	9.606250
1445	.002000 x	60.356500 =	.120713
1444	.000100 x	74.507500 =	.007451
003	.945000 x	20.290479 =	19.174503

T.E = 28.908916

7521 7521

331	1.150000 x	76.850000 =	88.377500
003	5.700000 x	20.290479 =	115.655730
1445	.020000 x	60.356500 =	1.207130

T.E = 205.240360

7523 7523

331	1.150000 x	76.850000 =	88.377500
003	4.800000 x	20.290479 =	97.394299
1445	.020000 x	60.356500 =	1.207130

T.E = 186.978929

7524 7524

331	1.250000 x	76.850000 =	96.062500
003	6.100000 x	20.290479 =	123.771922
1445	.020000 x	60.356500 =	1.207130

T.E = 221.041552

7526 7526

331	1.250000 x	76.850000 =	96.062500
1445	.020000 x	60.356500 =	1.207130
003	5.000000 x	20.290479 =	101.452395

T.E = 198.722025

7531 7531

332	1.150000 x	79.680000 =	91.632000
003	5.200000 x	20.290479 =	105.510491
1445	.020000 x	60.356500 =	1.207130

T.E = 198.349621

7532 7532

332	1.250000 x	79.680000 =	99.600000
003	5.400000 x	20.290479 =	109.568587
1445	.020000 x	60.356500 =	1.207130

T.E = 210.375717

7533 7533

334	1.150000 x	119.540000 =	137.471000
003	5.700000 x	20.290479 =	115.655730
1445	.020000 x	60.356500 =	1.207130

T.E = 254.333860

7534 7534

334	1.250000 x	119.540000 =	149.425000
1445	.020000 x	60.356500 =	1.207130
003	6.100000 x	20.290479 =	123.771922

T.E = 274.404052

7536 7536

334	.300000 x	119.540000 =	35.862000
003	3.000000 x	20.290479 =	60.871437
1445	.010000 x	60.356500 =	.603565

T.E = 97.337002

7537 7537

336	.300000 x	.000000 =	.000000
003	4.000000 x	20.290479 =	81.161916
1445	.010000 x	60.356500 =	.603565

T.E =

7541 7541

332	.170000 x	79.680000 =	13.545600
334	.350000 x	119.540000 =	41.839000
003	3.700000 x	20.290479 =	75.074772
1445	.010000 x	60.356500 =	.603565

T.E = 131.062937

7542 7542

332	.170000 x	79.680000 =	13.545600
336	.350000 x	.000000 =	.000000
1445	.010000 x	60.356500 =	.603565
003	4.200000 x	20.290479 =	85.220012

T.E =

7543 7543

332	.170000 x	79.680000 =	13.545600
003	4.800000 x	20.290479 =	97.394299
1445	.010000 x	60.356500 =	.603565
338	.350000 x	.000000 =	.000000

T.E =

7551 7551

321	1.150000 x	.000000 =	.000000
1445	.020000 x	60.356500 =	1.207130
003	7.000000 x	20.290479 =	142.033353

T.E =

7552 7552

322	1.150000 x	99.620000 =	114.563000
003	7.000000 x	20.290479 =	142.033353
1445	.020000 x	60.356500 =	1.207130

T.E =

7553 7553

323	1.150000 x	113.850000 =	130.927500
1445	.020000 x	60.356500 =	1.207130
003	7.000000 x	20.290479 =	142.033353

T.E =

7554 7554

321	1.150000 x	.000000 =	.000000
1445	.020000 x	60.356500 =	1.207130
003	9.000000 x	20.290479 =	182.614311

T.E =

7555 7555

322	1.150000 x	99.620000 =	114.563000
003	9.000000 x	20.290479 =	182.614311
1445	.020000 x	60.356500 =	1.207130

T.E =

7556 7556

323	1.150000 x	113.850000 =	130.927500
003	9.000000 x	20.290479 =	182.614311
1445	.020000 x	60.356500 =	1.207130

T.E =

314.748941

7558	7558				
331		.080000 x	76.850000 =	6.148000	
003		1.500000 x	20.290479 =	30.435719	
1445		.003000 x	60.356500 =	.181070	

			T.E =	36.764788	
7559	7559				
331		.080000 x	76.850000 =	6.148000	
1445		.003000 x	60.356500 =	.181070	
003		1.500000 x	20.290479 =	30.435719	

			T.E =	36.764788	
7561	7561				
332		1.150000 x	79.680000 =	91.632000	
1445		.020000 x	60.356500 =	1.207130	
003		5.200000 x	20.290479 =	105.510491	

			T.E =	198.349621	
7562	7562				
334		1.150000 x	119.540000 =	137.471000	
003		5.700000 x	20.290479 =	115.655730	
1445		.020000 x	60.356500 =	1.207130	

			T.E =	254.333860	
7563	7563				
332		1.250000 x	79.680000 =	99.600000	
1445		.020000 x	60.356500 =	1.207130	
003		5.400000 x	20.290479 =	109.568587	

			T.E =	210.375717	
7564	7564				
334		1.250000 x	119.540000 =	149.425000	
1445		.020000 x	60.356500 =	1.207130	
003		6.100000 x	20.290479 =	123.771922	

			T.E =	274.404052	
7565	7565				
003		1.500000 x	20.290479 =	30.435719	

			T.E =	30.435719	
7566	7566				
7561		1.500000 x	198.349621 =	297.524432	

			T.E =	297.524432	

7567	7567			
7562		1.500000 x	254.333860 =	381.500790

			T.E =	381.500790
7568	7568			
7563		1.500000 x	210.375717 =	315.563576

			T.E =	315.563576
7569	7569			
7564		1.500000 x	274.404052 =	411.606078

			T.E =	411.606078
7571.1	7571.1			
327.1		1.000000 x	.000000 =	.000000
327.1		.030000 x	.000000 =	.000000
003		3.000000 x	20.290479 =	60.871437

			T.E =	
7571.2	7571.2			
327.2		1.000000 x	.000000 =	.000000
003		3.000000 x	20.290479 =	60.871437
327.2		.030000 x	.000000 =	.000000

			T.E =	
7571.3	7571.3			
327.3		1.000000 x	176.980000 =	176.980000
327.3		.030000 x	176.980000 =	5.309400
003		3.000000 x	20.290479 =	60.871437

			T.E =	243.160837
7572	7572			
328		1.000000 x	.000000 =	.000000
003		4.000000 x	20.290479 =	81.161916
328		.030000 x	.000000 =	.000000

			T.E =	
7576	7576			
331		1.150000 x	76.850000 =	88.377500
003		3.800000 x	20.290479 =	77.103820

			T.E =	165.481320

7577 7577

334	1.150000 x	119.540000 =	137.471000
003	4.200000 x	20.290479 =	85.220012

T.E = 222.691012

7578 7578

336	1.150000 x	.000000 =	.000000
003	4.700000 x	20.290479 =	95.365251

T.E =

7581 7581

326	1.050000 x	57.180000 =	60.039000
3211	.020000 x	131.722583 =	2.634452
1445	.005000 x	60.356500 =	.301783
003	2.300000 x	20.290479 =	46.668102

T.E = 109.643336

7601 7601

401	1.100000 x	12.200000 =	13.420000
457	.500000 x	.827900 =	.413950
003	.500000 x	20.290479 =	10.145240

T.E = 23.979190

7602 7602

403	1.100000 x	14.290000 =	15.719000
457	.500000 x	.827900 =	.413950
003	.550000 x	20.290479 =	11.159763

T.E = 27.292713

7603 7603

406	1.100000 x	17.660000 =	19.426000
457	.500000 x	.827900 =	.413950
003	.650000 x	20.290479 =	13.188811

T.E = 33.028761

7604.1 7604.1

409	1.100000 x	21.030000 =	23.133000
003	.750000 x	20.290479 =	15.217859
457	.500000 x	.827900 =	.413950

T.E = 38.764809

7604.2 7604.2

410	1.100000 x	28.610000 =	31.471000
003	.750000 x	20.290479 =	15.217859
457	.500000 x	.827900 =	.413950

T.E = 47.102809

7606 7606

401	1.100000 x	12.200000 =	13.420000
003	.600000 x	20.290479 =	12.174287

T.E = 25.594287

7607 7607

403	1.100000 x	14.290000 =	15.719000
003	.650000 x	20.290479 =	13.188811

T.E = 28.907811

7608 7608

406	1.100000 x	17.660000 =	19.426000
003	.750000 x	20.290479 =	15.217859

T.E = 34.643859

7609.1 7609.1

409	1.100000 x	21.030000 =	23.133000
003	.850000 x	20.290479 =	17.246907

T.E = 40.379907

7609.2 7609.2

410	1.100000 x	28.610000 =	31.471000
003	.850000 x	20.290479 =	17.246907

T.E = 48.717907

7611 7611

411	1.100000 x	26.710000 =	29.381000
457	.500000 x	.827900 =	.413950
003	.500000 x	20.290479 =	10.145240

T.E = 39.940190

7612 7612

412	1.100000 x	28.830000 =	31.713000
003	.550000 x	20.290479 =	11.159763
457	.500000 x	.827900 =	.413950

T.E = 43.286713

7613	7613				
411		1.100000 x	26.710000 =	29.381000	
003		.600000 x	20.290479 =	12.174287	

			T.E =	41.555287	
7614	7614				
412		1.100000 x	28.830000 =	31.713000	
003		.650000 x	20.290479 =	13.188811	

			T.E =	44.901811	
7616	7616				
414		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.827900 =	.413950	
003		.600000 x	20.290479 =	12.174287	

			T.E =	35.721237	
7617	7617				
415		1.100000 x	21.030000 =	23.133000	
457		.500000 x	.827900 =	.413950	
003		.650000 x	20.290479 =	13.188811	

			T.E =	36.735761	
7618	7618				
414		1.100000 x	21.030000 =	23.133000	
003		.700000 x	20.290479 =	14.203335	

			T.E =	37.336335	
7619	7619				
415		1.100000 x	21.030000 =	23.133000	
003		.750000 x	20.290479 =	15.217859	

			T.E =	38.350859	
7621	7621				
418		1.100000 x	29.450000 =	32.395000	
457		.800000 x	.827900 =	.662320	
003		1.200000 x	20.290479 =	24.348575	

			T.E =	57.405895	
7622	7622				
419		1.100000 x	29.450000 =	32.395000	
003		1.400000 x	20.290479 =	28.406671	
457		.800000 x	.827900 =	.662320	

			T.E =	61.463991	

7626.1 7626.1

298.2	18.000000 x	5.730000 =	103.140000
421	1.000000 x	97.840000 =	97.840000
002	7.000000 x	17.205541 =	120.438787
003	7.000000 x	20.290479 =	142.033353

T.E = 463.452140

7626.2 7626.2

298.2	18.000000 x	5.730000 =	103.140000
422	1.000000 x	134.470000 =	134.470000
003	7.000000 x	20.290479 =	142.033353
002	7.000000 x	17.205541 =	120.438787

T.E = 500.082140

7627.1 7627.1

298.2	16.000000 x	5.730000 =	91.680000
003	6.000000 x	20.290479 =	121.742874
002	6.000000 x	17.205541 =	103.233246
421	1.000000 x	97.840000 =	97.840000

T.E = 414.496120

7627.2 7627.2

298.2	16.000000 x	5.730000 =	91.680000
422	1.000000 x	134.470000 =	134.470000
003	6.000000 x	20.290479 =	121.742874
002	6.000000 x	17.205541 =	103.233246

T.E = 451.126120

7631 7631

426	1.100000 x	.000000 =	.000000
003	.050000 x	20.290479 =	1.014524

T.E =

7636 7636

428	1.100000 x	4.390000 =	4.829000
003	.060000 x	20.290479 =	1.217429

T.E = 6.046429

7637 7637

429	1.100000 x	5.390000 =	5.929000
003	.080000 x	20.290479 =	1.623238

T.E = 7.552238

7638 7638

430	1.100000 x	7.480000 =	8.228000
003	.100000 x	20.290479 =	2.029048

T.E = 10.257048

7641 7641

431	1.000000 x	.000000 =	.000000
003	.060000 x	20.290479 =	1.217429

T.E =

7642 7642

432	1.000000 x	.000000 =	.000000
003	.060000 x	20.290479 =	1.217429

T.E =

7701 7701

024	.001500 x	45.000000 =	.067500
002	.050000 x	17.205541 =	.860277
003	.120000 x	20.290479 =	2.434857

T.E = 3.362635

7702 7702

024	.001800 x	45.000000 =	.081000
002	.050000 x	17.205541 =	.860277
003	.080000 x	20.290479 =	1.623238

T.E = 2.564515

7706 7706

024	.002000 x	45.000000 =	.090000
002	.080000 x	17.205541 =	1.376443
003	.150000 x	20.290479 =	3.043572

T.E = 4.510015

7707 7707

024	.002300 x	45.000000 =	.103500
003	.090000 x	20.290479 =	1.826143
002	.100000 x	17.205541 =	1.720554

T.E = 3.650197

7708 7708

024	.002500 x	45.000000 =	.112500
003	.180000 x	20.290479 =	3.652286
002	.120000 x	17.205541 =	2.064665

T.E = 5.829451

7709 7709

024	.002800 x	45.000000 =	.126000
002	.150000 x	17.205541 =	2.580831
003	.120000 x	20.290479 =	2.434857

T.E = 5.141689

7711 7711

002	.050000 x	17.205541 =	.860277
1485	.200000 x	.855511 =	.171102
003	.200000 x	20.290479 =	4.058096

T.E = 5.089475

7712 7712

002	.080000 x	17.205541 =	1.376443
003	.250000 x	20.290479 =	5.072620
1485	.250000 x	.855511 =	.213878

T.E = 6.662941

7713 7713

002	.160000 x	17.205541 =	2.752887
1485	.280000 x	.855511 =	.239543
003	.300000 x	20.290479 =	6.087144

T.E = 9.079573

7720 7720

443	.080000 x	1.987900 =	.159032
002	.100000 x	17.205541 =	1.720554
1485	.200000 x	.855511 =	.171102
003	.300000 x	20.290479 =	6.087144

T.E = 8.137832

7721 7721

002	.070000 x	17.205541 =	1.204388
1485	.200000 x	.855511 =	.171102
003	.200000 x	20.290479 =	4.058096

T.E = 5.433586

7722.1.1	7722.1.1			
7720		.300000 x	8.137832 =	2.441350

			T.E =	2.441350
7722.1.2	7722.1.2			
7721		.300000 x	5.433586 =	1.630076

			T.E =	1.630076
7722.2.1	7722.2.1			
7720		.400000 x	8.137832 =	3.255133

			T.E =	3.255133
7722.2.2	7722.2.2			
7721		.400000 x	5.433586 =	2.173434

			T.E =	2.173434
7725	7725			
471		.300000 x	3.960000 =	1.188000
003		.250000 x	20.290479 =	5.072620
002		.150000 x	17.205541 =	2.580831

			T.E =	8.841451
7735	7735			
441		.350000 x	.077700 =	.027195
444		.150000 x	2.207500 =	.331125
003		.150000 x	20.290479 =	3.043572

			T.E =	3.401892
7736	7736			
441		.500000 x	.077700 =	.038850
444		.085000 x	2.207500 =	.187638
445		.010000 x	1.600000 =	.016000
003		.250000 x	20.290479 =	5.072620
446		.005000 x	2.662500 =	.013313

			T.E =	5.328420
7737	7737			
441		.200000 x	.077700 =	.015540
1489		.200000 x	.895520 =	.179104
003		.300000 x	20.290479 =	6.087144
1488		.600000 x	.784064 =	.470438

			T.E =	6.752226

7738 7738

441	.200000 x	.077700 =	.015540
1489	.200000 x	.895520 =	.179104
1488	.300000 x	.784064 =	.235219
003	.300000 x	20.290479 =	6.087144

T.E = 6.517007

7739 7739

441	.100000 x	.077700 =	.007770
467	.100000 x	3.397500 =	.339750
003	.150000 x	20.290479 =	3.043572

T.E = 3.391092

7740 7740

442	.250000 x	.121800 =	.030450
003	.250000 x	20.290479 =	5.072620
1492	.250000 x	2.841075 =	.710269

T.E = 5.813339

7741 7741

442	.250000 x	.121800 =	.030450
462	.250000 x	.000000 =	.000000
003	.250000 x	20.290479 =	5.072620

T.E =

7742 7742

442	.250000 x	.121800 =	.030450
003	.200000 x	20.290479 =	4.058096
463	.125000 x	4.089100 =	.511138

T.E = 4.599683

7743 7743

442	.250000 x	.121800 =	.030450
003	.150000 x	20.290479 =	3.043572
464	.125000 x	3.630000 =	.453750

T.E = 3.527772

7744 7744

442	.250000 x	.121800 =	.030450
003	.150000 x	20.290479 =	3.043572
465	.125000 x	6.180000 =	.772500

T.E = 3.846522

7745	7745			
442		.250000 x	.121800 =	.030450
1492		.250000 x	2.841075 =	.710269
003		.800000 x	20.290479 =	16.232383
1489		.200000 x	.895520 =	.179104

			T.E =	17.152206
7746	7746			
441		.350000 x	.077700 =	.027195
003		.150000 x	20.290479 =	3.043572
443		.090000 x	1.987900 =	.178911

			T.E =	3.249678
7747	7747			
441		.350000 x	.077700 =	.027195
443		.170000 x	1.987900 =	.337943
003		.250000 x	20.290479 =	5.072620

			T.E =	5.437758
7748	7748			
443		.090000 x	1.987900 =	.178911
002		.100000 x	17.205541 =	1.720554
445		.030000 x	1.600000 =	.048000
003		.200000 x	20.290479 =	4.058096
450		.060000 x	2.842800 =	.170568

			T.E =	6.176129
7749	7749			
443		.160000 x	1.987900 =	.318064
445		.050000 x	1.600000 =	.080000
003		.250000 x	20.290479 =	5.072620
002		.150000 x	17.205541 =	2.580831
450		.100000 x	2.842800 =	.284280

			T.E =	8.335795
7751	7751			
003		.150000 x	20.290479 =	3.043572
1491		.125000 x	1.534505 =	.191813

			T.E =	3.235385
7752	7752			
003		.250000 x	20.290479 =	5.072620
1491		.250000 x	1.534505 =	.383626

			T.E =	5.456246

7753	7753			
441		1.000000 x	.077700 =	.077700
443		.080000 x	1.987900 =	.159032
003		.650000 x	20.290479 =	13.188811
1491		.200000 x	1.534505 =	.306901
1490		.090000 x	1.594219 =	.143480

			T.E =	13.875924
7754	7754			
441		.800000 x	.077700 =	.062160
1487		.090000 x	.621987 =	.055979
003		.800000 x	20.290479 =	16.232383
1491		.200000 x	1.534505 =	.306901
1490		.090000 x	1.594219 =	.143480

			T.E =	16.800903
7755	7755			
442		.250000 x	.121800 =	.030450
003		1.000000 x	20.290479 =	20.290479
1492		.160000 x	2.841075 =	.454572
1491		.200000 x	1.534505 =	.306901

			T.E =	21.082402
7756	7756			
442		.300000 x	.121800 =	.036540
003		.350000 x	20.290479 =	7.101668
1492		.300000 x	2.841075 =	.852323

			T.E =	7.990530
7761	7761			
441		.650000 x	.077700 =	.050505
1489		.200000 x	.895520 =	.179104
1488		.600000 x	.784064 =	.470438
003		.800000 x	20.290479 =	16.232383
467		.100000 x	3.397500 =	.339750
473		.100000 x	2.832500 =	.283250

			T.E =	17.555431
7762	7762			
473		.100000 x	2.832500 =	.283250
003		.200000 x	20.290479 =	4.058096

			T.E =	4.341346

7764	7764			
474		.125000 x	3.883100 =	.485388
003		.100000 x	20.290479 =	2.029048

			T.E =	2.514435
7765	7765			
475		.125000 x	6.416900 =	.802113
003		.200000 x	20.290479 =	4.058096

			T.E =	4.860208
7766	7766			
442		.275000 x	.121800 =	.033495
473		.110000 x	2.832500 =	.311575
1492		.275000 x	2.841075 =	.781296
003		.880000 x	20.290479 =	17.855622

			T.E =	18.981987
7767.1	7767.1			
7755		.150000 x	21.082402 =	3.162360

			T.E =	3.162360
7767.2	7767.2			
442		.250000 x	.121800 =	.030450
1492		.160000 x	2.841075 =	.454572
003		1.000000 x	20.290479 =	20.290479
473		.200000 x	2.832500 =	.566500

			=	21.342001
	T.E =	.150000 x	21.342001 =	3.201300

7767.3	7767.3			
7755		.250000 x	21.082402 =	5.270601

			T.E =	5.270601
7767.4	7767.4			
442		.250000 x	.121800 =	.030450
473		.200000 x	2.832500 =	.566500
003		1.000000 x	20.290479 =	20.290479
1492		.160000 x	2.841075 =	.454572

			=	21.342001
	T.E =	.250000 x	21.342001 =	5.335500

7767.5 7767.5

7755 .350000 x 21.082402 = 7.378841

T.E = 7.378841

7767.6 7767.6

442 .250000 x .121800 = .030450
473 .200000 x 2.832500 = .566500
1492 .160000 x 2.841075 = .454572
003 1.000000 x 20.290479 = 20.290479

= 21.342001

T.E = .350000 x 21.342001 = 7.469700

7767.7 7767.7

7755 .450000 x 21.082402 = 9.487081

T.E = 9.487081

7767.8 7767.8

442 .250000 x .121800 = .030450
473 .200000 x 2.832500 = .566500
1492 .160000 x 2.841075 = .454572
003 1.000000 x 20.290479 = 20.290479

= 21.342001

T.E = .450000 x 21.342001 = 9.603900

7768 7768

460 .200000 x 4.377500 = .875500
003 .450000 x 20.290479 = 9.130716
460 .030000 x 4.377500 = .131325
002 .450000 x 17.205541 = 7.742493

T.E = 17.880034

7769 7769

460 .200000 x 4.377500 = .875500
002 .200000 x 17.205541 = 3.441108
003 .200000 x 20.290479 = 4.058096
460 .030000 x 4.377500 = .131325

T.E = 8.506029

7770 7770

460 .090000 x 4.377500 = .393975
003 .150000 x 20.290479 = 3.043572
002 .150000 x 17.205541 = 2.580831
460 .020000 x 4.377500 = .087550

T.E = 6.105928

7771 7771

441	1.000000 x	.077700 =	.077700
1488	.160000 x	.784064 =	.125450
1487	.080000 x	.621987 =	.049759
003	1.300000 x	20.290479 =	26.377623
473	.100000 x	2.832500 =	.283250
467	.110000 x	3.397500 =	.373725

T.E = 27.287507

7772 7772

441	1.000000 x	.077700 =	.077700
458	.100000 x	5.280000 =	.528000
443	.100000 x	1.987900 =	.198790
003	.500000 x	20.290479 =	10.145240

T.E = 10.949730

7773 7773

441	1.000000 x	.077700 =	.077700
459	.100000 x	5.280000 =	.528000
443	.100000 x	1.987900 =	.198790
003	.600000 x	20.290479 =	12.174287

T.E = 12.978777

7774 7774

442	.250000 x	.121800 =	.030450
473	.200000 x	2.832500 =	.566500
1492	.160000 x	2.841075 =	.454572
003	1.000000 x	20.290479 =	20.290479

T.E = 21.342001

7785.1 7785.1

441	.350000 x	.077700 =	.027195
003	.700000 x	20.290479 =	14.203335
477	.160000 x	.000000 =	.000000
476	.120000 x	2.437300 =	.292476

T.E =

7785.2 7785.2

441	.350000 x	.077700 =	.027195
476	.120000 x	2.437300 =	.292476
478	.160000 x	3.060000 =	.489600
003	.700000 x	20.290479 =	14.203335

T.E = 15.012606

7786.1 7786.1

441	.350000 x	.077700 =	.027195
1489	.200000 x	.895520 =	.179104
003	1.000000 x	20.290479 =	20.290479
1488	.600000 x	.784064 =	.470438
477	.110000 x	.000000 =	.000000

T.E =

7786.2 7786.2

441	.350000 x	.077700 =	.027195
1489	.200000 x	.895520 =	.179104
1488	.600000 x	.784064 =	.470438
003	1.000000 x	20.290479 =	20.290479
478	.110000 x	3.060000 =	.336600

T.E =

21.303816

7787 7787

441	1.000000 x	.077700 =	.077700
476	.090000 x	2.437300 =	.219357
1488	.160000 x	.784064 =	.125450
1487	.080000 x	.621987 =	.049759
003	1.000000 x	20.290479 =	20.290479
477	.160000 x	.000000 =	.000000

T.E =

7788 7788

441	.250000 x	.077700 =	.019425
479	1.000000 x	1.876600 =	1.876600
003	.700000 x	20.290479 =	14.203335

T.E =

16.099360

7791 7791

441	1.000000 x	.077700 =	.077700
1487	.050000 x	.621987 =	.031099
1491	.200000 x	1.534505 =	.306901
003	.500000 x	20.290479 =	10.145240

T.E =

10.560940

7792 7792

482	.150000 x	1.539700 =	.230955
003	.500000 x	20.290479 =	10.145240

T.E =

10.376195

7793	7793			
480		.500000 x	.000000 =	.000000
003		.200000 x	20.290479 =	4.058096

			T.E =	
7794	7794			
482		.150000 x	1.539700 =	.230955
003		.500000 x	20.290479 =	10.145240

			T.E =	10.376195
7797	7797			
201		.000500 x	290.000000 =	.145000
002		.060000 x	17.205541 =	1.032332

			T.E =	1.177332
7798	7798			
201		.000600 x	290.000000 =	.174000
002		.070000 x	17.205541 =	1.204388

			T.E =	1.378388
7801	7801			
496		1.200000 x	.887400 =	1.064880
003		.150000 x	20.290479 =	3.043572

			T.E =	4.108452
7806	7806			
498		1.150000 x	.991400 =	1.140110
003		.300000 x	20.290479 =	6.087144

			T.E =	7.227254
7807	7807			
499		1.150000 x	1.359000 =	1.562850
003		.400000 x	20.290479 =	8.116192

			T.E =	9.679042
7808	7808			
500		1.150000 x	1.998800 =	2.298620
003		.600000 x	20.290479 =	12.174287

			T.E =	14.472907

7809	7809			
501		1.200000 x	2.700000 =	3.240000
003		.800000 x	20.290479 =	16.232383

			T.E =	19.472383
7810	7810			
502		1.200000 x	3.780000 =	4.536000
003		.900000 x	20.290479 =	18.261431

			T.E =	22.797431
7811	7811			
503		1.200000 x	.887400 =	1.064880
003		.800000 x	20.290479 =	16.232383

			T.E =	17.297263
7812	7812			
504		1.300000 x	1.175100 =	1.527630
003		.900000 x	20.290479 =	18.261431

			T.E =	19.789061
7813	7813			
505		1.000000 x	19.170000 =	19.170000
003		.600000 x	20.290479 =	12.174287

			T.E =	31.344287
7901	7901			
490		1.080000 x	.730000 =	.788400
003		.200000 x	20.290479 =	4.058096

			T.E =	4.846496
7902	7902			
527		1.050000 x	5.120000 =	5.376000
003		1.000000 x	20.290479 =	20.290479

			T.E =	25.666479
7903	7903			
528		1.050000 x	6.910000 =	7.255500
003		.600000 x	20.290479 =	12.174287

			T.E =	19.429787

7904	7904			
494		1.050000 x	5.480000 =	5.754000
003		.500000 x	20.290479 =	10.145240

			T.E =	15.899240
7911	7911			
493		1.200000 x	.730000 =	.876000
506		1.100000 x	1.431700 =	1.574870
003		.150000 x	20.290479 =	3.043572
002		.300000 x	17.205541 =	5.161662

			T.E =	10.656104
7912	7912			
493		1.200000 x	.730000 =	.876000
507		1.100000 x	1.880000 =	2.068000
003		.150000 x	20.290479 =	3.043572
002		.350000 x	17.205541 =	6.021939

			T.E =	12.009511
7913	7913			
493		1.200000 x	.730000 =	.876000
508		1.100000 x	.860000 =	.946000
003		.150000 x	20.290479 =	3.043572
002		.400000 x	17.205541 =	6.882216

			T.E =	11.747788
7914	7914			
509		1.100000 x	.410000 =	.451000
003		.080000 x	20.290479 =	1.623238

			T.E =	2.074238
7915.1	7915.1			
7911		.850000 x	10.656104 =	9.057688

			T.E =	9.057688
7915.2	7915.2			
7912		.850000 x	12.009511 =	10.208084

			T.E =	10.208084
7915.3	7915.3			
7913		.850000 x	11.747788 =	9.985620

			T.E =	9.985620

7921	7921			
529		1.030000 x	1.400000 =	1.442000
002		.040000 x	17.205541 =	.688222

			T.E =	2.130222
7922	7922			
530		1.030000 x	2.190000 =	2.255700
002		.050000 x	17.205541 =	.860277

			T.E =	3.115977
7923	7923			
531		1.030000 x	1.180000 =	1.215400
002		.050000 x	17.205541 =	.860277

			T.E =	2.075677
7931	7931			
519		1.050000 x	53.140000 =	55.797000
003		1.500000 x	20.290479 =	30.435719

			T.E =	86.232719
7932.1	7932.1			
514		.000000 x	45.650000 =	.000000
003		.000000 x	20.290479 =	.000000

			T.E =	.000000
7932.2	7932.2			
520		.000000 x	43.930000 =	.000000
003		.000000 x	20.290479 =	.000000

			T.E =	.000000
7933.1	7933.1			
514		.000000 x	45.650000 =	.000000
003		.000000 x	20.290479 =	.000000

			T.E =	.000000
7933.2	7933.2			
520		.000000 x	43.930000 =	.000000
003		.000000 x	20.290479 =	.000000

			T.E =	.000000

7934	7934			
535		1.150000 x	7.050000 =	8.107500
002		.500000 x	17.205541 =	8.602771
003		.500000 x	20.290479 =	10.145240

			T.E =	26.855510
7935	7935			
536		.150000 x	2.500000 =	.375000
003		.250000 x	20.290479 =	5.072620

			T.E =	5.447620
7936	7936			
536		.300000 x	2.500000 =	.750000
003		.100000 x	20.290479 =	2.029048

			T.E =	2.779048
7940	7940			
176		1.050000 x	.000000 =	.000000
002		.300000 x	17.205541 =	5.161662
003		.300000 x	20.290479 =	6.087144
251		.100000 x	.927000 =	.092700

			T.E =	
7941	7941			
067		.040000 x	45.500000 =	1.820000
001		.100000 x	15.643441 =	1.564344

			T.E =	3.384344
7942	7942			
510		2.500000 x	3.020000 =	7.550000
001		.100000 x	15.643441 =	1.564344

			T.E =	9.114344