

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών

4ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.186900
212	1.419500
213	1.949500
214	4.160000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.895000
232	2.184000
233	.545500
233.1	.545500
233.2	.598400
233.3	8.200000
234	.941500
234.1	1.111500
234.2	1.006500
234.3	1.054000
235	.703000
236	.673000
237	1.218000
237.1	1.380000
241	7.750000
242	4.500000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.440000
361.1	13.520000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	17.490000
361.3	22.200000
361.4	
361.5	42.370000
361.6	56.540000
361.7	87.480000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	7.990000
372.2	12.580000
372.3	16.500000
372.4	25.540000
372.5	32.500000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.490000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.260000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	91.600000
376.10	502.070000
376.11	544.290000
376.12	91.600000
376.13	101.900000
376.14	113.040000
376.15	144.820000
376.16	182.130000
376.17	231.180000
376.18	311.830000
376.19	346.570000
376.2	101.900000
376.20	412.890000
376.21	502.070000
376.22	544.290000
376.3	113.040000
376.4	144.820000
376.5	182.130000
376.6	231.180000
376.7	311.830000
376.8	346.570000
376.9	412.890000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23
386.24
386.25
386.26
386.27
386.28
386.29
386.3
07/2012

113,082.000000

386.32
386.33
386.34
386.35
386.36
386.37
386.38
386.39
386.4
386.40
386.41
386.42
386.43
386.44
386.45
386.46
386.47
386.48
386.49
386.5
386.50
386.51
386.52
386.53
386.54
386.55
386.56
386.57
386.58
386.59
386.6
386.60
386.61
386.62
386.63
386.64
386.65
386.66
386.67
386.68
386.69
386.7
386.70
386.71
386.72
386.73
386.74
386.75
386.76

76,825.000000

134,053.000000

153,664.000000

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	25,662.000000
387.1	
387.2	
387.3	21,523.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,664.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,629.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	8,188.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	15,362.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.960000
396.12	4.250000
396.13	1.770000
396.14	42.680000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.950000
397.4	.167500
398.1	.250000
398.10	142.840000
398.11	140.870000
398.12	182.180000
398.13	10.300000
398.14	60.360000
398.15	77.960000
398.16	64.290000
398.17	107.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	6.400000

398.6	330.000000
398.7	1,360.000000
398.8	31.620000
398.9	131.840000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
419	4.530000
420	97.290000
421	32.560000
428	437.840000
429	77.590000
450	83.850000
451	4.870000
452	103.060000
453	
454	97.290000
455	31.280000
456	35.040000
457	457.700000
458	285.020000
459	422.050000
460	521.890000
461	239.030000
462	348.520000
463	43.800000
464	383.570000
465	102.610000
466	47.860000
467	348.520000
468	87.280000
469	87.280000
470	70.390000
471	61.000000
472	26.510000
473	17.050000
474	35.040000
475	1,970.400000
476	85.400000
477	6.950000
478	115.120000
479	185.200000
480	27.220000
481	812.490000

501	501			
211		50.000000 x	1.186900 =	59.345000
214		3.000000 x	4.160000 =	12.480000
118		3.000000 x	10.001019 =	30.003057
114		8.000000 x	23.886192 =	191.089536
401		1.000000 x	268.420000 =	268.420000

			ΑΘΡΟΙΣΜΑ =	561.337593

			Η.Δ. =	617.471352
502	502			
211		80.000000 x	1.186900 =	94.952000
214		7.000000 x	4.160000 =	29.120000
402		1.000000 x	380.180000 =	380.180000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	735.345612

			Η.Δ. =	808.880173
503	503			
211		110.000000 x	1.186900 =	130.559000
214		10.000000 x	4.160000 =	41.600000
114		8.000000 x	23.886192 =	191.089536
428		1.000000 x	437.840000 =	437.840000
118		4.000000 x	10.001019 =	40.004076

			ΑΘΡΟΙΣΜΑ =	841.092612

			Η.Δ. =	925.201873
504	504			
211		40.000000 x	1.186900 =	47.476000
214		2.000000 x	4.160000 =	8.320000
114		8.000000 x	23.886192 =	191.089536
403		1.000000 x	103.360000 =	103.360000

			ΑΘΡΟΙΣΜΑ =	350.245536

			Η.Δ. =	385.270090
505	505			
211		200.000000 x	1.186900 =	237.380000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
404		1.000000 x	212.730000 =	212.730000
214		10.000000 x	4.160000 =	41.600000

			ΑΘΡΟΙΣΜΑ =	762.807688

			Η.Δ. =	839.088457

506	506			
211		95.000000 x	1.186900 =	112.755500
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
242		2.500000 x	4.500000 =	11.250000
214		6.000000 x	4.160000 =	24.960000
405		1.000000 x	206.720000 =	206.720000

			ΑΘΡΟΙΣΜΑ =	626.783188

			Η.Δ. =	689.461507
507	507			
211		165.000000 x	1.186900 =	195.838500
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
214		10.000000 x	4.160000 =	41.600000
242		7.000000 x	4.500000 =	31.500000
406		1.000000 x	320.980000 =	320.980000

			ΑΘΡΟΙΣΜΑ =	861.016188

			Η.Δ. =	947.117807
508	508			
211		40.000000 x	1.186900 =	47.476000
116		16.000000 x	20.419486 =	326.711776
408		2.000000 x	4.530000 =	9.060000
214		2.000000 x	4.160000 =	8.320000
115		4.000000 x	21.778427 =	87.113708
407		1.000000 x	55.210000 =	55.210000

			ΑΘΡΟΙΣΜΑ =	533.891484

			Η.Δ. =	587.280632
509	509			
211		80.000000 x	1.186900 =	94.952000
117		8.000000 x	16.777917 =	134.223336
409		1.000000 x	126.080000 =	126.080000
214		5.000000 x	4.160000 =	20.800000

			ΑΘΡΟΙΣΜΑ =	376.055336

			Η.Δ. =	413.660870
510	510			
211		80.000000 x	1.186900 =	94.952000
117		8.000000 x	16.777917 =	134.223336
214		5.000000 x	4.160000 =	20.800000
410		1.000000 x	116.530000 =	116.530000

			ΑΘΡΟΙΣΜΑ =	366.505336

			Η.Δ. =	403.155870

511	511			
212		17.000000 x	1.419500 =	24.131500
112		30.000000 x	17.312112 =	519.363360
115		4.000000 x	21.778427 =	87.113708
214		1.000000 x	4.160000 =	4.160000
411		1.000000 x	27.370000 =	27.370000

			ΑΘΡΟΙΣΜΑ =	662.138568

			Η.Δ. =	728.352425
512	512			
211		10.000000 x	1.186900 =	11.869000
112		2.000000 x	17.312112 =	34.624224
115		2.000000 x	21.778427 =	43.556854
214		1.000000 x	4.160000 =	4.160000
412		1.000000 x	2.990000 =	2.990000

			ΑΘΡΟΙΣΜΑ =	97.200078

			Η.Δ. =	106.920086
513	513			
211		15.000000 x	1.186900 =	17.803500
115		3.000000 x	21.778427 =	65.335281
112		3.000000 x	17.312112 =	51.936336
413		1.000000 x	4.530000 =	4.530000
214		1.500000 x	4.160000 =	6.240000

			ΑΘΡΟΙΣΜΑ =	145.845117

			Η.Δ. =	160.429629
514	514			
211		21.000000 x	1.186900 =	24.924900
214		2.000000 x	4.160000 =	8.320000
414		1.000000 x	6.250000 =	6.250000
115		4.000000 x	21.778427 =	87.113708
112		4.000000 x	17.312112 =	69.248448

			ΑΘΡΟΙΣΜΑ =	195.857056

			Η.Δ. =	215.442762
515	515			
211		27.000000 x	1.186900 =	32.046300
115		5.000000 x	21.778427 =	108.892135
214		2.500000 x	4.160000 =	10.400000
112		6.000000 x	17.312112 =	103.872672
415		1.000000 x	8.780000 =	8.780000

			ΑΘΡΟΙΣΜΑ =	263.991107

			Η.Δ. =	290.390218

516	516			
211		33.000000 x	1.186900 =	39.167700
214		3.500000 x	4.160000 =	14.560000
112		8.000000 x	17.312112 =	138.496896
115		6.000000 x	21.778427 =	130.670562
416		1.000000 x	13.540000 =	13.540000

		ΑΘΡΟΙΣΜΑ =		336.435158

		Η.Δ. =		370.078674
517	517			
211		240.000000 x	1.186900 =	284.856000
115		8.000000 x	21.778427 =	174.227416
114		8.000000 x	23.886192 =	191.089536
113		2.000000 x	20.419486 =	40.838972
112		16.000000 x	17.312112 =	276.993792
111		16.000000 x	15.741598 =	251.865568
407		2.000000 x	55.210000 =	110.420000
251		.150000 x	290.000000 =	43.500000
406		1.000000 x	320.980000 =	320.980000
214		8.000000 x	4.160000 =	33.280000
116		8.000000 x	20.419486 =	163.355888
406		.400000 x	320.980000 =	128.392000

		ΑΘΡΟΙΣΜΑ =		2,019.799172

		Η.Δ. =		2,221.779089
518	518			
211		180.000000 x	1.186900 =	213.642000
212		5.000000 x	1.419500 =	7.097500
118		8.000000 x	10.001019 =	80.008152
112		8.000000 x	17.312112 =	138.496896
114		8.000000 x	23.886192 =	191.089536
417		1.000000 x	134.530000 =	134.530000
214		12.000000 x	4.160000 =	49.920000

		ΑΘΡΟΙΣΜΑ =		814.784084

		Η.Δ. =		896.262492
520	520			
211		80.000000 x	1.186900 =	94.952000
118		4.000000 x	10.001019 =	40.004076
115		8.000000 x	21.778427 =	174.227416
112		4.000000 x	17.312112 =	69.248448
419		1.000000 x	4.530000 =	4.530000
214		5.000000 x	4.160000 =	20.800000
212		2.000000 x	1.419500 =	2.839000

		ΑΘΡΟΙΣΜΑ =		406.600940

		Η.Δ. =		447.261034

521	521			
211		40.000000 x	1.186900 =	47.476000
214		3.000000 x	4.160000 =	12.480000
420		1.000000 x	97.290000 =	97.290000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	388.339612

			Η.Δ. =	427.173573
522	522			
211		20.000000 x	1.186900 =	23.738000
214		2.000000 x	4.160000 =	8.320000
118		2.000000 x	10.001019 =	20.002038
114		8.000000 x	23.886192 =	191.089536
421		1.000000 x	32.560000 =	32.560000

			ΑΘΡΟΙΣΜΑ =	275.709574

			Η.Δ. =	303.280531
529	529			
211		70.000000 x	1.186900 =	83.083000
429		1.000000 x	77.590000 =	77.590000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536
214		4.000000 x	4.160000 =	16.640000

			ΑΘΡΟΙΣΜΑ =	408.406612

			Η.Δ. =	449.247273
550	550			
211		90.000000 x	1.186900 =	106.821000
451		4.000000 x	4.870000 =	19.480000
116		32.000000 x	20.419486 =	653.423552
115		4.000000 x	21.778427 =	87.113708
450		1.000000 x	83.850000 =	83.850000
214		4.000000 x	4.160000 =	16.640000

			ΑΘΡΟΙΣΜΑ =	967.328260

			Η.Δ. =	1,064.061086
551	551			
211		95.000000 x	1.186900 =	112.755500
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
452		1.000000 x	103.060000 =	103.060000
214		6.000000 x	4.160000 =	24.960000
405		1.000000 x	206.720000 =	206.720000

			ΑΘΡΟΙΣΜΑ =	718.593188

			Η.Δ. =	790.452507

552	552			
211		18.000000 x	1.186900 =	21.364200
115		8.000000 x	21.778427 =	174.227416
453		1.000000 x	.000000 =	.000000
214		1.000000 x	4.160000 =	4.160000

			ΑΘΡΟΙΣΜΑ =	199.751616

			Η.Δ. =	
553	553			
211		100.000000 x	1.186900 =	118.690000
454		1.000000 x	97.290000 =	97.290000
214		4.000000 x	4.160000 =	16.640000

			ΑΘΡΟΙΣΜΑ =	232.620000

			Η.Δ. =	255.882000
554	554			
455		1.000000 x	31.280000 =	31.280000

			ΑΘΡΟΙΣΜΑ =	31.280000

			Η.Δ. =	34.408000
555	555			
212		17.000000 x	1.419500 =	24.131500
214		1.000000 x	4.160000 =	4.160000
115		4.000000 x	21.778427 =	87.113708
112		32.000000 x	17.312112 =	553.987584
456		1.000000 x	35.040000 =	35.040000

			ΑΘΡΟΙΣΜΑ =	704.432792

			Η.Δ. =	774.876071
556	556			
211		200.000000 x	1.186900 =	237.380000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
457		1.000000 x	457.700000 =	457.700000
214		18.000000 x	4.160000 =	74.880000

			ΑΘΡΟΙΣΜΑ =	1,041.057688

			Η.Δ. =	1,145.163457
557	557			
211		130.000000 x	1.186900 =	154.297000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
458		1.000000 x	285.020000 =	285.020000
214		11.000000 x	4.160000 =	45.760000

			ΑΘΡΟΙΣΜΑ =	756.174688

			Η.Δ. =	831.792157

558	558			
211		200.000000 x	1.186900 =	237.380000
118		8.000000 x	10.001019 =	80.008152
459		1.000000 x	422.050000 =	422.050000
114		8.000000 x	23.886192 =	191.089536
214		12.000000 x	4.160000 =	49.920000
242		9.500000 x	4.500000 =	42.750000

			ΑΘΡΟΙΣΜΑ =	1,023.197688

			Η.Δ. =	1,125.517457
559	559			
211		250.000000 x	1.186900 =	296.725000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
460		1.000000 x	521.890000 =	521.890000
242		12.000000 x	4.500000 =	54.000000
214		15.000000 x	4.160000 =	62.400000

			ΑΘΡΟΙΣΜΑ =	1,206.112688

			Η.Δ. =	1,326.723957
560	560			
211		160.000000 x	1.186900 =	189.904000
214		8.000000 x	4.160000 =	33.280000
461		1.000000 x	239.030000 =	239.030000
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	653.303536

			Η.Δ. =	718.633890
561	561			
211		230.000000 x	1.186900 =	272.987000
214		12.000000 x	4.160000 =	49.920000
114		8.000000 x	23.886192 =	191.089536
462		1.000000 x	348.520000 =	348.520000

			ΑΘΡΟΙΣΜΑ =	862.516536

			Η.Δ. =	948.768190
562	562			
211		50.000000 x	1.186900 =	59.345000
463		1.000000 x	43.800000 =	43.800000
214		2.400000 x	4.160000 =	9.984000

			ΑΘΡΟΙΣΜΑ =	113.129000

			Η.Δ. =	124.441900

563	563				
214		16.000000 x	4.160000 =	66.560000	
464		1.000000 x	383.570000 =	383.570000	
211.1		640.000000 x	.000000 =	.000000	
112		24.000000 x	17.312112 =	415.490688	
114		16.000000 x	23.886192 =	382.179072	
			ΑΘΡΟΙΣΜΑ =	1,247.799760	
			Η.Δ. =		
564	564				
465		1.000000 x	102.610000 =	102.610000	
115		8.000000 x	21.778427 =	174.227416	
567		3.000000 x	400.040472 =	1,200.121416	
115		8.000000 x	21.778427 =	174.227416	
111		8.000000 x	15.741598 =	125.932784	
			ΑΘΡΟΙΣΜΑ =	1,777.119032	
			Η.Δ. =	1,954.830935	
565	565				
450		3.000000 x	83.850000 =	251.550000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	
465		1.000000 x	102.610000 =	102.610000	
			Η.Δ. =	789.728540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	47.860000 =	47.860000	
115		2.000000 x	21.778427 =	43.556854	
112		1.000000 x	17.312112 =	17.312112	
			ΑΘΡΟΙΣΜΑ =	108.728966	
			Η.Δ. =		
567	567				
211		90.000000 x	1.186900 =	106.821000	
214		4.000000 x	4.160000 =	16.640000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
450		1.000000 x	83.850000 =	83.850000	
			ΑΘΡΟΙΣΜΑ =	363.673156	
			Η.Δ. =	400.040472	

568.1	568.1			
214		16.000000 x	4.160000 =	66.560000
467		1.000000 x	348.520000 =	348.520000
113		32.000000 x	20.419486 =	653.423552
114		8.000000 x	23.886192 =	191.089536
118		32.000000 x	10.001019 =	320.032608
567		2.000000 x	400.040472 =	800.080944
512		.240000 x	106.920086 =	25.660821
510		.072000 x	403.155870 =	29.027223

			ΑΘΡΟΙΣΜΑ =	2,434.394683

			Η.Δ. =	2,677.834152
568.2	568.2			
450		2.000000 x	83.850000 =	167.700000
467		1.000000 x	348.520000 =	348.520000
115		8.000000 x	21.778427 =	174.227416
114		8.000000 x	23.886192 =	191.089536

			Η.Δ. =	881.536952
569.1	569.1			
214		16.000000 x	4.160000 =	66.560000
468		1.000000 x	87.280000 =	87.280000
567		2.000000 x	400.040472 =	800.080944
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	1,225.018632

			Η.Δ. =	1,347.520495
569.2	569.2			
450		2.000000 x	83.850000 =	167.700000
115		8.000000 x	21.778427 =	174.227416
114		8.000000 x	23.886192 =	191.089536
468		1.000000 x	87.280000 =	87.280000

			Η.Δ. =	620.296952
570.1	570.1			
211		135.000000 x	1.186900 =	160.231500
469		1.000000 x	87.280000 =	87.280000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536
214		16.000000 x	4.160000 =	66.560000

			ΑΘΡΟΙΣΜΑ =	545.165112

			Η.Δ. =	599.681623

570.2	570.2			
469		1.000000 x	87.280000 =	87.280000
118		4.000000 x	10.001019 =	40.004076
			H.Δ. =	127.284076
571.1	571.1			
211		114.000000 x	1.186900 =	135.306600
214		4.000000 x	4.160000 =	16.640000
114		8.000000 x	23.886192 =	191.089536
470		1.000000 x	70.390000 =	70.390000
			AΘΡΟΙΣΜΑ =	413.426136
			H.Δ. =	454.768750
571.2	571.2			
470		1.000000 x	70.390000 =	70.390000
114		8.000000 x	23.886192 =	191.089536
			H.Δ. =	261.479536
572	572			
211		54.000000 x	1.186900 =	64.092600
114		8.000000 x	23.886192 =	191.089536
471		1.000000 x	61.000000 =	61.000000
111		24.000000 x	15.741598 =	377.798352
407		1.000000 x	55.210000 =	55.210000
214		8.000000 x	4.160000 =	33.280000
			AΘΡΟΙΣΜΑ =	782.470488
			H.Δ. =	860.717537
573	573			
211		54.000000 x	1.186900 =	64.092600
115		16.000000 x	21.778427 =	348.454832
111		24.000000 x	15.741598 =	377.798352
474		.250000 x	35.040000 =	8.760000
474		1.000000 x	35.040000 =	35.040000
473		.250000 x	17.050000 =	4.262500
473		1.000000 x	17.050000 =	17.050000
472		.250000 x	26.510000 =	6.627500
472		1.000000 x	26.510000 =	26.510000
407		.250000 x	55.210000 =	13.802500
407		1.000000 x	55.210000 =	55.210000
214		8.000000 x	4.160000 =	33.280000
			AΘΡΟΙΣΜΑ =	990.888284
			H.Δ. =	1,089.977112

574	574			
211		590.000000 x	1.186900 =	700.271000
214		30.000000 x	4.160000 =	124.800000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
111		16.000000 x	15.741598 =	251.865568
475		1.000000 x	1,970.400000 =	1,970.400000
242		7.000000 x	4.500000 =	31.500000

			ΑΘΡΟΙΣΜΑ =	3,349.934256

			Η.Δ. =	3,684.927682
574.1	574.1			
475		1.000000 x	1,970.400000 =	1,970.400000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536

			Η.Δ. =	2,241.497688
575	575			
211		470.000000 x	1.186900 =	557.843000
476		1.000000 x	85.400000 =	85.400000
214		23.000000 x	4.160000 =	95.680000
115		8.000000 x	21.778427 =	174.227416

			ΑΘΡΟΙΣΜΑ =	913.150416

			Η.Δ. =	1,004.465458
575.1	575.1			
476		1.000000 x	85.400000 =	85.400000
115		8.000000 x	21.778427 =	174.227416

			Η.Δ. =	259.627416
576	576			
477		1.000000 x	6.950000 =	6.950000

			ΑΘΡΟΙΣΜΑ =	6.950000

			Η.Δ. =	7.645000
576.1	576.1			
477		1.000000 x	6.950000 =	6.950000

			Η.Δ. =	6.950000

577	577			
211		70.000000 x	1.186900 =	83.083000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
111		8.000000 x	15.741598 =	125.932784
478		1.000000 x	115.120000 =	115.120000
242		2.000000 x	4.500000 =	9.000000
214		4.000000 x	4.160000 =	16.640000

			ΑΘΡΟΙΣΜΑ =	620.873472

			Η.Δ. =	682.960819
577.1	577.1			
478		1.000000 x	115.120000 =	115.120000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536

			Η.Δ. =	386.217688
578	578			
211		50.000000 x	1.186900 =	59.345000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536
112		4.000000 x	17.312112 =	69.248448
479		1.000000 x	185.200000 =	185.200000
214		5.000000 x	4.160000 =	20.800000
242		5.000000 x	4.500000 =	22.500000

			ΑΘΡΟΙΣΜΑ =	588.187060

			Η.Δ. =	647.005766
579	579			
212		28.000000 x	1.419500 =	39.746000
214		1.000000 x	4.160000 =	4.160000
117		8.000000 x	16.777917 =	134.223336
480		1.000000 x	27.220000 =	27.220000

			ΑΘΡΟΙΣΜΑ =	205.349336

			Η.Δ. =	225.884270
580	580			
211		168.000000 x	1.186900 =	199.399200
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
111		16.000000 x	15.741598 =	251.865568
481		1.000000 x	812.490000 =	812.490000
242		2.000000 x	4.500000 =	9.000000
214		8.000000 x	4.160000 =	33.280000

			ΑΘΡΟΙΣΜΑ =	1,577.132456

			Η.Δ. =	1,734.845702

581	581			
481		1.000000 x	812.490000 =	812.490000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152

			H.Δ. =	1,083.587688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
568.2		.550000 x	881.536952 =	484.845324
569.2		.670000 x	620.296952 =	415.598958
571.2		.150000 x	261.479536 =	39.221930
571.1		.350000 x	454.768750 =	159.169063
570.2		.350000 x	127.284076 =	44.549427
570.1		.150000 x	599.681623 =	89.952243
569.1		.330000 x	1,347.520495 =	444.681763
568.1		.450000 x	2,677.834152 =	1,205.025368
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	400.040472 =	400.040472

			H.Δ. =	3,572.373220
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.250000 x	2,677.834152 =	669.458538
569.1		.250000 x	1,347.520495 =	336.880124
571.2		.240000 x	261.479536 =	62.755089
571.1		.260000 x	454.768750 =	118.239875
570.2		.390000 x	127.284076 =	49.640790
570.1		.110000 x	599.681623 =	65.964979
569.2		.750000 x	620.296952 =	465.222714
568.2		.750000 x	881.536952 =	661.152714
567		1.000000 x	400.040472 =	400.040472
116		8.000000 x	20.419486 =	163.355888

			H.Δ. =	3,118.643966
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.150000 x	2,677.834152 =	401.675123
569.1		.180000 x	1,347.520495 =	242.553689
571.2		.310000 x	261.479536 =	81.058656
571.1		.190000 x	454.768750 =	86.406063
570.2		.420000 x	127.284076 =	53.459312
570.1		.080000 x	599.681623 =	47.974530
569.2		.820000 x	620.296952 =	508.643501
568.2		.850000 x	881.536952 =	749.306409
567		1.000000 x	400.040472 =	400.040472
116		8.000000 x	20.419486 =	163.355888

			H.Δ. =	2,860.406426

613	613			
111		.140000 x	15.741598 =	2.203824
504		.002800 x	385.270090 =	1.078756
503		.000770 x	925.201873 =	.712405
520		.003500 x	447.261034 =	1.565414

			B.T =	5.560399
614	614			
112		.070000 x	17.312112 =	1.211848
503		.000700 x	925.201873 =	.647641
518		.004375 x	896.262492 =	3.921148
509		.004375 x	413.660870 =	1.809766
504		.002800 x	385.270090 =	1.078756

			B.T =	8.669160
621.1	621.1			
213		.100000 x	1.949500 =	.194950
116		.140000 x	20.419486 =	2.858728
504		.003500 x	385.270090 =	1.348445
508		.003500 x	587.280632 =	2.055482
111		.560000 x	15.741598 =	8.815295

			B.T =	15.272900
622	622			
213		.100000 x	1.949500 =	.194950
518		.004340 x	896.262492 =	3.889779
509		.003500 x	413.660870 =	1.447813
508		.003500 x	587.280632 =	2.055482
504		.003500 x	385.270090 =	1.348445
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	13.007046
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.649312 =	55.363258
6314		.382500 x	2.016845 =	.771443
6314		7.650000 x	2.016845 =	15.428864
6330		.038000 x	182.220400 =	6.924375
6330		.190000 x	182.220400 =	34.621876

			B.T =	113.109816
6360.1 A2	6360.1 A2			
6304		.450000 x	5.649312 =	2.542190
6330		.013000 x	182.220400 =	2.368865
6310		2.142000 x	1.440603 =	3.085772

			B.T =	7.996827

6360.1 A3	6360.1 A3			
6304		.960000 x	5.649312 =	5.423340
6310		1.974000 x	1.440603 =	2.843750
6329.2		.037000 x	167.678404 =	6.204101

			B.T =	14.471191
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.649312 =	14.066787
6329.2		.109000 x	167.678404 =	18.276946

			B.T =	32.343733
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
113		.425000 x	20.419486 =	8.678282
6069.1		.056400 x	11.745887 =	.662468

			B.T =	99.519311
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.649312 =	60.165173
6314		.392500 x	2.016845 =	.791612
6330		.205000 x	182.220400 =	37.355182
6330		.041000 x	182.220400 =	7.471036
6314		7.850000 x	2.016845 =	15.832233

			B.T =	121.615236
6360.2 A2	6360.2 A2			
6304		.750000 x	5.649312 =	4.236984
6310		2.383500 x	1.440603 =	3.433677
6330		.019000 x	182.220400 =	3.462188

			B.T =	11.132849
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.649312 =	6.440216
6310		2.341500 x	1.440603 =	3.373172
6329.2		.054000 x	167.678404 =	9.054634

			B.T =	18.868021
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.649312 =	15.818074
6329.2		.118000 x	167.678404 =	19.786052

			B.T =	35.604125

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
6069.1		.059400 x	11.745887 =	.697706
113		2.975000 x	20.419486 =	60.747971
113		.382500 x	20.419486 =	7.810453
			B.T =	113.402016
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.649312 =	78.525437
6330		.270000 x	182.220400 =	49.199508
6314		.557500 x	2.016845 =	1.124391
6330		.054000 x	182.220400 =	9.839902
6314		11.150000 x	2.016845 =	22.487822
			B.T =	161.177059
6360.3 A2	6360.3 A2			
6304		.940000 x	5.649312 =	5.310353
6330		.031000 x	182.220400 =	5.648832
6310		3.360000 x	1.440603 =	4.840426
			B.T =	15.799612
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.649312 =	10.338241
6310		10.678500 x	1.440603 =	15.383479
6329.2		.099000 x	167.678404 =	16.600162
			B.T =	42.321882
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.649312 =	19.320647
6329.2		.139000 x	167.678404 =	23.307298
			B.T =	42.627945
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.745887 =	.866846
113		.340000 x	20.419486 =	6.942625
			B.T =	156.849214

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.649312 =	91.801320
6314		17.700000 x	2.016845 =	35.698157
6330		.075000 x	182.220400 =	13.666530
6330		.375000 x	182.220400 =	68.332650
6314		.885000 x	2.016845 =	1.784908

			B.T =	211.283564
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.649312 =	5.988271
6310		4.641000 x	1.440603 =	6.685839
6330		.048000 x	182.220400 =	8.746579

			B.T =	21.420688
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.649312 =	12.823938
6329.2		.125000 x	167.678404 =	20.959801
6310		20.454000 x	1.440603 =	29.466094

			B.T =	63.249833
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.649312 =	15.818074
6329.2		.118000 x	167.678404 =	19.786052

			B.T =	35.604125
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		4.250000 x	20.419486 =	86.782816
6069.1		.091800 x	11.745887 =	1.078272
113		.297500 x	20.419486 =	6.074797

			B.T =	211.658247
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.649312 =	101.405150
6330		.440000 x	182.220400 =	80.176976
6330		.088000 x	182.220400 =	16.035395
6314		21.000000 x	2.016845 =	42.353745
6314		1.050000 x	2.016845 =	2.117687

			B.T =	242.088954
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.649312 =	6.892161
6330		.061000 x	182.220400 =	11.115444
6310		6.048000 x	1.440603 =	8.712767

			B.T =	26.720372

6360.5 A3	6360.5 A3			
6304		2.480000 x	5.649312 =	14.010294
6329.2		.144000 x	167.678404 =	24.145690
6310		22.291500 x	1.440603 =	32.113202

			B.T =	70.269186
6360.5 A4	6360.5 A4			
6304		3.200000 x	5.649312 =	18.077798
6329.2		.112000 x	167.678404 =	18.779981

			B.T =	36.857780
6360.5 A5	6360.5 A5			
112		9.350000 x	17.312112 =	161.868247
113		5.950000 x	20.419486 =	121.495942
6069.1		.090600 x	11.745887 =	1.064177
113		.255000 x	20.419486 =	5.206969

			B.T =	289.635335
6360.6 A1	6360.6 A1			
6304		20.350000 x	5.649312 =	114.963499
6330		.116000 x	182.220400 =	21.137566
6330		.580000 x	182.220400 =	105.687832
6314		1.245000 x	2.016845 =	2.510972
6314		24.900000 x	2.016845 =	50.219441

			B.T =	294.519310
6360.6 A2	6360.6 A2			
6304		1.530000 x	5.649312 =	8.643447
6310		10.206000 x	1.440603 =	14.702794
6330		.092000 x	182.220400 =	16.764277

			B.T =	40.110518
6360.6 A3	6360.6 A3			
6304		2.670000 x	5.649312 =	15.083663
6329.2		.181000 x	167.678404 =	30.349791
6310		25.798500 x	1.440603 =	37.165396

			B.T =	82.598851
6360.6 A4	6360.6 A4			
6304		2.800000 x	5.649312 =	15.818074
6329.2		.118000 x	167.678404 =	19.786052

			B.T =	35.604125

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	.212500 x	20.419486 =	4.339141
6069.1	.120000 x	11.745887 =	1.409506
113	7.650000 x	20.419486 =	156.209068

B.T = 382.687143

641 641

231	.200000 x	.895000 =	.179000
113	.127500 x	20.419486 =	2.603484
251	.001500 x	290.000000 =	.435000
111	.170000 x	15.741598 =	2.676072
252	.002500 x	290.000000 =	.725000

B.T = 6.618556

651 651

221	150.000000 x	.099900 =	14.985000
224	120.000000 x	.070000 =	8.400000
T 630	.600000 x	1.817641 =	1.090585
T 625	.850000 x	21.923262 =	18.634773
511	.042500 x	728.352425 =	30.954978
509	.003060 x	413.660870 =	1.265802
509	.009435 x	413.660870 =	3.902890
112	.425000 x	17.312112 =	7.357648
111	1.275000 x	15.741598 =	20.070537

B.T = 106.662213

652 652

221	650.000000 x	.099900 =	64.935000
111	1.275000 x	15.741598 =	20.070537
T 630	.320000 x	1.817641 =	.581645
T 625	1.000000 x	21.923262 =	21.923262
511	.042500 x	728.352425 =	30.954978
509	.001632 x	413.660870 =	.675095
509	.009435 x	413.660870 =	3.902890
112	.425000 x	17.312112 =	7.357648

B.T = 150.401055

652.1 652.1

221	450.000000 x	.099900 =	44.955000
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648
T 630	.320000 x	1.817641 =	.581645
T 625	1.060000 x	21.923262 =	23.238658
511	.042500 x	728.352425 =	30.954978
510	.001632 x	403.155870 =	.657950
509	.010001 x	413.660870 =	4.137022

B.T = 131.953439

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
111		1.275000 x	15.741598 =	20.070537
509		.007548 x	413.660870 =	3.122312
112		.425000 x	17.312112 =	7.357648
T 625		.800000 x	21.923262 =	17.538610
T 630		.320000 x	1.817641 =	.581645
511		.042500 x	728.352425 =	30.954978
510		.001632 x	403.155870 =	.657950
			B.T =	170.193680
700	700			
221		13.000000 x	.099900 =	1.298700
397.5		2.150000 x	.000000 =	.000000
113		.935000 x	20.419486 =	19.092219
397.4		4.000000 x	.167500 =	.670000
324		7.650000 x	.580000 =	4.437000
			B.T =	
7001 A	7001 A			
502		.000365 x	808.880173 =	.295241
557		.001094 x	831.792157 =	.909981
			AΘΡΟΙΣΜΑ =	1.205222
	B.T =	.200000 x	1.205222 =	.241044
7001 B	7001 B			
558		.000700 x	1,125.517457 =	.787862
			B.T =	.787862
7001 E	7001 E			
503		.000875 x	925.201873 =	.809552
554		.000875 x	34.408000 =	.030107
			B.T =	.839659
7001 Γ	7001 Γ			
501		.000700 x	617.471352 =	.432230
502		.000700 x	808.880173 =	.566216
			B.T =	.998446

7001 Δ	7001 Δ			
502		.000292 x	808.880173 =	.236193
X 630.1		.060000 x	1.693255 =	.101595
X 630		.060000 x	1.496881 =	.089813
510		.000292 x	403.155870 =	.117722

			AΘΡΟΙΣΜΑ =	.545323
	B.T =	.600000 x	.545323 =	.327194

7003 Α	7003 Α			
502		.000365 x	808.880173 =	.295241
557		.001094 x	831.792157 =	.909981

			AΘΡΟΙΣΜΑ =	1.205222
	B.T =	.100000 x	1.205222 =	.120522

7003 Β	7003 Β			
559		.000464 x	1,326.723957 =	.615600

			B.T =	.615600
7003 Γ	7003 Γ			
502		.000700 x	808.880173 =	.566216

			B.T =	.566216
7003 Δ	7003 Δ			
502		.000875 x	808.880173 =	.707770
562		.000875 x	124.441900 =	.108887

			B.T =	.816657
7005 Α	7005 Α			
502		.000365 x	808.880173 =	.295241
557		.001094 x	831.792157 =	.909981

			AΘΡΟΙΣΜΑ =	1.205222
	B.T =	.100000 x	1.205222 =	.120522

7005 Β	7005 Β			
559		.000812 x	1,326.723957 =	1.077300

			B.T =	1.077300
7005 Ε	7005 Ε			
502		.000875 x	808.880173 =	.707770
562		.000875 x	124.441900 =	.108887

			B.T =	.816657

7005 Γ	7005 Γ			
559		.000232 x	1,326.723957 =	.307800

			B.T =	.307800
7005 Δ	7005 Δ			
502		.000700 x	808.880173 =	.566216

			B.T =	.566216
7010 Α	7010 Α			
558		.000315 x	1,125.517457 =	.354538

			B.T =	.354538
7010 Β	7010 Β			
558		.000473 x	1,125.517457 =	.532370

			B.T =	.532370
7010 Ε	7010 Ε			
503		.000875 x	925.201873 =	.809552
553		.000875 x	255.882000 =	.223897

			B.T =	1.033448
7010 Γ	7010 Γ			
502		.000700 x	808.880173 =	.566216

			B.T =	.566216
7010 Δ	7010 Δ			
502		.000292 x	808.880173 =	.236193
X 630		.060000 x	1.496881 =	.089813
510		.000292 x	403.155870 =	.117722
X 630.1		.060000 x	1.693255 =	.101595

			AΘΡΟΙΣΜΑ =	.545323
	B.T =	.600000 x	.545323 =	.327194

7016.1	7016.1			
223		350.000000 x	.119300 =	41.755000
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.830000 x	18.647423 =	15.477361
T 617		.500000 x	6.433490 =	3.216745
509		.007831 x	413.660870 =	3.239378
509		.004718 x	413.660870 =	1.951652

			B.T =	78.998570

7016.2	7016.2			
570.1		.586500 x	599.681623 =	351.713272
570.2		1.113500 x	127.284076 =	141.730819
571.1		.586500 x	454.768750 =	266.721872
571.2		1.113500 x	261.479536 =	291.157463

			AΘΡΟΙΣΜΑ =	1,051.323426
	B.T =	.025000 x	1,051.323426 =	26.283086

7016.3	7016.3			
564		.212500 x	1,954.830935 =	415.401574
565		.637500 x	789.728540 =	503.451944

			AΘΡΟΙΣΜΑ =	918.853518
	B.T =	.025000 x	918.853518 =	22.971338

7016.4	7016.4			
7016.1		1.000000 x	78.998570 =	78.998570
7016.3		1.000000 x	22.971338 =	22.971338
7016.2		1.000000 x	26.283086 =	26.283086

			B.T =	128.252994
7016.5	7016.5			
7016.4		.200000 x	128.252994 =	25.650599

			B.T =	25.650599
7016.6	7016.6			
7016.4		.250000 x	128.252994 =	32.063249
7016.5		.250000 x	25.650599 =	6.412650

			B.T =	38.475898
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
223		350.000000 x	.119300 =	41.755000
509		.004718 x	413.660870 =	1.951652
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.830000 x	18.647423 =	15.477361
T 617		.500000 x	6.433490 =	3.216745
509		.007831 x	413.660870 =	3.239378
396.5		10.500000 x	1.180000 =	12.390000

			B.T =	78.998570
7017.2	7017.2			
564		.425000 x	1,954.830935 =	830.803147
565		.425000 x	789.728540 =	335.634630

			AΘΡΟΙΣΜΑ =	1,166.437777
	B.T =	.012500 x	1,166.437777 =	14.580472

7017.3	7017.3			
7017.1		1.000000 x	78.998570 =	78.998570
7017.2		1.000000 x	14.580472 =	14.580472

			B.T =	93.579042
7017.4	7017.4			
7017.3		.200000 x	93.579042 =	18.715808

			B.T =	18.715808
7017.5	7017.5			
7017.3		.300000 x	93.579042 =	28.073713
7017.4		.300000 x	18.715808 =	5.614742

			B.T =	33.688455
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689

			B.T =	52.069689

7019 A1	7019 A1			
223		350.000000 x	.119300 =	41.755000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
509		.004718 x	413.660870 =	1.951652
509		.007548 x	413.660870 =	3.122312
396.5		5.000000 x	1.180000 =	5.900000
			B.T =	79.576968
7019 A2	7019 A2			
555		.012143 x	774.876071 =	9.409320
			B.T =	9.409320
7019 A3	7019 A3			
570.1		.850000 x	599.681623 =	509.729380
571.2		.850000 x	261.479536 =	222.257606
571.1		.850000 x	454.768750 =	386.553438
570.2		.850000 x	127.284076 =	108.191465
			ΑΘΡΟΙΣΜΑ =	1,226.731887
	B.T =	.014286 x	1,226.731887 =	17.525092
7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563
			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	79.576968 =	79.576968
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A5		1.000000 x	17.356563 =	17.356563
7019 A3		1.000000 x	17.525092 =	17.525092
7019 A2		1.000000 x	9.409320 =	9.409320
			B.T =	193.105397
7019 A7	7019 A7			
7019 A6		.100000 x	193.105397 =	19.310540
			B.T =	19.310540

710	710			
252		.001000 x	290.000000 =	.290000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
397.3		.006660 x	.000000 =	.000000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	385.270090 =	1.935982
509		.003750 x	413.660870 =	1.551228

			B.T =	3.487210
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
503		.001190 x	925.201873 =	1.100990
520		.005270 x	447.261034 =	2.357066
504		.004250 x	385.270090 =	1.637398

			B.T =	6.433490
T 621	T 621			
213		.100000 x	1.949500 =	.194950
111		.680000 x	15.741598 =	10.704287
508		.004250 x	587.280632 =	2.495943
116		.170000 x	20.419486 =	3.471313

			B.T =	16.866492
T 623	T 623			
213		.100000 x	1.949500 =	.194950
116		.170000 x	20.419486 =	3.471313
112		.085000 x	17.312112 =	1.471530
504		.004250 x	385.270090 =	1.637398
508		.004250 x	587.280632 =	2.495943
509		.004250 x	413.660870 =	1.758059
518		.008500 x	896.262492 =	7.618231

			B.T =	18.647423

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
509		.004250 x	413.660870 =	1.758059
518		.012155 x	896.262492 =	10.894071
508		.004250 x	587.280632 =	2.495943
504		.004250 x	385.270090 =	1.637398
			B.T =	21.923262
T 630	T 630			
512		.017000 x	106.920086 =	1.817641
			B.T =	1.817641
T 630.1	T 630.1			
510		.005100 x	403.155870 =	2.056095
			B.T =	2.056095
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678
			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
520		.004340 x	447.261034 =	1.941113
504		.003500 x	385.270090 =	1.348445
503		.000980 x	925.201873 =	.906698
			B.T =	5.298168
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	587.280632 =	2.055482
111		.560000 x	15.741598 =	8.815295
116		.140000 x	20.419486 =	2.858728
			B.T =	13.924455
X 623	X 623			
213		.100000 x	1.949500 =	.194950
504		.003500 x	385.270090 =	1.348445
518		.007000 x	896.262492 =	6.273837
509		.003500 x	413.660870 =	1.447813
508		.003500 x	587.280632 =	2.055482
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848
			B.T =	15.391104

X 625	X 625			
213		.100000 x	1.949500 =	.194950
509		.003500 x	413.660870 =	1.447813
518		.010010 x	896.262492 =	8.971588
504		.003500 x	385.270090 =	1.348445
508		.003500 x	587.280632 =	2.055482
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848
			B.T =	18.088854
X 630	X 630			
512		.014000 x	106.920086 =	1.496881
			B.T =	1.496881
X 630.1	X 630.1			
510		.004200 x	403.155870 =	1.693255
			B.T =	1.693255
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	413.660870 =	1.951652
T 623		.800000 x	18.647423 =	14.917938
511		.034000 x	728.352425 =	24.763982
509		.007548 x	413.660870 =	3.122312
509		.001275 x	413.660870 =	.527418
T 625		.500000 x	21.923262 =	10.961631
641		3.000000 x	6.618556 =	19.855668
T 630		.250000 x	1.817641 =	.454410
			T.E =	154.896926
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	413.660870 =	8.016748
			T.E =	74.918539
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	413.660870 =	3.340312
			T.E =	43.481386
6051	6051			
502		.000175 x	808.880173 =	.141554
			T.E =	.141554

6052	6052			
501		.000117 x	617.471352 =	.072244
521		.000088 x	427.173573 =	.037591
502		.000088 x	808.880173 =	.071181

			T.E =	.181017
6053	6053			
502		.000318 x	808.880173 =	.257224
507		.001000 x	947.117807 =	.947118

			T.E =	1.204342
6054	6054			
112		.004900 x	17.312112 =	.084829
507		.001077 x	947.117807 =	1.020046
509		.002975 x	413.660870 =	1.230641

			T.E =	2.335516
6055	6055			
213		.400000 x	1.949500 =	.779800
508		.007000 x	587.280632 =	4.110964
504		.001400 x	385.270090 =	.539378
503		.001167 x	925.201873 =	1.079711
116		.280000 x	20.419486 =	5.717456
112		.490000 x	17.312112 =	8.482935

			T.E =	20.710244
6056	6056			
507		.001750 x	947.117807 =	1.657456

			T.E =	1.657456
6057	6057			
506		.087500 x	689.461507 =	60.327882

			T.E =	60.327882
6058	6058			
507		.087500 x	947.117807 =	82.872808

			T.E =	82.872808
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
509		.002975 x	413.660870 =	1.230641
507		.001077 x	947.117807 =	1.020046
502		.001400 x	808.880173 =	1.132432
501		.000583 x	617.471352 =	.359986

			T.E =	3.864290
6062	6062			
213		.400000 x	1.949500 =	.779800
507		.001400 x	947.117807 =	1.325965
509		.002800 x	413.660870 =	1.158250
508		.002800 x	587.280632 =	1.644386
112		.175000 x	17.312112 =	3.029620
502		.002000 x	808.880173 =	1.617760
116		.175000 x	20.419486 =	3.573410

			T.E =	13.129191
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.140000 x	17.312112 =	2.423696
509		.003641 x	413.660870 =	1.506139
112		.070000 x	17.312112 =	1.211848
112		.070000 x	17.312112 =	1.211848

			T.E =	18.472009
6064	6064			
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696
507		.014000 x	947.117807 =	13.259649
509		.003641 x	413.660870 =	1.506139

			T.E =	18.401332
6065	6065			
506		.002800 x	689.461507 =	1.930492
506		.002100 x	689.461507 =	1.447869

			T.E =	3.378361

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	808.880173 =	.566216

			T.E =	1.668128
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630		.100000 x	1.496881 =	.149688
X 630.1		.100000 x	1.693255 =	.169326

			T.E =	15.745780
6068	6068			
111		.560000 x	15.741598 =	8.815295
112		.560000 x	17.312112 =	9.694783
X 630.1		.200000 x	1.693255 =	.338651
X 630		.200000 x	1.496881 =	.299376
622		1.351351 x	13.007046 =	17.577085
509		.016497 x	413.660870 =	6.824163

			T.E =	43.549353
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
509		.016497 x	413.660870 =	6.824163
112		.560000 x	17.312112 =	9.694783
614		1.351351 x	8.669160 =	11.715078
X 630.1		.200000 x	1.693255 =	.338651
X 630		.200000 x	1.496881 =	.299376

			T.E =	37.687346
6069	6069			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	413.660870 =	4.970963
X 625		1.050000 x	18.088854 =	18.993297

			T.E =	25.176107
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
X 617		1.050000 x	5.298168 =	5.563076
509		.012017 x	413.660870 =	4.970963

			T.E =	11.745887
6070	6070			
501		.000467 x	617.471352 =	.288359

			T.E =	.288359

6071	6071			
504		.002333 x	385.270090 =	.898835
509		.002975 x	413.660870 =	1.230641

			T.E =	2.129476
6072	6072			
504		.003500 x	385.270090 =	1.348445
509		.002800 x	413.660870 =	1.158250

			T.E =	2.506696
6073	6073			
509		.000833 x	413.660870 =	.344580

			T.E =	.344580
6074	6074			
509		.000784 x	413.660870 =	.324310

			T.E =	.324310
6075	6075			
509		.001096 x	413.660870 =	.453372

			T.E =	.453372
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	925.201873 =	.647641
507		.000840 x	947.117807 =	.795579
509		.003914 x	413.660870 =	1.619069

			T.E =	3.147118
6077	6077			
503		.001400 x	925.201873 =	1.295283

			T.E =	1.295283
6078	6078			
112		.004900 x	17.312112 =	.084829
501		.000056 x	617.471352 =	.034578
505		.001400 x	839.088457 =	1.174724
503		.000350 x	925.201873 =	.323821

			T.E =	1.617952

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
556		.001400 x	1,145.163457 =	1.603229
503		.000350 x	925.201873 =	.323821
501		.000056 x	617.471352 =	.034578

			T.E =	2.046457
6079	6079			
112		.014000 x	17.312112 =	.242370
529		.000980 x	449.247273 =	.440262
X 630		.150000 x	1.496881 =	.224532
509		.000630 x	413.660870 =	.260606
502		.000350 x	808.880173 =	.283108
501		.000700 x	617.471352 =	.432230

			T.E =	1.883108
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.693255 =	.169326
529		.000700 x	449.247273 =	.314473
502		.000292 x	808.880173 =	.236193
X 630		.100000 x	1.496881 =	.149688
501		.000583 x	617.471352 =	.359986

			T.E =	1.472035
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
506		.007000 x	689.461507 =	4.826231
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087

			T.E =	23.556180
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
6081.1		1.000000 x	23.556180 =	23.556180
112		.070000 x	17.312112 =	1.211848

			T.E =	35.787146
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
112		.140000 x	17.312112 =	2.423696
6081.1		1.000000 x	23.556180 =	23.556180

			T.E =	48.018113

6081.4	6081.4				
111		2.100000 x	15.741598 =	33.057356	
112		.210000 x	17.312112 =	3.635544	
6081.1		1.000000 x	23.556180 =	23.556180	

			T.E =	60.249079	
6082.1	6082.1				
213		.400000 x	1.949500 =	.779800	
116		.700000 x	20.419486 =	14.293640	
116		1.400000 x	20.419486 =	28.587280	
111		1.400000 x	15.741598 =	22.038237	
508		.070000 x	587.280632 =	41.109644	

			T.E =	106.808602	
6082.2	6082.2				
111		.700000 x	15.741598 =	11.019119	
112		.140000 x	17.312112 =	2.423696	
6082.1		1.000000 x	106.808602 =	106.808602	

			T.E =	120.251416	
6082.3	6082.3				
111		1.400000 x	15.741598 =	22.038237	
112		.280000 x	17.312112 =	4.847391	
6082.1		1.000000 x	106.808602 =	106.808602	

			T.E =	133.694231	
6082.4	6082.4				
111		2.100000 x	15.741598 =	33.057356	
6082.1		1.000000 x	106.808602 =	106.808602	
112		.420000 x	17.312112 =	7.271087	

			T.E =	147.137045	
6083.1	6083.1				
111		.280000 x	15.741598 =	4.407647	
112		.140000 x	17.312112 =	2.423696	
112		.280000 x	17.312112 =	4.847391	
506		.005833 x	689.461507 =	4.021629	

			T.E =	15.700363	
6083.2	6083.2				
111		.560000 x	15.741598 =	8.815295	
112		.070000 x	17.312112 =	1.211848	
6083.1		1.000000 x	15.700363 =	15.700363	

			T.E =	25.727506	

6083.3	6083.3				
111		1.120000 x	15.741598 =	17.630590	
112		.140000 x	17.312112 =	2.423696	
6083.1		1.000000 x	15.700363 =	15.700363	

			T.E =	35.754648	
6083.4	6083.4				
111		1.680000 x	15.741598 =	26.445885	
6083.1		1.000000 x	15.700363 =	15.700363	
112		.210000 x	17.312112 =	3.635544	

			T.E =	45.781791	
6084.1	6084.1				
213		.400000 x	1.949500 =	.779800	
116		1.050000 x	20.419486 =	21.440460	
508		.035000 x	587.280632 =	20.554822	
116		.700000 x	20.419486 =	14.293640	
111		1.470000 x	15.741598 =	23.140149	

			T.E =	80.208872	
6084.2	6084.2				
111		.560000 x	15.741598 =	8.815295	
112		.105000 x	17.312112 =	1.817772	
6084.1		1.000000 x	80.208872 =	80.208872	

			T.E =	90.841939	
6084.3	6084.3				
111		1.120000 x	15.741598 =	17.630590	
6084.1		1.000000 x	80.208872 =	80.208872	
112		.210000 x	17.312112 =	3.635544	

			T.E =	101.475005	
6084.4	6084.4				
111		1.680000 x	15.741598 =	26.445885	
6084.1		1.000000 x	80.208872 =	80.208872	
112		.315000 x	17.312112 =	5.453315	

			T.E =	112.108072	
6085.1	6085.1				
111		.140000 x	15.741598 =	2.203824	
112		.140000 x	17.312112 =	2.423696	
506		.004666 x	689.461507 =	3.217027	
502		.001400 x	808.880173 =	1.132432	

			T.E =	8.976979	

6085.2	6085.2				
111		.350000 x	15.741598 =	5.509559	
112		.070000 x	17.312112 =	1.211848	
6085.1		1.000000 x	8.976979 =	8.976979	
			T.E =	15.698386	
6085.3	6085.3				
111		.700000 x	15.741598 =	11.019119	
6085.1		1.000000 x	8.976979 =	8.976979	
112		.140000 x	17.312112 =	2.423696	
			T.E =	22.419793	
6085.4	6085.4				
111		1.050000 x	15.741598 =	16.528678	
6085.1		1.000000 x	8.976979 =	8.976979	
112		.210000 x	17.312112 =	3.635544	
			T.E =	29.141200	
6086.1	6086.1				
213		.400000 x	1.949500 =	.779800	
111		1.120000 x	15.741598 =	17.630590	
116		.280000 x	20.419486 =	5.717456	
508		.008750 x	587.280632 =	5.138706	
116		.490000 x	20.419486 =	10.005548	
			T.E =	39.272100	
6086.2	6086.2				
111		.350000 x	15.741598 =	5.509559	
6086.1		1.000000 x	39.272100 =	39.272100	
112		.105000 x	17.312112 =	1.817772	
			T.E =	46.599431	
6086.3	6086.3				
111		.700000 x	15.741598 =	11.019119	
6086.1		1.000000 x	39.272100 =	39.272100	
112		.210000 x	17.312112 =	3.635544	
			T.E =	53.926762	
6086.4	6086.4				
111		1.050000 x	15.741598 =	16.528678	
112		.315000 x	17.312112 =	5.453315	
6086.1		1.000000 x	39.272100 =	39.272100	
			T.E =	61.254093	

6087	6087			
252		.001000 x	290.000000 =	.290000
113		.210000 x	20.419486 =	4.288092
111		.210000 x	15.741598 =	3.305736
112		.350000 x	17.312112 =	6.059239
			T.E =	13.943067
6088	6088			
6081.1		1.000000 x	23.556180 =	23.556180
6081.1		.900000 x	23.556180 =	21.200562
			T.E =	44.756742
6089	6089			
6082.1		1.000000 x	106.808602 =	106.808602
6082.1		.900000 x	106.808602 =	96.127742
			T.E =	202.936344
6090	6090			
6083.1		1.000000 x	15.700363 =	15.700363
6083.1		1.300000 x	15.700363 =	20.410472
			T.E =	36.110835
6091	6091			
6084.1		1.000000 x	80.208872 =	80.208872
6084.1		1.300000 x	80.208872 =	104.271534
			T.E =	184.480406
6100	6100			
231		.200000 x	.895000 =	.179000
113		.105000 x	20.419486 =	2.144046
111		.175000 x	15.741598 =	2.754780
252.1		.002000 x	.000000 =	.000000
251		.002000 x	290.000000 =	.580000
			T.E =	
6101	6101			
231		15.000000 x	.895000 =	13.425000
112		3.500000 x	17.312112 =	60.592392
113		3.500000 x	20.419486 =	71.468201
252.1		.020000 x	.000000 =	.000000
252		.018000 x	290.000000 =	5.220000
251		.068000 x	290.000000 =	19.720000
			T.E =	

6102	6102			
244		1.000000 x	2.700000 =	2.700000
506		.000070 x	689.461507 =	.048262
509		.000051 x	413.660870 =	.021097
506		.000070 x	689.461507 =	.048262
112		.001400 x	17.312112 =	.024237
112		.002100 x	17.312112 =	.036355

			T.E =	2.878214
6103	6103			
244		.125000 x	2.700000 =	.337500
509		.000102 x	413.660870 =	.042193
506		.000140 x	689.461507 =	.096525
506		.000140 x	689.461507 =	.096525
112		.004200 x	17.312112 =	.072711
112		.002800 x	17.312112 =	.048474

			T.E =	.693927
6104	6104			
236		3.000000 x	.673000 =	2.019000
113		.280000 x	20.419486 =	5.717456
111		.280000 x	15.741598 =	4.407647
517		.017500 x	2,221.779089 =	38.881134

			T.E =	51.025238
6105	6105			
111		.210000 x	15.741598 =	3.305736
113		.140000 x	20.419486 =	2.858728
517		.014000 x	2,221.779089 =	31.104907

			T.E =	37.269371
6106	6106			
512		.087500 x	106.920086 =	9.355508

			T.E =	9.355508
6107	6107			
513		.087500 x	160.429629 =	14.037593

			T.E =	14.037593
6108	6108			
514		.087500 x	215.442762 =	18.851242

			T.E =	18.851242

6109	6109			
515		.087500 x	290.390218 =	25.409144

			T.E =	25.409144
6110	6110			
516		.087500 x	370.078674 =	32.381884

			T.E =	32.381884
6120	6120			
112		.004200 x	17.312112 =	.072711
502		.001750 x	808.880173 =	1.415540
501		.000070 x	617.471352 =	.043223

			T.E =	1.531474
6121	6121			
112		.004200 x	17.312112 =	.072711
509		.003113 x	413.660870 =	1.287726
507		.000875 x	947.117807 =	.828728
505		.000420 x	839.088457 =	.352417
502		.000315 x	808.880173 =	.254797
501		.000049 x	617.471352 =	.030256

			T.E =	2.826636
6151	6151			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000

			T.E =	2.640000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
T 611		1.050000 x	20.070537 =	21.074064
509		.003570 x	413.660870 =	1.476769
112		.425000 x	17.312112 =	7.357648

			T.E =	36.598660

6154	6154			
111		.425000 x	15.741598 =	6.690179
T 621		1.050000 x	16.866492 =	17.709817
509		.003570 x	413.660870 =	1.476769
112		.425000 x	17.312112 =	7.357648

			T.E =	33.234413
6155	6155			
111		.680000 x	15.741598 =	10.704287
652		.100000 x	150.401055 =	15.040106
113		1.275000 x	20.419486 =	26.034845
T 621		.350000 x	16.866492 =	5.903272
509		.003220 x	413.660870 =	1.331988

			T.E =	59.014497
6156	6156			
251		.000500 x	290.000000 =	.145000
652		.010000 x	150.401055 =	1.504011
113		.680000 x	20.419486 =	13.885250
112		.425000 x	17.312112 =	7.357648

			T.E =	22.891909
6157	6157			
111		.420000 x	15.741598 =	6.611471
X 621		1.050000 x	13.924455 =	14.620678
509		.002940 x	413.660870 =	1.216163
112		.420000 x	17.312112 =	7.271087

			T.E =	29.719399
6157.1	6157.1			
111		.420000 x	15.741598 =	6.611471
112		.420000 x	17.312112 =	7.271087
X 611		1.050000 x	16.528678 =	17.355112
509		.002940 x	413.660870 =	1.216163

			T.E =	32.453833
6158	6158			
111		.560000 x	15.741598 =	8.815295
621.1		1.050000 x	15.272900 =	16.036545
504		.001400 x	385.270090 =	.539378
509		.002940 x	413.660870 =	1.216163

			T.E =	26.607381

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	27.291284	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.991284	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	35.991284	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	39.691284	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
113		.637500 x	20.419486 =	13.017422	
111		.850000 x	15.741598 =	13.380358	

			T.E =	62.697781	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	81.897781	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	101.797781	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
111		.255000 x	15.741598 =	4.014107
113		.170000 x	20.419486 =	3.471313

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	18.088854 =	12.662198
X 623		.400000 x	15.391104 =	6.156442
509		.005439 x	413.660870 =	2.249901
509		.003108 x	413.660870 =	1.285658
112		.420000 x	17.312112 =	7.271087

			T.E =	32.931021
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
613		1.050000 x	5.560399 =	5.838419
509		.008702 x	413.660870 =	3.599677

			T.E =	20.014918

6205	6205			
111		.210000 x	15.741598 =	3.305736
613		1.000000 x	5.560399 =	5.560399
509		.002800 x	413.660870 =	1.158250
112		.070000 x	17.312112 =	1.211848

			T.E =	11.236233
6251	6251			
509		.002800 x	413.660870 =	1.158250
613		1.000000 x	5.560399 =	5.560399

			T.E =	6.718649
6252	6252			
509		.000784 x	413.660870 =	.324310

			T.E =	.324310
6253	6253			
112		.210000 x	17.312112 =	3.635544
X 630		.200000 x	1.496881 =	.299376
X 630.1		.200000 x	1.693255 =	.338651
501		.002917 x	617.471352 =	1.801164
521		.007000 x	427.173573 =	2.990215

			T.E =	9.064950
6301	6301			
231		.200000 x	.895000 =	.179000
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
113		.127500 x	20.419486 =	2.603484
111		.170000 x	15.741598 =	2.676072

			T.E =	6.618556
6302	6302			
231		.300000 x	.895000 =	.268500
252		.004000 x	290.000000 =	1.160000
111		.212500 x	15.741598 =	3.345090
251		.002000 x	290.000000 =	.580000
113		1.232500 x	20.419486 =	25.167016

			T.E =	30.520606
6303	6303			
6302		.666660 x	30.520606 =	20.346867

			T.E =	20.346867

6304	6304			
234.2		.018000 x	1.006500 =	.018117
235		.012000 x	.703000 =	.008436
113		.085000 x	20.419486 =	1.735656
113		.010200 x	20.419486 =	.208279
112		.212500 x	17.312112 =	3.678824

			T.E =	5.649312
6310	6310			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6311	6311			
233.1		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603
6312	6312			
233.3		1.010000 x	8.200000 =	8.282000
113		.085000 x	20.419486 =	1.735656
113		.085000 x	20.419486 =	1.735656
233.3		.303000 x	8.200000 =	2.484600

			T.E =	14.237913
6313	6313			
233.2		1.050000 x	.598400 =	.628320
113		.025500 x	20.419486 =	.520697

			T.E =	1.149017
6314	6314			
233.2		1.050000 x	.598400 =	.628320
113		.068000 x	20.419486 =	1.388525

			T.E =	2.016845
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	20.419486 =	.017357

			T.E =	1.417357

6320.2	6320.2				
396.2		1.000000 x	.770000 =		.770000
113		.000850 x	20.419486 =		.017357
				T.E =	.787357
6320.3	6320.3				
396.3		1.000000 x	1.680000 =		1.680000
113		.000850 x	20.419486 =		.017357
				T.E =	1.697357
6320.4	6320.4				
396.4		1.000000 x	.980000 =		.980000
113		.000850 x	20.419486 =		.017357
				T.E =	.997357
6320.5	6320.5				
396.5		1.000000 x	1.180000 =		1.180000
113		.000850 x	20.419486 =		.017357
				T.E =	1.197357
6320.6	6320.6				
396.6		1.000000 x	1.580000 =		1.580000
113		.000850 x	20.419486 =		.017357
				T.E =	1.597357
6321	6321				
221		140.000000 x	.099900 =		13.986000
111		.765000 x	15.741598 =		12.042322
T 630.1		.175000 x	2.056095 =		.359817
T 630		.175000 x	1.817641 =		.318087
T 625		.350000 x	21.923262 =		7.673142
T 623		.560000 x	18.647423 =		10.442557
T 621		.300000 x	16.866492 =		5.059948
511		.023800 x	728.352425 =		17.334788
509		.003019 x	413.660870 =		1.248842
509		.003302 x	413.660870 =		1.365908
509		.005284 x	413.660870 =		2.185784
113		.595000 x	20.419486 =		12.149594
112		.714000 x	17.312112 =		12.360848
				T.E =	96.527637

6322	6322			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
509		.003019 x	413.660870 =	1.248842
T 630.1		.175000 x	2.056095 =	.359817
T 630		.175000 x	1.817641 =	.318087
T 625		.350000 x	21.923262 =	7.673142
T 623		.560000 x	18.647423 =	10.442557
T 611		.300000 x	20.070537 =	6.021161
511		.023800 x	728.352425 =	17.334788
509		.003302 x	413.660870 =	1.365908
509		.005284 x	413.660870 =	2.185784
113		.595000 x	20.419486 =	12.149594
112		.714000 x	17.312112 =	12.360848

			T.E =	97.488850
6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.034000 x	728.352425 =	24.763982
113		.850000 x	20.419486 =	17.356563
509		.004718 x	413.660870 =	1.951652
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
509		.007548 x	413.660870 =	3.122312
112		1.020000 x	17.312112 =	17.658354

			T.E =	106.685867
6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
509		.007548 x	413.660870 =	3.122312
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

			T.E =	98.940981

6324	6324			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
113		.850000 x	20.419486 =	17.356563
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	413.660870 =	3.122312

			T.E =	111.680867
6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
509		.007548 x	413.660870 =	3.122312
112		1.020000 x	17.312112 =	17.658354
113		.850000 x	20.419486 =	17.356563

			T.E =	103.935981
6325	6325			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.034000 x	728.352425 =	24.763982
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

			T.E =	116.675867

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
509		.007548 x	413.660870 =	3.122312
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 108.930981

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
113		1.360000 x	20.419486 =	27.770501
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	413.660870 =	3.122312

T.E = 135.027864

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
509		.007548 x	413.660870 =	3.122312
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501

T.E = 127.282978

6327	6327				
222		300.000000 x	.116200 =	34.860000	
T 630.1		.250000 x	2.056095 =	.514024	
T 630		.250000 x	1.817641 =	.454410	
511		.034000 x	728.352425 =	24.763982	
509		.007548 x	413.660870 =	3.122312	
509		.004718 x	413.660870 =	1.951652	
T 625		.500000 x	21.923262 =	10.961631	
T 623		.800000 x	18.647423 =	14.917938	
113		1.275000 x	20.419486 =	26.034845	
112		2.295000 x	17.312112 =	39.731297	

			T.E =	157.312092	
6327.1	6327.1				
222		300.000000 x	.116200 =	34.860000	
T 630.1		.250000 x	2.056095 =	.514024	
T 630		.250000 x	1.817641 =	.454410	
T 623		.800000 x	18.647423 =	14.917938	
T 617		.500000 x	6.433490 =	3.216745	
511		.034000 x	728.352425 =	24.763982	
509		.004718 x	413.660870 =	1.951652	
509		.007548 x	413.660870 =	3.122312	
113		1.275000 x	20.419486 =	26.034845	
112		2.295000 x	17.312112 =	39.731297	

			T.E =	149.567206	
6328	6328				
221		350.000000 x	.099900 =	34.965000	
509		.004718 x	413.660870 =	1.951652	
113		1.445000 x	20.419486 =	29.506157	
112		2.295000 x	17.312112 =	39.731297	
T 630.1		.250000 x	2.056095 =	.514024	
T 630		.250000 x	1.817641 =	.454410	
T 625		.500000 x	21.923262 =	10.961631	
T 623		.800000 x	18.647423 =	14.917938	
511		.034000 x	728.352425 =	24.763982	
509		.007548 x	413.660870 =	3.122312	

			T.E =	160.888404	

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	413.660870 =	1.951652
511		.034000 x	728.352425 =	24.763982
T 617		.500000 x	6.433490 =	3.216745
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
509		.007548 x	413.660870 =	3.122312

			T.E =	153.143518
6329	6329			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	17.312112 =	39.731297
T 623		.800000 x	18.647423 =	14.917938
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 625		.500000 x	21.923262 =	10.961631
509		.007548 x	413.660870 =	3.122312
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
113		1.445000 x	20.419486 =	29.506157

			T.E =	166.593404
6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

			T.E =	158.848518

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.034000 x	728.352425 =	24.763982
509		.004718 x	413.660870 =	1.951652
113		1.445000 x	20.419486 =	29.506157
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	413.660870 =	3.122312

T.E = 167.678404

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

T.E = 159.933518

6330	6330			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
511		.042500 x	728.352425 =	30.954978
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 182.220400

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.042500 x	728.352425 =	30.954978
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297
			T.E =	174.475514
6331	6331			
222		450.000000 x	.116200 =	52.290000
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181
113		5.525000 x	20.419486 =	112.817660
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
511		.042500 x	728.352425 =	30.954978
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
			T.E =	347.057399
6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181
509		.007548 x	413.660870 =	3.122312
511		.042500 x	728.352425 =	30.954978
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
509		.004718 x	413.660870 =	1.951652
113		5.525000 x	20.419486 =	112.817660
			T.E =	339.312513

6351	6351			
221		120.000000 x	.099900 =	11.988000
T 623		.850000 x	18.647423 =	15.850310
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 625		.450000 x	21.923262 =	9.865468
509		.008020 x	413.660870 =	3.317560
511		.034000 x	728.352425 =	24.763982
509		.004246 x	413.660870 =	1.756404
112		1.275000 x	17.312112 =	22.072943
113		1.275000 x	20.419486 =	26.034845

			T.E =	123.236502
6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.850000 x	18.647423 =	15.850310
T 617		.450000 x	6.433490 =	2.895071
511		.034000 x	728.352425 =	24.763982
509		.008020 x	413.660870 =	3.317560
509		.004246 x	413.660870 =	1.756404
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

			T.E =	116.266104
6352	6352			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
509		.007548 x	413.660870 =	3.122312
509		.004718 x	413.660870 =	1.951652
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 625		.500000 x	21.923262 =	10.961631
T 623		.800000 x	18.647423 =	14.917938
511		.034000 x	728.352425 =	24.763982
113		2.550000 x	20.419486 =	52.069689

			T.E =	182.132433

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
509		.004718 x	413.660870 =	1.951652
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.056095 =	.514024
T 630		.250000 x	1.817641 =	.454410
T 623		.800000 x	18.647423 =	14.917938
T 617		.500000 x	6.433490 =	3.216745
511		.034000 x	728.352425 =	24.763982
509		.007548 x	413.660870 =	3.122312
113		2.550000 x	20.419486 =	52.069689
			T.E =	174.387547
6360.1	6360.1			
6360.1 A1		1.000000 x	113.109816 =	113.109816
6360.1 A2		1.000000 x	7.996827 =	7.996827
6360.1 A3		1.000000 x	14.471191 =	14.471191
6360.1 A4		1.000000 x	32.343733 =	32.343733
6360.1 A5		1.000000 x	99.519311 =	99.519311
			AΘΡΟΙΣΜΑ =	267.440878
	T.E =	.200000 x	267.440878 =	53.488176
6360.2	6360.2			
6360.2 A1		1.000000 x	121.615236 =	121.615236
6360.2 A3		1.000000 x	18.868021 =	18.868021
6360.2 A4		1.000000 x	35.604125 =	35.604125
6360.2 A2		1.000000 x	11.132849 =	11.132849
6360.2 A5		1.000000 x	113.402016 =	113.402016
			AΘΡΟΙΣΜΑ =	300.622247
	T.E =	.200000 x	300.622247 =	60.124449
6360.3	6360.3			
6360.3 A1		1.000000 x	161.177059 =	161.177059
6360.3 A3		1.000000 x	42.321882 =	42.321882
6360.3 A5		1.000000 x	156.849214 =	156.849214
6360.3 A4		1.000000 x	42.627945 =	42.627945
6360.3 A2		1.000000 x	15.799612 =	15.799612
			AΘΡΟΙΣΜΑ =	418.775712
	T.E =	.200000 x	418.775712 =	83.755142

6360.4	6360.4			
6360.4 A1		1.000000 x	211.283564 =	211.283564
6360.4 A2		1.000000 x	21.420688 =	21.420688
6360.4 A3		1.000000 x	63.249833 =	63.249833
6360.4 A5		1.000000 x	211.658247 =	211.658247
6360.4 A4		1.000000 x	35.604125 =	35.604125

			AΘΡΟΙΣΜΑ =	543.216457
	T.E =	.200000 x	543.216457 =	108.643291

6360.5	6360.5			
6360.5 A1		1.000000 x	242.088954 =	242.088954
6360.5 A2		1.000000 x	26.720372 =	26.720372
6360.5 A3		1.000000 x	70.269186 =	70.269186
6360.5 A5		1.000000 x	289.635335 =	289.635335
6360.5 A4		1.000000 x	36.857780 =	36.857780

			AΘΡΟΙΣΜΑ =	665.571627
	T.E =	.200000 x	665.571627 =	133.114325

6360.6	6360.6			
6360.6 A1		1.000000 x	294.519310 =	294.519310
6360.6 A5		1.000000 x	382.687143 =	382.687143
6360.6 A4		1.000000 x	35.604125 =	35.604125
6360.6 A3		1.000000 x	82.598851 =	82.598851
6360.6 A2		1.000000 x	40.110518 =	40.110518

			AΘΡΟΙΣΜΑ =	835.519947
	T.E =	.200000 x	835.519947 =	167.103989

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143
396.14		.003000 x	42.680000 =	.128040

			T.E =	16.933809
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	20.419486 =	4.339141
111		.212500 x	15.741598 =	3.345090

			T.E =	8.339230

6372	6372			
396.11		1.050000 x	2.960000 =	3.108000
396.13		.700000 x	1.770000 =	1.239000
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	16.641769
6373	6373			
396.12		1.050000 x	4.250000 =	4.462500
113		.425000 x	20.419486 =	8.678282
111		.425000 x	15.741598 =	6.690179
396.13		.700000 x	1.770000 =	1.239000

			T.E =	21.069961
6401	6401			
327		.500000 x	.540000 =	.270000
113		.212500 x	20.419486 =	4.339141

			T.E =	4.609141
6402	6402			
252		.000500 x	290.000000 =	.145000
652		.011500 x	150.401055 =	1.729612
652.2		.005500 x	170.193680 =	.936065
111		.595000 x	15.741598 =	9.366251
113		.595000 x	20.419486 =	12.149594

			T.E =	24.326522
6403	6403			
251		.000500 x	290.000000 =	.145000
652.2		.005500 x	170.193680 =	.936065
652		.016500 x	150.401055 =	2.481617
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

			T.E =	34.299604
6404	6404			
111		1.275000 x	15.741598 =	20.070537
652		.020000 x	150.401055 =	3.008021
113		1.700000 x	20.419486 =	34.713126

			T.E =	57.791685
6404.1	6404.1			
397.8		54.000000 x	.000000 =	.000000
6404		1.000000 x	57.791685 =	57.791685

			T.E =	

6405	6405				
111		.425000 x	15.741598 =		6.690179
113		.850000 x	20.419486 =		17.356563
652		.020000 x	150.401055 =		3.008021

			T.E =		27.054763
6451.1	6451.1				
386.1		1.000000 x	.000000 =		.000000
386.1		.150000 x	.000000 =		.000000

			T.E =		
6451.10	6451.10				
386.10		1.000000 x	.000000 =		.000000
386.10		.150000 x	.000000 =		.000000

			T.E =		
6451.11	6451.11				
386.11		1.000000 x	.000000 =		.000000
386.11		.150000 x	.000000 =		.000000

			T.E =		
6451.12	6451.12				
386.12		1.000000 x	.000000 =		.000000
386.12		.150000 x	.000000 =		.000000

			T.E =		
6451.13	6451.13				
386.13		1.000000 x	.000000 =		.000000
386.13		.150000 x	.000000 =		.000000

			T.E =		
6451.14	6451.14				
386.14		1.000000 x	.000000 =		.000000
386.14		.150000 x	.000000 =		.000000

			T.E =		
6451.15	6451.15				
386.15		1.000000 x	.000000 =		.000000
386.15		.150000 x	.000000 =		.000000

			T.E =		

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	25,662.000000 =	25,662.000000
386.9		.150000 x	25,662.000000 =	3,849.300000

			T.E =	29,511.300000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19				
386.40		1.000000 x	76,825.000000 =		76,825.000000
386.40		.150000 x	76,825.000000 =		11,523.750000
				T.E =	88,348.750000
6452.2	6452.2				
386.23		1.000000 x	.000000 =		.000000
386.23		.150000 x	.000000 =		.000000
				T.E =	
6452.20	6452.20				
386.41		1.000000 x	.000000 =		.000000
386.41		.150000 x	.000000 =		.000000
				T.E =	
6452.21	6452.21				
386.42		1.000000 x	.000000 =		.000000
386.42		.150000 x	.000000 =		.000000
				T.E =	
6452.22	6452.22				
386.43		1.000000 x	.000000 =		.000000
386.43		.150000 x	.000000 =		.000000
				T.E =	
6452.23	6452.23				
386.44		1.000000 x	.000000 =		.000000
386.44		.150000 x	.000000 =		.000000
				T.E =	
6452.24	6452.24				
386.45		1.000000 x	.000000 =		.000000
386.45		.150000 x	.000000 =		.000000
				T.E =	
6452.25	6452.25				
386.46		1.000000 x	.000000 =		.000000
386.46		.150000 x	.000000 =		.000000
				T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	113,082.000000 =	113,082.000000
386.30		.150000 x	113,082.000000 =	16,962.300000

			T.E =	130,044.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17				
386.64		1.000000 x	153,664.000000 =	153,664.000000	
386.64		.150000 x	153,664.000000 =	23,049.600000	
					T.E = 176,713.600000
6453.18	6453.18				
386.65		1.000000 x	.000000 =	.000000	
386.65		.150000 x	.000000 =	.000000	
					T.E =
6453.19	6453.19				
386.66		1.000000 x	.000000 =	.000000	
386.66		.150000 x	.000000 =	.000000	
					T.E =
6453.2	6453.2				
386.49		1.000000 x	.000000 =	.000000	
386.49		.150000 x	.000000 =	.000000	
					T.E =
6453.20	6453.20				
386.67		1.000000 x	.000000 =	.000000	
386.67		.150000 x	.000000 =	.000000	
					T.E =
6453.3	6453.3				
386.50		1.000000 x	.000000 =	.000000	
386.50		.150000 x	.000000 =	.000000	
					T.E =
6453.4	6453.4				
386.51		1.000000 x	.000000 =	.000000	
386.51		.150000 x	.000000 =	.000000	
					T.E =
6453.5	6453.5				
386.52		1.000000 x	.000000 =	.000000	
386.52		.150000 x	.000000 =	.000000	
					T.E =

6453.6	6453.6				
386.53		1.000000 x	134,053.000000 =	134,053.000000	
386.53		.150000 x	134,053.000000 =	20,107.950000	

			T.E =	154,160.950000	
6453.7	6453.7				
386.54		1.000000 x	.000000 =	.000000	
386.54		.150000 x	.000000 =	.000000	

			T.E =		
6453.8	6453.8				
386.55		1.000000 x	.000000 =	.000000	
386.55		.150000 x	.000000 =	.000000	

			T.E =		
6453.9	6453.9				
386.56		1.000000 x	.000000 =	.000000	
386.56		.150000 x	.000000 =	.000000	

			T.E =		
6454.1	6454.1				
386.68		1.000000 x	.000000 =	.000000	
386.68		.150000 x	.000000 =	.000000	

			T.E =		
6454.10	6454.10				
386.77		1.000000 x	.000000 =	.000000	
386.77		.150000 x	.000000 =	.000000	

			T.E =		
6454.11	6454.11				
386.78		1.000000 x	.000000 =	.000000	
386.78		.150000 x	.000000 =	.000000	

			T.E =		
6454.12	6454.12				
386.79		1.000000 x	.000000 =	.000000	
386.79		.150000 x	.000000 =	.000000	

			T.E =		

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	21,523.000000 =	21,523.000000
387.3		.100000 x	21,523.000000 =	2,152.300000

			T.E =	23,675.300000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	1.006500 =	209.352000
235		338.000000 x	.703000 =	237.614000
113		154.700001 x	20.419486 =	3,158.894505

			AΘΡΟΙΣΜΑ =	3,605.860505

			T.E =	5,408.790757
6456.2	6456.2			
234.2		336.000000 x	1.006500 =	338.184000
235		546.000000 x	.703000 =	383.838000
113		249.900000 x	20.419486 =	5,102.829551

			AΘΡΟΙΣΜΑ =	5,824.851551

			T.E =	8,154.792172
6456.3	6456.3			
234.2		384.000000 x	1.006500 =	386.496000
235		624.000000 x	.703000 =	438.672000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,656.973161

			T.E =	9,319.762425
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

T.E =				
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

T.E =				
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

T.E =				
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

T.E =				
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

T.E =				
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

T.E =				
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

T.E =				
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

T.E =				

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,664.000000 =	6,664.000000
389.4		.200000 x	6,664.000000 =	1,332.800000

			T.E =	7,996.800000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,629.000000 =	5,629.000000
390.14		.150000 x	5,629.000000 =	844.350000

			T.E =	6,473.350000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	8,188.000000 =	8,188.000000
390.31		.150000 x	8,188.000000 =	1,228.200000

			T.E =	9,416.200000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

T.E =				
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

T.E =				
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

T.E =				
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

T.E =				
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

T.E =				
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

T.E =				
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

T.E =				
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

T.E =				

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		.150000 x	.000000 =	.000000
391.15		1.000000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

T.E =				
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

T.E =				
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

T.E =				
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

T.E =				
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

T.E =				
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

T.E =				
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

T.E =				
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

T.E =				

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	15,362.000000 =	15,362.000000
393.1		.150000 x	15,362.000000 =	2,304.300000

			T.E =	17,666.300000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.950000 =	6.950000

			T.E =	6.950000
6501	6501			
237		1.000000 x	1.218000 =	1.218000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.574563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,221.779089 =	94.425611

			T.E =	97.368670
6505	6505			
233		1.050000 x	.545500 =	.572775
113		.042500 x	20.419486 =	.867828

			T.E =	1.440603

6506	6506				
233.1		1.050000 x	.545500 =	.572775	
113		.042500 x	20.419486 =	.867828	
			T.E =	1.440603	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
261		1.000000 x	15.100000 =	15.100000	
111		.255000 x	15.741598 =	4.014107	
			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
113		.297500 x	20.419486 =	6.074797	
111		.297500 x	15.741598 =	4.683125	
			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	
			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
111		.510000 x	15.741598 =	8.028215	
113		.510000 x	20.419486 =	10.413938	
263.2		1.000000 x	46.700000 =	46.700000	
			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	
			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

			T.E =	147.834921
6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

			T.E =	255.002782
6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.649312 =	38.923760
6310		32.020000 x	1.440603 =	46.128108
6329.2		.418000 x	167.678404 =	70.089573
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

			T.E =	210.534402
6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.016845 =	27.691282
6329.2		.478000 x	167.678404 =	80.150277
6304		9.290000 x	5.649312 =	52.482108

			T.E =	177.680231
6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

			T.E =	
6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

			T.E =	

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

			T.E =	
6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

			T.E =	
6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

			T.E =	
6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

			T.E =	

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

			T.E =	
6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

			T.E =	
6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

			T.E =	
6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

			T.E =	
6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

			T.E =	

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

			T.E =	
6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

			T.E =	
6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

			T.E =	
6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

			T.E =	

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

			T.E =	
6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

			T.E =	
6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

			T.E =	
6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

			T.E =	

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

			T.E =	
6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

			T.E =	
6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

			T.E =	
6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

			T.E =	
6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

			T.E =	

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

			T.E =	
6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

			T.E =	
6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

			T.E =	

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

			T.E =	
6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

			T.E =	
6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

			T.E =	
6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

			T.E =	
6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

			T.E =	

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

			T.E =	
6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

			T.E =	
6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

			T.E =	
6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

			T.E =	
6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

			T.E =	

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

			T.E =	
6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

			T.E =	
6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

			T.E =	
6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

			T.E =	

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

			T.E =	
6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

			T.E =	
6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

			T.E =	
6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

			T.E =	
6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

			T.E =	

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.025500 x	20.419486 =	.520697
113		.085000 x	20.419486 =	1.735656
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	13.520000 =	13.520000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

			T.E =	28.026354
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	17.490000 =	17.490000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942

			T.E =	32.732118
6611.3	6611.3			
361.3		1.000000 x	22.200000 =	22.200000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471

			T.E =	40.450494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	42.370000 =	42.370000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

			T.E =	69.712368
6611.6	6611.6			
361.6		1.000000 x	56.540000 =	56.540000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

			T.E =	88.362273

6611.7	6611.7			
361.7		1.000000 x	87.480000 =	87.480000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	125.319024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	7.990000 =	8.149800
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.151613
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.540000 =	26.050800
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.892321
6621.5	6621.5			
372.5		1.020000 x	32.500000 =	33.150000
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.423889
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098
111		.662150 x	15.741598 =	10.423299

			T.E =	101.104384
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213
111		.841500 x	15.741598 =	13.246555

			T.E =	126.764443
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218
111		1.068450 x	15.741598 =	16.819110

			T.E =	158.723104
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
111		.080750 x	15.741598 =	1.271134
112		.131750 x	17.312112 =	2.280871
113		.235450 x	20.419486 =	4.807768

			T.E =	20.497773
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	15.741598 =	2.060575
113		.299200 x	20.419486 =	6.109510
112		.212500 x	17.312112 =	3.678824

			T.E =	31.004509
6622.3	6622.3			
373.3		1.020000 x	24.490000 =	24.979800
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	39.458492

6623	6623			
360.2		1.000000 x	2.440000 =	2.440000
113		.025500 x	20.419486 =	.520697
113		.085000 x	20.419486 =	1.735656
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	6.101136
6630.1	6630.1			
376.12		1.000000 x	91.600000 =	91.600000
111		.855100 x	15.741598 =	13.460640
112		2.439500 x	17.312112 =	42.232897
113		2.550000 x	20.419486 =	52.069689
113		.610300 x	20.419486 =	12.462012
113		1.067600 x	20.419486 =	21.799843

			T.E =	233.625083
6630.10	6630.10			
376.21		1.000000 x	502.070000 =	502.070000
111		7.690800 x	15.741598 =	121.065482
113		3.349000 x	20.419486 =	68.384859
113		3.203650 x	20.419486 =	65.416886
113		2.550000 x	20.419486 =	52.069689
112		13.396000 x	17.312112 =	231.913052

			T.E =	1,040.919968
6630.11	6630.11			
376.22		1.000000 x	544.290000 =	544.290000
113		3.471400 x	20.419486 =	70.884204
113		3.629500 x	20.419486 =	74.112524
113		2.550000 x	20.419486 =	52.069689
111		9.025300 x	15.741598 =	142.072644
112		14.518000 x	17.312112 =	251.337242

			T.E =	1,134.766304
6630.2	6630.2			
376.13		1.000000 x	101.900000 =	101.900000
113		1.201050 x	20.419486 =	24.524824
113		.680000 x	20.419486 =	13.885250
113		2.550000 x	20.419486 =	52.069689
112		2.720000 x	17.312112 =	47.088945
111		1.081200 x	15.741598 =	17.019816

			T.E =	256.488524

6630.3	6630.3			
376.14		1.000000 x	113.040000 =	113.040000
113		.760750 x	20.419486 =	15.534124
113		2.550000 x	20.419486 =	52.069689
112		3.043000 x	17.312112 =	52.680757
111		1.334500 x	15.741598 =	21.007163
113		1.334500 x	20.419486 =	27.249804

			T.E =	281.581537
6630.4	6630.4			
376.15		1.000000 x	144.820000 =	144.820000
111		1.922700 x	15.741598 =	30.266370
112		3.570000 x	17.312112 =	61.804240
113		2.550000 x	20.419486 =	52.069689
113		1.602250 x	20.419486 =	32.717121
113		.892500 x	20.419486 =	18.224391

			T.E =	339.901812
6630.5	6630.5			
376.16		1.000000 x	182.130000 =	182.130000
112		4.658000 x	17.312112 =	80.639818
111		2.617150 x	15.741598 =	41.198123
113		1.869150 x	20.419486 =	38.167082
113		1.164500 x	20.419486 =	23.778491
113		2.550000 x	20.419486 =	52.069689

			T.E =	417.983204
6630.6	6630.6			
376.17		1.000000 x	231.180000 =	231.180000
112		5.882000 x	17.312112 =	101.829843
111		3.418700 x	15.741598 =	53.815801
113		1.470500 x	20.419486 =	30.026854
113		2.136050 x	20.419486 =	43.617043
113		2.550000 x	20.419486 =	52.069689

			T.E =	512.539230
6630.7	6630.7			
376.18		1.000000 x	311.830000 =	311.830000
113		2.402950 x	20.419486 =	49.067004
113		2.550000 x	20.419486 =	52.069689
113		2.031500 x	20.419486 =	41.482186
112		8.126000 x	17.312112 =	140.678222
111		4.326500 x	15.741598 =	68.106024

			T.E =	663.233125

6630.8	6630.8			
376.19		1.000000 x	346.570000 =	346.570000
113		2.550000 x	20.419486 =	52.069689
113		2.669850 x	20.419486 =	54.516965
113		2.261000 x	20.419486 =	46.168458
112		9.044000 x	17.312112 =	156.570741
111		5.340550 x	15.741598 =	84.068791
			T.E =	739.964644
6630.9	6630.9			
376.20		1.000000 x	412.890000 =	412.890000
111		6.461700 x	15.741598 =	101.717484
113		2.936750 x	20.419486 =	59.966926
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
112		10.948000 x	17.312112 =	189.533002
			T.E =	872.065234
6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
111		1.334500 x	15.741598 =	21.007163
113		1.667700 x	20.419486 =	34.053577
113		2.550000 x	20.419486 =	52.069689
112		3.043000 x	17.312112 =	52.680757
			T.E =	
6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.002600 x	20.419486 =	40.892063
113		2.550000 x	20.419486 =	52.069689
111		1.922700 x	15.741598 =	30.266370
112		3.570000 x	17.312112 =	61.804240
			T.E =	
6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192
112		4.658000 x	17.312112 =	80.639818
111		2.617150 x	15.741598 =	41.198123
			T.E =	

6640.4	6640.4			
377.4		1.000000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689
111		3.418700 x	15.741598 =	53.815801
112		5.882000 x	17.312112 =	101.829843

			T.E =	
6640.5	6640.5			
377.5		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		3.003900 x	20.419486 =	61.338094
111		4.326500 x	15.741598 =	68.106024
112		8.126000 x	17.312112 =	140.678222

			T.E =	
6640.6	6640.6			
377.6		1.000000 x	.000000 =	.000000
113		3.337100 x	20.419486 =	68.141867
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741
111		5.340550 x	15.741598 =	84.068791

			T.E =	
6640.7	6640.7			
377.7		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		3.671150 x	20.419486 =	74.962996
112		10.948000 x	17.312112 =	189.533002
111		6.461700 x	15.741598 =	101.717484

			T.E =	
6640.8	6640.8			
377.8		1.000000 x	.000000 =	.000000
112		13.396000 x	17.312112 =	231.913052
113		2.550000 x	20.419486 =	52.069689
113		4.004350 x	20.419486 =	81.766769
111		7.690800 x	15.741598 =	121.065482

			T.E =	

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242
111		9.025300 x	15.741598 =	142.072644

			T.E =	
6641	6641			
233.3		1.000000 x	8.200000 =	8.200000

			T.E =	8.200000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		.050000 x	.000000 =	.000000
383.10		1.000000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.8		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3	6662.3			
384.1		1.000000 x	537.050000 =	537.050000
384.3		1.000000 x	.000000 =	.000000
384.7		2.000000 x	.000000 =	.000000
384.9		2.000000 x	.000000 =	.000000
384.8		2.000000 x	.000000 =	.000000
384.5		2.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.4	6662.4			
384.1		1.000000 x	537.050000 =	537.050000
384.9		2.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.7		2.000000 x	.000000 =	.000000
384.6		2.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.5	6662.5			
384.2		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000
384.8		3.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.5		3.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6662.6	6662.6			
384.2		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.6		3.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.1		.224000 x	.000000 =	.000000

			T.E =	

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000

			T.E =	
6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

			T.E =	
6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

			T.E =	
6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

			T.E =	

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

			T.E =	
6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

			T.E =	
6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

			T.E =	
6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

			T.E =	
6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

			T.E =	
6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
111		.408000 x	15.741598 =	6.422572
113		.085000 x	20.419486 =	1.735656
369.12		.224000 x	.000000 =	.000000

			T.E =	

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
369.14		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804
369.15		.224000 x	.000000 =	.000000

			T.E =	
6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
111		.518500 x	15.741598 =	8.162019
113		.170000 x	20.419486 =	3.471313

			T.E =	
6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	
6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
369.18		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

			T.E =	

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269
369.19		.224000 x	.000000 =	.000000

			T.E =	
6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161

			T.E =	
6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625
369.30		.224000 x	.000000 =	.000000

			T.E =	
6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
369.23		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.24		.224000 x	.000000 =	.000000

			T.E =	

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	
6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
369.27		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	
6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.28		.224000 x	.000000 =	.000000

			T.E =	
6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.29		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

			T.E =	
6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
370.8		1.000000 x	.000000 =	.000000

			T.E =	

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	
6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.408000 x	15.741598 =	6.422572
113		.085000 x	20.419486 =	1.735656

			T.E =	
6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
370.16		1.000000 x	.000000 =	.000000
111		.518500 x	15.741598 =	8.162019

			T.E =	

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

			T.E =	
6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

			T.E =	
6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
113		.026350 x	20.419486 =	.538053
6326		.327500 x	135.027864 =	44.221625
111		.085000 x	15.741598 =	1.338036

			T.E =	
6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
6326		.352500 x	135.027864 =	47.597322
113		.040800 x	20.419486 =	.833115
111		.119000 x	15.741598 =	1.873250

			T.E =	
6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
6326		.372500 x	135.027864 =	50.297879
113		.051000 x	20.419486 =	1.041394
111		.161500 x	15.741598 =	2.542268

			T.E =	
6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
113		.063750 x	20.419486 =	1.301742
6326		.382500 x	135.027864 =	51.648158

			T.E =	

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
111		.187000 x	15.741598 =	2.943679
6326		.391250 x	135.027864 =	52.829652
113		.068000 x	20.419486 =	1.388525

			T.E =	
6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
6327		.393750 x	157.312092 =	61.941636
113		.076500 x	20.419486 =	1.562091

			T.E =	
6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
6327		.431250 x	157.312092 =	67.840840
113		.093500 x	20.419486 =	1.909222
111		.289000 x	15.741598 =	4.549322

			T.E =	
6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	157.312092 =	78.656046
113		.119000 x	20.419486 =	2.429919

			T.E =	
6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	25.176107 =	9.315160
111		.161500 x	15.741598 =	2.542268
113		.017000 x	20.419486 =	.347131

			T.E =	20.884759
6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
6069		.390000 x	25.176107 =	9.818682
111		.187000 x	15.741598 =	2.943679
113		.021250 x	20.419486 =	.433914

			T.E =	26.792875

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
6069		.400000 x	25.176107 =	10.070443
113		.026350 x	20.419486 =	.538053
111		.204000 x	15.741598 =	3.211286

			T.E =	35.025582
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
113		.040800 x	20.419486 =	.833115
6069		.420000 x	25.176107 =	10.573965

			T.E =	49.610384
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
111		.289000 x	15.741598 =	4.549322
6069		.430000 x	25.176107 =	10.825726
113		.051000 x	20.419486 =	1.041394

			T.E =	60.072442
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
111		.297500 x	15.741598 =	4.683125
6069		.440000 x	25.176107 =	11.077487
113		.063750 x	20.419486 =	1.301742

			T.E =	72.376955
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	25.176107 =	13.091576
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.941617
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2				
375.9		1.050000 x	14.980000 =	15.729000	
375.13		1.000000 x	10.160000 =	10.160000	
113		.850000 x	20.419486 =	17.356563	

			T.E =	43.245563	
6712.3	6712.3				
375.10		1.050000 x	20.150000 =	21.157500	
113		.850000 x	20.419486 =	17.356563	
375.13		1.000000 x	10.160000 =	10.160000	

			T.E =	48.674063	
6712.4	6712.4				
375.11		1.050000 x	27.290000 =	28.654500	
375.13		1.000000 x	10.160000 =	10.160000	
113		.850000 x	20.419486 =	17.356563	

			T.E =	56.171063	
6712.5	6712.5				
375.12		1.050000 x	34.560000 =	36.288000	
113		.850000 x	20.419486 =	17.356563	
375.13		1.000000 x	10.160000 =	10.160000	

			T.E =	63.804563	
6713	6713				
375.13		1.000000 x	10.160000 =	10.160000	
113		.021250 x	20.419486 =	.433914	
111		.187000 x	15.741598 =	2.943679	
375.14		1.000000 x	17.510000 =	17.510000	

			T.E =	31.047593	
6720.1	6720.1				
394.2		1.050000 x	.000000 =	.000000	
700		.200000 x	.000000 =	.000000	
6323		.090000 x	106.685867 =	9.601728	
112		1.190000 x	17.312112 =	20.601413	
113		.255000 x	20.419486 =	5.206969	

			T.E =		

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	116.675867 =	25.785367
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	116.675867 =	27.302153
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	116.675867 =	28.118884
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	106.685867 =	11.735445
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	106.685867 =	13.975849
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	106.685867 =	16.429624
700		.350000 x	.000000 =	.000000

			T.E =	
6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	106.685867 =	17.709854
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

			T.E =	
6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	106.685867 =	18.456655
113		.637500 x	20.419486 =	13.017422

			T.E =	
6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	116.675867 =	16.101270
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

			T.E =	
6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	116.675867 =	19.251518
700		.250000 x	.000000 =	.000000

			T.E =	

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	116.675867 =	22.518442
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	106.685867 =	6.401152
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	116.675867 =	15.167863
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	116.675867 =	16.334621
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	116.675867 =	17.501380
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	106.685867 =	7.468011
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

			T.E =	
6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	106.685867 =	8.534869
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

			T.E =	
6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	106.685867 =	9.601728
700		.350000 x	.000000 =	.000000

			T.E =	
6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	106.685867 =	10.668587
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

			T.E =	
6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	106.685867 =	11.735445
113		.637500 x	20.419486 =	13.017422

			T.E =	

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	116.675867 =	11.667587
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

			T.E =	
6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	116.675867 =	12.834345
700		.250000 x	.000000 =	.000000

			T.E =	
6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	116.675867 =	14.001104
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

			T.E =	
6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

			T.E =	
6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	106.685867 =	9.601728
652		.002500 x	150.401055 =	.376003
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	39.601889

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.675867 =	29.052291
652		.004500 x	150.401055 =	.676805
113		.340000 x	20.419486 =	6.942625
			T.E =	82.732494
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	116.675867 =	36.169519
652		.005000 x	150.401055 =	.752005
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	111.287547
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.675867 =	43.170071
652		.006500 x	150.401055 =	.977607
112		.680000 x	17.312112 =	11.772236
			T.E =	142.064687
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	106.685867 =	11.735445
652		.003000 x	150.401055 =	.451203
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	47.690807
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.685867 =	13.975849
652		.003500 x	150.401055 =	.526404
113		.297500 x	20.419486 =	6.074797
			T.E =	58.159022

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	106.685867 =	18.136597
652		.004500 x	150.401055 =	.676805
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648
			T.E =	71.816800
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.685867 =	24.111006
652		.005000 x	150.401055 =	.752005
112		.552500 x	17.312112 =	9.564942
			T.E =	99.229034
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	106.685867 =	29.231928
652		.006500 x	150.401055 =	.977607
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179
			T.E =	128.126544
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.675867 =	16.101270
652		.002500 x	150.401055 =	.376003
113		.255000 x	20.419486 =	5.206969
			T.E =	46.101431
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	116.675867 =	19.251518
652		.003000 x	150.401055 =	.451203
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
			T.E =	55.206880

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	116.675867 =	22.518442
652		.003500 x	150.401055 =	.526404
112		.382500 x	17.312112 =	6.621883
			T.E =	66.701616
6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	106.685867 =	9.601728
652		.002500 x	150.401055 =	.376003
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	
6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	116.675867 =	29.052291
652		.004500 x	150.401055 =	.676805
113		.340000 x	20.419486 =	6.942625
			T.E =	
6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	116.675867 =	36.169519
652		.005000 x	150.401055 =	.752005
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	
6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	116.675867 =	43.170071
652		.006500 x	150.401055 =	.977607
112		.680000 x	17.312112 =	11.772236
			T.E =	

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	106.685867 =	11.735445
652		.003000 x	150.401055 =	.451203
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	
6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	106.685867 =	13.975849
652		.003500 x	150.401055 =	.526404
113		.297500 x	20.419486 =	6.074797

			T.E =	
6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	106.685867 =	18.136597
652		.004500 x	150.401055 =	.676805
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

			T.E =	
6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	106.685867 =	24.111006
652		.005000 x	150.401055 =	.752005
112		.552500 x	17.312112 =	9.564942

			T.E =	
6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	106.685867 =	29.231928
652		.006500 x	150.401055 =	.977607
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

			T.E =	

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	116.675867 =	16.101270
652		.002500 x	150.401055 =	.376003
111		.170000 x	15.741598 =	2.676072

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	116.675867 =	19.251518
652		.003000 x	150.401055 =	.451203
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.382500 x	17.312112 =	6.621883
6325		.193000 x	116.675867 =	22.518442
652		.003500 x	150.401055 =	.526404
111		.212500 x	15.741598 =	3.345090

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	20.346867 =	38.252110
6326		.940000 x	135.027864 =	126.926192

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	135.027864 =	98.570341

T.E =

6741.1	6741.1				
710		3.770000 x	.000000 =	.000000	
6326		.940000 x	135.027864 =	126.926192	

			T.E =		
6741.2	6741.2				
6741.1		1.000000 x	.000000 =	.000000	
6326		.730000 x	135.027864 =	98.570341	

			T.E =		
6742.1	6742.1				
6303		3.040000 x	20.346867 =	61.854476	
6328		.400000 x	160.888404 =	64.355362	

			T.E =	126.209837	
6742.10	6742.10				
6303		7.520000 x	20.346867 =	153.008440	
6328		2.110000 x	160.888404 =	339.474532	

			T.E =	492.482972	
6742.11	6742.11				
6303		8.030000 x	20.346867 =	163.385342	
6328		2.430000 x	160.888404 =	390.958822	

			T.E =	554.344164	
6742.2	6742.2				
6303		3.500000 x	20.346867 =	71.214035	
6328		.500000 x	160.888404 =	80.444202	

			T.E =	151.658237	
6742.3	6742.3				
6303		4.020000 x	20.346867 =	81.794405	
6328		.630000 x	160.888404 =	101.359695	

			T.E =	183.154100	
6742.4	6742.4				
6303		4.530000 x	20.346867 =	92.171308	
6328		.800000 x	160.888404 =	128.710723	

			T.E =	220.882031	

6742.5	6742.5				
6303		5.000000 x	20.346867 =	101.734335	
6328		.950000 x	160.888404 =	152.843984	

			T.E =	254.578319	
6742.6	6742.6				
6303		5.530000 x	20.346867 =	112.518175	
6328		1.170000 x	160.888404 =	188.239433	

			T.E =	300.757607	
6742.7	6742.7				
6303		6.040000 x	20.346867 =	122.895077	
6328		1.410000 x	160.888404 =	226.852650	

			T.E =	349.747726	
6742.8	6742.8				
6303		6.520000 x	20.346867 =	132.661573	
6328		1.610000 x	160.888404 =	259.030330	

			T.E =	391.691903	
6742.9	6742.9				
6303		7.040000 x	20.346867 =	143.241944	
6328		1.880000 x	160.888404 =	302.470200	

			T.E =	445.712143	
6743.1	6743.1				
6303		3.040000 x	20.346867 =	61.854476	
6328		.440000 x	160.888404 =	70.790898	

			T.E =	132.645373	
6743.10	6743.10				
6303		7.520000 x	20.346867 =	153.008440	
6328		2.240000 x	160.888404 =	360.390025	

			T.E =	513.398465	
6743.11	6743.11				
6303		8.030000 x	20.346867 =	163.385342	
6328		2.570000 x	160.888404 =	413.483198	

			T.E =	576.868540	

6743.12	6743.12			
6303		3.040000 x	20.346867 =	61.854476
6328		.750000 x	160.888404 =	120.666303

			T.E =	182.520779
6743.13	6743.13			
6303		3.500000 x	20.346867 =	71.214035
6328		.910000 x	160.888404 =	146.408448

			T.E =	217.622482
6743.14	6743.14			
6303		4.020000 x	20.346867 =	81.794405
6328		1.090000 x	160.888404 =	175.368360

			T.E =	257.162766
6743.15	6743.15			
6303		4.530000 x	20.346867 =	92.171308
6328		1.300000 x	160.888404 =	209.154925

			T.E =	301.326233
6743.16	6743.16			
6303		5.000000 x	20.346867 =	101.734335
6328		1.550000 x	160.888404 =	249.377026

			T.E =	351.111361
6743.17	6743.17			
6303		5.530000 x	20.346867 =	112.518175
6328		1.850000 x	160.888404 =	297.643547

			T.E =	410.161722
6743.2	6743.2			
6303		3.500000 x	20.346867 =	71.214035
6328		.550000 x	160.888404 =	88.488622

			T.E =	159.702657
6743.3	6743.3			
6303		4.020000 x	20.346867 =	81.794405
6328		.690000 x	160.888404 =	111.012999

			T.E =	192.807404

6743.4	6743.4				
6303		4.530000 x	20.346867 =	92.171308	
6328		.860000 x	160.888404 =	138.364027	
			T.E =	230.535335	
6743.5	6743.5				
6303		5.000000 x	20.346867 =	101.734335	
6328		1.020000 x	160.888404 =	164.106172	
			T.E =	265.840507	
6743.6	6743.6				
6303		5.530000 x	20.346867 =	112.518175	
6328		1.260000 x	160.888404 =	202.719389	
			T.E =	315.237564	
6743.7	6743.7				
6303		6.040000 x	20.346867 =	122.895077	
6328		1.500000 x	160.888404 =	241.332606	
			T.E =	364.227683	
6743.8	6743.8				
6303		6.520000 x	20.346867 =	132.661573	
6328		1.720000 x	160.888404 =	276.728055	
			T.E =	409.389628	
6743.9	6743.9				
6303		7.040000 x	20.346867 =	143.241944	
6328		2.000000 x	160.888404 =	321.776808	
			T.E =	465.018752	
6744	6744				
111		2.125000 x	15.741598 =	33.450896	
113		2.125000 x	20.419486 =	43.391408	
113		2.125000 x	20.419486 =	43.391408	
111		4.250000 x	15.741598 =	66.901792	
112		2.125000 x	17.312112 =	36.788238	
			T.E =	223.923741	

6751	6751			
234.2		.400000 x	1.006500 =	.402600
113		.051000 x	20.419486 =	1.041394
113		.170000 x	20.419486 =	3.471313
235		.650000 x	.703000 =	.456950

			T.E =	5.372256
6752	6752			
237		1.050000 x	1.218000 =	1.278900
111		.025500 x	15.741598 =	.401411
113		.017000 x	20.419486 =	.347131

			T.E =	2.027442
6753	6753			
237		1.050000 x	1.218000 =	1.278900
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	4.486086
6754	6754			
237.1		1.000000 x	1.380000 =	1.380000
113		.212500 x	20.419486 =	4.339141
112		.017000 x	17.312112 =	.294306
111		.051000 x	15.741598 =	.802821

			T.E =	6.816268
6801	6801			
232		.700000 x	2.184000 =	1.528800
111		.850000 x	15.741598 =	13.380358
113		2.550000 x	20.419486 =	52.069689
112		1.700000 x	17.312112 =	29.430590
251		.008000 x	290.000000 =	2.320000

			T.E =	98.729438
6802	6802			
231		15.000000 x	.895000 =	13.425000
251		.050000 x	290.000000 =	14.500000
111		4.250000 x	15.741598 =	66.901792
252.1		.050000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689

			T.E =	

6803	6803			
302		1.020000 x	6.700000 =	6.834000
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250
652		.012000 x	150.401055 =	1.804813

			T.E =	30.552278
6804	6804			
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250
652		.120000 x	150.401055 =	18.048127

			T.E =	39.961592
6805	6805			
301		1.000000 x	4.060000 =	4.060000
113		.340000 x	20.419486 =	6.942625
2522		.005000 x	154.896926 =	.774485
652		.002000 x	150.401055 =	.300802
111		.340000 x	15.741598 =	5.352143

			T.E =	17.430055
6806	6806			
111		.340000 x	15.741598 =	5.352143
652		.002000 x	150.401055 =	.300802
6326		.005000 x	135.027864 =	.675139
113		.340000 x	20.419486 =	6.942625

			T.E =	13.270710
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.750000 =	20.150000
241		1.300000 x	7.750000 =	10.075000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448

			T.E =	86.002715

6811	6811			
236		6.430000 x	.673000 =	4.327390
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.750000 =	24.412500

			T.E =	115.522706
6812	6812			
243		11.900000 x	2.400000 =	28.560000
6324		.250000 x	111.680867 =	27.920217
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179
397.1		2.100000 x	7.050000 =	14.805000

			AΘΡΟΙΣΜΑ =	164.758211
	T.E =	.262500 x	164.758211 =	43.249030

7001	7001			
7001 A		1.000000 x	.241044 =	.241044
7001 B		1.000000 x	.787862 =	.787862
7001 Δ		1.000000 x	.327194 =	.327194
7001 Γ		1.000000 x	.998446 =	.998446
7001 E		1.000000 x	.839659 =	.839659

			AΘΡΟΙΣΜΑ =	3.194205

			T.E =	3.673336
7002	7002			
560		.005104 x	718.633890 =	3.667907

			T.E =	3.667907
7003	7003			
7003 A		1.000000 x	.120522 =	.120522
7003 B		1.000000 x	.615600 =	.615600
7003 Γ		1.000000 x	.566216 =	.566216
7003 Δ		1.000000 x	.816657 =	.816657

			AΘΡΟΙΣΜΑ =	2.118995

			T.E =	2.330895
7004	7004			
561		.003250 x	948.768190 =	3.083497

			T.E =	3.083497

7005	7005			
7005 Α		1.000000 x	.120522 =	.120522
7005 Γ		1.000000 x	.307800 =	.307800
7005 Β		1.000000 x	1.077300 =	1.077300
7005 Ε		1.000000 x	.816657 =	.816657
7005 Δ		1.000000 x	.566216 =	.566216

			ΑΘΡΟΙΣΜΑ =	2.888495

			T.E =	3.177345
7006	7006			
561		.001723 x	948.768190 =	1.634728
561		.000812 x	948.768190 =	.770400
561		.000862 x	948.768190 =	.817838

			T.E =	3.222966
7007	7007			
213		.100000 x	1.949500 =	.194950
550		.003500 x	1,064.061086 =	3.724214
518		.001750 x	896.262492 =	1.568459
502		.000583 x	808.880173 =	.471577
116		.280000 x	20.419486 =	5.717456

			T.E =	11.676656
7008	7008			
111		.021000 x	15.741598 =	.330574
507		.000875 x	947.117807 =	.828728
558		.000972 x	1,125.517457 =	1.094003
503		.001750 x	925.201873 =	1.619103
7007		1.100000 x	11.676656 =	12.844322
112		.210000 x	17.312112 =	3.635544

			T.E =	20.352273
7009	7009			
560		.006417 x	718.633890 =	4.611474

			T.E =	4.611474
7010	7010			
7010 Α		1.000000 x	.354538 =	.354538
7010 Β		1.000000 x	.532370 =	.532370
7010 Γ		1.000000 x	.566216 =	.566216
7010 Ε		1.000000 x	1.033448 =	1.033448
7010 Δ		1.000000 x	.327194 =	.327194

			ΑΘΡΟΙΣΜΑ =	2.813766

			T.E =	3.235831

7011	7011			
502		.001367 x	808.880173 =	1.105739
502		.000700 x	808.880173 =	.566216
558		.000729 x	1,125.517457 =	.820502
563		.001367 x	.000000 =	.000000
558		.000729 x	1,125.517457 =	.820502
554		.000438 x	34.408000 =	.015071
503		.000438 x	925.201873 =	.405238

			ΑΘΡΟΙΣΜΑ =	3.733269

			T.E =	
7012	7012			
7008		1.000000 x	20.352273 =	20.352273

			ΑΘΡΟΙΣΜΑ =	20.352273

			T.E =	22.387500
7013	7013			
7003		1.000000 x	2.330895 =	2.330895

			ΑΘΡΟΙΣΜΑ =	2.330895

			T.E =	2.563985
7014	7014			
7005		1.000000 x	3.177345 =	3.177345

			ΑΘΡΟΙΣΜΑ =	3.177345

			T.E =	3.495080
7015	7015			
111		.056000 x	15.741598 =	.881529
7001		.900000 x	3.673336 =	3.306002
X 630.1		.300000 x	1.693255 =	.507977
X 630		.300000 x	1.496881 =	.449064

			T.E =	5.144573
7016.9	7016.9			
7016.4		1.000000 x	128.252994 =	128.252994
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.650599 =	25.650599
7016.6		1.000000 x	38.475898 =	38.475898
7016.7		1.000000 x	80.282150 =	80.282150

			T.E =	376.801020

7017.8	7017.8				
7017.3		1.000000 x	93.579042 =		93.579042
7017.4		1.000000 x	18.715808 =		18.715808
7017.5		1.000000 x	33.688455 =		33.688455
7017.6		1.000000 x	80.282150 =		80.282150
7017.7		1.000000 x	52.069689 =		52.069689
				T.E =	278.335144
7018	7018				
233.2		1.150000 x	.598400 =		.688160
113		.051000 x	20.419486 =		1.041394
				AΘΡΟΙΣΜΑ =	1.729554
				T.E =	1.902509
7019	7019				
7019 A6		1.000000 x	193.105397 =		193.105397
7019 A7		1.000000 x	19.310540 =		19.310540
				T.E =	212.415937
7019.1	7019.1				
396.5		5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	212.415937 =		212.415937
				T.E =	206.515937
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,572.373220 =		39.074618
				T.E =	59.378140
7020.1	7020.1				
570.2		.350000 x	127.284076 =		44.549427
571.2		.070000 x	261.479536 =		18.303568
571.1		.280000 x	454.768750 =		127.335250
				AΘΡΟΙΣΜΑ =	190.188244
		T.E =	.015625 x	190.188244 =	2.971691
7021	7021				
213		.150000 x	1.949500 =		.292425
7021.2		.014583 x	3,118.643966 =		45.479185
116		1.120000 x	20.419486 =		22.869824
				T.E =	68.641434

7021.1	7021.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	454.768750 =	127.335250
571.2		.070000 x	261.479536 =	18.303568

			ΑΘΡΟΙΣΜΑ =	190.188244
	T.E =	.020833 x	190.188244 =	3.962192

7022	7022			
213		.150000 x	1.949500 =	.292425
7022.2		.020000 x	2,860.406426 =	57.208129
116		1.400000 x	20.419486 =	28.587280

			T.E =	86.087834
7022.1	7022.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	454.768750 =	127.335250
571.2		.070000 x	261.479536 =	18.303568

			ΑΘΡΟΙΣΜΑ =	190.188244
	T.E =	.028571 x	190.188244 =	5.433868

7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
550		.012143 x	1,064.061086 =	12.920894
116		.850000 x	20.419486 =	17.356563
111		.425000 x	15.741598 =	6.690179

			T.E =	77.917636
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
550		.020238 x	1,064.061086 =	21.534468
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563

			T.E =	94.931211
7025	7025			
233		6.180000 x	.545500 =	3.371190
396.5		.009000 x	1.180000 =	.010620
111		.425000 x	15.741598 =	6.690179
652		.001000 x	150.401055 =	.150401
550		.020238 x	1,064.061086 =	21.534468
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
398.4		1.000000 x	63.000000 =	63.000000

			T.E =	119.471069

7026	7026			
236		16.808000 x	.673000 =	11.311784
113		3.400000 x	20.419486 =	69.426252
113		.909160 x	20.419486 =	18.564580
6310		12.350000 x	1.440603 =	17.791447
398.5		125.400000 x	6.400000 =	802.560000

			ΑΘΡΟΙΣΜΑ =	919.654063
	T.E =	.007259 x	919.654063 =	6.675769

7027	7027			
236		1.100000 x	.673000 =	.740300
113		.059500 x	20.419486 =	1.214959

			T.E =	1.955259
7028	7028			
111		.144500 x	15.741598 =	2.274661
112		.144500 x	17.312112 =	2.501600
6751		.600000 x	5.372256 =	3.223354
111		.425000 x	15.741598 =	6.690179
6751		.120000 x	5.372256 =	.644671

			ΑΘΡΟΙΣΜΑ =	15.334465

			T.E =	17.634634
7029	7029			
568.1		.021250 x	2,677.834152 =	56.903976
569.2		.021250 x	620.296952 =	13.181310
570.2		.021250 x	127.284076 =	2.704787
571.2		.021250 x	261.479536 =	5.556440

			T.E =	78.346513
7030	7030			
398.6		.015385 x	330.000000 =	5.077050
572		.026563 x	860.717537 =	22.863240

			ΑΘΡΟΙΣΜΑ =	27.940290

			T.E =	39.116406
7031	7031			
573		.106250 x	1,089.977112 =	115.810068

			ΑΘΡΟΙΣΜΑ =	115.810068

			T.E =	133.181578
7032	7032			
573		.212500 x	1,089.977112 =	231.620136

			ΑΘΡΟΙΣΜΑ =	231.620136

			T.E =	301.106177

7101.1	7101.1			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.056095 =	.215890
T 630		.105000 x	1.817641 =	.190852
574		.132813 x	3,684.927682 =	489.406300
567		.132813 x	400.040472 =	53.130575

			ΑΘΡΟΙΣΜΑ =	546.693618

			T.E =	563.094426
7101.2	7101.2			
398.1		15.000000 x	.250000 =	3.750000
567		.148750 x	400.040472 =	59.506020
574		.148750 x	3,684.927682 =	548.132993
T 630.1		.105000 x	2.056095 =	.215890
T 630		.105000 x	1.817641 =	.190852

			ΑΘΡΟΙΣΜΑ =	611.795755

			T.E =	630.149628
7101.3	7101.3			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.056095 =	.215890
567		.159375 x	400.040472 =	63.756450
T 630		.105000 x	1.817641 =	.190852
574		.159375 x	3,684.927682 =	587.285349

			ΑΘΡΟΙΣΜΑ =	655.198542

			T.E =	674.854498
7101.4	7101.4			
398.1		15.000000 x	.250000 =	3.750000
567		.170000 x	400.040472 =	68.006880
T 630		.105000 x	1.817641 =	.190852
T 630.1		.105000 x	2.056095 =	.215890
574		.170000 x	3,684.927682 =	626.437706

			ΑΘΡΟΙΣΜΑ =	698.601328

			T.E =	719.559368
7101.5	7101.5			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.056095 =	.215890
T 630		.105000 x	1.817641 =	.190852
574		.191250 x	3,684.927682 =	704.742419
567		.191250 x	400.040472 =	76.507740

			ΑΘΡΟΙΣΜΑ =	785.406902

			T.E =	808.969109

7102.1	7102.1				
398.1		15.000000 x	.250000 =	3.750000	
567		.302813 x	400.040472 =	121.137455	
574		.302813 x	3,684.927682 =	1,115.844006	
T 630.1		.105000 x	2.056095 =	.215890	
T 630		.105000 x	1.817641 =	.190852	

			ΑΘΡΟΙΣΜΑ =	1,241.138204	

			T.E =	1,278.372350	
7102.2	7102.2				
398.1		15.000000 x	.250000 =	3.750000	
T 630.1		.105000 x	2.056095 =	.215890	
567		.329375 x	400.040472 =	131.763330	
T 630		.105000 x	1.817641 =	.190852	
574		.329375 x	3,684.927682 =	1,213.723055	

			ΑΘΡΟΙΣΜΑ =	1,349.643128	

			T.E =	1,390.132422	
7102.3	7102.3				
398.1		15.000000 x	.250000 =	3.750000	
567		.361250 x	400.040472 =	144.514621	
T 630		.105000 x	1.817641 =	.190852	
T 630.1		.105000 x	2.056095 =	.215890	
574		.361250 x	3,684.927682 =	1,331.180125	

			ΑΘΡΟΙΣΜΑ =	1,479.851488	

			T.E =	1,524.247033	
7102.4	7102.4				
398.1		15.000000 x	.250000 =	3.750000	
T 630.1		.105000 x	2.056095 =	.215890	
T 630		.105000 x	1.817641 =	.190852	
574		.403750 x	3,684.927682 =	1,487.789552	
567		.403750 x	400.040472 =	161.516341	

			ΑΘΡΟΙΣΜΑ =	1,653.462634	

			T.E =	1,703.066513	
7102.5	7102.5				
398.1		15.000000 x	.250000 =	3.750000	
567		.446250 x	400.040472 =	178.518061	
T 630		.105000 x	1.817641 =	.190852	
574		.446250 x	3,684.927682 =	1,644.398978	
T 630.1		.105000 x	2.056095 =	.215890	

			ΑΘΡΟΙΣΜΑ =	1,827.073781	

			T.E =	1,881.885994	

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	1,004.465458 =	106.724455

			T.E =	183.478853
7104	7104			
113		1.700000 x	20.419486 =	34.713126
567		.106250 x	400.040472 =	42.504300
576		.106250 x	7.645000 =	.812281

			T.E =	78.029708
7105	7105			
111		.850000 x	15.741598 =	13.380358
576		.106250 x	7.645000 =	.812281
567		.106250 x	400.040472 =	42.504300
113		.850000 x	20.419486 =	17.356563

			T.E =	74.053503
7106.1	7106.1			
577		.265625 x	682.960819 =	181.411468

			AΘΡΟΙΣΜΑ =	181.411468

			T.E =	190.482041
7106.2	7106.2			
577		.297500 x	682.960819 =	203.180844

			AΘΡΟΙΣΜΑ =	203.180844

			T.E =	213.339886
7106.3	7106.3			
577		.350625 x	682.960819 =	239.463137

			AΘΡΟΙΣΜΑ =	239.463137

			T.E =	251.436294
7106.4	7106.4			
577		.425000 x	682.960819 =	290.258348

			AΘΡΟΙΣΜΑ =	290.258348

			T.E =	304.771265

7106.5	7106.5				
577		.531250 x	682.960819 =	362.822935	
			AΘΡΟΙΣΜΑ =	362.822935	
			T.E =	380.964082	
7107.1	7107.1				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.1		1.000000 x	190.482041 =	190.482041	
			T.E =	231.282041	
7107.2	7107.2				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.2		1.000000 x	213.339886 =	213.339886	
			T.E =	254.139886	
7107.3	7107.3				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.3		1.000000 x	251.436294 =	251.436294	
			T.E =	292.236294	
7107.4	7107.4				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.4		1.000000 x	304.771265 =	304.771265	
			T.E =	345.571265	
7107.5	7107.5				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.5		1.000000 x	380.964082 =	380.964082	
			T.E =	421.764082	
7108	7108				
398.11		1.000000 x	140.870000 =	140.870000	
574		.053125 x	3,684.927682 =	195.761783	
			T.E =	336.631783	
7109	7109				
398.12		1.000000 x	182.180000 =	182.180000	
574		.053125 x	3,684.927682 =	195.761783	
			T.E =	377.941783	

7110	7110				
398.10		1.170000 x	142.840000 =		167.122800
574		.053125 x	3,684.927682 =		195.761783

				T.E =	362.884583
7111	7111				
398.9		1.170000 x	131.840000 =		154.252800
574		.053125 x	3,684.927682 =		195.761783

				T.E =	350.014583
7112	7112				
398.13		1.300000 x	10.300000 =		13.390000
577		.010625 x	682.960819 =		7.256459

				T.E =	20.646459
7113	7113				
241		1.200000 x	7.750000 =		9.300000
574		.001063 x	3,684.927682 =		3.917078

				T.E =	13.217078
7114	7114				
398.8		.120000 x	31.620000 =		3.794400
577		.053125 x	682.960819 =		36.282294

				T.E =	40.076694
7115	7115				
574		.026563 x	3,684.927682 =		97.882734

				T.E =	97.882734
7116	7116				
577		.170000 x	682.960819 =		116.103339

				T.E =	116.103339
7117	7117				
574		.001063 x	3,684.927682 =		3.917078

				T.E =	3.917078

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
574.1		.425000 x	2,241.497688 =	952.636517
578		.850000 x	647.005766 =	549.954901

			T.E =	1,930.762884
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,241.497688 =	1,905.273035
578		.850000 x	647.005766 =	549.954901

			T.E =	3,097.485134
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	386.217688 =	98.485510

			T.E =	312.571243
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	386.217688 =	229.799524

			T.E =	443.885257
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
578		.425000 x	647.005766 =	274.977451
575.1		.425000 x	259.627416 =	110.341652

			T.E =	545.883402
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	647.005766 =	824.932352
575.1		1.275000 x	259.627416 =	331.024955

			T.E =	1,423.564473
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
578		.425000 x	647.005766 =	274.977451
576.1		.425000 x	6.950000 =	2.953750

			T.E =	384.974067

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	647.005766 =	274.977451
			T.E =	384.974067
7122	7122			
398.1		15.000000 x	.250000 =	3.750000
T 630		.105000 x	1.817641 =	.190852
T 630.1		.105000 x	2.056095 =	.215890
567		.122188 x	400.040472 =	48.880145
580		.122188 x	1,734.845702 =	211.977327
			AΘΡΟΙΣΜΑ =	265.014214
			T.E =	272.964641
7123	7123			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.056095 =	.215890
T 630		.105000 x	1.817641 =	.190852
567		.286875 x	400.040472 =	114.761610
580		.286875 x	1,734.845702 =	497.683861
			AΘΡΟΙΣΜΑ =	616.602213
			T.E =	635.100280
7124	7124			
398.1		15.000000 x	.250000 =	3.750000
T 630.1		.105000 x	2.056095 =	.215890
T 630		.105000 x	1.817641 =	.190852
580		.063750 x	1,734.845702 =	110.596414
567		.063750 x	400.040472 =	25.502580
			T.E =	140.255736
7125	7125			
398.1		15.000000 x	.250000 =	3.750000
567		.127500 x	400.040472 =	51.005160
T 630		.105000 x	1.817641 =	.190852
580		.127500 x	1,734.845702 =	221.192827
T 630.1		.105000 x	2.056095 =	.215890
			T.E =	276.354729
7126	7126			
398.16		1.000000 x	64.290000 =	64.290000
580		.053125 x	1,734.845702 =	92.163678
			T.E =	156.453678

7127	7127				
398.15		1.170000 x	77.960000 =		91.213200
580		.015938 x	1,734.845702 =		27.649971

			T.E =		118.863171
7128	7128				
398.14		1.170000 x	60.360000 =		70.621200
580		.015938 x	1,734.845702 =		27.649971

			T.E =		98.271171
7129	7129				
6751		1.000000 x	5.372256 =		5.372256

			T.E =		5.372256