

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών

1ο Τρίμηνο του 2012

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.243100
212	1.434100
213	1.949500
214	4.550000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.895000
232	2.184000
233	.558700
233.1	.558700
233.2	.611600
233.3	8.250000
234	.847400
234.1	1.000400
234.2	.905900
234.3	.940000
235	.632700
236	.624500
237	1.218000
237.1	1.380000
241	7.750000
242	4.500000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	3.860000
302	6.360000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.440000
361.1	13.520000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	17.490000
361.3	22.200000
361.4	
361.5	42.370000
361.6	56.540000
361.7	87.480000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	4.830000
371.2	7.640000
371.3	9.930000
371.4	15.450000
371.5	19.550000
371.6	30.720000
371.7	39.530000
371.8	50.240000
371.9	63.060000
372.1	7.600000
372.2	11.960000
372.3	15.680000
372.4	24.270000
372.5	30.880000
372.6	48.660000

372.7	61.800000
372.8	78.570000
372.9	99.470000
373.1	11.310000
373.2	17.850000
373.3	23.270000
373.4	36.390000
373.5	45.770000
373.6	72.660000
373.7	92.400000
373.8	117.270000
373.9	148.850000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.090000
375.10	19.140000
375.11	25.920000
375.12	32.830000
375.13	9.650000
375.14	16.640000
375.2	12.670000
375.3	19.750000
375.4	31.970000
375.5	40.660000
375.6	51.520000
375.7	83.510000
375.8	11.060000
375.9	14.230000
376.1	91.600000
376.10	502.070000
376.11	544.290000
376.12	91.600000
376.13	101.900000
376.14	113.040000
376.15	144.820000
376.16	182.130000
376.17	231.180000
376.18	311.830000
376.19	346.570000
376.2	101.900000
376.20	412.890000
376.21	502.070000
376.22	544.290000
376.3	113.040000
376.4	144.820000
376.5	182.130000
376.6	231.180000
376.7	311.830000
376.8	346.570000
376.9	412.890000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	113,082.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	76,825.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	134,053.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	153,664.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	25,662.000000
387.1	
387.2	
387.3	21,523.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,664.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.11	
390.12	
390.13	
390.14	5,629.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	8,188.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	
390.40	

390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	15,362.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.960000
396.12	4.250000
396.13	1.770000
396.14	42.680000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.950000
397.4	.167500
398.1	.255000
398.10	142.840000
398.11	140.870000
398.12	182.180000
398.13	10.300000
398.14	60.360000
398.15	77.960000
398.16	64.290000
398.17	112.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	6.400000
398.6	330.000000

398.7	1,360.00000
398.8	31.62000
398.9	131.84000
401	268.42000
402	380.18000
403	103.36000
404	212.73000
405	206.72000
406	320.98000
407	55.21000
408	4.53000
409	126.08000
410	116.53000
411	27.37000
412	2.99000
413	4.53000
414	6.25000
415	8.78000
416	13.54000
417	134.53000
419	4.53000
420	97.29000
421	32.56000
428	437.84000
429	77.59000
450	83.85000
451	4.87000
452	103.06000
453	
454	97.29000
455	31.28000
456	35.04000
457	457.70000
458	285.02000
459	422.05000
460	521.89000
461	239.03000
462	348.52000
463	43.80000
464	383.57000
465	102.61000
466	47.86000
467	348.52000
468	87.28000
469	87.28000
470	70.39000
471	61.00000
472	26.51000
473	17.05000
474	35.04000
475	1,970.40000
476	85.40000
477	6.95000
478	115.12000
479	185.20000
480	27.22000
481	812.49000

501	501			
211		50.000000 x	1.243100 =	62.155000
214		3.000000 x	4.550000 =	13.650000
118		3.000000 x	10.001019 =	30.003057
114		8.000000 x	23.886192 =	191.089536
401		1.000000 x	268.420000 =	268.420000

			ΑΘΡΟΙΣΜΑ =	565.317593

			Η.Δ. =	621.849352
502	502			
211		80.000000 x	1.243100 =	99.448000
214		7.000000 x	4.550000 =	31.850000
402		1.000000 x	380.180000 =	380.180000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.886192 =	191.089536

			ΑΘΡΟΙΣΜΑ =	742.571612

			Η.Δ. =	816.828773
503	503			
211		110.000000 x	1.243100 =	136.741000
214		10.000000 x	4.550000 =	45.500000
114		8.000000 x	23.886192 =	191.089536
428		1.000000 x	437.840000 =	437.840000
118		4.000000 x	10.001019 =	40.004076

			ΑΘΡΟΙΣΜΑ =	851.174612

			Η.Δ. =	936.292073
504	504			
211		40.000000 x	1.243100 =	49.724000
214		2.000000 x	4.550000 =	9.100000
114		8.000000 x	23.886192 =	191.089536
403		1.000000 x	103.360000 =	103.360000

			ΑΘΡΟΙΣΜΑ =	353.273536

			Η.Δ. =	388.600890
505	505			
211		200.000000 x	1.243100 =	248.620000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
404		1.000000 x	212.730000 =	212.730000
214		10.000000 x	4.550000 =	45.500000

			ΑΘΡΟΙΣΜΑ =	777.947688

			Η.Δ. =	855.742457

506	506			
211		95.000000 x	1.243100 =	118.094500
405		1.000000 x	206.720000 =	206.720000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
242		2.500000 x	4.500000 =	11.250000
214		6.000000 x	4.550000 =	27.300000

			ΑΘΡΟΙΣΜΑ =	634.462188

			Η.Δ. =	697.908407
507	507			
211		165.000000 x	1.243100 =	205.111500
406		1.000000 x	320.980000 =	320.980000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
242		7.000000 x	4.500000 =	31.500000
214		10.000000 x	4.550000 =	45.500000

			ΑΘΡΟΙΣΜΑ =	874.189188

			Η.Δ. =	961.608107
508	508			
211		40.000000 x	1.243100 =	49.724000
407		1.000000 x	55.210000 =	55.210000
115		4.000000 x	21.778427 =	87.113708
116		16.000000 x	20.419486 =	326.711776
408		2.000000 x	4.530000 =	9.060000
214		2.000000 x	4.550000 =	9.100000

			ΑΘΡΟΙΣΜΑ =	536.919484

			Η.Δ. =	590.611432
509	509			
211		80.000000 x	1.243100 =	99.448000
117		8.000000 x	16.777917 =	134.223336
409		1.000000 x	126.080000 =	126.080000
214		5.000000 x	4.550000 =	22.750000

			ΑΘΡΟΙΣΜΑ =	382.501336

			Η.Δ. =	420.751470
510	510			
211		80.000000 x	1.243100 =	99.448000
117		8.000000 x	16.777917 =	134.223336
410		1.000000 x	116.530000 =	116.530000
214		5.000000 x	4.550000 =	22.750000

			ΑΘΡΟΙΣΜΑ =	372.951336

			Η.Δ. =	410.246470

511	511			
212		17.000000 x	1.434100 =	24.379700
112		30.000000 x	17.312112 =	519.363360
115		4.000000 x	21.778427 =	87.113708
214		1.000000 x	4.550000 =	4.550000
411		1.000000 x	27.370000 =	27.370000

				ΑΘΡΟΙΣΜΑ = 662.776768

				Η.Δ. = 729.054445
512	512			
211		10.000000 x	1.243100 =	12.431000
115		2.000000 x	21.778427 =	43.556854
112		2.000000 x	17.312112 =	34.624224
214		1.000000 x	4.550000 =	4.550000
412		1.000000 x	2.990000 =	2.990000

				ΑΘΡΟΙΣΜΑ = 98.152078

				Η.Δ. = 107.967286
513	513			
211		15.000000 x	1.243100 =	18.646500
115		3.000000 x	21.778427 =	65.335281
112		3.000000 x	17.312112 =	51.936336
214		1.500000 x	4.550000 =	6.825000
413		1.000000 x	4.530000 =	4.530000

				ΑΘΡΟΙΣΜΑ = 147.273117

				Η.Δ. = 162.000429
514	514			
211		21.000000 x	1.243100 =	26.105100
115		4.000000 x	21.778427 =	87.113708
112		4.000000 x	17.312112 =	69.248448
414		1.000000 x	6.250000 =	6.250000
214		2.000000 x	4.550000 =	9.100000

				ΑΘΡΟΙΣΜΑ = 197.817256

				Η.Δ. = 217.598982
515	515			
211		27.000000 x	1.243100 =	33.563700
214		2.500000 x	4.550000 =	11.375000
112		6.000000 x	17.312112 =	103.872672
115		5.000000 x	21.778427 =	108.892135
415		1.000000 x	8.780000 =	8.780000

				ΑΘΡΟΙΣΜΑ = 266.483507

				Η.Δ. = 293.131858

516	516			
211		33.000000 x	1.243100 =	41.022300
214		3.500000 x	4.550000 =	15.925000
115		6.000000 x	21.778427 =	130.670562
112		8.000000 x	17.312112 =	138.496896
416		1.000000 x	13.540000 =	13.540000

			ΑΘΡΟΙΣΜΑ =	339.654758

			Η.Δ. =	373.620234
517	517			
211		240.000000 x	1.243100 =	298.344000
406		.400000 x	320.980000 =	128.392000
116		8.000000 x	20.419486 =	163.355888
115		8.000000 x	21.778427 =	174.227416
114		8.000000 x	23.886192 =	191.089536
113		2.000000 x	20.419486 =	40.838972
112		16.000000 x	17.312112 =	276.993792
111		16.000000 x	15.741598 =	251.865568
407		2.000000 x	55.210000 =	110.420000
406		1.000000 x	320.980000 =	320.980000
214		8.000000 x	4.550000 =	36.400000
251		.150000 x	290.000000 =	43.500000

			ΑΘΡΟΙΣΜΑ =	2,036.407172

			Η.Δ. =	2,240.047889
518	518			
211		180.000000 x	1.243100 =	223.758000
214		12.000000 x	4.550000 =	54.600000
417		1.000000 x	134.530000 =	134.530000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
112		8.000000 x	17.312112 =	138.496896
212		5.000000 x	1.434100 =	7.170500

			ΑΘΡΟΙΣΜΑ =	829.653084

			Η.Δ. =	912.618392
520	520			
211		80.000000 x	1.243100 =	99.448000
118		4.000000 x	10.001019 =	40.004076
115		8.000000 x	21.778427 =	174.227416
112		4.000000 x	17.312112 =	69.248448
419		1.000000 x	4.530000 =	4.530000
214		5.000000 x	4.550000 =	22.750000
212		2.000000 x	1.434100 =	2.868200

			ΑΘΡΟΙΣΜΑ =	413.076140

			Η.Δ. =	454.383754

521	521			
211		40.000000 x	1.243100 =	49.724000
214		3.000000 x	4.550000 =	13.650000
420		1.000000 x	97.290000 =	97.290000
114		8.000000 x	23.886192 =	191.089536
118		4.000000 x	10.001019 =	40.004076

			ΑΘΡΟΙΣΜΑ =	391.757612

			Η.Δ. =	430.933373
522	522			
211		20.000000 x	1.243100 =	24.862000
214		2.000000 x	4.550000 =	9.100000
118		2.000000 x	10.001019 =	20.002038
114		8.000000 x	23.886192 =	191.089536
421		1.000000 x	32.560000 =	32.560000

			ΑΘΡΟΙΣΜΑ =	277.613574

			Η.Δ. =	305.374931
529	529			
211		70.000000 x	1.243100 =	87.017000
114		8.000000 x	23.886192 =	191.089536
429		1.000000 x	77.590000 =	77.590000
118		4.000000 x	10.001019 =	40.004076
214		4.000000 x	4.550000 =	18.200000

			ΑΘΡΟΙΣΜΑ =	413.900612

			Η.Δ. =	455.290673
550	550			
211		90.000000 x	1.243100 =	111.879000
214		4.000000 x	4.550000 =	18.200000
116		32.000000 x	20.419486 =	653.423552
115		4.000000 x	21.778427 =	87.113708
451		4.000000 x	4.870000 =	19.480000
450		1.000000 x	83.850000 =	83.850000

			ΑΘΡΟΙΣΜΑ =	973.946260

			Η.Δ. =	1,071.340886
551	551			
211		95.000000 x	1.243100 =	118.094500
118		8.000000 x	10.001019 =	80.008152
452		1.000000 x	103.060000 =	103.060000
114		8.000000 x	23.886192 =	191.089536
214		6.000000 x	4.550000 =	27.300000
405		1.000000 x	206.720000 =	206.720000

			ΑΘΡΟΙΣΜΑ =	726.272188

			Η.Δ. =	798.899407

552	552			
211		18.000000 x	1.243100 =	22.375800
453		1.000000 x	.000000 =	.000000
115		8.000000 x	21.778427 =	174.227416
214		1.000000 x	4.550000 =	4.550000

			ΑΘΡΟΙΣΜΑ =	201.153216

			Η.Δ. =	
553	553			
211		100.000000 x	1.243100 =	124.310000
454		1.000000 x	97.290000 =	97.290000
214		4.000000 x	4.550000 =	18.200000

			ΑΘΡΟΙΣΜΑ =	239.800000

			Η.Δ. =	263.780000
554	554			
455		1.000000 x	31.280000 =	31.280000

			ΑΘΡΟΙΣΜΑ =	31.280000

			Η.Δ. =	34.408000
555	555			
212		17.000000 x	1.434100 =	24.379700
112		32.000000 x	17.312112 =	553.987584
115		4.000000 x	21.778427 =	87.113708
214		1.000000 x	4.550000 =	4.550000
456		1.000000 x	35.040000 =	35.040000

			ΑΘΡΟΙΣΜΑ =	705.070992

			Η.Δ. =	775.578091
556	556			
211		200.000000 x	1.243100 =	248.620000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
214		18.000000 x	4.550000 =	81.900000
457		1.000000 x	457.700000 =	457.700000

			ΑΘΡΟΙΣΜΑ =	1,059.317688

			Η.Δ. =	1,165.249457
557	557			
211		130.000000 x	1.243100 =	161.603000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
458		1.000000 x	285.020000 =	285.020000
214		11.000000 x	4.550000 =	50.050000

			ΑΘΡΟΙΣΜΑ =	767.770688

			Η.Δ. =	844.547757

558	558			
211		200.000000 x	1.243100 =	248.620000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
459		1.000000 x	422.050000 =	422.050000
242		9.500000 x	4.500000 =	42.750000
214		12.000000 x	4.550000 =	54.600000

			ΑΘΡΟΙΣΜΑ =	1,039.117688

			Η.Δ. =	1,143.029457
559	559			
211		250.000000 x	1.243100 =	310.775000
460		1.000000 x	521.890000 =	521.890000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
214		15.000000 x	4.550000 =	68.250000
242		12.000000 x	4.500000 =	54.000000

			ΑΘΡΟΙΣΜΑ =	1,226.012688

			Η.Δ. =	1,348.613957
560	560			
211		160.000000 x	1.243100 =	198.896000
461		1.000000 x	239.030000 =	239.030000
114		8.000000 x	23.886192 =	191.089536
214		8.000000 x	4.550000 =	36.400000

			ΑΘΡΟΙΣΜΑ =	665.415536

			Η.Δ. =	731.957090
561	561			
211		230.000000 x	1.243100 =	285.913000
114		8.000000 x	23.886192 =	191.089536
462		1.000000 x	348.520000 =	348.520000
214		12.000000 x	4.550000 =	54.600000

			ΑΘΡΟΙΣΜΑ =	880.122536

			Η.Δ. =	968.134790
562	562			
211		50.000000 x	1.243100 =	62.155000
463		1.000000 x	43.800000 =	43.800000
214		2.400000 x	4.550000 =	10.920000

			ΑΘΡΟΙΣΜΑ =	116.875000

			Η.Δ. =	128.562500

563	563				
214		16.000000 x	4.550000 =	72.800000	
114		16.000000 x	23.886192 =	382.179072	
112		24.000000 x	17.312112 =	415.490688	
211.1		640.000000 x	.000000 =	.000000	
464		1.000000 x	383.570000 =	383.570000	
			ΑΘΡΟΙΣΜΑ =	1,254.039760	
			Η.Δ. =		
564	564				
465		1.000000 x	102.610000 =	102.610000	
567		3.000000 x	407.320272 =	1,221.960816	
115		8.000000 x	21.778427 =	174.227416	
115		8.000000 x	21.778427 =	174.227416	
111		8.000000 x	15.741598 =	125.932784	
			ΑΘΡΟΙΣΜΑ =	1,798.958432	
			Η.Δ. =	1,978.854275	
565	565				
450		3.000000 x	83.850000 =	251.550000	
465		1.000000 x	102.610000 =	102.610000	
115		8.000000 x	21.778427 =	174.227416	
115		12.000000 x	21.778427 =	261.341124	
			Η.Δ. =	789.728540	
566	566				
211.1		680.000000 x	.000000 =	.000000	
112		1.000000 x	17.312112 =	17.312112	
115		2.000000 x	21.778427 =	43.556854	
466		1.000000 x	47.860000 =	47.860000	
			ΑΘΡΟΙΣΜΑ =	108.728966	
			Η.Δ. =		
567	567				
211		90.000000 x	1.243100 =	111.879000	
450		1.000000 x	83.850000 =	83.850000	
115		4.000000 x	21.778427 =	87.113708	
112		4.000000 x	17.312112 =	69.248448	
214		4.000000 x	4.550000 =	18.200000	
			ΑΘΡΟΙΣΜΑ =	370.291156	
			Η.Δ. =	407.320272	

568.1	568.1			
214		16.000000 x	4.550000 =	72.800000
113		32.000000 x	20.419486 =	653.423552
114		8.000000 x	23.886192 =	191.089536
510		.072000 x	410.246470 =	29.537746
567		2.000000 x	407.320272 =	814.640544
512		.240000 x	107.967286 =	25.912149
118		32.000000 x	10.001019 =	320.032608
467		1.000000 x	348.520000 =	348.520000

			ΑΘΡΟΙΣΜΑ =	2,455.956134

			Η.Δ. =	2,701.551748
568.2	568.2			
450		2.000000 x	83.850000 =	167.700000
115		8.000000 x	21.778427 =	174.227416
114		8.000000 x	23.886192 =	191.089536
467		1.000000 x	348.520000 =	348.520000

			Η.Δ. =	881.536952
569.1	569.1			
214		16.000000 x	4.550000 =	72.800000
567		2.000000 x	407.320272 =	814.640544
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
468		1.000000 x	87.280000 =	87.280000

			ΑΘΡΟΙΣΜΑ =	1,245.818232

			Η.Δ. =	1,370.400055
569.2	569.2			
450		2.000000 x	83.850000 =	167.700000
468		1.000000 x	87.280000 =	87.280000
114		8.000000 x	23.886192 =	191.089536
115		8.000000 x	21.778427 =	174.227416

			Η.Δ. =	620.296952
570.1	570.1			
211		135.000000 x	1.243100 =	167.818500
114		8.000000 x	23.886192 =	191.089536
214		16.000000 x	4.550000 =	72.800000
118		4.000000 x	10.001019 =	40.004076
469		1.000000 x	87.280000 =	87.280000

			ΑΘΡΟΙΣΜΑ =	558.992112

			Η.Δ. =	614.891323

570.2	570.2			
469		1.000000 x	87.280000 =	87.280000
118		4.000000 x	10.001019 =	40.004076

			H.Δ. =	127.284076
571.1	571.1			
211		114.000000 x	1.243100 =	141.713400
114		8.000000 x	23.886192 =	191.089536
470		1.000000 x	70.390000 =	70.390000
214		4.000000 x	4.550000 =	18.200000

			ΑΘΡΟΙΣΜΑ =	421.392936

			H.Δ. =	463.532230
571.2	571.2			
470		1.000000 x	70.390000 =	70.390000
114		8.000000 x	23.886192 =	191.089536

			H.Δ. =	261.479536
572	572			
211		54.000000 x	1.243100 =	67.127400
111		24.000000 x	15.741598 =	377.798352
407		1.000000 x	55.210000 =	55.210000
114		8.000000 x	23.886192 =	191.089536
471		1.000000 x	61.000000 =	61.000000
214		8.000000 x	4.550000 =	36.400000

			ΑΘΡΟΙΣΜΑ =	788.625288

			H.Δ. =	867.487817
573	573			
211		54.000000 x	1.243100 =	67.127400
111		24.000000 x	15.741598 =	377.798352
474		.250000 x	35.040000 =	8.760000
474		1.000000 x	35.040000 =	35.040000
473		.250000 x	17.050000 =	4.262500
473		1.000000 x	17.050000 =	17.050000
472		.250000 x	26.510000 =	6.627500
407		.250000 x	55.210000 =	13.802500
407		1.000000 x	55.210000 =	55.210000
115		16.000000 x	21.778427 =	348.454832
214		8.000000 x	4.550000 =	36.400000
472		1.000000 x	26.510000 =	26.510000

			ΑΘΡΟΙΣΜΑ =	997.043084

			H.Δ. =	1,096.747392

574	574			
211		590.000000 x	1.243100 =	733.429000
475		1.000000 x	1,970.400000 =	1,970.400000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
111		16.000000 x	15.741598 =	251.865568
242		7.000000 x	4.500000 =	31.500000
214		30.000000 x	4.550000 =	136.500000

			ΑΘΡΟΙΣΜΑ =	3,394.792256

			Η.Δ. =	3,734.271482
574.1	574.1			
475		1.000000 x	1,970.400000 =	1,970.400000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152

			Η.Δ. =	2,241.497688
575	575			
211		470.000000 x	1.243100 =	584.257000
115		8.000000 x	21.778427 =	174.227416
476		1.000000 x	85.400000 =	85.400000
214		23.000000 x	4.550000 =	104.650000

			ΑΘΡΟΙΣΜΑ =	948.534416

			Η.Δ. =	1,043.387858
575.1	575.1			
476		1.000000 x	85.400000 =	85.400000
115		8.000000 x	21.778427 =	174.227416

			Η.Δ. =	259.627416
576	576			
477		1.000000 x	6.950000 =	6.950000

			ΑΘΡΟΙΣΜΑ =	6.950000

			Η.Δ. =	7.645000
576.1	576.1			
477		1.000000 x	6.950000 =	6.950000

			Η.Δ. =	6.950000

577	577			
211		70.000000 x	1.243100 =	87.017000
242		2.000000 x	4.500000 =	9.000000
478		1.000000 x	115.120000 =	115.120000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
111		8.000000 x	15.741598 =	125.932784
214		4.000000 x	4.550000 =	18.200000

				ΑΘΡΟΙΣΜΑ = 626.367472

				Η.Δ. = 689.004219
577.1	577.1			
478		1.000000 x	115.120000 =	115.120000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152

				Η.Δ. = 386.217688
578	578			
211		50.000000 x	1.243100 =	62.155000
214		5.000000 x	4.550000 =	22.750000
114		8.000000 x	23.886192 =	191.089536
118		4.000000 x	10.001019 =	40.004076
112		4.000000 x	17.312112 =	69.248448
479		1.000000 x	185.200000 =	185.200000
242		5.000000 x	4.500000 =	22.500000

				ΑΘΡΟΙΣΜΑ = 592.947060

				Η.Δ. = 652.241766
579	579			
212		28.000000 x	1.434100 =	40.154800
480		1.000000 x	27.220000 =	27.220000
117		8.000000 x	16.777917 =	134.223336
214		1.000000 x	4.550000 =	4.550000

				ΑΘΡΟΙΣΜΑ = 206.148136

				Η.Δ. = 226.762950
580	580			
211		168.000000 x	1.243100 =	208.840800
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
111		16.000000 x	15.741598 =	251.865568
481		1.000000 x	812.490000 =	812.490000
242		2.000000 x	4.500000 =	9.000000
214		8.000000 x	4.550000 =	36.400000

				ΑΘΡΟΙΣΜΑ = 1,589.694056

				Η.Δ. = 1,748.663462

581	581			
481		1.000000 x	812.490000 =	812.490000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152

			H.Δ. =	1,083.587688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
568.2		.550000 x	881.536952 =	484.845324
569.2		.670000 x	620.296952 =	415.598958
571.2		.150000 x	261.479536 =	39.221930
571.1		.350000 x	463.532230 =	162.236281
570.2		.350000 x	127.284076 =	44.549427
570.1		.150000 x	614.891323 =	92.233698
569.1		.330000 x	1,370.400055 =	452.232018
568.1		.450000 x	2,701.551748 =	1,215.698287
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	407.320272 =	407.320272

			H.Δ. =	3,603.224866
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.250000 x	2,701.551748 =	675.387937
569.1		.250000 x	1,370.400055 =	342.600014
571.2		.240000 x	261.479536 =	62.755089
571.1		.260000 x	463.532230 =	120.518380
570.2		.390000 x	127.284076 =	49.640790
570.1		.110000 x	614.891323 =	67.638046
569.2		.750000 x	620.296952 =	465.222714
568.2		.750000 x	881.536952 =	661.152714
567		1.000000 x	407.320272 =	407.320272
116		8.000000 x	20.419486 =	163.355888

			H.Δ. =	3,141.524626
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
568.1		.150000 x	2,701.551748 =	405.232762
569.1		.180000 x	1,370.400055 =	246.672010
571.2		.310000 x	261.479536 =	81.058656
571.1		.190000 x	463.532230 =	88.071124
570.2		.420000 x	127.284076 =	53.459312
570.1		.080000 x	614.891323 =	49.191306
569.2		.820000 x	620.296952 =	508.643501
568.2		.850000 x	881.536952 =	749.306409
567		1.000000 x	407.320272 =	407.320272
116		8.000000 x	20.419486 =	163.355888

			H.Δ. =	2,878.244024

613	613			
111		.140000 x	15.741598 =	2.203824
504		.002800 x	388.600890 =	1.088082
503		.000770 x	936.292073 =	.720945
520		.003500 x	454.383754 =	1.590343

			B.T =	5.603194
614	614			
112		.070000 x	17.312112 =	1.211848
503		.000700 x	936.292073 =	.655404
518		.004375 x	912.618392 =	3.992705
509		.004375 x	420.751470 =	1.840788
504		.002800 x	388.600890 =	1.088082

			B.T =	8.788828
621.1	621.1			
213		.100000 x	1.949500 =	.194950
116		.140000 x	20.419486 =	2.858728
504		.003500 x	388.600890 =	1.360103
508		.003500 x	590.611432 =	2.067140
111		.560000 x	15.741598 =	8.815295

			B.T =	15.296216
622	622			
213		.100000 x	1.949500 =	.194950
518		.004340 x	912.618392 =	3.960764
509		.003500 x	420.751470 =	1.472630
508		.003500 x	590.611432 =	2.067140
504		.003500 x	388.600890 =	1.360103
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	13.126163
6360.1 A1	6360.1 A1			
6304		9.800000 x	5.646657 =	55.337239
6314		.382500 x	2.030705 =	.776745
6314		7.650000 x	2.030705 =	15.534893
6330		.038000 x	182.637305 =	6.940218
6330		.190000 x	182.637305 =	34.701088

			B.T =	113.290182
6360.1 A2	6360.1 A2			
6304		.450000 x	5.646657 =	2.540996
6330		.013000 x	182.637305 =	2.374285
6310		2.142000 x	1.454463 =	3.115460

			B.T =	8.030740

6360.1 A3	6360.1 A3			
6304		.960000 x	5.646657 =	5.420791
6310		1.974000 x	1.454463 =	2.871110
6329.2		.037000 x	168.089342 =	6.219306

			B.T =	14.511206
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.646657 =	14.060176
6329.2		.109000 x	168.089342 =	18.321738

			B.T =	32.381914
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
113		.425000 x	20.419486 =	8.678282
6069.1		.056400 x	11.887206 =	.670438

			B.T =	99.527281
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.646657 =	60.136897
6314		.392500 x	2.030705 =	.797052
6330		.205000 x	182.637305 =	37.440648
6330		.041000 x	182.637305 =	7.488130
6314		7.850000 x	2.030705 =	15.941034

			B.T =	121.803760
6360.2 A2	6360.2 A2			
6304		.750000 x	5.646657 =	4.234993
6310		2.383500 x	1.454463 =	3.466713
6330		.019000 x	182.637305 =	3.470109

			B.T =	11.171814
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.646657 =	6.437189
6310		2.341500 x	1.454463 =	3.405625
6329.2		.054000 x	168.089342 =	9.076824

			B.T =	18.919639
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.646657 =	15.810640
6329.2		.118000 x	168.089342 =	19.834542

			B.T =	35.645182

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
6069.1		.059400 x	11.887206 =	.706100
113		2.975000 x	20.419486 =	60.747971
113		.382500 x	20.419486 =	7.810453
			B.T =	113.410410
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.646657 =	78.488532
6330		.270000 x	182.637305 =	49.312072
6314		.557500 x	2.030705 =	1.132118
6330		.054000 x	182.637305 =	9.862414
6314		11.150000 x	2.030705 =	22.642361
			B.T =	161.437498
6360.3 A2	6360.3 A2			
6304		.940000 x	5.646657 =	5.307858
6330		.031000 x	182.637305 =	5.661756
6310		3.360000 x	1.454463 =	4.886996
			B.T =	15.856610
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.646657 =	10.333382
6310		10.678500 x	1.454463 =	15.531483
6329.2		.099000 x	168.089342 =	16.640845
			B.T =	42.505710
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.646657 =	19.311567
6329.2		.139000 x	168.089342 =	23.364419
			B.T =	42.675985
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.887206 =	.877276
113		.340000 x	20.419486 =	6.942625
			B.T =	156.859643

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.646657 =	91.758176
6314		17.700000 x	2.030705 =	35.943479
6330		.075000 x	182.637305 =	13.697798
6330		.375000 x	182.637305 =	68.488989
6314		.885000 x	2.030705 =	1.797174

			B.T =	211.685616
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.646657 =	5.985456
6310		4.641000 x	1.454463 =	6.750163
6330		.048000 x	182.637305 =	8.766591

			B.T =	21.502210
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.646657 =	12.817911
6329.2		.125000 x	168.089342 =	21.011168
6310		20.454000 x	1.454463 =	29.749586

			B.T =	63.578665
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.646657 =	15.810640
6329.2		.118000 x	168.089342 =	19.834542

			B.T =	35.645182
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		4.250000 x	20.419486 =	86.782816
6069.1		.091800 x	11.887206 =	1.091246
113		.297500 x	20.419486 =	6.074797

			B.T =	211.671220
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.646657 =	101.357493
6330		.440000 x	182.637305 =	80.360414
6330		.088000 x	182.637305 =	16.072083
6314		21.000000 x	2.030705 =	42.644805
6314		1.050000 x	2.030705 =	2.132240

			B.T =	242.567035
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.646657 =	6.888922
6330		.061000 x	182.637305 =	11.140876
6310		6.048000 x	1.454463 =	8.796592

			B.T =	26.826389

6360.5 A3	6360.5 A3			
6304		2.480000 x	5.646657 =	14.003709
6329.2		.144000 x	168.089342 =	24.204865
6310		22.291500 x	1.454463 =	32.422162

			B.T =	70.630737
6360.5 A4	6360.5 A4			
6304		3.200000 x	5.646657 =	18.069302
6329.2		.112000 x	168.089342 =	18.826006

			B.T =	36.895309
6360.5 A5	6360.5 A5			
112		9.350000 x	17.312112 =	161.868247
113		5.950000 x	20.419486 =	121.495942
6069.1		.090600 x	11.887206 =	1.076981
113		.255000 x	20.419486 =	5.206969

			B.T =	289.648139
6360.6 A1	6360.6 A1			
6304		20.350000 x	5.646657 =	114.909470
6330		.116000 x	182.637305 =	21.185927
6330		.580000 x	182.637305 =	105.929637
6314		1.245000 x	2.030705 =	2.528228
6314		24.900000 x	2.030705 =	50.564555

			B.T =	295.117816
6360.6 A2	6360.6 A2			
6304		1.530000 x	5.646657 =	8.639385
6310		10.206000 x	1.454463 =	14.844249
6330		.092000 x	182.637305 =	16.802632

			B.T =	40.286267
6360.6 A3	6360.6 A3			
6304		2.670000 x	5.646657 =	15.076574
6329.2		.181000 x	168.089342 =	30.424171
6310		25.798500 x	1.454463 =	37.522964

			B.T =	83.023709
6360.6 A4	6360.6 A4			
6304		2.800000 x	5.646657 =	15.810640
6329.2		.118000 x	168.089342 =	19.834542

			B.T =	35.645182

6360.6 A5	6360.6 A5			
112		12.750000 x	17.312112 =	220.729428
113		.212500 x	20.419486 =	4.339141
6069.1		.120000 x	11.887206 =	1.426465
113		7.650000 x	20.419486 =	156.209068

			B.T =	382.704101
641	641			
231		.200000 x	.895000 =	.179000
113		.127500 x	20.419486 =	2.603484
251		.001500 x	290.000000 =	.435000
111		.170000 x	15.741598 =	2.676072
252		.002500 x	290.000000 =	.725000

			B.T =	6.618556
651	651			
221		150.000000 x	.099900 =	14.985000
224		120.000000 x	.070000 =	8.400000
T 630		.600000 x	1.835444 =	1.101266
T 625		.850000 x	22.180515 =	18.853438
511		.042500 x	729.054445 =	30.984814
509		.003060 x	420.751470 =	1.287499
509		.009435 x	420.751470 =	3.969790
112		.425000 x	17.312112 =	7.357648
111		1.275000 x	15.741598 =	20.070537

			B.T =	107.009993
652	652			
221		650.000000 x	.099900 =	64.935000
111		1.275000 x	15.741598 =	20.070537
T 630		.320000 x	1.835444 =	.587342
T 625		1.000000 x	22.180515 =	22.180515
511		.042500 x	729.054445 =	30.984814
509		.001632 x	420.751470 =	.686666
509		.009435 x	420.751470 =	3.969790
112		.425000 x	17.312112 =	7.357648

			B.T =	150.772313
652.1	652.1			
221		450.000000 x	.099900 =	44.955000
111		1.275000 x	15.741598 =	20.070537
112		.425000 x	17.312112 =	7.357648
T 630		.320000 x	1.835444 =	.587342
T 625		1.060000 x	22.180515 =	23.511346
511		.042500 x	729.054445 =	30.984814
510		.001632 x	410.246470 =	.669522
509		.010001 x	420.751470 =	4.207935

			B.T =	132.344145

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
111		1.275000 x	15.741598 =	20.070537
509		.007548 x	420.751470 =	3.175832
112		.425000 x	17.312112 =	7.357648
T 625		.800000 x	22.180515 =	17.744412
T 630		.320000 x	1.835444 =	.587342
511		.042500 x	729.054445 =	30.984814
510		.001632 x	410.246470 =	.669522
			B.T =	170.500107
700	700			
221		13.000000 x	.099900 =	1.298700
397.5		2.150000 x	.000000 =	.000000
113		.935000 x	20.419486 =	19.092219
397.4		4.000000 x	.167500 =	.670000
324		7.650000 x	.580000 =	4.437000
			B.T =	
7001 A	7001 A			
502		.000365 x	816.828773 =	.298143
557		.001094 x	844.547757 =	.923935
			AΘΡΟΙΣΜΑ =	1.222078
	B.T =	.200000 x	1.222078 =	.244416
7001 B	7001 B			
558		.000700 x	1,143.029457 =	.800121
			B.T =	.800121
7001 E	7001 E			
503		.000875 x	936.292073 =	.819256
554		.000875 x	34.408000 =	.030107
			B.T =	.849363
7001 Γ	7001 Γ			
501		.000700 x	621.849352 =	.435295
502		.000700 x	816.828773 =	.571780
			B.T =	1.007075

7001 Δ	7001 Δ			
502		.000292 x	816.828773 =	.238514
X 630.1		.060000 x	1.723035 =	.103382
X 630		.060000 x	1.511542 =	.090693
510		.000292 x	410.246470 =	.119792

			AΘΡΟΙΣΜΑ =	.552381
	B.T =	.600000 x	.552381 =	.331428

7003 Α	7003 Α			
502		.000365 x	816.828773 =	.298143
557		.001094 x	844.547757 =	.923935

			AΘΡΟΙΣΜΑ =	1.222078
	B.T =	.100000 x	1.222078 =	.122208

7003 Β	7003 Β			
559		.000464 x	1,348.613957 =	.625757

			B.T =	.625757
7003 Γ	7003 Γ			
502		.000700 x	816.828773 =	.571780

			B.T =	.571780
7003 Δ	7003 Δ			
502		.000875 x	816.828773 =	.714725
562		.000875 x	128.562500 =	.112492

			B.T =	.827217
7005 Α	7005 Α			
502		.000365 x	816.828773 =	.298143
557		.001094 x	844.547757 =	.923935

			AΘΡΟΙΣΜΑ =	1.222078
	B.T =	.100000 x	1.222078 =	.122208

7005 Β	7005 Β			
559		.000812 x	1,348.613957 =	1.095075

			B.T =	1.095075
7005 Ε	7005 Ε			
502		.000875 x	816.828773 =	.714725
562		.000875 x	128.562500 =	.112492

			B.T =	.827217

7005 Γ	7005 Γ			
559		.000232 x	1,348.613957 =	.312878

			B.T =	.312878
7005 Δ	7005 Δ			
502		.000700 x	816.828773 =	.571780

			B.T =	.571780
7010 Α	7010 Α			
558		.000315 x	1,143.029457 =	.360054

			B.T =	.360054
7010 Β	7010 Β			
558		.000473 x	1,143.029457 =	.540653

			B.T =	.540653
7010 Ε	7010 Ε			
503		.000875 x	936.292073 =	.819256
553		.000875 x	263.780000 =	.230808

			B.T =	1.050063
7010 Γ	7010 Γ			
502		.000700 x	816.828773 =	.571780

			B.T =	.571780
7010 Δ	7010 Δ			
502		.000292 x	816.828773 =	.238514
X 630		.060000 x	1.511542 =	.090693
510		.000292 x	410.246470 =	.119792
X 630.1		.060000 x	1.723035 =	.103382

			AΘΡΟΙΣΜΑ =	.552381
	B.T =	.600000 x	.552381 =	.331428

7016.1	7016.1			
223		350.000000 x	.119300 =	41.755000
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.830000 x	18.844895 =	15.641263
T 617		.500000 x	6.498380 =	3.249190
509		.007831 x	420.751470 =	3.294905
509		.004718 x	420.751470 =	1.985105

			B.T =	79.297388

7016.2	7016.2			
570.1		.586500 x	614.891323 =	360.633761
570.2		1.113500 x	127.284076 =	141.730819
571.1		.586500 x	463.532230 =	271.861653
571.2		1.113500 x	261.479536 =	291.157463

			ΑΘΡΟΙΣΜΑ =	1,065.383696
	B.T =	.025000 x	1,065.383696 =	26.634592

7016.3	7016.3			
564		.212500 x	1,978.854275 =	420.506533
565		.637500 x	789.728540 =	503.451944

			ΑΘΡΟΙΣΜΑ =	923.958478
	B.T =	.025000 x	923.958478 =	23.098962

7016.4	7016.4			
7016.1		1.000000 x	79.297388 =	79.297388
7016.3		1.000000 x	23.098962 =	23.098962
7016.2		1.000000 x	26.634592 =	26.634592

			B.T =	129.030942
7016.5	7016.5			
7016.4		.200000 x	129.030942 =	25.806188

			B.T =	25.806188
7016.6	7016.6			
7016.4		.250000 x	129.030942 =	32.257736
7016.5		.250000 x	25.806188 =	6.451547

			B.T =	38.709283
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
223		350.000000 x	.119300 =	41.755000
509		.004718 x	420.751470 =	1.985105
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.830000 x	18.844895 =	15.641263
T 617		.500000 x	6.498380 =	3.249190
509		.007831 x	420.751470 =	3.294905
396.5		10.500000 x	1.180000 =	12.390000
			B.T =	79.297388
7017.2	7017.2			
564		.425000 x	1,978.854275 =	841.013067
565		.425000 x	789.728540 =	335.634630
			AΘΡΟΙΣΜΑ =	1,176.647696
	B.T =	.012500 x	1,176.647696 =	14.708096
7017.3	7017.3			
7017.1		1.000000 x	79.297388 =	79.297388
7017.2		1.000000 x	14.708096 =	14.708096
			B.T =	94.005484
7017.4	7017.4			
7017.3		.200000 x	94.005484 =	18.801097
			B.T =	18.801097
7017.5	7017.5			
7017.3		.300000 x	94.005484 =	28.201645
7017.4		.300000 x	18.801097 =	5.640329
			B.T =	33.841974
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150
			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689
			B.T =	52.069689

7019 A1	7019 A1			
223		350.000000 x	.119300 =	41.755000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
509		.004718 x	420.751470 =	1.985105
509		.007548 x	420.751470 =	3.175832
396.5		5.000000 x	1.180000 =	5.900000
			B.T =	79.964036
7019 A2	7019 A2			
555		.012143 x	775.578091 =	9.417845
			B.T =	9.417845
7019 A3	7019 A3			
570.1		.850000 x	614.891323 =	522.657625
571.2		.850000 x	261.479536 =	222.257606
571.1		.850000 x	463.532230 =	394.002396
570.2		.850000 x	127.284076 =	108.191465
			ΑΘΡΟΙΣΜΑ =	1,247.109090
	B.T =	.014286 x	1,247.109090 =	17.816200
7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563
			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	79.964036 =	79.964036
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A5		1.000000 x	17.356563 =	17.356563
7019 A3		1.000000 x	17.816200 =	17.816200
7019 A2		1.000000 x	9.417845 =	9.417845
			B.T =	193.792098
7019 A7	7019 A7			
7019 A6		.100000 x	193.792098 =	19.379210
			B.T =	19.379210

710	710			
252		.001000 x	290.000000 =	.290000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
397.3		.006660 x	.000000 =	.000000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	388.600890 =	1.952719
509		.003750 x	420.751470 =	1.577818

			B.T =	3.530537
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
503		.001190 x	936.292073 =	1.114188
520		.005270 x	454.383754 =	2.394602
504		.004250 x	388.600890 =	1.651554

			B.T =	6.498380
T 621	T 621			
213		.100000 x	1.949500 =	.194950
111		.680000 x	15.741598 =	10.704287
508		.004250 x	590.611432 =	2.510099
116		.170000 x	20.419486 =	3.471313

			B.T =	16.880648
T 623	T 623			
213		.100000 x	1.949500 =	.194950
116		.170000 x	20.419486 =	3.471313
112		.085000 x	17.312112 =	1.471530
504		.004250 x	388.600890 =	1.651554
508		.004250 x	590.611432 =	2.510099
509		.004250 x	420.751470 =	1.788194
518		.008500 x	912.618392 =	7.757256

			B.T =	18.844895

T 625	T 625			
213		.100000 x	1.949500 =	.194950
112		.085000 x	17.312112 =	1.471530
116		.170000 x	20.419486 =	3.471313
509		.004250 x	420.751470 =	1.788194
518		.012155 x	912.618392 =	11.092877
508		.004250 x	590.611432 =	2.510099
504		.004250 x	388.600890 =	1.651554
			B.T =	22.180515
T 630	T 630			
512		.017000 x	107.967286 =	1.835444
			B.T =	1.835444
T 630.1	T 630.1			
510		.005100 x	410.246470 =	2.092257
			B.T =	2.092257
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678
			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
520		.004340 x	454.383754 =	1.972025
504		.003500 x	388.600890 =	1.360103
503		.000980 x	936.292073 =	.917566
			B.T =	5.351607
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	590.611432 =	2.067140
111		.560000 x	15.741598 =	8.815295
116		.140000 x	20.419486 =	2.858728
			B.T =	13.936113
X 623	X 623			
213		.100000 x	1.949500 =	.194950
504		.003500 x	388.600890 =	1.360103
518		.007000 x	912.618392 =	6.388329
509		.003500 x	420.751470 =	1.472630
508		.003500 x	590.611432 =	2.067140
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848
			B.T =	15.553728

X 625	X 625			
213		.100000 x	1.949500 =	.194950
509		.003500 x	420.751470 =	1.472630
518		.010010 x	912.618392 =	9.135310
504		.003500 x	388.600890 =	1.360103
508		.003500 x	590.611432 =	2.067140
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848
			B.T =	18.300709
X 630	X 630			
512		.014000 x	107.967286 =	1.511542
			B.T =	1.511542
X 630.1	X 630.1			
510		.004200 x	410.246470 =	1.723035
			B.T =	1.723035
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	420.751470 =	1.985105
T 623		.800000 x	18.844895 =	15.075916
511		.034000 x	729.054445 =	24.787851
509		.007548 x	420.751470 =	3.175832
509		.001275 x	420.751470 =	.536458
T 625		.500000 x	22.180515 =	11.090258
641		3.000000 x	6.618556 =	19.855668
T 630		.250000 x	1.835444 =	.458861
			T.E =	155.307864
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	420.751470 =	8.154163
			T.E =	75.055955
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	420.751470 =	3.397568
			T.E =	43.538643
6051	6051			
502		.000175 x	816.828773 =	.142945
			T.E =	.142945

6052	6052			
501		.000117 x	621.849352 =	.072756
521		.000088 x	430.933373 =	.037922
502		.000088 x	816.828773 =	.071881

			T.E =	.182559
6053	6053			
502		.000318 x	816.828773 =	.259752
507		.001000 x	961.608107 =	.961608

			T.E =	1.221360
6054	6054			
112		.004900 x	17.312112 =	.084829
507		.001077 x	961.608107 =	1.035652
509		.002975 x	420.751470 =	1.251736

			T.E =	2.372217
6055	6055			
213		.400000 x	1.949500 =	.779800
508		.007000 x	590.611432 =	4.134280
504		.001400 x	388.600890 =	.544041
503		.001167 x	936.292073 =	1.092653
116		.280000 x	20.419486 =	5.717456
112		.490000 x	17.312112 =	8.482935

			T.E =	20.751165
6056	6056			
507		.001750 x	961.608107 =	1.682814

			T.E =	1.682814
6057	6057			
506		.087500 x	697.908407 =	61.066986

			T.E =	61.066986
6058	6058			
507		.087500 x	961.608107 =	84.140709

			T.E =	84.140709
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
509		.002975 x	420.751470 =	1.251736
507		.001077 x	961.608107 =	1.035652
502		.001400 x	816.828773 =	1.143560
501		.000583 x	621.849352 =	.362538

			T.E =	3.914671
6062	6062			
213		.400000 x	1.949500 =	.779800
507		.001400 x	961.608107 =	1.346251
509		.002800 x	420.751470 =	1.178104
508		.002800 x	590.611432 =	1.653712
112		.175000 x	17.312112 =	3.029620
502		.002000 x	816.828773 =	1.633658
116		.175000 x	20.419486 =	3.573410

			T.E =	13.194555
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.140000 x	17.312112 =	2.423696
509		.003641 x	420.751470 =	1.531956
112		.070000 x	17.312112 =	1.211848
112		.070000 x	17.312112 =	1.211848

			T.E =	18.497826
6064	6064			
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696
507		.014000 x	961.608107 =	13.462513
509		.003641 x	420.751470 =	1.531956

			T.E =	18.630013
6065	6065			
506		.002800 x	697.908407 =	1.954144
506		.002100 x	697.908407 =	1.465608

			T.E =	3.419751

6066	6066			
111		.070000 x	15.741598 =	1.101912
502		.000700 x	816.828773 =	.571780

			T.E =	1.673692
6067	6067			
111		.980000 x	15.741598 =	15.426766
X 630		.100000 x	1.511542 =	.151154
X 630.1		.100000 x	1.723035 =	.172304

			T.E =	15.750224
6068	6068			
111		.560000 x	15.741598 =	8.815295
112		.560000 x	17.312112 =	9.694783
X 630.1		.200000 x	1.723035 =	.344607
X 630		.200000 x	1.511542 =	.302308
622		1.351351 x	13.126163 =	17.738053
509		.016497 x	420.751470 =	6.941137

			T.E =	43.836183
6068.1	6068.1			
111		.560000 x	15.741598 =	8.815295
509		.016497 x	420.751470 =	6.941137
112		.560000 x	17.312112 =	9.694783
614		1.351351 x	8.788828 =	11.876792
X 630.1		.200000 x	1.723035 =	.344607
X 630		.200000 x	1.511542 =	.302308

			T.E =	37.974922
6069	6069			
112		.070000 x	17.312112 =	1.211848
509		.012017 x	420.751470 =	5.056170
X 625		1.050000 x	18.300709 =	19.215744

			T.E =	25.483763
6069.1	6069.1			
112		.070000 x	17.312112 =	1.211848
X 617		1.050000 x	5.351607 =	5.619187
509		.012017 x	420.751470 =	5.056170

			T.E =	11.887206
6070	6070			
501		.000467 x	621.849352 =	.290404

			T.E =	.290404

6071	6071			
504		.002333 x	388.600890 =	.906606
509		.002975 x	420.751470 =	1.251736

			T.E =	2.158341
6072	6072			
504		.003500 x	388.600890 =	1.360103
509		.002800 x	420.751470 =	1.178104

			T.E =	2.538207
6073	6073			
509		.000833 x	420.751470 =	.350486

			T.E =	.350486
6074	6074			
509		.000784 x	420.751470 =	.329869

			T.E =	.329869
6075	6075			
509		.001096 x	420.751470 =	.461144

			T.E =	.461144
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	936.292073 =	.655404
507		.000840 x	961.608107 =	.807751
509		.003914 x	420.751470 =	1.646821

			T.E =	3.194806
6077	6077			
503		.001400 x	936.292073 =	1.310809

			T.E =	1.310809
6078	6078			
112		.004900 x	17.312112 =	.084829
501		.000056 x	621.849352 =	.034824
505		.001400 x	855.742457 =	1.198039
503		.000350 x	936.292073 =	.327702

			T.E =	1.645395

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
556		.001400 x	1,165.249457 =	1.631349
503		.000350 x	936.292073 =	.327702
501		.000056 x	621.849352 =	.034824

			T.E =	2.078704
6079	6079			
112		.014000 x	17.312112 =	.242370
529		.000980 x	455.290673 =	.446185
X 630		.150000 x	1.511542 =	.226731
509		.000630 x	420.751470 =	.265073
502		.000350 x	816.828773 =	.285890
501		.000700 x	621.849352 =	.435295

			T.E =	1.901544
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.723035 =	.172304
529		.000700 x	455.290673 =	.318703
502		.000292 x	816.828773 =	.238514
X 630		.100000 x	1.511542 =	.151154
501		.000583 x	621.849352 =	.362538

			T.E =	1.485583
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
506		.007000 x	697.908407 =	4.885359
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087

			T.E =	23.615308
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
6081.1		1.000000 x	23.615308 =	23.615308
112		.070000 x	17.312112 =	1.211848

			T.E =	35.846274
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
112		.140000 x	17.312112 =	2.423696
6081.1		1.000000 x	23.615308 =	23.615308

			T.E =	48.077241

6081.4	6081.4				
111		2.100000 x	15.741598 =	33.057356	
112		.210000 x	17.312112 =	3.635544	
6081.1		1.000000 x	23.615308 =	23.615308	
			T.E =	60.308207	
6082.1	6082.1				
213		.400000 x	1.949500 =	.779800	
116		.700000 x	20.419486 =	14.293640	
116		1.400000 x	20.419486 =	28.587280	
111		1.400000 x	15.741598 =	22.038237	
508		.070000 x	590.611432 =	41.342800	
			T.E =	107.041758	
6082.2	6082.2				
111		.700000 x	15.741598 =	11.019119	
112		.140000 x	17.312112 =	2.423696	
6082.1		1.000000 x	107.041758 =	107.041758	
			T.E =	120.484572	
6082.3	6082.3				
111		1.400000 x	15.741598 =	22.038237	
112		.280000 x	17.312112 =	4.847391	
6082.1		1.000000 x	107.041758 =	107.041758	
			T.E =	133.927387	
6082.4	6082.4				
111		2.100000 x	15.741598 =	33.057356	
6082.1		1.000000 x	107.041758 =	107.041758	
112		.420000 x	17.312112 =	7.271087	
			T.E =	147.370201	
6083.1	6083.1				
111		.280000 x	15.741598 =	4.407647	
112		.140000 x	17.312112 =	2.423696	
112		.280000 x	17.312112 =	4.847391	
506		.005833 x	697.908407 =	4.070900	
			T.E =	15.749634	
6083.2	6083.2				
111		.560000 x	15.741598 =	8.815295	
112		.070000 x	17.312112 =	1.211848	
6083.1		1.000000 x	15.749634 =	15.749634	
			T.E =	25.776777	

6083.3	6083.3				
111		1.120000 x	15.741598 =	17.630590	
112		.140000 x	17.312112 =	2.423696	
6083.1		1.000000 x	15.749634 =	15.749634	

			T.E =	35.803919	
6083.4	6083.4				
111		1.680000 x	15.741598 =	26.445885	
6083.1		1.000000 x	15.749634 =	15.749634	
112		.210000 x	17.312112 =	3.635544	

			T.E =	45.831062	
6084.1	6084.1				
213		.400000 x	1.949500 =	.779800	
116		1.050000 x	20.419486 =	21.440460	
508		.035000 x	590.611432 =	20.671400	
116		.700000 x	20.419486 =	14.293640	
111		1.470000 x	15.741598 =	23.140149	

			T.E =	80.325450	
6084.2	6084.2				
111		.560000 x	15.741598 =	8.815295	
112		.105000 x	17.312112 =	1.817772	
6084.1		1.000000 x	80.325450 =	80.325450	

			T.E =	90.958517	
6084.3	6084.3				
111		1.120000 x	15.741598 =	17.630590	
6084.1		1.000000 x	80.325450 =	80.325450	
112		.210000 x	17.312112 =	3.635544	

			T.E =	101.591583	
6084.4	6084.4				
111		1.680000 x	15.741598 =	26.445885	
6084.1		1.000000 x	80.325450 =	80.325450	
112		.315000 x	17.312112 =	5.453315	

			T.E =	112.224650	
6085.1	6085.1				
111		.140000 x	15.741598 =	2.203824	
112		.140000 x	17.312112 =	2.423696	
506		.004666 x	697.908407 =	3.256441	
502		.001400 x	816.828773 =	1.143560	

			T.E =	9.027520	

6085.2	6085.2				
111		.350000 x	15.741598 =	5.509559	
112		.070000 x	17.312112 =	1.211848	
6085.1		1.000000 x	9.027520 =	9.027520	

			T.E =	15.748927	
6085.3	6085.3				
111		.700000 x	15.741598 =	11.019119	
6085.1		1.000000 x	9.027520 =	9.027520	
112		.140000 x	17.312112 =	2.423696	

			T.E =	22.470334	
6085.4	6085.4				
111		1.050000 x	15.741598 =	16.528678	
6085.1		1.000000 x	9.027520 =	9.027520	
112		.210000 x	17.312112 =	3.635544	

			T.E =	29.191741	
6086.1	6086.1				
213		.400000 x	1.949500 =	.779800	
111		1.120000 x	15.741598 =	17.630590	
116		.280000 x	20.419486 =	5.717456	
508		.008750 x	590.611432 =	5.167850	
116		.490000 x	20.419486 =	10.005548	

			T.E =	39.301244	
6086.2	6086.2				
111		.350000 x	15.741598 =	5.509559	
6086.1		1.000000 x	39.301244 =	39.301244	
112		.105000 x	17.312112 =	1.817772	

			T.E =	46.628575	
6086.3	6086.3				
111		.700000 x	15.741598 =	11.019119	
6086.1		1.000000 x	39.301244 =	39.301244	
112		.210000 x	17.312112 =	3.635544	

			T.E =	53.955906	
6086.4	6086.4				
111		1.050000 x	15.741598 =	16.528678	
112		.315000 x	17.312112 =	5.453315	
6086.1		1.000000 x	39.301244 =	39.301244	

			T.E =	61.283237	

6087	6087			
252		.001000 x	290.000000 =	.290000
113		.210000 x	20.419486 =	4.288092
111		.210000 x	15.741598 =	3.305736
112		.350000 x	17.312112 =	6.059239

			T.E =	13.943067
6088	6088			
6081.1		1.000000 x	23.615308 =	23.615308
6081.1		.900000 x	23.615308 =	21.253777

			T.E =	44.869085
6089	6089			
6082.1		1.000000 x	107.041758 =	107.041758
6082.1		.900000 x	107.041758 =	96.337582

			T.E =	203.379340
6090	6090			
6083.1		1.000000 x	15.749634 =	15.749634
6083.1		1.300000 x	15.749634 =	20.474524

			T.E =	36.224158
6091	6091			
6084.1		1.000000 x	80.325450 =	80.325450
6084.1		1.300000 x	80.325450 =	104.423085

			T.E =	184.748535
6100	6100			
231		.200000 x	.895000 =	.179000
113		.105000 x	20.419486 =	2.144046
111		.175000 x	15.741598 =	2.754780
252.1		.002000 x	.000000 =	.000000
251		.002000 x	290.000000 =	.580000

			T.E =	
6101	6101			
231		15.000000 x	.895000 =	13.425000
112		3.500000 x	17.312112 =	60.592392
113		3.500000 x	20.419486 =	71.468201
252.1		.020000 x	.000000 =	.000000
252		.018000 x	290.000000 =	5.220000
251		.068000 x	290.000000 =	19.720000

			T.E =	

6102	6102			
244		1.000000 x	2.700000 =	2.700000
506		.000070 x	697.908407 =	.048854
509		.000051 x	420.751470 =	.021458
506		.000070 x	697.908407 =	.048854
112		.001400 x	17.312112 =	.024237
112		.002100 x	17.312112 =	.036355

			T.E =	2.879758
6103	6103			
244		.125000 x	2.700000 =	.337500
509		.000102 x	420.751470 =	.042917
506		.000140 x	697.908407 =	.097707
506		.000140 x	697.908407 =	.097707
112		.004200 x	17.312112 =	.072711
112		.002800 x	17.312112 =	.048474

			T.E =	.697016
6104	6104			
236		3.000000 x	.624500 =	1.873500
113		.280000 x	20.419486 =	5.717456
111		.280000 x	15.741598 =	4.407647
517		.017500 x	2,240.047889 =	39.200838

			T.E =	51.199442
6105	6105			
111		.210000 x	15.741598 =	3.305736
113		.140000 x	20.419486 =	2.858728
517		.014000 x	2,240.047889 =	31.360670

			T.E =	37.525134
6106	6106			
512		.087500 x	107.967286 =	9.447138

			T.E =	9.447138
6107	6107			
513		.087500 x	162.000429 =	14.175038

			T.E =	14.175038
6108	6108			
514		.087500 x	217.598982 =	19.039911

			T.E =	19.039911

6109	6109			
515		.087500 x	293.131858 =	25.649038

			T.E =	25.649038
6110	6110			
516		.087500 x	373.620234 =	32.691770

			T.E =	32.691770
6120	6120			
112		.004200 x	17.312112 =	.072711
502		.001750 x	816.828773 =	1.429450
501		.000070 x	621.849352 =	.043529

			T.E =	1.545691
6121	6121			
112		.004200 x	17.312112 =	.072711
509		.003113 x	420.751470 =	1.309799
507		.000875 x	961.608107 =	.841407
505		.000420 x	855.742457 =	.359412
502		.000315 x	816.828773 =	.257301
501		.000049 x	621.849352 =	.030471

			T.E =	2.871101
6151	6151			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000

			T.E =	2.640000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
T 611		1.050000 x	20.070537 =	21.074064
509		.003570 x	420.751470 =	1.502083
112		.425000 x	17.312112 =	7.357648

			T.E =	36.623973

6154	6154			
111		.425000 x	15.741598 =	6.690179
T 621		1.050000 x	16.880648 =	17.724680
509		.003570 x	420.751470 =	1.502083
112		.425000 x	17.312112 =	7.357648

			T.E =	33.274590
6155	6155			
111		.680000 x	15.741598 =	10.704287
652		.100000 x	150.772313 =	15.077231
113		1.275000 x	20.419486 =	26.034845
T 621		.350000 x	16.880648 =	5.908227
509		.003220 x	420.751470 =	1.354820

			T.E =	59.079409
6156	6156			
251		.000500 x	290.000000 =	.145000
652		.010000 x	150.772313 =	1.507723
113		.680000 x	20.419486 =	13.885250
112		.425000 x	17.312112 =	7.357648

			T.E =	22.895621
6157	6157			
111		.420000 x	15.741598 =	6.611471
X 621		1.050000 x	13.936113 =	14.632919
509		.002940 x	420.751470 =	1.237009
112		.420000 x	17.312112 =	7.271087

			T.E =	29.752486
6157.1	6157.1			
111		.420000 x	15.741598 =	6.611471
112		.420000 x	17.312112 =	7.271087
X 611		1.050000 x	16.528678 =	17.355112
509		.002940 x	420.751470 =	1.237009

			T.E =	32.474679
6158	6158			
111		.560000 x	15.741598 =	8.815295
621.1		1.050000 x	15.296216 =	16.061027
504		.001400 x	388.600890 =	.544041
509		.002940 x	420.751470 =	1.237009

			T.E =	26.657372

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	90.497781

6202.1	6202.1			
281.1		1.000000 x	17.600000 =	17.600000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	27.291284
6202.2	6202.2			
281		1.000000 x	21.300000 =	21.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	30.991284
6202.3	6202.3			
281.2		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6202.4	6202.4			
282		1.000000 x	30.000000 =	30.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	39.691284
6202.5	6202.5			
283		1.000000 x	36.300000 =	36.300000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	62.697781
6202.6	6202.6			
283.1		1.000000 x	55.500000 =	55.500000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	81.897781
6202.7	6202.7			
284		1.000000 x	75.400000 =	75.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	101.797781

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
111		.255000 x	15.741598 =	4.014107
113		.170000 x	20.419486 =	3.471313

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	18.300709 =	12.810496
X 623		.400000 x	15.553728 =	6.221491
509		.005439 x	420.751470 =	2.288467
509		.003108 x	420.751470 =	1.307696
112		.420000 x	17.312112 =	7.271087

			T.E =	33.204973
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
613		1.050000 x	5.603194 =	5.883354
509		.008702 x	420.751470 =	3.661379

			T.E =	20.121556

6205	6205			
111		.210000 x	15.741598 =	3.305736
613		1.000000 x	5.603194 =	5.603194
509		.002800 x	420.751470 =	1.178104
112		.070000 x	17.312112 =	1.211848

			T.E =	11.298882
6251	6251			
509		.002800 x	420.751470 =	1.178104
613		1.000000 x	5.603194 =	5.603194

			T.E =	6.781298
6252	6252			
509		.000784 x	420.751470 =	.329869

			T.E =	.329869
6253	6253			
112		.210000 x	17.312112 =	3.635544
X 630		.200000 x	1.511542 =	.302308
X 630.1		.200000 x	1.723035 =	.344607
501		.002917 x	621.849352 =	1.813935
521		.007000 x	430.933373 =	3.016534

			T.E =	9.112927
6301	6301			
231		.200000 x	.895000 =	.179000
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
113		.127500 x	20.419486 =	2.603484
111		.170000 x	15.741598 =	2.676072

			T.E =	6.618556
6302	6302			
231		.300000 x	.895000 =	.268500
252		.004000 x	290.000000 =	1.160000
111		.212500 x	15.741598 =	3.345090
251		.002000 x	290.000000 =	.580000
113		1.232500 x	20.419486 =	25.167016

			T.E =	30.520606
6303	6303			
6302		.666660 x	30.520606 =	20.346867

			T.E =	20.346867

6304	6304			
234.2		.018000 x	.905900 =	.016306
113		.010200 x	20.419486 =	.208279
235		.012000 x	.632700 =	.007592
112		.212500 x	17.312112 =	3.678824
113		.085000 x	20.419486 =	1.735656

			T.E =	5.646657
6310	6310			
233		1.050000 x	.558700 =	.586635
113		.042500 x	20.419486 =	.867828

			T.E =	1.454463
6311	6311			
233.1		1.050000 x	.558700 =	.586635
113		.042500 x	20.419486 =	.867828

			T.E =	1.454463
6312	6312			
233.3		1.010000 x	8.250000 =	8.332500
113		.085000 x	20.419486 =	1.735656
113		.085000 x	20.419486 =	1.735656
233.3		.303000 x	8.250000 =	2.499750

			T.E =	14.303563
6313	6313			
233.2		1.050000 x	.611600 =	.642180
113		.025500 x	20.419486 =	.520697

			T.E =	1.162877
6314	6314			
233.2		1.050000 x	.611600 =	.642180
113		.068000 x	20.419486 =	1.388525

			T.E =	2.030705
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	20.419486 =	.017357

			T.E =	1.417357

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357
			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357
			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357
			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357
			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357
			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
T 630.1		.175000 x	2.092257 =	.366145
T 630		.175000 x	1.835444 =	.321203
T 625		.350000 x	22.180515 =	7.763180
T 623		.560000 x	18.844895 =	10.553141
T 621		.300000 x	16.880648 =	5.064194
511		.023800 x	729.054445 =	17.351496
509		.003019 x	420.751470 =	1.270249
509		.003302 x	420.751470 =	1.389321
509		.005284 x	420.751470 =	2.223251
113		.595000 x	20.419486 =	12.149594
112		.714000 x	17.312112 =	12.360848
			T.E =	96.840945

6322	6322			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
509		.003019 x	420.751470 =	1.270249
T 630.1		.175000 x	2.092257 =	.366145
T 630		.175000 x	1.835444 =	.321203
T 625		.350000 x	22.180515 =	7.763180
T 623		.560000 x	18.844895 =	10.553141
T 611		.300000 x	20.070537 =	6.021161
511		.023800 x	729.054445 =	17.351496
509		.003302 x	420.751470 =	1.389321
509		.005284 x	420.751470 =	2.223251
113		.595000 x	20.419486 =	12.149594
112		.714000 x	17.312112 =	12.360848

			T.E =	97.797911
6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
511		.034000 x	729.054445 =	24.787851
113		.850000 x	20.419486 =	17.356563
509		.004718 x	420.751470 =	1.985105
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
509		.007548 x	420.751470 =	3.175832
112		1.020000 x	17.312112 =	17.658354

			T.E =	107.096805
6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
509		.007548 x	420.751470 =	3.175832
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

			T.E =	99.255737

6324

6324

221	200.000000 x	.099900 =	19.980000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
511	.034000 x	729.054445 =	24.787851
509	.004718 x	420.751470 =	1.985105
113	.850000 x	20.419486 =	17.356563
T 625	.500000 x	22.180515 =	11.090258
T 623	.800000 x	18.844895 =	15.075916
112	1.020000 x	17.312112 =	17.658354
509	.007548 x	420.751470 =	3.175832

T.E =

112.091805

6324.1

6324.1

221	200.000000 x	.099900 =	19.980000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
T 623	.800000 x	18.844895 =	15.075916
T 617	.500000 x	6.498380 =	3.249190
511	.034000 x	729.054445 =	24.787851
509	.004718 x	420.751470 =	1.985105
509	.007548 x	420.751470 =	3.175832
112	1.020000 x	17.312112 =	17.658354
113	.850000 x	20.419486 =	17.356563

T.E =

104.250737

6325

6325

221	250.000000 x	.099900 =	24.975000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
511	.034000 x	729.054445 =	24.787851
509	.007548 x	420.751470 =	3.175832
509	.004718 x	420.751470 =	1.985105
T 625	.500000 x	22.180515 =	11.090258
T 623	.800000 x	18.844895 =	15.075916
113	.850000 x	20.419486 =	17.356563
112	1.020000 x	17.312112 =	17.658354

T.E =

117.086805

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
509		.007548 x	420.751470 =	3.175832
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 109.245737

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
113		1.360000 x	20.419486 =	27.770501
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	420.751470 =	3.175832

T.E = 135.438802

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
509		.007548 x	420.751470 =	3.175832
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501

T.E = 127.597734

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
511		.034000 x	729.054445 =	24.787851
509		.007548 x	420.751470 =	3.175832
509		.004718 x	420.751470 =	1.985105
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 157.723029

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
509		.007548 x	420.751470 =	3.175832
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 149.881962

6328	6328			
221		350.000000 x	.099900 =	34.965000
509		.004718 x	420.751470 =	1.985105
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
511		.034000 x	729.054445 =	24.787851
509		.007548 x	420.751470 =	3.175832

T.E = 161.299342

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	420.751470 =	1.985105
511		.034000 x	729.054445 =	24.787851
T 617		.500000 x	6.498380 =	3.249190
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
509		.007548 x	420.751470 =	3.175832

T.E = 153.458274

6329	6329			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	17.312112 =	39.731297
T 623		.800000 x	18.844895 =	15.075916
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.500000 x	22.180515 =	11.090258
509		.007548 x	420.751470 =	3.175832
511		.034000 x	729.054445 =	24.787851
509		.004718 x	420.751470 =	1.985105
113		1.445000 x	20.419486 =	29.506157

T.E = 167.004342

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.007548 x	420.751470 =	3.175832
509		.004718 x	420.751470 =	1.985105
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 159.163274

6329.2

6329.2

223	350.000000 x	.119300 =	41.755000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
511	.034000 x	729.054445 =	24.787851
509	.007548 x	420.751470 =	3.175832
509	.004718 x	420.751470 =	1.985105
T 625	.500000 x	22.180515 =	11.090258
T 623	.800000 x	18.844895 =	15.075916
113	1.445000 x	20.419486 =	29.506157
112	2.295000 x	17.312112 =	39.731297

T.E =

168.089342

6329.3

6329.3

223	350.000000 x	.119300 =	41.755000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
T 623	.800000 x	18.844895 =	15.075916
T 617	.500000 x	6.498380 =	3.249190
511	.034000 x	729.054445 =	24.787851
509	.007548 x	420.751470 =	3.175832
509	.004718 x	420.751470 =	1.985105
112	2.295000 x	17.312112 =	39.731297
113	1.445000 x	20.419486 =	29.506157

T.E =

160.248274

6330

6330

223	420.000000 x	.119300 =	50.106000
T 630.1	.250000 x	2.092257 =	.523064
T 630	.250000 x	1.835444 =	.458861
511	.042500 x	729.054445 =	30.984814
509	.004718 x	420.751470 =	1.985105
509	.007548 x	420.751470 =	3.175832
T 625	.500000 x	22.180515 =	11.090258
T 623	.800000 x	18.844895 =	15.075916
113	1.445000 x	20.419486 =	29.506157
112	2.295000 x	17.312112 =	39.731297

T.E =

182.637305

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.042500 x	729.054445 =	30.984814
509		.007548 x	420.751470 =	3.175832
509		.004718 x	420.751470 =	1.985105
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297
			T.E =	174.796237
6331	6331			
222		450.000000 x	.116200 =	52.290000
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181
113		5.525000 x	20.419486 =	112.817660
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
511		.042500 x	729.054445 =	30.984814
509		.007548 x	420.751470 =	3.175832
509		.004718 x	420.751470 =	1.985105
			T.E =	347.474303
6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181
509		.007548 x	420.751470 =	3.175832
511		.042500 x	729.054445 =	30.984814
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
509		.004718 x	420.751470 =	1.985105
113		5.525000 x	20.419486 =	112.817660
			T.E =	339.633236

6351	6351			
221		120.000000 x	.099900 =	11.988000
T 623		.850000 x	18.844895 =	16.018161
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.450000 x	22.180515 =	9.981232
509		.008020 x	420.751470 =	3.374427
511		.034000 x	729.054445 =	24.787851
509		.004246 x	420.751470 =	1.786511
112		1.275000 x	17.312112 =	22.072943
113		1.275000 x	20.419486 =	26.034845

T.E = 123.644450

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.850000 x	18.844895 =	16.018161
T 617		.450000 x	6.498380 =	2.924271
511		.034000 x	729.054445 =	24.787851
509		.008020 x	420.751470 =	3.374427
509		.004246 x	420.751470 =	1.786511
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 116.587489

6352	6352			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
509		.007548 x	420.751470 =	3.175832
509		.004718 x	420.751470 =	1.985105
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 625		.500000 x	22.180515 =	11.090258
T 623		.800000 x	18.844895 =	15.075916
511		.034000 x	729.054445 =	24.787851
113		2.550000 x	20.419486 =	52.069689

T.E = 182.543371

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
509		.004718 x	420.751470 =	1.985105
6301		1.000000 x	6.618556 =	6.618556
T 630.1		.250000 x	2.092257 =	.523064
T 630		.250000 x	1.835444 =	.458861
T 623		.800000 x	18.844895 =	15.075916
T 617		.500000 x	6.498380 =	3.249190
511		.034000 x	729.054445 =	24.787851
509		.007548 x	420.751470 =	3.175832
113		2.550000 x	20.419486 =	52.069689
			T.E =	174.702303
6360.1	6360.1			
6360.1 A1		1.000000 x	113.290182 =	113.290182
6360.1 A2		1.000000 x	8.030740 =	8.030740
6360.1 A3		1.000000 x	14.511206 =	14.511206
6360.1 A4		1.000000 x	32.381914 =	32.381914
6360.1 A5		1.000000 x	99.527281 =	99.527281
			AΘΡΟΙΣΜΑ =	267.741323
	T.E =	.200000 x	267.741323 =	53.548265
6360.2	6360.2			
6360.2 A1		1.000000 x	121.803760 =	121.803760
6360.2 A3		1.000000 x	18.919639 =	18.919639
6360.2 A4		1.000000 x	35.645182 =	35.645182
6360.2 A2		1.000000 x	11.171814 =	11.171814
6360.2 A5		1.000000 x	113.410410 =	113.410410
			AΘΡΟΙΣΜΑ =	300.950805
	T.E =	.200000 x	300.950805 =	60.190161
6360.3	6360.3			
6360.3 A1		1.000000 x	161.437498 =	161.437498
6360.3 A3		1.000000 x	42.505710 =	42.505710
6360.3 A5		1.000000 x	156.859643 =	156.859643
6360.3 A4		1.000000 x	42.675985 =	42.675985
6360.3 A2		1.000000 x	15.856610 =	15.856610
			AΘΡΟΙΣΜΑ =	419.335446
	T.E =	.200000 x	419.335446 =	83.867089

6360.4	6360.4			
6360.4 A1		1.000000 x	211.685616 =	211.685616
6360.4 A2		1.000000 x	21.502210 =	21.502210
6360.4 A3		1.000000 x	63.578665 =	63.578665
6360.4 A5		1.000000 x	211.671220 =	211.671220
6360.4 A4		1.000000 x	35.645182 =	35.645182

			AΘΡΟΙΣΜΑ =	544.082893
	T.E =	.200000 x	544.082893 =	108.816579

6360.5	6360.5			
6360.5 A1		1.000000 x	242.567035 =	242.567035
6360.5 A2		1.000000 x	26.826389 =	26.826389
6360.5 A3		1.000000 x	70.630737 =	70.630737
6360.5 A5		1.000000 x	289.648139 =	289.648139
6360.5 A4		1.000000 x	36.895309 =	36.895309

			AΘΡΟΙΣΜΑ =	666.567609
	T.E =	.200000 x	666.567609 =	133.313522

6360.6	6360.6			
6360.6 A1		1.000000 x	295.117816 =	295.117816
6360.6 A5		1.000000 x	382.704101 =	382.704101
6360.6 A4		1.000000 x	35.645182 =	35.645182
6360.6 A3		1.000000 x	83.023709 =	83.023709
6360.6 A2		1.000000 x	40.286267 =	40.286267

			AΘΡΟΙΣΜΑ =	836.777075
	T.E =	.200000 x	836.777075 =	167.355415

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	20.419486 =	.347131
111		.085000 x	15.741598 =	1.338036

			T.E =	2.065167
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	20.419486 =	6.942625
396.14		.003000 x	42.680000 =	.128040
111		.340000 x	15.741598 =	5.352143

			T.E =	16.933809
6371	6371			
326		.500000 x	1.310000 =	.655000
111		.212500 x	15.741598 =	3.345090
113		.212500 x	20.419486 =	4.339141

			T.E =	8.339230

6372	6372			
396.11		1.050000 x	2.960000 =	3.108000
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
396.13		.700000 x	1.770000 =	1.239000

			T.E =	16.641769
6373	6373			
396.12		1.050000 x	4.250000 =	4.462500
113		.425000 x	20.419486 =	8.678282
111		.425000 x	15.741598 =	6.690179
396.13		.700000 x	1.770000 =	1.239000

			T.E =	21.069961
6401	6401			
327		.500000 x	.540000 =	.270000
113		.212500 x	20.419486 =	4.339141

			T.E =	4.609141
6402	6402			
252		.000500 x	290.000000 =	.145000
652		.011500 x	150.772313 =	1.733882
652.2		.005500 x	170.500107 =	.937751
111		.595000 x	15.741598 =	9.366251
113		.595000 x	20.419486 =	12.149594

			T.E =	24.332477
6403	6403			
251		.000500 x	290.000000 =	.145000
652.2		.005500 x	170.500107 =	.937751
652		.016500 x	150.772313 =	2.487743
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

			T.E =	34.307415
6404	6404			
111		1.275000 x	15.741598 =	20.070537
652		.020000 x	150.772313 =	3.015446
113		1.700000 x	20.419486 =	34.713126

			T.E =	57.799110
6404.1	6404.1			
397.8		54.000000 x	.000000 =	.000000
6404		1.000000 x	57.799110 =	57.799110

			T.E =	

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	150.772313 =	3.015446

			T.E =	27.062189
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	25,662.000000 =	25,662.000000
386.9		.150000 x	25,662.000000 =	3,849.300000

			T.E =	29,511.300000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19				
386.40		1.000000 x	76,825.000000 =		76,825.000000
386.40		.150000 x	76,825.000000 =		11,523.750000

			T.E =		88,348.750000
6452.2	6452.2				
386.23		1.000000 x	.000000 =		.000000
386.23		.150000 x	.000000 =		.000000

			T.E =		
6452.20	6452.20				
386.41		1.000000 x	.000000 =		.000000
386.41		.150000 x	.000000 =		.000000

			T.E =		
6452.21	6452.21				
386.42		1.000000 x	.000000 =		.000000
386.42		.150000 x	.000000 =		.000000

			T.E =		
6452.22	6452.22				
386.43		1.000000 x	.000000 =		.000000
386.43		.150000 x	.000000 =		.000000

			T.E =		
6452.23	6452.23				
386.44		1.000000 x	.000000 =		.000000
386.44		.150000 x	.000000 =		.000000

			T.E =		
6452.24	6452.24				
386.45		1.000000 x	.000000 =		.000000
386.45		.150000 x	.000000 =		.000000

			T.E =		
6452.25	6452.25				
386.46		1.000000 x	.000000 =		.000000
386.46		.150000 x	.000000 =		.000000

			T.E =		

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	113,082.000000 =	113,082.000000
386.30		.150000 x	113,082.000000 =	16,962.300000

			T.E =	130,044.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17				
386.64		1.000000 x	153,664.000000 =	153,664.000000	
386.64		.150000 x	153,664.000000 =	23,049.600000	
					T.E = 176,713.600000
6453.18	6453.18				
386.65		1.000000 x	.000000 =	.000000	
386.65		.150000 x	.000000 =	.000000	
					T.E =
6453.19	6453.19				
386.66		1.000000 x	.000000 =	.000000	
386.66		.150000 x	.000000 =	.000000	
					T.E =
6453.2	6453.2				
386.49		1.000000 x	.000000 =	.000000	
386.49		.150000 x	.000000 =	.000000	
					T.E =
6453.20	6453.20				
386.67		1.000000 x	.000000 =	.000000	
386.67		.150000 x	.000000 =	.000000	
					T.E =
6453.3	6453.3				
386.50		1.000000 x	.000000 =	.000000	
386.50		.150000 x	.000000 =	.000000	
					T.E =
6453.4	6453.4				
386.51		1.000000 x	.000000 =	.000000	
386.51		.150000 x	.000000 =	.000000	
					T.E =
6453.5	6453.5				
386.52		1.000000 x	.000000 =	.000000	
386.52		.150000 x	.000000 =	.000000	
					T.E =

6453.6	6453.6			
386.53		1.000000 x	134,053.000000 =	134,053.000000
386.53		.150000 x	134,053.000000 =	20,107.950000

			T.E =	154,160.950000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	21,523.000000 =	21,523.000000
387.3		.100000 x	21,523.000000 =	2,152.300000

			T.E =	23,675.300000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

T.E =				
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

T.E =				
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

T.E =				
6456.1	6456.1			
234.2		208.000000 x	.905900 =	188.427200
235		338.000000 x	.632700 =	213.852600
113		154.700001 x	20.419486 =	3,158.894505

ΑΘΡΟΙΣΜΑ =				3,561.174305

T.E = 5,341.761457				
6456.2	6456.2			
234.2		336.000000 x	.905900 =	304.382400
235		546.000000 x	.632700 =	345.454200
113		249.900000 x	20.419486 =	5,102.829551

ΑΘΡΟΙΣΜΑ =				5,752.666151

T.E = 8,053.732612				
6456.3	6456.3			
234.2		384.000000 x	.905900 =	347.865600
235		624.000000 x	.632700 =	394.804800
113		285.599998 x	20.419486 =	5,831.805161

ΑΘΡΟΙΣΜΑ =				6,574.475561

T.E = 9,204.265785				
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

T.E =				

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,664.000000 =	6,664.000000
389.4		.200000 x	6,664.000000 =	1,332.800000

			T.E =	7,996.800000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		.150000 x	.000000 =	.000000
390.11		1.000000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,629.000000 =	5,629.000000
390.14		.150000 x	5,629.000000 =	844.350000

			T.E =	6,473.350000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	8,188.000000 =	8,188.000000
390.31		.150000 x	8,188.000000 =	1,228.200000

			T.E =	9,416.200000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1				
393.1		1.000000 x	15,362.000000 =		15,362.000000
393.1		.150000 x	15,362.000000 =		2,304.300000

			T.E =		17,666.300000
6473.2	6473.2				
393.2		1.000000 x	.000000 =		.000000
393.2		.150000 x	.000000 =		.000000

			T.E =		
6473.3	6473.3				
393.3		1.000000 x	.000000 =		.000000
393.3		.150000 x	.000000 =		.000000

			T.E =		
6473.4	6473.4				
393.4		1.000000 x	.000000 =		.000000
393.4		.150000 x	.000000 =		.000000

			T.E =		
6474	6474				
397.2		1.000000 x	6.950000 =		6.950000

			T.E =		6.950000
6501	6501				
237		1.000000 x	1.218000 =		1.218000
113		.850000 x	20.419486 =		17.356563

			T.E =		18.574563
6502	6502				
112		.170000 x	17.312112 =		2.943059
517		.042500 x	2,240.047889 =		95.202035

			T.E =		98.145094
6505	6505				
233		1.050000 x	.558700 =		.586635
113		.042500 x	20.419486 =		.867828

			T.E =		1.454463

6506	6506				
233.1		1.050000 x	.558700 =	.586635	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.454463	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
261		1.000000 x	15.100000 =	15.100000	
111		.255000 x	15.741598 =	4.014107	

			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
113		.297500 x	20.419486 =	6.074797	
111		.297500 x	15.741598 =	4.683125	

			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
111		.510000 x	15.741598 =	8.028215	
113		.510000 x	20.419486 =	10.413938	
263.2		1.000000 x	46.700000 =	46.700000	

			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

			T.E =	147.834921
6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

			T.E =	255.002782
6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.646657 =	38.905467
6310		32.020000 x	1.454463 =	46.571905
6329.2		.418000 x	168.089342 =	70.261345
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

			T.E =	211.131678
6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.030705 =	27.881580
6329.2		.478000 x	168.089342 =	80.346705
6304		9.290000 x	5.646657 =	52.457444

			T.E =	178.042292
6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

			T.E =	
6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

			T.E =	

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

			T.E =	
6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

			T.E =	
6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

			T.E =	
6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

			T.E =	

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

			T.E =	
6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

			T.E =	
6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

			T.E =	
6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

			T.E =	
6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

			T.E =	

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

			T.E =	
6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

			T.E =	
6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

			T.E =	
6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

			T.E =	

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

			T.E =	
6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

			T.E =	
6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

			T.E =	
6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

			T.E =	

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

			T.E =	
6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

			T.E =	
6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

			T.E =	
6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

			T.E =	
6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

			T.E =	

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

			T.E =	
6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

			T.E =	
6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

			T.E =	
6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

			T.E =	

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

			T.E =	
6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

			T.E =	
6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

			T.E =	
6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

			T.E =	
6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

			T.E =	

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

			T.E =	
6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

			T.E =	
6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

			T.E =	
6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

			T.E =	
6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

			T.E =	

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

			T.E =	
6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

			T.E =	
6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

			T.E =	
6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

			T.E =	
6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

			T.E =	

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

			T.E =	
6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

			T.E =	
6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

			T.E =	
6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

			T.E =	
6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

			T.E =	

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.025500 x	20.419486 =	.520697
113		.085000 x	20.419486 =	1.735656
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	
6611.1	6611.1			
361.1		1.000000 x	13.520000 =	13.520000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

			T.E =	28.026354
6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

			T.E =	
6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

			T.E =	
6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

			T.E =	
6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

			T.E =	

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
112		3.825000 x	17.312112 =	66.218828
113		1.445000 x	20.419486 =	29.506157
			T.E =	
6611.2	6611.2			
361.2		1.000000 x	17.490000 =	17.490000
111		.085000 x	15.741598 =	1.338036
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942
			T.E =	32.732118
6611.3	6611.3			
361.3		1.000000 x	22.200000 =	22.200000
111		.127500 x	15.741598 =	2.007054
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471
			T.E =	40.450494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072
			T.E =	
6611.5	6611.5			
361.5		1.000000 x	42.370000 =	42.370000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453
			T.E =	69.712368
6611.6	6611.6			
361.6		1.000000 x	56.540000 =	56.540000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884
			T.E =	88.362273

6611.7	6611.7			
361.7		1.000000 x	87.480000 =	87.480000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	125.319024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	4.830000 =	4.926600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	10.764393
6620.2	6620.2			
371.2		1.020000 x	7.640000 =	7.792800
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	15.980614
6620.3	6620.3			
371.3		1.020000 x	9.930000 =	10.128600
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.075730

6620.4	6620.4			
371.4		1.020000 x	15.450000 =	15.759000
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424
			T.E =	29.667645
6620.5	6620.5			
371.5		1.020000 x	19.550000 =	19.941000
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414
			T.E =	36.583980
6620.6	6620.6			
371.6		1.020000 x	30.720000 =	31.334400
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563
			T.E =	54.862529
6620.7	6620.7			
371.7		1.020000 x	39.530000 =	40.320600
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299
			T.E =	68.764512
6620.8	6620.8			
371.8		1.020000 x	50.240000 =	51.244800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541
			T.E =	85.932713
6620.9	6620.9			
371.9		1.020000 x	63.060000 =	64.321200
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709
			T.E =	106.646868

6621.1	6621.1			
372.1		1.020000 x	7.600000 =	7.752000
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	14.753813
6621.2	6621.2			
372.2		1.020000 x	11.960000 =	12.199200
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.048336
6621.3	6621.3			
372.3		1.020000 x	15.680000 =	15.993600
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.000497
6621.4	6621.4			
372.4		1.020000 x	24.270000 =	24.755400
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	41.596921
6621.5	6621.5			
372.5		1.020000 x	30.880000 =	31.497600
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	51.771489
6621.6	6621.6			
372.6		1.020000 x	48.660000 =	49.633200
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	78.338100

6621.7	6621.7			
372.7		1.020000 x	61.800000 =	63.036000
112		.710600 x	17.312112 =	12.301987
113		.589050 x	20.419486 =	12.028098
111		.662150 x	15.741598 =	10.423299

			T.E =	97.789384
6621.8	6621.8			
372.8		1.020000 x	78.570000 =	80.141400
113		.663850 x	20.419486 =	13.555476
112		.901000 x	17.312112 =	15.598213
111		.841500 x	15.741598 =	13.246555

			T.E =	122.541643
6621.9	6621.9			
372.9		1.020000 x	99.470000 =	101.459400
113		.748000 x	20.419486 =	15.273776
112		1.145800 x	17.312112 =	19.836218
111		1.068450 x	15.741598 =	16.819110

			T.E =	153.388504
6622.1	6622.1			
373.1		1.020000 x	11.310000 =	11.536200
111		.080750 x	15.741598 =	1.271134
112		.131750 x	17.312112 =	2.280871
113		.235450 x	20.419486 =	4.807768

			T.E =	19.895973
6622.2	6622.2			
373.2		1.020000 x	17.850000 =	18.207000
111		.130900 x	15.741598 =	2.060575
113		.299200 x	20.419486 =	6.109510
112		.212500 x	17.312112 =	3.678824

			T.E =	30.055909
6622.3	6622.3			
373.3		1.020000 x	23.270000 =	23.735400
111		.170850 x	15.741598 =	2.689452
113		.341700 x	20.419486 =	6.977338
112		.277950 x	17.312112 =	4.811902

			T.E =	38.214092

6623	6623			
360.2		1.000000 x	2.440000 =	2.440000
113		.025500 x	20.419486 =	.520697
113		.085000 x	20.419486 =	1.735656
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

			T.E =	6.101136
6630.1	6630.1			
376.12		1.000000 x	91.600000 =	91.600000
111		.855100 x	15.741598 =	13.460640
112		2.439500 x	17.312112 =	42.232897
113		2.550000 x	20.419486 =	52.069689
113		.610300 x	20.419486 =	12.462012
113		1.067600 x	20.419486 =	21.799843

			T.E =	233.625083
6630.10	6630.10			
376.21		1.000000 x	502.070000 =	502.070000
111		7.690800 x	15.741598 =	121.065482
113		3.349000 x	20.419486 =	68.384859
113		3.203650 x	20.419486 =	65.416886
113		2.550000 x	20.419486 =	52.069689
112		13.396000 x	17.312112 =	231.913052

			T.E =	1,040.919968
6630.11	6630.11			
376.22		1.000000 x	544.290000 =	544.290000
113		3.471400 x	20.419486 =	70.884204
113		3.629500 x	20.419486 =	74.112524
113		2.550000 x	20.419486 =	52.069689
111		9.025300 x	15.741598 =	142.072644
112		14.518000 x	17.312112 =	251.337242

			T.E =	1,134.766304
6630.2	6630.2			
376.13		1.000000 x	101.900000 =	101.900000
113		1.201050 x	20.419486 =	24.524824
113		.680000 x	20.419486 =	13.885250
113		2.550000 x	20.419486 =	52.069689
112		2.720000 x	17.312112 =	47.088945
111		1.081200 x	15.741598 =	17.019816

			T.E =	256.488524

6630.3	6630.3			
376.14		1.000000 x	113.040000 =	113.040000
113		.760750 x	20.419486 =	15.534124
113		2.550000 x	20.419486 =	52.069689
112		3.043000 x	17.312112 =	52.680757
111		1.334500 x	15.741598 =	21.007163
113		1.334500 x	20.419486 =	27.249804

			T.E =	281.581537
6630.4	6630.4			
376.15		1.000000 x	144.820000 =	144.820000
111		1.922700 x	15.741598 =	30.266370
112		3.570000 x	17.312112 =	61.804240
113		2.550000 x	20.419486 =	52.069689
113		1.602250 x	20.419486 =	32.717121
113		.892500 x	20.419486 =	18.224391

			T.E =	339.901812
6630.5	6630.5			
376.16		1.000000 x	182.130000 =	182.130000
112		4.658000 x	17.312112 =	80.639818
111		2.617150 x	15.741598 =	41.198123
113		1.869150 x	20.419486 =	38.167082
113		1.164500 x	20.419486 =	23.778491
113		2.550000 x	20.419486 =	52.069689

			T.E =	417.983204
6630.6	6630.6			
376.17		1.000000 x	231.180000 =	231.180000
112		5.882000 x	17.312112 =	101.829843
111		3.418700 x	15.741598 =	53.815801
113		1.470500 x	20.419486 =	30.026854
113		2.136050 x	20.419486 =	43.617043
113		2.550000 x	20.419486 =	52.069689

			T.E =	512.539230
6630.7	6630.7			
376.18		1.000000 x	311.830000 =	311.830000
113		2.402950 x	20.419486 =	49.067004
113		2.550000 x	20.419486 =	52.069689
113		2.031500 x	20.419486 =	41.482186
112		8.126000 x	17.312112 =	140.678222
111		4.326500 x	15.741598 =	68.106024

			T.E =	663.233125

6630.8	6630.8			
376.19		1.000000 x	346.570000 =	346.570000
113		2.550000 x	20.419486 =	52.069689
113		2.669850 x	20.419486 =	54.516965
113		2.261000 x	20.419486 =	46.168458
112		9.044000 x	17.312112 =	156.570741
111		5.340550 x	15.741598 =	84.068791
			T.E =	739.964644
6630.9	6630.9			
376.20		1.000000 x	412.890000 =	412.890000
111		6.461700 x	15.741598 =	101.717484
113		2.936750 x	20.419486 =	59.966926
113		2.737000 x	20.419486 =	55.888133
113		2.550000 x	20.419486 =	52.069689
112		10.948000 x	17.312112 =	189.533002
			T.E =	872.065234
6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
111		1.334500 x	15.741598 =	21.007163
113		1.667700 x	20.419486 =	34.053577
113		2.550000 x	20.419486 =	52.069689
112		3.043000 x	17.312112 =	52.680757
			T.E =	
6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.002600 x	20.419486 =	40.892063
113		2.550000 x	20.419486 =	52.069689
111		1.922700 x	15.741598 =	30.266370
112		3.570000 x	17.312112 =	61.804240
			T.E =	
6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		2.336650 x	20.419486 =	47.713192
112		4.658000 x	17.312112 =	80.639818
111		2.617150 x	15.741598 =	41.198123
			T.E =	

6640.4	6640.4			
377.4		1.000000 x	.000000 =	.000000
111		3.418700 x	15.741598 =	53.815801
112		5.882000 x	17.312112 =	101.829843
113		2.669850 x	20.419486 =	54.516965
113		2.550000 x	20.419486 =	52.069689

			T.E =	
6640.5	6640.5			
377.5		1.000000 x	.000000 =	.000000
111		4.326500 x	15.741598 =	68.106024
112		8.126000 x	17.312112 =	140.678222
113		2.550000 x	20.419486 =	52.069689
113		3.003900 x	20.419486 =	61.338094

			T.E =	
6640.6	6640.6			
377.6		1.000000 x	.000000 =	.000000
111		5.340550 x	15.741598 =	84.068791
113		3.337100 x	20.419486 =	68.141867
113		2.550000 x	20.419486 =	52.069689
112		9.044000 x	17.312112 =	156.570741

			T.E =	
6640.7	6640.7			
377.7		1.000000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689
113		3.671150 x	20.419486 =	74.962996
112		10.948000 x	17.312112 =	189.533002
111		6.461700 x	15.741598 =	101.717484

			T.E =	
6640.8	6640.8			
377.8		1.000000 x	.000000 =	.000000
112		13.396000 x	17.312112 =	231.913052
113		2.550000 x	20.419486 =	52.069689
113		4.004350 x	20.419486 =	81.766769
111		7.690800 x	15.741598 =	121.065482

			T.E =	

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242
111		9.025300 x	15.741598 =	142.072644

			T.E =	
6641	6641			
233.3		1.000000 x	8.250000 =	8.250000

			T.E =	8.250000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		.050000 x	.000000 =	.000000
383.10		1.000000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

T.E =				
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

T.E =				
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

T.E =				
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

T.E =				
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

T.E =				
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

T.E =				
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

T.E =				
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

T.E =				

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.8		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3	6662.3			
384.1		1.000000 x	537.050000 =	537.050000
384.3		1.000000 x	.000000 =	.000000
384.7		2.000000 x	.000000 =	.000000
384.9		2.000000 x	.000000 =	.000000
384.8		2.000000 x	.000000 =	.000000
384.5		2.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.4	6662.4			
384.1		1.000000 x	537.050000 =	537.050000
384.9		2.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.7		2.000000 x	.000000 =	.000000
384.6		2.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.5	6662.5			
384.2		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000
384.8		3.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.5		3.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	
6662.6	6662.6			
384.2		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.6		3.000000 x	.000000 =	.000000
384.7		3.000000 x	.000000 =	.000000
384.9		3.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	.000000

			T.E =	

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.1		.224000 x	.000000 =	.000000

		T.E =		

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000

			T.E =	
6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

			T.E =	
6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

			T.E =	
6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

			T.E =	

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

			T.E =	
6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

			T.E =	
6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

			T.E =	
6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

			T.E =	
6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

			T.E =	
6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
111		.408000 x	15.741598 =	6.422572
113		.085000 x	20.419486 =	1.735656
369.12		.224000 x	.000000 =	.000000

			T.E =	

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
369.14		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804
369.15		.224000 x	.000000 =	.000000

			T.E =	
6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
111		.518500 x	15.741598 =	8.162019
113		.170000 x	20.419486 =	3.471313

			T.E =	
6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	
6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
369.18		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

			T.E =	

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269
369.19		.224000 x	.000000 =	.000000

			T.E =	
6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161

			T.E =	
6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625
369.30		.224000 x	.000000 =	.000000

			T.E =	
6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
369.23		.224000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
369.24		.224000 x	.000000 =	.000000

			T.E =	

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	
6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
369.27		.224000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	
6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251
369.28		.224000 x	.000000 =	.000000

			T.E =	
6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.29		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

			T.E =	
6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
370.8		1.000000 x	.000000 =	.000000

			T.E =	

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

			T.E =	
6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

			T.E =	

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.408000 x	15.741598 =	6.422572
113		.085000 x	20.419486 =	1.735656

			T.E =	
6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

			T.E =	
6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
370.16		1.000000 x	.000000 =	.000000
111		.518500 x	15.741598 =	8.162019

			T.E =	

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010
370.16		1.000000 x	.000000 =	.000000

			T.E =	
6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

			T.E =	
6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

			T.E =	
6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

			T.E =	
6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

			T.E =	
6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.24		1.000000 x	.000000 =	.000000

			T.E =	
6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
113		.026350 x	20.419486 =	.538053
6326		.327500 x	135.438802 =	44.356208
111		.085000 x	15.741598 =	1.338036

			T.E =	
6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
6326		.352500 x	135.438802 =	47.742178
113		.040800 x	20.419486 =	.833115
111		.119000 x	15.741598 =	1.873250

			T.E =	
6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
6326		.372500 x	135.438802 =	50.450954
113		.051000 x	20.419486 =	1.041394
111		.161500 x	15.741598 =	2.542268

			T.E =	
6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
113		.063750 x	20.419486 =	1.301742
6326		.382500 x	135.438802 =	51.805342

			T.E =	

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
111		.187000 x	15.741598 =	2.943679
6326		.391250 x	135.438802 =	52.990431
113		.068000 x	20.419486 =	1.388525

			T.E =	
6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
6327		.393750 x	157.723029 =	62.103443
113		.076500 x	20.419486 =	1.562091

			T.E =	
6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
6327		.431250 x	157.723029 =	68.018056
113		.093500 x	20.419486 =	1.909222
111		.289000 x	15.741598 =	4.549322

			T.E =	
6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	157.723029 =	78.861515
113		.119000 x	20.419486 =	2.429919

			T.E =	
6711.1	6711.1			
375.1		1.020000 x	8.090000 =	8.251800
6069		.370000 x	25.483763 =	9.428992
111		.161500 x	15.741598 =	2.542268
113		.017000 x	20.419486 =	.347131

			T.E =	20.570192
6711.2	6711.2			
375.2		1.020000 x	12.670000 =	12.923400
6069		.390000 x	25.483763 =	9.938668
111		.187000 x	15.741598 =	2.943679
113		.021250 x	20.419486 =	.433914

			T.E =	26.239660

6711.3	6711.3			
375.3		1.020000 x	19.750000 =	20.145000
6069		.400000 x	25.483763 =	10.193505
113		.026350 x	20.419486 =	.538053
111		.204000 x	15.741598 =	3.211286
			T.E =	34.087845
6711.4	6711.4			
375.4		1.020000 x	31.970000 =	32.609400
111		.246500 x	15.741598 =	3.880304
113		.040800 x	20.419486 =	.833115
6069		.420000 x	25.483763 =	10.703180
			T.E =	48.025999
6711.5	6711.5			
375.5		1.020000 x	40.660000 =	41.473200
111		.289000 x	15.741598 =	4.549322
6069		.430000 x	25.483763 =	10.958018
113		.051000 x	20.419486 =	1.041394
			T.E =	58.021934
6711.6	6711.6			
375.6		1.020000 x	51.520000 =	52.550400
111		.297500 x	15.741598 =	4.683125
6069		.440000 x	25.483763 =	11.212856
113		.063750 x	20.419486 =	1.301742
			T.E =	69.748123
6711.7	6711.7			
375.7		1.020000 x	83.510000 =	85.180200
6069		.520000 x	25.483763 =	13.251557
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750
			T.E =	105.613598
6712.1	6712.1			
375.8		1.050000 x	11.060000 =	11.613000
375.13		1.000000 x	9.650000 =	9.650000
113		.850000 x	20.419486 =	17.356563
			T.E =	38.619563

6712.2	6712.2			
375.9		1.050000 x	14.230000 =	14.941500
375.13		1.000000 x	9.650000 =	9.650000
113		.850000 x	20.419486 =	17.356563
			T.E =	41.948063
6712.3	6712.3			
375.10		1.050000 x	19.140000 =	20.097000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	9.650000 =	9.650000
			T.E =	47.103563
6712.4	6712.4			
375.11		1.050000 x	25.920000 =	27.216000
375.13		1.000000 x	9.650000 =	9.650000
113		.850000 x	20.419486 =	17.356563
			T.E =	54.222563
6712.5	6712.5			
375.12		1.050000 x	32.830000 =	34.471500
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	9.650000 =	9.650000
			T.E =	61.478063
6713	6713			
375.13		1.000000 x	9.650000 =	9.650000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	16.640000 =	16.640000
			T.E =	29.667593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	107.096805 =	9.638712
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969
			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	117.086805 =	25.876184
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472
			T.E =	
6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	117.086805 =	27.398312
700		.380000 x	.000000 =	.000000
			T.E =	
6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	117.086805 =	28.217920
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
			T.E =	
6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	107.096805 =	11.780649
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
			T.E =	
6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	107.096805 =	14.029681
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943
			T.E =	

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.154000 x	107.096805 =	16.492908
700		.350000 x	.000000 =	.000000

			T.E =	
6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	107.096805 =	17.778070
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

			T.E =	
6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.173000 x	107.096805 =	18.527747
113		.637500 x	20.419486 =	13.017422

			T.E =	
6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	117.086805 =	16.157979
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

			T.E =	
6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.165000 x	117.086805 =	19.319323
700		.250000 x	.000000 =	.000000

			T.E =	

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	117.086805 =	22.597753
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	107.096805 =	6.425808
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	117.086805 =	15.221285
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	117.086805 =	16.392153
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	117.086805 =	17.563021
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	107.096805 =	7.496776
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
			T.E =	
6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	107.096805 =	8.567744
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943
			T.E =	
6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	107.096805 =	9.638712
700		.350000 x	.000000 =	.000000
			T.E =	
6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	107.096805 =	10.709681
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594
			T.E =	
6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	107.096805 =	11.780649
113		.637500 x	20.419486 =	13.017422
			T.E =	

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	117.086805 =	11.708681
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

			T.E =	
6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	117.086805 =	12.879549
700		.250000 x	.000000 =	.000000

			T.E =	
6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	117.086805 =	14.050417
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

			T.E =	
6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

			T.E =	
6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	107.096805 =	9.638712
652		.002500 x	150.772313 =	.376931
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	39.639802

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	117.086805 =	29.154614
652		.004500 x	150.772313 =	.678475
113		.340000 x	20.419486 =	6.942625
			T.E =	82.836488
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	117.086805 =	36.296910
652		.005000 x	150.772313 =	.753862
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	111.416794
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	117.086805 =	43.322118
652		.006500 x	150.772313 =	.980020
112		.680000 x	17.312112 =	11.772236
			T.E =	142.219147
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	107.096805 =	11.780649
652		.003000 x	150.772313 =	.452317
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	47.737124
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	107.096805 =	14.029681
652		.003500 x	150.772313 =	.527703
113		.297500 x	20.419486 =	6.074797
			T.E =	58.214154

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	107.096805 =	18.206457
652		.004500 x	150.772313 =	.678475
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648
			T.E =	71.888331
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	107.096805 =	24.203878
652		.005000 x	150.772313 =	.753862
112		.552500 x	17.312112 =	9.564942
			T.E =	99.323763
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	107.096805 =	29.344525
652		.006500 x	150.772313 =	.980020
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179
			T.E =	128.241554
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	117.086805 =	16.157979
652		.002500 x	150.772313 =	.376931
113		.255000 x	20.419486 =	5.206969
			T.E =	46.159069
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	117.086805 =	19.319323
652		.003000 x	150.772313 =	.452317
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
			T.E =	55.275798

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	117.086805 =	22.597753
652		.003500 x	150.772313 =	.527703
112		.382500 x	17.312112 =	6.621883
			T.E =	66.782226
6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	107.096805 =	9.638712
652		.002500 x	150.772313 =	.376931
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072
			T.E =	
6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	117.086805 =	29.154614
652		.004500 x	150.772313 =	.678475
113		.340000 x	20.419486 =	6.942625
			T.E =	
6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	117.086805 =	36.296910
652		.005000 x	150.772313 =	.753862
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942
			T.E =	
6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	117.086805 =	43.322118
652		.006500 x	150.772313 =	.980020
112		.680000 x	17.312112 =	11.772236
			T.E =	

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	107.096805 =	11.780649
652		.003000 x	150.772313 =	.452317
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	107.096805 =	14.029681
652		.003500 x	150.772313 =	.527703
113		.297500 x	20.419486 =	6.074797

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	107.096805 =	18.206457
652		.004500 x	150.772313 =	.678475
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	107.096805 =	24.203878
652		.005000 x	150.772313 =	.753862
112		.552500 x	17.312112 =	9.564942

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	107.096805 =	29.344525
652		.006500 x	150.772313 =	.980020
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	117.086805 =	16.157979
652		.002500 x	150.772313 =	.376931
113		.255000 x	20.419486 =	5.206969

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	117.086805 =	19.319323
652		.003000 x	150.772313 =	.452317
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	117.086805 =	22.597753
652		.003500 x	150.772313 =	.527703
112		.382500 x	17.312112 =	6.621883

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	20.346867 =	38.252110
6326		.940000 x	135.438802 =	127.312474

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	135.438802 =	98.870325

T.E =

6741.1	6741.1				
710		3.770000 x	.000000 =		.000000
6326		.940000 x	135.438802 =		127.312474

			T.E =		
6741.2	6741.2				
6741.1		1.000000 x	.000000 =		.000000
6326		.730000 x	135.438802 =		98.870325

			T.E =		
6742.1	6742.1				
6303		3.040000 x	20.346867 =		61.854476
6328		.400000 x	161.299342 =		64.519737

			T.E =		126.374212
6742.10	6742.10				
6303		7.520000 x	20.346867 =		153.008440
6328		2.110000 x	161.299342 =		340.341612

			T.E =		493.350051
6742.11	6742.11				
6303		8.030000 x	20.346867 =		163.385342
6328		2.430000 x	161.299342 =		391.957401

			T.E =		555.342743
6742.2	6742.2				
6303		3.500000 x	20.346867 =		71.214035
6328		.500000 x	161.299342 =		80.649671

			T.E =		151.863706
6742.3	6742.3				
6303		4.020000 x	20.346867 =		81.794405
6328		.630000 x	161.299342 =		101.618585

			T.E =		183.412991
6742.4	6742.4				
6303		4.530000 x	20.346867 =		92.171308
6328		.800000 x	161.299342 =		129.039474

			T.E =		221.210781

6742.5	6742.5				
6303		5.000000 x	20.346867 =	101.734335	
6328		.950000 x	161.299342 =	153.234375	

			T.E =	254.968710	
6742.6	6742.6				
6303		5.530000 x	20.346867 =	112.518175	
6328		1.170000 x	161.299342 =	188.720230	

			T.E =	301.238405	
6742.7	6742.7				
6303		6.040000 x	20.346867 =	122.895077	
6328		1.410000 x	161.299342 =	227.432072	

			T.E =	350.327149	
6742.8	6742.8				
6303		6.520000 x	20.346867 =	132.661573	
6328		1.610000 x	161.299342 =	259.691941	

			T.E =	392.353513	
6742.9	6742.9				
6303		7.040000 x	20.346867 =	143.241944	
6328		1.880000 x	161.299342 =	303.242763	

			T.E =	446.484707	
6743.1	6743.1				
6303		3.040000 x	20.346867 =	61.854476	
6328		.440000 x	161.299342 =	70.971710	

			T.E =	132.826186	
6743.10	6743.10				
6303		7.520000 x	20.346867 =	153.008440	
6328		2.240000 x	161.299342 =	361.310526	

			T.E =	514.318966	
6743.11	6743.11				
6303		8.030000 x	20.346867 =	163.385342	
6328		2.570000 x	161.299342 =	414.539309	

			T.E =	577.924651	

6743.12	6743.12			
6303		3.040000 x	20.346867 =	61.854476
6328		.750000 x	161.299342 =	120.974507

			T.E =	182.828982
6743.13	6743.13			
6303		3.500000 x	20.346867 =	71.214035
6328		.910000 x	161.299342 =	146.782401

			T.E =	217.996436
6743.14	6743.14			
6303		4.020000 x	20.346867 =	81.794405
6328		1.090000 x	161.299342 =	175.816283

			T.E =	257.610688
6743.15	6743.15			
6303		4.530000 x	20.346867 =	92.171308
6328		1.300000 x	161.299342 =	209.689145

			T.E =	301.860452
6743.16	6743.16			
6303		5.000000 x	20.346867 =	101.734335
6328		1.550000 x	161.299342 =	250.013980

			T.E =	351.748315
6743.17	6743.17			
6303		5.530000 x	20.346867 =	112.518175
6328		1.850000 x	161.299342 =	298.403783

			T.E =	410.921957
6743.2	6743.2			
6303		3.500000 x	20.346867 =	71.214035
6328		.550000 x	161.299342 =	88.714638

			T.E =	159.928673
6743.3	6743.3			
6303		4.020000 x	20.346867 =	81.794405
6328		.690000 x	161.299342 =	111.296546

			T.E =	193.090951

6743.4	6743.4			
6303		4.530000 x	20.346867 =	92.171308
6328		.860000 x	161.299342 =	138.717434

			T.E =	230.888742
6743.5	6743.5			
6303		5.000000 x	20.346867 =	101.734335
6328		1.020000 x	161.299342 =	164.525329

			T.E =	266.259664
6743.6	6743.6			
6303		5.530000 x	20.346867 =	112.518175
6328		1.260000 x	161.299342 =	203.237171

			T.E =	315.755345
6743.7	6743.7			
6303		6.040000 x	20.346867 =	122.895077
6328		1.500000 x	161.299342 =	241.949013

			T.E =	364.844090
6743.8	6743.8			
6303		6.520000 x	20.346867 =	132.661573
6328		1.720000 x	161.299342 =	277.434868

			T.E =	410.096441
6743.9	6743.9			
6303		7.040000 x	20.346867 =	143.241944
6328		2.000000 x	161.299342 =	322.598684

			T.E =	465.840628
6744	6744			
111		2.125000 x	15.741598 =	33.450896
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408
111		4.250000 x	15.741598 =	66.901792
112		2.125000 x	17.312112 =	36.788238

			T.E =	223.923741

6751	6751			
234.2		.400000 x	.905900 =	.362360
113		.051000 x	20.419486 =	1.041394
113		.170000 x	20.419486 =	3.471313
235		.650000 x	.632700 =	.411255

			T.E =	5.286321
6752	6752			
237		1.050000 x	1.218000 =	1.278900
111		.025500 x	15.741598 =	.401411
113		.017000 x	20.419486 =	.347131

			T.E =	2.027442
6753	6753			
237		1.050000 x	1.218000 =	1.278900
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	4.486086
6754	6754			
237.1		1.000000 x	1.380000 =	1.380000
113		.212500 x	20.419486 =	4.339141
112		.017000 x	17.312112 =	.294306
111		.051000 x	15.741598 =	.802821

			T.E =	6.816268
6801	6801			
232		.700000 x	2.184000 =	1.528800
111		.850000 x	15.741598 =	13.380358
113		2.550000 x	20.419486 =	52.069689
112		1.700000 x	17.312112 =	29.430590
251		.008000 x	290.000000 =	2.320000

			T.E =	98.729438
6802	6802			
231		15.000000 x	.895000 =	13.425000
251		.050000 x	290.000000 =	14.500000
111		4.250000 x	15.741598 =	66.901792
252.1		.050000 x	.000000 =	.000000
113		2.550000 x	20.419486 =	52.069689

			T.E =	

6803	6803			
302		1.020000 x	6.360000 =	6.487200
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250
652		.012000 x	150.772313 =	1.809268
			T.E =	30.209933
6804	6804			
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250
652		.120000 x	150.772313 =	18.092678
			T.E =	40.006143
6805	6805			
301		1.000000 x	3.860000 =	3.860000
113		.340000 x	20.419486 =	6.942625
2522		.005000 x	155.307864 =	.776539
652		.002000 x	150.772313 =	.301545
111		.340000 x	15.741598 =	5.352143
			T.E =	17.232853
6806	6806			
111		.340000 x	15.741598 =	5.352143
652		.002000 x	150.772313 =	.301545
6326		.005000 x	135.438802 =	.677194
113		.340000 x	20.419486 =	6.942625
			T.E =	13.273507
6807	6807			
111		1.700000 x	15.741598 =	26.760717
			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179
			T.E =	6.690179
6810	6810			
241		2.600000 x	7.750000 =	20.150000
241		1.300000 x	7.750000 =	10.075000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
			T.E =	86.002715

6811	6811			
236		6.430000 x	.624500 =	4.015535
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.750000 =	24.412500

			T.E =	115.210851
6812	6812			
243		11.900000 x	2.400000 =	28.560000
6324		.250000 x	112.091805 =	28.022951
113		4.250000 x	20.419486 =	86.782816
111		.425000 x	15.741598 =	6.690179
397.1		2.100000 x	7.050000 =	14.805000

			AΘΡΟΙΣΜΑ =	164.860946
	T.E =	.262500 x	164.860946 =	43.275998

7001	7001			
7001 A		1.000000 x	.244416 =	.244416
7001 B		1.000000 x	.800121 =	.800121
7001 Δ		1.000000 x	.331428 =	.331428
7001 Γ		1.000000 x	1.007075 =	1.007075
7001 E		1.000000 x	.849363 =	.849363

			AΘΡΟΙΣΜΑ =	3.232403

			T.E =	3.717263
7002	7002			
560		.005104 x	731.957090 =	3.735909

			T.E =	3.735909
7003	7003			
7003 A		1.000000 x	.122208 =	.122208
7003 B		1.000000 x	.625757 =	.625757
7003 Γ		1.000000 x	.571780 =	.571780
7003 Δ		1.000000 x	.827217 =	.827217

			AΘΡΟΙΣΜΑ =	2.146962

			T.E =	2.361658
7004	7004			
561		.003250 x	968.134790 =	3.146438

			T.E =	3.146438

7005	7005			
7005 Α		1.000000 x	.122208 =	.122208
7005 Γ		1.000000 x	.312878 =	.312878
7005 Β		1.000000 x	1.095075 =	1.095075
7005 Ε		1.000000 x	.827217 =	.827217
7005 Δ		1.000000 x	.571780 =	.571780

			ΑΘΡΟΙΣΜΑ =	2.929158

			T.E =	3.222074
7006	7006			
561		.001723 x	968.134790 =	1.668096
561		.000812 x	968.134790 =	.786125
561		.000862 x	968.134790 =	.834532

			T.E =	3.288754
7007	7007			
213		.100000 x	1.949500 =	.194950
550		.003500 x	1,071.340886 =	3.749693
518		.001750 x	912.618392 =	1.597082
502		.000583 x	816.828773 =	.476211
116		.280000 x	20.419486 =	5.717456

			T.E =	11.735393
7008	7008			
111		.021000 x	15.741598 =	.330574
558		.000972 x	1,143.029457 =	1.111025
507		.000875 x	961.608107 =	.841407
503		.001750 x	936.292073 =	1.638511
7007		1.100000 x	11.735393 =	12.908932
112		.210000 x	17.312112 =	3.635544

			T.E =	20.465992
7009	7009			
560		.006417 x	731.957090 =	4.696969

			T.E =	4.696969
7010	7010			
7010 Α		1.000000 x	.360054 =	.360054
7010 Β		1.000000 x	.540653 =	.540653
7010 Γ		1.000000 x	.571780 =	.571780
7010 Ε		1.000000 x	1.050063 =	1.050063
7010 Δ		1.000000 x	.331428 =	.331428

			ΑΘΡΟΙΣΜΑ =	2.853978

			T.E =	3.282075

7011	7011			
502		.001367 x	816.828773 =	1.116605
502		.000700 x	816.828773 =	.571780
558		.000729 x	1,143.029457 =	.833268
563		.001367 x	.000000 =	.000000
558		.000729 x	1,143.029457 =	.833268
554		.000438 x	34.408000 =	.015071
503		.000438 x	936.292073 =	.410096

			ΑΘΡΟΙΣΜΑ =	3.780089

			T.E =	
7012	7012			
7008		1.000000 x	20.465992 =	20.465992

			ΑΘΡΟΙΣΜΑ =	20.465992

			T.E =	22.512591
7013	7013			
7003		1.000000 x	2.361658 =	2.361658

			ΑΘΡΟΙΣΜΑ =	2.361658

			T.E =	2.597824
7014	7014			
7005		1.000000 x	3.222074 =	3.222074

			ΑΘΡΟΙΣΜΑ =	3.222074

			T.E =	3.544281
7015	7015			
111		.056000 x	15.741598 =	.881529
7001		.900000 x	3.717263 =	3.345537
X 630.1		.300000 x	1.723035 =	.516911
X 630		.300000 x	1.511542 =	.453463

			T.E =	5.197439
7016.9	7016.9			
7016.4		1.000000 x	129.030942 =	129.030942
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.806188 =	25.806188
7016.6		1.000000 x	38.709283 =	38.709283
7016.7		1.000000 x	80.282150 =	80.282150

			T.E =	377.967942

7017.8	7017.8				
7017.3		1.000000 x	94.005484 =		94.005484
7017.4		1.000000 x	18.801097 =		18.801097
7017.5		1.000000 x	33.841974 =		33.841974
7017.6		1.000000 x	80.282150 =		80.282150
7017.7		1.000000 x	52.069689 =		52.069689
				T.E =	279.000394
7018	7018				
233.2		1.150000 x	.611600 =		.703340
113		.051000 x	20.419486 =		1.041394
				AΘΡΟΙΣΜΑ =	1.744734
				T.E =	1.919207
7019	7019				
7019 A6		1.000000 x	193.792098 =		193.792098
7019 A7		1.000000 x	19.379210 =		19.379210
				T.E =	213.171308
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	213.171308 =		213.171308
				T.E =	207.271308
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,603.224866 =		39.412074
				T.E =	59.715595
7020.1	7020.1				
570.2		.350000 x	127.284076 =		44.549427
571.2		.070000 x	261.479536 =		18.303568
571.1		.280000 x	463.532230 =		129.789024
				AΘΡΟΙΣΜΑ =	192.642019
	T.E =	.015625 x	192.642019 =		3.010032
7021	7021				
213		.150000 x	1.949500 =		.292425
7021.2		.014583 x	3,141.524626 =		45.812854
116		1.120000 x	20.419486 =		22.869824
				T.E =	68.975103

7021.1	7021.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	463.532230 =	129.789024
571.2		.070000 x	261.479536 =	18.303568
			AΘΡΟΙΣΜΑ =	192.642019
	T.E =	.020833 x	192.642019 =	4.013311
7022	7022			
213		.150000 x	1.949500 =	.292425
7022.2		.020000 x	2,878.244024 =	57.564880
116		1.400000 x	20.419486 =	28.587280
			T.E =	86.444586
7022.1	7022.1			
570.2		.350000 x	127.284076 =	44.549427
571.1		.280000 x	463.532230 =	129.789024
571.2		.070000 x	261.479536 =	18.303568
			AΘΡΟΙΣΜΑ =	192.642019
	T.E =	.028571 x	192.642019 =	5.503975
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
550		.012143 x	1,071.340886 =	13.009292
116		.850000 x	20.419486 =	17.356563
111		.425000 x	15.741598 =	6.690179
			T.E =	78.006035
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
550		.020238 x	1,071.340886 =	21.681797
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
			T.E =	95.078539
7025	7025			
233		6.180000 x	.558700 =	3.452766
396.5		.009000 x	1.180000 =	.010620
111		.425000 x	15.741598 =	6.690179
652		.001000 x	150.772313 =	.150772
550		.020238 x	1,071.340886 =	21.681797
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.700345

7026	7026			
236		16.808000 x	.624500 =	10.496596
113		3.400000 x	20.419486 =	69.426252
113		.909160 x	20.419486 =	18.564580
6310		12.350000 x	1.454463 =	17.962618
398.5		125.400000 x	6.400000 =	802.560000

			ΑΘΡΟΙΣΜΑ =	919.010046
	T.E =	.007259 x	919.010046 =	6.671094

7027	7027			
236		1.100000 x	.624500 =	.686950
113		.059500 x	20.419486 =	1.214959

			T.E =	1.901909
7028	7028			
111		.144500 x	15.741598 =	2.274661
112		.144500 x	17.312112 =	2.501600
6751		.600000 x	5.286321 =	3.171793
111		.425000 x	15.741598 =	6.690179
6751		.120000 x	5.286321 =	.634359

			ΑΘΡΟΙΣΜΑ =	15.272591

			T.E =	17.563480
7029	7029			
568.1		.021250 x	2,701.551748 =	57.407975
569.2		.021250 x	620.296952 =	13.181310
570.2		.021250 x	127.284076 =	2.704787
571.2		.021250 x	261.479536 =	5.556440

			T.E =	78.850512
7030	7030			
398.6		.015385 x	330.000000 =	5.077050
572		.026563 x	867.487817 =	23.043079

			ΑΘΡΟΙΣΜΑ =	28.120129

			T.E =	39.368180
7031	7031			
573		.106250 x	1,096.747392 =	116.529410

			ΑΘΡΟΙΣΜΑ =	116.529410

			T.E =	134.008822
7032	7032			
573		.212500 x	1,096.747392 =	233.058821

			ΑΘΡΟΙΣΜΑ =	233.058821

			T.E =	302.976467

7101.1	7101.1			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722
574		.132813 x	3,734.271482 =	495.959798
567		.132813 x	407.320272 =	54.097427

			ΑΘΡΟΙΣΜΑ =	554.294634

			T.E =	570.923473
7101.2	7101.2			
398.1		15.000000 x	.255000 =	3.825000
567		.148750 x	407.320272 =	60.588890
574		.148750 x	3,734.271482 =	555.472883
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722

			ΑΘΡΟΙΣΜΑ =	620.299182

			T.E =	638.908157
7101.3	7101.3			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
567		.159375 x	407.320272 =	64.916668
T 630		.105000 x	1.835444 =	.192722
574		.159375 x	3,734.271482 =	595.149517

			ΑΘΡΟΙΣΜΑ =	664.303594

			T.E =	684.232702
7101.4	7101.4			
398.1		15.000000 x	.255000 =	3.825000
567		.170000 x	407.320272 =	69.244446
T 630		.105000 x	1.835444 =	.192722
T 630.1		.105000 x	2.092257 =	.219687
574		.170000 x	3,734.271482 =	634.826152

			ΑΘΡΟΙΣΜΑ =	708.308007

			T.E =	729.557247
7101.5	7101.5			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722
574		.191250 x	3,734.271482 =	714.179421
567		.191250 x	407.320272 =	77.900002

			ΑΘΡΟΙΣΜΑ =	796.316832

			T.E =	820.206337

7102.1	7102.1			
398.1		15.000000 x	.255000 =	3.825000
567		.302813 x	407.320272 =	123.341874
574		.302813 x	3,734.271482 =	1,130.785950
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722

			ΑΘΡΟΙΣΜΑ =	1,258.365232

			T.E =	1,296.116189
7102.2	7102.2			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
567		.329375 x	407.320272 =	134.161115
T 630		.105000 x	1.835444 =	.192722
574		.329375 x	3,734.271482 =	1,229.975669

			ΑΘΡΟΙΣΜΑ =	1,368.374193

			T.E =	1,409.425418
7102.3	7102.3			
398.1		15.000000 x	.255000 =	3.825000
567		.361250 x	407.320272 =	147.144448
T 630		.105000 x	1.835444 =	.192722
T 630.1		.105000 x	2.092257 =	.219687
574		.361250 x	3,734.271482 =	1,349.005573

			ΑΘΡΟΙΣΜΑ =	1,500.387430

			T.E =	1,545.399053
7102.4	7102.4			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722
574		.403750 x	3,734.271482 =	1,507.712111
567		.403750 x	407.320272 =	164.455560

			ΑΘΡΟΙΣΜΑ =	1,676.405079

			T.E =	1,726.697232
7102.5	7102.5			
398.1		15.000000 x	.255000 =	3.825000
567		.446250 x	407.320272 =	181.766671
T 630		.105000 x	1.835444 =	.192722
574		.446250 x	3,734.271482 =	1,666.418649
T 630.1		.105000 x	2.092257 =	.219687

			ΑΘΡΟΙΣΜΑ =	1,852.422729

			T.E =	1,907.995411

7103	7103			
113		3.400000 x	20.419486 =	69.426252
113		.283333 x	20.419486 =	5.785514
115		.070833 x	21.778427 =	1.542631
575		.106250 x	1,043.387858 =	110.859960

			T.E =	187.614358
7104	7104			
113		1.700000 x	20.419486 =	34.713126
567		.106250 x	407.320272 =	43.277779
576		.106250 x	7.645000 =	.812281

			T.E =	78.803186
7105	7105			
111		.850000 x	15.741598 =	13.380358
576		.106250 x	7.645000 =	.812281
567		.106250 x	407.320272 =	43.277779
113		.850000 x	20.419486 =	17.356563

			T.E =	74.826982
7106.1	7106.1			
577		.265625 x	689.004219 =	183.016746

			AΘΡΟΙΣΜΑ =	183.016746

			T.E =	192.167583
7106.2	7106.2			
577		.297500 x	689.004219 =	204.978755

			AΘΡΟΙΣΜΑ =	204.978755

			T.E =	215.227693
7106.3	7106.3			
577		.350625 x	689.004219 =	241.582104

			AΘΡΟΙΣΜΑ =	241.582104

			T.E =	253.661210
7106.4	7106.4			
577		.425000 x	689.004219 =	292.826793

			AΘΡΟΙΣΜΑ =	292.826793

			T.E =	307.468133

7106.5	7106.5				
577		.531250 x	689.004219 =	366.033491	

			ΑΘΡΟΙΣΜΑ =	366.033491	

			T.E =	384.335166	
7107.1	7107.1				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.1		1.000000 x	192.167583 =	192.167583	

			T.E =	232.967583	
7107.2	7107.2				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.2		1.000000 x	215.227693 =	215.227693	

			T.E =	256.027693	
7107.3	7107.3				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.3		1.000000 x	253.661210 =	253.661210	

			T.E =	294.461210	
7107.4	7107.4				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.4		1.000000 x	307.468133 =	307.468133	

			T.E =	348.268133	
7107.5	7107.5				
398.7		.030000 x	1,360.000000 =	40.800000	
7106.5		1.000000 x	384.335166 =	384.335166	

			T.E =	425.135166	
7108	7108				
398.11		1.000000 x	140.870000 =	140.870000	
574		.053125 x	3,734.271482 =	198.383172	

			T.E =	339.253172	
7109	7109				
398.12		1.000000 x	182.180000 =	182.180000	
574		.053125 x	3,734.271482 =	198.383172	

			T.E =	380.563172	

7110	7110				
398.10		1.170000 x	142.840000 =		167.122800
574		.053125 x	3,734.271482 =		198.383172

				T.E =	365.505972
7111	7111				
398.9		1.170000 x	131.840000 =		154.252800
574		.053125 x	3,734.271482 =		198.383172

				T.E =	352.635972
7112	7112				
398.13		1.300000 x	10.300000 =		13.390000
577		.010625 x	689.004219 =		7.320670

				T.E =	20.710670
7113	7113				
241		1.200000 x	7.750000 =		9.300000
574		.001063 x	3,734.271482 =		3.969531

				T.E =	13.269531
7114	7114				
398.8		.120000 x	31.620000 =		3.794400
577		.053125 x	689.004219 =		36.603349

				T.E =	40.397749
7115	7115				
574		.026563 x	3,734.271482 =		99.193453

				T.E =	99.193453
7116	7116				
577		.170000 x	689.004219 =		117.130717

				T.E =	117.130717
7117	7117				
574		.001063 x	3,734.271482 =		3.969531

				T.E =	3.969531

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
574.1		.425000 x	2,241.497688 =	952.636517
578		.850000 x	652.241766 =	554.405501

			T.E =	1,935.213484
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,241.497688 =	1,905.273035
578		.850000 x	652.241766 =	554.405501

			T.E =	3,101.935734
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	386.217688 =	98.485510

			T.E =	312.571243
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	386.217688 =	229.799524

			T.E =	443.885257
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
578		.425000 x	652.241766 =	277.202751
575.1		.425000 x	259.627416 =	110.341652

			T.E =	548.108702
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	652.241766 =	831.608252
575.1		1.275000 x	259.627416 =	331.024955

			T.E =	1,430.240373
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
578		.425000 x	652.241766 =	277.202751
576.1		.425000 x	6.950000 =	2.953750

			T.E =	387.199367

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.950000 =	2.953750
578		.425000 x	652.241766 =	277.202751
			T.E =	387.199367
7122	7122			
398.1		15.000000 x	.255000 =	3.825000
T 630		.105000 x	1.835444 =	.192722
T 630.1		.105000 x	2.092257 =	.219687
567		.122188 x	407.320272 =	49.769649
580		.122188 x	1,748.663462 =	213.665691
			AΘΡΟΙΣΜΑ =	267.672749
			T.E =	275.702932
7123	7123			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722
567		.286875 x	407.320272 =	116.850003
580		.286875 x	1,748.663462 =	501.647831
			AΘΡΟΙΣΜΑ =	622.735242
			T.E =	641.417300
7124	7124			
398.1		15.000000 x	.255000 =	3.825000
T 630.1		.105000 x	2.092257 =	.219687
T 630		.105000 x	1.835444 =	.192722
580		.063750 x	1,748.663462 =	111.477296
567		.063750 x	407.320272 =	25.966667
			T.E =	141.681372
7125	7125			
398.1		15.000000 x	.255000 =	3.825000
567		.127500 x	407.320272 =	51.933335
T 630		.105000 x	1.835444 =	.192722
580		.127500 x	1,748.663462 =	222.954591
T 630.1		.105000 x	2.092257 =	.219687
			T.E =	279.125335
7126	7126			
398.16		1.000000 x	64.290000 =	64.290000
580		.053125 x	1,748.663462 =	92.897746
			T.E =	157.187746

7127 7127

398.15
580

1.170000 x
.015938 x

77.960000 =
1,748.663462 =

91.213200
27.870198

T.E = 119.083398

7128 7128

398.14
580

1.170000 x
.015938 x

60.360000 =
1,748.663462 =

70.621200
27.870198

T.E = 98.491398

7129 7129

6751

1.000000 x

5.286321 =

5.286321

T.E = 5.286321