

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

4ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	Κατχ Τιμή X 1.8117/ 6.46	16.829739
112	Κατχ Τιμή X 1.8117/ 6.46	18.705943
113	Κατχ Τιμή X 1.8117/ 6.46	24.769248
114	Κατχ Τιμή X 1.8117/ 6.67	23.989407
115	Κατχ Τιμή X 1.8117/ 6.67	19.931416
116	Κατχ Τιμή X 1.8117/ 6.46	24.152261
117	Κατχ Τιμή X 1.8117/ 6.67	19.931416
118	Κατχ Τιμή X 1.8117/ 6.67	18.233796
150		.074800
211		.826000
212		.961300
213		1.895000
214		3.490000
221		.098900
221.1		.089500
222		.116200
222.1		.104900
223		.119300
223.1		.104900
224		.070000
231		.695000
232		1.785000
233		.528700
233.1		.528700
233.2		.560100
233.3		7.650000
234		.691500
234.1		.792500
234.2		.719000
234.3		.755000
235		.553000
236		.523000
237		1.060000
237.1		1.200000
241		7.050000
242		5.000000
243		1.900000
244		2.470000
251		290.000000
252		210.000000
252.1		
252.2		
261		15.100000
261.1		13.500000
261.2		20.700000
261.3		
261.4		
262		26.300000
262.1		
263		32.400000
263.1		
263.2		46.700000
263.3		
264		64.100000
264.1		
265		115.100000
265.1		
271		206.300000
271.1		

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.120000
361.1	11.750000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.300000
361.3	19.280000
361.4	
361.5	36.800000
361.6	49.220000
361.7	76.000000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	95,302.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	64,900.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	113,243.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	129,809.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	21,676.000000
387.1	
387.2	
387.3	18,183.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	5,630.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	4,757.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	6,917.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	12,978.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	41.560000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	9.400000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	88.000000
398.2	42.300000
398.3	48.000000
398.4	64.000000
398.5	5.780000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	255.610000
402	369.270000
403	100.390000
404	202.580000
405	200.790000
406	311.770000
407	52.580000
408	4.310000
409	120.060000
410	110.970000
411	26.060000
412	2.840000
413	4.310000
414	5.950000
415	8.370000
416	12.890000
417	128.110000
419	4.310000
420	92.650000
421	31.010000
428	425.280000
429	73.880000
450	79.840000
451	4.640000
452	100.100000
453	
454	92.650000
455	29.790000
456	33.360000
457	435.860000
458	271.410000
459	409.940000
460	506.910000
461	227.610000
462	331.880000
463	41.700000
464	365.250000
465	97.710000
466	45.580000
467	331.880000
468	83.110000
469	83.110000
470	67.030000
471	58.090000
472	25.250000
473	16.230000
474	33.360000
475	1,876.330000
476	81.330000
477	6.620000
478	109.630000
479	176.370000
480	25.920000
481	773.710000

501	501				
401		1.000000 x	255.610000 =	255.610000	
211		50.000000 x	.826000 =	41.300000	
118		3.000000 x	18.233796 =	54.701388	
114		8.000000 x	23.989407 =	191.915256	
214		3.000000 x	3.490000 =	10.470000	

			ΑΘΡΟΙΣΜΑ =	553.996644	

			Η.Δ. =	609.396308	
502	502				
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.490000 =	24.430000	
211		80.000000 x	.826000 =	66.080000	
118		4.000000 x	18.233796 =	72.935184	
114		8.000000 x	23.989407 =	191.915256	

			ΑΘΡΟΙΣΜΑ =	724.630440	

			Η.Δ. =	797.093484	
503	503				
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.490000 =	34.900000	
211		110.000000 x	.826000 =	90.860000	
114		8.000000 x	23.989407 =	191.915256	
118		4.000000 x	18.233796 =	72.935184	

			ΑΘΡΟΙΣΜΑ =	815.890440	

			Η.Δ. =	897.479484	
504	504				
403		1.000000 x	100.390000 =	100.390000	
211		40.000000 x	.826000 =	33.040000	
114		8.000000 x	23.989407 =	191.915256	
214		2.000000 x	3.490000 =	6.980000	

			ΑΘΡΟΙΣΜΑ =	332.325256	

			Η.Δ. =	365.557782	
505	505				
404		1.000000 x	202.580000 =	202.580000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
214		10.000000 x	3.490000 =	34.900000	
211		200.000000 x	.826000 =	165.200000	

			ΑΘΡΟΙΣΜΑ =	740.465624	

			Η.Δ. =	814.512186	

506	506				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	3.490000 =	20.940000	
211		95.000000 x	.826000 =	78.470000	

			ΑΘΡΟΙΣΜΑ =	650.485624	

			Η.Δ. =	715.534186	
507	507				
406		1.000000 x	311.770000 =	311.770000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	3.490000 =	34.900000	
211		165.000000 x	.826000 =	136.290000	

			ΑΘΡΟΙΣΜΑ =	855.745624	

			Η.Δ. =	941.320186	
508	508				
407		1.000000 x	52.580000 =	52.580000	
116		16.000000 x	24.152261 =	386.436176	
214		2.000000 x	3.490000 =	6.980000	
211		40.000000 x	.826000 =	33.040000	
115		4.000000 x	19.931416 =	79.725664	
408		2.000000 x	4.310000 =	8.620000	

			ΑΘΡΟΙΣΜΑ =	567.381840	

			Η.Δ. =	624.120024	
509	509				
409		1.000000 x	120.060000 =	120.060000	
117		8.000000 x	19.931416 =	159.451328	
214		5.000000 x	3.490000 =	17.450000	
211		80.000000 x	.826000 =	66.080000	

			ΑΘΡΟΙΣΜΑ =	363.041328	

			Η.Δ. =	399.345461	
510	510				
410		1.000000 x	110.970000 =	110.970000	
117		8.000000 x	19.931416 =	159.451328	
211		80.000000 x	.826000 =	66.080000	
214		5.000000 x	3.490000 =	17.450000	

			ΑΘΡΟΙΣΜΑ =	353.951328	

			Η.Δ. =	389.346461	

511	511				
411		1.000000 x	26.060000 =	26.060000	
112		30.000000 x	18.705943 =	561.178290	
115		4.000000 x	19.931416 =	79.725664	
214		1.000000 x	3.490000 =	3.490000	
212		17.000000 x	.961300 =	16.342100	

		ΑΘΡΟΙΣΜΑ =		686.796054	

		Η.Δ. =		755.475659	
512	512				
412		1.000000 x	2.840000 =	2.840000	
214		1.000000 x	3.490000 =	3.490000	
115		2.000000 x	19.931416 =	39.862832	
112		2.000000 x	18.705943 =	37.411886	
211		10.000000 x	.826000 =	8.260000	

		ΑΘΡΟΙΣΜΑ =		91.864718	

		Η.Δ. =		101.051190	
513	513				
413		1.000000 x	4.310000 =	4.310000	
211		15.000000 x	.826000 =	12.390000	
115		3.000000 x	19.931416 =	59.794248	
112		3.000000 x	18.705943 =	56.117829	
214		1.500000 x	3.490000 =	5.235000	

		ΑΘΡΟΙΣΜΑ =		137.847077	

		Η.Δ. =		151.631785	
514	514				
414		1.000000 x	5.950000 =	5.950000	
115		4.000000 x	19.931416 =	79.725664	
112		4.000000 x	18.705943 =	74.823772	
214		2.000000 x	3.490000 =	6.980000	
211		21.000000 x	.826000 =	17.346000	

		ΑΘΡΟΙΣΜΑ =		184.825436	

		Η.Δ. =		203.307980	
515	515				
415		1.000000 x	8.370000 =	8.370000	
112		6.000000 x	18.705943 =	112.235658	
115		5.000000 x	19.931416 =	99.657080	
214		2.500000 x	3.490000 =	8.725000	
211		27.000000 x	.826000 =	22.302000	

		ΑΘΡΟΙΣΜΑ =		251.289738	

		Η.Δ. =		276.418712	

516	516				
416		1.000000 x	12.890000 =	12.890000	
115		6.000000 x	19.931416 =	119.588496	
112		8.000000 x	18.705943 =	149.647544	
214		3.500000 x	3.490000 =	12.215000	
211		33.000000 x	.826000 =	27.258000	

		ΑΘΡΟΙΣΜΑ =		321.599040	

		H.Δ. =		353.758944	
517	517				
406		1.000000 x	311.770000 =	311.770000	
406		.400000 x	311.770000 =	124.708000	
116		8.000000 x	24.152261 =	193.218088	
114		8.000000 x	23.989407 =	191.915256	
113		2.000000 x	24.769248 =	49.538496	
112		16.000000 x	18.705943 =	299.295088	
111		16.000000 x	16.829739 =	269.275824	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	3.490000 =	27.920000	
211		240.000000 x	.826000 =	198.240000	
407		2.000000 x	52.580000 =	105.160000	
115		8.000000 x	19.931416 =	159.451328	

		ΑΘΡΟΙΣΜΑ =		1,973.992080	

		H.Δ. =		2,171.391288	
518	518				
417		1.000000 x	128.110000 =	128.110000	
214		12.000000 x	3.490000 =	41.880000	
212		5.000000 x	.961300 =	4.806500	
211		180.000000 x	.826000 =	148.680000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
112		8.000000 x	18.705943 =	149.647544	

		ΑΘΡΟΙΣΜΑ =		810.909668	

		H.Δ. =		892.000635	
520	520				
419		1.000000 x	4.310000 =	4.310000	
212		2.000000 x	.961300 =	1.922600	
211		80.000000 x	.826000 =	66.080000	
118		4.000000 x	18.233796 =	72.935184	
115		8.000000 x	19.931416 =	159.451328	
112		4.000000 x	18.705943 =	74.823772	
214		5.000000 x	3.490000 =	17.450000	

		ΑΘΡΟΙΣΜΑ =		396.972884	

		H.Δ. =		436.670172	

521	521				
420		1.000000 x	92.650000 =	92.650000	
118		4.000000 x	18.233796 =	72.935184	
114		8.000000 x	23.989407 =	191.915256	
214		3.000000 x	3.490000 =	10.470000	
211		40.000000 x	.826000 =	33.040000	
			AΘΡΟΙΣΜΑ =	401.010440	
			H.Δ. =	441.111484	
522	522				
421		1.000000 x	31.010000 =	31.010000	
114		8.000000 x	23.989407 =	191.915256	
118		2.000000 x	18.233796 =	36.467592	
214		2.000000 x	3.490000 =	6.980000	
211		20.000000 x	.826000 =	16.520000	
			AΘΡΟΙΣΜΑ =	282.892848	
			H.Δ. =	311.182133	
529	529				
429		1.000000 x	73.880000 =	73.880000	
211		70.000000 x	.826000 =	57.820000	
118		4.000000 x	18.233796 =	72.935184	
114		8.000000 x	23.989407 =	191.915256	
214		4.000000 x	3.490000 =	13.960000	
			AΘΡΟΙΣΜΑ =	410.510440	
			H.Δ. =	451.561484	
550	550				
450		1.000000 x	79.840000 =	79.840000	
451		4.000000 x	4.640000 =	18.560000	
116		32.000000 x	24.152261 =	772.872352	
115		4.000000 x	19.931416 =	79.725664	
214		4.000000 x	3.490000 =	13.960000	
211		90.000000 x	.826000 =	74.340000	
			AΘΡΟΙΣΜΑ =	1,039.298016	
			H.Δ. =	1,143.227818	
551	551				
405		1.000000 x	200.790000 =	200.790000	
211		95.000000 x	.826000 =	78.470000	
214		6.000000 x	3.490000 =	20.940000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
452		1.000000 x	100.100000 =	100.100000	
			AΘΡΟΙΣΜΑ =	738.085624	
			H.Δ. =	811.894186	

552	552			
453		1.000000 x	.000000 =	.000000
115		8.000000 x	19.931416 =	159.451328
214		1.000000 x	3.490000 =	3.490000
211		18.000000 x	.826000 =	14.868000

		ΑΘΡΟΙΣΜΑ =		177.809328

		H.Δ. =		
553	553			
454		1.000000 x	92.650000 =	92.650000
214		4.000000 x	3.490000 =	13.960000
211		100.000000 x	.826000 =	82.600000

		ΑΘΡΟΙΣΜΑ =		189.210000

		H.Δ. =		208.131000
554	554			
455		1.000000 x	29.790000 =	29.790000

		ΑΘΡΟΙΣΜΑ =		29.790000

		H.Δ. =		32.769000
555	555			
456		1.000000 x	33.360000 =	33.360000
212		17.000000 x	.961300 =	16.342100
112		32.000000 x	18.705943 =	598.590176
115		4.000000 x	19.931416 =	79.725664
214		1.000000 x	3.490000 =	3.490000

		ΑΘΡΟΙΣΜΑ =		731.507940

		H.Δ. =		804.658734
556	556			
457		1.000000 x	435.860000 =	435.860000
114		8.000000 x	23.989407 =	191.915256
118		8.000000 x	18.233796 =	145.870368
214		18.000000 x	3.490000 =	62.820000
211		200.000000 x	.826000 =	165.200000

		ΑΘΡΟΙΣΜΑ =		1,001.665624

		H.Δ. =		1,101.832186
557	557			
458		1.000000 x	271.410000 =	271.410000
118		8.000000 x	18.233796 =	145.870368
114		8.000000 x	23.989407 =	191.915256
214		11.000000 x	3.490000 =	38.390000
211		130.000000 x	.826000 =	107.380000

		ΑΘΡΟΙΣΜΑ =		754.965624

		H.Δ. =		830.462186

558	558				
459		1.000000 x	409.940000 =	409.940000	
214		12.000000 x	3.490000 =	41.880000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	.826000 =	165.200000	
			AΘΡΟΙΣΜΑ =	1,002.305624	
			H.Δ. =	1,102.536186	
559	559				
460		1.000000 x	506.910000 =	506.910000	
211		250.000000 x	.826000 =	206.500000	
214		15.000000 x	3.490000 =	52.350000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
242		12.000000 x	5.000000 =	60.000000	
			AΘΡΟΙΣΜΑ =	1,163.545624	
			H.Δ. =	1,279.900186	
560	560				
461		1.000000 x	227.610000 =	227.610000	
114		8.000000 x	23.989407 =	191.915256	
211		160.000000 x	.826000 =	132.160000	
214		8.000000 x	3.490000 =	27.920000	
			AΘΡΟΙΣΜΑ =	579.605256	
			H.Δ. =	637.565782	
561	561				
462		1.000000 x	331.880000 =	331.880000	
214		12.000000 x	3.490000 =	41.880000	
114		8.000000 x	23.989407 =	191.915256	
211		230.000000 x	.826000 =	189.980000	
			AΘΡΟΙΣΜΑ =	755.655256	
			H.Δ. =	831.220782	
562	562				
463		1.000000 x	41.700000 =	41.700000	
214		2.400000 x	3.490000 =	8.376000	
211		50.000000 x	.826000 =	41.300000	
			AΘΡΟΙΣΜΑ =	91.376000	
			H.Δ. =	100.513600	

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	23.989407 =	383.830512	
112		24.000000 x	18.705943 =	448.942632	
214		16.000000 x	3.490000 =	55.840000	
464		1.000000 x	365.250000 =	365.250000	

		ΑΘΡΟΙΣΜΑ =		1,253.863144	

		H.Δ. =			
564	564				
465		1.000000 x	97.710000 =	97.710000	
567		3.000000 x	354.958380 =	1,064.875140	
111		8.000000 x	16.829739 =	134.637912	
115		8.000000 x	19.931416 =	159.451328	
115		8.000000 x	19.931416 =	159.451328	

		ΑΘΡΟΙΣΜΑ =		1,616.125708	

		H.Δ. =		1,777.738279	
565	565				
450		3.000000 x	79.840000 =	239.520000	
465		1.000000 x	97.710000 =	97.710000	
115		8.000000 x	19.931416 =	159.451328	
115		12.000000 x	19.931416 =	239.176992	

		H.Δ. =		735.858320	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	45.580000 =	45.580000	
112		1.000000 x	18.705943 =	18.705943	
115		2.000000 x	19.931416 =	39.862832	

		ΑΘΡΟΙΣΜΑ =		104.148775	

		H.Δ. =			
567	567				
450		1.000000 x	79.840000 =	79.840000	
115		4.000000 x	19.931416 =	79.725664	
112		4.000000 x	18.705943 =	74.823772	
214		4.000000 x	3.490000 =	13.960000	
211		90.000000 x	.826000 =	74.340000	

		ΑΘΡΟΙΣΜΑ =		322.689436	

		H.Δ. =		354.958380	

568.1	568.1				
467		1.000000 x	331.880000 =	331.880000	
567		2.000000 x	354.958380 =	709.916760	
512		.240000 x	101.051190 =	24.252286	
510		.072000 x	389.346461 =	28.032945	
118		32.000000 x	18.233796 =	583.481472	
114		8.000000 x	23.989407 =	191.915256	
113		32.000000 x	24.769248 =	792.615936	
214		16.000000 x	3.490000 =	55.840000	
			AΘΡΟΙΣΜΑ =	2,717.934655	
			H.Δ. =	2,989.728120	
568.2	568.2				
450		2.000000 x	79.840000 =	159.680000	
115		8.000000 x	19.931416 =	159.451328	
467		1.000000 x	331.880000 =	331.880000	
114		8.000000 x	23.989407 =	191.915256	
			H.Δ. =	842.926584	
569.1	569.1				
468		1.000000 x	83.110000 =	83.110000	
214		16.000000 x	3.490000 =	55.840000	
567		2.000000 x	354.958380 =	709.916760	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
			AΘΡΟΙΣΜΑ =	1,186.652384	
			H.Δ. =	1,305.317622	
569.2	569.2				
450		2.000000 x	79.840000 =	159.680000	
115		8.000000 x	19.931416 =	159.451328	
114		8.000000 x	23.989407 =	191.915256	
468		1.000000 x	83.110000 =	83.110000	
			H.Δ. =	594.156584	
570.1	570.1				
469		1.000000 x	83.110000 =	83.110000	
211		135.000000 x	.826000 =	111.510000	
114		8.000000 x	23.989407 =	191.915256	
118		4.000000 x	18.233796 =	72.935184	
214		16.000000 x	3.490000 =	55.840000	
			AΘΡΟΙΣΜΑ =	515.310440	
			H.Δ. =	566.841484	

570.2	570.2				
469		1.000000 x	83.110000 =	83.110000	
118		4.000000 x	18.233796 =	72.935184	

			H.Δ. =	156.045184	
571.1	571.1				
470		1.000000 x	67.030000 =	67.030000	
114		8.000000 x	23.989407 =	191.915256	
214		4.000000 x	3.490000 =	13.960000	
211		114.000000 x	.826000 =	94.164000	

			ΑΘΡΟΙΣΜΑ =	367.069256	

			H.Δ. =	403.776182	
571.2	571.2				
470		1.000000 x	67.030000 =	67.030000	
114		8.000000 x	23.989407 =	191.915256	

			H.Δ. =	258.945256	
572	572				
407		1.000000 x	52.580000 =	52.580000	
471		1.000000 x	58.090000 =	58.090000	
114		8.000000 x	23.989407 =	191.915256	
214		8.000000 x	3.490000 =	27.920000	
111		24.000000 x	16.829739 =	403.913736	
211		54.000000 x	.826000 =	44.604000	

			ΑΘΡΟΙΣΜΑ =	779.022992	

			H.Δ. =	856.925291	
573	573				
407		1.000000 x	52.580000 =	52.580000	
473		.250000 x	16.230000 =	4.057500	
474		.250000 x	33.360000 =	8.340000	
474		1.000000 x	33.360000 =	33.360000	
473		1.000000 x	16.230000 =	16.230000	
115		16.000000 x	19.931416 =	318.902656	
111		24.000000 x	16.829739 =	403.913736	
214		8.000000 x	3.490000 =	27.920000	
211		54.000000 x	.826000 =	44.604000	
407		.250000 x	52.580000 =	13.145000	
472		.250000 x	25.250000 =	6.312500	
472		1.000000 x	25.250000 =	25.250000	

			ΑΘΡΟΙΣΜΑ =	954.615392	

			H.Δ. =	1,050.076931	

574	574				
475		1.000000 x	1,876.330000 =		1,876.330000
214		30.000000 x	3.490000 =		104.700000
118		8.000000 x	18.233796 =		145.870368
114		8.000000 x	23.989407 =		191.915256
111		16.000000 x	16.829739 =		269.275824
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	.826000 =		487.340000
				ΑΘΡΟΙΣΜΑ =	3,110.431448
				Η.Δ. =	3,421.474593
574.1	574.1				
475		1.000000 x	1,876.330000 =		1,876.330000
114		8.000000 x	23.989407 =		191.915256
118		8.000000 x	18.233796 =		145.870368
				Η.Δ. =	2,214.115624
575	575				
476		1.000000 x	81.330000 =		81.330000
214		23.000000 x	3.490000 =		80.270000
115		8.000000 x	19.931416 =		159.451328
211		470.000000 x	.826000 =		388.220000
				ΑΘΡΟΙΣΜΑ =	709.271328
				Η.Δ. =	780.198461
575.1	575.1				
476		1.000000 x	81.330000 =		81.330000
115		8.000000 x	19.931416 =		159.451328
				Η.Δ. =	240.781328
576	576				
477		1.000000 x	6.620000 =		6.620000
				ΑΘΡΟΙΣΜΑ =	6.620000
				Η.Δ. =	7.282000
576.1	576.1				
477		1.000000 x	6.620000 =		6.620000
				Η.Δ. =	6.620000

577	577				
478		1.000000 x	109.630000 =	109.630000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.989407 =	191.915256	
118		8.000000 x	18.233796 =	145.870368	
111		8.000000 x	16.829739 =	134.637912	
214		4.000000 x	3.490000 =	13.960000	
211		70.000000 x	.826000 =	57.820000	

				ΑΘΡΟΙΣΜΑ =	663.833536

				Η.Δ. =	730.216890
577.1	577.1				
478		1.000000 x	109.630000 =	109.630000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	

				Η.Δ. =	447.415624
578	578				
479		1.000000 x	176.370000 =	176.370000	
211		50.000000 x	.826000 =	41.300000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	18.233796 =	72.935184	
114		8.000000 x	23.989407 =	191.915256	
112		4.000000 x	18.705943 =	74.823772	
214		5.000000 x	3.490000 =	17.450000	

				ΑΘΡΟΙΣΜΑ =	599.794212

				Η.Δ. =	659.773633
579	579				
480		1.000000 x	25.920000 =	25.920000	
212		28.000000 x	.961300 =	26.916400	
117		8.000000 x	19.931416 =	159.451328	
214		1.000000 x	3.490000 =	3.490000	

				ΑΘΡΟΙΣΜΑ =	215.777728

				Η.Δ. =	237.355501
580	580				
481		1.000000 x	773.710000 =	773.710000	
211		168.000000 x	.826000 =	138.768000	
242		2.000000 x	5.000000 =	10.000000	
118		8.000000 x	18.233796 =	145.870368	
114		8.000000 x	23.989407 =	191.915256	
111		16.000000 x	16.829739 =	269.275824	
214		8.000000 x	3.490000 =	27.920000	

				ΑΘΡΟΙΣΜΑ =	1,557.459448

				Η.Δ. =	1,713.205393

581	581				
481		1.000000 x	773.710000 =		773.710000
114		8.000000 x	23.989407 =		191.915256
118		8.000000 x	18.233796 =		145.870368
				H.Δ. =	1,111.495624
7020.2	7020.2				
111		8.000000 x	16.829739 =		134.637912
571.2		.150000 x	258.945256 =		38.841788
571.1		.350000 x	403.776182 =		141.321664
570.2		.350000 x	156.045184 =		54.615814
570.1		.150000 x	566.841484 =		85.026223
569.2		.670000 x	594.156584 =		398.084911
569.1		.330000 x	1,305.317622 =		430.754815
568.2		.550000 x	842.926584 =		463.609621
568.1		.450000 x	2,989.728120 =		1,345.377654
567		1.000000 x	354.958380 =		354.958380
116		8.000000 x	24.152261 =		193.218088
				H.Δ. =	3,640.446871
7021.2	7021.2				
111		8.000000 x	16.829739 =		134.637912
571.2		.240000 x	258.945256 =		62.146861
571.1		.260000 x	403.776182 =		104.981807
570.2		.390000 x	156.045184 =		60.857622
570.1		.110000 x	566.841484 =		62.352563
569.2		.750000 x	594.156584 =		445.617438
116		8.000000 x	24.152261 =		193.218088
567		1.000000 x	354.958380 =		354.958380
568.1		.250000 x	2,989.728120 =		747.432030
569.1		.250000 x	1,305.317622 =		326.329406
568.2		.750000 x	842.926584 =		632.194938
				H.Δ. =	3,124.727045
7022.2	7022.2				
111		8.000000 x	16.829739 =		134.637912
571.2		.310000 x	258.945256 =		80.273029
571.1		.190000 x	403.776182 =		76.717475
570.2		.420000 x	156.045184 =		65.538977
570.1		.080000 x	566.841484 =		45.347319
569.2		.820000 x	594.156584 =		487.208399
569.1		.180000 x	1,305.317622 =		234.957172
568.2		.850000 x	842.926584 =		716.487596
568.1		.150000 x	2,989.728120 =		448.459218
567		1.000000 x	354.958380 =		354.958380
116		8.000000 x	24.152261 =		193.218088
				H.Δ. =	2,837.803565

613	613			
111		.140000 x	16.829739 =	2.356163
520		.003500 x	436.670172 =	1.528346
503		.000770 x	897.479484 =	.691059
504		.002800 x	365.557782 =	1.023562

			B.T =	5.599130
614	614			
112		.070000 x	18.705943 =	1.309416
504		.002800 x	365.557782 =	1.023562
518		.004375 x	892.000635 =	3.902503
509		.004375 x	399.345461 =	1.747136
503		.000700 x	897.479484 =	.628236

			B.T =	8.610853
621.1	621.1			
213		.100000 x	1.895000 =	.189500
116		.140000 x	24.152261 =	3.381317
504		.003500 x	365.557782 =	1.279452
508		.003500 x	624.120024 =	2.184420
111		.560000 x	16.829739 =	9.424654

			B.T =	16.459343
622	622			
213		.100000 x	1.895000 =	.189500
112		.070000 x	18.705943 =	1.309416
116		.140000 x	24.152261 =	3.381317
509		.003500 x	399.345461 =	1.397709
508		.003500 x	624.120024 =	2.184420
518		.004340 x	892.000635 =	3.871283
504		.003500 x	365.557782 =	1.279452

			B.T =	13.613097
6360.1 A1	6360.1 A1			
6304		9.800000 x	6.352623 =	62.255705
6330		.038000 x	193.571772 =	7.355727
6330		.190000 x	193.571772 =	36.778637
6314		.382500 x	2.272414 =	.869198
6314		7.650000 x	2.272414 =	17.383967

			B.T =	124.643235
6360.1 A2	6360.1 A2			
6304		.450000 x	6.352623 =	2.858680
6310		2.142000 x	1.607828 =	3.443968
6330		.013000 x	193.571772 =	2.516433

			B.T =	8.819081

6360.1 A3	6360.1 A3			
6304		.960000 x	6.352623 =	6.098518
6329.2		.037000 x	178.799229 =	6.615571
6310		1.974000 x	1.607828 =	3.173852

			B.T =	15.887942
6360.1 A4	6360.1 A4			
6304		2.490000 x	6.352623 =	15.818031
6329.2		.109000 x	178.799229 =	19.489116

			B.T =	35.307147
6360.1 A5	6360.1 A5			
112		1.700000 x	18.705943 =	31.800103
113		2.975000 x	24.769248 =	73.688513
113		.425000 x	24.769248 =	10.526930
6069.1		.056400 x	11.602173 =	.654363

			B.T =	116.669909
6360.2 A1	6360.2 A1			
6304		10.650000 x	6.352623 =	67.655435
6314		.392500 x	2.272414 =	.891922
6314		7.850000 x	2.272414 =	17.838450
6330		.041000 x	193.571772 =	7.936443
6330		.205000 x	193.571772 =	39.682213

			B.T =	134.004463
6360.2 A2	6360.2 A2			
6304		.750000 x	6.352623 =	4.764467
6330		.019000 x	193.571772 =	3.677864
6310		2.383500 x	1.607828 =	3.832258

			B.T =	12.274589
6360.2 A3	6360.2 A3			
6304		1.140000 x	6.352623 =	7.241990
6310		2.341500 x	1.607828 =	3.764729
6329.2		.054000 x	178.799229 =	9.655158

			B.T =	20.661878
6360.2 A4	6360.2 A4			
6304		2.800000 x	6.352623 =	17.787344
6329.2		.118000 x	178.799229 =	21.098309

			B.T =	38.885653

6360.2 A5	6360.2 A5			
112		2.550000 x	18.705943 =	47.700155
113		.382500 x	24.769248 =	9.474237
113		2.975000 x	24.769248 =	73.688513
6069.1		.059400 x	11.602173 =	.689169

			B.T =	131.552074
6360.3 A1	6360.3 A1			
6304		13.900000 x	6.352623 =	88.301460
6314		.557500 x	2.272414 =	1.266871
6314		11.150000 x	2.272414 =	25.337416
6330		.270000 x	193.571772 =	52.264378
6330		.054000 x	193.571772 =	10.452876

			B.T =	177.623001
6360.3 A2	6360.3 A2			
6304		.940000 x	6.352623 =	5.971466
6330		.031000 x	193.571772 =	6.000725
6310		3.360000 x	1.607828 =	5.402302

			B.T =	17.374493
6360.3 A3	6360.3 A3			
6304		1.830000 x	6.352623 =	11.625300
6310		10.678500 x	1.607828 =	17.169191
6329.2		.099000 x	178.799229 =	17.701124

			B.T =	46.495615
6360.3 A4	6360.3 A4			
6304		3.420000 x	6.352623 =	21.725971
6329.2		.139000 x	178.799229 =	24.853093

			B.T =	46.579063
6360.3 A5	6360.3 A5			
112		5.100000 x	18.705943 =	95.400309
113		.340000 x	24.769248 =	8.421544
113		2.975000 x	24.769248 =	73.688513
6069.1		.073800 x	11.602173 =	.856240

			B.T =	178.366607

6360.4 A1	6360.4 A1			
6304		16.250000 x	6.352623 =	103.230124
6314		.885000 x	2.272414 =	2.011086
6314		17.700000 x	2.272414 =	40.221728
6330		.075000 x	193.571772 =	14.517883
6330		.375000 x	193.571772 =	72.589415

			B.T =	232.570235
6360.4 A2	6360.4 A2			
6304		1.060000 x	6.352623 =	6.733780
6330		.048000 x	193.571772 =	9.291445
6310		4.641000 x	1.607828 =	7.461930

			B.T =	23.487155
6360.4 A3	6360.4 A3			
6304		2.270000 x	6.352623 =	14.420454
6310		20.454000 x	1.607828 =	32.886514
6329.2		.125000 x	178.799229 =	22.349904

			B.T =	69.656872
6360.4 A4	6360.4 A4			
6304		2.800000 x	6.352623 =	17.787344
6329.2		.118000 x	178.799229 =	21.098309

			B.T =	38.885653
6360.4 A5	6360.4 A5			
112		6.800000 x	18.705943 =	127.200412
113		.297500 x	24.769248 =	7.368851
113		4.250000 x	24.769248 =	105.269304
6069.1		.091800 x	11.602173 =	1.065079

			B.T =	240.903647
6360.5 A1	6360.5 A1			
6304		17.950000 x	6.352623 =	114.029583
6314		1.050000 x	2.272414 =	2.386035
6314		21.000000 x	2.272414 =	47.720694
6330		.088000 x	193.571772 =	17.034316
6330		.440000 x	193.571772 =	85.171580

			B.T =	266.342207
6360.5 A2	6360.5 A2			
6304		1.220000 x	6.352623 =	7.750200
6330		.061000 x	193.571772 =	11.807878
6310		6.048000 x	1.607828 =	9.724144

			B.T =	29.282222

6360.5 A3	6360.5 A3			
6304		2.480000 x	6.352623 =	15.754505
6310		22.291500 x	1.607828 =	35.840898
6329.2		.144000 x	178.799229 =	25.747089

			B.T =	77.342492
6360.5 A4	6360.5 A4			
6304		3.200000 x	6.352623 =	20.328394
6329.2		.112000 x	178.799229 =	20.025514

			B.T =	40.353907
6360.5 A5	6360.5 A5			
112		9.350000 x	18.705943 =	174.900567
113		5.950000 x	24.769248 =	147.377026
113		.255000 x	24.769248 =	6.316158
6069.1		.090600 x	11.602173 =	1.051157

			B.T =	329.644908
6360.6 A1	6360.6 A1			
6304		20.350000 x	6.352623 =	129.275878
6314		24.900000 x	2.272414 =	56.583109
6330		.116000 x	193.571772 =	22.454326
6330		.580000 x	193.571772 =	112.271628
6314		1.245000 x	2.272414 =	2.829155

			B.T =	323.414095
6360.6 A2	6360.6 A2			
6304		1.530000 x	6.352623 =	9.719513
6330		.092000 x	193.571772 =	17.808603
6310		10.206000 x	1.607828 =	16.409493

			B.T =	43.937609
6360.6 A3	6360.6 A3			
6304		2.670000 x	6.352623 =	16.961503
6329.2		.181000 x	178.799229 =	32.362660
6310		25.798500 x	1.607828 =	41.479551

			B.T =	90.803715
6360.6 A4	6360.6 A4			
6304		2.800000 x	6.352623 =	17.787344
6329.2		.118000 x	178.799229 =	21.098309

			B.T =	38.885653

6360.6 A5

6360.6 A5

112	12.750000 x	18.705943 =	238.500773
113	.212500 x	24.769248 =	5.263465
6069.1	.120000 x	11.602173 =	1.392261
113	7.650000 x	24.769248 =	189.484747

B.T = 434.641246

641

641

231	.200000 x	.695000 =	.139000
251	.001500 x	290.000000 =	.435000
113	.127500 x	24.769248 =	3.158079
111	.170000 x	16.829739 =	2.861056
252	.002500 x	210.000000 =	.525000

B.T = 7.118135

651

651

221	150.000000 x	.098900 =	14.835000
224	120.000000 x	.070000 =	8.400000
509	.009435 x	399.345461 =	3.767824
509	.003060 x	399.345461 =	1.221997
T 630	.600000 x	1.717870 =	1.030722
T 625	.850000 x	22.631006 =	19.236355
511	.042500 x	755.475659 =	32.107716
112	.425000 x	18.705943 =	7.950026
111	1.275000 x	16.829739 =	21.457917

B.T = 110.007557

652

652

221	650.000000 x	.098900 =	64.285000
T 630	.320000 x	1.717870 =	.549718
T 625	1.000000 x	22.631006 =	22.631006
511	.042500 x	755.475659 =	32.107716
509	.001632 x	399.345461 =	.651732
509	.009435 x	399.345461 =	3.767824
111	1.275000 x	16.829739 =	21.457917
112	.425000 x	18.705943 =	7.950026

B.T = 153.400939

652.1

652.1

221	450.000000 x	.098900 =	44.505000
111	1.275000 x	16.829739 =	21.457917
509	.010001 x	399.345461 =	3.993854
T 630	.320000 x	1.717870 =	.549718
T 625	1.060000 x	22.631006 =	23.988866
511	.042500 x	755.475659 =	32.107716
510	.001632 x	389.346461 =	.635413
112	.425000 x	18.705943 =	7.950026

B.T = 135.188511

652.2	652.2			
221		900.000000 x	.098900 =	89.010000
509		.007548 x	399.345461 =	3.014260
T 630		.320000 x	1.717870 =	.549718
T 625		.800000 x	22.631006 =	18.104805
511		.042500 x	755.475659 =	32.107716
510		.001632 x	389.346461 =	.635413
111		1.275000 x	16.829739 =	21.457917
112		.425000 x	18.705943 =	7.950026
			B.T =	172.829855
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.098900 =	1.285700
113		.935000 x	24.769248 =	23.159247
			B.T =	
7001 A	7001 A			
502		.000365 x	797.093484 =	.290939
557		.001094 x	830.462186 =	.908526
			AΘΡΟΙΣΜΑ =	1.199465
	B.T =	.200000 x	1.199465 =	.239893
7001 B	7001 B			
558		.000700 x	1,102.536186 =	.771775
			B.T =	.771775
7001 E	7001 E			
503		.000875 x	897.479484 =	.785295
554		.000875 x	32.769000 =	.028673
			B.T =	.813967
7001 Γ	7001 Γ			
501		.000700 x	609.396308 =	.426577
502		.000700 x	797.093484 =	.557965
			B.T =	.984543

7001 Δ	7001 Δ			
502		.000292 x	797.093484 =	.232751
510		.000292 x	389.346461 =	.113689
X 630.1		.060000 x	1.635255 =	.098115
X 630		.060000 x	1.414717 =	.084883

			AΘΡΟΙΣΜΑ =	.529439
	B.T =	.600000 x	.529439 =	.317663

7003 Α	7003 Α			
502		.000365 x	797.093484 =	.290939
557		.001094 x	830.462186 =	.908526

			AΘΡΟΙΣΜΑ =	1.199465
	B.T =	.100000 x	1.199465 =	.119946

7003 Β	7003 Β			
559		.000464 x	1,279.900186 =	.593874

			B.T =	.593874
7003 Γ	7003 Γ			
502		.000700 x	797.093484 =	.557965

			B.T =	.557965
7003 Δ	7003 Δ			
502		.000875 x	797.093484 =	.697457
562		.000875 x	100.513600 =	.087949

			B.T =	.785406
7005 Α	7005 Α			
502		.000365 x	797.093484 =	.290939
557		.001094 x	830.462186 =	.908526

			AΘΡΟΙΣΜΑ =	1.199465
	B.T =	.100000 x	1.199465 =	.119946

7005 Β	7005 Β			
559		.000812 x	1,279.900186 =	1.039279

			B.T =	1.039279
7005 Ε	7005 Ε			
502		.000875 x	797.093484 =	.697457
562		.000875 x	100.513600 =	.087949

			B.T =	.785406

7005 Γ	7005 Γ			
559		.000232 x	1,279.900186 =	.296937

			B.T =	.296937
7005 Δ	7005 Δ			
502		.000700 x	797.093484 =	.557965

			B.T =	.557965
7010 Α	7010 Α			
558		.000315 x	1,102.536186 =	.347299

			B.T =	.347299
7010 Β	7010 Β			
558		.000473 x	1,102.536186 =	.521500

			B.T =	.521500
7010 Ε	7010 Ε			
503		.000875 x	897.479484 =	.785295
553		.000875 x	208.131000 =	.182115

			B.T =	.967409
7010 Γ	7010 Γ			
502		.000700 x	797.093484 =	.557965

			B.T =	.557965
7010 Δ	7010 Δ			
502		.000292 x	797.093484 =	.232751
X 630		.060000 x	1.414717 =	.084883
X 630.1		.060000 x	1.635255 =	.098115
510		.000292 x	389.346461 =	.113689

			ΑΘΡΟΙΣΜΑ =	.529439
	B.T =	.600000 x	.529439 =	.317663

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.830000 x	19.370744 =	16.077718
T 617		.500000 x	6.353401 =	3.176701
509		.007831 x	399.345461 =	3.127274
509		.004718 x	399.345461 =	1.884112
223		350.000000 x	.119300 =	41.755000

			B.T =	79.336688

7016.2	7016.2			
570.1		.586500 x	566.841484 =	332.452530
570.2		1.113500 x	156.045184 =	173.756312
571.2		1.113500 x	258.945256 =	288.335543
571.1		.586500 x	403.776182 =	236.814731

			ΑΘΡΟΙΣΜΑ =	1,031.359116
	B.T =	.025000 x	1,031.359116 =	25.783978

7016.3	7016.3			
564		.212500 x	1,777.738279 =	377.769384
565		.637500 x	735.858320 =	469.109679

			ΑΘΡΟΙΣΜΑ =	846.879063
	B.T =	.025000 x	846.879063 =	21.171977

7016.4	7016.4			
7016.1		1.000000 x	79.336688 =	79.336688
7016.2		1.000000 x	25.783978 =	25.783978
7016.3		1.000000 x	21.171977 =	21.171977

			B.T =	126.292643
7016.5	7016.5			
7016.4		.200000 x	126.292643 =	25.258529

			B.T =	25.258529
7016.6	7016.6			
7016.4		.250000 x	126.292643 =	31.573161
7016.5		.250000 x	25.258529 =	6.314632

			B.T =	37.887793
7016.7	7016.7			
111		5.100000 x	16.829739 =	85.831669

			B.T =	85.831669
7016.8	7016.8			
113		5.100000 x	24.769248 =	126.323165

			B.T =	126.323165

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.830000 x	19.370744 =	16.077718
T 617		.500000 x	6.353401 =	3.176701
509		.007831 x	399.345461 =	3.127274
509		.004718 x	399.345461 =	1.884112
223		350.000000 x	.119300 =	41.755000

			B.T =	79.336688
7017.2	7017.2			
564		.425000 x	1,777.738279 =	755.538769
565		.425000 x	735.858320 =	312.739786

			AΘΡΟΙΣΜΑ =	1,068.278555
	B.T =	.012500 x	1,068.278555 =	13.353482

7017.3	7017.3			
7017.1		1.000000 x	79.336688 =	79.336688
7017.2		1.000000 x	13.353482 =	13.353482

			B.T =	92.690170
7017.4	7017.4			
7017.3		.200000 x	92.690170 =	18.538034

			B.T =	18.538034
7017.5	7017.5			
7017.3		.300000 x	92.690170 =	27.807051
7017.4		.300000 x	18.538034 =	5.561410

			B.T =	33.368461
7017.6	7017.6			
111		5.100000 x	16.829739 =	85.831669

			B.T =	85.831669
7017.7	7017.7			
113		2.550000 x	24.769248 =	63.161582

			B.T =	63.161582

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
223		350.000000 x	.119300 =	41.755000

			B.T =	80.291354
7019 A2	7019 A2			
555		.012143 x	804.658734 =	9.770971

			B.T =	9.770971
7019 A3	7019 A3			
570.1		.850000 x	566.841484 =	481.815261
571.1		.850000 x	403.776182 =	343.209755
571.2		.850000 x	258.945256 =	220.103468
570.2		.850000 x	156.045184 =	132.638406

			ΑΘΡΟΙΣΜΑ =	1,177.766890
	B.T =	.014286 x	1,177.766890 =	16.825578

7019 A4	7019 A4			
112		2.295000 x	18.705943 =	42.930139
113		1.445000 x	24.769248 =	35.791563

			B.T =	78.721703
7019 A5	7019 A5			
113		.850000 x	24.769248 =	21.053861

			B.T =	21.053861
7019 A6	7019 A6			
7019 A1		1.000000 x	80.291354 =	80.291354
7019 A4		1.000000 x	78.721703 =	78.721703
7019 A2		1.000000 x	9.770971 =	9.770971
7019 A3		1.000000 x	16.825578 =	16.825578
7019 A5		1.000000 x	21.053861 =	21.053861

			B.T =	206.663467
7019 A7	7019 A7			
7019 A6		.100000 x	206.663467 =	20.666347

			B.T =	20.666347

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	16.829739 =	8.583167
113		.170000 x	24.769248 =	4.210772
252		.001000 x	210.000000 =	.210000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	365.557782 =	1.836928
509		.003750 x	399.345461 =	1.497545

			B.T =	3.334473
T 611	T 611			
111		1.275000 x	16.829739 =	21.457917

			B.T =	21.457917
T 617	T 617			
111		.085000 x	16.829739 =	1.430528
520		.005270 x	436.670172 =	2.301252
504		.004250 x	365.557782 =	1.553621
503		.001190 x	897.479484 =	1.068001

			B.T =	6.353401
T 621	T 621			
213		.100000 x	1.895000 =	.189500
508		.004250 x	624.120024 =	2.652510
116		.170000 x	24.152261 =	4.105884
111		.680000 x	16.829739 =	11.444223

			B.T =	18.392117
T 623	T 623			
213		.100000 x	1.895000 =	.189500
112		.085000 x	18.705943 =	1.590005
116		.170000 x	24.152261 =	4.105884
504		.004250 x	365.557782 =	1.553621
508		.004250 x	624.120024 =	2.652510
518		.008500 x	892.000635 =	7.582005
509		.004250 x	399.345461 =	1.697218

			B.T =	19.370744

T 625	T 625			
213		.100000 x	1.895000 =	.189500
112		.085000 x	18.705943 =	1.590005
116		.170000 x	24.152261 =	4.105884
509		.004250 x	399.345461 =	1.697218
518		.012155 x	892.000635 =	10.842268
508		.004250 x	624.120024 =	2.652510
504		.004250 x	365.557782 =	1.553621

			B.T =	22.631006
T 630	T 630			
512		.017000 x	101.051190 =	1.717870

			B.T =	1.717870
T 630.1	T 630.1			
510		.005100 x	389.346461 =	1.985667

			B.T =	1.985667
X 611	X 611			
111		1.050000 x	16.829739 =	17.671226

			B.T =	17.671226
X 617	X 617			
111		.070000 x	16.829739 =	1.178082
520		.004340 x	436.670172 =	1.895149
504		.003500 x	365.557782 =	1.279452
503		.000980 x	897.479484 =	.879530

			B.T =	5.232212
X 621	X 621			
213		.100000 x	1.895000 =	.189500
508		.003500 x	624.120024 =	2.184420
111		.560000 x	16.829739 =	9.424654
116		.140000 x	24.152261 =	3.381317

			B.T =	15.179890
X 623	X 623			
213		.100000 x	1.895000 =	.189500
504		.003500 x	365.557782 =	1.279452
518		.007000 x	892.000635 =	6.244004
509		.003500 x	399.345461 =	1.397709
508		.003500 x	624.120024 =	2.184420
116		.140000 x	24.152261 =	3.381317
112		.070000 x	18.705943 =	1.309416

			B.T =	15.985818

X 625	X 625			
213		.100000 x	1.895000 =	.189500
509		.003500 x	399.345461 =	1.397709
518		.010010 x	892.000635 =	8.928926
504		.003500 x	365.557782 =	1.279452
508		.003500 x	624.120024 =	2.184420
116		.140000 x	24.152261 =	3.381317
112		.070000 x	18.705943 =	1.309416

			B.T =	18.670740
X 630	X 630			
512		.014000 x	101.051190 =	1.414717

			B.T =	1.414717
X 630.1	X 630.1			
510		.004200 x	389.346461 =	1.635255

			B.T =	1.635255
2522	2522			
221		300.000000 x	.098900 =	29.670000
112		1.190000 x	18.705943 =	22.260072
113		1.360000 x	24.769248 =	33.686177
509		.004718 x	399.345461 =	1.884112
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.007548 x	399.345461 =	3.014260
509		.001275 x	399.345461 =	.509165
T 625		.500000 x	22.631006 =	11.315503
641		3.000000 x	7.118135 =	21.354405
T 630		.250000 x	1.717870 =	.429468

			T.E =	165.305929
6021	6021			
111		4.250000 x	16.829739 =	71.526391
509		.019380 x	399.345461 =	7.739315

			T.E =	79.265706
6022	6022			
111		2.550000 x	16.829739 =	42.915834
509		.008075 x	399.345461 =	3.224715

			T.E =	46.140549
6051	6051			
502		.000175 x	797.093484 =	.139491

			T.E =	.139491

6052	6052			
501		.000117 x	609.396308 =	.071299
502		.000088 x	797.093484 =	.070144
521		.000088 x	441.111484 =	.038818
			T.E =	.180261
6053	6053			
502		.000318 x	797.093484 =	.253476
507		.001000 x	941.320186 =	.941320
			T.E =	1.194796
6054	6054			
112		.004900 x	18.705943 =	.091659
509		.002975 x	399.345461 =	1.188053
507		.001077 x	941.320186 =	1.013802
			T.E =	2.293514
6055	6055			
213		.400000 x	1.895000 =	.758000
503		.001167 x	897.479484 =	1.047359
508		.007000 x	624.120024 =	4.368840
504		.001400 x	365.557782 =	.511781
112		.490000 x	18.705943 =	9.165912
116		.280000 x	24.152261 =	6.762633
			T.E =	22.614525
6056	6056			
507		.001750 x	941.320186 =	1.647310
			T.E =	1.647310
6057	6057			
506		.087500 x	715.534186 =	62.609241
			T.E =	62.609241
6058	6058			
507		.087500 x	941.320186 =	82.365516
			T.E =	82.365516
6059	6059			
112		.070000 x	18.705943 =	1.309416
			T.E =	1.309416

6060	6060			
112		.350000 x	18.705943 =	6.547080

			T.E =	6.547080
6061	6061			
112		.007000 x	18.705943 =	.130942
507		.001077 x	941.320186 =	1.013802
509		.002975 x	399.345461 =	1.188053
501		.000583 x	609.396308 =	.355278
502		.001400 x	797.093484 =	1.115931

			T.E =	3.804005
6062	6062			
213		.400000 x	1.895000 =	.758000
509		.002800 x	399.345461 =	1.118167
508		.002800 x	624.120024 =	1.747536
507		.001400 x	941.320186 =	1.317848
502		.002000 x	797.093484 =	1.594187
116		.175000 x	24.152261 =	4.226646
112		.175000 x	18.705943 =	3.273540

			T.E =	14.035924
6063	6063			
112		.700000 x	18.705943 =	13.094160
112		.070000 x	18.705943 =	1.309416
509		.003641 x	399.345461 =	1.454017
112		.070000 x	18.705943 =	1.309416
112		.140000 x	18.705943 =	2.618832

			T.E =	19.785841
6064	6064			
112		.140000 x	18.705943 =	2.618832
509		.003641 x	399.345461 =	1.454017
507		.014000 x	941.320186 =	13.178483
112		.070000 x	18.705943 =	1.309416

			T.E =	18.560747
6065	6065			
506		.002800 x	715.534186 =	2.003496
506		.002100 x	715.534186 =	1.502622

			T.E =	3.506118

6066	6066				
111		.070000 x	16.829739 =	1.178082	
502		.000700 x	797.093484 =	.557965	

			T.E =	1.736047	
6067	6067				
111		.980000 x	16.829739 =	16.493144	
X 630		.100000 x	1.414717 =	.141472	
X 630.1		.100000 x	1.635255 =	.163526	

			T.E =	16.798141	
6068	6068				
111		.560000 x	16.829739 =	9.424654	
622		1.351351 x	13.613097 =	18.396072	
X 630.1		.200000 x	1.635255 =	.327051	
X 630		.200000 x	1.414717 =	.282943	
112		.560000 x	18.705943 =	10.475328	
509		.016497 x	399.345461 =	6.588002	

			T.E =	45.494051	
6068.1	6068.1				
111		.560000 x	16.829739 =	9.424654	
X 630.1		.200000 x	1.635255 =	.327051	
X 630		.200000 x	1.414717 =	.282943	
614		1.351351 x	8.610853 =	11.636285	
509		.016497 x	399.345461 =	6.588002	
112		.560000 x	18.705943 =	10.475328	

			T.E =	38.734263	
6069	6069				
112		.070000 x	18.705943 =	1.309416	
509		.012017 x	399.345461 =	4.798934	
X 625		1.050000 x	18.670740 =	19.604277	

			T.E =	25.712627	
6069.1	6069.1				
112		.070000 x	18.705943 =	1.309416	
509		.012017 x	399.345461 =	4.798934	
X 617		1.050000 x	5.232212 =	5.493823	

			T.E =	11.602173	
6070	6070				
501		.000467 x	609.396308 =	.284588	

			T.E =	.284588	

6071	6071			
504		.002333 x	365.557782 =	.852846
509		.002975 x	399.345461 =	1.188053

			T.E =	2.040899
6072	6072			
504		.003500 x	365.557782 =	1.279452
509		.002800 x	399.345461 =	1.118167

			T.E =	2.397620
6073	6073			
509		.000833 x	399.345461 =	.332655

			T.E =	.332655
6074	6074			
509		.000784 x	399.345461 =	.313087

			T.E =	.313087
6075	6075			
509		.001096 x	399.345461 =	.437683

			T.E =	.437683
6076	6076			
112		.004900 x	18.705943 =	.091659
503		.000700 x	897.479484 =	.628236
509		.003914 x	399.345461 =	1.563038
507		.000840 x	941.320186 =	.790709

			T.E =	3.073642
6077	6077			
503		.001400 x	897.479484 =	1.256471

			T.E =	1.256471
6078	6078			
112		.004900 x	18.705943 =	.091659
505		.001400 x	814.512186 =	1.140317
501		.000056 x	609.396308 =	.034126
503		.000350 x	897.479484 =	.314118

			T.E =	1.580220

6078.1	6078.1			
112		.004900 x	18.705943 =	.091659
501		.000056 x	609.396308 =	.034126
503		.000350 x	897.479484 =	.314118
556		.001400 x	1,101.832186 =	1.542565

			T.E =	1.982468
6079	6079			
112		.014000 x	18.705943 =	.261883
501		.000700 x	609.396308 =	.426577
529		.000980 x	451.561484 =	.442530
X 630		.150000 x	1.414717 =	.212208
509		.000630 x	399.345461 =	.251588
502		.000350 x	797.093484 =	.278983

			T.E =	1.873769
6080	6080			
112		.014000 x	18.705943 =	.261883
X 630.1		.100000 x	1.635255 =	.163526
X 630		.100000 x	1.414717 =	.141472
529		.000700 x	451.561484 =	.316093
502		.000292 x	797.093484 =	.232751
501		.000583 x	609.396308 =	.355278

			T.E =	1.471003
6081.1	6081.1			
111		.420000 x	16.829739 =	7.068490
112		.280000 x	18.705943 =	5.237664
112		.420000 x	18.705943 =	7.856496
506		.007000 x	715.534186 =	5.008739

			T.E =	25.171390
6081.2	6081.2			
111		.700000 x	16.829739 =	11.780817
112		.070000 x	18.705943 =	1.309416
6081.1		1.000000 x	25.171390 =	25.171390

			T.E =	38.261623
6081.3	6081.3			
111		1.400000 x	16.829739 =	23.561635
6081.1		1.000000 x	25.171390 =	25.171390
112		.140000 x	18.705943 =	2.618832

			T.E =	51.351857

6081.4	6081.4			
111		2.100000 x	16.829739 =	35.342452
6081.1		1.000000 x	25.171390 =	25.171390
112		.210000 x	18.705943 =	3.928248

			T.E =	64.442090
6082.1	6082.1			
213		.400000 x	1.895000 =	.758000
111		1.400000 x	16.829739 =	23.561635
116		.700000 x	24.152261 =	16.906583
508		.070000 x	624.120024 =	43.688402
116		1.400000 x	24.152261 =	33.813165

			T.E =	118.727784
6082.2	6082.2			
111		.700000 x	16.829739 =	11.780817
6082.1		1.000000 x	118.727784 =	118.727784
112		.140000 x	18.705943 =	2.618832

			T.E =	133.127433
6082.3	6082.3			
111		1.400000 x	16.829739 =	23.561635
6082.1		1.000000 x	118.727784 =	118.727784
112		.280000 x	18.705943 =	5.237664

			T.E =	147.527083
6082.4	6082.4			
111		2.100000 x	16.829739 =	35.342452
112		.420000 x	18.705943 =	7.856496
6082.1		1.000000 x	118.727784 =	118.727784

			T.E =	161.926732
6083.1	6083.1			
111		.280000 x	16.829739 =	4.712327
112		.280000 x	18.705943 =	5.237664
506		.005833 x	715.534186 =	4.173711
112		.140000 x	18.705943 =	2.618832

			T.E =	16.742534
6083.2	6083.2			
111		.560000 x	16.829739 =	9.424654
6083.1		1.000000 x	16.742534 =	16.742534
112		.070000 x	18.705943 =	1.309416

			T.E =	27.476604

6083.3	6083.3				
111		1.120000 x	16.829739 =	18.849308	
112		.140000 x	18.705943 =	2.618832	
6083.1		1.000000 x	16.742534 =	16.742534	

			T.E =	38.210674	
6083.4	6083.4				
111		1.680000 x	16.829739 =	28.273962	
112		.210000 x	18.705943 =	3.928248	
6083.1		1.000000 x	16.742534 =	16.742534	

			T.E =	48.944744	
6084.1	6084.1				
213		.400000 x	1.895000 =	.758000	
111		1.470000 x	16.829739 =	24.739716	
116		.700000 x	24.152261 =	16.906583	
508		.035000 x	624.120024 =	21.844201	
116		1.050000 x	24.152261 =	25.359874	

			T.E =	89.608374	
6084.2	6084.2				
111		.560000 x	16.829739 =	9.424654	
112		.105000 x	18.705943 =	1.964124	
6084.1		1.000000 x	89.608374 =	89.608374	

			T.E =	100.997152	
6084.3	6084.3				
111		1.120000 x	16.829739 =	18.849308	
112		.210000 x	18.705943 =	3.928248	
6084.1		1.000000 x	89.608374 =	89.608374	

			T.E =	112.385930	
6084.4	6084.4				
111		1.680000 x	16.829739 =	28.273962	
112		.315000 x	18.705943 =	5.892372	
6084.1		1.000000 x	89.608374 =	89.608374	

			T.E =	123.774708	
6085.1	6085.1				
111		.140000 x	16.829739 =	2.356163	
506		.004666 x	715.534186 =	3.338683	
502		.001400 x	797.093484 =	1.115931	
112		.140000 x	18.705943 =	2.618832	

			T.E =	9.429609	

6085.2	6085.2			
111		.350000 x	16.829739 =	5.890409
112		.070000 x	18.705943 =	1.309416
6085.1		1.000000 x	9.429609 =	9.429609

			T.E =	16.629434
6085.3	6085.3			
111		.700000 x	16.829739 =	11.780817
112		.140000 x	18.705943 =	2.618832
6085.1		1.000000 x	9.429609 =	9.429609

			T.E =	23.829258
6085.4	6085.4			
111		1.050000 x	16.829739 =	17.671226
112		.210000 x	18.705943 =	3.928248
6085.1		1.000000 x	9.429609 =	9.429609

			T.E =	31.029083
6086.1	6086.1			
213		.400000 x	1.895000 =	.758000
508		.008750 x	624.120024 =	5.461050
111		1.120000 x	16.829739 =	18.849308
116		.490000 x	24.152261 =	11.834608
116		.280000 x	24.152261 =	6.762633

			T.E =	43.665599
6086.2	6086.2			
111		.350000 x	16.829739 =	5.890409
112		.105000 x	18.705943 =	1.964124
6086.1		1.000000 x	43.665599 =	43.665599

			T.E =	51.520132
6086.3	6086.3			
111		.700000 x	16.829739 =	11.780817
6086.1		1.000000 x	43.665599 =	43.665599
112		.210000 x	18.705943 =	3.928248

			T.E =	59.374664
6086.4	6086.4			
111		1.050000 x	16.829739 =	17.671226
6086.1		1.000000 x	43.665599 =	43.665599
112		.315000 x	18.705943 =	5.892372

			T.E =	67.229197

6087	6087				
252		.001000 x	210.000000 =		.210000
113		.210000 x	24.769248 =		5.201542
112		.350000 x	18.705943 =		6.547080
111		.210000 x	16.829739 =		3.534245

			T.E =		15.492867
6088	6088				
6081.1		1.000000 x	25.171390 =		25.171390
6081.1		.900000 x	25.171390 =		22.654251

			T.E =		47.825641
6089	6089				
6082.1		1.000000 x	118.727784 =		118.727784
6082.1		.900000 x	118.727784 =		106.855006

			T.E =		225.582790
6090	6090				
6083.1		1.000000 x	16.742534 =		16.742534
6083.1		1.300000 x	16.742534 =		21.765294

			T.E =		38.507828
6091	6091				
6084.1		1.000000 x	89.608374 =		89.608374
6084.1		1.300000 x	89.608374 =		116.490886

			T.E =		206.099260
6100	6100				
231		.200000 x	.695000 =		.139000
111		.175000 x	16.829739 =		2.945204
251		.002000 x	290.000000 =		.580000
113		.105000 x	24.769248 =		2.600771
252.1		.002000 x	.000000 =		.000000

			T.E =		
6101	6101				
231		15.000000 x	.695000 =		10.425000
252		.018000 x	210.000000 =		3.780000
113		3.500000 x	24.769248 =		86.692368
112		3.500000 x	18.705943 =		65.470801
252.1		.020000 x	.000000 =		.000000
251		.068000 x	290.000000 =		19.720000

			T.E =		

6102	6102			
244		1.000000 x	2.470000 =	2.470000
112		.002100 x	18.705943 =	.039282
112		.001400 x	18.705943 =	.026188
506		.000070 x	715.534186 =	.050087
509		.000051 x	399.345461 =	.020367
506		.000070 x	715.534186 =	.050087

			T.E =	2.656012
6103	6103			
244		.125000 x	2.470000 =	.308750
112		.002800 x	18.705943 =	.052377
112		.004200 x	18.705943 =	.078565
509		.000102 x	399.345461 =	.040733
506		.000140 x	715.534186 =	.100175
506		.000140 x	715.534186 =	.100175

			T.E =	.680774
6104	6104			
236		3.000000 x	.523000 =	1.569000
517		.017500 x	2,171.391288 =	37.999348
111		.280000 x	16.829739 =	4.712327
113		.280000 x	24.769248 =	6.935389

			T.E =	51.216064
6105	6105			
111		.210000 x	16.829739 =	3.534245
517		.014000 x	2,171.391288 =	30.399478
113		.140000 x	24.769248 =	3.467695

			T.E =	37.401418
6106	6106			
512		.087500 x	101.051190 =	8.841979

			T.E =	8.841979
6107	6107			
513		.087500 x	151.631785 =	13.267781

			T.E =	13.267781
6108	6108			
514		.087500 x	203.307980 =	17.789448

			T.E =	17.789448

6109	6109			
515		.087500 x	276.418712 =	24.186637

			T.E =	24.186637
6110	6110			
516		.087500 x	353.758944 =	30.953908

			T.E =	30.953908
6120	6120			
112		.004200 x	18.705943 =	.078565
502		.001750 x	797.093484 =	1.394914
501		.000070 x	609.396308 =	.042658

			T.E =	1.516136
6121	6121			
112		.004200 x	18.705943 =	.078565
509		.003113 x	399.345461 =	1.243162
502		.000315 x	797.093484 =	.251084
505		.000420 x	814.512186 =	.342095
507		.000875 x	941.320186 =	.823655
501		.000049 x	609.396308 =	.029860

			T.E =	2.768423
6151	6151			
243		1.020000 x	1.900000 =	1.938000
243		.080000 x	1.900000 =	.152000

			T.E =	2.090000
6152	6152			
112		.085000 x	18.705943 =	1.590005
113		.085000 x	24.769248 =	2.105386

			T.E =	3.695391
6153	6153			
111		.425000 x	16.829739 =	7.152639
T 611		1.050000 x	21.457917 =	22.530813
509		.003570 x	399.345461 =	1.425663
112		.425000 x	18.705943 =	7.950026

			T.E =	39.059141

6154	6154				
111		.425000 x	16.829739 =	7.152639	
T 621		1.050000 x	18.392117 =	19.311723	
112		.425000 x	18.705943 =	7.950026	
509		.003570 x	399.345461 =	1.425663	

			T.E =	35.840051	
6155	6155				
111		.680000 x	16.829739 =	11.444223	
T 621		.350000 x	18.392117 =	6.437241	
652		.100000 x	153.400939 =	15.340094	
509		.003220 x	399.345461 =	1.285892	
113		1.275000 x	24.769248 =	31.580791	

			T.E =	66.088241	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	153.400939 =	1.534009	
113		.680000 x	24.769248 =	16.843089	
112		.425000 x	18.705943 =	7.950026	

			T.E =	26.472124	
6157	6157				
111		.420000 x	16.829739 =	7.068490	
509		.002940 x	399.345461 =	1.174076	
112		.420000 x	18.705943 =	7.856496	
X 621		1.050000 x	15.179890 =	15.938885	

			T.E =	32.037947	
6157.1	6157.1				
111		.420000 x	16.829739 =	7.068490	
509		.002940 x	399.345461 =	1.174076	
X 611		1.050000 x	17.671226 =	18.554787	
112		.420000 x	18.705943 =	7.856496	

			T.E =	34.653849	
6158	6158				
111		.560000 x	16.829739 =	9.424654	
621.1		1.050000 x	16.459343 =	17.282310	
509		.002940 x	399.345461 =	1.174076	
504		.001400 x	365.557782 =	.511781	

			T.E =	28.392821	

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	24.485576
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	26.085576
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	24.769248 =	5.263465
111		.340000 x	16.829739 =	5.722111

			T.E =	31.685576
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	37.285576
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	16.829739 =	14.305278
113		.637500 x	24.769248 =	15.790396

			T.E =	62.495674
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	16.829739 =	14.305278
113		.637500 x	24.769248 =	15.790396

			T.E =	76.795674
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	24.769248 =	15.790396
111		.850000 x	16.829739 =	14.305278

			T.E =	94.195674

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
111		.340000 x	16.829739 =	5.722111	
113		.212500 x	24.769248 =	5.263465	
			T.E =	28.585576	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	16.829739 =	5.722111	
113		.212500 x	24.769248 =	5.263465	
			T.E =	32.285576	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	16.829739 =	5.722111	
113		.212500 x	24.769248 =	5.263465	
			T.E =	37.285576	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
113		.212500 x	24.769248 =	5.263465	
111		.340000 x	16.829739 =	5.722111	
			T.E =	40.985576	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
111		.850000 x	16.829739 =	14.305278	
113		.637500 x	24.769248 =	15.790396	
			T.E =	66.395674	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	16.829739 =	14.305278	
113		.637500 x	24.769248 =	15.790396	
			T.E =	85.595674	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	16.829739 =	14.305278	
113		.637500 x	24.769248 =	15.790396	
			T.E =	105.495674	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.255000 x	16.829739 =	4.291583

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	16.829739 =	5.722111
113		.212500 x	24.769248 =	5.263465

			T.E =	
6204	6204			
111		.210000 x	16.829739 =	3.534245
X 625		.700000 x	18.670740 =	13.069518
X 623		.400000 x	15.985818 =	6.394327
509		.005439 x	399.345461 =	2.172040
509		.003108 x	399.345461 =	1.241166
112		.420000 x	18.705943 =	7.856496

			T.E =	34.267792
6204.1	6204.1			
111		.210000 x	16.829739 =	3.534245
112		.420000 x	18.705943 =	7.856496
509		.008702 x	399.345461 =	3.475104
613		1.050000 x	5.599130 =	5.879087

			T.E =	20.744932

6205	6205				
111		.210000 x	16.829739 =	3.534245	
112		.070000 x	18.705943 =	1.309416	
509		.002800 x	399.345461 =	1.118167	
613		1.000000 x	5.599130 =	5.599130	

				T.E =	11.560958
6251	6251				
509		.002800 x	399.345461 =	1.118167	
613		1.000000 x	5.599130 =	5.599130	

				T.E =	6.717297
6252	6252				
509		.000784 x	399.345461 =	.313087	

				T.E =	.313087
6253	6253				
112		.210000 x	18.705943 =	3.928248	
X 630.1		.200000 x	1.635255 =	.327051	
501		.002917 x	609.396308 =	1.777609	
521		.007000 x	441.111484 =	3.087780	
X 630		.200000 x	1.414717 =	.282943	

				T.E =	9.403632
6301	6301				
231		.200000 x	.695000 =	.139000	
252		.002500 x	210.000000 =	.525000	
113		.127500 x	24.769248 =	3.158079	
111		.170000 x	16.829739 =	2.861056	
251		.001500 x	290.000000 =	.435000	

				T.E =	7.118135
6302	6302				
231		.300000 x	.695000 =	.208500	
251		.002000 x	290.000000 =	.580000	
111		.212500 x	16.829739 =	3.576320	
252		.004000 x	210.000000 =	.840000	
113		1.232500 x	24.769248 =	30.528098	

				T.E =	35.732918
6303	6303				
6302		.666660 x	35.732918 =	23.821707	

				T.E =	23.821707

6304	6304			
234.2		.018000 x	.719000 =	.012942
112		.212500 x	18.705943 =	3.975013
113		.010200 x	24.769248 =	.252646
113		.085000 x	24.769248 =	2.105386
235		.012000 x	.553000 =	.006636

			T.E =	6.352623
6310	6310			
233		1.050000 x	.528700 =	.555135
113		.042500 x	24.769248 =	1.052693

			T.E =	1.607828
6311	6311			
233.1		1.050000 x	.528700 =	.555135
113		.042500 x	24.769248 =	1.052693

			T.E =	1.607828
6312	6312			
233.3		1.010000 x	7.650000 =	7.726500
233.3		.303000 x	7.650000 =	2.317950
113		.085000 x	24.769248 =	2.105386
113		.085000 x	24.769248 =	2.105386

			T.E =	14.255222
6313	6313			
233.2		1.050000 x	.560100 =	.588105
113		.025500 x	24.769248 =	.631616

			T.E =	1.219721
6314	6314			
233.2		1.050000 x	.560100 =	.588105
113		.068000 x	24.769248 =	1.684309

			T.E =	2.272414
6320.1	6320.1			
396.1		1.000000 x	1.400000 =	1.400000
113		.000850 x	24.769248 =	.021054

			T.E =	1.421054

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	24.769248 =	.021054

			T.E =	.791054
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	24.769248 =	.021054

			T.E =	1.701054
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	24.769248 =	.021054

			T.E =	1.001054
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	24.769248 =	.021054

			T.E =	1.201054
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	24.769248 =	.021054

			T.E =	1.601054
6321	6321			
221		140.000000 x	.098900 =	13.846000
111		.765000 x	16.829739 =	12.874750
113		.595000 x	24.769248 =	14.737703
509		.003302 x	399.345461 =	1.318639
509		.003019 x	399.345461 =	1.205624
T 630.1		.175000 x	1.985667 =	.347492
T 630		.175000 x	1.717870 =	.300627
T 625		.350000 x	22.631006 =	7.920852
T 623		.560000 x	19.370744 =	10.847617
T 621		.300000 x	18.392117 =	5.517635
511		.023800 x	755.475659 =	17.980321
509		.005284 x	399.345461 =	2.110141
112		.714000 x	18.705943 =	13.356043

			T.E =	102.363444

6322	6322			
221		140.000000 x	.098900 =	13.846000
509		.003019 x	399.345461 =	1.205624
T 623		.560000 x	19.370744 =	10.847617
T 630.1		.175000 x	1.985667 =	.347492
T 630		.175000 x	1.717870 =	.300627
T 625		.350000 x	22.631006 =	7.920852
511		.023800 x	755.475659 =	17.980321
T 611		.300000 x	21.457917 =	6.437375
509		.003302 x	399.345461 =	1.318639
509		.005284 x	399.345461 =	2.110141
113		.595000 x	24.769248 =	14.737703
111		.765000 x	16.829739 =	12.874750
112		.714000 x	18.705943 =	13.356043

T.E = 103.283184

6323	6323			
221		150.000000 x	.098900 =	14.835000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
113		.850000 x	24.769248 =	21.053861
112		1.020000 x	18.705943 =	19.080062

T.E = 113.291449

6323.1	6323.1			
221		150.000000 x	.098900 =	14.835000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		1.020000 x	18.705943 =	19.080062
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		.850000 x	24.769248 =	21.053861

T.E = 105.152646

6324	6324			
221		200.000000 x	.098900 =	19.780000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
112		1.020000 x	18.705943 =	19.080062
509		.004718 x	399.345461 =	1.884112
113		.850000 x	24.769248 =	21.053861
509		.007548 x	399.345461 =	3.014260

T.E = 118.236449

6324.1	6324.1			
221		200.000000 x	.098900 =	19.780000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		1.020000 x	18.705943 =	19.080062
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		.850000 x	24.769248 =	21.053861

T.E = 110.097646

6325	6325			
221		250.000000 x	.098900 =	24.725000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
113		.850000 x	24.769248 =	21.053861
112		1.020000 x	18.705943 =	19.080062

T.E = 123.181449

6325.1	6325.1			
221		250.000000 x	.098900 =	24.725000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		1.020000 x	18.705943 =	19.080062
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		.850000 x	24.769248 =	21.053861

T.E = 115.042646

6326	6326			
221		300.000000 x	.098900 =	29.670000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
113		1.360000 x	24.769248 =	33.686177
112		1.190000 x	18.705943 =	22.260072

T.E = 143.938776

6326.1	6326.1			
221		300.000000 x	.098900 =	29.670000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		1.190000 x	18.705943 =	22.260072
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		1.360000 x	24.769248 =	33.686177

T.E = 135.799973

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
113		1.275000 x	24.769248 =	31.580791
112		2.295000 x	18.705943 =	42.930139

T.E = 167.693457

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		2.295000 x	18.705943 =	42.930139
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		1.275000 x	24.769248 =	31.580791

T.E = 159.554654

6328	6328			
221		350.000000 x	.098900 =	34.615000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
112		2.295000 x	18.705943 =	42.930139
509		.007548 x	399.345461 =	3.014260
113		1.445000 x	24.769248 =	35.791563
509		.004718 x	399.345461 =	1.884112

T.E = 171.659229

6328.1	6328.1			
221		350.000000 x	.098900 =	34.615000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
112		2.295000 x	18.705943 =	42.930139
509		.007548 x	399.345461 =	3.014260
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
113		1.445000 x	24.769248 =	35.791563

T.E = 163.520426

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.007548 x	399.345461 =	3.014260
509		.004718 x	399.345461 =	1.884112
113		1.445000 x	24.769248 =	35.791563
112		2.295000 x	18.705943 =	42.930139

T.E = 177.714229

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
112		2.295000 x	18.705943 =	42.930139
113		1.445000 x	24.769248 =	35.791563
509		.007548 x	399.345461 =	3.014260
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112

T.E = 169.575426

6329.2 6329.2

223	350.000000 x	.119300 =	41.755000
112	2.295000 x	18.705943 =	42.930139
T 625	.500000 x	22.631006 =	11.315503
T 630.1	.250000 x	1.985667 =	.496417
T 630	.250000 x	1.717870 =	.429468
T 623	.800000 x	19.370744 =	15.496595
113	1.445000 x	24.769248 =	35.791563
511	.034000 x	755.475659 =	25.686172
509	.007548 x	399.345461 =	3.014260
509	.004718 x	399.345461 =	1.884112

T.E = 178.799229

6329.3 6329.3

223	350.000000 x	.119300 =	41.755000
112	2.295000 x	18.705943 =	42.930139
T 630.1	.250000 x	1.985667 =	.496417
T 630	.250000 x	1.717870 =	.429468
T 623	.800000 x	19.370744 =	15.496595
T 617	.500000 x	6.353401 =	3.176701
511	.034000 x	755.475659 =	25.686172
509	.007548 x	399.345461 =	3.014260
509	.004718 x	399.345461 =	1.884112
113	1.445000 x	24.769248 =	35.791563

T.E = 170.660426

6330 6330

223	420.000000 x	.119300 =	50.106000
112	2.295000 x	18.705943 =	42.930139
509	.007548 x	399.345461 =	3.014260
509	.004718 x	399.345461 =	1.884112
113	1.445000 x	24.769248 =	35.791563
T 630.1	.250000 x	1.985667 =	.496417
T 630	.250000 x	1.717870 =	.429468
T 625	.500000 x	22.631006 =	11.315503
T 623	.800000 x	19.370744 =	15.496595
511	.042500 x	755.475659 =	32.107716

T.E = 193.571772

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
113		1.445000 x	24.769248 =	35.791563
509		.004718 x	399.345461 =	1.884112
112		2.295000 x	18.705943 =	42.930139
509		.007548 x	399.345461 =	3.014260
511		.042500 x	755.475659 =	32.107716
T 617		.500000 x	6.353401 =	3.176701
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595

T.E = 185.432969

6331	6331			
222		450.000000 x	.116200 =	52.290000
113		5.525000 x	24.769248 =	136.850095
111		3.825000 x	16.829739 =	64.373752
T 623		.800000 x	19.370744 =	15.496595
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
509		.004718 x	399.345461 =	1.884112
511		.042500 x	755.475659 =	32.107716
509		.007548 x	399.345461 =	3.014260
112		3.400000 x	18.705943 =	63.600206

T.E = 381.858122

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
511		.042500 x	755.475659 =	32.107716
509		.007548 x	399.345461 =	3.014260
509		.004718 x	399.345461 =	1.884112
113		5.525000 x	24.769248 =	136.850095
112		3.400000 x	18.705943 =	63.600206
111		3.825000 x	16.829739 =	64.373752

T.E = 373.719320

6351	6351			
221		120.000000 x	.098900 =	11.868000
509		.004246 x	399.345461 =	1.695621
509		.008020 x	399.345461 =	3.202751
6301		1.000000 x	7.118135 =	7.118135
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.450000 x	22.631006 =	10.183953
T 623		.850000 x	19.370744 =	16.465132
511		.034000 x	755.475659 =	25.686172
113		1.275000 x	24.769248 =	31.580791
112		1.275000 x	18.705943 =	23.850077

T.E = 132.576517

6351.1	6351.1			
221		120.000000 x	.098900 =	11.868000
509		.004246 x	399.345461 =	1.695621
6301		1.000000 x	7.118135 =	7.118135
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.850000 x	19.370744 =	16.465132
T 617		.450000 x	6.353401 =	2.859030
511		.034000 x	755.475659 =	25.686172
509		.008020 x	399.345461 =	3.202751
112		1.275000 x	18.705943 =	23.850077
113		1.275000 x	24.769248 =	31.580791

T.E = 125.251594

6352	6352			
221		300.000000 x	.098900 =	29.670000
112		2.125000 x	18.705943 =	39.750129
6301		1.000000 x	7.118135 =	7.118135
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 625		.500000 x	22.631006 =	11.315503
T 623		.800000 x	19.370744 =	15.496595
511		.034000 x	755.475659 =	25.686172
509		.004718 x	399.345461 =	1.884112
509		.007548 x	399.345461 =	3.014260
113		2.550000 x	24.769248 =	63.161582

T.E = 198.022373

6352.1	6352.1			
221		300.000000 x	.098900 =	29.670000
113		2.550000 x	24.769248 =	63.161582
112		2.125000 x	18.705943 =	39.750129
511		.034000 x	755.475659 =	25.686172
6301		1.000000 x	7.118135 =	7.118135
T 630.1		.250000 x	1.985667 =	.496417
T 630		.250000 x	1.717870 =	.429468
T 623		.800000 x	19.370744 =	15.496595
T 617		.500000 x	6.353401 =	3.176701
509		.007548 x	399.345461 =	3.014260
509		.004718 x	399.345461 =	1.884112
			T.E =	189.883570
6360.1	6360.1			
6360.1 A1		1.000000 x	124.643235 =	124.643235
6360.1 A2		1.000000 x	8.819081 =	8.819081
6360.1 A5		1.000000 x	116.669909 =	116.669909
6360.1 A4		1.000000 x	35.307147 =	35.307147
6360.1 A3		1.000000 x	15.887942 =	15.887942
			AΘΡΟΙΣΜΑ =	301.327314
	T.E =	.200000 x	301.327314 =	60.265463
6360.2	6360.2			
6360.2 A1		1.000000 x	134.004463 =	134.004463
6360.2 A2		1.000000 x	12.274589 =	12.274589
6360.2 A3		1.000000 x	20.661878 =	20.661878
6360.2 A4		1.000000 x	38.885653 =	38.885653
6360.2 A5		1.000000 x	131.552074 =	131.552074
			AΘΡΟΙΣΜΑ =	337.378657
	T.E =	.200000 x	337.378657 =	67.475731
6360.3	6360.3			
6360.3 A1		1.000000 x	177.623001 =	177.623001
6360.3 A2		1.000000 x	17.374493 =	17.374493
6360.3 A3		1.000000 x	46.495615 =	46.495615
6360.3 A5		1.000000 x	178.366607 =	178.366607
6360.3 A4		1.000000 x	46.579063 =	46.579063
			AΘΡΟΙΣΜΑ =	466.438779
	T.E =	.200000 x	466.438779 =	93.287756

6360.4	6360.4			
6360.4 A1		1.000000 x	232.570235 =	232.570235
6360.4 A2		1.000000 x	23.487155 =	23.487155
6360.4 A3		1.000000 x	69.656872 =	69.656872
6360.4 A5		1.000000 x	240.903647 =	240.903647
6360.4 A4		1.000000 x	38.885653 =	38.885653

			AΘΡΟΙΣΜΑ =	605.503562
	T.E =	.200000 x	605.503562 =	121.100712

6360.5	6360.5			
6360.5 A1		1.000000 x	266.342207 =	266.342207
6360.5 A2		1.000000 x	29.282222 =	29.282222
6360.5 A3		1.000000 x	77.342492 =	77.342492
6360.5 A5		1.000000 x	329.644908 =	329.644908
6360.5 A4		1.000000 x	40.353907 =	40.353907

			AΘΡΟΙΣΜΑ =	742.965736
	T.E =	.200000 x	742.965736 =	148.593147

6360.6	6360.6			
6360.6 A1		1.000000 x	323.414095 =	323.414095
6360.6 A2		1.000000 x	43.937609 =	43.937609
6360.6 A4		1.000000 x	38.885653 =	38.885653
6360.6 A3		1.000000 x	90.803715 =	90.803715
6360.6 A5		1.000000 x	434.641246 =	434.641246

			AΘΡΟΙΣΜΑ =	931.682318
	T.E =	.200000 x	931.682318 =	186.336464

6361	6361			
396.7		.100000 x	3.800000 =	.380000
113		.017000 x	24.769248 =	.421077
111		.085000 x	16.829739 =	1.430528

			T.E =	2.231605
6370	6370			
396.10		.650000 x	6.940000 =	4.511000
113		.340000 x	24.769248 =	8.421544
111		.340000 x	16.829739 =	5.722111
396.14		.003000 x	41.560000 =	.124680

			T.E =	18.779336
6371	6371			
326		.500000 x	1.310000 =	.655000
113		.212500 x	24.769248 =	5.263465
111		.212500 x	16.829739 =	3.576320

			T.E =	9.494785

6372	6372				
396.11		1.050000 x	2.560000 =	2.688000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	16.829739 =	5.722111	
113		.340000 x	24.769248 =	8.421544	

			T.E =	18.070656	
6373	6373				
396.12		1.050000 x	3.680000 =	3.864000	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	24.769248 =	10.526930	
111		.425000 x	16.829739 =	7.152639	

			T.E =	22.782569	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	24.769248 =	5.263465	

			T.E =	5.533465	
6402	6402				
252		.000500 x	210.000000 =	.105000	
111		.595000 x	16.829739 =	10.013695	
113		.595000 x	24.769248 =	14.737703	
652		.011500 x	153.400939 =	1.764111	
652.2		.005500 x	172.829855 =	.950564	

			T.E =	27.571072	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	16.829739 =	14.305278	
113		.850000 x	24.769248 =	21.053861	
652.2		.005500 x	172.829855 =	.950564	
652		.016500 x	153.400939 =	2.531115	

			T.E =	38.985819	
6404	6404				
111		1.275000 x	16.829739 =	21.457917	
113		1.700000 x	24.769248 =	42.107722	
652		.020000 x	153.400939 =	3.068019	

			T.E =	66.633658	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	66.633658 =	66.633658	

			T.E =		

6405	6405			
111		.425000 x	16.829739 =	7.152639
113		.850000 x	24.769248 =	21.053861
652		.020000 x	153.400939 =	3.068019

			T.E =	31.274519
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	21,676.000000 =	21,676.000000
386.9		.150000 x	21,676.000000 =	3,251.400000

			T.E =	24,927.400000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	64,900.000000 =	64,900.000000
386.40		.150000 x	64,900.000000 =	9,735.000000

			T.E =	74,635.000000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	95,302.000000 =	95,302.000000
386.30		.150000 x	95,302.000000 =	14,295.300000

			T.E =	109,597.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17			
386.64		1.000000 x	129,809.000000 =	129,809.000000
386.64		.150000 x	129,809.000000 =	19,471.350000

			T.E =	149,280.350000
6453.18	6453.18			
386.65		1.000000 x	.000000 =	.000000
386.65		.150000 x	.000000 =	.000000

			T.E =	
6453.19	6453.19			
386.66		1.000000 x	.000000 =	.000000
386.66		.150000 x	.000000 =	.000000

			T.E =	
6453.2	6453.2			
386.49		1.000000 x	.000000 =	.000000
386.49		.150000 x	.000000 =	.000000

			T.E =	
6453.20	6453.20			
386.67		1.000000 x	.000000 =	.000000
386.67		.150000 x	.000000 =	.000000

			T.E =	
6453.3	6453.3			
386.50		1.000000 x	.000000 =	.000000
386.50		.150000 x	.000000 =	.000000

			T.E =	
6453.4	6453.4			
386.51		1.000000 x	.000000 =	.000000
386.51		.150000 x	.000000 =	.000000

			T.E =	
6453.5	6453.5			
386.52		1.000000 x	.000000 =	.000000
386.52		.150000 x	.000000 =	.000000

			T.E =	

6453.6	6453.6			
386.53		1.000000 x	113,243.000000 =	113,243.000000
386.53		.150000 x	113,243.000000 =	16,986.450000

			T.E =	130,229.450000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	18,183.000000 =	18,183.000000
387.3		.100000 x	18,183.000000 =	1,818.300000

			T.E =	20,001.300000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.719000 =	149.552000
113		154.700001 x	24.769248 =	3,831.802690
235		338.000000 x	.553000 =	186.914000

			ΑΘΡΟΙΣΜΑ =	4,168.268690

			T.E =	6,252.403036
6456.2	6456.2			
234.2		336.000000 x	.719000 =	241.584000
113		249.900000 x	24.769248 =	6,189.835075
235		546.000000 x	.553000 =	301.938000

			ΑΘΡΟΙΣΜΑ =	6,733.357075

			T.E =	9,426.699905
6456.3	6456.3			
234.2		384.000000 x	.719000 =	276.096000
235		624.000000 x	.553000 =	345.072000
113		285.599998 x	24.769248 =	7,074.097179

			ΑΘΡΟΙΣΜΑ =	7,695.265179

			T.E =	10,773.371251
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	24.769248 =	421.077216

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	5,630.000000 =	5,630.000000
389.4		.200000 x	5,630.000000 =	1,126.000000

			T.E =	6,756.000000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	4,757.000000 =	4,757.000000
390.14		.150000 x	4,757.000000 =	713.550000

			T.E =	5,470.550000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	6,917.000000 =	6,917.000000
390.31		.150000 x	6,917.000000 =	1,037.550000

			T.E =	7,954.550000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	12,978.000000 =	12,978.000000
393.1		.150000 x	12,978.000000 =	1,946.700000

			T.E =	14,924.700000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000

			T.E =	6.320000
6501	6501			
237		1.000000 x	1.060000 =	1.060000
113		.850000 x	24.769248 =	21.053861

			T.E =	22.113861
6502	6502			
112		.170000 x	18.705943 =	3.180010
517		.042500 x	2,171.391288 =	92.284130

			T.E =	95.464140
6505	6505			
233		1.050000 x	.528700 =	.555135
113		.042500 x	24.769248 =	1.052693

			T.E =	1.607828

6506	6506				
233.1		1.050000 x	.528700 =	.555135	
113		.042500 x	24.769248 =	1.052693	

			T.E =	1.607828	
6551.1	6551.1				
221		6.000000 x	.098900 =	.593400	
113		.255000 x	24.769248 =	6.316158	
111		.255000 x	16.829739 =	4.291583	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	26.301142	
6551.2	6551.2				
221		8.000000 x	.098900 =	.791200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	16.829739 =	5.006847	
113		.297500 x	24.769248 =	7.368851	

			T.E =	39.466899	
6551.3	6551.3				
221		10.000000 x	.098900 =	.989000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	24.769248 =	8.421544	
111		.340000 x	16.829739 =	5.722111	

			T.E =	47.532656	
6551.4	6551.4				
221		13.000000 x	.098900 =	1.285700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	24.769248 =	12.632316	
111		.510000 x	16.829739 =	8.583167	

			T.E =	69.201183	
6551.5	6551.5				
221		16.000000 x	.098900 =	1.582400	
113		.595000 x	24.769248 =	14.737703	
111		.595000 x	16.829739 =	10.013695	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	90.433797	

6551.6	6551.6			
221		20.000000 x	.098900 =	1.978000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	16.829739 =	14.305278
113		.850000 x	24.769248 =	21.053861

T.E = 152.437139

6551.7	6551.7			
221		26.000000 x	.098900 =	2.571400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	24.769248 =	31.580791
111		1.275000 x	16.829739 =	21.457917

T.E = 261.910108

6552	6552			
221		26.000000 x	.098900 =	2.571400
6304		6.890000 x	6.352623 =	43.769572
6310		32.020000 x	1.607828 =	51.482653
6329.2		.418000 x	178.799229 =	74.738078
111		1.700000 x	16.829739 =	28.610556
113		1.275000 x	24.769248 =	31.580791

T.E = 232.753050

6553	6553			
113		.850000 x	24.769248 =	21.053861
6314		13.730000 x	2.272414 =	31.200244
6329.2		.478000 x	178.799229 =	85.466031
6304		9.290000 x	6.352623 =	59.015868

T.E = 196.736004

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	24.769248 =	4.947657
112		.276250 x	18.705943 =	5.167517
111		.067150 x	16.829739 =	1.130117

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	18.705943 =	57.335586
113		.901000 x	24.769248 =	22.317092
111		1.351500 x	16.829739 =	22.745392

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	24.769248 =	24.780394
112		3.858150 x	18.705943 =	72.170334
111		1.669400 x	16.829739 =	28.095566

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	24.769248 =	29.770159
112		5.523300 x	18.705943 =	103.318535
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	16.829739 =	40.441021

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	16.829739 =	55.061016
113		1.401650 x	24.769248 =	34.717816
112		6.712450 x	18.705943 =	125.562707
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	18.705943 =	163.547930
113		1.602250 x	24.769248 =	39.686528
111		4.272950 x	16.829739 =	71.912633
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	24.769248 =	6.189835
112		.379950 x	18.705943 =	7.107323
111		.104550 x	16.829739 =	1.759549
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	16.829739 =	2.532034
113		.300050 x	24.769248 =	7.432013
112		.488750 x	18.705943 =	9.142530

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	24.769248 =	9.916368
363.5		.224000 x	.000000 =	.000000
112		.765000 x	18.705943 =	14.310046
111		.266900 x	16.829739 =	4.491857

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	18.705943 =	19.016462
113		.500650 x	24.769248 =	12.400724
111		.417350 x	16.829739 =	7.023892

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	24.769248 =	14.864026
112		1.484950 x	18.705943 =	27.777390
111		.600950 x	16.829739 =	10.113832
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	16.829739 =	13.761678
113		.700400 x	24.769248 =	17.348381
112		1.926100 x	18.705943 =	36.029517

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	24.769248 =	19.832737
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	18.705943 =	45.553648
111		1.068450 x	16.829739 =	17.981735

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	18.705943 =	5.771719
113		.266900 x	24.769248 =	6.610912
111		.067150 x	16.829739 =	1.130117

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	24.769248 =	29.749105
112		4.232150 x	18.705943 =	79.166357
111		1.351500 x	16.829739 =	22.745392
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	24.769248 =	33.054561
112		5.156950 x	18.705943 =	96.465613
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	16.829739 =	28.095566

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	16.829739 =	40.441021
113		1.602250 x	24.769248 =	39.686528
112		7.410300 x	18.705943 =	138.616649
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	18.705943 =	170.337252
113		1.869150 x	24.769248 =	46.297440
111		3.271650 x	16.829739 =	55.061016

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	24.769248 =	52.908352
112		11.979050 x	18.705943 =	224.079426
111		4.272950 x	16.829739 =	71.912633

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	24.769248 =	8.253113
112		.452200 x	18.705943 =	8.458827
111		.104550 x	16.829739 =	1.759549
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	16.829739 =	2.532034
113		.400350 x	24.769248 =	9.916368
112		.612850 x	18.705943 =	11.463937

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	24.769248 =	13.221825
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	18.705943 =	19.684264
111		.266900 x	16.829739 =	4.491857

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	18.705943 =	25.758084
113		.667250 x	24.769248 =	16.527281
111		.417350 x	16.829739 =	7.023892

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	24.769248 =	19.832737
112		1.989000 x	18.705943 =	37.206121
111		.600950 x	16.829739 =	10.113832
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	16.829739 =	13.761678
113		.934150 x	24.769248 =	23.138193
112		2.718300 x	18.705943 =	50.848365

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	24.769248 =	26.443649
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	18.705943 =	64.411184
111		1.068450 x	16.829739 =	17.981735

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	18.705943 =	7.457124
113		.333200 x	24.769248 =	8.253113
111		.067150 x	16.829739 =	1.130117

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	24.769248 =	37.181118
112		5.308250 x	18.705943 =	99.295822
111		1.351500 x	16.829739 =	22.745392
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	24.769248 =	41.307675
112		6.644450 x	18.705943 =	124.290703
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	16.829739 =	28.095566

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	16.829739 =	40.441021
113		2.002600 x	24.769248 =	49.602896
112		9.562500 x	18.705943 =	178.875580
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	18.705943 =	216.797203
113		2.336650 x	24.769248 =	57.877063
111		3.271650 x	16.829739 =	55.061016

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	24.769248 =	66.130177
112		14.965950 x	18.705943 =	279.952208
111		4.272950 x	16.829739 =	71.912633

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	24.769248 =	10.316392
112		.523600 x	18.705943 =	9.794432
111		.104550 x	16.829739 =	1.759549
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	24.769248 =	12.400724
112		.748000 x	18.705943 =	13.992045
367.3		.224000 x	.000000 =	.000000
111		.150450 x	16.829739 =	2.532034

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	16.829739 =	4.491857
113		.667250 x	24.769248 =	16.527281
112		1.269050 x	18.705943 =	23.738777
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	18.705943 =	33.819410
113		.833850 x	24.769248 =	20.653837
111		.417350 x	16.829739 =	7.023892

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	24.769248 =	24.780394
112		2.597600 x	18.705943 =	48.590558
111		.600950 x	16.829739 =	10.113832

T.E =

6603.8 6603.8

366.8	1.020000 x	.000000 =	.000000
113	1.167900 x	24.769248 =	28.928005
112	3.439100 x	18.705943 =	64.331609
111	.817700 x	16.829739 =	13.761678
367.8	.224000 x	.000000 =	.000000

T.E =

6603.9 6603.9

366.9	1.020000 x	.000000 =	.000000
367.9	.224000 x	.000000 =	.000000
111	1.068450 x	16.829739 =	17.981735
113	1.334500 x	24.769248 =	33.054561
112	4.386850 x	18.705943 =	82.060166

T.E =

6604.1 6604.1

366.15	1.020000 x	.000000 =	.000000
113	.400350 x	24.769248 =	9.916368
367.15	.224000 x	.000000 =	.000000
112	.504900 x	18.705943 =	9.444631
111	.067150 x	16.829739 =	1.130117

T.E =

6604.10 6604.10

366.24	1.020000 x	.000000 =	.000000
367.24	.224000 x	.000000 =	.000000
112	6.546700 x	18.705943 =	122.462197
113	1.802000 x	24.769248 =	44.634185
111	1.351500 x	16.829739 =	22.745392

T.E =

6604.11 6604.11

366.25	1.020000 x	.000000 =	.000000
113	2.001750 x	24.769248 =	49.581842
112	8.181250 x	18.705943 =	153.037996
111	1.669400 x	16.829739 =	28.095566
367.25	.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	16.829739 =	40.441021
113		2.403800 x	24.769248 =	59.540318
112		11.789500 x	18.705943 =	220.533715

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	24.769248 =	69.456687
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	18.705943 =	268.631371
111		3.271650 x	16.829739 =	55.061016

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	18.705943 =	350.135035
113		3.204500 x	24.769248 =	79.373055
111		4.272950 x	16.829739 =	71.912633

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	24.769248 =	12.379670
112		.647700 x	18.705943 =	12.115839
111		.104550 x	16.829739 =	1.759549
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	18.705943 =	17.458257
113		.600950 x	24.769248 =	14.885080
111		.150450 x	16.829739 =	2.532034

T.E =

6604.5 6604.5

366.19	1.020000 x	.000000 =	.000000
367.19	.224000 x	.000000 =	.000000
113	.800700 x	24.769248 =	19.832737
112	1.592900 x	18.705943 =	29.796697
111	.266900 x	16.829739 =	4.491857

T.E =

6604.6 6604.6

366.20	1.020000 x	.000000 =	.000000
367.20	.224000 x	.000000 =	.000000
113	1.001300 x	24.769248 =	24.801448
112	2.094400 x	18.705943 =	39.177727
111	.417350 x	16.829739 =	7.023892

T.E =

6604.7 6604.7

366.21	1.020000 x	.000000 =	.000000
113	1.201050 x	24.769248 =	29.749105
112	2.952900 x	18.705943 =	55.236779
111	.600950 x	16.829739 =	10.113832
367.21	.224000 x	.000000 =	.000000

T.E =

6604.8 6604.8

366.22	1.020000 x	.000000 =	.000000
112	3.979700 x	18.705943 =	74.444041
113	1.401650 x	24.769248 =	34.717816
111	.817700 x	16.829739 =	13.761678
367.22	.224000 x	.000000 =	.000000

T.E =

6604.9 6604.9

366.23	1.020000 x	.000000 =	.000000
111	1.068450 x	16.829739 =	17.981735
113	1.601400 x	24.769248 =	39.665474
112	5.210500 x	18.705943 =	97.467316
367.23	.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
113		.025500 x	24.769248 =	.631616
112		.042500 x	18.705943 =	.795003
111		.042500 x	16.829739 =	.715264

T.E =

6611.1	6611.1			
361.1		1.000000 x	11.750000 =	11.750000
113		.212500 x	24.769248 =	5.263465
112		.510000 x	18.705943 =	9.540031
111		.085000 x	16.829739 =	1.430528

T.E =

27.984024

6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	16.829739 =	8.583167
112		2.125000 x	18.705943 =	39.750129
113		.765000 x	24.769248 =	18.948475

T.E =

6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	16.829739 =	10.728959
113		.935000 x	24.769248 =	23.159247
112		2.550000 x	18.705943 =	47.700155

T.E =

6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	16.829739 =	12.874750
113		1.105000 x	24.769248 =	27.370019
112		2.975000 x	18.705943 =	55.650180

T.E =

6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	24.769248 =	31.580791
112		3.400000 x	18.705943 =	63.600206
111		.892500 x	16.829739 =	15.020542

T.E =

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	16.829739 =	17.166334
112		3.825000 x	18.705943 =	71.550232
113		1.445000 x	24.769248 =	35.791563

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.300000 =	15.300000
111		.085000 x	16.829739 =	1.430528
113		.212500 x	24.769248 =	5.263465
112		.552500 x	18.705943 =	10.335034

			T.E =	32.329027
6611.3	6611.3			
361.3		1.000000 x	19.280000 =	19.280000
111		.127500 x	16.829739 =	2.145792
113		.255000 x	24.769248 =	6.316158
112		.637500 x	18.705943 =	11.925039

			T.E =	39.666989
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	24.769248 =	7.368851
112		.680000 x	18.705943 =	12.720041
111		.170000 x	16.829739 =	2.861056

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	36.800000 =	36.800000
111		.212500 x	16.829739 =	3.576320
112		.935000 x	18.705943 =	17.490057
113		.382500 x	24.769248 =	9.474237

			T.E =	67.340614
6611.6	6611.6			
361.6		1.000000 x	49.220000 =	49.220000
111		.255000 x	16.829739 =	4.291583
113		.425000 x	24.769248 =	10.526930
112		1.105000 x	18.705943 =	20.670067

			T.E =	84.708581

6611.7	6611.7			
361.7		1.000000 x	76.000000 =	76.000000
111		.340000 x	16.829739 =	5.722111
113		.510000 x	24.769248 =	12.632316
112		1.275000 x	18.705943 =	23.850077

			T.E =	118.204505
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	24.769248 =	15.790396
112		1.700000 x	18.705943 =	31.800103
111		.382500 x	16.829739 =	6.437375

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	16.829739 =	7.152639
112		1.870000 x	18.705943 =	34.980113
113		.680000 x	24.769248 =	16.843089

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	16.829739 =	1.359001
113		.176800 x	24.769248 =	4.379203
112		.055250 x	18.705943 =	1.033503

			T.E =	11.953308
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	16.829739 =	2.203013
113		.224400 x	24.769248 =	5.558219
112		.089250 x	18.705943 =	1.669505

			T.E =	17.641737
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	24.769248 =	6.358266
112		.116450 x	18.705943 =	2.178307
111		.170850 x	16.829739 =	2.875361

			T.E =	22.081134

6620.4	6620.4				
371.4		1.020000 x	16.260000 =	16.585200	
111		.266900 x	16.829739 =	4.491857	
112		.182750 x	18.705943 =	3.418511	
113		.320450 x	24.769248 =	7.937306	
			T.E =	32.432874	
6620.5	6620.5				
371.5		1.020000 x	20.580000 =	20.991600	
111		.338300 x	16.829739 =	5.693501	
113		.360400 x	24.769248 =	8.926837	
112		.228650 x	18.705943 =	4.277114	
			T.E =	39.889052	
6620.6	6620.6				
371.6		1.020000 x	32.340000 =	32.986800	
111		.523600 x	16.829739 =	8.812051	
113		.448800 x	24.769248 =	11.116439	
112		.353600 x	18.705943 =	6.614421	
			T.E =	59.529711	
6620.7	6620.7				
371.7		1.020000 x	41.610000 =	42.442200	
113		.504900 x	24.769248 =	12.505993	
112		.445400 x	18.705943 =	8.331627	
111		.662150 x	16.829739 =	11.143812	
			T.E =	74.423632	
6620.8	6620.8				
371.8		1.020000 x	52.890000 =	53.947800	
111		.841500 x	16.829739 =	14.162225	
112		.567800 x	18.705943 =	10.621234	
113		.568650 x	24.769248 =	14.085033	
			T.E =	92.816293	
6620.9	6620.9				
371.9		1.020000 x	66.370000 =	67.697400	
111		1.068450 x	16.829739 =	17.981735	
113		.640900 x	24.769248 =	15.874611	
112		.717400 x	18.705943 =	13.419644	
			T.E =	114.973389	

6621.1	6621.1				
372.1		1.020000 x	8.000000 =	8.160000	
111		.080750 x	16.829739 =	1.359001	
113		.205700 x	24.769248 =	5.095034	
112		.088400 x	18.705943 =	1.653605	

			T.E =	16.267641	
6621.2	6621.2				
372.2		1.020000 x	12.580000 =	12.831600	
113		.261800 x	24.769248 =	6.484589	
112		.141100 x	18.705943 =	2.639409	
111		.130900 x	16.829739 =	2.203013	

			T.E =	24.158611	
6621.3	6621.3				
372.3		1.020000 x	16.500000 =	16.830000	
111		.170850 x	16.829739 =	2.875361	
112		.185300 x	18.705943 =	3.466211	
113		.299200 x	24.769248 =	7.410959	

			T.E =	30.582531	
6621.4	6621.4				
372.4		1.020000 x	25.550000 =	26.061000	
111		.266900 x	16.829739 =	4.491857	
113		.374000 x	24.769248 =	9.263699	
112		.289000 x	18.705943 =	5.406018	

			T.E =	45.222574	
6621.5	6621.5				
372.5		1.020000 x	32.410000 =	33.058200	
111		.338300 x	16.829739 =	5.693501	
113		.420750 x	24.769248 =	10.421661	
112		.367200 x	18.705943 =	6.868822	

			T.E =	56.042184	
6621.6	6621.6				
372.6		1.020000 x	51.220000 =	52.244400	
113		.523600 x	24.769248 =	12.969178	
112		.564400 x	18.705943 =	10.557634	
111		.523600 x	16.829739 =	8.812051	

			T.E =	84.583264	

6621.7	6621.7			
372.7		1.020000 x	65.050000 =	66.351000
111		.662150 x	16.829739 =	11.143812
112		.710600 x	18.705943 =	13.292443
113		.589050 x	24.769248 =	14.590326

			T.E =	105.377580
6621.8	6621.8			
372.8		1.020000 x	82.710000 =	84.364200
111		.841500 x	16.829739 =	14.162225
113		.663850 x	24.769248 =	16.443065
112		.901000 x	18.705943 =	16.854055

			T.E =	131.823545
6621.9	6621.9			
372.9		1.020000 x	104.700000 =	106.794000
111		1.068450 x	16.829739 =	17.981735
113		.748000 x	24.769248 =	18.527398
112		1.145800 x	18.705943 =	21.433269

			T.E =	164.736402
6622.1	6622.1			
373.1		1.020000 x	11.900000 =	12.138000
113		.235450 x	24.769248 =	5.831919
112		.131750 x	18.705943 =	2.464508
111		.080750 x	16.829739 =	1.359001

			T.E =	21.793429
6622.2	6622.2			
373.2		1.020000 x	18.780000 =	19.155600
111		.130900 x	16.829739 =	2.203013
112		.212500 x	18.705943 =	3.975013
113		.299200 x	24.769248 =	7.410959

			T.E =	32.744585
6622.3	6622.3			
373.3		1.020000 x	24.500000 =	24.990000
111		.170850 x	16.829739 =	2.875361
113		.341700 x	24.769248 =	8.463652
112		.277950 x	18.705943 =	5.199317

			T.E =	41.528330

6623	6623				
360.2		1.000000 x	2.120000 =	2.120000	
113		.085000 x	24.769248 =	2.105386	
111		.042500 x	16.829739 =	.715264	
113		.025500 x	24.769248 =	.631616	
112		.042500 x	18.705943 =	.795003	

			T.E =	6.367268	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	24.769248 =	63.161582	
113		.610300 x	24.769248 =	15.116672	
113		1.067600 x	24.769248 =	26.443649	
112		2.439500 x	18.705943 =	45.633148	
111		.855100 x	16.829739 =	14.391110	

			T.E =	253.706161	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	16.829739 =	129.434157	
113		3.349000 x	24.769248 =	82.952212	
113		3.203650 x	24.769248 =	79.352001	
113		2.550000 x	24.769248 =	63.161582	
112		13.396000 x	18.705943 =	250.584812	

			T.E =	1,093.084764	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	16.829739 =	151.893443	
113		3.471400 x	24.769248 =	85.983968	
113		3.629500 x	24.769248 =	89.899986	
113		2.550000 x	24.769248 =	63.161582	
112		14.518000 x	18.705943 =	271.572880	

			T.E =	1,191.111859	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	24.769248 =	63.161582	
113		1.201050 x	24.769248 =	29.749105	
113		.680000 x	24.769248 =	16.843089	
111		1.081200 x	16.829739 =	18.196314	
112		2.720000 x	18.705943 =	50.880165	

			T.E =	277.790255	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	24.769248 =	33.054561	
113		2.550000 x	24.769248 =	63.161582	
113		.760750 x	24.769248 =	18.843205	
112		3.043000 x	18.705943 =	56.922185	
111		1.334500 x	16.829739 =	22.459287	

			T.E =	304.222821	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	16.829739 =	32.358539	
113		.892500 x	24.769248 =	22.106554	
113		1.602250 x	24.769248 =	39.686528	
113		2.550000 x	24.769248 =	63.161582	
112		3.570000 x	18.705943 =	66.780217	

			T.E =	364.743420	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	16.829739 =	44.045951	
113		1.164500 x	24.769248 =	28.843789	
113		2.550000 x	24.769248 =	63.161582	
113		1.869150 x	24.769248 =	46.297440	
112		4.658000 x	18.705943 =	87.132282	

			T.E =	446.361046	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	24.769248 =	63.161582	
113		2.136050 x	24.769248 =	52.908352	
113		1.470500 x	24.769248 =	36.423179	
111		3.418700 x	16.829739 =	57.535829	
112		5.882000 x	18.705943 =	110.028357	

			T.E =	544.577299	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.031500 x	24.769248 =	50.318727	
113		2.402950 x	24.769248 =	59.519264	
113		2.550000 x	24.769248 =	63.161582	
112		8.126000 x	18.705943 =	152.004493	
111		4.326500 x	16.829739 =	72.813866	

			T.E =	700.457933	

6630.8	6630.8			
376.19		1.000000 x	336.580000 =	336.580000
111		5.340550 x	16.829739 =	89.880063
112		9.044000 x	18.705943 =	169.176548
113		2.550000 x	24.769248 =	63.161582
113		2.669850 x	24.769248 =	66.130177
113		2.261000 x	24.769248 =	56.003270

T.E = 780.931640

6630.9	6630.9			
376.20		1.000000 x	400.990000 =	400.990000
111		6.461700 x	16.829739 =	108.748724
113		2.936750 x	24.769248 =	72.741089
113		2.550000 x	24.769248 =	63.161582
113		2.737000 x	24.769248 =	67.793432
112		10.948000 x	18.705943 =	204.792664

T.E = 918.227492

6640.1	6640.1			
377.1		1.000000 x	.000000 =	.000000
113		2.550000 x	24.769248 =	63.161582
113		1.667700 x	24.769248 =	41.307675
111		1.334500 x	16.829739 =	22.459287
112		3.043000 x	18.705943 =	56.922185

T.E =

6640.2	6640.2			
377.2		1.000000 x	.000000 =	.000000
113		2.550000 x	24.769248 =	63.161582
113		2.002600 x	24.769248 =	49.602896
112		3.570000 x	18.705943 =	66.780217
111		1.922700 x	16.829739 =	32.358539

T.E =

6640.3	6640.3			
377.3		1.000000 x	.000000 =	.000000
111		2.617150 x	16.829739 =	44.045951
112		4.658000 x	18.705943 =	87.132282
113		2.550000 x	24.769248 =	63.161582
113		2.336650 x	24.769248 =	57.877063

T.E =

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	16.829739 =	57.535829
112	5.882000 x	18.705943 =	110.028357
113	2.669850 x	24.769248 =	66.130177
113	2.550000 x	24.769248 =	63.161582

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	16.829739 =	72.813866
113	3.003900 x	24.769248 =	74.404344
113	2.550000 x	24.769248 =	63.161582
112	8.126000 x	18.705943 =	152.004493

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	24.769248 =	63.161582
113	3.337100 x	24.769248 =	82.657458
112	9.044000 x	18.705943 =	169.176548
111	5.340550 x	16.829739 =	89.880063

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	16.829739 =	108.748724
112	10.948000 x	18.705943 =	204.792664
113	3.671150 x	24.769248 =	90.931625
113	2.550000 x	24.769248 =	63.161582

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	16.829739 =	129.434157
112	13.396000 x	18.705943 =	250.584812
113	2.550000 x	24.769248 =	63.161582
113	4.004350 x	24.769248 =	99.184738

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	16.829739 =	151.893443
113		4.339250 x	24.769248 =	107.479959
113		2.550000 x	24.769248 =	63.161582
112		14.518000 x	18.705943 =	271.572880

			T.E =	
6641	6641			
233.3		1.000000 x	7.650000 =	7.650000

			T.E =	7.650000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		1.000000 x	396.000000 =	396.000000
380.1		.100000 x	396.000000 =	39.600000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		.100000 x	583.000000 =	58.300000
380.3		1.000000 x	583.000000 =	583.000000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			ΑΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7 6662.7

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.5	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.8	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.8 6662.8

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.9	4.000000 x	.000000 =	.000000
384.7	4.000000 x	.000000 =	.000000
384.6	4.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.1 6663.1

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.4	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6663.2 6663.2

385.1	1.000000 x	.000000 =	.000000
385.5	1.000000 x	.000000 =	.000000
385.2	1.000000 x	.000000 =	.000000
385.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6701.1 6701.1

368.1	1.020000 x	.000000 =	.000000
369.1	.224000 x	.000000 =	.000000
113	.068000 x	24.769248 =	1.684309
111	.382500 x	16.829739 =	6.437375

T.E =

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	24.769248 =	8.421544
369.10		.224000 x	.000000 =	.000000
111		.680000 x	16.829739 =	11.444223

T.E =

6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534
369.2		.224000 x	.000000 =	.000000

T.E =

6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	16.829739 =	7.295692
113		.102000 x	24.769248 =	2.526463

T.E =

6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	24.769248 =	2.947541
111		.459000 x	16.829739 =	7.724850

T.E =

6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	24.769248 =	3.579156
111		.484500 x	16.829739 =	8.154009

T.E =

6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.518500 x	16.829739 =	8.726220
369.6		.224000 x	.000000 =	.000000

T.E =

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	16.829739 =	9.298431
113		.195500 x	24.769248 =	4.842388

			T.E =	
6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	24.769248 =	5.895081
111		.595000 x	16.829739 =	10.013695

			T.E =	
6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	24.769248 =	7.158313
111		.637500 x	16.829739 =	10.728959

			T.E =	
6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	24.769248 =	1.684309
111		.382500 x	16.829739 =	6.437375
369.11		.224000 x	.000000 =	.000000

			T.E =	
6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	16.829739 =	11.444223
113		.340000 x	24.769248 =	8.421544

			T.E =	
6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534

			T.E =	

6702.3	6702.3			
368.13		1.020000 x	.000000 =	.000000
369.13		.224000 x	.000000 =	.000000
113		.102000 x	24.769248 =	2.526463
111		.433500 x	16.829739 =	7.295692

T.E =

6702.4	6702.4			
368.14		1.020000 x	.000000 =	.000000
113		.119000 x	24.769248 =	2.947541
111		.459000 x	16.829739 =	7.724850
369.14		.224000 x	.000000 =	.000000

T.E =

6702.5	6702.5			
368.15		1.020000 x	.000000 =	.000000
369.15		.224000 x	.000000 =	.000000
111		.484500 x	16.829739 =	8.154009
113		.144500 x	24.769248 =	3.579156

T.E =

6702.6	6702.6			
368.16		1.020000 x	.000000 =	.000000
369.16		.224000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.518500 x	16.829739 =	8.726220

T.E =

6702.7	6702.7			
368.17		1.020000 x	.000000 =	.000000
369.17		.224000 x	.000000 =	.000000
113		.195500 x	24.769248 =	4.842388
111		.552500 x	16.829739 =	9.298431

T.E =

6702.8	6702.8			
368.18		1.020000 x	.000000 =	.000000
113		.238000 x	24.769248 =	5.895081
111		.595000 x	16.829739 =	10.013695
369.18		.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	24.769248 =	7.158313
369.19		.224000 x	.000000 =	.000000
111		.637500 x	16.829739 =	10.728959

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	16.829739 =	6.437375
113		.068000 x	24.769248 =	1.684309
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	24.769248 =	8.421544
111		.680000 x	16.829739 =	11.444223

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	24.769248 =	2.526463
111		.433500 x	16.829739 =	7.295692
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	16.829739 =	7.724850
113		.119000 x	24.769248 =	2.947541

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	24.769248 =	3.579156
111		.484500 x	16.829739 =	8.154009

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.518500 x	16.829739 =	8.726220

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	24.769248 =	4.842388
111		.552500 x	16.829739 =	9.298431
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	16.829739 =	10.013695
113		.238000 x	24.769248 =	5.895081

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	24.769248 =	7.158313
111		.637500 x	16.829739 =	10.728959

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	24.769248 =	1.684309
111		.382500 x	16.829739 =	6.437375

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	16.829739 =	7.295692
113		.102000 x	24.769248 =	2.526463

T.E =

6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	24.769248 =	2.947541
111		.459000 x	16.829739 =	7.724850

T.E =

6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	24.769248 =	3.579156
111		.484500 x	16.829739 =	8.154009

T.E =

6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.518500 x	16.829739 =	8.726220
370.8		1.000000 x	.000000 =	.000000

T.E =

6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	16.829739 =	9.298431
113		.195500 x	24.769248 =	4.842388

T.E =

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	24.769248 =	1.684309
111		.382500 x	16.829739 =	6.437375

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	24.769248 =	2.526463
111		.433500 x	16.829739 =	7.295692
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	16.829739 =	7.724850
113		.119000 x	24.769248 =	2.947541

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	24.769248 =	3.579156
111		.484500 x	16.829739 =	8.154009

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	24.769248 =	4.210772
111		.518500 x	16.829739 =	8.726220

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	24.769248 =	4.842388
111		.552500 x	16.829739 =	9.298431
370.16		1.000000 x	.000000 =	.000000

T.E =

6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	16.829739 =	6.437375
113		.068000 x	24.769248 =	1.684309

T.E =

6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	24.769248 =	2.105386
111		.408000 x	16.829739 =	6.866534

T.E =

6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	24.769248 =	2.526463
111		.433500 x	16.829739 =	7.295692

T.E =

6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	24.769248 =	2.947541
111		.459000 x	16.829739 =	7.724850
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	16.829739 =	8.154009
113		.144500 x	24.769248 =	3.579156

T.E =

6706.6 6706.6

370.22	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
113	.170000 x	24.769248 =	4.210772
111	.518500 x	16.829739 =	8.726220

T.E =

6706.7 6706.7

370.23	1.000000 x	.000000 =	.000000
370.24	1.000000 x	.000000 =	.000000
113	.195500 x	24.769248 =	4.842388
111	.552500 x	16.829739 =	9.298431

T.E =

6710.1 6710.1

374.1	1.020000 x	.000000 =	.000000
6326	.327500 x	143.938776 =	47.139949
113	.026350 x	24.769248 =	.652670
111	.085000 x	16.829739 =	1.430528

T.E =

6710.2 6710.2

374.2	1.020000 x	.000000 =	.000000
111	.119000 x	16.829739 =	2.002739
113	.040800 x	24.769248 =	1.010585
6326	.352500 x	143.938776 =	50.738419

T.E =

6710.3 6710.3

374.3	1.020000 x	.000000 =	.000000
111	.161500 x	16.829739 =	2.718003
6326	.372500 x	143.938776 =	53.617194
113	.051000 x	24.769248 =	1.263232

T.E =

6710.4 6710.4

374.4	1.020000 x	.000000 =	.000000
111	.170000 x	16.829739 =	2.861056
6326	.382500 x	143.938776 =	55.056582
113	.063750 x	24.769248 =	1.579040

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	143.938776 =	56.316046
113		.068000 x	24.769248 =	1.684309
111		.187000 x	16.829739 =	3.147161

			T.E =	
6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	16.829739 =	3.433267
113		.076500 x	24.769248 =	1.894847
6327		.393750 x	167.693457 =	66.029299

			T.E =	
6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	16.829739 =	4.863795
6327		.431250 x	167.693457 =	72.317803
113		.093500 x	24.769248 =	2.315925

			T.E =	
6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	16.829739 =	5.722111
6327		.500000 x	167.693457 =	83.846729
113		.119000 x	24.769248 =	2.947541

			T.E =	
6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	25.712627 =	9.513672
113		.017000 x	24.769248 =	.421077
111		.161500 x	16.829739 =	2.718003

			T.E =	21.332952
6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	16.829739 =	3.147161
6069		.390000 x	25.712627 =	10.027925
113		.021250 x	24.769248 =	.526347

			T.E =	27.298032

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	16.829739 =	3.433267
6069		.400000 x	25.712627 =	10.285051
113		.026350 x	24.769248 =	.652670

			T.E =	35.576787
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	16.829739 =	4.148531
6069		.420000 x	25.712627 =	10.799303
113		.040800 x	24.769248 =	1.010585

			T.E =	50.281419
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	25.712627 =	11.056430
113		.051000 x	24.769248 =	1.263232
111		.289000 x	16.829739 =	4.863795

			T.E =	60.839456
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	25.712627 =	11.313556
113		.063750 x	24.769248 =	1.579040
111		.297500 x	16.829739 =	5.006847

			T.E =	73.214043
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	25.712627 =	13.370566
113		.076500 x	24.769248 =	1.894847
111		.357000 x	16.829739 =	6.008217

			T.E =	110.941830
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	24.769248 =	21.053861

			T.E =	43.435861

6712.2	6712.2				
375.9		1.050000 x	14.980000 =	15.729000	
375.13		1.000000 x	10.160000 =	10.160000	
113		.850000 x	24.769248 =	21.053861	
			T.E =	46.942861	
6712.3	6712.3				
375.10		1.050000 x	20.150000 =	21.157500	
375.13		1.000000 x	10.160000 =	10.160000	
113		.850000 x	24.769248 =	21.053861	
			T.E =	52.371361	
6712.4	6712.4				
375.11		1.050000 x	27.290000 =	28.654500	
375.13		1.000000 x	10.160000 =	10.160000	
113		.850000 x	24.769248 =	21.053861	
			T.E =	59.868361	
6712.5	6712.5				
375.12		1.050000 x	34.560000 =	36.288000	
113		.850000 x	24.769248 =	21.053861	
375.13		1.000000 x	10.160000 =	10.160000	
			T.E =	67.501861	
6713	6713				
375.13		1.000000 x	10.160000 =	10.160000	
113		.021250 x	24.769248 =	.526347	
111		.187000 x	16.829739 =	3.147161	
375.14		1.000000 x	17.510000 =	17.510000	
			T.E =	31.343508	
6720.1	6720.1				
394.2		1.050000 x	.000000 =	.000000	
700		.200000 x	.000000 =	.000000	
6323		.090000 x	113.291449 =	10.196230	
112		1.190000 x	18.705943 =	22.260072	
113		.255000 x	24.769248 =	6.316158	
			T.E =		

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	123.181449 =	27.223100
700		.350000 x	.000000 =	.000000
113		.510000 x	24.769248 =	12.632316
112		1.360000 x	18.705943 =	25.440082

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	18.705943 =	27.030088
113		.595000 x	24.769248 =	14.737703
6325		.234000 x	123.181449 =	28.824459
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	123.181449 =	29.686729
112		1.487500 x	18.705943 =	27.825090
700		.400000 x	.000000 =	.000000
113		.637500 x	24.769248 =	15.790396

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	113.291449 =	12.462059
112		1.275000 x	18.705943 =	23.850077
700		.250000 x	.000000 =	.000000
113		.340000 x	24.769248 =	8.421544

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	113.291449 =	14.841180
700		.300000 x	.000000 =	.000000
113		.425000 x	24.769248 =	10.526930
112		1.275000 x	18.705943 =	23.850077

T.E =

6720.4	6720.4			
394.5		1.050000 x	.000000 =	.000000
112		1.360000 x	18.705943 =	25.440082
113		.510000 x	24.769248 =	12.632316
6323		.154000 x	113.291449 =	17.446883
700		.350000 x	.000000 =	.000000

T.E =

6720.5	6720.5			
394.6		1.050000 x	.000000 =	.000000
6323		.166000 x	113.291449 =	18.806381
112		1.445000 x	18.705943 =	27.030088
700		.380000 x	.000000 =	.000000
113		.595000 x	24.769248 =	14.737703

T.E =

6720.6	6720.6			
394.7		1.050000 x	.000000 =	.000000
112		1.487500 x	18.705943 =	27.825090
700		.400000 x	.000000 =	.000000
6323		.173000 x	113.291449 =	19.599421
113		.637500 x	24.769248 =	15.790396

T.E =

6720.7	6720.7			
394.2		1.050000 x	.000000 =	.000000
6325		.138000 x	123.181449 =	16.999040
700		.200000 x	.000000 =	.000000
113		.255000 x	24.769248 =	6.316158
112		1.190000 x	18.705943 =	22.260072

T.E =

6720.8	6720.8			
394.3		1.050000 x	.000000 =	.000000
112		1.275000 x	18.705943 =	23.850077
113		.340000 x	24.769248 =	8.421544
6325		.165000 x	123.181449 =	20.324939
700		.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	123.181449 =	23.774020
112		1.275000 x	18.705943 =	23.850077
700		.300000 x	.000000 =	.000000
113		.425000 x	24.769248 =	10.526930

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	113.291449 =	6.797487
112		1.190000 x	18.705943 =	22.260072
700		.200000 x	.000000 =	.000000
113		.255000 x	24.769248 =	6.316158

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	123.181449 =	16.013588
700		.350000 x	.000000 =	.000000
113		.510000 x	24.769248 =	12.632316
112		1.360000 x	18.705943 =	25.440082

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	18.705943 =	27.030088
113		.595000 x	24.769248 =	14.737703
6325		.140000 x	123.181449 =	17.245403
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	123.181449 =	18.477217
112		1.487500 x	18.705943 =	27.825090
700		.400000 x	.000000 =	.000000
113		.637500 x	24.769248 =	15.790396

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	113.291449 =	7.930401
112		1.275000 x	18.705943 =	23.850077
700		.250000 x	.000000 =	.000000
113		.340000 x	24.769248 =	8.421544

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	113.291449 =	9.063316
700		.300000 x	.000000 =	.000000
113		.425000 x	24.769248 =	10.526930
112		1.275000 x	18.705943 =	23.850077

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	18.705943 =	25.440082
113		.510000 x	24.769248 =	12.632316
6323		.090000 x	113.291449 =	10.196230
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	113.291449 =	11.329145
112		1.445000 x	18.705943 =	27.030088
700		.380000 x	.000000 =	.000000
113		.595000 x	24.769248 =	14.737703

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	18.705943 =	27.825090
700		.400000 x	.000000 =	.000000
6323		.110000 x	113.291449 =	12.462059
113		.637500 x	24.769248 =	15.790396

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	123.181449 =	12.318145
700		.200000 x	.000000 =	.000000
113		.255000 x	24.769248 =	6.316158
112		1.190000 x	18.705943 =	22.260072

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	18.705943 =	23.850077
113		.340000 x	24.769248 =	8.421544
6325		.110000 x	123.181449 =	13.549959
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	123.181449 =	14.781774
112		1.275000 x	18.705943 =	23.850077
700		.300000 x	.000000 =	.000000
113		.425000 x	24.769248 =	10.526930

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	18.705943 =	7.950026
700		.120000 x	.000000 =	.000000
113		.255000 x	24.769248 =	6.316158

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	113.291449 =	10.196230
652		.002500 x	153.400939 =	.383502
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021
111		.170000 x	16.829739 =	2.861056

T.E = 41.971967

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	16.829739 =	5.006847
112		.425000 x	18.705943 =	7.950026
6325		.249000 x	123.181449 =	30.672181
652		.004500 x	153.400939 =	.690304
113		.340000 x	24.769248 =	8.421544
			T.E =	86.760902
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	123.181449 =	38.186249
652		.005000 x	153.400939 =	.767005
111		.340000 x	16.829739 =	5.722111
113		.510000 x	24.769248 =	12.632316
112		.552500 x	18.705943 =	10.335034
			T.E =	116.677715
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	16.829739 =	7.152639
113		.595000 x	24.769248 =	14.737703
6325		.370000 x	123.181449 =	45.577136
652		.006500 x	153.400939 =	.997106
112		.680000 x	18.705943 =	12.720041
			T.E =	148.489625
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	113.291449 =	12.462059
652		.003000 x	153.400939 =	.460203
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021
111		.170000 x	16.829739 =	2.861056
			T.E =	50.194497
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	16.829739 =	3.576320
112		.382500 x	18.705943 =	7.155023
6323		.131000 x	113.291449 =	14.841180
652		.003500 x	153.400939 =	.536903
113		.297500 x	24.769248 =	7.368851
			T.E =	61.093277

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	113.291449 =	19.259546
652		.004500 x	153.400939 =	.690304
111		.297500 x	16.829739 =	5.006847
113		.340000 x	24.769248 =	8.421544
112		.425000 x	18.705943 =	7.950026

			T.E =	75.348268
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	16.829739 =	5.722111
113		.510000 x	24.769248 =	12.632316
6323		.226000 x	113.291449 =	25.603867
652		.005000 x	153.400939 =	.767005
112		.552500 x	18.705943 =	10.335034

			T.E =	104.095333
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	113.291449 =	31.041857
652		.006500 x	153.400939 =	.997106
113		.595000 x	24.769248 =	14.737703
112		.680000 x	18.705943 =	12.720041
111		.425000 x	16.829739 =	7.152639

			T.E =	133.954346
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	16.829739 =	2.861056
112		.340000 x	18.705943 =	6.360021
6325		.138000 x	123.181449 =	16.999040
652		.002500 x	153.400939 =	.383502
113		.255000 x	24.769248 =	6.316158

			T.E =	48.774777
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	123.181449 =	20.324939
652		.003000 x	153.400939 =	.460203
111		.170000 x	16.829739 =	2.861056
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021

			T.E =	58.057376

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	16.829739 =	3.576320
113		.297500 x	24.769248 =	7.368851
6325		.193000 x	123.181449 =	23.774020
652		.003500 x	153.400939 =	.536903
112		.382500 x	18.705943 =	7.155023

T.E = 70.026117

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	113.291449 =	10.196230
652		.002500 x	153.400939 =	.383502
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021
111		.170000 x	16.829739 =	2.861056

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	16.829739 =	5.006847
112		.425000 x	18.705943 =	7.950026
6325		.249000 x	123.181449 =	30.672181
652		.004500 x	153.400939 =	.690304
113		.340000 x	24.769248 =	8.421544

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	123.181449 =	38.186249
652		.005000 x	153.400939 =	.767005
111		.340000 x	16.829739 =	5.722111
113		.510000 x	24.769248 =	12.632316
112		.552500 x	18.705943 =	10.335034

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	16.829739 =	7.152639
113		.595000 x	24.769248 =	14.737703
6325		.370000 x	123.181449 =	45.577136
652		.006500 x	153.400939 =	.997106
112		.680000 x	18.705943 =	12.720041

T.E =

6731.2	6731.2			
261.4		1.050000 x	.000000 =	.000000
6323		.110000 x	113.291449 =	12.462059
652		.003000 x	153.400939 =	.460203
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021
111		.170000 x	16.829739 =	2.861056

T.E =

6731.3	6731.3			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	16.829739 =	3.576320
112		.382500 x	18.705943 =	7.155023
6323		.131000 x	113.291449 =	14.841180
652		.003500 x	153.400939 =	.536903
113		.297500 x	24.769248 =	7.368851

T.E =

6731.4	6731.4			
263.1		1.050000 x	.000000 =	.000000
6323		.170000 x	113.291449 =	19.259546
652		.004500 x	153.400939 =	.690304
111		.297500 x	16.829739 =	5.006847
113		.340000 x	24.769248 =	8.421544
112		.425000 x	18.705943 =	7.950026

T.E =

6731.5	6731.5			
263.3		1.050000 x	.000000 =	.000000
111		.340000 x	16.829739 =	5.722111
113		.510000 x	24.769248 =	12.632316
6323		.226000 x	113.291449 =	25.603867
652		.005000 x	153.400939 =	.767005
112		.552500 x	18.705943 =	10.335034

T.E =

6731.6	6731.6			
264.1		1.050000 x	.000000 =	.000000
6323		.274000 x	113.291449 =	31.041857
652		.006500 x	153.400939 =	.997106
113		.595000 x	24.769248 =	14.737703
112		.680000 x	18.705943 =	12.720041
111		.425000 x	16.829739 =	7.152639

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	16.829739 =	2.861056
112		.340000 x	18.705943 =	6.360021
6325		.138000 x	123.181449 =	16.999040
652		.002500 x	153.400939 =	.383502
113		.255000 x	24.769248 =	6.316158

T.E =

6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	123.181449 =	20.324939
652		.003000 x	153.400939 =	.460203
111		.170000 x	16.829739 =	2.861056
113		.255000 x	24.769248 =	6.316158
112		.340000 x	18.705943 =	6.360021

T.E =

6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	16.829739 =	3.576320
113		.297500 x	24.769248 =	7.368851
6325		.193000 x	123.181449 =	23.774020
652		.003500 x	153.400939 =	.536903
112		.382500 x	18.705943 =	7.155023

T.E =

6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	24.769248 =	21.053861

T.E =

6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	143.938776 =	135.302449
6303		1.880000 x	23.821707 =	44.784809

T.E =

6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	143.938776 =	105.075306

T.E =

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	143.938776 =	135.302449

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	143.938776 =	105.075306

			T.E =	
6742.1	6742.1			
6303		3.040000 x	23.821707 =	72.417989
6328		.400000 x	171.659229 =	68.663692

			T.E =	141.081681
6742.10	6742.10			
6303		7.520000 x	23.821707 =	179.139237
6328		2.110000 x	171.659229 =	362.200973

			T.E =	541.340210
6742.11	6742.11			
6303		8.030000 x	23.821707 =	191.288307
6328		2.430000 x	171.659229 =	417.131926

			T.E =	608.420234
6742.2	6742.2			
6303		3.500000 x	23.821707 =	83.375975
6328		.500000 x	171.659229 =	85.829615

			T.E =	169.205589
6742.3	6742.3			
6303		4.020000 x	23.821707 =	95.763262
6328		.630000 x	171.659229 =	108.145314

			T.E =	203.908576
6742.4	6742.4			
6303		4.530000 x	23.821707 =	107.912333
6328		.800000 x	171.659229 =	137.327383

			T.E =	245.239716

6742.5	6742.5			
6303		5.000000 x	23.821707 =	119.108535
6328		.950000 x	171.659229 =	163.076268

			T.E =	282.184803
6742.6	6742.6			
6303		5.530000 x	23.821707 =	131.734040
6328		1.170000 x	171.659229 =	200.841298

			T.E =	332.575338
6742.7	6742.7			
6303		6.040000 x	23.821707 =	143.883110
6328		1.410000 x	171.659229 =	242.039513

			T.E =	385.922623
6742.8	6742.8			
6303		6.520000 x	23.821707 =	155.317530
6328		1.610000 x	171.659229 =	276.371359

			T.E =	431.688888
6742.9	6742.9			
6303		7.040000 x	23.821707 =	167.704817
6328		1.880000 x	171.659229 =	322.719351

			T.E =	490.424168
6743.1	6743.1			
6303		3.040000 x	23.821707 =	72.417989
6328		.440000 x	171.659229 =	75.530061

			T.E =	147.948050
6743.10	6743.10			
6303		7.520000 x	23.821707 =	179.139237
6328		2.240000 x	171.659229 =	384.516673

			T.E =	563.655910
6743.11	6743.11			
6303		8.030000 x	23.821707 =	191.288307
6328		2.570000 x	171.659229 =	441.164219

			T.E =	632.452526

6743.12	6743.12			
6303		3.040000 x	23.821707 =	72.417989
6328		.750000 x	171.659229 =	128.744422

			T.E =	201.162411
6743.13	6743.13			
6303		3.500000 x	23.821707 =	83.375975
6328		.910000 x	171.659229 =	156.209898

			T.E =	239.585873
6743.14	6743.14			
6303		4.020000 x	23.821707 =	95.763262
6328		1.090000 x	171.659229 =	187.108560

			T.E =	282.871822
6743.15	6743.15			
6303		4.530000 x	23.821707 =	107.912333
6328		1.300000 x	171.659229 =	223.156998

			T.E =	331.069330
6743.16	6743.16			
6303		5.000000 x	23.821707 =	119.108535
6328		1.550000 x	171.659229 =	266.071805

			T.E =	385.180340
6743.17	6743.17			
6303		5.530000 x	23.821707 =	131.734040
6328		1.850000 x	171.659229 =	317.569574

			T.E =	449.303613
6743.2	6743.2			
6303		3.500000 x	23.821707 =	83.375975
6328		.550000 x	171.659229 =	94.412576

			T.E =	177.788550
6743.3	6743.3			
6303		4.020000 x	23.821707 =	95.763262
6328		.690000 x	171.659229 =	118.444868

			T.E =	214.208130

6743.4	6743.4				
6303		4.530000 x	23.821707 =	107.912333	
6328		.860000 x	171.659229 =	147.626937	

			T.E =	255.539270	
6743.5	6743.5				
6303		5.000000 x	23.821707 =	119.108535	
6328		1.020000 x	171.659229 =	175.092414	

			T.E =	294.200949	
6743.6	6743.6				
6303		5.530000 x	23.821707 =	131.734040	
6328		1.260000 x	171.659229 =	216.290629	

			T.E =	348.024668	
6743.7	6743.7				
6303		6.040000 x	23.821707 =	143.883110	
6328		1.500000 x	171.659229 =	257.488844	

			T.E =	401.371954	
6743.8	6743.8				
6303		6.520000 x	23.821707 =	155.317530	
6328		1.720000 x	171.659229 =	295.253874	

			T.E =	450.571404	
6743.9	6743.9				
6303		7.040000 x	23.821707 =	167.704817	
6328		2.000000 x	171.659229 =	343.318458	

			T.E =	511.023275	
6744	6744				
111		2.125000 x	16.829739 =	35.763195	
111		4.250000 x	16.829739 =	71.526391	
112		2.125000 x	18.705943 =	39.750129	
113		2.125000 x	24.769248 =	52.634652	
113		2.125000 x	24.769248 =	52.634652	

			T.E =	252.309019	

6751	6751				
234.2		.400000 x	.719000 =	.287600	
235		.650000 x	.553000 =	.359450	
113		.170000 x	24.769248 =	4.210772	
113		.051000 x	24.769248 =	1.263232	

			T.E =	6.121054	
6752	6752				
237		1.050000 x	1.060000 =	1.113000	
113		.017000 x	24.769248 =	.421077	
111		.025500 x	16.829739 =	.429158	

			T.E =	1.963236	
6753	6753				
237		1.050000 x	1.060000 =	1.113000	
112		.085000 x	18.705943 =	1.590005	
113		.085000 x	24.769248 =	2.105386	

			T.E =	4.808391	
6754	6754				
237.1		1.000000 x	1.200000 =	1.200000	
112		.017000 x	18.705943 =	.318001	
111		.051000 x	16.829739 =	.858317	
113		.212500 x	24.769248 =	5.263465	

			T.E =	7.639783	
6801	6801				
232		.700000 x	1.785000 =	1.249500	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	24.769248 =	63.161582	
112		1.700000 x	18.705943 =	31.800103	
111		.850000 x	16.829739 =	14.305278	

			T.E =	112.836464	
6802	6802				
231		15.000000 x	.695000 =	10.425000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	24.769248 =	63.161582	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	16.829739 =	71.526391	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	153.400939 =	1.840811
111		.510000 x	16.829739 =	8.583167
113		.680000 x	24.769248 =	16.843089

			T.E =	34.101067
6804	6804			
111		.510000 x	16.829739 =	8.583167
652		.120000 x	153.400939 =	18.408113
113		.680000 x	24.769248 =	16.843089

			T.E =	43.834368
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	153.400939 =	.306802
2522		.005000 x	165.305929 =	.826530
113		.340000 x	24.769248 =	8.421544
111		.340000 x	16.829739 =	5.722111

			T.E =	19.336987
6806	6806			
111		.340000 x	16.829739 =	5.722111
113		.340000 x	24.769248 =	8.421544
6326		.005000 x	143.938776 =	.719694
652		.002000 x	153.400939 =	.306802

			T.E =	15.170151
6807	6807			
111		1.700000 x	16.829739 =	28.610556

			T.E =	28.610556
6808	6808			
111		.425000 x	16.829739 =	7.152639

			T.E =	7.152639
6810	6810			
241		2.600000 x	7.050000 =	18.330000
113		1.062500 x	24.769248 =	26.317326
113		.850000 x	24.769248 =	21.053861
111		1.062500 x	16.829739 =	17.881598
241		1.300000 x	7.050000 =	9.165000

			T.E =	92.747784

6811	6811			
236		6.430000 x	.523000 =	3.362890
113		.850000 x	24.769248 =	21.053861
113		3.400000 x	24.769248 =	84.215443
241		3.150000 x	7.050000 =	22.207500

T.E = 130.839694

6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
243		11.900000 x	1.900000 =	22.610000
6324		.250000 x	118.236449 =	29.559112
113		4.250000 x	24.769248 =	105.269304
111		.425000 x	16.829739 =	7.152639

AΘΡΟΙΣΜΑ = 179.396055
T.E = .262500 x 179.396055 = 47.091465

7001	7001			
7001 Α		1.000000 x	.239893 =	.239893
7001 Β		1.000000 x	.771775 =	.771775
7001 Ε		1.000000 x	.813967 =	.813967
7001 Δ		1.000000 x	.317663 =	.317663
7001 Γ		1.000000 x	.984543 =	.984543

AΘΡΟΙΣΜΑ = 3.127841

T.E = 3.597017

7002	7002			
560		.005104 x	637.565782 =	3.254136

T.E = 3.254136

7003	7003			
7003 Α		1.000000 x	.119946 =	.119946
7003 Β		1.000000 x	.593874 =	.593874
7003 Δ		1.000000 x	.785406 =	.785406
7003 Γ		1.000000 x	.557965 =	.557965

AΘΡΟΙΣΜΑ = 2.057191

T.E = 2.262910

7004	7004			
561		.003250 x	831.220782 =	2.701468

T.E = 2.701468

7005	7005			
7005 Α		1.000000 x	.119946 =	.119946
7005 Γ		1.000000 x	.296937 =	.296937
7005 Ε		1.000000 x	.785406 =	.785406
7005 Δ		1.000000 x	.557965 =	.557965
7005 Β		1.000000 x	1.039279 =	1.039279

			ΑΘΡΟΙΣΜΑ =	2.799533

			T.E =	3.079486
7006	7006			
561		.001723 x	831.220782 =	1.432193
561		.000862 x	831.220782 =	.716512
561		.000812 x	831.220782 =	.674951

			T.E =	2.823657
7007	7007			
213		.100000 x	1.895000 =	.189500
116		.280000 x	24.152261 =	6.762633
550		.003500 x	1,143.227818 =	4.001297
518		.001750 x	892.000635 =	1.561001
502		.000583 x	797.093484 =	.464706

			T.E =	12.979137
7008	7008			
111		.021000 x	16.829739 =	.353425
112		.210000 x	18.705943 =	3.928248
503		.001750 x	897.479484 =	1.570589
507		.000875 x	941.320186 =	.823655
558		.000972 x	1,102.536186 =	1.071665
7007		1.100000 x	12.979137 =	14.277051

			T.E =	22.024633
7009	7009			
560		.006417 x	637.565782 =	4.091260

			T.E =	4.091260
7010	7010			
7010 Α		1.000000 x	.347299 =	.347299
7010 Β		1.000000 x	.521500 =	.521500
7010 Ε		1.000000 x	.967409 =	.967409
7010 Δ		1.000000 x	.317663 =	.317663
7010 Γ		1.000000 x	.557965 =	.557965

			ΑΘΡΟΙΣΜΑ =	2.711836

			T.E =	3.118611

7011	7011			
502		.001367 x	797.093484 =	1.089627
563		.001367 x	.000000 =	.000000
558		.000729 x	1,102.536186 =	.803749
558		.000729 x	1,102.536186 =	.803749
554		.000438 x	32.769000 =	.014353
502		.000700 x	797.093484 =	.557965
503		.000438 x	897.479484 =	.393096

			ΑΘΡΟΙΣΜΑ =	3.662539

			T.E =	
7012	7012			
7008		1.000000 x	22.024633 =	22.024633

			ΑΘΡΟΙΣΜΑ =	22.024633

			T.E =	24.227096
7013	7013			
7003		1.000000 x	2.262910 =	2.262910

			ΑΘΡΟΙΣΜΑ =	2.262910

			T.E =	2.489201
7014	7014			
7005		1.000000 x	3.079486 =	3.079486

			ΑΘΡΟΙΣΜΑ =	3.079486

			T.E =	3.387435
7015	7015			
111		.056000 x	16.829739 =	.942465
X 630.1		.300000 x	1.635255 =	.490577
7001		.900000 x	3.597017 =	3.237315
X 630		.300000 x	1.414717 =	.424415

			T.E =	5.094772
7016.9	7016.9			
7016.4		1.000000 x	126.292643 =	126.292643
7016.6		1.000000 x	37.887793 =	37.887793
7016.7		1.000000 x	85.831669 =	85.831669
7016.8		1.000000 x	126.323165 =	126.323165
7016.5		1.000000 x	25.258529 =	25.258529

			T.E =	401.593799

7017.8	7017.8				
7017.3		1.000000 x	92.690170 =		92.690170
7017.4		1.000000 x	18.538034 =		18.538034
7017.5		1.000000 x	33.368461 =		33.368461
7017.7		1.000000 x	63.161582 =		63.161582
7017.6		1.000000 x	85.831669 =		85.831669
			T.E =		293.589916
7018	7018				
233.2		1.150000 x	.560100 =		.644115
113		.051000 x	24.769248 =		1.263232
			AΘΡΟΙΣΜΑ =		1.907347
			T.E =		2.098081
7019	7019				
7019 A6		1.000000 x	206.663467 =		206.663467
7019 A7		1.000000 x	20.666347 =		20.666347
			T.E =		227.329814
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	227.329814 =		227.329814
			T.E =		221.429814
7020	7020				
213		.150000 x	1.895000 =		.284250
116		.980000 x	24.152261 =		23.669216
7020.2		.010938 x	3,640.446871 =		39.819208
			T.E =		63.772674
7020.1	7020.1				
570.2		.350000 x	156.045184 =		54.615814
571.2		.070000 x	258.945256 =		18.126168
571.1		.280000 x	403.776182 =		113.057331
			AΘΡΟΙΣΜΑ =		185.799313
	T.E =	.015625 x	185.799313 =		2.903114
7021	7021				
213		.150000 x	1.895000 =		.284250
116		1.120000 x	24.152261 =		27.050532
7021.2		.014583 x	3,124.727045 =		45.567894
			T.E =		72.902677

7021.1	7021.1			
570.2		.350000 x	156.045184 =	54.615814
571.2		.070000 x	258.945256 =	18.126168
571.1		.280000 x	403.776182 =	113.057331

			ΑΘΡΟΙΣΜΑ =	185.799313
	T.E =	.020833 x	185.799313 =	3.870757

7022	7022			
213		.150000 x	1.895000 =	.284250
116		1.400000 x	24.152261 =	33.813165
7022.2		.020000 x	2,837.803565 =	56.756071

			T.E =	90.853487
7022.1	7022.1			
570.2		.350000 x	156.045184 =	54.615814
571.2		.070000 x	258.945256 =	18.126168
571.1		.280000 x	403.776182 =	113.057331

			ΑΘΡΟΙΣΜΑ =	185.799313
	T.E =	.028571 x	185.799313 =	5.308472

7023	7023			
398.2		1.050000 x	42.300000 =	44.415000
111		.425000 x	16.829739 =	7.152639
116		.850000 x	24.152261 =	20.529422
550		.012143 x	1,143.227818 =	13.882215

			T.E =	85.979276
7024	7024			
398.3		1.050000 x	48.000000 =	50.400000
116		.850000 x	24.152261 =	20.529422
550		.020238 x	1,143.227818 =	23.136645
111		.425000 x	16.829739 =	7.152639

			T.E =	101.218706
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	153.400939 =	.153401
550		.020238 x	1,143.227818 =	23.136645
116		.850000 x	24.152261 =	20.529422
112		.425000 x	18.705943 =	7.950026
111		.425000 x	16.829739 =	7.152639
233		6.180000 x	.528700 =	3.267366
398.4		1.000000 x	64.000000 =	64.000000

			T.E =	126.200118

7026	7026				
398.5		125.400000 x	5.780000 =		724.812000
236		16.808000 x	.523000 =		8.790584
113		.909160 x	24.769248 =		22.519210
113		3.400000 x	24.769248 =		84.215443
6310		12.350000 x	1.607828 =		19.856676

			AΘΡΟΙΣΜΑ =		860.193913
	T.E =	.007259 x	860.193913 =		6.244148

7027	7027				
236		1.100000 x	.523000 =		.575300
113		.059500 x	24.769248 =		1.473770

			T.E =		2.049070
7028	7028				
111		.144500 x	16.829739 =		2.431897
6751		.120000 x	6.121054 =		.734526
6751		.600000 x	6.121054 =		3.672632
111		.425000 x	16.829739 =		7.152639
112		.144500 x	18.705943 =		2.703009

			AΘΡΟΙΣΜΑ =		16.694704

			T.E =		19.198910
7029	7029				
568.1		.021250 x	2,989.728120 =		63.531723
569.2		.021250 x	594.156584 =		12.625827
570.2		.021250 x	156.045184 =		3.315960
571.2		.021250 x	258.945256 =		5.502587

			T.E =		84.976097
7030	7030				
398.6		.015385 x	330.000000 =		5.077050
572		.026563 x	856.925291 =		22.762507

			AΘΡΟΙΣΜΑ =		27.839557

			T.E =		38.975379
7031	7031				
573		.106250 x	1,050.076931 =		111.570674

			AΘΡΟΙΣΜΑ =		111.570674

			T.E =		128.306275
7032	7032				
573		.212500 x	1,050.076931 =		223.141348

			AΘΡΟΙΣΜΑ =		223.141348

			T.E =		290.083752

7101.1	7101.1			
398.1		15.000000 x	.225000 =	3.375000
574		.132813 x	3,421.474593 =	454.416305
T 630		.105000 x	1.717870 =	.180376
T 630.1		.105000 x	1.985667 =	.208495
567		.132813 x	354.958380 =	47.143087

			AΘΡΟΙΣΜΑ =	505.323264

			T.E =	520.482962
7101.2	7101.2			
398.1		15.000000 x	.225000 =	3.375000
574		.148750 x	3,421.474593 =	508.944346
T 630.1		.105000 x	1.985667 =	.208495
T 630		.105000 x	1.717870 =	.180376
567		.148750 x	354.958380 =	52.800059

			AΘΡΟΙΣΜΑ =	565.508276

			T.E =	582.473524
7101.3	7101.3			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.985667 =	.208495
T 630		.105000 x	1.717870 =	.180376
574		.159375 x	3,421.474593 =	545.297513
567		.159375 x	354.958380 =	56.571492

			AΘΡΟΙΣΜΑ =	605.632876

			T.E =	623.801863
7101.4	7101.4			
398.1		15.000000 x	.225000 =	3.375000
567		.170000 x	354.958380 =	60.342925
574		.170000 x	3,421.474593 =	581.650681
T 630.1		.105000 x	1.985667 =	.208495
T 630		.105000 x	1.717870 =	.180376

			AΘΡΟΙΣΜΑ =	645.757477

			T.E =	665.130201
7101.5	7101.5			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.985667 =	.208495
567		.191250 x	354.958380 =	67.885790
T 630		.105000 x	1.717870 =	.180376
574		.191250 x	3,421.474593 =	654.357016

			AΘΡΟΙΣΜΑ =	726.006677

			T.E =	747.786878

7102.1	7102.1				
398.1		15.000000 x	.225000 =		3.375000
567		.302813 x	354.958380 =		107.486012
T 630		.105000 x	1.717870 =		.180376
T 630.1		.105000 x	1.985667 =		.208495
574		.302813 x	3,421.474593 =		1,036.066986
				ΑΘΡΟΙΣΜΑ =	1,147.316869
				T.E =	1,181.736375
7102.2	7102.2				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.985667 =		.208495
T 630		.105000 x	1.717870 =		.180376
574		.329375 x	3,421.474593 =		1,126.948194
567		.329375 x	354.958380 =		116.914416
				ΑΘΡΟΙΣΜΑ =	1,247.626482
				T.E =	1,285.055276
7102.3	7102.3				
398.1		15.000000 x	.225000 =		3.375000
567		.361250 x	354.958380 =		128.228715
T 630		.105000 x	1.717870 =		.180376
T 630.1		.105000 x	1.985667 =		.208495
574		.361250 x	3,421.474593 =		1,236.007697
				ΑΘΡΟΙΣΜΑ =	1,368.000283
				T.E =	1,409.040291
7102.4	7102.4				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.985667 =		.208495
T 630		.105000 x	1.717870 =		.180376
574		.403750 x	3,421.474593 =		1,381.420367
567		.403750 x	354.958380 =		143.314446
				ΑΘΡΟΙΣΜΑ =	1,528.498684
				T.E =	1,574.353645
7102.5	7102.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.985667 =		.208495
T 630		.105000 x	1.717870 =		.180376
567		.446250 x	354.958380 =		158.400177
574		.446250 x	3,421.474593 =		1,526.833037
				ΑΘΡΟΙΣΜΑ =	1,688.997086
				T.E =	1,739.666998

7103	7103			
113		3.400000 x	24.769248 =	84.215443
113		.283333 x	24.769248 =	7.017945
115		.070833 x	19.931416 =	1.411802
575		.106250 x	780.198461 =	82.896086

			T.E =	175.541277
7104	7104			
113		1.700000 x	24.769248 =	42.107722
576		.106250 x	7.282000 =	.773713
567		.106250 x	354.958380 =	37.714328

			T.E =	80.595762
7105	7105			
111		.850000 x	16.829739 =	14.305278
113		.850000 x	24.769248 =	21.053861
576		.106250 x	7.282000 =	.773713
567		.106250 x	354.958380 =	37.714328

			T.E =	73.847179
7106.1	7106.1			
577		.265625 x	730.216890 =	193.963861

			AΘΡΟΙΣΜΑ =	193.963861

			T.E =	203.662054
7106.2	7106.2			
577		.297500 x	730.216890 =	217.239525

			AΘΡΟΙΣΜΑ =	217.239525

			T.E =	228.101501
7106.3	7106.3			
577		.350625 x	730.216890 =	256.032297

			AΘΡΟΙΣΜΑ =	256.032297

			T.E =	268.833912
7106.4	7106.4			
577		.425000 x	730.216890 =	310.342178

			AΘΡΟΙΣΜΑ =	310.342178

			T.E =	325.859287

7106.5	7106.5			
577		.531250 x	730.216890 =	387.927723

			ΑΘΡΟΙΣΜΑ =	387.927723

			T.E =	407.324109
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	203.662054 =	203.662054

			T.E =	244.462054
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	228.101501 =	228.101501

			T.E =	268.901501
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	268.833912 =	268.833912

			T.E =	309.633912
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	325.859287 =	325.859287

			T.E =	366.659287
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	407.324109 =	407.324109

			T.E =	448.124109
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,421.474593 =	181.765838

			T.E =	318.535838
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,421.474593 =	181.765838

			T.E =	358.645838

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,421.474593 =		181.765838

			T.E =		344.079938
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,421.474593 =		181.765838

			T.E =		331.525838
7112	7112				
398.13		1.300000 x	9.400000 =		12.220000
577		.010625 x	730.216890 =		7.758554

			T.E =		19.978554
7113	7113				
241		1.200000 x	7.050000 =		8.460000
574		.001063 x	3,421.474593 =		3.637027

			T.E =		12.097027
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	730.216890 =		38.792772

			T.E =		42.482772
7115	7115				
574		.026563 x	3,421.474593 =		90.884630

			T.E =		90.884630
7116	7116				
577		.170000 x	730.216890 =		124.136871

			T.E =		124.136871
7117	7117				
574		.001063 x	3,421.474593 =		3.637027

			T.E =		3.637027

7118.1	7118.1				
111		27.200000 x	16.829739 =	457.768901	
578		.850000 x	659.773633 =	560.807588	
574.1		.425000 x	2,214.115624 =	940.999140	

			T.E =	1,959.575629	
7118.2	7118.2				
111		40.800000 x	16.829739 =	686.653351	
574.1		.850000 x	2,214.115624 =	1,881.998280	
578		.850000 x	659.773633 =	560.807588	

			T.E =	3,129.459220	
7119.1	7119.1				
111		13.600000 x	16.829739 =	228.884450	
577.1		.255000 x	447.415624 =	114.090984	

			T.E =	342.975435	
7119.2	7119.2				
111		13.600000 x	16.829739 =	228.884450	
577.1		.595000 x	447.415624 =	266.212296	

			T.E =	495.096747	
7120.1	7120.1				
111		10.200000 x	16.829739 =	171.663338	
575.1		.425000 x	240.781328 =	102.332064	
578		.425000 x	659.773633 =	280.403794	

			T.E =	554.399196	
7120.2	7120.2				
111		17.000000 x	16.829739 =	286.105563	
578		1.275000 x	659.773633 =	841.211382	
575.1		1.275000 x	240.781328 =	306.996193	

			T.E =	1,434.313138	
7121.1	7121.1				
111		6.800000 x	16.829739 =	114.442225	
576.1		.425000 x	6.620000 =	2.813500	
578		.425000 x	659.773633 =	280.403794	

			T.E =	397.659519	

7121.2 7121.2

111	6.800000 x	16.829739 =	114.442225
576.1	.425000 x	6.620000 =	2.813500
578	.425000 x	659.773633 =	280.403794

T.E = 397.659519

7122 7122

398.1	15.000000 x	.225000 =	3.375000
T 630	.105000 x	1.717870 =	.180376
T 630.1	.105000 x	1.985667 =	.208495
567	.122188 x	354.958380 =	43.371655
580	.122188 x	1,713.205393 =	209.333141

AΘΡΟΙΣΜΑ = 256.468666

T.E = 264.162726

7123 7123

398.1	15.000000 x	.225000 =	3.375000
T 630.1	.105000 x	1.985667 =	.208495
T 630	.105000 x	1.717870 =	.180376
580	.286875 x	1,713.205393 =	491.475797
567	.286875 x	354.958380 =	101.828685

AΘΡΟΙΣΜΑ = 597.068354

T.E = 614.980404

7124 7124

398.1	15.000000 x	.225000 =	3.375000
567	.063750 x	354.958380 =	22.628597
T 630	.105000 x	1.717870 =	.180376
T 630.1	.105000 x	1.985667 =	.208495
580	.063750 x	1,713.205393 =	109.216844

T.E = 135.609312

7125 7125

398.1	15.000000 x	.225000 =	3.375000
T 630.1	.105000 x	1.985667 =	.208495
567	.127500 x	354.958380 =	45.257193
T 630	.105000 x	1.717870 =	.180376
580	.127500 x	1,713.205393 =	218.433688

T.E = 267.454752

7126 7126

398.16	1.000000 x	62.420000 =	62.420000
580	.053125 x	1,713.205393 =	91.014037

T.E = 153.434037

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,713.205393 =		27.305068
				T.E =	115.862368
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,713.205393 =		27.305068
				T.E =	95.878768
7129	7129				
6751		1.000000 x	6.121054 =		6.121054
				T.E =	6.121054