

. .& .

3

μ

2

μ

2012

\*\*\*\*\*

\*\*\*\*\*

021	2.670000
111	15.643441
114	23.647167
117	16.609513
118	10.001019
150	.074800
211	1.271500
214	4.550000
242	4.500000
402	380.180000
405	206.720000
410	116.530000
428	437.840000
450	115.120000

502	502			
211		80.000000 x	1.271500 =	101.720000
402		1.000000 x	380.180000 =	380.180000
214		7.000000 x	4.550000 =	31.850000
114		8.000000 x	23.647167 =	189.177336
118		4.000000 x	10.001019 =	40.004076
			-----	
			=	742.931412
			-----	
			H. . =	817.224553
503	503			
211		110.000000 x	1.271500 =	139.865000
214		10.000000 x	4.550000 =	45.500000
428		1.000000 x	437.840000 =	437.840000
118		4.000000 x	10.001019 =	40.004076
114		8.000000 x	23.647167 =	189.177336
			-----	
			=	852.386412
			-----	
			H. . =	937.625053
506	506			
211		95.000000 x	1.271500 =	120.792500
405		1.000000 x	206.720000 =	206.720000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.647167 =	189.177336
242		2.500000 x	4.500000 =	11.250000
214		6.000000 x	4.550000 =	27.300000
			-----	
			=	635.247988
			-----	
			H. . =	698.772787
510	510			
211		80.000000 x	1.271500 =	101.720000
214		5.000000 x	4.550000 =	22.750000
117		8.000000 x	16.609513 =	132.876104
410		1.000000 x	116.530000 =	116.530000
			-----	
			=	373.876104
			-----	
			H. . =	411.263714
550	550			
211		80.000000 x	1.271500 =	101.720000
117		8.000000 x	16.609513 =	132.876104
450		1.000000 x	115.120000 =	115.120000
214		5.000000 x	4.550000 =	22.750000
			-----	
			=	372.466104
			-----	
			H. . =	409.712714
1110	1110			
503		.200000 x	937.625053 =	187.525011
			-----	
			T.E =	187.525011

1120	1120			
503		.100000 x	937.625053 =	93.762505
		-----		
			T.E =	93.762505
1200	1200			
502		.050000 x	817.224553 =	40.861228
		-----		
			T.E =	40.861228
1310	1310			
503		.001500 x	937.625053 =	1.406438
		-----		
			T.E =	1.406438
1320	1320			
502		.002400 x	817.224553 =	1.961339
		-----		
			T.E =	1.961339
2110	2110			
506		.002800 x	698.772787 =	1.956564
		-----		
			T.E =	1.956564
2120	2120			
506		.002500 x	698.772787 =	1.746932
		-----		
			T.E =	1.746932
2211	2211			
111		.050000 x	15.643441 =	.782172
		-----		
			T.E =	.782172
2212	2212			
111		.070000 x	15.643441 =	1.095041
		-----		
			T.E =	1.095041
2221	2221			
111		.100000 x	15.643441 =	1.564344
		-----		
			T.E =	1.564344
2222	2222			
111		.160000 x	15.643441 =	2.502951
		-----		
			T.E =	2.502951

3112	3112			
111		.100000 x	15.643441 =	1.564344
		-----		
			T.E =	1.564344
3113	3113			
111		.200000 x	15.643441 =	3.128688
		-----		
			T.E =	3.128688
3121	3121			
111		.050000 x	15.643441 =	.782172
		-----		
			T.E =	.782172
3122	3122			
111		.100000 x	15.643441 =	1.564344
		-----		
			T.E =	1.564344
3210	3210			
111		.100000 x	15.643441 =	1.564344
550		.008000 x	409.712714 =	3.277702
		-----		
			T.E =	4.842046
3221	3221			
111		.040000 x	15.643441 =	.625738
		-----		
			T.E =	.625738
3222	3222			
111		.100000 x	15.643441 =	1.564344
		-----		
			T.E =	1.564344
4100	4100			
111		.035000 x	15.643441 =	.547520
		-----		
			T.E =	.547520
4200	4200			
111		.025000 x	15.643441 =	.391086
		-----		
			T.E =	.391086

2 μ

2012

. 6  
μ/ 09/01/2014

4300

4300

021  
510  
111

.015000 x  
.000600 x  
.008000 x

2.670000 =  
411.263714 =  
15.643441 =

.040050  
.246758  
.125148

-----  
T.E =

.411956