

ΑΤΥΕ

Αναλυτικά Τιμολόγια Υδραυλικών Έργων

3ο Τρίμηνο του 2010

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.949547
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.047200
212	1.300000
213	1.949500
214	3.930000
221	.099900
221.1	.089500
222	.116200
222.1	.104900
223	.119300
223.1	.104900
224	.070000
231	.775000
232	1.900000
233	.583300
233.1	.583300
233.2	.639200
233.3	7.950000
234	.835300
234.1	1.003300
234.2	.901300
234.3	.944000
235	.643000
236	.612000
237	1.110000
237.1	1.260000
241	7.050000
242	5.000000
243	2.100000
244	2.590000
251	290.000000
252	290.000000
252.1	
252.2	
261	15.100000
261.1	13.500000
261.2	20.700000
261.3	
261.4	
262	26.300000
262.1	
263	32.400000
263.1	
263.2	46.700000
263.3	
264	64.100000
264.1	
265	115.100000
265.1	
271	206.300000
271.1	

281	21.300000
281.1	17.600000
281.2	26.300000
282	30.000000
283	36.300000
283.1	55.500000
284	75.400000
301	4.060000
302	6.700000
324	.580000
326	1.310000
327	.540000
360.1	
360.2	2.220000
361.1	12.320000
361.10	
361.11	
361.12	
361.13	
361.14	
361.2	15.940000
361.3	20.220000
361.4	
361.5	38.600000
361.6	51.610000
361.7	79.690000
361.8	
361.9	
362.1	
362.10	
362.11	
362.12	
362.13	
362.14	
362.2	
362.3	
362.4	
362.5	
362.6	
362.7	
362.8	
362.9	
363.1	
363.10	
363.11	
363.12	
363.13	
363.14	
363.15	
363.16	
363.17	
363.18	
363.19	
363.2	
363.20	
363.21	
363.22	
363.23	
363.24	

363.25
363.26
363.27
363.28
363.3
363.4
363.5
363.6
363.7
363.8
363.9
364.1
364.10
364.11
364.12
364.13
364.14
364.2
364.3
364.4
364.5
364.6
364.7
364.8
364.9
365.1
365.10
365.11
365.12
365.13
365.14
365.15
365.16
365.17
365.18
365.19
365.2
365.20
365.21
365.22
365.23
365.24
365.25
365.26
365.27
365.28
365.3
365.4
365.5
365.6
365.7
365.8
365.9
366.1
366.10
366.11
366.12
366.13
366.14

366.15
366.16
366.17
366.18
366.19
366.2
366.20
366.21
366.22
366.23
366.24
366.25
366.26
366.27
366.28
366.3
366.4
366.5
366.6
366.7
366.8
366.9
367.1
367.10
367.11
367.12
367.13
367.14
367.15
367.16
367.17
367.18
367.19
367.2
367.20
367.21
367.22
367.23
367.24
367.25
367.26
367.27
367.28
367.29
367.3
367.30
367.31
367.32
367.33
367.34
367.35
367.36
367.37
367.38
367.39
367.4
367.40
367.41
367.42

367.43
367.44
367.45
367.46
367.47
367.48
367.49
367.5
367.50
367.51
367.52
367.53
367.54
367.55
367.56
367.6
367.7
367.8
367.9
368.1
368.10
368.11
368.12
368.13
368.14
368.15
368.16
368.17
368.18
368.19
368.2
368.20
368.21
368.22
368.23
368.24
368.25
368.26
368.27
368.28
368.29
368.3
368.30
368.4
368.5
368.6
368.7
368.8
368.9
369.1
369.10
369.11
369.12
369.13
369.14
369.15
369.16
369.17
369.18

369.19	
369.2	
369.20	
369.21	
369.22	
369.23	
369.24	
369.25	
369.26	
369.27	
369.28	
369.29	
369.3	
369.30	
369.4	
369.5	
369.6	
369.7	
369.8	
369.9	
370.1	
370.10	
370.11	
370.12	
370.13	
370.14	
370.15	
370.16	
370.17	
370.18	
370.19	
370.2	
370.20	
370.21	
370.22	
370.23	
370.24	
370.3	
370.4	
370.5	
370.6	
370.7	
370.8	
370.9	
371.1	5.080000
371.2	8.050000
371.3	10.460000
371.4	16.260000
371.5	20.580000
371.6	32.340000
371.7	41.610000
371.8	52.890000
371.9	66.370000
372.1	8.000000
372.2	12.580000
372.3	16.500000
372.4	25.550000
372.5	32.410000
372.6	51.220000

372.7	65.050000
372.8	82.710000
372.9	104.700000
373.1	11.900000
373.2	18.780000
373.3	24.500000
373.4	38.310000
373.5	48.180000
373.6	76.480000
373.7	97.270000
373.8	123.440000
373.9	156.680000
374.1	
374.2	
374.3	
374.4	
374.5	
374.6	
374.7	
374.8	
375.1	8.510000
375.10	20.150000
375.11	27.290000
375.12	34.560000
375.13	10.160000
375.14	17.510000
375.2	13.330000
375.3	20.790000
375.4	33.650000
375.5	42.800000
375.6	54.230000
375.7	87.910000
375.8	11.640000
375.9	14.980000
376.1	88.960000
376.10	487.600000
376.11	528.600000
376.12	88.960000
376.13	98.960000
376.14	109.782000
376.15	140.650000
376.16	176.880000
376.17	224.520000
376.18	302.640000
376.19	336.580000
376.2	98.960000
376.20	400.990000
376.21	487.600000
376.22	528.600000
376.3	109.780000
376.4	140.650000
376.5	176.880000
376.6	224.520000
376.7	302.840000
376.8	336.580000
376.9	400.990000
377.1	
377.2	
377.3	

377.4	
377.5	
377.6	
377.7	
377.8	
377.9	
378.1	69.000000
378.2	106.000000
378.3	136.000000
378.4	188.000000
378.5	231.000000
378.6	
378.7	338.000000
378.8	512.000000
378.9	724.000000
379.1	
379.2	
379.3	
379.4	1,907.550000
379.5	
379.6	
379.7	
379.8	
379.9	7,395.450000
380.1	396.000000
380.2	502.000000
380.3	583.000000
380.4	1,056.000000
380.5	1,420.000000
380.6	1,966.000000
384.1	537.050000
384.2	
384.3	
384.4	
384.5	
384.6	
384.7	
384.8	
384.9	
385.1	
385.2	
385.3	
385.4	
385.5	
386.1	
386.10	
386.11	
386.12	
386.13	
386.14	
386.15	
386.16	
386.17	
386.18	
386.19	
386.2	
386.20	
386.21	
386.22	

386.23	
386.24	
386.25	
386.26	
386.27	
386.28	
386.29	
386.3	
386.30	108,702.000000
386.31	
386.32	
386.33	
386.34	
386.35	
386.36	
386.37	
386.38	
386.39	
386.4	
386.40	73,850.000000
386.41	
386.42	
386.43	
386.44	
386.45	
386.46	
386.47	
386.48	
386.49	
386.5	
386.50	
386.51	
386.52	
386.53	128,861.000000
386.54	
386.55	
386.56	
386.57	
386.58	
386.59	
386.6	
386.60	
386.61	
386.62	
386.63	
386.64	147,712.000000
386.65	
386.66	
386.67	
386.68	
386.69	
386.7	
386.70	
386.71	
386.72	
386.73	
386.74	
386.75	
386.76	

386.77	
386.78	
386.79	
386.8	
386.80	
386.81	
386.82	
386.83	
386.9	24,668.000000
387.1	
387.2	
387.3	20,690.000000
387.4	
387.5	
387.6	
387.7	
389.1	
389.2	
389.3	
389.4	6,406.000000
389.5	
389.6	
389.7	
389.8	
389.9	
390.1	
390.10	
390.11	
390.12	
390.13	
390.14	5,412.000000
390.15	
390.16	
390.17	
390.18	
390.19	
390.2	
390.20	
390.21	
390.22	
390.23	
390.24	
390.25	
390.26	
390.27	
390.28	
390.29	
390.3	
390.30	
390.31	7,871.000000
390.32	
390.33	
390.34	
390.35	
390.36	
390.37	
390.38	
390.39	
390.4	

390.40	
390.41	
390.42	
390.43	
390.44	
390.45	
390.46	
390.47	
390.48	
390.49	
390.5	
390.50	
390.51	
390.52	
390.53	
390.54	
390.55	
390.56	
390.57	
390.58	
390.59	
390.6	
390.7	
390.8	
390.9	
393.1	14,767.000000
393.2	
393.3	
393.4	
396.1	1.400000
396.10	6.940000
396.11	2.560000
396.12	3.680000
396.13	1.770000
396.14	38.800000
396.2	.770000
396.3	1.680000
396.4	.980000
396.5	1.180000
396.6	1.580000
396.7	3.800000
396.8	5.120000
396.9	6.910000
397.1	7.050000
397.2	6.320000
397.4	.165000
398.1	.225000
398.10	138.730000
398.11	136.770000
398.12	176.880000
398.13	9.400000
398.14	58.610000
398.15	75.690000
398.16	62.420000
398.17	93.000000
398.2	39.000000
398.3	47.000000
398.4	63.000000
398.5	5.780000

398.6	330.000000
398.7	1,360.000000
398.8	30.750000
398.9	128.000000
401	260.720000
402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
419	4.400000
420	94.500000
421	31.630000
428	425.280000
429	75.360000
450	81.440000
451	4.730000
452	100.100000
453	
454	94.500000
455	30.380000
456	34.030000
457	444.570000
458	276.840000
459	409.940000
460	506.910000
461	232.170000
462	338.520000
463	42.540000
464	372.560000
465	99.670000
466	46.490000
467	338.520000
468	84.780000
469	84.780000
470	68.370000
471	59.250000
472	25.750000
473	16.560000
474	34.030000
475	1,913.860000
476	82.950000
477	6.750000
478	111.820000
479	179.890000
480	26.440000
481	789.180000

501	501				
401		1.000000 x	260.720000 =	260.720000	
211		50.000000 x	1.047200 =	52.360000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	

				ΑΘΡΟΙΣΜΑ =	545.962593

				Η.Δ. =	600.558852
502	502				
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.930000 =	27.510000	
211		80.000000 x	1.047200 =	83.776000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	711.649612

				Η.Δ. =	782.814573
503	503				
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.930000 =	39.300000	
114		8.000000 x	23.886192 =	191.089536	
211		110.000000 x	1.047200 =	115.192000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	810.865612

				Η.Δ. =	891.952173
504	504				
403		1.000000 x	100.390000 =	100.390000	
214		2.000000 x	3.930000 =	7.860000	
114		8.000000 x	23.886192 =	191.089536	
211		40.000000 x	1.047200 =	41.888000	

				ΑΘΡΟΙΣΜΑ =	341.227536

				Η.Δ. =	375.350290
505	505				
404		1.000000 x	206.630000 =	206.630000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
214		10.000000 x	3.930000 =	39.300000	
211		200.000000 x	1.047200 =	209.440000	

				ΑΘΡΟΙΣΜΑ =	726.467688

				Η.Δ. =	799.114457

506	506				
405		1.000000 x	200.790000 =	200.790000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		2.500000 x	5.000000 =	12.500000	
214		6.000000 x	3.930000 =	23.580000	
211		95.000000 x	1.047200 =	99.484000	

			ΑΘΡΟΙΣΜΑ =	607.451688	

			Η.Δ. =	668.196857	
507	507				
406		1.000000 x	311.770000 =	311.770000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		7.000000 x	5.000000 =	35.000000	
214		10.000000 x	3.930000 =	39.300000	
211		165.000000 x	1.047200 =	172.788000	

			ΑΘΡΟΙΣΜΑ =	829.955688	

			Η.Δ. =	912.951257	
508	508				
407		1.000000 x	53.630000 =	53.630000	
116		16.000000 x	20.419486 =	326.711776	
211		40.000000 x	1.047200 =	41.888000	
214		2.000000 x	3.930000 =	7.860000	
115		4.000000 x	21.949547 =	87.798188	
408		2.000000 x	4.400000 =	8.800000	

			ΑΘΡΟΙΣΜΑ =	526.687964	

			Η.Δ. =	579.356760	
509	509				
409		1.000000 x	122.460000 =	122.460000	
117		8.000000 x	16.777917 =	134.223336	
214		5.000000 x	3.930000 =	19.650000	
211		80.000000 x	1.047200 =	83.776000	

			ΑΘΡΟΙΣΜΑ =	360.109336	

			Η.Δ. =	396.120270	
510	510				
410		1.000000 x	113.190000 =	113.190000	
117		8.000000 x	16.777917 =	134.223336	
211		80.000000 x	1.047200 =	83.776000	
214		5.000000 x	3.930000 =	19.650000	

			ΑΘΡΟΙΣΜΑ =	350.839336	

			Η.Δ. =	385.923270	

511	511				
411		1.000000 x	26.580000 =	26.580000	
214		1.000000 x	3.930000 =	3.930000	
112		30.000000 x	17.312112 =	519.363360	
115		4.000000 x	21.949547 =	87.798188	
212		17.000000 x	1.300000 =	22.100000	

				ΑΘΡΟΙΣΜΑ =	659.771548

				Η.Δ. =	725.748703
512	512				
412		1.000000 x	2.900000 =	2.900000	
214		1.000000 x	3.930000 =	3.930000	
115		2.000000 x	21.949547 =	43.899094	
112		2.000000 x	17.312112 =	34.624224	
211		10.000000 x	1.047200 =	10.472000	

				ΑΘΡΟΙΣΜΑ =	95.825318

				Η.Δ. =	105.407850
513	513				
413		1.000000 x	4.400000 =	4.400000	
211		15.000000 x	1.047200 =	15.708000	
115		3.000000 x	21.949547 =	65.848641	
112		3.000000 x	17.312112 =	51.936336	
214		1.500000 x	3.930000 =	5.895000	

				ΑΘΡΟΙΣΜΑ =	143.787977

				Η.Δ. =	158.166775
514	514				
414		1.000000 x	6.070000 =	6.070000	
115		4.000000 x	21.949547 =	87.798188	
112		4.000000 x	17.312112 =	69.248448	
214		2.000000 x	3.930000 =	7.860000	
211		21.000000 x	1.047200 =	21.991200	

				ΑΘΡΟΙΣΜΑ =	192.967836

				Η.Δ. =	212.264620
515	515				
415		1.000000 x	8.530000 =	8.530000	
112		6.000000 x	17.312112 =	103.872672	
115		5.000000 x	21.949547 =	109.747735	
214		2.500000 x	3.930000 =	9.825000	
211		27.000000 x	1.047200 =	28.274400	

				ΑΘΡΟΙΣΜΑ =	260.249807

				Η.Δ. =	286.274788

516	516				
416		1.000000 x	13.150000 =	13.150000	
115		6.000000 x	21.949547 =	131.697282	
112		8.000000 x	17.312112 =	138.496896	
214		3.500000 x	3.930000 =	13.755000	
211		33.000000 x	1.047200 =	34.557600	

				ΑΘΡΟΙΣΜΑ =	331.656778

				Η.Δ. =	364.822456
517	517				
406		1.000000 x	311.770000 =	311.770000	
406		.400000 x	311.770000 =	124.708000	
116		8.000000 x	20.419486 =	163.355888	
115		8.000000 x	21.949547 =	175.596376	
114		8.000000 x	23.886192 =	191.089536	
113		2.000000 x	20.419486 =	40.838972	
112		16.000000 x	17.312112 =	276.993792	
111		16.000000 x	15.741598 =	251.865568	
251		.150000 x	290.000000 =	43.500000	
214		8.000000 x	3.930000 =	31.440000	
211		240.000000 x	1.047200 =	251.328000	
407		2.000000 x	53.630000 =	107.260000	

				ΑΘΡΟΙΣΜΑ =	1,969.746132

				Η.Δ. =	2,166.720745
518	518				
417		1.000000 x	130.670000 =	130.670000	
118		8.000000 x	10.001019 =	80.008152	
112		8.000000 x	17.312112 =	138.496896	
212		5.000000 x	1.300000 =	6.500000	
214		12.000000 x	3.930000 =	47.160000	
114		8.000000 x	23.886192 =	191.089536	
211		180.000000 x	1.047200 =	188.496000	

				ΑΘΡΟΙΣΜΑ =	782.420584

				Η.Δ. =	860.662642
520	520				
419		1.000000 x	4.400000 =	4.400000	
211		80.000000 x	1.047200 =	83.776000	
212		2.000000 x	1.300000 =	2.600000	
118		4.000000 x	10.001019 =	40.004076	
115		8.000000 x	21.949547 =	175.596376	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.930000 =	19.650000	

				ΑΘΡΟΙΣΜΑ =	395.274900

				Η.Δ. =	434.802390

521	521				
420		1.000000 x	94.500000 =	94.500000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		3.000000 x	3.930000 =	11.790000	
211		40.000000 x	1.047200 =	41.888000	

				ΑΘΡΟΙΣΜΑ =	379.271612

				Η.Δ. =	417.198773
522	522				
421		1.000000 x	31.630000 =	31.630000	
114		8.000000 x	23.886192 =	191.089536	
118		2.000000 x	10.001019 =	20.002038	
214		2.000000 x	3.930000 =	7.860000	
211		20.000000 x	1.047200 =	20.944000	

				ΑΘΡΟΙΣΜΑ =	271.525574

				Η.Δ. =	298.678131
529	529				
429		1.000000 x	75.360000 =	75.360000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	3.930000 =	15.720000	
211		70.000000 x	1.047200 =	73.304000	

				ΑΘΡΟΙΣΜΑ =	395.477612

				Η.Δ. =	435.025373
550	550				
450		1.000000 x	81.440000 =	81.440000	
451		4.000000 x	4.730000 =	18.920000	
116		32.000000 x	20.419486 =	653.423552	
115		4.000000 x	21.949547 =	87.798188	
214		4.000000 x	3.930000 =	15.720000	
211		90.000000 x	1.047200 =	94.248000	

				ΑΘΡΟΙΣΜΑ =	951.549740

				Η.Δ. =	1,046.704714
551	551				
405		1.000000 x	200.790000 =	200.790000	
211		95.000000 x	1.047200 =	99.484000	
214		6.000000 x	3.930000 =	23.580000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
452		1.000000 x	100.100000 =	100.100000	

				ΑΘΡΟΙΣΜΑ =	695.051688

				Η.Δ. =	764.556857

552	552			
453		1.000000 x	.000000 =	.000000
115		8.000000 x	21.949547 =	175.596376
214		1.000000 x	3.930000 =	3.930000
211		18.000000 x	1.047200 =	18.849600

		ΑΘΡΟΙΣΜΑ =		198.375976

		H.Δ. =		
553	553			
454		1.000000 x	94.500000 =	94.500000
214		4.000000 x	3.930000 =	15.720000
211		100.000000 x	1.047200 =	104.720000

		ΑΘΡΟΙΣΜΑ =		214.940000

		H.Δ. =		236.434000
554	554			
455		1.000000 x	30.380000 =	30.380000

		ΑΘΡΟΙΣΜΑ =		30.380000

		H.Δ. =		33.418000
555	555			
456		1.000000 x	34.030000 =	34.030000
212		17.000000 x	1.300000 =	22.100000
112		32.000000 x	17.312112 =	553.987584
115		4.000000 x	21.949547 =	87.798188
214		1.000000 x	3.930000 =	3.930000

		ΑΘΡΟΙΣΜΑ =		701.845772

		H.Δ. =		772.030349
556	556			
457		1.000000 x	444.570000 =	444.570000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
214		18.000000 x	3.930000 =	70.740000
211		200.000000 x	1.047200 =	209.440000

		ΑΘΡΟΙΣΜΑ =		995.847688

		H.Δ. =		1,095.432457
557	557			
458		1.000000 x	276.840000 =	276.840000
118		8.000000 x	10.001019 =	80.008152
114		8.000000 x	23.886192 =	191.089536
214		11.000000 x	3.930000 =	43.230000
211		130.000000 x	1.047200 =	136.136000

		ΑΘΡΟΙΣΜΑ =		727.303688

		H.Δ. =		800.034057

558	558				
459		1.000000 x	409.940000 =	409.940000	
214		12.000000 x	3.930000 =	47.160000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		9.500000 x	5.000000 =	47.500000	
211		200.000000 x	1.047200 =	209.440000	
			ΑΘΡΟΙΣΜΑ =	985.137688	
			Η.Δ. =	1,083.651457	
559	559				
460		1.000000 x	506.910000 =	506.910000	
211		250.000000 x	1.047200 =	261.800000	
214		15.000000 x	3.930000 =	58.950000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	
242		12.000000 x	5.000000 =	60.000000	
			ΑΘΡΟΙΣΜΑ =	1,158.757688	
			Η.Δ. =	1,274.633457	
560	560				
461		1.000000 x	232.170000 =	232.170000	
114		8.000000 x	23.886192 =	191.089536	
211		160.000000 x	1.047200 =	167.552000	
214		8.000000 x	3.930000 =	31.440000	
			ΑΘΡΟΙΣΜΑ =	622.251536	
			Η.Δ. =	684.476690	
561	561				
462		1.000000 x	338.520000 =	338.520000	
214		12.000000 x	3.930000 =	47.160000	
114		8.000000 x	23.886192 =	191.089536	
211		230.000000 x	1.047200 =	240.856000	
			ΑΘΡΟΙΣΜΑ =	817.625536	
			Η.Δ. =	899.388090	
562	562				
463		1.000000 x	42.540000 =	42.540000	
214		2.400000 x	3.930000 =	9.432000	
211		50.000000 x	1.047200 =	52.360000	
			ΑΘΡΟΙΣΜΑ =	104.332000	
			Η.Δ. =	114.765200	

563	563				
211.1		640.000000 x	.000000 =	.000000	
114		16.000000 x	23.886192 =	382.179072	
112		24.000000 x	17.312112 =	415.490688	
214		16.000000 x	3.930000 =	62.880000	
464		1.000000 x	372.560000 =	372.560000	

		ΑΘΡΟΙΣΜΑ =		1,233.109760	

		H.Δ. =			
564	564				
465		1.000000 x	99.670000 =	99.670000	
567		3.000000 x	383.300100 =	1,149.900300	
111		8.000000 x	15.741598 =	125.932784	
115		8.000000 x	21.949547 =	175.596376	
115		8.000000 x	21.949547 =	175.596376	

		ΑΘΡΟΙΣΜΑ =		1,726.695836	

		H.Δ. =		1,899.365420	
565	565				
450		3.000000 x	81.440000 =	244.320000	
465		1.000000 x	99.670000 =	99.670000	
115		8.000000 x	21.949547 =	175.596376	
115		12.000000 x	21.949547 =	263.394564	

		H.Δ. =		782.980940	
566	566				
211.1		680.000000 x	.000000 =	.000000	
466		1.000000 x	46.490000 =	46.490000	
112		1.000000 x	17.312112 =	17.312112	
115		2.000000 x	21.949547 =	43.899094	

		ΑΘΡΟΙΣΜΑ =		107.701206	

		H.Δ. =			
567	567				
450		1.000000 x	81.440000 =	81.440000	
115		4.000000 x	21.949547 =	87.798188	
112		4.000000 x	17.312112 =	69.248448	
214		4.000000 x	3.930000 =	15.720000	
211		90.000000 x	1.047200 =	94.248000	

		ΑΘΡΟΙΣΜΑ =		348.454636	

		H.Δ. =		383.300100	

568.1	568.1				
467		1.000000 x	338.520000 =	338.520000	
567		2.000000 x	383.300100 =	766.600200	
512		.240000 x	105.407850 =	25.297884	
510		.072000 x	385.923270 =	27.786475	
118		32.000000 x	10.001019 =	320.032608	
114		8.000000 x	23.886192 =	191.089536	
113		32.000000 x	20.419486 =	653.423552	
214		16.000000 x	3.930000 =	62.880000	

				ΑΘΡΟΙΣΜΑ =	2,385.630255

				Η.Δ. =	2,624.193281
568.2	568.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.949547 =	175.596376	
467		1.000000 x	338.520000 =	338.520000	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	868.085912
569.1	569.1				
468		1.000000 x	84.780000 =	84.780000	
214		16.000000 x	3.930000 =	62.880000	
567		2.000000 x	383.300100 =	766.600200	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	1,185.357888

				Η.Δ. =	1,303.893677
569.2	569.2				
450		2.000000 x	81.440000 =	162.880000	
115		8.000000 x	21.949547 =	175.596376	
114		8.000000 x	23.886192 =	191.089536	
468		1.000000 x	84.780000 =	84.780000	

				Η.Δ. =	614.345912
570.1	570.1				
469		1.000000 x	84.780000 =	84.780000	
211		135.000000 x	1.047200 =	141.372000	
114		8.000000 x	23.886192 =	191.089536	
118		4.000000 x	10.001019 =	40.004076	
214		16.000000 x	3.930000 =	62.880000	

				ΑΘΡΟΙΣΜΑ =	520.125612

				Η.Δ. =	572.138173

570.2	570.2				
469		1.000000 x	84.780000 =	84.780000	
118		4.000000 x	10.001019 =	40.004076	

			H.Δ. =	124.784076	
571.1	571.1				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	
214		4.000000 x	3.930000 =	15.720000	
211		114.000000 x	1.047200 =	119.380800	

			AΘΡΟΙΣΜΑ =	394.560336	

			H.Δ. =	434.016370	
571.2	571.2				
470		1.000000 x	68.370000 =	68.370000	
114		8.000000 x	23.886192 =	191.089536	

			H.Δ. =	259.459536	
572	572				
407		1.000000 x	53.630000 =	53.630000	
471		1.000000 x	59.250000 =	59.250000	
114		8.000000 x	23.886192 =	191.089536	
214		8.000000 x	3.930000 =	31.440000	
111		24.000000 x	15.741598 =	377.798352	
211		54.000000 x	1.047200 =	56.548800	

			AΘΡΟΙΣΜΑ =	769.756688	

			H.Δ. =	846.732357	
573	573				
407		1.000000 x	53.630000 =	53.630000	
473		.250000 x	16.560000 =	4.140000	
474		.250000 x	34.030000 =	8.507500	
474		1.000000 x	34.030000 =	34.030000	
473		1.000000 x	16.560000 =	16.560000	
115		16.000000 x	21.949547 =	351.192752	
111		24.000000 x	15.741598 =	377.798352	
214		8.000000 x	3.930000 =	31.440000	
211		54.000000 x	1.047200 =	56.548800	
407		.250000 x	53.630000 =	13.407500	
472		.250000 x	25.750000 =	6.437500	
472		1.000000 x	25.750000 =	25.750000	

			AΘΡΟΙΣΜΑ =	979.442404	

			H.Δ. =	1,077.386644	

574	574				
475		1.000000 x	1,913.860000 =		1,913.860000
214		30.000000 x	3.930000 =		117.900000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
111		16.000000 x	15.741598 =		251.865568
242		7.000000 x	5.000000 =		35.000000
211		590.000000 x	1.047200 =		617.848000
			ΑΘΡΟΙΣΜΑ =		3,207.571256
			Η.Δ. =		3,528.328382
574.1	574.1				
475		1.000000 x	1,913.860000 =		1,913.860000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
			Η.Δ. =		2,184.957688
575	575				
476		1.000000 x	82.950000 =		82.950000
214		23.000000 x	3.930000 =		90.390000
115		8.000000 x	21.949547 =		175.596376
211		470.000000 x	1.047200 =		492.184000
			ΑΘΡΟΙΣΜΑ =		841.120376
			Η.Δ. =		925.232414
575.1	575.1				
476		1.000000 x	82.950000 =		82.950000
115		8.000000 x	21.949547 =		175.596376
			Η.Δ. =		258.546376
576	576				
477		1.000000 x	6.750000 =		6.750000
			ΑΘΡΟΙΣΜΑ =		6.750000
			Η.Δ. =		7.425000
576.1	576.1				
477		1.000000 x	6.750000 =		6.750000
			Η.Δ. =		6.750000

577	577				
478		1.000000 x	111.820000 =	111.820000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
111		8.000000 x	15.741598 =	125.932784	
214		4.000000 x	3.930000 =	15.720000	
211		70.000000 x	1.047200 =	73.304000	

				ΑΘΡΟΙΣΜΑ =	607.874472

				Η.Δ. =	668.661919
577.1	577.1				
478		1.000000 x	111.820000 =	111.820000	
118		8.000000 x	10.001019 =	80.008152	
114		8.000000 x	23.886192 =	191.089536	

				Η.Δ. =	382.917688
578	578				
479		1.000000 x	179.890000 =	179.890000	
211		50.000000 x	1.047200 =	52.360000	
242		5.000000 x	5.000000 =	25.000000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	
112		4.000000 x	17.312112 =	69.248448	
214		5.000000 x	3.930000 =	19.650000	

				ΑΘΡΟΙΣΜΑ =	577.242060

				Η.Δ. =	634.966266
579	579				
480		1.000000 x	26.440000 =	26.440000	
212		28.000000 x	1.300000 =	36.400000	
117		8.000000 x	16.777917 =	134.223336	
214		1.000000 x	3.930000 =	3.930000	

				ΑΘΡΟΙΣΜΑ =	200.993336

				Η.Δ. =	221.092670
580	580				
481		1.000000 x	789.180000 =	789.180000	
214		8.000000 x	3.930000 =	31.440000	
242		2.000000 x	5.000000 =	10.000000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
211		168.000000 x	1.047200 =	175.929600	
111		16.000000 x	15.741598 =	251.865568	

				ΑΘΡΟΙΣΜΑ =	1,529.512856

				Η.Δ. =	1,682.464142

581	581			
481		1.000000 x	789.180000 =	789.180000
114		8.000000 x	23.886192 =	191.089536
118		8.000000 x	10.001019 =	80.008152
			H.Δ. =	1,060.277688
7020.2	7020.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.150000 x	259.459536 =	38.918930
571.1		.350000 x	434.016370 =	151.905730
570.2		.350000 x	124.784076 =	43.674427
570.1		.150000 x	572.138173 =	85.820726
569.2		.670000 x	614.345912 =	411.611761
569.1		.330000 x	1,303.893677 =	430.284913
568.2		.550000 x	868.085912 =	477.447252
568.1		.450000 x	2,624.193281 =	1,180.886976
567		1.000000 x	383.300100 =	383.300100
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	3,493.139487
7021.2	7021.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.240000 x	259.459536 =	62.270289
571.1		.260000 x	434.016370 =	112.844256
570.2		.390000 x	124.784076 =	48.665790
570.1		.110000 x	572.138173 =	62.935199
569.2		.750000 x	614.345912 =	460.759434
116		8.000000 x	20.419486 =	163.355888
567		1.000000 x	383.300100 =	383.300100
568.1		.250000 x	2,624.193281 =	656.048320
569.1		.250000 x	1,303.893677 =	325.973419
568.2		.750000 x	868.085912 =	651.064434
			H.Δ. =	3,053.149913
7022.2	7022.2			
111		8.000000 x	15.741598 =	125.932784
571.2		.310000 x	259.459536 =	80.432456
571.1		.190000 x	434.016370 =	82.463110
570.2		.420000 x	124.784076 =	52.409312
570.1		.080000 x	572.138173 =	45.771054
569.2		.820000 x	614.345912 =	503.763648
569.1		.180000 x	1,303.893677 =	234.700862
568.2		.850000 x	868.085912 =	737.873025
568.1		.150000 x	2,624.193281 =	393.628992
567		1.000000 x	383.300100 =	383.300100
116		8.000000 x	20.419486 =	163.355888
			H.Δ. =	2,803.631231

613	613				
111		.140000 x	15.741598 =		2.203824
503		.000770 x	891.952173 =		.686803
520		.003500 x	434.802390 =		1.521808
504		.002800 x	375.350290 =		1.050981

			B.T =		5.463416
614	614				
112		.070000 x	17.312112 =		1.211848
509		.004375 x	396.120270 =		1.733026
518		.004375 x	860.662642 =		3.765399
504		.002800 x	375.350290 =		1.050981
503		.000700 x	891.952173 =		.624367

			B.T =		8.385620
621.1	621.1				
213		.100000 x	1.949500 =		.194950
116		.140000 x	20.419486 =		2.858728
111		.560000 x	15.741598 =		8.815295
508		.003500 x	579.356760 =		2.027749
504		.003500 x	375.350290 =		1.313726

			B.T =		15.210448
622	622				
213		.100000 x	1.949500 =		.194950
116		.140000 x	20.419486 =		2.858728
112		.070000 x	17.312112 =		1.211848
508		.003500 x	579.356760 =		2.027749
504		.003500 x	375.350290 =		1.313726
518		.004340 x	860.662642 =		3.735276
509		.003500 x	396.120270 =		1.386421

			B.T =		12.728697
6360.1 A1	6360.1 A1				
6304		9.800000 x	5.646698 =		55.337640
6330		.038000 x	181.212255 =		6.886066
6330		.190000 x	181.212255 =		34.430328
6314		.382500 x	2.059685 =		.787830
6314		7.650000 x	2.059685 =		15.756590

			B.T =		113.198454
6360.1 A2	6360.1 A2				
6304		.450000 x	5.646698 =		2.541014
6310		2.142000 x	1.480293 =		3.170788
6330		.013000 x	181.212255 =		2.355759

			B.T =		8.067561

6360.1 A3	6360.1 A3			
6304		.960000 x	5.646698 =	5.420830
6329.2		.037000 x	166.692391 =	6.167618
6310		1.974000 x	1.480293 =	2.922098

			B.T =	14.510547
6360.1 A4	6360.1 A4			
6304		2.490000 x	5.646698 =	14.060278
6329.2		.109000 x	166.692391 =	18.169471

			B.T =	32.229749
6360.1 A5	6360.1 A5			
112		1.700000 x	17.312112 =	29.430590
113		2.975000 x	20.419486 =	60.747971
6069.1		.056400 x	11.407658 =	.643392
113		.425000 x	20.419486 =	8.678282

			B.T =	99.500235
6360.2 A1	6360.2 A1			
6304		10.650000 x	5.646698 =	60.137334
6330		.041000 x	181.212255 =	7.429702
6330		.205000 x	181.212255 =	37.148512
6314		.392500 x	2.059685 =	.808426
6314		7.850000 x	2.059685 =	16.168527

			B.T =	121.692502
6360.2 A2	6360.2 A2			
6304		.750000 x	5.646698 =	4.235024
6330		.019000 x	181.212255 =	3.443033
6310		2.383500 x	1.480293 =	3.528278

			B.T =	11.206335
6360.2 A3	6360.2 A3			
6304		1.140000 x	5.646698 =	6.437236
6310		2.341500 x	1.480293 =	3.466106
6329.2		.054000 x	166.692391 =	9.001389

			B.T =	18.904731
6360.2 A4	6360.2 A4			
6304		2.800000 x	5.646698 =	15.810754
6329.2		.118000 x	166.692391 =	19.669702

			B.T =	35.480457

6360.2 A5	6360.2 A5			
112		2.550000 x	17.312112 =	44.145886
113		2.975000 x	20.419486 =	60.747971
6069.1		.059400 x	11.407658 =	.677615
113		.382500 x	20.419486 =	7.810453

			B.T =	113.381925
6360.3 A1	6360.3 A1			
6304		13.900000 x	5.646698 =	78.489102
6314		11.150000 x	2.059685 =	22.965488
6330		.270000 x	181.212255 =	48.927309
6330		.054000 x	181.212255 =	9.785462
6314		.557500 x	2.059685 =	1.148274

			B.T =	161.315635
6360.3 A2	6360.3 A2			
6304		.940000 x	5.646698 =	5.307896
6310		3.360000 x	1.480293 =	4.973784
6330		.031000 x	181.212255 =	5.617580

			B.T =	15.899261
6360.3 A3	6360.3 A3			
6304		1.830000 x	5.646698 =	10.333457
6329.2		.099000 x	166.692391 =	16.502547
6310		10.678500 x	1.480293 =	15.807309

			B.T =	42.643313
6360.3 A4	6360.3 A4			
6304		3.420000 x	5.646698 =	19.311707
6329.2		.139000 x	166.692391 =	23.170242

			B.T =	42.481950
6360.3 A5	6360.3 A5			
112		5.100000 x	17.312112 =	88.291771
113		2.975000 x	20.419486 =	60.747971
6069.1		.073800 x	11.407658 =	.841885
113		.340000 x	20.419486 =	6.942625

			B.T =	156.824252

6360.4 A1	6360.4 A1			
6304		16.250000 x	5.646698 =	91.758843
6330		.375000 x	181.212255 =	67.954596
6330		.075000 x	181.212255 =	13.590919
6314		17.700000 x	2.059685 =	36.456425
6314		.885000 x	2.059685 =	1.822821

			B.T =	211.583603
6360.4 A2	6360.4 A2			
6304		1.060000 x	5.646698 =	5.985500
6330		.048000 x	181.212255 =	8.698188
6310		4.641000 x	1.480293 =	6.870040

			B.T =	21.553728
6360.4 A3	6360.4 A3			
6304		2.270000 x	5.646698 =	12.818004
6329.2		.125000 x	166.692391 =	20.836549
6310		20.454000 x	1.480293 =	30.277913

			B.T =	63.932466
6360.4 A4	6360.4 A4			
6304		2.800000 x	5.646698 =	15.810754
6329.2		.118000 x	166.692391 =	19.669702

			B.T =	35.480457
6360.4 A5	6360.4 A5			
112		6.800000 x	17.312112 =	117.722362
113		4.250000 x	20.419486 =	86.782816
113		.297500 x	20.419486 =	6.074797
6069.1		.091800 x	11.407658 =	1.047223

			B.T =	211.627197
6360.5 A1	6360.5 A1			
6304		17.950000 x	5.646698 =	101.358229
6330		.088000 x	181.212255 =	15.946678
6330		.440000 x	181.212255 =	79.733392
6314		1.050000 x	2.059685 =	2.162669
6314		21.000000 x	2.059685 =	43.253385

			B.T =	242.454354
6360.5 A2	6360.5 A2			
6304		1.220000 x	5.646698 =	6.888972
6310		6.048000 x	1.480293 =	8.952812
6330		.061000 x	181.212255 =	11.053948

			B.T =	26.895731

ΑΤΥΠ	3ο Τρίμηνο του 2010	Σελ.	31
		Ημ/νία	16/07/2011
6360.5 A3	6360.5 A3		
6304	2.480000 x	5.646698 =	14.003811
6310	22.291500 x	1.480293 =	32.997951
6329.2	.144000 x	166.692391 =	24.003704

		B.T =	71.005467
6360.5 A4	6360.5 A4		
6304	3.200000 x	5.646698 =	18.069434
6329.2	.112000 x	166.692391 =	18.669548

		B.T =	36.738981
6360.5 A5	6360.5 A5		
112	9.350000 x	17.312112 =	161.868247
113	5.950000 x	20.419486 =	121.495942
6069.1	.090600 x	11.407658 =	1.033534
113	.255000 x	20.419486 =	5.206969

		B.T =	289.604692
6360.6 A1	6360.6 A1		
6304	20.350000 x	5.646698 =	114.910304
6314	24.900000 x	2.059685 =	51.286157
6330	.580000 x	181.212255 =	105.103108
6330	.116000 x	181.212255 =	21.020622
6314	1.245000 x	2.059685 =	2.564308

		B.T =	294.884498
6360.6 A2	6360.6 A2		
6304	1.530000 x	5.646698 =	8.639448
6330	.092000 x	181.212255 =	16.671527
6310	10.206000 x	1.480293 =	15.107870

		B.T =	40.418846
6360.6 A3	6360.6 A3		
6304	2.670000 x	5.646698 =	15.076684
6329.2	.181000 x	166.692391 =	30.171323
6310	25.798500 x	1.480293 =	38.189339

		B.T =	83.437345
6360.6 A4	6360.6 A4		
6304	2.800000 x	5.646698 =	15.810754
6329.2	.118000 x	166.692391 =	19.669702

		B.T =	35.480457

6360.6 A5

6360.6 A5

112	12.750000 x	17.312112 =	220.729428
113	7.650000 x	20.419486 =	156.209068
6069.1	.120000 x	11.407658 =	1.368919
113	.212500 x	20.419486 =	4.339141

B.T = 382.646556

641

641

231	.200000 x	.775000 =	.155000
251	.001500 x	290.000000 =	.435000
113	.127500 x	20.419486 =	2.603484
111	.170000 x	15.741598 =	2.676072
252	.002500 x	290.000000 =	.725000

B.T = 6.594556

651

651

221	150.000000 x	.099900 =	14.985000
111	1.275000 x	15.741598 =	20.070537
509	.009435 x	396.120270 =	3.737395
509	.003060 x	396.120270 =	1.212128
T 630	.600000 x	1.791933 =	1.075160
T 625	.850000 x	21.340163 =	18.139139
511	.042500 x	725.748703 =	30.844320
112	.425000 x	17.312112 =	7.357648
224	120.000000 x	.070000 =	8.400000

B.T = 105.821326

652

652

221	650.000000 x	.099900 =	64.935000
T 630	.320000 x	1.791933 =	.573419
T 625	1.000000 x	21.340163 =	21.340163
511	.042500 x	725.748703 =	30.844320
509	.001632 x	396.120270 =	.646468
509	.009435 x	396.120270 =	3.737395
111	1.275000 x	15.741598 =	20.070537
112	.425000 x	17.312112 =	7.357648

B.T = 149.504950

652.1

652.1

221	450.000000 x	.099900 =	44.955000
112	.425000 x	17.312112 =	7.357648
510	.001632 x	385.923270 =	.629827
511	.042500 x	725.748703 =	30.844320
T 630	.320000 x	1.791933 =	.573419
T 625	1.060000 x	21.340163 =	22.620573
509	.010001 x	396.120270 =	3.961599
111	1.275000 x	15.741598 =	20.070537

B.T = 131.012922

652.2	652.2			
221		900.000000 x	.099900 =	89.910000
509		.007548 x	396.120270 =	2.989916
T 630		.320000 x	1.791933 =	.573419
T 625		.800000 x	21.340163 =	17.072130
511		.042500 x	725.748703 =	30.844320
510		.001632 x	385.923270 =	.629827
112		.425000 x	17.312112 =	7.357648
111		1.275000 x	15.741598 =	20.070537

			B.T =	169.447796
700	700			
397.4		4.000000 x	.165000 =	.660000
397.5		2.150000 x	.000000 =	.000000
324		7.650000 x	.580000 =	4.437000
221		13.000000 x	.099900 =	1.298700
113		.935000 x	20.419486 =	19.092219

			B.T =	
7001 A	7001 A			
502		.000365 x	782.814573 =	.285727
557		.001094 x	800.034057 =	.875237

			AΘΡΟΙΣΜΑ =	1.160965
	B.T =	.200000 x	1.160965 =	.232193

7001 B	7001 B			
558		.000700 x	1,083.651457 =	.758556

			B.T =	.758556
7001 E	7001 E			
503		.000875 x	891.952173 =	.780458
554		.000875 x	33.418000 =	.029241

			B.T =	.809699
7001 Γ	7001 Γ			
501		.000700 x	600.558852 =	.420391
502		.000700 x	782.814573 =	.547970

			B.T =	.968361

7001 Δ	7001 Δ			
502		.000292 x	782.814573 =	.228582
510		.000292 x	385.923270 =	.112690
X 630.1		.060000 x	1.620878 =	.097253
X 630		.060000 x	1.475710 =	.088543

			AΘΡΟΙΣΜΑ =	.527067
	B.T =	.600000 x	.527067 =	.316240

7003 Α	7003 Α			
502		.000365 x	782.814573 =	.285727
557		.001094 x	800.034057 =	.875237

			AΘΡΟΙΣΜΑ =	1.160965
	B.T =	.100000 x	1.160965 =	.116096

7003 Β	7003 Β			
559		.000464 x	1,274.633457 =	.591430

			B.T =	.591430
7003 Γ	7003 Γ			
502		.000700 x	782.814573 =	.547970

			B.T =	.547970
7003 Δ	7003 Δ			
502		.000875 x	782.814573 =	.684963
562		.000875 x	114.765200 =	.100420

			B.T =	.785382
7005 Α	7005 Α			
502		.000365 x	782.814573 =	.285727
557		.001094 x	800.034057 =	.875237

			AΘΡΟΙΣΜΑ =	1.160965
	B.T =	.100000 x	1.160965 =	.116096

7005 Β	7005 Β			
559		.000812 x	1,274.633457 =	1.035002

			B.T =	1.035002
7005 Ε	7005 Ε			
502		.000875 x	782.814573 =	.684963
562		.000875 x	114.765200 =	.100420

			B.T =	.785382

7005 Γ	7005 Γ			
559		.000232 x	1,274.633457 =	.295715

			B.T =	.295715
7005 Δ	7005 Δ			
502		.000700 x	782.814573 =	.547970

			B.T =	.547970
7010 Α	7010 Α			
558		.000315 x	1,083.651457 =	.341350

			B.T =	.341350
7010 Β	7010 Β			
558		.000473 x	1,083.651457 =	.512567

			B.T =	.512567
7010 Ε	7010 Ε			
503		.000875 x	891.952173 =	.780458
553		.000875 x	236.434000 =	.206880

			B.T =	.987338
7010 Γ	7010 Γ			
502		.000700 x	782.814573 =	.547970

			B.T =	.547970
7010 Δ	7010 Δ			
502		.000292 x	782.814573 =	.228582
510		.000292 x	385.923270 =	.112690
X 630.1		.060000 x	1.620878 =	.097253
X 630		.060000 x	1.475710 =	.088543

			AΘΡΟΙΣΜΑ =	.527067
	B.T =	.600000 x	.527067 =	.316240

7016.1	7016.1			
396.5		10.500000 x	1.180000 =	12.390000
223		350.000000 x	.119300 =	41.755000
509		.007831 x	396.120270 =	3.102018
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.830000 x	18.194441 =	15.101386
T 617		.500000 x	6.286106 =	3.143053
509		.004718 x	396.120270 =	1.868895

			B.T =	78.300388

7016.2	7016.2			
570.1		.586500 x	572.138173 =	335.559038
571.1		.586500 x	434.016370 =	254.550601
570.2		1.113500 x	124.784076 =	138.947069
571.2		1.113500 x	259.459536 =	288.908193

			ΑΘΡΟΙΣΜΑ =	1,017.964901
	B.T =	.025000 x	1,017.964901 =	25.449123

7016.3	7016.3			
564		.212500 x	1,899.365420 =	403.615152
565		.637500 x	782.980940 =	499.150349

			ΑΘΡΟΙΣΜΑ =	902.765501
	B.T =	.025000 x	902.765501 =	22.569138

7016.4	7016.4			
7016.1		1.000000 x	78.300388 =	78.300388
7016.3		1.000000 x	22.569138 =	22.569138
7016.2		1.000000 x	25.449123 =	25.449123

			B.T =	126.318649
7016.5	7016.5			
7016.4		.200000 x	126.318649 =	25.263730

			B.T =	25.263730
7016.6	7016.6			
7016.4		.250000 x	126.318649 =	31.579662
7016.5		.250000 x	25.263730 =	6.315933

			B.T =	37.895595
7016.7	7016.7			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7016.8	7016.8			
113		5.100000 x	20.419486 =	104.139379

			B.T =	104.139379

7017.1	7017.1			
396.5		10.500000 x	1.180000 =	12.390000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.830000 x	18.194441 =	15.101386
T 617		.500000 x	6.286106 =	3.143053
509		.007831 x	396.120270 =	3.102018
509		.004718 x	396.120270 =	1.868895
223		350.000000 x	.119300 =	41.755000

			B.T =	78.300388
7017.2	7017.2			
564		.425000 x	1,899.365420 =	807.230304
565		.425000 x	782.980940 =	332.766900

			ΑΘΡΟΙΣΜΑ =	1,139.997203
	B.T =	.012500 x	1,139.997203 =	14.249965

7017.3	7017.3			
7017.1		1.000000 x	78.300388 =	78.300388
7017.2		1.000000 x	14.249965 =	14.249965

			B.T =	92.550353
7017.4	7017.4			
7017.3		.200000 x	92.550353 =	18.510071

			B.T =	18.510071
7017.5	7017.5			
7017.3		.300000 x	92.550353 =	27.765106
7017.4		.300000 x	18.510071 =	5.553021

			B.T =	33.318127
7017.6	7017.6			
111		5.100000 x	15.741598 =	80.282150

			B.T =	80.282150
7017.7	7017.7			
113		2.550000 x	20.419486 =	52.069689

			B.T =	52.069689

7019 A1	7019 A1			
396.5		5.000000 x	1.180000 =	5.900000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
223		350.000000 x	.119300 =	41.755000

			B.T =	78.679481
7019 A2	7019 A2			
555		.012143 x	772.030349 =	9.374765

			B.T =	9.374765
7019 A3	7019 A3			
570.1		.850000 x	572.138173 =	486.317447
571.1		.850000 x	434.016370 =	368.913915
571.2		.850000 x	259.459536 =	220.540606
570.2		.850000 x	124.784076 =	106.066465

			ΑΘΡΟΙΣΜΑ =	1,181.838432
	B.T =	.014286 x	1,181.838432 =	16.883744

7019 A4	7019 A4			
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

			B.T =	69.237454
7019 A5	7019 A5			
113		.850000 x	20.419486 =	17.356563

			B.T =	17.356563
7019 A6	7019 A6			
7019 A1		1.000000 x	78.679481 =	78.679481
7019 A4		1.000000 x	69.237454 =	69.237454
7019 A2		1.000000 x	9.374765 =	9.374765
7019 A3		1.000000 x	16.883744 =	16.883744
7019 A5		1.000000 x	17.356563 =	17.356563

			B.T =	191.532007
7019 A7	7019 A7			
7019 A6		.100000 x	191.532007 =	19.153201

			B.T =	19.153201

710	710			
397.3		.006660 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
113		.170000 x	20.419486 =	3.471313
252		.001000 x	290.000000 =	.290000

			B.T =	
720	720			
566		.000174 x	.000000 =	.000000

			B.T =	
A 626	A 626			
504		.005025 x	375.350290 =	1.886135
509		.003750 x	396.120270 =	1.485451

			B.T =	3.371586
T 611	T 611			
111		1.275000 x	15.741598 =	20.070537

			B.T =	20.070537
T 617	T 617			
111		.085000 x	15.741598 =	1.338036
520		.005270 x	434.802390 =	2.291409
504		.004250 x	375.350290 =	1.595239
503		.001190 x	891.952173 =	1.061423

			B.T =	6.286106
T 621	T 621			
213		.100000 x	1.949500 =	.194950
508		.004250 x	579.356760 =	2.462266
116		.170000 x	20.419486 =	3.471313
111		.680000 x	15.741598 =	10.704287

			B.T =	16.832815
T 623	T 623			
213		.100000 x	1.949500 =	.194950
504		.004250 x	375.350290 =	1.595239
518		.008500 x	860.662642 =	7.315632
509		.004250 x	396.120270 =	1.683511
508		.004250 x	579.356760 =	2.462266
116		.170000 x	20.419486 =	3.471313
112		.085000 x	17.312112 =	1.471530

			B.T =	18.194441

T 625	T 625			
213		.100000 x	1.949500 =	.194950
116		.170000 x	20.419486 =	3.471313
518		.012155 x	860.662642 =	10.461354
509		.004250 x	396.120270 =	1.683511
508		.004250 x	579.356760 =	2.462266
504		.004250 x	375.350290 =	1.595239
112		.085000 x	17.312112 =	1.471530

			B.T =	21.340163
T 630	T 630			
512		.017000 x	105.407850 =	1.791933

			B.T =	1.791933
T 630.1	T 630.1			
510		.005100 x	385.923270 =	1.968209

			B.T =	1.968209
X 611	X 611			
111		1.050000 x	15.741598 =	16.528678

			B.T =	16.528678
X 617	X 617			
111		.070000 x	15.741598 =	1.101912
504		.003500 x	375.350290 =	1.313726
520		.004340 x	434.802390 =	1.887042
503		.000980 x	891.952173 =	.874113

			B.T =	5.176793
X 621	X 621			
213		.100000 x	1.949500 =	.194950
508		.003500 x	579.356760 =	2.027749
111		.560000 x	15.741598 =	8.815295
116		.140000 x	20.419486 =	2.858728

			B.T =	13.896722
X 623	X 623			
213		.100000 x	1.949500 =	.194950
518		.007000 x	860.662642 =	6.024638
509		.003500 x	396.120270 =	1.386421
508		.003500 x	579.356760 =	2.027749
504		.003500 x	375.350290 =	1.313726
116		.140000 x	20.419486 =	2.858728
112		.070000 x	17.312112 =	1.211848

			B.T =	15.018060

X 625	X 625			
213		.100000 x	1.949500 =	.194950
518		.010010 x	860.662642 =	8.615233
509		.003500 x	396.120270 =	1.386421
508		.003500 x	579.356760 =	2.027749
504		.003500 x	375.350290 =	1.313726
112		.070000 x	17.312112 =	1.211848
116		.140000 x	20.419486 =	2.858728

			B.T =	17.608655
X 630	X 630			
512		.014000 x	105.407850 =	1.475710

			B.T =	1.475710
X 630.1	X 630.1			
510		.004200 x	385.923270 =	1.620878

			B.T =	1.620878
2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.190000 x	17.312112 =	20.601413
113		1.360000 x	20.419486 =	27.770501
509		.004718 x	396.120270 =	1.868895
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.007548 x	396.120270 =	2.989916
509		.001275 x	396.120270 =	.505053
T 625		.500000 x	21.340163 =	10.670082
641		3.000000 x	6.594556 =	19.783668
T 630		.250000 x	1.791933 =	.447983

			T.E =	153.838520
6021	6021			
111		4.250000 x	15.741598 =	66.901792
509		.019380 x	396.120270 =	7.676811

			T.E =	74.578602
6022	6022			
111		2.550000 x	15.741598 =	40.141075
509		.008075 x	396.120270 =	3.198671

			T.E =	43.339746
6051	6051			
502		.000175 x	782.814573 =	.136993

			T.E =	.136993

6052	6052			
501		.000117 x	600.558852 =	.070265
502		.000088 x	782.814573 =	.068888
521		.000088 x	417.198773 =	.036713

			T.E =	.175867
6053	6053			
502		.000318 x	782.814573 =	.248935
507		.001000 x	912.951257 =	.912951

			T.E =	1.161886
6054	6054			
112		.004900 x	17.312112 =	.084829
509		.002975 x	396.120270 =	1.178458
507		.001077 x	912.951257 =	.983249

			T.E =	2.246536
6055	6055			
213		.400000 x	1.949500 =	.779800
503		.001167 x	891.952173 =	1.040908
508		.007000 x	579.356760 =	4.055497
504		.001400 x	375.350290 =	.525490
112		.490000 x	17.312112 =	8.482935
116		.280000 x	20.419486 =	5.717456

			T.E =	20.602087
6056	6056			
507		.001750 x	912.951257 =	1.597665

			T.E =	1.597665
6057	6057			
506		.087500 x	668.196857 =	58.467225

			T.E =	58.467225
6058	6058			
507		.087500 x	912.951257 =	79.883235

			T.E =	79.883235
6059	6059			
112		.070000 x	17.312112 =	1.211848

			T.E =	1.211848

6060	6060			
112		.350000 x	17.312112 =	6.059239

			T.E =	6.059239
6061	6061			
112		.007000 x	17.312112 =	.121185
507		.001077 x	912.951257 =	.983249
509		.002975 x	396.120270 =	1.178458
501		.000583 x	600.558852 =	.350126
502		.001400 x	782.814573 =	1.095940

			T.E =	3.728957
6062	6062			
213		.400000 x	1.949500 =	.779800
509		.002800 x	396.120270 =	1.109137
508		.002800 x	579.356760 =	1.622199
507		.001400 x	912.951257 =	1.278132
502		.002000 x	782.814573 =	1.565629
116		.175000 x	20.419486 =	3.573410
112		.175000 x	17.312112 =	3.029620

			T.E =	12.957926
6063	6063			
112		.700000 x	17.312112 =	12.118478
112		.070000 x	17.312112 =	1.211848
509		.003641 x	396.120270 =	1.442274
112		.070000 x	17.312112 =	1.211848
112		.140000 x	17.312112 =	2.423696

			T.E =	18.408144
6064	6064			
112		.140000 x	17.312112 =	2.423696
509		.003641 x	396.120270 =	1.442274
507		.014000 x	912.951257 =	12.781318
112		.070000 x	17.312112 =	1.211848

			T.E =	17.859135
6065	6065			
506		.002800 x	668.196857 =	1.870951
506		.002100 x	668.196857 =	1.403213

			T.E =	3.274165

6066	6066				
111		.070000 x	15.741598 =	1.101912	
502		.000700 x	782.814573 =	.547970	

			T.E =	1.649882	
6067	6067				
111		.980000 x	15.741598 =	15.426766	
X 630		.100000 x	1.475710 =	.147571	
X 630.1		.100000 x	1.620878 =	.162088	

			T.E =	15.736425	
6068	6068				
111		.560000 x	15.741598 =	8.815295	
622		1.351351 x	12.728697 =	17.200937	
X 630.1		.200000 x	1.620878 =	.324176	
X 630		.200000 x	1.475710 =	.295142	
112		.560000 x	17.312112 =	9.694783	
509		.016497 x	396.120270 =	6.534796	

			T.E =	42.865129	
6068.1	6068.1				
111		.560000 x	15.741598 =	8.815295	
X 630.1		.200000 x	1.620878 =	.324176	
X 630		.200000 x	1.475710 =	.295142	
614		1.351351 x	8.385620 =	11.331916	
509		.016497 x	396.120270 =	6.534796	
112		.560000 x	17.312112 =	9.694783	

			T.E =	36.996107	
6069	6069				
112		.070000 x	17.312112 =	1.211848	
509		.012017 x	396.120270 =	4.760177	
X 625		1.050000 x	17.608655 =	18.489088	

			T.E =	24.461113	
6069.1	6069.1				
112		.070000 x	17.312112 =	1.211848	
509		.012017 x	396.120270 =	4.760177	
X 617		1.050000 x	5.176793 =	5.435633	

			T.E =	11.407658	
6070	6070				
501		.000467 x	600.558852 =	.280461	

			T.E =	.280461	

6071	6071			
504		.002333 x	375.350290 =	.875692
509		.002975 x	396.120270 =	1.178458

			T.E =	2.054150
6072	6072			
504		.003500 x	375.350290 =	1.313726
509		.002800 x	396.120270 =	1.109137

			T.E =	2.422863
6073	6073			
509		.000833 x	396.120270 =	.329968

			T.E =	.329968
6074	6074			
509		.000784 x	396.120270 =	.310558

			T.E =	.310558
6075	6075			
509		.001096 x	396.120270 =	.434148

			T.E =	.434148
6076	6076			
112		.004900 x	17.312112 =	.084829
503		.000700 x	891.952173 =	.624367
509		.003914 x	396.120270 =	1.550415
507		.000840 x	912.951257 =	.766879

			T.E =	3.026490
6077	6077			
503		.001400 x	891.952173 =	1.248733

			T.E =	1.248733
6078	6078			
112		.004900 x	17.312112 =	.084829
505		.001400 x	799.114457 =	1.118760
501		.000056 x	600.558852 =	.033631
503		.000350 x	891.952173 =	.312183

			T.E =	1.549404

6078.1	6078.1			
112		.004900 x	17.312112 =	.084829
501		.000056 x	600.558852 =	.033631
503		.000350 x	891.952173 =	.312183
556		.001400 x	1,095.432457 =	1.533605

			T.E =	1.964249
6079	6079			
112		.014000 x	17.312112 =	.242370
501		.000700 x	600.558852 =	.420391
529		.000980 x	435.025373 =	.426325
X 630		.150000 x	1.475710 =	.221357
509		.000630 x	396.120270 =	.249556
502		.000350 x	782.814573 =	.273985

			T.E =	1.833983
6080	6080			
112		.014000 x	17.312112 =	.242370
X 630.1		.100000 x	1.620878 =	.162088
X 630		.100000 x	1.475710 =	.147571
529		.000700 x	435.025373 =	.304518
502		.000292 x	782.814573 =	.228582
501		.000583 x	600.558852 =	.350126

			T.E =	1.435254
6081.1	6081.1			
111		.420000 x	15.741598 =	6.611471
112		.280000 x	17.312112 =	4.847391
112		.420000 x	17.312112 =	7.271087
506		.007000 x	668.196857 =	4.677378

			T.E =	23.407328
6081.2	6081.2			
111		.700000 x	15.741598 =	11.019119
112		.070000 x	17.312112 =	1.211848
6081.1		1.000000 x	23.407328 =	23.407328

			T.E =	35.638294
6081.3	6081.3			
111		1.400000 x	15.741598 =	22.038237
6081.1		1.000000 x	23.407328 =	23.407328
112		.140000 x	17.312112 =	2.423696

			T.E =	47.869261

6081.4	6081.4			
111		2.100000 x	15.741598 =	33.057356
6081.1		1.000000 x	23.407328 =	23.407328
112		.210000 x	17.312112 =	3.635544

			T.E =	60.100227
6082.1	6082.1			
213		.400000 x	1.949500 =	.779800
111		1.400000 x	15.741598 =	22.038237
116		.700000 x	20.419486 =	14.293640
508		.070000 x	579.356760 =	40.554973
116		1.400000 x	20.419486 =	28.587280

			T.E =	106.253931
6082.2	6082.2			
111		.700000 x	15.741598 =	11.019119
6082.1		1.000000 x	106.253931 =	106.253931
112		.140000 x	17.312112 =	2.423696

			T.E =	119.696745
6082.3	6082.3			
111		1.400000 x	15.741598 =	22.038237
6082.1		1.000000 x	106.253931 =	106.253931
112		.280000 x	17.312112 =	4.847391

			T.E =	133.139560
6082.4	6082.4			
111		2.100000 x	15.741598 =	33.057356
112		.420000 x	17.312112 =	7.271087
6082.1		1.000000 x	106.253931 =	106.253931

			T.E =	146.582374
6083.1	6083.1			
111		.280000 x	15.741598 =	4.407647
112		.280000 x	17.312112 =	4.847391
506		.005833 x	668.196857 =	3.897592
112		.140000 x	17.312112 =	2.423696

			T.E =	15.576327
6083.2	6083.2			
111		.560000 x	15.741598 =	8.815295
6083.1		1.000000 x	15.576327 =	15.576327
112		.070000 x	17.312112 =	1.211848

			T.E =	25.603470

6083.3	6083.3			
111		1.120000 x	15.741598 =	17.630590
112		.140000 x	17.312112 =	2.423696
6083.1		1.000000 x	15.576327 =	15.576327

			T.E =	35.630612
6083.4	6083.4			
111		1.680000 x	15.741598 =	26.445885
112		.210000 x	17.312112 =	3.635544
6083.1		1.000000 x	15.576327 =	15.576327

			T.E =	45.657755
6084.1	6084.1			
213		.400000 x	1.949500 =	.779800
111		1.470000 x	15.741598 =	23.140149
116		.700000 x	20.419486 =	14.293640
508		.035000 x	579.356760 =	20.277487
116		1.050000 x	20.419486 =	21.440460

			T.E =	79.931536
6084.2	6084.2			
111		.560000 x	15.741598 =	8.815295
112		.105000 x	17.312112 =	1.817772
6084.1		1.000000 x	79.931536 =	79.931536

			T.E =	90.564603
6084.3	6084.3			
111		1.120000 x	15.741598 =	17.630590
112		.210000 x	17.312112 =	3.635544
6084.1		1.000000 x	79.931536 =	79.931536

			T.E =	101.197669
6084.4	6084.4			
111		1.680000 x	15.741598 =	26.445885
112		.315000 x	17.312112 =	5.453315
6084.1		1.000000 x	79.931536 =	79.931536

			T.E =	111.830736
6085.1	6085.1			
111		.140000 x	15.741598 =	2.203824
506		.004666 x	668.196857 =	3.117807
502		.001400 x	782.814573 =	1.095940
112		.140000 x	17.312112 =	2.423696

			T.E =	8.841266

6085.2	6085.2			
111		.350000 x	15.741598 =	5.509559
112		.070000 x	17.312112 =	1.211848
6085.1		1.000000 x	8.841266 =	8.841266

			T.E =	15.562673
6085.3	6085.3			
111		.700000 x	15.741598 =	11.019119
112		.140000 x	17.312112 =	2.423696
6085.1		1.000000 x	8.841266 =	8.841266

			T.E =	22.284080
6085.4	6085.4			
111		1.050000 x	15.741598 =	16.528678
112		.210000 x	17.312112 =	3.635544
6085.1		1.000000 x	8.841266 =	8.841266

			T.E =	29.005487
6086.1	6086.1			
213		.400000 x	1.949500 =	.779800
508		.008750 x	579.356760 =	5.069372
111		1.120000 x	15.741598 =	17.630590
116		.490000 x	20.419486 =	10.005548
116		.280000 x	20.419486 =	5.717456

			T.E =	39.202766
6086.2	6086.2			
111		.350000 x	15.741598 =	5.509559
112		.105000 x	17.312112 =	1.817772
6086.1		1.000000 x	39.202766 =	39.202766

			T.E =	46.530097
6086.3	6086.3			
111		.700000 x	15.741598 =	11.019119
6086.1		1.000000 x	39.202766 =	39.202766
112		.210000 x	17.312112 =	3.635544

			T.E =	53.857428
6086.4	6086.4			
111		1.050000 x	15.741598 =	16.528678
6086.1		1.000000 x	39.202766 =	39.202766
112		.315000 x	17.312112 =	5.453315

			T.E =	61.184759

6087	6087				
252		.001000 x	290.000000 =	.290000	
113		.210000 x	20.419486 =	4.288092	
112		.350000 x	17.312112 =	6.059239	
111		.210000 x	15.741598 =	3.305736	

			T.E =	13.943067	
6088	6088				
6081.1		1.000000 x	23.407328 =	23.407328	
6081.1		.900000 x	23.407328 =	21.066595	

			T.E =	44.473923	
6089	6089				
6082.1		1.000000 x	106.253931 =	106.253931	
6082.1		.900000 x	106.253931 =	95.628538	

			T.E =	201.882469	
6090	6090				
6083.1		1.000000 x	15.576327 =	15.576327	
6083.1		1.300000 x	15.576327 =	20.249225	

			T.E =	35.825552	
6091	6091				
6084.1		1.000000 x	79.931536 =	79.931536	
6084.1		1.300000 x	79.931536 =	103.910997	

			T.E =	183.842533	
6100	6100				
231		.200000 x	.775000 =	.155000	
111		.175000 x	15.741598 =	2.754780	
251		.002000 x	290.000000 =	.580000	
113		.105000 x	20.419486 =	2.144046	
252.1		.002000 x	.000000 =	.000000	

			T.E =		
6101	6101				
231		15.000000 x	.775000 =	11.625000	
252		.018000 x	290.000000 =	5.220000	
113		3.500000 x	20.419486 =	71.468201	
112		3.500000 x	17.312112 =	60.592392	
252.1		.020000 x	.000000 =	.000000	
251		.068000 x	290.000000 =	19.720000	

			T.E =		

6102	6102				
244		1.000000 x	2.590000 =	2.590000	
112		.002100 x	17.312112 =	.036355	
506		.000070 x	668.196857 =	.046774	
506		.000070 x	668.196857 =	.046774	
509		.000051 x	396.120270 =	.020202	
112		.001400 x	17.312112 =	.024237	

			T.E =	2.764342	
6103	6103				
244		.125000 x	2.590000 =	.323750	
112		.002800 x	17.312112 =	.048474	
509		.000102 x	396.120270 =	.040404	
506		.000140 x	668.196857 =	.093548	
506		.000140 x	668.196857 =	.093548	
112		.004200 x	17.312112 =	.072711	

			T.E =	.672434	
6104	6104				
236		3.000000 x	.612000 =	1.836000	
111		.280000 x	15.741598 =	4.407647	
517		.017500 x	2,166.720745 =	37.917613	
113		.280000 x	20.419486 =	5.717456	

			T.E =	49.878717	
6105	6105				
111		.210000 x	15.741598 =	3.305736	
517		.014000 x	2,166.720745 =	30.334090	
113		.140000 x	20.419486 =	2.858728	

			T.E =	36.498554	
6106	6106				
512		.087500 x	105.407850 =	9.223187	

			T.E =	9.223187	
6107	6107				
513		.087500 x	158.166775 =	13.839593	

			T.E =	13.839593	
6108	6108				
514		.087500 x	212.264620 =	18.573154	

			T.E =	18.573154	

6109	6109			
515		.087500 x	286.274788 =	25.049044

			T.E =	25.049044
6110	6110			
516		.087500 x	364.822456 =	31.921965

			T.E =	31.921965
6120	6120			
112		.004200 x	17.312112 =	.072711
501		.000070 x	600.558852 =	.042039
502		.001750 x	782.814573 =	1.369926

			T.E =	1.484675
6121	6121			
112		.004200 x	17.312112 =	.072711
501		.000049 x	600.558852 =	.029427
509		.003113 x	396.120270 =	1.233122
507		.000875 x	912.951257 =	.798832
505		.000420 x	799.114457 =	.335628
502		.000315 x	782.814573 =	.246587

			T.E =	2.716308
6151	6151			
243		1.020000 x	2.100000 =	2.142000
243		.080000 x	2.100000 =	.168000

			T.E =	2.310000
6152	6152			
112		.085000 x	17.312112 =	1.471530
113		.085000 x	20.419486 =	1.735656

			T.E =	3.207186
6153	6153			
111		.425000 x	15.741598 =	6.690179
112		.425000 x	17.312112 =	7.357648
509		.003570 x	396.120270 =	1.414149
T 611		1.050000 x	20.070537 =	21.074064

			T.E =	36.536040

6154	6154				
111		.425000 x	15.741598 =	6.690179	
112		.425000 x	17.312112 =	7.357648	
T 621		1.050000 x	16.832815 =	17.674456	
509		.003570 x	396.120270 =	1.414149	

			T.E =	33.136432	
6155	6155				
111		.680000 x	15.741598 =	10.704287	
652		.100000 x	149.504950 =	14.950495	
113		1.275000 x	20.419486 =	26.034845	
T 621		.350000 x	16.832815 =	5.891485	
509		.003220 x	396.120270 =	1.275507	

			T.E =	58.856619	
6156	6156				
251		.000500 x	290.000000 =	.145000	
652		.010000 x	149.504950 =	1.495050	
113		.680000 x	20.419486 =	13.885250	
112		.425000 x	17.312112 =	7.357648	

			T.E =	22.882948	
6157	6157				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	396.120270 =	1.164594	
112		.420000 x	17.312112 =	7.271087	
X 621		1.050000 x	13.896722 =	14.591558	

			T.E =	29.638710	
6157.1	6157.1				
111		.420000 x	15.741598 =	6.611471	
509		.002940 x	396.120270 =	1.164594	
X 611		1.050000 x	16.528678 =	17.355112	
112		.420000 x	17.312112 =	7.271087	

			T.E =	32.402264	
6158	6158				
111		.560000 x	15.741598 =	8.815295	
621.1		1.050000 x	15.210448 =	15.970970	
509		.002940 x	396.120270 =	1.164594	
504		.001400 x	375.350290 =	.525490	

			T.E =	26.476349	

6201.1	6201.1			
261.1		1.000000 x	13.500000 =	13.500000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	23.191284
6201.2	6201.2			
261		1.000000 x	15.100000 =	15.100000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	24.791284
6201.3	6201.3			
261.2		1.000000 x	20.700000 =	20.700000
113		.212500 x	20.419486 =	4.339141
111		.340000 x	15.741598 =	5.352143

			T.E =	30.391284
6201.4	6201.4			
262		1.000000 x	26.300000 =	26.300000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	35.991284
6201.5	6201.5			
263		1.000000 x	32.400000 =	32.400000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	58.797781
6201.6	6201.6			
263.2		1.000000 x	46.700000 =	46.700000
111		.850000 x	15.741598 =	13.380358
113		.637500 x	20.419486 =	13.017422

			T.E =	73.097781
6201.7	6201.7			
264		1.000000 x	64.100000 =	64.100000
113		.637500 x	20.419486 =	13.017422
111		.850000 x	15.741598 =	13.380358

			T.E =	90.497781

6202.1	6202.1				
281.1		1.000000 x	17.600000 =	17.600000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	27.291284	
6202.2	6202.2				
281		1.000000 x	21.300000 =	21.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	30.991284	
6202.3	6202.3				
281.2		1.000000 x	26.300000 =	26.300000	
111		.340000 x	15.741598 =	5.352143	
113		.212500 x	20.419486 =	4.339141	

			T.E =	35.991284	
6202.4	6202.4				
282		1.000000 x	30.000000 =	30.000000	
113		.212500 x	20.419486 =	4.339141	
111		.340000 x	15.741598 =	5.352143	

			T.E =	39.691284	
6202.5	6202.5				
283		1.000000 x	36.300000 =	36.300000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	62.697781	
6202.6	6202.6				
283.1		1.000000 x	55.500000 =	55.500000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	81.897781	
6202.7	6202.7				
284		1.000000 x	75.400000 =	75.400000	
111		.850000 x	15.741598 =	13.380358	
113		.637500 x	20.419486 =	13.017422	

			T.E =	101.797781	

6203.1	6203.1			
395.1		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.255000 x	15.741598 =	4.014107

			T.E =	
6203.2	6203.2			
395.2		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.3	6203.3			
395.3		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6203.4	6203.4			
395.4		1.000000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
113		.212500 x	20.419486 =	4.339141

			T.E =	
6204	6204			
111		.210000 x	15.741598 =	3.305736
X 625		.700000 x	17.608655 =	12.326059
X 623		.400000 x	15.018060 =	6.007224
509		.005439 x	396.120270 =	2.154498
509		.003108 x	396.120270 =	1.231142
112		.420000 x	17.312112 =	7.271087

			T.E =	32.295745
6204.1	6204.1			
111		.210000 x	15.741598 =	3.305736
112		.420000 x	17.312112 =	7.271087
509		.008702 x	396.120270 =	3.447039
613		1.050000 x	5.463416 =	5.736587

			T.E =	19.760448

6205	6205				
111		.210000 x	15.741598 =	3.305736	
112		.070000 x	17.312112 =	1.211848	
509		.002800 x	396.120270 =	1.109137	
613		1.000000 x	5.463416 =	5.463416	

			T.E =	11.090136	
6251	6251				
509		.002800 x	396.120270 =	1.109137	
613		1.000000 x	5.463416 =	5.463416	

			T.E =	6.572553	
6252	6252				
509		.000784 x	396.120270 =	.310558	

			T.E =	.310558	
6253	6253				
112		.210000 x	17.312112 =	3.635544	
X 630.1		.200000 x	1.620878 =	.324176	
X 630		.200000 x	1.475710 =	.295142	
521		.007000 x	417.198773 =	2.920391	
501		.002917 x	600.558852 =	1.751830	

			T.E =	8.927083	
6301	6301				
231		.200000 x	.775000 =	.155000	
252		.002500 x	290.000000 =	.725000	
111		.170000 x	15.741598 =	2.676072	
113		.127500 x	20.419486 =	2.603484	
251		.001500 x	290.000000 =	.435000	

			T.E =	6.594556	
6302	6302				
231		.300000 x	.775000 =	.232500	
251		.002000 x	290.000000 =	.580000	
252		.004000 x	290.000000 =	1.160000	
111		.212500 x	15.741598 =	3.345090	
113		1.232500 x	20.419486 =	25.167016	

			T.E =	30.484606	
6303	6303				
6302		.666660 x	30.484606 =	20.322867	

			T.E =	20.322867	

6304	6304				
234.2		.018000 x	.901300 =	.016223	
112		.212500 x	17.312112 =	3.678824	
113		.085000 x	20.419486 =	1.735656	
113		.010200 x	20.419486 =	.208279	
235		.012000 x	.643000 =	.007716	

			T.E =	5.646698	
6310	6310				
233		1.050000 x	.583300 =	.612465	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.480293	
6311	6311				
233.1		1.050000 x	.583300 =	.612465	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.480293	
6312	6312				
233.3		1.010000 x	7.950000 =	8.029500	
233.3		.303000 x	7.950000 =	2.408850	
113		.085000 x	20.419486 =	1.735656	
113		.085000 x	20.419486 =	1.735656	

			T.E =	13.909663	
6313	6313				
233.2		1.050000 x	.639200 =	.671160	
113		.025500 x	20.419486 =	.520697	

			T.E =	1.191857	
6314	6314				
233.2		1.050000 x	.639200 =	.671160	
113		.068000 x	20.419486 =	1.388525	

			T.E =	2.059685	
6320.1	6320.1				
396.1		1.000000 x	1.400000 =	1.400000	
113		.000850 x	20.419486 =	.017357	

			T.E =	1.417357	

6320.2	6320.2			
396.2		1.000000 x	.770000 =	.770000
113		.000850 x	20.419486 =	.017357

			T.E =	.787357
6320.3	6320.3			
396.3		1.000000 x	1.680000 =	1.680000
113		.000850 x	20.419486 =	.017357

			T.E =	1.697357
6320.4	6320.4			
396.4		1.000000 x	.980000 =	.980000
113		.000850 x	20.419486 =	.017357

			T.E =	.997357
6320.5	6320.5			
396.5		1.000000 x	1.180000 =	1.180000
113		.000850 x	20.419486 =	.017357

			T.E =	1.197357
6320.6	6320.6			
396.6		1.000000 x	1.580000 =	1.580000
113		.000850 x	20.419486 =	.017357

			T.E =	1.597357
6321	6321			
221		140.000000 x	.099900 =	13.986000
111		.765000 x	15.741598 =	12.042322
113		.595000 x	20.419486 =	12.149594
509		.003302 x	396.120270 =	1.307989
509		.003019 x	396.120270 =	1.195887
T 630.1		.175000 x	1.968209 =	.344437
T 630		.175000 x	1.791933 =	.313588
T 625		.350000 x	21.340163 =	7.469057
T 623		.560000 x	18.194441 =	10.188887
T 621		.300000 x	16.832815 =	5.049845
511		.023800 x	725.748703 =	17.272819
509		.005284 x	396.120270 =	2.093100
112		.714000 x	17.312112 =	12.360848

			T.E =	95.774373

6322	6322			
221		140.000000 x	.099900 =	13.986000
509		.003019 x	396.120270 =	1.195887
T 623		.560000 x	18.194441 =	10.188887
T 630.1		.175000 x	1.968209 =	.344437
T 630		.175000 x	1.791933 =	.313588
T 625		.350000 x	21.340163 =	7.469057
511		.023800 x	725.748703 =	17.272819
T 611		.300000 x	20.070537 =	6.021161
509		.003302 x	396.120270 =	1.307989
509		.005284 x	396.120270 =	2.093100
113		.595000 x	20.419486 =	12.149594
111		.765000 x	15.741598 =	12.042322
112		.714000 x	17.312112 =	12.360848

T.E = 96.745689

6323	6323			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 105.699854

6323.1	6323.1			
221		150.000000 x	.099900 =	14.985000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		.850000 x	20.419486 =	17.356563

T.E = 98.172826

6324	6324			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
112		1.020000 x	17.312112 =	17.658354
509		.004718 x	396.120270 =	1.868895
113		.850000 x	20.419486 =	17.356563
509		.007548 x	396.120270 =	2.989916

T.E = 110.694854

6324.1	6324.1			
221		200.000000 x	.099900 =	19.980000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		.850000 x	20.419486 =	17.356563

T.E = 103.167826

6325	6325			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		.850000 x	20.419486 =	17.356563
112		1.020000 x	17.312112 =	17.658354

T.E = 115.689854

6325.1	6325.1			
221		250.000000 x	.099900 =	24.975000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		1.020000 x	17.312112 =	17.658354
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		.850000 x	20.419486 =	17.356563

T.E = 108.162826

6326	6326			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		1.360000 x	20.419486 =	27.770501
112		1.190000 x	17.312112 =	20.601413

T.E = 134.041851

6326.1	6326.1			
221		300.000000 x	.099900 =	29.970000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		1.190000 x	17.312112 =	20.601413
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		1.360000 x	20.419486 =	27.770501

T.E = 126.514823

6327	6327			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		1.275000 x	20.419486 =	26.034845
112		2.295000 x	17.312112 =	39.731297

T.E = 156.326079

6327.1	6327.1			
222		300.000000 x	.116200 =	34.860000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		1.275000 x	20.419486 =	26.034845

T.E = 148.799050

6328	6328			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	396.120270 =	2.989916
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	396.120270 =	1.868895

T.E = 159.902391

6328.1	6328.1			
221		350.000000 x	.099900 =	34.965000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
112		2.295000 x	17.312112 =	39.731297
509		.007548 x	396.120270 =	2.989916
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
113		1.445000 x	20.419486 =	29.506157

T.E = 152.375363

6329	6329			
222		350.000000 x	.116200 =	40.670000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 165.607391

6329.1	6329.1			
222		350.000000 x	.116200 =	40.670000
511		.034000 x	725.748703 =	24.675456
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895
113		1.445000 x	20.419486 =	29.506157
112		2.295000 x	17.312112 =	39.731297

T.E = 158.080363

6329.2	6329.2			
223		350.000000 x	.119300 =	41.755000
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895

T.E = 166.692391

6329.3	6329.3			
223		350.000000 x	.119300 =	41.755000
T 630		.250000 x	1.791933 =	.447983
T 630.1		.250000 x	1.968209 =	.492052
511		.034000 x	725.748703 =	24.675456
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

T.E = 159.165363

6330	6330			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.042500 x	725.748703 =	30.844320
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895
112		2.295000 x	17.312112 =	39.731297
113		1.445000 x	20.419486 =	29.506157

T.E = 181.212255

6330.1	6330.1			
223		420.000000 x	.119300 =	50.106000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
113		1.445000 x	20.419486 =	29.506157
509		.004718 x	396.120270 =	1.868895
511		.042500 x	725.748703 =	30.844320
509		.007548 x	396.120270 =	2.989916
112		2.295000 x	17.312112 =	39.731297

T.E = 173.685227

6331	6331			
222		450.000000 x	.116200 =	52.290000
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.042500 x	725.748703 =	30.844320
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		5.525000 x	20.419486 =	112.817660
112		3.400000 x	17.312112 =	58.861181
111		3.825000 x	15.741598 =	60.211612

T.E = 346.049254

6331.1	6331.1			
222		450.000000 x	.116200 =	52.290000
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
511		.042500 x	725.748703 =	30.844320
113		5.525000 x	20.419486 =	112.817660
111		3.825000 x	15.741598 =	60.211612
112		3.400000 x	17.312112 =	58.861181

T.E = 338.522226

6351	6351			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.594556 =	6.594556
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.450000 x	21.340163 =	9.603073
511		.034000 x	725.748703 =	24.675456
509		.008020 x	396.120270 =	3.176885
113		1.275000 x	20.419486 =	26.034845
T 623		.850000 x	18.194441 =	15.465275
509		.004246 x	396.120270 =	1.681927
112		1.275000 x	17.312112 =	22.072943

T.E = 122.232994

6351.1	6351.1			
221		120.000000 x	.099900 =	11.988000
6301		1.000000 x	6.594556 =	6.594556
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.850000 x	18.194441 =	15.465275
T 617		.450000 x	6.286106 =	2.828748
511		.034000 x	725.748703 =	24.675456
509		.008020 x	396.120270 =	3.176885
509		.004246 x	396.120270 =	1.681927
113		1.275000 x	20.419486 =	26.034845
112		1.275000 x	17.312112 =	22.072943

T.E = 115.458669

6352	6352			
221		300.000000 x	.099900 =	29.970000
6301		1.000000 x	6.594556 =	6.594556
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 625		.500000 x	21.340163 =	10.670082
T 623		.800000 x	18.194441 =	14.555553
511		.034000 x	725.748703 =	24.675456
509		.004718 x	396.120270 =	1.868895
509		.007548 x	396.120270 =	2.989916
113		2.550000 x	20.419486 =	52.069689
112		2.125000 x	17.312112 =	36.788238

T.E = 181.122420

6352.1	6352.1			
221		300.000000 x	.099900 =	29.970000
112		2.125000 x	17.312112 =	36.788238
113		2.550000 x	20.419486 =	52.069689
6301		1.000000 x	6.594556 =	6.594556
T 630.1		.250000 x	1.968209 =	.492052
T 630		.250000 x	1.791933 =	.447983
T 623		.800000 x	18.194441 =	14.555553
T 617		.500000 x	6.286106 =	3.143053
511		.034000 x	725.748703 =	24.675456
509		.007548 x	396.120270 =	2.989916
509		.004718 x	396.120270 =	1.868895
			T.E =	173.595392
6360.1	6360.1			
6360.1 A1		1.000000 x	113.198454 =	113.198454
6360.1 A5		1.000000 x	99.500235 =	99.500235
6360.1 A4		1.000000 x	32.229749 =	32.229749
6360.1 A3		1.000000 x	14.510547 =	14.510547
6360.1 A2		1.000000 x	8.067561 =	8.067561
			AΘΡΟΙΣΜΑ =	267.506546
	T.E =	.200000 x	267.506546 =	53.501309
6360.2	6360.2			
6360.2 A1		1.000000 x	121.692502 =	121.692502
6360.2 A2		1.000000 x	11.206335 =	11.206335
6360.2 A3		1.000000 x	18.904731 =	18.904731
6360.2 A5		1.000000 x	113.381925 =	113.381925
6360.2 A4		1.000000 x	35.480457 =	35.480457
			AΘΡΟΙΣΜΑ =	300.665950
	T.E =	.200000 x	300.665950 =	60.133190
6360.3	6360.3			
6360.3 A1		1.000000 x	161.315635 =	161.315635
6360.3 A2		1.000000 x	15.899261 =	15.899261
6360.3 A3		1.000000 x	42.643313 =	42.643313
6360.3 A5		1.000000 x	156.824252 =	156.824252
6360.3 A4		1.000000 x	42.481950 =	42.481950
			AΘΡΟΙΣΜΑ =	419.164411
	T.E =	.200000 x	419.164411 =	83.832882

6360.4	6360.4				
6360.4 A1		1.000000 x	211.583603 =	211.583603	
6360.4 A3		1.000000 x	63.932466 =	63.932466	
6360.4 A2		1.000000 x	21.553728 =	21.553728	
6360.4 A4		1.000000 x	35.480457 =	35.480457	
6360.4 A5		1.000000 x	211.627197 =	211.627197	

			AΘΡΟΙΣΜΑ =	544.177451	
	T.E =	.200000 x	544.177451 =	108.835490	

6360.5	6360.5				
6360.5 A1		1.000000 x	242.454354 =	242.454354	
6360.5 A2		1.000000 x	26.895731 =	26.895731	
6360.5 A5		1.000000 x	289.604692 =	289.604692	
6360.5 A4		1.000000 x	36.738981 =	36.738981	
6360.5 A3		1.000000 x	71.005467 =	71.005467	

			AΘΡΟΙΣΜΑ =	666.699225	
	T.E =	.200000 x	666.699225 =	133.339845	

6360.6	6360.6				
6360.6 A1		1.000000 x	294.884498 =	294.884498	
6360.6 A5		1.000000 x	382.646556 =	382.646556	
6360.6 A4		1.000000 x	35.480457 =	35.480457	
6360.6 A3		1.000000 x	83.437345 =	83.437345	
6360.6 A2		1.000000 x	40.418846 =	40.418846	

			AΘΡΟΙΣΜΑ =	836.867702	
	T.E =	.200000 x	836.867702 =	167.373540	

6361	6361				
396.7		.100000 x	3.800000 =	.380000	
113		.017000 x	20.419486 =	.347131	
111		.085000 x	15.741598 =	1.338036	

			T.E =	2.065167	
6370	6370				
396.10		.650000 x	6.940000 =	4.511000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	
396.14		.003000 x	38.800000 =	.116400	

			T.E =	16.922169	
6371	6371				
326		.500000 x	1.310000 =	.655000	
113		.212500 x	20.419486 =	4.339141	
111		.212500 x	15.741598 =	3.345090	

			T.E =	8.339230	

6372	6372				
396.11		1.050000 x	2.560000 =	2.688000	
396.13		.700000 x	1.770000 =	1.239000	
111		.340000 x	15.741598 =	5.352143	
113		.340000 x	20.419486 =	6.942625	

			T.E =	16.221769	
6373	6373				
396.12		1.050000 x	3.680000 =	3.864000	
396.13		.700000 x	1.770000 =	1.239000	
113		.425000 x	20.419486 =	8.678282	
111		.425000 x	15.741598 =	6.690179	

			T.E =	20.471461	
6401	6401				
327		.500000 x	.540000 =	.270000	
113		.212500 x	20.419486 =	4.339141	

			T.E =	4.609141	
6402	6402				
252		.000500 x	290.000000 =	.145000	
111		.595000 x	15.741598 =	9.366251	
113		.595000 x	20.419486 =	12.149594	
652		.011500 x	149.504950 =	1.719307	
652.2		.005500 x	169.447796 =	.931963	

			T.E =	24.312115	
6403	6403				
251		.000500 x	290.000000 =	.145000	
111		.850000 x	15.741598 =	13.380358	
113		.850000 x	20.419486 =	17.356563	
652.2		.005500 x	169.447796 =	.931963	
652		.016500 x	149.504950 =	2.466832	

			T.E =	34.280716	
6404	6404				
111		1.275000 x	15.741598 =	20.070537	
113		1.700000 x	20.419486 =	34.713126	
652		.020000 x	149.504950 =	2.990099	

			T.E =	57.773763	
6404.1	6404.1				
397.8		54.000000 x	.000000 =	.000000	
6404		1.000000 x	57.773763 =	57.773763	

			T.E =		

6405	6405			
111		.425000 x	15.741598 =	6.690179
113		.850000 x	20.419486 =	17.356563
652		.020000 x	149.504950 =	2.990099

			T.E =	27.036841
6451.1	6451.1			
386.1		1.000000 x	.000000 =	.000000
386.1		.150000 x	.000000 =	.000000

			T.E =	
6451.10	6451.10			
386.10		1.000000 x	.000000 =	.000000
386.10		.150000 x	.000000 =	.000000

			T.E =	
6451.11	6451.11			
386.11		1.000000 x	.000000 =	.000000
386.11		.150000 x	.000000 =	.000000

			T.E =	
6451.12	6451.12			
386.12		1.000000 x	.000000 =	.000000
386.12		.150000 x	.000000 =	.000000

			T.E =	
6451.13	6451.13			
386.13		1.000000 x	.000000 =	.000000
386.13		.150000 x	.000000 =	.000000

			T.E =	
6451.14	6451.14			
386.14		1.000000 x	.000000 =	.000000
386.14		.150000 x	.000000 =	.000000

			T.E =	
6451.15	6451.15			
386.15		1.000000 x	.000000 =	.000000
386.15		.150000 x	.000000 =	.000000

			T.E =	

6451.16	6451.16			
386.16		1.000000 x	.000000 =	.000000
386.16		.150000 x	.000000 =	.000000

			T.E =	
6451.17	6451.17			
386.17		1.000000 x	.000000 =	.000000
386.17		.150000 x	.000000 =	.000000

			T.E =	
6451.18	6451.18			
386.18		1.000000 x	.000000 =	.000000
386.18		.150000 x	.000000 =	.000000

			T.E =	
6451.19	6451.19			
386.19		1.000000 x	.000000 =	.000000
386.19		.150000 x	.000000 =	.000000

			T.E =	
6451.2	6451.2			
386.2		1.000000 x	.000000 =	.000000
386.2		.150000 x	.000000 =	.000000

			T.E =	
6451.20	6451.20			
386.20		1.000000 x	.000000 =	.000000
386.20		.150000 x	.000000 =	.000000

			T.E =	
6451.21	6451.21			
386.21		1.000000 x	.000000 =	.000000
386.21		.150000 x	.000000 =	.000000

			T.E =	
6451.3	6451.3			
386.3		1.000000 x	.000000 =	.000000
386.3		.150000 x	.000000 =	.000000

			T.E =	

6451.4	6451.4			
386.4		1.000000 x	.000000 =	.000000
386.4		.150000 x	.000000 =	.000000

			T.E =	
6451.5	6451.5			
386.5		1.000000 x	.000000 =	.000000
386.5		.150000 x	.000000 =	.000000

			T.E =	
6451.6	6451.6			
386.6		1.000000 x	.000000 =	.000000
386.6		.150000 x	.000000 =	.000000

			T.E =	
6451.7	6451.7			
386.7		1.000000 x	.000000 =	.000000
386.7		.150000 x	.000000 =	.000000

			T.E =	
6451.8	6451.8			
386.8		1.000000 x	.000000 =	.000000
386.8		.150000 x	.000000 =	.000000

			T.E =	
6451.9	6451.9			
386.9		1.000000 x	24,668.000000 =	24,668.000000
386.9		.150000 x	24,668.000000 =	3,700.200000

			T.E =	28,368.200000
6452.1	6452.1			
386.22		1.000000 x	.000000 =	.000000
386.22		.150000 x	.000000 =	.000000

			T.E =	
6452.10	6452.10			
386.31		1.000000 x	.000000 =	.000000
386.31		.150000 x	.000000 =	.000000

			T.E =	

6452.11	6452.11			
386.32		1.000000 x	.000000 =	.000000
386.32		.150000 x	.000000 =	.000000

			T.E =	
6452.12	6452.12			
386.33		1.000000 x	.000000 =	.000000
386.33		.150000 x	.000000 =	.000000

			T.E =	
6452.13	6452.13			
386.34		1.000000 x	.000000 =	.000000
386.34		.150000 x	.000000 =	.000000

			T.E =	
6452.14	6452.14			
386.35		1.000000 x	.000000 =	.000000
386.35		.150000 x	.000000 =	.000000

			T.E =	
6452.15	6452.15			
386.36		1.000000 x	.000000 =	.000000
386.36		.150000 x	.000000 =	.000000

			T.E =	
6452.16	6452.16			
386.37		1.000000 x	.000000 =	.000000
386.37		.150000 x	.000000 =	.000000

			T.E =	
6452.17	6452.17			
386.38		1.000000 x	.000000 =	.000000
386.38		.150000 x	.000000 =	.000000

			T.E =	
6452.18	6452.18			
386.39		1.000000 x	.000000 =	.000000
386.39		.150000 x	.000000 =	.000000

			T.E =	

6452.19	6452.19			
386.40		1.000000 x	73,850.000000 =	73,850.000000
386.40		.150000 x	73,850.000000 =	11,077.500000

			T.E =	84,927.500000
6452.2	6452.2			
386.23		1.000000 x	.000000 =	.000000
386.23		.150000 x	.000000 =	.000000

			T.E =	
6452.20	6452.20			
386.41		1.000000 x	.000000 =	.000000
386.41		.150000 x	.000000 =	.000000

			T.E =	
6452.21	6452.21			
386.42		1.000000 x	.000000 =	.000000
386.42		.150000 x	.000000 =	.000000

			T.E =	
6452.22	6452.22			
386.43		1.000000 x	.000000 =	.000000
386.43		.150000 x	.000000 =	.000000

			T.E =	
6452.23	6452.23			
386.44		1.000000 x	.000000 =	.000000
386.44		.150000 x	.000000 =	.000000

			T.E =	
6452.24	6452.24			
386.45		1.000000 x	.000000 =	.000000
386.45		.150000 x	.000000 =	.000000

			T.E =	
6452.25	6452.25			
386.46		1.000000 x	.000000 =	.000000
386.46		.150000 x	.000000 =	.000000

			T.E =	

6452.26	6452.26			
386.47		1.000000 x	.000000 =	.000000
386.47		.150000 x	.000000 =	.000000

			T.E =	
6452.3	6452.3			
386.24		1.000000 x	.000000 =	.000000
386.24		.150000 x	.000000 =	.000000

			T.E =	
6452.4	6452.4			
386.25		1.000000 x	.000000 =	.000000
386.25		.150000 x	.000000 =	.000000

			T.E =	
6452.5	6452.5			
386.26		1.000000 x	.000000 =	.000000
386.26		.150000 x	.000000 =	.000000

			T.E =	
6452.6	6452.6			
386.27		1.000000 x	.000000 =	.000000
386.27		.150000 x	.000000 =	.000000

			T.E =	
6452.7	6452.7			
386.28		1.000000 x	.000000 =	.000000
386.28		.150000 x	.000000 =	.000000

			T.E =	
6452.8	6452.8			
386.29		1.000000 x	.000000 =	.000000
386.29		.150000 x	.000000 =	.000000

			T.E =	
6452.9	6452.9			
386.30		1.000000 x	108,702.000000 =	108,702.000000
386.30		.150000 x	108,702.000000 =	16,305.300000

			T.E =	125,007.300000

6453.1	6453.1			
386.48		1.000000 x	.000000 =	.000000
386.48		.150000 x	.000000 =	.000000

			T.E =	
6453.10	6453.10			
386.57		1.000000 x	.000000 =	.000000
386.57		.150000 x	.000000 =	.000000

			T.E =	
6453.11	6453.11			
386.58		1.000000 x	.000000 =	.000000
386.58		.150000 x	.000000 =	.000000

			T.E =	
6453.12	6453.12			
386.59		1.000000 x	.000000 =	.000000
386.59		.150000 x	.000000 =	.000000

			T.E =	
6453.13	6453.13			
386.60		1.000000 x	.000000 =	.000000
386.60		.150000 x	.000000 =	.000000

			T.E =	
6453.14	6453.14			
386.61		1.000000 x	.000000 =	.000000
386.61		.150000 x	.000000 =	.000000

			T.E =	
6453.15	6453.15			
386.62		1.000000 x	.000000 =	.000000
386.62		.150000 x	.000000 =	.000000

			T.E =	
6453.16	6453.16			
386.63		1.000000 x	.000000 =	.000000
386.63		.150000 x	.000000 =	.000000

			T.E =	

6453.17	6453.17				
386.64		1.000000 x	147,712.000000 =		147,712.000000
386.64		.150000 x	147,712.000000 =		22,156.800000
				T.E =	169,868.800000
6453.18	6453.18				
386.65		1.000000 x	.000000 =		.000000
386.65		.150000 x	.000000 =		.000000
				T.E =	
6453.19	6453.19				
386.66		1.000000 x	.000000 =		.000000
386.66		.150000 x	.000000 =		.000000
				T.E =	
6453.2	6453.2				
386.49		1.000000 x	.000000 =		.000000
386.49		.150000 x	.000000 =		.000000
				T.E =	
6453.20	6453.20				
386.67		1.000000 x	.000000 =		.000000
386.67		.150000 x	.000000 =		.000000
				T.E =	
6453.3	6453.3				
386.50		1.000000 x	.000000 =		.000000
386.50		.150000 x	.000000 =		.000000
				T.E =	
6453.4	6453.4				
386.51		1.000000 x	.000000 =		.000000
386.51		.150000 x	.000000 =		.000000
				T.E =	
6453.5	6453.5				
386.52		1.000000 x	.000000 =		.000000
386.52		.150000 x	.000000 =		.000000
				T.E =	

6453.6	6453.6			
386.53		1.000000 x	128,861.000000 =	128,861.000000
386.53		.150000 x	128,861.000000 =	19,329.150000

			T.E =	148,190.150000
6453.7	6453.7			
386.54		1.000000 x	.000000 =	.000000
386.54		.150000 x	.000000 =	.000000

			T.E =	
6453.8	6453.8			
386.55		1.000000 x	.000000 =	.000000
386.55		.150000 x	.000000 =	.000000

			T.E =	
6453.9	6453.9			
386.56		1.000000 x	.000000 =	.000000
386.56		.150000 x	.000000 =	.000000

			T.E =	
6454.1	6454.1			
386.68		1.000000 x	.000000 =	.000000
386.68		.150000 x	.000000 =	.000000

			T.E =	
6454.10	6454.10			
386.77		1.000000 x	.000000 =	.000000
386.77		.150000 x	.000000 =	.000000

			T.E =	
6454.11	6454.11			
386.78		1.000000 x	.000000 =	.000000
386.78		.150000 x	.000000 =	.000000

			T.E =	
6454.12	6454.12			
386.79		1.000000 x	.000000 =	.000000
386.79		.150000 x	.000000 =	.000000

			T.E =	

6454.13	6454.13			
386.80		1.000000 x	.000000 =	.000000
386.80		.150000 x	.000000 =	.000000

			T.E =	
6454.14	6454.14			
386.81		1.000000 x	.000000 =	.000000
386.81		.150000 x	.000000 =	.000000

			T.E =	
6454.15	6454.15			
386.82		1.000000 x	.000000 =	.000000
386.82		.150000 x	.000000 =	.000000

			T.E =	
6454.16	6454.16			
386.83		1.000000 x	.000000 =	.000000
386.83		.150000 x	.000000 =	.000000

			T.E =	
6454.2	6454.2			
386.69		1.000000 x	.000000 =	.000000
386.69		.150000 x	.000000 =	.000000

			T.E =	
6454.3	6454.3			
386.70		1.000000 x	.000000 =	.000000
386.70		.150000 x	.000000 =	.000000

			T.E =	
6454.4	6454.4			
386.71		1.000000 x	.000000 =	.000000
386.71		.150000 x	.000000 =	.000000

			T.E =	
6454.5	6454.5			
386.72		1.000000 x	.000000 =	.000000
386.72		.150000 x	.000000 =	.000000

			T.E =	

6454.6	6454.6			
386.73		1.000000 x	.000000 =	.000000
386.73		.150000 x	.000000 =	.000000

			T.E =	
6454.7	6454.7			
386.74		1.000000 x	.000000 =	.000000
386.74		.150000 x	.000000 =	.000000

			T.E =	
6454.8	6454.8			
386.75		1.000000 x	.000000 =	.000000
386.75		.150000 x	.000000 =	.000000

			T.E =	
6454.9	6454.9			
386.76		1.000000 x	.000000 =	.000000
386.76		.150000 x	.000000 =	.000000

			T.E =	
6455.1	6455.1			
387.1		1.000000 x	.000000 =	.000000
387.1		.100000 x	.000000 =	.000000

			T.E =	
6455.2	6455.2			
387.2		1.000000 x	.000000 =	.000000
387.2		.100000 x	.000000 =	.000000

			T.E =	
6455.3	6455.3			
387.3		1.000000 x	20,690.000000 =	20,690.000000
387.3		.100000 x	20,690.000000 =	2,069.000000

			T.E =	22,759.000000
6455.4	6455.4			
387.4		1.000000 x	.000000 =	.000000
387.4		.100000 x	.000000 =	.000000

			T.E =	

6455.5	6455.5			
387.5		1.000000 x	.000000 =	.000000
387.5		.100000 x	.000000 =	.000000

			T.E =	
6455.6	6455.6			
387.6		1.000000 x	.000000 =	.000000
387.6		.100000 x	.000000 =	.000000

			T.E =	
6455.7	6455.7			
387.7		1.000000 x	.000000 =	.000000
387.7		.100000 x	.000000 =	.000000

			T.E =	
6456.1	6456.1			
234.2		208.000000 x	.901300 =	187.470400
113		154.700001 x	20.419486 =	3,158.894505
235		338.000000 x	.643000 =	217.334000

			AΘΡΟΙΣΜΑ =	3,563.698905

			T.E =	5,345.548357
6456.2	6456.2			
234.2		336.000000 x	.901300 =	302.836800
113		249.900000 x	20.419486 =	5,102.829551
235		546.000000 x	.643000 =	351.078000

			AΘΡΟΙΣΜΑ =	5,756.744351

			T.E =	8,059.442092
6456.3	6456.3			
234.2		384.000000 x	.901300 =	346.099200
235		624.000000 x	.643000 =	401.232000
113		285.599998 x	20.419486 =	5,831.805161

			AΘΡΟΙΣΜΑ =	6,579.136361

			T.E =	9,210.790905
6457	6457			
252.2		1.100000 x	.000000 =	.000000
113		17.000000 x	20.419486 =	347.131262

			T.E =	

6458.1	6458.1			
388.1		1.000000 x	.000000 =	.000000
388.1		.150000 x	.000000 =	.000000

			T.E =	
6458.10	6458.10			
388.10		1.000000 x	.000000 =	.000000
388.10		.150000 x	.000000 =	.000000

			T.E =	
6458.11	6458.11			
388.11		1.000000 x	.000000 =	.000000
388.11		.150000 x	.000000 =	.000000

			T.E =	
6458.12	6458.12			
388.12		1.000000 x	.000000 =	.000000
388.12		.150000 x	.000000 =	.000000

			T.E =	
6458.2	6458.2			
388.2		1.000000 x	.000000 =	.000000
388.2		.150000 x	.000000 =	.000000

			T.E =	
6458.3	6458.3			
388.3		1.000000 x	.000000 =	.000000
388.3		.150000 x	.000000 =	.000000

			T.E =	
6458.4	6458.4			
388.4		1.000000 x	.000000 =	.000000
388.4		.150000 x	.000000 =	.000000

			T.E =	
6458.5	6458.5			
388.5		1.000000 x	.000000 =	.000000
388.5		.150000 x	.000000 =	.000000

			T.E =	

6458.6	6458.6			
388.6		1.000000 x	.000000 =	.000000
388.6		.150000 x	.000000 =	.000000

			T.E =	
6458.7	6458.7			
388.7		1.000000 x	.000000 =	.000000
388.7		.150000 x	.000000 =	.000000

			T.E =	
6458.8	6458.8			
388.8		1.000000 x	.000000 =	.000000
388.8		.150000 x	.000000 =	.000000

			T.E =	
6458.9	6458.9			
388.9		1.000000 x	.000000 =	.000000
388.9		.150000 x	.000000 =	.000000

			T.E =	
6459.1	6459.1			
389.1		1.000000 x	.000000 =	.000000
389.1		.200000 x	.000000 =	.000000

			T.E =	
6459.2	6459.2			
389.2		1.000000 x	.000000 =	.000000
389.2		.200000 x	.000000 =	.000000

			T.E =	
6459.3	6459.3			
389.3		1.000000 x	.000000 =	.000000
389.3		.200000 x	.000000 =	.000000

			T.E =	
6459.4	6459.4			
389.4		1.000000 x	6,406.000000 =	6,406.000000
389.4		.200000 x	6,406.000000 =	1,281.200000

			T.E =	7,687.200000

6459.5	6459.5			
389.5		1.000000 x	.000000 =	.000000
389.5		.200000 x	.000000 =	.000000

			T.E =	
6459.6	6459.6			
389.6		1.000000 x	.000000 =	.000000
389.6		.200000 x	.000000 =	.000000

			T.E =	
6459.7	6459.7			
389.7		1.000000 x	.000000 =	.000000
389.7		.200000 x	.000000 =	.000000

			T.E =	
6459.8	6459.8			
389.8		1.000000 x	.000000 =	.000000
389.8		.200000 x	.000000 =	.000000

			T.E =	
6459.9	6459.9			
389.9		1.000000 x	.000000 =	.000000
389.9		.200000 x	.000000 =	.000000

			T.E =	
6470.1	6470.1			
390.1		1.000000 x	.000000 =	.000000
390.1		.150000 x	.000000 =	.000000

			T.E =	
6470.10	6470.10			
390.10		1.000000 x	.000000 =	.000000
390.10		.150000 x	.000000 =	.000000

			T.E =	
6470.11	6470.11			
390.11		1.000000 x	.000000 =	.000000
390.11		.150000 x	.000000 =	.000000

			T.E =	

6470.12	6470.12			
390.12		1.000000 x	.000000 =	.000000
390.12		.150000 x	.000000 =	.000000

			T.E =	
6470.13	6470.13			
390.13		1.000000 x	.000000 =	.000000
390.13		.150000 x	.000000 =	.000000

			T.E =	
6470.14	6470.14			
390.14		1.000000 x	5,412.000000 =	5,412.000000
390.14		.150000 x	5,412.000000 =	811.800000

			T.E =	6,223.800000
6470.15	6470.15			
390.15		1.000000 x	.000000 =	.000000
390.15		.150000 x	.000000 =	.000000

			T.E =	
6470.16	6470.16			
390.16		1.000000 x	.000000 =	.000000
390.16		.150000 x	.000000 =	.000000

			T.E =	
6470.17	6470.17			
390.17		1.000000 x	.000000 =	.000000
390.17		.150000 x	.000000 =	.000000

			T.E =	
6470.18	6470.18			
390.18		1.000000 x	.000000 =	.000000
390.18		.150000 x	.000000 =	.000000

			T.E =	
6470.19	6470.19			
390.19		1.000000 x	.000000 =	.000000
390.19		.150000 x	.000000 =	.000000

			T.E =	

6470.2	6470.2			
390.2		1.000000 x	.000000 =	.000000
390.2		.150000 x	.000000 =	.000000

			T.E =	
6470.20	6470.20			
390.20		1.000000 x	.000000 =	.000000
390.20		.150000 x	.000000 =	.000000

			T.E =	
6470.21	6470.21			
390.21		1.000000 x	.000000 =	.000000
390.21		.150000 x	.000000 =	.000000

			T.E =	
6470.22	6470.22			
390.22		1.000000 x	.000000 =	.000000
390.22		.150000 x	.000000 =	.000000

			T.E =	
6470.23	6470.23			
390.23		1.000000 x	.000000 =	.000000
390.23		.150000 x	.000000 =	.000000

			T.E =	
6470.24	6470.24			
390.24		1.000000 x	.000000 =	.000000
390.24		.150000 x	.000000 =	.000000

			T.E =	
6470.25	6470.25			
390.25		1.000000 x	.000000 =	.000000
390.25		.150000 x	.000000 =	.000000

			T.E =	
6470.26	6470.26			
390.26		1.000000 x	.000000 =	.000000
390.26		.150000 x	.000000 =	.000000

			T.E =	

6470.27	6470.27			
390.27		1.000000 x	.000000 =	.000000
390.27		.150000 x	.000000 =	.000000

			T.E =	
6470.28	6470.28			
390.28		1.000000 x	.000000 =	.000000
390.28		.150000 x	.000000 =	.000000

			T.E =	
6470.29	6470.29			
390.29		1.000000 x	.000000 =	.000000
390.29		.150000 x	.000000 =	.000000

			T.E =	
6470.3	6470.3			
390.3		1.000000 x	.000000 =	.000000
390.3		.150000 x	.000000 =	.000000

			T.E =	
6470.30	6470.30			
390.30		1.000000 x	.000000 =	.000000
390.30		.150000 x	.000000 =	.000000

			T.E =	
6470.31	6470.31			
390.31		1.000000 x	7,871.000000 =	7,871.000000
390.31		.150000 x	7,871.000000 =	1,180.650000

			T.E =	9,051.650000
6470.32	6470.32			
390.32		1.000000 x	.000000 =	.000000
390.32		.150000 x	.000000 =	.000000

			T.E =	
6470.33	6470.33			
390.33		1.000000 x	.000000 =	.000000
390.33		.150000 x	.000000 =	.000000

			T.E =	

6470.34	6470.34			
390.34		1.000000 x	.000000 =	.000000
390.34		.150000 x	.000000 =	.000000

			T.E =	
6470.35	6470.35			
390.35		1.000000 x	.000000 =	.000000
390.35		.150000 x	.000000 =	.000000

			T.E =	
6470.36	6470.36			
390.36		1.000000 x	.000000 =	.000000
390.36		.150000 x	.000000 =	.000000

			T.E =	
6470.37	6470.37			
390.37		1.000000 x	.000000 =	.000000
390.37		.150000 x	.000000 =	.000000

			T.E =	
6470.38	6470.38			
390.38		1.000000 x	.000000 =	.000000
390.38		.150000 x	.000000 =	.000000

			T.E =	
6470.39	6470.39			
390.39		1.000000 x	.000000 =	.000000
390.39		.150000 x	.000000 =	.000000

			T.E =	
6470.4	6470.4			
390.4		1.000000 x	.000000 =	.000000
390.4		.150000 x	.000000 =	.000000

			T.E =	
6470.40	6470.40			
390.40		1.000000 x	.000000 =	.000000
390.40		.150000 x	.000000 =	.000000

			T.E =	

6470.41	6470.41			
390.41		1.000000 x	.000000 =	.000000
390.41		.150000 x	.000000 =	.000000

			T.E =	
6470.42	6470.42			
390.42		1.000000 x	.000000 =	.000000
390.42		.150000 x	.000000 =	.000000

			T.E =	
6470.43	6470.43			
390.43		1.000000 x	.000000 =	.000000
390.43		.150000 x	.000000 =	.000000

			T.E =	
6470.44	6470.44			
390.44		1.000000 x	.000000 =	.000000
390.44		.150000 x	.000000 =	.000000

			T.E =	
6470.45	6470.45			
390.45		1.000000 x	.000000 =	.000000
390.45		.150000 x	.000000 =	.000000

			T.E =	
6470.46	6470.46			
390.46		1.000000 x	.000000 =	.000000
390.46		.150000 x	.000000 =	.000000

			T.E =	
6470.47	6470.47			
390.47		1.000000 x	.000000 =	.000000
390.47		.150000 x	.000000 =	.000000

			T.E =	
6470.48	6470.48			
390.48		1.000000 x	.000000 =	.000000
390.48		.150000 x	.000000 =	.000000

			T.E =	

6470.49	6470.49			
390.49		1.000000 x	.000000 =	.000000
390.49		.150000 x	.000000 =	.000000

			T.E =	
6470.5	6470.5			
390.5		1.000000 x	.000000 =	.000000
390.5		.150000 x	.000000 =	.000000

			T.E =	
6470.50	6470.50			
390.50		1.000000 x	.000000 =	.000000
390.50		.150000 x	.000000 =	.000000

			T.E =	
6470.51	6470.51			
390.51		1.000000 x	.000000 =	.000000
390.51		.150000 x	.000000 =	.000000

			T.E =	
6470.52	6470.52			
390.52		1.000000 x	.000000 =	.000000
390.52		.150000 x	.000000 =	.000000

			T.E =	
6470.53	6470.53			
390.53		1.000000 x	.000000 =	.000000
390.53		.150000 x	.000000 =	.000000

			T.E =	
6470.54	6470.54			
390.54		1.000000 x	.000000 =	.000000
390.54		.150000 x	.000000 =	.000000

			T.E =	
6470.55	6470.55			
390.55		1.000000 x	.000000 =	.000000
390.55		.150000 x	.000000 =	.000000

			T.E =	

6470.56	6470.56			
390.56		1.000000 x	.000000 =	.000000
390.56		.150000 x	.000000 =	.000000

			T.E =	
6470.57	6470.57			
390.57		1.000000 x	.000000 =	.000000
390.57		.150000 x	.000000 =	.000000

			T.E =	
6470.58	6470.58			
390.58		1.000000 x	.000000 =	.000000
390.58		.150000 x	.000000 =	.000000

			T.E =	
6470.59	6470.59			
390.59		1.000000 x	.000000 =	.000000
390.59		.150000 x	.000000 =	.000000

			T.E =	
6470.6	6470.6			
390.6		1.000000 x	.000000 =	.000000
390.6		.150000 x	.000000 =	.000000

			T.E =	
6470.7	6470.7			
390.7		1.000000 x	.000000 =	.000000
390.7		.150000 x	.000000 =	.000000

			T.E =	
6470.8	6470.8			
390.8		1.000000 x	.000000 =	.000000
390.8		.150000 x	.000000 =	.000000

			T.E =	
6470.9	6470.9			
390.9		1.000000 x	.000000 =	.000000
390.9		.150000 x	.000000 =	.000000

			T.E =	

6471.1	6471.1			
391.1		1.000000 x	.000000 =	.000000
391.1		.150000 x	.000000 =	.000000

			T.E =	
6471.10	6471.10			
391.10		1.000000 x	.000000 =	.000000
391.10		.150000 x	.000000 =	.000000

			T.E =	
6471.11	6471.11			
391.11		1.000000 x	.000000 =	.000000
391.11		.150000 x	.000000 =	.000000

			T.E =	
6471.12	6471.12			
391.12		1.000000 x	.000000 =	.000000
391.12		.150000 x	.000000 =	.000000

			T.E =	
6471.13	6471.13			
391.13		1.000000 x	.000000 =	.000000
391.13		.150000 x	.000000 =	.000000

			T.E =	
6471.14	6471.14			
391.14		1.000000 x	.000000 =	.000000
391.14		.150000 x	.000000 =	.000000

			T.E =	
6471.15	6471.15			
391.15		1.000000 x	.000000 =	.000000
391.15		.150000 x	.000000 =	.000000

			T.E =	
6471.16	6471.16			
391.16		1.000000 x	.000000 =	.000000
391.16		.150000 x	.000000 =	.000000

			T.E =	

6471.17	6471.17			
391.17		1.000000 x	.000000 =	.000000
391.17		.150000 x	.000000 =	.000000

			T.E =	
6471.18	6471.18			
391.18		1.000000 x	.000000 =	.000000
391.18		.150000 x	.000000 =	.000000

			T.E =	
6471.19	6471.19			
391.19		1.000000 x	.000000 =	.000000
391.19		.150000 x	.000000 =	.000000

			T.E =	
6471.2	6471.2			
391.2		1.000000 x	.000000 =	.000000
391.2		.150000 x	.000000 =	.000000

			T.E =	
6471.20	6471.20			
391.20		1.000000 x	.000000 =	.000000
391.20		.150000 x	.000000 =	.000000

			T.E =	
6471.21	6471.21			
391.21		1.000000 x	.000000 =	.000000
391.21		.150000 x	.000000 =	.000000

			T.E =	
6471.22	6471.22			
391.22		1.000000 x	.000000 =	.000000
391.22		.150000 x	.000000 =	.000000

			T.E =	
6471.23	6471.23			
391.23		1.000000 x	.000000 =	.000000
391.23		.150000 x	.000000 =	.000000

			T.E =	

6471.24	6471.24			
391.24		1.000000 x	.000000 =	.000000
391.24		.150000 x	.000000 =	.000000

			T.E =	
6471.25	6471.25			
391.25		1.000000 x	.000000 =	.000000
391.25		.150000 x	.000000 =	.000000

			T.E =	
6471.26	6471.26			
391.26		1.000000 x	.000000 =	.000000
391.26		.150000 x	.000000 =	.000000

			T.E =	
6471.27	6471.27			
391.27		1.000000 x	.000000 =	.000000
391.27		.150000 x	.000000 =	.000000

			T.E =	
6471.28	6471.28			
391.28		1.000000 x	.000000 =	.000000
391.28		.150000 x	.000000 =	.000000

			T.E =	
6471.29	6471.29			
391.29		1.000000 x	.000000 =	.000000
391.29		.150000 x	.000000 =	.000000

			T.E =	
6471.3	6471.3			
391.3		1.000000 x	.000000 =	.000000
391.3		.150000 x	.000000 =	.000000

			T.E =	
6471.30	6471.30			
391.30		1.000000 x	.000000 =	.000000
391.30		.150000 x	.000000 =	.000000

			T.E =	

6471.31	6471.31			
391.31		1.000000 x	.000000 =	.000000
391.31		.150000 x	.000000 =	.000000

			T.E =	
6471.32	6471.32			
391.32		1.000000 x	.000000 =	.000000
391.32		.150000 x	.000000 =	.000000

			T.E =	
6471.33	6471.33			
391.33		1.000000 x	.000000 =	.000000
391.33		.150000 x	.000000 =	.000000

			T.E =	
6471.34	6471.34			
391.34		1.000000 x	.000000 =	.000000
391.34		.150000 x	.000000 =	.000000

			T.E =	
6471.35	6471.35			
391.35		1.000000 x	.000000 =	.000000
391.35		.150000 x	.000000 =	.000000

			T.E =	
6471.36	6471.36			
391.36		1.000000 x	.000000 =	.000000
391.36		.150000 x	.000000 =	.000000

			T.E =	
6471.37	6471.37			
391.37		1.000000 x	.000000 =	.000000
391.37		.150000 x	.000000 =	.000000

			T.E =	
6471.38	6471.38			
391.38		1.000000 x	.000000 =	.000000
391.38		.150000 x	.000000 =	.000000

			T.E =	

6471.39	6471.39			
391.39		1.000000 x	.000000 =	.000000
391.39		.150000 x	.000000 =	.000000

			T.E =	
6471.4	6471.4			
391.4		1.000000 x	.000000 =	.000000
391.4		.150000 x	.000000 =	.000000

			T.E =	
6471.40	6471.40			
391.40		1.000000 x	.000000 =	.000000
391.40		.150000 x	.000000 =	.000000

			T.E =	
6471.41	6471.41			
391.41		1.000000 x	.000000 =	.000000
391.41		.150000 x	.000000 =	.000000

			T.E =	
6471.42	6471.42			
391.42		1.000000 x	.000000 =	.000000
391.42		.150000 x	.000000 =	.000000

			T.E =	
6471.43	6471.43			
391.43		1.000000 x	.000000 =	.000000
391.43		.150000 x	.000000 =	.000000

			T.E =	
6471.44	6471.44			
391.44		1.000000 x	.000000 =	.000000
391.44		.150000 x	.000000 =	.000000

			T.E =	
6471.45	6471.45			
391.45		1.000000 x	.000000 =	.000000
391.45		.150000 x	.000000 =	.000000

			T.E =	

6471.46	6471.46			
391.46		1.000000 x	.000000 =	.000000
391.46		.150000 x	.000000 =	.000000

			T.E =	
6471.47	6471.47			
391.47		1.000000 x	.000000 =	.000000
391.47		.150000 x	.000000 =	.000000

			T.E =	
6471.48	6471.48			
391.48		1.000000 x	.000000 =	.000000
391.48		.150000 x	.000000 =	.000000

			T.E =	
6471.49	6471.49			
391.49		1.000000 x	.000000 =	.000000
391.49		.150000 x	.000000 =	.000000

			T.E =	
6471.5	6471.5			
391.5		1.000000 x	.000000 =	.000000
391.5		.150000 x	.000000 =	.000000

			T.E =	
6471.50	6471.50			
391.50		1.000000 x	.000000 =	.000000
391.50		.150000 x	.000000 =	.000000

			T.E =	
6471.51	6471.51			
391.51		1.000000 x	.000000 =	.000000
391.51		.150000 x	.000000 =	.000000

			T.E =	
6471.52	6471.52			
391.52		1.000000 x	.000000 =	.000000
391.52		.150000 x	.000000 =	.000000

			T.E =	

6471.53	6471.53			
391.53		1.000000 x	.000000 =	.000000
391.53		.150000 x	.000000 =	.000000

			T.E =	
6471.54	6471.54			
391.54		1.000000 x	.000000 =	.000000
391.54		.150000 x	.000000 =	.000000

			T.E =	
6471.55	6471.55			
391.55		1.000000 x	.000000 =	.000000
391.55		.150000 x	.000000 =	.000000

			T.E =	
6471.56	6471.56			
391.56		1.000000 x	.000000 =	.000000
391.56		.150000 x	.000000 =	.000000

			T.E =	
6471.6	6471.6			
391.6		1.000000 x	.000000 =	.000000
391.6		.150000 x	.000000 =	.000000

			T.E =	
6471.7	6471.7			
391.7		1.000000 x	.000000 =	.000000
391.7		.150000 x	.000000 =	.000000

			T.E =	
6471.8	6471.8			
391.8		1.000000 x	.000000 =	.000000
391.8		.150000 x	.000000 =	.000000

			T.E =	
6471.9	6471.9			
391.9		1.000000 x	.000000 =	.000000
391.9		.150000 x	.000000 =	.000000

			T.E =	

6472.1	6472.1			
392.1		1.000000 x	.000000 =	.000000
392.1		.100000 x	.000000 =	.000000

			T.E =	
6472.2	6472.2			
392.2		1.000000 x	.000000 =	.000000
392.2		.100000 x	.000000 =	.000000

			T.E =	
6472.3	6472.3			
392.3		1.000000 x	.000000 =	.000000
392.3		.100000 x	.000000 =	.000000

			T.E =	
6472.4	6472.4			
392.4		1.000000 x	.000000 =	.000000
392.4		.100000 x	.000000 =	.000000

			T.E =	
6472.5	6472.5			
392.5		1.000000 x	.000000 =	.000000
392.5		.100000 x	.000000 =	.000000

			T.E =	
6472.6	6472.6			
392.6		1.000000 x	.000000 =	.000000
392.6		.100000 x	.000000 =	.000000

			T.E =	
6472.7	6472.7			
392.7		1.000000 x	.000000 =	.000000
392.7		.100000 x	.000000 =	.000000

			T.E =	
6472.8	6472.8			
392.8		1.000000 x	.000000 =	.000000
392.8		.100000 x	.000000 =	.000000

			T.E =	

6473.1	6473.1			
393.1		1.000000 x	14,767.000000 =	14,767.000000
393.1		.150000 x	14,767.000000 =	2,215.050000

			T.E =	16,982.050000
6473.2	6473.2			
393.2		1.000000 x	.000000 =	.000000
393.2		.150000 x	.000000 =	.000000

			T.E =	
6473.3	6473.3			
393.3		1.000000 x	.000000 =	.000000
393.3		.150000 x	.000000 =	.000000

			T.E =	
6473.4	6473.4			
393.4		1.000000 x	.000000 =	.000000
393.4		.150000 x	.000000 =	.000000

			T.E =	
6474	6474			
397.2		1.000000 x	6.320000 =	6.320000

			T.E =	6.320000
6501	6501			
237		1.000000 x	1.110000 =	1.110000
113		.850000 x	20.419486 =	17.356563

			T.E =	18.466563
6502	6502			
112		.170000 x	17.312112 =	2.943059
517		.042500 x	2,166.720745 =	92.085632

			T.E =	95.028691
6505	6505			
233		1.050000 x	.583300 =	.612465
113		.042500 x	20.419486 =	.867828

			T.E =	1.480293

6506	6506				
233.1		1.050000 x	.583300 =	.612465	
113		.042500 x	20.419486 =	.867828	

			T.E =	1.480293	
6551.1	6551.1				
221		6.000000 x	.099900 =	.599400	
113		.255000 x	20.419486 =	5.206969	
111		.255000 x	15.741598 =	4.014107	
261		1.000000 x	15.100000 =	15.100000	

			T.E =	24.920476	
6551.2	6551.2				
221		8.000000 x	.099900 =	.799200	
262		1.000000 x	26.300000 =	26.300000	
111		.297500 x	15.741598 =	4.683125	
113		.297500 x	20.419486 =	6.074797	

			T.E =	37.857122	
6551.3	6551.3				
221		10.000000 x	.099900 =	.999000	
263		1.000000 x	32.400000 =	32.400000	
113		.340000 x	20.419486 =	6.942625	
111		.340000 x	15.741598 =	5.352143	

			T.E =	45.693769	
6551.4	6551.4				
221		13.000000 x	.099900 =	1.298700	
263.2		1.000000 x	46.700000 =	46.700000	
113		.510000 x	20.419486 =	10.413938	
111		.510000 x	15.741598 =	8.028215	

			T.E =	66.440853	
6551.5	6551.5				
221		16.000000 x	.099900 =	1.598400	
113		.595000 x	20.419486 =	12.149594	
111		.595000 x	15.741598 =	9.366251	
264		1.000000 x	64.100000 =	64.100000	

			T.E =	87.214245	

6551.6	6551.6			
221		20.000000 x	.099900 =	1.998000
265		1.000000 x	115.100000 =	115.100000
111		.850000 x	15.741598 =	13.380358
113		.850000 x	20.419486 =	17.356563

T.E = 147.834921

6551.7	6551.7			
221		26.000000 x	.099900 =	2.597400
271		1.000000 x	206.300000 =	206.300000
113		1.275000 x	20.419486 =	26.034845
111		1.275000 x	15.741598 =	20.070537

T.E = 255.002782

6552	6552			
221		26.000000 x	.099900 =	2.597400
6304		6.890000 x	5.646698 =	38.905749
6310		32.020000 x	1.480293 =	47.398982
6329.2		.418000 x	166.692391 =	69.677419
111		1.700000 x	15.741598 =	26.760717
113		1.275000 x	20.419486 =	26.034845

T.E = 211.375112

6553	6553			
113		.850000 x	20.419486 =	17.356563
6314		13.730000 x	2.059685 =	28.279475
6329.2		.478000 x	166.692391 =	79.678963
6304		9.290000 x	5.646698 =	52.457824

T.E = 177.772825

6601.1	6601.1			
362.1		1.020000 x	.000000 =	.000000
363.1		.224000 x	.000000 =	.000000
113		.199750 x	20.419486 =	4.078792
112		.276250 x	17.312112 =	4.782471
111		.067150 x	15.741598 =	1.057048

T.E =

6601.10	6601.10			
362.10		1.020000 x	.000000 =	.000000
363.10		.224000 x	.000000 =	.000000
112		3.065100 x	17.312112 =	53.063354
113		.901000 x	20.419486 =	18.397957
111		1.351500 x	15.741598 =	21.274770

T.E =

6601.11	6601.11			
362.11		1.020000 x	.000000 =	.000000
363.11		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		3.858150 x	17.312112 =	66.792725
111		1.669400 x	15.741598 =	26.279024

T.E =

6601.12	6601.12			
362.12		1.020000 x	.000000 =	.000000
113		1.201900 x	20.419486 =	24.542180
112		5.523300 x	17.312112 =	95.619988
363.12		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273

T.E =

6601.13	6601.13			
362.13		1.020000 x	.000000 =	.000000
111		3.271650 x	15.741598 =	51.500999
113		1.401650 x	20.419486 =	28.620973
112		6.712450 x	17.312112 =	116.206686
363.13		.224000 x	.000000 =	.000000

T.E =

6601.14	6601.14			
362.14		1.020000 x	.000000 =	.000000
112		8.743100 x	17.312112 =	151.361526
113		1.602250 x	20.419486 =	32.717121
111		4.272950 x	15.741598 =	67.263061
363.14		.224000 x	.000000 =	.000000

T.E =

6601.2	6601.2			
362.2		1.020000 x	.000000 =	.000000
113		.249900 x	20.419486 =	5.102830
112		.379950 x	17.312112 =	6.577737
111		.104550 x	15.741598 =	1.645784
363.2		.224000 x	.000000 =	.000000

T.E =

6601.3	6601.3			
362.3		1.020000 x	.000000 =	.000000
363.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.300050 x	20.419486 =	6.126867
112		.488750 x	17.312112 =	8.461295

T.E =

6601.5	6601.5			
362.5		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
363.5		.224000 x	.000000 =	.000000
112		.765000 x	17.312112 =	13.243766
111		.266900 x	15.741598 =	4.201433

T.E =

6601.6	6601.6			
362.6		1.020000 x	.000000 =	.000000
363.6		.224000 x	.000000 =	.000000
112		1.016600 x	17.312112 =	17.599493
113		.500650 x	20.419486 =	10.223016
111		.417350 x	15.741598 =	6.569756

T.E =

6601.7	6601.7			
362.7		1.020000 x	.000000 =	.000000
113		.600100 x	20.419486 =	12.253734
112		1.484950 x	17.312112 =	25.707621
111		.600950 x	15.741598 =	9.459913
363.7		.224000 x	.000000 =	.000000

T.E =

6601.8	6601.8			
362.8		1.020000 x	.000000 =	.000000
363.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.700400 x	20.419486 =	14.301808
112		1.926100 x	17.312112 =	33.344859

T.E =

6601.9	6601.9			
362.9		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
363.9		.224000 x	.000000 =	.000000
112		2.435250 x	17.312112 =	42.159321
111		1.068450 x	15.741598 =	16.819110

T.E =

6602.1	6602.1			
364.1		1.020000 x	.000000 =	.000000
365.1		.224000 x	.000000 =	.000000
112		.308550 x	17.312112 =	5.341652
113		.266900 x	20.419486 =	5.449961
111		.067150 x	15.741598 =	1.057048

T.E =

6602.10	6602.10			
364.10		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		4.232150 x	17.312112 =	73.267455
111		1.351500 x	15.741598 =	21.274770
365.10		.224000 x	.000000 =	.000000

T.E =

6602.11	6602.11			
364.11		1.020000 x	.000000 =	.000000
113		1.334500 x	20.419486 =	27.249804
112		5.156950 x	17.312112 =	89.277696
365.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6602.12	6602.12			
364.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		1.602250 x	20.419486 =	32.717121
112		7.410300 x	17.312112 =	128.287944
365.12		.224000 x	.000000 =	.000000

T.E =

6602.13	6602.13			
364.13		1.020000 x	.000000 =	.000000
365.13		.224000 x	.000000 =	.000000
112		9.106050 x	17.312112 =	157.644957
113		1.869150 x	20.419486 =	38.167082
111		3.271650 x	15.741598 =	51.500999

T.E =

6602.14	6602.14			
364.14		1.020000 x	.000000 =	.000000
365.14		.224000 x	.000000 =	.000000
113		2.136050 x	20.419486 =	43.617043
112		11.979050 x	17.312112 =	207.382655
111		4.272950 x	15.741598 =	67.263061

T.E =

6602.2	6602.2			
364.2		1.020000 x	.000000 =	.000000
113		.333200 x	20.419486 =	6.803773
112		.452200 x	17.312112 =	7.828537
111		.104550 x	15.741598 =	1.645784
365.2		.224000 x	.000000 =	.000000

T.E =

6602.3	6602.3			
364.3		1.020000 x	.000000 =	.000000
365.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323
113		.400350 x	20.419486 =	8.174941
112		.612850 x	17.312112 =	10.609728

T.E =

6602.5	6602.5			
364.5		1.020000 x	.000000 =	.000000
113		.533800 x	20.419486 =	10.899922
365.5		.224000 x	.000000 =	.000000
112		1.052300 x	17.312112 =	18.217535
111		.266900 x	15.741598 =	4.201433

T.E =

6602.6	6602.6			
364.6		1.020000 x	.000000 =	.000000
365.6		.224000 x	.000000 =	.000000
112		1.377000 x	17.312112 =	23.838778
113		.667250 x	20.419486 =	13.624902
111		.417350 x	15.741598 =	6.569756

T.E =

6602.7	6602.7			
364.7		1.020000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.989000 x	17.312112 =	34.433791
111		.600950 x	15.741598 =	9.459913
365.7		.224000 x	.000000 =	.000000

T.E =

6602.8	6602.8			
364.8		1.020000 x	.000000 =	.000000
365.8		.224000 x	.000000 =	.000000
111		.817700 x	15.741598 =	12.871905
113		.934150 x	20.419486 =	19.074863
112		2.718300 x	17.312112 =	47.059514

T.E =

6602.9	6602.9			
364.9		1.020000 x	.000000 =	.000000
113		1.067600 x	20.419486 =	21.799843
365.9		.224000 x	.000000 =	.000000
112		3.443354 x	17.312112 =	59.611730
111		1.068450 x	15.741598 =	16.819110

T.E =

6603.1	6603.1			
366.1		1.020000 x	.000000 =	.000000
367.1		.224000 x	.000000 =	.000000
112		.398650 x	17.312112 =	6.901473
113		.333200 x	20.419486 =	6.803773
111		.067150 x	15.741598 =	1.057048

T.E =

6603.10	6603.10			
366.10		1.020000 x	.000000 =	.000000
113		1.501100 x	20.419486 =	30.651690
112		5.308250 x	17.312112 =	91.897019
111		1.351500 x	15.741598 =	21.274770
367.10		.224000 x	.000000 =	.000000

T.E =

6603.11	6603.11			
366.11		1.020000 x	.000000 =	.000000
113		1.667700 x	20.419486 =	34.053577
112		6.644450 x	17.312112 =	115.029463
367.11		.224000 x	.000000 =	.000000
111		1.669400 x	15.741598 =	26.279024

T.E =

6603.12	6603.12			
366.12		1.020000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.002600 x	20.419486 =	40.892063
112		9.562500 x	17.312112 =	165.547071
367.12		.224000 x	.000000 =	.000000

T.E =

6603.13	6603.13			
366.13		1.020000 x	.000000 =	.000000
367.13		.224000 x	.000000 =	.000000
112		11.589750 x	17.312112 =	200.643050
113		2.336650 x	20.419486 =	47.713192
111		3.271650 x	15.741598 =	51.500999

T.E =

6603.14	6603.14			
366.14		1.020000 x	.000000 =	.000000
367.14		.224000 x	.000000 =	.000000
113		2.669850 x	20.419486 =	54.516965
112		14.965950 x	17.312112 =	259.092203
111		4.272950 x	15.741598 =	67.263061

T.E =

6603.2	6603.2			
366.2		1.020000 x	.000000 =	.000000
113		.416500 x	20.419486 =	8.504716
112		.523600 x	17.312112 =	9.064622
111		.104550 x	15.741598 =	1.645784
367.2		.224000 x	.000000 =	.000000

T.E =

6603.3	6603.3			
366.3		1.020000 x	.000000 =	.000000
113		.500650 x	20.419486 =	10.223016
112		.748000 x	17.312112 =	12.949460
367.3		.224000 x	.000000 =	.000000
111		.150450 x	15.741598 =	2.368323

T.E =

6603.5	6603.5			
366.5		1.020000 x	.000000 =	.000000
111		.266900 x	15.741598 =	4.201433
113		.667250 x	20.419486 =	13.624902
112		1.269050 x	17.312112 =	21.969936
367.5		.224000 x	.000000 =	.000000

T.E =

6603.6	6603.6			
366.6		1.020000 x	.000000 =	.000000
367.6		.224000 x	.000000 =	.000000
112		1.807950 x	17.312112 =	31.299433
113		.833850 x	20.419486 =	17.026788
111		.417350 x	15.741598 =	6.569756

T.E =

6603.7	6603.7			
366.7		1.020000 x	.000000 =	.000000
367.7		.224000 x	.000000 =	.000000
113		1.000450 x	20.419486 =	20.428675
112		2.597600 x	17.312112 =	44.969942
111		.600950 x	15.741598 =	9.459913

T.E =

6603.8	6603.8			
366.8		1.020000 x	.000000 =	.000000
113		1.167900 x	20.419486 =	23.847918
112		3.439100 x	17.312112 =	59.538084
111		.817700 x	15.741598 =	12.871905
367.8		.224000 x	.000000 =	.000000

T.E =

6603.9	6603.9			
366.9		1.020000 x	.000000 =	.000000
367.9		.224000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.334500 x	20.419486 =	27.249804
112		4.386850 x	17.312112 =	75.945639

T.E =

6604.1	6604.1			
366.15		1.020000 x	.000000 =	.000000
113		.400350 x	20.419486 =	8.174941
367.15		.224000 x	.000000 =	.000000
112		.504900 x	17.312112 =	8.740885
111		.067150 x	15.741598 =	1.057048

T.E =

6604.10	6604.10			
366.24		1.020000 x	.000000 =	.000000
367.24		.224000 x	.000000 =	.000000
112		6.546700 x	17.312112 =	113.337204
113		1.802000 x	20.419486 =	36.795914
111		1.351500 x	15.741598 =	21.274770

T.E =

6604.11	6604.11			
366.25		1.020000 x	.000000 =	.000000
113		2.001750 x	20.419486 =	40.874706
112		8.181250 x	17.312112 =	141.634716
111		1.669400 x	15.741598 =	26.279024
367.25		.224000 x	.000000 =	.000000

T.E =

6604.12	6604.12			
366.26		1.020000 x	.000000 =	.000000
367.26		.224000 x	.000000 =	.000000
111		2.402950 x	15.741598 =	37.826273
113		2.403800 x	20.419486 =	49.084360
112		11.789500 x	17.312112 =	204.101144

T.E =

6604.13	6604.13			
366.27		1.020000 x	.000000 =	.000000
113		2.804150 x	20.419486 =	57.259302
367.27		.224000 x	.000000 =	.000000
112		14.360750 x	17.312112 =	248.614912
111		3.271650 x	15.741598 =	51.500999

T.E =

6604.14	6604.14			
366.28		1.020000 x	.000000 =	.000000
367.28		.224000 x	.000000 =	.000000
112		18.717850 x	17.312112 =	324.045516
113		3.204500 x	20.419486 =	65.434243
111		4.272950 x	15.741598 =	67.263061

T.E =

6604.2	6604.2			
366.16		1.020000 x	.000000 =	.000000
113		.499800 x	20.419486 =	10.205659
112		.647700 x	17.312112 =	11.213055
111		.104550 x	15.741598 =	1.645784
367.16		.224000 x	.000000 =	.000000

T.E =

6604.3	6604.3			
366.17		1.020000 x	.000000 =	.000000
367.17		.224000 x	.000000 =	.000000
112		.933300 x	17.312112 =	16.157394
113		.600950 x	20.419486 =	12.271090
111		.150450 x	15.741598 =	2.368323

T.E =

6604.5	6604.5			
366.19		1.020000 x	.000000 =	.000000
367.19		.224000 x	.000000 =	.000000
113		.800700 x	20.419486 =	16.349882
112		1.592900 x	17.312112 =	27.576463
111		.266900 x	15.741598 =	4.201433

T.E =

6604.6	6604.6			
366.20		1.020000 x	.000000 =	.000000
367.20		.224000 x	.000000 =	.000000
113		1.001300 x	20.419486 =	20.446031
112		2.094400 x	17.312112 =	36.258487
111		.417350 x	15.741598 =	6.569756

T.E =

6604.7	6604.7			
366.21		1.020000 x	.000000 =	.000000
113		1.201050 x	20.419486 =	24.524824
112		2.952900 x	17.312112 =	51.120936
111		.600950 x	15.741598 =	9.459913
367.21		.224000 x	.000000 =	.000000

T.E =

6604.8	6604.8			
366.22		1.020000 x	.000000 =	.000000
112		3.979700 x	17.312112 =	68.897012
113		1.401650 x	20.419486 =	28.620973
111		.817700 x	15.741598 =	12.871905
367.22		.224000 x	.000000 =	.000000

T.E =

6604.9	6604.9			
366.23		1.020000 x	.000000 =	.000000
111		1.068450 x	15.741598 =	16.819110
113		1.601400 x	20.419486 =	32.699765
112		5.210500 x	17.312112 =	90.204760
367.23		.224000 x	.000000 =	.000000

T.E =

6610	6610			
360.1		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
113		.025500 x	20.419486 =	.520697
112		.042500 x	17.312112 =	.735765
111		.042500 x	15.741598 =	.669018

T.E =

6611.1	6611.1			
361.1		1.000000 x	12.320000 =	12.320000
113		.212500 x	20.419486 =	4.339141
112		.510000 x	17.312112 =	8.829177
111		.085000 x	15.741598 =	1.338036

T.E = 26.826354

6611.10	6611.10			
361.10		1.000000 x	.000000 =	.000000
111		.510000 x	15.741598 =	8.028215
112		2.125000 x	17.312112 =	36.788238
113		.765000 x	20.419486 =	15.620907

T.E =

6611.11	6611.11			
361.11		1.000000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269
113		.935000 x	20.419486 =	19.092219
112		2.550000 x	17.312112 =	44.145886

T.E =

6611.12	6611.12			
361.12		1.000000 x	.000000 =	.000000
111		.765000 x	15.741598 =	12.042322
113		1.105000 x	20.419486 =	22.563532
112		2.975000 x	17.312112 =	51.503533

T.E =

6611.13	6611.13			
361.13		1.000000 x	.000000 =	.000000
113		1.275000 x	20.419486 =	26.034845
112		3.400000 x	17.312112 =	58.861181
111		.892500 x	15.741598 =	14.049376

T.E =

6611.14	6611.14			
361.14		1.000000 x	.000000 =	.000000
111		1.020000 x	15.741598 =	16.056430
113		1.445000 x	20.419486 =	29.506157
112		3.825000 x	17.312112 =	66.218828

			T.E =	
6611.2	6611.2			
361.2		1.000000 x	15.940000 =	15.940000
113		.212500 x	20.419486 =	4.339141
112		.552500 x	17.312112 =	9.564942
111		.085000 x	15.741598 =	1.338036

			T.E =	31.182118
6611.3	6611.3			
361.3		1.000000 x	20.220000 =	20.220000
113		.255000 x	20.419486 =	5.206969
112		.637500 x	17.312112 =	11.036471
111		.127500 x	15.741598 =	2.007054

			T.E =	38.470494
6611.4	6611.4			
361.4		1.000000 x	.000000 =	.000000
113		.297500 x	20.419486 =	6.074797
112		.680000 x	17.312112 =	11.772236
111		.170000 x	15.741598 =	2.676072

			T.E =	
6611.5	6611.5			
361.5		1.000000 x	38.600000 =	38.600000
111		.212500 x	15.741598 =	3.345090
112		.935000 x	17.312112 =	16.186825
113		.382500 x	20.419486 =	7.810453

			T.E =	65.942368
6611.6	6611.6			
361.6		1.000000 x	51.610000 =	51.610000
111		.255000 x	15.741598 =	4.014107
113		.425000 x	20.419486 =	8.678282
112		1.105000 x	17.312112 =	19.129884

			T.E =	83.432273

6611.7	6611.7			
361.7		1.000000 x	79.690000 =	79.690000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		1.275000 x	17.312112 =	22.072943

			T.E =	117.529024
6611.8	6611.8			
361.8		1.000000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422
112		1.700000 x	17.312112 =	29.430590
111		.382500 x	15.741598 =	6.021161

			T.E =	
6611.9	6611.9			
361.9		1.000000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
112		1.870000 x	17.312112 =	32.373649
113		.680000 x	20.419486 =	13.885250

			T.E =	
6620.1	6620.1			
371.1		1.020000 x	5.080000 =	5.181600
111		.080750 x	15.741598 =	1.271134
113		.176800 x	20.419486 =	3.610165
112		.055250 x	17.312112 =	.956494

			T.E =	11.019393
6620.2	6620.2			
371.2		1.020000 x	8.050000 =	8.211000
111		.130900 x	15.741598 =	2.060575
113		.224400 x	20.419486 =	4.582133
112		.089250 x	17.312112 =	1.545106

			T.E =	16.398814
6620.3	6620.3			
371.3		1.020000 x	10.460000 =	10.669200
113		.256700 x	20.419486 =	5.241682
112		.116450 x	17.312112 =	2.015995
111		.170850 x	15.741598 =	2.689452

			T.E =	20.616330

6620.4	6620.4			
371.4		1.020000 x	16.260000 =	16.585200
111		.266900 x	15.741598 =	4.201433
112		.182750 x	17.312112 =	3.163788
113		.320450 x	20.419486 =	6.543424

			T.E =	30.493845
6620.5	6620.5			
371.5		1.020000 x	20.580000 =	20.991600
111		.338300 x	15.741598 =	5.325383
113		.360400 x	20.419486 =	7.359183
112		.228650 x	17.312112 =	3.958414

			T.E =	37.634580
6620.6	6620.6			
371.6		1.020000 x	32.340000 =	32.986800
111		.523600 x	15.741598 =	8.242301
113		.448800 x	20.419486 =	9.164265
112		.353600 x	17.312112 =	6.121563

			T.E =	56.514929
6620.7	6620.7			
371.7		1.020000 x	41.610000 =	42.442200
113		.504900 x	20.419486 =	10.309798
112		.445400 x	17.312112 =	7.710815
111		.662150 x	15.741598 =	10.423299

			T.E =	70.886112
6620.8	6620.8			
371.8		1.020000 x	52.890000 =	53.947800
111		.841500 x	15.741598 =	13.246555
112		.567800 x	17.312112 =	9.829817
113		.568650 x	20.419486 =	11.611541

			T.E =	88.635713
6620.9	6620.9			
371.9		1.020000 x	66.370000 =	67.697400
111		1.068450 x	15.741598 =	16.819110
113		.640900 x	20.419486 =	13.086849
112		.717400 x	17.312112 =	12.419709

			T.E =	110.023068

6621.1	6621.1			
372.1		1.020000 x	8.000000 =	8.160000
111		.080750 x	15.741598 =	1.271134
113		.205700 x	20.419486 =	4.200288
112		.088400 x	17.312112 =	1.530391

			T.E =	15.161813
6621.2	6621.2			
372.2		1.020000 x	12.580000 =	12.831600
113		.261800 x	20.419486 =	5.345821
112		.141100 x	17.312112 =	2.442739
111		.130900 x	15.741598 =	2.060575

			T.E =	22.680736
6621.3	6621.3			
372.3		1.020000 x	16.500000 =	16.830000
111		.170850 x	15.741598 =	2.689452
112		.185300 x	17.312112 =	3.207934
113		.299200 x	20.419486 =	6.109510

			T.E =	28.836897
6621.4	6621.4			
372.4		1.020000 x	25.550000 =	26.061000
111		.266900 x	15.741598 =	4.201433
113		.374000 x	20.419486 =	7.636888
112		.289000 x	17.312112 =	5.003200

			T.E =	42.902521
6621.5	6621.5			
372.5		1.020000 x	32.410000 =	33.058200
111		.338300 x	15.741598 =	5.325383
113		.420750 x	20.419486 =	8.591499
112		.367200 x	17.312112 =	6.357008

			T.E =	53.332089
6621.6	6621.6			
372.6		1.020000 x	51.220000 =	52.244400
113		.523600 x	20.419486 =	10.691643
112		.564400 x	17.312112 =	9.770956
111		.523600 x	15.741598 =	8.242301

			T.E =	80.949300

6621.7	6621.7				
372.7		1.020000 x	65.050000 =	66.351000	
111		.662150 x	15.741598 =	10.423299	
112		.710600 x	17.312112 =	12.301987	
113		.589050 x	20.419486 =	12.028098	

			T.E =	101.104384	
6621.8	6621.8				
372.8		1.020000 x	82.710000 =	84.364200	
111		.841500 x	15.741598 =	13.246555	
113		.663850 x	20.419486 =	13.555476	
112		.901000 x	17.312112 =	15.598213	

			T.E =	126.764443	
6621.9	6621.9				
372.9		1.020000 x	104.700000 =	106.794000	
111		1.068450 x	15.741598 =	16.819110	
113		.748000 x	20.419486 =	15.273776	
112		1.145800 x	17.312112 =	19.836218	

			T.E =	158.723104	
6622.1	6622.1				
373.1		1.020000 x	11.900000 =	12.138000	
113		.235450 x	20.419486 =	4.807768	
112		.131750 x	17.312112 =	2.280871	
111		.080750 x	15.741598 =	1.271134	

			T.E =	20.497773	
6622.2	6622.2				
373.2		1.020000 x	18.780000 =	19.155600	
111		.130900 x	15.741598 =	2.060575	
112		.212500 x	17.312112 =	3.678824	
113		.299200 x	20.419486 =	6.109510	

			T.E =	31.004509	
6622.3	6622.3				
373.3		1.020000 x	24.500000 =	24.990000	
111		.170850 x	15.741598 =	2.689452	
113		.341700 x	20.419486 =	6.977338	
112		.277950 x	17.312112 =	4.811902	

			T.E =	39.468692	

6623	6623				
360.2		1.000000 x	2.220000 =	2.220000	
113		.085000 x	20.419486 =	1.735656	
111		.042500 x	15.741598 =	.669018	
113		.025500 x	20.419486 =	.520697	
112		.042500 x	17.312112 =	.735765	

			T.E =	5.881136	
6630.1	6630.1				
376.12		1.000000 x	88.960000 =	88.960000	
113		2.550000 x	20.419486 =	52.069689	
113		.610300 x	20.419486 =	12.462012	
113		1.067600 x	20.419486 =	21.799843	
112		2.439500 x	17.312112 =	42.232897	
111		.855100 x	15.741598 =	13.460640	

			T.E =	230.985083	
6630.10	6630.10				
376.21		1.000000 x	487.600000 =	487.600000	
111		7.690800 x	15.741598 =	121.065482	
113		3.349000 x	20.419486 =	68.384859	
113		3.203650 x	20.419486 =	65.416886	
113		2.550000 x	20.419486 =	52.069689	
112		13.396000 x	17.312112 =	231.913052	

			T.E =	1,026.449968	
6630.11	6630.11				
376.22		1.000000 x	528.600000 =	528.600000	
111		9.025300 x	15.741598 =	142.072644	
113		3.471400 x	20.419486 =	70.884204	
113		3.629500 x	20.419486 =	74.112524	
113		2.550000 x	20.419486 =	52.069689	
112		14.518000 x	17.312112 =	251.337242	

			T.E =	1,119.076304	
6630.2	6630.2				
376.13		1.000000 x	98.960000 =	98.960000	
113		2.550000 x	20.419486 =	52.069689	
113		1.201050 x	20.419486 =	24.524824	
113		.680000 x	20.419486 =	13.885250	
111		1.081200 x	15.741598 =	17.019816	
112		2.720000 x	17.312112 =	47.088945	

			T.E =	253.548524	

6630.3	6630.3				
376.14		1.000000 x	109.782000 =	109.782000	
113		1.334500 x	20.419486 =	27.249804	
113		2.550000 x	20.419486 =	52.069689	
113		.760750 x	20.419486 =	15.534124	
112		3.043000 x	17.312112 =	52.680757	
111		1.334500 x	15.741598 =	21.007163	

			T.E =	278.323537	
6630.4	6630.4				
376.15		1.000000 x	140.650000 =	140.650000	
111		1.922700 x	15.741598 =	30.266370	
113		.892500 x	20.419486 =	18.224391	
113		1.602250 x	20.419486 =	32.717121	
113		2.550000 x	20.419486 =	52.069689	
112		3.570000 x	17.312112 =	61.804240	

			T.E =	335.731812	
6630.5	6630.5				
376.16		1.000000 x	176.880000 =	176.880000	
111		2.617150 x	15.741598 =	41.198123	
113		1.164500 x	20.419486 =	23.778491	
113		2.550000 x	20.419486 =	52.069689	
113		1.869150 x	20.419486 =	38.167082	
112		4.658000 x	17.312112 =	80.639818	

			T.E =	412.733204	
6630.6	6630.6				
376.17		1.000000 x	224.520000 =	224.520000	
113		2.550000 x	20.419486 =	52.069689	
113		2.136050 x	20.419486 =	43.617043	
113		1.470500 x	20.419486 =	30.026854	
111		3.418700 x	15.741598 =	53.815801	
112		5.882000 x	17.312112 =	101.829843	

			T.E =	505.879230	
6630.7	6630.7				
376.18		1.000000 x	302.640000 =	302.640000	
113		2.402950 x	20.419486 =	49.067004	
113		2.550000 x	20.419486 =	52.069689	
113		2.031500 x	20.419486 =	41.482186	
112		8.126000 x	17.312112 =	140.678222	
111		4.326500 x	15.741598 =	68.106024	

			T.E =	654.043125	

6630.8	6630.8				
376.19		1.000000 x	336.580000 =	336.580000	
111		5.340550 x	15.741598 =	84.068791	
113		2.261000 x	20.419486 =	46.168458	
113		2.669850 x	20.419486 =	54.516965	
113		2.550000 x	20.419486 =	52.069689	
112		9.044000 x	17.312112 =	156.570741	

			T.E =	729.974644	
6630.9	6630.9				
376.20		1.000000 x	400.990000 =	400.990000	
111		6.461700 x	15.741598 =	101.717484	
113		2.737000 x	20.419486 =	55.888133	
113		2.550000 x	20.419486 =	52.069689	
113		2.936750 x	20.419486 =	59.966926	
112		10.948000 x	17.312112 =	189.533002	

			T.E =	860.165234	
6640.1	6640.1				
377.1		1.000000 x	.000000 =	.000000	
113		2.550000 x	20.419486 =	52.069689	
113		1.667700 x	20.419486 =	34.053577	
111		1.334500 x	15.741598 =	21.007163	
112		3.043000 x	17.312112 =	52.680757	

			T.E =		
6640.2	6640.2				
377.2		1.000000 x	.000000 =	.000000	
113		2.550000 x	20.419486 =	52.069689	
113		2.002600 x	20.419486 =	40.892063	
112		3.570000 x	17.312112 =	61.804240	
111		1.922700 x	15.741598 =	30.266370	

			T.E =		
6640.3	6640.3				
377.3		1.000000 x	.000000 =	.000000	
111		2.617150 x	15.741598 =	41.198123	
112		4.658000 x	17.312112 =	80.639818	
113		2.550000 x	20.419486 =	52.069689	
113		2.336650 x	20.419486 =	47.713192	

			T.E =		

6640.4 6640.4

377.4	1.000000 x	.000000 =	.000000
111	3.418700 x	15.741598 =	53.815801
112	5.882000 x	17.312112 =	101.829843
113	2.669850 x	20.419486 =	54.516965
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.5 6640.5

377.5	1.000000 x	.000000 =	.000000
111	4.326500 x	15.741598 =	68.106024
113	3.003900 x	20.419486 =	61.338094
113	2.550000 x	20.419486 =	52.069689
112	8.126000 x	17.312112 =	140.678222

T.E =

6640.6 6640.6

377.6	1.000000 x	.000000 =	.000000
113	2.550000 x	20.419486 =	52.069689
113	3.337100 x	20.419486 =	68.141867
112	9.044000 x	17.312112 =	156.570741
111	5.340550 x	15.741598 =	84.068791

T.E =

6640.7 6640.7

377.7	1.000000 x	.000000 =	.000000
111	6.461700 x	15.741598 =	101.717484
112	10.948000 x	17.312112 =	189.533002
113	3.671150 x	20.419486 =	74.962996
113	2.550000 x	20.419486 =	52.069689

T.E =

6640.8 6640.8

377.8	1.000000 x	.000000 =	.000000
111	7.690800 x	15.741598 =	121.065482
112	13.396000 x	17.312112 =	231.913052
113	2.550000 x	20.419486 =	52.069689
113	4.004350 x	20.419486 =	81.766769

T.E =

6640.9	6640.9			
377.9		1.000000 x	.000000 =	.000000
111		9.025300 x	15.741598 =	142.072644
113		4.339250 x	20.419486 =	88.605255
113		2.550000 x	20.419486 =	52.069689
112		14.518000 x	17.312112 =	251.337242

			T.E =	
6641	6641			
233.3		1.000000 x	7.950000 =	7.950000

			T.E =	7.950000
6651.1	6651.1			
378.1		1.000000 x	69.000000 =	69.000000
378.1		.050000 x	69.000000 =	3.450000

			T.E =	72.450000
6651.2	6651.2			
378.2		1.000000 x	106.000000 =	106.000000
378.2		.050000 x	106.000000 =	5.300000

			T.E =	111.300000
6651.3	6651.3			
378.3		1.000000 x	136.000000 =	136.000000
378.3		.050000 x	136.000000 =	6.800000

			T.E =	142.800000
6651.4	6651.4			
378.4		1.000000 x	188.000000 =	188.000000
378.4		.050000 x	188.000000 =	9.400000

			T.E =	197.400000
6651.5	6651.5			
378.5		1.000000 x	231.000000 =	231.000000
378.5		.050000 x	231.000000 =	11.550000

			T.E =	242.550000
6651.6	6651.6			
378.6		1.000000 x	.000000 =	.000000
378.6		.050000 x	.000000 =	.000000

			T.E =	

6651.7	6651.7			
378.7		1.000000 x	338.000000 =	338.000000
378.7		.050000 x	338.000000 =	16.900000

			T.E =	354.900000
6651.8	6651.8			
378.8		1.000000 x	512.000000 =	512.000000
378.8		.050000 x	512.000000 =	25.600000

			T.E =	537.600000
6651.9	6651.9			
378.9		1.000000 x	724.000000 =	724.000000
378.9		.050000 x	724.000000 =	36.200000

			T.E =	760.200000
6652.1	6652.1			
379.1		1.000000 x	.000000 =	.000000
379.1		.050000 x	.000000 =	.000000

			T.E =	
6652.2	6652.2			
379.2		1.000000 x	.000000 =	.000000
379.2		.050000 x	.000000 =	.000000

			T.E =	
6652.3	6652.3			
379.3		1.000000 x	.000000 =	.000000
379.3		.050000 x	.000000 =	.000000

			T.E =	
6653.1	6653.1			
379.4		1.000000 x	1,907.550000 =	1,907.550000
379.4		.050000 x	1,907.550000 =	95.377500

			T.E =	2,002.927500
6653.2	6653.2			
379.5		1.000000 x	.000000 =	.000000
379.5		.050000 x	.000000 =	.000000

			T.E =	

6653.3	6653.3			
379.6		1.000000 x	.000000 =	.000000
379.6		.050000 x	.000000 =	.000000

			T.E =	
6653.4	6653.4			
379.7		1.000000 x	.000000 =	.000000
379.7		.050000 x	.000000 =	.000000

			T.E =	
6653.5	6653.5			
379.8		1.000000 x	.000000 =	.000000
379.8		.050000 x	.000000 =	.000000

			T.E =	
6653.6	6653.6			
379.9		1.000000 x	7,395.450000 =	7,395.450000
379.9		.050000 x	7,395.450000 =	369.772500

			T.E =	7,765.222500
6654.1	6654.1			
383.1		1.000000 x	.000000 =	.000000
383.1		.050000 x	.000000 =	.000000

			T.E =	
6654.10	6654.10			
383.10		1.000000 x	.000000 =	.000000
383.10		.050000 x	.000000 =	.000000

			T.E =	
6654.11	6654.11			
383.11		1.000000 x	.000000 =	.000000
383.11		.050000 x	.000000 =	.000000

			T.E =	
6654.12	6654.12			
383.12		1.000000 x	.000000 =	.000000
383.12		.050000 x	.000000 =	.000000

			T.E =	

6654.13	6654.13			
383.13		1.000000 x	.000000 =	.000000
383.13		.050000 x	.000000 =	.000000

			T.E =	
6654.14	6654.14			
383.14		1.000000 x	.000000 =	.000000
383.14		.050000 x	.000000 =	.000000

			T.E =	
6654.15	6654.15			
383.15		1.000000 x	.000000 =	.000000
383.15		.050000 x	.000000 =	.000000

			T.E =	
6654.16	6654.16			
383.16		1.000000 x	.000000 =	.000000
383.16		.050000 x	.000000 =	.000000

			T.E =	
6654.17	6654.17			
383.17		1.000000 x	.000000 =	.000000
383.17		.050000 x	.000000 =	.000000

			T.E =	
6654.18	6654.18			
383.18		1.000000 x	.000000 =	.000000
383.18		.050000 x	.000000 =	.000000

			T.E =	
6654.19	6654.19			
383.19		1.000000 x	.000000 =	.000000
383.19		.050000 x	.000000 =	.000000

			T.E =	
6654.2	6654.2			
383.2		1.000000 x	.000000 =	.000000
383.2		.050000 x	.000000 =	.000000

			T.E =	

6654.20	6654.20			
383.20		1.000000 x	.000000 =	.000000
383.20		.050000 x	.000000 =	.000000

			T.E =	
6654.21	6654.21			
383.21		1.000000 x	.000000 =	.000000
383.21		.050000 x	.000000 =	.000000

			T.E =	
6654.22	6654.22			
383.22		1.000000 x	.000000 =	.000000
383.22		.050000 x	.000000 =	.000000

			T.E =	
6654.23	6654.23			
383.23		1.000000 x	.000000 =	.000000
383.23		.050000 x	.000000 =	.000000

			T.E =	
6654.24	6654.24			
383.24		1.000000 x	.000000 =	.000000
383.24		.050000 x	.000000 =	.000000

			T.E =	
6654.25	6654.25			
383.25		1.000000 x	.000000 =	.000000
383.25		.050000 x	.000000 =	.000000

			T.E =	
6654.26	6654.26			
383.26		1.000000 x	.000000 =	.000000
383.26		.050000 x	.000000 =	.000000

			T.E =	
6654.27	6654.27			
383.27		1.000000 x	.000000 =	.000000
383.27		.050000 x	.000000 =	.000000

			T.E =	

6654.28	6654.28			
383.28		1.000000 x	.000000 =	.000000
383.28		.050000 x	.000000 =	.000000

			T.E =	
6654.29	6654.29			
383.29		1.000000 x	.000000 =	.000000
383.29		.050000 x	.000000 =	.000000

			T.E =	
6654.3	6654.3			
383.3		1.000000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000
383.3		.050000 x	.000000 =	.000000

			T.E =	
6654.30	6654.30			
383.30		1.000000 x	.000000 =	.000000
383.30		.050000 x	.000000 =	.000000

			T.E =	
6654.31	6654.31			
383.31		1.000000 x	.000000 =	.000000
383.31		.050000 x	.000000 =	.000000

			T.E =	
6654.32	6654.32			
383.32		1.000000 x	.000000 =	.000000
383.32		.050000 x	.000000 =	.000000

			T.E =	
6654.33	6654.33			
383.33		1.000000 x	.000000 =	.000000
383.33		.050000 x	.000000 =	.000000

			T.E =	
6654.34	6654.34			
383.34		1.000000 x	.000000 =	.000000
383.34		.050000 x	.000000 =	.000000

			T.E =	

6654.4	6654.4			
383.4		1.000000 x	.000000 =	.000000
383.4		.050000 x	.000000 =	.000000

			T.E =	
6654.5	6654.5			
383.5		1.000000 x	.000000 =	.000000
383.5		.050000 x	.000000 =	.000000

			T.E =	
6654.6	6654.6			
383.6		1.000000 x	.000000 =	.000000
383.6		.050000 x	.000000 =	.000000

			T.E =	
6654.7	6654.7			
383.7		1.000000 x	.000000 =	.000000
383.7		.050000 x	.000000 =	.000000

			T.E =	
6654.8	6654.8			
383.8		1.000000 x	.000000 =	.000000
383.8		.050000 x	.000000 =	.000000

			T.E =	
6654.9	6654.9			
383.9		1.000000 x	.000000 =	.000000
383.9		.050000 x	.000000 =	.000000

			T.E =	
6655.1	6655.1			
381.1		1.000000 x	.000000 =	.000000
381.1		.100000 x	.000000 =	.000000

			T.E =	
6655.2	6655.2			
381.2		1.000000 x	.000000 =	.000000
381.2		.100000 x	.000000 =	.000000

			T.E =	

6655.3	6655.3			
381.3		1.000000 x	.000000 =	.000000
381.3		.100000 x	.000000 =	.000000

			T.E =	
6656.1	6656.1			
381.4		1.000000 x	.000000 =	.000000
381.4		.100000 x	.000000 =	.000000

			T.E =	
6656.2	6656.2			
381.5		1.000000 x	.000000 =	.000000
381.5		.100000 x	.000000 =	.000000

			T.E =	
6656.3	6656.3			
381.6		1.000000 x	.000000 =	.000000
381.6		.100000 x	.000000 =	.000000

			T.E =	
6657.1	6657.1			
381.7		1.000000 x	.000000 =	.000000
381.7		.100000 x	.000000 =	.000000

			T.E =	
6657.2	6657.2			
381.8		1.000000 x	.000000 =	.000000
381.8		.100000 x	.000000 =	.000000

			T.E =	
6657.3	6657.3			
381.9		1.000000 x	.000000 =	.000000
381.9		.100000 x	.000000 =	.000000

			T.E =	
6658.1	6658.1			
382.1		1.000000 x	.000000 =	.000000
382.1		.100000 x	.000000 =	.000000

			T.E =	

6658.2	6658.2			
382.2		1.000000 x	.000000 =	.000000
382.2		.100000 x	.000000 =	.000000

			T.E =	
6658.3	6658.3			
382.3		1.000000 x	.000000 =	.000000
382.3		.100000 x	.000000 =	.000000

			T.E =	
6659.1	6659.1			
382.4		1.000000 x	.000000 =	.000000
382.4		.100000 x	.000000 =	.000000

			T.E =	
6659.2	6659.2			
382.5		1.000000 x	.000000 =	.000000
382.5		.100000 x	.000000 =	.000000

			T.E =	
6659.3	6659.3			
382.6		1.000000 x	.000000 =	.000000
382.6		.100000 x	.000000 =	.000000

			T.E =	
6659.4	6659.4			
382.7		1.000000 x	.000000 =	.000000
382.7		.100000 x	.000000 =	.000000

			T.E =	
6659.5	6659.5			
382.8		1.000000 x	.000000 =	.000000
382.8		.100000 x	.000000 =	.000000

			T.E =	
6659.6	6659.6			
382.9		1.000000 x	.000000 =	.000000
382.9		.100000 x	.000000 =	.000000

			T.E =	

6660.1	6660.1			
382.10		1.000000 x	.000000 =	.000000
382.10		.100000 x	.000000 =	.000000

			T.E =	
6660.2	6660.2			
382.11		1.000000 x	.000000 =	.000000
382.11		.100000 x	.000000 =	.000000

			T.E =	
6660.3	6660.3			
382.12		1.000000 x	.000000 =	.000000
382.12		.100000 x	.000000 =	.000000

			T.E =	
6660.4	6660.4			
382.13		1.000000 x	.000000 =	.000000
382.13		.100000 x	.000000 =	.000000

			T.E =	
6660.5	6660.5			
382.14		1.000000 x	.000000 =	.000000
382.14		.100000 x	.000000 =	.000000

			T.E =	
6660.6	6660.6			
382.15		1.000000 x	.000000 =	.000000
382.15		.100000 x	.000000 =	.000000

			T.E =	
6661.1	6661.1			
380.1		.100000 x	396.000000 =	39.600000
380.1		1.000000 x	396.000000 =	396.000000

			T.E =	435.600000
6661.2	6661.2			
380.2		1.000000 x	502.000000 =	502.000000
380.2		.100000 x	502.000000 =	50.200000

			T.E =	552.200000

6661.3	6661.3			
380.3		1.000000 x	583.000000 =	583.000000
380.3		.100000 x	583.000000 =	58.300000

			T.E =	641.300000
6661.4	6661.4			
380.4		1.000000 x	1,056.000000 =	1,056.000000
380.4		.100000 x	1,056.000000 =	105.600000

			T.E =	1,161.600000
6661.5	6661.5			
380.5		1.000000 x	1,420.000000 =	1,420.000000
380.5		.100000 x	1,420.000000 =	142.000000

			T.E =	1,562.000000
6661.6	6661.6			
380.6		1.000000 x	1,966.000000 =	1,966.000000
380.6		.100000 x	1,966.000000 =	196.600000

			T.E =	2,162.600000
6662.1	6662.1			
384.1		1.000000 x	537.050000 =	537.050000
384.8		1.000000 x	.000000 =	.000000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	
6662.2	6662.2			
384.1		1.000000 x	537.050000 =	537.050000
384.9		1.000000 x	.000000 =	.000000
384.7		1.000000 x	.000000 =	.000000
384.6		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.4		1.000000 x	.000000 =	.000000

			AΘΡΟΙΣΜΑ =	537.050000

			T.E =	

6662.3 6662.3

384.1	1.000000 x	537.050000 =	537.050000
384.7	2.000000 x	.000000 =	.000000
384.9	2.000000 x	.000000 =	.000000
384.8	2.000000 x	.000000 =	.000000
384.5	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.4 6662.4

384.1	1.000000 x	537.050000 =	537.050000
384.9	2.000000 x	.000000 =	.000000
384.7	2.000000 x	.000000 =	.000000
384.6	2.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = 537.050000

T.E =

6662.5 6662.5

384.2	1.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.8	3.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.5	3.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.6 6662.6

384.2	1.000000 x	.000000 =	.000000
384.3	1.000000 x	.000000 =	.000000
384.4	1.000000 x	.000000 =	.000000
384.7	3.000000 x	.000000 =	.000000
384.9	3.000000 x	.000000 =	.000000
384.6	3.000000 x	.000000 =	.000000

ΑΘΡΟΙΣΜΑ = .000000

T.E =

6662.7	6662.7			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.5		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.8		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6662.8	6662.8			
384.2		1.000000 x	.000000 =	.000000
384.3		1.000000 x	.000000 =	.000000
384.9		4.000000 x	.000000 =	.000000
384.7		4.000000 x	.000000 =	.000000
384.6		4.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.1	6663.1			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.4		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6663.2	6663.2			
385.1		1.000000 x	.000000 =	.000000
385.5		1.000000 x	.000000 =	.000000
385.2		1.000000 x	.000000 =	.000000
385.3		1.000000 x	.000000 =	.000000

		ΑΘΡΟΙΣΜΑ =		.000000

		T.E =		
6701.1	6701.1			
368.1		1.020000 x	.000000 =	.000000
369.1		.224000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

		T.E =		

6701.10	6701.10			
368.10		1.030000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
369.10		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287

			T.E =	
6701.2	6701.2			
368.2		1.020000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
369.2		.224000 x	.000000 =	.000000

			T.E =	
6701.3	6701.3			
368.3		1.020000 x	.000000 =	.000000
369.3		.224000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

			T.E =	
6701.4	6701.4			
368.4		1.020000 x	.000000 =	.000000
369.4		.224000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6701.5	6701.5			
368.5		1.020000 x	.000000 =	.000000
369.5		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6701.6	6701.6			
368.6		1.020000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
369.6		.224000 x	.000000 =	.000000

			T.E =	

6701.7	6701.7			
368.7		1.020000 x	.000000 =	.000000
369.7		.224000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

T.E =

6701.8	6701.8			
368.8		1.020000 x	.000000 =	.000000
369.8		.224000 x	.000000 =	.000000
113		.238000 x	20.419486 =	4.859838
111		.595000 x	15.741598 =	9.366251

T.E =

6701.9	6701.9			
368.9		1.030000 x	.000000 =	.000000
369.9		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6702.1	6702.1			
368.11		1.020000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161
369.11		.224000 x	.000000 =	.000000

T.E =

6702.10	6702.10			
368.20		1.020000 x	.000000 =	.000000
369.20		.224000 x	.000000 =	.000000
111		.680000 x	15.741598 =	10.704287
113		.340000 x	20.419486 =	6.942625

T.E =

6702.2	6702.2			
368.12		1.020000 x	.000000 =	.000000
369.12		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6702.3

6702.3

368.13	1.020000 x	.000000 =	.000000
369.13	.224000 x	.000000 =	.000000
113	.102000 x	20.419486 =	2.082788
111	.433500 x	15.741598 =	6.823983

T.E =

6702.4

6702.4

368.14	1.020000 x	.000000 =	.000000
113	.119000 x	20.419486 =	2.429919
111	.459000 x	15.741598 =	7.225393
369.14	.224000 x	.000000 =	.000000

T.E =

6702.5

6702.5

368.15	1.020000 x	.000000 =	.000000
369.15	.224000 x	.000000 =	.000000
111	.484500 x	15.741598 =	7.626804
113	.144500 x	20.419486 =	2.950616

T.E =

6702.6

6702.6

368.16	1.020000 x	.000000 =	.000000
369.16	.224000 x	.000000 =	.000000
113	.170000 x	20.419486 =	3.471313
111	.518500 x	15.741598 =	8.162019

T.E =

6702.7

6702.7

368.17	1.020000 x	.000000 =	.000000
369.17	.224000 x	.000000 =	.000000
113	.195500 x	20.419486 =	3.992010
111	.552500 x	15.741598 =	8.697233

T.E =

6702.8

6702.8

368.18	1.020000 x	.000000 =	.000000
113	.238000 x	20.419486 =	4.859838
111	.595000 x	15.741598 =	9.366251
369.18	.224000 x	.000000 =	.000000

T.E =

6702.9	6702.9			
368.19		1.020000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
369.19		.224000 x	.000000 =	.000000
111		.637500 x	15.741598 =	10.035269

T.E =

6703.1	6703.1			
368.21		1.020000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525
369.21		.224000 x	.000000 =	.000000

T.E =

6703.10	6703.10			
368.30		1.020000 x	.000000 =	.000000
369.30		.224000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625
111		.680000 x	15.741598 =	10.704287

T.E =

6703.2	6703.2			
368.22		1.020000 x	.000000 =	.000000
369.22		.224000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6703.3	6703.3			
368.23		1.020000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
369.23		.224000 x	.000000 =	.000000

T.E =

6703.4	6703.4			
368.24		1.020000 x	.000000 =	.000000
369.24		.224000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6703.5	6703.5			
368.25		1.020000 x	.000000 =	.000000
369.25		.224000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6703.6	6703.6			
368.26		1.020000 x	.000000 =	.000000
369.26		.224000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6703.7	6703.7			
368.27		1.020000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
369.27		.224000 x	.000000 =	.000000

T.E =

6703.8	6703.8			
368.28		1.020000 x	.000000 =	.000000
369.28		.224000 x	.000000 =	.000000
111		.595000 x	15.741598 =	9.366251
113		.238000 x	20.419486 =	4.859838

T.E =

6703.9	6703.9			
368.29		1.020000 x	.000000 =	.000000
369.29		.224000 x	.000000 =	.000000
113		.289000 x	20.419486 =	5.901231
111		.637500 x	15.741598 =	10.035269

T.E =

6704.1	6704.1			
370.1		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6704.2	6704.2			
370.2		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.3	6704.3			
370.3		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.433500 x	15.741598 =	6.823983
113		.102000 x	20.419486 =	2.082788

			T.E =	
6704.4	6704.4			
370.4		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393

			T.E =	
6704.5	6704.5			
370.5		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

			T.E =	
6704.6	6704.6			
370.6		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019
370.8		1.000000 x	.000000 =	.000000

			T.E =	
6704.7	6704.7			
370.7		1.000000 x	.000000 =	.000000
370.8		1.000000 x	.000000 =	.000000
111		.552500 x	15.741598 =	8.697233
113		.195500 x	20.419486 =	3.992010

			T.E =	

6705.1	6705.1			
370.9		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.068000 x	20.419486 =	1.388525
111		.382500 x	15.741598 =	6.021161

T.E =

6705.2	6705.2			
370.10		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6705.3	6705.3			
370.11		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983
370.16		1.000000 x	.000000 =	.000000

T.E =

6705.4	6705.4			
370.12		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
111		.459000 x	15.741598 =	7.225393
113		.119000 x	20.419486 =	2.429919

T.E =

6705.5	6705.5			
370.13		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.144500 x	20.419486 =	2.950616
111		.484500 x	15.741598 =	7.626804

T.E =

6705.6	6705.6			
370.14		1.000000 x	.000000 =	.000000
370.16		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6705.7	6705.7			
370.15		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233
370.16		1.000000 x	.000000 =	.000000

T.E =

6706.1	6706.1			
370.17		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.382500 x	15.741598 =	6.021161
113		.068000 x	20.419486 =	1.388525

T.E =

6706.2	6706.2			
370.18		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.085000 x	20.419486 =	1.735656
111		.408000 x	15.741598 =	6.422572

T.E =

6706.3	6706.3			
370.19		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.102000 x	20.419486 =	2.082788
111		.433500 x	15.741598 =	6.823983

T.E =

6706.4	6706.4			
370.20		1.000000 x	.000000 =	.000000
113		.119000 x	20.419486 =	2.429919
111		.459000 x	15.741598 =	7.225393
370.24		1.000000 x	.000000 =	.000000

T.E =

6706.5	6706.5			
370.21		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
111		.484500 x	15.741598 =	7.626804
113		.144500 x	20.419486 =	2.950616

T.E =

6706.6	6706.6			
370.22		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.170000 x	20.419486 =	3.471313
111		.518500 x	15.741598 =	8.162019

T.E =

6706.7	6706.7			
370.23		1.000000 x	.000000 =	.000000
370.24		1.000000 x	.000000 =	.000000
113		.195500 x	20.419486 =	3.992010
111		.552500 x	15.741598 =	8.697233

T.E =

6710.1	6710.1			
374.1		1.020000 x	.000000 =	.000000
6326		.327500 x	134.041851 =	43.898706
113		.026350 x	20.419486 =	.538053
111		.085000 x	15.741598 =	1.338036

T.E =

6710.2	6710.2			
374.2		1.020000 x	.000000 =	.000000
111		.119000 x	15.741598 =	1.873250
113		.040800 x	20.419486 =	.833115
6326		.352500 x	134.041851 =	47.249752

T.E =

6710.3	6710.3			
374.3		1.020000 x	.000000 =	.000000
111		.161500 x	15.741598 =	2.542268
6326		.372500 x	134.041851 =	49.930589
113		.051000 x	20.419486 =	1.041394

T.E =

6710.4	6710.4			
374.4		1.020000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
6326		.382500 x	134.041851 =	51.271008
113		.063750 x	20.419486 =	1.301742

T.E =

6710.5	6710.5			
374.5		1.020000 x	.000000 =	.000000
6326		.391250 x	134.041851 =	52.443874
113		.068000 x	20.419486 =	1.388525
111		.187000 x	15.741598 =	2.943679

T.E =

6710.6	6710.6			
374.6		1.020000 x	.000000 =	.000000
111		.204000 x	15.741598 =	3.211286
113		.076500 x	20.419486 =	1.562091
6327		.393750 x	156.326079 =	61.553394

T.E =

6710.7	6710.7			
374.7		1.020000 x	.000000 =	.000000
111		.289000 x	15.741598 =	4.549322
6327		.431250 x	156.326079 =	67.415622
113		.093500 x	20.419486 =	1.909222

T.E =

6710.8	6710.8			
374.8		1.020000 x	.000000 =	.000000
111		.340000 x	15.741598 =	5.352143
6327		.500000 x	156.326079 =	78.163040
113		.119000 x	20.419486 =	2.429919

T.E =

6711.1	6711.1			
375.1		1.020000 x	8.510000 =	8.680200
6069		.370000 x	24.461113 =	9.050612
113		.017000 x	20.419486 =	.347131
111		.161500 x	15.741598 =	2.542268

T.E =

20.620211

6711.2	6711.2			
375.2		1.020000 x	13.330000 =	13.596600
111		.187000 x	15.741598 =	2.943679
6069		.390000 x	24.461113 =	9.539834
113		.021250 x	20.419486 =	.433914

T.E =

26.514027

6711.3	6711.3			
375.3		1.020000 x	20.790000 =	21.205800
111		.204000 x	15.741598 =	3.211286
6069		.400000 x	24.461113 =	9.784445
113		.026350 x	20.419486 =	.538053

			T.E =	34.739585
6711.4	6711.4			
375.4		1.020000 x	33.650000 =	34.323000
111		.246500 x	15.741598 =	3.880304
6069		.420000 x	24.461113 =	10.273667
113		.040800 x	20.419486 =	.833115

			T.E =	49.310086
6711.5	6711.5			
375.5		1.020000 x	42.800000 =	43.656000
6069		.430000 x	24.461113 =	10.518279
113		.051000 x	20.419486 =	1.041394
111		.289000 x	15.741598 =	4.549322

			T.E =	59.764994
6711.6	6711.6			
375.6		1.020000 x	54.230000 =	55.314600
6069		.440000 x	24.461113 =	10.762890
113		.063750 x	20.419486 =	1.301742
111		.297500 x	15.741598 =	4.683125

			T.E =	72.062357
6711.7	6711.7			
375.7		1.020000 x	87.910000 =	89.668200
6069		.520000 x	24.461113 =	12.719779
113		.076500 x	20.419486 =	1.562091
111		.357000 x	15.741598 =	5.619750

			T.E =	109.569820
6712.1	6712.1			
375.8		1.050000 x	11.640000 =	12.222000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	39.738563

6712.2	6712.2			
375.9		1.050000 x	14.980000 =	15.729000
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	43.245563
6712.3	6712.3			
375.10		1.050000 x	20.150000 =	21.157500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	48.674063
6712.4	6712.4			
375.11		1.050000 x	27.290000 =	28.654500
375.13		1.000000 x	10.160000 =	10.160000
113		.850000 x	20.419486 =	17.356563

			T.E =	56.171063
6712.5	6712.5			
375.12		1.050000 x	34.560000 =	36.288000
113		.850000 x	20.419486 =	17.356563
375.13		1.000000 x	10.160000 =	10.160000

			T.E =	63.804563
6713	6713			
375.13		1.000000 x	10.160000 =	10.160000
113		.021250 x	20.419486 =	.433914
111		.187000 x	15.741598 =	2.943679
375.14		1.000000 x	17.510000 =	17.510000

			T.E =	31.047593
6720.1	6720.1			
394.2		1.050000 x	.000000 =	.000000
700		.200000 x	.000000 =	.000000
6323		.090000 x	105.699854 =	9.512987
112		1.190000 x	17.312112 =	20.601413
113		.255000 x	20.419486 =	5.206969

			T.E =	

6720.10	6720.10			
394.5		1.050000 x	.000000 =	.000000
6325		.221000 x	115.689854 =	25.567458
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6720.11	6720.11			
394.6		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.234000 x	115.689854 =	27.071426
700		.380000 x	.000000 =	.000000

T.E =

6720.12	6720.12			
394.7		1.050000 x	.000000 =	.000000
6325		.241000 x	115.689854 =	27.881255
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6720.2	6720.2			
394.3		1.050000 x	.000000 =	.000000
6323		.110000 x	105.699854 =	11.626984
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6720.3	6720.3			
394.4		1.050000 x	.000000 =	.000000
6323		.131000 x	105.699854 =	13.846681
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6720.4 6720.4

394.5	1.050000 x	.000000 =	.000000
112	1.360000 x	17.312112 =	23.544472
113	.510000 x	20.419486 =	10.413938
6323	.154000 x	105.699854 =	16.277778
700	.350000 x	.000000 =	.000000

T.E =

6720.5 6720.5

394.6	1.050000 x	.000000 =	.000000
6323	.166000 x	105.699854 =	17.546176
112	1.445000 x	17.312112 =	25.016002
700	.380000 x	.000000 =	.000000
113	.595000 x	20.419486 =	12.149594

T.E =

6720.6 6720.6

394.7	1.050000 x	.000000 =	.000000
112	1.487500 x	17.312112 =	25.751767
700	.400000 x	.000000 =	.000000
6323	.173000 x	105.699854 =	18.286075
113	.637500 x	20.419486 =	13.017422

T.E =

6720.7 6720.7

394.2	1.050000 x	.000000 =	.000000
6325	.138000 x	115.689854 =	15.965200
700	.200000 x	.000000 =	.000000
113	.255000 x	20.419486 =	5.206969
112	1.190000 x	17.312112 =	20.601413

T.E =

6720.8 6720.8

394.3	1.050000 x	.000000 =	.000000
112	1.275000 x	17.312112 =	22.072943
113	.340000 x	20.419486 =	6.942625
6325	.165000 x	115.689854 =	19.088826
700	.250000 x	.000000 =	.000000

T.E =

6720.9	6720.9			
394.4		1.050000 x	.000000 =	.000000
6325		.193000 x	115.689854 =	22.328142
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6721.1	6721.1			
394.8		1.050000 x	.000000 =	.000000
6323		.060000 x	105.699854 =	6.341991
112		1.190000 x	17.312112 =	20.601413
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6721.10	6721.10			
394.11		1.050000 x	.000000 =	.000000
6325		.130000 x	115.689854 =	15.039681
700		.350000 x	.000000 =	.000000
113		.510000 x	20.419486 =	10.413938
112		1.360000 x	17.312112 =	23.544472

T.E =

6721.11	6721.11			
394.12		1.050000 x	.000000 =	.000000
112		1.445000 x	17.312112 =	25.016002
113		.595000 x	20.419486 =	12.149594
6325		.140000 x	115.689854 =	16.196580
700		.380000 x	.000000 =	.000000

T.E =

6721.12	6721.12			
394.13		1.050000 x	.000000 =	.000000
6325		.150000 x	115.689854 =	17.353478
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
113		.637500 x	20.419486 =	13.017422

T.E =

6721.2	6721.2			
394.9		1.050000 x	.000000 =	.000000
6323		.070000 x	105.699854 =	7.398990
112		1.275000 x	17.312112 =	22.072943
700		.250000 x	.000000 =	.000000
113		.340000 x	20.419486 =	6.942625

T.E =

6721.3	6721.3			
394.10		1.050000 x	.000000 =	.000000
6323		.080000 x	105.699854 =	8.455988
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282
112		1.275000 x	17.312112 =	22.072943

T.E =

6721.4	6721.4			
394.11		1.050000 x	.000000 =	.000000
112		1.360000 x	17.312112 =	23.544472
113		.510000 x	20.419486 =	10.413938
6323		.090000 x	105.699854 =	9.512987
700		.350000 x	.000000 =	.000000

T.E =

6721.5	6721.5			
394.12		1.050000 x	.000000 =	.000000
6323		.100000 x	105.699854 =	10.569985
112		1.445000 x	17.312112 =	25.016002
700		.380000 x	.000000 =	.000000
113		.595000 x	20.419486 =	12.149594

T.E =

6721.6	6721.6			
394.13		1.050000 x	.000000 =	.000000
112		1.487500 x	17.312112 =	25.751767
700		.400000 x	.000000 =	.000000
6323		.110000 x	105.699854 =	11.626984
113		.637500 x	20.419486 =	13.017422

T.E =

6721.7	6721.7			
394.8		1.050000 x	.000000 =	.000000
6325		.100000 x	115.689854 =	11.568985
700		.200000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969
112		1.190000 x	17.312112 =	20.601413

T.E =

6721.8	6721.8			
394.9		1.050000 x	.000000 =	.000000
112		1.275000 x	17.312112 =	22.072943
113		.340000 x	20.419486 =	6.942625
6325		.110000 x	115.689854 =	12.725884
700		.250000 x	.000000 =	.000000

T.E =

6721.9	6721.9			
394.10		1.050000 x	.000000 =	.000000
6325		.120000 x	115.689854 =	13.882782
112		1.275000 x	17.312112 =	22.072943
700		.300000 x	.000000 =	.000000
113		.425000 x	20.419486 =	8.678282

T.E =

6722	6722			
394.1		1.050000 x	.000000 =	.000000
112		.425000 x	17.312112 =	7.357648
700		.120000 x	.000000 =	.000000
113		.255000 x	20.419486 =	5.206969

T.E =

6730.1	6730.1			
261		1.050000 x	15.100000 =	15.855000
6323		.090000 x	105.699854 =	9.512987
652		.002500 x	149.504950 =	.373762
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E = 39.510908

6730.10	6730.10			
263		1.050000 x	32.400000 =	34.020000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	115.689854 =	28.806774
652		.004500 x	149.504950 =	.672772
113		.340000 x	20.419486 =	6.942625

			T.E =	82.482944
6730.11	6730.11			
263.2		1.050000 x	46.700000 =	49.035000
6325		.310000 x	115.689854 =	35.863855
652		.005000 x	149.504950 =	.747525
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

			T.E =	110.977403
6730.12	6730.12			
264		1.050000 x	64.100000 =	67.305000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	115.689854 =	42.805246
652		.006500 x	149.504950 =	.971782
112		.680000 x	17.312112 =	11.772236

			T.E =	141.694038
6730.2	6730.2			
261.2		1.050000 x	20.700000 =	21.735000
6323		.110000 x	105.699854 =	11.626984
652		.003000 x	149.504950 =	.448515
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

			T.E =	47.579657
6730.3	6730.3			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
112		.382500 x	17.312112 =	6.621883
6323		.131000 x	105.699854 =	13.846681
652		.003500 x	149.504950 =	.523267
113		.297500 x	20.419486 =	6.074797

			T.E =	58.026718

6730.4	6730.4			
263		1.050000 x	32.400000 =	34.020000
6323		.170000 x	105.699854 =	17.968975
652		.004500 x	149.504950 =	.672772
111		.297500 x	15.741598 =	4.683125
113		.340000 x	20.419486 =	6.942625
112		.425000 x	17.312112 =	7.357648
			T.E =	71.645146
6730.5	6730.5			
263.2		1.050000 x	46.700000 =	49.035000
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
6323		.226000 x	105.699854 =	23.888167
652		.005000 x	149.504950 =	.747525
112		.552500 x	17.312112 =	9.564942
			T.E =	99.001715
6730.6	6730.6			
264		1.050000 x	64.100000 =	67.305000
6323		.274000 x	105.699854 =	28.961760
652		.006500 x	149.504950 =	.971782
113		.595000 x	20.419486 =	12.149594
112		.680000 x	17.312112 =	11.772236
111		.425000 x	15.741598 =	6.690179
			T.E =	127.850552
6730.7	6730.7			
261		1.050000 x	15.100000 =	15.855000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	115.689854 =	15.965200
652		.002500 x	149.504950 =	.373762
113		.255000 x	20.419486 =	5.206969
			T.E =	45.963121
6730.8	6730.8			
261.2		1.050000 x	20.700000 =	21.735000
6325		.165000 x	115.689854 =	19.088826
652		.003000 x	149.504950 =	.448515
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
			T.E =	55.041499

6730.9	6730.9			
262		1.050000 x	26.300000 =	27.615000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	115.689854 =	22.328142
652		.003500 x	149.504950 =	.523267
112		.382500 x	17.312112 =	6.621883

T.E = 66.508179

6731.1	6731.1			
261.3		1.050000 x	.000000 =	.000000
6323		.090000 x	105.699854 =	9.512987
652		.002500 x	149.504950 =	.373762
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118
111		.170000 x	15.741598 =	2.676072

T.E =

6731.10	6731.10			
263.1		1.050000 x	.000000 =	.000000
111		.297500 x	15.741598 =	4.683125
112		.425000 x	17.312112 =	7.357648
6325		.249000 x	115.689854 =	28.806774
652		.004500 x	149.504950 =	.672772
113		.340000 x	20.419486 =	6.942625

T.E =

6731.11	6731.11			
263.3		1.050000 x	.000000 =	.000000
6325		.310000 x	115.689854 =	35.863855
652		.005000 x	149.504950 =	.747525
111		.340000 x	15.741598 =	5.352143
113		.510000 x	20.419486 =	10.413938
112		.552500 x	17.312112 =	9.564942

T.E =

6731.12	6731.12			
264.1		1.050000 x	.000000 =	.000000
111		.425000 x	15.741598 =	6.690179
113		.595000 x	20.419486 =	12.149594
6325		.370000 x	115.689854 =	42.805246
652		.006500 x	149.504950 =	.971782
112		.680000 x	17.312112 =	11.772236

T.E =

6731.2 6731.2

261.4	1.050000 x	.000000 =	.000000
6323	.110000 x	105.699854 =	11.626984
652	.003000 x	149.504950 =	.448515
113	.255000 x	20.419486 =	5.206969
112	.340000 x	17.312112 =	5.886118
111	.170000 x	15.741598 =	2.676072

T.E =

6731.3 6731.3

262.1	1.050000 x	.000000 =	.000000
111	.212500 x	15.741598 =	3.345090
112	.382500 x	17.312112 =	6.621883
6323	.131000 x	105.699854 =	13.846681
652	.003500 x	149.504950 =	.523267
113	.297500 x	20.419486 =	6.074797

T.E =

6731.4 6731.4

263.1	1.050000 x	.000000 =	.000000
6323	.170000 x	105.699854 =	17.968975
652	.004500 x	149.504950 =	.672772
111	.297500 x	15.741598 =	4.683125
113	.340000 x	20.419486 =	6.942625
112	.425000 x	17.312112 =	7.357648

T.E =

6731.5 6731.5

263.3	1.050000 x	.000000 =	.000000
111	.340000 x	15.741598 =	5.352143
113	.510000 x	20.419486 =	10.413938
6323	.226000 x	105.699854 =	23.888167
652	.005000 x	149.504950 =	.747525
112	.552500 x	17.312112 =	9.564942

T.E =

6731.6 6731.6

264.1	1.050000 x	.000000 =	.000000
6323	.274000 x	105.699854 =	28.961760
652	.006500 x	149.504950 =	.971782
113	.595000 x	20.419486 =	12.149594
112	.680000 x	17.312112 =	11.772236
111	.425000 x	15.741598 =	6.690179

T.E =

6731.7	6731.7			
261.3		1.050000 x	.000000 =	.000000
111		.170000 x	15.741598 =	2.676072
112		.340000 x	17.312112 =	5.886118
6325		.138000 x	115.689854 =	15.965200
652		.002500 x	149.504950 =	.373762
113		.255000 x	20.419486 =	5.206969

			T.E =	
6731.8	6731.8			
261.4		1.050000 x	.000000 =	.000000
6325		.165000 x	115.689854 =	19.088826
652		.003000 x	149.504950 =	.448515
111		.170000 x	15.741598 =	2.676072
113		.255000 x	20.419486 =	5.206969
112		.340000 x	17.312112 =	5.886118

			T.E =	
6731.9	6731.9			
262.1		1.050000 x	.000000 =	.000000
111		.212500 x	15.741598 =	3.345090
113		.297500 x	20.419486 =	6.074797
6325		.193000 x	115.689854 =	22.328142
652		.003500 x	149.504950 =	.523267
112		.382500 x	17.312112 =	6.621883

			T.E =	
6732	6732			
395.5		1.050000 x	.000000 =	.000000
113		.850000 x	20.419486 =	17.356563

			T.E =	
6740.1	6740.1			
710		3.770000 x	.000000 =	.000000
6303		1.880000 x	20.322867 =	38.206990
6326		.940000 x	134.041851 =	125.999340

			T.E =	
6740.2	6740.2			
6740.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.041851 =	97.850551

			T.E =	

6741.1	6741.1			
710		3.770000 x	.000000 =	.000000
6326		.940000 x	134.041851 =	125.999340

			T.E =	
6741.2	6741.2			
6741.1		1.000000 x	.000000 =	.000000
6326		.730000 x	134.041851 =	97.850551

			T.E =	
6742.1	6742.1			
6303		3.040000 x	20.322867 =	61.781516
6328		.400000 x	159.902391 =	63.960956

			T.E =	125.742472
6742.10	6742.10			
6303		7.520000 x	20.322867 =	152.827960
6328		2.110000 x	159.902391 =	337.394045

			T.E =	490.222005
6742.11	6742.11			
6303		8.030000 x	20.322867 =	163.192622
6328		2.430000 x	159.902391 =	388.562810

			T.E =	551.755432
6742.2	6742.2			
6303		3.500000 x	20.322867 =	71.130035
6328		.500000 x	159.902391 =	79.951196

			T.E =	151.081230
6742.3	6742.3			
6303		4.020000 x	20.322867 =	81.697925
6328		.630000 x	159.902391 =	100.738506

			T.E =	182.436432
6742.4	6742.4			
6303		4.530000 x	20.322867 =	92.062588
6328		.800000 x	159.902391 =	127.921913

			T.E =	219.984500

6742.5	6742.5			
6303		5.000000 x	20.322867 =	101.614335
6328		.950000 x	159.902391 =	151.907271

			T.E =	253.521606
6742.6	6742.6			
6303		5.530000 x	20.322867 =	112.385455
6328		1.170000 x	159.902391 =	187.085797

			T.E =	299.471252
6742.7	6742.7			
6303		6.040000 x	20.322867 =	122.750117
6328		1.410000 x	159.902391 =	225.462371

			T.E =	348.212488
6742.8	6742.8			
6303		6.520000 x	20.322867 =	132.505093
6328		1.610000 x	159.902391 =	257.442850

			T.E =	389.947942
6742.9	6742.9			
6303		7.040000 x	20.322867 =	143.072984
6328		1.880000 x	159.902391 =	300.616495

			T.E =	443.689479
6743.1	6743.1			
6303		3.040000 x	20.322867 =	61.781516
6328		.440000 x	159.902391 =	70.357052

			T.E =	132.138568
6743.10	6743.10			
6303		7.520000 x	20.322867 =	152.827960
6328		2.240000 x	159.902391 =	358.181356

			T.E =	511.009316
6743.11	6743.11			
6303		8.030000 x	20.322867 =	163.192622
6328		2.570000 x	159.902391 =	410.949145

			T.E =	574.141767

6743.12	6743.12			
6303		3.040000 x	20.322867 =	61.781516
6328		.750000 x	159.902391 =	119.926793

			T.E =	181.708309
6743.13	6743.13			
6303		3.500000 x	20.322867 =	71.130035
6328		.910000 x	159.902391 =	145.511176

			T.E =	216.641210
6743.14	6743.14			
6303		4.020000 x	20.322867 =	81.697925
6328		1.090000 x	159.902391 =	174.293606

			T.E =	255.991532
6743.15	6743.15			
6303		4.530000 x	20.322867 =	92.062588
6328		1.300000 x	159.902391 =	207.873108

			T.E =	299.935696
6743.16	6743.16			
6303		5.000000 x	20.322867 =	101.614335
6328		1.550000 x	159.902391 =	247.848706

			T.E =	349.463041
6743.17	6743.17			
6303		5.530000 x	20.322867 =	112.385455
6328		1.850000 x	159.902391 =	295.819423

			T.E =	408.204878
6743.2	6743.2			
6303		3.500000 x	20.322867 =	71.130035
6328		.550000 x	159.902391 =	87.946315

			T.E =	159.076350
6743.3	6743.3			
6303		4.020000 x	20.322867 =	81.697925
6328		.690000 x	159.902391 =	110.332650

			T.E =	192.030575

6743.4	6743.4			
6303		4.530000 x	20.322867 =	92.062588
6328		.860000 x	159.902391 =	137.516056

			T.E =	229.578644
6743.5	6743.5			
6303		5.000000 x	20.322867 =	101.614335
6328		1.020000 x	159.902391 =	163.100439

			T.E =	264.714774
6743.6	6743.6			
6303		5.530000 x	20.322867 =	112.385455
6328		1.260000 x	159.902391 =	201.477013

			T.E =	313.862467
6743.7	6743.7			
6303		6.040000 x	20.322867 =	122.750117
6328		1.500000 x	159.902391 =	239.853587

			T.E =	362.603703
6743.8	6743.8			
6303		6.520000 x	20.322867 =	132.505093
6328		1.720000 x	159.902391 =	275.032113

			T.E =	407.537205
6743.9	6743.9			
6303		7.040000 x	20.322867 =	143.072984
6328		2.000000 x	159.902391 =	319.804782

			T.E =	462.877766
6744	6744			
111		2.125000 x	15.741598 =	33.450896
111		4.250000 x	15.741598 =	66.901792
113		2.125000 x	20.419486 =	43.391408
113		2.125000 x	20.419486 =	43.391408
112		2.125000 x	17.312112 =	36.788238

			T.E =	223.923741

6751	6751				
234.2		.400000 x	.901300 =	.360520	
113		.051000 x	20.419486 =	1.041394	
113		.170000 x	20.419486 =	3.471313	
235		.650000 x	.643000 =	.417950	

			T.E =	5.291176	
6752	6752				
237		1.050000 x	1.110000 =	1.165500	
113		.017000 x	20.419486 =	.347131	
111		.025500 x	15.741598 =	.401411	

			T.E =	1.914042	
6753	6753				
237		1.050000 x	1.110000 =	1.165500	
112		.085000 x	17.312112 =	1.471530	
113		.085000 x	20.419486 =	1.735656	

			T.E =	4.372686	
6754	6754				
237.1		1.000000 x	1.260000 =	1.260000	
112		.017000 x	17.312112 =	.294306	
111		.051000 x	15.741598 =	.802821	
113		.212500 x	20.419486 =	4.339141	

			T.E =	6.696268	
6801	6801				
232		.700000 x	1.900000 =	1.330000	
251		.008000 x	290.000000 =	2.320000	
113		2.550000 x	20.419486 =	52.069689	
112		1.700000 x	17.312112 =	29.430590	
111		.850000 x	15.741598 =	13.380358	

			T.E =	98.530638	
6802	6802				
231		15.000000 x	.775000 =	11.625000	
251		.050000 x	290.000000 =	14.500000	
113		2.550000 x	20.419486 =	52.069689	
252.1		.050000 x	.000000 =	.000000	
111		4.250000 x	15.741598 =	66.901792	

			T.E =		

6803	6803			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	149.504950 =	1.794059
111		.510000 x	15.741598 =	8.028215
113		.680000 x	20.419486 =	13.885250

			T.E =	30.541525
6804	6804			
111		.510000 x	15.741598 =	8.028215
652		.120000 x	149.504950 =	17.940594
113		.680000 x	20.419486 =	13.885250

			T.E =	39.854059
6805	6805			
301		1.000000 x	4.060000 =	4.060000
652		.002000 x	149.504950 =	.299010
2522		.005000 x	153.838520 =	.769193
113		.340000 x	20.419486 =	6.942625
111		.340000 x	15.741598 =	5.352143

			T.E =	17.422971
6806	6806			
111		.340000 x	15.741598 =	5.352143
113		.340000 x	20.419486 =	6.942625
6326		.005000 x	134.041851 =	.670209
652		.002000 x	149.504950 =	.299010

			T.E =	13.263988
6807	6807			
111		1.700000 x	15.741598 =	26.760717

			T.E =	26.760717
6808	6808			
111		.425000 x	15.741598 =	6.690179

			T.E =	6.690179
6810	6810			
241		2.600000 x	7.050000 =	18.330000
113		1.062500 x	20.419486 =	21.695704
113		.850000 x	20.419486 =	17.356563
111		1.062500 x	15.741598 =	16.725448
241		1.300000 x	7.050000 =	9.165000

			T.E =	83.272715

6811	6811			
236		6.430000 x	.612000 =	3.935160
113		.850000 x	20.419486 =	17.356563
113		3.400000 x	20.419486 =	69.426252
241		3.150000 x	7.050000 =	22.207500

			T.E =	112.925476
6812	6812			
397.1		2.100000 x	7.050000 =	14.805000
111		.425000 x	15.741598 =	6.690179
6324		.250000 x	110.694854 =	27.673714
113		4.250000 x	20.419486 =	86.782816
243		11.900000 x	2.100000 =	24.990000

			AΘΡΟΙΣΜΑ =	160.941708
	T.E =	.262500 x	160.941708 =	42.247198

7001	7001			
7001 A		1.000000 x	.232193 =	.232193
7001 Δ		1.000000 x	.316240 =	.316240
7001 Ε		1.000000 x	.809699 =	.809699
7001 Γ		1.000000 x	.968361 =	.968361
7001 Β		1.000000 x	.758556 =	.758556

			AΘΡΟΙΣΜΑ =	3.085049

			T.E =	3.547806
7002	7002			
560		.005104 x	684.476690 =	3.493569

			T.E =	3.493569
7003	7003			
7003 A		1.000000 x	.116096 =	.116096
7003 Δ		1.000000 x	.785382 =	.785382
7003 Γ		1.000000 x	.547970 =	.547970
7003 Β		1.000000 x	.591430 =	.591430

			AΘΡΟΙΣΜΑ =	2.040878

			T.E =	2.244966
7004	7004			
561		.003250 x	899.388090 =	2.923011

			T.E =	2.923011

7005	7005			
7005 Α		1.000000 x	.116096 =	.116096
7005 Ε		1.000000 x	.785382 =	.785382
7005 Δ		1.000000 x	.547970 =	.547970
7005 Γ		1.000000 x	.295715 =	.295715
7005 Β		1.000000 x	1.035002 =	1.035002

			ΑΘΡΟΙΣΜΑ =	2.780165

			T.E =	3.058182
7006	7006			
561		.000862 x	899.388090 =	.775273
561		.001723 x	899.388090 =	1.549646
561		.000812 x	899.388090 =	.730303

			T.E =	3.055221
7007	7007			
213		.100000 x	1.949500 =	.194950
550		.003500 x	1,046.704714 =	3.663466
518		.001750 x	860.662642 =	1.506160
502		.000583 x	782.814573 =	.456381
116		.280000 x	20.419486 =	5.717456

			T.E =	11.538413
7008	7008			
111		.021000 x	15.741598 =	.330574
112		.210000 x	17.312112 =	3.635544
7007		1.100000 x	11.538413 =	12.692254
558		.000972 x	1,083.651457 =	1.053309
507		.000875 x	912.951257 =	.798832
503		.001750 x	891.952173 =	1.560916

			T.E =	20.071429
7009	7009			
560		.006417 x	684.476690 =	4.392287

			T.E =	4.392287
7010	7010			
7010 Α		1.000000 x	.341350 =	.341350
7010 Δ		1.000000 x	.316240 =	.316240
7010 Ε		1.000000 x	.987338 =	.987338
7010 Γ		1.000000 x	.547970 =	.547970
7010 Β		1.000000 x	.512567 =	.512567

			ΑΘΡΟΙΣΜΑ =	2.705465

			T.E =	3.111285

7011	7011			
502		.001367 x	782.814573 =	1.070108
502		.000700 x	782.814573 =	.547970
503		.000438 x	891.952173 =	.390675
563		.001367 x	.000000 =	.000000
558		.000729 x	1,083.651457 =	.789982
558		.000729 x	1,083.651457 =	.789982
554		.000438 x	33.418000 =	.014637

			ΑΘΡΟΙΣΜΑ =	3.603354

			T.E =	
7012	7012			
7008		1.000000 x	20.071429 =	20.071429

			ΑΘΡΟΙΣΜΑ =	20.071429

			T.E =	22.078572
7013	7013			
7003		1.000000 x	2.244966 =	2.244966

			ΑΘΡΟΙΣΜΑ =	2.244966

			T.E =	2.469463
7014	7014			
7005		1.000000 x	3.058182 =	3.058182

			ΑΘΡΟΙΣΜΑ =	3.058182

			T.E =	3.364000
7015	7015			
111		.056000 x	15.741598 =	.881529
7001		.900000 x	3.547806 =	3.193025
X 630		.300000 x	1.475710 =	.442713
X 630.1		.300000 x	1.620878 =	.486263

			T.E =	5.003531
7016.9	7016.9			
7016.4		1.000000 x	126.318649 =	126.318649
7016.8		1.000000 x	104.139379 =	104.139379
7016.5		1.000000 x	25.263730 =	25.263730
7016.7		1.000000 x	80.282150 =	80.282150
7016.6		1.000000 x	37.895595 =	37.895595

			T.E =	373.899503

7017.8	7017.8				
7017.3		1.000000 x	92.550353 =		92.550353
7017.4		1.000000 x	18.510071 =		18.510071
7017.5		1.000000 x	33.318127 =		33.318127
7017.7		1.000000 x	52.069689 =		52.069689
7017.6		1.000000 x	80.282150 =		80.282150

			T.E =		276.730390
7018	7018				
233.2		1.150000 x	.639200 =		.735080
113		.051000 x	20.419486 =		1.041394

			AΘΡΟΙΣΜΑ =		1.776474

			T.E =		1.954121
7019	7019				
7019 A6		1.000000 x	191.532007 =		191.532007
7019 A7		1.000000 x	19.153201 =		19.153201

			T.E =		210.685208
7019.1	7019.1				
396.5	-	5.000000 x	1.180000 =	-	5.900000
7019		1.000000 x	210.685208 =		210.685208

			T.E =		204.785208
7020	7020				
213		.150000 x	1.949500 =		.292425
116		.980000 x	20.419486 =		20.011096
7020.2		.010938 x	3,493.139487 =		38.207960

			T.E =		58.511481
7020.1	7020.1				
570.2		.350000 x	124.784076 =		43.674427
571.2		.070000 x	259.459536 =		18.162168
571.1		.280000 x	434.016370 =		121.524584

			AΘΡΟΙΣΜΑ =		183.361178
	T.E =	.015625 x	183.361178 =		2.865018

7021	7021				
213		.150000 x	1.949500 =		.292425
116		1.120000 x	20.419486 =		22.869824
7021.2		.014583 x	3,053.149913 =		44.524085

			T.E =		67.686335

7021.1	7021.1			
570.2		.350000 x	124.784076 =	43.674427
571.1		.280000 x	434.016370 =	121.524584
571.2		.070000 x	259.459536 =	18.162168
			AΘΡΟΙΣΜΑ =	183.361178
	T.E =	.020833 x	183.361178 =	3.819963
7022	7022			
213		.150000 x	1.949500 =	.292425
116		1.400000 x	20.419486 =	28.587280
7022.2		.020000 x	2,803.631231 =	56.072625
			T.E =	84.952330
7022.1	7022.1			
570.2		.350000 x	124.784076 =	43.674427
571.1		.280000 x	434.016370 =	121.524584
571.2		.070000 x	259.459536 =	18.162168
			AΘΡΟΙΣΜΑ =	183.361178
	T.E =	.028571 x	183.361178 =	5.238812
7023	7023			
398.2		1.050000 x	39.000000 =	40.950000
111		.425000 x	15.741598 =	6.690179
116		.850000 x	20.419486 =	17.356563
550		.012143 x	1,046.704714 =	12.710135
			T.E =	77.706878
7024	7024			
398.3		1.050000 x	47.000000 =	49.350000
111		.425000 x	15.741598 =	6.690179
550		.020238 x	1,046.704714 =	21.183210
116		.850000 x	20.419486 =	17.356563
			T.E =	94.579952
7025	7025			
396.5		.009000 x	1.180000 =	.010620
652		.001000 x	149.504950 =	.149505
550		.020238 x	1,046.704714 =	21.183210
116		.850000 x	20.419486 =	17.356563
112		.425000 x	17.312112 =	7.357648
111		.425000 x	15.741598 =	6.690179
233		6.180000 x	.583300 =	3.604794
398.4		1.000000 x	63.000000 =	63.000000
			T.E =	119.352519

7026	7026				
398.5		125.400000 x	5.780000 =	724.812000	
236		16.808000 x	.612000 =	10.286496	
113		.909160 x	20.419486 =	18.564580	
113		3.400000 x	20.419486 =	69.426252	
6310		12.350000 x	1.480293 =	18.281619	
			AΘΡΟΙΣΜΑ =	841.370947	
	T.E =	.007259 x	841.370947 =	6.107512	
7027	7027				
236		1.100000 x	.612000 =	.673200	
113		.059500 x	20.419486 =	1.214959	
			T.E =	1.888159	
7028	7028				
111		.144500 x	15.741598 =	2.274661	
6751		.120000 x	5.291176 =	.634941	
6751		.600000 x	5.291176 =	3.174706	
111		.425000 x	15.741598 =	6.690179	
112		.144500 x	17.312112 =	2.501600	
			AΘΡΟΙΣΜΑ =	15.276087	
			T.E =	17.567500	
7029	7029				
568.1		.021250 x	2,624.193281 =	55.764107	
569.2		.021250 x	614.345912 =	13.054851	
570.2		.021250 x	124.784076 =	2.651662	
571.2		.021250 x	259.459536 =	5.513515	
			T.E =	76.984135	
7030	7030				
398.6		.015385 x	330.000000 =	5.077050	
572		.026563 x	846.732357 =	22.491752	
			AΘΡΟΙΣΜΑ =	27.568802	
			T.E =	38.596322	
7031	7031				
573		.106250 x	1,077.386644 =	114.472331	
			AΘΡΟΙΣΜΑ =	114.472331	
			T.E =	131.643181	
7032	7032				
573		.212500 x	1,077.386644 =	228.944662	
			AΘΡΟΙΣΜΑ =	228.944662	
			T.E =	297.628060	

7101.1	7101.1				
398.1		15.000000 x	.225000 =		3.375000
574		.132813 x	3,528.328382 =		468.607877
T 630		.105000 x	1.791933 =		.188153
T 630.1		.105000 x	1.968209 =		.206662
567		.132813 x	383.300100 =		50.907236
				ΑΘΡΟΙΣΜΑ =	523.284928
				T.E =	538.983476
7101.2	7101.2				
398.1		15.000000 x	.225000 =		3.375000
574		.148750 x	3,528.328382 =		524.838847
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
567		.148750 x	383.300100 =		57.015890
				ΑΘΡΟΙΣΜΑ =	585.624552
				T.E =	603.193288
7101.3	7101.3				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
574		.159375 x	3,528.328382 =		562.327336
567		.159375 x	383.300100 =		61.088453
				ΑΘΡΟΙΣΜΑ =	627.185604
				T.E =	646.001172
7101.4	7101.4				
398.1		15.000000 x	.225000 =		3.375000
567		.170000 x	383.300100 =		65.161017
574		.170000 x	3,528.328382 =		599.815825
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
				ΑΘΡΟΙΣΜΑ =	668.746657
				T.E =	688.809057
7101.5	7101.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.968209 =		.206662
567		.191250 x	383.300100 =		73.306144
T 630		.105000 x	1.791933 =		.188153
574		.191250 x	3,528.328382 =		674.792803
				ΑΘΡΟΙΣΜΑ =	751.868762
				T.E =	774.424825

7102.1	7102.1				
398.1		15.000000 x	.225000 =		3.375000
567		.302813 x	383.300100 =		116.068253
T 630		.105000 x	1.791933 =		.188153
T 630.1		.105000 x	1.968209 =		.206662
574		.302813 x	3,528.328382 =		1,068.423702
			AΘΡΟΙΣΜΑ =		1,188.261770
			T.E =		1,223.909624
7102.2	7102.2				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
574		.329375 x	3,528.328382 =		1,162.143161
567		.329375 x	383.300100 =		126.249470
			AΘΡΟΙΣΜΑ =		1,292.162446
			T.E =		1,330.927320
7102.3	7102.3				
398.1		15.000000 x	.225000 =		3.375000
567		.361250 x	383.300100 =		138.467161
T 630		.105000 x	1.791933 =		.188153
T 630.1		.105000 x	1.968209 =		.206662
574		.361250 x	3,528.328382 =		1,274.608628
			AΘΡΟΙΣΜΑ =		1,416.845604
			T.E =		1,459.350972
7102.4	7102.4				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
574		.403750 x	3,528.328382 =		1,424.562584
567		.403750 x	383.300100 =		154.757415
			AΘΡΟΙΣΜΑ =		1,583.089815
			T.E =		1,630.582509
7102.5	7102.5				
398.1		15.000000 x	.225000 =		3.375000
T 630.1		.105000 x	1.968209 =		.206662
T 630		.105000 x	1.791933 =		.188153
567		.446250 x	383.300100 =		171.047670
574		.446250 x	3,528.328382 =		1,574.516540
			AΘΡΟΙΣΜΑ =		1,749.334025
			T.E =		1,801.814046

7103	7103				
113		3.400000 x	20.419486 =	69.426252	
113		.283333 x	20.419486 =	5.785514	
115		.070833 x	21.949547 =	1.554752	
575		.106250 x	925.232414 =	98.305944	

			T.E =	175.072463	
7104	7104				
113		1.700000 x	20.419486 =	34.713126	
576		.106250 x	7.425000 =	.788906	
567		.106250 x	383.300100 =	40.725636	

			T.E =	76.227668	
7105	7105				
111		.850000 x	15.741598 =	13.380358	
113		.850000 x	20.419486 =	17.356563	
576		.106250 x	7.425000 =	.788906	
567		.106250 x	383.300100 =	40.725636	

			T.E =	72.251463	
7106.1	7106.1				
577		.265625 x	668.661919 =	177.613322	

			AΘΡΟΙΣΜΑ =	177.613322	

			T.E =	186.493988	
7106.2	7106.2				
577		.297500 x	668.661919 =	198.926921	

			AΘΡΟΙΣΜΑ =	198.926921	

			T.E =	208.873267	
7106.3	7106.3				
577		.350625 x	668.661919 =	234.449585	

			AΘΡΟΙΣΜΑ =	234.449585	

			T.E =	246.172065	
7106.4	7106.4				
577		.425000 x	668.661919 =	284.181316	

			AΘΡΟΙΣΜΑ =	284.181316	

			T.E =	298.390381	

7106.5	7106.5			
577		.531250 x	668.661919 =	355.226644

			ΑΘΡΟΙΣΜΑ =	355.226644

			T.E =	372.987977
7107.1	7107.1			
398.7		.030000 x	1,360.000000 =	40.800000
7106.1		1.000000 x	186.493988 =	186.493988

			T.E =	227.293988
7107.2	7107.2			
398.7		.030000 x	1,360.000000 =	40.800000
7106.2		1.000000 x	208.873267 =	208.873267

			T.E =	249.673267
7107.3	7107.3			
398.7		.030000 x	1,360.000000 =	40.800000
7106.3		1.000000 x	246.172065 =	246.172065

			T.E =	286.972065
7107.4	7107.4			
398.7		.030000 x	1,360.000000 =	40.800000
7106.4		1.000000 x	298.390381 =	298.390381

			T.E =	339.190381
7107.5	7107.5			
398.7		.030000 x	1,360.000000 =	40.800000
7106.5		1.000000 x	372.987977 =	372.987977

			T.E =	413.787977
7108	7108			
398.11		1.000000 x	136.770000 =	136.770000
574		.053125 x	3,528.328382 =	187.442445

			T.E =	324.212445
7109	7109			
398.12		1.000000 x	176.880000 =	176.880000
574		.053125 x	3,528.328382 =	187.442445

			T.E =	364.322445

7110	7110				
398.10		1.170000 x	138.730000 =		162.314100
574		.053125 x	3,528.328382 =		187.442445

			T.E =		349.756545
7111	7111				
398.9		1.170000 x	128.000000 =		149.760000
574		.053125 x	3,528.328382 =		187.442445

			T.E =		337.202445
7112	7112				
398.13		1.300000 x	9.400000 =		12.220000
577		.010625 x	668.661919 =		7.104533

			T.E =		19.324533
7113	7113				
241		1.200000 x	7.050000 =		8.460000
574		.001063 x	3,528.328382 =		3.750613

			T.E =		12.210613
7114	7114				
398.8		.120000 x	30.750000 =		3.690000
577		.053125 x	668.661919 =		35.522664

			T.E =		39.212664
7115	7115				
574		.026563 x	3,528.328382 =		93.722987

			T.E =		93.722987
7116	7116				
577		.170000 x	668.661919 =		113.672526

			T.E =		113.672526
7117	7117				
574		.001063 x	3,528.328382 =		3.750613

			T.E =		3.750613

7118.1	7118.1			
111		27.200000 x	15.741598 =	428.171466
578		.850000 x	634.966266 =	539.721326
574.1		.425000 x	2,184.957688 =	928.607017

			T.E =	1,896.499809
7118.2	7118.2			
111		40.800000 x	15.741598 =	642.257198
574.1		.850000 x	2,184.957688 =	1,857.214035
578		.850000 x	634.966266 =	539.721326

			T.E =	3,039.192559
7119.1	7119.1			
111		13.600000 x	15.741598 =	214.085733
577.1		.255000 x	382.917688 =	97.644010

			T.E =	311.729743
7119.2	7119.2			
111		13.600000 x	15.741598 =	214.085733
577.1		.595000 x	382.917688 =	227.836024

			T.E =	441.921757
7120.1	7120.1			
111		10.200000 x	15.741598 =	160.564300
575.1		.425000 x	258.546376 =	109.882210
578		.425000 x	634.966266 =	269.860663

			T.E =	540.307172
7120.2	7120.2			
111		17.000000 x	15.741598 =	267.607166
578		1.275000 x	634.966266 =	809.581989
575.1		1.275000 x	258.546376 =	329.646629

			T.E =	1,406.835785
7121.1	7121.1			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	634.966266 =	269.860663

			T.E =	379.772279

7121.2	7121.2			
111		6.800000 x	15.741598 =	107.042866
576.1		.425000 x	6.750000 =	2.868750
578		.425000 x	634.966266 =	269.860663

			T.E =	379.772279
7122	7122			
398.1		15.000000 x	.225000 =	3.375000
T 630		.105000 x	1.791933 =	.188153
T 630.1		.105000 x	1.968209 =	.206662
567		.122188 x	383.300100 =	46.834673
580		.122188 x	1,682.464142 =	205.576929

			AΘΡΟΙΣΜΑ =	256.181416

			T.E =	263.866859
7123	7123			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.968209 =	.206662
T 630		.105000 x	1.791933 =	.188153
580		.286875 x	1,682.464142 =	482.656901
567		.286875 x	383.300100 =	109.959216

			AΘΡΟΙΣΜΑ =	596.385932

			T.E =	614.277510
7124	7124			
398.1		15.000000 x	.225000 =	3.375000
567		.063750 x	383.300100 =	24.435381
T 630		.105000 x	1.791933 =	.188153
T 630.1		.105000 x	1.968209 =	.206662
580		.063750 x	1,682.464142 =	107.257089

			T.E =	135.462285
7125	7125			
398.1		15.000000 x	.225000 =	3.375000
T 630.1		.105000 x	1.968209 =	.206662
567		.127500 x	383.300100 =	48.870763
T 630		.105000 x	1.791933 =	.188153
580		.127500 x	1,682.464142 =	214.514178

			T.E =	267.154756
7126	7126			
398.16		1.000000 x	62.420000 =	62.420000
580		.053125 x	1,682.464142 =	89.380908

			T.E =	151.800908

7127	7127				
398.15		1.170000 x	75.690000 =		88.557300
580		.015938 x	1,682.464142 =		26.815113
				T.E =	115.372413
7128	7128				
398.14		1.170000 x	58.610000 =		68.573700
580		.015938 x	1,682.464142 =		26.815113
				T.E =	95.388813
7129	7129				
6751		1.000000 x	5.291176 =		5.291176
				T.E =	5.291176