

ΑΤΕΟ (ΝΕΟ)

Αναλυτικά Τιμολόγια Έργων Οδοποιΐας

1ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
211	1.140600
212	1.362600
213	1.949500
214	4.160000
215	.835000
221	.099900
222	.116200
223	.119300
224	.070000
231	.825000
232	2.020000
233	.556800
234	.912400
235	.664600
236	.643700
237	1.165000
238	.556800
239	8.000000
241	7.750000
242	5.000000
243	2.250000
244	2.590000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	4.060000
302	6.700000
321	.447500
322	
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	748.500000
352	1,015.000000
353	3.720000
354	4.780000
355	.118300
401	260.720000

402	369.270000
403	100.390000
404	206.630000
405	200.790000
406	311.770000
407	53.630000
408	4.400000
409	122.460000
410	113.190000
411	26.580000
412	2.900000
413	4.400000
414	6.070000
415	8.530000
416	13.150000
417	130.670000
418	43.600000
419	4.400000
420	94.500000
421	31.630000
422	36.920000
423	12.180000
424	40.720000
425	160.590000
426	1,199.420000
427	180.510000
428	425.280000
429	75.360000
501.1M	281.740000
501.2M	358.050000
501.3M	281.740000
501.4M	181.960000
502.1M	325.640000
502.2M	421.350000
502.3M	652.530000
502.4M	872.520000
502.5M	1,510.130000
502.6M	664.960000
504.1M	277.220000
504.2M	400.680000
504.3M	220.140000
504.4M	269.060000
505.1M	598.870000
505.2M	843.860000
506.10M	383.030000
506.1M	123.390000
506.2M	130.900000
506.3M	174.350000
506.4M	199.400000
506.5M	171.670000
506.6M	203.850000
506.7M	305.780000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	21.970000
508.4M	30.520000
509.1M	92.080000

509.2M	92.080000
509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	302.090000
515.5M	332.300000
515.6M	443.070000
515.7M	634.400000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	259.330000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	75.040000
521.2M	75.040000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000

528.1M	312.250000
528.2M	349.720000
528.3M	349.720000
528.4M	374.700000
529.1M	112.410000

501	501				
501.1		.100000 x	568.132532 =	56.813253	
501.2		.600000 x	717.493686 =	430.496212	
501.4		.150000 x	511.405818 =	76.710873	
501.3		.150000 x	568.132532 =	85.219880	
			H.Δ. =	649.240217	
501.1	501.1				
211		146.190706 x	1.140600 =	166.745119	
211		14.619071 x	1.140600 =	16.674512	
501.1M		.800000 x	281.740000 =	225.392000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	568.132532	
501.2	501.2				
211		216.578823 x	1.140600 =	247.029806	
211		21.657882 x	1.140600 =	24.702980	
114		6.670000 x	23.886192 =	159.320901	
501.2M		.800000 x	358.050000 =	286.440000	
			H.Δ. =	717.493686	
501.3	501.3				
211		14.619071 x	1.140600 =	16.674512	
114		6.670000 x	23.886192 =	159.320901	
501.3M		.800000 x	281.740000 =	225.392000	
211		146.190706 x	1.140600 =	166.745119	
			H.Δ. =	568.132532	
501.4	501.4				
211		164.599905 x	1.140600 =	187.742652	
211		16.459991 x	1.140600 =	18.774266	
501.4M		.800000 x	181.960000 =	145.568000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	511.405818	
502	502				
502.1		.200000 x	745.534324 =	149.106865	
502.3		.400000 x	1,221.035894 =	488.414358	
502.2		.400000 x	881.543870 =	352.617548	
			H.Δ. =	990.138770	

502.1	502.1			
211		24.365118 x	1.140600 =	27.790854
118		2.000000 x	10.001019 =	20.002038
211		243.651176 x	1.140600 =	277.908531
114		6.670000 x	23.886192 =	159.320901
502.1M		.800000 x	325.640000 =	260.512000
		-----		
			H.Δ. =	745.534324
502.2	502.2			
211		291.027794 x	1.140600 =	331.946302
211		29.102779 x	1.140600 =	33.194630
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.2M		.800000 x	421.350000 =	337.080000
		-----		
			H.Δ. =	881.543870
502.3	502.3			
211		414.207001 x	1.140600 =	472.444505
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.3M		.800000 x	652.530000 =	522.024000
211		41.420700 x	1.140600 =	47.244450
		-----		
			H.Δ. =	1,221.035894
503	503			
502.3		.150000 x	1,221.035894 =	183.155384
503.4		.400000 x	1,505.721006 =	602.288402
503.6		.100000 x	1,271.739814 =	127.173981
503.5		.350000 x	2,270.558500 =	794.695475
		-----		
			H.Δ. =	1,707.313243
503.4	503.4			
211		50.083853 x	1.140600 =	57.125643
211		500.838528 x	1.140600 =	571.256425
502.4M		.800000 x	872.520000 =	698.016000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	1,505.721006
503.5	503.5			
211		703.881180 x	1.140600 =	802.846874
118		2.000000 x	10.001019 =	20.002038
211		70.388118 x	1.140600 =	80.284687
114		6.670000 x	23.886192 =	159.320901
502.5M		.800000 x	1,510.130000 =	1,208.104000
		-----		
			H.Δ. =	2,270.558500

503.6	503.6			
211		44.669383 x	1.140600 =	50.949898
211		446.693825 x	1.140600 =	509.498977
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.6M		.800000 x	664.960000 =	531.968000
		-----		
			H.Δ. =	1,271.739814
504	504			
504.1		.350000 x	700.382926 =	245.134024
504.4		.100000 x	672.116302 =	67.211630
504.2		.450000 x	880.670762 =	396.301843
504.3		.100000 x	654.718926 =	65.471893
		-----		
			H.Δ. =	774.119390
504.1	504.1			
211		254.480118 x	1.140600 =	290.260023
114		6.670000 x	23.886192 =	159.320901
504.1M		.800000 x	277.220000 =	221.776000
211		25.448012 x	1.140600 =	29.026002
		-----		
			H.Δ. =	700.382926
504.2	504.2			
211		319.453766 x	1.140600 =	364.368965
211		31.945376 x	1.140600 =	36.436896
504.2M		.800000 x	400.680000 =	320.544000
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	880.670762
504.3	504.3			
211		25.448012 x	1.140600 =	29.026002
211		254.480118 x	1.140600 =	290.260023
114		6.670000 x	23.886192 =	159.320901
504.3M		.800000 x	220.140000 =	176.112000
		-----		
			H.Δ. =	654.718926
504.4	504.4			
211		237.153812 x	1.140600 =	270.497638
211		23.715381 x	1.140600 =	27.049764
114		6.670000 x	23.886192 =	159.320901
504.4M		.800000 x	269.060000 =	215.248000
		-----		
			H.Δ. =	672.116302



505	505				
505.1		.500000 x	1,126.780077 =	563.390039	
505.2		.500000 x	1,322.772077 =	661.386039	
			H.Δ. =	1,224.776077	
505.1	505.1				
211		35.735506 x	1.140600 =	40.759918	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.886192 =	159.320901	
505.1M		.800000 x	598.870000 =	479.096000	
211		357.355061 x	1.140600 =	407.599183	
			H.Δ. =	1,126.780077	
505.2	505.2				
211		35.735506 x	1.140600 =	40.759918	
211		357.355061 x	1.140600 =	407.599183	
505.2M		.800000 x	843.860000 =	675.088000	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	1,322.772077	
506	506				
506.1		.100000 x	411.976558 =	41.197656	
506.4		.350000 x	518.413021 =	181.444557	
506.2		.200000 x	451.837933 =	90.367587	
506.3		.350000 x	465.991531 =	163.097036	
			H.Δ. =	476.106836	
506.1	506.1				
211		10.675531 x	1.140600 =	12.176511	
118		2.000000 x	10.001019 =	20.002038	
506.1M		.800000 x	123.390000 =	98.712000	
114		6.670000 x	23.886192 =	159.320901	
211		106.755312 x	1.140600 =	121.765109	
			H.Δ. =	411.976558	
506.2	506.2				
211		13.373742 x	1.140600 =	15.254090	
506.2M		.800000 x	130.900000 =	104.720000	
114		6.670000 x	23.886192 =	159.320901	
118		2.000000 x	10.001019 =	20.002038	
211		133.737423 x	1.140600 =	152.540905	
			H.Δ. =	451.837933	

506.3	506.3			
211		117.313529 x	1.140600 =	133.807811
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.3M		.800000 x	174.350000 =	139.480000
211		11.731353 x	1.140600 =	13.380781
-----				
			H.Δ. =	465.991531
506.4	506.4			
211		14.312251 x	1.140600 =	16.324553
211		143.122505 x	1.140600 =	163.245529
506.4M		.800000 x	199.400000 =	159.520000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	518.413021
507	507			
507.5		.100000 x	552.160687 =	55.216069
507.8		.100000 x	617.512344 =	61.751234
507.10		.250000 x	905.234428 =	226.308607
507.9		.350000 x	717.515667 =	251.130483
507.6		.100000 x	673.577272 =	67.357727
507.7		.100000 x	769.840131 =	76.984013
-----				
			H.Δ. =	738.748134
507.10	507.10			
211		334.343559 x	1.140600 =	381.352263
118		2.000000 x	10.001019 =	20.002038
211		33.434356 x	1.140600 =	38.135226
114		6.670000 x	23.886192 =	159.320901
506.10M		.800000 x	383.030000 =	306.424000
-----				
			H.Δ. =	905.234428
507.5	507.5			
211		187.701647 x	1.140600 =	214.092499
506.5M		.800000 x	171.670000 =	137.336000
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
211		18.770165 x	1.140600 =	21.409250
-----				
			H.Δ. =	552.160687

507.6	507.6			
211		263.955441 x	1.140600 =	301.067576
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.6M		.800000 x	203.850000 =	163.080000
211		26.395544 x	1.140600 =	30.106757
-----				
			H.Δ. =	673.577272
507.7	507.7			
211		27.568679 x	1.140600 =	31.444835
211		275.686794 x	1.140600 =	314.448357
506.7M		.800000 x	305.780000 =	244.624000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
-----				
			H.Δ. =	769.840131
507.8	507.8			
211		191.221052 x	1.140600 =	218.106732
118		2.000000 x	10.001019 =	20.002038
211		19.122105 x	1.140600 =	21.810673
114		6.670000 x	23.886192 =	159.320901
506.8M		.800000 x	247.840000 =	198.272000
-----				
			H.Δ. =	617.512344
507.9	507.9			
211		23.931960 x	1.140600 =	27.296794
211		239.319599 x	1.140600 =	272.967935
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.9M		.800000 x	297.410000 =	237.928000
-----				
			H.Δ. =	717.515667
508	508			
508.1		.250000 x	365.926060 =	91.481515
508.4		.250000 x	450.760242 =	112.690061
508.2		.250000 x	413.010638 =	103.252660
508.3		.250000 x	413.010638 =	103.252660
-----				
			H.Δ. =	410.676895
508.1	508.1			
211		28.155247 x	1.140600 =	32.113875
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
508.1M		.800000 x	18.310000 =	14.648000
211		2.815525 x	1.140600 =	3.211388
-----				
			H.Δ. =	365.926060

508.2	508.2				
211		6.334931 x	1.140600 =	7.225622	
211		63.349306 x	1.140600 =	72.256218	
508.2M		.800000 x	21.970000 =	17.576000	
116		13.340000 x	20.419486 =	272.395943	
115		2.000000 x	21.778427 =	43.556854	
-----					
			H.Δ. =	413.010638	
508.3	508.3				
211		6.334931 x	1.140600 =	7.225622	
116		13.340000 x	20.419486 =	272.395943	
211		63.349306 x	1.140600 =	72.256218	
115		2.000000 x	21.778427 =	43.556854	
508.3M		.800000 x	21.970000 =	17.576000	
-----					
			H.Δ. =	413.010638	
508.4	508.4				
211		87.985147 x	1.140600 =	100.355859	
211		8.798515 x	1.140600 =	10.035586	
115		2.000000 x	21.778427 =	43.556854	
116		13.340000 x	20.419486 =	272.395943	
508.4M		.800000 x	30.520000 =	24.416000	
-----					
			H.Δ. =	450.760242	
509	509				
509.1		.100000 x	542.221988 =	54.222199	
509.4		.500000 x	579.055929 =	289.527965	
509.2		.200000 x	491.272091 =	98.254418	
509.3		.200000 x	601.586877 =	120.317375	
-----					
			H.Δ. =	562.321957	
509.1	509.1				
211		284.259705 x	1.140600 =	324.226620	
117		6.670000 x	16.777917 =	111.908706	
509.1M		.800000 x	92.080000 =	73.664000	
211		28.425971 x	1.140600 =	32.422663	
-----					
			H.Δ. =	542.221988	
509.2	509.2				
211		243.651176 x	1.140600 =	277.908531	
211		24.365118 x	1.140600 =	27.790854	
509.2M		.800000 x	92.080000 =	73.664000	
117		6.670000 x	16.777917 =	111.908706	
-----					
			H.Δ. =	491.272091	

509.3	509.3			
211		32.892909 x	1.140600 =	37.517652
211		328.929089 x	1.140600 =	375.176519
117		6.670000 x	16.777917 =	111.908706
509.3M		.800000 x	96.230000 =	76.984000
		-----		
			H.Δ. =	601.586877
509.4	509.4			
211		308.624825 x	1.140600 =	352.017475
211		30.862482 x	1.140600 =	35.201747
117		6.670000 x	16.777917 =	111.908706
509.4M		.800000 x	99.910000 =	79.928000
		-----		
			H.Δ. =	579.055929
511	511			
511.1		.150000 x	391.376892 =	58.706534
511.4		.225000 x	394.726525 =	88.813468
511.5		.125000 x	396.318525 =	49.539816
511.6		.125000 x	394.952892 =	49.369112
511.3		.225000 x	394.352892 =	88.729401
511.2		.150000 x	389.882361 =	58.482354
		-----		
			H.Δ. =	393.640684
511.1	511.1			
211		.496326 x	1.140600 =	.566109
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.1M		.800000 x	11.180000 =	8.944000
211		4.963265 x	1.140600 =	5.661100
		-----		
			H.Δ. =	391.376892
511.2	511.2			
211		.377208 x	1.140600 =	.430243
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.2M		.800000 x	11.180000 =	8.944000
211		3.772081 x	1.140600 =	4.302436
		-----		
			H.Δ. =	389.882361
511.3	511.3			
211		4.963265 x	1.140600 =	5.661100
211		.496326 x	1.140600 =	.566109
511.3M		.800000 x	14.900000 =	11.920000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
		-----		
			H.Δ. =	394.352892

511.4	511.4			
211		5.261061 x	1.140600 =	6.000766
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.4M		.800000 x	14.900000 =	11.920000
211		.526106 x	1.140600 =	.600077
		-----		
			H.Δ. =	394.726525
511.5	511.5			
211		5.261061 x	1.140600 =	6.000766
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.5M		.800000 x	16.890000 =	13.512000
211		.526106 x	1.140600 =	.600077
		-----		
			H.Δ. =	396.318525
511.6	511.6			
211		4.963265 x	1.140600 =	5.661100
112		13.340000 x	17.312112 =	230.943574
511.6M		.800000 x	15.650000 =	12.520000
115		6.670000 x	21.778427 =	145.262108
211		.496326 x	1.140600 =	.566109
		-----		
			H.Δ. =	394.952892
512	512			
512.1		.200000 x	105.758527 =	21.151705
512.4		.200000 x	155.415415 =	31.083083
512.5		.200000 x	157.679855 =	31.535971
512.2		.200000 x	109.515187 =	21.903037
512.3		.200000 x	112.911846 =	22.582369
		-----		
			H.Δ. =	128.256166
512.1	512.1			
211		1.804824 x	1.140600 =	2.058582
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
512.1M		.800000 x	1.530000 =	1.224000
211		.180482 x	1.140600 =	.205858
		-----		
			H.Δ. =	105.758527

512.2	512.2			
211		4.512059 x	1.140600 =	5.146454
211		.451206 x	1.140600 =	.514646
512.2M		.800000 x	1.980000 =	1.584000
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
-----				
			H.Δ. =	109.515187
512.3	512.3			
211		.721929 x	1.140600 =	.823432
117		3.000000 x	16.777917 =	50.333751
211		7.219294 x	1.140600 =	8.234327
112		3.000000 x	17.312112 =	51.936336
512.3M		.800000 x	1.980000 =	1.584000
-----				
			H.Δ. =	112.911846
512.4	512.4			
211		1.353618 x	1.140600 =	1.543937
211		13.536176 x	1.140600 =	15.439362
112		4.000000 x	17.312112 =	69.248448
117		4.000000 x	16.777917 =	67.111668
512.4M		.800000 x	2.590000 =	2.072000
-----				
			H.Δ. =	155.415415
512.5	512.5			
211		15.341000 x	1.140600 =	17.497945
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
512.5M		.800000 x	2.590000 =	2.072000
211		1.534100 x	1.140600 =	1.749794
-----				
			H.Δ. =	157.679855
512A	512A			
512.1		.333333 x	105.758527 =	35.252807
512.2		.333333 x	109.515187 =	36.505026
512.3		.333333 x	112.911846 =	37.637244
-----				
			H.Δ. =	109.395077
512B	512B			
512.4		.500000 x	155.415415 =	77.707708
512.5		.500000 x	157.679855 =	78.839928
-----				
			H.Δ. =	156.547635

513	513				
513.6		.250000 x	207.952743 =	51.988186	
513.9		.250000 x	273.906213 =	68.476553	
513.8		.250000 x	261.100671 =	65.275168	
513.7		.250000 x	219.274942 =	54.818736	
		-----			
			H.Δ. =	240.558642	
513.6	513.6				
211		2.707235 x	1.140600 =	3.087872	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
211		27.072353 x	1.140600 =	30.878726	
512.6M		.800000 x	4.420000 =	3.536000	
		-----			
			H.Δ. =	207.952743	
513.7	513.7				
211		3.609647 x	1.140600 =	4.117163	
512.7M		.800000 x	4.420000 =	3.536000	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
211		36.096470 x	1.140600 =	41.171634	
		-----			
			H.Δ. =	219.274942	
513.8	513.8				
211		1.714582 x	1.140600 =	1.955652	
211		17.145823 x	1.140600 =	19.556526	
512.8M		.800000 x	15.260000 =	12.208000	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
		-----			
			H.Δ. =	261.100671	
513.9	513.9				
211		23.462706 x	1.140600 =	26.761562	
211		2.346271 x	1.140600 =	2.676157	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
512.9M		.800000 x	21.360000 =	17.088000	
		-----			
			H.Δ. =	273.906213	
513A	513A				
513.6		.500000 x	207.952743 =	103.976372	
513.7		.500000 x	219.274942 =	109.637471	
		-----			
			H.Δ. =	213.613843	



513B	513B				
513.9		1.000000 x	273.906213 =	273.906213	
			H.Δ. =	273.906213	
514	514				
514.1		.150000 x	587.084097 =	88.062615	
514.3		.150000 x	665.019397 =	99.752910	
514.4		.250000 x	729.953295 =	182.488324	
514.5		.300000 x	861.829790 =	258.548937	
514.2		.150000 x	602.266078 =	90.339912	
			H.Δ. =	719.192697	
514.1	514.1				
211		5.865676 x	1.140600 =	6.690390	
114		13.340000 x	23.886192 =	318.641801	
514.1M		.800000 x	243.560000 =	194.848000	
211		58.656765 x	1.140600 =	66.903906	
			H.Δ. =	587.084097	
514.2	514.2				
211		66.778471 x	1.140600 =	76.167524	
211		6.677847 x	1.140600 =	7.616752	
514.2M		.800000 x	249.800000 =	199.840000	
114		13.340000 x	23.886192 =	318.641801	
			H.Δ. =	602.266078	
514.3	514.3				
211		7.219294 x	1.140600 =	8.234327	
211		72.192941 x	1.140600 =	82.343269	
114		13.340000 x	23.886192 =	318.641801	
514.3M		.800000 x	319.750000 =	255.800000	
			H.Δ. =	665.019397	
514.4	514.4				
211		112.801471 x	1.140600 =	128.661358	
211		11.280147 x	1.140600 =	12.866136	
114		13.340000 x	23.886192 =	318.641801	
514.4M		.800000 x	337.230000 =	269.784000	
			H.Δ. =	729.953295	

514.5	514.5			
211		18.048235 x	1.140600 =	20.585817
114		13.340000 x	23.886192 =	318.641801
514.5M		.800000 x	395.930000 =	316.744000
211		180.482353 x	1.140600 =	205.858172
		-----		
			H.Δ. =	861.829790
515	515			
515.1		.200000 x	373.551807 =	74.710361
515.2		.200000 x	456.307294 =	91.261459
515.4		.200000 x	604.792491 =	120.958498
515.5		.200000 x	669.720407 =	133.944081
515.3		.200000 x	603.886716 =	120.777343
		-----		
			H.Δ. =	541.651743
515.1	515.1			
211		8.085609 x	1.140600 =	9.222446
515.1M		.800000 x	140.980000 =	112.784000
211		80.856094 x	1.140600 =	92.224461
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	373.551807
515.2	515.2			
211		10.828941 x	1.140600 =	12.351490
211		108.289412 x	1.140600 =	123.514903
114		6.670000 x	23.886192 =	159.320901
515.2M		.800000 x	201.400000 =	161.120000
		-----		
			H.Δ. =	456.307294
515.3	515.3			
211		16.171219 x	1.140600 =	18.444892
515.3M		.800000 x	302.090000 =	241.672000
114		6.670000 x	23.886192 =	159.320901
211		161.712189 x	1.140600 =	184.448923
		-----		
			H.Δ. =	603.886716
515.4	515.4			
211		16.243412 x	1.140600 =	18.527236
114		6.670000 x	23.886192 =	159.320901
515.4M		.800000 x	302.090000 =	241.672000
211		162.434118 x	1.140600 =	185.272355
		-----		
			H.Δ. =	604.792491

515.5	515.5			
211		194.920940 x	1.140600 =	222.326824
515.5M		.800000 x	332.300000 =	265.840000
114		6.670000 x	23.886192 =	159.320901
211		19.492094 x	1.140600 =	22.232682
		-----		
			H.Δ. =	669.720407
516	516			
515.5		.150000 x	669.720407 =	100.458061
516.6		.150000 x	776.451929 =	116.467789
516.8		.350000 x	923.630454 =	323.270659
516.7		.350000 x	1,006.506885 =	352.277410
		-----		
			H.Δ. =	892.473919
516.6	516.6			
211		209.359530 x	1.140600 =	238.795480
114		6.670000 x	23.886192 =	159.320901
515.6M		.800000 x	443.070000 =	354.456000
211		20.935953 x	1.140600 =	23.879548
		-----		
			H.Δ. =	776.451929
516.7	516.7			
211		27.072353 x	1.140600 =	30.878726
114		6.670000 x	23.886192 =	159.320901
515.7M		.800000 x	634.400000 =	507.520000
211		270.723530 x	1.140600 =	308.787258
		-----		
			H.Δ. =	1,006.506885
516.8	516.8			
211		265.670025 x	1.140600 =	303.023231
114		6.670000 x	23.886192 =	159.320901
211		26.567002 x	1.140600 =	30.302322
515.8M		.800000 x	538.730000 =	430.984000
		-----		
			H.Δ. =	923.630454
517	517			
517.1		.100000 x	1,239.577667 =	123.957767
517.2		.250000 x	2,190.116256 =	547.529064
517.3		.250000 x	2,505.475046 =	626.368762
517.4		.100000 x	1,138.973173 =	113.897317
517.6		.200000 x	1,398.132664 =	279.626533
517.5		.100000 x	1,211.272169 =	121.127217
		-----		
			H.Δ. =	1,812.506659

517.1	517.1			
211		15.792206 x	1.140600 =	18.012590
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
211		157.922058 x	1.140600 =	180.125899
517.1M		.800000 x	509.760000 =	407.808000
		-----		
			H.Δ. =	1,239.577667
517.2	517.2			
211		365.476765 x	1.140600 =	416.862798
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
211		36.547677 x	1.140600 =	41.686280
517.2M		.800000 x	1,372.420000 =	1,097.936000
		-----		
			H.Δ. =	2,190.116256
517.3	517.3			
211		49.181441 x	1.140600 =	56.096352
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.3M		.800000 x	1,568.480000 =	1,254.784000
211		491.814411 x	1.140600 =	560.963517
		-----		
			H.Δ. =	2,505.475046
517.4	517.4			
211		9.024118 x	1.140600 =	10.292909
211		90.241177 x	1.140600 =	102.929086
517.4M		.800000 x	490.150000 =	392.120000
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
		-----		
			H.Δ. =	1,138.973173
517.5	517.5			
211		135.361765 x	1.140600 =	154.393629
114		13.340000 x	23.886192 =	318.641801
211		13.536176 x	1.140600 =	15.439362
111		20.010000 x	15.741598 =	314.989376
517.5M		.800000 x	509.760000 =	407.808000
		-----		
			H.Δ. =	1,211.272169

517.6	517.6			
211		20.304265 x	1.140600 =	23.159045
211		203.042646 x	1.140600 =	231.590442
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
517.6M		.800000 x	637.190000 =	509.752000
		-----		
			H.Δ. =	1,398.132664
518	518			
518.1		.250000 x	1,917.042106 =	479.260527
518.4		.250000 x	2,747.550421 =	686.887605
518.2		.250000 x	2,684.146106 =	671.036527
518.3		.250000 x	2,715.848264 =	678.962066
		-----		
			H.Δ. =	2,516.146724
518.1	518.1			
211		265.309059 x	1.140600 =	302.611513
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.1M		.800000 x	958.880000 =	767.104000
211		26.530906 x	1.140600 =	30.261151
		-----		
			H.Δ. =	1,917.042106
518.2	518.2			
211		26.530906 x	1.140600 =	30.261151
211		265.309059 x	1.140600 =	302.611513
518.2M		.800000 x	1,917.760000 =	1,534.208000
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
		-----		
			H.Δ. =	2,684.146106
518.3	518.3			
211		290.576588 x	1.140600 =	331.431656
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
211		29.057659 x	1.140600 =	33.143166
114		20.010000 x	23.886192 =	477.962702
518.3M		.800000 x	1,917.760000 =	1,534.208000
		-----		
			H.Δ. =	2,715.848264

518.4	518.4			
211		31.584412 x	1.140600 =	36.025180
211		315.844116 x	1.140600 =	360.251799
114		20.010000 x	23.886192 =	477.962702
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
518.4M		.800000 x	1,917.760000 =	1,534.208000
-----				
			H.Δ. =	2,747.550421
519	519			
519.1		.050000 x	738.312144 =	36.915607
519.6		.300000 x	697.931883 =	209.379565
519.5		.100000 x	1,006.068709 =	100.606871
519.2		.050000 x	835.165265 =	41.758263
519.4		.200000 x	758.160689 =	151.632138
519.3		.300000 x	794.912117 =	238.473635
-----				
			H.Δ. =	778.766079
519.1	519.1			
211		171.277754 x	1.140600 =	195.359406
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
519.1M		.800000 x	259.330000 =	207.464000
211		17.127775 x	1.140600 =	19.535940
-----				
			H.Δ. =	738.312144
519.2	519.2			
211		234.627058 x	1.140600 =	267.615622
211		23.462706 x	1.140600 =	26.761562
519.2M		.800000 x	324.160000 =	259.328000
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
-----				
			H.Δ. =	835.165265
519.3	519.3			
211		20.529868 x	1.140600 =	23.416367
116		6.670000 x	20.419486 =	136.197972
211		205.298676 x	1.140600 =	234.163670
115		6.670000 x	21.778427 =	145.262108
519.3M		.800000 x	319.840000 =	255.872000
-----				
			H.Δ. =	794.912117

519.4	519.4			
211		199.433001 x	1.140600 =	227.473281
211		19.943300 x	1.140600 =	22.747328
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.4M		.800000 x	283.100000 =	226.480000
		-----		
			H.Δ. =	758.160689
519.5	519.5			
211		32.261220 x	1.140600 =	36.797148
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.5M		.800000 x	399.800000 =	319.840000
211		322.612206 x	1.140600 =	367.971482
		-----		
			H.Δ. =	1,006.068709
519.6	519.6			
211		16.658521 x	1.140600 =	19.000709
211		166.585213 x	1.140600 =	190.007094
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.6M		.800000 x	259.330000 =	207.464000
		-----		
			H.Δ. =	697.931883
521	521			
521.1		.250000 x	323.101730 =	80.775433
521.4		.150000 x	373.978961 =	56.096844
521.5		.150000 x	384.482961 =	57.672444
521.2		.250000 x	329.895052 =	82.473763
521.3		.200000 x	315.315059 =	63.063012
		-----		
			H.Δ. =	340.081496
521.1	521.1			
211		7.471969 x	1.140600 =	8.522528
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.1M		.800000 x	75.040000 =	60.032000
211		74.719694 x	1.140600 =	85.225283
		-----		
			H.Δ. =	323.101730

521.2	521.2			
211		80.134165 x	1.140600 =	91.401029
114		6.670000 x	23.886192 =	159.320901
521.2M		.800000 x	75.040000 =	60.032000
118		1.000000 x	10.001019 =	10.001019
211		8.013417 x	1.140600 =	9.140103
		-----		
			H.Δ. =	329.895052
521.3	521.3			
211		76.885483 x	1.140600 =	87.695582
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.3M		.800000 x	61.910000 =	49.528000
211		7.688548 x	1.140600 =	8.769558
		-----		
			H.Δ. =	315.315059
521.4	521.4			
211		11.586967 x	1.140600 =	13.216095
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.4M		.800000 x	74.100000 =	59.280000
211		115.869671 x	1.140600 =	132.160947
		-----		
			H.Δ. =	373.978961
521.5	521.5			
211		115.869671 x	1.140600 =	132.160947
211		11.586967 x	1.140600 =	13.216095
521.5M		.800000 x	87.230000 =	69.784000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	384.482961
522	522			
522.6		.500000 x	472.783841 =	236.391921
522.7		.500000 x	467.349184 =	233.674592
		-----		
			H.Δ. =	470.066513
522.6	522.6			
211		17.109727 x	1.140600 =	19.515355
521.6M		.800000 x	98.490000 =	78.792000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
211		171.097271 x	1.140600 =	195.153547
		-----		
			H.Δ. =	472.783841



522.7	522.7			
211		16.676569 x	1.140600 =	19.021295
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
521.7M		.800000 x	98.490000 =	78.792000
211		166.765694 x	1.140600 =	190.212951
		-----		
			H.Δ. =	467.349184
523	523			
523.1		1.000000 x	359.790362 =	359.790362
		-----		
			H.Δ. =	359.790362
523.1	523.1			
211		54.144706 x	1.140600 =	61.757452
523.1M		.800000 x	93.690000 =	74.952000
117		6.670000 x	16.777917 =	111.908706
111		6.670000 x	15.741598 =	104.996459
211		5.414471 x	1.140600 =	6.175746
		-----		
			H.Δ. =	359.790362
525	525			
525.1		1.000000 x	251.298253 =	251.298253
		-----		
			H.Δ. =	251.298253
525.1	525.1			
211		4.512059 x	1.140600 =	5.146454
118		6.670000 x	10.001019 =	66.706797
111		6.670000 x	15.741598 =	104.996459
525.1M		.800000 x	28.730000 =	22.984000
211		45.120588 x	1.140600 =	51.464543
		-----		
			H.Δ. =	251.298253
526	526			
526.1		1.000000 x	572.515148 =	572.515148
		-----		
			H.Δ. =	572.515148
526.1	526.1			
211		243.651176 x	1.140600 =	277.908531
118		3.000000 x	10.001019 =	30.003057
117		6.670000 x	16.777917 =	111.908706
526.1M		.800000 x	156.130000 =	124.904000
211		24.365118 x	1.140600 =	27.790854
		-----		
			H.Δ. =	572.515148

527	527			
527.1		.400000 x	2,149.929839 =	859.971936
527.2		.600000 x	3,155.556235 =	1,893.333741

H.Δ. = 2,753.305677

527.1	527.1			
211		433.157646 x	1.140600 =	494.059611
114		16.680000 x	23.886192 =	398.421683
118		6.670000 x	10.001019 =	66.706797
211		43.315765 x	1.140600 =	49.405962
112		6.670000 x	17.312112 =	115.471787
527.1M		.800000 x	1,282.330000 =	1,025.864000

H.Δ. = 2,149.929839

527.2	527.2			
211		54.144706 x	1.140600 =	61.757452
118		6.670000 x	10.001019 =	66.706797
114		16.680000 x	23.886192 =	398.421683
112		6.670000 x	17.312112 =	115.471787
211		541.447060 x	1.140600 =	617.574517
527.2M		.800000 x	2,369.530000 =	1,895.624000

H.Δ. = 3,155.556235

528	528			
528.1		.250000 x	806.406627 =	201.601657
528.4		.250000 x	926.564263 =	231.641066
528.2		.250000 x	868.084785 =	217.021196
528.3		.250000 x	856.762586 =	214.190647

H.Δ. = 864.454565

528.1	528.1			
211		79.412235 x	1.140600 =	90.577595
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
528.1M		.800000 x	312.250000 =	249.800000
211		7.941224 x	1.140600 =	9.057760

H.Δ. = 806.406627

528.2	528.2			
211		10.467976 x	1.140600 =	11.939773
211		104.679765 x	1.140600 =	119.397740
528.2M		.800000 x	349.720000 =	279.776000
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574

-----  
 Η.Δ. = 868.084785

528.3	528.3			
211		9.565565 x	1.140600 =	10.910483
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
211		95.655647 x	1.140600 =	109.104831
112		13.340000 x	17.312112 =	230.943574
528.3M		.800000 x	349.720000 =	279.776000

-----  
 Η.Δ. = 856.762586

528.4	528.4			
211		135.361765 x	1.140600 =	154.393629
211		13.536176 x	1.140600 =	15.439362
112		13.340000 x	17.312112 =	230.943574
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
528.4M		.800000 x	374.700000 =	299.760000

-----  
 Η.Δ. = 926.564263

529	529			
529.1		1.000000 x	738.479665 =	738.479665

-----  
 Η.Δ. = 738.479665

529.1	529.1			
211		243.651176 x	1.140600 =	277.908531
117		6.670000 x	16.777917 =	111.908706
112		13.340000 x	17.312112 =	230.943574
529.1M		.800000 x	112.410000 =	89.928000
211		24.365118 x	1.140600 =	27.790854

-----  
 Η.Δ. = 738.479665

2730A	2730A			
234		48.000000 x	.912400 =	43.795200
251		.040000 x	290.000000 =	11.600000
509		.400000 x	562.321957 =	224.928783
511		.150000 x	393.640684 =	59.046103
513		.250000 x	240.558642 =	60.139661
517		1.000000 x	1,812.506659 =	1,812.506659
504		.400000 x	774.119390 =	309.647756
509		.200000 x	562.321957 =	112.464391
113		13.340000 x	20.419486 =	272.395943
111		6.670000 x	15.741598 =	104.996459
112		6.670000 x	17.312112 =	115.471787
235		24.000000 x	.664600 =	15.950400

-----  
 B.T = 3,142.943141

2730B	2730B			
234		1,000.000000 x	.912400 =	912.400000
506		2.500000 x	476.106836 =	1,190.267090
517		9.000000 x	1,812.506659 =	16,312.559931
515		7.000000 x	541.651743 =	3,791.562201
509		5.000000 x	562.321957 =	2,811.609785
509		2.209627 x	562.321957 =	1,242.521779
113		140.000000 x	20.419486 =	2,858.728040
112		360.000000 x	17.312112 =	6,232.360320
111		360.000000 x	15.741598 =	5,666.975280
252		2.000000 x	290.000000 =	580.000000
235		500.000000 x	.664600 =	332.300000
251		2.000000 x	290.000000 =	580.000000

-----  
 B.T = 42,511.284426

2730Γ	2730Γ			
222		350.000000 x	.116200 =	40.670000
630		.200000 x	.545730 =	.109146
623		.800000 x	14.773671 =	11.818937
625		.500000 x	16.294607 =	8.147304

-----  
 B.T = 60.745386

611	611			
111		1.400000 x	15.741598 =	22.038237

-----  
 B.T = 22.038237

612	612			
111		.250000 x	15.741598 =	3.935400
503		.000588 x	1,707.313243 =	1.003900
504		.000833 x	774.119390 =	.644841

-----  
 B.T = 5.584141

613	613			
111		.200000 x	15.741598 =	3.148320
518		.000500 x	2,516.146724 =	1.258073
504		.001000 x	774.119390 =	.774119
503		.000667 x	1,707.313243 =	1.138778
-----				
			B.T =	6.319290
614	614			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,516.146724 =	6.290367
504		.001000 x	774.119390 =	.774119
509		.001950 x	562.321957 =	1.096528
503		.000909 x	1,707.313243 =	1.551948
-----				
			B.T =	11.097931
615	615			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,516.146724 =	6.290367
504		.001000 x	774.119390 =	.774119
509		.001950 x	562.321957 =	1.096528
503		.000909 x	1,707.313243 =	1.551948
-----				
			B.T =	11.097931
616	616			
112		.080000 x	17.312112 =	1.384969
503		.000909 x	1,707.313243 =	1.551948
518		.002500 x	2,516.146724 =	6.290367
504		.001000 x	774.119390 =	.774119
509		.001950 x	562.321957 =	1.096528
-----				
			B.T =	11.097931
617	617			
111		.100000 x	15.741598 =	1.574160
503		.001000 x	1,707.313243 =	1.707313
518		.000625 x	2,516.146724 =	1.572592
504		.001000 x	774.119390 =	.774119
-----				
			B.T =	5.628184
621	621			
213		1.000000 x	1.949500 =	1.949500
519		.002500 x	778.766079 =	1.946915
111		.650000 x	15.741598 =	10.232039
116		.060000 x	20.419486 =	1.225169
-----				
			B.T =	15.353623

622	622			
213		1.000000 x	1.949500 =	1.949500
518		.001515 x	2,516.146724 =	3.811962
504		.001111 x	774.119390 =	.860047
519		.002500 x	778.766079 =	1.946915
509		.001950 x	562.321957 =	1.096528
503		.000909 x	1,707.313243 =	1.551948
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
-----				
			B.T =	14.990059
623	623			
213		1.000000 x	1.949500 =	1.949500
112		.100000 x	17.312112 =	1.731211
503		.000909 x	1,707.313243 =	1.551948
519		.002500 x	778.766079 =	1.946915
518		.001429 x	2,516.146724 =	3.595574
504		.001111 x	774.119390 =	.860047
509		.001950 x	562.321957 =	1.096528
116		.100000 x	20.419486 =	2.041949
-----				
			B.T =	14.773671
624	624			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
518		.001515 x	2,516.146724 =	3.811962
504		.001111 x	774.119390 =	.860047
519		.002500 x	778.766079 =	1.946915
509		.001950 x	562.321957 =	1.096528
503		.000909 x	1,707.313243 =	1.551948
112		.100000 x	17.312112 =	1.731211
-----				
			B.T =	14.990059
625	625			
213		1.000000 x	1.949500 =	1.949500
518		.002119 x	2,516.146724 =	5.331715
504		.000833 x	774.119390 =	.644841
519		.002500 x	778.766079 =	1.946915
509		.001950 x	562.321957 =	1.096528
503		.000909 x	1,707.313243 =	1.551948
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
-----				
			B.T =	16.294607
626	626			
509		.001786 x	562.321957 =	1.004307
504		.002000 x	774.119390 =	1.548239
-----				
			B.T =	2.552546

630	630			
512		.004255 x	128.256166 =	.545730
-----				
			B.T =	.545730
641	641			
231		.200000 x	.825000 =	.165000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
-----				
			B.T =	7.536243
642	642			
231		.300000 x	.825000 =	.247500
113		.250000 x	20.419486 =	5.104872
111		.250000 x	15.741598 =	3.935400
252		.005000 x	290.000000 =	1.450000
251		.003000 x	290.000000 =	.870000
-----				
			B.T =	11.607771
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
625		1.000000 x	16.294607 =	16.294607
511		.040000 x	393.640684 =	15.745627
509		.007516 x	562.321957 =	4.226412
509		.002166 x	562.321957 =	1.217989
630		.600000 x	.545730 =	.327438
224		120.000000 x	.070000 =	8.400000
-----				
			B.T =	93.465527
652	652			
221		650.000000 x	.099900 =	64.935000
111		1.500000 x	15.741598 =	23.612397
511		.040000 x	393.640684 =	15.745627
509		.002166 x	562.321957 =	1.217989
509		.007516 x	562.321957 =	4.226412
630		.320000 x	.545730 =	.174634
625		1.000000 x	16.294607 =	16.294607
112		.500000 x	17.312112 =	8.656056
-----				
			B.T =	134.862722

661	661			
353		.160000 x	3.720000 =	.595200
354		.220000 x	4.780000 =	1.051600
113		1.100000 x	20.419486 =	22.461435
355		.250000 x	.118300 =	.029575
-----				
			B.T =	24.137810
671	671			
215		.562500 x	.835000 =	.469688
525		.000067 x	251.298253 =	.016837
111		.002000 x	15.741598 =	.031483
321		.550000 x	.447500 =	.246125
-----				
			B.T =	.764133
671.1	671.1			
215		.562500 x	.835000 =	.469688
525		.000067 x	251.298253 =	.016837
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.518008
672	672			
215		.075000 x	.835000 =	.062625
321		.940000 x	.447500 =	.420650
525		.000067 x	251.298253 =	.016837
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.531595
672.1	672.1			
215		.075000 x	.835000 =	.062625
525		.000067 x	251.298253 =	.016837
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.110945
4311A	4311A			
321		80.000000 x	.447500 =	35.800000
616		.200000 x	11.097931 =	2.219586
615		.370000 x	11.097931 =	4.106234
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
626		.030000 x	2.552546 =	.076576
625		.500000 x	16.294607 =	8.147304
-----				
			B.T =	56.649682



4311A.1	4311A.1			
625		.500000 x	16.294607 =	8.147304
626		.030000 x	2.552546 =	.076576
504		.001786 x	774.119390 =	1.382577
527		.001786 x	2,753.305677 =	4.917404
616		.200000 x	11.097931 =	2.219586
615		.370000 x	11.097931 =	4.106234

-----  
B.T = 20.849682

4311B	4311B			
321		80.000000 x	.447500 =	35.800000
626		.030000 x	2.552546 =	.076576
625		.500000 x	16.294607 =	8.147304
623		.370000 x	14.773671 =	5.466258
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
624		.200000 x	14.990059 =	2.998012

-----  
B.T = 58.788131

4311B.1	4311B.1			
623		.370000 x	14.773671 =	5.466258
625		.500000 x	16.294607 =	8.147304
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
626		.030000 x	2.552546 =	.076576
624		.200000 x	14.990059 =	2.998012

-----  
B.T = 22.988131

4312	4312			
509		.001622 x	562.321957 =	.912086
504		.001000 x	774.119390 =	.774119

-----  
B.T = 1.686206

4411A	4411A			
321		80.000000 x	.447500 =	35.800000
616		.200000 x	11.097931 =	2.219586
615		.370000 x	11.097931 =	4.106234
626		.030000 x	2.552546 =	.076576
625		.500000 x	16.294607 =	8.147304
504		.001786 x	774.119390 =	1.382577
527		.001786 x	2,753.305677 =	4.917404

-----  
B.T = 56.649682

4411A.1	4411A.1			
625		.500000 x	16.294607 =	8.147304
626		.030000 x	2.552546 =	.076576
527		.001786 x	2,753.305677 =	4.917404
616		.200000 x	11.097931 =	2.219586
615		.370000 x	11.097931 =	4.106234
504		.001786 x	774.119390 =	1.382577
-----				
			B.T =	20.849682
4411B	4411B			
321		80.000000 x	.447500 =	35.800000
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
625		.500000 x	16.294607 =	8.147304
623		.370000 x	14.773671 =	5.466258
624		.200000 x	14.990059 =	2.998012
626		.030000 x	2.552546 =	.076576
-----				
			B.T =	58.788131
4411B.1	4411B.1			
623		.370000 x	14.773671 =	5.466258
624		.200000 x	14.990059 =	2.998012
626		.030000 x	2.552546 =	.076576
625		.500000 x	16.294607 =	8.147304
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
-----				
			B.T =	22.988131
4412	4412			
509		.001622 x	562.321957 =	.912086
504		.001000 x	774.119390 =	.774119
-----				
			B.T =	1.686206
4511A	4511A			
321		90.000000 x	.447500 =	40.275000
616		.300000 x	11.097931 =	3.329379
615		.370000 x	11.097931 =	4.106234
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
626		.050000 x	2.552546 =	.127627
625		.450000 x	16.294607 =	7.332573
-----				
			B.T =	61.470795

4511A.1	4511A.1			
625		.450000 x	16.294607 =	7.332573
616		.300000 x	11.097931 =	3.329379
615		.370000 x	11.097931 =	4.106234
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
626		.050000 x	2.552546 =	.127627
-----				
			B.T =	21.195795
4511B	4511B			
321		90.000000 x	.447500 =	40.275000
624		.300000 x	14.990059 =	4.497018
623		.370000 x	14.773671 =	5.466258
626		.050000 x	2.552546 =	.127627
527		.001786 x	2,753.305677 =	4.917404
504		.001786 x	774.119390 =	1.382577
625		.450000 x	16.294607 =	7.332573
-----				
			B.T =	63.998458
4511B.1	4511B.1			
623		.370000 x	14.773671 =	5.466258
624		.300000 x	14.990059 =	4.497018
626		.050000 x	2.552546 =	.127627
504		.001786 x	774.119390 =	1.382577
527		.001786 x	2,753.305677 =	4.917404
625		.450000 x	16.294607 =	7.332573
-----				
			B.T =	23.723458
4512	4512			
509		.001622 x	562.321957 =	.912086
504		.001000 x	774.119390 =	.774119
-----				
			B.T =	1.686206
1110	1110			
503		.000455 x	1,707.313243 =	.776828
501		.000250 x	649.240217 =	.162310
-----				
			T.E =	.939138
1121	1121			
112		.005000 x	17.312112 =	.086561
501		.000083 x	649.240217 =	.053887
503		.000714 x	1,707.313243 =	1.219022
-----				
			T.E =	1.359469

1122	1122			
112		.005000 x	17.312112 =	.086561
509		.002000 x	562.321957 =	1.124644
507		.000385 x	738.748134 =	.284418
501		.000080 x	649.240217 =	.051939
505		.000316 x	1,224.776077 =	.387029
503		.000100 x	1,707.313243 =	.170731
		-----		
			T.E =	2.105322
1123.A	1123.A			
112		.005000 x	17.312112 =	.086561
503		.000500 x	1,707.313243 =	.853657
509		.001429 x	562.321957 =	.803558
507		.000769 x	738.748134 =	.568097
501		.000080 x	649.240217 =	.051939
		-----		
			T.E =	2.363812
1123.B	1123.B			
509		.000870 x	562.321957 =	.489220
		-----		
			T.E =	.489220
1131	1131			
213		1.000000 x	1.949500 =	1.949500
519		.000952 x	778.766079 =	.741385
112		.030000 x	17.312112 =	.519363
503		.000909 x	1,707.313243 =	1.551948
		-----		
			T.E =	4.762196
1132	1132			
213		1.000000 x	1.949500 =	1.949500
504		.001000 x	774.119390 =	.774119
503		.000909 x	1,707.313243 =	1.551948
112		.120000 x	17.312112 =	2.077453
519		.000952 x	778.766079 =	.741385
509		.002000 x	562.321957 =	1.124644
		-----		
			T.E =	8.219050
1133.A	1133.A			
213		1.000000 x	1.949500 =	1.949500
112		.120000 x	17.312112 =	2.077453
504		.001000 x	774.119390 =	.774119
519		.000952 x	778.766079 =	.741385
509		.001176 x	562.321957 =	.661291
503		.000909 x	1,707.313243 =	1.551948
		-----		
			T.E =	7.755696

1133.B	1133.B			
509		.000870 x	562.321957 =	.489220
<hr/>				
			T.E =	.489220
1140	1140			
112		.006000 x	17.312112 =	.103873
522		.000133 x	470.066513 =	.062519
501		.000050 x	649.240217 =	.032462
<hr/>				
			T.E =	.198854
1211	1211			
112		.200000 x	17.312112 =	3.462422
501		.001538 x	649.240217 =	.998531
507		.001538 x	738.748134 =	1.136195
<hr/>				
			T.E =	5.597148
1212	1212			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	738.748134 =	1.136195
501		.001538 x	649.240217 =	.998531
509		.002298 x	562.321957 =	1.292216
<hr/>				
			T.E =	6.889364
1220	1220			
213		1.000000 x	1.949500 =	1.949500
116		.060000 x	20.419486 =	1.225169
519		.002222 x	778.766079 =	1.730418
111		.500000 x	15.741598 =	7.870799
112		.060000 x	17.312112 =	1.038727
<hr/>				
			T.E =	13.814613
1310	1310			
112		.070000 x	17.312112 =	1.211848
501		.000385 x	649.240217 =	.249957
<hr/>				
			T.E =	1.461805
1320	1320			
112		1.500000 x	17.312112 =	25.968168
<hr/>				
			T.E =	25.968168

1410	1410			
112		.005000 x	17.312112 =	.086561
501		.000083 x	649.240217 =	.053887
503		.000833 x	1,707.313243 =	1.422192
-----				
			T.E =	1.562639
1420	1420			
112		.006000 x	17.312112 =	.103873
509		.001826 x	562.321957 =	1.026800
503		.000208 x	1,707.313243 =	.355121
501		.000050 x	649.240217 =	.032462
507		.000385 x	738.748134 =	.284418
505		.000316 x	1,224.776077 =	.387029
-----				
			T.E =	2.189703
1510	1510			
112		.007000 x	17.312112 =	.121185
509		.001429 x	562.321957 =	.803558
504		.000714 x	774.119390 =	.552721
503		.000385 x	1,707.313243 =	.657316
-----				
			T.E =	2.134780
1520	1520			
509		.000833 x	562.321957 =	.468414
-----				
			T.E =	.468414
1530	1530			
630		.150000 x	.545730 =	.081860
502		.000208 x	990.138770 =	.205949
501		.000250 x	649.240217 =	.162310
509		.000413 x	562.321957 =	.232239
522		.000556 x	470.066513 =	.261357
-----				
			T.E =	.943714
1610	1610			
111		.040000 x	15.741598 =	.629664
503		.000111 x	1,707.313243 =	.189512
507		.000118 x	738.748134 =	.087172
1122		.200000 x	2.105322 =	.421064
501		.000050 x	649.240217 =	.032462
-----				
			T.E =	1.359874

1620	1620			
112		.200000 x	17.312112 =	3.462422
1122		1.000000 x	2.105322 =	2.105322
501		.000714 x	649.240217 =	.463558
-----				
			T.E =	6.031302
2111	2111			
112		.010000 x	17.312112 =	.173121
503		.001053 x	1,707.313243 =	1.797801
507		.000667 x	738.748134 =	.492745
501		.000500 x	649.240217 =	.324620
509		.002124 x	562.321957 =	1.194372
-----				
			T.E =	3.982659
2112	2112			
213		1.000000 x	1.949500 =	1.949500
112		.250000 x	17.312112 =	4.328028
507		.000667 x	738.748134 =	.492745
519		.002041 x	778.766079 =	1.589462
509		.002124 x	562.321957 =	1.194372
503		.001613 x	1,707.313243 =	2.753896
116		.060000 x	20.419486 =	1.225169
-----				
			T.E =	13.533172
2151	2151			
213		.300000 x	1.949500 =	.584850
112		.100000 x	17.312112 =	1.731211
112		.200000 x	17.312112 =	3.462422
113		.030000 x	20.419486 =	.612585
112		.100000 x	17.312112 =	1.731211
507		.003333 x	738.748134 =	2.462248
519		.001200 x	778.766079 =	.934519
509		.002124 x	562.321957 =	1.194372
-----				
			T.E =	12.713418
2152	2152			
112		.100000 x	17.312112 =	1.731211
507		.006667 x	738.748134 =	4.925234
509		.003196 x	562.321957 =	1.797181
112		.200000 x	17.312112 =	3.462422
-----				
			T.E =	11.916048

2211	2211			
244		1.000000 x	2.590000 =	2.590000
515		.000004 x	541.651743 =	.002167
515		.000004 x	541.651743 =	.002167
509		.000051 x	562.321957 =	.028678
112		.002000 x	17.312112 =	.034624
112		.003000 x	17.312112 =	.051936
-----				
			T.E =	2.709572
2212	2212			
244		.125000 x	2.590000 =	.323750
112		.007000 x	17.312112 =	.121185
515		.000008 x	541.651743 =	.004333
509		.000051 x	562.321957 =	.028678
-----				
			T.E =	.477946
2213	2213			
236		3.000000 x	.643700 =	1.931100
517		.016667 x	1,812.506659 =	30.209048
515		.016667 x	541.651743 =	9.027710
113		.300000 x	20.419486 =	6.125846
111		.300000 x	15.741598 =	4.722479
-----				
			T.E =	52.016183
2214	2214			
111		.200000 x	15.741598 =	3.148320
515		.016667 x	541.651743 =	9.027710
113		.110000 x	20.419486 =	2.246143
111		.170000 x	15.741598 =	2.676072
113		.200000 x	20.419486 =	4.083897
-----				
			T.E =	21.182142
2251	2251			
111		.450000 x	15.741598 =	7.083719
112		.450000 x	17.312112 =	7.790450
509		.007516 x	562.321957 =	4.226412
621		1.050000 x	15.353623 =	16.121304
-----				
			T.E =	35.221885
2252	2252			
111		1.250000 x	15.741598 =	19.676998
621		1.050000 x	15.353623 =	16.121304
509		.007516 x	562.321957 =	4.226412
113		1.250000 x	20.419486 =	25.524358
-----				
			T.E =	65.549071



2253	2253				
111		1.500000 x	15.741598 =	23.612397	
621		1.050000 x	15.353623 =	16.121304	
652		.020000 x	134.862722 =	2.697254	
509		.007891 x	562.321957 =	4.437283	
651		.250000 x	93.465527 =	23.366382	
113		2.500000 x	20.419486 =	51.048715	
112		.200000 x	17.312112 =	3.462422	
		-----			
			T.E =	124.745757	
2254	2254				
111		.750000 x	15.741598 =	11.806199	
652		.100000 x	134.862722 =	13.486272	
113		1.450000 x	20.419486 =	29.608255	
509		.002630 x	562.321957 =	1.478907	
621		.350000 x	15.353623 =	5.373768	
		-----			
			T.E =	61.753400	
2311	2311				
243		1.020000 x	2.250000 =	2.295000	
243		.080000 x	2.250000 =	.180000	
		-----			
			T.E =	2.475000	
2312	2312				
112		.080000 x	17.312112 =	1.384969	
113		.080000 x	20.419486 =	1.633559	
		-----			
			T.E =	3.018528	
2313	2313				
111		.400000 x	15.741598 =	6.296639	
509		.003326 x	562.321957 =	1.870283	
611		1.050000 x	22.038237 =	23.140149	
112		.400000 x	17.312112 =	6.924845	
		-----			
			T.E =	38.231916	
2350	2350				
112		.100000 x	17.312112 =	1.731211	
652		.022000 x	134.862722 =	2.966980	
113		.250000 x	20.419486 =	5.104872	
		-----			
			T.E =	9.803063	
2411	2411				
327		.500000 x	.540000 =	.270000	
113		.180000 x	20.419486 =	3.675507	
		-----			
			T.E =	3.945507	

2412	2412			
328		2.200000 x	1.840000 =	4.048000
111		.150000 x	15.741598 =	2.361240
329		2.000000 x	.730000 =	1.460000
2350		1.000000 x	9.803063 =	9.803063
113		.300000 x	20.419486 =	6.125846
			T.E =	23.798149
2511	2511			
221		200.000000 x	.099900 =	19.980000
623		.800000 x	14.773671 =	11.818937
625		.500000 x	16.294607 =	8.147304
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.016667 x	562.321957 =	9.372220
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.006012 x	562.321957 =	3.380680
630		.250000 x	.545730 =	.136433
112		.400000 x	17.312112 =	6.924845
113		.250000 x	20.419486 =	5.104872
			T.E =	70.730040
2512	2512			
221		250.000000 x	.099900 =	24.975000
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
630		.250000 x	.545730 =	.136433
641		2.000000 x	7.536243 =	15.072486
625		.500000 x	16.294607 =	8.147304
509		.018182 x	562.321957 =	10.224138
623		.800000 x	14.773671 =	11.818937
112		.500000 x	17.312112 =	8.656056
113		.500000 x	20.419486 =	10.209743
			T.E =	98.485526

2521	2521			
221		50.000000 x	.099900 =	4.995000
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
509		.006012 x	562.321957 =	3.380680
641		2.000000 x	7.536243 =	15.072486
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
221		250.000000 x	.099900 =	24.975000

T.E = 103.480526

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		.600000 x	17.312112 =	10.387267
623		.800000 x	14.773671 =	11.818937
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		3.000000 x	7.536243 =	22.608729
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
113		.800000 x	20.419486 =	16.335589

T.E = 118.873826

2523	2523			
221		300.000000 x	.099900 =	29.970000
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206
509		.018182 x	562.321957 =	10.224138
509		.001444 x	562.321957 =	.811993
509		.006012 x	562.321957 =	3.380680
112		.750000 x	17.312112 =	12.984084
641		3.000000 x	7.536243 =	22.608729
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		1.050000 x	20.419486 =	21.440460

T.E = 126.575514

2524	2524			
221		300.000000 x	.099900 =	29.970000
113		.800000 x	20.419486 =	16.335589
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		1.300000 x	7.536243 =	9.797116
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 116.449480

2531	2531			
222		300.000000 x	.116200 =	34.860000
509		.006012 x	562.321957 =	3.380680
509		.001444 x	562.321957 =	.811993
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206
509		.018182 x	562.321957 =	10.224138
641		1.300000 x	7.536243 =	9.797116
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		.900000 x	20.419486 =	18.377537
112		1.300000 x	17.312112 =	22.505746

-----  
 T.E = 125.112640

2532	2532			
222		300.000000 x	.116200 =	34.860000
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		4.000000 x	7.536243 =	30.144972
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
112		1.600000 x	17.312112 =	27.699379
113		.900000 x	20.419486 =	18.377537
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818

-----  
 T.E = 150.654130

2533	2533			
222		300.000000 x	.116200 =	34.860000
623		.800000 x	14.773671 =	11.818937
113		1.200000 x	20.419486 =	24.503383
630		.250000 x	.545730 =	.136433
509		.001444 x	562.321957 =	.811993
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.018182 x	562.321957 =	10.224138
641		8.000000 x	7.536243 =	60.289944
625		.500000 x	16.294607 =	8.147304
112		1.800000 x	17.312112 =	31.161802

-----  
 T.E = 190.387370

2541	2541			
222		300.000000 x	.116200 =	34.860000
509		.018182 x	562.321957 =	10.224138
509		.001444 x	562.321957 =	.811993
509		.006012 x	562.321957 =	3.380680
641		4.500000 x	7.536243 =	33.913094
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		1.200000 x	20.419486 =	24.503383
112		1.600000 x	17.312112 =	27.699379
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206

-----  
 T.E = 160.548097

2542	2542			
222		300.000000 x	.116200 =	34.860000
112		1.650000 x	17.312112 =	28.564985
623		.800000 x	14.773671 =	11.818937
509		.018182 x	562.321957 =	10.224138
509		.003758 x	562.321957 =	2.113206
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.001444 x	562.321957 =	.811993
630		.250000 x	.545730 =	.136433
642		4.500000 x	11.607771 =	52.234970
625		.500000 x	16.294607 =	8.147304
113		1.250000 x	20.419486 =	25.524358

-----  
 T.E = 180.756553

2543 2543

222	300.000000 x	.116200 =	34.860000
514	.002857 x	719.192697 =	2.054734
504	.001143 x	774.119390 =	.884818
509	.003758 x	562.321957 =	2.113206
509	.001444 x	562.321957 =	.811993
509	.018182 x	562.321957 =	10.224138
509	.006012 x	562.321957 =	3.380680
641	5.000000 x	7.536243 =	37.681215
630	.250000 x	.545730 =	.136433
625	.500000 x	16.294607 =	8.147304
623	.800000 x	14.773671 =	11.818937
112	1.550000 x	17.312112 =	26.833774
113	1.250000 x	20.419486 =	25.524358
113	.500000 x	20.419486 =	10.209743

T.E = 174.681330

2544 2544

222	300.000000 x	.116200 =	34.860000
514	.002857 x	719.192697 =	2.054734
504	.001143 x	774.119390 =	.884818
509	.003758 x	562.321957 =	2.113206
509	.018182 x	562.321957 =	10.224138
509	.001444 x	562.321957 =	.811993
509	.006012 x	562.321957 =	3.380680
113	.700000 x	20.419486 =	14.293640
112	1.650000 x	17.312112 =	28.564985
625	.500000 x	16.294607 =	8.147304
642	5.000000 x	11.607771 =	58.038855
630	.250000 x	.545730 =	.136433
623	.800000 x	14.773671 =	11.818937
113	1.250000 x	20.419486 =	25.524358

T.E = 200.854079

2545 2545

222	300.000000 x	.116200 =	34.860000
514	.002857 x	719.192697 =	2.054734
504	.001143 x	774.119390 =	.884818
509	.006012 x	562.321957 =	3.380680
509	.003758 x	562.321957 =	2.113206
509	.001444 x	562.321957 =	.811993
509	.018182 x	562.321957 =	10.224138
641	6.000000 x	7.536243 =	45.217458
630	.250000 x	.545730 =	.136433
625	.500000 x	16.294607 =	8.147304
623	.800000 x	14.773671 =	11.818937
113	1.900000 x	20.419486 =	38.797023
112	1.650000 x	17.312112 =	28.564985

T.E = 187.011707

2546	2546			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		6.000000 x	7.536243 =	45.217458
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
112		1.850000 x	17.312112 =	32.027407
113		1.900000 x	20.419486 =	38.797023

-----  
T.E = 190.474130

2547	2547			
222		300.000000 x	.116200 =	34.860000
113		1.900000 x	20.419486 =	38.797023
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206
509		.018182 x	562.321957 =	10.224138
509		.001444 x	562.321957 =	.811993
509		.006012 x	562.321957 =	3.380680
641		5.000000 x	7.536243 =	37.681215
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
112		1.550000 x	17.312112 =	26.833774

-----  
T.E = 177.744253

2548	2548			
222		300.000000 x	.116200 =	34.860000
112		1.950000 x	17.312112 =	33.758618
623		.800000 x	14.773671 =	11.818937
630		.250000 x	.545730 =	.136433
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		5.000000 x	7.536243 =	37.681215
625		.500000 x	16.294607 =	8.147304
113		2.400000 x	20.419486 =	49.006766

-----  
T.E = 194.878841

2551	2551			
222		360.000000 x	.116200 =	41.832000
514		.002857 x	719.192697 =	2.054734
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
112		1.550000 x	17.312112 =	26.833774
641		4.500000 x	7.536243 =	33.913094
630		.250000 x	.545730 =	.136433
509		.018182 x	562.321957 =	10.224138
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		1.050000 x	20.419486 =	21.440460

-----  
 T.E = 163.591568

2561	2561			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		4.500000 x	7.536243 =	33.913094
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		2.800000 x	20.419486 =	57.174561
112		1.800000 x	17.312112 =	31.161802
111		1.250000 x	15.741598 =	19.676998

-----  
 T.E = 234.397851

2562	2562			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
509		.003758 x	562.321957 =	2.113206
111		1.950000 x	15.741598 =	30.696116
112		1.800000 x	17.312112 =	31.161802
625		.500000 x	16.294607 =	8.147304
642		4.500000 x	11.607771 =	52.234970
630		.250000 x	.545730 =	.136433
623		.800000 x	14.773671 =	11.818937
113		2.800000 x	20.419486 =	57.174561

-----  
 T.E = 263.738845



2563	2563			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		5.000000 x	7.536243 =	37.681215
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
111		1.950000 x	15.741598 =	30.696116
113		3.900000 x	20.419486 =	79.635995
112		1.800000 x	17.312112 =	31.161802
113		.900000 x	20.419486 =	18.377537

T.E = 290.024063

2564	2564			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
642		5.000000 x	11.607771 =	58.038855
111		1.950000 x	15.741598 =	30.696116
113		3.900000 x	20.419486 =	79.635995
623		.800000 x	14.773671 =	11.818937
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802

T.E = 310.381703

2565	2565			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.006012 x	562.321957 =	3.380680
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
641		6.000000 x	7.536243 =	45.217458
630		.250000 x	.545730 =	.136433
625		.500000 x	16.294607 =	8.147304
623		.800000 x	14.773671 =	11.818937
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755

T.E = 311.336658

2566	2566			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	719.192697 =	2.663890
504		.001143 x	774.119390 =	.884818
509		.003758 x	562.321957 =	2.113206
509		.001444 x	562.321957 =	.811993
509		.018182 x	562.321957 =	10.224138
509		.006012 x	562.321957 =	3.380680
111		2.350000 x	15.741598 =	36.992755
112		2.350000 x	17.312112 =	40.683463
625		.500000 x	16.294607 =	8.147304
642		6.000000 x	11.607771 =	69.646626
630		.250000 x	.545730 =	.136433
623		.800000 x	14.773671 =	11.818937
113		4.700000 x	20.419486 =	95.971584
-----				
			T.E =	335.765826
2611	2611			
233		1.050000 x	.556800 =	.584640
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.299322
2612	2612			
238		1.050000 x	.556800 =	.584640
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.299322
2620	2620			
239		1.010000 x	8.000000 =	8.080000
113		.080000 x	20.419486 =	1.633559
113		.080000 x	20.419486 =	1.633559
239		.303000 x	8.000000 =	2.424000
-----				
			T.E =	13.771118
2651	2651			
235		1.050000 x	.664600 =	.697830
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	2.739779
2652	2652			
235		1.050000 x	.664600 =	.697830
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.355059

2653	2653			
241		1.050000 x	7.750000 =	8.137500
113		.800000 x	20.419486 =	16.335589
661		.120000 x	24.137810 =	2.896537
		-----		
			T.E =	27.369626
2671	2671			
237		1.000000 x	1.165000 =	1.165000
113		.015000 x	20.419486 =	.306292
		-----		
			T.E =	1.471292
2672	2672			
235		1.050000 x	.664600 =	.697830
661		.050000 x	24.137810 =	1.206891
113		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	4.355059
2711	2711			
2551		1.000000 x	163.591568 =	163.591568
		-----		
			T.E =	163.591568
2712	2712			
2611		1.000000 x	1.299322 =	1.299322
		-----		
			T.E =	1.299322
2713	2713			
237		1.000000 x	1.165000 =	1.165000
113		.070000 x	20.419486 =	1.429364
		-----		
			T.E =	2.594364
2714	2714			
112		1.900000 x	17.312112 =	32.893013
516		.015385 x	892.473919 =	13.730711
517		.015385 x	1,812.506659 =	27.885415
		-----		
			T.E =	74.509139
2731	2731			
2730Α		.149925 x	3,142.943141 =	471.205750
2730Β		.000667 x	42,511.284426 =	28.355027
2730Γ		1.000000 x	60.745386 =	60.745386
		-----		
			T.E =	560.306163

2732	2732			
2730Α		.179910 x	3,142.943141 =	565.446900
2730Γ		1.000000 x	60.745386 =	60.745386
2730Β		.000667 x	42,511.284426 =	28.355027
		-----		
			T.E =	654.547313
2733	2733			
233		1.050000 x	.556800 =	.584640
113		.035000 x	20.419486 =	.714682
		-----		
			T.E =	1.299322
2734	2734			
238		1.050000 x	.556800 =	.584640
113		.035000 x	20.419486 =	.714682
		-----		
			T.E =	1.299322
2811	2811			
112		.170000 x	17.312112 =	2.943059
507		.001538 x	738.748134 =	1.136195
501		.000500 x	649.240217 =	.324620
509		.002217 x	562.321957 =	1.246668
		-----		
			T.E =	5.650542
2815	2815			
111		.250000 x	15.741598 =	3.935400
112		.350000 x	17.312112 =	6.059239
509		.003006 x	562.321957 =	1.690340
509		.005261 x	562.321957 =	2.958376
623		.400000 x	14.773671 =	5.909468
625		.700000 x	16.294607 =	11.406225
		-----		
			T.E =	31.959048
2861	2861			
221		6.000000 x	.099900 =	.599400
281		1.000000 x	21.300000 =	21.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	29.918697
2862	2862			
221		8.000000 x	.099900 =	.799200
282		1.000000 x	30.000000 =	30.000000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	38.818497

2863	2863			
221		8.000000 x	.099900 =	.799200
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
283		1.000000 x	36.300000 =	36.300000
-----				
			T.E =	58.561956
2864	2864			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
284		1.000000 x	75.400000 =	75.400000
111		.700000 x	15.741598 =	11.019119
-----				
			T.E =	99.248236
2881	2881			
221		6.000000 x	.099900 =	.599400
111		.250000 x	15.741598 =	3.935400
113		.200000 x	20.419486 =	4.083897
261		1.000000 x	15.100000 =	15.100000
-----				
			T.E =	23.718697
2882	2882			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	35.118497
2883	2883			
221		10.000000 x	.099900 =	.999000
263		1.000000 x	32.400000 =	32.400000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
-----				
			T.E =	54.861756
2884	2884			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
264		1.000000 x	64.100000 =	64.100000
-----				
			T.E =	87.948236

2885	2885			
221		20.000000 x	.099900 =	1.998000
113		.750000 x	20.419486 =	15.314615
265		1.000000 x	115.100000 =	115.100000
111		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	148.154213
2888	2888			
221		26.000000 x	.099900 =	2.597400
111		1.400000 x	15.741598 =	22.038237
271		1.000000 x	206.300000 =	206.300000
113		1.100000 x	20.419486 =	22.461435
-----				
			T.E =	253.397072
2911	2911			
351		1.050000 x	748.500000 =	785.925000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	888.022430
2912	2912			
352		1.050000 x	1,015.000000 =	1,065.750000
113		5.000000 x	20.419486 =	102.097430
-----				
			T.E =	1,167.847430
2921	2921			
301		1.000000 x	4.060000 =	4.060000
113		.250000 x	20.419486 =	5.104872
652		.002000 x	134.862722 =	.269725
2522		.005000 x	118.873826 =	.594369
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	13.964366
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.015000 x	134.862722 =	2.022941
113		.600000 x	20.419486 =	12.251692
111		.350000 x	15.741598 =	5.509559
-----				
			T.E =	26.618192
2951	2951			
512A		.150000 x	109.395077 =	16.409262
-----				
			T.E =	16.409262

2952	2952			
512B		.150000 x	156.547635 =	23.482145
		-----		
			T.E =	23.482145
2953	2953			
513A		.150000 x	213.613843 =	32.042076
		-----		
			T.E =	32.042076
2954	2954			
513B		.150000 x	273.906213 =	41.085932
		-----		
			T.E =	41.085932
3111A	3111A			
112		.020000 x	17.312112 =	.346242
522		.000263 x	470.066513 =	.123627
509		.000193 x	562.321957 =	.108528
509		.000072 x	562.321957 =	.040487
630		.020000 x	.545730 =	.010915
501		.000182 x	649.240217 =	.118162
614		.135000 x	11.097931 =	1.498221
		-----		
			T.E =	2.246182
3111B	3111B			
112		.020000 x	17.312112 =	.346242
630		.020000 x	.545730 =	.010915
509		.000072 x	562.321957 =	.040487
501		.000182 x	649.240217 =	.118162
509		.000193 x	562.321957 =	.108528
522		.000263 x	470.066513 =	.123627
622		.135000 x	14.990059 =	2.023658
		-----		
			T.E =	2.771619
3112	3112			
509		.000094 x	562.321957 =	.052858
		-----		
			T.E =	.052858
3121A	3121A			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	649.240217 =	1.180319
614		1.350000 x	11.097931 =	14.982207
509		.001929 x	562.321957 =	1.084719
509		.000722 x	562.321957 =	.405996
522		.002632 x	470.066513 =	1.237215
630		.200000 x	.545730 =	.109146
		-----		
			T.E =	22.462025

3121B	3121B			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	649.240217 =	1.180319
509		.000722 x	562.321957 =	.405996
509		.001929 x	562.321957 =	1.084719
522		.002632 x	470.066513 =	1.237215
630		.200000 x	.545730 =	.109146
622		1.350000 x	14.990059 =	20.236580
-----				
			T.E =	27.716397
3122	3122			
509		.000940 x	562.321957 =	.528583
-----				
			T.E =	.528583
3211A	3211A			
112		.025000 x	17.312112 =	.432803
522		.000263 x	470.066513 =	.123627
501		.000182 x	649.240217 =	.118162
614		.135000 x	11.097931 =	1.498221
509		.000072 x	562.321957 =	.040487
509		.000193 x	562.321957 =	.108528
630		.020000 x	.545730 =	.010915
-----				
			T.E =	2.332743
3211B	3211B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	14.990059 =	2.023658
509		.000072 x	562.321957 =	.040487
509		.000193 x	562.321957 =	.108528
522		.000263 x	470.066513 =	.123627
501		.000182 x	649.240217 =	.118162
630		.020000 x	.545730 =	.010915
-----				
			T.E =	2.858180
3212	3212			
509		.000141 x	562.321957 =	.079287
-----				
			T.E =	.079287



3221	3221			
622		.202500 x	14.990059 =	3.035487
509		.000286 x	562.321957 =	.160824
501		.000250 x	649.240217 =	.162310
509		.000250 x	562.321957 =	.140580
509		.000469 x	562.321957 =	.263729
509		.000250 x	562.321957 =	.140580
522		.000500 x	470.066513 =	.235033
630		.100000 x	.545730 =	.054573
		-----		
			T.E =	4.193117
3222	3222			
221		1.000000 x	.099900 =	.099900
		-----		
			T.E =	.099900
3223	3223			
509		.000141 x	562.321957 =	.079287
		-----		
			T.E =	.079287
3231	3231			
112		.025000 x	17.312112 =	.432803
509		.000054 x	562.321957 =	.030365
630		.015000 x	.545730 =	.008186
501		.000213 x	649.240217 =	.138288
522		.000286 x	470.066513 =	.134439
		-----		
			T.E =	.744081
3232A	3232A			
630		.200000 x	.545730 =	.109146
614		1.350000 x	11.097931 =	14.982207
509		.001929 x	562.321957 =	1.084719
		-----		
			T.E =	16.176072
3232B	3232B			
622		1.350000 x	14.990059 =	20.236580
509		.001929 x	562.321957 =	1.084719
630		.200000 x	.545730 =	.109146
		-----		
			T.E =	21.430445
3233	3233			
509		.000940 x	562.321957 =	.528583
		-----		
			T.E =	.528583

3241A	3241A			
112		.025000 x	17.312112 =	.432803
614		.135000 x	11.097931 =	1.498221
501		.000213 x	649.240217 =	.138288
509		.000193 x	562.321957 =	.108528
522		.000286 x	470.066513 =	.134439
509		.000072 x	562.321957 =	.040487
630		.020000 x	.545730 =	.010915
-----				
			T.E =	2.363681
3241B	3241B			
112		.025000 x	17.312112 =	.432803
501		.000213 x	649.240217 =	.138288
509		.000072 x	562.321957 =	.040487
509		.000193 x	562.321957 =	.108528
522		.000286 x	470.066513 =	.134439
630		.020000 x	.545730 =	.010915
622		.135000 x	14.990059 =	2.023658
-----				
			T.E =	2.889118
3242	3242			
509		.000094 x	562.321957 =	.052858
-----				
			T.E =	.052858
3311A	3311A			
112		.025000 x	17.312112 =	.432803
630		.020000 x	.545730 =	.010915
509		.000193 x	562.321957 =	.108528
509		.000072 x	562.321957 =	.040487
501		.000213 x	649.240217 =	.138288
614		.135000 x	11.097931 =	1.498221
522		.000286 x	470.066513 =	.134439
-----				
			T.E =	2.363681
3311B	3311B			
112		.025000 x	17.312112 =	.432803
522		.000286 x	470.066513 =	.134439
501		.000213 x	649.240217 =	.138288
509		.000072 x	562.321957 =	.040487
509		.000193 x	562.321957 =	.108528
630		.020000 x	.545730 =	.010915
622		.135000 x	14.990059 =	2.023658
-----				
			T.E =	2.889118

3312	3312			
509		.000094 x	562.321957 =	.052858
				-----
			T.E =	.052858
3321A	3321A			
112		.030000 x	17.312112 =	.519363
509		.000193 x	562.321957 =	.108528
509		.000072 x	562.321957 =	.040487
501		.000213 x	649.240217 =	.138288
614		.135000 x	11.097931 =	1.498221
630		.020000 x	.545730 =	.010915
522		.000286 x	470.066513 =	.134439
				-----
			T.E =	2.450241
3321B	3321B			
112		.030000 x	17.312112 =	.519363
509		.000193 x	562.321957 =	.108528
501		.000213 x	649.240217 =	.138288
509		.000072 x	562.321957 =	.040487
622		.135000 x	14.990059 =	2.023658
522		.000286 x	470.066513 =	.134439
630		.020000 x	.545730 =	.010915
				-----
			T.E =	2.975678
3322	3322			
509		.000094 x	562.321957 =	.052858
				-----
			T.E =	.052858
3401	3401			
111		1.300000 x	15.741598 =	20.464077
509		.000361 x	562.321957 =	.202998
521		.014286 x	340.081496 =	4.858404
630		.100000 x	.545730 =	.054573
112		.900000 x	17.312112 =	15.580901
				-----
			T.E =	41.160954
3402A	3402A			
509		.001929 x	562.321957 =	1.084719
614		1.350000 x	11.097931 =	14.982207
				-----
			T.E =	16.066926
3402B	3402B			
622		1.350000 x	14.990059 =	20.236580
509		.001929 x	562.321957 =	1.084719
				-----
			T.E =	21.321299

3403	3403			
509		.000940 x	562.321957 =	.528583
-----				
				T.E =
				.528583
4110	4110			
112		.008000 x	17.312112 =	.138497
523		.000143 x	359.790362 =	.051450
526		.000100 x	572.515148 =	.057252
671		1.200000 x	.764133 =	.916960
-----				
				T.E =
				1.164158
4110.1	4110.1			
112		.008000 x	17.312112 =	.138497
671.1		1.200000 x	.518008 =	.621610
526		.000100 x	572.515148 =	.057252
523		.000143 x	359.790362 =	.051450
-----				
				T.E =
				.868808
4120	4120			
321		.500000 x	.447500 =	.223750
525		.000067 x	251.298253 =	.016837
526		.000100 x	572.515148 =	.057252
523		.000143 x	359.790362 =	.051450
112		.006000 x	17.312112 =	.103873
-----				
				T.E =
				.453161
4120.1	4120.1			
112		.006000 x	17.312112 =	.103873
523		.000143 x	359.790362 =	.051450
525		.000067 x	251.298253 =	.016837
526		.000100 x	572.515148 =	.057252
-----				
				T.E =
				.229411
4131A	4131A			
321		1.000000 x	.447500 =	.447500
509		.000143 x	562.321957 =	.080412
509		.000014 x	562.321957 =	.007873
509		.000028 x	562.321957 =	.015745
504		.000143 x	774.119390 =	.110699
616		.015000 x	11.097931 =	.166469
525		.000067 x	251.298253 =	.016837
526		.000143 x	572.515148 =	.081870
523		.000143 x	359.790362 =	.051450
112		.008000 x	17.312112 =	.138497
522		.000143 x	470.066513 =	.067220
-----				
				T.E =
				1.184571

4131A.1	4131A.1			
112		.008000 x	17.312112 =	.138497
509		.000028 x	562.321957 =	.015745
616		.015000 x	11.097931 =	.166469
525		.000067 x	251.298253 =	.016837
526		.000143 x	572.515148 =	.081870
523		.000143 x	359.790362 =	.051450
504		.000143 x	774.119390 =	.110699
509		.000014 x	562.321957 =	.007873
522		.000143 x	470.066513 =	.067220
509		.000143 x	562.321957 =	.080412

-----  
 T.E = .737071

4131B	4131B			
321		1.000000 x	.447500 =	.447500
525		.000067 x	251.298253 =	.016837
526		.000143 x	572.515148 =	.081870
523		.000143 x	359.790362 =	.051450
504		.000143 x	774.119390 =	.110699
509		.000143 x	562.321957 =	.080412
509		.000014 x	562.321957 =	.007873
509		.000028 x	562.321957 =	.015745
522		.000143 x	470.066513 =	.067220
624		.015000 x	14.990059 =	.224851
112		.008000 x	17.312112 =	.138497

-----  
 T.E = 1.242953

4131B.1	4131B.1			
112		.008000 x	17.312112 =	.138497
509		.000028 x	562.321957 =	.015745
525		.000067 x	251.298253 =	.016837
526		.000143 x	572.515148 =	.081870
523		.000143 x	359.790362 =	.051450
504		.000143 x	774.119390 =	.110699
509		.000143 x	562.321957 =	.080412
509		.000014 x	562.321957 =	.007873
522		.000143 x	470.066513 =	.067220
624		.015000 x	14.990059 =	.224851

-----  
 T.E = .795453

4132	4132			
509		.000009 x	562.321957 =	.005061

-----  
 T.E = .005061

4141A	4141A			
112		.013000 x	17.312112 =	.225057
616		.012000 x	11.097931 =	.133175
615		.015000 x	11.097931 =	.166469
526		.000244 x	572.515148 =	.139694
523		.000143 x	359.790362 =	.051450
504		.000244 x	774.119390 =	.188885
509		.000244 x	562.321957 =	.137207
672		1.500000 x	.531595 =	.797393
522		.000244 x	470.066513 =	.114696
509		.000024 x	562.321957 =	.013496
509		.000038 x	562.321957 =	.021368
671		1.200000 x	.764133 =	.916960

T.E = 2.905849

4141A.1	4141A.1			
112		.013000 x	17.312112 =	.225057
616		.012000 x	11.097931 =	.133175
615		.015000 x	11.097931 =	.166469
526		.000244 x	572.515148 =	.139694
523		.000143 x	359.790362 =	.051450
504		.000244 x	774.119390 =	.188885
509		.000244 x	562.321957 =	.137207
509		.000024 x	562.321957 =	.013496
509		.000038 x	562.321957 =	.021368
522		.000244 x	470.066513 =	.114696
672.1		1.500000 x	.110945 =	.166418
671.1		1.200000 x	.518008 =	.621610

T.E = 1.979524

4141B	4141B			
112		.013000 x	17.312112 =	.225057
509		.000024 x	562.321957 =	.013496
526		.000244 x	572.515148 =	.139694
523		.000143 x	359.790362 =	.051450
504		.000244 x	774.119390 =	.188885
509		.000244 x	562.321957 =	.137207
509		.000038 x	562.321957 =	.021368
623		.015000 x	14.773671 =	.221605
522		.000244 x	470.066513 =	.114696
672		1.500000 x	.531595 =	.797393
671		1.200000 x	.764133 =	.916960
624		.012000 x	14.990059 =	.179881

T.E = 3.007691

4141B.1	4141B.1			
112		.013000 x	17.312112 =	.225057
623		.015000 x	14.773671 =	.221605
526		.000244 x	572.515148 =	.139694
523		.000143 x	359.790362 =	.051450
504		.000244 x	774.119390 =	.188885
509		.000244 x	562.321957 =	.137207
509		.000024 x	562.321957 =	.013496
509		.000038 x	562.321957 =	.021368
522		.000244 x	470.066513 =	.114696
672.1		1.500000 x	.110945 =	.166418
671.1		1.200000 x	.518008 =	.621610
624		.012000 x	14.990059 =	.179881
			T.E =	2.081366
4142	4142			
509		.000017 x	562.321957 =	.009559
			T.E =	.009559
4211A	4211A			
672		25.000000 x	.531595 =	13.289875
509		.001429 x	562.321957 =	.803558
615		.700000 x	11.097931 =	7.768552
501		.007024 x	649.240217 =	4.560263
616		.300000 x	11.097931 =	3.329379
526		.002857 x	572.515148 =	1.635676
522		.003846 x	470.066513 =	1.807876
			T.E =	33.195179
4211A.1	4211A.1			
672.1		25.000000 x	.110945 =	2.773625
501		.007024 x	649.240217 =	4.560263
616		.300000 x	11.097931 =	3.329379
615		.700000 x	11.097931 =	7.768552
526		.002857 x	572.515148 =	1.635676
509		.001429 x	562.321957 =	.803558
522		.003846 x	470.066513 =	1.807876
			T.E =	22.678929
4211B	4211B			
623		.700000 x	14.773671 =	10.341570
672		25.000000 x	.531595 =	13.289875
624		.300000 x	14.990059 =	4.497018
501		.007024 x	649.240217 =	4.560263
526		.002857 x	572.515148 =	1.635676
509		.001429 x	562.321957 =	.803558
522		.003846 x	470.066513 =	1.807876
			T.E =	36.935835

4211B.1	4211B.1			
623		.700000 x	14.773671 =	10.341570
501		.007024 x	649.240217 =	4.560263
526		.002857 x	572.515148 =	1.635676
672.1		25.000000 x	.110945 =	2.773625
624		.300000 x	14.990059 =	4.497018
522		.003846 x	470.066513 =	1.807876
509		.001429 x	562.321957 =	.803558
-----				
			T.E =	26.419585
4212	4212			
509		.000614 x	562.321957 =	.345266
-----				
			T.E =	.345266
4221A	4221A			
672		37.000000 x	.531595 =	19.669015
509		.001429 x	562.321957 =	.803558
615		.600000 x	11.097931 =	6.658759
501		.008226 x	649.240217 =	5.340650
616		.400000 x	11.097931 =	4.439172
526		.004000 x	572.515148 =	2.290061
522		.004348 x	470.066513 =	2.043849
-----				
			T.E =	41.245064
4221A.1	4221A.1			
672.1		37.000000 x	.110945 =	4.104965
616		.400000 x	11.097931 =	4.439172
615		.600000 x	11.097931 =	6.658759
526		.004000 x	572.515148 =	2.290061
501		.008226 x	649.240217 =	5.340650
509		.001429 x	562.321957 =	.803558
522		.004348 x	470.066513 =	2.043849
-----				
			T.E =	25.681014
4221B	4221B			
623		.600000 x	14.773671 =	8.864203
672		37.000000 x	.531595 =	19.669015
501		.008226 x	649.240217 =	5.340650
526		.004000 x	572.515148 =	2.290061
509		.001429 x	562.321957 =	.803558
522		.004348 x	470.066513 =	2.043849
624		.400000 x	14.990059 =	5.996024
-----				
			T.E =	45.007359



4221B.1	4221B.1			
623		.600000 x	14.773671 =	8.864203
672.1		37.000000 x	.110945 =	4.104965
624		.400000 x	14.990059 =	5.996024
509		.001429 x	562.321957 =	.803558
522		.004348 x	470.066513 =	2.043849
501		.008226 x	649.240217 =	5.340650
526		.004000 x	572.515148 =	2.290061
-----				
			T.E =	29.443309
4222	4222			
509		.000614 x	562.321957 =	.345266
-----				
			T.E =	.345266
4231A	4231A			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
509		.000044 x	562.321957 =	.024742
509		.000357 x	562.321957 =	.200749
615		.025000 x	11.097931 =	.277448
616		.006000 x	11.097931 =	.066588
526		.000222 x	572.515148 =	.127098
523		.000143 x	359.790362 =	.051450
509		.000036 x	562.321957 =	.020244
522		.000357 x	470.066513 =	.167814
672		2.500000 x	.531595 =	1.328988
-----				
			T.E =	2.871044
4231A.1	4231A.1			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
616		.006000 x	11.097931 =	.066588
615		.025000 x	11.097931 =	.277448
526		.000222 x	572.515148 =	.127098
523		.000143 x	359.790362 =	.051450
509		.000036 x	562.321957 =	.020244
509		.000044 x	562.321957 =	.024742
509		.000357 x	562.321957 =	.200749
522		.000357 x	470.066513 =	.167814
672.1		2.500000 x	.110945 =	.277363
-----				
			T.E =	1.819419

4231B	4231B			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
623		.025000 x	14.773671 =	.369342
624		.006000 x	14.990059 =	.089940
522		.000357 x	470.066513 =	.167814
526		.000222 x	572.515148 =	.127098
523		.000143 x	359.790362 =	.051450
509		.000357 x	562.321957 =	.200749
509		.000044 x	562.321957 =	.024742
509		.000036 x	562.321957 =	.020244
672		2.500000 x	.531595 =	1.328988

-----  
 T.E = 2.986290

4231B.1	4231B.1			
112		.005000 x	17.312112 =	.086561
509		.000044 x	562.321957 =	.024742
509		.000357 x	562.321957 =	.200749
526		.000222 x	572.515148 =	.127098
523		.000143 x	359.790362 =	.051450
509		.000036 x	562.321957 =	.020244
112		.030000 x	17.312112 =	.519363
672.1		2.500000 x	.110945 =	.277363
522		.000357 x	470.066513 =	.167814
624		.006000 x	14.990059 =	.089940
623		.025000 x	14.773671 =	.369342

-----  
 T.E = 1.934665

4232	4232			
509		.000024 x	562.321957 =	.013496

-----  
 T.E = .013496

4321A	4321A			
521		.000128 x	340.081496 =	.043530
523		.000143 x	359.790362 =	.051450
4312		.071000 x	1.686206 =	.119721
4311A		.071000 x	56.649682 =	4.022127
528		.000128 x	864.454565 =	.110650
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795

-----  
 T.E = 4.464442

4321A.1	4321A.1			
521		.000128 x	340.081496 =	.043530
4312		.071000 x	1.686206 =	.119721
4311A.1		.071000 x	20.849682 =	1.480327
528		.000128 x	864.454565 =	.110650
522		.000128 x	470.066513 =	.060169
523		.000143 x	359.790362 =	.051450
509		.000101 x	562.321957 =	.056795
-----				
			T.E =	1.922642
4321B	4321B			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
4312		.071000 x	1.686206 =	.119721
4311B		.071000 x	58.788131 =	4.173957
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
509		.000101 x	562.321957 =	.056795
-----				
			T.E =	4.616272
4321B.1	4321B.1			
521		.000128 x	340.081496 =	.043530
4312		.071000 x	1.686206 =	.119721
4311B.1		.071000 x	22.988131 =	1.632157
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
509		.000101 x	562.321957 =	.056795
522		.000128 x	470.066513 =	.060169
-----				
			T.E =	2.074472
4322	4322			
509		.000049 x	562.321957 =	.027554
-----				
			T.E =	.027554
4421A	4421A			
521		.000128 x	340.081496 =	.043530
528		.000128 x	864.454565 =	.110650
4411A		.071000 x	56.649682 =	4.022127
4312		.071000 x	1.686206 =	.119721
523		.000143 x	359.790362 =	.051450
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795
-----				
			T.E =	4.464442

4421A.1	4421A.1			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795
4412		.071000 x	1.686206 =	.119721
4411A.1		.071000 x	20.849682 =	1.480327
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
-----				
			T.E =	1.922642
4421B	4421B			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795
523		.000143 x	359.790362 =	.051450
4411B		.071000 x	58.788131 =	4.173957
4412		.071000 x	1.686206 =	.119721
528		.000128 x	864.454565 =	.110650
-----				
			T.E =	4.616272
4421B.1	4421B.1			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795
4412		.071000 x	1.686206 =	.119721
4411B.1		.071000 x	22.988131 =	1.632157
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
-----				
			T.E =	2.074472
4422	4422			
509		.000049 x	562.321957 =	.027554
-----				
			T.E =	.027554
4521A	4521A			
521		.000128 x	340.081496 =	.043530
4511A		.071000 x	61.470795 =	4.364426
4512		.071000 x	1.686206 =	.119721
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
509		.000101 x	562.321957 =	.056795
522		.000128 x	470.066513 =	.060169
-----				
			T.E =	4.806741

4521A.1	4521A.1			
521		.000128 x	340.081496 =	.043530
4512		.071000 x	1.686206 =	.119721
4511A.1		.071000 x	21.195795 =	1.504901
528		.000128 x	864.454565 =	.110650
523		.000143 x	359.790362 =	.051450
509		.000101 x	562.321957 =	.056795
522		.000128 x	470.066513 =	.060169
-----				
			T.E =	1.947216
4521B	4521B			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
509		.000101 x	562.321957 =	.056795
523		.000143 x	359.790362 =	.051450
4512		.071000 x	1.686206 =	.119721
4511B		.071000 x	63.998458 =	4.543891
528		.000128 x	864.454565 =	.110650
-----				
			T.E =	4.986205
4521B.1	4521B.1			
521		.000128 x	340.081496 =	.043530
522		.000128 x	470.066513 =	.060169
523		.000143 x	359.790362 =	.051450
4512		.071000 x	1.686206 =	.119721
4511B.1		.071000 x	23.723458 =	1.684366
528		.000128 x	864.454565 =	.110650
509		.000101 x	562.321957 =	.056795
-----				
			T.E =	2.126680
4522	4522			
509		.000049 x	562.321957 =	.027554
-----				
			T.E =	.027554
4611.1	4611.1			
326		45.000000 x	1.310000 =	58.950000
623		.033000 x	14.773671 =	.487531
617		.013000 x	5.628184 =	.073166
4120.1		1.000000 x	.229411 =	.229411
529		.002857 x	738.479665 =	2.109836
525		.000286 x	251.298253 =	.071871
509		.000046 x	562.321957 =	.025867
522		.000667 x	470.066513 =	.313534
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	64.303166

4611A	4611A			
321		3.000000 x	.447500 =	1.342500
326		45.000000 x	1.310000 =	58.950000
509		.000046 x	562.321957 =	.025867
4120		1.000000 x	.453161 =	.453161
529		.002857 x	738.479665 =	2.109836
525		.000286 x	251.298253 =	.071871
522		.000667 x	470.066513 =	.313534
113		.100000 x	20.419486 =	2.041949
623		.033000 x	14.773671 =	.487531
617		.013000 x	5.628184 =	.073166
-----				
			T.E =	65.869416
4612	4612			
509		.000040 x	562.321957 =	.022493
-----				
			T.E =	.022493
4710A	4710A			
111		1.900000 x	15.741598 =	29.909036
112		2.400000 x	17.312112 =	41.549069
613		1.000000 x	6.319290 =	6.319290
509		.000361 x	562.321957 =	.202998
509		.005305 x	562.321957 =	2.983118
630		.200000 x	.545730 =	.109146
112		1.200000 x	17.312112 =	20.774534
-----				
			T.E =	101.847192
4710A.1	4710A.1			
111		1.900000 x	15.741598 =	29.909036
112		1.200000 x	17.312112 =	20.774534
112		2.400000 x	17.312112 =	41.549069
509		.000361 x	562.321957 =	.202998
614		1.000000 x	11.097931 =	11.097931
509		.005305 x	562.321957 =	2.983118
630		.200000 x	.545730 =	.109146
-----				
			T.E =	106.625833
4710B	4710B			
111		1.900000 x	15.741598 =	29.909036
112		2.400000 x	17.312112 =	41.549069
509		.000361 x	562.321957 =	.202998
509		.005305 x	562.321957 =	2.983118
630		.200000 x	.545730 =	.109146
622		1.000000 x	14.990059 =	14.990059
112		1.200000 x	17.312112 =	20.774534
-----				
			T.E =	110.517961

4720A	4720A			
111		1.900000 x	15.741598 =	29.909036
4522		140.000000 x	.027554 =	3.857560
4512		1.000000 x	1.686206 =	1.686206
4511B		1.000000 x	63.998458 =	63.998458
671		20.000000 x	.764133 =	15.282660
112		2.000000 x	17.312112 =	34.624224
112		2.400000 x	17.312112 =	41.549069
111		1.000000 x	15.741598 =	15.741598
-----				
			T.E =	206.648811
4720A.1	4720A.1			
111		1.900000 x	15.741598 =	29.909036
111		1.000000 x	15.741598 =	15.741598
112		2.000000 x	17.312112 =	34.624224
4511B.1		1.000000 x	23.723458 =	23.723458
4522		140.000000 x	.027554 =	3.857560
4512		1.000000 x	1.686206 =	1.686206
671.1		20.000000 x	.518008 =	10.360160
112		2.400000 x	17.312112 =	41.549069
-----				
			T.E =	161.451311
4800	4800			
325		1.000000 x	2.780000 =	2.780000
112		.010000 x	17.312112 =	.173121
-----				
			T.E =	2.953121