

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

4ο Τρίμηνο του 2009

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021		2.670000
029		.152800
051		15.400000
111	Κατχ Τιμή X 1.8117/ 6.46	16.829739
112	Κατχ Τιμή X 1.8117/ 6.46	18.705943
113	Κατχ Τιμή X 1.8117/ 6.46	24.769248
114	Κατχ Τιμή X 1.8117/ 6.67	23.989407
115	Κατχ Τιμή X 1.8117/ 6.67	19.931416
116	Κατχ Τιμή X 1.8117/ 6.46	24.152261
117	Κατχ Τιμή X 1.8117/ 6.67	19.931416
118	Κατχ Τιμή X 1.8117/ 6.67	18.233796
150		.074800
211		.826000
212		.961300
213		1.895000
214		3.490000
221		.098900
224		.070000
231		.695000
241		7.050000
242		5.000000
251		290.000000
252		210.000000
301		4.060000
302		6.700000
360		10.700000
361		27.500000
362		5.250000
363		.580000
364		3.520000
365		22.500000
366		20.630000
367		.118700
368		20.000000
369		12.150000
370		8.000000
371		7.200000
372		1.270000
373		2.040000
374		2.750000
375		1.500000
376		
377		3.190000
378		.540000
379		14.000000
380		.260000
401		255.610000
402		369.270000
403		100.390000
404		202.580000
405		200.790000
406		311.770000
407		52.580000
408		4.310000
409		120.060000
410		110.970000
411		26.060000
412		2.840000
417		128.110000

420	92.650000
428	425.280000
450	109.630000
451	151.930000
452	93.090000
453	86.390000
454	116.790000
455	412.330000

501	501				
211		50.000000 x	.826000 =	41.300000	
214		3.000000 x	3.490000 =	10.470000	
401		1.000000 x	255.610000 =	255.610000	
118		3.000000 x	18.233796 =	54.701388	
114		8.000000 x	23.989407 =	191.915256	
			AΘΡΟΙΣΜΑ =	553.996644	
			H.Δ. =	609.396308	
502	502				
211		80.000000 x	.826000 =	66.080000	
114		8.000000 x	23.989407 =	191.915256	
402		1.000000 x	369.270000 =	369.270000	
214		7.000000 x	3.490000 =	24.430000	
118		4.000000 x	18.233796 =	72.935184	
			AΘΡΟΙΣΜΑ =	724.630440	
			H.Δ. =	797.093484	
503	503				
211		110.000000 x	.826000 =	90.860000	
428		1.000000 x	425.280000 =	425.280000	
214		10.000000 x	3.490000 =	34.900000	
118		4.000000 x	18.233796 =	72.935184	
114		8.000000 x	23.989407 =	191.915256	
			AΘΡΟΙΣΜΑ =	815.890440	
			H.Δ. =	897.479484	
504	504				
211		40.000000 x	.826000 =	33.040000	
214		2.000000 x	3.490000 =	6.980000	
114		8.000000 x	23.989407 =	191.915256	
403		1.000000 x	100.390000 =	100.390000	
			AΘΡΟΙΣΜΑ =	332.325256	
			H.Δ. =	365.557782	
505	505				
211		200.000000 x	.826000 =	165.200000	
214		10.000000 x	3.490000 =	34.900000	
114		8.000000 x	23.989407 =	191.915256	
118		8.000000 x	18.233796 =	145.870368	
404		1.000000 x	202.580000 =	202.580000	
			AΘΡΟΙΣΜΑ =	740.465624	
			H.Δ. =	814.512186	

506	506			
211		95.000000 x	.826000 =	78.470000
214		6.000000 x	3.490000 =	20.940000
405		1.000000 x	200.790000 =	200.790000
242		2.500000 x	5.000000 =	12.500000
118		8.000000 x	18.233796 =	145.870368
114		8.000000 x	23.989407 =	191.915256

		ΑΘΡΟΙΣΜΑ =		650.485624

		H.Δ. =		715.534186
507	507			
211		165.000000 x	.826000 =	136.290000
214		10.000000 x	3.490000 =	34.900000
242		7.000000 x	5.000000 =	35.000000
406		1.000000 x	311.770000 =	311.770000
114		8.000000 x	23.989407 =	191.915256
118		8.000000 x	18.233796 =	145.870368

		ΑΘΡΟΙΣΜΑ =		855.745624

		H.Δ. =		941.320186
508	508			
211		40.000000 x	.826000 =	33.040000
407		1.000000 x	52.580000 =	52.580000
115		4.000000 x	19.931416 =	79.725664
116		16.000000 x	24.152261 =	386.436176
408		2.000000 x	4.310000 =	8.620000
214		2.000000 x	3.490000 =	6.980000

		ΑΘΡΟΙΣΜΑ =		567.381840

		H.Δ. =		624.120024
509	509			
211		80.000000 x	.826000 =	66.080000
117		8.000000 x	19.931416 =	159.451328
409		1.000000 x	120.060000 =	120.060000
214		5.000000 x	3.490000 =	17.450000

		ΑΘΡΟΙΣΜΑ =		363.041328

		H.Δ. =		399.345461
510	510			
211		80.000000 x	.826000 =	66.080000
117		8.000000 x	19.931416 =	159.451328
214		5.000000 x	3.490000 =	17.450000
410		1.000000 x	110.970000 =	110.970000

		ΑΘΡΟΙΣΜΑ =		353.951328

		H.Δ. =		389.346461

511	511			
212		17.000000 x	.961300 =	16.342100
411		1.000000 x	26.060000 =	26.060000
214		1.000000 x	3.490000 =	3.490000
115		4.000000 x	19.931416 =	79.725664
112		30.000000 x	18.705943 =	561.178290

				ΑΘΡΟΙΣΜΑ = 686.796054

				Η.Δ. = 755.475659
512	512			
211		10.000000 x	.826000 =	8.260000
115		2.000000 x	19.931416 =	39.862832
214		1.000000 x	3.490000 =	3.490000
112		2.000000 x	18.705943 =	37.411886
412		1.000000 x	2.840000 =	2.840000

				ΑΘΡΟΙΣΜΑ = 91.864718

				Η.Δ. = 101.051190
518	518			
211		180.000000 x	.826000 =	148.680000
212		5.000000 x	.961300 =	4.806500
118		8.000000 x	18.233796 =	145.870368
114		8.000000 x	23.989407 =	191.915256
112		8.000000 x	18.705943 =	149.647544
417		1.000000 x	128.110000 =	128.110000
214		12.000000 x	3.490000 =	41.880000

				ΑΘΡΟΙΣΜΑ = 810.909668

				Η.Δ. = 892.000635
521	521			
211		40.000000 x	.826000 =	33.040000
118		4.000000 x	18.233796 =	72.935184
114		8.000000 x	23.989407 =	191.915256
214		3.000000 x	3.490000 =	10.470000
420		1.000000 x	92.650000 =	92.650000

				ΑΘΡΟΙΣΜΑ = 401.010440

				Η.Δ. = 441.111484
550	550			
211		80.000000 x	.826000 =	66.080000
214		5.000000 x	3.490000 =	17.450000
117		8.000000 x	19.931416 =	159.451328
450		1.000000 x	109.630000 =	109.630000

				ΑΘΡΟΙΣΜΑ = 352.611328

				Η.Δ. = 387.872461

560	560			
211		80.000000 x	.826000 =	66.080000
117		8.000000 x	19.931416 =	159.451328
455		1.000000 x	412.330000 =	412.330000
214		7.000000 x	3.490000 =	24.430000

			ΑΘΡΟΙΣΜΑ =	662.291328

			H.Δ. =	728.520461
621	621			
213		.100000 x	1.895000 =	.189500
508		.005000 x	624.120024 =	3.120600
116		.200000 x	24.152261 =	4.830452
111		.800000 x	16.829739 =	13.463791

			B.T =	21.604344
623	623			
213		.100000 x	1.895000 =	.189500
504		.005000 x	365.557782 =	1.827789
116		.200000 x	24.152261 =	4.830452
112		.100000 x	18.705943 =	1.870594
508		.005000 x	624.120024 =	3.120600
518		.010000 x	892.000635 =	8.920006
509		.005000 x	399.345461 =	1.996727

			B.T =	22.755669
625	625			
213		.100000 x	1.895000 =	.189500
116		.200000 x	24.152261 =	4.830452
112		.100000 x	18.705943 =	1.870594
504		.005000 x	365.557782 =	1.827789
509		.005000 x	399.345461 =	1.996727
518		.014300 x	892.000635 =	12.755609
508		.005000 x	624.120024 =	3.120600

			B.T =	26.591272
630	630			
512		.020000 x	101.051190 =	2.021024

			B.T =	2.021024
630.1	630.1			
510		.006000 x	389.346461 =	2.336079

			B.T =	2.336079

641	641			
231		.200000 x	.695000 =	.139000
251		.001500 x	290.000000 =	.435000
111		.200000 x	16.829739 =	3.365948
113		.150000 x	24.769248 =	3.715387
252		.002500 x	210.000000 =	.525000

			B.T =	8.180335
651	651			
221		150.000000 x	.098900 =	14.835000
111		1.500000 x	16.829739 =	25.244609
112		.500000 x	18.705943 =	9.352972
509		.003600 x	399.345461 =	1.437644
509		.011100 x	399.345461 =	4.432735
511		.050000 x	755.475659 =	37.773783
630		.600000 x	2.021024 =	1.212614
625		1.000000 x	26.591272 =	26.591272
224		120.000000 x	.070000 =	8.400000

			B.T =	129.280628
652	652			
221		650.000000 x	.098900 =	64.285000
509		.011000 x	399.345461 =	4.392800
630		.320000 x	2.021024 =	.646728
625		1.000000 x	26.591272 =	26.591272
511		.050000 x	755.475659 =	37.773783
509		.001920 x	399.345461 =	.766743
112		.500000 x	18.705943 =	9.352972
111		1.500000 x	16.829739 =	25.244609

			B.T =	169.053906
1121	1121			
112		.007000 x	18.705943 =	.130942
501		.000100 x	609.396308 =	.060940
503		.002000 x	897.479484 =	1.794959

			T.E =	1.986840
1122	1122			
112		.007000 x	18.705943 =	.130942
503		.000330 x	897.479484 =	.296168
501		.000080 x	609.396308 =	.048752
505		.000600 x	814.512186 =	.488707
507		.001400 x	941.320186 =	1.317848
509		.004447 x	399.345461 =	1.775889

			T.E =	4.058306

1123A	1123A			
112		.007000 x	18.705943 =	.130942
501		.000100 x	609.396308 =	.060940
503		.002000 x	897.479484 =	1.794959
509		.005312 x	399.345461 =	2.121323
506		.001330 x	715.534186 =	.951660

			T.E =	5.059824
1123B	1123B			
509		.001487 x	399.345461 =	.593827

			T.E =	.593827
1140	1140			
112		.010000 x	18.705943 =	.187059
521		.000200 x	441.111484 =	.088222
501		.000100 x	609.396308 =	.060940

			T.E =	.336221
1610	1610			
111		.050000 x	16.829739 =	.841487
1122		.200000 x	4.058306 =	.811661
507		.000200 x	941.320186 =	.188264
501		.000100 x	609.396308 =	.060940
502		.000200 x	797.093484 =	.159419

			T.E =	2.061771
1620	1620			
112		.250000 x	18.705943 =	4.676486
1122		1.000000 x	4.058306 =	4.058306
501		.002000 x	609.396308 =	1.218793

			T.E =	9.953584
1710	1710			
360		1.000000 x	10.700000 =	10.700000
111		.250000 x	16.829739 =	4.207435
501		.000100 x	609.396308 =	.060940

			T.E =	14.968374
2111	2111			
112		.010000 x	18.705943 =	.187059
509		.005202 x	399.345461 =	2.077395
507		.001540 x	941.320186 =	1.449633
502		.002000 x	797.093484 =	1.594187
501		.000830 x	609.396308 =	.505799

			T.E =	5.814074

2112	2112			
213		.400000 x	1.895000 =	.758000
502		.002900 x	797.093484 =	2.311571
112		.250000 x	18.705943 =	4.676486
116		.250000 x	24.152261 =	6.038065
507		.002000 x	941.320186 =	1.882640
509		.004896 x	399.345461 =	1.955195
508		.004000 x	624.120024 =	2.496480

			T.E =	20.118438
2251	2251			
111		.600000 x	16.829739 =	10.097843
621		1.050000 x	21.604344 =	22.684561
112		.600000 x	18.705943 =	11.223566
509		.012432 x	399.345461 =	4.964663

			T.E =	48.970633
2252	2252			
111		1.400000 x	16.829739 =	23.561635
621		1.050000 x	21.604344 =	22.684561
113		1.400000 x	24.769248 =	34.676947
509		.012432 x	399.345461 =	4.964663

			T.E =	85.887806
2253	2253			
111		1.500000 x	16.829739 =	25.244609
621		1.050000 x	21.604344 =	22.684561
652		.020000 x	169.053906 =	3.381078
651		.250000 x	129.280628 =	32.320157
509		.012432 x	399.345461 =	4.964663
113		2.500000 x	24.769248 =	61.923120
112		.200000 x	18.705943 =	3.741189

			T.E =	154.259376
2254	2254			
111		.800000 x	16.829739 =	13.463791
652		.100000 x	169.053906 =	16.905391
621		.350000 x	21.604344 =	7.561520
509		.003788 x	399.345461 =	1.512721
113		1.500000 x	24.769248 =	37.153872

			T.E =	76.597295

2522	2522			
221		300.000000 x	.098900 =	29.670000
112		1.400000 x	18.705943 =	26.188320
623		.800000 x	22.755669 =	18.204535
630		.250000 x	2.021024 =	.505256
641		3.000000 x	8.180335 =	24.541005
625		.500000 x	26.591272 =	13.295636
511		.040000 x	755.475659 =	30.219026
509		.008880 x	399.345461 =	3.546188
509		.001500 x	399.345461 =	.599018
509		.005550 x	399.345461 =	2.216367
113		1.600000 x	24.769248 =	39.630797

			T.E =	188.616149
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	188.616149 =	.943081
652		.002000 x	169.053906 =	.338108
113		.400000 x	24.769248 =	9.907699
111		.400000 x	16.829739 =	6.731896

			T.E =	21.980783
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	169.053906 =	2.028647
111		.600000 x	16.829739 =	10.097843
113		.800000 x	24.769248 =	19.815398

			T.E =	38.775889
5110	5110			
111		.100000 x	16.829739 =	1.682974

			T.E =	1.682974
5120	5120			
111		.080000 x	16.829739 =	1.346379

			T.E =	1.346379
5130	5130			
111		.050000 x	16.829739 =	.841487

			T.E =	.841487
5140	5140			
111		.030000 x	16.829739 =	.504892
550		.003750 x	387.872461 =	1.454522

			T.E =	1.959414

5150	5150			
111		.030000 x	16.829739 =	.504892
550		.002500 x	387.872461 =	.969681

			T.E =	1.474573
5160	5160			
213		.400000 x	1.895000 =	.758000
111		.160000 x	16.829739 =	2.692758
508		.001500 x	624.120024 =	.936180

			T.E =	4.386938
5210	5210			
363		.100000 x	.580000 =	.058000
112		.050000 x	18.705943 =	.935297
111		.040000 x	16.829739 =	.673190

			T.E =	1.666487
5220	5220			
363		.100000 x	.580000 =	.058000
112		.030000 x	18.705943 =	.561178
111		.020000 x	16.829739 =	.336595

			T.E =	.955773
5230	5230			
364		1.000000 x	3.520000 =	3.520000
112		.080000 x	18.705943 =	1.496475

			T.E =	5.016475
5240	5240			
112		.080000 x	18.705943 =	1.496475

			T.E =	1.496475
5311	5311			
111		.002000 x	16.829739 =	.033659
630.1		.020000 x	2.336079 =	.046722
510		.000250 x	389.346461 =	.097337
630		.020000 x	2.021024 =	.040420

			T.E =	.218138

5312	5312			
111		.001300 x	16.829739 =	.021879
630.1		.020000 x	2.336079 =	.046722
510		.000163 x	389.346461 =	.063463
630		.020000 x	2.021024 =	.040420

			T.E =	.172484
5321	5321			
111		.004000 x	16.829739 =	.067319

			T.E =	.067319
5322	5322			
111		.003300 x	16.829739 =	.055538

			T.E =	.055538
5330	5330			
111		.022200 x	16.829739 =	.373620

			T.E =	.373620
5340	5340			
363		.100000 x	.580000 =	.058000
111		.003300 x	16.829739 =	.055538

			T.E =	.113538
5351	5351			
113		.005000 x	24.769248 =	.123846

			T.E =	.123846
5352	5352			
111		.005000 x	16.829739 =	.084149
113		.014000 x	24.769248 =	.346769

			T.E =	.430918
5353	5353			
111		.010000 x	16.829739 =	.168297
113		.020000 x	24.769248 =	.495385

			T.E =	.663682

5354	5354				
111		.035000 x	16.829739 =		.589041
113		.025000 x	24.769248 =		.619231

			T.E =		1.208272
5361A	5361A				
365		.003000 x	22.500000 =		.067500
630		.000300 x	2.021024 =		.000606
510		.000188 x	389.346461 =		.073197
113		.001500 x	24.769248 =		.037154

			T.E =		.178457
5361B	5361B				
366		.003000 x	20.630000 =		.061890
510		.000188 x	389.346461 =		.073197
630		.000300 x	2.021024 =		.000606
113		.001500 x	24.769248 =		.037154

			T.E =		.172847
5362A	5362A				
365		.005000 x	22.500000 =		.112500
630		.000500 x	2.021024 =		.001011
510		.000313 x	389.346461 =		.121865
113		.002500 x	24.769248 =		.061923

			T.E =		.297299
5362B	5362B				
366		.005000 x	20.630000 =		.103150
630		.000500 x	2.021024 =		.001011
510		.000313 x	389.346461 =		.121865
113		.002500 x	24.769248 =		.061923

			T.E =		.287949
5363A	5363A				
365		.003000 x	22.500000 =		.067500
113		.001000 x	24.769248 =		.024769
510		.000125 x	389.346461 =		.048668
630		.000300 x	2.021024 =		.000606

			T.E =		.141544

5363B	5363B			
366		.003000 x	20.630000 =	.061890
113		.001000 x	24.769248 =	.024769
630		.000300 x	2.021024 =	.000606
510		.000125 x	389.346461 =	.048668

			T.E =	.135934
5364A	5364A			
365		.005000 x	22.500000 =	.112500
113		.001800 x	24.769248 =	.044585
630		.000500 x	2.021024 =	.001011
510		.000225 x	389.346461 =	.087603

			T.E =	.245698
5364B	5364B			
366		.005000 x	20.630000 =	.103150
630		.000500 x	2.021024 =	.001011
510		.000225 x	389.346461 =	.087603
113		.001800 x	24.769248 =	.044585

			T.E =	.236348
5371	5371			
111		17.300000 x	16.829739 =	291.154485
111		9.600000 x	16.829739 =	161.565494

			T.E =	452.719979
5372	5372			
379		2.000000 x	14.000000 =	28.000000
510		.100000 x	389.346461 =	38.934646
630		.100000 x	2.021024 =	.202102
113		.800000 x	24.769248 =	19.815398

			T.E =	86.952147
5380	5380			
111		5.000000 x	16.829739 =	84.148695
550		.412500 x	387.872461 =	159.997390

			T.E =	244.146085
5390	5390			
111		.120000 x	16.829739 =	2.019569
111		.030000 x	16.829739 =	.504892

			T.E =	2.524461

5510	5510				
361		15.000000 x	27.500000 =	412.500000	
363		20.000000 x	.580000 =	11.600000	
362		30.000000 x	5.250000 =	157.500000	
550		.375000 x	387.872461 =	145.452173	
113		20.000000 x	24.769248 =	495.384960	
365		2.000000 x	22.500000 =	45.000000	
111		20.000000 x	16.829739 =	336.594780	

			T.E =	1,604.031913	
5521	5521				
111		1.000000 x	16.829739 =	16.829739	
630.1		10.000000 x	2.336079 =	23.360790	
510		.125000 x	389.346461 =	48.668308	
630		10.000000 x	2.021024 =	20.210240	

			T.E =	109.069077	
5522	5522				
111		1.500000 x	16.829739 =	25.244609	

			T.E =	25.244609	
5530	5530				
453		.187500 x	86.390000 =	16.198125	
111		1.000000 x	16.829739 =	16.829739	
111		1.000000 x	16.829739 =	16.829739	

			T.E =	49.857603	
5540	5540				
363		15.000000 x	.580000 =	8.700000	
111		.750000 x	16.829739 =	12.622304	

			T.E =	21.322304	
5551	5551				
111		2.000000 x	16.829739 =	33.659478	
111		1.000000 x	16.829739 =	16.829739	

			T.E =	50.489217	
5552	5552				
379		1.000000 x	14.000000 =	14.000000	
630		.100000 x	2.021024 =	.202102	
510		.050000 x	389.346461 =	19.467323	
113		.400000 x	24.769248 =	9.907699	

			T.E =	43.577125	

5560A	5560A			
365		1.000000 x	22.500000 =	22.500000
113		.800000 x	24.769248 =	19.815398
630		.100000 x	2.021024 =	.202102
510		.100000 x	389.346461 =	38.934646

			T.E =	81.452147
5560B	5560B			
366		1.000000 x	20.630000 =	20.630000
510		.100000 x	389.346461 =	38.934646
630		.100000 x	2.021024 =	.202102
113		.800000 x	24.769248 =	19.815398

			T.E =	79.582147
5570	5570			
111		.100000 x	16.829739 =	1.682974
111		.030000 x	16.829739 =	.504892

			T.E =	2.187866
5580	5580			
111		.020000 x	16.829739 =	.336595
111		.030000 x	16.829739 =	.504892

			T.E =	.841487
5610	5610			
363		15.000000 x	.580000 =	8.700000
111		30.000000 x	16.829739 =	504.892170
550		.125000 x	387.872461 =	48.484058
367		20,000.000000 x	.118700 =	2,374.000000

			T.E =	2,936.076228
5621	5621			
111		1.000000 x	16.829739 =	16.829739
630		10.000000 x	2.021024 =	20.210240
630.1		10.000000 x	2.336079 =	23.360790
510		.125000 x	389.346461 =	48.668308

			T.E =	109.069077
5622	5622			
111		1.500000 x	16.829739 =	25.244609

			T.E =	25.244609

5630	5630			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	16.829739 =	12.622304

			T.E =	21.322304
5640	5640			
111		10.000000 x	16.829739 =	168.297390
111		2.000000 x	16.829739 =	33.659478

			T.E =	201.956868
5650	5650			
111		.120000 x	16.829739 =	2.019569
111		.030000 x	16.829739 =	.504892

			T.E =	2.524461
5710	5710			
362		40.000000 x	5.250000 =	210.000000
111		5.000000 x	16.829739 =	84.148695
112		1.000000 x	18.705943 =	18.705943
560		.125000 x	728.520461 =	91.065058
510		.125000 x	389.346461 =	48.668308
509		.125000 x	399.345461 =	49.918183
114		1.000000 x	23.989407 =	23.989407
380		800.000000 x	.260000 =	208.000000
363		15.000000 x	.580000 =	8.700000
377		250.000000 x	3.190000 =	797.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,594.695593
5720	5720			
111		.500000 x	16.829739 =	8.414870
510		.062500 x	389.346461 =	24.334154
630		10.000000 x	2.021024 =	20.210240
630.1		10.000000 x	2.336079 =	23.360790

			T.E =	76.320053
5730	5730			
363		15.000000 x	.580000 =	8.700000
111		.750000 x	16.829739 =	12.622304

			T.E =	21.322304