

ΑΤΕΠ

Αναλυτικά Τιμολόγια Έργων Πρασίνου

2ο Τρίμηνο του 2011

***** ΒΑΣΙΚΕΣ ΤΙΜΕΣ *****

021	2.670000
029	.151500
051	15.400000
111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
150	.074800
211	1.218700
212	1.421100
213	1.949500
214	4.160000
221	.099900
224	.070000
231	.861000
241	7.750000
242	5.000000
251	290.000000
252	290.000000
301	4.060000
302	6.700000
360	11.600000
361	29.800000
362	3.800000
363	.610000
364	3.710000
365	24.300000
366	22.400000
367	.128500
368	21.100000
369	12.830000
370	8.440000
371	7.600000
372	1.340000
373	2.150000
374	2.900000
375	1.580000
376	
377	3.450000
378	.540000
379	15.150000
380	.280000
401	268.420000
402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
417	134.530000

420	97.290000
428	437.840000
450	115.120000
451	159.550000
452	97.760000
453	90.720000
454	122.640000
455	432.990000

501	501				
211		50.000000 x	1.218700 =	60.935000	
214		3.000000 x	4.160000 =	12.480000	
401		1.000000 x	268.420000 =	268.420000	
118		3.000000 x	10.001019 =	30.003057	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	562.927593

				Η.Δ. =	619.220352
502	502				
211		80.000000 x	1.218700 =	97.496000	
114		8.000000 x	23.886192 =	191.089536	
402		1.000000 x	380.180000 =	380.180000	
214		7.000000 x	4.160000 =	29.120000	
118		4.000000 x	10.001019 =	40.004076	

				ΑΘΡΟΙΣΜΑ =	737.889612

				Η.Δ. =	811.678573
503	503				
211		110.000000 x	1.218700 =	134.057000	
428		1.000000 x	437.840000 =	437.840000	
214		10.000000 x	4.160000 =	41.600000	
118		4.000000 x	10.001019 =	40.004076	
114		8.000000 x	23.886192 =	191.089536	

				ΑΘΡΟΙΣΜΑ =	844.590612

				Η.Δ. =	929.049673
504	504				
211		40.000000 x	1.218700 =	48.748000	
214		2.000000 x	4.160000 =	8.320000	
114		8.000000 x	23.886192 =	191.089536	
403		1.000000 x	103.360000 =	103.360000	

				ΑΘΡΟΙΣΜΑ =	351.517536

				Η.Δ. =	386.669290
505	505				
211		200.000000 x	1.218700 =	243.740000	
214		10.000000 x	4.160000 =	41.600000	
114		8.000000 x	23.886192 =	191.089536	
118		8.000000 x	10.001019 =	80.008152	
404		1.000000 x	212.730000 =	212.730000	

				ΑΘΡΟΙΣΜΑ =	769.167688

				Η.Δ. =	846.084457

506	506				
211		95.000000 x	1.218700 =		115.776500
214		6.000000 x	4.160000 =		24.960000
405		1.000000 x	206.720000 =		206.720000
242		2.500000 x	5.000000 =		12.500000
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
				ΑΘΡΟΙΣΜΑ =	631.054188
				Η.Δ. =	694.159607
507	507				
211		165.000000 x	1.218700 =		201.085500
214		10.000000 x	4.160000 =		41.600000
242		7.000000 x	5.000000 =		35.000000
406		1.000000 x	320.980000 =		320.980000
114		8.000000 x	23.886192 =		191.089536
118		8.000000 x	10.001019 =		80.008152
				ΑΘΡΟΙΣΜΑ =	869.763188
				Η.Δ. =	956.739507
508	508				
211		40.000000 x	1.218700 =		48.748000
407		1.000000 x	55.210000 =		55.210000
115		4.000000 x	21.778427 =		87.113708
116		16.000000 x	20.419486 =		326.711776
408		2.000000 x	4.530000 =		9.060000
214		2.000000 x	4.160000 =		8.320000
				ΑΘΡΟΙΣΜΑ =	535.163484
				Η.Δ. =	588.679832
509	509				
211		80.000000 x	1.218700 =		97.496000
117		8.000000 x	16.777917 =		134.223336
409		1.000000 x	126.080000 =		126.080000
214		5.000000 x	4.160000 =		20.800000
				ΑΘΡΟΙΣΜΑ =	378.599336
				Η.Δ. =	416.459270
510	510				
211		80.000000 x	1.218700 =		97.496000
117		8.000000 x	16.777917 =		134.223336
214		5.000000 x	4.160000 =		20.800000
410		1.000000 x	116.530000 =		116.530000
				ΑΘΡΟΙΣΜΑ =	369.049336
				Η.Δ. =	405.954270

511	511				
212		17.000000 x	1.421100 =		24.158700
411		1.000000 x	27.370000 =		27.370000
214		1.000000 x	4.160000 =		4.160000
115		4.000000 x	21.778427 =		87.113708
112		30.000000 x	17.312112 =		519.363360

		ΑΘΡΟΙΣΜΑ =			662.165768

		Η.Δ. =			728.382345
512	512				
211		10.000000 x	1.218700 =		12.187000
115		2.000000 x	21.778427 =		43.556854
214		1.000000 x	4.160000 =		4.160000
112		2.000000 x	17.312112 =		34.624224
412		1.000000 x	2.990000 =		2.990000

		ΑΘΡΟΙΣΜΑ =			97.518078

		Η.Δ. =			107.269886
518	518				
211		180.000000 x	1.218700 =		219.366000
212		5.000000 x	1.421100 =		7.105500
118		8.000000 x	10.001019 =		80.008152
114		8.000000 x	23.886192 =		191.089536
112		8.000000 x	17.312112 =		138.496896
417		1.000000 x	134.530000 =		134.530000
214		12.000000 x	4.160000 =		49.920000

		ΑΘΡΟΙΣΜΑ =			820.516084

		Η.Δ. =			902.567692
521	521				
211		40.000000 x	1.218700 =		48.748000
118		4.000000 x	10.001019 =		40.004076
114		8.000000 x	23.886192 =		191.089536
214		3.000000 x	4.160000 =		12.480000
420		1.000000 x	97.290000 =		97.290000

		ΑΘΡΟΙΣΜΑ =			389.611612

		Η.Δ. =			428.572773
550	550				
211		80.000000 x	1.218700 =		97.496000
214		5.000000 x	4.160000 =		20.800000
117		8.000000 x	16.777917 =		134.223336
450		1.000000 x	115.120000 =		115.120000

		ΑΘΡΟΙΣΜΑ =			367.639336

		Η.Δ. =			404.403270

560	560				
211		80.000000 x	1.218700 =	97.496000	
117		8.000000 x	16.777917 =	134.223336	
455		1.000000 x	432.990000 =	432.990000	
214		7.000000 x	4.160000 =	29.120000	
			ΑΘΡΟΙΣΜΑ =	693.829336	
			Η.Δ. =	763.212270	
621	621				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	588.679832 =	2.943399	
116		.200000 x	20.419486 =	4.083897	
111		.800000 x	15.741598 =	12.593278	
			B.T =	19.815525	
623	623				
213		.100000 x	1.949500 =	.194950	
508		.005000 x	588.679832 =	2.943399	
504		.005000 x	386.669290 =	1.933346	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
518		.010000 x	902.567692 =	9.025677	
509		.005000 x	416.459270 =	2.082296	
			B.T =	21.994777	
625	625				
213		.100000 x	1.949500 =	.194950	
116		.200000 x	20.419486 =	4.083897	
112		.100000 x	17.312112 =	1.731211	
504		.005000 x	386.669290 =	1.933346	
509		.005000 x	416.459270 =	2.082296	
518		.014300 x	902.567692 =	12.906718	
508		.005000 x	588.679832 =	2.943399	
			B.T =	25.875818	
630	630				
512		.020000 x	107.269886 =	2.145398	
			B.T =	2.145398	
630.1	630.1				
510		.006000 x	405.954270 =	2.435726	
			B.T =	2.435726	

641	641			
231		.200000 x	.861000 =	.172200
251		.001500 x	290.000000 =	.435000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000

			B.T =	7.543443
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
509		.003600 x	416.459270 =	1.499253
509		.011100 x	416.459270 =	4.622698
511		.050000 x	728.382345 =	36.419117
630		.600000 x	2.145398 =	1.287239
625		1.000000 x	25.875818 =	25.875818
224		120.000000 x	.070000 =	8.400000

			B.T =	125.357578
652	652			
221		650.000000 x	.099900 =	64.935000
509		.011000 x	416.459270 =	4.581052
630		.320000 x	2.145398 =	.686527
625		1.000000 x	25.875818 =	25.875818
511		.050000 x	728.382345 =	36.419117
509		.001920 x	416.459270 =	.799602
112		.500000 x	17.312112 =	8.656056
111		1.500000 x	15.741598 =	23.612397

			B.T =	165.565569
1121	1121			
112		.007000 x	17.312112 =	.121185
501		.000100 x	619.220352 =	.061922
503		.002000 x	929.049673 =	1.858099

			T.E =	2.041206
1122	1122			
112		.007000 x	17.312112 =	.121185
503		.000330 x	929.049673 =	.306586
501		.000080 x	619.220352 =	.049538
505		.000600 x	846.084457 =	.507651
507		.001400 x	956.739507 =	1.339435
509		.004447 x	416.459270 =	1.851994

			T.E =	4.176389

1123A	1123A			
112		.007000 x	17.312112 =	.121185
501		.000100 x	619.220352 =	.061922
503		.002000 x	929.049673 =	1.858099
509		.005312 x	416.459270 =	2.212232
506		.001330 x	694.159607 =	.923232

			T.E =	5.176670
1123B	1123B			
509		.001487 x	416.459270 =	.619275

			T.E =	.619275
1140	1140			
112		.010000 x	17.312112 =	.173121
521		.000200 x	428.572773 =	.085715
501		.000100 x	619.220352 =	.061922

			T.E =	.320758
1610	1610			
111		.050000 x	15.741598 =	.787080
1122		.200000 x	4.176389 =	.835278
507		.000200 x	956.739507 =	.191348
501		.000100 x	619.220352 =	.061922
502		.000200 x	811.678573 =	.162336

			T.E =	2.037963
1620	1620			
112		.250000 x	17.312112 =	4.328028
1122		1.000000 x	4.176389 =	4.176389
501		.002000 x	619.220352 =	1.238441

			T.E =	9.742858
1710	1710			
360		1.000000 x	11.600000 =	11.600000
111		.250000 x	15.741598 =	3.935400
501		.000100 x	619.220352 =	.061922

			T.E =	15.597322
2111	2111			
112		.010000 x	17.312112 =	.173121
509		.005202 x	416.459270 =	2.166421
507		.001540 x	956.739507 =	1.473379
502		.002000 x	811.678573 =	1.623357
501		.000830 x	619.220352 =	.513953

			T.E =	5.950231

2112	2112			
213		.400000 x	1.949500 =	.779800
502		.002900 x	811.678573 =	2.353868
112		.250000 x	17.312112 =	4.328028
116		.250000 x	20.419486 =	5.104872
507		.002000 x	956.739507 =	1.913479
509		.004896 x	416.459270 =	2.038985
508		.004000 x	588.679832 =	2.354719

			T.E =	18.873750
2251	2251			
111		.600000 x	15.741598 =	9.444959
621		1.050000 x	19.815525 =	20.806301
112		.600000 x	17.312112 =	10.387267
509		.012432 x	416.459270 =	5.177422

			T.E =	45.815949
2252	2252			
111		1.400000 x	15.741598 =	22.038237
621		1.050000 x	19.815525 =	20.806301
113		1.400000 x	20.419486 =	28.587280
509		.012432 x	416.459270 =	5.177422

			T.E =	76.609240
2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	19.815525 =	20.806301
652		.020000 x	165.565569 =	3.311311
651		.250000 x	125.357578 =	31.339395
509		.012432 x	416.459270 =	5.177422
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422

			T.E =	138.757963
2254	2254			
111		.800000 x	15.741598 =	12.593278
652		.100000 x	165.565569 =	16.556557
621		.350000 x	19.815525 =	6.935434
509		.003788 x	416.459270 =	1.577548
113		1.500000 x	20.419486 =	30.629229

			T.E =	68.292046

2522	2522			
221		300.000000 x	.099900 =	29.970000
112		1.400000 x	17.312112 =	24.236957
623		.800000 x	21.994777 =	17.595822
630		.250000 x	2.145398 =	.536350
641		3.000000 x	7.543443 =	22.630329
625		.500000 x	25.875818 =	12.937909
511		.040000 x	728.382345 =	29.135294
509		.008880 x	416.459270 =	3.698158
509		.001500 x	416.459270 =	.624689
509		.005550 x	416.459270 =	2.311349
113		1.600000 x	20.419486 =	32.671178

			T.E =	176.348033
2921	2921			
301		1.000000 x	4.060000 =	4.060000
2522		.005000 x	176.348033 =	.881740
652		.002000 x	165.565569 =	.331131
113		.400000 x	20.419486 =	8.167794
111		.400000 x	15.741598 =	6.296639

			T.E =	19.737305
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.012000 x	165.565569 =	1.986787
111		.600000 x	15.741598 =	9.444959
113		.800000 x	20.419486 =	16.335589

			T.E =	34.601334
5110	5110			
111		.100000 x	15.741598 =	1.574160

			T.E =	1.574160
5120	5120			
111		.080000 x	15.741598 =	1.259328

			T.E =	1.259328
5130	5130			
111		.050000 x	15.741598 =	.787080

			T.E =	.787080
5140	5140			
111		.030000 x	15.741598 =	.472248
550		.003750 x	404.403270 =	1.516512

			T.E =	1.988760

ΑΤΕΠ	2ο Τρίμηνο του 2011	Σελ.	12
		Ημ/νία	22/12/2011
5150	5150		
111		.030000 x	15.741598 =
550		.002500 x	404.403270 =

		T.E =	1.483256
5160	5160		
213		.400000 x	1.949500 =
111		.160000 x	15.741598 =
508		.001500 x	588.679832 =

		T.E =	4.181475
5210	5210		
363		.100000 x	.610000 =
112		.050000 x	17.312112 =
111		.040000 x	15.741598 =

		T.E =	1.556270
5220	5220		
363		.100000 x	.610000 =
112		.030000 x	17.312112 =
111		.020000 x	15.741598 =

		T.E =	.895195
5230	5230		
364		1.000000 x	3.710000 =
112		.080000 x	17.312112 =

		T.E =	5.094969
5240	5240		
112		.080000 x	17.312112 =

		T.E =	1.384969
5311	5311		
111		.002000 x	15.741598 =
630.1		.020000 x	2.435726 =
510		.000250 x	405.954270 =
630		.020000 x	2.145398 =

		T.E =	.224594

5312	5312			
111		.001300 x	15.741598 =	.020464
630.1		.020000 x	2.435726 =	.048715
510		.000163 x	405.954270 =	.066171
630		.020000 x	2.145398 =	.042908

			T.E =	.178257
5321	5321			
111		.004000 x	15.741598 =	.062966

			T.E =	.062966
5322	5322			
111		.003300 x	15.741598 =	.051947

			T.E =	.051947
5330	5330			
111		.022200 x	15.741598 =	.349463

			T.E =	.349463
5340	5340			
363		.100000 x	.610000 =	.061000
111		.003300 x	15.741598 =	.051947

			T.E =	.112947
5351	5351			
113		.005000 x	20.419486 =	.102097

			T.E =	.102097
5352	5352			
111		.005000 x	15.741598 =	.078708
113		.014000 x	20.419486 =	.285873

			T.E =	.364581
5353	5353			
111		.010000 x	15.741598 =	.157416
113		.020000 x	20.419486 =	.408390

			T.E =	.565806

5354	5354				
111		.035000 x	15.741598 =		.550956
113		.025000 x	20.419486 =		.510487

			T.E =		1.061443
5361A	5361A				
365		.003000 x	24.300000 =		.072900
630		.000300 x	2.145398 =		.000644
510		.000188 x	405.954270 =		.076319
113		.001500 x	20.419486 =		.030629

			T.E =		.180492
5361B	5361B				
366		.003000 x	22.400000 =		.067200
510		.000188 x	405.954270 =		.076319
630		.000300 x	2.145398 =		.000644
113		.001500 x	20.419486 =		.030629

			T.E =		.174792
5362A	5362A				
365		.005000 x	24.300000 =		.121500
630		.000500 x	2.145398 =		.001073
510		.000313 x	405.954270 =		.127064
113		.002500 x	20.419486 =		.051049

			T.E =		.300685
5362B	5362B				
366		.005000 x	22.400000 =		.112000
630		.000500 x	2.145398 =		.001073
510		.000313 x	405.954270 =		.127064
113		.002500 x	20.419486 =		.051049

			T.E =		.291185
5363A	5363A				
365		.003000 x	24.300000 =		.072900
113		.001000 x	20.419486 =		.020419
510		.000125 x	405.954270 =		.050744
630		.000300 x	2.145398 =		.000644

			T.E =		.144707

5363B	5363B			
366		.003000 x	22.400000 =	.067200
113		.001000 x	20.419486 =	.020419
630		.000300 x	2.145398 =	.000644
510		.000125 x	405.954270 =	.050744

			T.E =	.139007
5364A	5364A			
365		.005000 x	24.300000 =	.121500
113		.001800 x	20.419486 =	.036755
630		.000500 x	2.145398 =	.001073
510		.000225 x	405.954270 =	.091340

			T.E =	.250667
5364B	5364B			
366		.005000 x	22.400000 =	.112000
630		.000500 x	2.145398 =	.001073
510		.000225 x	405.954270 =	.091340
113		.001800 x	20.419486 =	.036755

			T.E =	.241167
5371	5371			
111		17.300000 x	15.741598 =	272.329645
111		9.600000 x	15.741598 =	151.119341

			T.E =	423.448986
5372	5372			
379		2.000000 x	15.150000 =	30.300000
510		.100000 x	405.954270 =	40.595427
630		.100000 x	2.145398 =	.214540
113		.800000 x	20.419486 =	16.335589

			T.E =	87.445556
5380	5380			
111		5.000000 x	15.741598 =	78.707990
550		.412500 x	404.403270 =	166.816349

			T.E =	245.524339
5390	5390			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240

5510	5510				
361		15.000000 x	29.800000 =	447.000000	
363		20.000000 x	.610000 =	12.200000	
362		30.000000 x	3.800000 =	114.000000	
550		.375000 x	404.403270 =	151.651226	
113		20.000000 x	20.419486 =	408.389720	
365		2.000000 x	24.300000 =	48.600000	
111		20.000000 x	15.741598 =	314.831960	

			T.E =	1,496.672906	
5521	5521				
111		1.000000 x	15.741598 =	15.741598	
630.1		10.000000 x	2.435726 =	24.357260	
510		.125000 x	405.954270 =	50.744284	
630		10.000000 x	2.145398 =	21.453980	

			T.E =	112.297122	
5522	5522				
111		1.500000 x	15.741598 =	23.612397	

			T.E =	23.612397	
5530	5530				
453		.187500 x	90.720000 =	17.010000	
111		1.000000 x	15.741598 =	15.741598	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	48.493196	
5540	5540				
363		15.000000 x	.610000 =	9.150000	
111		.750000 x	15.741598 =	11.806199	

			T.E =	20.956199	
5551	5551				
111		2.000000 x	15.741598 =	31.483196	
111		1.000000 x	15.741598 =	15.741598	

			T.E =	47.224794	
5552	5552				
379		1.000000 x	15.150000 =	15.150000	
630		.100000 x	2.145398 =	.214540	
510		.050000 x	405.954270 =	20.297714	
113		.400000 x	20.419486 =	8.167794	

			T.E =	43.830048	

5560A	5560A			
365		1.000000 x	24.300000 =	24.300000
113		.800000 x	20.419486 =	16.335589
630		.100000 x	2.145398 =	.214540
510		.100000 x	405.954270 =	40.595427
			T.E =	81.445556
5560B	5560B			
366		1.000000 x	22.400000 =	22.400000
510		.100000 x	405.954270 =	40.595427
630		.100000 x	2.145398 =	.214540
113		.800000 x	20.419486 =	16.335589
			T.E =	79.545556
5570	5570			
111		.100000 x	15.741598 =	1.574160
111		.030000 x	15.741598 =	.472248
			T.E =	2.046408
5580	5580			
111		.020000 x	15.741598 =	.314832
111		.030000 x	15.741598 =	.472248
			T.E =	.787080
5610	5610			
363		15.000000 x	.610000 =	9.150000
111		30.000000 x	15.741598 =	472.247940
550		.125000 x	404.403270 =	50.550409
367		20,000.000000 x	.128500 =	2,570.000000
			T.E =	3,101.948349
5621	5621			
111		1.000000 x	15.741598 =	15.741598
630		10.000000 x	2.145398 =	21.453980
630.1		10.000000 x	2.435726 =	24.357260
510		.125000 x	405.954270 =	50.744284
			T.E =	112.297122
5622	5622			
111		1.500000 x	15.741598 =	23.612397
			T.E =	23.612397

5630	5630			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199
5640	5640			
111		10.000000 x	15.741598 =	157.415980
111		2.000000 x	15.741598 =	31.483196

			T.E =	188.899176
5650	5650			
111		.120000 x	15.741598 =	1.888992
111		.030000 x	15.741598 =	.472248

			T.E =	2.361240
5710	5710			
362		40.000000 x	3.800000 =	152.000000
111		5.000000 x	15.741598 =	78.707990
112		1.000000 x	17.312112 =	17.312112
560		.125000 x	763.212270 =	95.401534
510		.125000 x	405.954270 =	50.744284
509		.125000 x	416.459270 =	52.057409
114		1.000000 x	23.886192 =	23.886192
380		800.000000 x	.280000 =	224.000000
363		15.000000 x	.610000 =	9.150000
377		250.000000 x	3.450000 =	862.500000
378		100.000000 x	.540000 =	54.000000

			T.E =	1,619.759520
5720	5720			
111		.500000 x	15.741598 =	7.870799
510		.062500 x	405.954270 =	25.372142
630		10.000000 x	2.145398 =	21.453980
630.1		10.000000 x	2.435726 =	24.357260

			T.E =	79.054181
5730	5730			
363		15.000000 x	.610000 =	9.150000
111		.750000 x	15.741598 =	11.806199

			T.E =	20.956199