

ΑΤΕΟ (ΝΕΟ)

Αναλυτικά Τιμολόγια Έργων

4ο Τρίμηνο του 2011

\*\*\*\*\* ΒΑΣΙΚΕΣ ΤΙΜΕΣ \*\*\*\*\*

111	15.741598
112	17.312112
113	20.419486
114	23.886192
115	21.778427
116	20.419486
117	16.777917
118	10.001019
211	1.186900
212	1.419500
213	1.949500
214	4.160000
215	1.034500
221	.099900
222	.116200
223	.119300
224	.070000
231	.895000
232	2.184000
233	.545500
234	.941500
235	.703000
236	.673000
237	1.218000
238	.545500
239	8.200000
241	7.750000
242	4.500000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	4.060000
302	6.700000
321	.539400
322	
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	765.000000
352	1,035.000000
353	3.630000
354	4.020000
355	.121800
401	268.420000

402	380.180000
403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
418	44.890000
419	4.530000
420	97.290000
421	32.560000
422	38.010000
423	12.540000
424	41.920000
425	165.330000
426	1,234.850000
427	185.840000
428	437.840000
429	77.590000
501.1M	287.610000
501.2M	322.830000
501.3M	281.740000
501.4M	199.570000
502.1M	326.260000
502.2M	478.520000
502.3M	677.380000
502.4M	901.110000
502.5M	1,590.920000
502.6M	664.960000
504.1M	297.020000
504.2M	436.790000
504.3M	220.140000
504.4M	269.060000
505.1M	639.700000
505.2M	762.190000
506.10M	383.030000
506.1M	123.390000
506.2M	134.110000
506.3M	174.620000
506.4M	199.400000
506.5M	177.030000
506.6M	209.220000
506.7M	413.070000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	31.740000
508.4M	42.730000
509.1M	92.080000

509.2M	92.080000
509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	382.650000
515.5M	483.350000
515.6M	538.730000
515.7M	619.290000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	324.160000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	73.160000
521.2M	73.160000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000

528.1M  
528.2M  
528.3M  
528.4M  
529.1M

312.250000  
349.720000  
349.720000  
374.700000  
112.410000

501	501				
501.1		.100000 x	580.274025 =	58.027403	
501.4		.150000 x	533.876891 =	80.081534	
501.2		.600000 x	700.348046 =	420.208828	
501.3		.150000 x	575.578025 =	86.336704	
			H.Δ. =	644.654468	
501.1	501.1				
211		146.190706 x	1.186900 =	173.513749	
114		6.670000 x	23.886192 =	159.320901	
501.1M		.800000 x	287.610000 =	230.088000	
211		14.619071 x	1.186900 =	17.351375	
			H.Δ. =	580.274025	
501.2	501.2				
211		216.578823 x	1.186900 =	257.057405	
211		21.657882 x	1.186900 =	25.705740	
501.2M		.800000 x	322.830000 =	258.264000	
114		6.670000 x	23.886192 =	159.320901	
			H.Δ. =	700.348046	
501.3	501.3				
211		14.619071 x	1.186900 =	17.351375	
211		146.190706 x	1.186900 =	173.513749	
114		6.670000 x	23.886192 =	159.320901	
501.3M		.800000 x	281.740000 =	225.392000	
			H.Δ. =	575.578025	
501.4	501.4				
211		164.599905 x	1.186900 =	195.363627	
211		16.459991 x	1.186900 =	19.536363	
114		6.670000 x	23.886192 =	159.320901	
501.4M		.800000 x	199.570000 =	159.656000	
			H.Δ. =	533.876891	
502	502				
502.1		.200000 x	758.439478 =	151.687896	
502.3		.400000 x	1,262.011457 =	504.804583	
502.2		.400000 x	942.101916 =	376.840766	
			H.Δ. =	1,033.333245	

502.1	502.1			
211		24.365118 x	1.186900 =	28.918959
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.1M		.800000 x	326.260000 =	261.008000
211		243.651176 x	1.186900 =	289.189581
		-----		
			H.Δ. =	758.439478
502.2	502.2			
211		291.027794 x	1.186900 =	345.420889
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
211		29.102779 x	1.186900 =	34.542088
502.2M		.800000 x	478.520000 =	382.816000
		-----		
			H.Δ. =	942.101916
502.3	502.3			
211		414.207001 x	1.186900 =	491.622289
502.3M		.800000 x	677.380000 =	541.904000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
211		41.420700 x	1.186900 =	49.162229
		-----		
			H.Δ. =	1,262.011457
503	503			
502.3		.150000 x	1,262.011457 =	189.301719
503.6		.100000 x	1,294.489930 =	129.448993
503.5		.350000 x	2,371.039168 =	829.863709
503.4		.400000 x	1,554.100713 =	621.640285
		-----		
			H.Δ. =	1,770.254706
503.4	503.4			
211		50.083853 x	1.186900 =	59.444525
211		500.838528 x	1.186900 =	594.445249
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
502.4M		.800000 x	901.110000 =	720.888000
		-----		
			H.Δ. =	1,554.100713
503.5	503.5			
211		703.881180 x	1.186900 =	835.436573
211		70.388118 x	1.186900 =	83.543657
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.5M		.800000 x	1,590.920000 =	1,272.736000
		-----		
			H.Δ. =	2,371.039168

503.6	503.6			
211		446.693825 x	1.186900 =	530.180901
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
502.6M		.800000 x	664.960000 =	531.968000
211		44.669383 x	1.186900 =	53.018091
-----				
			H.Δ. =	1,294.489930
504	504			
504.1		.350000 x	729.183598 =	255.214259
504.2		.450000 x	925.828542 =	416.622844
504.4		.100000 x	684.194546 =	68.419455
504.3		.100000 x	667.679598 =	66.767960
-----				
			H.Δ. =	807.024518
504.1	504.1			
211		254.480118 x	1.186900 =	302.042452
114		6.670000 x	23.886192 =	159.320901
211		25.448012 x	1.186900 =	30.204245
504.1M		.800000 x	297.020000 =	237.616000
-----				
			H.Δ. =	729.183598
504.2	504.2			
211		319.453766 x	1.186900 =	379.159675
114		6.670000 x	23.886192 =	159.320901
211		31.945376 x	1.186900 =	37.915967
504.2M		.800000 x	436.790000 =	349.432000
-----				
			H.Δ. =	925.828542
504.3	504.3			
211		25.448012 x	1.186900 =	30.204245
114		6.670000 x	23.886192 =	159.320901
504.3M		.800000 x	220.140000 =	176.112000
211		254.480118 x	1.186900 =	302.042452
-----				
			H.Δ. =	667.679598
504.4	504.4			
211		237.153812 x	1.186900 =	281.477859
211		23.715381 x	1.186900 =	28.147786
114		6.670000 x	23.886192 =	159.320901
504.4M		.800000 x	269.060000 =	215.248000
-----				
			H.Δ. =	684.194546



505	505			
505.1		.500000 x	1,177.644171 =	588.822086
505.2		.500000 x	1,275.636171 =	637.818086
-----				
			H.Δ. =	1,226.640171
505.1	505.1			
211		35.735506 x	1.186900 =	42.414472
211		357.355061 x	1.186900 =	424.144722
118		4.000000 x	10.001019 =	40.004076
114		6.670000 x	23.886192 =	159.320901
505.1M		.800000 x	639.700000 =	511.760000
-----				
			H.Δ. =	1,177.644171
505.2	505.2			
211		35.735506 x	1.186900 =	42.414472
114		6.670000 x	23.886192 =	159.320901
118		4.000000 x	10.001019 =	40.004076
211		357.355061 x	1.186900 =	424.144722
505.2M		.800000 x	762.190000 =	609.752000
-----				
			H.Δ. =	1,275.636171
506	506			
506.1		.100000 x	417.413606 =	41.741361
506.2		.200000 x	461.217180 =	92.243436
506.3		.350000 x	472.182309 =	165.263808
506.4		.350000 x	525.702251 =	183.995788
-----				
			H.Δ. =	483.244393
506.1	506.1			
211		10.675531 x	1.186900 =	12.670788
118		2.000000 x	10.001019 =	20.002038
211		106.755312 x	1.186900 =	126.707880
114		6.670000 x	23.886192 =	159.320901
506.1M		.800000 x	123.390000 =	98.712000
-----				
			H.Δ. =	417.413606
506.2	506.2			
211		13.373742 x	1.186900 =	15.873294
211		133.737423 x	1.186900 =	158.732947
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.2M		.800000 x	134.110000 =	107.288000
-----				
			H.Δ. =	461.217180

506.3	506.3			
211		117.313529 x	1.186900 =	139.239428
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.3M		.800000 x	174.620000 =	139.696000
211		11.731353 x	1.186900 =	13.923943
-----				
			H.Δ. =	472.182309
506.4	506.4			
211		14.312251 x	1.186900 =	16.987211
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.4M		.800000 x	199.400000 =	159.520000
211		143.122505 x	1.186900 =	169.872101
-----				
			H.Δ. =	525.702251
507	507			
507.5		.100000 x	566.008332 =	56.600833
507.6		.100000 x	691.316523 =	69.131652
507.7		.100000 x	869.712860 =	86.971286
507.8		.100000 x	627.251232 =	62.725123
507.10		.250000 x	922.262546 =	230.565637
507.9		.350000 x	729.704214 =	255.396475
-----				
			H.Δ. =	761.391006
507.10	507.10			
211		334.343559 x	1.186900 =	396.832370
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.10M		.800000 x	383.030000 =	306.424000
211		33.434356 x	1.186900 =	39.683237
-----				
			H.Δ. =	922.262546
507.5	507.5			
211		187.701647 x	1.186900 =	222.783085
211		18.770165 x	1.186900 =	22.278309
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.5M		.800000 x	177.030000 =	141.624000
-----				
			H.Δ. =	566.008332

507.6	507.6			
211		263.955441 x	1.186900 =	313.288713
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.6M		.800000 x	209.220000 =	167.376000
211		26.395544 x	1.186900 =	31.328871
-----				
			H.Δ. =	691.316523
507.7	507.7			
211		27.568679 x	1.186900 =	32.721265
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
506.7M		.800000 x	413.070000 =	330.456000
211		275.686794 x	1.186900 =	327.212656
-----				
			H.Δ. =	869.712860
507.8	507.8			
211		191.221052 x	1.186900 =	226.960267
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.8M		.800000 x	247.840000 =	198.272000
211		19.122105 x	1.186900 =	22.696026
-----				
			H.Δ. =	627.251232
507.9	507.9			
211		23.931960 x	1.186900 =	28.404843
211		239.319599 x	1.186900 =	284.048432
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.886192 =	159.320901
506.9M		.800000 x	297.410000 =	237.928000
-----				
			H.Δ. =	729.704214
508	508			
508.1		.250000 x	367.360007 =	91.840002
508.2		.250000 x	416.237018 =	104.059255
508.3		.250000 x	424.053018 =	106.013255
508.4		.250000 x	465.009326 =	116.252332
-----				
			H.Δ. =	418.164842
508.1	508.1			
211		28.155247 x	1.186900 =	33.417463
115		2.000000 x	21.778427 =	43.556854
116		13.340000 x	20.419486 =	272.395943
508.1M		.800000 x	18.310000 =	14.648000
211		2.815525 x	1.186900 =	3.341747
-----				
			H.Δ. =	367.360007

508.2	508.2			
211		6.334931 x	1.186900 =	7.518930
115		2.000000 x	21.778427 =	43.556854
116		13.340000 x	20.419486 =	272.395943
508.2M		.800000 x	21.970000 =	17.576000
211		63.349306 x	1.186900 =	75.189291
-----				
			H.Δ. =	416.237018
508.3	508.3			
211		63.349306 x	1.186900 =	75.189291
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
508.3M		.800000 x	31.740000 =	25.392000
211		6.334931 x	1.186900 =	7.518930
-----				
			H.Δ. =	424.053018
508.4	508.4			
211		87.985147 x	1.186900 =	104.429571
211		8.798515 x	1.186900 =	10.442957
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
508.4M		.800000 x	42.730000 =	34.184000
-----				
			H.Δ. =	465.009326
509	509			
509.1		.100000 x	556.699335 =	55.669934
509.2		.200000 x	503.681246 =	100.736249
509.4		.500000 x	594.774191 =	297.387096
509.3		.200000 x	618.339236 =	123.667847
-----				
			H.Δ. =	577.461125
509.1	509.1			
211		284.259705 x	1.186900 =	337.387844
509.1M		.800000 x	92.080000 =	73.664000
117		6.670000 x	16.777917 =	111.908706
211		28.425971 x	1.186900 =	33.738785
-----				
			H.Δ. =	556.699335
509.2	509.2			
211		243.651176 x	1.186900 =	289.189581
509.2M		.800000 x	92.080000 =	73.664000
117		6.670000 x	16.777917 =	111.908706
211		24.365118 x	1.186900 =	28.918959
-----				
			H.Δ. =	503.681246

509.3	509.3			
211		32.892909 x	1.186900 =	39.040594
117		6.670000 x	16.777917 =	111.908706
509.3M		.800000 x	96.230000 =	76.984000
211		328.929089 x	1.186900 =	390.405936
-----				
			H.Δ. =	618.339236
509.4	509.4			
211		308.624825 x	1.186900 =	366.306805
211		30.862482 x	1.186900 =	36.630680
117		6.670000 x	16.777917 =	111.908706
509.4M		.800000 x	99.910000 =	79.928000
-----				
			H.Δ. =	594.774191
511	511			
511.1		.150000 x	391.629671 =	58.744451
511.4		.225000 x	394.994471 =	88.873756
511.2		.150000 x	390.074473 =	58.511171
511.3		.225000 x	394.605671 =	88.786276
511.5		.125000 x	396.586471 =	49.573309
511.6		.125000 x	395.205671 =	49.400709
-----				
			H.Δ. =	393.889671
511.1	511.1			
211		.496326 x	1.186900 =	.589089
511.1M		.800000 x	11.180000 =	8.944000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
211		4.963265 x	1.186900 =	5.890899
-----				
			H.Δ. =	391.629671
511.2	511.2			
211		.377208 x	1.186900 =	.447708
112		13.340000 x	17.312112 =	230.943574
115		6.670000 x	21.778427 =	145.262108
511.2M		.800000 x	11.180000 =	8.944000
211		3.772081 x	1.186900 =	4.477083
-----				
			H.Δ. =	390.074473
511.3	511.3			
211		4.963265 x	1.186900 =	5.890899
115		6.670000 x	21.778427 =	145.262108
511.3M		.800000 x	14.900000 =	11.920000
112		13.340000 x	17.312112 =	230.943574
211		.496326 x	1.186900 =	.589089
-----				
			H.Δ. =	394.605671

511.4	511.4			
211		5.261061 x	1.186900 =	6.244353
211		.526106 x	1.186900 =	.624435
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
511.4M		.800000 x	14.900000 =	11.920000
		-----		
			H.Δ. =	394.994471
511.5	511.5			
211		5.261061 x	1.186900 =	6.244353
211		.526106 x	1.186900 =	.624435
112		13.340000 x	17.312112 =	230.943574
115		6.670000 x	21.778427 =	145.262108
511.5M		.800000 x	16.890000 =	13.512000
		-----		
			H.Δ. =	396.586471
511.6	511.6			
211		4.963265 x	1.186900 =	5.890899
511.6M		.800000 x	15.650000 =	12.520000
115		6.670000 x	21.778427 =	145.262108
112		13.340000 x	17.312112 =	230.943574
211		.496326 x	1.186900 =	.589089
		-----		
			H.Δ. =	395.205671
512	512			
512.1		.200000 x	105.850447 =	21.170089
512.3		.200000 x	113.279525 =	22.655905
512.4		.200000 x	156.104812 =	31.220962
512.5		.200000 x	158.461172 =	31.692234
512.2		.200000 x	109.744986 =	21.948997
		-----		
			H.Δ. =	128.688188
512.1	512.1			
211		1.804824 x	1.186900 =	2.142146
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
211		.180482 x	1.186900 =	.214214
512.1M		.800000 x	1.530000 =	1.224000
		-----		
			H.Δ. =	105.850447

512.2	512.2			
211		4.512059 x	1.186900 =	5.355363
211		.451206 x	1.186900 =	.535536
112		3.000000 x	17.312112 =	51.936336
117		3.000000 x	16.777917 =	50.333751
512.2M		.800000 x	1.980000 =	1.584000
		-----		
			H.Δ. =	109.744986
512.3	512.3			
211		.721929 x	1.186900 =	.856858
211		7.219294 x	1.186900 =	8.568580
117		3.000000 x	16.777917 =	50.333751
112		3.000000 x	17.312112 =	51.936336
512.3M		.800000 x	1.980000 =	1.584000
		-----		
			H.Δ. =	113.279525
512.4	512.4			
211		1.353618 x	1.186900 =	1.606609
211		13.536176 x	1.186900 =	16.066087
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
512.4M		.800000 x	2.590000 =	2.072000
		-----		
			H.Δ. =	156.104812
512.5	512.5			
211		15.341000 x	1.186900 =	18.208233
512.5M		.800000 x	2.590000 =	2.072000
117		4.000000 x	16.777917 =	67.111668
112		4.000000 x	17.312112 =	69.248448
211		1.534100 x	1.186900 =	1.820823
		-----		
			H.Δ. =	158.461172
512A	512A			
512.1		.333333 x	105.850447 =	35.283447
512.2		.333333 x	109.744986 =	36.581625
512.3		.333333 x	113.279525 =	37.759804
		-----		
			H.Δ. =	109.624876
512B	512B			
512.4		.500000 x	156.104812 =	78.052406
512.5		.500000 x	158.461172 =	79.230586
		-----		
			H.Δ. =	157.282992

513	513				
513.6		.250000 x	209.331538 =	52.332885	
513.7		.250000 x	221.113335 =	55.278334	
513.8		.250000 x	261.973908 =	65.493477	
513.9		.250000 x	275.101168 =	68.775292	
			H.Δ. =	241.879987	
513.6	513.6				
211		2.707235 x	1.186900 =	3.213217	
211		27.072353 x	1.186900 =	32.132176	
512.6M		.800000 x	4.420000 =	3.536000	
117		5.000000 x	16.777917 =	83.889585	
112		5.000000 x	17.312112 =	86.560560	
			H.Δ. =	209.331538	
513.7	513.7				
211		3.609647 x	1.186900 =	4.284290	
512.7M		.800000 x	4.420000 =	3.536000	
211		36.096470 x	1.186900 =	42.842900	
112		5.000000 x	17.312112 =	86.560560	
117		5.000000 x	16.777917 =	83.889585	
			H.Δ. =	221.113335	
513.8	513.8				
211		1.714582 x	1.186900 =	2.035037	
512.8M		.800000 x	15.260000 =	12.208000	
211		17.145823 x	1.186900 =	20.350377	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
			H.Δ. =	261.973908	
513.9	513.9				
211		23.462706 x	1.186900 =	27.847886	
211		2.346271 x	1.186900 =	2.784789	
117		6.670000 x	16.777917 =	111.908706	
112		6.670000 x	17.312112 =	115.471787	
512.9M		.800000 x	21.360000 =	17.088000	
			H.Δ. =	275.101168	
513A	513A				
513.6		.500000 x	209.331538 =	104.665769	
513.7		.500000 x	221.113335 =	110.556668	
			H.Δ. =	215.222437	





514.5	514.5			
211		18.048235 x	1.186900 =	21.421450
114		13.340000 x	23.886192 =	318.641801
514.5M		.800000 x	395.930000 =	316.744000
211		180.482353 x	1.186900 =	214.214505
		-----		
			H.Δ. =	871.021756
515	515			
515.1		.200000 x	377.669808 =	75.533962
515.2		.200000 x	461.822474 =	92.364495
515.4		.200000 x	677.513261 =	135.502652
515.5		.200000 x	800.487731 =	160.097546
515.3		.200000 x	612.122718 =	122.424544
		-----		
			H.Δ. =	585.923198
515.1	515.1			
211		8.085609 x	1.186900 =	9.596809
114		6.670000 x	23.886192 =	159.320901
211		80.856094 x	1.186900 =	95.968098
515.1M		.800000 x	140.980000 =	112.784000
		-----		
			H.Δ. =	377.669808
515.2	515.2			
211		10.828941 x	1.186900 =	12.852870
114		6.670000 x	23.886192 =	159.320901
211		108.289412 x	1.186900 =	128.528703
515.2M		.800000 x	201.400000 =	161.120000
		-----		
			H.Δ. =	461.822474
515.3	515.3			
211		16.171219 x	1.186900 =	19.193620
211		161.712189 x	1.186900 =	191.936197
114		6.670000 x	23.886192 =	159.320901
515.3M		.800000 x	302.090000 =	241.672000
		-----		
			H.Δ. =	612.122718
515.4	515.4			
211		16.243412 x	1.186900 =	19.279306
211		162.434118 x	1.186900 =	192.793055
515.4M		.800000 x	382.650000 =	306.120000
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	677.513261

515.5	515.5			
211		194.920940 x	1.186900 =	231.351664
211		19.492094 x	1.186900 =	23.135166
515.5M		.800000 x	483.350000 =	386.680000
114		6.670000 x	23.886192 =	159.320901
		-----		
			H.Δ. =	800.487731
516	516			
515.5		.150000 x	800.487731 =	120.073160
516.8		.350000 x	937.161028 =	328.006360
516.7		.350000 x	1,008.206834 =	352.872392
516.6		.150000 x	863.642609 =	129.546391
		-----		
			H.Δ. =	930.498303
516.6	516.6			
211		209.359530 x	1.186900 =	248.488826
211		20.935953 x	1.186900 =	24.848883
114		6.670000 x	23.886192 =	159.320901
515.6M		.800000 x	538.730000 =	430.984000
		-----		
			H.Δ. =	863.642609
516.7	516.7			
211		27.072353 x	1.186900 =	32.132176
114		6.670000 x	23.886192 =	159.320901
515.7M		.800000 x	619.290000 =	495.432000
211		270.723530 x	1.186900 =	321.321758
		-----		
			H.Δ. =	1,008.206834
516.8	516.8			
211		265.670025 x	1.186900 =	315.323753
515.8M		.800000 x	538.730000 =	430.984000
114		6.670000 x	23.886192 =	159.320901
211		26.567002 x	1.186900 =	31.532375
		-----		
			H.Δ. =	937.161028
517	517			
517.1		.100000 x	1,247.620637 =	124.762064
517.4		.100000 x	1,143.569156 =	114.356916
517.2		.250000 x	2,208.729987 =	552.182497
517.3		.250000 x	2,530.523154 =	632.630789
517.5		.100000 x	1,218.166143 =	121.816614
517.6		.200000 x	1,408.473626 =	281.694725
		-----		
			H.Δ. =	1,827.443604

517.1	517.1			
211		15.792206 x	1.186900 =	18.743769
517.1M		.800000 x	509.760000 =	407.808000
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
211		157.922058 x	1.186900 =	187.437691
		-----		
			H.Δ. =	1,247.620637
517.2	517.2			
211		365.476765 x	1.186900 =	433.784372
211		36.547677 x	1.186900 =	43.378438
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.2M		.800000 x	1,372.420000 =	1,097.936000
		-----		
			H.Δ. =	2,208.729987
517.3	517.3			
211		49.181441 x	1.186900 =	58.373452
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.3M		.800000 x	1,568.480000 =	1,254.784000
211		491.814411 x	1.186900 =	583.734524
		-----		
			H.Δ. =	2,530.523154
517.4	517.4			
211		9.024118 x	1.186900 =	10.710726
111		20.010000 x	15.741598 =	314.989376
114		13.340000 x	23.886192 =	318.641801
517.4M		.800000 x	490.150000 =	392.120000
211		90.241177 x	1.186900 =	107.107253
		-----		
			H.Δ. =	1,143.569156
517.5	517.5			
211		135.361765 x	1.186900 =	160.660879
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.5M		.800000 x	509.760000 =	407.808000
211		13.536176 x	1.186900 =	16.066087
		-----		
			H.Δ. =	1,218.166143

517.6	517.6			
211		20.304265 x	1.186900 =	24.099132
211		203.042646 x	1.186900 =	240.991317
114		13.340000 x	23.886192 =	318.641801
111		20.010000 x	15.741598 =	314.989376
517.6M		.800000 x	637.190000 =	509.752000
			H.Δ. =	1,408.473626
518	518			
518.1		.250000 x	1,930.554296 =	482.638574
518.2		.250000 x	2,697.658296 =	674.414574
518.4		.250000 x	2,763.636362 =	690.909091
518.3		.250000 x	2,730.647330 =	682.661833
			H.Δ. =	2,530.624071
518.1	518.1			
211		265.309059 x	1.186900 =	314.895322
116		13.340000 x	20.419486 =	272.395943
118		6.670000 x	10.001019 =	66.706797
114		20.010000 x	23.886192 =	477.962702
518.1M		.800000 x	958.880000 =	767.104000
211		26.530906 x	1.186900 =	31.489532
			H.Δ. =	1,930.554296
518.2	518.2			
211		26.530906 x	1.186900 =	31.489532
114		20.010000 x	23.886192 =	477.962702
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
518.2M		.800000 x	1,917.760000 =	1,534.208000
211		265.309059 x	1.186900 =	314.895322
			H.Δ. =	2,697.658296
518.3	518.3			
211		290.576588 x	1.186900 =	344.885352
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.3M		.800000 x	1,917.760000 =	1,534.208000
211		29.057659 x	1.186900 =	34.488535
			H.Δ. =	2,730.647330

518.4	518.4			
211		31.584412 x	1.186900 =	37.487539
211		315.844116 x	1.186900 =	374.875381
118		6.670000 x	10.001019 =	66.706797
116		13.340000 x	20.419486 =	272.395943
114		20.010000 x	23.886192 =	477.962702
518.4M		.800000 x	1,917.760000 =	1,534.208000
			H.Δ. =	2,763.636362
519	519			
519.1		.050000 x	798.899320 =	39.944966
519.2		.050000 x	847.114821 =	42.355741
519.3		.300000 x	805.367979 =	241.610394
519.5		.100000 x	1,022.499349 =	102.249935
519.6		.300000 x	706.416068 =	211.924820
519.4		.200000 x	768.317811 =	153.663562
			H.Δ. =	791.749418
519.1	519.1			
211		171.277754 x	1.186900 =	203.289566
116		13.340000 x	20.419486 =	272.395943
115		2.000000 x	21.778427 =	43.556854
211		17.127775 x	1.186900 =	20.328956
519.1M		.800000 x	324.160000 =	259.328000
			H.Δ. =	798.899320
519.2	519.2			
211		234.627058 x	1.186900 =	278.478855
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.2M		.800000 x	324.160000 =	259.328000
211		23.462706 x	1.186900 =	27.847886
			H.Δ. =	847.114821
519.3	519.3			
211		20.529868 x	1.186900 =	24.366900
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
211		205.298676 x	1.186900 =	243.668999
519.3M		.800000 x	319.840000 =	255.872000
			H.Δ. =	805.367979

519.4	519.4			
211		199.433001 x	1.186900 =	236.707029
211		19.943300 x	1.186900 =	23.670703
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.4M		.800000 x	283.100000 =	226.480000
-----				
			H.Δ. =	768.317811
519.5	519.5			
211		32.261220 x	1.186900 =	38.290842
116		6.670000 x	20.419486 =	136.197972
115		6.670000 x	21.778427 =	145.262108
519.5M		.800000 x	399.800000 =	319.840000
211		322.612206 x	1.186900 =	382.908427
-----				
			H.Δ. =	1,022.499349
519.6	519.6			
211		16.658521 x	1.186900 =	19.771999
115		6.670000 x	21.778427 =	145.262108
116		6.670000 x	20.419486 =	136.197972
519.6M		.800000 x	259.330000 =	207.464000
211		166.585213 x	1.186900 =	197.719989
-----				
			H.Δ. =	706.416068
521	521			
521.1		.250000 x	325.403204 =	81.350801
521.2		.250000 x	332.472285 =	83.118071
521.3		.200000 x	319.230837 =	63.846167
521.4		.150000 x	379.880203 =	56.982030
521.5		.150000 x	390.384203 =	58.557630
-----				
			H.Δ. =	343.854701
521.1	521.1			
211		7.471969 x	1.186900 =	8.868480
118		1.000000 x	10.001019 =	10.001019
211		74.719694 x	1.186900 =	88.684805
114		6.670000 x	23.886192 =	159.320901
521.1M		.800000 x	73.160000 =	58.528000
-----				
			H.Δ. =	325.403204

521.2	521.2			
211		80.134165 x	1.186900 =	95.111240
211		8.013417 x	1.186900 =	9.511125
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.2M		.800000 x	73.160000 =	58.528000
			H.Δ. =	332.472285
521.3	521.3			
211		76.885483 x	1.186900 =	91.255380
211		7.688548 x	1.186900 =	9.125538
114		6.670000 x	23.886192 =	159.320901
118		1.000000 x	10.001019 =	10.001019
521.3M		.800000 x	61.910000 =	49.528000
			H.Δ. =	319.230837
521.4	521.4			
211		11.586967 x	1.186900 =	13.752571
521.4M		.800000 x	74.100000 =	59.280000
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
211		115.869671 x	1.186900 =	137.525713
			H.Δ. =	379.880203
521.5	521.5			
211		115.869671 x	1.186900 =	137.525713
118		1.000000 x	10.001019 =	10.001019
114		6.670000 x	23.886192 =	159.320901
521.5M		.800000 x	87.230000 =	69.784000
211		11.586967 x	1.186900 =	13.752571
			H.Δ. =	390.384203
522	522			
522.6		.500000 x	481.497825 =	240.748913
522.7		.500000 x	475.842561 =	237.921281
			H.Δ. =	478.670193
522.6	522.6			
211		17.109727 x	1.186900 =	20.307535
211		171.097271 x	1.186900 =	203.075351
114		6.670000 x	23.886192 =	159.320901
118		2.000000 x	10.001019 =	20.002038
521.6M		.800000 x	98.490000 =	78.792000
			H.Δ. =	481.497825



522.7	522.7				
211		16.676569 x	1.186900 =	19.793420	
118		2.000000 x	10.001019 =	20.002038	
211		166.765694 x	1.186900 =	197.934202	
114		6.670000 x	23.886192 =	159.320901	
521.7M		.800000 x	98.490000 =	78.792000	
		-----			
			H.Δ. =	475.842561	
523	523				
523.1		1.000000 x	362.547952 =	362.547952	
		-----			
			H.Δ. =	362.547952	
523.1	523.1				
211		54.144706 x	1.186900 =	64.264352	
117		6.670000 x	16.777917 =	111.908706	
111		6.670000 x	15.741598 =	104.996459	
211		5.414471 x	1.186900 =	6.426436	
523.1M		.800000 x	93.690000 =	74.952000	
		-----			
			H.Δ. =	362.547952	
525	525				
525.1		1.000000 x	253.596244 =	253.596244	
		-----			
			H.Δ. =	253.596244	
525.1	525.1				
211		4.512059 x	1.186900 =	5.355363	
118		6.670000 x	10.001019 =	66.706797	
111		6.670000 x	15.741598 =	104.996459	
525.1M		.800000 x	28.730000 =	22.984000	
211		45.120588 x	1.186900 =	53.553626	
		-----			
			H.Δ. =	253.596244	
526	526				
526.1		1.000000 x	584.924303 =	584.924303	
		-----			
			H.Δ. =	584.924303	
526.1	526.1				
211		243.651176 x	1.186900 =	289.189581	
118		3.000000 x	10.001019 =	30.003057	
117		6.670000 x	16.777917 =	111.908706	
526.1M		.800000 x	156.130000 =	124.904000	
211		24.365118 x	1.186900 =	28.918959	
		-----			
			H.Δ. =	584.924303	

527	527			
527.1		.400000 x	2,171.990558 =	868.796223
527.2		.600000 x	3,183.132133 =	1,909.879280
-----				
			H.Δ. =	2,778.675503
527.1	527.1			
211		433.157646 x	1.186900 =	514.114810
114		16.680000 x	23.886192 =	398.421683
118		6.670000 x	10.001019 =	66.706797
211		43.315765 x	1.186900 =	51.411481
112		6.670000 x	17.312112 =	115.471787
527.1M		.800000 x	1,282.330000 =	1,025.864000
-----				
			H.Δ. =	2,171.990558
527.2	527.2			
211		54.144706 x	1.186900 =	64.264352
118		6.670000 x	10.001019 =	66.706797
114		16.680000 x	23.886192 =	398.421683
112		6.670000 x	17.312112 =	115.471787
211		541.447060 x	1.186900 =	642.643516
527.2M		.800000 x	2,369.530000 =	1,895.624000
-----				
			H.Δ. =	3,183.132133
528	528			
528.1		.250000 x	810.451092 =	202.612773
528.4		.250000 x	933.458238 =	233.364560
528.2		.250000 x	873.416125 =	218.354031
528.3		.250000 x	861.634328 =	215.408582
-----				
			H.Δ. =	869.739946
528.1	528.1			
211		7.941224 x	1.186900 =	9.425439
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
528.1M		.800000 x	312.250000 =	249.800000
211		79.412235 x	1.186900 =	94.254382
-----				
			H.Δ. =	810.451092

528.2	528.2			
211		10.467976 x	1.186900 =	12.424441
211		104.679765 x	1.186900 =	124.244413
528.2M		.800000 x	349.720000 =	279.776000
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
112		13.340000 x	17.312112 =	230.943574
-----				
			H.Δ. =	873.416125
528.3	528.3			
211		95.655647 x	1.186900 =	113.533687
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
211		9.565565 x	1.186900 =	11.353369
112		13.340000 x	17.312112 =	230.943574
528.3M		.800000 x	349.720000 =	279.776000
-----				
			H.Δ. =	861.634328
528.4	528.4			
211		135.361765 x	1.186900 =	160.660879
211		13.536176 x	1.186900 =	16.066087
112		13.340000 x	17.312112 =	230.943574
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.886192 =	159.320901
528.4M		.800000 x	374.700000 =	299.760000
-----				
			H.Δ. =	933.458238
529	529			
529.1		1.000000 x	750.888820 =	750.888820
-----				
			H.Δ. =	750.888820
529.1	529.1			
211		24.365118 x	1.186900 =	28.918959
117		6.670000 x	16.777917 =	111.908706
112		13.340000 x	17.312112 =	230.943574
529.1M		.800000 x	112.410000 =	89.928000
211		243.651176 x	1.186900 =	289.189581
-----				
			H.Δ. =	750.888820

2730A	2730A			
234		48.000000 x	.941500 =	45.192000
251		.040000 x	290.000000 =	11.600000
509		.200000 x	577.461125 =	115.492225
511		.150000 x	393.889671 =	59.083451
513		.250000 x	241.879987 =	60.469997
517		1.000000 x	1,827.443604 =	1,827.443604
504		.400000 x	807.024518 =	322.809807
509		.400000 x	577.461125 =	230.984450
113		13.340000 x	20.419486 =	272.395943
111		6.670000 x	15.741598 =	104.996459
112		6.670000 x	17.312112 =	115.471787
235		24.000000 x	.703000 =	16.872000

-----  
 B.T = 3,182.811723

2730B	2730B			
234		1,000.000000 x	.941500 =	941.500000
506		2.500000 x	483.244393 =	1,208.110983
517		9.000000 x	1,827.443604 =	16,446.992436
515		7.000000 x	585.923198 =	4,101.462386
509		5.000000 x	577.461125 =	2,887.305625
509		2.209627 x	577.461125 =	1,275.973693
113		140.000000 x	20.419486 =	2,858.728040
112		360.000000 x	17.312112 =	6,232.360320
111		360.000000 x	15.741598 =	5,666.975280
252		2.000000 x	290.000000 =	580.000000
251		2.000000 x	290.000000 =	580.000000
235		500.000000 x	.703000 =	351.500000

-----  
 B.T = 43,130.908763

2730Γ	2730Γ			
222		350.000000 x	.116200 =	40.670000
625		.500000 x	16.471888 =	8.235944
630		.200000 x	.547568 =	.109514
623		.800000 x	14.950110 =	11.960088

-----  
 B.T = 60.975546

611	611			
111		1.400000 x	15.741598 =	22.038237

-----  
 B.T = 22.038237

612	612			
111		.250000 x	15.741598 =	3.935400
503		.000588 x	1,770.254706 =	1.040910
504		.000833 x	807.024518 =	.672251

-----  
 B.T = 5.648561

613	613			
111		.200000 x	15.741598 =	3.148320
518		.000500 x	2,530.624071 =	1.265312
504		.001000 x	807.024518 =	.807025
503		.000667 x	1,770.254706 =	1.180760
-----				
			B.T =	6.401416
614	614			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,530.624071 =	6.326560
504		.001000 x	807.024518 =	.807025
509		.001950 x	577.461125 =	1.126049
503		.000909 x	1,770.254706 =	1.609162
-----				
			B.T =	11.253764
615	615			
112		.080000 x	17.312112 =	1.384969
518		.002500 x	2,530.624071 =	6.326560
504		.001000 x	807.024518 =	.807025
509		.001950 x	577.461125 =	1.126049
503		.000909 x	1,770.254706 =	1.609162
-----				
			B.T =	11.253764
616	616			
112		.080000 x	17.312112 =	1.384969
503		.000909 x	1,770.254706 =	1.609162
518		.002500 x	2,530.624071 =	6.326560
504		.001000 x	807.024518 =	.807025
509		.001950 x	577.461125 =	1.126049
-----				
			B.T =	11.253764
617	617			
111		.100000 x	15.741598 =	1.574160
503		.001000 x	1,770.254706 =	1.770255
518		.000625 x	2,530.624071 =	1.581640
504		.001000 x	807.024518 =	.807025
-----				
			B.T =	5.733079
621	621			
213		1.000000 x	1.949500 =	1.949500
519		.002500 x	791.749418 =	1.979374
111		.650000 x	15.741598 =	10.232039
116		.060000 x	20.419486 =	1.225169
-----				
			B.T =	15.386081

622	622			
213		1.000000 x	1.949500 =	1.949500
518		.001515 x	2,530.624071 =	3.833895
504		.001111 x	807.024518 =	.896604
519		.002500 x	791.749418 =	1.979374
509		.001950 x	577.461125 =	1.126049
503		.000909 x	1,770.254706 =	1.609162
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
			B.T =	15.167744
623	623			
213		1.000000 x	1.949500 =	1.949500
112		.100000 x	17.312112 =	1.731211
503		.000909 x	1,770.254706 =	1.609162
519		.002500 x	791.749418 =	1.979374
518		.001429 x	2,530.624071 =	3.616262
504		.001111 x	807.024518 =	.896604
509		.001950 x	577.461125 =	1.126049
116		.100000 x	20.419486 =	2.041949
			B.T =	14.950110
624	624			
213		1.000000 x	1.949500 =	1.949500
116		.100000 x	20.419486 =	2.041949
518		.001515 x	2,530.624071 =	3.833895
504		.001111 x	807.024518 =	.896604
519		.002500 x	791.749418 =	1.979374
509		.001950 x	577.461125 =	1.126049
503		.000909 x	1,770.254706 =	1.609162
112		.100000 x	17.312112 =	1.731211
			B.T =	15.167744
625	625			
213		1.000000 x	1.949500 =	1.949500
518		.002119 x	2,530.624071 =	5.362392
504		.000833 x	807.024518 =	.672251
519		.002500 x	791.749418 =	1.979374
509		.001950 x	577.461125 =	1.126049
503		.000909 x	1,770.254706 =	1.609162
116		.100000 x	20.419486 =	2.041949
112		.100000 x	17.312112 =	1.731211
			B.T =	16.471888
626	626			
509		.001786 x	577.461125 =	1.031346
504		.002000 x	807.024518 =	1.614049
			B.T =	2.645395

630	630			
512		.004255 x	128.688188 =	.547568
-----				
			B.T =	.547568
641	641			
231		.200000 x	.895000 =	.179000
111		.200000 x	15.741598 =	3.148320
113		.150000 x	20.419486 =	3.062923
252		.002500 x	290.000000 =	.725000
251		.001500 x	290.000000 =	.435000
-----				
			B.T =	7.550243
642	642			
231		.300000 x	.895000 =	.268500
113		.250000 x	20.419486 =	5.104872
111		.250000 x	15.741598 =	3.935400
252		.005000 x	290.000000 =	1.450000
251		.003000 x	290.000000 =	.870000
-----				
			B.T =	11.628771
651	651			
221		150.000000 x	.099900 =	14.985000
111		1.500000 x	15.741598 =	23.612397
112		.500000 x	17.312112 =	8.656056
625		1.000000 x	16.471888 =	16.471888
511		.040000 x	393.889671 =	15.755587
509		.002166 x	577.461125 =	1.250781
509		.007516 x	577.461125 =	4.340198
630		.600000 x	.547568 =	.328541
224		120.000000 x	.070000 =	8.400000
-----				
			B.T =	93.800447
652	652			
221		650.000000 x	.099900 =	64.935000
111		1.500000 x	15.741598 =	23.612397
511		.040000 x	393.889671 =	15.755587
509		.002166 x	577.461125 =	1.250781
509		.007516 x	577.461125 =	4.340198
630		.320000 x	.547568 =	.175222
625		1.000000 x	16.471888 =	16.471888
112		.500000 x	17.312112 =	8.656056
-----				
			B.T =	135.197128

661	661			
353		.160000 x	3.630000 =	.580800
354		.220000 x	4.020000 =	.884400
113		1.100000 x	20.419486 =	22.461435
355		.250000 x	.121800 =	.030450
-----				
			B.T =	23.957085
671	671			
215		.562500 x	1.034500 =	.581906
525		.000067 x	253.596244 =	.016991
111		.002000 x	15.741598 =	.031483
321		.550000 x	.539400 =	.296670
-----				
			B.T =	.927050
671.1	671.1			
215		.562500 x	1.034500 =	.581906
525		.000067 x	253.596244 =	.016991
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.630380
672	672			
215		.075000 x	1.034500 =	.077588
321		.940000 x	.539400 =	.507036
525		.000067 x	253.596244 =	.016991
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.633098
672.1	672.1			
215		.075000 x	1.034500 =	.077588
525		.000067 x	253.596244 =	.016991
111		.002000 x	15.741598 =	.031483
-----				
			B.T =	.126062
4311A	4311A			
321		80.000000 x	.539400 =	43.152000
616		.200000 x	11.253764 =	2.250753
615		.370000 x	11.253764 =	4.163893
527		.001786 x	2,778.675503 =	4.962714
625		.500000 x	16.471888 =	8.235944
504		.001786 x	807.024518 =	1.441346
626		.030000 x	2.645395 =	.079362
-----				
			B.T =	64.286012



4311A.1	4311A.1			
625		.500000 x	16.471888 =	8.235944
616		.200000 x	11.253764 =	2.250753
615		.370000 x	11.253764 =	4.163893
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
626		.030000 x	2.645395 =	.079362
-----				
			B.T =	21.134012
4311B	4311B			
321		80.000000 x	.539400 =	43.152000
625		.500000 x	16.471888 =	8.235944
623		.370000 x	14.950110 =	5.531541
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
626		.030000 x	2.645395 =	.079362
624		.200000 x	15.167744 =	3.033549
-----				
			B.T =	66.436456
4311B.1	4311B.1			
623		.370000 x	14.950110 =	5.531541
625		.500000 x	16.471888 =	8.235944
626		.030000 x	2.645395 =	.079362
504		.001786 x	807.024518 =	1.441346
527		.001786 x	2,778.675503 =	4.962714
624		.200000 x	15.167744 =	3.033549
-----				
			B.T =	23.284456
4312	4312			
509		.001622 x	577.461125 =	.936642
504		.001000 x	807.024518 =	.807025
-----				
			B.T =	1.743666
4411A	4411A			
321		80.000000 x	.539400 =	43.152000
625		.500000 x	16.471888 =	8.235944
504		.001786 x	807.024518 =	1.441346
615		.370000 x	11.253764 =	4.163893
616		.200000 x	11.253764 =	2.250753
527		.001786 x	2,778.675503 =	4.962714
626		.030000 x	2.645395 =	.079362
-----				
			B.T =	64.286012

4411A.1	4411A.1			
625		.500000 x	16.471888 =	8.235944
527		.001786 x	2,778.675503 =	4.962714
616		.200000 x	11.253764 =	2.250753
615		.370000 x	11.253764 =	4.163893
504		.001786 x	807.024518 =	1.441346
626		.030000 x	2.645395 =	.079362
-----				
			B.T =	21.134012
4411B	4411B			
321		80.000000 x	.539400 =	43.152000
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
626		.030000 x	2.645395 =	.079362
625		.500000 x	16.471888 =	8.235944
624		.200000 x	15.167744 =	3.033549
623		.370000 x	14.950110 =	5.531541
-----				
			B.T =	66.436456
4411B.1	4411B.1			
623		.370000 x	14.950110 =	5.531541
624		.200000 x	15.167744 =	3.033549
625		.500000 x	16.471888 =	8.235944
626		.030000 x	2.645395 =	.079362
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
-----				
			B.T =	23.284456
4412	4412			
509		.001622 x	577.461125 =	.936642
504		.001000 x	807.024518 =	.807025
-----				
			B.T =	1.743666
4511A	4511A			
321		90.000000 x	.539400 =	48.546000
625		.450000 x	16.471888 =	7.412350
616		.300000 x	11.253764 =	3.376129
615		.370000 x	11.253764 =	4.163893
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
626		.050000 x	2.645395 =	.132270
-----				
			B.T =	70.034701

4511A.1	4511A.1			
625		.450000 x	16.471888 =	7.412350
626		.050000 x	2.645395 =	.132270
616		.300000 x	11.253764 =	3.376129
615		.370000 x	11.253764 =	4.163893
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
-----				
			B.T =	21.488701
4511B	4511B			
321		90.000000 x	.539400 =	48.546000
623		.370000 x	14.950110 =	5.531541
624		.300000 x	15.167744 =	4.550323
626		.050000 x	2.645395 =	.132270
625		.450000 x	16.471888 =	7.412350
527		.001786 x	2,778.675503 =	4.962714
504		.001786 x	807.024518 =	1.441346
-----				
			B.T =	72.576543
4511B.1	4511B.1			
623		.370000 x	14.950110 =	5.531541
624		.300000 x	15.167744 =	4.550323
625		.450000 x	16.471888 =	7.412350
626		.050000 x	2.645395 =	.132270
504		.001786 x	807.024518 =	1.441346
527		.001786 x	2,778.675503 =	4.962714
-----				
			B.T =	24.030543
4512	4512			
509		.001622 x	577.461125 =	.936642
504		.001000 x	807.024518 =	.807025
-----				
			B.T =	1.743666
1110	1110			
503		.000455 x	1,770.254706 =	.805466
501		.000250 x	644.654468 =	.161164
-----				
			T.E =	.966630
1121	1121			
112		.005000 x	17.312112 =	.086561
501		.000083 x	644.654468 =	.053506
503		.000714 x	1,770.254706 =	1.263962
-----				
			T.E =	1.404029

1122	1122			
112		.005000 x	17.312112 =	.086561
507		.000385 x	761.391006 =	.293136
501		.000080 x	644.654468 =	.051572
505		.000316 x	1,226.640171 =	.387618
509		.002000 x	577.461125 =	1.154922
503		.000100 x	1,770.254706 =	.177025
		-----		
			T.E =	2.150834
1123.A	1123.A			
112		.005000 x	17.312112 =	.086561
507		.000769 x	761.391006 =	.585510
501		.000080 x	644.654468 =	.051572
509		.001429 x	577.461125 =	.825192
503		.000500 x	1,770.254706 =	.885127
		-----		
			T.E =	2.433962
1123.B	1123.B			
509		.000870 x	577.461125 =	.502391
		-----		
			T.E =	.502391
1131	1131			
213		1.000000 x	1.949500 =	1.949500
519		.000952 x	791.749418 =	.753745
112		.030000 x	17.312112 =	.519363
503		.000909 x	1,770.254706 =	1.609162
		-----		
			T.E =	4.831770
1132	1132			
213		1.000000 x	1.949500 =	1.949500
504		.001000 x	807.024518 =	.807025
519		.000952 x	791.749418 =	.753745
509		.002000 x	577.461125 =	1.154922
503		.000909 x	1,770.254706 =	1.609162
112		.120000 x	17.312112 =	2.077453
		-----		
			T.E =	8.351807
1133.A	1133.A			
213		1.000000 x	1.949500 =	1.949500
112		.120000 x	17.312112 =	2.077453
504		.001000 x	807.024518 =	.807025
519		.000952 x	791.749418 =	.753745
509		.001176 x	577.461125 =	.679094
503		.000909 x	1,770.254706 =	1.609162
		-----		
			T.E =	7.875979

1133.B	1133.B			
509		.000870 x	577.461125 =	.502391
		-----		
			T.E =	.502391
1140	1140			
112		.006000 x	17.312112 =	.103873
522		.000133 x	478.670193 =	.063663
501		.000050 x	644.654468 =	.032233
		-----		
			T.E =	.199769
1211	1211			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	761.391006 =	1.171019
501		.001538 x	644.654468 =	.991479
		-----		
			T.E =	5.624920
1212	1212			
112		.200000 x	17.312112 =	3.462422
507		.001538 x	761.391006 =	1.171019
501		.001538 x	644.654468 =	.991479
509		.002298 x	577.461125 =	1.327006
		-----		
			T.E =	6.951926
1220	1220			
213		1.000000 x	1.949500 =	1.949500
111		.500000 x	15.741598 =	7.870799
519		.002222 x	791.749418 =	1.759267
116		.060000 x	20.419486 =	1.225169
112		.060000 x	17.312112 =	1.038727
		-----		
			T.E =	13.843462
1310	1310			
112		.070000 x	17.312112 =	1.211848
501		.000385 x	644.654468 =	.248192
		-----		
			T.E =	1.460040
1320	1320			
112		1.500000 x	17.312112 =	25.968168
		-----		
			T.E =	25.968168

1410	1410			
112		.005000 x	17.312112 =	.086561
503		.000833 x	1,770.254706 =	1.474622
501		.000083 x	644.654468 =	.053506
-----				
			T.E =	1.614689
1420	1420			
112		.006000 x	17.312112 =	.103873
505		.000316 x	1,226.640171 =	.387618
503		.000208 x	1,770.254706 =	.368213
507		.000385 x	761.391006 =	.293136
501		.000050 x	644.654468 =	.032233
509		.001826 x	577.461125 =	1.054444
-----				
			T.E =	2.239516
1510	1510			
112		.007000 x	17.312112 =	.121185
504		.000714 x	807.024518 =	.576216
509		.001429 x	577.461125 =	.825192
503		.000385 x	1,770.254706 =	.681548
-----				
			T.E =	2.204140
1520	1520			
509		.000833 x	577.461125 =	.481025
-----				
			T.E =	.481025
1530	1530			
630		.150000 x	.547568 =	.082135
501		.000250 x	644.654468 =	.161164
509		.000413 x	577.461125 =	.238491
502		.000208 x	1,033.333245 =	.214933
522		.000556 x	478.670193 =	.266141
-----				
			T.E =	.962864
1610	1610			
111		.040000 x	15.741598 =	.629664
501		.000050 x	644.654468 =	.032233
503		.000111 x	1,770.254706 =	.196498
1122		.200000 x	2.150834 =	.430167
507		.000118 x	761.391006 =	.089844
-----				
			T.E =	1.378406

1620	1620			
112		.200000 x	17.312112 =	3.462422
1122		1.000000 x	2.150834 =	2.150834
501		.000714 x	644.654468 =	.460283
-----				
			T.E =	6.073540
2111	2111			
112		.010000 x	17.312112 =	.173121
507		.000667 x	761.391006 =	.507848
501		.000500 x	644.654468 =	.322327
509		.002124 x	577.461125 =	1.226527
503		.001053 x	1,770.254706 =	1.864078
-----				
			T.E =	4.093902
2112	2112			
213		1.000000 x	1.949500 =	1.949500
116		.060000 x	20.419486 =	1.225169
507		.000667 x	761.391006 =	.507848
509		.002124 x	577.461125 =	1.226527
519		.002041 x	791.749418 =	1.615961
112		.250000 x	17.312112 =	4.328028
503		.001613 x	1,770.254706 =	2.855421
-----				
			T.E =	13.708454
2151	2151			
213		.300000 x	1.949500 =	.584850
112		.100000 x	17.312112 =	1.731211
112		.200000 x	17.312112 =	3.462422
507		.003333 x	761.391006 =	2.537716
519		.001200 x	791.749418 =	.950099
509		.002124 x	577.461125 =	1.226527
113		.030000 x	20.419486 =	.612585
112		.100000 x	17.312112 =	1.731211
-----				
			T.E =	12.836622
2152	2152			
112		.200000 x	17.312112 =	3.462422
112		.100000 x	17.312112 =	1.731211
507		.006667 x	761.391006 =	5.076194
509		.003196 x	577.461125 =	1.845566
-----				
			T.E =	12.115393

2211	2211			
244		1.000000 x	2.700000 =	2.700000
515		.000004 x	585.923198 =	.002344
112		.003000 x	17.312112 =	.051936
112		.002000 x	17.312112 =	.034624
509		.000051 x	577.461125 =	.029451
515		.000004 x	585.923198 =	.002344
-----				
			T.E =	2.820698
2212	2212			
244		.125000 x	2.700000 =	.337500
112		.007000 x	17.312112 =	.121185
515		.000008 x	585.923198 =	.004687
509		.000051 x	577.461125 =	.029451
-----				
			T.E =	.492823
2213	2213			
236		3.000000 x	.673000 =	2.019000
517		.016667 x	1,827.443604 =	30.458003
515		.016667 x	585.923198 =	9.765582
113		.300000 x	20.419486 =	6.125846
111		.300000 x	15.741598 =	4.722479
-----				
			T.E =	53.090910
2214	2214			
111		.170000 x	15.741598 =	2.676072
515		.016667 x	585.923198 =	9.765582
113		.110000 x	20.419486 =	2.246143
111		.200000 x	15.741598 =	3.148320
113		.200000 x	20.419486 =	4.083897
-----				
			T.E =	21.920014
2251	2251			
111		.450000 x	15.741598 =	7.083719
112		.450000 x	17.312112 =	7.790450
509		.007516 x	577.461125 =	4.340198
621		1.050000 x	15.386081 =	16.155385
-----				
			T.E =	35.369752
2252	2252			
111		1.250000 x	15.741598 =	19.676998
621		1.050000 x	15.386081 =	16.155385
509		.007516 x	577.461125 =	4.340198
113		1.250000 x	20.419486 =	25.524358
-----				
			T.E =	65.696938



2253	2253			
111		1.500000 x	15.741598 =	23.612397
621		1.050000 x	15.386081 =	16.155385
652		.020000 x	135.197128 =	2.703943
509		.007891 x	577.461125 =	4.556746
651		.250000 x	93.800447 =	23.450112
113		2.500000 x	20.419486 =	51.048715
112		.200000 x	17.312112 =	3.462422
-----				
			T.E =	124.989719
2254	2254			
111		.750000 x	15.741598 =	11.806199
652		.100000 x	135.197128 =	13.519713
113		1.450000 x	20.419486 =	29.608255
509		.002630 x	577.461125 =	1.518723
621		.350000 x	15.386081 =	5.385128
-----				
			T.E =	61.838017
2311	2311			
243		1.020000 x	2.400000 =	2.448000
243		.080000 x	2.400000 =	.192000
-----				
			T.E =	2.640000
2312	2312			
112		.080000 x	17.312112 =	1.384969
113		.080000 x	20.419486 =	1.633559
-----				
			T.E =	3.018528
2313	2313			
111		.400000 x	15.741598 =	6.296639
112		.400000 x	17.312112 =	6.924845
611		1.050000 x	22.038237 =	23.140149
509		.003326 x	577.461125 =	1.920636
-----				
			T.E =	38.282269
2350	2350			
112		.100000 x	17.312112 =	1.731211
113		.250000 x	20.419486 =	5.104872
652		.022000 x	135.197128 =	2.974337
-----				
			T.E =	9.810420
2411	2411			
327		.500000 x	.540000 =	.270000
113		.180000 x	20.419486 =	3.675507
-----				
			T.E =	3.945507

2412	2412			
328		2.200000 x	1.840000 =	4.048000
111		.150000 x	15.741598 =	2.361240
113		.300000 x	20.419486 =	6.125846
329		2.000000 x	.730000 =	1.460000
2350		1.000000 x	9.810420 =	9.810420
-----				
			T.E =	23.805506
2511	2511			
221		200.000000 x	.099900 =	19.980000
623		.800000 x	14.950110 =	11.960088
625		.500000 x	16.471888 =	8.235944
630		.250000 x	.547568 =	.136892
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.016667 x	577.461125 =	9.624545
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.006012 x	577.461125 =	3.471696
112		.400000 x	17.312112 =	6.924845
113		.250000 x	20.419486 =	5.104872
-----				
			T.E =	71.436292
2512	2512			
221		250.000000 x	.099900 =	24.975000
509		.001444 x	577.461125 =	.833854
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.018182 x	577.461125 =	10.499398
623		.800000 x	14.950110 =	11.960088
641		2.000000 x	7.550243 =	15.100486
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
-----				
			T.E =	99.242714

2521	2521			
221		50.000000 x	.099900 =	4.995000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.006012 x	577.461125 =	3.471696
641		2.000000 x	7.550243 =	15.100486
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		.500000 x	20.419486 =	10.209743
112		.500000 x	17.312112 =	8.656056
221		250.000000 x	.099900 =	24.975000

-----  
T.E = 104.237714

2522	2522			
221		300.000000 x	.099900 =	29.970000
113		.800000 x	20.419486 =	16.335589
625		.500000 x	16.471888 =	8.235944
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		3.000000 x	7.550243 =	22.650729
630		.250000 x	.547568 =	.136892
623		.800000 x	14.950110 =	11.960088
112		.600000 x	17.312112 =	10.387267

-----  
T.E = 119.645014

2523	2523			
221		300.000000 x	.099900 =	29.970000
623		.800000 x	14.950110 =	11.960088
509		.001444 x	577.461125 =	.833854
509		.003758 x	577.461125 =	2.170099
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.018182 x	577.461125 =	10.499398
509		.006012 x	577.461125 =	3.471696
641		3.000000 x	7.550243 =	22.650729
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
113		1.050000 x	20.419486 =	21.440460
112		.750000 x	17.312112 =	12.984084

-----  
T.E = 127.346702

2524	2524			
221		x	.099900 =	29.970000
514		x	724.896312 =	2.071029
504		x	807.024518 =	.922429
509		x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		1.300000 x	7.550243 =	9.815316
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		.800000 x	20.419486 =	16.335589
112		1.200000 x	17.312112 =	20.774534

-----  
 T.E = 117.196868

2531	2531			
222		300.000000 x	.116200 =	34.860000
112		1.300000 x	17.312112 =	22.505746
113		.900000 x	20.419486 =	18.377537
630		.250000 x	.547568 =	.136892
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.001444 x	577.461125 =	.833854
509		.006012 x	577.461125 =	3.471696
641		1.300000 x	7.550243 =	9.815316
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088

-----  
 T.E = 125.860028

2532	2532			
222		300.000000 x	.116200 =	34.860000
		.006012 x	577.461125 =	3.471696
		.001444 x	577.461125 =	.833854
		.018182 x	577.461125 =	10.499398
		.003758 x	577.461125 =	2.170099
		4.000000 x	7.550243 =	30.200972
		.250000 x	.547568 =	.136892
		.500000 x	16.471888 =	8.235944
		1.600000 x	17.312112 =	27.699379
		.800000 x	14.950110 =	11.960088
		.900000 x	20.419486 =	18.377537
		.002857 x	724.896312 =	2.071029
		.001143 x	807.024518 =	.922429

-----  
 T.E = 151.439318

2533	2533			
222		300.000000 x	.116200 =	34.860000
112		1.800000 x	17.312112 =	31.161802
623		.800000 x	14.950110 =	11.960088
630		.250000 x	.547568 =	.136892
509		.001444 x	577.461125 =	.833854
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.018182 x	577.461125 =	10.499398
641		8.000000 x	7.550243 =	60.401944
625		.500000 x	16.471888 =	8.235944
113		1.200000 x	20.419486 =	24.503383

-----  
T.E = 191.228558

2541	2541			
222		300.000000 x	.116200 =	34.860000
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		1.200000 x	20.419486 =	24.503383
112		1.600000 x	17.312112 =	27.699379
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696

-----  
T.E = 161.340285

2542	2542			
222		300.000000 x	.116200 =	34.860000
112		1.650000 x	17.312112 =	28.564985
623		.800000 x	14.950110 =	11.960088
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.001444 x	577.461125 =	.833854
630		.250000 x	.547568 =	.136892
642		4.500000 x	11.628771 =	52.329470
625		.500000 x	16.471888 =	8.235944
113		1.250000 x	20.419486 =	25.524358

-----  
T.E = 181.580241

2543	2543			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
112		1.550000 x	17.312112 =	26.833774
113		.500000 x	20.419486 =	10.209743
113		1.250000 x	20.419486 =	25.524358

-----  
T.E = 175.480518

2544	2544			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
113		1.250000 x	20.419486 =	25.524358
112		1.650000 x	17.312112 =	28.564985
625		.500000 x	16.471888 =	8.235944
642		5.000000 x	11.628771 =	58.143855
630		.250000 x	.547568 =	.136892
623		.800000 x	14.950110 =	11.960088
113		.700000 x	20.419486 =	14.293640

-----  
T.E = 201.688267

2545	2545			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
641		6.000000 x	7.550243 =	45.301458
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		1.900000 x	20.419486 =	38.797023
112		1.650000 x	17.312112 =	28.564985

-----  
T.E = 187.824895

2546	2546			
222		300.000000 x	.116200 =	34.860000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		6.000000 x	7.550243 =	45.301458
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
112		1.850000 x	17.312112 =	32.027407
113		1.900000 x	20.419486 =	38.797023

-----  
 T.E = 191.287318

2547	2547			
222		300.000000 x	.116200 =	34.860000
113		1.900000 x	20.419486 =	38.797023
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.003758 x	577.461125 =	2.170099
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
112		1.550000 x	17.312112 =	26.833774

-----  
 T.E = 178.543441

2548	2548			
222		300.000000 x	.116200 =	34.860000
112		1.950000 x	17.312112 =	33.758618
623		.800000 x	14.950110 =	11.960088
630		.250000 x	.547568 =	.136892
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		5.000000 x	7.550243 =	37.751215
625		.500000 x	16.471888 =	8.235944
113		2.400000 x	20.419486 =	49.006766

-----  
 T.E = 195.678029

2551	2551			
222		360.000000 x	.116200 =	41.832000
514		.002857 x	724.896312 =	2.071029
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
112		1.550000 x	17.312112 =	26.833774
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.547568 =	.136892
509		.018182 x	577.461125 =	10.499398
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		1.050000 x	20.419486 =	21.440460

-----  
 T.E = 164.383756

2561	2561			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		4.500000 x	7.550243 =	33.976094
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		2.800000 x	20.419486 =	57.174561
112		1.800000 x	17.312112 =	31.161802
111		1.250000 x	15.741598 =	19.676998

-----  
 T.E = 235.194870

2562	2562			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.003758 x	577.461125 =	2.170099
		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
509		.006012 x	577.461125 =	3.471696
111		1.950000 x	15.741598 =	30.696116
112		1.800000 x	17.312112 =	31.161802
625		.500000 x	16.471888 =	8.235944
642		4.500000 x	11.628771 =	52.329470
630		.250000 x	.547568 =	.136892
623		.800000 x	14.950110 =	11.960088
113		2.800000 x	20.419486 =	57.174561

-----  
 T.E = 264.567364



2563	2563			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.003758 x	577.461125 =	2.170099
509		.018182 x	577.461125 =	10.499398
509		.001444 x	577.461125 =	.833854
509		.006012 x	577.461125 =	3.471696
641		5.000000 x	7.550243 =	37.751215
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
111		1.950000 x	15.741598 =	30.696116
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802
113		3.900000 x	20.419486 =	79.635995

-----  
 T.E = 290.828082

2564	2564			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
642		5.000000 x	11.628771 =	58.143855
111		1.950000 x	15.741598 =	30.696116
113		3.900000 x	20.419486 =	79.635995
623		.800000 x	14.950110 =	11.960088
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
113		.900000 x	20.419486 =	18.377537
112		1.800000 x	17.312112 =	31.161802

-----  
 T.E = 311.220722

2565	2565			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
641		6.000000 x	7.550243 =	45.301458
630		.250000 x	.547568 =	.136892
625		.500000 x	16.471888 =	8.235944
623		.800000 x	14.950110 =	11.960088
113		4.700000 x	20.419486 =	95.971584
112		2.350000 x	17.312112 =	40.683463
111		2.350000 x	15.741598 =	36.992755

-----  
 T.E = 312.154677

2566	2566			
222		450.000000 x	.116200 =	52.290000
514		.003704 x	724.896312 =	2.685016
504		.001143 x	807.024518 =	.922429
509		.006012 x	577.461125 =	3.471696
509		.003758 x	577.461125 =	2.170099
509		.001444 x	577.461125 =	.833854
509		.018182 x	577.461125 =	10.499398
111		2.350000 x	15.741598 =	36.992755
112		2.350000 x	17.312112 =	40.683463
625		.500000 x	16.471888 =	8.235944
642		6.000000 x	11.628771 =	69.772626
630		.250000 x	.547568 =	.136892
623		.800000 x	14.950110 =	11.960088
113		4.700000 x	20.419486 =	95.971584
-----				
			T.E =	336.625845
2611	2611			
233		1.050000 x	.545500 =	.572775
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.287457
2612	2612			
238		1.050000 x	.545500 =	.572775
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.287457
2620	2620			
239		1.010000 x	8.200000 =	8.282000
113		.080000 x	20.419486 =	1.633559
113		.080000 x	20.419486 =	1.633559
239		.303000 x	8.200000 =	2.484600
-----				
			T.E =	14.033718
2651	2651			
235		1.050000 x	.703000 =	.738150
113		.100000 x	20.419486 =	2.041949
-----				
			T.E =	2.780099
2652	2652			
235		1.050000 x	.703000 =	.738150
661		.050000 x	23.957085 =	1.197854
113		.120000 x	20.419486 =	2.450338
-----				
			T.E =	4.386343

2653	2653			
241		1.050000 x	7.750000 =	8.137500
113		.800000 x	20.419486 =	16.335589
661		.120000 x	23.957085 =	2.874850
		-----		
			T.E =	27.347939
2671	2671			
237		1.000000 x	1.218000 =	1.218000
113		.015000 x	20.419486 =	.306292
		-----		
			T.E =	1.524292
2672	2672			
235		1.050000 x	.703000 =	.738150
661		.050000 x	23.957085 =	1.197854
113		.120000 x	20.419486 =	2.450338
		-----		
			T.E =	4.386343
2711	2711			
2551		1.000000 x	164.383756 =	164.383756
		-----		
			T.E =	164.383756
2712	2712			
2611		1.000000 x	1.287457 =	1.287457
		-----		
			T.E =	1.287457
2713	2713			
237		1.000000 x	1.218000 =	1.218000
113		.070000 x	20.419486 =	1.429364
		-----		
			T.E =	2.647364
2714	2714			
112		1.900000 x	17.312112 =	32.893013
516		.015385 x	930.498303 =	14.315716
517		.015385 x	1,827.443604 =	28.115220
		-----		
			T.E =	75.323949
2731	2731			
2730A		.149925 x	3,182.811723 =	477.183048
2730Γ		1.000000 x	60.975546 =	60.975546
2730B		.000667 x	43,130.908763 =	28.768316
		-----		
			T.E =	566.926910

2732	2732			
2730A		.179910 x	3,182.811723 =	572.619657
2730Γ		1.000000 x	60.975546 =	60.975546
2730B		.000667 x	43,130.908763 =	28.768316
-----				
			T.E =	662.363519
2733	2733			
233		1.050000 x	.545500 =	.572775
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.287457
2734	2734			
238		1.050000 x	.545500 =	.572775
113		.035000 x	20.419486 =	.714682
-----				
			T.E =	1.287457
2811	2811			
112		.170000 x	17.312112 =	2.943059
509		.002217 x	577.461125 =	1.280231
501		.000500 x	644.654468 =	.322327
507		.001538 x	761.391006 =	1.171019
-----				
			T.E =	5.716637
2815	2815			
111		.250000 x	15.741598 =	3.935400
623		.400000 x	14.950110 =	5.980044
625		.700000 x	16.471888 =	11.530322
509		.005261 x	577.461125 =	3.038023
509		.003006 x	577.461125 =	1.735848
112		.350000 x	17.312112 =	6.059239
-----				
			T.E =	32.278875
2861	2861			
221		6.000000 x	.099900 =	.599400
113		.200000 x	20.419486 =	4.083897
281		1.000000 x	21.300000 =	21.300000
111		.250000 x	15.741598 =	3.935400
-----				
			T.E =	29.918697
2862	2862			
221		8.000000 x	.099900 =	.799200
111		.250000 x	15.741598 =	3.935400
113		.200000 x	20.419486 =	4.083897
282		1.000000 x	30.000000 =	30.000000
-----				
			T.E =	38.818497

2863	2863			
221		8.000000 x	.099900 =	.799200
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
283		1.000000 x	36.300000 =	36.300000
		-----		
			T.E =	58.561956
2864	2864			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
284		1.000000 x	75.400000 =	75.400000
		-----		
			T.E =	99.248236
2881	2881			
221		6.000000 x	.099900 =	.599400
261		1.000000 x	15.100000 =	15.100000
111		.250000 x	15.741598 =	3.935400
113		.200000 x	20.419486 =	4.083897
		-----		
			T.E =	23.718697
2882	2882			
221		8.000000 x	.099900 =	.799200
262		1.000000 x	26.300000 =	26.300000
113		.200000 x	20.419486 =	4.083897
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	35.118497
2883	2883			
221		10.000000 x	.099900 =	.999000
263		1.000000 x	32.400000 =	32.400000
113		.550000 x	20.419486 =	11.230717
111		.650000 x	15.741598 =	10.232039
		-----		
			T.E =	54.861756
2884	2884			
221		16.000000 x	.099900 =	1.598400
113		.550000 x	20.419486 =	11.230717
111		.700000 x	15.741598 =	11.019119
264		1.000000 x	64.100000 =	64.100000
		-----		
			T.E =	87.948236

2885	2885			
221		20.000000 x	.099900 =	1.998000
113		.750000 x	20.419486 =	15.314615
265		1.000000 x	115.100000 =	115.100000
111		1.000000 x	15.741598 =	15.741598
		-----		
			T.E =	148.154213
2888	2888			
221		26.000000 x	.099900 =	2.597400
111		1.400000 x	15.741598 =	22.038237
271		1.000000 x	206.300000 =	206.300000
113		1.100000 x	20.419486 =	22.461435
		-----		
			T.E =	253.397072
2911	2911			
351		1.050000 x	765.000000 =	803.250000
113		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	905.347430
2912	2912			
352		1.050000 x	1,035.000000 =	1,086.750000
113		5.000000 x	20.419486 =	102.097430
		-----		
			T.E =	1,188.847430
2921	2921			
301		1.000000 x	4.060000 =	4.060000
113		.250000 x	20.419486 =	5.104872
652		.002000 x	135.197128 =	.270394
2522		.005000 x	119.645014 =	.598225
111		.250000 x	15.741598 =	3.935400
		-----		
			T.E =	13.968890
2922	2922			
302		1.020000 x	6.700000 =	6.834000
652		.015000 x	135.197128 =	2.027957
113		.600000 x	20.419486 =	12.251692
111		.350000 x	15.741598 =	5.509559
		-----		
			T.E =	26.623208
2951	2951			
512A		.150000 x	109.624876 =	16.443731
		-----		
			T.E =	16.443731

2952	2952			
512B		.150000 x	157.282992 =	23.592449
				-----
			T.E =	23.592449
2953	2953			
513A		.150000 x	215.222437 =	32.283366
				-----
			T.E =	32.283366
2954	2954			
513B		.150000 x	275.101168 =	41.265175
				-----
			T.E =	41.265175
3111A	3111A			
112		.020000 x	17.312112 =	.346242
522		.000263 x	478.670193 =	.125890
509		.000072 x	577.461125 =	.041577
509		.000193 x	577.461125 =	.111450
630		.020000 x	.547568 =	.010951
501		.000182 x	644.654468 =	.117327
614		.135000 x	11.253764 =	1.519258
				-----
			T.E =	2.272696
3111B	3111B			
112		.020000 x	17.312112 =	.346242
630		.020000 x	.547568 =	.010951
509		.000193 x	577.461125 =	.111450
501		.000182 x	644.654468 =	.117327
509		.000072 x	577.461125 =	.041577
522		.000263 x	478.670193 =	.125890
622		.135000 x	15.167744 =	2.047645
				-----
			T.E =	2.801084
3112	3112			
509		.000094 x	577.461125 =	.054281
				-----
			T.E =	.054281
3121A	3121A			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	644.654468 =	1.171982
614		1.350000 x	11.253764 =	15.192581
509		.000722 x	577.461125 =	.416927
509		.001929 x	577.461125 =	1.113923
522		.002632 x	478.670193 =	1.259860
630		.200000 x	.547568 =	.109514
				-----
			T.E =	22.727209

3121B	3121B			
112		.200000 x	17.312112 =	3.462422
501		.001818 x	644.654468 =	1.171982
509		.001929 x	577.461125 =	1.113923
509		.000722 x	577.461125 =	.416927
522		.002632 x	478.670193 =	1.259860
630		.200000 x	.547568 =	.109514
622		1.350000 x	15.167744 =	20.476454
			T.E =	28.011082
3122	3122			
509		.000940 x	577.461125 =	.542813
			T.E =	.542813
3211A	3211A			
112		.025000 x	17.312112 =	.432803
522		.000263 x	478.670193 =	.125890
501		.000182 x	644.654468 =	.117327
614		.135000 x	11.253764 =	1.519258
509		.000193 x	577.461125 =	.111450
509		.000072 x	577.461125 =	.041577
630		.020000 x	.547568 =	.010951
			T.E =	2.359257
3211B	3211B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	15.167744 =	2.047645
509		.000193 x	577.461125 =	.111450
509		.000072 x	577.461125 =	.041577
522		.000263 x	478.670193 =	.125890
501		.000182 x	644.654468 =	.117327
630		.020000 x	.547568 =	.010951
			T.E =	2.887644
3212	3212			
509		.000141 x	577.461125 =	.081422
			T.E =	.081422



3221	3221			
622		.202500 x	15.167744 =	3.071468
509		.000469 x	577.461125 =	.270829
501		.000250 x	644.654468 =	.161164
509		.000250 x	577.461125 =	.144365
509		.000286 x	577.461125 =	.165154
509		.000250 x	577.461125 =	.144365
522		.000500 x	478.670193 =	.239335
630		.100000 x	.547568 =	.054757
		-----		
			T.E =	4.251437
3222	3222			
221		1.000000 x	.099900 =	.099900
		-----		
			T.E =	.099900
3223	3223			
509		.000141 x	577.461125 =	.081422
		-----		
			T.E =	.081422
3231	3231			
112		.025000 x	17.312112 =	.432803
630		.015000 x	.547568 =	.008214
501		.000213 x	644.654468 =	.137311
522		.000286 x	478.670193 =	.136900
509		.000054 x	577.461125 =	.031183
		-----		
			T.E =	.746410
3232A	3232A			
630		.200000 x	.547568 =	.109514
509		.001929 x	577.461125 =	1.113923
614		1.350000 x	11.253764 =	15.192581
		-----		
			T.E =	16.416018
3232B	3232B			
622		1.350000 x	15.167744 =	20.476454
630		.200000 x	.547568 =	.109514
509		.001929 x	577.461125 =	1.113923
		-----		
			T.E =	21.699891
3233	3233			
509		.000940 x	577.461125 =	.542813
		-----		
			T.E =	.542813

3241A	3241A			
112		.025000 x	17.312112 =	.432803
630		.020000 x	.547568 =	.010951
522		.000286 x	478.670193 =	.136900
509		.000072 x	577.461125 =	.041577
501		.000213 x	644.654468 =	.137311
614		.135000 x	11.253764 =	1.519258
509		.000193 x	577.461125 =	.111450
-----				
			T.E =	2.390251
3241B	3241B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	15.167744 =	2.047645
630		.020000 x	.547568 =	.010951
501		.000213 x	644.654468 =	.137311
509		.000193 x	577.461125 =	.111450
509		.000072 x	577.461125 =	.041577
522		.000286 x	478.670193 =	.136900
-----				
			T.E =	2.918638
3242	3242			
509		.000094 x	577.461125 =	.054281
-----				
			T.E =	.054281
3311A	3311A			
112		.025000 x	17.312112 =	.432803
509		.000072 x	577.461125 =	.041577
501		.000213 x	644.654468 =	.137311
614		.135000 x	11.253764 =	1.519258
509		.000193 x	577.461125 =	.111450
630		.020000 x	.547568 =	.010951
522		.000286 x	478.670193 =	.136900
-----				
			T.E =	2.390251
3311B	3311B			
112		.025000 x	17.312112 =	.432803
622		.135000 x	15.167744 =	2.047645
630		.020000 x	.547568 =	.010951
522		.000286 x	478.670193 =	.136900
501		.000213 x	644.654468 =	.137311
509		.000072 x	577.461125 =	.041577
509		.000193 x	577.461125 =	.111450
-----				
			T.E =	2.918638

3312	3312			
509		.000094 x	577.461125 =	.054281
-----				
			T.E =	.054281
3321A	3321A			
112		.030000 x	17.312112 =	.519363
522		.000286 x	478.670193 =	.136900
630		.020000 x	.547568 =	.010951
509		.000072 x	577.461125 =	.041577
509		.000193 x	577.461125 =	.111450
501		.000213 x	644.654468 =	.137311
614		.135000 x	11.253764 =	1.519258
-----				
			T.E =	2.476811
3321B	3321B			
112		.030000 x	17.312112 =	.519363
522		.000286 x	478.670193 =	.136900
630		.020000 x	.547568 =	.010951
501		.000213 x	644.654468 =	.137311
509		.000193 x	577.461125 =	.111450
509		.000072 x	577.461125 =	.041577
622		.135000 x	15.167744 =	2.047645
-----				
			T.E =	3.005198
3322	3322			
509		.000094 x	577.461125 =	.054281
-----				
			T.E =	.054281
3401	3401			
111		1.300000 x	15.741598 =	20.464077
112		.900000 x	17.312112 =	15.580901
509		.000361 x	577.461125 =	.208463
521		.014286 x	343.854701 =	4.912308
630		.100000 x	.547568 =	.054757
-----				
			T.E =	41.220507
3402A	3402A			
509		.001929 x	577.461125 =	1.113923
614		1.350000 x	11.253764 =	15.192581
-----				
			T.E =	16.306504
3402B	3402B			
622		1.350000 x	15.167744 =	20.476454
509		.001929 x	577.461125 =	1.113923
-----				
			T.E =	21.590377

3403	3403			
509		.000940 x	577.461125 =	.542813
			T.E =	.542813
4110	4110			
112		.008000 x	17.312112 =	.138497
671		1.200000 x	.927050 =	1.112460
526		.000100 x	584.924303 =	.058492
523		.000143 x	362.547952 =	.051844
			T.E =	1.361294
4110.1	4110.1			
112		.008000 x	17.312112 =	.138497
671.1		1.200000 x	.630380 =	.756456
526		.000100 x	584.924303 =	.058492
523		.000143 x	362.547952 =	.051844
			T.E =	1.005290
4120	4120			
321		.500000 x	.539400 =	.269700
525		.000067 x	253.596244 =	.016991
526		.000100 x	584.924303 =	.058492
523		.000143 x	362.547952 =	.051844
112		.006000 x	17.312112 =	.103873
			T.E =	.500900
4120.1	4120.1			
112		.006000 x	17.312112 =	.103873
523		.000143 x	362.547952 =	.051844
525		.000067 x	253.596244 =	.016991
526		.000100 x	584.924303 =	.058492
			T.E =	.231200
4131A	4131A			
321		1.000000 x	.539400 =	.539400
522		.000143 x	478.670193 =	.068450
509		.000014 x	577.461125 =	.008084
509		.000143 x	577.461125 =	.082577
509		.000028 x	577.461125 =	.016169
504		.000143 x	807.024518 =	.115405
616		.015000 x	11.253764 =	.168806
525		.000067 x	253.596244 =	.016991
526		.000143 x	584.924303 =	.083644
523		.000143 x	362.547952 =	.051844
112		.008000 x	17.312112 =	.138497
			T.E =	1.289867

4131A.1	4131A.1			
112		.008000 x	17.312112 =	.138497
509		.000014 x	577.461125 =	.008084
509		.000028 x	577.461125 =	.016169
616		.015000 x	11.253764 =	.168806
525		.000067 x	253.596244 =	.016991
526		.000143 x	584.924303 =	.083644
523		.000143 x	362.547952 =	.051844
504		.000143 x	807.024518 =	.115405
509		.000143 x	577.461125 =	.082577
522		.000143 x	478.670193 =	.068450

T.E = .750467

4131B	4131B			
321		1.000000 x	.539400 =	.539400
112		.008000 x	17.312112 =	.138497
525		.000067 x	253.596244 =	.016991
526		.000143 x	584.924303 =	.083644
523		.000143 x	362.547952 =	.051844
504		.000143 x	807.024518 =	.115405
509		.000143 x	577.461125 =	.082577
509		.000014 x	577.461125 =	.008084
509		.000028 x	577.461125 =	.016169
522		.000143 x	478.670193 =	.068450
624		.015000 x	15.167744 =	.227516

T.E = 1.348577

4131B.1	4131B.1			
112		.008000 x	17.312112 =	.138497
509		.000143 x	577.461125 =	.082577
509		.000014 x	577.461125 =	.008084
525		.000067 x	253.596244 =	.016991
526		.000143 x	584.924303 =	.083644
523		.000143 x	362.547952 =	.051844
504		.000143 x	807.024518 =	.115405
509		.000028 x	577.461125 =	.016169
624		.015000 x	15.167744 =	.227516
522		.000143 x	478.670193 =	.068450

T.E = .809177

4132	4132			
509		.000009 x	577.461125 =	.005197

T.E = .005197

4141A	4141A			
112		.013000 x	17.312112 =	.225057
523		.000143 x	362.547952 =	.051844
616		.012000 x	11.253764 =	.135045
615		.015000 x	11.253764 =	.168806
526		.000244 x	584.924303 =	.142722
504		.000244 x	807.024518 =	.196914
509		.000244 x	577.461125 =	.140901
509		.000024 x	577.461125 =	.013859
671		1.200000 x	.927050 =	1.112460
522		.000244 x	478.670193 =	.116796
509		.000038 x	577.461125 =	.021944
672		1.500000 x	.633098 =	.949647

-----  
 T.E = 3.275995

4141A.1	4141A.1			
112		.013000 x	17.312112 =	.225057
616		.012000 0	11.253764 =	.135045
615		.015000	11.253764 =	.168806
526		.000244 3	584.924303 =	.142722
523		.000143	362.547952 =	.051844
504		.000244 1	807.024518 =	.196914
509		.000024	577.461125 =	.013859
509		.000038 1	577.461125 =	.021944
509		.000244	577.461125 =	.140901
522		.000244 1	478.670193 =	.116796
672.1		1.500000	.126062 =	.189093
671.1		1.200000 0	.630380 =	.756456

-----  
 T.E = 2.159437

4141B	4141B			
112		.013000	17.312112 =	.225057
509		.000244 0	577.461125 =	.140901
526		.000244	584.924303 =	.142722
523		.000143 1	362.547952 =	.051844
504		.000244 x	807.024518 =	.196914
509		.000024 x	577.461125 =	.013859
522		.000244 x	478.670193 =	.116796
624		.012000 x	15.167744 =	.182013
672		1.500000 x	.633098 =	.949647
509		.000038 x	577.461125 =	.021944
671		1.200000 x	.927050 =	1.112460
623		.015000 x	14.950110 =	.224252

-----  
 T.E = 3.378408

4141B.1	4141B.1			
112		.013000 x	17.312112 =	.225057
526		.000244 x	584.924303 =	.142722
523		.000143 x	362.547952 =	.051844
504		.000244 x	807.024518 =	.196914
509		.000024 x	577.461125 =	.013859
509		.000038 x	577.461125 =	.021944
509		.000244 x	577.461125 =	.140901
522		.000244 x	478.670193 =	.116796
672.1		1.500000 x	.126062 =	.189093
671.1		1.200000 x	.630380 =	.756456
624		.012000 x	15.167744 =	.182013
623		.015000 x	14.950110 =	.224252
			-----	
			T.E =	2.261850
4142	4142			
509		.000017 x	577.461125 =	.009817
			-----	
			T.E =	.009817
4211A	4211A			
672		25.000000 x	.633098 =	15.827450
501		.007024 x	644.654468 =	4.528053
616		.300000 x	11.253764 =	3.376129
615		.700000 x	11.253764 =	7.877635
526		.002857 x	584.924303 =	1.671129
509		.001429 x	577.461125 =	.825192
522		.003846 x	478.670193 =	1.840966
			-----	
			T.E =	35.946553
4211A.1	4211A.1			
672.1		25.000000 x	.126062 =	3.151550
522		.003846 x	478.670193 =	1.840966
509		.001429 x	577.461125 =	.825192
615		.700000 x	11.253764 =	7.877635
501		.007024 x	644.654468 =	4.528053
616		.300000 x	11.253764 =	3.376129
526		.002857 x	584.924303 =	1.671129
			-----	
			T.E =	23.270653
4211B	4211B			
623		.700000 x	14.950110 =	10.465077
522		.003846 x	478.670193 =	1.840966
501		.007024 x	644.654468 =	4.528053
672		25.000000 x	.633098 =	15.827450
526		.002857 x	584.924303 =	1.671129
509		.001429 x	577.461125 =	.825192
624		.300000 x	15.167744 =	4.550323
			-----	
			T.E =	39.708189

4211B.1	4211B.1			
623		.700000 x	14.950110 =	10.465077
501		.007024 x	644.654468 =	4.528053
526		.002857 x	584.924303 =	1.671129
509		.001429 x	577.461125 =	.825192
522		.003846 x	478.670193 =	1.840966
672.1		25.000000 x	.126062 =	3.151550
624		.300000 x	15.167744 =	4.550323
			T.E =	27.032289
4212	4212			
509		.000614 x	577.461125 =	.354561
			T.E =	.354561
4221A	4221A			
672		37.000000 x	.633098 =	23.424626
526		.004000 x	584.924303 =	2.339697
501		.008226 x	644.654468 =	5.302928
616		.400000 x	11.253764 =	4.501506
615		.600000 x	11.253764 =	6.752258
522		.004348 x	478.670193 =	2.081258
509		.001429 x	577.461125 =	.825192
			T.E =	45.227465
4221A.1	4221A.1			
672.1		37.000000 x	.126062 =	4.664294
501		.008226 x	644.654468 =	5.302928
616		.400000 x	11.253764 =	4.501506
615		.600000 x	11.253764 =	6.752258
526		.004000 x	584.924303 =	2.339697
509		.001429 x	577.461125 =	.825192
522		.004348 x	478.670193 =	2.081258
			T.E =	26.467133
4221B	4221B			
623		.600000 x	14.950110 =	8.970066
624		.400000 x	15.167744 =	6.067098
501		.008226 x	644.654468 =	5.302928
526		.004000 x	584.924303 =	2.339697
509		.001429 x	577.461125 =	.825192
522		.004348 x	478.670193 =	2.081258
672		37.000000 x	.633098 =	23.424626
			T.E =	49.010864



4221B.1	4221B.1			
623		.600000 x	14.950110 =	8.970066
672.1		37.000000 x	.126062 =	4.664294
522		.004348 x	478.670193 =	2.081258
509		.001429 x	577.461125 =	.825192
624		.400000 x	15.167744 =	6.067098
501		.008226 x	644.654468 =	5.302928
526		.004000 x	584.924303 =	2.339697
-----				
			T.E =	30.250532
4222	4222			
509		.000614 x	577.461125 =	.354561
-----				
			T.E =	.354561
4231A	4231A			
112		.005000 x	17.312112 =	.086561
672		2.500000 x	.633098 =	1.582745
509		.000036 x	577.461125 =	.020789
526		.000222 x	584.924303 =	.129853
616		.006000 x	11.253764 =	.067523
615		.025000 x	11.253764 =	.281344
523		.000143 x	362.547952 =	.051844
509		.000044 x	577.461125 =	.025408
509		.000357 x	577.461125 =	.206154
522		.000357 x	478.670193 =	.170885
112		.030000 x	17.312112 =	.519363
-----				
			T.E =	3.142469
4231A.1	4231A.1			
112		.005000 x	17.312112 =	.086561
616		.006000 x	11.253764 =	.067523
615		.025000 x	11.253764 =	.281344
526		.000222 x	584.924303 =	.129853
523		.000143 x	362.547952 =	.051844
509		.000357 x	577.461125 =	.206154
509		.000036 x	577.461125 =	.020789
509		.000044 x	577.461125 =	.025408
522		.000357 x	478.670193 =	.170885
672.1		2.500000 x	.126062 =	.315155
112		.030000 x	17.312112 =	.519363
-----				
			T.E =	1.874879

4231B	4231B			
112		.005000 x	17.312112 =	.086561
509		.000044 x	577.461125 =	.025408
526		.000222 x	584.924303 =	.129853
523		.000143 x	362.547952 =	.051844
509		.000357 x	577.461125 =	.206154
509		.000036 x	577.461125 =	.020789
623		.025000 x	14.950110 =	.373753
522		.000357 x	478.670193 =	.170885
624		.006000 x	15.167744 =	.091006
672		2.500000 x	.633098 =	1.582745
112		.030000 x	17.312112 =	.519363
		-----		
			T.E =	3.258361
4231B.1	4231B.1			
112		.005000 x	17.312112 =	.086561
112		.030000 x	17.312112 =	.519363
623		.025000 x	14.950110 =	.373753
526		.000222 x	584.924303 =	.129853
523		.000143 x	362.547952 =	.051844
509		.000044 x	577.461125 =	.025408
509		.000357 x	577.461125 =	.206154
509		.000036 x	577.461125 =	.020789
522		.000357 x	478.670193 =	.170885
672.1		2.500000 x	.126062 =	.315155
624		.006000 x	15.167744 =	.091006
		-----		
			T.E =	1.990771
4232	4232			
509		.000024 x	577.461125 =	.013859
		-----		
			T.E =	.013859
4321A	4321A			
521		.000128 x	343.854701 =	.044013
4312		.071000 x	1.743666 =	.123800
4311A		.071000 x	64.286012 =	4.564307
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
528		.000128 x	869.739946 =	.111327
522		.000128 x	478.670193 =	.061270
		-----		
			T.E =	5.014885

4321A.1	4321A.1			
521		.000128 x	343.854701 =	.044013
4312		.071000 x	1.743666 =	.123800
4311A.1		.071000 x	21.134012 =	1.500515
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	1.951093
4321B	4321B			
521		.000128 x	343.854701 =	.044013
4312		.071000 x	1.743666 =	.123800
4311B		.071000 x	66.436456 =	4.716988
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	5.167566
4321B.1	4321B.1			
521		.000128 x	343.854701 =	.044013
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
4312		.071000 x	1.743666 =	.123800
4311B.1		.071000 x	23.284456 =	1.653196
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
-----				
			T.E =	2.103774
4322	4322			
509		.000049 x	577.461125 =	.028296
-----				
			T.E =	.028296
4421A	4421A			
521		.000128 x	343.854701 =	.044013
509		.000101 x	577.461125 =	.058324
528		.000128 x	869.739946 =	.111327
4312		.071000 x	1.743666 =	.123800
4411A		.071000 x	64.286012 =	4.564307
523		.000143 x	362.547952 =	.051844
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	5.014885

4421A.1	4421A.1			
521		.000128 x	343.854701 =	.044013
4411A.1		.071000 x	21.134012 =	1.500515
4412		.071000 x	1.743666 =	.123800
523		.000143 x	362.547952 =	.051844
528		.000128 x	869.739946 =	.111327
522		.000128 x	478.670193 =	.061270
509		.000101 x	577.461125 =	.058324
-----				
			T.E =	1.951093
4421B	4421B			
521		.000128 x	343.854701 =	.044013
4412		.071000 x	1.743666 =	.123800
4411B		.071000 x	66.436456 =	4.716988
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	5.167566
4421B.1	4421B.1			
521		.000128 x	343.854701 =	.044013
4412		.071000 x	1.743666 =	.123800
4411B.1		.071000 x	23.284456 =	1.653196
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	2.103774
4422	4422			
509		.000049 x	577.461125 =	.028296
-----				
			T.E =	.028296
4521A	4521A			
521		.000128 x	343.854701 =	.044013
528		.000128 x	869.739946 =	.111327
4512		.071000 x	1.743666 =	.123800
4511A		.071000 x	70.034701 =	4.972464
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	5.423042

4521A.1	4521A.1			
521		.000128 x	343.854701 =	.044013
4512		.071000 x	1.743666 =	.123800
4511A.1		.071000 x	21.488701 =	1.525698
528		.000128 x	869.739946 =	.111327
523		.000143 x	362.547952 =	.051844
509		.000101 x	577.461125 =	.058324
522		.000128 x	478.670193 =	.061270
-----				
			T.E =	1.976276
4521B	4521B			
521		.000128 x	343.854701 =	.044013
522		.000128 x	478.670193 =	.061270
509		.000101 x	577.461125 =	.058324
523		.000143 x	362.547952 =	.051844
4512		.071000 x	1.743666 =	.123800
4511B		.071000 x	72.576543 =	5.152935
528		.000128 x	869.739946 =	.111327
-----				
			T.E =	5.603513
4521B.1	4521B.1			
521		.000128 x	343.854701 =	.044013
522		.000128 x	478.670193 =	.061270
523		.000143 x	362.547952 =	.051844
4512		.071000 x	1.743666 =	.123800
4511B.1		.071000 x	24.030543 =	1.706169
528		.000128 x	869.739946 =	.111327
509		.000101 x	577.461125 =	.058324
-----				
			T.E =	2.156747
4522	4522			
509		.000049 x	577.461125 =	.028296
-----				
			T.E =	.028296
4611.1	4611.1			
326		45.000000 x	1.310000 =	58.950000
113		.100000 x	20.419486 =	2.041949
617		.013000 x	5.733079 =	.074530
4120.1		1.000000 x	.231200 =	.231200
529		.002857 x	750.888820 =	2.145289
525		.000286 x	253.596244 =	.072529
509		.000046 x	577.461125 =	.026563
522		.000667 x	478.670193 =	.319273
623		.033000 x	14.950110 =	.493354
-----				
			T.E =	64.354686

4611A	4611A			
321		3.000000 x	.539400 =	1.618200
617		.013000 x	5.733079 =	.074530
113		.100000 x	20.419486 =	2.041949
623		.033000 x	14.950110 =	.493354
509		.000046 x	577.461125 =	.026563
4120		1.000000 x	.500900 =	.500900
529		.002857 x	750.888820 =	2.145289
525		.000286 x	253.596244 =	.072529
522		.000667 x	478.670193 =	.319273
326		45.000000 x	1.310000 =	58.950000
				-----
			T.E =	66.242586
4612	4612			
509		.000040 x	577.461125 =	.023098
				-----
			T.E =	.023098
4710A	4710A			
111		1.900000 x	15.741598 =	29.909036
613		1.000000 x	6.401416 =	6.401416
509		.000361 x	577.461125 =	.208463
509		.005305 x	577.461125 =	3.063431
112		1.200000 x	17.312112 =	20.774534
630		.200000 x	.547568 =	.109514
112		2.400000 x	17.312112 =	41.549069
				-----
			T.E =	102.015464
4710A.1	4710A.1			
111		1.900000 x	15.741598 =	29.909036
614		1.000000 x	11.253764 =	11.253764
509		.000361 x	577.461125 =	.208463
509		.005305 x	577.461125 =	3.063431
630		.200000 x	.547568 =	.109514
112		1.200000 x	17.312112 =	20.774534
112		2.400000 x	17.312112 =	41.549069
				-----
			T.E =	106.867812
4710B	4710B			
111		1.900000 x	15.741598 =	29.909036
509		.005305 x	577.461125 =	3.063431
509		.000361 x	577.461125 =	.208463
112		2.400000 x	17.312112 =	41.549069
630		.200000 x	.547568 =	.109514
622		1.000000 x	15.167744 =	15.167744
112		1.200000 x	17.312112 =	20.774534
				-----
			T.E =	110.781792

4720A	4720A			
111		1.900000 x	15.741598 =	29.909036
112		2.000000 x	17.312112 =	34.624224
112		2.400000 x	17.312112 =	41.549069
4522		140.000000 x	.028296 =	3.961440
4512		1.000000 x	1.743666 =	1.743666
4511B		1.000000 x	72.576543 =	72.576543
671		20.000000 x	.927050 =	18.541000
111		1.000000 x	15.741598 =	15.741598
			T.E =	218.646576
4720A.1	4720A.1			
111		1.900000 x	15.741598 =	29.909036
111		1.000000 x	15.741598 =	15.741598
671.1		20.000000 x	.630380 =	12.607600
112		2.000000 x	17.312112 =	34.624224
4511B.1		1.000000 x	24.030543 =	24.030543
4522		140.000000 x	.028296 =	3.961440
4512		1.000000 x	1.743666 =	1.743666
112		2.400000 x	17.312112 =	41.549069
			T.E =	164.167176
4800	4800			
325		1.000000 x	2.780000 =	2.780000
112		.010000 x	17.312112 =	.173121
			T.E =	2.953121