

. .& .

3

μ

μ

3

μ

2012

001	15.315315
002	16.843762
003	19.864197
026	.099900
036	.090700
273	1.084300
297.1	1.910000
510	3.020000
511	.620000
513	1.200000
561	2.030000
565.3	3.800000
566.3	5.050000
567.13	19.210000
571.5.1	2.620000
572.1.7	3.450000
575.3	
581.2	9.090000
582.2	27.000000
588.3	
603.3	5.650000
605.3.5	136.000000
619.2.2	44.600000
620.1	73.000000
621.1	65.000000
630.1.2	305.000000
634.1.1	95.000000
647.2	19.000000
660.1.1	16.000000
667	139.000000
671.3.8	4,500.000000
672.4.6	5,380.000000
673.1.5	5,600.000000
684.6.2	115.000000
686.1	410.000000
687.1.1	2,400.000000
703.2.2	27.500000
714.2.6	5,140.000000
715.2.9	5,098.000000
718.3.3	1,070.000000
719.1.3	1,100.000000
720.11	9.000000
729.1.2	972.000000
730.2.5	2.300000
732.5.30	75.000000
744.9	70,000.000000
755.10	13,260.000000
757.1.4	17,490.000000
760.1.4	4,800.000000
801.3.2	.225000
801.7.1	1.940000
812.1.2	.164500
812.2.3	1.698700
813.2.3	2.731200
816.3.2	.881800
820.5.1	.816500
820.5.4	2.848900
825.6.1	.537000
826.2.1	1.700000

835.1.2	76.500000
841.3.5	192.000000
842.3.2	81.400000
848.1.2	34.200000
852.1.6	995.000000
855.1.13	2,732.000000
858.1.2	3.200000
859.1.2	5.000000
865.13.10	19,950.000000
865.13.9	16,500.000000
865.8.3	41.000000
867.1.22	75,800.000000
871.7.4	57.000000
872.23.1	5.030000
880.1.2	.780000
885.1.2	20.000000
890.1.1	120.000000
910.2.5	9,500.000000
911.1.17	3,430.000000
912.1.5	3,694.000000
913.1.9	68.900000
914.1.8	155.000000
915.1.6	345.000000
915.3.10	13,101.000000
916.1.3	
916.2.3	
916.3.3	
917.1	7,780.000000
918.1.1	2,010.000000
920.1.1	7,479.000000
923.1.1	61.620000
923.2.1	161.400000
925.1.1	4,600.000000
931.1.5	370.000000
931.2.4	1,070.000000
932.4.2	348.000000
933.1.1	15.500000
934.1.1	324.000000
935.1.1	76.500000
950.1.1	6.000000
951.1.7	701.000000
951.2.2	12,650.000000
952.1.4	331.800000
953.1.3	26,500.000000

1	1				
026		1.100000 x	.099900 =	.109890	
297.1		1.200000 x	1.910000 =	2.292000	
582.2		1.300000 x	27.000000 =	35.100000	
002		1.300000 x	16.843762 =	21.896891	
003		1.300000 x	19.864197 =	25.823456	

			T.E =	85.222237	
10	10				
581.2		1.200000 x	9.090000 =	10.908000	
003		.300000 x	19.864197 =	5.959259	
001		.300000 x	15.315315 =	4.594595	

			T.E =	21.461854	
100	100				
931.1.5		1.000000 x	370.000000 =	370.000000	
003		4.000000 x	19.864197 =	79.456788	
002		6.000000 x	16.843762 =	101.062572	

			T.E =	550.519360	
101	101				
931.2.4		1.000000 x	1,070.000000 =	1,070.000000	
002		9.000000 x	16.843762 =	151.593858	
003		6.000000 x	19.864197 =	119.185182	

			T.E =	1,340.779040	
102	102				
820.5.4		1.020000 x	2.848900 =	2.905878	
002		.200000 x	16.843762 =	3.368752	
003		.200000 x	19.864197 =	3.972839	

			T.E =	10.247470	
103	103				
932.4.2		1.000000 x	348.000000 =	348.000000	
002		2.500000 x	16.843762 =	42.109405	
003		2.500000 x	19.864197 =	49.660493	

			T.E =	439.769898	
104	104				
933.1.1		1.000000 x	15.500000 =	15.500000	
003		1.200000 x	19.864197 =	23.837036	
002		1.200000 x	16.843762 =	20.212514	

			T.E =	59.549551	

105	105				
934.1.1		1.000000 x	324.000000 =	324.000000	
002		2.000000 x	16.843762 =	33.687524	
003		2.000000 x	19.864197 =	39.728394	

			T.E =	397.415918	
106	106				
951.1.7		1.030000 x	701.000000 =	722.030000	
002		4.000000 x	16.843762 =	67.375048	
003		4.000000 x	19.864197 =	79.456788	

			T.E =	868.861836	
107	107				
952.1.4		1.030000 x	331.800000 =	341.754000	
002		1.000000 x	16.843762 =	16.843762	
003		1.000000 x	19.864197 =	19.864197	

			T.E =	378.461959	
108	108				
951.2.2		1.030000 x	12,650.000000 =	13,029.500000	
003		6.000000 x	19.864197 =	119.185182	
002		6.000000 x	16.843762 =	101.062572	

			T.E =	13,249.747754	
109	109				
953.1.3		1.030000 x	26,500.000000 =	27,295.000000	
003		12.000000 x	19.864197 =	238.370364	
002		12.000000 x	16.843762 =	202.125144	

			T.E =	27,735.495508	
11	11				
603.3		1.030000 x	5.650000 =	5.819500	
003		.500000 x	19.864197 =	9.932099	

			T.E =	15.751599	
110	110				
950.1.1		1.050000 x	6.000000 =	6.300000	
002		.200000 x	16.843762 =	3.368752	
003		.200000 x	19.864197 =	3.972839	

			T.E =	13.641592	

12	12				
605.3.5		1.050000 x	136.000000 =	142.800000	
002		.600000 x	16.843762 =	10.106257	
003		.600000 x	19.864197 =	11.918518	

			T.E =	164.824775	
13	13				
619.2.2		1.030000 x	44.600000 =	45.938000	
002		.400000 x	16.843762 =	6.737505	
003		.400000 x	19.864197 =	7.945679	

			T.E =	60.621184	
14	14				
026		15.000000 x	.099900 =	1.498500	
620.1		1.000000 x	73.000000 =	73.000000	
003		2.000000 x	19.864197 =	39.728394	
002		2.000000 x	16.843762 =	33.687524	

			T.E =	147.914418	
15	15				
621.1		1.000000 x	65.000000 =	65.000000	
003		2.000000 x	19.864197 =	39.728394	
002		2.000000 x	16.843762 =	33.687524	
621.1		.100000 x	65.000000 =	6.500000	

			T.E =	144.915918	
16	16				
630.1.2		1.000000 x	305.000000 =	305.000000	
003		3.000000 x	19.864197 =	59.592591	
002		3.000000 x	16.843762 =	50.531286	
630.1.2		.050000 x	305.000000 =	15.250000	

			T.E =	430.373877	
17	17				
634.1.1		1.200000 x	95.000000 =	114.000000	
003		2.000000 x	19.864197 =	39.728394	
002		.200000 x	16.843762 =	3.368752	
634.1.1		.050000 x	95.000000 =	4.750000	

			T.E =	161.847146	
18	18				
647.2		1.000000 x	19.000000 =	19.000000	
003		.200000 x	19.864197 =	3.972839	

			T.E =	22.972839	

19	19				
660.1.1		1.030000 x	16.000000 =	16.480000	
003		.200000 x	19.864197 =	3.972839	
002		.200000 x	16.843762 =	3.368752	

			T.E =	23.821592	
2	2				
561		5.320000 x	2.030000 =	10.799600	
003		.600000 x	19.864197 =	11.918518	
002		.600000 x	16.843762 =	10.106257	

			T.E =	32.824375	
20	20				
667		1.000000 x	139.000000 =	139.000000	
667		.020000 x	139.000000 =	2.780000	
003		4.000000 x	19.864197 =	79.456788	
002		4.000000 x	16.843762 =	67.375048	

			T.E =	288.611836	
21	21				
671.3.8		1.000000 x	4,500.000000 =	4,500.000000	
671.3.8		.100000 x	4,500.000000 =	450.000000	
002		20.000000 x	16.843762 =	336.875240	
003		20.000000 x	19.864197 =	397.283940	

			T.E =	5,684.159180	
22	22				
672.4.6		1.000000 x	5,380.000000 =	5,380.000000	
672.4.6		.100000 x	5,380.000000 =	538.000000	
003		20.000000 x	19.864197 =	397.283940	
002		20.000000 x	16.843762 =	336.875240	

			T.E =	6,652.159180	
23	23				
673.1.5		1.000000 x	5,600.000000 =	5,600.000000	
003		25.000000 x	19.864197 =	496.604925	
002		25.000000 x	16.843762 =	421.094050	
687.1.1		.020000 x	2,400.000000 =	48.000000	
687.1.1		1.000000 x	2,400.000000 =	2,400.000000	
673.1.5		.020000 x	5,600.000000 =	112.000000	

			T.E =	9,077.698975	

24	24				
684.6.2		1.000000 x	115.000000 =	115.000000	
003		1.000000 x	19.864197 =	19.864197	
684.6.2		.020000 x	115.000000 =	2.300000	
002		1.000000 x	16.843762 =	16.843762	

			T.E =	154.007959	
25	25				
686.1		1.000000 x	410.000000 =	410.000000	
003		4.000000 x	19.864197 =	79.456788	
002		4.000000 x	16.843762 =	67.375048	
686.1		.020000 x	410.000000 =	8.200000	

			T.E =	565.031836	
26	26				
703.2.2		1.020000 x	27.500000 =	28.050000	
003		.250000 x	19.864197 =	4.966049	
002		.250000 x	16.843762 =	4.210941	

			T.E =	37.226990	
27	27				
714.2.6		1.000000 x	5,140.000000 =	5,140.000000	
003		10.000000 x	19.864197 =	198.641970	
002		10.000000 x	16.843762 =	168.437620	
714.2.6		.020000 x	5,140.000000 =	102.800000	
001		5.000000 x	15.315315 =	76.576575	

			T.E =	5,686.456165	
28	28				
715.2.9		1.000000 x	5,098.000000 =	5,098.000000	
003		12.000000 x	19.864197 =	238.370364	
002		12.000000 x	16.843762 =	202.125144	
001		6.000000 x	15.315315 =	91.891890	
715.2.9		.020000 x	5,098.000000 =	101.960000	

			T.E =	5,732.347398	
29	29				
718.3.3		1.000000 x	1,070.000000 =	1,070.000000	
002		8.000000 x	16.843762 =	134.750096	
718.3.3		.050000 x	1,070.000000 =	53.500000	
003		8.000000 x	19.864197 =	158.913576	

			T.E =	1,417.163672	

3	3			
026		1.200000 x	.099900 =	.119880
588.3		1.300000 x	.000000 =	.000000
003		1.200000 x	19.864197 =	23.837036
002		1.200000 x	16.843762 =	20.212514

T.E =

30	30			
719.1.3		.100000 x	1,100.000000 =	110.000000
719.1.3		1.000000 x	1,100.000000 =	1,100.000000
001		8.000000 x	15.315315 =	122.522520
003		16.000000 x	19.864197 =	317.827152
002		16.000000 x	16.843762 =	269.500192

T.E = 1,919.849864

31	31			
720.11		1.020000 x	9.000000 =	9.180000
003		.300000 x	19.864197 =	5.959259

T.E = 15.139259

32	32			
729.1.2		1.000000 x	972.000000 =	972.000000
002		2.000000 x	16.843762 =	33.687524
729.1.2		.030000 x	972.000000 =	29.160000
003		2.000000 x	19.864197 =	39.728394

T.E = 1,074.575918

33	33			
757.1.4		1.000000 x	17,490.000000 =	17,490.000000
757.1.4		.050000 x	17,490.000000 =	874.500000
001		7.000000 x	15.315315 =	107.207205
003		15.000000 x	19.864197 =	297.962955
002		15.000000 x	16.843762 =	252.656430

T.E = 19,022.326590

34	34			
273		1.000000 x	1.084300 =	1.084300
002		.300000 x	16.843762 =	5.053129
003		.300000 x	19.864197 =	5.959259
273		.100000 x	1.084300 =	.108430

T.E = 12.205118

35	35				
730.2.5		1.050000 x	2.300000 =	2.415000	
003		.120000 x	19.864197 =	2.383704	
002		.120000 x	16.843762 =	2.021251	
730.2.5		.250000 x	2.300000 =	.575000	

			T.E =	7.394955	
36	36				
732.5.30		1.050000 x	75.000000 =	78.750000	
003		.400000 x	19.864197 =	7.945679	
002		.400000 x	16.843762 =	6.737505	

			T.E =	93.433184	
37	37				
744.9		1.000000 x	70,000.000000 =	70,000.000000	
744.9		.020000 x	70,000.000000 =	1,400.000000	
001		10.000000 x	15.315315 =	153.153150	
002		20.000000 x	16.843762 =	336.875240	
003		20.000000 x	19.864197 =	397.283940	

			T.E =	72,287.312330	
38	38				
755.10		1.000000 x	13,260.000000 =	13,260.000000	
755.10		.020000 x	13,260.000000 =	265.200000	
001		10.000000 x	15.315315 =	153.153150	
002		10.000000 x	16.843762 =	168.437620	
003		10.000000 x	19.864197 =	198.641970	

			T.E =	14,045.432740	
39	39				
760.1.4		1.000000 x	4,800.000000 =	4,800.000000	
760.1.4		.050000 x	4,800.000000 =	240.000000	
002		3.500000 x	16.843762 =	58.953167	
003		3.500000 x	19.864197 =	69.524690	

			T.E =	5,168.477857	
4	4				
565.3		1.250000 x	3.800000 =	4.750000	
002		.600000 x	16.843762 =	10.106257	
003		.600000 x	19.864197 =	11.918518	

			T.E =	26.774775	

40	40				
036		3.000000 x	.090700 =	.272100	
003		.450000 x	19.864197 =	8.938889	
002		.450000 x	16.843762 =	7.579693	
510		.350000 x	3.020000 =	1.057000	
511		.250000 x	.620000 =	.155000	
513		.250000 x	1.200000 =	.300000	

			T.E =	18.302682	
41	41				
801.3.2		1.050000 x	.225000 =	.236250	
003		.100000 x	19.864197 =	1.986420	
801.3.2		.105000 x	.225000 =	.023625	
002		.100000 x	16.843762 =	1.684376	

			T.E =	3.930671	
42	42				
801.7.1		1.050000 x	1.940000 =	2.037000	
003		.200000 x	19.864197 =	3.972839	
002		.200000 x	16.843762 =	3.368752	
801.7.1		.210000 x	1.940000 =	.407400	

			T.E =	9.785992	
43	43				
812.1.2		1.050000 x	.164500 =	.172725	
003		.020000 x	19.864197 =	.397284	
002		.020000 x	16.843762 =	.336875	

			T.E =	.906884	
44	44				
812.2.3		1.050000 x	1.698700 =	1.783635	
003		.060000 x	19.864197 =	1.191852	
002		.060000 x	16.843762 =	1.010626	

			T.E =	3.986113	
45	45				
813.2.3		1.050000 x	2.731200 =	2.867760	
813.2.3		.105000 x	2.731200 =	.286776	
003		.050000 x	19.864197 =	.993210	
002		.050000 x	16.843762 =	.842188	

			T.E =	4.989934	

46	46				
816.3.2		.157500 x	.881800 =	.138884	
816.3.2		1.050000 x	.881800 =	.925890	
002		.120000 x	16.843762 =	2.021251	
003		.120000 x	19.864197 =	2.383704	

			T.E =	5.469729	
47	47				
820.5.1		1.050000 x	.816500 =	.857325	
820.5.1		.157500 x	.816500 =	.128599	
003		.140000 x	19.864197 =	2.780988	
002		.140000 x	16.843762 =	2.358127	

			T.E =	6.125038	
48	48				
825.6.1		1.050000 x	.537000 =	.563850	
003		.100000 x	19.864197 =	1.986420	
002		.100000 x	16.843762 =	1.684376	
825.6.1		.157500 x	.537000 =	.084578	

			T.E =	4.319223	
49	49				
826.2.1		1.000000 x	1.700000 =	1.700000	
003		.200000 x	19.864197 =	3.972839	

			T.E =	5.672839	
5	5				
566.3		1.250000 x	5.050000 =	6.312500	
002		.600000 x	16.843762 =	10.106257	
003		.600000 x	19.864197 =	11.918518	

			T.E =	28.337275	
50	50				
842.3.2		1.000000 x	81.400000 =	81.400000	
842.3.2		.030000 x	81.400000 =	2.442000	
002		.500000 x	16.843762 =	8.421881	
003		.500000 x	19.864197 =	9.932099	

			T.E =	102.195980	
51	51				
841.3.5		1.000000 x	192.000000 =	192.000000	
841.3.5		.030000 x	192.000000 =	5.760000	
003		1.000000 x	19.864197 =	19.864197	
002		1.000000 x	16.843762 =	16.843762	

			T.E =	234.467959	

52	52				
835.1.2		1.050000 x	76.500000 =	80.325000	
003		3.000000 x	19.864197 =	59.592591	
002		3.000000 x	16.843762 =	50.531286	

			T.E =	190.448877	
53	53				
848.1.2		1.020000 x	34.200000 =	34.884000	
003		.200000 x	19.864197 =	3.972839	

			T.E =	38.856839	
54	54				
858.1.2		1.020000 x	3.200000 =	3.264000	
003		.200000 x	19.864197 =	3.972839	

			T.E =	7.236839	
55	55				
859.1.2		1.020000 x	5.000000 =	5.100000	
003		.200000 x	19.864197 =	3.972839	

			T.E =	9.072839	
56	56				
865.8.3		1.050000 x	41.000000 =	43.050000	
002		2.000000 x	16.843762 =	33.687524	
003		2.000000 x	19.864197 =	39.728394	

			T.E =	116.465918	
57	57				
865.13.9		1.020000 x	16,500.000000 =	16,830.000000	
002		25.000000 x	16.843762 =	421.094050	
001		10.000000 x	15.315315 =	153.153150	
003		25.000000 x	19.864197 =	496.604925	

			T.E =	17,900.852125	
58	58				
867.1.22		1.000000 x	75,800.000000 =	75,800.000000	
867.1.22		.030000 x	75,800.000000 =	2,274.000000	
001		130.000000 x	15.315315 =	1,990.990950	
003		130.000000 x	19.864197 =	2,582.345610	
002		130.000000 x	16.843762 =	2,189.689060	

			T.E =	84,837.025620	

59	59				
871.7.4		1.000000 x	57.000000 =	57.000000	
002		1.200000 x	16.843762 =	20.212514	
003		1.200000 x	19.864197 =	23.837036	
871.7.4		.020000 x	57.000000 =	1.140000	

			T.E =	102.189551	
6	6				
567.13		1.300000 x	19.210000 =	24.973000	
003		1.000000 x	19.864197 =	19.864197	
002		1.000000 x	16.843762 =	16.843762	

			T.E =	61.680959	
60	60				
872.23.1		1.020000 x	5.030000 =	5.130600	
003		.600000 x	19.864197 =	11.918518	
002		.600000 x	16.843762 =	10.106257	
880.1.2		1.000000 x	.780000 =	.780000	

			T.E =	27.935375	
61	61				
885.1.2		1.000000 x	20.000000 =	20.000000	
002		.600000 x	16.843762 =	10.106257	
003		.600000 x	19.864197 =	11.918518	

			T.E =	42.024775	
62	62				
890.1.1		1.000000 x	120.000000 =	120.000000	
890.1.1		.050000 x	120.000000 =	6.000000	
002		2.000000 x	16.843762 =	33.687524	
003		2.000000 x	19.864197 =	39.728394	

			T.E =	199.415918	
63	63				
910.2.5		1.000000 x	9,500.000000 =	9,500.000000	
002		50.000000 x	16.843762 =	842.188100	
001		30.000000 x	15.315315 =	459.459450	
003		50.000000 x	19.864197 =	993.209850	
910.2.5		.020000 x	9,500.000000 =	190.000000	

			T.E =	11,984.857400	

7	7				
571.5.1		1.400000 x	2.620000 =	3.668000	
003		.300000 x	19.864197 =	5.959259	
002		.300000 x	16.843762 =	5.053129	

			T.E =	14.680388	
8	8				
572.1.7		1.350000 x	3.450000 =	4.657500	
002		.700000 x	16.843762 =	11.790633	
003		.700000 x	19.864197 =	13.904938	

			T.E =	30.353071	
80	80				
911.1.17		1.050000 x	3,430.000000 =	3,601.500000	
002		30.000000 x	16.843762 =	505.312860	
003		30.000000 x	19.864197 =	595.925910	

			T.E =	4,702.738770	
81	81				
912.1.5		1.050000 x	3,694.000000 =	3,878.700000	
002		30.000000 x	16.843762 =	505.312860	
003		30.000000 x	19.864197 =	595.925910	

			T.E =	4,979.938770	
82	82				
913.1.9		1.200000 x	68.900000 =	82.680000	
003		4.000000 x	19.864197 =	79.456788	
002		4.000000 x	16.843762 =	67.375048	

			T.E =	229.511836	
83	83				
914.1.8		1.100000 x	155.000000 =	170.500000	
002		2.000000 x	16.843762 =	33.687524	
003		2.000000 x	19.864197 =	39.728394	

			T.E =	243.915918	
84	84				
915.1.6		1.050000 x	345.000000 =	362.250000	
002		8.000000 x	16.843762 =	134.750096	
003		8.000000 x	19.864197 =	158.913576	

			T.E =	655.913672	

85	85			
915.3.10		1.050000 x	13,101.000000 =	13,756.050000
002		20.000000 x	16.843762 =	336.875240
003		20.000000 x	19.864197 =	397.283940

 T.E = 14,490.209180

86	86			
865.13.10		1.020000 x	19,950.000000 =	20,349.000000
003		40.000000 x	19.864197 =	794.567880
002		40.000000 x	16.843762 =	673.750480

 T.E = 21,817.318360

87	87			
916.1.3		1.030000 x	.000000 =	.000000
916.3.3		1.010000 x	.000000 =	.000000
916.2.3		1.020000 x	.000000 =	.000000
003		120.000000 x	19.864197 =	2,383.703640
002		120.000000 x	16.843762 =	2,021.251440

 T.E =

88	88			
917.1		1.000000 x	7,780.000000 =	7,780.000000
917.1		.030000 x	7,780.000000 =	233.400000
918.1.1		.030000 x	2,010.000000 =	60.300000
920.1.1		.030000 x	7,479.000000 =	224.370000
923.1.1		.030000 x	61.620000 =	1.848600
003		40.000000 x	19.864197 =	794.567880
002		40.000000 x	16.843762 =	673.750480
923.2.1		.030000 x	161.400000 =	4.842000
923.2.1		1.000000 x	161.400000 =	161.400000
923.1.1		1.000000 x	61.620000 =	61.620000
920.1.1		1.000000 x	7,479.000000 =	7,479.000000
918.1.1		1.000000 x	2,010.000000 =	2,010.000000

 T.E = 19,485.098960

89	89			
852.1.6		1.000000 x	995.000000 =	995.000000
855.1.13		1.000000 x	2,732.000000 =	2,732.000000
855.1.13		.020000 x	2,732.000000 =	54.640000
925.1.1		.020000 x	4,600.000000 =	92.000000
003		60.000000 x	19.864197 =	1,191.851820
002		60.000000 x	16.843762 =	1,010.625720
925.1.1		1.000000 x	4,600.000000 =	4,600.000000
852.1.6		.020000 x	995.000000 =	19.900000

 T.E = 10,696.017540

3 μ 2012

. 17
μ/ 09/01/2014

9 9

575.3
003
002

1.200000 x
.300000 x
.300000 x

.000000 =
19.864197 =
16.843762 =

.000000
5.959259
5.053129

T.E =